Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for
this publication.

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
Washington, D. C. 20555

NUREC
Vol. 6,

Title List of Documents Made Publicly Available

August 1-31, 1984

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface v
Arrangement of Items by Docket Number ix
Alphabetic Arrangement of Docket Items by Facility Name xvii
Docketed Items
Low Level Radwaste Disposal Sites — Docket 27. 1
Domestic Licensing of Source Material — Docket 40 1
Domestic Licensing of Production and Utilization Facilities — Docket 50 9
Domestic Licensing of Special Nuclear Material — Docket 70 424
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71 431
Licensing of Independent Spent Fuel Storage — Docket 72 444
Nondocketed Items 445
10 CFR — Commission Meeting Records 445
ACRS — Advisory Committee on Reactor Safeguards 445
ADVCM — NRC Advisory Committees 447
COMMISSION — NRC Commissioners 447
CONTRACT — NRC Contracts and Modifications 449
FOIA — Freedom of Information Act Requests and Releases 453
GEN TECH IS — Generic Technical Issues 466
I&E — Inspection and Enforcement 468
MISC — Public Document Room Miscellaneous 471
NUREG — NUREG Reports and Related Correspondence 471
ORG — Correspondence with Other Organizations 487
PR — Proposed Rule 490
PRM — Petition for Rulemaking 492
PROJ — Projects - Predocket Licensing 492
PT21 — Noncompliance Reports and Related Correspondence 492
QA999 — Quality Assurance Inspections 494
REGGD — Regulatory Guides 497
REVIEW GROUP — NRC Research Review Groups 498
SECY — Position Papers Before the Commission 498
STATE PROG — State Programs 499
TOPREP — Vendor Reports and Related Correspondence 500
WASTE MGT — Nuclear Waste Management 508
WASTE RES — Waste Management Research Reports 515
XPORTLIC — Export and Import Licenses 516
Personal Author Index 521
Corporate Source Index 553
Report Number Index 583
Cross Reference of Enclosures to Principal Documents 585
Appendix A — Definitions of Docket 50 Categories A-1
Appendix B — Definitions of Nondocketed Categories B-1

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication It contains descriptions of the information received and generated by the U S Nuclear Regulatory Commission (NRC) This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979 Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address

We encourage your comments, criticisms, and suggestions In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base In so far as possible, we would like this document to be a valuable part of your reference material

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room Those categories are:

A. Application/construction stage documents and correspondence
B Utility Preliminary Safety Analysis Report (PSAR), amendments
C. Utility Environmental Report (ER), amendments and correspondence
D NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
E. NRC Safety Evaluation Report (SER), supplements and correspondence
F. Security, medical, emergency and fire-protection plans
G. Adjudicatory correspondence
H. General correspondence
I. Financial information
J. Insurance and indemnity information
K Utility Final Safety Analysis Report (FSAR) and amendments
L. Limited work authorization and related correspondence
M. Antitrust correspondence
N. Antitrust hearing transcripts
O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
P. Operating license stage documents and correspondence
Q. Inspection reports, IE Bulletins and correspondence
R. Periodic operating reports and related correspondence
S. Reportable occurrences, LERs and related correspondence
T. Hearing transcripts on non-antitrust matters
U Congressional/executive correspondence
V. Licensing operators and related correspondence

W Decommissioning stage documents and correspondence
X Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report

The principal elements of the entries in the list are:

(1) P Operating license stage documents & correspondence

(2) (3)
8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510
(4) MILLS, L.M (5) Tennessee Valley Authority. (6) 82/03/04 (7) VASSALLO, D B
Operating Reactors Branch 2 (8) 1p. 1216:254. 24XFiche: 50-259, 82/03/04,
8203090028.
(12) (9) (10) (11)

1 NRC/PDR Document category (see Appendix A).
2. NRC Accession Number (year, month, day, and sequence number of item).
3. Description of information contained in the document.
4. Personal author(s) An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source
6. Date of document described
7. Recipient of document and NRC or corporate affiliation.
8. Pages in this document.
9 The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
10. This three-digit portion of this entry is the number of the frame on which this document starts.
11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
12 If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items Entries indented and preceded by a dash are items that were submitted as enclosures to principal items In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5

NONDOCKETED ITEMS


The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are·

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement
MISC — Public Document Room Miscellaneous
NUREG — NUREG Reports and Related Correspondence
ORG — Correspondence with Other Organizations
PR — Proposed Rule
PRM — Petition for Rulemaking
PROJ — Projects—Predocket Licensing
PT21 — Noncompliance Reports and Related Correspondence
QA999 — Quality Assurance Inspections
REGGD — Regulatory Guides
RES — Research and Technical Assistance Reports
REVIEW GRP — NRC Research Review Groups
RM — Rulemakings
SECY — Position Papers Before the Commission
STATE PROG — State Programs
TOPREP — Vendor Reports and Related Correspondence
WASH — Regulatory Publications—Pre-NUREG Series
WASTE MGT — Nuclear Waste Management
XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number (year, month, day, and sequence number of item)
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author.
6. Corporate, agency or other nonindividual source.
7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
8. Secondary report number assigned by originator.
9. Date of document described.
10. NRC organizational recipient.
11. Pages in document.
12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
13. Price for which NRC sells the document.

14 The NRC 48X microfiche designation for this document This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files

15. This three-digit portion of this entry is the number of the frame on which this document starts

The Nondocketed Items list is arranged sequentially by Accession Number within category Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:
   Director
   Division of Technical Information and Document Control
   U.S. Nuclear Regulatory Commission
   Washington, D.C 20555

   To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:
   National Technical Information Service
   Springfield, Virginia 22161

   To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order

3. The address for the PDR is:
   1717 H Street, N.W.
   Washington, D.C. 20555

   To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

   Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is $0 05 per page except for oversized documents and engineering drawings, which vary from $0.50 to $1.00 per square foot; (2) microform to paper is $0.05 a page for pages on microfiche and is $0.20 a square foot for a full-size print or $0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is $0.10 per microfiche and $0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials

   Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page
Low Level Radwaste Disposal Sites — Docket 27		
27-039	Sheffield, IL, U S Ecology, Inc	1
27-048	Richland, WA, U S Ecology, Inc	1
Domestic Licensing of Source Material — Docket 40		
40-0299	Union Carbide Corp , Grand Junction, CO	1
40-0672	Nuclear Metals, Inc , Concord, MA	2
40-0791	United Technologies Corp , East Hartford, CT	2
40-1162	Western Nuclear, Inc., Jeffrey City, WY	2
40-1341	Tennessee Valley Authority, Chattanooga, TN	2
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	2
40-2259	Pathfinder Mines Corp., Riverton, WY	3
40-3392	Allied Chemical Corp., Morristown, NJ	4
40-3453	Atlas Minerals, Inc , Denver, CO	4
40-4492	Federal-American Partners, Riverton, WY	4
40-6499	Maine Maritime Academy, Castine, ME	4
40-6500	Energy, Dept of, Canonsburg, PA	4
40-6622	Pathfinder Mines Corp , Shirley Basin, WY	4
40-6659	Getty Oil Co -Petrotomics Co., Shirley Basin, WY	5
40-6940	Kawecki Berylco Industries, Inc., Boyertown, PA	5
40-7455	Whittaker Metals, Los Angeles, CA	5
40-7869	Plateau Resources, Ltd., Grand Junction, CO	5
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	5
40-8064	Exxon Minerals Co , USA, Houston, TX	5
40-8084	Rio Algom Corp., Moab, UT	5
40-8102	Exxon Co , USA, Houston, TX	5
40-8380	Rocky Mountain Energy Co , Broomfield, CO	6
40-8434	Homestake Mining Co., Lakewood, CO	6
40-8452	Bear Creek Uranium Co , Casper, WY	6
40-8502	Wyoming Mineral Corp , Lakewood, CO	6
40-8584	Minerals Exploration Co , Los Angeles, CA	7
40-8585	Wyoming Mineral Corp , Lakewood, CO	7
40-8586	Kerr-McGee Nuclear Corp , Oklahoma City, OK	7
40-8602	Silver King Mines, Inc , Casper, WY	7
40-8674	Plateau Resources, Ltd Grand Junction, CO	7
40-8675	Energy Fuels Nuclear, Inc , Denver, CO	7
40-8681	Energy Fuels Nuclear, Inc , Denver, CO	7
40-8684	Western Nuclear, Inc , Lakewood, CO	8
40-8697	Rocky Mountain Energy Co , Denver, CO	8
40-8698	Plateau Resources, Ltd , Grand Junction, CO	8
40-8722	Brush Wellman, Inc., Cleveland, OH	8
40-8724	Chemetron Corp , Chicago, IL	8
40-8727	Kerr-McGee Nuclear Corp , Oklahoma City, OK	8
40-8728	Teton Exploration Drilling Co , Inc , Casper, WY	8
40-8745	Ogle Petroleum, Inc., Casper, WY	8
40-8768	Kerr-McGee Nuclear Corp , Oklahoma City, OK	8
40-8769	Exxon Co., USA, Billings, MT	9
40-8783	Uranerz USA, Inc , Casper, WY	9
40-8786	Uranium Resources, Inc., Richardson, TX	9
40-8822	Omaha Public Power District, Omaha, NE	9
40-8829	Wyoming Fuel Co., Lakewood, CO	9
40-8842	Minnesota, Univ of, Minneapolis, MN	9
40-8857	Everest Minerals Corp., Converse County, WY	9
Domestic Licensing of Production and Utilization Facilities— Docket 50		
50-2	Univ of Michigan Research Reactor	9
50-3	Indian Point Station, Unit 1	9

Docket	Name	Page
50-5	Pennsylvania State Univ Research Reactor	10
50-10	Dresden Nuclear Power Station, Unit 1	10
50-13	Babcock & Wilcox Co. Critical Facility	12
50-27	Washington State Univ Research Reactor	12
50-29	Yankee-Rowe Nuclear Power Station	12
50-30	Plum Brook Research Reactor Facility	14
50-54	Union Carbide Research Reactor	15
50-57	State Univ. of New York Research Reactor	15
50-59	Texas A&M Univ. Research Reactor	15
50 62	Univ. of Virginia Research Reactor	15
50-70	General Electric Test Reactor	15
50-73	General Electric Nuclear Test Reactor	15
50-89	General Atomic Co	15
50-97	Cornell Univ Zero Power Reactor	16
50-112	Univ. of Oklahoma Research Reactor	16
50-116	Iowa State Univ. Research Reactor	16
50-123	Univ of Missouri Research Reactor	16
50-133	Humboldt Bay Power Plant, Unit 3	16
50-134	Worcester Polytechnic Institute Research Reactor	17
50-139	Univ of Washington Research Reactor	17
50-142	UCLA Training Reactor	17
50-150	Ohio State Univ. Research Reactor	17
50-151	Univ of Illinois Research Reactor	17
50-155	Big Rock Point Nuclear Plant	18
50-156	Univ. of Wisconsin Research Reactor	20
50-157	Cornell Univ Research Reactor	21
50-160	Georgia Institute of Technology Research Reactor	21
50-163	GA Technologies	21
50-166	Univ. of Maryland Research Reactor	21
50-170	National Naval Medical Center	22
50-171	Peach Bottom Atomic Power Station, Unit 1	22
50-182	Purdue Univ. Research Reactor	22
50-184	National Bureau of Standards Reactor	22
50-185	Plum Brook Reactor—Mock-Up	22
50-186	Univ. of Missouri Research Reactor	22
50-188	Kansas State Univ Research Reactor	22
50-192	Univ of Texas Research Reactor	22
50-193	Rhode Island & Providence Plantations AEC	22
50-199	Manhattan College Research Reactor	23
50-206	San Onofre Nuclear Station, Unit 1	23
50-213	Haddam Neck Plant	26
50-219	Oyster Creek Nuclear Power Plant	28
50-220	Nine Mile Point Nuclear Station, Unit 1	31
50-223	Univ. of Lowell Research Reactor	33
50-225	RPI Critical Experiment	33
50-237	Dresden Nuclear Power Station, Unit 2	33
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	36
50-245	Millstone Nuclear Power Station, Unit 1	38
50-247	Indian Point Station, Unit 2	41
50-249	Dresden Nuclear Power Station, Unit 3	44
50-250	Turkey Point Plant, Unit 3	46
50-251	Turkey Point Plant, Unit 4	49
50-252	Univ. of New Mexico Research Reactor	52
50-254	Quad-Cities Station, Unit 1	52
50-255	Palisades Nuclear Plant	54
50-259	Browns Ferry Nuclear Power Station, Unit 1	57
50-260	Browns Ferry Nuclear Power Station, Unit 2	61
50-261	H B Robinson Plant, Unit 2	65
50-262	Brigham Young Univ Research Reactor	68
50-263	Monticello Nuclear Generating Plant	68
50-264	Dow Chemical Co	70
50-265	Quad-Cities Station, Unit 2	70
50-266	Point Beach Nuclear Plant, Unit 1	72
50-267	Fort St. Vrain Nuclear Generating Station	74
50-269	Oconee Nuclear Station, Unit 1	76
50-270	Oconee Nuclear Station, Unit 2	79
50-271	Vermont Yankee Nuclear Power Station	81
50-272	Salem Nuclear Generating Station, Unit 1	83
50-274	U.S Geological Survey Research Reactor	85

Docket	Name	Page
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	85
50-276	Georgia Tech Research Reactor	90
50-277	Peach Bottom Atomic Power Station, Unit 2	90
50-278	Peach Bottom Atomic Power Station, Unit 3	92
50-280	Surry Power Station, Unit 1	94
50-281	Surry Power Station, Unit 2	97
50-282	Prairie Island Nuclear Station, Unit 1	98
50-284	Idaho State Univ Research Reactor	100
50-285	Fort Calhoun Station, Unit 1	100
50-286	Indian Point Station, Unit 3	101
50-287	Oconee Nuclear Station, Unit 3	103
50-289	Three Mile Island Nuclear Station, Unit 1	106
50-293	Pilgrim Nuclear Power Station, Unit 1	112
50-294	Michigan State Univ Research Reactor	115
50-295	Zion Nuclear Power Station, Unit 1	115
50-296	Browns Ferry Nuclear Power Station, Unit 3	119
50-297	North Carolina State Univ PULSTAR Reactor	122
50-298	Cooper Nuclear Station	122
50-301	Point Beach Nuclear Plant, Unit 2	124
50-302	Crystal River Nuclear Plant, Unit 3	127
50-304	Zion Nuclear Power Station, Unit 2	129
50-305	Kewaunee Nuclear Power Plant	132
50-306	Prairie Island Nuclear Station, Unit 2	134
50-309	Maine Yankee Atomic Power Plant	135
50-311	Salem Nuclear Generating Station, Unit 2	137
50-312	Rancho Seco Nuclear Generating Station	139
50-313	Arkansas Nuclear One, Unit 1	142
50-315	Donald C Cook Nuclear Power Plant, Unit 1	144
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	146
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	148
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	151
50-320	Three Mile Island Nuclear Station, Unit 2	153
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	156
50-322	Shoreham Nuclear Power Station	159
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	167
50-324	Brunswick Steam Electric Plant, Unit 2	171
50-325	Brunswick Steam Electric Plant Unit 1	173
50-326	Univ of California at Irvine Research Reactor	175
50-327	Sequoyah Nuclear Plant, Unit 1	175
50-328	Sequoyah Nuclear Plant, Unit 2	177
50-329	Midland Plant, Unit 1	179
50-330	Midland Plant, Unit 2	195
50-331	Duane Arnold Energy Center	211
50-333	James A Fitzpatrick Nuclear Power Plant	213
50-334	Beaver Valley Power Station, Unit 1	215
50-335	St Lucie Plant, Unit 1	217
50-336	Millstone Nuclear Power Station, Unit 2	219
50-338	North Anna Power Station, Unit 1	222
50-339	North Anna Power Station, Unit 2	225
50-341	Enrico Fermi Atomic Power Plant, Unit 2	227
50-344	Trojan Nuclear Plant	231
50-346	Davis-Besse Nuclear Power Station, Unit 1	234
50-348	Joseph M Farley Nuclear Plant, Unit 1	237
50-352	Limerick Generating Station, Unit 1	238
50-353	Limerick Generating Station, Unit 2	246
50-354	Hope Creek Nuclear Station, Unit 1	253
50-355	Hope Creek Nuclear Station, Unit 2	258
50-356	Univ of Illinois Research Reactor	258
50-358	William H Zimmer Nuclear Station, Unit 1	259
50-361	San Onofre Nuclear Station, Unit 2	260
50-362	San Onofre Nuclear Station, Unit 3	262
50-364	Joseph M Farley Nuclear Plant, Unit 2	265
50-366	Edwin I Hatch Nuclear Plant, Unit 2	266
50-367	Bailly Generating Station	269
50-368	Arkansas Nuclear One, Unit 2	269
50-369	William B McGuire Nuclear Station, Unit 1	272
50-370	William B. McGuire Nuclear Station, Unit 2	274
50-373	LaSalle County Station, Unit 1	276
50-374	LaSalle County Station, Unit 2	279

Docket	Name	Page
50-382	Waterford Generating Station, Unit 3	283
50-387	Susquehanna Steam Electric Station Unit 1	287
50-388	Susquehanna Steam Electric Station Unit 2	289
50-389	St Lucie Plant Unit 2	291
50-390	Watts Bar Nuclear Plant Unit 1	293
50-391	Watts Bar Nuclear Plant, Unit 2	295
50-395	Virgil C Summer Nuclear Station Unit 1	297
50-396	Univ of Virginia Cavalier Reactor	299
50-397	WPPSS Nuclear Project Unit 2	299
50-400	Shearon Harris Nuclear Power Plant Unit 1	302
50-401	Shearon Harris Nuclear Power Plant, Unit 2	306
50-409	La Crosse Boiling Water Reactor	308
50-410	Nine Mile Point Nuclear Station, Unit 2	310
50-412	Beaver Valley Power Station, Unit 2	312
50-413	Catawba Nuclear Station, Unit 1	314
50-414	Catawba Nuclear Station, Unit 2	320
50-416	Grand Gulf Nuclear Station, Unit 1	324
50-417	Grand Gulf Nuclear Station, Unit 2	329
50-423	Millstone Nuclear Power Station, Unit 3	332
50-424	Vogtle Electric Generating Plant	333
50-425	Vogtle Electric Generating Plant	336
50-433	UC-Santa Barbara Research Reactor	338
STN-50-437	Floating Nuclear Plant	339
50-438	Bellefonte Nuclear Plant, Unit 1	339
50-439	Bellefonte Nuclear Plant, Unit 2	341
50-440	Perry Nuclear Power Plant, Unit 1	343
50-441	Perry Nuclear Power Plant, Unit 2	346
50-443	Seabrook Nuclear Station, Unit 1	349
50-444	Seabrook Nuclear Station, Unit 2	350
50-445	Comanche Peak Steam Electric Station, Unit 1	352
50-446	Comanche Peak Steam Electric Station, Unit 2	361
STN-50-447	GESSAR-238	369
STN-50-454	Byron Station, Unit 1	370
STN-50-455	Byron Station, Unit 2	376
STN-50-456	Braidwood Station Unit 1	381
STN-50-457	Braidwood Station Unit 2	384
50-458	River Bend Station Unit 1	388
50-459	River Bend Station Unit 2	392
50-460	WPPSS Nuclear Project Unit 1	393
50-461	Clinton Power Station Unit 1	394
50-462	Clinton Power Station Unit 2	396
STN-50-470	CESSAR System 80	396
STN-50-482	Wolf Creek Generating Station	397
STN-50-483	Callaway Plant, Unit 1	400
STN-50-491	Cherokee Nuclear Station Unit 1	403
STN-50-492	Cherokee Nuclear Station Unit 2	403
STN-50-493	Cherokee Nuclear Station Unit 3	403
50-496	Montague Nuclear Power Station Unit 1	403
50-497	Montague Nuclear Power Station Unit 2	403
STN-50-498	South Texas Project Unit 1	404
STN-50-499	South Texas Project Unit 2	406
STN-50-508	WPPSS Nuclear Project Unit 3	407
STN-50-509	WPPSS Nuclear Project, Unit 5	408
STN-50-518	Hartsville Nuclear Plant, Unit 1	408
STN-50-520	Hartsville Nuclear Plant, Unit 3	408
50-522	Skagit Nuclear Power Project Unit 1	408
50-523	Skagit Nuclear Power Project, Unit 2	409
STN-50-528	Palo Verde Nuclear Station Unit 1	409
STN-50-529	Palo Verde Nuclear Station Unit 2	414
STN-50-530	Palo Verde Nuclear Station, Unit 3	418
50-538	Memphis State Univ Research Reactor	422
STN-50-546	Marble Hill Nuclear Station Unit 1	422
STN-50-547	Marble Hill Nuclear Station Unit 2	423
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	423
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	423
50-601	RESAR SP/90	423

Domestic Licensing of Special Nuclear Material — Docket 70

70-0008	Battelle Memorial Institute, Columbus, OH	424

Docket	Name	Page
70-0025	Rockwell International Corp Canoga Park, CA	424
70-0027	Babcock & Wilcox Co , Lynchburg, VA	424
70-0036	Combustion Engineering Inc Windsor CT	425
70-0143	Nuclear Fuel Services, Inc Erwin, TN	425
70-0221	General Dynamics Corp , Groton, CT	427
70-0303	Carnegie-Mellon Univ Pittsburgh, PA	427
70-0364	Babcock & Wilcox Co Apollo PA	427
70-0371	UNC Naval Products, Inc , Uncasville, CT	427
70-0398	Commerce, Dept of, Washington, DC	427
70-0466	Maine Maritime Academy, Castine, ME	427
70-0687	Union Carbide Corp , Tuxedo, NY	428
70-0734	GA Technologies, Inc , San Diego, CA	428
70-0820	United Nuclear Corp , Wood River Junction, RI	428
70-0824	Babcock & Wilcox Co , Lynchburg, VA	428
70-0925	Kerr-McGee Nuclear Corp , Oklahoma City, OK	428
70-0938	Massachusetts Institute of Technology, Cambridge MA	428
70-0984	Battelle Memorial Institute, Richland, WA	429
70-1068	Florida, Univ of, Gainesville, FL	429
70-1113	General Electric Co , Wilmington, NC	429
70-1143	Westinghouse Electric Corp , Pittsburgh, PA	429
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	429
70-1193	Kerr-McGee Nuclear Corp., Oklahoma City, OK	430
70-1201	Babcock & Wilcox Co., Lynchburg, VA	430
70-1257	Exxon Nuclear Co , Inc , Richland, WA	430
70-1308	General Electric Co , San Jose, CA	430
70-1342	Coratomic, Inc., Indiana, PA	430
70-1362	Hahnemann Medical College & Hospital, Philadelphia, PA	430
70-1450	Berkshire Medical Center, Pittsfield, MA	431
70-1941	Passaic General Hospital, Passaic, NJ	431
70-2377	Dentsply International, Inc , York, PA	431
70-2571	Yale-New Haven Hospital, New Haven, CT	431
70-2838	Cincinnati Gas & Electric Co , Cincinnati, OH	431
70-2872	RS Holding Inc Cleveland OH	431
70-2881	Long Island Lighting Co Hicksville NY	431
70-2988	Philadelphia Electric Co , Philadelphia, PA	431
70-2998	Gulf States Utilities Co Beaumont TX	431

Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71

71-0008	Commonwealth Edison Co	431
71-0011	Arrow Tank & Engineering Co	431
71-0014	Adirondack Steel Casting Co	431
71-0015	Chicago Bridge & Iron Co	432
71-0016	Northwest Airlines, Inc	432
71-0020	International Testing Laboratories	432
71-0022	Newport News Industrial Corp	432
71-0028	Borg-Warner Corp	432
71-0032	Panhandle Eastern Pipe Line Co	432
71-0033	Industrial Testing Laboratory Services Corp	432
71-0034	Babcock & Wilcox Co	432
71-0036	ITT Grinnell Corp	432
71-0037	Navy, Dept of	432
71-0038	Crane Co	432
71-0039	Walworth Co	432
71-0044	United Airlines, Inc	432
71-0047	Capitol International Airways, Inc	432
71-0051	Harrison Steel Castings Co	432
71-0055	H R. Inspection Service	433
71-0056	Philadelphia Electric Co.	433
71-0057	Exxon Co , USA	433
71-0059	General Electric Co.	433
71-0061	Navy, Dept of	433
71-0063	Ozark Airlines, Inc	433
71-0066	Certified Testing Laboratories, Inc	433
71-0068	Yankee Atomic Electric Co	433
71-0070	Gamma Field Radiographic Facility	433
71-0074	Nuclear Welding, Inc.	433
71-0075	Norfolk Shipbuilding & Dry Dock Co	433

Docket	Name	Page
71-0077	Midstate Testing Laboratory	433
71-0080	Transworld Airlines, Inc	433
71-0081	ITT Grinnell Industrial Piping Inc	433
71-0083	Northern States Power Co	433
71-0087	Navy Dept of	434
71-0089	Navy Dept of	434
71-0093	Huntington Testing	434
71-0095	United States Testing Co Inc	434
71-0099	Foster Wheeler Energy Corp	434
71-0100	Venegas Industrial Testing Laboratories	434
71-0103	Twin City Testing & Engineering Laboratory Inc	434
71-0104	Chicago Bridge & Iron Co	434
71-0105	Universal Testing Laboratories	434
71-0110	Buckeye Steel Castings	434
71-0111	Material Testing Laboratory of Virginia, Inc	434
71-0113	Nooter Corp	434
71-0119	Ingersoll-Rand Co	434
71-0120	Daniel International Corp	434
71-0123	Herron Testing Laboratories, Inc	434
71-0124	Houston Inspection Laboratories, Inc	434
71-0125	Testco, Inc	435
71-0127	National Annealing Box Co	435
71-0128	Amoco Oil Co	435
71-0130	Chicago Bridge & Iron Co	435
71-0132	Advanced Radiation Service	435
71-0133	Navy, Dept of	435
71-0134	Labarge, Inc	435
71-0137	Metals Testing Co , Inc	435
71-0140	Walworth Co	435
71-0145	Thayer Inspection Service, Inc	435
71-0148	United Engineers & Constructors, Inc.	435
71-0151	Hess Oil Virgin Islands Corp.	435
71-0152	Virginia Commonwealth of	435
71-0154	General Dynamics Corp	435
71-0156	Industrial Fabricating Co	435
71-0157	Froehling & Robertson Inc	435
71-0158	X-Ray Industries Inc	436
71-0161	Curtiss-Wright Corp	436
71-0162	Ebasco Services Inc	436
71-0166	New York Testing Laboratories Inc	436
71-0167	Finlay Testing Laboratories	436
71-0168	Quality Assurance Laboratories	436
71-0169	Florida Power & Light Co	436
71-0171	Industrial Inspection Industries	436
71-0172	Empire Steel Castings, Inc	436
71-0174	Southern California Edison Co	436
71-0175	QC Services, Inc.	436
71-0181	Consolidated X-Ray Service Corp.	436
71-0183	Gamma Sonics Examination Laboratories, Inc	436
71-0184	Pullman Power Products	436
71-0186	High Steel Structures, Inc	436
71-0188	Maynard Steel Casting Co	436
71-0195	Toledo Edison Co	437
71-0202	Pacific Gas & Electric Co	437
71-0205	Quality Testing, Inc	437
71-0207	Connecticut Yankee Atomic Power Co	437
71-0208	Northeast Nuclear Energy Co	437
71-0211	Boston Edison Co.	437
71-0212	General Electric Co	437
71-0213	Intermountain Testing Co	437
71-0214	Gas Rentals, Inc	437
71-0215	Space Science Services Inc	437
71-0216	Nuclear Energy Services Inc	437
71-0217	Pullman, Inc	437
71-0218	Cumberland Bridge Co	437
71-0219	Terex Corp	437
71-0220	General Dynamics Corp	437
71-0221	Allis-Chalmers Corp	437

Docket	Name	Page
71-0222	St Louis Testing Laboratories Inc	437
71-0223	Benjamin F Shaw Co	438
71-0224	Guyon Power & Process Piping	438
71-0225	Navy Dept of	438
71-0229	Word Industries Pipe Fabricating Inc	438
71-0232	Lakehead Testing Laboratories Inc	438
71-0233	O Neill Tank Co Inc	438
71-0234	X-Ray Inc	438
71-0237	Columbia Gas Transmission Corp	438
71-0240	Power Authority of State of New York	438
71-0242	Law Engineering Testing Co	438
71-0245	Navy Dept of	438
71-0247	IRT Corp	438
71-0253	Twin Ports Testing Inc	438
71-0254	General Electric Co	438
71-0256	Omaha Public Power District	438
71-0257	Industrial Laboratories Inc	438
71-0261	Navy Dept of	439
71-0268	Navy Dept of	439
71-0269	Lehigh Testing Laboratories Inc	439
71-0270	Factory Mutual Engineering Corp	439
71-0272	Crane Co	439
71-0274	Navy Dept of	439
71-0275	Duquesne Light Co	439
71-0276	Navy Dept of	439
71-0279	Universal Testing, Inc	439
71-0280	ABCO Perforators Inc	439
71-0281	Delta Airlines, Inc	439
71-0282	WKM Wellhead Systems, Inc	439
71-0283	McManus Inspection Service	439
71-0284	Ultrasonic Specialists, Inc	439
71-0285	Belt Geophysics	439
71-0286	BPB Instruments Inc	439
71-0287	Carson Non-Destructive Testing	439
71-0288	North Dakota, State of	439
71-0289	Terradata Geophysical, Inc	440
71-0290	United Testing Services, Inc	440
71-0291	DJ Inspection Services, Inc	440
71-0292	Industrial Gamma Inspection	440
71-0293	Brand X Perforators, Inc	440
71-0294	Applied Engineering Co	440
71-0295	Acurex Corp	440
71-0296	Iowa Electric Light & Power Co	440
71-0297	E Lewis Cook & Associates	440
71-0298	Steel Tank Construction Co	440
71-0299	Quality Control Services	440
71-0300	Independent Testing Laboratories	440
71-0301	CTL Engineering, Inc	440
71-0302	Associated Piping & Engineering Corp	440
71-0303	Memphis Testing Services, Inc	440
71-0304	Teledyne Brown Engineering, Co	440
71-0305	American X-Ray & Inspection, Inc	440
71-0306	Snyder Drilling & Well Servicing	441
71-0307	Texas Pipe Bending Co. of Puerto Rico	441
71-0310	Bucyrus-Erie Co	441
71-0311	Logwell, Inc	441
71-0312	Metalforms, Inc	441
71-0313	Precision Inspection, Ltd	441
71-0314	Smith-Emery Co.	441
71-0317	Hudson Products Corp.	441
71-0318	Marathon Oil Co	441
71-0319	General Testing & Inspection Co	441
71-0320	Pittsburgh-Des Moines Steel Co	441
71-0322	Babcock & Wilcox Co	441
71-0325	Consumers Power Co.	441
71-0326	Industrial NDT Services Division	441
71-0327	Portland General Electric Co.	441
71-0328	Public Service Electric & Gas Co	441
71-0329	Howmet Turbine Components Corp	441
71-0330	Allied Inspection Services, Inc.	442

Docket	Name	Page
71-0522	California Univ of Los Angeles, CA	442
71-5805	Model CNS 3-55 Chem-Nuclear Systems, Inc	442
71-5926	Model GE-100, General Electric Co	442
71-6244	Model 6244, Chem-Nuclear Systems, Inc	442
71-6346	Model FSV-1, GA Technologies, Inc	442
71-6581	Model 51032-1 & 1A Exxon Nuclear Co , Inc	442
71-6717	Model 6717-B, Gamma Industries	442
71-9001	Model IF-300, General Electric Co	442
71-9016	Model TN-9, No Users	442
71-9021	Model 750, Technical Operations, Inc	443
71-9073	Model OH-142 Series & NUS 10-135, Nuclear Packaging, Inc	443
71-9092	Model HN-300, Hittman Nuclear & Development Corp	443
71-9093	Model HN-400, Hittman Nuclear & Development Corp	443
71-9111	Model CNS 6-80-2 & CNS 6-80-2A, Chem-Nuclear Systems Inc	443
71-9126	Model 20 20A, 50 50A Gamma Industries	443
71-9143	Model 920, Technical Operations Inc	443
71-9147	Model 850 Technical Operations Inc	443
71-9151	Model HN-100 Series 3 CNS 14-170 Series III & NUS	443
71-9163	Model GNG-20 Gulf Nuclear, Inc	443
71-9184	Model PAS-1, Nuclear Packaging, Inc	443
71-9186	Model S-6213, Energy, Dept of	443
71-9188	Model AP-300, ANEFCO, Inc	444
71-9192	Model AP-300, ANEFCO, Inc	444
71-9193	Model NES-5, Nuclear Energy Services Inc	444

Licensing of Independent Spent Fuel Storage — Docket 72

Docket	Name	Page
72-0001	Morris Operations, General Electric Co	444
72-0002	Virginia Electric & Power Co	444

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 27		
Richland, WA, U S Ecology, Inc	27-048	1
Sheffield, IL, U S Ecology, Inc	27-039	1
Domestic Licensing of Source Material — Docket 40		
Allied Chemical Corp , Morristown, NJ	40-3392	4
Atlas Minerals, Inc , Denver, CO	40-3453	4
Bear Creek Uranium Co , Casper, WY	40-8452	6
Brush Wellman, Inc , Cleveland, OH	40-8722	8
Chemetron Corp , Chicago, IL	40-8724	8
Energy Fuels Nuclear, Inc , Denver, CO	40-8675	7
Energy Fuels Nuclear, Inc , Denver, CO	40-8681	7
Energy, Dept of, Canonsburg, PA	40-6500	4
Everest Minerals Corp., Converse County, WY	40-8857	9
Exxon Co., USA, Billings, MT	40-8769	9
Exxon Co , USA, Houston, TX	40-8102	5
Exxon Minerals Co., USA, Houston, TX	40-8064	5
Federal-American Partners, Riverton, WY	40-4492	4
Getty Oil Co.-Petrotomics Co , Shirley Basin, WY	40-6659	5
Homestake Mining Co , Lakewood, CO	40-8434	6
Kaweckı Berylco Industries Inc., Boyertown, PA	40-6940	5
Kerr-McGee Chemical Corp , Oklahoma City, OK	40-2061	2
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	5
Kerr-McGee Nuclear Corp , Oklahoma City, OK	40-8586	7
Kerr-McGee Nuclear Corp , Oklahoma City, OK	40-8727	8
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	8
Maine Maritime Academy, Castine, ME	40-6499	4
Minerals Exploration Co Los Angeles CA	40-8584	7
Minnesota Univ of Minneapolis MN	40-8842	9
Nuclear Metals Inc Concord MA	40-0672	2
Ogle Petroleum Inc Casper WY	40-8745	8
Omaha Public Power District, Omaha NE	40-8822	9
Pathfinder Mines Corp Riverton WY	40-2259	3
Pathfinder Mines Corp Shirley Basin WY	40-6622	4
Plateau Resources Ltd Grand Junction CO	40-7869	5
Plateau Resources Ltd Grand Junction CO	40-8674	7
Plateau Resources Ltd Grand Junction CO	40-8698	8
Rio Algom Corp Moab UT	40-8084	5
Rocky Mountain Energy Co Broomfield CO	40-8380	6
Rocky Mountain Energy Co Denver CO	40-8697	8
Silver King Mines Inc Casper WY	40-8602	7
Tennessee Valley Authority Chattanooga TN	40-1311	2
Teton Exploration Drilling Co Inc Casper, WY	40-8728	8
Union Carbide Corp Grand Junction, CO	40-0299	1
United Technologies Corp East Hartford CT	40-0791	2
Uranerz USA Inc. Casper WY	40-8783	9
Uranium Resources, Inc Richardson TX	40-8786	9
Western Nuclear Inc , Jeffrey City, WY	40-1162	2
Western Nuclear Inc , Lakewood CO	40-8684	8
Whittaker Metals, Los Angeles CA	40-7455	5
Wyoming Fuel Co Lakewood CO	40-8829	9
Wyoming Mineral Corp Lakewood, CO	40-8502	6
Wyoming Mineral Corp , Lakewood, CO	40-8585	7
Domestic Licensing of Production Docket 50		
Arkansas Nuclear One, Unit 1		

Name	Docket	Page
Arkansas Nuclear One Unit 2	50-368	269
Babcock & Wilcox Co Critical Facility	50-13	12
Bailly Generating Station	50-367	269
Beaver Valley Power Station Unit 1	50-334	215
Beaver Valley Power Station Unit 2	50-412	312
Bellefonte Nuclear Plant, Unit 1	50-438	339
Bellefonte Nuclear Plant, Unit 2	50-439	341
Big Rock Point Nuclear Plant	50-155	18
Braidwood Station Unit 1	STN-50-456	381
Braidwood Station Unit 2	STN-50-457	384
Brigham Young Univ Research Reactor	50-262	68
Browns Ferry Nuclear Power Station Unit 1	50-259	57
Browns Ferry Nuclear Power Station, Unit 2	50-260	61
Browns Ferry Nuclear Power Station, Unit 3	50-296	119
Brunswick Steam Electric Plant Unit 1	50-325	173
Brunswick Steam Electric Plant Unit 2	50-324	171
Byron Station Unit 1	STN-50-454	370
Byron Station Unit 2	STN-50-455	376
Callaway Plant, Unit 1	STN-50-483	400
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	148
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	151
Catawba Nuclear Station Unit 1	50-413	314
Catawba Nuclear Station, Unit 2	50-414	320
CESSAR System 80	STN-50-470	396
Cherokee Nuclear Station Unit 1	STN-50-491	403
Cherokee Nuclear Station, Unit 2	STN-50-492	403
Cherokee Nuclear Station, Unit 3	STN-50-493	403
Clinton Power Station, Unit 1	50-461	394
Clinton Power Station, Unit 2	50-462	396
Comanche Peak Steam Electric Station Unit 1	50-445	352
Comanche Peak Steam Electric Station Unit 2	50-446	361
Cooper Nuclear Station	50-298	122
Cornell Univ Research Reactor	50-157	21
Cornell Univ Zero Power Reactor	50-97	16
Crystal River Nuclear Plant Unit 3	50-302	127
Davis-Besse Nuclear Power Station Unit 1	50-346	234
Diablo Canyon Nuclear Power Plant Unit 1	50-275	85
Diablo Canyon Nuclear Power Plant Unit 2	50-323	167
Donald C Cook Nuclear Power Plant Unit 1	50-315	144
Donald C Cook Nuclear Power Plant Unit 2	50-316	146
Dow Chemical Co	50-264	70
Dresden Nuclear Power Station Unit 1	50-10	10
Dresden Nuclear Power Station Unit 2	50-237	33
Dresden Nuclear Power Station Unit 3	50-249	44
Duane Arnold Energy Center	50-331	211
Edwin I Hatch Nuclear Plant, Unit 1	50-321	156
Edwin I Hatch Nuclear Plant Unit 2	50-366	266
Enrico Fermi Atomic Power Plant Unit 2	50-341	227
Floating Nuclear Plant	STN-50-437	339
Fort Calhoun Station Unit 1	50-285	100
Fort St Vrain Nuclear Generating Station	50-267	74
GA Technologies	50-163	21
General Atomic Co	50-89	15
General Electric Nuclear Test Reactor	50-73	15
General Electric Test Reactor	50-70	15
Georgia Institute of Technology Research Reactor	50-160	21
Georgia Tech Research Reactor	50-276	90
GESSAR-238	STN-50-447	369
Grand Gulf Nuclear Station Unit 1	50-416	324
Grand Gulf Nuclear Station Unit 2	50-417	329
H B Robinson Plant, Unit 2	50-261	65
Haddam Neck Plant	50-213	26
Hartsville Nuclear Plant, Unit 1	STN-50-518	408
Hartsville Nuclear Plant, Unit 3	STN-50-520	408
Hope Creek Nuclear Station Unit 1	50-354	253
Hope Creek Nuclear Station Unit 2	50-355	258
Humboldt Bay Power Plant, Unit 3	50-133	16
Idaho State Univ. Research Reactor	50-284	100

Name	Docket	Page
Indian Point Station Unit 1	50-3	9
Indian Point Station Unit 2	50-247	41
Indian Point Station Unit 3	50-286	101
Iowa State Univ Research Reactor	50-116	16
James A Fitzpatrick Nuclear Power Plant	50-333	213
Joseph M Farley Nuclear Plant Unit 1	50-348	237
Joseph M Farley Nuclear Plant Unit 2	50-364	265
Kansas State Univ Research Reactor	50-188	22
Kewaunee Nuclear Power Plant	50-305	132
La Crosse Boiling Water Reactor	50-409	308
LaSalle County Station Unit 1	50-373	276
LaSalle County Station Unit 2	50-374	279
Limerick Generating Station Unit 1	50-352	238
Limerick Generating Station Unit 2	50-353	246
Maine Yankee Atomic Power Plant	50-309	135
Manhattan College Research Reactor	50-199	23
Marble Hill Nuclear Station Unit 1	STN-50-546	422
Marble Hill Nuclear Station Unit 2	STN-50-547	423
Memphis State Univ Research Reactor	50-538	422
Michigan State Univ Research Reactor	50-294	115
Midland Plant Unit 1	50-329	179
Midland Plant Unit 2	50-330	195
Millstone Nuclear Power Station Unit 1	50-245	38
Millstone Nuclear Power Station Unit 2	50-336	219
Millstone Nuclear Power Station Unit 3	50-423	332
Montague Nuclear Power Station Unit 1	50-496	403
Montague Nuclear Power Station Unit 2	50-497	403
Monticello Nuclear Generating Plant	50-263	68
National Bureau of Standards Reactor	50-184	22
National Naval Medical Center	50-170	22
Nine Mile Point Nuclear Station, Unit 1	50-220	31
Nine Mile Point Nuclear Station Unit 2	50-410	310
North Anna Power Station Unit 1	50-338	222
North Anna Power Station Unit 2	50-339	225
North Carolina State Univ PULSTAR Reactor	50-297	122
Oconee Nuclear Station Unit 1	50-269	76
Oconee Nuclear Station Unit 2	50-270	79
Oconee Nuclear Station Unit 3	50-287	103
Ohio State Univ Research Reactor	50-150	17
Oyster Creek Nuclear Power Plant	50-219	28
Palisades Nuclear Plant	50-255	54
Palo Verde Nuclear Station Unit 1	STN-50-528	409
Palo Verde Nuclear Station Unit 2	STN-50-529	414
Palo Verde Nuclear Station Unit 3	STN-50-530	418
Peach Bottom Atomic Power Station Unit 1	50-171	22
Peach Bottom Atomic Power Station Unit 2	50-277	90
Peach Bottom Atomic Power Station Unit 3	50-278	92
Pennsylvania State Univ Research Reactor	50-5	10
Perry Nuclear Power Plant Unit 1	50-440	343
Perry Nuclear Power Plant Unit 2	50-441	346
Pilgrim Nuclear Power Station Unit 1	50-293	112
Plum Brook Reactor—Mock-Up	50-185	22
Plum Brook Research Reactor Facility	50-30	14
Point Beach Nuclear Plant Unit 1	50-266	72
Point Beach Nuclear Plant Unit 2	50-301	124
Prairie Island Nuclear Station Unit 1	50-282	98
Prairie Island Nuclear Station Unit 2	50-306	134
Purdue Univ Research Reactor	50-182	22
Quad-Cities Station Unit 1	50-254	52
Quad-Cities Station Unit 2	50-265	70
Rancho Seco Nuclear Generating Station	50-312	139
RLSAR SP 90	50-601	423
Rhode Island & Providence Plantations AEC	50-193	22
River Bend Station, Unit 1	50-458	388
River Bend Station Unit 2	50-459	392
Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	36
RPI Critical Experiment	50-225	33
Salem Nuclear Generating Station, Unit 1	50-272	83
Salem Nuclear Generating Station, Unit 2	50-311	137
San Onofre Nuclear Station Unit 1	50-206	23

Name	Docket	Page
San Onofre Nuclear Station Unit 2	50-361	260
San Onofre Nuclear Station Unit 3	50-362	262
Seabrook Nuclear Station Unit 1	50-443	349
Seabrook Nuclear Station Unit 2	50-444	350
Sequoyah Nuclear Plant Unit 1	50-327	175
Sequoyah Nuclear Plant Unit 2	50-328	177
Shearon Harris Nuclear Power Plant Unit 1	50-400	302
Shearon Harris Nuclear Power Plant Unit 2	50-401	306
Shoreham Nuclear Power Station	50-322	159
Skagit Nuclear Power Project Unit 1	50-522	408
Skagit Nuclear Power Project Unit 2	50-523	409
South Texas Project Unit 1	STN-50-498	404
South Texas Project Unit 2	STN-50-499	406
St Lucie Plant, Unit 1	50-335	217
St Lucie Plant, Unit 2	50-389	291
State Univ of New York Research Reactor	50-57	15
Surry Power Station Unit 1	50-280	94
Surry Power Station Unit 2	50-281	97
Susquehanna Steam Electric Station, Unit 1	50-387	287
Susquehanna Steam Electric Station, Unit 2	50-388	289
Texas A&M Univ Research Reactor	50-59	15
Three Mile Island Nuclear Station Unit 1	50-289	106
Three Mile Island Nuclear Station Unit 2	50-320	153
Trojan Nuclear Plant	50-344	231
Turkey Point Plant, Unit 3	50-250	46
Turkey Point Plant, Unit 4	50-251	49
U S Geological Survey Research Reactor	50-274	85
UC-Santa Barbara Research Reactor	50-433	338
UCLA Training Reactor	50-142	17
Union Carbide Research Reactor	50-54	15
Univ of California at Irvine Research Reactor	50-326	175
Univ of Illinois Research Reactor	50-356	258
Univ of Illinois Research Reactor	50-151	17
Univ of Lowell Research Reactor	50-223	33
Univ of Maryland Research Reactor	50-166	21
Univ of Michigan Research Reactor	50-2	9
Univ of Missouri Research Reactor	50-186	22
Univ of Missouri Research Reactor	50-123	16
Univ of New Mexico Research Reactor	50-252	52
Univ of Oklahoma Research Reactor	50-112	16
Univ of Texas Research Reactor	50-192	22
Univ of Virginia Cavalier Reactor	50-396	299
Univ of Virginia Research Reactor	50-62	15
Univ of Washington Research Reactor	50-139	17
Univ of Wisconsin Research Reactor	50-156	20
Vermont Yankee Nuclear Power Station	50-271	81
Virgil C Summer Nuclear Station Unit 1	50-395	297
Vogtle Electric Generating Plant	50-424	333
Vogtle Electric Generating Plant	50-425	336
Washington State Univ Research Reactor	50-27	12
Waterford Generating Station Unit 3	50-382	283
Watts Bar Nuclear Plant Unit 1	50-390	293
Watts Bar Nuclear Plant Unit 2	50-391	295
William B McGuire Nuclear Station Unit 1	50-369	272
William B McGuire Nuclear Station Unit 2	50-370	274
William H Zimmer Nuclear Station, Unit 1	50-358	259
Wolf Creek Generating Station	STN-50-482	397
Worcester Polytechnic Research Reactor	50-134	17
WPPSS Nuclear Project, Unit 1	50-460	393
WPPSS Nuclear Project Unit 2	50-397	299
WPPSS Nuclear Project, Unit 3	STN-50-508	407
WPPSS Nuclear Project, Unit 5	STN-50-509	408
Yankee-Rowe Nuclear Power Station	50-29	12
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	423
Yellow Creek Nuclear Plant Unit 2	STN-50-567	423
Zion Nuclear Power Station, Unit 1	50-295	115
Zion Nuclear Power Station, Unit 2	50-304	129
Domestic Licensing of Special Nuclear Material — Docket 70		
Babcock & Wilcox Co , Apollo, PA	70-0364	427
Babcock & Wilcox Co., Lynchburg, VA	70-0824	428

Name	Docket	Page
Babcock & Wilcox Co Lynchburg, VA	70-1201	430
Babcock & Wilcox Co , Lynchburg VA	70-0027	424
Battelle Memorial Institute, Columbus OH	70-0008	424
Battelle Memorial Institute, Richland WA	70-0984	429
Berkshire Medical Center, Pittsfield MA	70-1450	431
Carnegie-Mellon Univ , Pittsburgh, PA	70-0303	427
Cincinnati Gas & Electric Co , Cincinnati, OH	70-2838	431
Combustion Engineering, Inc., Windsor CT	70-0036	425
Commerce, Dept of, Washington, DC	70-0398	427
Coratomic, Inc , Indiana, PA	70-1342	430
Dentsply International, Inc York, PA	70-2377	431
Exxon Nuclear Co , Inc , Richland WA	70-1257	430
Florida, Univ of, Gainesville, FL	70-1068	429
GA Technologies, Inc , San Diego, CA	70-0734	428
General Dynamics Corp , Groton, CT	70-0221	427
General Electric Co , San Jose, CA	70-1308	430
General Electric Co Wilmington, NC	70-1113	429
Gulf States Utilities Co , Beaumont, TX	70-2998	431
Hahnemann Medical College & Hospital, Philadelphia, PA	70-1362	430
Kerr-McGee Nuclear Corp , Oklahoma City, OK	70-0925	428
Kerr-McGee Nuclear Corp , Oklahoma City, OK	70-1193	430
Long Island Lighting Co , Hicksville, NY	70-2884	431
Maine Maritime Academy, Castine, ME	70-0466	427
Massachusetts Institute of Technology, Cambridge, MA	70-0938	428
Nuclear Fuel Services, Inc , Erwin, TN	70-0143	425
Passaic General Hospital, Passaic, NJ	70-1941	431
Philadelphia Electric Co , Philadelphia, PA	70-2988	431
Rockwell International Corp., Canoga Park, CA	70-0025	424
RS Holding, Inc , Cleveland, OH	70-2872	431
UNC Naval Products, Inc , Uncasville, CT	70-0371	427
Union Carbide Corp , Tuxedo, NY	70-0687	428
United Nuclear Corp , Wood River Junction, RI	70-0820	428
Westinghouse Electric Corp Pittsburgh PA	70-1143	429
Westinghouse Electric Corp Pittsburgh PA	70-1151	429
Yale-New Haven Hospital New Haven CT	70-2571	431
ABCO Perforators Inc	71-0280	439
Acurex Corp	71-0295	440
Adirondack Steel Casting Co	71-0014	431
Advanced Radiation Service	71-0132	435
Allied Inspection Services Inc	71-0330	442
Allis-Chalmers Corp	71-0221	437
American X-Ray & Inspection Inc	71-0305	440
Amoco Oil Co	71-0128	435
Applied Engineering Co	71-0294	440
Arrow Tank & Engineering Co	71-0011	431
Associated Piping & Engineering Corp	71-0302	440
Babcock & Wilcox Co	71-0034	432
Babcock & Wilcox Co	71-0322	441
Bell Geophysics	71-0285	439
Benjamin F Shaw Co	71-0223	438
Borg-Warner Corp	71-0028	432
Boston Edison Co.	71-0211	437
BPB Instruments, Inc	71-0286	439
Brand X Perforators, Inc	71-0293	440
Buckeye Steel Castings	71-0110	434
Bucyrus-Erie Co	71-0310	441
California, Univ. of, Los Angeles, CA	71-0522	442
Capitol International Airways, Inc	71-0047	432
Carson Non-Destructive Testing	71-0287	439
Certified Testing Laboratories	71-0066	433
Chicago Bridge & Iron Co	71-0015	432
Chicago Bridge & Iron Co	71-0104	434
Chicago Bridge & Iron Co	71-0130	435
Columbia Gas Transmission Corp	71-0237	438
Commonwealth Edison Co	71-0008	431
Connecticut Yankee Atomic Power Co	71-0207	437
Consolidated X-Ray Service Corp	71-0181	436

Name	Docket	Page
Consumers Power Co	71-0325	441
Crane Co	71-0038	432
Crane Co	71-0272	439
CTL Engineering Inc	71-0301	440
Cumberland Bridge Co	71-0218	437
Curtiss-Wright Corp	71-0161	436
Daniel International Corp	71-0120	434
Delta Airlines Inc	71-0281	439
DJ Inspection Services Inc	71-0291	440
Duquesne Light Co	71-0275	439
E Lewis Cook & Associates	71-0297	440
Ebasco Services Inc	71-0162	436
Empire Steel Castings, Inc	71-0172	436
Exxon Co USA	71-0057	433
Factory Mutual Engineering Corp	71-0270	439
Finlay Testing Laboratories	71-0167	436
Florida Power & Light Co	71-0169	436
Foster Wheeler Energy Corp	71-0099	434
Froehling & Robertson, Inc	71-0157	435
Gamma Field Radiographic Facility	71-0070	433
Gamma Somes Examination Laboratories, Inc	71-0183	436
Gas Rentals, Inc	71-0214	437
General Dynamics Corp	71-0154	435
General Dynamics Corp	71-0220	437
General Electric Co.	71-0059	433
General Electric Co	71-0212	437
General Electric Co	71-0254	438
General Testing & Inspection Co.	71-0319	441
Guyon Power & Process Piping	71-0224	438
H R Inspection Service	71-0055	433
Harrison Steel Castings Co	71-0051	432
Herron Testing Laboratories, Inc	71-0123	434
Hess Oil Virgin Islands Corp	71-0151	435
High Steel Structures, Inc	71-0186	436
Houston Inspection Laboratories, Inc.	71-0124	434
Howmet Turbine Components Corp	71-0329	441
Hudson Products Corp	71-0317	441
Huntington Testing	71-0093	434
Industrial Testing Laboratories Services Corp	71-0033	432
Independent Testing Laboratories	71-0300	440
Industrial Fabricating Co	71-0156	435
Industrial Gamma Inspection	71-0292	440
Industrial Inspection Industries	71-0171	436
Industrial Laboratories, Inc.	71-0257	438
Industrial NDT Services Division	71-0326	441
Ingersoll-Rand Co	71-0119	434
Intermountain Testing Co.	71-0213	437
International Testing Laboratories	71-0020	432
Iowa Electric Light & Power Co	71-0296	440
IRT Corp	71-0247	438
ITT Grinnell Corp	71-0036	432
ITT Grinnell Industrial Piping, Inc	71-0081	433
Labarge, Inc.	71-0134	435
Lakehead Testing Laboratories, Inc	71-0232	438
Law Engineering Testing Co	71-0242	438
Lehigh Testing Laboratories, Inc.	71-0269	439
Logwell, Inc.	71-0311	441
Marathon Oil Co.	71-0318	441
Material Testing Laboratories of Virginia, Inc.	71-0111	434
Maynard Steel Casting Co.	71-0188	436
McManus Inspection Service	71-0283	439
Memphis Testing Services, Inc.	71-0303	440
Metalforms, Inc.	71-0312	441
Metals Testing Co., Inc.	71-0137	435
Midstate Testing Laboratory	71-0077	433
Model. 20, 20A, 50, 50A, Gamma Industries	71-9126	443
Model 51032-1 & 1A, Exxon Nuclear Co., Inc.	71-6581	442
Model: 6244, Chem-Nuclear Systems, Inc.	71-6244	442
Model: 6717-B, Gamma Industries	71-6717	442

Name	Docket	Page
Model 750 Technical Operations, Inc	71-9021	443
Model 850, Technical Operations, Inc	71-9147	443
Model 920, Technical Operations, Inc	71-9143	443
Model AP-300, ANEFCO, Inc	71-9188	444
Model, AP-300, ANEFCO, Inc	71-9192	444
Model CNS 3-55, Chem-Nuclear Systems, Inc	71-5805	442
Model CNS 6-80-2 & CNS 6-80-2A, Chem-Nuclear Systems, Inc	71-9111	443
Model FSV-1, GA Technologies, Inc	71-6346	442
Model GE-100, General Electric Co	71-5926	442
Model GNG-20, Gulf Nuclear, Inc	71-9163	443
Model, HN-100 Series 3, CNS 14-170 Series III & NUS	71-9151	443
Model, HN-300, Hittman Nuclear & Development Corp	71-9092	443
Model HN-400, Hittman Nuclear & Development Corp	71-9093	443
Model IF-300, General Electric Co	71-9001	442
Model NES-5, Nuclear Energy Services, Inc	71-9193	444
Model, OH-142 Series & NUS 10-135, Nuclear Packaging, Inc.	71-9073	443
Model PAS-1, Nuclear Packaging, Inc	71-9184	443
Model S-6213, Energy, Dept. of	71-9186	443
Model TN-9, No Users	71-9016	442
National Annealing Box Co	71-0127	435
Navy Dept of	71-0087	434
Navy, Dept. of	71-0037	432
Navy, Dept of	71-0089	434
Navy Dept of	71-0061	433
Navy, Dept of	71-0261	439
Navy, Dept of	71-0245	438
Navy, Dept. of	71-0133	435
Navy, Dept of	71-0274	439
Navy, Dept of	71-0268	439
Navy, Dept. of	71-0276	439
Navy, Dept. of	71-0225	438
New York Testing Laboratories, Inc	71-0166	436
Newport News Industrial Corp	71-0022	432
Nooter Corp	71-0113	434
Norfolk Shipbuilding & Dry Dock Co	71-0075	433
North Dakota, State of	71-0288	439
Northeast Nuclear Energy Co	71-0208	437
Northern States Power Co	71-0083	433
Northwest Airlines, Inc	71-0016	432
Nuclear Energy Services Inc	71-0216	437
Nuclear Welding, Inc	71-0074	433
O'Neill Tank Co , Inc	71-0233	438
Omaha Public Power District	71-0256	438
Ozark Airlines, Inc	71-0063	433
Pacific Gas & Electric Co	71-0202	437
Panhandle Eastern Pipe Line Co	71-0032	432
Philadelphia Electric Co	71-0056	433
Pittsburgh-Des Moines Steel Co	71-0320	441
Portland General Electric Co	71-0327	441
Power Authority of State of New York	71-0240	438
Precision Inspection, Ltd	71-0313	441
Public Service Electric & Gas Co.	71-0328	441
Pullman Power Products	71-0184	436
Pullman, Inc.	71-0217	437
QC Services, Inc.	71-0175	436
Quality Assurance Laboratories	71-0168	436
Quality Control Services	71-0299	440
Quality Testing, Inc	71-0205	437
Smith-Emery Co.	71-0314	441
Snyder Drilling & Well Servicing	71-0306	441
Southern California Edison Co	71-0174	436
Space Science Services, Inc.	71-0215	437
St Louis Testing Laboratories, Inc.	71-0222	437
Steel Tank Construction Co	71-0298	440
Teledyne Brown Engineering Co.	71-0304	440
Terex Corp.	71-0219	437
Terradata Geophysical, Inc.	71-0289	440

Name	Docket	Page
Testco Inc	71-0125	435
Texas Pipe Bending Co of Puerto Rico	71-0307	441
Thayer Inspection Service, Inc	71-0145	435
Toledo Edison Co	71-0195	437
Transworld Airlines Inc	71-0080	433
Twin City Testing & Engineering Laboratories	71-0103	434
Twin Ports Testing Inc	71-0253	438
Ultrasonic Specialists Inc	71-0284	439
United Airlines, Inc	71-0044	432
United Engineers & Constructors, Inc.	71-0148	435
United States Testing Co , Inc.	71-0095	434
United Testing Services, Inc.	71-0290	440
Universal Testing Laboratories	71-0105	434
Universal Testing Inc	71-0279	439
Venegas Industrial Testing Laboratories Inc	71 0100	434
Virginia Commonwealth of	71-0152	435
Walworth Co	71-0039	432
Walworth Co	71-0140	435
WKM Wellhead Systems, Inc	71-0282	439
Word Industries Pipe Fabricating, Inc	71-0229	438
X-Ray Industries Inc	71-0158	436
X-Ray, Inc	71-0234	438
Yankee Atomic Electric Co	71-0068	433
Licensing of Independent Spent Fuel Storage — Docket 72		
Morris Operations, General Electric Co	72-0001	444
Virginia Electric & Power Co.	72-0002	444

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

8408060026 "Piezometers & Wells Trench 18 Monitoring Rept, Apr-June 1984 " W/840706 ltr
ARMBRUST, A J U S Ecology, Inc (formerly Nuclear Engineering, Inc) 84/06/30 SHAFFNER, J Division of Waste Management 2pp 25936 360

DOCKET 27-048 RICHLAND, WA, U S ECOLOGY, INC

8408010034 Forwards two oversize drawings showing proposed method of disposal of containers containing glove boxes contaminated w/Pu Method meets stability & intruder protection requirements of 10CFR61 Aperture cards in PDR
SAUER, R E U S Ecology, Inc (formerly Nuclear Engineering, Inc) 84/07/24 SCHAFFNER, J Low Level Waste Licensing Branch 2pp 25972 328

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO

8407230131 Confirms 840104 telcon reporting that level of liquor in low grade liquor collection pond lowered on 840103 & all flow into monitor drain ceased on 840104 Plastic liner will be repaired as weather allows Withheld
LYONS, P J Union Carbide Corp 84/01/06 CAIN, C L Region 4, Office of Director 1p 26255 355

8408270188 Informs of 500-gallon spill of tailings water to restricted area at Gas Hills Mill on 840522 Pipeline shutdown until repair made Mine spoils affected
LYONS, P J Union Carbide Corp 84/06/14 GARCIA, P J Uranium Recovery Field Office 2pp 26277 318

8408060383 Application for amend to License SUA-648, requesting variance from License Condition 47, allowing disposal of 247,000 tons of tailings during 1984 One oversize map encl Aperture card available in PDR
LYONS, P J Union Carbide Corp 84/06/29 GARCIA, P Uranium Recovery Field Office, 2pp 25951 355

8408280399 Forwards maps showing temporarily installed surface line extending from Standpipe 10 to Standpipe 16 in order to mitigate operation of buried line w/o monitor stations W/two oversize maps Aperture cards available in PDR
LYONS, P J Union Carbide Corp 84/07/09 GARCIA, P Uranium Recovery Field Office, 2pp 26299 361

8408240344 Informs that final rept on 840606 spill of heap leach liquor at Umetco Mineral Corp Gas Hills Mill will not be issued until all Ra-226 analyses on soil samples received. Analyses should be available by 840720
LYONS, P J. Union Carbide Corp 84/07/10 PETTENGILL, H Uranium Recovery Field Office 1p 26253 312

8408240412 Forwards water level evaluation repts for monitor wells near A-9 seepage collection sys Diagrams encl
LYONS, P J Union Carbide Corp. 01253 84/07/10 PETTENGILL, H Uranium Recovery Field Office 23pp. 26248 286.

8408240396 Forwards quarterly rept for Second Quarter 1984 re A-9 collection drip sys Control of acid drip to sys has not been optimum Request to use micrometering valves in place of bellows metering pumps will be submitted
LYONS, P J Union Carbide Corp 84/07/17 GARLAND, W L. Wyoming, State of 3pp. 26248, 343

--8408240400 Rept for Second Quarter 1984 re A-9 collection drip sys
* Union Carbide Corp 84/06/30 11pp 26248, 346

8408270120 Advises that submittal of final rept on stability of inactive tailings will be delayed until mid-Sept 1984 Water, Waste & Land, Inc 840605 ltr encl
LYONS, P J Union Carbide Corp 84/07/18 GARCIA, P Uranium Recovery Field Office 2pp 26277 352

8408240384 Advises of steps taken to address license compliance deficiencies, deviations & areas of concern from NRC 840619-22 insp, per 840622 closeout meeting Revised shift record sheet printed for use in dryer operation section
LYONS, P J Union Carbide Corp 84/07/23 SMITH, R D Uranium Recovery Field Office 10pp 26254 304

8408270064 Reviews Union Carbide Corp rept re seepage leaving impoundment, deterioration of groundwater & hydrology near inactive tailings Addl review of groundwater & reclamation activities recommended
KONWINSKI, G R , PETTENGILL, H J Uranium Recovery Field Office. 84/07/23 Uranium Recovery Field Office 5pp 26278 345

8408240213 Informs of issuance of Amend 24 to License SUA-648, revising Condition 42 Amend incorporates berm sump monitoring program & deletes certain requirements no longer necessary
SMITH, R D Uranium Recovery Field Office 84/07/25 Union Carbide Corp 2pp 26254 356

8408270037 Recommends issuance of Amend 24 to License SUA-648 re berm sump monitoring programs, deleting unnecessary requirements by revising Condition 42
GARCIA, P J , PETTENGILL, H J Uranium Recovery Field Office 84/07/25 Uranium Recovery Field Office 1p 26258 337.

8408240018 Forwards riders for Permits 349c & 356c-L2, changing name to Umetco Minerals Corp
LYONS, P J Union Carbide Corp 84/07/27 BOSCO, C Wyoming, State of 9pp 26254 291

8408270077 Forwards 840606 rept on heap leach liquor spill W/one oversize map Aperture card available in PDR
LYONS, P J Union Carbide Corp. 84/07/27 PETTENGILL, H. Uranium Recovery Field Office 8pp 26278 148

8408240185 Recommends issuance of Amend 25 to License SUA-648, revising Condition 47 re variance for Tailings Area A-9, per licensee 840629 request
GARCIA, P J , PETTENGILL, H J Uranium Recovery Field Office 84/08/02 Uranium Recovery Field Office 3pp 26255 266

8408270487 Advises of issuance of Amend 25 to License SUA-648, revising Condition 47 re disposal of 1,600,000 tons of tailings in A-9 tailings area
SMITH, R D Uranium Recovery Field Office 84/08/02 Union Carbide Corp 1p 26277-063.

8408240189 Recommends issuance of Amend 26 to License SUA-648, changing name in Condition 1 to Umetco Minerals Corp to reflect corporate reorganization per 840301, 02, 20 & 0727 ltrs.
SHOPENN, N M , PETTENGILL, H J Uranium Recovery Field Office 84/08/06 Uranium Recovery Field Office 2pp 26254 361

8408270354 Advises of issuance of Amend 26 to License SUA-648, revising Condition 1 re name change.
SMITH, R D Uranium Recovery Field Office 84/08/06 UMETCO Minerals Corp (subs of Union Carbide Corp.) 1p. 26277.239

8408240192 Informs that Amend 27 to License SUA-648, issued 840807 to change tailings line insp from monthly to quarterly, exempt from fees
JIERREE, C C., PETTENGILL, H J Uranium Recovery Field Office 84/08/07 MILLER, W O License Fee Management Branch 1p. 26255 255

DOCKETED ITEMS

--8408240197 Recommends issuance of Amend 27 to License SUA-648, changing monthly testing to quarterly
JIERREE, C C , PETTENGILL, H J Uranium Recovery Field Office
84/08/07 Uranium Recovery Field Office 1p 26255 256

--8408240201 Issues Amend 27 to License SUA-648 changing testing from monthly to quarterly per 840619-22 insp
SMITH, R D Uranium Recovery Field Office 84/08/07 UMETCO Minerals Corp (subs of Union Carbide Corp) 1p 26255 257

8408240163 Advises that Amend 28 to License SUA-648 issued 840808 exempt from fees
GARCIA, P J , PETTENGILL, H J Uranium Recovery Field Office
84/08/08 MILLER, W D License Fee Management Branch 1p
26254 258

--8408240166 Advises of issuance of Amend 28 to License SUA-648, revising address
SMITH, R D Uranium Recovery Field Office 84/08/08 UMETCO
Minerals Corp (subs of Union Carbide Corp) 1p 26254 259

8408240380 Presents review of Union Carbide Corp 1983 environ monitoring data for East Gas Hills Mill Licensee 830831 & 840228 submittals indicate sampling & analysis performed as required by License Condition 38
GARCIA, P J , PETTENGILL, H J Uranium Recovery Field Office
84/08/09 Uranium Recovery Field Office 5pp 26254 327

8408240116 Discusses request for amend to License SUA-648 re compaction of clay cap matl Amend 29 should require 90% compaction of clay cap & soil cover matl, four field density tests & submittal of const rept within 3 months of const completion
GARCIA, P J Uranium Recovery Field Office 84/08/14. Uranium Recovery Field Office 4pp 26254 262

8408270068 Summarizes Umetco Minerals Corp 840604 ltr re 840522 tailings line spill at East Gas Hills Mill Spill of approx 500 gallons of tailings liquid resulted from crack in flange of pipeline Repair made Area will be reclaimed
GARCIA, P J , PETTENGILL, H J Uranium Recovery Field Office
84/08/14 Uranium Recovery Field Office 2pp 26278 350

8408280006 Advises of issuance of Amend 29 to License SUA-648, revising Condition 67 re const specs for placement of reclamation cover on inactive tailings area
SMITH, R D Uranium Recovery Field Office 84/08/14 UMETCO
Minerals Corp (subs of Union Carbide Corp) 2pp 26293 360

DOCKET 40-0672 NUCLEAR METALS, INC , CONCORD, MA

8408270283 Forwards Insp Repts 40-0672/84-01 & 30-19394/84-01 on 840616-19
MARTIN, T T Division of Engineering & Technical Programs 84/08/09
TUFFIN, W B Nuclear Metals, Inc 2pp 26256 241

--8408270297 Insp Repts 40-0672/84-01 & 30-19394/84-01 on 840616-19 Violations noted employee exposure in excess of NRC limits, contamination on trailer in excess of DOT regulations & failure to self-monitor for contamination on exit
ROWE, C , THOMPSON, T., KINNEMAN, J. Region 1, Office of Director
84/08/09 5pp 26256 243

DOCKET 40-0791 UNITED TECHNOLOGIES CORP , EAST HARTFORD, CT

8408230193 Ack receipt of 840410 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0791/84-01. Actions will be examined during future insp
MARTIN, T T Division of Engineering & Technical Programs 84/08/17
BALADUER, J P United Technologies Corp. 2pp. 26209 244

--8408230198 Responds to NRC 840321 ltr re violations noted in IE Insp Rept 40-0791/84-01 Corrective actions transfer of nickel-thoria waste to Suisman & Blumenthal discontinued in March 1983
PARSONS, G E United Technologies Corp 84/04/10 MARTIN, T T
Division of Engineering & Technical Programs 1p 26209 246

DOCKET 40-1162 WESTERN NUCLEAR, INC , JEFFREY CITY, WY

8408270131 Forwards rept re semiannual audit/ALARA proceedings on 840326-29, per License Condition 43
BOGDEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp)
84/05/10 PETTENGILL, H J Uranium Recovery Field Office 21pp
26277.331

8408240186 Informs of issuance of Amend 20 to License SUA-56, revising License Conditions 11 & 61 Amend authorizes changes in air sampling frequencies, instrument calibr procedures & other radiological requirements
SMITH, R D Uranium Recovery Field Office 84/07/18 BOGDEN, G
Western Nuclear, Inc (subs of Phelps Dodge Corp) 2pp
26255 264

8408240324 Discusses Amend 20 to License SUA-56 re air sampling frequencies, instrument calibr procedures & other radiological monitoring requirements Proposed mods listed
KONWINSKI, G R Uranium Recovery Field Office 84/07/18 Uranium Recovery Field Office 7pp 26253 340

8408240345 Responds to 840628 ltr detailing insp of heap leach & forwards documentation re reclamation program Licensee has fulfilled reclamation requirements Meeting planned w/ licensee re site visit & further action W/o encls
PETTENGILL, H J Uranium Recovery Field Office 84/08/02 MOXLEY, M
Wyoming, State of 2pp 26253 310

8408270047 Trip rept of 840601 site visit w/Western Nuclear re pumpback wells, tailings impoundment & associated alluvial valleys
KONWINSKI, G R , PETTENGILL, H J Uranium Recovery Field Office
84/08/02 Uranium Recovery Field Office 2pp 26258 313

8408270220 Reviews First Quarter 1984 water quality sampling results for Split Rock Mill, submitted in compliance w/License Conditions 23, 25 & 31
KONWINSKI, G R Uranium Recovery Field Office 84/08/02 Uranium Recovery Field Office 5pp 26277 309

8408270063 Reviews Western Nuclear semiannual audit/ALARA rept for Split Rock V Mill, submitted per License Condition 43
KONWINSKI, G R Uranium Recovery Field Office 84/08/07 Uranium Recovery Field Office 2pp 26277 362

8408270033 Trip rept of 840809 site visit w/American Nuclear Corp & State of WY Mining District re heap leach locations
KONWINSKI, G R , PETTENGILL, H J Uranium Recovery Field Office
84/08/14 Uranium Recovery Field Office 4pp 26258 343

DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8408240211 Forwards, for execution, DOE/TVA interagency agreement for disposal of residual radioactive matls removed by DOE from Edgemont, SD vicinity Agreement subj to NRC & State of SD concurrence
HILL, T V Energy, Dept of 84/05/31 DONOVAN, T K Tennessee
Valley Authority 12pp 26255 157

8408270056 Summary of 840711 meeting w/TVA at Recovery Field Ofc re project schedule rev to Edgemont Decommissioning Project
BRICH, R F Uranium Recovery Field Office 84/07/26 Uranium Recovery Field Office 6pp 26278 354

8408240391 Presents review of TVA 10CFR40 65 environ monitoring rept for Edgemont Mill for Nov 1982 - Oct 1983 Util has not followed license requirements precisely re sediment monitoring program Corrective action taken
BRICH, R F Uranium Recovery Field Office 84/08/08 Uranium Recovery Field Office 5pp 26249 355

DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , OKLAHOMA CITY, OK

8408010244 Requests info re removal of thorium from Reed-Keppler Park & sanitary treatment plant
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety DSB 656
84/07/26 RENNELS, A E Chicago, IL 3pp 25856 006

8408030183 Amends license to permit onsite receipt of contaminated matl in accordance w/city of West Chicago-Kerr-McGee agreement Procedures for removal & transport of radwaste discussed
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 84/07/26
RENNELS, A E West Chicago, IL 3pp 25917 356

8408060023 Requests listed info, should Kerr-McGee decide to move thorium from Reed-Keppler Park & sanitary treatment plant
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 84/07/26
RICE, G Kerr-McGee Corp 4pp 25937 001

8408150062 Response supporting Nichiren Shoshu Temple (NST) & People of State of IL petition for leave to intervene, subj to limiting Contention I to radiological matters & NST submission of one admissible contention Certificate of Svc encl
CUOCO, L M Regional Operations & Enforcement Division BURNS, S. G
Regulations Division. 84/07/30 Atomic Safety and Licensing Board Panel. 18pp 26104.319.

8408070311 Notices of appearance in proceeding Svc list encl
RAPKIN,A , BARZANO,W J Illinois, State of DSB 787 84/08/02
4pp 25947 358

8408070294 Motion for extension of time until 840915 for all parties to respond to requests for admissions,interrogatories & requests for documents Certificate of Svc encl
MESERVE,R A Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
DSB 800 84/08/03 Atomic Safety and Licensing Board Panel 5pp
25948 073

8408070482 Forwards motion for extension of time W/o encl Related correspondence
MESERVE,R A Covington & Burling MESERVE,R A Kerr-McGee Corp
DSB 799 84/08/03 Docketing & Services Branch 1p 25941 214

8408080235 Motion for extension of time until 840915 for all parties to respond to requests for admissions,to interrogatories & to requests for documents Granted for ASLAB on 840806 Served on 840807
MESERVE,R A Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
MESERVE,R A Covington & Burling DSB 830 84/08/03 Atomic Safety and Licensing Board Panel 3pp 25967 050

8408080173 Forwards suppl to 840711 petition for leave to intervene Nichiren Shoshu Temple welcomes ASLB decision to tour Kress Creek & visit property
PROTO,N T Kelley Drye & Warren PROTO,N T Nichiren Shoshu Temple DSB 827 84/08/06 FRYE,J H Atomic Safety and Licensing Board Panel 4pp 25959 004

--8408080180 Suppl to 840711 petition for leave to intervene Nichiren Shoshu Temple requests contentions be admitted & petition for leave to intervene be granted Certificate of Svc encl
PROTO,N T Nichiren Shoshu Temple PROTO,N T Kelley Drye & Warren 84/08/06 Commissioners 14pp 25959 008

8408200603 Responds to 840724 ltr re remedial investigation/feasibility study (RI/FS) for vendor radiation sites Vendor considers any implementation of work plan unlawful & unwarranted duplication of previous scientific surveys
RICE,G B Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
DSB 160 84/08/06 CONSTANTELOS,B Environmental Protection Agency 5pp 26137 156

8408130329 Motion for leave to file reply brief instanter Motion due 840806,but due to difficulties w/word processing equipment, final printout of brief unavailable until 840807
RAPKIN,A , BARZANO,W J Illinois, State of DSB 907 84/08/07
Atomic Safety and Licensing Board Panel 1p 26007 001

--8408130337 Reply brief responding to Kerr-McGee & staff briefs on People of State of IL contentions,including Kerr-McGee supplemental memorandum on Contentions 2(u) & (w)
RAPKIN,A , BARZANO,W J Illinois, State of 84/08/07 Atomic Safety and Licensing Board Panel 85pp 26007 002

8408170310 Provides director w/items of interest Items include 840822 conference for Kress Creek in Chicago,IL re consolidation of Kress Creek & main plant & 840713-26 visit to Madrid,Spain to view new LWR fuel fabrication facility
PAGE,R G Uranium Fuel Licensing Branch 84/08/09 DAVIS,J G
Office of Nuclear Material Safety & Safeguards,Director 1p
26134,197

8408170383 Motion for leave to file Contention 2(x) re long-term radiological impacts resulting from onsite disposal & second discovery request Related correspondence
RAPKIN,A Illinois, State of DSB 098 84/08/15 Atomic Safety and Licensing Board Panel 2pp 26128 244

--8408170387 First set of interrogatories & request for documents Related correspondence
RAPKIN,A Illinois, State of 84/08/15 Office of the Executive Legal Director 7pp 26128 246

--8408170389 Second set of interrogatories & request for documents Proof of Svc & svc list encl Related correspondence
RAPKIN,A Illinois, State of 84/08/15 Kerr-McGee Chemical Corp. (subs of Kerr-McGee Corp) 6pp. 26128 253

8408170396 Amend to 840710 petition for leave to intervene,amending Contention 3 & adding Contention 6 re liability of Kerr McGee to clean up Kress Creek contamination Proof of Svc & svc list encl
RAPKIN,A Illinois, State of DSB 099 84/08/15 Atomic Safety and Licensing Board Panel 5pp 26128 239

8408230055 Submits items of interest re Whittaker Corp,Greenville,PA, EIAs & Kerr-McGee - Oklahoma
PAGE,R G Uranium Fuel Licensing Branch 84/08/16 DAVIS,J G
Office of Nuclear Material Safety & Safeguards,Director 2pp
26233 288

8408220351 Notice of appearance in proceeding Certificate of Svc encl
LUBLINSKI,M Nichiren Shoshu Temple LUBLINSKI,M Kelley Drye & Warren DSB 192 84/08/17 4pp 26189 351

8408270189 Transcript of 840822 hearing in Chicago,IL Pp 220-244
* Atomic Safety and Licensing Board Panel 84/08/22 45pp
26240 218

8408270445 Transcript of 840822 hearing in Chicago,IL re decontamination Pp 1-61
* Atomic Safety and Licensing Board Panel 84/08/22 61pp
26239 160

8408290008 Contention 2(x) re inaccuracy of applicant & NRC assessments of post-closure radiation doses & applicant failure to demonstrate that doses will be low enough to adequately protect public Proof of svc encl
RAPKIN,A Illinois, State of DSB 353 84/08/22 Atomic Safety and Licensing Board Panel 4pp 26291 282

DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY

8408200400 Responds to 840419 ltr re discontinuance of any free surface flow of solutions across surface of tailings impoundment Engineering plan encl Surface flow reduced,per 840413 discussion
NUGENT,E L Pathfinder Mines Corp 84/06/29 PETTENGILL,H
Uranium Recovery Field Office 1p 26141 194

--8408200401 "Proposed Program for Cessation of Mill Yard Drainage to Tailings Pond 1 at Lucky McMine,Gas Hills,WY "
* Pathfinder Mines Corp 84/06/30 15pp 26141 195

8408240181 Informs of issuance of Amend 19 to License SUA-672,adding Condition 39 Amend diverts mill yard draining from Tailings Pond 1 to Tailings Pond 2A Proposed program to be operational by 841201
SMITH,R D Uranium Recovery Field Office 84/07/26 NUGENT,E L
Pathfinder Mines Corp 1p 26255 270

8408270041 Recommends issuance of Amend 19 to License SUA-612 by adding Condition 39 re cessation of mill yard drainage.
KONWINSKI,G R , PETTENGILL,H J Uranium Recovery Field Office
84/07/26 Uranium Recovery Field Office 3pp 26258 330

8408270093 Forwards two 200-scale topographic maps,covering Lucky Mc tailings area,per request Wells C-8,T2-4 & T2-33 added to tailings monitor well sys W/o maps
HARDGROVE,T W Pathfinder Mines Corp 84/07/27 KONWINSKI,G.
Uranium Recovery Field Office 1p 26277 290

8408210110 Forwards IE Insp Rept 40-2259/84-01 on 840528-0601 & notices of violation & deviation
PETTENGILL,H J Uranium Recovery Field Office 84/07/31
Pathfinder Mines Corp 2pp 26184 174

--8408210111 Notice of violation from insp on 840528-0601
* Region 4, Office of Director 84/07/31 2pp. 26184 176

--8408210114 Notice of deviation from insp on 840528-0601
* Region 4, Office of Director 84/07/31 1p 26184:178

--8408210120 IE Insp Rept 40-2259/84-01 on 840528-0601 Violations noted, failure to establish std operating procedures for air sampling,failure to calibr airborne samples quarterly & failure to perform weekly documented insps of ore piles
GARCIA,P J , JIERREE,C.C , SPITZBERG,D B. Region 4, Office of Director 84/07/31 11pp 26184 179

8408240413 Forwards statistical data for source term evaluation program
HARDGROVE,T W Pathfinder Mines Corp. 84/08/02 JIERREE,C.
Uranium Recovery Field Office 11pp 26248 275.

8408240414 Forwards addendum to application for renewal of License SUA-672,describing proposed renovation program.
NUGENT,E L Pathfinder Mines Corp. 84/08/02 PETTENGILL,H.
Uranium Recovery Field Office 1p 26237:244

--8408240419 Addendum to application for renewal of License SUA-672, describing proposed renovation program for Lucky McMill.
* Pathfinder Mines Corp 84/08/31. 21pp 26237:245

DOCKETED ITEMS

DOCKET 40-3392 ALLIED CHEMICAL CORP , MORRISTOWN, NJ

8408130240 Submits addl info re application for renewal of License SUB-526, concerning UF6 product cylinders within plant, per telcon Three operating options to reduce handling of each full cylinder listed
CIPOLLA, A J Allied Chemical Corp 84/07/09 KOSLA, B M Uranium Fuel Licensing Branch 5pp 26040 358

8408130273 Advises that during Second Quarter 1984, average airborne radioactivity measured at nearest residence sampling station exceeded concentration action level specified in Amend 4 to license
CIPOLLA, A J Allied Chemical Corp 84/07/19 Office of Nuclear Material Safety & Safeguards, Director 2pp 26040 341

8408170395 Forwards corrected Page C-11 of application for renewal of License SUB-526, reflecting conditions at ore concentrate sampling plant
CIPOLLA, A J Allied Chemical Corp 84/08/01 KOSLA, B M Uranium Fuel Licensing Branch 2pp 26134 182

DOCKET 40-3453 ATLAS MINERALS, INC , DENVER, CO

8408270044 Reviews Second Half 1983 environ monitoring rept for Moab Mill, submitted per License Condition 43 & 10CFR40 65
SHOPENN, N M , PETTENGILL, H J Uranium Recovery Field Office 84/07/19 Uranium Recovery Field Office 5pp 26258 315

8408270062 Summarizes 840223 tailings reclaim line rupture during routine weekly cleaning operation Approx 5,000 gallons of tailings solution released Area cleaned Berm will be constructed to retain any future leaks
SHOPENN, N M , PETTENGILL, H J Uranium Recovery Field Office. 84/07/25 Uranium Recovery Field Office 2pp 26278 352

8408240056 Submits annual technical evaluation of embankment performance, per License Condition 52(2)
BLUBAUGH, R E Atlas Minerals, Inc 84/07/26 SMITH, R. D Uranium Recovery Field Office 7pp 26255 327

8408270235 Reviews annual technical evaluation of embankment performance for Moab Mill, submitted in compliance w/License Condition 52
KONWINSKI, G R Uranium Recovery Field Office 84/08/10 Uranium Recovery Field Office 2pp 26277 236

8408240190 Discusses Amend 16 to License SUA-917, revising in-plant radiological monitoring & environ monitoring programs License should be amended by deleting Conditions 30 & 39 & revising Conditions 12, 25, 28 & 37
SHOPENN, N M , PETTENGILL, H J Uranium Recovery Field Office 84/08/14 Uranium Recovery Field Office 6pp 26255 258

8408280023 Advises of issuance of Amend 16 to License SUA-917, deleting Conditions 30 & 39 & revising Conditions 12, 25, 28 & 37 re daily visual surveillance of mill area to insure proper implementation of good radiation safety practices
SMITH, R D Uranium Recovery Field Office 84/08/14 Atlas Minerals, Inc 3pp 26293 352

8408240142 Recommends approval of request to amend License SUA-917, authorizing disposal of contaminated solid wastes in sump collection pond south of main tailings disposal area
SHOPPEN, N M , PETTENGILL, H J Uranium Recovery Field Office 84/08/15 Uranium Recovery Field Office 3pp 26253 359

8408270482 Advises of issuance of Amend 17 to License SUA-917, changing License Condition 36 re disposal of matls w/o authorization of U Recovery Field Ofc
SMITH, R.D Uranium Recovery Field Office. 84/08/15 Atlas Minerals, Inc 2pp 26277-064

DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

8408310338 Forwards delayed response to 830410 ltr re Amend 14 to License SUA-667, adding License Condition 40 Delay due to impending new EPA stds codified after issuance of Amend 14. W/two oversize maps Aperture cards available in PDR
ANDRUS, N J. American Nuclear Corp 84/05/02 SMITH, R. D Uranium Recovery Field Office 15pp 26350. 109

8408270104 Forwards permit transfer approvals, per request Present bond deficient & raise of figure proposed
ENGELMANN, R Wyoming, State of. 84/06/04 GARCIA, P Uranium ery Field Office 11pp. 26278-303

8408240174 Comments on 840604 cost estimates for American Nuclear Corp Gas Hills, WY Mill decommissioning & tailings area reclamation
PETTENGILL, H J Uranium Recovery Field Office 84/07/10 MOXLEY, M Wyoming, State of 2pp 26255 271

8408240399 Forwards 840628 annual insp rept re Permits 323C, 352, 436 & 438 Rept summarizes reclamation & remedial action projects requiring completion in 1984 Revised bonds requested within 30 days
MOXLEY, M Wyoming, State of 84/07/11 ANDRUS, N American Nuclear Corp 10pp 26248 328

8408270361 Forwards corrected copy of analysis for U308 & calculations re max burden that could have been received by employees collecting samples, per request
ANDRUS, N J American Nuclear Corp 84/07/31 SHOPENN, M Uranium Recovery Field Office 3pp 26277 227

8408240182 Advises that manhours expended on Amends 15 & 16 to License SUA-667, issued 831228 & 840517, respectively, should be incorporated into time charged to ANC reclamation plan Manpower rept forthcoming
PETTENGILL, H J Uranium Recovery Field Office 84/08/02
WEISS, D J License Fee Management Branch 1p 26255 269

8408210129 Forwards IE Insp Rept 40-4492/84-01 on 840618-19 & notices of violation & deviation
PETTENGILL, H J Uranium Recovery Field Office 84/08/03 COX, E J American Nuclear Corp 2pp 26184 143

--8408210131 Notice of violation from insp on 840618-19
* Region 4, Office of Director 84/08/03 1p 26184 145

--8408210134 Notice of deviation from insp on 840618-19
* Region 4, Office of Director 84/08/03 2pp 26184 146

--8408210143 IE Insp Rept 40-4492/84-01 on 840618-19 Violations & deviations noted employee exposures not accurately determined, inspectors not instructed to self-monitor after exiting mill & restricted boundary not replaced
SHOPENN, N M , GARCIA, P J , JIERREE, C C Region 4, Office of Director 84/08/03 4pp 26184 148

8408270033 Trip rept of 840809 site visit w/American Nuclear Corp & State of WY Mining District re heap leach locations
KONWINSKI, G R , PETTENGILL, H J Uranium Recovery Field Office 84/08/14 Uranium Recovery Field Office 4pp 26258 343

DOCKET 40-6499 MAINE MARITIME ACADEMY, CASTINE, ME

8408010397 Discusses IE Insp of Licenses SNM-493 & SUB-283 on 840614 & forwards notice of violation
MARTIN, T T Region 1, Office of Director 84/07/19 CUKIERSKI, M W Maine Maritime Academy, Castine, ME 2pp 25866 053

--8408010400 Notice of violation from insp on 840614 Violation noted yearly calibr of survey meters undocumented, monthly exchange of film badges not performed & sealed sources not tested for leakage
* Region 1, Office of Director 84/07/19 1p 25866 055

DOCKET 40-6500 ENERGY, DEPT OF, CANONSBURG, PA

8408150193 Forwards Mod A003 to Cooperative Agreement DE-FC04-82AL19487 between DOE & Commonwealth of PA Mod reflects std format being negotiated w/other affected states
HILL, T V Energy, Dept. of. 84/06/27 HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 51pp 26104 067

DOCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY

8408080326 Requests extension to 840815 for submitting proposal to mitigate seepage from tailings pond, per 840508 ltr, due to necessary addl field work, including drilling 14 holes to define geological extent of surficial aquifer
RUSSELL, J E Pathfinder Mines Corp. 84/06/13 PETTENGILL, H J Uranium Recovery Field Office 3pp. 25978-201

8408240334 Responds to notice of violation from insp on 840529-31 Corrective actions fill matl placed in four embankment areas threatened by erosion & tailings discharge line constructed
RUSSELL, J E Pathfinder Mines Corp. 84/07/11 PETTINGILL, H J Uranium Recovery Field Office 1p 26253 332

8408240347 Accepts licensee commitment to submit mitigative action plan by 840815,per 840613 ltr Program will utilize hydrological data from two wells,per 840712 telcon
PETTENGILL,H J Uranium Recovery Field Office 84/07/25
RUSSELL,J Pathfinder Mines Corp 1p 26253 204

8408240340 Ack receipt of 840711 ltr responding to 840705 notice of violation Corrective actions will be examined at future insp
PETTENGILL,H J Uranium Recovery Field Office 84/08/03
POYSER,R W Pathfinder Mines Corp 1p 26253 318

DOCKET 40-6659 GETTY OIL CO - PETROTOMICS CO , SHIRLEY BASIN, WY

8408240336 Responds to 840620 notice of violation Corrective actions personnel briefed on respirator incident & trained during refresher course & procedure established to insure pressure readings properly recorded W/o stated procedure
WHITMAN,J H Getty/Petrotomics Co 84/07/11 PETTENGILL,H J
Region 4, Office of Director 2pp 26253 323

8408240346 "Radioactive Airborne U Dust Samples,840509 "
PFAFF,S J Getty/Petrotomics Co 84/07/11 PETTENGILL,H J
Uranium Recovery Field Office 2pp 26253 201

8408270022 Ack receipt of 840711 ltr informing NRC of steps taken to correct violations noted in 840620 notice of violation Corrective actions to be examined at future insp
PETTENGILL,H J Uranium Recovery Field Office, 84/08/03
WHITMAN,J H Getty/Petrotomics Co 1p 26258 356

DOCKET 40-6940 KAWECKI BERYLCO IND , INC , BOYERTOWN, PA

8408090319 Forwards request for addl info re proposed groundwater monitoring program
CROW,W T Uranium Fuel Licensing Branch 84/08/03 COYLE,F T
Kawecki Berylco Industries, Inc 2pp 25984 350

DOCKET 40-7455 WHITTAKER METALS, LOS ANGELES, CA

8408230055 Submits items of interest re Whittaker Corp,Greenville,PA, EIAs & Kerr-McGee - Oklahoma
PAGE,R G Uranium Fuel Licensing Branch 84/08/16 DAVIS,J G
Office of Nuclear Material Safety & Safeguards,Director 2pp
26233 288

DOCKET 40-7869 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO

8408240351 Informs of resignation of radiation safety officer,effective 840809
GERDEMAN,F W Plateau Resources, Ltd 84/07/31 SMITH,R D
Uranium Recovery Field Office 1p 26253 282

DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8406130219 Requests public hearing re raffinate deep well injection project at facility near Gore,OK
HENSHAW,E Affiliation Not Assigned 84/05/22 NIXON,W A
Division of Fuel Cycle & Material Safety 1p 26011 361

8408020103 Provides followup to recent telcons re Kerr-McGee Nuclear Corp UF6 facility near Gore,OK Clarification of discrepancies concerning levels of injected raffinate requested
KIMERY,A L Affiliation Not Assigned 84/06/20 CROW,W T Uranium
Fuel Licensing Branch 3pp 25898 104

8408020153 Forwards HK Van Poollen rept on modeling results for injection of 35 million gallons of treated raffinate
STAUTER,J C Kerr-McGee Corp 84/07/05 WYNGARDEN,S Uranium Fuel
Licensing Branch 8pp 25898 082

8408020161 Summarizes info supplied by Kerr-McGee re estimate of final pressure buildup to be expected after injection of proposed 35 million gallons of treated liquid raffinate injection can be done w/o exceeding allowable pressure
WARNER,D L Don L Warner, Inc 84/07/10 WYNGARDEN,S D Uranium
Fuel Licensing Branch 2pp 25898 076

8407230112 Responds to 840522 request for hearing on proposed amend permitting disposal of raffinate through deep well injection Addl info re issues to be raised requested within 10 days
CHILK,S J Office of the Secretary of the Commission DSB 403
84/07/20 HENSHAW,E Affiliation Not Assigned 1p 25706 102

8408150671 Forwards "Environ Assessment Update of Raffinate Pond 2 "
STAUTER,J C Kerr-McGee Corp 84/07/26 CROW,W T Uranium Fuel
Licensing Branch 1p 26105 270

--8408150675 "Environ Assessment Update of Raffinate Pond 2 "
STAUTER,J C Kerr-McGee Corp 84/06/30 58pp 26105 272

8408080455 Requests hearing on proposed license amend re disposal of well matl
HENSHAW,E Affiliation Not Assigned DSB 834 84/07/31
CHILK,S J Office of the Secretary of the Commission 2pp
25963 274

8408230055 Submits items of interest re Whittaker Corp,Greenville,PA, EIAs & Kerr-McGee - Oklahoma
PAGE,R G Uranium Fuel Licensing Branch 84/08/16 DAVIS,J G
Office of Nuclear Material Safety & Safeguards,Director 2pp
26233 288

DOCKET 40-8064 EXXON MINERALS CO , USA, HOUSTON, TX

8408270197 Summarizes Exxon Minerals Co rept for First Quarter 1984 Pilot well field conditions stable In-plant radiological monitoring performed as required Rn-222 & U concentrations at or below 2% of 10CFR20 max for restricted areas
WASTLER,S L , HAWKINS,E F Uranium Recovery Field Office 84/07/20
Uranium Recovery Field Office 2pp 26277 316

DOCKET 40-8084 RIO ALGOM CORP , MOAB, UT

8408070509 "Remedial Action Plan for Groundwater Contamination Control at Lisbon U Mill," Vol 1 - text,W/nine oversize maps
Aperture cards available in PDR
* EarthFax Engineering, Inc 84/04/30 128pp 25956 001

8408270228 Reviews addendum to environ monitoring rept for Second Half 1983,containing Th-230 & Pb-210 air particulate data not in 840217 original rept
GARCIA,P J , PETTENGILL,H J Uranium Recovery Field Office
84/07/19 Uranium Recovery Field Office 1p 26277 238

8408240158 Advises of issuance of Amend 21 to License SUA-1119, incorporating name change & authorizing const of berm in upper tailings pond
SMITH,R D Uranium Recovery Field Office 84/08/10 Rio Algom
Corp 2pp 26253 362

8408240209 Recommends issuance of Amend 21 to License SUA-1119,changing name in Condition 1 to Rio Algom Mining Corp & revising Conditions 31,32 & 34 re upper tailings pond
JIERREE,C C , PETTENGILL,H J Uranium Recovery Field Office
84/08/10 Uranium Recovery Field Office 4pp 26253 244

DOCKET 40-8102 EXXON CO , USA, HOUSTON, TX

8408060297 Forwards list of activities to be undertaken during period between end of milling & issuance of decommissioning license amend
PATTON,J D Exxon Corp 84/06/14 SMITH,R D Uranium Recovery
Field Office 5pp 25950 355

8408270055 Reviews environ & effluent monitoring rept for Jul-Dec 1983,submitted per 10CFR40 65 & License Conditions 14 & 35
PANOBURN,O C , PETTENGILL,H J Uranium Recovery Field Office,
84/07/24 Uranium Recovery Field Office 4pp 26279 037

8408230472 Forwards IE Insp Rept 40-8102/84-01 on 840709-12 & notices of violation & deviation
PETTENGILL,H J Uranium Recovery Field Office, 84/07/31
SHANNON,J B, Exxon Corp 2pp 26212:192

--8408230475 Notice of violation from insp on 840709-12
* Region 4, Office of Director 84/07/31 1p. 26212 194

--8408230478 Notice of deviation from insp on 840709-12
* Region 4, Office of Director, 84/07/31, 1p, 26212 195

DOCKETED ITEMS

--8408230481 IE Insp Rept 40-8102/84-01 on 840709-12 Violation noted lack of approved respiratory protection program & use of uncertified respirator Deviation noted failure to calibr alpha survey instruments
JIERREE, C C , PANOBURN, G C , PETTENGILL, H J Uranium Recovery Field Office 84/07/31 10pp 26212 196

8408240169 Advises of issuance of Amend 8 to License SUA-1139, revising License Condition 11
SMITH, D F Uranium Recovery Field Office 84/08/03 PATTON, J D Exxon Corp 2pp 26254 260

8408270035 Recommends issuance of Amend 8 to License SUA-1139, changing Condition 11 to allow routine organizational & administrative changes w/o approval in form of amend
PANOBURN, G C , PETTENGILL, H J Uranium Recovery Field Office 84/08/03 Uranium Recovery Field Office 2pp 26258 341

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO , BROOMFIELD, CO

8408240149 Forwards Form NRC-591, "Insp Findings & Licensee Ack," re violations observed during 840626 insp of License SUA-1228 Signature requested within 30 days W/o encl
WASTLER, S L Uranium Recovery Field Office 84/07/13 NEUMAN, M R Rocky Mountain Energy Co 1p 26254 257

8408240102 "Nine Mile Lake Quarterly Rept, Second Quarter 1984 "
SPIELES, P R Rocky Mountain Energy Co 84/07/31 SMITH, R D Uranium Recovery Field Office 10pp 26254 272

DOCKET 40-8434 HOMESTAKE MINING CO , LAKEWOOD, CO

8408280365 Confirms that Homestake Mining Co does not intend to renew License SUA-1249
CROUCH, D B Homestake Mining Co 84/07/30 WASTLER, S Uranium Recovery Field Office 1p 26292 360

DOCKET 40-8452 BEAR CREEK URANIUM CO , CASPER, WY

8408080429 Application for amend to License SUA-1319, revising Nov 1981 tailings mgt plan to include plans to raise tailings dam to intermediate elevation of 5,166 ft W/three oversize drawings Aperture cards in PDR Fee encl
MEDLOCK, R L Bear Creek Uranium Co 84/04/19 PETTENGILL, H , PANOBURN, G Uranium Recovery Field Office 11p 25975 337

8408270106 Submits review of 1984 reclamation & decommissioning bonds Bond amount adequate for tasks License SUA-1310, Condition 16 satisfied
PANOBURN, G C , PETTENGILL, H J Uranium Recovery Field Office 84/07/31 Uranium Recovery Field Office 2pp 26277 360

8408270049 Reviews Bear Creek U Mill environ monitoring data for Oct 1981 - Sept 1982 re 40CFR190 compliance assessment
JIERREE, C C Uranium Recovery Field Office 84/08/01 Uranium Recovery Field Office, 2pp 26277 285

8408240212 Recommends issuance of Amend 24 to License SUA-1310, revising Condition 31 re tailing dam raise, per licensee 831122 request
PANOBURN, G C , PETTENGILL, H J Uranium Recovery Field Office 84/08/03 Uranium Recovery Field Office 3pp 26254 358

8408270031 Advises of issuance of Amend 24 to License SUA-1310, revising Condition 31 re const of proposed dam raise, per const Specs C-1 & C-2
SMITH, R D Uranium Recovery Field Office 84/08/07 Bear Creek Uranium Co 3pp 26277 240.

DOCKET 40-8502 WYOMING MINERAL CORP , LAKEWOOD, CO

8408240427 Requests confirmation of timely filing of 830928 renewal application for License SUA-1341 & application fee Extension ltr requested.
RUTLEDGE, C Westinghouse Electric Corp 84/01/27 Division of Fuel Cycle & Material Safety 1p 26248 226

8408240381 Forwards rept of action for mitigation re 830605 event concerning Monitor Wells RS-79 in production area exceeding action levels for chloride Rept submitted per Condition 16D, License SUA-1341
RUTLEDGE, C. Westinghouse Electric Corp 84/02/16 SMITH, R D Uranium Recovery Field Office 4pp. 26254 323

8408240409 Submits monthly rept on corrective action status of Well 9RS-25 at Irigaray Mine Site Chloride returned below upper control limit
RUTLEDGE, C Westinghouse Electric Corp 84/02/16 CHANCELLOR, R Wyoming, State of 2pp 26248 312

8408240402 Recommends that no action be taken on groundwater restoration plan for alternative lixiviant test area until addl info submitted re listed issues
OGLE, K M Wyoming Mineral Corp 84/02/17 Wyoming Mineral Corp 4pp 26248 320

8408270424 Discusses items of concern requiring response before approval may be granted for 831115 proposed groundwater restoration for alternate lixiviant test area
MOONEY, G Wyoming, State of 84/02/23 RUTLEDGE, C Westinghouse Electric Corp 4pp 26277 230

8408240397 Provides status rept on mitigation of excessive chloride action levels in monitor wells at Irigaray Mine Site, per License Condition 16D
RUTLEDGE, C Westinghouse Electric Corp 84/03/19 PETERSON, K Uranium Recovery Field Office 5pp 26248 338

8408270032 Forwards monthly rept re analyses of samples from Monitor Well 9RS-25 Well exhibited irregular behavior Chloride remained under upper control limit for 4 wks
RUTLEDGE, C Westinghouse Electric Corp 84/03/19 CHANCELLOR, R Wyoming, State of 2pp 26258 347

--8408270034 Analyses of samples from Monitor Well 9RS-25 for 840830-0311
* Westinghouse Electric Corp 84/03/11 2pp 26258 348

8408270562 Forwards response to 840223 request for addl info re alternate lixiviant test area restoration demonstration Expeditious review requested
RUTLEDGE, C Westinghouse Electric Corp 84/03/28 MOONEY, G Wyoming, State of 10pp 26277 253

8408270138 Submits status rept on action for mitigation of excessive chloride action levels in Wells 9RS-79, 517-M1 & 517-M2, per License Condition 16D
FAUBER, J Westinghouse Electric Corp 84/04/18 SMITH, D Uranium Recovery Field Office 3pp 26277 328

8408270042 Comments on Westinghouse 840328 responses to 840223 ltr re Irigaray Ranch Mine, Permit 478
MOONEY, G Wyoming, State of 84/05/11 RUTLEDGE, C Westinghouse Electric Corp 10pp 26258 320

8408270031 Monthly rept on corrective action status of Wells 9RS-79, 517-M1 & 517-M2 at Irigaray Mine, 830605-840513
FAUBER, J Westinghouse Electric Corp 84/05/16 SMITH, D NRC - No Detailed Affiliation Given 3pp 26258 349

8408270550 Reviews Western Nuclear 840419 submittal re alternate lixiviant test area restoration demonstration Addl info requested re well integrity testing
OGLE, K M Wyoming, State of 84/05/25 Wyoming, State of 12pp 26277 273

8408240349 Ack receipt of 840522 ltr re 840412 request for redefinition of carbonaceous shale zone & review of proposed monitoring & restoration program Review of revised monitoring & restoration program as applied to license requested
RITNER, T H Westinghouse Electric Corp 84/06/12 SMITH, R D Uranium Recovery Field Office 1p 26253 203

8408270364 Forwards response to 840605 request for addl info re restoration demonstration Authorization for demonstration requested
RUTLEDGE, C Westinghouse Electric Corp 84/06/19 RANDEN, L D Wyoming, State of 10pp 26279 005

8408270069 Forwards monthly rept on corrective action status of Wells 9RS-79 & 517-M2 at Irigaray Mine
FAUBER, J Westinghouse Electric Corp 84/06/20 SMITH, D Uranium Recovery Field Office 3pp 26277 287

8408270571 Forwards response to 840611 request for addl info re application for groundwater pollution control permit Issuance of permit to begin work requested
RUTLEDGE, C Westinghouse Electric Corp 84/06/20 GARLAND, W Wyoming, State of 2pp 26279 015

8408270177 Informs that response to 830627 request for amend to License SUA-1341, authorizing action level adjustment for Irigaray Mine Site, not received
RUTLEDGE, C Westinghouse Electric Corp 84/06/27 SMITH, R D Uranium Recovery Field Office 1p 26277 320

8408280014 Advises of issuance of Amend 9 to License SUA-1341, authorizing addl restoration of Wellfield E at site
SMITH,R D Uranium Recovery Field Office 84/07/16 RUTLEDGE,C Westinghouse Electric Corp 2pp 26293 335

--8408280016 Documents issuance of Amend 9 to License SUA-1341, authorizing addl restoration of Wellfield E at site
PETERSON,K A Uranium Recovery Field Office 84/07/16 Uranium Recovery Field Office 3pp 26293 357

8408270545 Confirms plan to drill Well 517-NM2,per 840727 discussion Application for permit to appropriate groundwater filed w/State of WY & application to substitute new well forthcoming
VASELIN,J Westinghouse Electric Corp 84/07/30 MOONEY,G Wyoming, State of 1p 26277 038

DOCKET 40-8584 MINERALS EXPLORATION CO , LOS ANGELES, CA

8408270238 Forwards revised application for renewal of License SUA-1350,describing existing mill processes & monitoring programs Summary listing of license conditions & amends included as integral part of renewal application
HILL,C Z Union Minerals 84/04/03 PETTENGILL,H Uranium Recovery Field Office 14pp 26276 276

--8408270243 Revised application for renewal of License SUA-1350, describing existing mill process & monitoring programs W/ one oversize map Aperture card available in PDR
* Union Minerals 84/03/31 64pp 26276 295

8408270157 Informs that on 840521,two corners of hypalon liner matl observed separating Storm ripped liner matl & areas stabilized by plastic sheeting & sandbagging Repairs made
KLEIN,T J Union 76 Minerals Exploration Co 84/05/23 SMITH,R D Uranium Recovery Field Office 3pp 26277 325

8408240406 Reviews 840512 responses to Fall 1983 completeness review W/exception of vegetation,soils & wind erosion,sufficient info supplied for technical review Adequacy of soils, vegetation & wind erosion info not yet evaluated
ENGELMANN,R Wyoming, State of 84/07/11 HILL,C Z Minerals Exploration Co (subs of Union Oil Co of California) 2pp 26248 318

8408240408 Advises that proposal for addl monitoring wells modified to include Tailings Monitor Wells TMW-16,TMW-17 & TMW-18 Initial analysis will include listed parameters TMW-15 sampling will be revised
KLEIN,T J Union Minerals 84/07/20 SMITH,R D Uranium Recovery Field Office 4pp 26248 314

8408240417 Forwards revised Pages 5-9 & 5-18A to 840403 application to renew License SUA-1350, including external radiation exposure history & discussion of tailings cell leak detection monitoring sys 40CFR192 requirements,respectively
HILL,C Z Union Minerals 84/07/27 PETTENGILL,H Uranium Recovery Field Office 3pp 26248 272

--8408240423 Revised Pages 5-9 & 5-18A to 840403 application to renew License SUA-1350, including external radiation exposure history & discussion of tailings cell leak detection monitoring sys 40CFR192 requirements,respectively
* Union Minerals 84/07/27 2pp 26248 273

8408270053 Summary of 840601 meeting w/licensee & State of WY at mill site re liner damage reported in 840522 telcon
KONWINSKI,G R , PETTENGILL,H J Uranium Recovery Field Office 84/08/02 Uranium Recovery Field Office 3pp 26278 360

8408270248 Provides annual review of bond covering mill decommissioning & site reclamation,submitted in compliance w/License Condition 17
KONWINSKI,G R , PETTENGILL,H J Uranium Recovery Field Office 84/09/10 Uranium Recovery Field Office 2pp 26277 234

DOCKET 40-8585 WYOMING MINERAL CORP , LAKEWOOD, CO

8408270028 Forwards "Semiannual Effluent Monitoring Rept,Jul-Dec 1983 " Name changed to U Resources Div of Westinghouse, effective 840101
BERG,R E Westinghouse Electric Corp 84/02/27 Region 4, Office of Director 1p 26258 352

--8408270029 "Semiannual Effluent Monitoring Rept,Jul-Dec 1983 "
* Westinghouse Electric Corp 83/12/31 1p 26258 353

DOCKET 40-8586 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8408240331 Responds to 831121 notice not to renew License SUA-1330 Insp performed 840628 confirmed wells properly plugged & reclaimed License SUA-1330 terminated
SMITH,R D Uranium Recovery Field Office 84/08/07 STAUTER,J Sequoyah Fuels Corp 1p 26253 333

--8408240333 Discusses decommissioning of facility & termination of License SUA-1330 Facility decommissioned & reclaimed per license conditions
HILDENBRAND,P Uranium Recovery Field Office 84/08/07 Uranium Recovery Field Office 2pp 26253 334

DOCKET 40-8602 SILVER KING MINES, INC , CASPER, WY

8408240216 Reviews Silver King Mines,Inc 840228 submittal re preoperational radiological environ monitoring rept for Jul-Dec 1983
PANOBURN,G C , PETTENGILL,H J Uranium Recovery Field Office 84/08/14 Uranium Recovery Field Office 4pp 26254 347

DOCKET 40-8674 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO

8408130272 Requests amend to Condition 26 D of License SUA-1386, reflecting renewal of ltr of credit Revised ltr of credit expires 880413
GERDEMAN,F W Plateau Resources, Ltd 84/07/10 Uranium Recovery Field Office 1p 26040 344

8408240047 Explains reason for not revising estimate of decommissioning costs for Blanding Ore Buying Station,per License Condition 26 Dollar amount for surety exceeds amount for decommissioning
GERDEMAN,F W Plateau Resources, Ltd 84/07/26 SMITH,R D Uranium Recovery Field Office 2pp 26255 340

8408240351 Informs of resignation of radiation safety officer, effective 840809
GERDEMAN,F W Plateau Resources, Ltd 84/07/31 SMITH,R D Uranium Recovery Field Office 1p 26253 282

8408240385 Presents review of Plateau Resources,Ltd 10CFR40 65 environ monitoring rept for Blanding Ore Buying Station for First Half 1983 No ore stored at facility No further action necessary
HILDENBRAND,P Uranium Recovery Field Office 84/08/07 Uranium Recovery Field Office 2pp 26252 361

DOCKET 40-8675 ENERGY FUELS NUCLEAR, INC , DENVER, CO

8408280110 Application for amend to License SUA-1325,to dispose of approx 4,000 tons of contaminated soil & low grade ore in licensed tailings disposal facility
ROBERTS,H R Energy Fuels Nuclear, Inc 84/09/10 HAWKINS,E Region 4, Office of Director 1p 26294 140

8408280010 Forwards decommissioning plan for Hanksville Buying Station Decommissioning activities will begin on 840604 w/equipment removal & cleanup of sample plant bldg interior
VINCELETTE,M D Energy Fuels Nuclear, Inc 84/09/25
HILDENBRAND,P Uranium Recovery Field Office 1p 26294:001.

--8408280012 Decommissioning plan for Hanksville Buying Station
* Energy Fuels Nuclear, Inc 84/09/24 4pp 26294 002

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC , DENVER, CO

8408080144 Application for amend to License SUA-1358,transferring White Mesa,UT facility to Umetco Minerals Corp Umetco acquired 70% undivided interest in U & vanadium milling facility at White Mesa
GRANELEY,G W Energy Fuels Nuclear, Inc ALESIO,W G. UMETCO Minerals Corp (subs of Union Carbide Corp) 84/05/15 SMITH,R D Uranium Recovery Field Office 26pp 25979,056.

8408240393 Notifies that two acres of grazing land cleared for agricultural use & that residence under const,in compliance w/License SUA-1358 requirement for annual accounting of changes in land use
PERKINS,L K. Energy Fuels Nuclear, Inc 84/07/13 SMITH,R D Uranium Recovery Field Office 1p 26248 362

8408270040 Summarizes Energy Fuels Nuclear 840504 semiannual environ monitoring rept for Jul-Dec 1983,per 10CFR40 65 & License Condition 38 Concern expressed re significant change noted in Ra-226 analyses of vegetation samples
HILDENBRAND,P , HAWKINS,E F Uranium Recovery Field Office
84/07/20 Uranium Recovery Field Office 4pp 26258 333

8408290216 Application for amend to License SUA-135,extending license for 90 days beyond 840831 expiration date
VINCELETTE,M D Energy Fuels Nuclear, Inc 84/07/23
HILDENBRAND,M Uranium Recovery Field Office 1p 26312 343

8408270117 Submits review of semiannual ALARA rept for 1983 for White Mesa Mill
HILDENBRAND,P , HAWKINS,E F Uranium Recovery Field Office
84/07/26 Uranium Recovery Field Office 6pp 26277 354

8408290366 Forwards fee for amend to License SUA-1358,extending expiration date by 90 days,per 840723 ltr
VINCELETTE,M D Energy Fuels Nuclear, Inc 84/07/30
HILDENBRAND,M Uranium Recovery Field Office 1p 26310 359

DOCKET 40-8684 WESTERN NUCLEAR, INC , LAKEWOOD, CO

8408270038 Application for amend to License SUA-1337,revising App D-1 re past & present land use;App D-7 re soil assessment & App D-8 re vegetation inventory W/four oversize figures Aperture cards available in PDR
BOGDEN,G Western Nuclear, Inc (subs of Phelps Dodge Corp)
84/07/23 HILDENBRAND,P Uranium Recovery Field Office 147pp
26278 156

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO , DENVER, CO

8408240031 Environ monitoring quarterly rept for Apr-June 1984,Reno Creek R&D project
SPIELES,P Rocky Mountain Energy Co 84/07/24 SMITH,R D Uranium Recovery Field Office 9pp 26254 282

DOCKET 40-8698 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO

8408240410 Updates situation in which tailings contaminated solution exceeded level of clay liner in lower impoundment area at Shootaring Canyon processing facility Coring program will be initiated Survey results encl
GERDEMAN,F W Plateau Resources, Ltd 84/07/18 SMITH,R D
Uranium Recovery Field Office 3pp 26248 309

8408240207 Summary of 840628 meeting w/Plateau Resources,Ltd in Denver, CO re Shootaring Canyon U Mill license & Blanding Ore Buying Station license renewal application
SHOPENN,N M , PETTENGILL,H J , HAWKINS,E F Uranium Recovery Field Office 84/07/27 Uranium Recovery Field Office 3pp
26255 248

8408240351 Informs of resignation of radiation safety officer,effective 840809
GERDEMAN,F W Plateau Resources, Ltd 84/07/31 SMITH,R D
Uranium Recovery Field Office 1p 26253 282

8408240195 Recommends License SUA-1371 be amended to extend expiration date to 841231 to allow time for preparation of renewal application
SHOPENN,N M Uranium Recovery Field Office 84/08/07 Uranium Recovery Field Office 2pp 26255 252

--8408240198 Issues Amend 10 to License SUA-1371,extending expiration date to 841231
SMITH,R D Uranium Recovery Field Office 84/08/07
GERDEMAN,F W Plateau Resources, Ltd 1p 26255 254

8408240373 Presents review of Plateau Resources,Ltd 830826 & 840305 environ monitoring data for Shootaring Canyon facility for 1983 Environ monitoring in accordance w/License Conditions 34 & 44
KONWINSKI,G R , PETTENGILL,H J Uranium Recovery Field Office
84/08/07 Uranium Recovery Field Office 4pp 26254 340

8408270100 Reviews 1982 chemical analysis & analytical detection limits re groundwater for Shootaring Canyon U processing facility
HAWKINS,E F , SHOPENN,N M Uranium Recovery Field Office 84/08/08
Uranium Recovery Field Office 4pp 26278 314

DOCKET 40-8722 BRUSH WELLMAN, INC , CLEVELAND, OH

8408060300 Application for renewal of License SUA-1354,extending expiration date until Jan 1986 Fee encl
VALIQUETTE,J C Brush Wellman, Inc 84/06/01 SMITH,R D Uranium Recovery Field Office 6pp 25951 001

8408240177 Ack receipt of renewal application for License SUA-1354
HAWKINS,E F Uranium Recovery Field Office 84/07/19
VALIQUETTE,J C Brush Wellman, Inc 1p 26255 273

DOCKET 40-8724 CHEMETRON CORP , CHICAGO, IL

8408020228 Forwards Health Physics Procedure 9, "Confirmatory Survey Methods " Procedure will be included in decontamination plan
PECK,S Radiation Management Corp 84/06/28 CODL,D NRC - No Detailed Affiliation Given 1p 25898 193

--8408020230 Health Physics Procedure 9, "Confirmatory Survey Methods "
* Radiation Management Corp 84/06/28 4pp 25898 194

DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8408240040 Notifies that R&D License BRD may be terminated & responsibility for revegetation must be included in Permit 304c
SUNDIN,R , RANDEN,L , OARLAND,W Wyoming, State of 84/07/31
STAUTER,J C Sequoyah Fuels Corp 1pp 26255 342

DOCKET 40-8728 TETON EXPLORATION DRILLING CO , INC , CASPER, WY

8408270205 Summarizes Teton Exploration First Quarter 1984 rept Site remained shutdown Activities included evaporation pond insp, leak detection monitoring, in-plant radiation monitoring & security No leaks detected in pond liners
WASTLER,S L , HAWKINS,E F Uranium Recovery Field Office 84/07/20
Uranium Recovery Field Office 2pp 26277 314

DOCKET 40-8745 OGLE PETROLEUM, INC , CASPER, WY

8408240079 Requests that Dison Basin Mine,Permit 504,be placed on interim stabilization,per 35-11-401(n) Mine not in operation due to depressed market conditions Required environ sampling & analyses continues to take place Table withheld
CATCHPOLE,G J Ogle Petroleum, Inc 84/07/16 ENGELMANN,R
Wyoming, State of 2pp 26255 334

8408240050 Forwards matl re Technology Lab, Inc alpha contamination survey,per request
CATCHPOLE,G J Ogle Petroleum, Inc 84/08/06 WASTLER,S Uranium Recovery Field Office 4pp 26255 336

DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8408240175 Forwards amended License SUA-1387,EIA & BER
SMITH,R D Uranium Recovery Field Office 84/07/25 STANTER,J
Sequoyah Fuels Corp 1p 26253 001

--8408240178 Amended License SUA-1387 for Sequoyah Fuels Corp,authorizing R&D scale U in situ leach activities
SMITH,R D Uranium Recovery Field Office 84/07/25 15pp
26253 002

--8408240180 Safety evaluation supporting amend to License SUA-1387
HILDENBRAND,P , HAWKINS,E F Uranium Recovery Field Office
84/07/06 6pp 26253 017

--8408240183 EIA supporting amend to License SUA-1387
HILDENBRAND,P , HAWKINS,E F Uranium Recovery Field Office
84/07/25 177pp. 26253-023

8408240339 "Soil Sediment Analysis Summary,NPDES Drainage Sys,June 1983 - Mar 1984 "
FREEMAN,M D Sequoyah Fuels Corp 84/06/07 HILDENBRAND,P
Uranium Recovery Field Office 2pp 26253 319

8408240377 Notifies of 840702 lab analysis of Ra-266 at 10 8 pCi/g for 840404 soil samplefrom outfall location.8 3 pCi/g above baseline value Sample taken on 840611 showed only 1 pCi/g above baseline Similar reading occurred in first quarter
FREEMAN,M D Sequoyah Fuels Corp 84/07/09 HAWKINS,E ,
HILDENBRAND,P Uranium Recovery Field Office 1p 26254 333

8408240154 Forwards form NRC-591, "Insp Findings & Licensee Ack," re violations observed during 840627-28 insp of License SUA-1387 Signature requested within 30 days W/o encl
WASTLER,S L Uranium Recovery Field Office 84/07/13 ORELL,E
Kerr-McGee Nuclear Corp 1p 26254 256

8408240375 Ack receipt of 840613 ltr to R Spears Q-Sand restoration proposal acceptable As stated on Page 2,approval from Dept of Environ Quality & NRC needed before sodium sulfide added to injection stream
MCCARTY,C Wyoming, State of 84/07/23 FREEMAN,M L Sequoyah Fuels Corp 1p 26254 339

8408270048 Reviews Sequoyah Fuels Corp First Quarter 1984 rept for Q-Sand R&D In Situ Leach Project,submitted per License Condition 58
HILDENBRAND,P , HAWKINS,E F Uranium Recovery Field Office
84/07/26 Uranium Recovery Field Office 4pp 26258 309

8408280334 Reviews Sequoyah Fuels Corp semiannual ALARA audit rept of Q-Sand R&D In Situ Leach Project for Nov 1983 - Apr 1984, submitted per License Condition 27
HILDENBRAND,P , HAWKINS,E F Uranium Recovery Field Office
84/07/26 Uranium Recovery Field Office 4pp 26294 109

DOCKET 40-8769 EXXON CO , USA, BILLINGS, MT

8408090157 IE Insp Findings & Licensee Ack on 840710 of License SUB-1382 Insp findings records re receipt of licensed matl not properly maintained & documents not properly posted
WILSORN,L Region 4, Office of Director 84/07/10 1p 25994 326

DOCKET 40-8783 URANERZ USA, INC , CASPER, WY

8408240341 Forwards author 840710 ltr to State of WY Dept of Environ Quality re state annual rept & request to skip monitor well sampling period
SOMERVILLE,K G Uranerz USA, Inc 84/07/10 HAWKINS,E Uranium Recovery Field Office 3pp 26253 315

DOCKET 40-8786 URANIUM RESOURCES, INC , RICHARDSON, TX

8408070226 Forwards IE Insp Rept 40-8786/84-01 on 840105 & 09 & notice of violation Insp examined allegations of violations of license conditions One allegation substantiated Insp rept withheld
SMITH,R D Uranium Recovery Field Office 84/07/09 RICHARDSON
Uranium Resources, Inc 2pp 25957 048

--8408070231 Notice of violation from insp on 840105 & 09 Violation noted failure to rept leaks in east & west ponds on 840310 & 830120,respectively
* Region 4, Office of Director 84/07/09 1p 25957 050

8408240353 Responds to 840709 notice of violation of Condition 17 re failure to rept leaks in evaporation ponds on 820310 & 830120 Corrective action holes patched to prevent leakage into monitor sumps
PELIZZA,M S Uranium Resources, Inc 84/07/20 SMITH,R D Uranium
Recovery Field Office 1p 26253 281

8408270026 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in 840620 notice of violation Actions to be examined at future insp NRC reporting requirements reiterated
SMITH,R D Uranium Recovery Field Office 84/08/10 PELIZZA,M S
Uranium Resources, Inc 2pp 26258 354

DOCKET 40-8822 OMAHA PUBLIC POWER DISTRICT, OMAHA, NE

8408090127 IE Insp Findings & Licensee Ack on 840716-17 of License SMC-1420 Insp findings no violations observed
SPITZBERG,D B Region 4, Office of Director 84/07/17 2pp
25993 146

DOCKET 40-8829 WYOMING FUEL CO , LAKEWOOD, CO

8408240395 Reviews draft EIA re source matl license for Wyoming Fuel Co Document should be entitled "Draft Environ Assessment" rather than DES Conclusion should not foreshadow decision
BROWN,W L Region 4, Office of Director 84/07/27 SMITH,R D
Uranium Recovery Field Office 3pp 26248 357

8408270099 Summary of 840716 informal public meeting w/State of NE,EPA & public interest groups in Crawford,NE re draft EIA for proposed Crow Butte project Appropriate comments will be incorporated into EIA
WASTLER,S L , HAWKINS,E F Uranium Recovery Field Office 84/08/08
Uranium Recovery Field Office 2pp 26277 291

DOCKET 40-8842 MINNESOTA, UNIV OF, MINNEAPOLIS, MN

8408010394 IE Insp Findings & Licensee Ack on 840710-11 of Licenses 22-00187-49,22-00187-08,22-00187-53,22-00218-31 & SUD-1434 Insp findings no violations observed
LYNCH,J L Region 3, Office of Director 84/07/11 1p 25866 062

DOCKET 40-8857 EVEREST MINERALS CORP , CONVERSE COUNTY, WY

8408280018 Forwards application for license to conduct production scale recovery & processing of natural U via in situ leaching operations at Highland Site in Converse County,WY "Highland In Situ U Project" also encl Fee paid
MAYS,W M Everest Minerals Corp 84/07/24 HAWKINS,E F Uranium
Recovery Field Office 4pp 26292 090

--8408280022 Application for license to conduct production scale recovery & processing of natural U via in situ leaching operations at Highland Site in Converse County,WY
MAYS,W M Everest Minerals Corp 84/07/17 2pp 26292 094

--8408280024 "Highland In Situ U Project " W/two oversize figures Aperture cards available in PDR
* Everest Minerals Corp 84/07/24 250pp 26292 096

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan,
Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000,
84/08/10,8408140426

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8405240290 Responds to 840424 memo for FEMA review of util request for delay in scheduling next full-scale emergency preparedness exercise at site until 841130 Delay acceptable
KRIMM,R Federal Emergency Management Agency 84/05/18
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 8pp 24614 336 24X Fiche 50-003,84/05/18,
8405240290

8408060349 Forwards revs to physical security plan Revs withheld (ref 10CFR73 21)
O'TOOLE,J D Consolidated Edison Co of New York, Inc 84/07/16
MURLEY,T E Region 1, Office of Director 1p. 25936 052 24X
Fiche,50-003,84/07/16,8408060349

8408150121 Forwards public version of revs to Book II to emergency procedures document,including App A, "Emergency Roster" & App B, "Con Ed Medical Dept,Consultants & Agencies "
O'TOOLE,J D Consolidated Edison Co of New York, Inc 84/07/16
MURLEY,T E Region 1, Office of Director 2pp 26104 258 24X
Fiche 50-003,84/07/16,8408150121

--8408150125 Public version of revs to Book II to emergency procedures document,including App A, "Emergency Roster" & App B "Con Ed Medical Dept,Consultants & Agencies " W/JM Felton 840808 release memo
* Consolidated Edison Co of New York, Inc 84/06/29 21pp
26104 260 24X Fiche 50-003,84/07/16,8408150121

P Operating license stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408280333 Staff requirements memo re 840816 continuation of 840723 discussion of issues requiring resolution prior to issuance of order in proceeding Commission requested briefing on PRA including discussion of uncertainties & basis of comparison
CHILK, S J Office of the Secretary of the Commission 84/08/21
DIRCKS, W J Office of the Executive Director for Operations
ZERBE, J E Office of Policy Evaluations 2pp 26294 050 24X
Fiche 50-003, 84/08/21, 8408280333

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 83pp 26067 278 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26129 256 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26197 337 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

T Hearing transcripts on non-antitrust matters

8408280025 Transcript of 840816 Commission meeting in Washington, DC re continuation of 840723 discussion of adjudicatory proceeding Pp 1-76
* Commissioners 84/08/16 78pp 26293 169 24X
Fiche 50-003, 84/08/16, 8408280025

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408030205 Requests application for renewal of License R-2, including environ rept, emergency plan, physical security plan & Tech Spec info, per 10CFR50 33 & 10CFR50 34 OL scheduled to expire on 850630
THOMAS, C O Standardization & Special Projects Branch 84/07/26
CUNNINGHAM, R G Pennsylvania State Univ , University Park, PA 7pp 25921 352 24X Fiche 50-005, 84/07/26, 8408030205

P Operating license stage documents & correspondence

8408030205 Requests application for renewal of License R-2, including environ rept, emergency plan, physical security plan & Tech Spec info, per 10CFR50 33 & 10CFR50 34 OL scheduled to expire on 850630
THOMAS, C O Standardization & Special Projects Branch 84/07/26
CUNNINGHAM, R G Pennsylvania State Univ , University Park, PA 7pp 25921 352 24X Fiche 50-005, 84/07/26, 8408030205

8408230267 Responds to 840726 ltr re renewal of License R-2 Documentation requested in ltr will be included in application for renewal of license to be submitted during First Quarter 1985
CUNNINGHAM, R G Pennsylvania State Univ , University Park, PA
84/08/10 THOMAS, C Standardization & Special Projects Branch 1p 26209 322 24X Fiche 50-005, 84/08/10, 8408230267

8408270327 Responds to 840612 ltr re notification of change in storage location of SNM Info acceptable
MARTIN, T T Division of Engineering & Technical Programs 84/08/22
CUNNINGHAM, R G Pennsylvania State Univ , University Park, PA
2pp 26243 278 24X Fiche 50-005, 84/08/22, 8408270327

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8404040169 Forwards exercise repts for LaSalle & Dresden offsite radiological emergency preparedness exercises conducted 820414-15 & 0629-30, respectively
KRIMM, R W Federal Emergency Management Agency 84/03/26
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 22883 122 24X Fiche 50-000, 84/03/26, 8404040169

--8404040172 Evaluation of State of IL full-scale emergency preparedness exercise plan, final rept
* Federal Emergency Management Agency 82/05/31 68pp
22883 124 24X Fiche 50-000, 84/03/26, 8404040169

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO, C J Region 3, Office of Director 84/08/07 REED, C
Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000, 84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV D Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR, D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J
Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000, 84/08/07, 8408130401

8408130289 Forwards FR notice of environ assessment & finding of no significant impact re 840405 & 26 requests for exemption of state & local govt participation in 840605 exercise
PAULSON, W A Operating Reactors Branch 5 84/08/10 FARRAR, D L
Commonwealth Edison Co 2pp 26010 262 24X Fiche 50-010, 84/08/10, 8408130289

--8408130298 Notice of environ assessment & finding of no significant impact re exemption from requirements of 10CFR50, App E re state & local govt participation at 840605 exercise
EISENHUT, D G Division of Licensing 84/08/10 1pp 26010 264
24X Fiche 50-010, 84/08/10, 8408130289

8408200281 Advises that 840803 Rev 15 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/08/14 FARRAR, D L
Commonwealth Edison Co 2pp 26133 023 24X Fiche 50-010, 84/08/14, 8408200281

8408210001 Forwards exemption from certain requirements of Section IV F 1 of App E to 10CFR50 for Dresden 840605 emergency preparedness exercise w/o full-scale participation by state & local govts in plume exposure pathway
PAULSON, W A Operating Reactors Branch 5 84/08/14 FARRAR, D L
Commonwealth Edison Co 3pp 26181 320 24X Fiche 50-010, 84/08/14, 8408210001

--8408210005 Exemption from Section IV F 1 of App E to 10CFR50 requiring full-scale emergency preparedness exercise at least annually, involving participation of state & local govts within plume exposure pathway emergency planning zone
EISENHUT, D G Division of Licensing 84/08/14 Commonwealth Edison Co 3pp 26181 323 24X Fiche 50-010, 84/08/14, 8408210001

8408230283 Revised emergency plan implementing procedures, including EPIP 100-C3 re generating station emergency plan log, replacing record of generating station emergency plan activities form W/840820 ltr
SCOTT, D J Commonwealth Edison Co 84/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 67pp 26207 295 24X
Fiche 50-010, 84/08/20, 8408230283

J Insurance & indemnity information

8408290038 Forwards Endorsement 158 to NELIA Policy NF-43 & Endorsement 134 to MAELU Policy MF-22
OSTER, J Commonwealth Edison Co 84/08/22 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 26291 251 24X
Fiche 50-010, 84/08/22, 8408290038

P Operating license stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8408030251 Ack receipt of 840622 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/84-05, 50-237/84-07 & 50-249/84-06
PAPERIELLO, C J Region 3, Office of Director 84/07/10 REED, C
Commonwealth Edison Co 1p 25917 226 24X Fiche 50-010, 84/07/10, 8408030251

--8408030252 Responds to NRC 840524 ltr re violations noted in IE Insp Repts 50-010/84-05, 50-237/84-07 & 50-249/84-06 Corrective actions sludge removed from Toledo & Joliet facilities Survey of sumps found no residual activity
FARRAR, D L Commonwealth Edison Co 84/06/22 KEPPLER, J G
Region 3, Office of Director 4pp 25917 227 24X
Fiche 50-010, 84/07/10, 8408030251

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC
NORELIUS, C E Region 3, Office of Director 84/08/03 REED, C
Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000, 84/08/03, 8408070066

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, 'Deliberate Circumventing of Station Health Physics Procedures ' Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26067 278 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, 84/08/08, 8408140344

8408300095 Forwards Insp Rpts 50-010/84-10, 50-237/84-12 & 50-249/84-11 on 840618-0726 & notice of violation
SHAFER, W D Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26307 201 24X Fiche 50-010, 84/08/08, 8408300095

--8408300099 Notice of violation from insp on 840618-0726
SHAFER, W D Region 3, Office of Director 84/08/08 1p
26307 203 24X Fiche 50-010, 84/08/08, 8408300095

--8408300108 Insp Rpts 50-010/84-10, 50-237/84-12 & 50-249/84-11 on 840618-0726 Noncompliance noted inadequate corrective action taken in response to Tech Spec violation re open submarine door in Unit 2 reactor bldg
TONGUE, T M , STASEK, S , ANDERSON, C D Region 3, Office of Director 84/08/07 11pp 26307 204 24X Fiche 50-010, 84/08/08, 8408300095

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments ' Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12pp 26129 256 24X Fiche 50-000, 84/08/10, 8408070376

8408160139 Ack receipt of 840730 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-010/84-09, 50-237/84-11 & 50-249/84-10
SHAFER, W D Region 3, Office of Director 84/08/10, REED, C
Commonwealth Edison Co 1p 26092 040 24X Fiche 50-010, 84/08/10, 8408160139

--8408160145 Responds to NRC 840703 ltr re noncompliance noted in IE Insp Repts 50-010/84-09, 50-237/84-11 & 50-249/84-10 Corrective actions special procedure for testing automatic function of master pilot valve incorporated into existing Cardox sys
FARRAR, D L Commonwealth Edison Co 84/07/30 KEPPLER, J G
Region 3, Office of Director 3pp 26092 041 24X
Fiche 50-010, 84/08/10, 8408160139

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26197 337 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12Opp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408300368 "Rept of Radioactive Effluents," Jan-June 1984 W/840815 ltr
SCOTT,D J Commonwealth Edison Co 84/06/30 KEPPLER,J G Region 3, Office of Director 17pp 26308 172 24X Fiche 50-010,84/06/30,8408300368

S Reportable occurrences, LERs & related correspondence

8408200501 LER 84-001-00 on 840717,unplanned radioactive release to discharge canal determined Caused by stagnant contaminated water & corrosion products flushed out into discharge canal New operating order & mod established W/840813 ltr
COYLE,L , SCOTT,D J Commonwealth Edison Co 84/08/13 4pp 26138 302 24X Fiche 50-010,84/08/13,8408200501

DOCKET 50-13 BABCOCK & WILCOX CO CRITICAL FACILITY

F Security, medical, emergency & fire protection plans

8408310068 Confirms arrangements made between JB Wahle & DA Pethick re 840531 mgt meeting in Atlanta,GA to apprise NRC of B&W organization & responsibilities of key radiation safety & safeguards mgt personnel Proposed agenda encl
STOHR,J P Region 2, Office of Director 84/05/29 ECKERT,J P Babcock & Wilcox Co 2pp 26334-343 24X Fiche 50-013,84/05/29,8408310068

P, Operating license stage documents & correspondence

8408150115 Application to amend License CX-10,to dismantle reactor & dispose of component parts Fee encl
OLSEN,A F Babcock & Wilcox Co 84/08/07 Standardization & Special Projects Branch 2pp 26073 274 24X Fiche 50-013, 84/08/07,8408150115

--8408150118 "Dismantling Plan for CX-10 Reactor "
* Babcock & Wilcox Co 84/07/31 30pp 26073 276 24X
Fiche 50-013,84/08/07,8408150115

DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

8408300293 "Annual Rept on Operation of Washington State Univ TRIGA Reactor,Jul 1983 - June 1984," W/840815 ltr
* Washington State Univ , Pullman, WA 84/06/30 6pp 26306 340 24X Fiche 50-027,84/06/30,8408300293

S Reportable occurrences, LERs & related correspondence

8408140461 Ack receipt of Part 21 rept re potentially defective personnel neutron dosimeters Requests resolution of problem, plans to disseminate info to potentially affected customers & steps planned or taken to prevent recurrence
BAER,R L Engineering & Generic Communications Branch 84/08/03
TODD,W E Siemens Gammasonics, Inc 3pp 26061 286 24X
Fiche 50-027,84/08/03,8408140461

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8408150573 Forwards IE Insp Rept 50-029/84-12 on 840626-29 No violations noted.
MARTIN,T T Division of Engineering & Technical Programs 84/07/26
HEIDER,L H Yankee Atomic Electric Co 2pp 26079 217 24X
Fiche 50-029,84/07/26,8408150573

--8408150580 IE Insp Rept 50-029/84-12 on 840626-29 No violations noted Major areas inspected status of programs for shift staffing & augmentation, public info, licensee audits & emergency worker protection
HOLTNER,E , CROCKER,H W Region 1, Office of Director 84/07/16
3pp 26079 219 24X Fiche 50-029,84/07/26,8408150573

8408070393 Submits info on schedule for implementing upgraded emergency operating procedures, per Suppl 1 to NUREG-0737 Schedule outline prepared to perform listed actions Upgraded procedures will be implemented prior to Cycle 19 operation
KAY,J A Yankee Atomic Electric Co 84/07/27 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 25945 246 24X
Fiche 50-029,84/07/27,8408070393

8408160073 Forwards Enforcement Conference Rept 50-029/84-16 on 840621
STAROSTECKI,R Division of Project & Resident Programs 84/07/27
HEIDER,L H Yankee Atomic Electric Co 2pp 26108 226 24X
Fiche 50-029,84/07/27,8408160073

--8408160082 IE Enforcement Conference Rept 50-029/84-16 on 840621 Major areas discussed failure to procedurally implement required security program compensatory measures Safeguards info deleted (ref 10CFR73 21)
EICHENHOLZ,H , KEIMIG,R , WENZINGER,E Region 1, Office of Director 84/07/27 4pp 26108 228 24X Fiche 50-029,84/07/27,8408160073

8408200476 Forwards IE Safeguards Insp Rept 50-029/84-09 on 840514-17 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/07/30
HEIDER,L H Yankee Atomic Electric Co 2pp 26138 283 24X
Fiche 50-029,84/07/30,8408200476

--8408200487 IE Safeguards Insp Rept 50-029/84-09 on 840514-17 No violations noted Major areas inspected security organization,security program audit & physical barriers Safeguards info deleted (ref 10CFR73 21 & 2 790)
MADDEN,W J , KEIMIG,R R Region 1, Office of Director 84/07/26
5pp 26138 285 24X Fiche 50-029,84/07/30,8408200476

8408140304 Revised emergency plan operating procedures,consisting of Rev 38 to table of contents, Rev 2 to OP-3343, "Release of Public Info Under Emergency Conditions" & Rev 1 to OP-3346, "Vital Computer Sys Operation Under Emergency Conditions "
* Yankee Atomic Electric Co 84/08/07 29pp 26043 150 24X
Fiche 50-029,84/08/07,8408140304

8408130350 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-029/84-06
STAROSTECKI,R Division of Project & Resident Programs 84/08/09
HEIDER,L H Yankee Atomic Electric Co 2pp 26010 245 24X
Fiche 50-029,84/08/09,8408130350

--8408130354 Responds to NRC 840613 ltr re violations noted in IE Safeguards Insp Rept 50-029/84-06 Corrective actions effectiveness of mgt control sys will be improved Safeguards info deleted (ref 10CFR73 21)
VANDENBURGH,D Yankee Atomic Electric Co 84/07/13 MURLEY,T E Region 1, Office of Director 3pp 26010 247 24X
Fiche 50-029,84/08/09,8408130350

8408270577 Forwards Insp Rept 50-029/84-07 on 840320-0630 No violations noted
STAROSTECKI,R Division of Project & Resident Programs 84/08/10
HEIDER,L H Yankee Atomic Electric Co 2pp 26256 068 24X
Fiche 50-029,84/08/10,8408270577

--8408270579 Insp Rept 50-029/84-07 on 840320-0630 No violations noted Major areas inspected licensee action on previous insp findings, operational safety verification reviews & reviews of plant events & LERs
EICHENHOLZ,H , WENZINGER,E Region 1, Office of Director
84/08/06 33pp 26256 070 24X Fiche 50-029,84/08/10,8408270577

8408240266 Forwards order correcting administrative error in 840612 order re licensee commitments on emergency response capability Order requires implementation to meet criteria of Table 1 of Suppl 1 to NUREG-0737 by 850901
PAULSON,W A Operating Reactors Branch 5 84/08/23 KAY,J A
Yankee Atomic Electric Co 3pp 26223 112 24X
Fiche 50-029,84/08/23,8408240266

--8408240281 Order confirming further licensee commitment on emergency response capability.Licensee required to complete implementation of upgraded emergency operations facility to meet criteria of Table 1 of Suppl 1 to NUREG-0737 by 850901
MIRAGLIA,F J Division of Licensing 84/08/23 Yankee Atomic Electric Co 4pp 26223 115 24X Fiche 50-029,84/08/23, 8408240266

8408130322 Change 6, consisting of Rev 5 to emergency plan
* Yankee Atomic Electric Co 84/08/31 175pp 26006 025 24X
Fiche 50-029, 84/08/31, 8408130322

8408220012 Rev 3 to Emergency Plan Implementing Procedure OP-3300, "Classification of Emergencies ' W/840817 transmittal ltr
* Yankee Atomic Electric Co 84/08/31 35pp 26193 203 24X
Fiche 50-029, 84/08/31, 8408220012

8408240153 Rev 6 to emergency plan
ST LAURENT, N N Yankee Atomic Electric Co 84/08/31 20pp
26228 185 24X Fiche 50-029, 84/08/31, 8408240153

P Operating license stage documents & correspondence

8408010141 Submits schedule to provide addl info requested in NRC 840725 ltr re YAEC-1300P, "RELAP5YA - Computer Program for LWR Sys Thermal-Hydraulic Analysis," submitted in response to TMI Action Item II K 3 30
KAY, J A Yankee Atomic Electric Co 84/07/25 CRUTCHFIELD D
Operating Reactors Branch 5 2pp 25855 182 24X
Fiche 50-029, 84/07/25, 8408010141

8408020039 Submits current status of updated SEP schedule containing intermediate milestones, per 831118 ltr in response to NRC 831006 request All scheduled items completed to date
KAY, J A Yankee Atomic Electric Co 84/07/26 CRUTCHFIELD, D
Operating Reactors Branch 5 5pp 25880 260 24X
Fiche 50-029, 84/07/26, 8408020039

8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers," omitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/07/31
KAY, J A Yankee Atomic Electric Co COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 25955 227 24X
Fiche 50-000, 84/07/31, 8408070099

8408070472 Forwards "Reactor Coolant Pump Operation During Small Break LOCA Transients at Yankee Nuclear Power Station," per TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pump" & Generic Ltr 83-32
THAYER, J K Yankee Atomic Electric Co 84/08/01 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 25941 011 24X
Fiche 50-029, 84/08/01, 8408070472

--8408070478 "Reactor Coolant Pump Operation During Small Break LOCA Transients at Yankee Nuclear Power Station "
LOOMIS, J N , PHILLIPS, J H , HUSAIN, A Yankee Atomic Electric Co
YAEC-1437 84/08/01 155pp 25941 013 24X
Fiche 50-029, 84/08/01, 8408070472

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140312 Responds to request for addl info re degraded grid voltage protection sys, clarifying installed second level undervoltage protection for number of relays & describing currently installed sys
KAY, J A Yankee Atomic Electric Co 84/08/07 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 26042 356 24X
Fiche 50-029, 84/08/07, 8408140312

8408130282 Forwards request for addl info re 840309, 13, 0615 & 0725 requests for exemption from App K requirements, to proceed w/evaluation of YAEC-1431-P
PAULSON, W A Operating Reactors Branch 5 84/08/08 KAY, J A
Yankee Atomic Electric Co 5pp 26008 340 24X
Fiche 50-029, 84/08/08, 8408130282

8408130358 Forwards SER re licensee 831105, 08 & 840113 responses to Generic Ltr 83-28, Item 4 3, "Automatic Shunt Trip for Scram Breakers " Loss of power will disable shunt trip & drop control rods No further action required
PAULSON, W A Operating Reactors Branch 5 84/08/09 KAY, J A
Yankee Atomic Electric Co 2pp 26010 067 24X
Fiche 50-029, 84/08/09, 8408130358

--8408130363 Safety evaluation re licensee 831105, 08 & 840113 responses to Generic Ltr 83-28, Item 4 3, "Automatic Shunt Trip for Scram Breakers " Item does not apply to facility No further action required
* Office of Nuclear Reactor Regulation, Director, 84/08/09 5pp
26010 069 24X Fiche 50-029, 84/08/09, 8408130358

8408160149 Forwards summary of 840717 meeting w/util in Bethesda, MD re 810531 exemption request from App K requirements Summary includes schedule of submittals in response to NRC questions & attendee list
PAULSON, W A Operating Reactors Branch 5 84/08/15 KAY, J A
Yankee Atomic Electric Co 8pp 26085 172 24X
Fiche 50-029, 84/08/15, 8408160149

8408210419 Forwards Rev 0 to CYGNA rept, "Main Steam/Feedwater Piping Analysis Rept " Rept addresses SEP Topic III-6 re safe shutdown sys piping outside vapor container
KAY, J A Yankee Atomic Electric Co 84/08/16 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 26178 196 24X
Fiche 50-029, 84/08/16, 8408210419

--8408210426 Rev 0 to "Main Steam/Feedwater Piping Analysis Rept, Yankee Nuclear Power Station "
NGUYEN, T , MINICHIELLO, J , STIJGEREN, E V CYGNA Energy Services
E-Y-YR-83033-4 R00 84/07/31 48pp 26178 197 24X
Fiche 50-029, 84/08/16, 8408210419

8408210573 Notification of 840823 meeting w/util in Bethesda, MD to discuss SEP schedule
BOYLE, M L Systematic Evaluation Program Branch 84/08/16
GRIMES, C I Systematic Evaluation Program Branch 2pp 26187 361
24X Fiche 50-029, 84/08/16, 8408210573

8408230162 Forwards response to concerns re staff review of proposed Change 180 concerning containment isolation sys, per request Test, vent & drain connections reviewed to determine isolation
KAY, J A Yankee Atomic Electric Co 84/08/16 CRUTCHFIELD, D
Operating Reactors Branch 5 5pp 26209 277 24X
Fiche 50-029, 84/08/16, 8408230162

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8408100053 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays Used in Class IE Safety Sys " HFA relays having coils wound on nylon or Lexan spools replaced w/new GE Century Series HFA relays having Tefzel spool
HEIDER, L H Yankee Atomic Electric Co 84/07/23 MURLEY, T E
Region 1, Office of Director 2pp 25990 036 24X
Fiche 50-029, 84/07/23, 8408100053

8408150573 Forwards IE Insp Rept 50-029/84-12 on 840626-29 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/07/26
HEIDER, L H Yankee Atomic Electric Co 2pp 26079 217 24X
Fiche 50-029, 84/07/26, 8408150573

--8408150580 IE Insp Rept 50-029/84-12 on 840626-29 No violations noted Major areas inspected status of programs for shift staffing & augmentation, public info, licensee audits & emergency worker protection
WOLTNER, E , CROCKER, H W Region 1, Office of Director 84/07/16
3pp 26079 219 24X Fiche 50-029, 84/07/26, 8408150573

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408160073 Forwards Enforcement Conference Rept 50-029/84-16 on 840621
STAROSTECKI, R Division of Project & Resident Programs 84/07/27
HEIDER, L H Yankee Atomic Electric Co 2pp 26108 226 24X
Fiche 50-029, 84/07/27, 8408160073

--8408160082 IE Enforcement Conference Rept 50-029/84-16 on 840621 Major areas discussed failure to procedurally implement required security program compensatory measures Safeguards info deleted (ref 10CFR73 21).
EICHENHOLZ, H , KEIMIG, R , WENZINGER, E Region 1, Office of Director 84/07/27 4pp 26108 228 24X Fiche 50-029, 84/07/27, 8408160073

8408200476 Forwards IE Safeguards Insp Rept 50-029/84-09 on 840514-17 No violations noted
MARTIN, T T Division of Engineering & Technical Programs. 84/07/30
HEIDER, L H Yankee Atomic Electric Co 2pp. 26138 283 24X
Fiche 50-029, 84/07/30, 8408200476

--8408200487 IE Safeguards Insp Rept 50-029/84-09 on 840514-17 No violations noted Major areas inspected security organization, security program audit & physical barriers Safeguards info deleted (ref 10CFR73 21 & 2 790)
MADDEN, W J , KEIMIG, R R Region 1, Office of Director 84/07/26
5pp 26138 285 24X Fiche 50-029, 84/07/30, 8408200476

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408130350 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-029/84-06
STAROSTECKI, R Division of Project & Resident Programs 84/08/09
HEIDER, L H Yankee Atomic Electric Co 2pp 26010 245 24X
Fiche 50-029, 84/08/09, 8408130350

--8408130354 Responds to NRC 840613 ltr re violations noted in IE Safeguards Insp Rept 50-029/84-06 Corrective actions effectiveness of mgt control sys will be improved Safeguards info deleted (ref 10CFR73 21)
VANDENBURGH, D Yankee Atomic Electric Co 84/07/13 MURLEY, T E
Region 1, Office of Director 3pp 26010 247 24X
Fiche 50-029, 84/08/09, 8408130350

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408270577 Forwards Insp Rept 50-029/84-07 on 840320-0630 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/10
HEIDER, L H Yankee Atomic Electric Co 2pp 26256 068 24X
Fiche 50-029, 84/08/10, 8408270577

--8408270579 Insp Rept 50-029/84-07 on 840320-0630 No violations noted Major areas inspected licensee action on previous insp findings, operational safety verification reviews & reviews of plant events & LERs
EICHENHOLZ, H , WENZINGER, E Region 1, Office of Director
84/08/06 33pp 26256 070 24X Fiche 50-029, 84/08/10, 8408270577

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408300107 Forwards Insp Rept 50-029/84-14 on 840709-13 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/08/13
HEIDEN, L H Yankee Atomic Electric Co 2pp 26308 107 24X
Fiche 50-029, 84/08/13, 8408300107

--8408300116 Insp Rept 50-029/84-14 on 840709-13 No violations noted Major areas inspected actions in response to IE Bulletins 79-02 re pipe support design, 79-04 re swing check valves & 79-07 & 79-14 re seismic analysis of piping
NARROW, L , DURR, J P Region 1, Office of Director 84/08/05
7pp 26308 109 24X Fiche 50-029, 84/08/13, 8408300107

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Uderrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408070205 PNO-I-84-065 on 840802, personnel noted smoke coming from cubicle in switchgear room Caused by tripped breaker due to electrical fault during surveillance testing Damaged bus deenergized Licensee decreasing power for plant shutdown
ELSASSER, T , GREENMAN, E Region 1, Office of Director 84/08/02
2pp 25949 268 24X Fiche 50-029, 84/08/02, 8408070205

8408090104 LER 84-011-00 on 840703, during review of documentation accompanying recent replacement of two pressurizer code safety valves, determined lift setpoint of safety valve PR-SV-182 exceeded Tech Specs W/840802 ltr
ELLIS, D W , ST LAURENT, N N Yankee Atomic Electric Co 84/08/02
3pp 25992 239 24X Fiche 50-029, 84/08/02, 8408090104

8408210350 Forwards LER 84-011-00
ST LAURENT, N N Yankee Atomic Electric Co 84/08/02 MURLEY, T E
Region 1, Office of Director 1p 26179 195 24X
Fiche 50-029, 84/08/02, 8408210350

8408100035 PNO-I-84-065A on 840802, plant shut down following switchgear fire Cause unidentified Extensive bus & switchgear damage found Corrective actions will be monitored
ASARO, A , FERLIC, K Region 1, Office of Director 84/08/03 1p
25990 060 24X Fiche 50-029, 84/08/03, 8408100035

8408160529 LER 84-012-00 on 840712, automatic reactor scram followed by turbine trip, cross tie of ctr bus via 620TX relay & start of emergency diesel generator 2 occurred Cause Indeterminable Effects of scram mitigated W/840810 ltr
MAY, E L , ST LAURENT, N Yankee Atomic Electric Co 84/08/10 2pp
26108 040 24X Fiche 50-029, 84/08/10, 8408160529

8408300441 Forwards LER 84-012-00
ST LAURENT, N N Yankee Atomic Electric Co 84/08/10 MURLEY, T E
Region 1, Office of Director 1p 26314 215 24X
Fiche 50-029, 84/08/10, 8408300441

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/08/16
EISENHUT, D G Division of Licensing 20pp 26233 249 24X
Fiche 50-000, 84/08/16, 8408230077

8408230540 LER 84-011-01 on 840703, during documentation review, lift setpoint of safety valve PR-SV-182 found to exceed Tech Spec tolerance Cause not stated Proposed Tech Spec change will be submitted W/840817 ltr
ELLIS, D W , ST LAURENT, N N Yankee Atomic Electric Co 84/08/17
3pp 26212 353 24X Fiche 50-029, 84/08/17, 8408230540

DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

P Operating license stage documents & correspondence

8408210629 Advises that Licenses TR-3 & R-93 should be reinstated to prior possess-but-not-use status or revised dismantlement plans should be submitted, per 10CFR50 82 or 10CFR50 90, respectively Plans should update mgt controls
THOMAS, C O Standardization & Special Projects Branch 84/06/26
RICHLEY, E A National Aeronautics & Space Admin 3pp 26187 357
24X Fiche 50-030, 84/06/26, 8408210629

W Decommissioning Stage Documents & Correspondence

8408240107 Requests submittal of either request for reinstatement of possess but-not-use license or revised dismantlement plan w/schedule commitments Dismantlement authorized in 1981 delayed by lack of funds
THOMAS,C O Standardization & Special Projects Branch 84/08/16
RICHLEY,E A National Aeronautics & Space Admin 5pp 26255 313
24X Fiche 50-030,84/08/16,8408240107

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8408270510 Forwards Insp Repts 50 054/84-02 & 70-0687/84-02 on 840709-11 No violations observed
STAROSTECKI,R Division of Project & Resident Programs 84/08/07
MCGOVERN,J J Union Carbide Corp 2pp 26256 162 24X
Fiche 50-054,84/08/01,8408270510

--8408270518 Insp Repts 50-054/84-02 & 70-0687/84-02 on 840709-11 No deviations or violations identified Major areas inspected organization,facility changes & mods,safety committees, nuclear criticality safety & radiation protection
ROTH,J Region 1, Office of Director ELSASSER,T C Division of Project & Resident Programs 84/08/02 6pp 26256 164 24X
Fiche 50-054,84/08/07,8408270510

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408060162 Forwards Rev 1 to "Nuclear Science & Technology Facility Emergency Plan " Amend request will be forwarded upon completion & approval by nuclear safety committee
HENRY,L G New York, State Univ of, Buffalo, NY 84/07/31
THOMAS,C Standardization & Special Projects Branch 1p
25933 013 24X Fiche 50-057,84/07/31,8408060162

--8408060167 Rev 1 to "Nuclear Science & Technology Facility Emergency Plan "
* New York, State Univ of, Buffalo, NY 84/07/31 36pp
25933 014 24X Fiche 50-057,84/07/31,8408060162

DOCKET 50-59 TEXAS A&M UNIV RESEARCH REACTOR

R Periodic operating reports & related correspondence

8408150371 "Annual Operations Rept of Texas A&M Univ AGN-201M Training Reactor,June 1983 - May 1984 " W/840706 ltr
CARPENTER,D C , ERDMAN,C A Texas A&M Univ , College Station, TX
84/05/31 COLLINS,J Region 4, Office of Director 10pp
26075 191 24X Fiche 50-059,84/05/31,8408150371

DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408010391 Forwards revised emergency plan,incorporated addl info,per request Info should resolve plan prior deficiencies Univ of Virginia reactor safety committee will review plan Approval expected
MULDER,R U Virginia, Univ of, Charlottesville, VA 84/07/12
THOMAS,C O Standardization & Special Projects Branch 1p
25866 063 24X Fiche 50-062,84/07/12,8408010391

8408010350 Resubmits 840712 request for approval of emergency plan Ltr notarized per request Univ of Virginia reactor safety committee reviewed & approved emergency plan on 840725
MULDER,R U Virginia, Univ of, Charlottesville, VA 84/07/26
THOMAS,C O Standardization & Special Projects Branch 1p
25866 307 24X Fiche 50-062,84/07/26,8408010350

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

Q Adjudicatory correspondence

8408060183 Responses to GE & NRC filings re California PIRG participation in proceeding
BARLOW,G Public Interest Research Group, California DSB 749
84/07/30 6pp 25932 253 24X Fiche 50-070,84/07/30,8408060183

8408060191 Revised contentions & responses to ASLB 810703 order re participation in proceeding
BARLOW,G Public Interest Research Group California 84/07/31
Atomic Safety and Licensing Board Panel 20pp 25932 259 24X
Fiche 50-070,84/07/30,8408060183

--8408060197 Declaration of California PIRG members Notice of appearance encl
BAISEL,J MEEK,S , BARLOW,G Public Interest Research Group, California 84/07/26 3pp 25932 279 24X Fiche 50-070
84/07/30 8408060183

--8408060206 Request for readmission to proceedings Statement of correct address & Certificate of Svc encl
BARLOW,G Public Interest Research Group, California 84/06/08
Commissioners 4pp 25932 282 24X Fiche 50-070,84/07/30,
8408060183

8408060209 Submittal of new info re 840424 Morgan Hill earthquake Request to consolidate party opposed
TURK,J Turk, J DSB 748 84/07/31 Atomic Safety and Licensing Board Panel 14pp 25923 310 24X Fiche 50-070,84/07/31,
8408060209

8408220288 Prehearing conference order directing staff,GE & J Turk to confer re contentions & rept results by 841119 & California PIRG to serve & file chronology of events re involvement by 840907 Served on 840821
LINENBERGER,C , FRYE,J H Atomic Safety and Licensing Board Panel
DSB 205 84/08/20 Office of the Executive Legal Director 51pp
26193 084 24X Fiche 50-070,84/08/20,8408220288

T Hearing transcripts on non-antitrust matters

8408140269 Transcript of 840809 hearing in San Francisco,CA Pp 1-230
* Atomic Safety and Licensing Board Panel 84/08/09 231pp
26055 074 24X Fiche 50-070,84/08/09,8408140269

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

P Operating license stage documents & correspondence

8408090335 Forwards "Proposed Tech Specs for GE Nuclear Test Reactor," per 840601 request New License Condition 2 B also encl
CUNNINGHAM,C E General Electric Co 84/08/02 THOMAS,C O
Standardization & Special Projects Branch 3pp 25971 097 24X
Fiche 50-073,84/08/02,8408090335

--8408090337 "Proposed Tech Specs for GE Nuclear Test Reactor "
* General Electric Co NEDO-12729A 84/07/31 51pp 25971 060
24X Fiche 50-073,84/08/02,8408090335

DOCKET 50-89 GENERAL ATOMIC CO

F Security, medical, emergency & fire protection plans

8408270311 Forwards ltrs documenting cooperation w/local law enforcement agencies & medical facilities re radiological contingency plan
MOWRY,W R GA Technologies, Inc /General Atomic Co 84/08/22
CUNNINGHAM,R Division of Fuel Cycle & Material Safety THOMAS,C O
Standardization & Special Projects Branch 4pp 26241 004 24X
Fiche 50-089,84/08/22,8408270311

P Operating license stage documents & correspondence

8405160470 Forwards Amend 25 & 31 to Licenses R-38 & R-67,respectively & notice of issuance & availability Amends change corporate name of licensee to GA Technologies,Inc
EISENHUT,D G Division of Licensing 84/04/27 MOWRY,W R GA
Technologies, Inc /General Atomic Co 3pp 24492 253 24X
Fiche 50-089,84/04/27,8405160470

--8405160473 Amends 25 & 31 to Licenses R-38 & R-67,respectively,changing corporate name of licensee to GA Technologies,Inc
EISENHUT,D G Division of Licensing 84/04/27 4pp 24492 256
24X Fiche 50-089,84/04/27,8405160470

--8405160476 Notice of issuance & availability of Amends 25 & 31 to Licenses R-38 & R-67,respectively
THOMAS,C O Standardization & Special Projects Branch 84/04/27
2pp 24492 260 24X Fiche 50-089,84/04/27,8405160470

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

F Security, medical, emergency & fire protection plans

8408210097 Forwards "Emergency Plan Evaluation Rept, Cornell Univ " Plan meets requirements of regulations & guidelines & is acceptable
THOMAS, C O Standardization & Special Projects Branch 84/08/15
CLARK, D D Cornell Univ , Ithaca, NY 3pp 26195 213 24X
Fiche 50-097, 84/08/15, 8408210097

--8408140349 "Emergency Plan Evaluation Rept, Cornell Univ "
* Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/31 4pp 26195 216 24X Fiche 50-097, 84/08/15, 8408210097

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408030066 Ack receipt of ltr approving emergency plan Plan implementation begun Requests extension for completion until 841130
JENSEN, C M Oklahoma, Univ of, Norman, OK 84/07/24 THOMAS, C O Standardization & Special Projects Branch 1p 25917 322 24X
Fiche 50-112, 84/07/24, 8408030066

DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408210101 Forwards "Emergency Plan Evaluation Rept, Iowa State Univ " Evaluation revised to correctly describe status of facility Plan meets requirements of regulations & guidelines & is acceptable
THOMAS, C O Standardization & Special Projects Branch 84/08/14
HENDRICKSON, R Iowa State Univ , Ames, IA 3pp 26195 345 24X
Fiche 50-116, 84/08/14, 8408210101

--8408210117 Revised "Emergency Plan Evaluation Rept, Iowa State Univ "
* Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/31 3pp 26195 348 24X Fiche 50-116, 84/08/14, 8408210101

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

P Operating license stage documents & correspondence

8408020056 Forwards Application Request 84-01 for amend to License DPR-7, reflecting plans for facility decommissioning & maint of safe storage condition for 30 yrs before ultimate removal Fee encl
SCHUYLER, J O Pacific Gas & Electric Co 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25894 245
24X Fiche 50-133, 84/07/30, 8408020056

--8408020063 Application Request 84-01 for amend to License DPR-7, reflecting plans for facility decommissioning & maint of safe storage condition for 30 yrs before ultimate removal Two Bechtel decommissioning repts encl
SCHUYLER, J O Pacific Gas & Electric Co 84/07/30 4pp
25894 247 24X Fiche 50-133, 84/07/30, 8408020056

--8408020067 "SAFSTOR Decommissioning "
* Pacific Gas & Electric Co 84/07/30 394pp 25894 251 24X
Fiche 50-133, 84/07/30, 8408020056

--8408020070 "For Decommissioning of Humboldt Bay Power Plant, Unit 3," environ rept
AUSMUS, B S , HOFMAN, L A TRINOSKEY, P A Bechtel Corp 84/07/31
492pp 25895 285 24X Fiche 50-133, 84/07/30, 8408020056

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26069 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408060146 Forwards "Emergency Plan Evaluation Rept, Worcester Polytechnic Inst " Plan meets requirements of 10CFR50, App E & ANSI/ANS-15 16-1982 Full implementation requested within 120 days of ltr receipt
THOMAS, C O Standardization & Special Projects Branch 84/07/26
WILBUR, L C Worcester Polytechnic Institute, Worcester, MA 3pp
25936 344 24X Fiche 50-134, 84/07/26, 8408060146

--8408060160 "Emergency Plan Evaluation Rept, Worcester Polytechnic Inst "
* NRC - No Detailed Affiliation Given 84/07/31 3pp
25936 347 24X Fiche 50-134, 84/07/26, 8408060146

DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408170040 Forwards amend to security plan Amend withheld (ref 10CFR73 21)
ROSKIN, M A Washington, Univ of, Seattle, WA 84/07/27 Office of Nuclear Material Safety & Safeguards, Director 1p 26118 357
24X Fiche 50-139, 84/07/27, 8408170040

DOCKET 50-142 UCLA TRAINING REACTOR

F Security, medical, emergency & fire protection plans

8408210161 Forwards IE Safeguards Insp Rept 50-142/84-01 on 840320-21 & 0604-07 No violations noted
SCHUSTER, M D Region 5, Office of Director 84/07/26 WEGST, W
California, Univ of, Los Angeles, CA 1p 26180 353 24X
Fiche 50-142, 84/07/26, 8408210161

--8408210167 IE Safeguards Insp Rept 50-142/84-01 on 840320-21, 0604-07 & 0716 No violations noted Major areas inspected security plan & procedures, access control, alarm sys, locks & surveillance Details withheld (ref 10CFR2 790)
NORDERHAUG, L R , SCHAFFER, D , SCHUSTER, M D Region 5, Office of Director 84/07/26 1p 26180 354 24X Fiche 50-142, 84/07/26, 8408210161

G Adjudicatory correspondence

8408010207 Reply to Committee to Bridge the Gap 840703 response to univ 840614 request to withdraw application for renewal of license ASLB should grant univ request for withdrawal Certificate of Svc encl
WOODHEAD, C P Hearing Branch 4 DSB 679 84/07/27 Atomic Safety and Licensing Board Panel 9pp 25855 173 24X
Fiche 50-142, 84/07/27, 8408010207

8408070386 Response opposing staff proposed conditions for UCLA withdrawal of license renewal application ASLB should follow required practice consistent w/NRC case law Certificate of Svc encl
HIRSCH, D Committee to Bridge the Gap DSB 801 84/08/01
Atomic Safety and Licensing Board Panel 83pp 25945 280 24X
Fiche 50-142, 84/08/01, 8408070386

8408070474 Informs of unsuccessful attempts to reach Jill Frye to inform of delay in pleading re UCLA reactor renewal due to breakdown of typewriter Pleading sent out by express mail to ensure prompt delivery Related correspondence
HIRSCH, D Committee to Bridge the Gap DSB 805 84/08/01
FRYE, J H Atomic Safety and Licensing Board Panel 1p 25940 342
24X Fiche 50-142, 84/08/01, 8408070474

8408080239 Memorandum & order requesting further elaboration of staff position re applicability of Atomic Energy Act, Section 189 to UCLA request to decommission reactor & terminate license, by 840907 Served on 840806,
FRYE, J H Atomic Safety and Licensing Board Panel DSB 829
84/08/06 Office of the Executive Legal Director 2pp
25967 063 24X Fiche 50-142, 84/08/06, 8408080239

8408310209 Requests prompt notification when petitions for leave to intervene & for hearing may be formally filed on proposed parallel license amends & related 10CFR50 82 dismantlement/ license termination application
HIRSCH, D Government Accountability Project DSB 425 84/08/25
Office of the Secretary of the Commission 3pp 26318 064 24X
Fiche 50-142, 84/08/25, 8408310209

P Operating license stage documents & correspondence

8408310152 FOIA request for all correspondence or other documents between UCLA & NRC re incident occurring in early Feb 1984, which led to current shutdown of UCLA research reactor
HIRSCH, D Committee to Bridge the Gap 84/04/24 Office of Administration 1p 26351 356 24X Fiche 50-142, 84/04/24, 8408310152

8408310151 Responds to FOIA request for documents between UCLA & NRC re current reactor shutdown & records re proposed work to be performed during shutdown Forwards WF Wegst 840213 ltr to NRC
FELTON, J M Division of Rules and Records 84/06/04 HIRSCH, D
Committee to Bridge the Gap 1p 26351 355 24X
Fiche 50-142, 84/06/04, 8408310151

8408010339 Application to terminate License R-71 Request for amend to Tech Specs to provide immediate relief from reactor calibr, maint & reporting requirements will be submitted separately
WEGST, W F California, Univ of, Los Angeles, CA 84/07/26
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25864 072 24X Fiche 50-142, 84/07/26, 8408010339

8408270142 Forwards M Gonzalez-Cuesta memo re assessment of risk from seismic errors in design & const, per 840810 telcon
OKRENT, D California, Univ of, Los Angeles, CA 84/08/13
DEYOUNG, R Director's Office, Office of Inspection and Enforcement
8pp 26257 290 24X Fiche 50-142, 84/08/13, 8408270142

G Inspection reports, IE Bulletins & correspondence

8408210161 Forwards IE Safeguards Insp Rept 50-142/84-01 on 840320-21 & 0604-07 No violations noted
SCHUSTER, M D Region 5, Office of Director 84/07/26 WEGST, W
California, Univ of, Los Angeles, CA 1p 26180 353 24X
Fiche 50-142, 84/07/26, 8408210161

--8408210167 IE Safeguards Insp Rept 50-142/84-01 on 840320-21, 0604-07 & 0716 No violations noted Major areas inspected security plan & procedures, access control, alarm sys, locks & surveillance Details withheld (ref 10CFR2 790)
NORDERHAUG, L R , SCHAEFER, D , SCHUSTER, M D Region 5, Office of Director 84/07/26 1p 26180 354 24X Fiche 50-142, 84/07/26, 8408210161

R Periodic operating reports & related correspondence

8408300109 "Annual Rept 1983, Nuclear Energy Lab " W/830821 ltr
OSTRANDER, N C California, Univ of, Los Angeles, CA 83/12/31
16pp 26314 335 24X Fiche 50-142, 83/12/31, 8408300109

DOCKET 50-150 OHIO STATE UNIV RESEARCH REACTOR

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408010302 Forwards IE Insp Repts 50-151/84-01 & 50-356/84-01 on 840619-22 No noncompliance noted
NORELIUS, C E Region 3, Office of Director 84/07/19 MILEY, G H
Illinois, Univ of, Urbana, IL 2pp 25866 117 24X
Fiche 50-151, 84/07/19, 8408010302

--8408010308 IE Insp Repts 50-151/84-01 & 50-356/84-01 on 840619-22, No noncompliance noted Major areas inpected requalification training fuel handling & surveillance activities, radiation control practices & emergency planning
TAUBLING, T N Region 3, Office of Director THOMAS, C C ,
HYDER, J E, Los Alamos Scientific Laboratory 84/07/18 10pp
25866 119 24X Fiche 50-151, 84/07/19, 8408010302

8408030276 Certifies nuclear reactor committee formal approval of additions & changes to emergency plan on 840723 Last sentence in Section 3 4 3 changed for clarity
BECK, G P , HOPKE, P K , MILEY, G H Illinois, Univ of, Urbana, IL
84/07/24 THOMAS, C O Standardization & Special Projects Branch
1p 25917 258 24X Fiche 50-151, 84/07/24, 8408030276

O Inspection reports, IE Bulletins ' correspondence

8408010302 Forwards IE Insp Repts 50-151/84-01 & 50-356/84-01 on 840619-22 No noncompliance noted
NORELIUS, C E Region 3, Office of Director 84/07/19 MILEY, G H Illinois, Univ of, Urbana, IL 2pp 25866 117 24X Fiche 50-151, 84/07/19, 8408010302

--8408010308 IE Insp Repts 50-151/84-01 & 50-356/84-01 on 840619-22 No noncompliance noted Major areas inpected requalification training fuel handling & surveillance activities, radiation control practices & emergency planning
TAUBLING, T N Region 3, Office of Director THOMAS, C C , HYDER, J E Los Alamos Scientific Laboratory 84/07/18 10pp 25866 119 24X Fiche 50-151, 84/07/19, 8408010302

S Reportable occurrences, LERs & related correspondence

8408300184 RO on 840816, fast transient control rod remained in withdrawn position 20 s after air released Caused by swelling of control rod Nylon piece removed & replaced Section of rod where air supplied cleaned
BECK, G P , STUBBINS, J F Illinois, Univ of, Urbana, IL 84/08/24 Record Services Branch (Document Control Desk) 1p 26308 356 24X Fiche 50-151, 84/08/24, 8408300184

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26031 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8408210498 Responds to NRC 840601 ltr approving util 840417 request for schedule change for 1984 annual medical exercise Annual medical exercise scheduled for 841030-31
KRICH, R M Consumers Power Co 84/06/28 KEPPLER, J G Region 3, Office of Director 1p 26148 174 24X Fiche 50-155, 84/06/28, 8408210498

8408070368 Advises of FEMA 840706 completion of analysis of alert notification sys Sys adequate eliminating caveat in FEMA 830516 finding FEMA rept encl Related correspondence
GODDARD, R J Hearing Branch 3 DSB 817 84/08/02 BLOCH, P B , PARIS, O H , SHON, F J Atomic Safety and Licensing Board Panel 72pp 25944 210 24X Fiche 50-155, 84/08/02, 8408070368

8408130370 Responds to 840711 ltr re access authorization program Access authorization list development & maint functions being transferred to Div of Resource Mgt Notification of terminated employees will be on as needed basis
AXELSON, W L Region 3, Office of Director 84/08/09
VANDEWALLE, D J Consumers Power Co 1p 26010 359 24X Fiche 50-000, 84/08/09, 8408130370

--8408130376 Submits list of items discussed in 840703 telcon No termination notifications received Updates on activities will be submitted Concurrence needed for documentation
LATHWELL, M J Consumers Power Co 84/07/11 CREED, J Region 3, Office of Director 2pp 26010 359 24X Fiche 50-000, 84/08/09, 8408130370

8408140130 Ack receipt of 831216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/82-13
LITTLE, W S Region 3, Office of Director 84/08/10 DEWITT, R B Consumers Power Co 1p 26047 011 24X Fiche 50-155, 84/08/10, 8408140130

8408270390 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-155/84-03
PAPERIELLO, C J Region 3, Office of Director 84/08/22
DEWITT, R B Consumers Power Co 2pp 26240 197 24X
Fiche 50-155, 84/08/22, 8408270390

--8408270392 Responds to NRC 840627 ltr re violations noted in Insp Rept 50-155/84-03 Corrective actions site emergency plan implementing procedure reporting time requirements revised, following 840222 incident
VANDEWALLE, D J Consumers Power Co 84/07/27 KEPPLER, J G Region 3, Office of Director 3pp 26240 199 24X
Fiche 50-155, 84/08/22, 8408270390

G Adjudicatory correspondence

8408010260 Forwards affidavits of F Turski & C Norman, in response to request made by Judge Bloch during 840713 & 16 telcons re clarification of relationship between 1 ton jib crane & 75 ton gantry crane Related correspondence
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Consumers Power Co DSB 673 84/07/30 BLOCH, P B , SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 2pp 25854 071 24X
Fiche 50-155, 84/07/30, 8408010260

--8408010263 Affidavit of A Turski re relationship between 1 ton jib crane & 75 ton single gantry crane in context of seismic events
TURSKI, F A Consumers Power Co 84/07/20 7pp 25854 073 24X
Fiche 50-155, 84/07/30, 8408010260

--8408010269 Affidavit of CR Norman re relationship between 1 ton jib crane & 75 ton single leg gantry crane in context of seismic event
NORMAN, C R Whiting Corp NORMAN, C R Consumers Power Co 84/07/23 Atomic Safety and Licensing Board Panel 9pp 25854 080 24X Fiche 50-155, 84/07/30, 8408010260

8408070368 Advises of FEMA 840706 completion of analysis of alert notification sys Sys adequate eliminating caveat in FEMA 830516 finding FEMA rept encl Related correspondence
GODDARD, R J Hearing Branch 3 DSB 817 84/08/02 BLOCH, P B , PARIS, O H , SHON, F J Atomic Safety and Licensing Board Panel 72pp 25944 210 24X Fiche 50-155, 84/08/02, 8408070368

8408080224 Forwards Whiting Corp 840727 rept re analysis of structural adequacy of jib crane to withstand seismic event Rept referenced in 840730 response to ASLB request for clarification re jib crane/gantry crane relationship
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Consumers Power Co DSB 823 84/08/06 BLOCH, P B , PARIS, O H , SHON, F J Atomic Safety and Licensing Board Panel 16pp 25967 034 24X
Fiche 50-155, 84/08/06, 8408080224

8408210327 Motion for show cause order on whether util financially qualified to safely modify & maintain modified spent fuel pool as proposed
O'NEILL, J O'Neill, J DSB 179 84/08/15 Office of Nuclear Reactor Regulation, Director 4pp 26179 274 24X
Fiche 50-155, 84/08/15, 8408210327

--8408210330 Motion for enforcement of Atomic Energy Act & 10CFR50 33(f) re whether util financially qualified to safely modify & maintain modified spent fuel pool Certificate of Svc encl
O'NEILL, J O'Neill, J 84/08/15 Atomic Safety and Licensing Board Panel 18pp 26179 278 24X Fiche 50-155, 84/08/15, 8408210327

--8408210337 Motion for default against staff re ability of monitors to operate during accident conditions, inadequate address of root cause of multiple systematic errors & possibility of further errors Certificate of Svc encl
O'NEILL, J O'Neill, J 84/08/14 Atomic Safety and Licensing Board Panel 2pp 26179 296 24X Fiche 50-155, 84/08/15, 8408210327

8408270164 Forwards affidavit of NC Chokshi attesting to adequacy of seismic stability of jib crane issue raised during hearings on seismic adequacy of util semigantry crane in 1983 Related correspondence
GODDARD, R J Hearing Branch 3 DSB 305 84/08/22 BLOCH, P B , SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 1p 26246 089 24X Fiche 50-155, 84/08/22, 8408270164

--8408270170 Affidavit of NC Chokshi attesting to adequacy of seismic stability of jib crane, issue raised during hearings on seismic adequacy of util semigantry crane in 1983 Related correspondence
CHOKSHI, N C Hydrologic & Geotechnical Engineering Branch 84/08/22 3pp 26246 090 24X Fiche 50-155, 84/08/22, 8408270164

8408280244 Motion re violation of full disclosure requirement Documents detailing number of areas in which full disclosure requirements violated & Certificates of Svc encl Related correspondence
O'NEILL, J P O'Neill, J DSB 324 84/08/22 Atomic Safety and Licensing Board Panel 5pp 26279 206 24X Fiche 50-155, 84/08/22, 8408280244

8408280391 Memorandum & order deciding three motions filed by J O'Neill in 840625 document, including motion to strike testimony of R Krich, relief from alleged violation of full disclosure requirement & financial qualifications Served on 840828
BLOCH, P B , SHON, F J Atomic Safety and Licensing Board Panel DSB 350 84/08/27 O'NEILL, J O'Neill, J 4pp 26280 034 24X
Fiche 50-155, 84/08/27, 8408280391

8408300152 Initial Decision 79-432-11 LA on all remaining issues, including Christa-Maria Contention 8 & O'Neill Contention IIIE-2 re reliability of makeup water sys Served on 840829
* Atomic Safety and Licensing Board Panel DSB 387 84/08/29 279pp 26302 240 24X Fiche 50-155, 84/08/29, 8408300152

P Operating license stage documents & correspondence

8408030109 Forwards application for amend to DPR-6, revising Tech Specs re administrative controls & definitions per NRC request
VANDEWALLE, D J Consumers Power Co 84/07/30 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 25916 087 24X
Fiche 50-155, 84/07/30, 8408030109

--8408030113 Application for amend to DPR-6, revising Tech Specs re administrative controls & definitions to reflect 10CFR90 72 & 90 73 reporting requirements
REYNOLDS, J W Consumers Power Co 84/07/30 2pp 25916 088
24X Fiche 50-155, 84/07/30, 8408030109

--8408030116 Proposed Tech Specs, Section 1 2 re definitions & 6 0 re administrative controls
* Consumers Power Co 84/07/30 10pp 25916 090 24X
Fiche 50-155, 84/07/30, 8408030109

8408070040 Requests remittance of application fee for 840629 request for exemption from 10CFR50 49 schedular requirement for environ qualification of electrical equipment Request filed after effective date of revised 10CFR170
DIGGS, R M License Fee Management Branch 84/07/30
VANDEWALLE, D J Consumers Power Co 1p 25935 351 24X
Fiche 50-155, 84/07/30, 8408070040

8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers," omitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/07/31
KAY, J A Yankee Atomic Electric Co FARRAR, D L Commonwealth Edison Co VANDEWALLE, D J Consumers Power Co 4pp 25955 227
24X Fiche 50-000, 84/07/31, 8408070099

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408080224 Forwards Whiting Corp 840727 rept re analysis of structural adequacy of jib crane to withstand seismic event Rept referenced in 840730 response to ASLB request for clarification re jib crane/gantry crane relationship
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Consumers Power Co DSB 823 84/08/06 BLOCH, P B , PARIS, G H , SHON, F J
Atomic Safety and Licensing Board Panel 16pp 25967 034 24X
Fiche 50-155, 84/08/06, 8408080224

8408090166 Forwards application for amend to License DPR-6, revising Tech Specs re plant review committee review & approval of documents by document routing Fee encl
VANDEWALLE, D J Consumers Power Co 84/08/06 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 25971 034 24X
Fiche 50-155, 84/08/06, 8408090166

--8408090171 Application for amend to License DPR-6, revising Tech Specs re plant review committee review & approval of documents by document routing
VANDEWALLE, D J Consumers Power Co 84/08/06 4pp 25971 035
24X Fiche 50-155, 84/08/06, 8408090166

--8408090327 Proposed Tech Spec changes re plant review committee review & approval of documents by document routing
* Consumers Power Co 84/08/06 2pp 25971 039 24X
Fiche 50-155, 84/08/06, 8408090166

8408090307 Forwards rept of electrical equipment environ qualification audit on 840605-07 Files inadequate to demonstrate qualification Reaudit planned for late Summer 1984
PAULSON, W A Operating Reactors Branch 5 84/08/08
VANDEWALLE, D J Consumers Power Co 4pp 25972 127 24X
Fiche 50-155, 84/08/08, 8408090307

8408160172 Board Notification 84-141 forwards rept of electrical equipment environ qualification audit on 840605-07, for consideration in current litigation re spent fuel pool storage expansion
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/08/09
BLOCH, P B , PARIS, G H , SHON, F J Atomic Safety and Licensing Board Panel 3pp 26126 253 24X Fiche 50-155, 84/08/09, 8408160172

8408160181 Forwards remittance for extension request re 10CFR50 49 schedular requirements for environ qualification of electrical equipment, per NRC 840730 request
KUEMIN, J L Consumers Power Co 84/08/09 MILLER, W D License Fee Management Branch 1p 26091 242 24X Fiche 50-155, 84/08/09, 8408160181

8408160343 Notification of 840824 meeting w/util in Charlevoix, MI to discuss radiological effluent Tech Specs
EMCH, R L Operating Reactors Branch 5 84/08/14 PAULSON, W A
Operating Reactors Branch 5 4pp 26092 129 24X
Fiche 50-155, 84/08/14, 8408160343

8408160346 Notification of 840905 meeting w/util in Bethesda, MD to discuss environ qualification of electrical equipment
EMCH, R L Operating Reactors Branch 5 84/08/14 PAULSON, W A
Operating Reactors Branch 5 4pp 26092 185 24X
Fiche 50-155, 84/08/14, 8408160346

8408170022 Informs that 840523 QA program submittal requires identification of each change, reason for change & basis for concluding that revised program incorporating each change satisfies 10CFR50, App B & SAR QA program commitments
SPESSARD, R L Region 3, Office of Director 84/08/14 DEWITT, R B
Consumers Power Co 2pp 26119 077 24X Fiche 50-000, 84/08/14, 8408170022

8408210287 Forwards listings of issues completed between 840202 & end of 1984 refueling outage, issues scheduled to be completed, but delayed between 840202 & end of 1984 refueling outage & remaining active issues
KRICH, R M Consumers Power Co 84/08/14 CRUTCHFIELD, D Operating Reactors Branch 5 14pp 26180 201 24X Fiche 50-155, 84/08/14, 8408210287

8408210338 Informs that no addl post-accident sampling sys required to meet guidance of NUREG-0737, Item II B 3 Item complete High-range containment radiation monitors acceptable method of providing indication of core damage
PAULSON, W A Operating Reactors Branch 5 84/08/17
VANDEWALLE, D J Consumers Power Co 3pp 26179 358 24X
Fiche 50-155, 84/08/17, 8408210338

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408290001 Advises that Multi-Plant Action B-59 re masonry wall design complete Plant structures will be seismically evaluated for weak links, per NUREG-0828
PAULSON, W A Operating Reactors Branch 5 84/08/27
VANDEWALLE, D J Consumers Power Co 5pp 26291 289 24X
Fiche 50-155, 84/08/27, 8408290001

G Inspection reports, IE Bulletins & correspondence

8408030176 Forwards IE Insp Rept 50-155/84-05 on 840421-0615 No noncompliance noted
SHAFER, W D Region 3, Office of Director 84/07/13 DEWITT, R B
Consumers Power Co 2pp 25917 302 24X Fiche 50-155, 84/07/13, 8408030176

--8408030179 IE Insp Rept 50-155/84-05 on 840421-0615 No noncompliance noted Major areas inspected licensee actions on previous insp findings, operational safety & surveillance
DEFAYETTE, R W , TAMBLING, T N , GUTHRIE, G Region 3, Office of Director 84/07/12 4pp 25917 304 24X Fiche 50-155, 84/07/13, 8408030176

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408060110 Ack receipt of 840627 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/84-04 Clarification of calibr practices on portable high-range gamma measuring instruments awaited
PAPERIELLO, C J Region 3, Office of Director 84/07/31
DEWITT, R B Consumers Power Co 1p 25933 176 24X
Fiche 50-155, 84/07/31, 8408060110

--8408060113 Responds to NRC 840529 ltr re violations noted in IE Insp Rept 50-155/84-04 Corrective actions Xetex fission pole & Eberline telector sent to vendors for calibr on all scales & will be calibr on all scales every 6 months
KRICH,R M Consumers Power Co 84/06/27 KEPPLER,J G Region 3, Office of Director 2pp 25933 177 24X Fiche 50-155,84/07/31, 8408060110

8408200233 Forwards IE Insp Rept 50-155/84-08 on 840709-12 No violations noted
PAPERIELLO,C J Region 3, Office of Director 84/08/02
DEWITT,R B Consumers Power Co 2pp 26140 155 24X
Fiche 50-155,84/08/02,8408200233

--8408200241 IE Insp Rept 50-155/84-08 on 840709-12 No violations noted Major areas inspected operational radiation protection program,including planning & preparation,changes,training & qualifications of new personnel & exposure control
LOVENDALE,P C , FRANCE,G M , GREGER,L R Region 3, Office of Director 84/08/01 7pp 26140 157 24X Fiche 50-155,84/08/02, 8408200233

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408140130 Ack receipt of 831216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/82-13
LITTLE,W S Region 3, Office of Director 84/08/10 DEWITT,R B Consumers Power Co 1p 26047 011 24X Fiche 50-155,84/08/10, 8408140130

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408270390 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-155/84-03
PAPERIELLO,C J Region 3, Office of Director 84/08/22
DEWITT,R B Consumers Power Co 2pp 26240 197 24X
Fiche 50-155,84/08/22,8408270390

--8408270392 Responds to NRC 840627 ltr re violations noted in Insp Rept 50-155/84-03 Corrective actions site emergency plan implementing procedure reporting time requirements revised, following 840222 incident
VANDEWALLE,D J Consumers Power Co 84/07/27 KEPPLER,J G
Region 3, Office of Director 3pp 26240 199 24X
Fiche 50-155,84/08/22,8408270390

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,D G General Electric Co 84/04/13 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348

8408230239 LER 84-003-01 on 840530, samples taken of water in below-grade wall of radwaste pump room indicated presence of tritium & I-131 Caused by leak in underground pipe Pipe replaced & discharge canal monitored daily W/840816 ltr
DEMOOR,D E , KEUMIN,J L Consumers Power Co 84/08/16 5pp 26213 298 24X Fiche 50-155,84/08/16,8408230239

8408300086 LER 83-007//01T-1 on 830809,MSIV MO-7050 failed to stroke closed Caused by bent tripper arm on torque switch & probable increased switch sensitivity due to interference w/gear case hardened lubricant W/840816 ltr
KUEMIN,J L Consumers Power Co 84/08/16 KEPPLER,J G Region 3, Office of Director 3pp 26307 198 24X Fiche 50-155,84/08/16, 8408300086

8408290067 LER 84-010-00 on 840727,w/control rods inserted for turbine bypass valve investigation,reactor protection sys Channel 5 period monitor spuriously tripped, indicating short reactor period,due to electrical noise interference W/840822 ltr
CASTIGLIONE,L , KUEMIN,J L Consumers Power Co 84/08/22 3pp 26297 322 24X Fiche 50-155,84/08/22,8408290067

8408290251 LER 84-009-00 on 840726,w/plant at 13% power,reactor scram from high pressure occurred Caused by turbine bypass valve failing closed in automatic mode Turbine bypass valve operational characteristics to be examined W/840822 ltr
CASTIGLIONE,L , KUEMIN,J L Consumers Power Co 84/08/22 4pp 26294 358 24X Fiche 50-155,84/08/22,8408290251

V Operator Examinations

8408200233 Forwards IE Insp Rept 50-155/84-08 on 840709-12 No violations noted
PAPERIELLO,C J Region 3, Office of Director 84/08/02
DEWITT,R B Consumers Power Co 2pp 26140 155 24X
Fiche 50-155,84/08/02,8408200233

--8408200241 IE Insp Rept 50-155/84-08 on 840709-12 No violations noted Major areas inspected operational radiation protection program,including planning & preparation,changes,training & qualifications of new personnel & exposure control
LOVENDALE,P C , FRANCE,G M , GREGER,L R Region 3, Office of Director 84/08/01 7pp 26140 157 24X Fiche 50-155,84/08/02, 8408200233

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408010045 Forwards "Emergency Plan Evaluation Rept,Univ of Wisconsin " Plan acceptable Plan should be implemented within 120 days of ltr date
THOMAS,C O Standardization & Special Projects Branch 84/07/25
CASHWELL,R J Wisconsin, Univ of, Madison, WI 3pp 25866 335
24X Fiche 50-156,84/07/25,8408010045

--8408010047 "Emergency Plan Evaluation Rept, Univ of Wisconsin "
* NRC - No Detailed Affiliation Given 84/07/31 3pp
25866 338 24X Fiche 50-156, 84/07/25, 8408010045

8408140521 Advises that recently approved emergency plan will be fully implemented by 840831
CASHWELL, R J Wisconsin, Univ of, Madison, WI 84/08/06
THOMAS, C O Standardization & Special Projects Branch 1p
26064 142 24X Fiche 50-156, 84/08/06, 8408140521

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408210097 Forwards "Emergency Plan Evaluation Rept, Cornell Univ " Plan meets requirements of regulations & guidelines & is acceptable
THOMAS, C O Standardization & Special Projects Branch 84/08/15
CLARK, D D Cornell Univ , Ithaca, NY 3pp 26195 213 24X Fiche 50-097, 84/08/15, 8408210097

--8408140349 "Emergency Plan Evaluation Rept, Cornell Univ "
* Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/31 4pp 26195 216 24X Fiche 50-097, 84/08/15, 8408210097

DOCKET 50-160 GEORGIA INST OF TECH RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408280195 "Emergency Preparedness Plan for Neely Nuclear Research Ctr, Georgia Inst of Technology " W/one oversize brochure
Aperture card available in PDR W/840821 ltr
KARAM, R A Georgia Institute of Technology, Atlanta, GA 84/08/31
THOMAS, C O Standardization & Special Projects Branch 35pp
26275 001 24X Fiche 50-160, 84/08/31, 8408280195

P Operating license stage documents & correspondence

8408010259 Requests application for amend executed per 10CFR50 30(a)-(c) & info showing all parts of Section 6 1 of Tech Specs being fulfilled before action can be taken on 840524 request for dismantling facilities
THOMAS, C O Standardization & Special Projects Branch 84/07/23
KARAM, R A Georgia Institute of Technology, Atlanta, GA 3pp
25872 339 24X Fiche 50-160, 84/07/23, 8408010259

DOCKET 50-163 GA TECHNOLOGIES

F Security, medical, emergency & fire protection plans

8408270311 Forwards ltrs documenting cooperation w/local law enforcement agencies & medical facilities re radiological contingency plan
MOWRY, W R GA Technologies, Inc /General Atomic Co 84/08/22
CUNNINGHAM, R Division of Fuel Cycle & Material Safety THOMAS, C O Standardization & Special Projects Branch 4pp 26241 004 24X Fiche 50-089, 84/08/22, 8408270311

P Operating license stage documents & correspondence

8405160470 Forwards Amend 25 & 31 to Licenses R-38 & R-67, respectively & notice of issuance & availability Amends change corporate name of licensee to GA Technologies, Inc
EISENHUT, D G Division of Licensing 84/04/27 MOWRY, W R GA Technologies, Inc /General Atomic Co 3pp 24492 253 24X Fiche 50-089, 84/04/27, 8405160470

--8405160473 Amends 25 & 31 to Licenses R-38 & R-67, respectively, changing corporate name of licensee to GA Technologies, Inc
EISENHUT, D G Division of Licensing 84/04/27 4pp 24492 256 24X Fiche 50-089, 84/04/27, 8405160470

8408290277 Forwards Amend 33 to License R-67 & safety evaluation Amend authorizes increase in number of thermionic devices to be irradiated simultaneously from three to four & removes limit on total reactivity worth of combination of experiments
THOMAS, C O Standardization & Special Projects Branch 84/08/17
MOWRY, W R GA Technologies, Inc /General Atomic Co 3pp
26312 331 24X Fiche 50-163, 84/08/17, 8408290277

--8408290286 Amend 33 to License R-67, increasing in number of thermionic devices to be irradiated simultaneously, removing limit on total reactivity worth of combination of experiments & changing fastening restrictions
THOMAS, C O Standardization & Special Projects Branch 84/08/17
5pp 26312 334 24X Fiche 50-163, 84/08/17, 8408290277

--8408290291 Safety evaluation supporting Amend 33 to License R-67
* Office of Nuclear Reactor Regulation, Director 84/08/17 4pp
26312 339 24X Fiche 50-163, 84/08/17, 8408290277

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

P Operating license stage documents & correspondence

8408070124 Forwards FR notice of final finding of no significant environ impact re proposed renewal of License R-70
THOMAS, C O Standardization & Special Projects Branch 84/07/31
KERR, F Maryland, Univ of, College Park, MD 3pp 25957 201 24X Fiche 50-166, 84/07/31, 8408070124

--8408070127 Notice of final finding of no significant environ impact re proposed renewal of License R-70
EISENHUT, D G Division of Licensing 84/07/31 6pp 25957 204 24X Fiche 50-166, 84/07/31, 8408070124

8408140558 Forwards Amend 7 to License R-70, SER, EIA & notice of issuance & availability Amend renews license until June 29, 2000
EISENHUT, D G Division of Licensing 84/08/07 KERR, F Maryland, Univ of, College Park, MD 3pp 26065 236 24X Fiche 50-166, 84/08/07, 8408140558

--8408140561 Amend 7 to License R-70, renewing license until June 29, 2000, Tech Specs encl
EISENHUT, D G Division of Licensing 84/08/07 34pp 26065 239 24X Fiche 50-166, 84/08/07, 8408140558

--8408140569 Notice of renewal of License R-70
THOMAS, C O Standardization & Special Projects Branch 84/08/07
2pp 26065 274 24X Fiche 50-166, 84/08/07, 8408140558

--8408140564 EIA supporting Amend 7 to License R-70
* NRC - No Detailed Affiliation Given 84/08/07 7pp
26065 276 24X Fiche 50-166, 84/08/07, 8408140558

8408300079 Application for amend to License R-40, correcting typographical error on Tech Spec Page 12
WOCKENFUSS, W A Maryland, Univ of, College Park, MD 84/08/17
THOMAS, C O Standardization & Special Projects Branch 1p.
26305 361 24X Fiche 50-166, 84/08/17, 8408300079

--8408300083 Proposed Tech Spec correcting typographical error on Page 12
* Maryland, Univ of, College Park, MD 84/08/17 1p
26305 362 24X Fiche 50-166, 84/08/17, 8408300079

8408270462 Forwards errata to Amend 8 to License R-70, correcting editorial error in Tech Spec re min radiation monitoring channels
THOMAS, C O Standardization & Special Projects Branch 84/08/21
KERR, F Maryland, Univ of, College Park, MD 3pp 26277 220 24X Fiche 50-166, 84/08/21, 8408270462

--8408270466 Errata to Amend 8 to License R-70, correcting editorial error in Tech Spec re min radiation monitoring channels
THOMAS, C O Standardization & Special Projects Branch 84/08/21
4pp 26277 223 24X Fiche 50-166, 84/08/21, 8408270462

R Periodic operating reports & related correspondence

8408220172 Annual operating rept, Jul 1983 - June 1984
BELCHER, R L Maryland, Univ of, College Park, MD. 84/07/23
TEDESCO, R L Division of Licensing 4pp 26188 172 24X Fiche 50-166, 84/07/23, 8408220172

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

P Operating license stage documents & correspondence

8408070035 Forwards FR notice of final finding of no significant environ impact re renewal of License R-84
THOMAS,C O Standardization & Special Projects Branch 84/07/30
ADCOCK,B National Naval Medical Center Bethesda,MD 3pp
25956 131 24X Fiche 50-170,84/07/30,8408070035

--8408070038 Notice of final finding of no significant environ impact re proposed amend to License R-84,renewing OL until Yr 2000
EISENHUT,D G Division of Licensing 84/07/27 7pp 25956 134
24X Fiche 50-170,84/07/30,8408070035

8408090533 Forwards Amend 18 to License R-84,safety evaluation,notice of issuance & availability & Tech Specs Amend renews license for 20 yrs
EISENHUT,D G Division of Licensing 84/08/01 ADCOCK,B Armed Forces Radiobiological Research Institute 4pp 25983 277 24X Fiche 50-170,84/08/01,8408090533

--8408090534 Amend 18 to License R-84,renewing license
EISENHUT,D G Division of Licensing 84/08/01 3pp 25983 281
24X Fiche 50-170,84/08/01,8408090533

--8408090536 Notice of issuance & availability of Amend 18 to License R-84
THOMAS,C O Standardization & Special Projects Branch 84/08/01
2pp 25983 284 24X Fiche 50-170,84/08/01,8408090533

--8408090537 "Tech Specs for AFRRI Reactor Facility "
* Armed Forces Radiobiological Research Institute 84/05/30
46pp 25983 286 24X Fiche 50-170,84/08/01,8408090533

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

R Periodic operating reports & related correspondence

8408210546 Forwards "Environ Radiation Monitoring Program,1983" & "Regional Radiological Environ Monitoring Program,1983 "
WILLSEY,W B Philadelphia Electric Co 84/08/09 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 1p
26185 001 24X Fiche 50-171,84/08/09,8408210546

--8408210549 "Environ Radiation Monitoring Program,1983 "
* Chemical Waste Management, Inc 41 83/12/31 124pp
26185 002 24X Fiche 50-171,84/08/09,8408210546

--8408210555 "Regional Radiological Environ Monitoring Program,1983 "
* Teledyne Isotopes 19 83/12/31 129pp 26185 126 24X
Fiche 50-171,84/08/09,8408210546

DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

G Inspection reports, IE Bulletins & correspondence

8408270477 Forwards Insp Rept 50-184/84-01 on 840711-12 No violations noted
STAROSTECKI,R Division of Project & Resident Programs 84/08/06
CARTER,R S Commerce, Dept of, National Bureau of Standards 2pp
26256 203 24X Fiche 50-184,84/08/06,8408270477

--8408270486 Insp Rept 50-184/84-01 on 840711-12 No violations or deviations noted Major areas inspected organization,logs & records,reviews & audits,equipment condition,experiments, surveillance activities & engineering changes
TRIMBLE,D C , ELSASSER,T C Region 1, Office of Director
84/08/01 6pp 26256 205 24X Fiche 50-184,84/08/06,8408270477

DOCKET 50-185 PLUM BROOK REACTOR - MOCK-UP

P Operating license stage documents & correspondence

8408210629 Advises that Licenses TR-3 & R-93 should be reinstated to prior possess-but-not-use status or revised dismantlement plans should be submitted,per 10CFR50 82 or 10CFR50 90, respectively Plans should update mgt controls
THOMAS,C O Standardization & Special Projects Branch 84/08/26
RICHLEY,E A National Aeronautics & Space Admin 3pp 26187 357
24X Fiche 50-030,84/08/26,8408210629

W Decommissioning Stage Documents & Correspondence

8408240107 Requests submittal of either request for reinstatement of possess-but-not-use license or revised dismantlement plan w/schedule commitments Dismantlement authorized in 1981 delayed by lack of funds
THOMAS,C O Standardization & Special Projects Branch 84/08/16
RICHLEY,E A National Aeronautics & Space Admin 5pp 26295 343
24X Fiche 50-030,84/08/16,8408240107

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408200461 Forwards review & evaluation of emergency plan for Kansas State Univ submitted on 840620,per 10CFR50 54(q) & (r) Emergency plan meets requirements of regulations & guidelines & is acceptable
THOMAS,C O Standardization & Special Projects Branch 84/08/13
FAW,R E Kansas State Univ , Manhattan, KS 3pp 26144 316 24X
Fiche 50-188,84/08/13,8408200461

--8408200464 "Emergency Plan Evaluation Rept - Kansas State Univ "
* NRC - No Detailed Affiliation Given 84/07/31 3pp
26144 319 24X Fiche 50-188,84/08/13,8408200461

8408310117 Ack receipt of 840813 emergency plan evaluation rept Last paragraph on Page 2 of rept in error Operations boundary encompasses reactor facility Room 110 of Ward Hall,per Paragraph 1 1 of emergency plan
FAW,R E Kansas State Univ , Manhattan, KS 84/08/20 CHU,A Standardization & Special Projects Branch 1p 26322 112 24X
Fiche 50-188,84/08/20,8408310117

DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8407110579 Forwards safety evaluation re 830721 emergency plan Plan acceptable Full implementation should be completed within 120 days of ltr date & NRC informed of date implementation achieved W/o encl
THOMAS,C O Standardization & Special Projects Branch 84/07/03
KLEIN,D E Texas, Univ of, Austin, TX 2pp 25545 358 24X
Fiche 50-192,84/07/03,8407110579

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

S Reportable occurrences, LERs & related correspondence

8408210328 RO on 840810,telephone lines between Narragansett,RI & Providence,RI failed,preventing transmission of signals from burglar alarm & supervisory sys Cause unknown Line restored
DIMEGLIO,A F Rhode Island & Providence Plantation 84/08/10
Region 1, Office of Director 1p 26179 331 24X
Fiche 50-193,84/08/10,8408210328

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

I Financial information

8408170407 Forwards proprietary financial info required for renewal of License R-94 & "Environ Rept," per 840702 telcon Proprietary info & rept withheld (ref 10CFR2 790)
KANE,R S Manhattan College, Riverdale, NY 84/08/13 THOMAS,C O
Standardization & Special Projects Branch 1p 26129 117 24X
Fiche 50-199,84/08/13,8408170407

P Operating license stage documents & correspondence

8408170407 Forwards proprietary financial info required for renewal of License R-94 & "Environ Rept," per 840702 telcon Proprietary info & rept withheld (ref 10CFR2 790)
KANE,R S Manhattan College, Riverdale, NY 84/08/13 THOMAS,C O
Standardization & Special Projects Branch 1p 26129 117 24X
Fiche 50-199,84/08/13,8408170407

V Operator Examinations

8408030301 Forwards evaluation of Rev 3 to operator requalification program Rev approved,per 10CFR55,App A
THOMAS,C O Standardization & Special Projects Branch 84/07/26
KANE,R S Manhattan College, Riverdale, NY 5pp 25920 063 24X
Fiche 50-199,84/07/26,8408030301

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408030123 Forwards Rev 2 to physical security plan & description of changes Encls withheld (ref 10CFR73 21)
HAYNES,J G Southern California Edison Co 84/07/25 MARTIN,J B
Region 5, Office of Director 1p 25916 119 24X
Fiche 50-206,84/07/25,8408030123

8408170130 Forwards Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15,respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas
PAULSON,W A Operating Reactors Branch 5 84/08/07 BASKIN,K
Southern California Edison Co 5pp 26134 302 24X
Fiche 50-206,84/08/07,8408170130

--8408170143 Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15, respectively,approving security plan revs which consolidate & reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary
PAULSON,W A Operating Reactors Branch 5 84/08/07 6pp
26134 307 24X Fiche 50-206,84/08/07,8408170130

--8408170155 Safety evaluation supporting Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15,respectively
* Office of Nuclear Reactor Regulation, Director 84/08/07 5pp
26134 313 24X Fiche 50-206,84/08/07,8408170130

8408130450 Advises that 840523 Revs 1-13 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
MCQUEEN,A D Region 5, Office of Director 84/08/08 HAYNES,J G
Southern California Edison Co 4pp 26004 359 24X
Fiche,50-206,84/08/08,8408130450

8408310285 Forwards Safeguards Insp Repts 50-206/84-18,50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 10CFR2 790 & 73 21)
SCHUSTER,M D Region 5, Office of Director 84/08/15 BASKIN,K B
Southern California Edison Co 2pp 26333 288 24X
Fiche 50-206,84/08/15,8408310285

8408230114 Informs that 840613 rev to emergency plan compatible w/provisions of 10CFR50 47,App E & Rev 1 to NUREG-0654
SCHUSTER,M D Region 5, Office of Director 84/08/16 MEDFORD,M O
Southern California Edison Co 3pp 26347 274 24X
Fiche 50-206,84/08/16,8408230114

P Operating license stage documents & correspondence

8408210042 Notification of contract execution,Mod 4,to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " Contractor MIT
HOPPER,A Administrative Contracts Branch FIN B-6898 84/06/12
VOLLMER,R Division of Engineering JACKSON,R NRC - No Detailed Affiliation Given 1p 26195 176 24X Fiche 50-206,84/06/12, 8408210042

--8408210046 Mod 4,deobligating unliquidated fee remaining in contract, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station "
AKI,K Massachusetts Institute of Technology, Cambridge, MA
HAGAN,T F Division of Contracts FIN B-6898 84/06/12 1p
26195 177 24X Fiche 50-206,84/06/12,8408210042

8408060408 Requests assistance in review of licensee 840717 Tech Spec revs on plant staff overtime limits (TMI Item I A 1 3 1)
Completed SER & SALP input due 840920
EISENHUT,D G Division of Licensing 84/07/25 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 3pp
25951 154 24X Fiche 50-206,84/07/25,8408060408

8408010038 Informs of review of 840629 ltr on operating experience, insp & analysis results re reliability of TDI V-20 diesels Lead engine testing,disassembly & insp not required before restart
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/07/26
BASKIN,K P Southern California Edison Co 7pp 25855 333 24X
Fiche 50-206,84/07/26,8408010038

8408010226 Forwards addl info re Proposed Changes 76 & 126 to Tech Specs,in response to NRC 840309 request Calculation sheets encl W/three oversize drawings Aperture cards available in PDR
MEDFORD,M O Southern California Edison Co 84/07/27
CRUTCHFIELD,D Operating Reactors Branch 5 132pp 25854 180 24X
Fiche 50-206,84/07/27,8408010226

8408010272 Requests extension of environ qualification of electrical equipment to 851130,per 10CFR50 49(g) & forwards Nucon Inc repts, "Plant Risk Impact Evaluation of Certain Electrical Equipment" & "Evaluation of Core Damage Risk "
MEDFORD,M O Southern California Edison Co 84/07/30
CRUTCHFIELD,D Operating Reactors Branch 5 7pp 25854 089 24X
Fiche 50-206,84/07/30,8408010272

--8408010276 "Plant Risk Impact Evaluation of Certain Electrical Equipment "
LYDELL,R O , MORGAN,T A , HUGHES,E A Nucon, Inc 84/07/31
62pp 25854 096 24X Fiche 50-206,84/07/30,8408010272

--8408010287 "Evaluation of Core Damage Risk Reduction Associated W/ Seismic Mods at San Onofre Nuclear Generating Station,Unit 1," executive summary
GUEY,C N , LAMBERT,H E , HUGHES,E A Nucon, Inc 84/07/31 10pp
25854 138 24X Fiche 50-206,84/07/30,8408010272

8408090208 Forwards draft memo re boron injection test,which will be finalized after comments received Final memo will satisfy final milestone defined in 189, "Boron Mixing & Cooldown Under Accident Conditions "
PRATT,W T Brookhaven National Laboratory FIN A-3368 84/07/30
LIANG,C Y Reactor Systems Branch 18pp 25971 193 24X
Fiche 50-206,84/07/30,8408090208

8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers," omitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated
CRUTCHFIELD,D Assistant Director for Safety Assessment, 84/07/31
KAY,J A Yankee Atomic Electric Co 4pp 25935 227 24X
Fiche 50-000,84/07/31,8408070099

8408030166 Forwards Rev 1 to "Offsite Dose Calculation Manual" & response to NRC 840418 comments
MEDFORD,M O Southern California Edison Co 84/08/01
CRUTCHFIELD,D Operating Reactors Branch 5 7pp 25914 047 24X
Fiche 50-206,84/08/01,8408030166

--8408030169 Rev 1 to "Offsite Dose Calculation Manual," consisting of corrected pages,per NRC 840418 request to support review of radiological effluent Tech Specs
* Southern California Edison Co 84/06/13 20pp 25914 054
24X Fiche 50-206,84/08/01,8408030166

8408070331 Informs that licensee 840709 proposal to resolve TMI Item II F 1 4 acceptable Computer software will be modified so that data will be collected once per second & highest value over each minute will be recorded
PAULSON,W A Operating Reactors Branch 5 84/08/03 BASKIN,K P
Southern California Edison Co 2pp 25945 235 24X
Fiche 50-206,84/08/03,8408070331

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408140188 Lists required confirmatory evaluations to be performed prior to startup to estimate inelastic capability of structural elements to retain function during DBE
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/08/07
BASKIN,K P Southern California Edison Co 4pp 26044 035 24X
Fiche 50-206,84/08/07,8408140188

--8408140194 Submits review of EG&G consultant agreement, "Adequacy of Structural Beams for Safety-Related Piping,San Onofre, Unit 1 " More rationally based,sys-wide study of safety sys appropriate
HALL,W J Dr W J Hall 84/05/21 CHENG,T Systematic Evaluation Program Branch BARNES,B L EG&G, Inc 7pp 26044 039 24X Fiche 50-206,84/08/07,8408140188

8408170130 Forwards Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15,respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas
PAULSON,W A Operating Reactors Branch 5 84/08/07 BASKIN,K Southern California Edison Co HOLCOMBE,J C San Diego Gas & Electric Co 5pp 26134 302 24X Fiche 50-206,84/08/07,8408170130

--8408170143 Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15, respectively,approving security plan revs which consolidate & reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary
PAULSON,W A Operating Reactors Branch 5 84/08/07 6pp 26134 307 24X Fiche 50-206,84/08/07,8408170130

--8408170155 Safety evaluation supporting Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15,respectively
* Office of Nuclear Reactor Regulation, Director 84/08/07 5pp 26134 313 24X Fiche 50-206,84/08/07,8408170130

8408160215 Forwards addl info re current alternate post-accident sampling sys methods,completion schedules for procurement of components,const & operator training & justification for deferral to Cycle IX refueling outage
MEDFORD,M O Southern California Edison Co 84/08/14 PAULSON,W A Operating Reactors Branch 5 17pp 26090 334 24X
Fiche 50-206,84/08/14,8408160215

8408160359 Notification of 840823 meeting w/util in Bethesda,MD to discuss intake structure rebar corrosion
MCKENNA,E Operating Reactors Branch 5 84/08/15 PAULSON,W A Operating Reactors Branch 5 3pp 26091 233 24X
Fiche 50-206,84/08/15,8408160359

8408160375 Notification of 840905 & 06 meetings w/util & Franklin Research Ctr in Berkeley & San Diego,CA,respectively,to audit results for masonry wall seismic qualification & conduct site visit
MCKENNA,E Operating Reactors Branch 5 84/08/15 PAULSON,W A Operating Reactors Branch 5 3pp 26092 176 24X
Fiche 50-206,84/08/15,8408160375

8408200114 Forwards SER re vertical seismic ground motion for facility, per SEP Topic III-6 Original estimate for free-field ground motion described in 820916 ltr appropriate for seismic reevaluation
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/08/16
BASKIN,K P Southern California Edison Co 9pp 26132 309 24X
Fiche 50-206,84/08/16,8408200114

8408210165 Application for amend to License DPR-13,changing Tech Specs re max reactor coolant activity,leakage,safety injection sys hydraulic valve testing,reactivity anomalies & miscellaneous radioactive matls sources,
MEDFORD,M O Southern California Edison Co 84/08/16 PAULSON,W A Operating Reactors Branch 5 4pp 26183 067 24X
Fiche 50-206,84/08/16,8408210165

--8408210179 Proposed & existing Tech Specs re max reactor coolant activity,leakage,safety injection sys hydraulic valve testing,reactivity anomalies & miscellaneous radioactive matls sources
* Southern California Edison Co 84/08/16 29pp 26183 071 24X Fiche 50-206,84/08/16,8408210165

8408210625 Requests remittance of fee for 840730 request for extension of 10CFR50 49 schedular requirements for environ qualification of certain electrical equipment.Application subj to 840620 rev to 10CFR170 on fees
DIGGS,R M License Fee Management Branch 84/08/16 RAY,H B Southern California Edison Co 1p 26187 360 24X
Fiche 50-206,84/08/16,8408210625

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408210371 Advises that concrete cracks & corrosion of underlying rebar found in wall of facility intake structure Licensee will make presentation on extent of problem & proposed corrective actions at 840823 meeting
PAULSON,W A Operating Reactors Branch 5 84/08/20 LEAR,G Structural & Geotechnical Engineering Branch 1p 26180 355 24X
Fiche 50-206,84/08/20,8408210371

8408230178 Forwards info to resolve SEP Topics IV-2, "Reactivity Control Sys" & VII-1 A, "Isolation of Reactor Protection Sys From Nonsafety Sys " Six oversize drawings encl
Aperture cards available in PDR
MEDFORD,M O Southern California Edison Co 84/08/21 PAULSON,W A Operating Reactors Branch 5 26207 188 24X
Fiche 50-206,84/08/21,8408230178

8408240168 Submits results of analyses re temp profile for 4,160-volt & 480-volt rooms to confirm post-accident cooling of room not necessary to assure operability of electrical components Info resolves SEP Topic IX-5
MEDFORD,M O Southern California Edison Co 84/08/21 PAULSON,W A Operating Reactors Branch 5 3pp 26228 175 24X
Fiche 50-206,84/08/21,8408240168

8408270325 Advises that Amend 7 to Topical Rept SCE-1-A, "QA Program," consistent w/provisions of 10CFR50 54(a) & acceptable
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 84/08/21 BASKIN,K P Southern California Edison Co
1p 26244 187 24X Fiche 50-206,84/08/21,8408270325

8408280173 Summary of 840823 meeting w/util & Bechtel in Bethesda,MD re degradation of intake structure reinforcing steel (rebar) Meeting attendees list & handouts encl
MCKENNA,E M Operating Reactors Branch 5 84/08/27 Operating Reactors Branch 5 39pp 26259 016 24X Fiche 50-206,84/08/27, 8408280173

8408290136 Forwards final SER re SEP Topics II 3-A re hydrologic description,II-3 B re flooding potential & protection, II-3 B 1 re coping w/design basis flood conditions & II-3 C re UHS
PAULSON,W A Operating Reactors Branch 5 84/08/27 BASKIN,K P Southern California Edison Co 8pp 26291 294 24X
Fiche 50-206,84/08/27,8408290136

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408070411 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " Thirty-one relays found at Unit 1 will be replaced by 860312
MEDFORD,M O Southern California Edison Co 84/07/30 MARTIN,J B Region 5, Office of Director 3pp 25942 170 24X
Fiche 50-206,84/07/30,8408070411

8408130203 Responds to NRC 840706 ltr re violations noted in IE Insp Rept 50-206/84-10 Corrective actions QA program implemented for enhanced contractor QA field surveillances to ensure work in conformance w/drawings & procedures
BASKIN,K P Southern California Edison Co 84/07/30 MARTIN,J B Region 5, Office of Director. 12pp. 26008 297 24X
Fiche 50-206,84/07/30,8408130203

8408310243 Forwards Exam Rept 50-206/OL-84-01 administered on 840710-13,written exam & answer key
PATE,R J Region 5, Office of Director 84/08/03 BASKIN,K P Southern California Edison Co 1p 26334 001 24X
Fiche 50-206,84/08/03,8408310243

--8408310244 Exam Rept 50-206/OL-84-01 administered on 840710-13 Exam results all candidates passed
ELLIN,J D , MILLER,L F Region 5, Office of Director 84/07/31 109pp 26334 002 24X Fiche 50-206,84/08/03,8408310243

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
ORACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408310285 Forwards Safeguards Insp Repts 50-206/84-18,50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 10CFR2 790 & 73 21)
SCHUSTER,M D Region 5, Office of Director 84/08/15 BASKIN,K B Southern California Edison Co 2pp 26333 288 24X Fiche 50-206,84/08/15,8408310285

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408280109 Forwards outline of actions required to insure reliability of TDI V-20 diesel engines prior to restart, in response to 840629 summary of operating experience, insp results & analysis results
BERLINGER,C H Division of Licensing 84/08/20 GRIMES,C I Systematic Evaluation Program Branch 11pp 26294 141 24X Fiche 50-206,84/08/20,8408280109

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408270349 Ack receipt of 840730 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-206/84-10
BISHOP,T W Region 5, Office of Director 84/08/21 BASKIN,K P Southern California Edison Co 1p 26244 357 24X Fiche 50-206,84/08/21,8408270349

S. Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group RAY,C L Duke Power Co 84/05/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group RAY,C L Duke Power Co 84/05/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000,84/05/24,8405290179

--8405290271 "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
* Failure Analysis Associates FAAA-84-3-16 84/05/22 89pp 24692 092 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp 25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/ TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc.) Owners Group RAY,C L Duke Power Co 84/07/10 BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10,8408060050

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group RAY,C L Duke Power Co 84/07/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000,84/07/27,8408060102

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group RAY,C L Duke Power Co 84/08/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24X Fiche 50-000,84/08/01,8408060324

--8408060387 "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-6-56 84/07/31 62pp 25927 066 24X Fiche 50-000,84/08/01,8408060324

8408140216 Special rept on 831219,fire detection sys back in svc but for Zones 8 & 16 Engineering evaluations complete Mods to Zones 8 & 16 will be finished & zones back in svc by 841015
HAYNES,J G Southern California Edison Co 84/08/01 MARTIN,J B Region 5, Office of Director 2pp 26053 361 24X Fiche 50-206,84/08/01,8408140216

8408070379 LER 84-007-00 on 840703,temporary change notice for Procedure S02-3-3 31, "Inservice Valve Testing Cold Shutdown," not approved within 14 days,contrary to Tech Specs Caused by administrative error W/840803 ltr
HAYNES,J G Southern California Edison Co 84/08/03 2pp 25947 156 24X Fiche 50-206,84/08/03,8408070379

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group RAY,C L Duke Power Co. 84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines,"
* Failure Analysis Associates FAAA-84-6-53 84/08/31. 44pp 26091 149 24X Fiche,50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G. Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group GEORGE,J B Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 1p 26255 194 24X Fiche 50-000,84/08/13,8408240115

DOCKETED ITEMS

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000, 84/08/13, 8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL, per NRC request
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L
Duke Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000, 84/08/14, 8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000, 84/08/14, 8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L
Duke Power Co 84/08/23 BERLINGER, C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000, 84/08/23, 8408290179

8408300232 Forwards description of program to implement TDI diesel insp requirements for restart & methods used to determine ESF loads, per 840726 request Program covers insps, tests & maint & surveillance activities
MEDFORD, M O Southern California Edison Co 84/08/28 PAULSON, W A
Operating Reactors Branch 5 12pp 26300 111 24X
Fiche 50-206, 84/08/28, 8408300232

T Hearing transcripts on non-antitrust matters

8406220259 Board Notification 84-120 forwards transcripts of 840426, 0502 & 24 meetings w/TDI Owners Group re status of program to establish diesel generator reliability
EISENHUT, D G Division of Licensing 84/06/20 PALLADINO, GILINSKY, ROBERTS Commissioners 54pp 25206 099 24X
Fiche 50-000, 84/06/20, 8406220259

V Operator Examinations

8408310243 Forwards Exam Rept 50-206/OL-84-01 administered on 840710-13, written exam & answer key
PATE, R J Region 5, Office of Director 84/08/03 BASKIN, K P
Southern California Edison Co 1p 26334 001 24X
Fiche 50-206, 84/08/03, 8408310243

--8408310244 Exam Rept 50-206/OL-84-01 administered on 840710-13 Exam results all candidates passed
ELIN, J O , MILLER, L F Region 5, Office of Director 84/07/31
109pp 26334 002 24X Fiche 50-206, 84/08/03, 8408310243

DOCKET 50-213 HADDAM NECK PLANT

E Security, medical, emergency & fire protection plans

8408090180 Responds to NRC 840419 ltr re violations noted in IE Insp Rept 50-213/84-03 Corrective actions cavity water level indication will be permanently installed
COUNSIL, W G Connecticut Yankee Atomic Power Co 84/05/17
STAROSTECKI, R Division of Project & Resident Programs 3pp
25992 072 24X Fiche 50-213, 84/05/17, 8408090180

8408090133 Forwards IE Insp Rept 50-213/84-07 on 840401-0605 No violations observed
STAROSTECKI, R Division of Project & Resident Programs 84/07/20
COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 25994 305
24X Fiche 50-213, 84/07/20, 8408090133

--8408090141 IE Insp Rept 50-213/84-07 on 840401-0605 No violations observed Major areas inspected turbine bldg, physical security, primary auxiliary bldg, auxiliary feed pump room & radiation protection Info deleted (ref 10CFR2 790)
SWETLAND, P D Region 1, Office of Director ELSASSER, T C
Division of Project & Resident Programs 84/06/22 13pp
25994 307 24X Fiche 50-213, 84/07/20, 8408090133

8408150251 Forwards IE Insp Rept 50-213/84-12 on 840605-0715 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/07/25
COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 26077 002
24X Fiche 50-213, 84/07/25, 8408150251

--8408150255 IE Insp Rept 50-213/84-12 on 840605-0715 No violations noted Major areas inspected control room, turbine bldg, primary auxiliary bldg, auxiliary feed pump room, radiation protection, physical security & plant procedures
SWETLAND, P D , ELSASSER, T C Region 1, Office of Director
84/07/24 12pp 26077 004 24X Fiche 50-213 84/07/25, 8408150251

8408160328 Revised Emergency Plan Implementing Procedures EPIP 1 5-2, "Notification & Communication," EPIP 1 5-10, "Offsite Emergency Radiological Surveys' & EPIP 1 5-45, "Emergency Communications Sys Testing ' W/840813 ltr
COUNSIL, W G Connecticut Yankee Atomic Power Co 84/08/13 83pp
26088 314 24X Fiche 50-213, 84/08/13, 8408160328

8408160350 Forwards revised emergency plan implementation procedures, including CONI 1 02 re corporate organization for nuclear incidents & CONI 4 02 re on-call manager or radiological consequences assessment W/o encls
COUNSIL, W G Northeast Utilities 84/08/13 Record Services Branch (Document Control Desk) 2pp) 26091 193 24X
Fiche 50-000, 84/08/13, 8408160350

8408280171 Responds to 840712 interpretation of order confirming licensee commitments on emergency capability, focusing on Suppl 1 to NUREG-0737 requirements Integrated assessment to be conducted pending Congressional consent
EISENHUT, D G Division of Licensing 84/08/23 COUNSIL, W G
Connecticut Yankee Atomic Power Co 3pp 26279 224 24X
Fiche 50-000, 84/08/23, 8408280171

8408310187 Submits update to corrective actions taken re deficiencies noted during 840512 emergency preparedness exercise Emergency action level procedure revised to place greater emphasis on classification/reclassification of emergencies
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/08/23 MURLEY, T E Region 1, Office of Director 3pp 26318 330 24X Fiche 50-000, 84/08/23, 8408310187

H General correspondence

8408070321 Advises that K McCarthy should appear on license amends as appropriate state official to receive amend applications McCarthy new director of radiation control for State of CT, Dept of Environ Protection
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/07/27 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 1p
25945 128 24X Fiche 50-000, 84/07/27, 8408070321

P Operating license stage documents & correspondence

8408070154 Ack receipt of 840409 application re revised inservice insp & testing program Remittance of Class III fee requested since review involves single safety issue
DIGGS, R M Office of Administration 84/07/30 COUNSIL, W G
Connecticut Yankee Atomic Power Co 1p 25957 118 24X
Fiche 50-213, 84/07/30, 8408070154

8408100063 Forwards Vols I & II of "NUSCo Thermal Hydraulic Model Qualification," for RETRAN & VIPRE
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/07/30 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5
2pp 25987 072 24X Fiche 50-213, 84/07/30, 8408100063

--8408100070 Vol I of "NUSCo Thermal Hydraulic Model Qualification (RETRAN) "
* Northeast Utilities NUSCO 140-1 84/07/30 262pp
25987 074 24X Fiche 50-213, 84/07/30, 8408100063

--8408100077 Vol II of "NUSCo Thermal Hydraulic Model Qualification (VIPRE) "
* Northeast Utilities NUSCO 140-2 84/07/30 225pp
25987 336 24X Fiche 50-213, 84/07/30, 8408100063

8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers," omitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/07/31
KAY, J A Yankee Atomic Electric Co COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 25955 227 24X
Fiche 50-000, 84/07/31, 8408070099

8408070320 Ack receipt of 840608 ltr forwarding Rev 6 to QA program topical rept, per 10CFR50 54 & 50 55 Revs acceptable
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 25945 244
24X Fiche 50-000, 84/08/01, 8408070320

8408070210 Informs that proposed radiological effluent Tech Specs under review by NRC & Franklin Research Ctr NRC guidelines for radiological effluent Tech Spec 840816-17 meetings encl
PAULSON, W A Operating Reactors Branch 5 84/08/03 COUNSIL, W G
Connecticut Yankee Atomic Power Co 2pp 25949 361 24X
Fiche 50-213, 84/08/03, 8408070210

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140408 Forwards request for addl info to complete evaluation of util 830311 response to Generic Ltr 82-28 re inadequate core cooling instrument sys, NUREG-0737, Item II F 2
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/08/06
COUNSIL, W G Connecticut Yankee Atomic Power Co 6pp 26050 349
24X Fiche 50-213, 84/08/06, 8408140408

8408290298 Requests extension until 841214 to respond to Generic Ltr 84-15 re proposed staff actions to improve & maintain diesel generator reliability Addl time will result in more complete & concise submittal
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/08/17 EISENHUT, D G
Division of Licensing 2pp 26290 342 24X Fiche 50-000, 84/08/17, 8408290298

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408220326 Forwards safety evaluation & technical evaluation rept re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants - Phase I " Sections 5 1 1 & 5 3 satisfied Phase I acceptalbe
PAULSON, W A Operating Reactors Branch 5 84/08/20 COUNSIL, W G
Connecticut Yankee Atomic Power Co 2pp 26193 111 24X
Fiche 50-213, 84/08/20, 8408220326

--8408220330 Safety evaluation re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants - Phase I "
* Operating Reactors Branch 5 84/08/20 2pp 26193 113 24X
Fiche 50-213, 84/08/20, 8408220326

--8407300136 "Control of Heavy Loads, Connecticut Yankee Atomic Power Co, Haddam Neck Plant," technical evaluation rept
BOMBERGER, C Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5506-358 84/07/25 SINGH, A NRC - No
Detailed Affiliation Given 24pp 26193 115 24X
Fiche 50-213, 84/08/20, 8408220326

8408230386 Notification of 840823 meeting w/util in Bethesda, MD to discuss amend request to increase amount of zirconium in four zirconium clad demonstration assemblies
LYONS, J E Operating Reactors Branch 5 84/08/21 PAULSON, W A
Operating Reactors Branch 5 3pp 26205 312 24X
Fiche 50-213, 84/08/21, 8408230386

8408300135 Forwards proprietary topical repts, Suppl 1 to "Northeast Utils Loss of Coolant Analysis Program" & "Calculative Methods for Northeast Utils Small Break LOCA ECCS Evaluation Model," for review Repts withheld (ref 10CFR2 790)
COUNSIL, W G Connecticut Yankee Atomic Power Co 84/08/23
PAULSON, W A Operating Reactors Branch 5 5pp 26305 189 24X
Fiche 50-213, 84/08/23, 8408300135

G Inspection reports, IE Bulletins & correspondence

8408090180 Responds to NRC 840419 ltr re violations noted in IE Insp Rept 50-213/84-03 Corrective actions cavity water level indication will be permanently installed
COUNSIL, W G Connecticut Yankee Atomic Power Co 84/05/17
STAROSTECKI, R Division of Project & Resident Programs 3pp
25992 072 24X Fiche 50-213, 84/05/17, 8408090180

8408060190 Forwards IE Insp Rept 50-213/84-06 on 840509-11 No violations noted Items of concern noted in App A
MARTIN, T T Division of Engineering & Technical Programs 84/07/09
COUNSIL, W G Connecticut Yankee Atomic Power Co 3pp 25935 191
24X Fiche 50-213, 84/07/09, 8408060190

--8408060208 IE Insp Rept 50-213/84-06 on 840509-11 No violations noted Major areas inspected status of previously identified insp items & IE Insp Procedures 82206, 82207 & 82208
SMITH, R H , CROCKER, H W Region 1, Office of Director 84/06/26
3pp 25935 194 24X Fiche 50-213, 84/07/09, 8408060190

8408090133 Forwards IE Insp Rept 50-213/84-07 on 840401-0605 No violations observed
STAROSTECKI, R Division of Project & Resident Programs 84/07/20
COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 25994 305
24X Fiche 50-213, 84/07/20, 8408090133

--8408090141 IE Insp Rept 50-213/84-07 on 840401-0605 No violations observed Major areas inspected turbine bldg, physical security, primary auxiliary bldg, auxiliary feed pump room & radiation protection Info deleted (ref 10CFR2 790)
SWETLAND, P D Region 1, Office of Director ELSASSER, T C
Division of Project & Resident Programs 84/06/22 13pp
25994 307 24X Fiche 50-213, 84/07/20, 8408090133

8408150251 Forwards IE Insp Rept 50-213/84-12 on 840605-0715 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/07/25
COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 26077 002
24X Fiche 50-213, 84/07/25, 8408150251

--8408150255 IE Insp Rept 50-213/84-12 on 840605-0715 No violations noted Major areas inspected control room, turbine bldg, primary auxiliary bldg, auxiliary feed pump room, radiation protection, physical security & plant procedures
SWETLAND, P D , ELSASSER, T C Region 1, Office of Director
84/07/24 12pp 26077 004 24X Fiche 50-213, 84/07/25, 8408150251

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070154 Ack receipt of 840409 application re revised inservice insp & testing program Remittance of Class III fee requested since review involves single safety issue
DIGGS, R M Office of Administration 84/07/30 COUNSIL, W G
Connecticut Yankee Atomic Power Co 1p 25957 118 24X
Fiche 50-213, 84/07/30, 8408070154

8408100116 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Entry & engineering evaluation for Millstone Unit 2 will be done by Feb 1985 refueling outage No Ray Miller products supplied at Haddam
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Connecticut Yankee Atomic Power Co
COUNSIL, W G Northeast Utilities 84/07/31 MURLEY, T E Region 1, Office of Director 3pp 25988 247 24X Fiche 50-000, 84/07/31, 8408100116

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408240220 Forwards Insp Rept 50-213/84-11 on 840626-29 & notices of violation & deviation
MARTIN, T T Division of Engineering & Technical Programs 84/08/06
COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 26236 300
24X Fiche 50-213, 84/08/06, 8408240220

--8408240223 Notice of violation from insp on 840626-29
* Region 1, Office of Director 84/07/31 2pp 26236 302 24X
Fiche 50-213, 84/08/06, 8408240220

--8408240226 Notice of deviation from insp on 840626-29
* Region 1, Office of Director 84/07/31 1p 26236 304 24X
Fiche 50-213, 84/08/06, 8408240220

--8408240231 Insp Rept 50-213/84-11 on 840626-29 Noncompliance noted receipt insps not performed on high integrity containers, QC program not conducted to ensure compliance of radwaste transfer & radwaste transfer matl not maintained
CLEMONS, P , PASCIAK, W Region 1, Office of Director 84/08/01
8pp 26236 305 24X Fiche 50-213, 84/08/06, 8408240220

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 12pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408210480 Responds to notice of violation in IE Insp Repts 50-213/83-25 & 50-245/84-07 Corrective actions taken to restore post-accident sampling sys units to svc & determine problem
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/08/10 DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 12pp 26181 196 24X Fiche 50-000, 84/08/10, 8408210480

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 11pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408220222 Forwards fee for review of revised inservice insp & testing program W/o encl
COUNSIL, W G Connecticut Yankee Atomic Power Co 84/08/13
DIGGS, R M License Fee Management Branch 1p 26194 093 24X Fiche 50-213, 84/08/13, 8408220222

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 10pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 11pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 11pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408230482 LER 84-008-00 on 840721, fire door separating safety & nonsafety-related areas discovered w/inoperable latching mechanism caused by personnel error Door repaired W/840814 ltr
ROOZINSKI, R M , GRAVES, R H Connecticut Yankee Atomic Power Co
84/08/14 3pp 26212 217 24X Fiche 50-213, 84/08/14, 8408230482

8408280107 PNO-I-84-070 on 840821, reactor vessel cavity seal failed when initially filled Caused by trip in containment sump pump under reactor vessel Licensee evaluating situation Notification of state & local authorities undertaken
SWETLAND, P , MCCABE, E Region 1, Office of Director 84/08/21 1p
26261 301 24X Fiche 50-213, 84/08/21, 8408280107

8408310107 Discusses 840821 reactor cavity seal ring failure & followup actions Evaluations of consequences of event or corrective actions incomplete NRC will be informed of findings prior to resumption of refueling activities
COUNSIL, W G Connecticut Yankee Atomic Power Co 84/08/23
CRUTCHFIELD, D Assistant Director for Safety Assessment 2pp
26322 279 24X Fiche 50-213, 84/08/23, 8408310107

8408310074 PNO-I-84-073 on 840824, offsite power lost Emergency diesel A started but did not close to bus & RHR flow for shutdown reactor lost until RHR pump supplied by emergency diesel placed on-line Tripped transformer placed on-line
SWETLAND, P , MCCABE, E Region 1, Office of Director 84/08/24 1p
26322 201 24X Fiche 50-213, 84/08/24, 8408310074

8408310111 PNO-I-84-070A on 840823, refueling cavity to reactor vessel seal failure identified during fuel transfer Cavity-to-vessel inflatable boot seal unique in US Failure w/fuel transfer tube open would result in high radiation
SWETLAND, P , MCCABE, E Region 1, Office of Director 84/08/24 1p
26322 113 24X Fiche 50-213, 84/08/24, 8408310111

8408310125 Advises that submittal of proposed corrective action for NRC review & approval will be required prior to any fuel handling over reactor or in transfer tube, per util 840823 notification of reactor cavity seal ring failure
PAULSON, W A Operating Reactors Branch 5 84/08/29 COUNSIL, W G
Connecticut Yankee Atomic Power Co 2pp 26322 109 24X
Fiche 50-213, 84/08/29, 8408310125

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8408060139 Ack receipt of 840924 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/84-05
MARTIN, T T Division of Engineering & Technical Programs 84/07/18
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
25935 161 24X Fiche 50-219, 84/07/18, 8408060139

--8408060142 Responds to NRC 840412 ltr re violations noted in IE Insp Rept 50-219/84-05 Corrective actions description of onsite meteorological monitoring sys will be included in emergency plan
FIEDLER, P B General Public Utilities - GPU Service Corp
84/05/24 MARTIN, T T Division of Engineering & Technical Programs 3pp 25935 163 24X Fiche 50-219, 84/07/18, 8408060139

8408150238 Advises that portions of 840131 Rev 15 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable Certain other portions of rev considered unacceptable Reasons stated in encl Encl withheld (ref 10CFR73 21)
MARTIN, T T Division of Engineering & Technical Programs 84/08/03
FIEDLER, P B General Public Utilities - GPU Service Corp 3pp
26066 001 24X Fiche 50-219, 84/08/03, 8408150238

8408130191 Informs of error in 840627 correspondence re NUREG-0737, Item I C 1, Table 2 Phase 1 emergency operating procedures (EOPs) not in place in Nov 1983 EOPs will be implemented prior to restart from Cycle 10 refueling outage
FIEDLER, P B General Public Utilities - GPU Service Corp 84/08/06
CRUTCHFIELD, D Operating Reactors Branch 5 1p 26006 362 24X
Fiche 50-219, 84/08/06, 8408130191

8408280291 Forwards Insp Rept 50-219/84-10 on 840316-0430 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/10
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
26282 183 24X Fiche 50-219, 84/08/10, 8408280291

--8408280293 Insp Rept 50-219/84-10 on 840316-0430 No violations noted Major areas inspected plant operations, logs & records, plant tours, physical security, radiation protection, maint observation, refueling preparations & periodic repts
WECHSELBERGER, CONGILL, C J , CONNER, E L Region 1, Office of Director 84/08/07 10pp 26282 185 24X Fiche 50-219, 84/08/10, 8408280291

8408300087 Forwards Insp Rept 50-219/84-03 on 840201-0315 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/10
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
26308 086 24X Fiche 50-219, 84/08/10, 8408300087

--8408300096 Insp Rept 50-219/84-03 on 840201-0315 No violations noted Major areas inspected previous insp items, records, plant operations, physical security, radiation protection, maint & surveillance & review of periodic repts
CONGILL, C J , WECHSELBERGER, CONNER, E L Region 1, Office of Director 84/08/08 8pp 26308 088 24X Fiche 50-219, 84/08/10, 8408300087

8408150269 Forwards "Evaluation of Detailed Control Room Design Review Summary Rept for Oyster Creek Nuclear Generating Station," technical evaluation rept, per Suppl 1 to NUREG-0737 SALP input also encl
PAULSON, W A Operating Reactors Branch 5 84/08/14 FIEDLER, P B General Public Utilities - GPU Service Corp 14pp 26067 066 24X Fiche 50-219, 84/08/14, 8408150269

--8408150275 "Evaluation of Detailed Control Room Design Review Summary Rept for Oyster Creek Nuclear Generating Station," final technical rept
* Science Applications, Inc NRC-03-82-096 1-263-07-557-48 84/07/20 35pp 26067 078 24X Fiche 50-219, 84/08/14, 8408150269

8408300172 Forwards exemption from schedular requirements re fire protection of equipment used for safe shutdown by means of separation & barriers, per 10CFR50 48(c)(4) Exemption effective until startup from Cycle 11 refueling outage
PAULSON, W A Operating Reactors Branch 5 84/08/23 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 26304 349 24X Fiche 50-219, 84/08/23, 8408300172

--8408300175 Exemption from schedular requirements re fire protection of equipment used for safe shutdown by means of separation & barriers
DENTON, H R Office of Nuclear Reactor Regulation, Director 84/08/23 General Public Utilities - GPU Service Corp 6pp 26304 351 24X Fiche 50-219, 84/08/23, 8408300172

O Adjudicatory correspondence

8408140449 Petition for revocation of license on basis of deficient character Licensee record of wrongdoing directly related to fundamental character flaws inherent within company Certificate of Svc encl
WAMBACH, P C , SHUMAKER, J Pennsylvania, Commonwealth of, SORDILL, P Women's International League for Peace & Freedom DSB 007 84/08/13 Commissioners 200pp 26061 023 24X Fiche 50-000, 84/08/13, 8408140449

8408240250 Forwards supplemental pages for 840813 petition for revocation of license of GPU on basis of deficient character
DOROSHOW, J Three Mile Island Alert DSB 258 84/08/22 Commissioners 1p 26223 018 24X Fiche 50-000, 84/08/22, 8408240250

--8408240257 Supplemental pages to petition for revocation of license on basis of deficient character Certificate of Svc encl
* General Public Utilities - GPU Service Corp 84/08/13 Atomic Safety and Licensing Board Panel 43pp 26223 019 24X Fiche 50-000, 84/08/22, 8408240250

P Operating license stage documents & correspondence

8408070052 Forwards "Evaluation of Spent Fuel Racks Structural Analysis, Oyster Creek," technical evaluation rept Adequacy of structural design cannot be determined Addl info requested within 15 days
PAULSON, W A Operating Reactors Branch 5 84/07/27 FIEDLER, P B General Public Utilities - GPU Service Corp 4pp 25956 141 24X Fiche 50-219, 84/07/27, 8408070052

--8407090037 "Evaluation of Spent Fuel Racks Structural Analysis, Oyster Creek Nuclear Generating Station," technical evaluation rept
HERRICK, R C Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-525 84/07/05 KIM, S B NRC - No Detailed Affiliation Given 34pp 25956 144 24X Fiche 50-219, 84/07/27, 8408070052

8408070300 Forwards "SEP Topic III-10A, Thermal Overload Protection for Motors of Motor Operated Valves " Methodology to determine optimum setpoints (heater size) for thermal overload relays developed
FIEDLER, P B General Public Utilities - GPU Service Corp 84/07/30 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 26106 063 24X Fiche 50-219, 84/07/30, 8408070300

--8408070306 "SEP Topic III-10A, Thermal Overload Protection for Motors of Motor Operated Valves "
* General Public Utilities - GPU Service Corp TDR 519 R00 84/07/30 33pp 25947 253 24X Fiche 50-219, 84/07/30, 8408070300

8408070454 Forwards Rev 2 to "SEP Topic VI-7 C 1, App K-Electrical Instrumentation & Control Re-Review," including new coordination plots for Faults F1-7, per 820528 commitment Trip units will installed by end of Cycle XI outage
FIEDLER, P B, General Public Utilities - GPU Service Corp 84/07/30 CRUTCHFIELD, D Operating Reactors Branch 5 27pp 25940 069 24X Fiche 50-219, 84/07/30, 8408070454

8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers," omitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/07/31 KAY, J A Yankee Atomic Electric Co KOBER, R W Rochester Gas & Electric Corp BASKIN, K P Southern California Edison Co 4pp 25955 227 24X Fiche 50-000, 84/07/31, 8408070099

8408070152 Forwards response to questions forwarded by 840727 ltr re util request to expand capacity of spent fuel pool
FIEDLER, P B General Public Utilities - GPU Service Corp 84/07/31 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 25949 358 24X Fiche 50-219, 84/07/31, 8408070152

8408070348 Forwards revised Pages 6-17 & 6-18 to 830902 submittal of facility description & SAR Amend 79 re spent fuel pool expansion
FIEDLER, P B General Public Utilities - GPU Service Corp 84/07/31 Office of Nuclear Reactor Regulation, Director 3pp 25945 196 24X Fiche 50-219, 84/07/31, 8408070348

8408070304 Forwards FR notice of environ assessment & finding of no significant impact re util 840802 request for schedular exemption from requirements of 10CFR50 44(c)(3)(iii)
PAULSON, W A Operating Reactors Branch 5 84/08/02 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 25947 224 24X Fiche 50-219, 84/08/02, 8408070304

--8408070309 Notice of environ assessment & finding of no significant impact re util 840802 request for schedular exemption from requirements of 10CFR50 44(c)(3)(iii) re isolation condenser high point vents
EISENHUT, D G Division of Licensing 84/08/02 5pp 25947 226 24X Fiche 50-219, 84/08/02, 8408070304

8408090250 Forwards Rev 0 to TDR 481, "SEP Topic VII-1A, Isolation of Reactor Protection Sys From Nonsafety Sys, Including Qualifications of Isolation Devices," failure mode & effects analysis
FIEDLER, P B General Public Utilities - GPU Service Corp 84/08/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 25972 267 24X Fiche 50-219, 84/08/03, 8408090250

--8408090257 Rev 0 to "SEP Topic VII-1A, Isolation of Reactor Protection Sys From Nonsafety Sys, Including Qualifications of Isolation Devices," failure mode & effects analysis
* General Public Utilities - GPU Service Corp TDR 481 R00 84/08/03 11pp 25972 269 24X Fiche 50-219, 84/08/03, 8408090250

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000, 84/08/06, 8408070110

8408150225 Forwards schedular exemption from compliance w/10CFR50 44 re installation of isolation condenser high point vents during current Cycle 10 refueling outage to Cycle 11 refueling outage
PAULSON, W A Operating Reactors Branch 5 84/08/09 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 26066 074 24X Fiche 50-219, 84/08/09, 8408150225

--8408150228 Schedular exemption from compliance w/10CFR50 44 re installation of isolation condenser high point vents during current Cycle 10 refueling outage to Cycle 11 refueling outage
EISENHUT, D G Division of Licensing 84/08/09 General Public Utilities - GPU Service Corp 5pp 26066 076 24X Fiche 50-219, 84/08/09, 8408150225

8408150229 Summary of 840718 meeting w/utils in Bethesda, MD re ECCS evaluation methodology for BWR-2 applications Agenda & viewgraphs encl
LOMBARDO, J J Operating Reactors Branch 5 84/08/14 Operating Reactors Branch 5 22pp 26066 048 24X Fiche 50-000, 84/08/14, 8408150229

8408220375 Responds to request for addl info re analysis to determine gas & water clearing thrust loads concerning second safety relief valve actuations in discharge lines, per NUREG-0661 Containment adequate for five & addl five valve actuation
FIEDLER, P B General Public Utilities - GPU Service Corp 84/08/15 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 26191 347 24X Fiche 50-219, 84/08/15, 8408220375

DOCKETED ITEMS

0356 Informs that procedural changes in response to Generic Ltr
8, Items 1 1 & 1 2 (post-trip review) not made by 840331
cheduled due to extended Cycle 10 outage Changes will be
prior to startup Rept re Item 4 5 3 due by 850915
LER, P B General Public Utilities - GPU Service Corp 84/08/16
ivision of Licensing 2pp 26189 355 24X
e 50-219, 84/08/16, 8408220356

0275 Generic Ltr 84-20 to all licensees of operating reactors '
icants for OLs re scheduling guidance for licensee
ittals of reloads that involve unreviewed safety
tions Svc list encl
NHUT, D G Division of Licensing 84/08/20 Consolidated
on Co of New York, Inc 17pp 26276 244 24X
ie 50-000, 84/08/20, 8408200275

0008 Forwards notice of environ assessment & finding of no
ificant impact re extension of deadline for safe
down equipment installation, per 840711 request for
dular exemption from 10CFR50 48(c)(4) requirements
SON, W A Operating Reactors Branch 5 84/08/20 FIEDLER, P B
ral Public Utilities - GPU Service Corp 2pp 26181 326 24X
ie 50-219, 84/08/20, 8408210008

8210011 Notice of environ assessment & finding of no significant
mpact re extension of deadline for safe shutdown
uipment installation
ISENHUT, D G Division of Licensing 84/08/20 4pp 26181 328
4X Fiche 50-219, 84/08/20, 8408210008

30384 Forwards SER re util resolution of integrated plant SAR
tion 4 14 re thermal overload protection of
or operated valves Program described in 840730 ltr
eptable
LSON, W A Operating Reactors Branch 5 84/08/20 FIEDLER, P B
sey Central Power & Light Co 2pp 26205 315 24X
he 50-219, 84/08/20, 8408230384

8230385 Safety evaluation re integrated plant SAR Section 4 14 re
hermal overload protection of motor operated valves Program
roposed in 840730 ltr acceptable
Operating Reactors Branch 5 84/08/20 2pp 26205 317 24X
iche 50-219, 84/08/20, 8408230384

70381 Responds to request for reliable ventilation for B battery &
or generator room & 460-volt switchgear room, per SEP
ic IX-5 New redundant relay w/switch & associated wiring
l be installed by end of next refueling outage
IDLER, P B General Public Utilities - GPU Service Corp 84/08/21
UTCHFIELD, D Operating Reactors Branch 5 2pp 26240 250 24X
he 50-219, 84/08/21, 8408270381

270285 Forwards Technical Data Rept 580 re repair & failure
alysis data for isolation condenser sys piping cracked
lds, per 840628 request concerning SER of Rev 1 to
IEG-0313 implementation
IDLER, P B General Public Utilities - GPU Service Corp 84/08/22
WILSON, W A Operating Reactors Branch 5 1p 26243 158 24X
che 50-219, 84/08/22, 8408270285

08270290 Rev 0 to "Isolation Condender Sys Piping Cracked Welds -
Repair & Failure Analysis "
ABRAMOVICI, J D , COVILL, D W , ELAM, B D General Public Utilities -
PU Service Corp 580 R00 84/08/04 86pp 26243 159 24X
Fiche 50-219, 84/08/22, 8408270285

300148 Forwards safety evaluation re NUREG-0737, Item II B 3
ncerning post-accident sampling sys Post-accident sampling
s acceptable
ULSON, W A Operating Reactors Branch 5 84/08/29 FIEDLER, P B
neral Public Utilities - GPU Service Corp 8pp 26306 001 24X
che 50-219, 84/08/29, 8408300148

nspection reports, IE Bulletins & correspondence

060139 Ack receipt of 840524 ltr informing NRC of steps taken to
rrect violations noted in IE Insp Rept 50-219/84-05
RTIN, T T Division of Engineering & Technical Programs 84/07/18
IEDLER, P B General Public Utilities - GPU Service Corp 2pp
935 161 24X Fiche 50-219, 84/07/18, 8408060139

08060142 Responds to NRC 840412 ltr re violations noted in IE Insp
Rept 50-219/84-05 Corrective actions description of onsite
meteorological monitoring sys will be included in emergency
plan
FIEDLER, P B General Public Utilities - GPU Service Corp
84/05/24 MARTIN, T T Division of Engineering & Technical
Programs 3pp 25935 163 24X Fiche 50-219, 84/07/18, 8408060139

8408080463 Forwards IE Insp Rept 50-219/84-17 on 840604-08 No
violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/07/20
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
25975 075 24X Fiche 50-219, 84/07/20, 8408080463

--8408080167 IE Insp Rept 50-219/84-17 on 840604-08 No noncompliance
noted Major areas inspected program for QA of analytical
measurements, training, ngt controls, audit results &
analytical procedures for chemistry & radiochemistry
JANG, J C , PASCIAK, W J Region 1, Office of Director 84/06/27
8pp 25975 077 24X Fiche 50-219, 84/07/20, 8408080463

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture
Intrusion in Safety-Related Electrical Equipment at
Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 11pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station
Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator
Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR
Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New
York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to
Patients Undergoing Co-60 Teletherapy Treatments " Svc
list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post
830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408230094 Ack receipt of 840725 ltr informing NRC of steps taken to
correct items noted in IE Insp Rept 50-219/83-24
MARTIN, T T Division of Engineering & Technical Programs 84/08/10
FIEDLER, P B General Public Utilities - GPU Service Corp 1p
26214 158 24X Fiche 50-219, 84/08/10, 8408230094

--8408230098 Responds to NRC 840209 ltr re items noted in IE Insp Rept
50-219/83-24 Corrective actions Procedure 125, "Engineering
Calculations & Technical Evaluations," prepared
FIEDLER, P B General Public Utilities - GPU Service Corp
84/07/25 MARTIN, T T Division of Engineering & Technical
Programs 2pp 26214 159 24X Fiche 50-219, 84/08/10, 8408230094

--8408230101 Rev 1 to Procedure 125, "Engineering Calculations &
Technical Evaluations "
General Public Utilities - GPU Service Corp 84/07/25 7pp
26214 161 24X Fiche 50-219, 84/08/10, 8408230094

8408280291 Forwards Insp Rept 50-219/84-10 on 840316-0410 No violations
noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/10
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
26282 183 24X Fiche 50-219, 84/08/10, 8408280291

--8408280293 Insp Rept 50-219/84-10 on 840316-0410 No violations noted
Major areas inspected plant operations, logs & records, plant
tours, physical security, radiation protection, maint
observation, refueling preparations & periodic repts
WECHSELBERGER, COWGILL, C J , CONNER, E L Region 1, Office of
Director 84/08/07 10pp 26282 185 24X Fiche 50-219, 84/08/10,
8408280291

8408300087 Forwards Insp Rept 50-219/84-03 on 840201-0315 No violations
noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/10
FIEDLER, P B General Public Utilities - GPU Service Corp 2pp
26308 086 24X Fiche 50-219, 84/08/10, 8408300087

--8408300096 Insp Rept 50-219/84-03 on 840201-0315 No violations noted
Major areas inspected previous insp items, records, plant
operations, physical security, radiation protection,
maint & surveillance & review of periodic repts
COWGILL, C J , WECHSELBERGER, CONNER, E L Region 1, Office of
Director 84/08/08 8pp 26308 088 24X Fiche 50-219, 84/08/10,
8408300087

8408100009 IE Info Notice 84-63, 'Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness ? Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24x Fiche 50-000, 84/08/13, 8408100009

8408310128 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller, Inc Mechanisms which can detect major breakdowns in QA program listed Current program verifies quality of safety items
FIEDLER, P B General Public Utilities - GPU Service Corp 84/08/14
EBNETER, S D Region 1, Office of Director 3pp 26322 257 24X
Fiche 50-219, 84/08/14, 8408310128

8408100038 IE Info Notice 84-64, 'BWR HPCI Initiation Seal-In & Indication ' Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Undetrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408010293 LER 84-016-00 on 840625, during review of instrument surveillance procedures, not all 60 installed excess flow check valves found functionally tested per Tech Specs Functional test surveillance rev in progress W/840724 ltr
MURDOCK, R J , FIEDLER, P B General Public Utilities GPU Service Corp 84/07/24 6pp 25866 191 24Y Fiche 50-219, 84/07/24, 8408010293

8408080498 LER 84-017-00 on 840627, during lifting of neutral electrical lead, 15 primary containment isolation valves repositioned & half scram experienced Caused by intermediate range monitor Neutral wiring configuration will be modified W/840726 ltr
ALLEN, M H , FIEDLER, P B General Public Utilities - GPU Service Corp 84/07/26 12pp 25975 220 24X Fiche 50-219, 84/07/26, 8408080498

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000, 84/08/21, 8408310186

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408060171 Revised emergency procedures, including Rev 1 to EPMP-5, "On-Call Procedure" & Rev 0 to EPMP-8, "Maint, Testing & Operation of Oswego County Prompt Notification Sys " W/840801 ltr
MANGAN, C V Niagara Mohawk Power Corp 84/08/01 87pp 25932 288 24X Fiche 50-220, 84/08/01, 8408060171

8408230226 Forwards IE Insp Rept 50-220/84-10 on 840611-15 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
HOOTEN, D G Niagara Mohawk Power Corp 2pp 26213 329 24X
Fiche 50-220 84/08/01, 8408230226

--8408230230 Notice of violation from insp on 840611-15 List of recommended emergency preparedness program improvements encl
* Region 1, Office of Director 84/07/31 2pp 26213 331 24X
Fiche 50-220, 84/08/01, 8408230226

--8408230235 IE Insp Rept 50-220/84-10 on 840611-15 Violation noted failure to conform to environ surveillance requirements for maintaining meteorological monitoring equipment
HAWXHURST, J , COHEN, I , CRACKER, H W Region 1, Office of Director 84/07/31 6pp 26213 333 24x Fiche 50-220, 84/08/01, 8408230226

8408070434 Forwards rev to "NY State Radiological Emergency Preparedness Plan "
MANGAN, C V Niagara Mohawk Power Corp 84/08/03 Record Services Branch (Document Control Desk) 2pp 25938 016 24X
Fiche 50-220, 84/08/03, 8408070434

--8408070439 Rev to "NY State Radiological Emergency Preparedness Plan "
* New York, State of 84/07/12 559pp 25938 018 24X
Fiche 50-220, 84/08/03, 8408070434

P Operating license stage documents & correspondence

8408030180 Forwards SER re completion of Multi-Plant Issues B-24, "Venting & Purging of Containment" & F-19, Item II E 4 2, "Containment Isolation Dependability " Demonstration of containment purge & vent valve operability acceptable
VASSALLO, D B Operating Reactors Branch 2 84/07/24 HOOTEN, D G
Niagara Mohawk Power Corp 7pp 25917 349 24X
Fiche 50-220, 84/07/24, 8408030180

8408060154 Completes response to Generic Ltr 84-09 re NRC decision not to backfit requirement for hydrogen recombiner capability in inerted Mark I containments to control post-accident hydrogen Capability not required
MANGAN, C V Niagara Mohawk Power Corp 84/07/31 VASSALLO, D B
Operating Reactors Branch 2 2pp 25933 051 24X
Fiche 50-220, 84/07/31, 8408060154

8408060248 Forwards addl response to Generic Ltr 83-28 re generic implications of Salem ATWS events Reactor protection sys on-line surveillance program requirements assure reliability of sys to function properly
MANGAN, C V Niagara Mohawk Power Corp 84/07/31 VASSALLO, D B
Operating Reactors Branch 2 4pp 25934 108 24X
Fiche 50-220, 84/07/31, 8408060248

8408060278 Notification of 840817 meeting w/util in Bethesda, MD to discuss control design review
HERMANN, R A Operating Reactors Branch 2 84/07/31 VASSALLO, D B
Operating Reactors Branch 2 2pp 25937 361 24X
Fiche 50-220, 84/07/31, 8408060278

8408060332 Notification of 840823-24 meetings w/utils in Waltham, MA to discuss open items on Mark I containment program
HERMANN, R A Operating Reactors Branch 2 84/07/31 VASSALLO, D B
Operating Reactors Branch 2 2pp 25937 357 24X
Fiche 50-000, 84/07/31, 8408060332

8408090077 Forwards Pages 226 & 226a to Table 3 6 2i of Tech Specs re diesel generator for instrument setpoint logic, in support of 840413 amend application Response to NRC questions also encl
MANGAN, C V Niagara Mohawk Power Corp 84/08/03 VASSALLO, D B
Operating Reactors Branch 2 1p 25993 001 24X
Fiche 50-220, 84/08/03, 8408090077

--8408090081 Proposed revs to Tech Spec Table 3 6 2i re diesel generator initiation, limiting condition for operation
* Niagara Mohawk Power Corp 84/08/03 9pp 25993 002 24X
Fiche 50-220, 84/08/03, 8408090077

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

DOCKETED ITEMS

8408100074 Forwards Rev 2 to "Leak-Before-Break Analysis of High Energy Piping Sys " Rept includes detailed stress & fracture mechanics analyses
MANGAN, C V Niagara Mohawk Power Corp 84/08/06 VASSALLO, D B
Operating Reactors Branch 2 1p 25988 285 24X
Fiche 50-220, 84/08/06, 8408100074

--8408100080 Rev 2 to "Leak-Before-Break Analysis of High Energy Piping Sys "
* MPR Associates, Inc MPR-820 R02 84/08/06 86pp 25988 287
24X Fiche 50-220, 84/08/06, 8408100074

8408100076 Forwards application for amend to License DPR-63, changing Tech Specs to remove commitment to perform independent audit under cognizance of Safety Review & Audit Board
MANGAN, C V Niagara Mohawk Power Corp 84/08/06 VASSALLO, D B
Operating Reactors Branch 2 1p 25987 020 24X
Fiche 50-220, 84/08/06, 8408100076

--8408100081 Application for amend to License DPR-63, changing Tech Specs to remove commitment to perform independent audit under cognizance of Safety Review & Audit Board
MANGAN, C V Niagara Mohawk Power Corp 84/08/06 2pp
25987 021 24X Fiche 50-220, 84/08/06, 8408100076

--8408100086 Proposed Tech Specs, removing commitment to perform independent audit under cognizance of Safety Review & Audit Board
* Niagara Mohawk Power Corp 84/08/06 4pp 25987 023 24X
Fiche 50-220, 84/08/06, 8408100076

8408100103 Forwards application for amend to License DPR-63, per Generic Ltr 83-19 Fee encl
MANGAN, C V Niagara Mohawk Power Corp 84/08/07 VASSALLO, D B
Operating Reactors Branch 2 1p 25990 355 24X
Fiche 50-220, 84/08/07, 8408100103

--8408100111 Application for amend to License DPR-63, changing Tech Specs by deleting "all" from review & audit section, to be consistent w/Rev 2 to BWR Tech Specs (NUREG-0123)
MANGAN, C V Niagara Mohawk Power Corp 84/08/07 5pp
25990 356 24X Fiche, 50-220, 84/08/07, 8408100103

--8408100120 Proposed Tech Spec 6 5 2 B re audits
* Niagara Mohawk Power Corp 84/08/07 1p 25990 361 24X
Fiche 50-220, 84/08/07, 8408100103

8408170079 Informs of review of 840610 & 11 QA program description changes Changes acceptable Concerns in unrevised portions of program noted
MARTIN, T T Division of Engineering & Technical Programs 84/08/09
HOOTEN, B J Niagara Mohawk Power Corp 2pp 26119 022 24X
Fiche 50-220, 84/08/09, 8408170079

8408150229 Summary of 840718 meeting w/utils in Bethesda, MD re ECCS evaluation methodology for BWR-2 applications Agenda & viewgraphs encl
LOMBARDO, J J Operating Reactors Branch 5 84/08/14 Operating Reactors Branch 5 22pp. 26066 048 24X Fiche 50-000, 84/08/14, 8408150229

8408160367 Forwards "SER, Evaluation of Turbine Missile Protection," per B00619 commitment Safe shutdown capability would be maintained if turbine missile generated
MANGAN, C V Niagara Mohawk Power Corp 84/08/14 VASSALLO, D B
Operating Reactors Branch 2 1p 26091 237 24X
Fiche 50-220, 84/08/14, 8408160367

-8408160372 "SER, Evaluation of Turbine Missile Protection "
* Niagara Mohawk Power Corp 84/07/31 4pp 26091 238 24X
Fiche 50-220, 84/08/14, 8408160367

408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408300035 Forwards application for amend to License DPR-63, changing Tech Specs re containment leak test program Application supplS 831101 amend request
MANGAN, C V Niagara Mohawk Power Corp 84/08/27 VASSALLO, D B
Operating Reactors Branch 2 1p 26306 028 24X
Fiche 50-220, 84/08/27, 8408300035

--8408300037 Application for amend to License DPR-63, changing Tech Specs to revise containment leak test program
MANGAN, C V Niagara Mohawk Power Corp 84/08/27 2pp
26306 029 24X Fiche 50-220, 84/08/27, 8408300035

--8408300041 Proposed changes to Tech Specs, revising containment leak test program
* Niagara Mohawk Power Corp 84/08/27 46pp 26306 031 24X
Fiche 50-220, 84/08/27, 8408300035

G Inspection reports, IE Bulletins & correspondence

8408080456 Forwards IE Insp Rept 50-220/84-08 on 840509-11 & 0606-08 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/07/18
HOOTEN, B G Niagara Mohawk Power Corp 2pp 25975 066 24X
Fiche 50-220, 84/07/18, 8408080456

--8408080461 IE Insp Rept 50-220/84-08 on 840509-11 & 0606-08 No violations noted Major areas inspected containment leakage testing program, including procedure review of integrated leak rate test & local leak rate test procedures
VITO, D J Region 1, Office of Director BETTENHAUSEN, L Division of Engineering & Technical Programs 84/06/29 7pp 25975 068
24X Fiche 50-220, 84/07/18, 8408080456

8408080204 Forwards IE Insp Rept 50-220/84-12 on 840618-22 No violations observed
MARTIN, T T Division of Engineering & Technical Programs 84/07/19
HOOTEN, B G , SEIBERT, C R Niagara Mohawk Power Corp 2pp
25975 016 24X Fiche 50-220, 84/07/19, 8408080204

--8408080209 IE Insp Rept 50-220/84-12 on 840618-22 No violations noted Major areas inspected nonradiological chemistry program, including staffing & training, QC of analytical measurements & procedures
ZIBULSKY, H , PASCIAK, W J Region 1, Office of Director 84/07/19
3pp 25975 018 24X Fiche 50-220, 84/07/19, 8408080204

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408230226 Forwards IE Insp Rept 50-220/84-10 on 840611-15 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
HOOTEN, B G Niagara Mohawk Power Corp 2pp 26213 329 24X
Fiche 50-220, 84/08/01, 8408230226

--8408230230 Notice of violation from insp on 840611-15 List of recommended emergency preparedness program improvements encl
* Region 1, Office of Director 84/07/31 2pp 26213 331 24X
Fiche 50-220, 84/08/01, 8408230226

--8408230235 IE Insp Rept 50-220/84-10 on 840611-15 Violation noted failure to conform to environ surveillance requirements for maintaining meteorological monitoring equipment
HAWKHURST, J , COHEN, I , CRACKER, H W Region 1, Office of Director
84/07/31 6pp 26213 333 24X Fiche 50-220, 84/08/01, 8408230226

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

DOCKETED ITEMS

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408280245 Ack receipt of 840731 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-220/80-11
MARTIN, T T Division of Engineering & Technical Programs 84/08/20
HOOTEN, B G Niagara Mohawk Power Corp 2pp 26262 001 24X
Fiche 50-220, 84/08/20, 8408280245

--8408280248 Responds to NRC ltr re violations noted in Insp Rept 50-220/80-11 Corrective actions addl supervisory & technical personnel added to radiation protection organization & respiratory protective equipment procedures revised
LEMPGES, T E Niagara Mohawk Power Corp 84/07/31 MURLEY, T E
Region 1, Office of Director 5pp 26262 003 24X
Fiche 50-220, 84/08/20, 8408280245

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408020115 Forwards revised rept of operating experience of monthly operating rept for Jul 1983
LEMPGES, T E Niagara Mohawk Power Corp 84/07/26 Director's Office, Office of Inspection and Enforcement 2pp 25892 264 24X
Fiche 50-220, 84/07/26, 8408020115

--8408020119 Revised operating experience rept, monthly operating rept for Jul 1983
ROMAN, T W Niagara Mohawk Power Corp 83/07/31 4pp 25892 266
24X Fiche 50-220, 84/07/26, 8408020115

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408030201 LER 84-011-00 on 840603, scram occurred when reactor mode switch changed to shutdown Caused by improper connection on reactor protection sys (RPS) Channel 11 RPS channel removed & checked W/840702 ltr
RANDALL, R , LEMPGES, T E Niagara Mohawk Power Corp 84/07/02 3pp
25917 119 24X Fiche 50-220, 84/07/02, 8408030201

8408080259 LER 84-013-01 on 840614, during testing, three main steam line solenoid actuated relief valves failed Two valves stuck open Caused by seat leakage Maint performed On 840617, three valves leaked again W/840727 ltr
RANDALL, R , LEMPGES, T E Niagara Mohawk Power Corp 84/07/27 4pp
25974 337 24X Fiche 50-220, 84/07/27, 8408080259

8408080483 LER 84-014-01 on 840617, during startup & re-testing of main steam line solenoid-actuated relief valves, one valve stuck open & three indicated seat leakage Reactor shut down & maint performed All valves operable on 840622 W/840727 ltr
RANDALL, R , LEMPGES, T E Niagara Mohawk Power Corp 84/07/27 4pp
25975 181 24X Fiche 50-220, 84/07/27, 8408080483

8408200535 LER 84-009-00, on 840713, loss of plant process computer caused each Acurex channel to become inoperable Channels disconnected from computer & manually restored to operable status Software changed to avoid future error W/840813 ltr
RANDALL, R , MANOAN, C V Niagara Mohawk Power Corp 84/08/13 3pp
26139 024 24X Fiche 50-220, 84/08/13, 8408200535

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl OE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000, 84/08/21, 8408310186

X Onsite Storage of Low Level Waste

8408230237 Forwards certificate re pollution control facilities for NRC signature per Internal Revenue Svc requirements Info re radwaste solidification & storage bldg, radioactive solid waste & spent fuel storage encl for approval
MANGAN, C V Niagara Mohawk Power Corp 84/08/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 26207 278
24X Fiche 50-220, 84/08/21, 8408230237

DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR

P Operating license stage documents & correspondence

8408060369 Informs of expiration of License R-125 on 850420 & outlines procedures for preparing renewal application Copy of Univ of Virginia renewal application encl for guidance
THOMAS, C O Standardization & Special Projects Branch 84/07/30
DEGHIAN, L Lowell, Univ of, Lowell, MA 5pp 25951 238 24X
Fiche 50-223, 84/07/30, 8408060369

DOCKET 50-225 RPI CRITICAL EXPERIMENT

F Security, medical, emergency & fire protection plans

8408070097 Forwards request for addl info re 840206 proposed revised emergency plan, per 10CFR50, App E requirements, Rev 1 to Reg Guide 2 6 & ANSI/ANS-15 16-1982 Response requested within 60 days of ltr receipt
THOMAS, C O Standardization & Special Projects Branch 84/07/30
HARRIS, D R Rensselaer Polytechnic Institute, Troy, NY 9pp
25955 241 24X Fiche 50-225, 84/07/30, 8408070097

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8404040169 Forwards exercise repts for LaSalle & Dresden offsite radiological emergency preparedness exercises conducted 820414-15 & 0629-30, respectively
KRIMM, R W Federal Emergency Management Agency 84/03/26
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 22883 122 24X Fiche 50-000, 84/03/26, 8404040169

8408140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 84/08/03 Region 3, Office of Director 1p 26044 252 24X Fiche 50-000, 84/08/03, 8408140139

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO, C J Region 3, Office of Director 84/08/07 REED, C
Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000, 84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR, D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J
Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000, 84/08/07, 8408130401

8408130289 Forwards FR notice of environ assessment & finding of no significant impact re 840405 & 26 requests for exemption of state & local govt participation in 840605 exercise
PAULSON, W A Operating Reactors Branch 5, 84/08/10 FARRAR, D L
Commonwealth Edison Co 2pp 26010 262 24X Fiche 50-010, 84/08/10, 8408130289

--8408130298 Notice of environ assessment & finding of no significant impact re exemption from requirements of 10CFR50, App E re state & local govt participation at 840605 exercise
EISENHUT, D, G Division of Licensing 84/08/10 4pp 26010 264
24X Fiche 50-010, 84/08/10, 8408130289

DOCKETED ITEMS

140397 Forwards summary of App R re-verification methodology & status per 840627 commitment to submit results of hot shutdown portion of fire protection program independent review W/28 oversize drawings Aperture cards in PDR
FARRAR, D L Commonwealth Edison Co 84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 222pp 26049 079 24X Fiche 50-237, 84/08/10, 8408140397

200281 Advises that 840803 Rev 15 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
OLSON, W L Region 3, Office of Director 84/08/14 FARRAR, D L Commonwealth Edison Co 2pp 26193 023 24X Fiche 50-010, 84/08/14, 08200281

210001 Forwards exemption from certain requirements of Section F 1 of App E to 10CFR50 for Dresden 840605 emergency preparedness exercise w/o full-scale participation by state local govts in plume exposure pathway
NILSON, W A Operating Reactors Branch 5 84/08/14 FARRAR, D L Commonwealth Edison Co 3pp 26181 320 24X Fiche 50-010, 84/08/14, 08210001

08210005 Exemption from Section IV F 1 of App E to 10CFR50 requiring full-scale emergency preparedness exercise at least annually, involving participation of state & local govts within plume exposure pathway emergency planning zone
EISENHUT, D G Division of Licensing 84/08/14 Commonwealth Edison Co 3pp 26181 323 24X Fiche 50-010, 84/08/14, 8408210001

230283 Revised emergency plan implementing procedures, including EIP 100-C3 re generating station emergency plan log, replacing record of generating station emergency plan activities form W/840920 ltr
SCOTT, D J Commonwealth Edison Co 84/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 67pp 26207 295 24X Fiche 50-010, 84/08/20, 8408230283

Operating license stage documents & correspondence

30460425 Notification of 840809-10 meetings w/utils, NUTECH, Franklin Research Ctr & BNL in San Jose, CA to discuss comments resulting from post-implementation review re plant-unique analysis repts
EVANS, R B , ROONEY, V L , THADANI, M C Operating Reactors Branch 2 1/07/31 VASSALLO, D B Operating Reactors Branch 2 1p 5937 335 24X Fiche 50-000, 84/07/31, 8408060425

80700099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers," mitted from 840503 ltr to all SEP licensees NRC position hat issue of Tech Specs for snubbers will be resolved on eneric basis restated
RUTCHFIELD, D Assistant Director for Safety Assessment 84/07/31 AY, J A Yankee Atomic Electric Co COUNSIL, W G Connecticut ankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co subs of Northeast Utilities) 4pp 25955 227 24X iche 50-000, 84/07/31, 8408070099

8150113 Forwards reformatted Tech Specs improving legibility & ersatility, per request W/o encl
YBAK, B Commonwealth Edison Co 84/08/01 DENTON, H R Office of uclear Reactor Regulation, Director 1p 26066 351 24X iche 50-237, 84/08/01, 8408150113

80602?6 Forwards revised Tech Spec changes to Licenses DPR-19 & PR-25, submitted on 840611 Tech Specs revised into new ormat, incorporating NRC comments w/o changing technical ontent
YBAK, B Commonwealth Edison Co 84/08/02 DENTON, H R Office of uclear Reactor Regulation, Director 3pp 25933 223 24X iche 50-237, 84/08/02, 8408060276

8408060280 Proposed Tech Specs, revising format to incorporate NRC comments w/o changing technical content
* Commonwealth Edison Co 84/08/02 30pp 25933 224 24X Fiche 50-237, 84/08/02, 8408060276

80701?0 Generic Ltr 84-19 to all licensees of operating reactors, pplicants for OLs & holders of CPs re availability of uppl 1 to NUREG-0933, "Prioritization of Generic Safety ssues " Svc list encl
ISENHUT, D G Division of Licensing 84/08/06 Consolidated dison Co of New York, Inc 18pp 26129 238 24X iche 50-000, 84/08/06, 8408070110

80703?7 Forwards monthly status rept re plant-specific backfitting ctivities for operating reactors & license applicants for ul 1984
REMELAY, P F Operating Reactors Assessment Branch 84/08/06 OLAHAN, G M Operating Reactors Assessment Branch 13pp 5991 350 24X Fiche 50-000, 84/08/06, 8408090317

8408160062 Forwards Amends 82 & 75 to Licenses DPR-19 & DPR-25 respectively Amends consist of reformatted Tech Specs to provide clarity
PAULSON, W A Operating Reactors Branch 5 84/08/06 FARRAR, D L Commonwealth Edison Co 3pp 26092 189 24X Fiche 50-237, 84/08/06, 8408160062

--8408160070 Amends 82 & 75 to Licenses DPR-19 & DPR-25, respectively, consisting of reformatted Tech Specs
PAULSON, W A Operating Reactors Branch 5 84/08/06 600pp 26092 192 24X Fiche 50-237, 84/08/06, 8408160062

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X Fiche 50-000, 84/08/06, 8408160345

8408170017 Notifies of Class I & II Fees due for 840611 Tech Spec change request Fee will be adjusted if appropriate
DIGGS, R M License Fee Management Branch 84/08/10 FARRAR, D L Commonwealth Edison Co 1p 26135 344 24X Fiche 50-237, 84/08/10, 8408170017

8408270114 Provides supplemental response to Generic Ltr 83-36, "NUREG-0737 Tech Specs " Mods to Quad Cities Radiological ERS will not be complete until Fall 1984 Complete response w/amend requests expected by 841115
ALEXANDER, G L Commonwealth Edison Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26247 390 24X Fiche 50-000, 84/08/15, 8408270114

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000, 84/08/20, 8408200275

8408310211 Forwards final response to second & final set of questions re Mark I containment plant-unique analysis
RYBAK, B Commonwealth Edison Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 37pp 26318 072 24X Fiche 50-000, 84/08/24, 8408310211

8408300102 Forwards corrected pages to 840806 Amends 82 & 75 to Licenses DPR-19 & DPR-25, respectively
PAULSON, W A Operating Reactors Branch 5 84/08/27 FARRAR, D L Commonwealth Edison Co 2pp 26306 135 24X Fiche 50-237, 84/08/27, 8408300102

--8408300111 Corrected pages to Amends 82 & 75 to Licenses DPR-19 & DPR-25, respectively
PAULSON, W A Operating Reactors Branch 5 84/08/27 3pp 26306 137 24X Fiche 50-237, 84/08/27, 8408300102

O Inspection reports, IE Bulletins & correspondence

8408030?51 Ack receipt of 840622 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/84-05, 50-237/84-07 & 50-249/84-06
PAPERIELLO, C J Region 3, Office of Director 84/07/10 REED, C Commonwealth Edison Co 1p 25917 226 24X Fiche 50-010, 84/07/10, 8408030251

--8408030252 Responds to NRC 840524 ltr re violations noted in IE Insp Repts 50-010/84-05, 50-237/84-07 & 50-249/84-06 Corrective actions sludge removed from Toledo & Joliet Facilities Survey of sumps found no residual activity
FARRAR, D L Commonwealth Edison Co 84/06/22 KEPPLER, J G Region 3, Office of Director 4pp 25917 227 24X Fiche 50-010, 84/07/10, 8408030251

8407250?29 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC
NORELIUS, C E Region 3, Office of Director 84/08/03 REED, C Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000, 84/08/03, 8408070066

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, 84/08/08, 8408140344

8408150098 SupplS 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26067 053 24X
Fiche 50-000, 84/08/08, 8408150098

8408200331 SupplS response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26132 318 24X
Fiche 50-000, 84/08/08, 8408200331

8408300095 Forwards Insp Repts 50-010/84-10, 50-237/84-12 & 50-249/84-11 on 840618-0726 & notice of violation
SHAFER, W D Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26307 201 24X Fiche 50-010, 84/08/08, 8408300095

--8408300099 Notice of violation from insp on 840618-0726
SHAFER, W D Region 3, Office of Director 84/08/08 1p
26307 203 24X Fiche 50-010, 84/08/08, 8408300095

--8408300108 Insp Repts 50-010/84-10, 50-237/84-12 & 50-249/84-11 on 840618-0726 Noncompliance noted inadequate corrective action taken in response to Tech Spec violation re open submarine door in Unit 2 reactor bldg
TONGUE, T M , STASEK, S , ANDERSON, C D Region 3, Office of Director 84/08/07 11pp 26307 204 24X Fiche 50-010, 84/08/08, 8408300095

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408160139 Ack receipt of 840730 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-010/84-09, 50-237/84-11 & 50-249/84-10
SHAFER, W D Region 3, Office of Director 84/08/10 REED, C
Commonwealth Edison Co 1p 26092 040 24X Fiche 50-010, 84/08/10, 8408160139

--8408160145 Responds to NRC 840703 ltr re noncompliance noted in IE Insp Repts 50-010/84-09, 50-237/84-11 & 50-249/84-10 Corrective actions special procedure for testing automatic function of master pilot valve incorporated into existing Cardox sys
FARRAR, D L Commonwealth Edison Co 84/07/30 KEPPLER, J G
Region 3, Office of Director 3pp 26092 041 24X
Fiche 50-010, 84/08/10, 8408160139

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "RWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408300368 "Rept of Radioactive Effluents," Jan-June 1984 W/840815 ltr
SCOTT, D J Commonwealth Edison Co 84/06/30 KEPPLER, J G Region 3, Office of Director 17pp 26308 1/2 24X Fiche 50-010, 84/06/30, 8408300368

8408130271 Monthly operating repts for Jul 1984 W/840803 ltr
SCHROEDER, D A , SCOTT, D J Commonwealth Edison Co 84/07/31 20pp 26006 342 24X Fiche 50-237, 84/07/31, 8408130271

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408130330 LER 84-012-00 on 840709, reactor scrammed Caused by instrument mechanic mistakenly turning reactor protective sys Channel B instead of Channel A hydrogen addition switch to off W/840807 ltr
WOJTULEWICZ, T , SCOTT, D J Commonwealth Edison Co 84/07/17 3pp 26010 325 24X Fiche 50-237, 84/07/17, 8408130330

8408060100 LER 84-010-00 on 840626, during startup, feeder breaker position in control room lost on breaker at bus 29 which feeds MCC 28-7 & 29-7 Breaker inadvertently tripped Caused by loose wire Operator training conducted W/840724 ltr
BERGAN, G W , SCOTT, D J Commonwealth Edison Co 84/07/24 4pp 25936 024 24X Fiche 50-237, 84/07/24, 8408060100

8408060203 LER 84-007-00 on 840628, during hot standby, fuse 2330-702 removed, causing loss of automatic control for LPCI/component cooling water sys HX delta p Caused by wiring sys using same fuse circuits W/840725 ltr
COYLE, L , SCOTT, L Commonwealth Edison Co 84/07/25 3pp 25935 199 24X Fiche 50-237, 84/07/25, 8408060203

8408060293 LER 84-011-00 on 840705, several mechanical penetrations found not sealed Fire watch established Penetrations sealed w/cerafiber & vimasco W/840726 ltr
MERRITT, S , SCOTT, D J Commonwealth Edison Co 84/07/26 3pp 25936 083 24X Fiche 50-237, 84/07/26, 8408060293

8408090052 LER 84-015-00 on 840627, during startup operation, time pumpdown of drywell equipment & floor drain sumps not performed at proper time Personnel involved given addl training W/840802 ltr
SMITH, G L , SCOTT, D J Commonwealth Edison Co 84/08/02 3pp 25992 136 24X Fiche 50-237, 84/08/02, 8408090052

8408090151 LER 84-014-00, on 840109, during normal operations, HPCI Turbine Trip Low Pressure Surveillance DIS 2300-3 performed late Caused by personnel error Addl training provided W/840802 ltr
SMITH, G L , SCOTT, D J Commonwealth Edison Co 84/08/02 3pp 25993 191 24X Fiche 50-237, 84/08/02, 8408090151

8408310067 LER 84-006-01 on 840208, east LPCI corner room submarine door to torus basement open & unattended Caused by personnel error Personnel retrained W/840809 ltr
LEAHY, M , SCOTT, D J Commonwealth Edison Co 84/08/09 4pp
26334 345 24X Fiche 50-237, 84/08/09, 8408310067

8408310063 LER 84-008-01 on 840530, during fire protection Tech Spec audit, lack of Cardox sys master valve test in automatic mode noted Surveillance procedure revised to test valve in both manual & automatic modes W/840813 ltr
MERRITT, S , SCOTT, D J Commonwealth Edison Co 84/08/13 4pp
26334 352 24X Fiche 50-237, 84/08/13, 8408310063

8408240218 LER 84-013-00 on 840722, flow bypass valve FV-1 of electro hydraulic control sys opened causing turbine trip & reactor scram Caused by personnel error Investigation committee convened to review event W/840817 ltr
COYLE, L , SCOTT, D J Commonwealth Edison Co 84/08/15 3pp
26236 297 24X Fiche 50-237, 84/08/15, 8408240218

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/08/16
EISENHUT, D G Division of Licensing 20pp 26233 249 24X
Fiche 50-000, 84/08/16, 8408230077

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 RDSBI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000, 84/08/21, 8408310186

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26051 240
24X Fiche 50-000, 84/08/07, 8408140372

--8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X
Fiche 50-000, 84/08/07, 8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8408100043 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/84-08
MARTIN, T T Division of Engineering & Technical Programs 84/08/03
KOBER, R W Rochester Gas & Electric Corp 1p 25990 191 24X
Fiche 50-244, 84/08/03, 8408100043

--8408100056 Responds to NRC 840621 ltr re violations noted in IE Insp Rept 50-244/84-08 Corrective actions Procedure SC-600 reviewed & revised to require individuals be retrained annually in emergency response function
KOBER, R W Rochester Gas & Electric Corp 84/07/20 MARTIN, T T
Division of Engineering & Technical Programs 4pp 25990 192
24X Fiche 50-244, 84/08/03, 8408100043

8408080029 Notification of 840813 meeting w/util in Bethesda, MD to discuss util alternative safe shutdown sys proposal
DICK, G F Operating Reactors Branch 5 84/08/06 PAULSON, W A
Operating Reactors Branch 5 3pp 25962 003 24X
Fiche 50-244, 84/08/06, 8408080029

8408140161 Forwards Rev 0 to "Nuclear Emergency Response Plan," incorporating offsite & onsite plans & responding to mods recommended in IE Insp Rept 50-244/83-25
KOBER, R W Rochester Gas & Electric Corp 84/08/09 MURLEY, T E
Region 1, Office of Director 1p 26045 026 24X
Fiche 50-244, 84/08/09, 8408140161

--8408140167 Rev 0 to "Nuclear Emergency Response Plan "
* Rochester Gas & Electric Corp 84/07/31 178pp 26045 027
24X Fiche 50-244, 84/08/09, 8408140161

8408270252 Revised emergency plan implementing procedures, including SC-100 re event evaluation/classification, SC-200 re emergency response organization/responsibilities, SC-212 re site evacuation & SC-420 re offsite doses W/840822 ltr
* Rochester Gas & Electric Corp 84/08/22 MURLEY, T E Region 1, Office of Director 131pp 26238 151 24X Fiche 50-244, 84/08/22, 8408270252

8408300027 Summary of 840813 meeting w/util re 840116 submittal revising proposals for fire protection mods Util described changes to fire hazards analysis & new info Agenda & list of attendees encl
DICK, G F Operating Reactors Branch 5 84/08/27 Operating Reactors Branch 5 4pp 26305 185 24X Fiche 50-244, 84/08/27, 8408300027

G Adjudicatory correspondence

8408070420 Motion to terminate proceeding based on ML Slade 840724 withdrawal of outstanding contentions No contentions remain to be heard or decided Proceeding should be terminated Certificate of Svc encl
VOIGT, H H Rochester Gas & Electric Corp VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae DSB 788 84/08/03 Atomic Safety and Licensing Board Panel 5pp 25942 028 24X Fiche 50-244, 84/08/03, 8408070420

8408150133 Status rept re discovery record & suggested schedule for prehearing & hearing activities, per ASLB 840525 memorandum & order Staff will not pursue discovery Certificate of Svc encl Related correspondence
YOUNG, M A Hearing Branch 4 DSB 037 84/08/14 4pp 26066 358
24X Fiche 50-244, 84/08/14, 8408150133

8408200507 Informs that as result of ML Slade 840724 motion withdrawing outstanding contentions, applicant believes schedule for further proceeding no longer appropriate Related correspondence
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae VOIGT, H H Rochester Gas & Electric Corp DSB 151 84/08/15 GROSSMAN, H , COLE, R F ,
LUEBKE, C A Atomic Safety and Licensing Board Panel 2pp
26136 358 24X Fiche 50-244, 84/08/15, 8408200507

J Insurance & indemnity information

8408150129 Forwards Endorsements 98 & 83 to NELIA Policy NF-170 & MAELU Policy NF-47, respectively
GOLDEN, M P Marsh & McLennan, Inc 84/08/10 SALTZMAN, J D
Assistant Director for State & Licensee Relations 3pp 26066 355
24X Fiche 50-244, 84/08/10, 8408150129

O Advisory Committee on Reactor Safeguards reports & correspondence

8408020250 Proposed minutes of ACRS Extreme External Phenomena 840404 meeting in Washington, DC re review of generic methodology for developing design basis severe winds for SEP plants & specific applications for Ginna Nuclear Power Plant
* ACRS - Advisory Committee on Reactor Safeguards 84/05/17
ACRS - Advisory Committee on Reactor Safeguards 25pp 25898 120
24X Fiche 50-244, 84/05/17, 8408020250

P Operating license stage documents & correspondence

8408070524 Forwards "Startup Physics Testing Program," per Tech Spec 6 9 1 1, as result of installation of 20 Westinghouse optimized fuel assemblies into Cycle 14 loading pattern for 1984
KOBER, R W Rochester Gas & Electric Corp 84/07/09 MURLEY, T E
Region 1, Office of Director 1p 25953 033 24X
Fiche 50-244, 84/07/09, 8408070524

--8408070526 "Startup Physics Testing Program "
* Rochester Gas & Electric Corp 84/06/26 4pp 25953 034 24X
Fiche 50-244, 84/07/09, 8408070524

8408090275 Forwards notice of consideration of issuance of amend to License DPR-18 & proposed NSHC determination & opportunity for hearing re proposed increase in spent fuel pool storage capacity
PAULSON, W A Operating Reactors Branch 5 84/07/24 KOBER, R W
Rochester Gas & Electric Corp 2pp 25994 184 24X
Fiche 50-244, 84/07/24, 8408090275

--8408090281 Notice of consideration of issuance of amend to License DPR-18 & proposed NSHC determination & opportunity for hearing on util 840402 & 0612 requests re spent fuel pool storage expansion
PAULSON, W A Operating Reactors Branch 5 84/07/24 15pp
25994 186 24X Fiche, 50-244, 84/07/24, 8408090275

8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers," omitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/07/31
KAY,J A Yankee Atomic Electric Co KOBER,R W Rochester Gas & Electric Corp BASKIN,K P Southern California Edison Co 4pp
25955 227 24X Fiche 50-000,84/07/31,8408070099

8408070248 Forwards application for withholding & nonproprietary & proprietary versions of revised DNBR licensing basis for steam break analysis at reduced pressure W/o nonproprietary version Encl withheld (ref 10CFR2 790)
KOBER,R W Rochester Gas & Electric Corp 84/07/31 PAULSON,W A
Operating Reactors Branch 5 2pp 25948 110 24X
Fiche 50-244,84/07/31,8408070248

--8408070257 Requests withholding of proprietary revised DNBR licensing basis for steam break analysis at reduced pressure Encl withheld (ref 10CFR2 790)
WIESEMANN,R A Westinghouse Electric Corp 84/07/20
CRUTCHFIELD,D Operating Reactors Branch 5 11pp 25948 112
24X Fiche 50-244,84/07/31,8408070248

8408070251 Forwards Amend 62 to License DPR-18 & safety evaluation Amend revises Tech Specs to limit working hours of staff performing safety-related functions & provides for reporting valve failures
PAULSON,W A Operating Reactors Branch 5 84/07/31 KOBER,R W
Rochester Gas & Electric Corp 4pp 25948 083 24X
Fiche 50-244,84/07/31,8408070251

--8408070255 Amend 62 to License DPR-18,revising Tech Specs to limit working hours of staff performing safety-related functions & providing for reporting of safety & relief valve failures & challenges
PAULSON,W A Operating Reactors Branch 5 84/07/31 9pp
25948 087 24X Fiche 50-244,84/07/31,8408070251

--8408070258 Safety evaluation supporting Amend 62 to License DPR-18
LAZARUS,W Region 1, Office of Director 84/07/31 5pp
25948 096 24X Fiche 50-244,84/07/31,8408070251

8408070515 Forwards "NUREG-0612,Control of Heavy Loads," final rept Submittal contains evaluation results & resolutions of open items since 840326 submittal
KOBER,R W Rochester Gas & Electric Corp 84/07/31 PAULSON,W A
Operating Reactors Branch 5 1p 25941 172 24X
Fiche 50-244,84/07/31,8408070515

--8408070516 "NUREG-0612,Control of Heavy Loads," final rept
* Rochester Gas & Electric Corp 84/08/31 12pp 25941 173
24X Fiche 50-244,84/07/31,8408070515

8408080091 Forwards responses to questions re 840402 application for amend to License DPR-18 Six proprietary oversize drawings encl Drawings withheld Aperture cards available in Central Files
KOBER,R W Rochester Gas & Electric Corp 84/07/31 PAULSON,W A
Operating Reactors Branch 5 24pp 25961 037 24X
Fiche 50-244,84/07/31,8408080091

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda,MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH,B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408130357 Forwards response to 840604 request for addl info re NUREG-0737,Item II F 2 concerning inadequate core cooling instrumentation
KOBER,R W Rochester Gas & Electric Corp 84/08/07 PAULSON,W A
Operating Reactors Branch 5 7pp 26010 060 24X
Fiche 50-244,84/08/07,8408130357

8408150108 Discusses encl results of analysis of Reactor Vessel Surveillance Capsule T,supporting 821208 application for amend to License DPR-18 Fluence data & analysis presented in WCAP-10086 verified
ROBER,R W Rochester Gas & Electric Corp 84/08/08 PAULSON,W A
Operating Reactors Branch 5 12pp 26067 001 24X
Fiche 50-244,84/08/08,8408150108

8408160482 Summary of 840724 meeting w/Westinghouse Owners Group re upper plenum injection for two loop plants
DIIANNI,D C Operating Reactors Branch 3 84/08/09 Operating
Reactors Branch 3 4pp 26108 327 24X Fiche 50-000,84/08/09,
8408160482

8408170047 Requests authorization to dispose of 70 tons low level radwaste in municipal landfill Matl from roofs of plant bldgs Average concentration of matl from auxiliary bldg 14 picocuries/g Annual dose equivalent 1 mrem
KOBER,R W Rochester Gas & Electric Corp 84/08/10 PAULSON,W A
Operating Reactors Branch 5 4pp 26119 089 24X
Fiche 50-244,84/08/10,8408170047

8408170058 Forwards responses to NRC questions re 840402 application for amend to License DPR-18 All employees involved in spent fuel pool rerack mods will be required to complete radiation protection training program
KOBER,R W Rochester Gas & Electric Corp 84/08/10 PAULSON,W A
Operating Reactors Branch 5 16pp 26119 096 24X
Fiche 50-244,84/08/10,8408170058

8408170168 Responds to 840609 submittal of Rev 9 to QA program Changes acceptable,except for Figure 2-1 re organizational structure,which reflects proposed Amend 63 to Tech Specs
MARTIN,T T Division of Engineering & Technical Programs 84/08/10
KOBER,R W Rochester Gas & Electric Corp 2pp 26118 345 24X
Fiche 50-244,84/08/10,8408170168

8408160353 Forwards Amend 63 to License DPR-18 & safety evaluation Amend approves Tech Spec changes to organization titles
PAULSON,W A Operating Reactors Branch 5 84/08/14 KOBER,R W
Rochester Gas & Electric Corp 3pp 26091 195 24X
Fiche 50-244,84/08/14,8408160353

--8408160356 Amend 63 to License DPR-18,revising Tech Specs to consolidate positions of superintendent of nuclear production & superintendent of plant & to recognize organizational title changes within util organization
PAULSON,W A Operating Reactors Branch 5 84/08/14 5pp
26091 198 24X Fiche 50-244,84/08/14,8408160353

--8408160361 SER supporting Amend 63 to License DPR-18
* Office of Nuclear Reactor Regulation, Director 84/08/14 3pp
26091 203 24X Fiche 50-244,84/08/14,8408160353

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

G Inspection reports, IE Bulletins & correspondence

8408080233 Forwards IE Insp Rept 50-244/84-13 on 840514-18 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 84/07/16
KOBER,R W Rochester Gas & Electric Corp 2pp 25975 001 24X
Fiche 50-244,84/07/16,8408080233

--8408080238 Notice of violation from insp on 840514-18
* Region 1, Office of Director 84/07/16 1p 25975 003 24X
Fiche 50-244,84/07/16,8408080233

--8408080242 IE Insp Rept 50-244/84-13 on 840514-18 Noncompliance noted failure to control access to Level D storage areas & failure of semiannual audits required by Tech Specs to include results of actions taken to correct deficiencies.
NAPUDA,G , OLIVEIRA,W Region 1, Office of Director GODY,A T
Division of Engineering & Technical Programs 84/07/09 8pp
25975 004 24X Fiche 50-244,84/07/16,8408080233

8408030005 Ack receipt of 840629 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/84-05
MARTIN,T T Division of Engineering & Technical Programs 84/07/26
KOBER,R W Rochester Gas & Electric Corp 2pp 25906.019 24X
Fiche 50-244,84/07/26,8408030005

--8408030014 Responds to NRC 840611 ltr re violations noted in IE Insp Rept 50-244/84-05 Corrective actions procedures developed or revised to provide formalized method re additions to inservice insp program for modified sys & components
KOBER,R W Rochester Gas & Electric Corp 84/06/29 MURLEY,T E
Region 1, Office of Director 2pp 25906 021 24X
Fiche 50-244,84/07/26,8408030005

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408070198 Forwards response to 840612 request for addl info re 831201 request for one-time exemption from containment tendon visual insp requirements Individual tendon force levels provided
KOBER,R W Rochester Gas & Electric Corp 84/07/31 PAULSON,W A Operating Reactors Branch 5 4pp 25950 021 24X
Fiche 50-244,84/07/31,8408070198

8408070174 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/84-02
MARTIN,T T Division of Engineering & Technical Programs 84/08/02
KOBER,R W Rochester Gas & Electric Corp 2pp 25950 042 24X
Fiche 50-244,84/08/02,8408070174

--8408070178 Responds to NRC 840602 ltr re violations noted in IE Insp Rept 50-244/84-02 Corrective actions development of new procedure to cover use of air sampling devices will be completed prior to 840901
KOBER,R W Rochester Gas & Electric Corp 84/07/27 MARTIN,T T Division of Engineering & Technical Programs 1p 25950 044 24X
Fiche 50-244,84/08/02,8408070174

8408100022 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/84-12
MARTIN,T T Division of Engineering & Technical Programs 84/08/03
KOBER,R W Rochester Gas & Electric Corp 1p 25990 188 24X
Fiche 50-244,84/08/03,8408100022

--8408100032 Responds to NRC 840629 ltr re violations noted in IE Insp Rept 50-244/84-12 Corrective actions procedure being developed to cover overall use of air samplers should be completed by 840901
KOBER,R W Rochester Gas & Electric Corp 84/07/27 MURLEY,T E Region 1, Office of Director 2pp 25990 189 24X
Fiche 50-244,84/08/03,8408100022

8408100043 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/84-08
MARTIN,T T Division of Engineering & Technical Programs 84/08/03
KOBER,R W Rochester Gas & Electric Corp 1p 25990 191 24X
Fiche 50-244,84/08/03,8408100043

--8408100056 Responds to NRC 840421 ltr re violations noted in IE Insp Rept 50-244/84-08 Corrective actions Procedure SC-600 reviewed & revised to require individuals be retrained annually in emergency response function
KOBER,R W Rochester Gas & Electric Corp 84/07/20 MARTIN,T T Division of Engineering & Technical Programs 4pp 25990 192 24X Fiche 50-244,84/08/03,8408100043

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120

8408140161 Forwards Rev 0 to "Nuclear Emergency Response Plan," incorporating offsite & onsite plans & responding to mods recommended in IE Insp Rept 50-244/83-25
KOBER,R W Rochester Gas & Electric Corp 84/08/09 MURLEY,T E Region 1, Office of Director 1p 26045 026 24X
Fiche 50-244,84/08/09,8408140161

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 25pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, BWR HPCI Initiation Seal-In & Indication Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8408290112 LER 84-008-00 on 840725, isolation valves left in closed position & firewatch removed violating Tech Specs which requires continuous firewatch when suppression sys inoperable Caused by miscommunication W/840824 ltr
LARIZZA,G F , KOBER,R W Rochester Gas & Electric Corp 84/08/24
3pp 26291 248 24X Fiche 50-244,84/08/24,8408290112

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408010288 Forwards IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 84/07/11
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25866 200 24X Fiche 50-245,84/07/11,8408010288

--8408010290 Notice of violation from insp on 840529-0601
* Region 1, Office of Director 84/07/11 1p 25866 202 24X
Fiche 50-245,84/07/11,8408010288

--8408010292 IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 Violations noted failure to adhere to Tech Spec 6 11 procedures for radiation work permit preparation
NIMITZ,R L , SHANBAKY,M M Region 1, Office of Director
84/07/02 12pp 25866 203 24X Fiche 50-245,84/07/11,8408010288

8408080353 Forwards IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 & notice of violations Also ack receipt of 840908 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-336/84-02
STAROSTECKI,R Division of Project & Resident Programs 84/07/20
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 25975 021 24X Fiche 50-245,84/07/20,8408080353

--8408080394 Notice of violation from insp on 840506-0609 Safeguards info deleted (ref 10CFR73 21)
* Region 1, Office of Director 84/07/20 1p 25975 025 24X
Fiche 50-245,84/07/20,8408080353

--8408080403 IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 Violations noted failure to follow radiation protection procedures & fulfill station security plan commitments Safeguards info deleted
SHEDLOSKY,J T , LIPINSKI,D R Region 1, Office of Director
ELSASSER,T C Division of Project & Resident Programs 84/06/26
3pp 25975 026 24X Fiche 50-245,84/07/20,8408080353

8408150688 Forwards IE Safeguards Insp Repts 50-245/84-14 & 50-336/84 14 on 840604-08 No noncompliance noted Steps taken to correct violations discussed in 831107 & 16 ltrs verified
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26079 001 24X Fiche 50-245, 84/07/27, 8408150688

--8408150693 IE Safeguards Insp Repts 50-245/84-14 & 50-336/84-14 on 840604-08 No noncompliance noted Major areas inspected security program audit & organization, testing & maint & assessment aids Safeguards info deleted (ref 10CFR2 790)
MADDEN, W , KEIMIG, R R Region 1, Office of Director 84/07/26
4pp 26079 003 24X Fiche 50-245, 84/07/27, 8408150688

8408210494 Forwards IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 & notices of violation & deviation
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26187 145 24X Fiche 50-245, 84/08/01, 8408210494

--8408210501 IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 Violations identified failure to perform surveillance testing per Tech Specs & to maintain integrity of fire barriers
KRASOPOULOS, A , PULLANI, S V , ANDERSON, C J Region 1, Office of Director 84/07/27 1p 26187 149 24X Fiche 50-245, 84/08/01, 8408210494

8408160350 Forwards revised emergency plan implementation procedures, including CONI 1 02 re corporate organization for nuclear incidents & CONI 4 02 re on-call manager of radiological consequences assessment W/o encls
COUNSIL, W G Northeast Utilities 84/08/13 Record Services Branch (Document Control Desk) 2pp1 26091 193 24X
Fiche 50-000, 84/08/13, 8408160350

8408280171 Responds to 840712 interpretation of order confirming licensee commitments on emergency capability, focusing on Suppl 1 to NUREG-0737 requirements Integrated assessment to be conducted pending Congressional consent
EISENHUT, D G Division of Licensing 84/08/23 COUNSIL, W G
Connecticut Yankee Atomic Power Co 3pp 26279 224 24X
Fiche 50-000, 84/08/23, 8408280171

8408310187 Submits update to corrective actions taken re deficiencies noted during 840912 emergency preparedness exercise Emergency action level procedure revised to place greater emphasis on classification/reclassification of emergencies
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/08/23 HURLEY, T E Region 1, Office of Director 3pp 26318 330 24X Fiche 50-000, 84/08/23, 8408310187

K General correspondence

8408070321 Advises that K McCarthy should appear on license amends as appropriate state official to receive amend applications McCarthy new director of radiation control for State of CT, Dept of Environ Protection
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/07/27 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 1p
25945 128 24X Fiche 50-000, 84/07/27, 8408070321

P Operating license stage documents & correspondence

8408100102 Confirms info discussed during 840622 conference call re plant-unique analysis rept Teledyne Engineering Svcs has done addl work re allowable multiplier which can be applied w/o exceeding allowable stress in torus shell
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/07/27
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 25990 275 24X
Fiche 50-245, 84/07/27, 8408100102

8408010030 Forwards SER re containment hydrogen monitor (NUREG-0737, Item II F 1 6) Monitor meets all criteria of NUREG-0737 except requirement for redundancy Response requested within 30 days
PAULSON, W A Operating Reactors Branch 5 84/07/30 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 7pp
25855 326 24X Fiche 50-245, 84/07/30, 8408010030

8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers," omitted from 840503 ltr to all SEP licensees NRC position that issue of Tech Specs for snubbers will be resolved on generic basis restated
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/07/31
KAY, J A Yankee Atomic Electric Co FARRAR, D L Commonwealth Edison Co VANDEWALLE, D J Consumers Power Co 4pp 25955 227, 24X Fiche 50-000, 84/07/31, 8408070099

8408070320 Ack receipt of 840608 ltr forwarding Rev 6 to QA program topical rept, per 10CFR50 54 & 50 55 Revs acceptable
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 25945 244
24X Fiche 50-000, 84/08/01, 8408070320

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408210306 Forwards requested info on TMI Item II K 3 28 re qualification of automatic depressurization sys accumulators
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/08/13
PAULSON, W A Operating Reactors Branch 5 5pp 26179 326 24X
Fiche 50-245, 84/08/13, 8408210306

8408200190 Forwards SER on proposed resolution for integrated plant SAR (NUREG-0824), Section 4 28 3 re gas turbine preventive maint program Program acceptable
SHEA, J Operating Reactors Branch 5 84/08/16 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp
26133 064 24X Fiche 50-245, 84/08/16, 8408200190

8408290298 Requests extension until 841214 to respond to Generic Ltr 84-15 re proposed staff actions to improve & maintain diesel generator reliability Addl time will result in more complete & concise submittal
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/08/17 EISENHUT, D G
Division of Licensing 2pp 26290 342 24X Fiche 50-000, 84/08/17, 8408290298

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8408010288 Forwards IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/11
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25866 200 24X Fiche 50-245, 84/07/11, 8408010288

--8408010290 Notice of violation from insp on 840529-0601
* Region 1, Office of Director 84/07/11 1p 25866 202 24X
Fiche 50-245, 84/07/11, 8408010288

--8408010292 IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 Violations noted failure to adhere to Tech Spec 6 11 procedures for radiation work permit preparation
NIMITZ, R L , SHANBAKY, M M Region 1, Office of Director
84/07/02 12pp 25866 203 24X Fiche 50-245, 84/07/11, 8408010288

8408080464 Forwards Exam Rept 50-245/84-17 of exam administered during wk of 840424
STAROSTECKI, R Division of Project & Resident Programs 84/07/17
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25975 085 24X Fiche 50-245, 84/07/17, 8408080464

--8408080466 Exam Rept 50-245/84-17 administered on 840424-26 Exam results four candidates passed & six failed
BERRY, J A Region 1, Office of Director 84/06/22 70pp
25975 087 24X Fiche 50-245, 84/07/17, 8408080464

8408080353 Forwards IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 & notice of violations Also ack receipt of 840508 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-336/84-02
STAROSTECKI, R Division of Project & Resident Programs 84/07/20
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 25975 021 24X Fiche 50-245, 84/07/20, 8408080353

--8408080383 Notice of violation from insp on 840506-0609
* Region 1, Office of Director 84/07/20 1p 25975 024 24X
Fiche 50-245, 84/07/20, 8408080353

--8408080394 Notice of violation from insp on 840506-0609 Safeguards info deleted (ref 10CFR73 21)
* Region 1, Office of Director 84/07/20 1p 25975 025 24X
Fiche 50-245, 84/07/20, 8408080353

--8408080403 IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 Violations noted failure to follow radiation protection procedures & fulfill station security plan commitments Safeguards info deleted SHEDLOSKY,J T , LIPINSKI,D R Region 1, Office of Director ELSASSER,T C Division of Project & Resident Programs 84/06/26 3pp 25975 026 24X Fiche 50-245,84/07/20,8408080353

--8408080414 Responds to NRC 840213 & 0409 ltrs re violations noted in IE Insp Rept 50-336/84-02 Corrective actions Instrument & Controls Procedure IC 2417M re design changes revised COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities 84/05/08 MURLEY,T E Region 1, Office of Director 3pp 25975 041 24X Fiche 50-245,84/07/20,8408080353

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408150688 Forwards IE Safeguards Insp Repts 50-245/84-14 & 50-336/84-14 on 840604-08 No noncompliance noted Steps taken to correct violations discussed in 831107 & 16 ltrs verified MARTIN,T T Division of Engineering & Technical Programs 84/07/27 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26079 001 24X Fiche 50-245,84/07/27,8408150688

--8408150693 IE Safeguards Insp Repts 50-245/84-14 & 50-336/84-14 on 840604-08 No noncompliance noted Major areas inspected security program audit & organization,testing & maint & assessment aids Safeguards info deleted (ref 10CFR2 790) MADDEN,W , HEIMIG,R A Region 1, Office of Director 84/07/26 4pp 26079 003 24X Fiche 50-245,84/07/27,8408150688

8408100116 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Entry & engineering evaluation for Millstone Unit 2 will be done by Feb 1985 refueling outage No Ray Miller products supplied at Haddam COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Connecticut Yankee Atomic Power Co COUNSIL,W G Northeast Utilities 84/07/31 MURLEY,T E Region 1, Office of Director 3pp 25988 247 24X Fiche 50-000,84/07/31, 8408100116

8408160235 Forwards IE Insp Rept 50-245/84-16 on 840613-15 No violations observed MARTIN,T T Division of Engineering & Technical Programs 84/08/01 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26106 214 24X Fiche 50-245,84/08/01,8408160235

--8408160246 IE Insp Rept 50-245/84-16 on 840613-15 No violations observed Major areas inspected emergency diesel generator operation in area of prelube oil seepage from exhaust flumes adjacent to turbocharger WOODHARD,C H , ANDERSON,C J Region 1, Office of Director 84/07/18 4pp 26106 216 24X Fiche 50-245,84/08/01,8408160235

8408160428 Forwards IE Insp Rept 50-245/84-18 on 840616-22 No violations observed MARTIN,T T Division of Engineering & Technical Programs 84/08/01 COUNSIL,G W Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26129 103 24X Fiche 50-245,84/08/01,8408160428

--8408160432 IE Insp Rept 50-245/84-18 on 840616-22 No violations observed Major areas inspected containment leakage testing program,local leak rate test,test results review & general tours of facility VITO,D J , LIPINSKI,D R , BETTENHAUSEN,L Region 1, Office of Director 84/07/18 9pp 26129 105 24X Fiche 50-245,84/08/01, 8408160428

8408210494 Forwards IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 & notices of violation & deviation MARTIN,T T Division of Engineering & Technical Programs 84/08/01 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26187 145 24X Fiche 50-245,84/08/01,8408210494

--8408210495 Notice of violation from insp on 840611-15 * Region 1, Office of Director 84/08/01 1p 26187 147 24X Fiche 50-245,84/08/01,8408210494

--8408210496 Notice of deviation from insp on 840611-15 * Region 1, Office of Director 84/08/01 1p 26187 148 24X Fiche 50-245,84/08/01,8408210494

--8408210501 IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 Violations identified failure to perform surveillance testing per Tech Specs & to maintain integrity of fire barriers KRASOPOULOS,A , PULLANI,S V , ANDERSON,C J Region 1, Office of Director 84/07/27 1p 26187 149 24X Fiche 50-245,84/08/01, 8408210494

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of All Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408210480 Responds to notice of violation in IE Insp Repts 50-213/83-25 & 50-245/84-07 Corrective actions taken to restore post-accident sampling sys units to svc & determine problem COUNSIL,W G Connecticut Yankee Atomic Power Co COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities 84/08/10 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 12pp 26181 196 24X Fiche 50-000,84/08/10,8408210480

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408230431 Monthly operating rept for Jul 1984 W/840815 ltr HARRAN,G , MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA,E J Northeast Utilities 84/07/31 5pp 26213 068 24X Fiche 50-245,84/07/31,8408230431

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,G G General Electric Co 84/04/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348

8408070112 LER 84-014-00 on 840709, isolation condenser containment isolation valve motor overloaded & 125-volt dc ground alarm annunciated in control room Caused by limit switch out of adjustment Breaker 1-IC-3 replaced W/840727 ltr
THULL,T S , MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA,E J Northeast Utilities 84/07/27 2pp 25953 113 24X Fiche 50-245,84/07/27,8408070112

8408090340 LER 84-015-00 on 840709, isolation condenser containment isolation valve motor overloaded & 125-volt dc ground alarm annunciated in control room Caused by limit switch out of adjustment Breaker replaced & switch adjusted W/840731 ltr
THULL,T S , HERBERT,R J Northeast Nuclear Energy Co (subs of Northeast Utilities) THULL,T S Northeast Utilities 84/07/30 2pp 25994 064 24X Fiche 50-245,84/07/30,8408090340

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA,R General Electric Co 84/08/21 ROSSI,C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000,84/08/21,8408310186

8408290004 LER 84-017-00 on 840802, unidentified leak rate increased to Tech Spec limit of 2 5 gpm & plant shut down in preparation for drywell entry Leak caused by packing leak in recirculation riser stop valve G W/840824 ltr
THULL,T S , MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA,E J Northeast Utilities 84/08/24 3pp 26291 238 24X Fiche 50-245,84/08/24,8408290004

V Operator Examinations

8408080464 Forwards Exam Rept 50-245/84-17 of exam administered during wk of 840424
STAROSTECKI,R Division of Project & Resident Programs 84/07/17
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25975 085 24X Fiche 50-245,84/07/17,8408080464

--8408080466 Exam Rept 50-245/84-17 administered on 840424-26 Exam results four candidates passed & six failed
BERRY,J A Region 1, Office of Director 84/06/22 70pp 25975 087 24X Fiche 50-245,84/07/17,8408080464

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8405240290 Responds to 840424 memo for FEMA review of util request for delay in scheduling next full-scale emergency preparedness exercise at site until 841130 Delay acceptable
KRIMM,R Federal Emergency Management Agency 84/05/18
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 24614 336 24X Fiche 50-003,84/05/18, 8405240290

8408010296 Forwards IE Insp Rept 50-247/84-12 on 840514-0615 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 84/07/12
O'TOOLE,J D Consolidated Edison Co of New York, Inc 3pp 25866 175 24X Fiche 50-247,84/07/12,8408010296

--8408010298 Notice of violation from insp on 840514-0615 Safeguards info deleted (ref 10CFR2 790 & 73 21)
* Division of Project & Resident Programs 84/07/12 2pp 25866 178 24X Fiche 50-247,84/07/12,8408010296

--8408010300 IE Insp Rept 50-247/84-12 on 840514-0615 Violations noted health physics program deficiencies & security personnel failed to comply w/access control procedures Safeguards info deleted (ref 10CFR2 790 & 73 21)
FOLEY,T , KOLTAY,P , NORRHOLM,L Division of Project & Resident Programs 84/06/27 10pp 25866 180 24X Fiche 50-247,84/07/12, 8408010296

8408010282 Forwards IE Insp Rept 50-247/84-13 on 840612-15 & 0705-06 & notice of violation Enforcement conference scheduled for 840718 to discuss unplanned exposure of two workers on 840619
MARTIN,T T Division of Engineering & Technical Programs 84/07/13
O'TOOLE,J D Consolidated Edison Co of New York, Inc 3pp 25866 222 24X Fiche 50-247,84/07/13,8408010282

--8408010286 IE Insp Rept 50-247/84-13 on 840612-15 & 0705-06 Violations noted failure to post & barricade high radiation area, failure to perform airborne radioactivity surveys & adhere to physical security plan Safeguards info deleted
NIMITZ,R L , MILLER,M M , CLEMONS,P E Region 1, Office of Director 84/07/13 15pp 25866 228 24X Fiche 50-247,84/07/13, 8408010282

8408060349 Forwards revs to physical security plan Revs withheld (ref 10CFR73 21)
O'TOOLE,J D Consolidated Edison Co of New York, Inc 84/07/16
MURLEY,T E Region 1, Office of Director 1p 25936 052 24X Fiche 50-003,84/07/16,8408060349

8408150121 Forwards public version of revs to Book II to emergency procedures document, including App A, "Emergency Roster" & App B, "Con Ed Medical Dept, Consultants & Agencies "
O'TOOLE,J D Consolidated Edison Co of New York, Inc 84/07/16
MURLEY,T E Region 1, Office of Director 2pp 26104 258 24X Fiche 50-003,84/07/16,8408150121

--8408150125 Public version of revs to Book II to emergency procedures document, including App A, "Emergency Roster" & App B "Con Ed Medical Dept, Consultants & Agencies " W/JM Felton 840808 release memo
* Consolidated Edison Co of New York, Inc 84/06/29 21pp 26104 260 24X Fiche 50-003,84/07/16,8408150121

8408070114 Provides schedule info re NUREG-0737, Suppl 1 on emergency response commitment & clarifies schedular error in 840612 confirmatory order Amend to order prior to Sept 1985 suggested
O'TOOLE,J D Consolidated Edison Co of New York, Inc 84/07/31
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25950 034 24X Fiche 50-247,84/07/31,8408070114

8408090056 Clarifies addl issues raised by NRC in 840626 telcon re New York PIRG petition to suspend OLs due to emergency planning inadequacies FEMA rept & State of NY response to FEMA 840611 ltr encl
KRIMM,R W Federal Emergency Management Agency 84/07/31
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 25992 335 24X Fiche 50-247,84/07/31, 8408090056

--8408090059 "Evaluation of Addl Issues Raised by NRC re New York PIRG Petition to Suspend Operation of Indian Point, Units 2 & 3 "
* Federal Emergency Management Agency 84/07/26 10pp 25992 336 24X Fiche 50-247,84/07/31,8408090056

--8408090061 "Addl Info Obtained From NY State on New York PIRG Petition Which Supplements FEMA Rept to NRC dtd 840608 "
* Federal Emergency Management Agency 84/07/26 8pp. 25992 346 24X Fiche 50-247,84/07/31,8408090056

8408070421 Responds to manual reactor coolant pump trip issue, Upgraded emergency operating procedures & integrated operator training being implemented, per Suppl 1 to NUREG-0737 & Generic Ltr 83-10D
O'TOOLE,J D Consolidated Edison Co of New York, Inc 84/08/01
EISENHUT,D G Division of Licensing 2pp 25942 026 24X Fiche 50-247,84/08/01,8408070421

8408130325 Submits schedule info on detailed control room design review summary rept, per Suppl 1 to NUREG-0737 Clarifies schedular error in 840612 confirmatory order Amend to order requested prior to Sept 1985
O'TOOLE,J D Consolidated Edison Co of New York, Inc. 84/08/06
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26010 057 24X Fiche:50-247,84/08/06,8408130325.

8408160299 Notifies of fees due for review of fire protection requests Discussion of 10CFR170 fee requirements & list of applications & fees due encl
MILLER,W.O. License Fee Management Branch 84/08/09 O'TOOLE,J D Consolidated Edison Co of New York, Inc 4pp 26122 359. 24X Fiche 50-247,84/08/09,8408160299

8408210002 Forwards SAR for safety assessment sys/safety parameter display sys, per NUREG-0737 Suppl 1 & 830415 & 840312 ltrs
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/08/15
EISENHUT, D G Division of Licensing 13pp 26183 054 24X
Fiche 50-247, 84/08/15, 8408210002

O Adjudicatory correspondence

8408140448 Responses to 840730 unpublished order directing NRC & inviting other parties to submit views on Judge Gleason dissent re ASLB recommendation concerning accident probability Certificate of Svc encl
SHOLLY, S C Union of Concerned Scientists DSB 029 84/08/13
Commissioners 8pp 26061 007 24X Fiche 50-247, 84/08/13, 8408140448

8408140488 Response to Commission 840730 order permitting comments from parties re Chairman Gleason dissent to ASLB recommendations to Commission Certificate of Svc encl
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates DSB 030 84/08/13
Commissioners 14pp 26060 261 24X Fiche 50-247, 84/08/13, 8408140488

8408140493 Comments on ASLB Chairman Gleason dissent in recommendations of special proceeding Significant risk reduction already accomplished at facility Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc DSB 031
84/08/13 Commissioners 12pp 26060 249 24X
Fiche 50-247, 84/08/13, 8408140493

8408150111 Response to Commission 840730 order directing NRC to file comments on Judge Gleason dissent to portion of ASLB recommendations Supports Gleason dissent
MOORE, J E Hearing Branch 1 DSB 042 84/08/13 Commissioners
14pp 26066 265 24X Fiche 50-247, 84/08/13, 8408150111

8408170270 Comments on dissenting views of Chairman Gleason re safety of plant mods Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc DSB 083
84/08/13 12pp 26118 041 24X Fiche 50-247, 84/08/13, 8408170270

P Operating license stage documents & correspondence

8407120020 Forwards request for addl info to complete SER re review of environ qualification of electrical equipment important to safety Info required by 840715
VARGA, S A Operating Reactors Branch 1 84/06/22 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 4pp 25573 128 24X
Fiche 50-247, 84/06/22, 8407120020

8408020138 Advises that Tech Spec change requests per Generic Ltr 83-37, "NUREG-0737 Tech Specs," will be submitted by 841231, per 840615 telcon request
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/07/26
EISENHUT, D G Division of Licensing 1p 25892 305 24X
Fiche 50-247, 84/07/26, 8408020138

8408130211 Forwards requests for relief from five testing requirements of ASME Code, Section XI Provisions of requests intended for application during current refueling & inservice insp outage
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/07/30
VARGA, S A Operating Reactors Branch 1 6pp 26010 019 24X
Fiche 50-247, 84/07/30, 8408130211

8408090530 Forwards request for addl info for review of 840214 submittal re control of heavy loads Tech Spec change Response requested within 45 days of ltr receipt
VARGA, S A Operating Reactors Branch 1 84/08/01 O'TOOLE, J
Consolidated Edison Co of New York, Inc 4pp 25983 332 24X
Fiche 50-247, 84/08/01, 8408090530

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408310136 Forwards Matls Engineering Branch request for addl info re potential flaw indication on reactor vessel, as discussed at 840811 meeting w/util
VARGA, S A Operating Reactors Branch 1 84/08/16 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 7pp 26352 019 24X
Fiche 50-247, 84/08/16, 8408310136

8408240164 Forwards requests for relief from ASME Boiler & Pressure Vessel Code Section XI requirements re exam of reactor vessel flange ligaments between threaded stud holes & hydrostatic pressure testing of generator coolers
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/08/17
VARGA, S A Operating Reactors Branch 1 5pp 26228 179 24X
Fiche 50-247, 84/08/17, 8408240164

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408280290 Forwards draft technical evaluation rept re control of heavy loads, for review & comment Project manager should be contacted within 30 days to discuss outstanding items W/o encl
VARGA, S A Operating Reactors Branch 1 84/08/20 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 1p 26294 086 24X
Fiche 50-247, 84/08/20, 8408280290

8408280333 Staff requirements memo re 840816 continuation of 840723 discussion of issues requiring resolution prior to issuance of order in proceeding Commission requested briefing on PRA including discussion of uncertainties & basis of comparison
CHILK, S J Office of the Secretary of the Commission 84/08/21
DIRCKS, W J Office of the Executive Director for Operations
ZERBE, J E Office of Policy Evaluations 2pp 26294 050 24X
Fiche 50-003, 84/08/21, 8408280333

R Inspection reports, IE Bulletins & correspondence

8408010296 Forwards IE Insp Rept 50-247/84-12 on 840514-0615 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/07/12
O'TOOLE, J D Consolidated Edison Co of New York, Inc 3pp
25966 179 24X Fiche 50-247, 84/07/12, 8408010296

--8408010298 Notice of violation from insp on 840514-0615 Safeguards info deleted (ref 10CFR2 790 & 73 21)
* Division of Project & Resident Programs 84/07/12 2pp
25966 178 24X Fiche 50-247, 84/07/12, 8408010296

--8408010300 IE Insp Rept 50-247/84-12 on 840514-0615 Violations noted health physics program deficiencies & security personnel failed to comply w/access control procedures Safeguards info deleted (ref 10CFR2 790 & 73 21)
FOLEY, T , KOLTAY, P , NORRHOLM, L Division of Project & Resident
Programs 84/06/27 10pp 25966 180 24X Fiche 50-247, 84/07/12, 8408010296

8408010282 Forwards IE Insp Rept 50-247/84-13 on 840612-15 & 0705-06 & notice of violation Enforcement conference scheduled for 840718 to discuss unplanned exposure of two workers on 840619
MARTIN, T T Division of Engineering & Technical Programs 84/07/13
O'TOOLE, J D Consolidated Edison Co of New York, Inc 3pp
25966 222 24X Fiche 50-247, 84/07/13, 8408010282

--8408010284 Notice of violation from insp on 840612-15 Safeguards info deleted
* Region 1, Office of Director 84/07/13 3pp 25966 225 24X
Fiche 50-247, 84/07/13, 8408010282

--8408010286 IE Insp Rept 50-247/84-13 on 840612-15 & 0705-06 Violations noted failure to post & barricade high radiation area, failure to perform airborne radioactivity surveys & adhere to physical security plan Safeguards info deleted
NIMITZ, R L , MILLER, M M , CLEVONS, P E Region 1, Office of
Director 84/07/13 15pp 25966 228 24X Fiche 50-247, 84/07/13, 8408010282

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25965 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070425 Responds to IE Bulletin 84-02, "Failure of GE Type HFA Relays in Use in Class IE Safety Sys " GE HFA relays not used in safety-related applications
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/07/30
MURLEY, T E Region 1, Office of Director 2pp 25942 023 24X
Fiche 50-247, 84/07/30, 8408070425

8408130211 Forwards requests for relief from five testing requirements of ASME Code Section XI Provisions of requests intended for application during current refueling & inservice insp outage
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/07/30
VARGA, S A Operating Reactors Branch 1 6pp 26010 019 24X
Fiche 50-247, 84/07/30, 8408130211

8408200510 Forwards IE Insp Rept 50-247/84-14 on 840618-22 & notices of violation & deviation
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
O'TOOLE, J D Consolidated Edison Co of New York, Inc 3pp
26138 173 24X Fiche 50-247, 84/08/01, 8408200510

--8408200518 Notice of violation from insp on 840618-22
* Region 1, Office of Director 84/08/01 2pp 26138 176 24X
Fiche 50-247, 84/08/01, 8408200510

--8408200530 Notice of deviation from insp on 840618-22
* Region 1, Office of Director 84/08/01 1p 26138 178 24X
Fiche 50-247, 84/08/01, 8408200510

--8408200544 IE Insp Rept 50-247/84-14 on 840618-22 Violations noted failure to comply w/conditions of certificate of compliance, failure to review & approve procedures & failure to train personnel involved in transportation activities
HOGAN, R T , STRUCKMEYER, R , PASCIAK, W J Region 1, Office of Director 84/07/20 6pp 26138 179 24X Fiche 50-247, 84/08/01, 8408200510

8408210238 Forwards IE Enforcement Conference Rept 50-247/84-20 on 840718 Appropriate enforcement action will be specified at later date
MARTIN, T T Division of Engineering & Technical Programs 84/08/02
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
26184 292 24X Fiche 50-247, 84/08/02, 8408210238

--8408210244 IE Enforcement Conference Rept 50-247/84-20 on 840718 Major areas discussed deficiencies in control of high radiation, performance & unplanned exposures of two workers on 840619
NIMITZ, R L , SHANBAKY, M M Region 1, Office of Director
84/07/31 3pp 26184 294 24X Fiche 50-247, 84/08/02, 8408210238

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408130385 Ack receipt of 840619 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/84-03 Corrective actions will be examined during future insp
MARTIN, T T Division of Engineering & Technical Programs 84/08/08
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
26010 175 24X Fiche 50-247, 84/08/08, 8408130385

--8408130388 Responds to NRC 840426 ltr re violations noted in IE Insp Rept 50-247/84-03 Corrective actions include implementation of engineering personnel training, maint procedural changes & QA procedures review & rev
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/06/19
MARTIN, T T Division of Engineering & Technical Programs 8pp
26010 177 24X Fiche 50-247, 84/08/08, 8408130385

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408200309 Advises of results of 840805 10-yr inservice insp of reactor vessel Significant amplification of indications on outside surface demonstrated Addl info will be submitted prior to return to power operation
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/08/13
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26132 361 24X Fiche 50-247, 84/08/13, 8408200309

8408300106 Forwards Insp Rept 50-247/84-18 on 840717-20 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/08/14
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
26308 100 24X Fiche 50-247, 84/08/14, 8408300106

--8408300113 Insp Rept 50-247/84-18 on 840717-20 No violations noted Major areas inspected inservice activities, including program review, observations of work in progress, NDE procedure & licensee actions re Reg Guide 1 150
MCGREARTY, R A Region 1, Office of Director DURR, J P Division of Engineering & Technical Programs 84/08/06 5pp 26308 102
24X Fiche 50-247, 84/08/14, 8408300106

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408290279 Forwards completed response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc," including review of general concern, per SD Ebneter 840618 request Fraudulent safety-related matl will not be used
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/08/17
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement EBNETER, S D Region 1, Office of Director 3pp
26290 333 24X Fiche 50-247, 84/08/17, 8408290279

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8 Reportable occurrences, LERs & related correspondence

8408100072 PNO-1-84-067 on 840806, indication detected in reactor vessel wall during ultrasonic test Evaluation & review of const records & photographs continuing Startup from 10-yr inservice insp outage scheduled for late Sept 1984
DURR, J P , NORRHOLM, L Region 1, Office of Director 84/08/08 1p
25990 043 24X Fiche 50-247, 84/08/08, 8408100072

8408200539 LER 84-007-00 on 840711, during continuous fire watch, personnel failed to watch cable spreading room for 4 h Personnel reinstructed W/840810 ltr
BLATT, M , O'TOOLE, J D Consolidated Edison Co of New York, Inc
84/08/10 3pp 26139 027 24X Fiche 50-247, 84/08/10, 8408200539

8408220214 LER 84-008-00 on 840713, during refueling outage, one channel of manual safety injection circuitry spuriously & partially actuated, causing partial initiation of engineered safeguards equipment Activation apparently inadvertent W/840812 ltr
BLATT, M , O'TOOLE, J D Consolidated Edison Co. of New York, Inc
84/08/12 3pp 26188 261 24X Fiche 50-247, 84/08/12, 8408220214

T Hearing transcripts on non-antitrust matters

8408280025 Transcript of 840816 Commission meeting in Washington, DC re continuation of 840723 discussion of adjudicatory proceeding Pp 1-76.
* Commissioners 84/08/16 78pp 26293 169 24X
Fiche 50-003, 84/08/16, 8408280025

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3
F Security, medical, emergency & fire protection plans

8404040169 Forwards exercise repts for LaSalle & Dresden offsite radiological emergency preparedness exercises conducted 820414-15 & 0&29-30, respectively
KRIMM, R W Federal Emergency Management Agency 84/03/26
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 22883 122 24X Fiche 50-000, 84/03/26, 8404040169

8408140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 84/08/03 Region 3, Office of Director 1p 26044 252 24X Fiche 50-000, 84/08/03, 8408140139

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO, C J Region 3, Office of Director 84/08/07 REED, C
Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000, 84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified.
FARRAR, D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J
Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000, 84/08/07, 8408130401

8408130289 Forwards FR notice of environ assessment & finding of no significant impact re 840405 & 26 requests for exemption of state & local govt participation in 840605 exercise
PAULSON, W A Operating Reactors Branch 5 84/08/10 FARRAR, D L
Commonwealth Edison Co 2pp 26010 262 24X Fiche 50-010, 84/08/10, 8408130289

--8408130298 Notice of environ assessment & finding of no significant impact re exemption from requirements of 10CFR50, App E re state & local govt participation at 840605 exercise
EISENHUT, D G Division of Licensing 84/08/10 4pp 26010 264
24X Fiche 50-010, 84/08/10, 8408130289

8408140397 Forwards summary of App R reverification methodology & status, per 840627 commitment to submit results of hot shutdown portion of fire protection program independent review W/28 oversize drawings Aperture cards in PDR
FARRAR, D L Commonwealth Edison Co 84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 222pp 26049 079 24X
Fiche 50-237, 84/08/10, 8408140397

8408200281 Advises that 840803 Rev 15 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/08/14 FARRAR, D L
Commonwealth Edison Co 2pp 26133 023 24X Fiche 50-010, 84/08/14, 8408200281

8408210001 Forwards exemption from certain requirements of Section IV F.1 of App E to 10CFR50 for Dresden 840605 emergency preparedness exercise w/o full-scale participation by state & local govts in plume exposure pathway
PAULSON, W A Operating Reactors Branch 5 84/08/14 FARRAR, D L
Commonwealth Edison Co 3pp 26181 320 24X Fiche 50-010, 84/08/14, 8408210001

--8408210005 Exemption from Section IV F 1 of App E to 10CFR50 requiring full-scale emergency preparedness exercise at least annually, involving participation of state & local govts within plume exposure pathway emergency planning zone
EISENHUT, D G Division of Licensing 84/08/14 Commonwealth
Edison Co 3pp 26181 323 24X Fiche 50-010, 84/08/14, 8408210001

8408230283 Revised emergency plan implementing procedures, including EPIP 100-C3 re generating station emergency plan log, replacing record of generating station emergency plan activities form W/840820 ltr
SCOTT, D J Commonwealth Edison Co 84/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 67pp 26207 295 24X
Fiche 50-010, 84/08/20, 8408230283

license stage documents & correspondence

of schedular requirements of
nt/mod of specific equipment subj
le. Next refueling outage

on Co 84/07/31 DENTON, H R Office of
Director 2pp 25923 006 24X
A0071

8408060425 Notification of 840809-10 meetings w/utils, NUTECH, Franklin Research Ctr & BNL in San Jose, CA to discuss comments resulting from post-implementation review re plant-unique analysis repts
BEVAN, R B , ROONEY, V L , THADANI, M C Operating Reactors Branch 2
84/07/31 VASSALLO, D B Operating Reactors Branch 2 1p
25937 335 24X Fiche 50-000, 84/07/31, 8408060425

8408150113 Forwards reformatted Tech Specs improving legibility & versatility, per request W/o encl
RYBAK, B Commonwealth Edison Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26066 351 24X
Fiche 50-237, 84/08/01, 8408150113

8408060276 Forwards revised Tech Spec changes to Licenses DPR-19 & DPR-25, submitted on 840611 Tech Specs revised into new format, incorporating NRC comments w/o changing technical content
RYBAK, B Commonwealth Edison Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 25933 223 24X
Fiche 50-237, 84/08/02, 8408060276

--8408060280 Proposed Tech Specs, revising format to incorporate NRC comments w/o changing technical content
= Commonwealth Edison Co 84/08/02 30pp 25933 226 24X
Fiche 50-237, 84/08/02, 8408060276

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160062 Forwards Amends 82 & 75 to Licenses DPR-19 & DPR-25, respectively Amends consist of reformatted Tech Specs to provide clarity
PAULSON, W A Operating Reactors Branch 5 84/08/06 FARRAR, D L
Commonwealth Edison Co 3pp 26092 189 24X Fiche 50-237, 84/08/06, 8408160062

--8408160070 Amends 82 & 75 to Licenses DPR-19 & DPR-25, respectively, consisting of reformatted Tech Specs
PAULSON, W A Operating Reactors Branch 5 84/08/06 600pp
26092 192 24X Fiche 50-237, 84/08/06, 8408160062

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X
Fiche 50-000, 84/08/06, 8408160345

8408170017 Notifies of Class I & II fees due for 840611 Tech Spec change request Fee will be adjusted if appropriate
DIGGS, R M License Fee Management Branch 84/08/10 FARRAR, D L
Commonwealth Edison Co 1p 26135 344 24X Fiche 50-237, 84/08/10, 8408170017

8408270114 Provides supplemental response to Generic Ltr 83-36, "NUREG-0737 Tech Specs " Mods to Quad Cities radiological ETB will not be complete until Fall 1984 Complete response w/amend requests expected by 841115
ALEXANDER, G L Commonwealth Edison Co 84/08/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26247 330
24X Fiche 50-000, 84/08/15, 8408270114

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310211 Forwards final response to second & final set of questions re Mark I containment plant-unique analysis
RYBAK, B Commonwealth Edison Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 37pp 26318 072 24X
Fiche 50-000, 84/08/24, 8408310211

8408300102 Forwards corrected pages to 840806 Amends 82 & 75 to Licenses DPR-19 & DPR-25, respectively
PAULSON, W A Operating Reactors Branch 5 84/08/27 FARRAR, D L
Commonwealth Edison Co 2pp 26306 135 24X Fiche 50-237, 84/08/27, 8408300102

--8408300111 Corrected pages to Amends 82 & 75 to Licenses DPR-19 & DPR-25, respectively
PAULSON, W A Operating Reactors Branch 5 84/08/27 3pp
26306 137 24X Fiche 50-237, 84/08/27, 8408300102

G Inspection reports, IE Bulletins & correspondence

8408030251 Ack receipt of 840622 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/84-05, 50-237/84-07 & 50-249/84-06
PAPERIELLO, C J Region 3, Office of Director 84/07/10 REED, C
Commonwealth Edison Co 1p 25917 226 24X Fiche 50-010, 84/07/10, 8408030251

--8408030252 Responds to NRC 840524 ltr re violations noted in IE Insp Repts 50-010/84-05, 50-237/84-07 & 50-249/84-06 Corrective actions sludge removed from Toledo & Joliet facilities Survey of sumps found no residual activity
FARRAR, D L Commonwealth Edison Co 84/06/22 KEPPLER, J G
Region 3, Office of Director 4pp 25917 227 24X
Fiche 50-010, 84/07/10, 8408030251

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC
NORELIUS, C E Region 3, Office of Director 84/08/03 REED, C
Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000, 84/08/03, 8408070066

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, 84/08/08, 8408140344

8408150098 Supplo 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26067 053 24X
Fiche 50-000, 84/08/08, 8408150098

8408200331 Supplo response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26132 318 24X
Fiche 50-000, 84/08/08, 8408200331

8408300095 Forwards Insp Repts 50-010/84-10, 50-237/84-12 & 50-249/84-11 on 840618-0726 & notice of violation
SHAFER, W D Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26307 201 24X Fiche 50-010, 84/08/08, 8408300095

--8408300108 Insp Repts 50-010/84-10, 50-237/84-12 & 50-249/84-11 on 840618-0726 Noncompliance noted inadequate corrective action taken in response to Tech Spec violation re open submarine door in Unit 2 reactor bldg
TONGUE, T M , STASEK, S , ANDERSON, C D Region 3, Office of Director 84/08/07 11pp 26307 204 24X Fiche 50-010, 84/08/08, 8408300095

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408160139 Ack receipt of 840730 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-010/84-09, 50-237/84-11 & 50-249/84-10
SHAFER, W D Region 3, Office of Director 84/08/10 REED, C
Commonwealth Edison Co 1p 26092 040 24X Fiche 50-010, 84/08/10, 8408160139

--8408160145 Responds to NRC 840703 ltr re noncompliance noted in IE Insp Repts 50-010/84-09, 50-237/84-11 & 50-249/84-10 Corrective actions special procedure for testing automatic function of master pilot valve incorporated into existing Cardox sys
FARRAR, D L Commonwealth Edison Co 84/07/30 KEPPLER, J G
Region 3, Office of Director 3pp 26092 041 24X
Fiche 50-010, 84/08/10, 8408160139

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408300368 "Rept of Radioactive Effluents," Jan-June 1984 W/840813 ltr
SCOTT, D J Commonwealth Edison Co 84/06/30 KEPPLER, J G Region 3, Office of Director 17pp 26308 172 24X Fiche 50-010, 84/06/30, 8408300368

8408130271 Monthly operating repts for Jul 1984 W/840803 ltr
SCHROEDER, B A , SCOTT, D J Commonwealth Edison Co 84/07/31, 20pp 26006 342 24X Fiche 50-237, 84/07/31, 8408130271

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408130146 LER 84-006-00 on 840711, reactor vessel found not vented at less than 149 F Caused by inadvertent procedure violation Reactor metal temp increased Personnel reminded of venting requirement W/840807 ltr
WOJTULEWICZ, T , SCOTT, D J Commonwealth Edison Co 84/08/03 3pp 26007 347 24X Fiche 50-249, 84/08/03, 8408130146

8408200519 LER 84-001-01 on 840323, reactor water level decreased to low level alarm point Coolant loss compounded by two open bypass valves Procedures revised to remind operators to close turbine valves W/840809 ltr
BERGAN, G W , SCOTT, D J Commonwealth Edison Co 84/08/09 4pp 26138 317 24X Fiche 50-249, 84/08/09, 8408200519

8408210104 LER 84-005-00 on 840716, east LPCI corner room submarine door found open Caused by stationmen working in area Door closed & Tech Specs requiring door to be closed emphasized Annunciators will be installed W/840813 ltr
LEAHY, M , SCOTT, D J Commonwealth Edison Co 84/08/13 3pp 26184 015 24X Fiche 50-249, 84/08/13, 8408210104

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/08/16
EISENHUT, D G Division of Licensing 20pp 26233 249 24X
Fiche 50-000, 84/08/16, 8408230077

8408270455 LER 84-007-00 on 840722, turbine bypass valve 1 operated erratically, causing Group 1 isolation on main steam low pressure Caused by failure of servovalve (Model 450-1680) mechanism for opening & closing valve W/840817 ltr
COYLE, L , SCOTT, D J Commonwealth Edison Co 84/08/17 3pp 26257:203 24X Fiche 50-249, 84/08/17, 8408270455

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000, 84/08/21, 8408310186

8408310071 LER 84-008-00 on 840804, while opening valve 1601-58, drywell to torus differential pressure fell below Tech Spec level Caused by closed pressure control valve 8599-538 Personnel counseled W/840822 ltr
BOYLE, L A , SCOTT, D J Commonwealth Edison Co 84/08/22 3pp 26334 239 24X Fiche 50-249, 84/08/22, 8408310071

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000, 84/08/07, 8408140372

--8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X
Fiche 50-000, 84/08/07, 8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

ICKET 50-250 TURKEY POINT PLANT, UNIT 3

Security, medical, emergency & fire protection plans

08010109 Informs that proposed schedules for implementation of alternate shutdown capability & mods for App R, Section III G in accordance w/10CFR50 48 & require no schedular exemptions
VARGA, S A Operating Reactors Branch 1 84/07/09 WILLIAMS, J W
Florida Power & Light Co. 3pp 25873 352 24X
Fiche 50-250, 84/07/09, 8408010109

8408270289 Forwards Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/09 WILLIAMS, J W
Florida Power & Light Co 2pp 26258 167 24X
Fiche 50-250, 84/07/09, 8408270289

-8408270295 Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted Major areas inspected emergency preparedness
MARSTON, R R , CLINE, W E Region 2, Office of Director 84/07/06 9pp 26258 169. 24X Fiche 50-250, 84/07/09, 8408270289

8408100016 Forwards Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization "
WILLIAMS, J W Florida Power & Light Co 84/08/08 O'REILLY, J P
Region 2, Office of Director 1p 25987 006 24X
Fiche 50-000, 84/08/08, 8408100016

--8408100054 Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization "
JOHNSON, H D Florida Power & Light Co 84/08/08 13pp
25987 007 24X Fiche 50-000, 84/08/08, 8408100016

8408240328 Confirms 840829 meeting in Bethesda, MD to discuss task analysis requirements of NUREG-0737, Suppl 1 & SER open items on CEN-152 re inadequate core cooling & reactor vessel level monitoring sys
THOMPSON, H L Division of Human Factors Safety 84/08/13
BARROW, J Florida Power & Light Co 1p 26253 336 24X
Fiche 50-250, 84/08/13, 8408240328

--8408240330 Notification of 840829 meeting w/util in Bethesda, MD to discuss task analysis requirements of NUREG-0737, Suppl 1 & SER open items on CEN-152 re inadequate core cooling & reactor vessel level monitoring sys
CLAYTON, H B Procedures & Systems Review Branch 84/08/09
ZIEMAN, D L Procedures & Systems Review Branch 2pp 26253 337
24X Fiche 50-250, 84/08/13, 8408240328

8408310003 Forwards request for addl info re safety parameter display sys implementation plan & parameter selection rept submitted in 840501 response to Generic Ltr 82-33 (NUREG-0737, Suppl 1) Response requested within 45 days
VARGA, S A Operating Reactors Branch 1 84/08/15 WILLIAMS, J W
Florida Power & Light Co 4pp 26350 202 24X
Fiche 50-250, 84/08/15, 8408310003

8408310133 Revs to emergency plan implementing procedures, including 2010, "Duties of Emergency Coordinator," 20201, "Maintaining Emergency Preparedness - Radiological Emergency Plan Training" & 20126, "Offsite Dose Calculation " W/840824 ltr
WILLIAMS, J W Florida Power & Light Co 84/08/24 O'REILLY, J P
Region 2, Office of Director 108pp 26322 001 24X
Fiche 50-250, 84/08/24, 8408310133

0 Adjudicatory correspondence

8408010213 Response supporting J Lorion & Ctr for Nuclear Responsibility 840709 request for hearing & petition for leave to intervene re amends to expand spent fuel pool Notice of appearance & Certificate of Svc encl
YOUNG, M A Hearing Branch 4 DSB 676 84/07/30 Atomic Safety and Licensing Board Panel 12pp 25856 040 24X
Fiche 50-250, 84/07/30, 8408010213

8408070305 Response supporting Ctr for Nuclear Responsibility request for hearing & petition for leave to intervene re amends to allow storage of fuel w/increased enrichment Notice of appearance & Certificate of Svc encl
YOUNG, M A Hearing Branch 4 DSB 810 84/07/31 Atomic Safety and Licensing Board Panel 12pp 25947 316 24X
Fiche 50-250, 84/07/31, 8408070305

8408090397 Notice of appearance in proceeding Certificate of Svc encl
COLL, N A Florida Power & Light Co COLL, N A Steel, Hector & Davis DSB 878 84/08/07 3pp 25982 173 24X
Fiche 50-250, 84/08/07, 8408090397

8408090437 Notice of appearance in proceeding Certificate of Svc encl
COLL, N A Florida Power & Light Co COLL, N A Steel, Hector & Davis DSB 879 84/08/07 Atomic Safety and Licensing Board Panel 3pp 25982 176 24X Fiche 50-250, 84/08/07, 8408090437

8408140214 Forwards 840810 motions for summary disposition of Intervenor Contentions (b) & (d) & statement of matl facts & memorandum of law in support of motions Related correspondence
BAUSER, M A Neuman & Holtzinger BAUSER, M A Florida Power & Light Co DSB 961 84/08/10 LAZO, R M , COLE, R F , LUEBKE, E A Atomic Safety and Licensing Board Panel 1p 26056.024 24X
Fiche 50-250, 84/08/10, 8408140214

--8408140220 Motion for summary dispositon of intervenor Contention b No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence
BAUSER, M A Florida Power & Light Co BAUSER, M A Neuman & Holtzinger 84/08/10 Atomic Safety and Licensing Board Panel 5pp 26056 025 24X Fiche 50-250, 84/08/10, 8408140214

--8408140226 Affidavit of MJ Parvin in support of applicant 840810 motion for summary dispositon of intervenor Contention (b) Related correspondence
PARVIN, M J Florida Power & Light Co PARVIN, M J Westinghouse Electric Corp 84/08/03 6pp 26056 030 24X
Fiche 50-250, 84/08/10, 8408140214

--8408140236 Statement of matl facts as to which there is no genuine issue Related correspondence
BAUSER,M A Florida Power & Light Co BAUSER,M A Newman & Holtzinger BAUSER,M A Steel, Hector & Davis 84/08/10
Atomic Safety and Licensing Board Panel 3pp 26056 036 24X
Fiche 50-250,84/08/10,8408140214

--8408140253 Motion for summary disposiiton of intervenor Contention (d) No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence
BAUSER,M A Florida Power & Light Co BAUSER,M A Newman & Holtzinger BAUSER,M A Steel, Hector & Davis 84/08/10
Atomic Safety and Licensing Board Panel 8pp 26056 039 24X
Fiche 50-250,84/08/10,8408140214

--8408140262 Affidavit of EA Dzenis in support of licensee 840810 motion for summary disposition of intervenor Contention (d)
Realted correspondence
DZENIS,E A Florida Power & Light Co DZENIS,E A Westinghouse Electric Corp 84/08/08 15pp 26056 047 24X
Fiche 50-250,84/08/10,8408140214

--8408140271 Statement of matl facts as to which there is no genuine issue re intervenor Contention (d) Related correspondence
BAUSER,M A Florida Power & Light Co BAUSER,M A Newman & Holtzinger 84/08/10 Atomic Safety and Licensing Board Panel 7pp 26056 062 24X Fiche 50-250,84/08/10,8408140214

--8408140277 Memorandum of law in support of motions for summary disposition of intervenor Contentions (b) & (d)
Certificate of Svc encl Related correspondence
BAUSER,M A Florida Power & Light Co BAUSER,M A Newman & Holtzinger BAUSER,M A Steel, Hector & Davis 84/08/10 8pp 26056 069 24X Fiche 50-250,84/08/10,8408140214

8408210347 Notice of appearance in proceeding Certificate of Svc encl
REIS,H F Florida Power & Light Co REIS,H F Newman & Holtzinger
DSB 178 84/08/16 3pp 26179 180 24X Fiche 50-250,84/08/16, 8408210347

8408210380 Notice of appearance in proceeding Certificate of Svc encl
REIS,H F Florida Power & Light Co REIS,H F Newman & Holtzinger
DSB 180 84/08/16 3pp 26180 248 24X Fiche 50-250,84/08/16, 8408210380

H General correspondence

8408210441 Informs of address change for plant manager
PEEBLES,T A Florida Power & Light Co 84/08/15 NRC - No Detailed Affiliation Given 2pp 26181 256 24X
Fiche 50-250,84/08/15,8408210441

K Utility Final Safety Analysis Report (FSAR) & amends

8407260218 Forwards Rev 2 to updated FSAR for Turkey Point,Units 3 & 4 Changes made under provisions of 10CFR50 59 for Jul 1983 - June 1984 will be provided by 840901
WILLIAMS,J W Florida Power & Light Co 84/07/23 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25771 129
24X Fiche 50-250,84/07/23,8407260218

--8407260220 Rev 2 to updated FSAR for Turkey Point,Units 3 & 4
* Florida Power & Light Co 84/07/31 425pp 25771 133 24X
Fiche 50-250,84/07/23,8407260218

P Operating license stage documents & correspondence

8408300382 Summarizes 840517 meeting w/util in Region II ofc re plant performance enhancement program Meeting beneficial & provided better understanding of plans
O'REILLY,J P Region 2, Office of Director 84/05/25
WILLIAMS,J W Florida Power & Light Co 1p 26308 160 24X
Fiche 50-250,84/05/25,8408300382

8408300419 Summarizes 840618 meeting w/util in Region II ofc re performance enhancement program & quarterly progress rept meeting scheduled for 840712
DANCE,H C Region 2, Office of Director 84/06/25 WILLIAMS,J W
Florida Power & Light Co 1p 26313 307 24X Fiche 50-250, 84/06/25,8408300419

8408010119 Forwards request for addl info re measures taken to ensure ALARA doses during proposed spent fuel pool expansion Response within 30 days of ltr receipt requested
VARGA,S A Operating Reactors Branch 1 84/07/19 WILLIAMS,J W
Florida Power & Light Co 6pp 25973 321 24X
Fiche 50-250,84/07/19,8408010119

8408060436 Summary of 840713 meeting w/util in Bethesda MD re reactor matls surveillance program
MCDONALD,D G Operating Reactors Branch 1 84/07/19 Operating Reactors Branch 1 3pp 25937 317 24X Fiche 50-250,84/07/19, 8408060436

8408070032 Corrects issuance date of ltr re proposed spent fuel pool expansion to 840702
MCDONALD,D G Operating Reactors Branch 1 84/07/19 WILLIAMS,J W
Florida Power & Light Co 2pp 25955 360 24X
Fiche 50-250,84/07/19,8408070032

8408010005 Request correction to date of ltr forwarded on 840602, requesting info on NUREG-0737,Item II D 1 re performance testing of relief & safety valves Correct date is 840702
VARGA,S A Operating Reactors Branch 1 84/07/23 MCDONALD,R P
Alabama Power Co 2pp 25867 361 24X Fiche 50-250,84/07/23, 8408010005

8408070075 Forwards request for addl info re pressurized thermal shock flux reduction program Response requested within 3 wks of ltr receipt W/o encl
VARGA,S A Operating Reactors Branch 1 84/07/26 WILLIAMS,J W
Florida Power & Light Co 2pp 25955 317 24X
Fiche 50-250,84/07/26,8408070075

8408090491 Requests remittance of fee for review of 840521 application for amend to Tech Specs re safety-related snubbers
DIGGS,R M License Fee Management Branch 84/07/31 WILLIAMS,J W
Florida Power & Light Co 1p 25983 152 24X Fiche 50-250, 84/07/31,8408090491

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408160319 Forwards "Maint & Surveillance Program Plan," revised following 840706 NRC/NUMARC meeting
RUSSELL,W T Division of Human Factors Safety 84/08/07
WOODY,C O Florida Power & Light Co 1p 26126 019 24X
Fiche 50-000,84/08/07,8408160319

--8408160325 "Maint & Surveillance Program Plan "
* NRC - No Detailed Affiliation Given 84/07/31 23pp
26126 020 24X Fiche 50-000,84/08/07,8408160319

8408210634 Requests addl info re structural design aspects of 830314 request for Tech Spec mod to expand spent fuel storage facilities Mod necessary to accommodate increased inventory Addl info requested within 2 wks to meet review schedule
VARGA,S A Operating Reactors Branch 1 84/08/13 WILLIAMS,J W
Florida Power & Light Co 1p 26187 356 24X Fiche 50-250, 84/08/13,8408210634

8408170084 Forwards addl info re spent fuel storage facility expansion, per NRC 840702 request NITAWL,XSDRNPM & Keno-IV used to calculate reactivity of checkerboard & configuration in Region 2
WILLIAMS,J W Florida Power & Light Co 84/08/14 VARGA,S A
Operating Reactors Branch 1 7pp 26119 024 24X
Fiche 50-250,84/08/14,8408170084

8408210564 Forwards draft safety evaluation of NUREG-0737,Item II F 2 re inadequate core cooling instrumentation sys Evaluation identifies open items Addl info requested within 2 wks W/o encl
VARGA,S A Operating Reactors Branch 1 84/08/14 WILLIAMS,J W
Florida Power & Light Co 1p 26195 255 24X Fiche 50-250, 84/08/14,8408210564

8408230477 Forwards Amends 104 & 98 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends provide protection of safety-related equipment subjected to degraded voltage at offsite power source W/o encls
MCDONALD,D G Operating Reactors Branch 1 84/08/14 WILLIAMS,J W
Florida Power & Light Co 1p, 26230 216 24X
Fiche 50-250,84/08/14,8408230477

8408230564 Notification of 840906 & 07 meetings w/util in Bethesda, MD to discuss control room design reviews
MCDONALD, D G Operating Reactors Branch 1 84/08/16 VARGA, S A ,
MILLER, J R Operating Reactors Branch 1 2pp 26230 260 24X
Fiche 50-000, 84/08/16, 8408230564

8408220546 Notification of 840823 meeting w/util in Bethesda, MD to discuss details & review process for converting facility Tech Specs to STS format & content for Westinghouse reactors
MCDONALD, D G Operating Reactors Branch 1 84/08/17 VARGA, S A
Operating Reactors Branch 1 2pp 26199 340 24X
Fiche 50-250, 84/08/17, 8408220546

8408270015 Requests meeting w/NRC to discuss details of proposed Tech Spec rev program including purpose for rev, plan & schedule, integration w/related projects, limitations & licensing approach
WILLIAMS, J W Florida Power & Light Co 84/08/17 EISENHUT, D G
Division of Licensing 1p 26247 193 24X Fiche 50-250, 84/08/17, 8408270015

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408270019 Forwards remittance for 840615 request for amends in response to Generic Ltr 83-37 re NUREG-0737 Tech Specs, per 10CFR170 22
WILLIAMS, J W Florida Power & Light Co 84/08/21 EISENHUT, D G
Division of Licensing 1p 26247 194 24X Fiche 50-250, 84/08/21, 8408270019

8408270344 Forwards response to NRC 840719 requests for addl info re health physics aspects of proposed amend to spent fuel storage facility expansion
WILLIAMS, J W Florida Power & Light Co 84/08/22 VARGA, S A
Operating Reactors Branch 1 28pp 26244 329 24X
Fiche 50-250, 84/08/22, 8408270344

8408280238 Forwards addl neutron source data for NRC review of pressurized thermal shock flux reduction program, per 840726 request
WILLIAMS, J W Florida Power & Light Co 84/08/22 VARGA, S A
Operating Reactors Branch 1 36pp 26262 243 24X
Fiche 50-250, 84/08/22, 8408280238

O Inspection reports, IE Bulletins & correspondence

8408270289 Forwards Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/09 WILLIAMS, J W
Florida Power & Light Co 2pp 26238 167 24X
Fiche 50-250, 84/07/09, 8408270289

--8408270295 Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted Major areas inspected emergency preparedness
MARSTON, R R , CLINE, W E Region 2, Office of Director 84/07/06
9pp 26258 169 24X Fiche 50-250, 84/07/09, 8408270289

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408270314 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-250/84-14 & 50-251/84-14
LEWIS, R C Division of Project & Resident Programs 84/07/31
WILLIAMS, J W Florida Power & Light Co 2pp 26257 263 24X
Fiche 50-250, 84/07/31, 8408270314

-8408270316 Responds to NRC 840615 ltr re violations noted in Insp Repts 50-250/84-14 & 50-251/84-14 Corrective actions tracking sys developed to ensure that all license amend requirements will be met during implementation process
WILLIAMS, J W Florida Power & Light Co 84/07/16 O'REILLY, J P
Region 2, Office of Director 4pp 26257 265 24X
Fiche 50-250, 84/07/31, 8408270314

8408270322 Forwards Insp Repts 50-250/84-14 & 50-251/84-14 on 840407-28 & notice of violation
LEWIS, R C Division of Project & Resident Programs 84/06/15
WILLIAMS, J W Florida Power & Light Co 2pp 26257 269 24X
Fiche 50-250, 84/07/31, 8408270314

--8408270324 Notice of violation from insp on 840407-28
* Region 2, Office of Director 84/06/15 2pp 26257 271 24X
Fiche 50-250, 84/07/31, 8408270314

--8408270329 Insp Repts 50-250/84-14 & 50-251/84-14 on 840407-28 Violation noted clearance tags not properly filled out, hung or lifted & insufficient data taken to complete evaluation of cooling sys
PEEBLES, T A Region 2, Office of Director ELROD, S A Division of Project & Resident Programs 84/06/15 11pp 26257 273 24X
Fiche 50-250, 84/07/31, 8408270314

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408230148 Ack receipt of 840101, 30, 0216 & 0713 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-32, 50-251/83-28, 50-250/83-40, 50-251/83-39, 50-250/83-41 & 50-251/83-40
LEWIS, R C Region 2, Office of Director 84/08/17 WILLIAMS, J W
Florida Power & Light Co 1p 26209 283 24X Fiche 50-250, 84/08/17, 8408230148

8408310189 Forwards request for addl info re inservice insp program Info needed to ensure conformance w/ASME Boiler & Pressure Vessel Code Section II Info should be provided within 30 days from receipt of ltr.
VARGA, S A Operating Reactors Branch 1 84/08/17 WILLIAMS, J W
Florida Power & Light Co 4pp 26350 359 24X
Fiche 50-250, 84/08/17, 8408310189

8408270384 Forwards responses to notice of violation & proposed imposition of civil penalty Corrective actions include implementation of performance enhancement program to address concerns re mgt control of operation Penalty paid
WILLIAMS, J W Florida Power & Light Co 84/08/20 O'REILLY, J P
Region 2, Office of Director 11pp 26239 116 24X
Fiche 50-250, 84/08/20, 8408270384

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8408030239 LER 84-019-00 on 840625,unit shut down due to RCS leak of approx 10 gpm Caused by packing leak due to broken gland follower on valve 3-532 Affected loop bistables tripped & valve 3-352 manually backseated W/840725 ltr
HART,R D , WILLIAMS,J W Florida Power & Light Co 84/07/25 3pp
25917 217 24X Fiche 50-250,84/07/25,8408030239

8408080230 LER 82-021/03L-0 on 820511,self-initiated audits revealed inadequate surveillance of emergency diesel generators for tests required by Tech Spec 4 8 1 a 5 Caused by inadequate review of Operating Procedure 4304 1 W/840730 ltr
HART,R D , WILLIAMS,J W Florida Power & Light Co 84/07/30 3pp
25974 359 24X Fiche 50-250,84/07/30,8408080230

8408160521 LER 84-020-00 on 840712,unit shut down due to RCS leak of approx 13 5 gpm Leakage caused by broken gland flange on valve 3-538 Valve packing gland flange replaced & all Rockwell 3/4-inch valves inspected W/840810 ltr
LOVELL,J , WILLIAMS,J W Florida Power & Light Co 84/08/10 3pp
26108 021 24X Fiche 50-250,84/08/10,8408160521

8408200273 LER 84-021-00 on 840714,reactor tripped from subcritical condition Caused by power interruption of source range nuclear instrumentation control power Personnel counseled W/ 840813 ltr
LOVELL,J , WILLIAMS,J W Florida Power & Light Co 84/08/13 3pp
26139 114 24X Fiche 50-250,84/08/13,8408200273

8408270203 LER 84-022-00 on 840721 & 22,daily calibr of nuclear power range (thermal power calculation) not performed per Tech Specs Caused by personnel oversight Checks for calculations made & supervisory discussions held W/840820 ltr
HART,R D , WILLIAMS,J W Florida Power & Light Co 84/08/20 2pp
26257 336 24X Fiche 50-250,84/08/20,8408270203

V Operator Examinations

8408300360 Summarizes 840426 meeting w/util in Region II ofc re eligibility criteria for certain candidates to take NRC senior operator license exam Attendance list encl
LEWIS,R C Region 2, Office of Director 84/05/25 WILLIAMS,J W
Florida Power & Light Co 3pp 26308 198 24X
Fiche 50-250,84/05/25,8408300360

8408310030 Forwards comments on equivalent cold license training program Requests addl info re hot license program Hot license program equivalent to cold license training for determining eligibility
DANCE,H C Region 2, Office of Director 84/06/07 WILLIAMS,J W
Florida Power & Light Co 3pp 26335 017 24X
Fiche 50-250,84/06/07,8408310030

8408310064 Confirmation of action ltr re 840614 telcon concerning results of NRC operator exams on 840430 Operators who failed exam prohibited from performing licensed duties until Sections 6 & 7 completed satisfactorily
O'REILLY,J P Region 2, Office of Director 84/06/18
WILLIAMS,J W Carolina Power & Light Co 2pp 26334 349 24X
Fiche 50-250,84/06/18,8408310064

8408310425 Forwards summary of NRC 840627 meeting w/util in Region II ofc re util plans for training program improvements
DANCE,H C Region 2, Office of Director 84/07/24 WILLIAMS,J W
Florida Power & Light Co 5pp 26335 024 24X
Fiche 50-250,84/07/24,8408310425

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

8408010109 Informs that proposed schedules for implementation of alternate shutdown capability & mods for App R,Section III G in accordance w/10CFR50 48 & require no schedular exemptions
VARGA,S A Operating Reactors Branch 1 84/07/09 WILLIAMS,J W
Florida Power & Light Co 3pp 25873 352 24X
Fiche 50-250,84/07/09,8408010109

8408270289 Forwards Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/09 WILLIAMS,J W
Florida Power & Light Co 2pp 26258 167 24X
Fiche 50-250,84/07/09,8408270289

--8408270295 Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted Major areas inspected emergency preparedness
MARSTON,A R Region 2, Office of Director 84/07/06 9pp
26258 169 24X Fiche 50-250,84/07/09,8408270289

8408100016 Forwards Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization "
WILLIAMS,J W Florida Power & Light Co 84/08/08 O'REILLY,J P
Region 2, Office of Director 1p 25987 006 24X
Fiche 50-000,84/08/08,8408100016

--8408100054 Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization "
JOHNSON,H D Florida Power & Light Co 84/08/08 13pp
25987 007 24X Fiche 50-000,84/08/08,8408100016

8408240328 Confirms 840829 meeting in Bethesda,MD to discuss task analysis requirements of NUREG-0737,Suppl 1 & SER open items on CEN-152 re inadequate core cooling & reactor vessel level monitoring sys
THOMPSON,H L Division of Human Factors Safety 84/08/13
BARRON,J Florida Power & Light Co 1p 26253 336 24X
Fiche 50-250,84/08/13,8408240328

--8408240330 Notification of 840829 meeting w/util in Bethesda,MD to discuss task analysis requirements of NUREG-0737,Suppl 1 & SER open items on CEN-152 re inadequate core cooling & reactor vessel level monitoring sys
CLAYTON,H B Procedures & Systems Review Branch 84/08/09
ZIEMAN,D L Procedures & Systems Review Branch 2pp 26253 337
24X Fiche 50-250,84/08/13,8408240328

8408310003 Forwards request for addl info re safety parameter display sys implementation plan & parameter selection rept submitted in 840501 response to Generic Ltr 82-33 (NUREG-0737,Suppl 1) Response requested within 45 days
VARGA,S A Operating Reactors Branch 1 84/08/15 WILLIAMS,J W
Florida Power & Light Co 4pp 26350 202 24X
Fiche 50-250,84/08/15,8408310003

8408310133 Revs to emergency plan implementing procedures, including 2010,"Duties of Emergency Coordinator," 20201,"Maintaining Emergency Preparedness - Radiological Emergency Plan Training" & 20126,"Offsite Dose Calculation " W/840824 ltr
WILLIAMS,J W Florida Power & Light Co 84/08/24 O'REILLY,J P
Region 2, Office of Director 108pp 26322 001 24X
Fiche 50-250,84/08/24,8408310133

Q Adjudicatory correspondence

8408010213 Response supporting J Lorion & Ctr for Nuclear Responsibility 840709 request for hearing & petition for leave to intervene re amends to expand spent fuel pool Notice of appearance & Certificate of Svc encl
YOUNG,M A Hearing Branch 4 DSB 676 84/07/30 Atomic Safety and Licensing Board Panel 12pp 25856 040 24X
Fiche 50-250,84/07/30,8408010213

8408070305 Response supporting Ctr for Nuclear Responsibility request for hearing & petition for leave to intervene re amends to allow storage of fuel w/increased enrichment Notice of appearance & Certificate of Svc encl
YOUNG,M A Hearing Branch 4 DSB 810 84/07/31 Atomic Safety and Licensing Board Panel 12pp 25947 316 24X
Fiche 50-250,84/07/31,8408070305

8408090397 Notice of appearance in proceeding Certificate of Svc encl
COLL,N A Florida Power & Light Co COLL,N A Steel, Hector & Davis DSB 878 84/08/07 3pp 25982 173 24X
Fiche 50-250,84/08/07,8408090397

8408090437 Notice of appearance in proceeding Certificate of Svc encl
COLL,N A Florida Power & Light Co COLL,N A Steel, Hector & Davis DSB 879 84/08/07 Atomic Safety and Licensing Board Panel 3pp 25982 176 24X Fiche 50-250,84/08/07,8408090437

8408140214 Forwards 840810 motions for summary disposition of intervenor Contentions (b) & (d) & statement of matl facts & memorandum of law in support of motions Related correspondence
BAUSER,M A Newman & Holtzinger BAUSER,M A Florida Power & Light Co DSB 961 84/08/10 LAZO,R M , COLE,R F , LUEBKE,E A Atomic Safety and Licensing Board Panel 1p 26056 024 24X
Fiche 50-250,84/08/10,8408140214

--8408140220 Motion for summary dispositon of intervenor Contention b No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence
BAUSER,M A Florida Power & Light Co BAUSER,M A Newman & Holtzinger 84/08/10 Atomic Safety and Licensing Board Panel 5pp 26056 025 24X Fiche 50-250,84/08/10,8408140214

--8408140226 Affidavit of MJ Parvin in support of applicant 840810 motion for summary dispositon of intervenor Contention (b) Related correspondence
PARVIN, M J Florida Power & Light Co PARVIN, M J Westinghouse Electric Corp 84/08/03 6pp 26056 030 24X
Fiche 50-250, 84/08/10, 8408140214

--8408140236 Statement of matl facts as to which there is no genuine issue Related correspondence
BAUSER, M A Florida Power & Light Co BAUSER, M A Newman & Holtzinger BAUSER, M A Steel, Hector & Davis 84/08/10
Atomic Safety and Licensing Board Panel 3pp 26056 036 24X
Fiche 50-250, 84/08/10, 8408140214

--8408140253 Motion for summary dispositon of intervenor Contention (d) No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence
BAUSER, M A Florida Power & Light Co BAUSER, M A Newman & Holtzinger BAUSER, M A Steel, Hector & Davis 84/08/10
Atomic Safety and Licensing Board Panel 8pp 26056 039 24X
Fiche 50-250, 84/08/10, 8408140214

--8408140262 Affidavit of EA Dzenis in support of licensee 840810 motion for summary disposition of intervenor Contention (d)
Realted correspondence
DZENIS, E A Florida Power & Light Co DZENIS, E A Westinghouse Electric Corp 84/08/08 15pp 26056 047 24X
Fiche 50-250, 84/08/10, 8408140214

--8408140271 Statement of matl facts as to which there is no genuine issue re intervenor Contention (d) Related correspondence
BAUSER, M A Florida Power & Light Co BAUSER, M A Newman & Holtzinger 84/08/10 Atomic Safety and Licensing Board Panel 7pp. 26056 062 24X Fiche 50-250, 84/08/10, 8408140214

--8408140277 Memorandum of law in support of motions for summary disposition of intervenor Contentions (b) & (d)
Certificate of Svc encl Related correspondence
BAUSER, M A Florida Power & Light Co BAUSER, M A Newman & Holtzinger BAUSER, M A Steel, Hector & Davis 84/08/10 8pp
26056 069 24X Fiche 50-250, 84/08/10, 8408140214

8408210347 Notice of appearance in proceeding Certificate of Svc encl
REIS, H F Florida Power & Light Co REIS, H F Newman & Holtzinger
DSB 178 84/08/16 3pp 26179 180 24X Fiche 50-250, 84/08/16, 8408210347

8408210380 Notice of appearance in proceeding Certificate of Svc encl
REIS, H F Florida Power & Light Co REIS, H F Newman & Holtzinger
DSB 180 84/08/16 3pp 26180 248 24X Fiche 50-250, 84/08/16, 8408210380

H. General correspondence

8408210441 Informs of address change for plant manager
PEEBLES, T A Florida Power & Light Co 84/08/15 NRC - No
Detailed Affiliation Given 2pp 26181 256 24X
Fiche 50-250, 84/08/15, 8408210441

K Utility Final Safety Analysis Report (FSAR) & amends

8407260218 Forwards Rev 2 to updated FSAR for Turkey Point, Units 3 & 4
Changes made under provisions of 10CFR50 59 for Jul 1983 -
June 1984 will be provided by 840901
WILLIAMS, J W Florida Power & Light Co 84/07/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25771 129
24X Fiche 50-250, 84/07/23, 8407260218

--8407260220 Rev 2 to updated FSAR for Turkey Point, Units 3 & 4
* Florida Power & Light Co, 84/07/31 425pp 25771 133 24X
Fiche. 50-250, 84/07/23, 8407260218

P Operating license stage documents & correspondence

8408300382 Summarizes 840517 meeting w/util in Region II ofc re plant performance enhancement program Meeting beneficial & provided better understanding of plans
O'REILLY, J P Region 2, Office of Director 84/05/25,
WILLIAMS, J W Florida Power & Light Co 1p 26308 160 24X
Fiche 50-250, 84/05/25, 8408300382

8408300419 Summarizes 840618 meeting w/util in Region II ofc re performance enhancement program & quarterly progress rept meeting scheduled for 840712
DANCE, H C Region 2, Office of Director 84/06/25 WILLIAMS, J W
Florida Power & Light Co 1p. 26313 307 24X Fiche 50-250, 84/06/25, 8408300419

8408010119 Forwards request for addl info re measures taken to ensure ALARA doses during proposed spent fuel pool expansion
Response within 30 days of ltr receipt requested
VARGA, S A Operating Reactors Branch 1 84/07/19 WILLIAMS, J W
Florida Power & Light Co 6pp 25873 321 24X
Fiche 50-250, 84/07/19, 8408010119

8408060436 Summary of 840713 meeting w/util in Bethesda, MD re reactor matls surveillance program
MCDONALD, D G Operating Reactors Branch 1 84/07/19 Operating Reactors Branch 1 3pp 25937 317 24X Fiche 50-250, 84/07/19, 8408060436

8408070032 Corrects issuance date of ltr re proposed spent fuel pool expansion to 840702
MCDONALD, D G Operating Reactors Branch 1 84/07/19 WILLIAMS, J W
Florida Power & Light Co 2pp 25955 360 24X
Fiche 50-250, 84/07/19, 8408070032

8408010005 Request correction to date of ltr, forwarded on 840602, requesting info on NUREG-0737, Item II D 1 re performance testing of relief & safety valves Correct date is 840702
VARGA, S A Operating Reactors Branch 1 84/07/23 MCDONALD, R P
Alabama Power Co 2pp 25867 361 24X Fiche 50-250, 84/07/23, 8408010005

8408070075 Forwards request for addl info re pressurized thermal shock flux reduction program Response requested within 3 wks of ltr receipt W/o encl
VARGA, S A Operating Reactors Branch 1 84/07/26 WILLIAMS, J W
Florida Power & Light Co 2pp 25955 317 24X
Fiche 50-250, 84/07/26, 8408070075

8408090491 Requests remittance of fee for review of 840521 application for amend to Tech Specs re safety-related snubbers
DIGGS, R M License Fee Management Branch 84/07/31 WILLIAMS, J W
Florida Power & Light Co 1p 25983 152 24X Fiche 50-250, 84/07/31, 8408090491

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY, P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN, G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000, 84/08/06, 8408090317

8408160319 Forwards "Maint & Surveillance Program Plan," revised following 840706 NRC/NUMARC meeting
RUSSELL, W T Division of Human Factors Safety 84/08/07
WOODY, C O Florida Power & Light Co 1p 26126 019 24X
Fiche 50-000, 84/08/07, 8408160319

8408210634 Requests addl info re structural design aspects of 830314 request for Tech Spec mod to expand spent fuel storage facilities Mod necessary to accommodate increased inventory
Addl info requested within 2 wks to meet review schedule
VARGA, S A Operating Reactors Branch 1 84/08/13 WILLIAMS, J W
Florida Power & Light Co 1p 26187 356 24X Fiche 50-250, 84/08/13, 8408210634

8408170084 Forwards addl info re spent fuel storage facility expansion, per NRC 840702 request NITAWL, XSDRNPM & Keno-IV used to calculate reactivity of checkerboard & configuration in Region 2
WILLIAMS, J W Florida Power & Light Co 84/08/14 VARGA, S A
Operating Reactors Branch 1 7pp 26119 024 24X
Fiche 50-250, 84/08/14, 8408170084

8408210564 Forwards draft safety evaluation of NUREG-0737, Item II F 2 re inadequate core cooling instrumentation sys Evaluation identifies open items Addl info requested within 2 wks W/o encl
VARGA, S A Operating Reactors Branch 1 84/08/14 WILLIAMS, J W
Florida Power & Light Co 1p 26195, 255 24X Fiche 50-250, 84/08/14, 8408210564

8408230477 Forwards Amends 104 & 98 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends provide protection of safety-related equipment subjected to degraded voltage at offsite power source W/o encls
MCDONALD, D G. Operating Reactors Branch 1 84/08/14 WILLIAMS, J W
Florida Power & Light Co 1p 26230 216 24X
Fiche 50-250, 84/08/14, 8408230477

8408230564 Notification or 840906 & 07 meetings w/util in Bethesda,MD to discuss control room design reviews
MCDONALD,D G Operating Reactors Branch 1 84/08/16 VARGA,S A ,
MILLER,J R Operating Reactors Branch 1 2pp 26230 260 24X
Fiche 50-000,84/08/16,8408230564

8408220546 Notification of 840823 meeting w/util in Bethesda,MD to discuss details & review process for converting facility Tech Specs to STS format & content for Westinghouse reactors
MCDONALD,D G Operating Reactors Branch 1 84/08/17 VARGA,S A
Operating Reactors Branch 1 2pp 26199 340 24X
Fiche 50-250,84/08/17,8408220546

8408270015 Requests meeting w/NRC to discuss details of proposed Tech Spec rev program,including purpose for rev,plan & schedule, integration w/related projects,limitations & licensing approach
WILLIAMS,J W Florida Power & Light Co 84/08/17 EISENHUT,D G
Division of Licensing 1p 26247 193 24X Fiche 50-250,84/08/17, 8408270015

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408270019 Forwards remittance for 840615 request for amends in response to Generic Ltr 83-37 re NUREG-0737 Tech Specs,per 10CFR170 22
WILLIAMS,J W Florida Power & Light Co 84/08/21 EISENHUT,D G
Division of Licensing 1p 26247 194 24X Fiche 50-250,84/08/21, 8408270019

8408270344 Forwards response to NRC 840719 requests for addl info re health physics aspects of proposed amend to spent fuel storage facility expansion
WILLIAMS,J W Florida Power & Light Co 84/08/22 VARGA,S A
Operating Reactors Branch 1 26pp 26244 329 24X
Fiche 50-250,84/08/22,8408270344

8408280238 Forwards addl neutron source data for NRC review of pressurized thermal shock flux reduction program,per 840726 request
WILLIAMS,J W Florida Power & Light Co 84/08/22 VARGA,S A
Operating Reactors Branch 1 36pp 26262 243 24X
Fiche 50-250,84/08/22,8408280238

G Inspection reports, IE Bulletins & correspondence
---------- ----------

8408270289 Forwards Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/09 WILLIAMS,J W
Florida Power & Light Co 2pp 26258 167 24X
Fiche 50-250,84/07/09,8408270289

--8408270295 Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted Major areas inspected emergency preparedness
MARSTON,R R , CLINE,W E Region 2, Office of Director 84/07/06
9pp 26258 169 24X Fiche 50-250,84/07/09,8408270289

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25868 047 24X Fiche 50-000,84/07/27,8407250229

8408270314 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in Insp Rapts 50-250/84-14 & 50-251/84-14
LEWIS,R C Division of Project & Resident Programs 84/07/31
WILLIAMS,J W Florida Power & Light Co 2pp 26257 263 24X
Fiche 50-250,84/07/31,8408270314

--8408270316 Responds to NRC 840615 ltr re violations noted in Insp Repts 50-250/84-14 & 50-251/84-14 Corrective actions tracking sys developed to ensure that all license amend requirements will be met during implementation process
WILLIAMS,J W Florida Power & Light Co 84/07/16 O'REILLY,J P
Region 2, Office of Director 4pp 26257 265 24X
Fiche 50-250,84/07/31,8408270314

--8408270322 Forwards Insp Repts 50-250/84-14 & 50-251/84-14 on 840407-28 & notice of violation
LEWIS,R C Division of Project & Resident Programs 84/06/15
WILLIAMS,J W Florida Power & Light Co 2pp 26257 269 24X
Fiche 50-250,84/07/31,8408270314

--8408270324 Notice of violation from insp on 840407-28
Region 2, Office or Director 84/06/15 2pp 26257 271 24X
Fiche 50-250,84/07/31,8408270314

--8408270329 Insp Repts 50-250/84-14 & 50-251/84-14 on 840407-28 Violation noted clearance tags not properly filled out,hung or lifted & insufficient data taken to complete evaluation of cooling sys
PEEBLES,T A Region 2, Office of Director ELROD,S A Division of Project & Resident Programs 84/06/15 11pp 26257 273 24X
Fiche 50-250,84/07/31,8408270314

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp. 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408230148 Ack receipt of 840101,30,0216 & 0713 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-32,50-251/83-28,50-250/83-40,50-251/83-39, 50-250/83-41 & 50-251/83-40
LEWIS,R C Region 2, Office of Director 84/08/17 WILLIAMS,J W
Florida Power & Light Co 1p, 26209 283 24X Fiche 50-250, 84/08/17,8408230148

8408230151 Ack receipt of 840806 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-251/84-21 Corrective actions will be examined during future insp
LEWIS,R C Region 2, Office of Director 84/08/17 WILLIAMS,J W
Florida Power & Light Co 1p 26209 284 24X Fiche. 50-251, 84/08/17,8408230151

--8408230155 Responds to NRC 840705 ltr re violations noted in IE Insp Rept 50-251/84-21 Corrective actions temporary sys alteration documentation required by Administrative Procedure 103 3 completed & personnel counseled
WILLIAMS,J W Florida Power & Light Co 84/08/06 O'REILLY,J P
Region 2, Office of Director 2pp 26209 285 24X
Fiche 50-251,84/08/17,8408230151

--8408230158 Forwards IE Insp Rept 50-251/84-21 on 840604-06 & notice of violation
LEWIS,R C Region 2, Office of Director 84/07/05 WILLIAMS,J W
Florida Power & Light Co 3pp 26209 287 24X
Fiche 50-251,84/08/17,8408230151

--8408230161 Notice of violation from insp on 840604-06
* Region 2, Office of Director 84/07/05 1p 26209 290 24X
Fiche 50-251,84/08/17,8408230151

--8408230166 IE Insp Rept 50-251/84-21 on 840604-06 Violations noted failure to follow plant procedure for temporary sys alteration
FALCONER,D P , KRUG,H E Region 2, Office of Director 84/07/02
7pp 26209 291 24X Fiche 50-251,84/08/17,8408230151

8408310189 Forwards request for addl info re inservice insp program Info needed to ensure conformance w/ASME Boiler & Pressure Vessel Code Section 11 Info should be provided within 30 days from receipt of ltr
VARGA,S A Operating Reactors Branch 1 84/08/17 WILLIAMS,J W
Florida Power & Light Co 4pp 26350 389 24X
Fiche 50-250,84/08/17,8408310189

8408270384 Forwards responses to notice of violation & proposed imposition of civil penalty Corrective actions include implementation of performance enhancement program to address concerns re mgt control of operation Penalty paid
WILLIAMS,J W Florida Power & Light Co 84/08/20 O'REILLY,J P
Region 2, Office of Director 11pp 26239 116 24X
Fiche 50-250,84/08/20,8408270384

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8408010311 LER 84-014-00 on 840625,reactor tripped from hot shutdown conditions while unit subcritical for practice startups Caused by failure of source range detector N-32 Detector replaced W/840725 ltr
HART,R D ; WILLIAMS,J W Florida Power & Light Co 84/07/25 3pp
25866 159 24X Fiche 50-251,84/07/25,8408010311

V Operator Examinations

8408300360 Summarizes 840426 meeting w/util in Region II ofc re eligibility criteria for certain candidates to take NRC senior operator license exam Attendance list encl
LEWIS,R C Region 2, Office of Director 84/05/25 WILLIAMS,J W
Florida Power & Light Co 3pp 26308 198 24X
Fiche 50-250,84/05/25,8408300360

8408310030 Forwards comments on equivalent cold license training program Requests addl info re hot license program Hot license program equivalent to cold license training for determining eligibility
DANCE,H C Region 2, Office of Director 84/06/07 WILLIAMS,J W
Florida Power & Light Co 3pp 26335 017. 24X
Fiche 50-250,84/06/07,8408310030

8408310064 Confirmation of action ltr re 840614 telcon concerning results of NRC operator exams on 840430 Operators who failed exam prohibited from performing licensed duties until Sections 6 & 7 completed satisfactorily
O'REILLY,J P Region 2, Office of Director 84/06/18,
WILLIAMS,J W Carolina Power & Light Co 2pp 26334 349 24X
Fiche 50-250,84/06/18,8408310064

8408310425 Forwards summary of NRC 840627 meeting w/util in Region II ofc re util plans for training program improvements
DANCE,H C Region 2, Office of Director 84/07/24, WILLIAMS,J W
Florida Power & Light Co. 5pp 26335 024 24X
Fiche 50-250,84/07/24,8408310425

DOCKET 50-252 UNIV OF NEW MEXICO RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408090525 Approves 840717 request for 30-day extension for resubmittal of revised emergency plan Revised plan expected by 840920
THOMAS,C O Standardization & Special Projects Branch 84/08/01
WHAN,G A New Mexico, Univ of, Albuquerque, NM 3pp 25983 123
Fiche 50-252,84/08/01,8408090525

DOCKET 50-254 QUAD CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21)
FARRAR,D L Commonwealth Edison Co 84/08/03 Region 3, Office of Director 1p 26044 252 24X Fiche 50-000,84/08/03,8408140139

8408140365 Revised emergency implementing procedures, including Rev 7 to QEP 110-2 re shift engineer, Rev 6 to QEP 180-0 re Rad-Chem director & Rev 17 to QEP 200-0 re emergency conditions
* Commonwealth Edison Co 84/08/04 84pp 26041 052 24X
Fiche 50-254,84/08/04,8408140365

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO,C J Region 3, Office of Director 84/08/07 REED,C
Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000,84/08/07,8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR,D L Commonwealth Edison Co 84/07/05 PAPERIELLO,C J
Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000,84/08/07,8408130401

8408200248 Advises that 840803 Rev 15 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
AXELSON,W L Region 3, Office of Director 84/08/14 FARRAR,D L
Commonwealth Edison Co 2pp 26133 190 24X Fiche 50-254,84/08/14,8408200248

8408230270 Revised emergency plan implementing procedures, including Rev 23 to QEP-310-0, "Notification of Responsible Authorities," & Rev 13 to QEP 310-T3, "Prioritized Notification Listing " W/rev receipt form
* Commonwealth Edison Co 84/08/16 11pp 26209 323 24X
Fiche 50-254,84/08/16,8408230270

P Operating license stage documents & correspondence

8408150611 Grants 840529 request for extension until 851001, but no later than 851130, for replacement of four Limitorque actuator motors & qualification of MSIV solenoid operators
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/07/30 FARRAR,D L Commonwealth Edison Co 3pp 26105 357
24X Fiche 50-254,84/07/30,8408150611

8408060425 Notification of 840809-10 meetings w/utils,NUTECH,Franklin Research Ctr & BNL in San Jose,CA to discuss comments resulting from post-implementation review re plant-unique analysis repts
BEVAN,R D , ROONEY,V L , THADANI,M C Operating Reactors Branch 2
84/07/31 VASSALLO,D B Operating Reactors Branch 2 1p
25937 335 24X Fiche 50-000,84/07/31,8408060425

8408140317 Forwards response to 840626 request for addl info re 125-volt dc sys Facility recently completed replacement of 125-volt battery chargers w/200 ampere-rated units
RYDAS,B Commonwealth Edison Co 84/08/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 17pp 26042 333 24X
Fiche 50-254,84/08/01,8408140317

8408150588 Forwards Amend 90 to License DPR-29 & safety evaluation Amend incorporates new MAPLHGR curves for new linear fuel & changes calibr & functional test frequencies for instrumentation
BEVAN,R B Operating Reactors Branch 2 84/08/02 FARRAR,D L
Commonwealth Edison Co 2pp 26106 025 24X Fiche 50-254,84/08/02,8408150588

--8408150593 Amend 90 to License DPR-29, incorporating new MAPLHGR curves for new linear fuel change calibr & functional test frequencies for instrumentation & adding new Tech Specs re modified scram discharge sys
VASSALLO,D B Operating Reactors Branch 2 84/08/02 23pp
26106 027 24X Fiche 50-254,84/08/02,8408150588

--8408150597 Safety evaluation supporting Amend 90 to License DPR-29
* Office of Nuclear Reactor Regulation, Director 84/08/02 4pp
26106 050 24X Fiche 50-254,84/08/02,8408150588

8408160465 Forwards 840802 SER re IGSCC insp & repair IGSCC insp & repair performed in accordance w/Generic Ltr 84-11
Insp &/or mod plans in util 840730 ltr meet requirements
VASSALLO, D B Operating Reactors Branch 2 84/08/02 FARRAR, D L
Commonwealth Edison Co 2pp 26120 349 24X Fiche 50-254, 84/08/02,
8408160465

--8408160469 Safety evaluation re reinsp & repairs of RCS piping Plant can be safely returned to power & operated in present configuration for one 18-month fuel cycle
* Office of Nuclear Reactor Regulation, Director 84/08/02
11pp 26120 351 24X Fiche 50-254, 84/08/02, 8408160465

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, 'Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear
Material Safety & Safeguards, Director 1p 26092 184 24X
Fiche 50-000, 84/08/06, 8408160345

8408270114 Provides supplemental response to Generic Ltr 83-36, "NUREG-0737 Tech Specs " Mods to Quad Cities radiological ETS will not be complete until Fall 1984 Complete response w/amend requests expected by 841115
ALEXANDER, G L Commonwealth Edison Co 84/08/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26247 330
24X Fiche 50-000, 84/08/15, 8408270114

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310203 Suppl to 830217 application for amend to Licenses DPR-29 & DPR-30, revising Tech Specs to incorporate listed changes reflecting rev to 10CFR50 72 & new Section 50 73 LER reporting requirements, per Generic Ltr 83-43
RYBAK, B Commonwealth Edison Co 84/08/23 DENTON, H R Office of
Nuclear Reactor Regulation, Director 6pp 26320 245 24X
Fiche 50-254, 84/08/23, 8408310203

--8408310206 Proposed Tech Spec changes reflecting revised 10CFR50 72 & new Section 50 73 LER reporting requirements
* Commonwealth Edison Co 84/08/23 62pp 26320 251 24X
Fiche 50-254, 84/08/23, 8408310203

8408310211 Forwards final response to second & final set of questions re Mark I containment plant-unique analysis
RYBAK, B Commonwealth Edison Co 84/08/24 DENTON, H R Office of
Nuclear Reactor Regulation, Director 37pp 26318 072 24X
Fiche 50-000, 84/08/24, 8408310211

G Inspection reports, IE Bulletins & correspondence

8408060065 Commits to performing visual exam of reactor coolant piping during each outage in which containment deinerted, per Generic Ltr 84-11
RYBAK, B Commonwealth Edison Co 84/07/25 DENTON, H R Office of
Nuclear Reactor Regulation, Director 1p 25933 103 24X
Fiche 50-254, 84/07/25, 8408060065

8408150392 Forwards IE Insp Repts 50-254/84-10 & 50-265/84-09 on 840625-28 & 0706 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/07/26 REED, C
Commonwealth Edison Co 2pp 26077 340 24X Fiche 50-254, 84/07/26,
8408150392

--8408150401 IE Insp Repts 50-254/84-10 & 50-265/84-09 on 840625-28 & 0706 No violations or deviations noted Major areas inspected confirmatory measures, radiological environ monitoring program & licensee actions on open items
ROZAK, S , OESTMANN, M J , SCHUMACHER, M C Region 3, Office of
Director 84/07/25 10pp 26077 342 24X Fiche 50-254, 84/07/26,
8408150392

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408060108 Advises that plans for insps, corrective actions &/or mods, including replacement of recirculation & piping, will be submitted 90 days prior to next refueling outage, per 840604 & 0725 commitments
RYBAK, B Commonwealth Edison Co 84/07/30 DENTON, H R Office of
Nuclear Reactor Regulation, Director 1p 25933 179 24X
Fiche 50-254, 84/07/30, 8408060108

8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC
NORELIUS, C E Region 3, Office of Director 84/08/03 REED, C
Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000, 84/08/03,
8408070066

8408230549 Forwards IE Insp Repts 50-254/84-08 & 50-265/84-07 on 840520-0623 & notice of violation Type A tests must be conducted during each refueling outage, unless request & granted exemption from requirement received
NORELIUS, C E Region 3, Office of Director 84/08/03 REED, C
Commonwealth Edison Co 2pp 26213 005 24X Fiche 50-254, 84/08/03,
8408230549

--8408230551 Notice of violation from insp on 840520-0623
NORELIUS, C E Region 3, Office of Director 84/08/03 2pp
26213 007 24X Fiche 50-254, 84/08/03, 8408230549

--8408230555 IE Insp Repts 50-254/84-08 & 50-265/84-07 on 840520-0623 Noncompliance noted failure to local leak rate test gasketed penetration & failure to quantify leakage during integrated leak rate test
CHRISSOTIMOS, N Region 3, Office of Director 84/07/23 9pp
26213 009 24X Fiche 50-254, 84/08/03, 8408230549

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New
York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, 84/08/08,
8408140344

8408150098 Suppls 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26067 053 24X
Fiche 50-000, 84/08/08, 8408150098

8408200331 Suppls response to IE Bulletin 84-02 re failure of MFA relays Exemption requested from commitment for visua insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/0F
Region 3, Office of Director 3pp 26132 318
Fiche 50-000, 84/08/08, 8408200331

8408070376 IE Info Notice 84-62, "Therapy Misadmi Patients Undergoing Co-60 Teletherapy Treatmant list encl
GRACE, J N Division of QA, Safeguards & Inspec
830103) 84/08/10 Consolidated Edison Co
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8

8408100009 IE Info Notice 84-63, "Defective RHR R Svc list encl
JORDAN, E L Division of Emergency Preparedness
Response (Post 830103) 84/08/13 Consolida
York, Inc 119pp 26197 218 24X Fiche 50-00

DOCKETED ITEMS

8408280080 Forwards Insp Rept 50-254/84-12 on 840720-26 No Noncompliance noted Containment integrated leak rate test exceeded App J limit due to leakage in HPCI turbine exhaust valve & MSIV Type A test must be performed at next outage
LITTLE,W S Region 3, Office of Director 84/08/13 REED,C Commonwealth Edison Co 2pp 26261 199 24X Fiche 50-254,84/08/13, 8408280080

--8408280085 Insp Rept 50-254/84-12 on 840720-26 No noncompliance or deviations noted Major areas inspected containment integrated leak rate test
HARE,S M , GULDEMOND,W G Region 3, Office of Director 84/08/10 5pp 26261 201 24X Fiche 50-254,84/08/13,8408280080

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408210068 Rept of changes, tests & experiments completed during Jul 1984 W/840801 ltr
KALIVIANAKIS,N Commonwealth Edison Co 84/07/31 CASE,E G Office of Nuclear Reactor Regulation, Director 2pp 26184 307 24X Fiche 50-254,84/07/31,8408210068

8408230435 Monthly operating repts for Jul 1984 W/840801 ltr
KIMLER,D , KALIVIANAKIS,N Commonwealth Edison Co 84/07/31 24pp 26213 074 24X Fiche 50-254,84/07/31,8408230435

8408300299 Forwards "Effluent & Waste Disposal Semiannual Rept, Jan-June 1984, Gaseous Effluents - Summation of All Releases" & errata to semiannual repts for Jan-June & Jul-Dec 1983
KALIVIANAKIS,N Commonwealth Edison Co 84/08/15 KEPPLER,J G Region 3, Office of Director 1p 26314 225 24X Fiche 50-254,84/08/15,8408300299

-8408300308 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1984 "
BEHRENS,P A Commonwealth Edison Co 84/08/30 12pp 26314 226 24X Fiche 50-254,84/08/15,8408300299

--8408300329 Errata to "Liquid Effluents - Summation of All Releases " Jan-June 1983
* Commonwealth Edison Co 83/06/30 7pp 26314 233 24X Fiche 50-254,84/08/15,8408300299

--8408300336 Errata to "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983, Gaseous Effluents - Summation of All Releases "
* Commonwealth Edison Co 83/12/31 2pp 26314 240 24X Fiche 50-254,84/08/15,8408300299

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,G G General Electric Co 84/04/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348

8408230496 LER 84-014-00 on 840808,while starting shutdown cooling mode of RHR sys,LPCI valves 1-1001-29A & B would not open Caused by personnel error Valve stems removed & being replaced W/840814 ltr
COOK,D B , KALIVIANAKIS,N Commonwealth Edison Co 84/08/14 4pp 26212 255 24X Fiche 50-254,84/08/14,8408230496

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA,R General Electric Co 84/08/21 ROSSI C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000,84/08/21,8408310186

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators,Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL,J G Commonwealth Edison Co 84/08/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000,84/08/07,8408140372

--8408140389 "Requalification Program for Licensed Operators,Senior Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X Fiche 50-000,84/08/07,8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET 50-255 PALISADES NUCLEAR PLANT

D NRC Draft/Final Environmental Statements, suppls & correspondence

8408130366 Forwards request for addl info re FES & final addendum in preparation for conversion of provisional OL Response requested within 30 days of ltr receipt
PAULSON,W A Operating Reactors Branch 5 84/08/08
VANDEWALLE,D J Consumers Power Co 3pp 26011 091 24X Fiche 50-255,84/08/08,8408130366

F Security, medical, emergency & fire protection plans

8408240082 Forwards IE Insp Rept 50-255/84-10 on 840529-0713 & notice of violation
SHAFER,W D Region 3, Office of Director 84/07/24 DEWITT,R B Consumers Power Co 2pp 26237 023 24X Fiche 50-255,84/07/24, 8408240082

--8408240085 Notice of violation from insp on 840529-0713
SHAFER,W D Region 3, Office of Director 84/07/24 1p 26237 025 24X Fiche 50-255,84/07/24,8408240082

--8408240088 IE Insp Rept 50-255/84-10 on 840529-0/13 Noncompliance noted failure to document missing tags when performing engineered safeguards (iodine removal) & auxiliary feedwater sys checklists
WRIGHT,G C Region 3, Office of Director 84/07/24 8pp 26237 026 24X Fiche 50-255,84/07/24,8408240082

8408070435 Forwards Rev 3 to milestone commitments on Suppl 1 to NUREG-0737 & "PSAR,Safety Parameter Display Sys." per 830913 & 16 submittals
JOHNSON,D D Consumers Power Co 84/07/31 CRUTCHFIELD,D Operating Reactors Branch 5 6pp 25942 361 24X Fiche 50-255,84/07/31,8408070435

--8408070441 "PSAR,Safety Parameter Display Sys "
* Consumers Power Co 84/07/31 201pp 25943 005 24X Fiche 50-255,84/07/31,8408070435

8408130353 Forwards Rev 10 to security plan & Rev 1 to safeguards contingency plan Revs withheld (ref 10CFR73 21)
VANDEWALLE,D Consumers Power Co 84/08/06 KEPPLER,J G Region 3, Office of Director, 1p 26010 059 24X Fiche 50-255,84/08/06, 8408130353

8408090179 Responds to 840417 request for exemption from App E to 10CFR50,excluding state & county participation in 840821 emergency preparedness exercise Request for exemption not required,per 840706 rev to App E
PAULSON,W A Operating Reactors Branch 5 84/08/07
VANDEWALLE,D J Consumers Power Co 2pp 25972 288 24X Fiche 50-255,84/08/07,8408090179

8408130370 Responds to 840711 ltr re access authorization program
Access authorization list development & maint functions
being transferred to Div of Resource Mgt Notification of
terminated employees will be on as needed basis
AXELSON,W L Region 3, Office of Director 84/08/09
VANDEWALLE,D J Consumers Power Co 1p 26010 358 24X
Fiche 50-000,84/08/09,8408130370

--8408130376 Submits list of items discussed in 840703 telcon No
termination notifications received Updates on activities
will be submitted Concurrence needed for documentation
LATHWELL,H J Consumers Power Co 84/07/11 CREED,J Region 3,
Office of Director 2pp 26010 359 24X Fiche 50-000,84/08/09,
8408130370

8408140295 Provides editorial changes to 840731 cover ltr & Attachment
1 re Suppl 1 to NUREG-0737,safety parameter display sys
PSAR & implementation schedule,per Reg Guide 1 97 variables
JOHNSON,D D Consumers Power Co 84/08/09 CRUTCHFIELD,D
Operating Reactors Branch 5 6pp 26043 144 24X
Fiche 50-255,84/08/09,8408140295

8408170364 Forwards Rev 3 to fire protection exemption requests &
modified commitments List of equipment necessary for safe
shutdown & exemption request re local tending of diesel
generators included
JOHNSON,D D Consumers Power Co 84/08/10 CRUTCHFIELD,D
Operating Reactors Branch 5 61pp 26114 001 24X
Fiche 50-255,84/08/10,8408170364

8408200319 Advises that 840806 Rev 10 to physical security plan & Rev 1
to safeguards contingency plan consistent w/provisions of
10CFR50 54(p) & acceptable
AXELSON,W L Region 3, Office of Director 84/08/13
VANDEWALLE,D J Consumers Power Co 2pp 26133 010 24X
Fiche 50-255,84/08/13,8408200319

8408280113 Responds to 840717 ltr requesting extension of completion
dates for submitting final rept re Reg Guide 1 97
requirements of Suppl 1 to NUREG-0737 Extension granted
Adequate justification provided
EISENHUT,D G Division of Licensing 84/08/23 VANDEWALLE,D J
Consumers Power Co 4pp 26261 276 24X Fiche 50-255,84/08/23,
8408280113

8408300048 Ack receipt of 840326 ltr re new volumetric intrusion
detection sys Concern expressed re delay in completion of
upgrade Compensatory measures may be required if not
complete by Dec 1986
PAULSON,W A Operating Reactors Branch 5 84/08/24
VANDEWALLE,D J Consumers Power Co 4pp 26331 341 24X
Fiche 50-255,84/08/24,8408300048

O Advisory Committee on Reactor Safeguards reports & correspondence

8408200182 Advises that encl "Rept to ACRS,CPC of Michigan Palisades
Plant," may be declassified & made available to public
FUNCHES,J L Planning & Program Analysis Staff 84/08/08
SCATOLINI,L B Public Document Branch 2pp 26142 295 24X
Fiche 50-255,84/08/08,8408200182

--8408200184 "Rept to ACRS,CPC of Michigan Palisades Plant "
* Atomic Energy Commission 69/08/26 24pp 26142 297 24X
Fiche 50-255,84/08/08,8408200182

P Operating license stage documents & correspondence

8408030150 Forwards application for amend to License DPR-20,modifying
Tech Spec Sections 1 0 & 6 0 re definitions & administrative
controls,respectively,to reflect 10CFR50 73 reporting
requirements
VANDEWALLE,D J Consumers Power Co 84/07/30 CRUTCHFIELD,D
Operating Reactors Branch 5 1p 25915 349 24X
Fiche 50-255,84/07/30,8408030150

--8408030151 Application to amend License DPR-20,modifying Tech Spec
Sections 1 0 & 6 0 re definitions & administrative controls,
respectively,reflecting 10CFR50 73 reporting requirements
REYNOLDS,J W Consumers Power Co 84/07/30 2pp 25915 350
24X Fiche 50-255,84/07/30,8408030150

--8408030152 Proposed changes to Tech Specs 1 0 & 6 0,reflecting
10CFR50 73 reporting requirements
* Consumers Power Co 84/07/30 11pp 25915 352 24X
Fiche 50-255,84/07/30,8408030150

8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers,"
omitted from 840503 ltr to all SEP licensees NRC position
that issue of Tech Specs for snubbers will be resolved on
generic basis restated
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/07/31
KAY,J A Yankee Atomic Electric Co LINDER,F Dairyland Power
Cooperative FIEDLER,P B General Public Utilities - GPU Service
Corp 4pp 25955 227 24X Fiche 50-000,84/07/31,8408070099

8408070431 Application for amend to License DPR-20,adding Section 3 0
limiting conditions for operation applicability,in response
to 831031 radiological effluent Tech Specs transmitting
Draft 7 of Rev 3 to NUREG-0472
VANDEWALLE,D J Consumers Power Co 84/07/31 CRUTCHFIELD,D
Operating Reactors Branch 5 10pp 25939 221 24X
Fiche 50-255,84/07/31,8408070431

--8408070438 Proposed Tech Specs adding Section 3 0 limiting conditions
for operation applicability,deleting Section 3 9, "Effluent
Releases" & adding new Section 4 24, "Radiological Effluent
Releases "
* Consumers Power Co 84/07/31 175pp 25939 228 24X
Fiche 50-255,84/07/31,8408070431

8408080331 Forwards addl fee for review of 840613 Tech Spec change
application re containment purge & ventilation sys
JOHNSON,D D Consumers Power Co 84/08/02 DIGGS,R M License Fee
Management Branch 1p 25964 109 24X Fiche 50-255,84/08/02,
8408080331

8408070110 Generic Ltr 84-19 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
Suppl 1 to NUREG-0933, "Prioritization of Generic Safety
Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting
activities for operating reactors & license applicants for
Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408100134 Application for amend to License DPR-20,changing Tech Spec
re plant review committee,in response to NRC concerns
VANDEWALLE,D J Consumers Power Co 84/08/06 CRUTCHFIELD,D
Operating Reactors Branch 5 5pp 25991 038 24X
Fiche 50-255,84/08/06,8408100134

--8408100138 Proposed Tech Spec re administrative controls
* Consumers Power Co 84/08/06 2pp 25991 040 24X
Fiche 50-255,84/08/06,8408100134

8408160295 Notifies of Class III fee due for review of 840514
request for relief from ASME Code requirements
DIGGS,R M License Fee Management Branch 84/08/09
VANDEWALLE,D J Consumers Power Co 1p 26124 345 24X
Fiche 50-255,84/08/09,8408160295

8408140388 Advises that NRC 840624 comments re Multi-Plant Action B-57,
"DHR Capability," reviewed Changes to Tech Specs may be
warranted Preparation of proposed changes & justifications
for specs not being altered will be submitted by Dec 1984
JOHNSON,D D Consumers Power Co 84/08/10 CRUTCHFIELD,D
Operating Reactors Branch 5 1p 26053 349 24X
Fiche 50-255,84/08/10,8408140388

8408170022 Informs that 840523 QA program submittal requires
identification of each change,reason for change & basis for
concluding that revised program incorporating each change
satisfies 10CFR50,App B & SAR QA program commitments
SPESSARD,R L Region 3, Office of Director 84/08/14, DEWITT,R B
Consumers Power Co 2pp 26119 077 24X Fiche 50-000,84/08/14,
8408170022

8408230201 Forwards remittance for hydrotest relief 840514 request,per
840809 ltr
JOHNSON,D D Consumers Power Co 84/08/17 DIGGS,R M License Fee
Management Branch 1p 26209 197 24X Fiche 50-255,84/08/17,
8408230201

8408200275 Generic Ltr 84-20 to all licensees of operating reactors &
applicants for OLs re scheduling guidance for licensee
submittals of reloads that involve unreviewed safety
questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408210307 Forwards notice of environ assessment & finding of no significant impact re 801112 application & 821116 supplemental ltr for relief from requirements of Section XI of ASME Boiler & Pressure Vessel Code
PAULSON,W A Operating Reactors Branch 5 84/08/20
VANDENHALLE,D J Consumers Power Co 2pp 26180 222 24X Fiche 50-255,84/08/20,8408210307

--8408210309 Notice of environ assessment & finding of no significant impact
EISENHUT,D G Division of Licensing 84/08/20 3pp 26180 224 24X Fiche 50-255,84/08/20,8408210307

8408240161 Requests extension until 840201 to submit final PRA & cost-benefit analyses in response to SEP Topic XV-2, "Spectrum of Steam Piping Failures Inside & Outside Containment (PWR) " Extension due to difficulties in new computer codes
VANDENHALLE,D J Consumers Power Co 84/08/21 Office of Nuclear Reactor Regulation, Director 1p 26228 184 24X Fiche 50-255,84/08/21,8408240161

G Inspection reports, IE Bulletins & correspondence

8408300156 Forwards Insp Rept 50-255/84-06 on 840322-23 & 0427 W/o notice of violation
KEPPLER,J G Region 3, Office of Director 84/07/11 DEWITT,R B Consumers Power Co 2pp 26307 333 24X Fiche 50-255,84/07/11, 8408300156

--8408300164 Insp Rept 50-255/84-06 on 840322-23 & 0427 Noncompliance noted dose to worker exceeded 10CFR20 101 limits, failure to provide proper monitoring for high radiation area access & failure to follow radiation protection procedures
LOVENDALE,P C ; GREGER,L R Region 3, Office of Director 84/07/10 13pp 26307 335 24X Fiche 50-255,84/07/11,8408300156

8408090192 Forwards IE Insp Rept 50-255/84-12 on 840713 No noncompliance identified
LITTLE,W S Region 3, Office of Director 84/07/24 DEWITT,R B Consumers Power Co 2pp 25992 084 24X Fiche 50-255,84/07/24, 8408090192

--8408090195 IE Insp Rept 50-255/84-12 on 840713 No noncompliance identified Major areas inspected followup of valve shaft insp & replacement of MSIVs
JONES,D E ; DANIELSON,D H Region 3, Office of Director 84/07/24 3pp 25992 086 24X Fiche 50-255,84/07/24,8408090192

8408240082 Forwards IE Insp Rept 50-255/84-10 on 840529-0713 & notice of violation
SHAFER,W D Region 3, Office of Director 84/07/24 DEWITT,R B Consumers Power Co 2pp 26237 023 24X Fiche 50-255,84/07/24, 8408240082

--8408240085 Notice of violation from insp on 840529-0713
SHAFER,W D Region 3, Office of Director 84/07/24 1p 26237 025 24X Fiche 50-255,84/07/24,8408240082

--8408240088 IE Insp Rept 50-255/84-10 on 840529-0713 Noncompliance noted failure to document missing tags when performing engineered safeguards (iodine removal) & auxiliary feedwater sys checklists
WRIGHT,G C Region 3, Office of Director 84/07/24 8pp 26237 026 24X Fiche 50-255,84/07/24,8408240082

408150290 Forwards IE Insp Rept 50-255/84-13 on 840711-12 No noncompliance noted
LITTLE,W S Region 3, Office of Director 84/07/25 DEWITT,R B Consumers Power Co 2pp 26075 292 24X Fiche 50-255,84/07/25, 8408150290

--8408150293 IE Insp Rept 50-255/84-13 on 840711-12 No noncompliance noted Major areas inspected corrective action on LER re cables damaged due to excessively high temp
NOIBU,K R ; FALEVITS,Z ; WILLIAMS,C C Region 3, Office of Director 84/07/24 3pp 26075 294 24X Fiche 50-255,84/07/25, 8408150290

8408150299 Submits listed actions to be taken prior to commencing power operations due to RO on 840703 event re cables damaged by excessively high temp
KEPPLER,J G Region 3, Office of Director 84/07/13 DEWITT,R B Consumers Power Co 2pp 26075 297 24X Fiche 50-255,84/07/25, 8408150293

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New Inc 119pp 25865 047 24X Fiche:50-000,84/07/27,8407250229

8408310161 Forwards summary of primary coolant pump inservice insp results for 831216-840504
JOHNSON,B D Consumers Power Co 84/08/02 KEPPLER,J G Region 3, Office of Director 1p 26319 143 24X Fiche 50-255,84/08/02, 8408310161

--8408310165 Inservice insp rept for 831216-840504 All reportable indications re primary coolant pumps evaluated & dispositioned to accept as is
VAN WAGNER,B V ; BEACH,D L ; ESCH,H E Consumers Power Co 84/08/02 29pp 26319 144 24X Fiche 50-255,84/08/02,8408310161

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408310299 Forwards exam rept of exam administered on 840626-0701
WALKER,R D Region 3, Office of Director 84/08/15 DEWITT,R B Consumers Power Co 2pp 26333 222 24X Fiche 50-255,84/08/15, 8408310299

--8408310302 Exam rept administered on 840626-0701 Exam results eight candidates passed & two candidates failed
HIGGINS,R L ; STREIER,O ; WHITTEMORE,J Region 3, Office of Director 84/08/14 63pp 26333 224 24X Fiche 50-255,84/08/15, 8408310299

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408270273 Ack receipt of 840815 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-255/84-06
* Region 3, Office of Director 84/08/21 Consumers Power Co
1p 26241 018 24X Fiche 50-255,84/08/21,8408270273

--8408270281 Responds to NRC 840711 ltr re violations noted in Insp Rept 50-255/84-06 Corrective actions detailed radiological work plan developed,reliable underwater survey equipment procured & personnel failing to document surveys counseled
VANDEWALLE,D J Consumers Power Co 84/08/15 KEPPLER,J G
Region 3, Office of Director 6pp 26241 019 24X
Fiche 50-255,84/08/21,8408270273

8408300128 Forwards safety evaluation supporting licensee request for relief from inservice insp requirements Safety evaluation delineates items for which relief granted & alternate schedules & procedures defined
PAULSON,W A Operating Reactors Branch 5 84/08/23
VANDEWALLE,D J Consumers Power Co 3pp 26306 088 24X
Fiche 50-255,84/08/23,8408300128

--8408300132 Safety evaluation supporting licensee request for relief from inservice insp requirements
* Office of Nuclear Reactor Regulation, Director 84/08/23
11pp 26306 091 24X Fiche 50-255,84/08/23,8408300128

8408280002 Ack receipt of 840810 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-255/84-09 Supplemental response required within 30 days of ltr date
WALKER,R D Region 3, Office of Director 84/08/24 DEWITT,R B
Consumers Power Co 1p 26261 235 24X Fiche 50-255,84/08/24,
8408280002

--8408280003 Responds to NRC 840629 ltr re violations noted in Insp Rept 50-255/84-09 Corrective actions Tech Spec Surveillance Procedure RM-45 modified by acceptance criteria reflecting ASME requirements for mechanical snubber operability
BORDINE,T C Consumers Power Co 84/08/10 KEPPLER,J G Region 3, Office of Director 5pp 26261 236 24X Fiche 50-255, 84/08/24,8408280002

R Periodic operating reports & related correspondence

8408160255 Monthly operating rept for Jul 1984 W/840810 ltr
DIENES,A F , VAN DENBERG,D Consumers Power Co 84/07/31 5pp
26106 188 24X Fiche 50-255,84/07/31,8408160255

S Reportable occurrences, LERs & related correspondence

8408060263 LER 84-009-00 on 840628 & 29,test of seals of inner door of personnel air lock revealed leakage due to cracks in inner seal Caused by personnel calculation error Adjustments completed on seals W/840726 ltr
ROGERS,D W , JOHNSON,B D Consumers Power Co 84/07/26 4pp
25936 174 24X Fiche 50-255,84/07/26,8408060263

8408090398 LER 84-009-00 on 840704,spurious left channel safety injection signal actuation occurred Caused by inadequate procedure Procedure revised & personnel counseled W/840803 ltr
ROGERS,D W , FRISCH,R R Consumers Power Co 84/08/03 2pp
25993 273 24X Fiche 50-255,84/08/03,8408090398

8408160279 LER 84-010-00 on 840703,section of cable tray encl by fire barrier discovered hot to touch Insp found insulation on cables sustained damage due to excessive temp Caused by long-term thermal degradation Cable replaced W/840813 ltr
ROGERS,D W , JOHNSON,B D Consumers Power Co 84/08/13 1p
26106 164 24X Fiche 50-255,84/08/13,8408160279

8408200308 PNO-III-84-063 on 840810,unusual event declared due to leakage from primary coolant sys pressure sensing line isolation valve MV-1019A Weld cracked Piping & weld to be cut out & replaced Startup scheduled by 840816
WRIGHT,G , SHAFER,W Region 3, Office of Director 84/08/13 1p
26133 018 24X Fiche 50-255,84/08/13,8408200308

8408270127 LER 84-012-00 on 840725,unidentified primary coolant sys (AB) leakage greater than 1gpm discovered Caused by leakage past loopcheck valves into safety injection lines Check valves flushed to facilitate improved seating W/840820 ltr
ROGERS,D W , BORDINE,T C Consumers Power Co 84/08/20 2pp
26258 200 24X Fiche 50-255,84/08/20,8408270127

8408270130 LER 84-011-00 on 840719,while technicians calibr containment pressure switches,two spurious containment high pressure signals generated resulting in ESF actuations Caused by personnel error W/840820 ltr
ROGERS,D W , BORDINE,T C Consumers Power Co 84/08/20 3pp
26258 195 24X Fiche 50-255,84/08/20,8408270130

8408310056 LER 84-014-00 on 840728,w/reactor critical in hot standby condition,primary coolant temp dropped below 525 F Caused by personnel error Procedure revised W/840827 ltr
ROGERS,D W , JOHNSON,B D Consumers Power Co 84/08/27 3pp
26335 009 24X Fiche 50-255,84/08/27,8408310056

8408310059 LER 84-013-00 on 840727,results of daily leak rate calculation indicated unidentified primary coolant sys leakage greater than 1 gpm Caused by charging pump seal leak Pump repaired & procedures revised W/840827 ltr
ROGERS,D W , JOHNSON,B D Consumers Power Co 84/08/27 3pp
26334 235 24X Fiche 50-255,84/08/27,8408310059

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

8408170050 Confirms scheduling of operator/senior operator licensing exams for 841211-14 & 17-19 List of ref matl required & NRC administrative requirements encl
WALKER,R D Region 3, Office of Director 84/08/14 DEWITT,R B
Consumers Power Co 5pp 26119 089 24X Fiche 50-255,84/08/14, 8408170050

8408310299 Forwards exam rept of exam administered on 840626-0701
WALKER,R D Region 3, Office of Director 84/08/15 DEWITT,R B
Consumers Power Co 2pp 26333 222 24X Fiche 50-255,84/08/15, 8408310299

--8408310302 Exam rept administered on 840626-0701 Exam results eight candidates passed & two candidates failed
HIGGINS,R L , STREIER,G , WHITTEMORE,J Region 3, Office of Director 84/08/14 63pp 26333 224 24X Fiche 50-255,84/08/15, 8408310299

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408300402 Forwards summary of 840530 meeting w/TVA,Alabama Power Co, Florida Power Corp,Florida Power & Light & Georgia Power Co re selected emergency preparedness issues
O'REILLY,J P Region 2, Office of Director 84/06/08 PARRIS,H G
Tennessee Valley Authority 4pp 26308 116 24X
Fiche 50-000,84/06/08,8408300402

8408280096 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17
VERRELLI,D M Region 2, Office of Director 84/07/25 PARRIS,H G
Tennessee Valley Authority 1p 26281 319 24X
Fiche 50-259,84/07/25,8408280096

--8408280116 Responds to NRC 840607 ltr re violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 Corrective actions temporary fire load form posted & daily fire load insps performed until removal of combustibles
MILLS,L M Tennessee Valley Authority 84/07/09 O'REILLY,J P
Region 2, Office of Director 2pp 26281 320 24X
Fiche 50-259,84/07/25,8408280096

--8408280124 Forwards Insp Repts 50-259/84-17, 50-260/8
50-296/84-17 on 840508-11 & notice of violation
VERRELLI,D M, Region 2, Office of Director 84/0
PARRIS,H G Tennessee Valley Authority 2pp 26
Fiche 50-259,84/07/25,8408280096

--8408280134 Notice of violation from insp on 8
* Region 2, Office of Director 84/06/0
Fiche 50-259,84/07/25,8408280096

--8408280140 Insp Repts 50-259/84
840508-11 Violations noted fa
prevention procedures for con
MADDEN,P M Region 2, Office
26281 325 24X Fiche 50-259,

8408020145 Forwards revs to imple
of IP-6, "Activation of Technic
"Technical Support Ctr Operatio
Emergency Plan "
MILLS,L M Tennessee Valley Au
Region 2, Office of Director
Fiche 50-259,84/07/27,840802014

--8408020151 Revs to radiological emergency plan procedures, consisting of IP-6, "Activation of Technical Support Ctr" & IP-20, "Technical Support Ctr Operation "
* Tennessee Valley Authority 84/07/27 12pp 25886 012 24X Fiche 50-259, 84/07/27, 8408020145

--8408020156 Rev 14 to "Radiological Emergency Plan "
* Tennessee Valley Authority BFN-REP R14 84/06/29 4pp 25886 024 24X Fiche 50-259, 84/07/27, 8408020145

8408030015 Forwards safety analysis, implementation plan & implementation schedule for safety parameter display sys, per DB Vassallo 840612 confirmatory order to HG Parris
MILLS, L M Tennessee Valley Authority 84/07/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 25907 118 24X Fiche 50-259, 84/07/30, 8408030015

8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15
LEWIS, R C Region 2, Office of Director 84/08/13 PARRIS, H G
Tennessee Valley Authority 1p 26206 316 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Corrective actions total sys walkdown for control air sys flow diagrams performed by plant personnel
MILLS, L M Tennessee Valley Authority 84/08/01 O'REILLY, J P
Region 2, Office of Director 6pp 26206 318 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Corrective actions Std Practice 14 25 revised to require second party verification in hanging & removing clearance tags
MILLS, L M Tennessee Valley Authority 84/06/29 O'REILLY, J P
Region 2, Office of Director 11pp 26206 324 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230225 Notice of violation from insp on 840326-0425
* Region 2, Office of Director 84/05/23 5pp 26206 337 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230240 IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 on 840326-0425 Violations noted misaligned sys valves on control air compressor, incorrect valve on control air sys & inadequate fire protection surveillance procedures
PAULK, G L Region 2, Office of Director 84/09/17 14pp 26206 342 24X Fiche 50-259, 84/08/13, 8408230167

8408290245 Forwards justification which supplS 840612 schedular exemption request re fire protection mods
MILLS, L M Tennessee Valley Authority 84/08/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 26290 317 24X Fiche 50-259, 84/08/23, 8408290245

P Operating license stage documents & correspondence

8408300434 Confirms 840601 telcon between JA Coffey & RC Lewis re 840621 enforcement conference in Region II ofc to discuss design problems w/power supply & distribution sys Proposed agenda encl
O'REILLY, J P Region 2, Office of Director 84/06/05 PARRIS, H B
Tennessee Valley Authority 2pp 26314 328 24X
Fiche 50-259, 84/06/05, 8408300434

8408140026 Forwards requests for addl info re Mark I containment long-term program vent sys analysis & details of seismic lugs Recommends 840910 meeting w/BNL & Franklin Research Ctr to discuss response prior to submittal of formal response
VASSALLO, D B Operating Reactors Branch 2 84/07/26 PARRIS, H G
Tennessee Valley Authority 14pp 26061 245 24X
Fiche 50-259, 84/07/26, 8408140026

8408010344 Responds to 840613 request for addl info re Mark I containment long-term program analyses Safety relief valve discharge piping sys mods based on most severe reflood conditions predicted by RVRIZ & RVPDR codes
MILLS, L M Tennessee Valley Authority 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp, 25866-322 24X Fiche 50-259, 84/07/27, 8408010344

8408130026 Forwards Amends 104 & 98 to Licenses DPR-33 & DPR-52, respectively & safety evaluation Amends change Tech Specs to delete surveillance requirements for Dampers FCO-150A & FCO-150C
CLARK, R J Operating Reactors Branch 2 84/07/27 PARRIS, H G
Tennessee Valley Authority 2pp 26038 329 24X
Fiche. 50-259, 84/07/27, 8408130026

--8408130032 Amends 104 & 98 to Licenses DPR-33 & DPR-52, respectively, changing Tech Specs to delete surveillance requirements for Dampers FCO-150A & FCO-150C
VASSALLO, D B Operating Reactors Branch 2 84/07/27 8pp 26038 331 24X Fiche 50-259, 84/07/27, 8408130026

--8408130037 Safety evaluation supporting Amends 104 & 98 to Licenses DPR-33 & DPR-52, respectively
* Office of Nuclear Reactor Regulation, Director 84/07/27 2pp 26038 339 24X Fiche 50-259, 84/07/27, 8408130026

8408150575 Responds to 830422 submittal of Tech Spec amends per TMI Item I A 1 3, "Limit Overtime" & Generic Ltr 83-02 Tech Spec change request, to ensure overtime controls implemented, required
VASSALLO, D B Operating Reactors Branch 2 84/07/27 PARRIS, H G
Tennessee Valley Authority 2pp 26080 353 24X
Fiche 50-259, 84/07/27, 8408150575

8408160155 Forwards SER on NUREG-0737, Item II K 3 22 re automatic switchover of RCIC sys suction Manual switchover of RCIC suction on low water level in condensate storage tank acceptable
VASSALLO, D B Operating Reactors Branch 2 84/07/27 PARRIS, H G
Tennessee Valley Authority 9pp 26126 154 24X
Fiche 50-259, 84/07/27, 8408160155

8408160424 Forwards Amends 105, 99 & 72 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends replace word "operator" w/ "reactor operator" to provide consistent nomenclature
CLARK, R J Operating Reactors Branch 2 84/07/30 PARRIS, H G
Tennessee Valley Authority 3pp 26126 229 24X
Fiche 50-259, 84/07/30, 8408160424

--8408160426 Amends 105, 99 & 72 to Licenses DPR-33, DPR-52 & DPR-68, respectively, replacing word "operator" w/ "reactor operator" to provide consistent nomenclature & permitting fuel handling supervised by senior reactor operator
VASSALLO, D B Operating Reactors Branch 2 84/07/30 12pp 26126 232 24X Fiche 50-259, 84/07/30, 8408160424

--8408160427 Safety evaluation supporting Amends 105, 99 & 72 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 84/07/30 2pp 26126 244 24X Fiche 50-259, 84/07/30, 8408160424

8408060021 Application for amend to License DPR-33, changing Tech Specs to allow operation w/flow control valve 84-88 (containment atmosphere dilution supply to torus for Sys A) inoperable until next cold shutdown Fee encl
MILLS, L M Tennessee Valley Authority 84/07/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 25923 049 24X Fiche 50-259, 84/07/31, 8408060021

--8408060029 Proposed changes to Tech Specs 3 7 & 4 7 to permit operation w/flow control valve 84-88 (containment atmosphere dilution supply to torus for Sys A) inoperable until next cold shutdown
* Tennessee Valley Authority 84/07/31 7pp 25923 052 24X Fiche 50-259, 84/07/31, 8408060021

8408070370 Suppl 1 to 831027 application for amend to Licenses DPR-33, DPR-52 & DPR-68, consisting of minor revs to Tech Specs in response to NRC 831220 comments & request for addl info
MILLS, L M Tennessee Valley Authority 84/08/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 25947 176 24X Fiche 50-259, 84/08/01, 8408070370

--8408070375 Proposed Tech Spec re radioactive gaseous effluent instrumentation surveillance
* Tennessee Valley Authority 84/08/01 44pp 25947 178 24X Fiche 50-259, 84/08/01, 8408070370

8408200264 Forwards Amends 106, 100 & 73 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends clarify correct operating positions & identify proper action for initiating signal for suppression chamber drain valves
CLARK, R J Operating Reactors Branch 2 84/08/02 PARRIS, H G
Tennessee Valley Authority 2pp 26142 345 24X
Fiche 50-259, 84/08/02, 8408200264

--8408200269 Amends 106, 100 & 73 to Licenses DPR-33, DPR-52 & DPR-68, respectively Amends change Tech Specs re suppression chamber drain valves, clarify operating positions & identify proper action in initiating signal
VASSALLO, D B Operating Reactors Branch 2 84/08/02 12pp 26142 347 24X Fiche. 50-259, 84/08/02, 8408200264

--8408200280 Safety evaluation supporting Amends 106, 100 & 73 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/02 2pp 26142 359 24X Fiche 50-259, 84/08/02, 8408200264

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140375 Forwards response to NRC 831012 request for addl info re reactor protection sys power monitoring sys design mods Tech Specs will be submitted in future W/12 oversize drawings Aperture cards available in PDR
DOMER, J A Tennessee Valley Authority 84/08/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp 26051 187
24X Fiche 50-259, 84/08/09, 8408140375

8408210003 Forwards Amends 107, 101 & 74 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends change Tech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed
CLARK, R J Operating Reactors Branch 2 84/08/09 PARRIS, H G
Tennessee Valley Authority 2pp 26195 194 24X
Fiche 50-259, 84/08/09, 8408210003

--8408210004 Amends 107, 101 & 74 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed
VASSALLO, D B Operating Reactors Branch 2 84/08/09 12pp
26195 196 24X Fiche 50-259, 84/08/09, 8408210003

--8408210007 Safety evaluation supporting Amends 107, 101 & 74 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/09 5pp
26195 208 24X Fiche 50-259, 84/08/09, 8408210003

8408200131 Forwards response to 840501 ltr re Criteria 1, 2, 10 & 11 for permanent post-accident sampling facility Info on interim sys submitted on 840606
DOMER, J A Tennessee Valley Authority 84/08/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 26133 255
24X Fiche 50-259, 84/08/13, 8408200131

8408220137 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, incorporating integrated schedule into license Detailed explanation of methodology utilized, definition of revised integrated schedule & fee encl
MILLS, L M Tennessee Valley Authority 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 86pp 26193 318
24X Fiche 50-259, 84/08/14, 8408220137

8408280257 Forwards Amends 110, 103 & 76 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends revise Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & maint
CLARK, R J Operating Reactors Branch 2 84/08/15 PARRIS, H G
Tennessee Valley Authority 2pp 26294 090 24X
Fiche 50-259, 84/08/15, 8408280257

--8408280261 Amends 110, 103 & 76 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & maint purposes
VASSALLO, D B Operating Reactors Branch 2 84/08/15 15pp
26294 092 24X Fiche 50-259, 84/08/15, 8408280257

--8408280276 Safety evaluation supporting Amends 110, 103 & 76 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/15 2pp
26294 107 24X Fiche 50-259, 84/08/15, 8408280257

8408290282 Forwards Amend 109 to License DPR-33 & safety evaluation Amend revises Tech Specs to temporarily permit Train A of containment air dilution sys to be considered operable w/ Valve FCV-84-88 inoperable
CLARK, R J Operating Reactors Branch 2 84/08/15 PARRIS, H G
Tennessee Valley Authority 2pp 26312 320 24X
Fiche 50-259, 84/08/15, 8408290282

--8408290287 Amend 109 to License DPR-33, changing Tech Specs to temporarily permit Train A of containment air dilution sys to be considered operable w/Valve FCV-84-88 inoperable
VASSALLO, D B Operating Reactors Branch 2 84/08/15 4pp
26312 322 24X Fiche 50-259, 84/08/15, 8408290282

--8408290292 Safety evaluation supporting Amend 109 to License DPR-33
* Office of Nuclear Reactor Regulation, Director 84/08/15 5pp
26312 326 24X Fiche 50-259, 84/08/15, 8408290282

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310414 Notification of 840913 meeting w/util & Franklin Research Ctr in Knoxville, TN to discuss resolution of issues identified in request for addl info on structural evaluation in plant-unique analysis rept re Mark I torus mod
CLARK, R J Operating Reactors Branch 2 84/08/24 VASSALLO, D B
Operating Reactors Branch 2 1p 26350 222 24X
Fiche 50-259, 84/08/24, 8408310414

8408310420 Notification of 840905 meeting w/util & BNL in Knoxville, TN to discuss resolution of issues identified in staff request for addl info on hydrodynamic loads in plant-unique analysis rept re Mark I torus mods
CLARK, R J Operating Reactors Branch 2 84/08/24 VASSALLO, D B
Operating Reactors Branch 2 1p 26350 215 24X
Fiche 50-259, 84/08/24, 8408310420

G Inspection reports, IE Bulletins & correspondence

8407100322 Responds to 840605 ltr providing results of reanalysis of four walls Info resolves concerns re four walls identified in 840116 SER concerning IE Bulletin 83-11, "Masonry Wall Design "
VASSALLO, D B Operating Reactors Branch 2 84/06/26 PARRIS, H G
Tennessee Valley Authority 2pp 25513 317 24X
Fiche 50-259, 84/06/26, 8407100322

8408310109 Forwards Enforcement Conference Repts 50-259/84-21, 50-260/84-21 & 50-296/84-21 on 840621
O'REILLY, J P Region 2, Office of Director 84/07/09 PARRIS, H G
Tennessee Valley Authority 2pp 26334 227 24X
Fiche 50-259, 84/07/09, 8408310109

--8408310114 Enforcement Conference Repts 50-259/84-21, 50-260/84-21 & 50-296/84-21 on 840621 Major areas discussed design errors associated w/separation of electrical cables, paralleling diesel generators & shutdown board room cooling
BUTCHER, R C Region 2, Office of Director CANTRELL, F S
Division of Project & Resident Programs 84/07/05 6pp
26334 229 24X Fiche 50-259, 84/07/09, 8408310109

8408240338 Forwards Insp Repts 50-259/84-22, 50-260/84-22 & 50-296/84-22 on 840626-29 No violations or deviations noted
VERRELLI, D M Region 2, Office of Director 84/07/12 PARRIS, H G
Tennessee Valley Authority 2pp 26236 131 24X
Fiche 50-259, 84/07/12, 8408240338

--8408240342 Insp Repts 50-259/84-22, 50-260/84-22 & 50-296/84-22 on 840626-29 No violations or deviations noted Major areas inspected licensee action on previous enforcement matters, welding, inservice testing, IE bulletins & LERs
GIRARD, E H , BLAKE, J J Region 2, Office of Director 84/07/12
6pp 26236 133 24X Fiche 50-259, 84/07/12, 8408240338

8408280096 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17
VERRELLI, D M Region 2, Office of Director 84/07/25 PARRIS, H G
Tennessee Valley Authority 1p 26281 319 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280116 Responds to NRC 840607 ltr re violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 Corrective actions temporary fire load form posted & daily fire load insps performed until removal of combustibles
MILLS, L M Tennessee Valley Authority 84/07/09 O'REILLY, J P
Region 2, Office of Director 2pp 26281 320 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280124 Forwards Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 & notice of violation.
VERRELLI, D M Region 2, Office of Director 84/06/07
PARRIS, H G Tennessee Valley Authority 2pp 26281 322 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280134 Notice of violation from insp on 840508-11
* Region 2, Office of Director 84/06/07 1p 26281 324. 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280140 Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 Violations noted failure to follow fire prevention procedures for control of temporary fire loads
MADDEN, P M , MILLER, W H , CONLON, T E Region 2, Office of Director 84/06/01 9pp 26281 325 24X Fiche 50-259, 84/07/25, 8408280096

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408270196 Ack receipt of 840719 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-10, 50-260/84-10 & 50-296/84-10
VERRELLI,D M Region 2, Office of Director 84/07/31 PARRIS,H G Tennessee Valley Authority 1p 26257 352 24X
Fiche 50-259,84/07/31,8408270196

--8408270199 Responds to NRC 840509 ltr re violations noted in Insp Repts 50-259/84-10,50-260/84-10 & 50-296/84-10 Corrective actions Procedures 1053 & 1053A revised to correct procedural violations
MILLS,L M Tennessee Valley Authority 84/07/19 O'REILLY,J P Region 2, Office of Director 2pp 26257 353 24X
Fiche 50-259,84/07/31,8408270196

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche,50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15
LEWIS,R C Region 2, Office of Director 84/08/13 PARRIS,H G Tennessee Valley Authority 1p 26206 316 24X
Fiche 50-259,84/08/13,8408230167

--8408230180 Ack receipt of 840629 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Supplemental response expected by 840801
LEWIS,R C Region 2, Office of Director 84/07/12 PARRIS,H G Tennessee Valley Authority 1p 26206 317 24X
Fiche 50-259,84/08/13,8408230167

-8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp Repts 50-259/84-15,50-260/84-15 & 50-296/84-15 Corrective actions total sys walkdown for control air sys flow diagrams performed by plant personnel
MILLS,L M Tennessee Valley Authority 84/08/01 O'REILLY,J P Region 2, Office of Director 6pp 26206-318 24X
Fiche 50-259,84/08/13,8408230167

--8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-15,50-260/84-15 & 50-296/84-15 Corrective actions Std Practice 14 25 revised to require second party verification in hanging & removing clearance tags
MILLS,L M Tennessee Valley Authority 84/06/29 O'REILLY,J P, Region 2, Office of Director 11pp 26206-324 24X
Fiche 50-259,84/08/13,8408230167

--8408230219 Forwards IE Insp Repts 50-259/84-15,50-260/84-15 & 50-296/84-15 on 840326-0425 & notice of violations Addl attention must be given to Tech Spec maint
LEWIS,R C Region 2, Office of Director 84/05/23 PARRIS,H G Tennessee Valley Authority 2pp 26206 335 24X
Fiche 50-259,84/08/13,8408230167

--8408230225 Notice of violation from insp on 840326-0425
* Region 2, Office of Director 84/05/23 5pp 26206 337 24X
Fiche 50-259,84/08/13,8408230167

--8408230240 IE Insp Repts 50-259/84-15,50-260/84-15 & 50-296/84-15 on 840326-0425 Violations noted misaligned sys valves on control air compressor, incorrect valve on control air sys & inadequate fire protection surveillance procedures
PAULK,G L , PATTERSON,C A , CANTRELL,F S Region 2, Office of Director 84/05/17 14pp 26206 342 24X Fiche 50-259,84/08/13, 8408230167

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408240109 Forwards response to NRC 840720 ltr re violations noted in listed insp repts & Proposed Civil Penalty Action EA 84-025 Corrective actions include rev to Plant Instruction TI-74 to upgrade post-trip review Civil penalty fee will be wired
DOMER,J A Tennessee Valley Authority 84/08/20 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 10pp 26228 233 24X Fiche 50-259,84/08/20,8408240109

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408060098 "NPDES Discharge Monitoring Rept for Apr 1984 "
* Tennessee Valley Authority 84/04/30 54pp 25935 208 24X
Fiche 50-259,84/04/30,8408060098

8408270366 Forwards "Effluent & Waste Disposal Semiannual Rept, Supplemental Info,First Half 1984" & revised "Effluent & Waste Disposal Semiannual Rept Liquid Releases for Second Half 1983 Batch Mode "
JONES,O T Tennessee Valley Authority 84/08/21 Director's Office, Office of Inspection and Enforcement 1p 26240 320 24X
Fiche 50-259,84/08/21,8408270366

--8408270369 "Effluent & Waste Disposal Semiannual Rept Supplemental Info,First Half 1984 "
* Tennessee Valley Authority 84/06/30 15pp 26240 321 24X
Fiche 50-259,84/08/21,8408270366

--8408270374 Revised "Effluent & Waste Disposal Semiannual Rept Liquid Releases for Second Half 1983 Batch Mode "
* Tennessee Valley Authority 83/12/31 1p 26240 336 24X
Fiche 50-259,84/08/21,8408270366

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,G O General Electric Co 84/04/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348.

8408090341 LER 83-016/03X-2 on 830309, analysis of charcoal sample from control room emergency ventilation sys showed methyl iodide removal efficiency of less than 90% Caused by degradation of stored charcoal prior to use W/840713 ltr
CLARK, J R , JONES, G T Tennessee Valley Authority 84/07/13
O'REILLY, J P Region 2, Office of Director 5pp 25994 059 24X
Fiche 50-259, 84/07/13, 8408090341

8408030257 Updated LER 84-022-01 on 840212, investigation determined that single failure or LOCA & loss of offsite power could cause equipment necessary for electrical board room cooling to be lost Caused by design oversight W/840720 ltr
WALKER, J B , JONES, G T Tennessee Valley Authority 84/07/20 3pp
25917 241 24X Fiche 50-259, 84/07/20, 8408030257

8408060113 LER 84-027-00 on 840627, during startup & at 1% power & rated pressure, main steam relief valve began to unseat, causing torus temp to approach limits Unit manually scrammed Cause unstated Valve replaced & unit restarted W/840724 ltr
SMITH, D L , JONES, G T Tennessee Valley Authority 84/07/24 3pp
25936 030 24X Fiche 50-259, 84/07/24, 8408060113

8408080518 LER 84-023-01 on 840518, during replacement of failed relay 16AK20, adjacent internal panel wire supplying power to primary containment isolation valves came loose Caused by wire incorrectly terminated W/840727 ltr
SMITH, D L , JONES, G T Tennessee Valley Authority 84/07/27 3pp
25975 269 24X Fiche 50-259, 84/07/27, 8408080518

8408090020 Updated LER 83-018/03I-2 on 830325, while performing SI 4 2 A-13, standby gas train B found inoperable Caused by erratic McDonnel & Miller flow switch Switch replaced & SI 4 7 B-1 & SI 4 7 A-13 completed W/840727 ltr
CARTER, S , JONES, G T Tennessee Valley Authority 84/07/27 3pp
25993 247 24X Fiche 50-259, 84/07/27, 8408090020

8408160508 LER 84-022-02 on 840512, IE Bulletin 79-01B investigation determined that single failure or LOCA & loss of offsite power could cause loss of electric board room cooling equipment Operating instructions revised W/840808 ltr
WALKER, J B , JONES, G T Tennessee Valley Authority 84/08/08 3pp
26107 357 24X Fiche 50-259, 84/08/08, 8408160508

8408160518 LER 84-021-01 on 840505, automatic depressurization sys relief valve cables not fully separated From nonautomatic depressurization sys relief valve cables Caused by design error Mods completed on 840524 W/840808 ltr
ROBERTS, W A , JONES, G T Tennessee Valley Authority 84/08/08
3pp 26107 361 24X Fiche 50-259, 84/08/08, 8408160518

8408160519 LER 84-028-00 on 840710, automatic discharge transfer logic for HPCI from discharging to condensate storage tanks to reactor vessel failed Caused by dirty contact on limit switch Contact cleaned W/840808 ltr
SMITH, D L , JONES, G T Tennessee Valley Authority 84/08/08 3pp
26108 024 24X Fiche 50-259, 84/08/08, 8408160519

8408140331 Requests approval of proposed Tech Spec 198 re failure of containment atmospheric dilution sys torus supply valve on 840717 Approval needed by 840817 to prevent forced shutdown
DOMER, J A Tennessee Valley Authority 84/08/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26042 353
24X Fiche 50-259, 84/08/09, 8408140331

8408200300 LER 84-026-01 on 840620, unidentified drywell leakage exceeded Tech Spec coolant leakage rate of 5 gpm Orderly shutdown initiated & unit manually scrammed at 59% power Seal replaced W/840810 ltr
ROBERTS, W A , JONES, G T Tennessee Valley Authority 84/08/10
3pp 26140 087 24X Fiche 50-259, 84/08/10, 8408200300

8408230040 PNO-II-84-049 on 840814, possible overpressurization of one core spray sys loop occurred Caused by backflow of primary coolant into loop because outboard isolation valve & inboard isolation check valve leaked
BUTCHER, R C , CANTRELL, F S Region 2, Office of Director 84/08/15
2pp 26204 018 24X Fiche 50-259, 84/08/15, 8408230040

8408280349 LER 84-029-00 on 840720, 24 h limiting condition for operation entered when ASME Section XI pump pressure criteria not met for four RHR svc water pumps Tech Spec flow met, but pumps declared inoperable W/840817 ltr
SMITH, D L , JONES, G T Tennessee Valley Authority 84/08/17, 3pp
26282 275 24X Fiche 50-259, 84/08/17, 8408280349

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers. Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000, 84/08/21, 8408310186

V Operator Examinations

8408310036 Confirmation of action ltr re 840521 telcon between RC Lewis & JA Coffey concerning results of operator exams conducted on 840323 Operators who failed exam prohibited from licensed duties until Sections 6 or 7 completed satisfactorily
O'REILLY, J P Region 2, Office of Director 84/05/23 PARRIS, H G
Tennessee Valley Authority 3pp 26335 020 24X
Fiche 50-259, 84/05/23, 8408310036

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8408300402 Forwards summary of 840530 meeting w/TVA, Alabama Power Co, Florida Power Corp, Florida Power & Light & Georgia Power Co re selected emergency preparedness issues
O'REILLY, J P Region 2, Office of Director 84/06/08 PARRIS, H G
Tennessee Valley Authority 4pp 26308 116 24X
Fiche 50-000, 84/06/08, 8408300402

8408280096 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17
VERRELLI, D M Region 2, Office of Director 84/07/25 PARRIS, H G
Tennessee Valley Authority 1p 26281 319 24X
Fiche 50-259, 84/07/25, 8408280096

---8408280116 Responds to NRC 840607 ltr re violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 Corrective actions, temporary fire load form posted & daily fire load insps performed until removal of combustibles
MILLS, L M Tennessee Valley Authority 84/07/09 O'REILLY, J P
Region 2, Office of Director 2pp 26281 320 24X
Fiche 50-259, 84/07/25, 8408280096

---8408280124 Forwards Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 & notice of violation
VERRELLI, D M Region 2, Office of Director 84/06/07
PARRIS, H G Tennessee Valley Authority 2pp 26281 322 24X
Fiche 50-259, 84/07/25, 8408280096

---8408280134 Notice of violation from insp on 840508-11
* Region 2, Office of Director 84/06/07 1p 26281 324 24X
Fiche 50-259, 84/07/25, 8408280096

---8408280140 Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 Violations noted failure to follow fire prevention procedures for control of temporary fire loads
MADDEN, P M Region 2, Office of Director 84/06/01 7pp
26281 325 24X Fiche 50-259, 84/07/25, 8408280096

8408020145 Forwards revs to implementing procedures document, consisting of IP-6, "Activation of Technical Support Ctr," IP-20, "Technical Support Ctr Operation" & Rev 14 to "Radiological Emergency Plan "
MILLS, L M Tennessee Valley Authority 84/07/27 O'REILLY, J P
Region 2, Office of Director 1p 25886 011 24X
Fiche 50-259, 84/07/27, 8408020145

---8408020151 Revs to radiological emergency plan procedures, consisting of IP-6, "Activation of Technical Support Ctr" & IP-20, "Technical Support Ctr Operation "
* Tennessee Valley Authority 84/07/27 1Rpp 25886 012 24X
Fiche 50-259, 84/07/27, 8408020145

---8408020156 Rev 14 to "Radiological Emergency Plan "
* Tennessee Valley Authority BFN-REP R14 84/06/29 4pp
25886 024 24X Fiche 50-259, 84/07/27, 8408020145

8408030015 Forwards safety analysis, implementation plan & implementation schedule for safety parameter display sys, per DB Vassallo 840612 confirmatory order to HQ Parris
MILLS, L M Tennessee Valley Authority 84/07/30 DENTON, H R,
Office of Nuclear Reactor Regulation, Director 6pp. 25907 118
24X Fiche 50-259, 84/07/30, 8408030015

8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15
LEWIS, R C Region 2, Office of Director 84/08/13 PARRIS, H G
Tennessee Valley Authority 1p 26206 316 24X
Fiche 50-259, 84/08/13, 8408230167

---8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15, Corrective actions: total sys walkdown for control air sys flow diagrams performed by plant personnel
MILLS, L M Tennessee Valley Authority 84/08/01, O'REILLY, J P
Region 2, Office of Director 6pp 26206 318 24X
Fiche 50-259, 84/08/13, 8408230167.

--8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Corrective actions Std Practice 14 25 revised to require second party verification in hanging & removing clearance tags
MILLS, L M Tennessee Valley Authority 84/06/29 O'REILLY, J P Region 2, Office of Director 11pp 26206 324 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230225 Notice of violation from insp on 840326-0425
* Region 2, Office of Director 84/05/23 5pp 26206 337 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230240 IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 on 840326-0425 Violations noted misaligned sys valves on control air compressor, incorrect valve on control air sys & inadequate fire protection surveillance procedures
PAULK, G L Region 2, Office of Director 84/05/17 14pp
26206 342 24X Fiche 50-259, 84/08/13, 8408230167

8408290245 Forwards justification which supplS 840612 schedular exemption request re fire protection mods
MILLS, L M Tennessee Valley Authority 84/08/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 26290 317
24X Fiche 50-259, 84/08/23, 8408290245

P Operating license stage documents & correspondence

8408300434 Confirms 840601 telcon between JA Coffey & RC Lewis re 840621 enforcement conference in Region II ofc to discuss design problems w/power supply & distribution sys Proposed agenda encl
O'REILLY, J P Region 2, Office of Director 84/06/05 PARRIS, H B
Tennessee Valley Authority 2pp 26314 328 24X
Fiche 50-259, 84/06/05, 8408300434

8408140026 Forwards requests for addl info re Mark I containment long-term program vent sys analysis & details of seismic lugs Recommends 840910 meeting w/BNL & Franklin Research Ctr to discuss response prior to submittal of formal response
VASSALLO, D B Operating Reactors Branch 2 84/07/26 PARRIS, H G
Tennessee Valley Authority 14pp 26061 245 24X
Fiche 50-259, 84/07/26, 8408140026

8408010344 Responds to 840613 request for addl info re Mark I containment long-term program analyses Safety relief valve discharge piping sys mods based on most severe reflood conditions predicted by RVRIZ & RVFDR codes
MILLS, L M Tennessee Valley Authority 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 25866 322
24X Fiche 50-259, 84/07/27, 8408010344

8408130026 Forwards Amends 104 & 98 to Licenses DPR-33 & DPR-52, respectively & safety evaluation Amends change Tech Specs to delete surveillance requirements for Dampers FCO-150A & FCO-150C
CLARK, R J Operating Reactors Branch 2 84/07/27 PARRIS, H G
Tennessee Valley Authority 2pp 26038 329 24X
Fiche 50-259, 84/07/27, 8408130026

--8408130032 Amends 104 & 98 to Licenses DPR-33 & DPR-52, respectively, changing Tech Specs to delete surveillance requirements for Dampers FCO-150A & FCO-150C
VASSALLO, D B Operating Reactors Branch 2 84/07/27 8pp
26038 331 24X Fiche 50-259, 84/07/27, 8408130026

8408130037 Safety evaluation supporting Amends 104 & 98 to Licenses DPR-33 & DPR-52, respectively
* Office of Nuclear Reactor Regulation, Director 84/07/27 2pp
26038 339 24X Fiche 50-259, 84/07/27, 8408130026

8408150575 Responds to 830422 submittal of Tech Spec amends per TMI Item I A 1 3, "Limit Overtime" & Generic Ltr 83-02 Tech Spec change request, to ensure overtime controls implemented, required
VASSALLO, D B Operating Reactors Branch 2 84/07/27 PARRIS, H G
Tennessee Valley Authority 2pp 26080 353 24X
Fiche 50-259, 84/07/27, 8408150575

8408160155 Forwards SER on NUREG-0737, Item II K 3 22 re automatic switchover of RCIC sys suction Manual switchover of RCIC suction on low water level in condensate storage tank acceptable
VASSALLO, D B Operating Reactors Branch 2 84/07/27 PARRIS, H G
Tennessee Valley Authority 9pp 26126 154 24X
Fiche 50-259, 84/07/27, 8408160155

8408160424 Forwards Amends 105, 99 & 72 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends replace word "operator" w/ "reactor operator" to provide consistent nomenclature
CLARK, R J Operating Reactors Branch 2 84/07/30 PARRIS, H G
Tennessee Valley Authority 3pp 26126 229 24X
Fiche 50-259, 84/07/30, 8408160424

--8408160426 Amends 105, 99 & 72 to Licenses DPR-33, DPR-52 & DPR-68, respectively, replacing word "operator" w/ "reactor operator" to provide consistent nomenclature & permitting fuel handling supervised by senior reactor operator
VASSALLO, D B Operating Reactors Branch 2 84/07/30 12pp
26126 232 24X Fiche 50-259, 84/07/30, 8408160424

--8408160427 Safety evaluation supporting Amends 105, 99 & 72 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 84/07/30 2pp
26126 244 24X Fiche 50-259, 84/07/30, 8408160424

8408070370 Suppl 1 to 831027 application for amend to Licenses DPR-33, DPR-52 & DPR-68, consisting of minor revs to Tech Specs in response to NRC 831220 comments & request for addl info
MILLS, L M Tennessee Valley Authority 84/08/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 25947 176
24X Fiche 50-259, 84/08/01, 8408070370

--8408070375 Proposed Tech Spec re radioactive gaseous effluent instrumentation surveillance
* Tennessee Valley Authority 84/08/01 44pp 25947 178 24X
Fiche 50-259, 84/08/01, 8408070370

8408200264 Forwards Amends 106, 100 & 73 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends clarify correct operating positions & identify proper action for initiating signal for suppression chamber drain valves
CLARK, R J Operating Reactors Branch 2 84/08/02 PARRIS, H G
Tennessee Valley Authority 2pp 26142 345 24X
Fiche 50-259, 84/08/02, 8408200264

--8408200269 Amends 106, 100 & 73 to Licenses DPR-33, DPR-52 & DPR-68, respectively Amends change Tech Specs re suppression chamber drain valves, clarify operating positions & identify proper action in initiating signal
VASSALLO, D B Operating Reactors Branch 2 84/08/02 12pp
26142 347 24X Fiche 50-259, 84/08/02, 8408200264

--8408200280 Safety evaluation supporting Amends 106, 100 & 73 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/02 2pp
26142 359 24X Fiche 50-259, 84/08/02, 8408200264

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140375 Forwards response to NRC 831012 request for addl info re reactor protection sys power monitoring sys design mods Tech Specs will be submitted in future W/12 oversize drawings Aperture cards available in PDR
DOMER, J A Tennessee Valley Authority 84/08/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp 26051 187
24X Fiche 50-259, 84/08/09, 8408140375

8408200390 Forwards notice of environ assessment & finding of no significant impact re 840402 application for exemption from requirements of 10CFR50, App J
VASSALLO, D B Operating Reactors Branch 2 84/08/09 PARRIS, H G
Tennessee Valley Authority 2pp 26141 210 24X
Fiche 50-260, 84/08/09, 8408200390

--8408200393 Notice of environ assessment & finding of no significant impact re 840725 exemption from requirements of 10CFR50, App J
VASSALLO, D B Operating Reactors Branch 2 84/08/09 3pp
26141 212 24X Fiche 50-260, 84/08/09, 8408200390

8408210003 Forwards Amends 107, 101 & 74 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends change Tech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed
CLARK, R J Operating Reactors Branch 2 84/08/09 PARRIS, H G
Tennessee Valley Authority 2pp 26195 194 24X
Fiche 50-259, 84/08/09, 8408210003

--8408210004 Amends 107, 101 & 74 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed
VASSALLO, D B Operating Reactors Branch 2 84/08/09 12pp
26195 196 24X Fiche 50-259, 84/08/09, 8408210003

--8408210007 Safety evaluation supporting Amends 107, 101 & 74 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/09 5pp
26195 208 24X Fiche 50-259, 84/08/09, 8408210003

8408200131 Forwards response to 840501 ltr re Criteria 1, 2, 10 & 11 for permanent post-accident sampling facility Info on interim sys submitted on 840606
DOMER, J A Tennessee Valley Authority 84/08/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 26133 255
24X Fiche 50-259, 84/08/13, 8408200131

8408200437 Forwards exemption to test interval requirements of App J to 10CFR50, in response to 840402 request Two-yr test interval for performing local leak rates extended to 840915 for components specified in exemption
VASSALLO, D B Operating Reactors Branch 2 84/08/13 PARRIS, H G
Tennessee Valley Authority 2pp 26144 329 24X
Fiche 50-260, 84/08/13, 8408200437

--8408200441 Exemption from test interval requirements of App J to 10CFR50 re local leak rate test interval for specified components
EISENHUT, D G Division of Licensing 84/08/13 Tennessee Valley Authority 7pp 26144 331 24X Fiche 50-260, 84/08/13, 8408200437

8408220137 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, incorporating integrated schedule into license Detailed explanation of methodology utilized, definition of revised integrated schedule & fee encl
MILLS, L M Tennessee Valley Authority 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 86pp 26193 318
24X Fiche 50-259, 84/08/14, 8408220137

8408280257 Forwards Amends 110, 103 & 76 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends revise Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & maint
CLARK, R J Operating Reactors Branch 2 84/08/15 PARRIS, H G
Tennessee Valley Authority 2pp 26294 090 24X
Fiche 50-259, 84/08/15, 8408280257

--8408280261 Amends 110, 103 & 76 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & maint purposes
VASSALLO, D B Operating Reactors Branch 2 84/08/15 15pp
26294 092 24X Fiche 50-259, 84/08/15, 8408280257

--8408280276 Safety evaluation supporting Amends 110, 103 & 76 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/15 2pp
26294 107 24X Fiche 50-259, 84/08/15, 8408280257

8408310424 Forwards Amends 104 & 77 to Licenses DPR-52 & DPR-68, respectively & safety evaluation Amends revise Tech Specs to change neutron flux trip setting adjustment factor
CLARK, R J Operating Reactors Branch 2 84/08/17 PARRIS, H G
Tennessee Valley Authority 2pp 26350 142 24X
Fiche 50-260, 84/08/17, 8408310424

--8408310431 Amends 104 & 77 to Licenses DPR-52 & DPR-68, respectively, revising Tech Specs to change neutron flux trip setting adjustment factor from limiting safety sys to limiting condition for operation w/6 h action statement
VASSALLO, D B Operating Reactors Branch 2 84/08/17 32pp
26350 144 24X Fiche 50-260, 84/08/17, 8408310424

--8408310432 Safety evaluation supporting Amends 104 & 77 to Licenses DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/17 2pp
26350 176 24X Fiche 50-260, 84/08/17, 8408310424

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408280220 Application for amend to License DPR-52, changing Tech Specs to accommodate Unit 2, Cycle 6 operation & reflecting plant mods to be performed during refueling outage
MILLS, L M Tennessee Valley Authority 84/08/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 26269 201
24X Fiche 50-260, 84/08/23, 8408280220

--8408280222 Proposed Tech Specs reflecting plant mods to be performed during refueling outage & changing Tech Specs to accommodate Unit 2, Cycle 6 operation
* Tennessee Valley Authority 84/08/23 53pp 26269 204 24X
Fiche 50-260, 84/08/23, 8408280220

--8408280226 'Reload Licensing Rept for Browns Ferry Unit 2, Cycle 6 " Determination of no significant hazards encl
* Tennessee Valley Authority TVA-RLR-002 84/07/31 38pp
26269 282 24X Fiche 50-260, 84/08/23, 8408280220

8408310414 Notification of 840913 meeting w/util & Franklin Research Ctr in Knoxville, TN to discuss resolution of issues identified in request for addl info on structural evaluation in plant-unique analysis rept re Mark I torus mod
CLARK, R J Operating Reactors Branch 2 84/08/24 VASSALLO, D B
Operating Reactors Branch 2 1p 26350 222 24X
Fiche 50-259, 84/08/24, 8408310414

8408310420 Notification of 840905 meeting w/util & BNL in Knoxville, TN to discuss resolution of issues identified in staff request for addl info on hydrodynamic loads in plant-unique analysis rept re Mark I torus mods
CLARK, R J Operating Reactors Branch 2 84/08/24 VASSALLO, D B
Operating Reactors Branch 2 1p 26350 215 24X
Fiche 50-259, 84/08/24, 8408310420

G Inspection reports, IE Bulletins & correspondence

8407100322 Responds to 840605 ltr providing results of reanalysis of four walls Info resolves concerns re four walls identified in 840116 SER concerning IE Bulletin 83-11, "Masonry Wall Design "
VASSALLO, D B Operating Reactors Branch 2 84/06/26 PARRIS, H G
Tennessee Valley Authority 2pp 25513 317 24X
Fiche 50-259, 84/06/26, 8407100322

8408310109 Forwards Enforcement Conference Repts 50-259/84-21, 50-260/84-21 & 50-296/84-21 on 840621
O'REILLY, J P Region 2, Office of Director 84/07/09 PARRIS, H G
Tennessee Valley Authority 2pp 26334 227 24X
Fiche 50-259, 84/07/09, 8408310109

--8408310114 Enforcement Conference Repts 50-259/84-21, 50-260/84-21 & 50-296/84-21 on 840621 Major areas discussed design errors associated w/separation of electrical cables, paralleling diesel generators & shutdown board room cooling
BUTCHER, R C Region 2, Office of Director CANTRELL, F S
Division of Project & Resident Programs 84/07/05 6pp
26334 229 24X Fiche 50-259, 84/07/09, 8408310109

8408240338 Forwards Insp Repts 50-259/84-22, 50-260/84-22 & 50-296/84-22 on 840626-29 No violations or deviations noted
VERRELLI, D M Region 2, Office of Director 84/07/12 PARRIS, H G
Tennessee Valley Authority 2pp 26236 131 24X
Fiche 50-259, 84/07/12, 8408240338

--8408240342 Insp Repts 50-259/84-22, 50-260/84-22 & 50-296/84-22 on 840626-29 No violations or deviations noted Major areas inspected licensee action on previous enforcement matters, welding, inservice testing, IE bulletins & LERs
GIRARD, E H , BLAKE, J J Region 2, Office of Director 84/07/12
6pp 26236 133 24X Fiche 50-259, 84/07/12, 8408240338

8408280096 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17
VERRELLI, D M Region 2, Office of Director 84/07/25 PARRIS, H G
Tennessee Valley Authority 1p 26281 319 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280116 Responds to NRC 840607 ltr re violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 Corrective actions temporary fire load form posted & daily fire load insps performed until removal of combustibles
MILLS, L M Tennessee Valley Authority 84/07/09 O'REILLY, J P
Region 2, Office of Director 2pp 26281 320 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280124 Forwards Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 & notice of violation
VERRELLI, D M Region 2, Office of Director 84/06/07
PARRIS, H G Tennessee Valley Authority 2pp 26281 322 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280134 Notice of Violation from insp on 840508-11
* Region 2, Office of Director, 84/06/07 1p 26281 324 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280140 Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 Violations noted failure to follow fire prevention procedures for control of temporary fire loads
MADDEN, P M , MILLER, W H , CONLON, T E Region 2, Office of Director 84/06/01 9pp, 26281 325 24X Fiche: 50-259, 84/07/25, 8408280096

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408270196 Ack receipt of 840719 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-10, 50-260/84-10 & 50-296/84-10
VERRELLI,D M Region 2, Office of Director 84/07/31 PARRIS,H G Tennessee Valley Authority 1p 26257 352 24X
Fiche 50-259,84/07/31,8408270196

--8408270199 Responds to NRC 840509 ltr re violations noted in Insp Repts 50-259/84-10, 50-260/84-10 & 50-296/84-10 Corrective actions Procedures 1053 & 1053A revised to correct procedural violations
MILLS,L M Tennessee Valley Authority 84/07/19 O'REILLY,J P Region 2, Office of Director 2pp 26257 353 24X
Fiche 50-259,84/07/31,8408270196

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 8pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26067 138 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 12pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12pp, 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 11pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15
LEWIS,R C Region 2, Office of Director 84/08/13 PARRIS,H G Tennessee Valley Authority 1p 26206 316 24X
Fiche 50-259,84/08/13,8408230167

--8408230180 Ack receipt of 840629 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Supplemental response expected by 840801
LEWIS,R C Region 2, Office of Director 84/07/12 PARRIS,H G Tennessee Valley Authority. 1p 26206 317 24X
Fiche 50-259,84/08/13,8408230167

-8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Corrective actions total sys walkdown for control air sys flow diagrams performed by plant personnel
MILLS,L M Tennessee Valley Authority 84/08/01 O'REILLY,J P Region 2, Office of Director 6pp 26206 318 24X
Fiche 50-259,84/08/13,8408230167

-8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Corrective actions Std Practice 14 25 revised to require second party verification in hanging & removing clearance tags
MILLS,L M Tennessee Valley Authority 84/06/29 O'REILLY,J P Region 2, Office of Director 11pp 26206 324 24X
Fiche 50-259,84/08/13,8408230167

--8408230219 Forwards IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 on 840326-0425 & notice of violations Addl attention must be given to Tech Spec maint
LEWIS,R C Region 2, Office of Director 84/05/23 PARRIS,H G Tennessee Valley Authority 2pp 26206 335 24X
Fiche 50-259,84/08/13,8408230167

--8408230225 Notice of violation from insp on 840326-0425 * Region 2, Office of Director 84/05/23 5pp 26206 337 24X
Fiche 50-259,84/08/13,8408230167

--8408230240 IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 on 840326-0425 Violations noted misaligned sys valves on control air compressor, incorrect valve on control air sys & inadequate fire protection surveillance procedures
PAULK,G L , PATTERSON,C A , CANTRELL,F S Region 2, Office of Director 84/05/17 14pp 26206 342 24X Fiche 50-259,84/08/13, 8408230167

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 10App 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 11Bpp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12Opp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12Zpp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408240109 Forwards response to NRC 840720 ltr re violations noted in listed insp repts & Proposed Civil Penalty Action EA 84-025 Corrective actions include rev to Plant Instruction TI-74 to upgrade post-trip review Civil penalty fee will be wired
DOMER,J A Tennessee Valley Authority 84/08/20 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 10pp 26228 233 24X Fiche 50-259,84/08/20,8408240109

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408060098 "NPDES Discharge Monitoring Rept for Apr 1984 "
* Tennessee Valley Authority 84/04/30 54pp 25935 208 24X
Fiche 50-259,84/04/30,8408060098

8408270366 Forwards "Effluent & Waste Disposal Semiannual Rept, Supplemental Info,First Half 1984" & revised "Effluent & Waste Disposal Semiannual Rept Liquid Releases for Second Half 1983 Batch Mode "
JONES,G T Tennessee Valley Authority 84/08/21 Director's Office, Office of Inspection and Enforcement 1p 26240 320 24X
Fiche 50-259,84/08/21,8408270366

--8408270369 "Effluent & Waste Disposal Semiannual Rept Supplemental Info,First Half 1984 "
* Tennessee Valley Authority 84/06/30 15pp 26240 321 24X
Fiche 50-259,84/08/21,8408270366

--8408270374 Revised "Effluent & Waste Disposal Semiannual Rept Liquid Releases for Second Half 1983 Batch Mode "
* Tennessee Valley Authority 83/12/31 1p 26240 336 24X
Fiche 50-259,84/08/21,8408270366

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL,D D Brown Boveri Corp. (subs of Brown Boveri & Co , Ltd) 84/03/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,Q G General Electric Co 84/04/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA,R General Electric Co 84/08/21 ROSSI,C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000,84/08/21,8408310186

V Operator Examinations

8408310036 Confirmation of action ltr re 840521 telcon between RC Lewis & JA Coffey concerning results of operator exams conducted on 840323 Operators who failed exam prohibited from licensed duties until Sections 6 or 7 completed satisfactorily
O'REILLY,J P Region 2, Office of Director 84/05/23 PARRIS,H G Tennessee Valley Authority 3pp 26335 020 24X
Fiche 50-259,84/05/23,8408310036

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408300361 Ack receipt of 840606 ltr re emergency exercise scheduled during wk of 840822 Final scenario & controller messages will be reviewed when received Comments will be made following evaluation of submittal
VERRELLI,D M Region 2, Office of Director 84/06/18 UTLEY,E E
Carolina Power & Light Co 1p 26308 213 24X
Fiche 50-261,84/06/18,8408300361

8408310411 Forwards summary of 840530 meeting re proposed 10CFR50 54(p) changes to industrial security plans & contractor screening program Meeting beneficial & provided better understanding between security staffs
LEWIS,R C Region 2, Office of Director 84/06/19 UTLEY,E E
Carolina Power & Light Co 3pp 26333 318 24X
Fiche 50-000,84/06/19,8408310411

8408240007 Forwards Insp Rept 50-261/84-21 on 840611-15 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 73 21)
VERRELLI,D M Region 2, Office of Director 84/07/10 UTLEY,E E
Carolina Power & Light Co 2pp 26228 249 24X
Fiche 50-261,84/07/10,8408240007

--8408240010 Insp Rept 50-261/84-21 on 840611-15 Violation identified failure to maintain security-related equipment in operable condition Details withheld (ref 10CFR2 790 & 73 21)
TILLMAN,A , MCGUIRE,D R Region 2, Office of Director 84/06/28
1p 26228 251 24X Fiche 50-261,84/07/10,8408240007

8408030094 Requests two technical exemptions from requirements of 10CFR50,App R,Section III G 3 per 10CFR50 12,re III G 3 suppression requirements for six plant fire areas & for suppression & detection for single fire area
CUTTER,A B Carolina Power & Light Co 84/07/20 VARGA,S A
Licensing Branch 1 8pp 25906 266 24X Fiche 50-261,84/07/20, 8408030094

8408030162 Requests withdrawal of 801202 license amend request re dedicated shutdown sys Implementation of sys concurrent w/ fire protection mods more appropriate Revised request will be submitted by 850329
CUTTER,A B Carolina Power & Light Co 84/07/20 VARGA,S A
Operating Reactors Branch 1 2pp, 25912 016 24X
Fiche 50-261,84/07/20,8408030162

8408060074 Advises that Amend 80 to License DPR-23 re relaxation of physical security requirements of 10CFR73 55 during steam generator repair outage,will not be implemented
ZIMMERMAN,S R Carolina Power & Light Co 84/07/30 VARGA,S A
Operating Reactors Branch 1 1p 25933 222 24X
Fiche 50-261,84/07/30,8408060074

8408310051 Advises that exercise scenario description & concurrence in scope & concept reviewed Detailed exercise package will be reviewed when received & comments provided
VERRELLI,D M Region 2, Office of Director 84/08/02 UTLEY,E E
Carolina Power & Light Co 1p 26334 358 24X
Fiche 50-261,84/08/02,8408310051

8408100004 Forwards Rev 5 to Emergency Plan & Procedure PEP-2004, "HB Robinson,Unit 2 Personnel," per 10CFR50 54(q) Listing of rev encl
MORGAN,R E Carolina Power & Light Co 84/08/07 O'REILLY,J P
Region 2, Office of Director 2pp 25986 357 24X
Fiche 50-261,84/08/07,8408100004

--8408100010 Rev 5 to Emergency Plan & Procedure PEP-2004, "HB Robinson, Unit 2 Personnel "
Carolina Power & Light Co 84/08/07 9pp 25986 359 24X
Fiche 50-261,84/08/07,8408100004

8408230073 Responds to 840427 request for exemption from App E to 10CFR50, to exclude state & local govt participation in 840821 annual emergency preparedness exercise Exemption not required in view of 840706 rev to App E to 10CFR50
VARGA,S A Operating Reactors Branch 1 84/08/15 UTLEY,E E
Carolina Power & Light Co 2pp 26233 269 24X
Fiche 50-261,84/08/15,8408230073

8408220126 Requests exemption from 10CFR50,App R,Section II G 2 to extent that Rockbestos cables inside containment be kept free of fire damage & provides addl technical info,per NRC request Fee encl
CUTTER,A B Carolina Power & Light Co 84/08/17 VARGA,S A
Operating Reactors Branch 1 7pp 26193 309 24X
Fiche 50-261,84/08/17,8408220126

8408300512 Forwards FR notice of environ assessment & finding of no significant impact re 820427,830607 & 840425 requests for exemption from 10CFR50,App R,to relax requirement for complete area-wide automatic fire suppression coverage
VARGA,S A Operating Reactors Branch 1 84/08/17 UTLEY,E E
Carolina Power & Light Co 3pp 26315 318 24X
Fiche 50-261,84/08/17,8408300512

--8408300515 Notice of environ assessment & finding of no significant impact re 820427,830607 & 840425 requests for exemption from 10CFR50,App R,to relax requirement for complete area-wide automatic fire suppression coverage
EISENHUT,D G Division of Licensing 84/08/17 3pp 26315 321
24X Fiche 50-261,84/08/17,8408300512

8408240091 Ack receipt of 840809 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-21
VERRELLI,D M Region 2, Office of Director 84/08/21 UTLEY,E E
Carolina Power & Light Co 1p 26228 246 24X
Fiche 50-261,84/08/21,8408240091

--8408240095 Forwards response NRC 840710 ltr re violations noted in Insp Rept 50-261/84-21 Response withheld (ref 10CFR2 790 & 73 21)
MORGAN,R E Carolina Power & Light Co 84/08/09 O'REILLY,J P
Region 2, Office of Director 1p 26228 247 24X
Fiche 50-261,84/08/21,8408240091

8408240316 Forwards SALP Repts 50-261/84-24,50-324/84-16,50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
LEWIS,R C Region 2, Office of Director 84/08/21 UTLEY,E E
Carolina Power & Light Co 2pp 26225 230 24X
Fiche 50-000,84/08/21,8408240316

--8408240319 SALP Repts 50-261/84-24,50-324/84-16,50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
Region 2, Office of Director 84/04/30 71pp 26225.232 24X
Fiche 50-000,84/08/21,8408240316

P Operating license stage documents & correspondence

8408090444 Notification of 840607 meeting w/util in Bethesda,MD to discuss status of Cycle 10 core reload review
REGUA,G Operating Reactors Branch 1 84/06/01, VARGA,S A
Operating Reactors Branch 1 3pp 25982 351 24X
Fiche 50-261,84/06/01,8408090444

8408030248 Informs that correct date of issuance of Amend 81 to License DPR-23 is 840628
REGUA,G Operating Reactors Branch 1 84/07/16 UTLEY,E E
Carolina Power & Light Co 2pp 25919 358 24X
Fiche,50-261,84/07/16,8408030248

8408030096 Application for amend to License DPR-23,revising Tech Specs re reactor vessel level instrumentation sys Revs will include instrumentation sys,per NUREG-0737 requirements
CUTTER,A B Carolina Power & Light Co 84/07/20 VARGA,S A
Operating Reactors Branch 1 2pp 25904 349 24X
Fiche 50-261,84/07/20,8408030096

--8408030100 Proposed Tech Specs re reactor vessel level instrumentation
Carolina Power & Light Co 84/07/20, 4pp 25904 351 24X
Fiche 50-261,84/07/20,8408030096

8408030162 Requests withdrawal of 801202 license amend request re dedicated shutdown sys Implementation of sys concurrent w/ fire protection mods more appropriate Revised request will be submitted by 850329
CUTTER,A B Carolina Power & Light Co 84/07/20 VARGA,S A
Operating Reactors Branch 1 2pp 25912.016 24X
Fiche 50-261,84/07/20,8408030162

8408030234 Submits integrated startup test plans for review, fulfilling requirement of Amend 77 to License DPR-23 Integrated startup test effort will demonstrate ability to safely return unit to operation
BEATTY, G P Carolina Power & Light Co 84/07/26 VARGA, S A
Operating Reactors Branch 1 13pp 25917 177 24X
Fiche 50-261, 84/07/26, 8408030234

8408080332 Responds to 840409 telcon & 840419 telecopy request for info on reactor trip breaker testing Periodic calibr & tests currently performed adequate Tech Spec changes unnecessary
ZIMMERMAN, S R Carolina Power & Light Co 84/07/27 VARGA, S A
Operating Reactors Branch 1 4pp 25964 105 24X
Fiche 50-261, 84/07/27, 8408080332

8408060074 Advises that Amend 80 to License DPR-23 re relaxation of physical security requirements of 10CFR73 55 during steam generator repair outage, will not be implemented
ZIMMERMAN, S R Carolina Power & Light Co 84/07/30 VARGA, S A
Operating Reactors Branch 1 1p 25933 222 24X
Fiche 50-261, 84/07/30, 8408060074

8408070374 Application for amend to License DPR-23, revising Tech Spec Section 3 6, "Containment Sys," to allow performance of CRD evolutions when containment integrity not intact while maintaining required level of safety
CUTTER, A B Carolina Power & Light Co 84/08/01 VARGA, S A
Operating Reactors Branch 1 3pp 25947 165 24X
Fiche 50-261, 84/08/01, 8408070374

--8408070378 Proposed revs to Tech Spec Section 3 6, "Containment Sys," for conduct of CRD evolutions when containment integrity not intact
* Carolina Power & Light Co 84/08/01 3pp 25947 168 24X
Fiche 50-261, 84/08/01, 8408070374

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408240309 Forwards preliminary neutronic parameters for steamline break analysis using RELAP5 Info developed assuming end-of-cycle core w/all control rod clusters, less most reactive control rod clusters
KILLGORE, M R Exxon Nuclear Co , Inc (subs of Exxon Corp) 84/08/07 GUTTMANN, J Reactor Systems Branch 6pp 26225 315 24X Fiche 50-261, 84/08/07, 8408240309

8408140356 Forwards Suppl 1 to Rev 2 to XN-NF-83-72, "HB Robinson, Unit 2, Cycle 10 SAR - Disposition of Chapter 15 Events " Rept provides confirmatory analyses results for SAR Remainder of analyses will be submitted by 840817
ZIMMERMAN, S R Carolina Power & Light Co 84/08/08 VARGA, S A
Operating Reactors Branch 1 2pp 26041 001 24X
Fiche: 50-261, 84/08/08, 8408140356

--8408140363 Suppl 1 to Rev 2 to "HB Robinson, Unit 2, Cycle 10 SAR - Disposition of Chapter 15 Events "
LEACH, C E , KAYSER, W V , CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp) XN-NF-83-72 SD1 R02 84/07/20 33pp 26041 003 24X Fiche 50-261, 84/08/08, 8408140356

8220094 Notification of 840827 meeting w/util in Bethesda, MD to iscuss Cycle 10 reload review & schedules
(EGUA, G Operating Reactors Branch 1 84/08/15 VARGA, S A
Operating Reactors Branch 1 2pp 26209.357 24X
Fiche 50-261, 84/08/15, 8408220094

8408220229 Requests that 840723 proposed Tech Spec revs for Cycle 10 operation receive expedited review & approval to support 840924 fuel load date
CUTTER, A B Carolina Power & Light Co 84/08/17 VARGA, S A
Operating Reactors Branch 1 1p 26194 080 24X
Fiche 50-261, 84/08/17, 8408220229

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408230093 Forwards XN-NF-84-72, Suppl 1, "Large Break LOCA-ECCS Analysis W/Increased Enthalpy Rise Factor Break Spectrum " Info submitted to suppl request for license amend for Cycle 10 operation
CUTTER, A B Carolina Power & Light Co 84/08/20 VARGA, S A
Operating Reactors Branch 1 2pp 26208 082 24X
Fiche 50-261, 84/08/20, 8408230093

--8408230103 "Large Break LOCA-ECCS Analysis W/Increased Enthalpy Rise Factor Break Spectrum "
TAHVILI, T , KAYSER, W V , CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp) XN-NF-84-72 SD1 84/08/31 102pp 26208 084 24X Fiche 50-261, 84/08/20, 8408230093

8408230117 Forwards XN-NF-84-74, "Plant Transient Analysis for HB Robinson Unit 2 at 2,300 MWt W/Increased FN(Delta)H "
CUTTER, A B Carolina Power & Light Co 84/08/20 VARGA, S A
Operating Reactors Branch 1 2pp 26208 187 24X
Fiche 50-261, 84/08/20, 8408230117

--8408230122 "Plant Transient Analysis for HB Robinson Unit 2 at 2,300 MWt W/Increased FN(Delta)H "
LEACH, C E , ADAMS, F T , KILLGORE, M R Exxon Nuclear Co , Inc (subs of Exxon Corp) XN-NF-84-74 84/08/16 200pp 26208 189 24X Fiche 50-261, 84/08/20, 8408230117

8408280199 Documents closeout of several issues raised by NRC during review of responses to requirements of Generic Ltr 81-14, "Seismic Qualification of Auxiliary Feedwater Sys " Any mods will be made per Generic Issue A-46
ZIMMERMAN, S R Carolina Power & Light Co 84/08/23 VARGA, S A
Operating Reactors Branch 1 1p 26275 362 24X
Fiche 50-261, 84/08/23, 8408280199

8408290011 Forwards fee for 840723 application for license amend, in response to 840810 request
ZIMMERMAN, S R Carolina Power & Light Co 84/08/23 MILLER, W O
License Fee Management Branch 1p 26291 281 24X
Fiche 50-261, 84/08/23, 8408290011

G Inspection reports, IE Bulletins & correspondence

8408280133 Provides updated schedule for completion of IE Bulletins 79-02 & 79-14 Due to increase in scope of project following thorough third party review, projected completion of insp & as-built documentation scheduled for 841030
MORGAN, R E Carolina Power & Light Co 84/08/29 O'REILLY, J P
Region 2, Office of Director 1p 26275 145 24X
Fiche 50-261, 84/08/29, 8408280133

8408240007 Forwards Insp Rept 50-261/84-21 on 840611-15 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 73 21)
VERRELLI, D M Region 2, Office of Director 84/07/10 UTLEY, E E
Carolina Power & Light Co 2pp 26228 249 24X
Fiche 50-261, 84/07/10, 8408240007

--8408240010 Insp Rept 50-261/84-21 on 840611-15 Violation identified failure to maintain security-related equipment in operable condition Details withheld (ref 10CFR2 790 & 73 21)
TILLMAN, A , MCGUIRE, D R Region 2, Office of Director 84/06/28 1p 26228 251 24X Fiche 50-261, 84/07/10, 8408240007

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408270513 Ack receipt of 840719 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-19
LEWIS, R C Region 2, Office of Director 84/07/30 UTLEY, E E
Carolina Power & Light Co 1p 26256 143 24X
Fiche 50-261, 84/07/30, 8408270513

--8408270521 Responds to NRC 840619 ltr re violations noted in Insp Rept 50-261/84-19 Corrective actions regulatory compliance instruction for preparing correspondence implemented & investigation of circuit conducted to identify occurrence
MORGAN, R E Carolina Power & Light Co 84/07/19 O'REILLY, J P
Region 2, Office of Director 3pp 26256 144 24X
Fiche 50-261, 84/07/30, 8408270513

--8408270528 Forwards Insp Rept 50-261/84-19 on 840511-0610 & notice of violation
LEWIS, R C Region 2, Office of Director 84/06/19 UTLEY, E E
Carolina Power & Light Co 2pp 26256 147 24X
Fiche 50-261, 84/07/30, 8408270513

--8408270530 Notice of violation from insp on 840511-0610
* Region 2, Office of Director 84/06/19 2pp 26256 149 24X
Fiche 50-261, 84/07/30, 8408270513

--8408270536 Insp Rept 50-261/84-19 on 840511-0610 Violations noted failure to implement procedures, failure to adequately establish surveillance procedures & inaccurate statement in LER.
WEISE, S , GARNER, L , BEMIS, P R Region 2, Office of Director 84/06/18 11pp 26256 151 24X Fiche 50-261, 84/07/30, 8408270513

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408280027 Ack receipt of 840726 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-22
VERRELLI,D M Region 2, Office of Director 84/08/07 UTLEY,E E
Carolina Power & Light Co 1p 26281 350 24X
Fiche 50-261,84/08/07,8408280027

--8408280035 Responds to NRC 840629 ltr re violations noted in Insp Rept 50-261/84-22 Corrective actions post-weld heat treatment contractor marked all thermocouple locations adjacent to thermocouples prior to grinding
MORGAN,R E Carolina Power & Light Co 84/07/26 O'REILLY,J P
Region 2, Office of Director 2pp 26281 351 24X
Fiche 50-261,84/08/07,8408280027

--8408280039 Forwards Insp Rept 50-261/84-22 on 840612-15 & notice of violation
VERRELLI,D M Region 2, Office of Director 84/08/29 UTLEY,E E
Carolina Power & Light Co 2pp 26281 353 24X
Fiche 50-261,84/08/07,8408280027

--8408280042 Notice of violation from insp on 840612-15
* Region 2, Office of Director 84/08/29 1p 26281 355 24X
Fiche 50-261,84/08/07,8408280027

--8408280046 Insp Rept 50-261/84-22 on 840612-15 Violation noted failure to follow temporary attachment procedure
KLEINSORGE,W P , BLAKE,J J Region 2, Office of Director
84/08/27 15pp 26281 356 24X Fiche 50-261,84/08/07,8408280027

8408290021 Ack receipt of 840608 & 0724 ltrs informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-11
VERRELLI,D M Region 2, Office of Director 84/08/07 UTLEY,E E
Carolina Power & Light Co 1p 26298 020 24X
Fiche 50-261,84/08/07,8408290021

--8408290025 Responds to NRC 840510 ltr re violations noted in Insp Rept 50-261/84-11 Corrective actions conservative changes made to WP-502 in Rev 11 & coated electrodes not issued in portable rod caddie destroyed regardless of exposure time
MORGAN,R E Carolina Power & Light Co 84/07/24 O'REILLY,J P
Region 2, Office of Director 2pp 26298 021 24X
Fiche 50-261,84/08/07,8408290021

--8408290028 Responds to violations noted in Insp Rept 50-261/84-11 Violation denied Conservative changes made to WP-502 in Rev 11 & coated electrodes not issued in portable rod caddie will be destroyed regardless of exposure time
MORGAN,R E Carolina Power & Light Co 84/06/08 O'REILLY,J P
Region 2, Office of Director 2pp 26298 023 24X
Fiche 50-261,84/08/07,8408290021

--8408290031 Ack receipt of 840608 response denying violations noted in Insp Rept 50-261/84-11 NRC concluded violation did occur Corrective actions requested within 30 days of ltr date
LEWIS,R C Region 2, Office of Director 84/06/29 UTLEY,E E
Carolina Power & Light Co 2pp 26298 025 24X
Fiche 50-261,84/08/07,8408290021

--8408290034 Forwards Insp Rept 50-261/84-11 on 840410-13 & notice of violation
VERRELLI,D M Region 2, Office of Director 84/05/10 UTLEY,E E
Carolina Power & Light Co 2pp 26298 027 24X
Fiche 50-261,84/08/07,8408290021

--8408290035 Notice of violation from insp on 840410-13
* Region 2, Office of Director 84/05/10 2pp 26298 029 24X
Fiche 50-261,84/08/07,8408290021

--8408290039 Insp Rept 50-261/84-11 on 840410-13 Violation noted procedure inadequate for segregation of weld rods w/exposure time
COLEY,J L , BLAKE,J J Region 2, Office of Director 84/05/09,
10pp 26298 031 24X Fiche 50-261,84/08/07,8408290021

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408240091 Ack receipt of 840809 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-261/84-21
VERRELLI,D M Region 2, Office of Director, 84/08/21 UTLEY,E E
Carolina Power & Light Co 1p 26228 246 24X
Fiche 50-261,84/08/21,8408240091

--8408240095 Forwards response NRC 840710 ltr re violations noted in Insp Rept 50-261/84-21 Response withheld (ref 10CFR2 790 & 73 21)
MORGAN,R E Carolina Power & Light Co 84/08/09 O'REILLY,J P
Region 2, Office of Director 1p 26228 247 24X
Fiche 50-261,84/08/21,8408240091

8408240316 Forwards SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
LEWIS,R C Region 2, Office of Director 84/08/21 UTLEY,E E
Carolina Power & Light Co 2pp 26225 230 24X
Fiche 50-000,84/08/21,8408240316

--8408240319 SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
* Region 2, Office of Director 84/04/30 71pp 26225 232 24X
Fiche 50-000,84/08/21,8408240316

8408300146 EN-84-009A notice of violation & proposed imposition of civil penalty in amount of $30,000 issued re failure to follow procedures for entry into locked high radiation area
FLACK,E , AXELRAD,J Director's Office, Office of Inspection and Enforcement 84/08/28 1p 26304 357 24X Fiche 50-261,84/08/28,
8408300146

R Periodic operating reports & related correspondence

8408160144 Monthly operating rept for Jul 1984 W/840809 ltr.
SCOTT,A E , MORGAN,R E Carolina Power & Light Co 84/07/31,
DEYOUNG,R Director's Office, Office of Inspection and Enforcement
4pp 26108 071 24X Fiche 50-261,84/07/31,8408160144.

S Reportable occurrences, LERs & related correspondence

8408060315 LER 84-008-00 on 840626,condensate storage tank level transmitters LT-1454A & B identified as out of calibr Caused by physical jarring Transmitters recalibr W/840726 ltr
WRIGHT,C.L , MORGAN,R E Carolina Power & Light Co 84/07/26, 3pp.
25936 089 24X Fiche 50-261,84/07/26,8408060315

8408170188 LER 84-009-00 on 840709, w/unit in shutdown, during annual containment pressure channel calibr, review of as found data revealed nonlinear error over range of instruments Caused by personnel error in test equipment setup W/840809 ltr
WRIGHT, C L , MORGAN, R E Carolina Power & Light Co 84/08/09 3pp 26130 028 24X Fiche 50-261, 84/08/09, 8408170188

V Operator Examinations

8408310014 Confirms 840605 telcon re 840612 mgt meeting in Region II ofcs to discuss upcoming operator exams & requalification of licensed operators following steam generator outage
O'REILLY, J P Region 2, Office of Director 84/06/08 UTLEY, E E
Carolina Power & Light Co 1p 26333 357 24X
Fiche 50-000, 84/06/08, 8408310014

DOCKET 50-262 BRIGHAM YOUND UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/08/16, Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche: 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E.L Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/08/21 Consolidated Edison Co of New York, Inc 115pp, 26329, 008 24X Fiche 50-000, 84/08/21, 8408210142

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

8408080171 Forwards IE Insp Rept 50-263/84-11 on 840521-25 & notice of deviation
SPESSARD, R L Region 3, Office of Director 84/07/20 LARSON, C E
Northern States Power Co 2pp 25974 278 24X
Fiche 50-263, 84/07/20, 8408080171

--8408080174 Notice of deviation from insp on 840521-25
SPESSARD, R L Region 3, Office of Director 84/07/20 1p
25974 280 24X Fiche 50-263, 84/07/20, 8408080171

--8408080181 IE Insp Rept 50-263/84-11 on 840521-25 Deviation noted failure of fire detection sys to provide permanent record of signals sent to central supervising station
ULIE, J M , GULDEMOND, W G Region 3, Office of Director 84/07/20
19pp 25974 281 24X Fiche 50-263, 84/07/20, 8408080171

8408090011 Forwards "Procedures Generation Package," as identified in Generic Ltr 82-33 & Commission 840612 order confirming licensee commitments
MUSOLF, D Northern States Power Co 84/07/31 Office of Nuclear Reactor Regulation, Director 1p 25972 300 24X
Fiche 50-263, 84/07/31, 8408090011

--8408090014 "Procedures Generation Package "
* Northern States Power Co 84/07/31 66pp 25972 331 24X
Fiche 50-263, 84/07/31, 8408090011

8408160169 Rev 4 to emergency plan W/transmittal & receipt forms
MATHIASE, C D , WILLIAMS, G Northern States Power Co 84/08/01
100pp 26091 259 24X Fiche 50-263, 84/08/01, 8408160169

8408300176 Forwards Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan " Rev includes changes resulting from annual internal review, update & certification of emergency plans & agreements
FEY, F L Northern States Power Co 84/08/02 Region 3, Office of Director 4pp 26302 106 24X Fiche 50-000, 84/08/02, 8408300176

--8408300180 Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan "
HUDSON, G , FEY, F L , LARSON, C E Northern States Power Co
84/08/02 116pp 26302.110 24X Fiche 50-000, 84/08/02, 8408300176

--8408300183 Revised "Radiation Environ Monitoring Plan "
CLARK, B W , FEY, F L Northern States Power Co 84/02/29 14pp
26302 226 24X Fiche 50-000, 84/08/02, 8408300176

P Operating license stage documents & correspondence

8408150513 Forwards request for info re torus attached piping & suppression chamber penetration as part of Mark I containment long-term program Response will be discussed at 840809 & 10 meetings w/NRC & consultants
VASSALLO, D B Operating Reactors Branch 2 84/07/27 MUSOLF, D M
Northern States Power Co 3pp 26105 360 24X
Fiche 50-263, 84/07/27, 8408150513

8408160222 Forwards application for amend to License DPR-22, changing Tech Specs to increase degraded voltage protection setpoint, per station electric distribution sys voltage analysis
Fee encl
MUSOLF, D Northern States Power Co 84/07/27 Office of Nuclear Reactor Regulation, Director 1p 26092 143 24X
Fiche 50-263, 84/07/27, 8408160222

--8408160229 Application for amend to License DPR-22, changing Tech Specs to increase degraded voltage protection setpoint
MUSOLF, D Northern States Power Co 84/07/27 3pp 26092 144
24X Fiche 50-263, 84/07/27, 8408160222

--8408160233 Proposed Tech Spec changes, increasing degraded voltage protection setpoint
* Northern States Power Co 84/07/27 7pp 26092 147 24X
Fiche 50-263, 84/07/27, 8408160222

8408060425 Notification of 840809-10 meetings w/utils, NUTECH, Franklin Research Ctr & BNL in San Jose, CA to discuss comments resulting from post-implementation review re plant-unique analysis repts
BEVAN, R D Operating Reactors Branch 2 84/07/31 VASSALLO, D B
Operating Reactors Branch 2 1p 25937 335 24X
Fiche 50-000, 84/07/31, 8408060425

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, 'Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200423 Forwards request for addl info re 831230 reanalysis of station electrical distribution sys voltages Response to encl questions requested within 60 days of ltr receipt
VASSALLO, D B Operating Reactors Branch 2 84/08/09 MUSOLF, D M
Northern States Power Co 3pp 26144 361 24X
Fiche 50-263, 84/08/09, 8408200423

8408290314 Forwards Amend 25 to License DPR-22 & safety evaluation Amend extends interval betweenintegrated containment leak rate tests & adds intake structure sprinkler sys requirements
ROONEY, V L Operating Reactors Branch 2 84/08/15 MUSOLF, D M
Northern States Power Co 2pp 26312 297 24X
Fiche 50-263, 84/08/15, 8408290314

--8408290324 Amend 25 to License DPR-22, extending interval between integrated containment leak rate tests, adding requirements for new intake structure sprinkler sys & making other nonsafety-related Tech Spec changes
VASSALLO, D B Operating Reactors Branch 2 84/08/15 1Bpp 26312 299 24X Fiche 50-263, 84/08/15, 8408290314

--8408290329 Safety evaluation supporting Amend 25 to License DPR-22
* Office of Nuclear Reactor Regulation, Director 84/08/15 3pp 26312 317 24X Fiche 50-263, 84/08/15, 8408290314

8408170252 Forwards Rev 1 to NEDO-30477, "Safety Analysis of RHR Intertie Line, Monticello Nuclear Generating Plant " Rev suppls 840329 application to amend License DPR-22
MUSOLF, D Northern States Power Co 84/08/16 Office of Nuclear Reactor Regulation, Director 1p 26118 103 24X
Fiche 50-263, 84/08/16, 8408170252

--8408170262 Rev 1 to, "Safety Analysis of RHR Intertie Line, Monticello Nuclear Generating Plant "
BRANDON, R J , GRIDLEY, R L General Electric Co NEDO-30477 R01 84/06/30 27pp 26118 104 24X Fiche 50-263, 84/08/16, 8408170252

8408270293 Forwards Rev 1 to 840103 application for amend to License DPR-22 Rev modifies surveillance requirements for emergency filtration train charcoal absorber & filters & toxic gas monitoring requirements for control room
MUSOLF, D Northern States Power Co 84/08/17 Office of Nuclear Reactor Regulation, Director 1p 26242 313 24X
Fiche 50-263, 84/08/17, 8408270293

--8408270299 Rev 1 to 840403 application for amend to License DPR-22, authorizing changes to Tech Specs re surveillance requirements for control room habitability & toxic gas monitors, per NUREG-0737, Item III D 3 4
MUSOLF, D Northern States Power Co 84/08/17 5pp 26242 314 24X Fiche 50-263, 84/08/17, 8408270293

--8408270302 Proposed Tech Spec changes re surveillance requirements for control room habitability & toxic gas monitors
* Northern States Power Co 84/08/17 17pp 26242 319 24X
Fiche 50-263, 84/08/17, 8408270293

--8408270307 "Monticello Generating Station Toxic Chemical Study Incapacitation Levels "
* Bechtel Corp 84/06/20 13pp 26242 336 24X
Fiche 50-263, 84/08/17, 8408270293

8408280160 Forwards application for amend to License DPR-22, revising Tech Specs to support use of Hybrid I control rod assemblies for completion of Cycle 11 fuel loading Fee paid
MUSOLF, D Northern States Power Co 84/08/17 Office of Nuclear Reactor Regulation, Director 1p 26275 109 24X
Fiche 50-263, 84/08/17, 8408280160

--8408280164 Application for amend to License DPR-22, revising Tech Specs to support use of Hybrid I control rod assemblies for completion of Cycle 11 fuel loading
MUSOLF, D Northern States Power Co 84/08/17 5pp 26275 110 24X Fiche 50-263, 84/08/17, 8408280160

--8408280169 Proposed Tech Spec 5 0, "Design Features," supporting use of Hybrid I control rod assemblies for completion of Cycle 11 fuel loading
* Northern States Power Co 84/08/17 1p 26275 115 24X
Fiche 50-263, 84/08/17, 8408280160

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8408010401 Forwards IE Insp Rept 50-263/84-09 on 840302-0616 No noncompliance noted
SHAFER, W D Region 3, Office of Director 84/07/12 LARSON, C E
Northern States Power Co 2pp 25866 044 24X
Fiche 50-263, 84/07/12, 8408010401

--8408010402 IE Insp Rept 50-263/84-09 on 840302-0616 No noncompliance noted Major areas inspected previous insp findings, ventilation sys damper actuators, Unistrut Bracket P-2073A insp, LERs, onsite review committee & long-term shutdown
BOYD, D C Region 3, Office of Director 84/07/11 5pp 25866 046 24X Fiche 50-263, 84/07/12, 8408010401

8408080171 Forwards IE Insp Rept 50-263/84-11 on 840521-25 & notice of deviation
SPESSARD, R L Region 3, Office of Director 84/07/20 LARSON, C E
Northern States Power Co 2pp 25974 278 24X
Fiche 50-263, 84/07/20, 8408080171

--8408080174 Notice of deviation from insp on 840521-25
SPESSARD, R L Region 3, Office of Director 84/07/20 1p 25974 280 24X Fiche 50-263, 84/07/20, 8408080171

--8408080181 IE Insp Rept 50-263/84-11 on 840521-25 Deviation noted, failure of fire detection sys to provide permanent record of signals sent to central supervising station
ULIE, J M , GULDEMOND, W G Region 3, Office of Director 84/07/20 19pp 25974 281 24X Fiche 50-263, 84/07/20, 8408080171

8408150544 Forwards IE Insp Rept 50-263/84-14 on 840625-29 & notice of violation
PAPERIELLO, C J Region 3, Office of Director 84/07/26
LARSON, C E Northern States Power Co 2pp 26079 222 24X
Fiche 50-263, 84/07/26, 8408150544

--8408150546 Notice of violation from insp on 840625-29
PAPERIELLO, C J Region 3, Office of Director 84/07/26 1p 26079 224 24X Fiche 50-263, 84/07/26, 8408150544

--8408150547 IE Insp Rept 50-263/84-14 on 840625-29 Violation noted solid radwaste contained free standing liquid
GRANT, W D , NICHOLSON, N A , GREGER, L R Region 3, Office of Director 84/07/26 9pp 26079 225 24X Fiche 50-263, 84/07/26, 8408150544

8408230489 Forwards IE Insp Rept 50-263/84-12 on 840617-0707 No noncompliance noted
SHAFER, W D Region 3, Office of Director 84/07/26 LARSON, C E
Northern States Power Co 2pp 26212 249 24X
Fiche 50-263, 84/07/26, 8408230489

--8408230497 IE Insp Rept 50-263/84-12 on 840612-0707 No noncompliance or deviations noted Major areas inspected onsite review committee, procedures, recirculation vessel riser & long-term shutdown
BOYD, D C Region 3, Office of Director 84/07/26 4pp 26212 251 24X Fiche 50-263, 84/07/26, 8408230489

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408300058 Forwards exam rept on 840626-28
WALKER, R D Region 3, Office of Director 84/08/13 LARSON, C E
Northern States Power Co 1p 26307 240 24X Fiche 50-263, 84/08/13, 8408300058

--8408300060 Exam rept on 840626-29 Exam results one operator candidate failed written & simulator exams
DIMMOCK, L , MCMILLEN, J T Region 3, Office of Director
GROVES, D N EG&G, Inc 84/08/10 64pp 26307 241 24X
Fiche 50-263, 84/08/13, 8408300058

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G O General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8407100420 LER 84-022-00 on 840605, reactor bldg ventilation isolation & standby gas treatment initiation occurred Caused by blown fuse in reactor bldg spent fuel pool radiation monitor Channel B Fuse replaced W/840705 ltr
BAYLESS, R S , MUSOLF, D Northern States Power Co 84/07/05 3pp 25464 280 24X Fiche 50-263, 84/07/05, 8407100420

8408080099 LER 84-024-00 on 840627, during cold shutdown, reactor bldg ventilation isolation & standby gas treatment sys initiation occurred Channel A reactor bldg vent wide range gas monitor deenergized Caused by personnel error W/840727 ltr
LARSON, D E , MUSOLF, D Northern States Power Co 84/07/27 3pp 25974 275 24X Fiche 50-263, 84/07/27, 8408080099

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318.327 24X Fiche 50-000, 84/08/21, 8408310186

8408280127 Part 21 rept re defects in 18-inch SA-333 RHR pipe Samples of defective pipe matl being shipped to Technitat Corp, per request Defects located in one length of SA-333 Grade 6 pipe
CROSBY, G E Northern States Power Co 84/08/22 COLLINS, J NRC - No Detailed Affiliation Given 1p 26275 144 24X
Fiche 50-263, 84/08/22, 8408280127

V. Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

8408300058 Forwards exam rept on 840626-28
WALKER, R D Region 3, Office of Director 84/08/13 LARSON, C E Northern States Power Co 1p 26307 240 24X Fiche 50-263, 84/08/13, 8408300058

--8408300060 Exam rept on 840626-29 Exam results one operator candidate failed written & simulator exams
DIMMOCK, L , MCMILLEN, J I Region 3, Office of Director
GROVES, D N EG&G, Inc 84/08/10 64pp 26307 241 24X
Fiche 50-263, 84/08/13, 8408300058

8408230132 Informs of review of 840705 ltr which clarified interpretation of on-shift training requirements Util will be required to provide documentation that senior reactor operator upgrade candidates comply w/listed requirements
WALKER, R D Region 3, Office of Director 84/08/20 LARSON, C E Northern States Power Co 2pp 26209 061 24X
Fiche 50-000, 84/08/20, 8408230132

DOCKET 50-264 DOW CHEMICAL CO

/ Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-265 QUAD CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8408140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 84/08/03 Region 3, Office of Director 1p 26044 252 24X Fiche 50-000, 84/08/03, 8408140139

8408140365 Revised emergency implementing procedures, including Rev 7 to GEP 110-2 re shift engineer, Rev 6 to GEP 180-0 re Rad-Chem director & Rev 17 to GEP 200-0 re emergency conditions
* Commonwealth Edison Co 84/08/04 84pp 26041 052 24X
Fiche 50-254, 84/08/04, 8408140365

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO, C J Region 3, Office of Director 84/08/07 REED, C Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000, 84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR, D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000, 84/08/07, 8408130401

8408200248 Advises that 840803 Rev 15 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/08/14 FARRAR, D L Commonwealth Edison Co 2pp 26133 190 24X Fiche 50-254, 84/08/14, 8408200248

8408230270 Revised emergency plan implementing procedures, including Rev 23 to GEP-310-0, "Notification of Responsible Authorities," & Rev 13 to GEP 310-T3, "Prioritized Notification Listing " W/rev receipt form
* Commonwealth Edison Co 84/08/16 11pp 26209 323 24X
Fiche 50-254, 84/08/16, 8408230270

P Operating license stage documents & correspondence

8408060425 Notification of 840809-10 meetings w/utils, NUTECH, Franklin Research Ctr & BNL in San Jose, CA to discuss comments resulting from post-implementation review re plant-unique analysis repts
BEVAN, R B Operating Reactors Branch 2 84/07/31 VASSALLO, D B Operating Reactors Branch 2 1p 25937 335 24X
Fiche 50-000, 84/07/31, 8408060425

8408140317 Forwards response to 840626 request for addl info re 125-volt dc sys Facility recently completed replacement of 125-volt battery chargers w/200 ampere-rated units
RYBAK, B Commonwealth Edison Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 26042 333 24X
Fiche 50-254, 84/08/01, 8408140317

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X
Fiche 50-000, 84/08/06, 8408160345

8408270114 Provides supplemental response to Generic Ltr 83-36, "NUREG-0737 Tech Specs " Mods to Quad Cities radiological ETS will not be complete until Fall 1984 Complete response w/Tech Spec amend requests expected by 841115
ALEXANDER, G L Commonwealth Edison Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26247 330 24X Fiche 50-000, 84/08/15, 8408270114

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310203 Suppl to 830217 application for amend to Licenses DPR-29 & DPR-30, revising Tech Specs to incorporate listed changes reflecting rev to 10CFR50 72 & new Section 50 73 LER reporting requirements, per Generic Ltr 83-43
RYBAK, B Commonwealth Edison Co 84/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 26320 245 24X
Fiche 50-254, 84/08/23, 8408310203

--8408310206 Proposed Tech Spec changes reflecting revised 10CFR50 72 & new Section 50 73 LER reporting requirements
* Commonwealth Edison Co 84/08/23 62pp 26320 251 24X
Fiche 50-254,84/08/23,8408310203

8408310211 Forwards final response to second & final set of questions re Mark I containment plant-unique analysis
RYDAK,B Commonwealth Edison Co 84/08/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 37pp 26318 072 24X
Fiche 50-000,84/08/24,8408310211

Q Inspection reports, IE Bulletins & correspondence

8408150392 Forwards IE Insp Repts 50-254/84-10 & 50-265/84-09 on 840625-28 & 0706 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 84/07/26 REED,C
Commonwealth Edison Co 2pp 26077 340 24X Fiche 50-254,84/07/26,
8408150392

--8408150401 IE Insp Repts 50-254/84-10 & 50-265/84-09 on 840625-28 & 0706 No violations or deviations noted Major areas inspected confirmatory measures,radiological environ monitoring program & licensee actions on open items
ROZAK,S , OESTMANN,M J , SCHUMACHER,M C Region 3, Office of Director 84/07/25 10pp 26077 342 24X Fiche 50-254,84/07/26,
8408150392

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC
NORELIUS,C E Region 3, Office of Director 84/08/03 REED,C
Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000,84/08/03,
8408070066

8408230549 Forwards IE Insp Repts 50-254/84-08 & 50-265/84-07 on 840520-0623 & notice of violation Type A tests must be conducted during each refueling outage,unless request & granted exemption from requirement received
NORELIUS,C E Region 3, Office of Director 84/08/03 REED,C
Commonwealth Edison Co 2pp 26213 005 24X Fiche 50-254,84/08/03,
8408230549

--8408230551 Notice of violation from insp on 840520-0623
NORELIUS,C E Region 3, Office of Director 84/08/03 2pp
26213 007 24X Fiche 50-254,84/08/03,8408230549

--8408230555 IE Insp Repts 50-254/84-08 & 50-265/84-07 on 840520-0623 Noncompliance noted failure to local leak rate test gasketed penetration & failure to quantify leakage during integrated leak rate test
CHRISSOTIMOS,N Region 3, Office of Director 84/07/23 9pp
26213 009 24X Fiche 50-254,84/08/03,8408230549

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn,IL to discuss regulatory improvement program
NORELIUS,C E Region 3, Office of Director 84/08/08 REED,C
Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000,84/08/08,
8408140344

8408150098 Suppls 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER,G L Commonwealth Edison Co 84/08/08 KEPPLER,J G
Region 3, Office of Director 3pp 26067 053 24X
Fiche 50-000,84/08/08,8408150098

8408200331 Suppls response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER,G L Commonwealth Edison Co 84/08/08 KEPPLER,J G
Region 3, Office of Director 3pp 26132 318 24X
Fiche 50-000,84/08/08,8408200331

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J M Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408210068 Rept of changes, tests & experiments completed during Jul 1984 W/840801 ltr
KALIVIANAKIS,N Commonwealth Edison Co 84/07/31 CASE,E G
Office of Nuclear Reactor Regulation, Director 2pp 26184 307
24X Fiche 50-254,84/07/31,8408210068

8408230435 Monthly operating repts for Jul 1984 W/840801 ltr
KIMLER,D , KALIVIANAKIS,N Commonwealth Edison Co 84/07/31 24pp
26213 074 24X Fiche 50-254,84/07/31,8408230435

8408300299 Forwards "Effluent & Waste Disposal Semiannual Rept, Jan-June 1984,Gaseous Effluents - Summation of All Releases"
& errata to semiannual repts for Jan-June & Jul-Dec 1983
KALIVIANAKIS,N Commonwealth Edison Co 84/08/15 KEPPLER,J G
Region 3, Office of Director 1p 26314 225 24X
Fiche 50-254,84/08/15,8408300299

--8408300308 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1984 "
DEHRENS,P A Commonwealth Edison Co 84/06/30 12pp 26314 226
24X Fiche 50-254,84/08/15,8408300299

--8408300329 Errata to "Liquid Effluents - Summation of All Releases " Jan-June 1983
* Commonwealth Edison Co 83/06/30 7pp 26314 233 24X
Fiche 50-254,84/08/15,8408300299

--8408300336 Errata to "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983,Gaseous Effluents - Summation of All Releases "
* Commonwealth Edison Co 83/12/31 2pp 26314 240 24X
Fiche 50-254,84/08/15,8408300299

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408060251 LER 84-008-00 on 840703, after surveillance, HPCI cooling water return valve MO-2-2301-4B could not be reopened from control room Cause unknown Valve manually opened, declared operable & cycled several times w/no problems W/840720 ltr
EAGLE, J B , KALIVIANAKIS, N Commonwealth Edison Co 84/07/20 3pp 25935 141 24X Fiche 50-265, 84/07/20, 8408060251

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000, 84/08/21, 8408310186

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000, 84/08/07, 8408140372

--8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X
Fiche 50-000, 84/08/07, 8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8408020150 Ack receipt of 840705 ltr forwarding scope & objectives for 840911 emergency preparedness exercise Proposed objectives acceptable, w/inclusion of assembly/accountability
PAPERIELLO, C J Region 3, Office of Director 84/07/27 FAY, C W Wisconsin Electric Power Co 1p 25886 028 24X
Fiche 50-266, 84/07/27, 8408020150.

--8408020155 Forwards draft scope for 840911 emergency preparedness exercise Detailed scenario will be provided by first wk of Aug & associated controller packages will be provided by third wk of Aug
BRITT, R W Wisconsin Electric Power Co 84/07/05 KEPPLER, J G Region 3, Office of Director 10pp 25886-029 24X
Fiche 50-266, 84/07/27, 8408020150

8408020160 Notifies that review completed re 840629 revs to App C of emergency plan Plan changes do not downgrade effectiveness of emergency plan
PAPERIELLO, C J Region 3, Office of Director 84/07/27 FAY, C W Wisconsin Electric Power Co 1p 25886 039 24X
Fiche 50-266, 84/07/27, 8408020160

8408030167 Forwards Rev 0 to "Control Room Design Review Program Plan," in partial fulfillment of Generic Ltr 82-33, "Suppl 1 to NUREG-0737 - Requirements for Emergency Response Capability "
FAY, C W Wisconsin Electric Power Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 25911 193 24X
Fiche 50-266, 84/07/31, 8408030167

--8408030170 Rev 0 to "Control Room Design Review Program Plan "
* Wisconsin Electric Power Co 84/07/31 180pp. 25911 194 24X
Fiche 50-266, 84/07/31, 8408030167

8408170198 Ack receipt of 840731 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-266/84-08 & 50-301/84-06
AXELSON, W L Region 3, Office of Director 84/08/13 CASSIDY, T J Wisconsin Electric Power Co 1p 26118 093 24X
Fiche 50-266, 84/08/13, 8408170198

--8408170203 Forwards response to NRC 840711 ltr re noncompliance noted in IE Insp Repts 50-266/84-08 & 50-301/84-06 Encl withheld (ref 10CFR/3 21)
CASSIDY, T J Wisconsin Electric Power Co 84/07/31 KEPPLER, J G Region 3, Office of Director 1p 26118 094 24X
Fiche 50-266, 84/08/13, 8408170198

8408210343 Revised emergency plan maint procedures including 1 1 re routine check, maint, calibr & inventory schedule for health physics equipment & 1 2 re routine check, maint & calibr instructions for emergency plan equipment W/840814 ltr
* Wisconsin Electric Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 74pp 26181 043 24X
Fiche 50-266, 84/08/14, 8408210343

8408290197 Informs that NRC representative will not be available to attend FEMA preexercise briefing W Snell will contact FEMA after NRC 840910 entrance & attend 840913 public critique Region III representation at FY85 public critiques unlikely
PAPERIELLO, C J Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/24 WEAVER, W J Federal Emergency Management Agency 1p 26291 176 24X Fiche 50-266, 84/08/24, 8408290197

--8408290206 Forwards schedule for 1984 emergency exercise NRC representation at pre & post-exercise briefings requested
WEAVER, W J Federal Emergency Management Agency 84/08/16
KEPPLER, J G Region 3, Office of Director 33p 26291 177 24X
Fiche 50-266, 84/08/24, 8408290197

H General correspondence

8408090514 Informs that NRC deleting organization on distribution for correspondence between NRC & util Correspondence available in LPDR
COLBURN, T G Operating Reactors Branch 3 84/07/27 ANDERSON, P Wisconsin's Environmental Decade 1p 25983 115 24X
Fiche 50-266, 84/07/27, 8408090514

K Utility Final Safety Analysis Report (FSAR) & amends

8407310166 Forwards rev to updated FSAR for Point Beach Nuclear Plant, Units 1 & 2
FAY, C W Wisconsin Electric Power Co 84/07/20 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 25905 001 24X
Fiche 50-266, 84/07/20, 8407310166

--8408020148 Rev to updated FSAR for Point Beach Nuclear Plant, Units 1 & 2
* Wisconsin Electric Power Co 84/07/20 360pp 25905 010 24X
Fiche 50-266, 84/07/20, 8407310166

P Operating license stage documents & correspondence

8408010120 Forwards marked-up radiological ETS for Units 1 & 2 Review of comments requested in preparation for discussion at meeting w/NRC, tentatively scheduled for mid-Aug in Bethesda, MD
MILLER, J R Operating Reactors Branch 3 84/07/17 FAY, C W Wisconsin Electric Power Co 81pp 25872 216 24X
Fiche 50-266, 84/07/17, 8408010120

8408070492 Forwards comments on 840502 amend application for Tech Spec changes concerning containment tendon surveillance Mod of application or justification of position requested within 45 days
MILLER, J R Operating Reactors Branch 3 84/07/24 FAY, C W Wisconsin Electric Power Co 6pp 25956 249 24X
Fiche 50-266, 84/07/24, 8408070492

8408060127 Advises of revised schedule to install new single-failure-proof auxiliary bldg crane trolley Installation will begin following Spring 1985 Unit 1 refueling outage Final design review & license amend application will be submitted
BRITT, R W Wisconsin Electric Power Co 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 1p 25933 057 24X
Fiche 50-266, 84/07/30, 8408060127

8408070328 Forwards Rev 1 to "Process Control Program," listing vendor procedures governing processing & packaging of solid radwaste
BRITT, R W Wisconsin Electric Power Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 1p 25945 139 24X
Fiche 50-266, 84/08/01, 8408070328

--8408070330 Rev 1 to "Process Control Program "
* Wisconsin Electric Power Co 84/08/01 3pp 25945 140 24X
Fiche 50-266, 84/08/01, 8408070328

8408200002 Forwards request for addl info re 830314 & 0906 requests for Tech Spec changes allowing use of Westinghouse optimized fuel W/o encl
MILLER, J R Operating Reactors Branch 3 84/08/01 FAY, C W
Wisconsin Electric Power Co 1p 26143 264 24X
Fiche 50-266, 84/08/01, 8408200002

8408070030 Responds to 840326 request for periodic updates re progress made toward alleviating shortage of licensed operators Adequate number of licensed operators anticipated after scheduled reactor license exam in Dec 1984
BRITT, R W Wisconsin Electric Power Co 84/08/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 25950 036 24X
Fiche 50-266, 84/08/02, 8408070030

8408070245 Requests extension of qualification program completion schedule to end of June 1985 refueling outage for Crosby lift indicating switch assemblies & Veam thermocouple connectors
BRITT, R W Wisconsin Electric Power Co 84/08/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 3pp 25949 017 24X
Fiche 50-266, 84/08/02, 8408070245

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160482 Summary of 840724 meeting w/Westinghouse Owners Group re upper plenum injection for two loop plants
DIIANNI, D C Operating Reactors Branch 3 84/08/09 Operating Reactors Branch 3 4pp 26108 327 24X Fiche 50-000, 84/08/09, 8408160482

8408270233 Forwards proprietary & nonproprietary responses to request for addl info re Tech Spec Change Request 87 concerning use of Westinghouse optimized fuel assembly Application for withholding proprietary response (ref 10CFR2 790) encl
FAY, C W Wisconsin Electric Power Co 84/08/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 3pp 26242 205 24X
Fiche 50-266, 84/08/17, 8408270233

--8408270246 Requests proprietary responses to NRC questions re optimized fuel assembly design be withheld (ref 10CFR2 790) Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp
26242 208 24X Fiche 50-266, 84/08/17, 8408270233

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408280216 Forwards addl info re methodology & results of analysis performed to determine impact of parking rod cluster control assemblies at 225 steps withdrawn position, per request
FAY, C W Wisconsin Electric Power Co 84/08/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Licensing Branch 3 4pp 26279 183 24X Fiche 50-266, 84/08/22, 8408280216

8408280128 Confirms 840823 telcon between R Seizert & C Trammel re existence of potential defect in Anker-Holth large bore snubbers Info provided in 840810 ltr presently being evaluated to determine impact upon facility operations
FAY, C W Wisconsin Electric Power Co 84/08/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 1p 26261 319 24X
Fiche 50-266, 84/08/24, 8408280128

8408310284 Advises that mods to motor operated discharge valves for electric driven auxiliary feedwater pumps completed & tested satisfactorily
EISENHUT, D G Division of Licensing 84/08/24 NORELIUS, C E
Division of Project & Resident Programs 1p 26351 334 24X
Fiche 50-266, 84/08/24, 8408310284

G Inspection reports, IE Bulletins & correspondence

8408090184 Forwards IE Insp Repts 50-266/84-12 & 50-301/84-10 on 840711 No noncompliance identified
LITTLE, W S Region 3, Office of Director 84/07/23 FAY, C W
Wisconsin Electric Power Co 2pp 25992 075 24X
Fiche 50-266, 84/07/23, 8408090184

--8408090189 IE Insp Repts 50-266/84-12 & 50-301/84-10 on 840711 No noncompliance identified Major areas inspected followup of valve shaft insps on main steamline isolation swing check & swing stop valves
JONES, D E , DANIELSON, D H Region 3, Office of Director
84/07/23 2pp 25992 077 24X Fiche 50-266, 84/07/23, 8408090184

8408150399 Forwards IE Insp Repts 50-266/84-10 & 50-301/84-08 on 840625-29 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/07/25 FAY, C W
Wisconsin Electric Power Co 2pp 26077 320 24X
Fiche 50-266, 84/07/25, 8408150399

--8408150406 IE Insp Repts 50-266/84-10 & 50-301/84-08 on 840625-29 No violations noted Major areas inspected operational radiation protection program, including mgt, staffing, exposure control, ALARA, surveys, posting & controls & TMI action items
PAUL, R A , GREGER, L R Region 3, Office of Director 84/07/25
8pp 26077 322 24X Fiche 50-266, 84/07/25, 8408150399

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408160329 Forwards IE Insp Repts 50-266/84-11 & 50-301/84-09 on 840702-03 No noncompliance noted
LITTLE, W S Region 3, Office of Director 84/07/30 Wisconsin Electric Power Co 2pp 26106 094 24X Fiche 50-266, 84/07/30, 8408160329

--8408160331 IE Insp Repts 50-266/84-11 & 50-301/84-09 on 840702-03 No noncompliance or deviations noted Major areas inspected Followup action of previously identified insp findings
MILBROT, W E , GULDEMOND, W G Region 3, Office of Director
84/07/27 5pp 26106 096 24X Fiche 50-266, 84/07/30, 8408160329

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408100044 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-21 & 50-301/83-20, per 840517 request
SPESSARD, R L Region 3, Office of Director 84/08/03 FAY, C W
Wisconsin Electric Power Co 1p 25987 063 24X
Fiche 50-266, 84/08/03, 8408100044

--8408100052 Further response to NRC 840517 ltr re violations noted in IE Insp Repts 50-266/83-21 & 50-301/83-20 Corrective actions drawings received after 840601 stamped w/ "For Info Only" unless updated control drawings Review completed
FAY, C W Wisconsin Electric Power Co 84/07/20 SPESSARD, R L
Region 3, Office of Director 4pp 25987 064 24X
Fiche 50-266, 84/08/03, 8408100044

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 89pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408290565 Forwards Insp Rpts 50-266/84-07 & 50-301/84-03 on 840601-0731 No noncompliance noted
SHAFER, W D Region 3, Office of Director 84/08/10 FAY, C W
Wisconsin Electric Power Co 2pp 26296 295 24X
Fiche 50-266, 84/08/10, 8408290565

--8408290570 Insp Repts 50-266/84-07 & 50-301/84-05 on 840601-0731 No noncompliance noted Major areas inspected operational safety, maint, surveillance, independent insp & plant trips
JACKIW, I N Region 3, Office of Director 84/08/09 9pp
26296 297 24X Fiche 50-266, 84/08/10, 8408290565

8409100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 11pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8409170198 Ack receipt of 840731 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-266/84-08 & 50-301/84-06
AXELSON, W L Region 3, Office of Director 84/08/13 CASSIDY, T J
Wisconsin Electric Power Co 1p 26118 093 24X
Fiche 50-266, 84/08/13, 8408170198

--8408170203 Forwards response to NRC 840711 ltr re noncompliance noted in IE Insp Repts 50-266/84-08 & 50-301/84-06 Encl withheld (ref 10CFR73 21)
CASSIDY, T J Wisconsin Electric Power Co 84/07/31 KEPPLER, J G
Region 3, Office of Director 1p 26118 094 24X
Fiche 50-266, 84/08/13, 8408170198

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408210550 Requests remittance of fee for 840706 application requesting relief from certain ASME Code requirements for second 10-yr insp interval Application subj to 840620 rev to 10CFR170 re fees Discussion of fees encl W/o encl
DIGGS, R M License Fee Management Branch 84/08/16 FAY, C W
Wisconsin Electric Power Co 1p 26195 262 24X
Fiche 50-266, 84/08/16, 8408210550

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408310229 "Semiannual Monitoring Rept, Jan-June 1984 "
* Wisconsin Electric Power Co 84/06/30 17pp 26322 165 24X
Fiche 50-266, 84/06/30, 8408310229

8408210232 Monthly operating repts for Jul 1984 W/840810 ltr
KRAUSE, C W , FAY, C W Wisconsin Electric Power Co 84/07/31 10pp
26184 297 24X Fiche 50-266, 84/07/31, 8408210232

S Reportable occurrences, LERs & related correspondence

8408300511 LER 84-004-00 on 840721, inadvertent actuation of reactor protection sys occurred on low pressurizer pressure Caused by interlock circuit P7 deenergized due to maint work Maint work procedure under review W/840820 ltr
FAY, C W Wisconsin Electric Power Co 84/08/20 KEPPLER, J G
Region 3, Office of Director 3pp 26313 340 24X
Fiche 50-266, 84/08/20, 8408300511

8408300518 LER 84-003-00 on 840721, high neutron flux generated by source range instrumentation Channel 32, activating reactor protection sys Caused by detector malfunction after source range intruments energized when unblocked W/840820 ltr
FAY, C W Wisconsin Electric Power Co 84/08/20 KEPPLER, J G
Region 3, Office of Director 33pp 26313 351 24X
Fiche 50-266, 84/08/20, 8408300518

V Operator Examinations

8408070030 Responds to 840326 request for periodic updates re progress made toward alleviating shortage of licensed operators Adequate number of licensed operators anticipated after scheduled reactor license exam in Dec 1984
BRITT, R W Wisconsin Electric Power Co 84/08/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 25950 036 24X
Fiche 50-266, 84/08/02, 8408070030

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

8408230521 Advises that operator & senior operator licensing exams scheduled for 841204-06 Matl listed in encl "Ref Matl Requirements for Operator/Senior Operator Licensing Exams" requested by 841004
WALKER, R D Region 3, Office of Director 84/08/17 FAY, C W
Wisconsin Electric Power Co 5pp 26212 286 24X
Fiche 50-266, 84/08/17, 8408230521

DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8408290264 Forwards complete package for 1984 Fort St Vrain radiological emergency exercise Package consists of scope & objectives, narrative summary & sequence of events, conduct of exercise & observer/prompter packages
WAREMBOURG, D W Public Service Co of Colorado 84/06/11
JOHNSON, E H Region 4, Office of Director 135pp 26295 065 24X
Fiche 50-267, 84/06/11, 8408290264

8408310040 Advises that Scenario FOSAVEX-84 does not support escalation to general emergency classification & not consistent w/App E of 10CFR50 Early warning alert sys should be included in exercise
JOHNSON, E H Region 4, Office of Director 84/07/09 LEE, O R
Public Service Co of Colorado 2pp 26333 358 24X
Fiche 50-267, 84/07/09, 8408310040

8408290181 Confirms scheduling change for 1984 radiological emergency exercise, per 840716, 17 & 18 telcons Exercise postponed until 840815 Revised scope & objectives, summary & sequence of events & conduct of exercise encl
WAREMBOURG, D W Public Service Co of Colorado 84/07/20
JOHNSON, E H Region 4, Office of Director 141pp 26309 010 24X
Fiche 50-267, 84/07/20, 8408290181

8408030168 Responds to NRC 840625 concerns re Bldg 10 const Concept of Bldg 10 finalized to relieve crowding conditions & to accommodate equipment replacements being planned Bldg 10 constitutes mod not requiring amend to OL
LEE, O R Public Service Co of Colorado 84/07/25 JOHNSON, E H
Region 4, Office of Director 359pp 25913 048 24X
Fiche 50-267, 84/07/25, 8408030168

8408070313 Forwards NRC/DOE Form 741 for Transaction YVB-JXI-0079 Encl withheld
WAREMBOURG, D Public Service Co of Colorado 84/07/30
JOHNSON, E H Region 4, Office of Director 1p 25948 001 24X
Fiche 50-267, 84/07/30, 8408070313

8408090311 Forwards application for amend to License DPR-34, revising Tech Specs to comply w/NUREG-0737, Items II B 3, II F 1 3 & III D 3 4
LEE, O R Public Service Co of Colorado 84/07/31 JOHNSON, E H
Region 4, Office of Director 3pp 25994 114 24X
Fiche 50-267, 84/07/31, 8408090311

--8408090316 Application for amend to License DPR-34, revising Tech Specs to comply w/NUREG-0737, Items II B 3, II F 1 3 & II D, 3 4 Fee encl
LEE, O R Public Service Co of Colorado 84/07/31 6pp
25994 117 24X Fiche 50-267, 84/07/31, 8408090311

--8408090322 Proposed revs to Tech Spec limiting conditions re control room temp, area radiation monitors, seismic instrumentation, primary coolant moisture instrumentation, switchgear room temp, emergency ventilation sys & fire suppression sys
* Public Service Co of Colorado 84/07/31 21pp 25994 123 24X Fiche 50-267, 84/07/31, 8408090311

8408280480 Forwards NRC/DOE Form 741 for Transaction YVD-JXI-0083 Encl withheld
GAHM, J W Public Service Co of Colorado 84/08/15 JOHNSON, E H
Region 4, Office of Director 1p 26282 102 24X
Fiche 50-267, 84/08/15, 8408280480

P Operating license stage documents & correspondence

8408020198 Provides advance notification of spent fuel shipments from plant in Platteville, CO to Idaho Chemical Processing Plant in Scoville, ID during Jul & Aug 1984 Info withheld (ref 10CFR73 72)
WAREMBOURG, D Public Service Co of Colorado 84/07/13
JOHNSON, E H , KELLEY, J Region 4, Office of Director 1p 25898 187 24X Fiche 50-267, 84/07/13, 8408020198

8408080525 Discusses proposal for documentation of disciplinary action against employees When NRC requests info re disciplinary action for employee, licensee will submit info w/individual name purged
LEE, O R Public Service Co of Colorado 84/07/24 COLLINS, J T
Region 4, Office of Director 2pp 25975 288 24X
Fiche 50-267, 84/07/24, 8408080525

8408070225 Ack receipt of 840627 ltr transmitting current description of QA program, implemented per 10CFR50 54(a) Review continuing
JOHNSON, E H Region 4, Office of Director 84/07/31 LEE, O R
Public Service Co of Colorado 1p 25948 303 24X
Fiche 50-267, 84/07/31, 8408070225

8408090311 Forwards application for amend to License DPR-34, revising Tech Specs to comply w/NUREG-0737, Items II B 3, II F 1 3 & III D 3 4
LEE, O R Public Service Co of Colorado 84/07/31 JOHNSON, E H
Region 4, Office of Director 3pp 25994 114 24X
Fiche 50-267, 84/07/31, 8408090311

--8408090316 Application for amend to License DPR-34, revising Tech Specs to comply w/NUREG-0737, Items II B 3, II F 1 3 & II D 3 4 Fee encl
LEE, O R Public Service Co of Colorado 84/07/31 6pp 25994 117 24X Fiche 50-267, 84/07/31, 8408090311

--8408090322 Proposed revs to Tech Spec limiting conditions re control room temp, area radiation monitors, seismic instrumentation, primary coolant moisture instrumentation, switchgear room temp, emergency ventilation sys & fire suppression sys
* Public Service Co of Colorado 84/07/31 21pp 25994 123 24X Fiche 50-267, 84/07/31, 8408090311

8408090405 Advises that refund will be sent for overpayment of fee for review of 830419 application for Amend 43 to License DPR-34
MILLER, W O License Fee Management Branch 84/08/01 LEE, O R
Public Service Co of Colorado 2pp 25978 076 24X
Fiche 50-267, 84/08/01, 8408080405

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160370 Amended notification of significant licensee meeting on 840823 in Arlington, TX to discuss progress on evaluating changes to Tech Spec Limiting Conditions for Operation 4 1 9
* Region 4, Office of Director 84/08/09 Region 4, Office of Director 1p 26126 246 24X Fiche 50-267, 84/08/09, 8408160370

8408200559 Confirms 840806 telcon on Tech Spec change request re tendon corrosion & anchor assembly surveillance Tech Spec change request will be submitted by 840930
WAREMBOURG, D W Public Service Co of Colorado 84/08/09
JOHNSON, E H Region 4, Office of Director 2pp 26139 041 24X
Fiche 50-267, 84/08/09, 8408200559

8408200581 Informs that Rev 1 to FSAR App B, QA program for plant operation, satisfies requirements of 10CFR50, App B & is acceptable
JOHNSON, E H Region 4, Office of Director 84/08/10 LEE, O R
Public Service Co of Colorado 2pp 26139 058 24X
Fiche 50-267, 84/08/10, 8408200581

8408290256 Forwards "Response to NRC/LASL Concerns re Cracked Fuel Element Integrity " Issues raised by LASL pose no problem w/ regard to fuel elements w/cracked webs
LEE, O R Public Service Co of Colorado 84/08/13 JOHNSON, E H
Region 4, Office of Director 7pp 26295 049 24X
Fiche 50-267, 84/08/13, 8408290256

8408210462 Forwards response to ORNL concerns & proposal identified in NRC 840523 ltr Basis for discussion of ORNL/util concerns & resolution of issues delaying implementation of revised Limiting Condition for Operation 4 1 9 discussed
GAHM, J W Public Service Co of Colorado 84/08/14 JOHNSON, E H
Region 4, Office of Director 9pp 26149 330 24X
Fiche 50-267, 84/08/14, 8408210462

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8408230471 Forwards IE Insp Rept 50-267/84-15 on 840604-08 No violations or deviations noted
JOHNSON, E H Region 4, Office of Director 84/07/05 LEE, O R
Public Service Co of Colorado 2pp 26212 184 24X
Fiche 50-267, 84/07/05, 8408230471

--8408230522 IE Insp Rept 50-267/84-15 on 840604-08 No violations or deviations noted Major areas inspected collection, storage & maint of QA records
EVANS, C A , HALL, R E Region 4, Office of Director 84/06/29 5pp 26212 186 24X Fiche 50 267, 84/07/05, 8408230471

8408080520 Informs of control rod & CRD insp & testing in response to NRC 840709 insp Major power consumption & scram verification of all 37 CRD & orifice assemblies completed & insp underway Plan for further action described
LEE, O R Public Service Co of Colorado 84/07/18 JOHNSON, E H
Region 4, Office of Director 5pp 25975 272 24X
Fiche 50-267, 84/07/18, 8408080520

8408160507 Forwards IE Insp Rept 50-267/84-15 on 840601-30 & notices of violation & deviation
JOHNSON, E H Region 4, Office of Director 84/07/23 LEE, O R
Public Service Co of Colorado 2pp 26107 335 24X
Fiche 50-267, 84/07/23, 8408160507

--8408160509 Notice of violation from insp on 840601-30
* Region 4, Office of Director 84/07/23 3pp 26107 337 24X
Fiche 50-267, 84/07/23, 8408160507

--8408160513 Notice of deviation from insp on 840601-30
* Region 4, Office of Director 84/07/23 1p 26107 340 24X
Fiche 50-267, 84/07/23, 8408160507

--8408160516 IE Insp Rept 50-267/84-15 on 840601-30 Violation & deviation noted special test initiated w/o supervisor signature & independent check of shift turnover procedures did not occur during 1983
PLUMLEE, G L , IRELAND, R E Region 4, Office of Director
84/07/17 16pp 26107 341 24X Fiche 50-267, 84/07/23, 8408160507

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830109) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408150306 Submits description of spent fuel insp program to be incorporated into Tech Specs Changes concern obtaining photographic record of vertical faces of fuel elements removed from core during each refueling
WAREMBOURG, D Public Service Co of Colorado 84/07/31
JOHNSON, E H Region 4, Office of Director 2pp 26075 290 24X
Fiche 50-267, 84/07/31, 8408150306

8408160207 Responds to NRC ltr re violations noted in IE Insp Rept 50-267/84-14 Corrective actions nitrogen pressurization sys returned to svc & shift supervisor warned re failure to sign off on power ascension procedure
WAREMBOURG, D W Public Service Co of Colorado 84/08/03
JOHNSON, E H Region 4, Office of Director 13pp 26106 287 24X
Fiche 50-267, 84/08/03, 8408160207

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408210428 Requests 30-day extension to implement shift turnover procedure in response to notice of violation in IE Insp Rept 50-247/84-16 Further R&D needed
WAREMBOURG,D Public Service Co of Colorado 84/08/10 JOHNSON,E Region 4, Office of Director 2pp 26179 202 24X Fiche 50-247,84/08/10,8408210428

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001. 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp. 26329 008 24X Fiche 50-000,84/08/21,8408210142

Periodic operating reports & related correspondence

8408010006 Forwards "Rept of Changes,Tests & Experiments Not Requiring Prior Commission Approval" for 840101-22 Anniversary date of rept changed to correspond w/submittal of annual update to FSAR Future annual repts will cover Jan 23 - Jan 22
WAREMBOURG,D Public Service Co of Colorado 84/07/20.
JOHNSON,E H Region 4, Office of Director 1p 25866 244 24X Fiche 50-267,84/07/20,8408010006

--8408010008 "Rept of Changes,Test & Experiments Not Requiring Prior Commission Approval per 10CFR50 59(a) for 840101-22 "
* Public Service Co of Colorado 84/01/22 22pp 25866 245 24X Fiche 50-267,84/07/20,8408010006

8408230456 Forwards monthly operating rept for Jul 1984 Revised monthly operating rept for June 1984 also encl due to problems experienced w/turbine generator integrator
GAHM,J W Public Service Co of Colorado 84/08/15 Record Services Branch (Document Control Desk) 1p 26213 105 24X Fiche 50-267,84/08/15,8408230456

--8408230457 Monthly operating rept for Jul 1984
FULLER,C Public Service Co of Colorado 126 84/07/31 8pp 26213 106 24X Fiche 50-267,84/08/15,8408230456

--8408230459 Revised monthly operating rept for June 1984
FULLER,C Public Service Co of Colorado 125 84/06/30 8pp 26213 114 24X Fiche 50-267,84/08/15,8408230456

S Reportable occurrences, LERs & related correspondence

8408080514 LER 84-005-01 on 840327, insp revealed wire failures in PCRV prestressing tendons Caused by corrosion Visual insp of anchor assemblies, lift-off testing, detensioning, gas sampling & metallurgical analysis completed W/840727 ltr
NOVACHEK,F , WAREMBOURG,D Public Service Co of Colorado 84/07/27 9pp 25974 235 24X Fiche 50-267,84/07/27,8408080514

8408090176 PNO-IV-84-015 on 840720, liquid release from reactor bldg exceeded Tech Spec gross beta limits by factor of 2 24 Violation not recognized until 840726 Investigation ongoing Special insp of event scheduled for wk of 840730
MURRAY,B , HALL,R Region 4, Office of Director 84/07/27 1p 25994 362 24X Fiche 50-267,84/07/27,8408090176

8408070233 Potential Part 21 rept re defective threaded rod matl supplied by Texas Bolt Co on 840618 Rods returned to vendor for replacement Nonconformance Repts 84-187 & 84-205 encl
LEE,D R Public Service Co of Colorado 84/07/30 Director's Office, Office of Inspection and Enforcement 19pp 25948 304 24X Fiche 50-267,84/07/30,8408070233

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408300244 Ack receipt of scope & objectives for 840621 emergency preparedness exercise Submittal fulfills min requirements for small-scale exercise Complete scenario will be reviewed when received & comments transmitted
DANCE,H C Region 2, Office of Director 84/05/21 TUCKER,H B
Duke Power Co 1p 26307 015 24X Fiche 50-269,84/05/21,
8408300244

8408300427 Forwards FEMA "Oconee Nuclear Power Plant Full-Scale Local Exercise Conducted on 830406," final rept
DANCE,H C Region 2, Office of Director 84/07/11 TUCKER,H B
Duke Power Co 1p 26315 209 24X Fiche 50-269,84/07/11,
8408300427

8408150326 Forwards public version of Rev 84-02 to "Emergency Plan Implementing Procedures "
TUCKER,H B Duke Power Co 84/07/17 O'REILLY,J P Region 2, Office of Director 1p 26099 001 24X Fiche 50-269,84/07/17,
8408150326

--8408150335 Public version of Rev 84-02 to "Emergency Plan Implementing Procedures " W/JM Felton 840808 release memo
TUCKMAN,M S Duke Power Co 84/06/07 195pp 26099 002 24X Fiche 50-269,84/07/17,8408150326

8408240416 Forwards Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/19 TUCKER,H B
Duke Power Co 1p 26237 113 24X Fiche 50-269,84/07/19,
8408240416

--8408240421 Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations, maint, surveillance, ESF, emergency drills & fuel handling
BRYANT,J Region 2, Office of Director 84/07/19 6pp 26237 114 24X Fiche 50-269,84/07/19,8408240416

8408280361 Forwards Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified
DANCE,H C Region 2, Office of Director 84/07/20 TUCKER,H B
Duke Power Co 2pp 26282 239 24X Fiche 50-269,84/07/20,
8408280361

--8408280370 Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise
DECKER,T R Region 2, Office of Director 84/07/06 9pp 26282 241 24X Fiche 50-269,84/07/20,8408280361

8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/08/07 TUCKER, H B Duke Power Co 2pp 26007 344 24X Fiche 50-269, 84/08/07, 8408130149

--8408130166 IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 73 21)
MOORE, D E Region 2, Office of Director 84/08/07 1p 26007 346 24X Fiche 50-269, 84/08/07, 8408130149

8408170329 Commits to assure that operators can obtain flashlight to assist in safe passage to standby shutdown facility, per requirements of 10CFR50, App R
TUCKER, H B Duke Power Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 26112 361 24X Fiche 50-269, 84/08/08, 8408170329

8408300357 Confirms 840806 telcon w/JP O'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50, fire protection & 10CFR73, physical protection Agenda encl
LEWIS, R C Region 2, Office of Director 84/08/08 TUCKER, H B Duke Power Co 3pp 26314 222 24X Fiche 50-000, 84/08/08, 8408300357

8408200414 Forwards draft safety evaluation of procedures generation package for emergency operating procedures Response to open items re writers guide & validation/verification programs requested within 30 days of ltr receipt
RIVENBARK, G W Operating Reactors Branch 4 84/08/09 TUCKER, H B Duke Power Co 2pp 26182 001 24X Fiche 50-269, 84/08/09, 8408200414

--8408200424 Draft safety evaluation of procedures generation package Package should be revised to address items in Section 2
* NRC - No Detailed Affiliation Given 84/08/09 11pp 26182 003 24X Fiche 50-269, 84/08/09, 8408200414

8408300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
TUCKER, H B Duke Power Co 84/08/10 Record Services Branch (Document Control Desk) 21pp 26332 393 24X
Fiche 50-000, 84/08/10, 8408300014

--8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations "
* Duke Power Co 84/08/15 30pp 26333 010 24X
Fiche 50-000, 84/08/10, 8408300014

--8408300028 Public version of revised crisis mgt plan implementing procedures, including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 memo
* Duke Power Co 84/08/15 170pp 26333 040 24X
Fiche 50-000, 84/08/10, 8408300014

8408220091 Forwards three exemption requests from 10CFR50, App R, Section III G 2 requirements re fire protection of safe shutdown capability, supplementing 831024 initial request No addl fees necessary
TUCKER, H B Duke Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 26193 289 24X Fiche 50-269, 84/08/14, 8408220091

8408310121 Requests extension of time to respond to 840720 ltr re util plans for establishing emergency operations facility design consistent w/requirements of Suppl 1 to NUREG-0737 Extension requested due to judicial review of util appeal
TUCKER, H B Duke Power Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 26322 243 24X Fiche 50-269, 84/08/24, 8408310121

I Financial information

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26237 137 24X
Fiche 50-000, 84/08/16, 8408240224

--8408240242 "1983 Annual Rept "
LEE, W S Duke Power Co 83/12/31 47pp 26237 167 24X
Fiche 50-000, 84/08/16, 8408240224

J Insurance & indemnity information

8408290006 Forwards Endorsements 11 & 12 to NELIA Policy NF-281
DJEMAL, A Marsh & McLennan, Inc 84/08/24 DINITZ, I Assistant Director for State & Licensee Relations 3pp 26291 235 24X
Fiche 50-269, 84/08/24, 8408290006

K Utility Final Safety Analysis Report (FSAR) & amends

8408220201 Forwards updated FSAR for Oconee Nuclear Station Info brings FSAR up to date as of 831231
TUCKER, H B Duke Power Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 26191 023 24X Fiche 50-269, 84/08/15, 8408220201

--8408220208 Updated FSAR for Oconee Nuclear Station
* Duke Power Co 83/12/31 180pp 26191 024 24X
Fiche 50-269, 84/08/15, 8408220201

P Operating license stage documents & correspondence

8408070389 Forwards "Extension of Retainer Lifetime to Four Cycles," for Oconee, Unit 3 w/results of exams of two retainers after three cycles Approval of four-cycle retainer usage requested before Dec 1984
TAYLOR, J H Babcock & Wilcox Co 84/07/24 STOLZ, J F Operating Reactors Branch 4 1p 25945 252 24X Fiche 50-000, 84/07/24, 8408070389

--8408070392 "Extension of Retainer Lifetime to 4 Cycles "
* Babcock & Wilcox Co 84/07/12 6pp 25945 253 24X
Fiche 50-000, 84/07/24, 8408070389

8408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI, P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 34pp 25978 228 24X Fiche 50-000, 84/07/27, 8408080288

8408160248 RELAP5 THERMAL-HYDRAULIC ANALYSES OF PRESSURIZED THERMAL SHOCK SEQUENCES FOR THE OCONEE-1 PRESSURIZED WATER REACTOR
FLETCHER, C D , OOLANDER, M A , STITT, B D EG&G, Inc FIN A-6047
NUREG/CR-3761 84/07/31 Division of Accident Evaluation 165pp 26125 001 24X Fiche 50-269, 84/07/31, 8408160248

8408200149 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, updating Tech Spec 4 2 4 re reactor vessel matl surveillance to incorporate changes documented in BAW-1543 W/o stated fee
TUCKER, H B Duke Power Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 26133 286 24X Fiche 50-269, 84/08/02, 8408200149

--8408200155 Proposed Tech Spec 4 2 4 re reactor vessel matl surveillance NSHC evaluation encl
* Duke Power Co 84/08/02 7pp 26133 289 24X
Fiche 50-269, 84/08/02, 8408200149

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238, 24X
Fiche 50-000, 84/08/06, 8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY, P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN, G M Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 50-000, 84/08/06, 8408090317

8408200059 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising air lock testing frequency from quarterly to semiannually Fee encl
TUCKER, H B Duke Power Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F. Operating Reactors Branch 4 3pp 26133, 296 24X Fiche 50-269, 84/08/08, 8408200059

--8408200069 Proposed Tech Specs 4 4 1 5 2 (a), revising air lock testing frequency from quarterly to semiannually
* Duke Power Co 84/08/08 6pp 26133 299 24X
Fiche 50-269, 84/08/08, 8408200059

8408220292 Forwards augmented response to Generic Ltr 83-28, Items 4 1 & 4 2 re reactor trip sys reliability vendor related mods & preventive maint & surveillance program for reactor trip breakers, respectively, per 831104 & 1230 ltrs
TUCKER, H B Duke Power Co 84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 6pp 26194 072 24X Fiche 50-269, 84/08/10, 8408220292

8408230527 Forwards payment for application fee re 840802 & 08 Tech Spec changes
BARR, S Duke Power Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 26236 286 24X Fiche 50-000, 84/08/15, 8408230527

8408270339 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs re reactor bldg purge sys, protection from inadvertent low temp overpressurization & min operator staffing requirements
TUCKER, H B Duke Power Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 8pp 26244 307 24X Fiche 50-269, 84/08/15, 8408270339

--8408270345 Proposed Tech Specs, changing reactor bldg purge sys, protection from inadequate low temp overpressurization & min operator staffing requirements
* Duke Power Co 84/08/15 14pp 26244 315 24X Fiche 50-269, 84/08/15, 8408270339

8408270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submittal of semiannual radioactive effluent release rept for Jul-Dec 1984
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 26279 112 24X Fiche 50-000, 84/08/16, 8408270160

--8408270169 Rev 4 to "Offsite Dose Calculation Manual "
BIRCH, M L , HAMPTON, J W Duke Power Co 84/07/18 39pp 26279 114 24X Fiche 50-000, 84/08/16, 8408270160

8408270464 Forwards list of questions generated during preliminary review of pump & valve inservice testing Conference call should be arranged w/staff able to provide appropriate technical expertise
STOLZ, J F Operating Reactors Branch 4 84/08/17 TUCKER, H B
Duke Power Co 10pp 26277 210 24X Fiche 50-269, 84/08/17, 8408270464

8408270499 Forwards request for addl info re NUREG-0737, Item III D 3 4, "Control Room Habitability " Response requested within 30 days of ltr receipt
STOLZ, J F Operating Reactors Branch 3 84/08/17 TUCKER, H B
Duke Power Co 3pp 26277 039 24X Fiche 50-269, 84/08/17, 8408270499

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety uestions Svc list encl
SENHUT, D G Division of Licensing 84/08/20 Consolidated ison Co of New York, Inc 17pp 26276 244 24X che 50-000, 84/08/20, 8408200275

nspection reports, IE Bulletins & correspondence

8280241 Informs of delay until 860301 to complete mods required by E Bulletin 79-14 Delay due to increase in total number of mods required
TUCKER, H B Duke Power Co 84/06/21 O'REILLY, J P Region 2, Office of Director 2pp 26262 241 24X Fiche 50-269, 84/06/21, 8408280241

108240416 Forwards Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/19 TUCKER, H B
Duke Power Co 1p 26237 113 24X Fiche 50-269, 84/07/19, 8408240416

--8408240421 Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations, maint, surveillance, ESF, emergency drills & fuel handling
BRYANT, J , SASSER, K , BROWNLEE, V L Region 2, Office of Director 84/07/19 6pp 26237 114 24X Fiche 50-269, 84/07/19, 8408240416

8408280361 Forwards Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/07/20 TUCKER, H B
Duke Power Co 2pp 26282 239 24X Fiche 50-269, 84/07/20, 8408280361

--8408280370 Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise
DECKER, T R , STANSBERRY, W W , CLINE, W E Region 2, Office of Director 84/07/06 9pp 26282 241 24X Fiche 50-269, 84/07/20, 8408280361

8407250229 IF Info Notice 84-57, Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408280472 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14
LEWIS, R C Region 2, Office of Director 84/08/01 TUCKER, H B
Duke Power Co 1p 26282 045 24X Fiche 50-269, 84/08/01, 8408280472

--8408280476 Responds to NRC 840622 ltr re violations noted in Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 Corrective actions Procedure OP/0/A/1510/10 revised to require neutron shield tank level prior to offsite shipments
TUCKER, H B Duke Power Co 84/07/20 O'REILLY, J P Region 2, Office of Director 4pp 26282 046 24X Fiche 50-269, 84/08/01, 8408280472

--8408280479 Forwards Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 on 840604-08 & notice of violation
LEWIS, R C Region 2, Office of Director 84/06/22 TUCKER, H B
Duke Power Co 2pp 26282 050 24X Fiche 50-269, 84/08/01, 8408280472

--8408280481 Notice of violation from insp on 840604-08
* Region 2, Office of Director 84/06/22 2pp 26282 052 24X Fiche 50-269, 84/08/01, 8408280472

--8408280485 Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 on 840604-08 Noncompliance noted failure to verify presence & condition of neutron radiation moderator prior to shipping & failure to perform neutron radiation surveys
WEDDINGTON, R E , JENKINS, G R Region 2, Office of Director 84/06/19 8pp 26282 054 24X Fiche 50-269, 84/08/01, 8408280472

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/08/07 TUCKER, H B
Duke Power Co 2pp 26007 344 24X Fiche 50-269, 84/08/07, 8408130149

--8408130166 IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 73 21)
MOORE, D E , MCGUIRE, D R Region 2, Office of Director 84/08/07 1p 26007 346 24X Fiche 50-269, 84/08/07, 8408130149

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication ' Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408220468 Monthly operating repts for Jul 1984 W/840815 ltr
REAVIS, J A , TUCKER, H B Duke Power Co 84/07/31 17pp
26196 033 24X Fiche 50-269, 84/07/31, 8408220468

S Reportable occurrences, LERs & related correspondence

8408160417 RO 269/83-20 re trip shaft & bearing assembly portions of CRD breaker front frame assemblies Nine of 17 GE frames defective Util awaiting schedule for delivery of new frames
TUCKER, H B Duke Power Co 84/07/27 O'REILLY, J P Region 2, Office of Director 2pp 26106 074 24X Fiche 50-269, 84/07/27, 8408160417

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8408300244 Ack receipt of scope & objectives for 840621 emergency preparedness exercise Submittal fulfills min requirements for small-scale exercise Complete scenario will be reviewed when received & comments transmitted
DANCE, H C Region 2, Office of Director 84/05/21 TUCKER, H B
Duke Power Co 1p 26307 015 24X Fiche 50-269, 84/05/21, 8408300244

8408300427 Forwards FEMA "Oconee Nuclear Power Plant Full-Scale Local Exercise Conducted on 830406," final rept
DANCE, H C Region 2, Office of Director 84/07/11 TUCKER, H B
Duke Power Co 1p 26315 205 24X Fiche 50-269, 84/07/11, 8408300427

8408150326 Forwards public version of Rev 84-02 to "Emergency Plan Implementing Procedures "
TUCKER, H B Duke Power Co 84/07/17 O'REILLY, J P Region 2, Office of Director 1p 26099 001 24X Fiche 50-269, 84/07/17, 8408150326

--8408150335 Public version of Rev 84-02 to "Emergency Plan Implementing Procedures " W/JM Felton 840808 release memo
TUCKMAN, M S Duke Power Co 84/06/07 193pp 26099 002 24X
Fiche 50-269, 84/07/17, 8408150326

8408240416 Forwards Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/19 TUCKER, H B
Duke Power Co 1p 26237 113 24X Fiche 50-269, 84/07/19, 8408240416

--8408240421 Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations, maint, surveillance, ESF, emergency drills & fuel handling
BRYANT, J Region 2, Office of Director 84/07/19 6pp
26237 114 24X Fiche 50-269, 84/07/19, 8408240416

8408280361 Forwards Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/07/20 TUCKER, H B
Duke Power Co 2pp 26282 239 24X Fiche 50-269, 84/07/20, 8408280361

--8408280370 Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise
DECKER, T R Region 2, Office of Director 84/07/06 9pp
26282 241 24X Fiche 50-269, 84/07/20, 8408280361

8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/08/07 TUCKER, H B
Duke Power Co 2pp 26007 344 24X Fiche 50-269, 84/08/07, 8408130149

--8408130166 IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 73 21)
MOORE, D E Region 2, Office of Director 84/08/07 1p
26007 346 24X Fiche 50-269, 84/08/07, 8408130149

8408170329 Commits to assure that operators can obtain flashlight to assist in safe passage to standby shutdown facility, per requirements of 10CFR50, App R
TUCKER, H B Duke Power Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 26112 361 24X Fiche 50-269, 84/08/08, 8408170329

8408300357 Confirms 840806 telcon w/JP O'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50, fire protection & 10CFR73, physical protection Agenda encl
LEWIS, R C Region 2, Office of Director 84/08/08 TUCKER, H B
Duke Power Co 3pp 26314 222 24X Fiche 50-000, 84/08/08, 8408300357

8408200414 Forwards draft safety evaluation of procedures generation package for emergency operating procedures Response to open items re writers guide & validation/verification programs requested within 30 days of ltr receipt
RIVENBARK, G W Operating Reactors Branch 4 84/08/09 TUCKER, H B
Duke Power Co 2pp 26182 001 24X Fiche 50-269, 84/08/09, 8408200414

--8408200424 Draft safety evaluation of procedures generation package Package should be revised to address items in Section 2
* NRC - No Detailed Affiliation Given 84/08/09 11pp
26182 003 24X Fiche 50-269, 84/08/09, 8408200414

8408300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
TUCKER, H B Duke Power Co 84/08/10 Record Services Branch (Document Control Desk) 21pp 26332 353 24X
Fiche 50-000, 84/08/10, 8408300014

--8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations "
* Duke Power Co 84/08/15 30pp 26333 010 24X
Fiche 50-000, 84/08/10, 8408300014

--8408300028 Public version of revised crisis mgt plan implementing procedures, including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 memo
* Duke Power Co 84/08/15 170pp 26333 040 24X
Fiche 50-000, 84/08/10, 8408300014

8408220091 Forwards three exemption requests from 10CFR50, App R, Section III G 2 requirements re fire protection of safe shutdown capability, supplementing 831024 initial request No addl fees necessary
TUCKER, H B Duke Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 26193 289 24X Fiche 50-269, 84/08/14, 8408220091

8408310121 Requests extension of time to respond to 840720 ltr re util plans for establishing emergency operations facility design consistent w/requirements of Suppl 1 to NUREG-0737 Extension requested due to judicial review of util appeal
TUCKER, H B Duke Power Co. 84/08/24 DENTON, H R. Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 26329 243 24X Fiche 50-269, 84/08/24, 8408310121

Financial information

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER,H B Duke Power Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26237 137 24X
Fiche 50-000,84/08/16,8408240224

-8408240242 "1983 Annual Rept "
LEE,W S Duke Power Co 83/12/31 47pp 26237 167 24X
Fiche 50-000,84/08/16,8408240224

. Utility Final Safety Analysis Report (FSAR) & amends

8408220201 Forwards updated FSAR for Oconee Nuclear Station Info brings FSAR up to date as of 831231
TUCKER,H B Duke Power Co 84/08/15 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 1p 26191 023 24X Fiche 50-269,84/08/15,8408220201

-8408220208 Updated FSAR for Oconee Nuclear Station
* Duke Power Co 83/12/31 180pp 26191 024 24X
Fiche 50-269,84/08/15,8408220201

. Operating license stage documents & correspondence

8408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24X Fiche 50-000,84/07/27,
8408080288

8408200149 Application for amend to Licenses DPR-38,DPR-47 & DPR-55, updating Tech Spec 4 2 4 re reactor vessel matl surveillance to incorporate changes documented in BAW-1543 W/o stated fee
TUCKER,H B Duke Power Co 84/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 3pp 26133 286 24X Fiche 50-269,84/08/02,8408200149

-8408200155 Proposed Tech Spec 4 2 4 re reactor vessel matl surveillance NSHC evaluation encl
* Duke Power Co 84/08/02 7pp 26133 289 24X
Fiche 50-269,84/08/02,8408200149

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 10pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408200059 Application for amend to Licenses DPR-38,DPR-47 & DPR-55, revising air lock testing frequency from quarterly to semiannually Fee encl
TUCKER,H B Duke Power Co 84/08/08 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 3pp 26133 296 24X Fiche 50-269,84/08/08,8408200059

-8408200069 Proposed Tech Specs 4 4 1 5 2 (a),revising air lock testing frequency from quarterly to semiannually
* Duke Power Co 84/08/08 6pp. 26133 299 24X
Fiche 50-269,84/08/08,8408200059

8408220292 Forwards augmented response to Generic Ltr 83-28, Items 4 1 & 4 2 re reactor trip sys reliability vendor related mods & preventive maint & surveillance program for reactor trip breakers,respectively,per B31104 & 1230 ltrs
TUCKER,H B Duke Power Co 84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 6pp 26194 072 24X Fiche 50-269,84/08/10,8408220292

8408230527 Forwards payment for application fee re 840802 & 08 Tech Spec changes
BARR,S. Duke Power Co 84/08/15 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 1p 26236 286 24X Fiche 50-000,84/08/15,8408230527

8408270339 Application for amend to Licenses DPR-38,DPR-47 & DPR-55, revising Tech Specs re reactor bldg purge sys,protection from inadvertent low temp overpressurization & min operator staffing requirements
TUCKER,H B Duke Power Co 84/08/15 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 8pp 26244 307 24X Fiche 50-269,84/08/15,8408270339

--8408270345 Proposed Tech Specs,changing reactor bldg purge sys, protection from inadequate low temp overpressurization & min operator staffing requirements
* Duke Power Co 84/08/15 14pp 26244 315 24X
Fiche 50-269,84/08/15,8408270339

8408270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submittal of semiannual radioactive effluent release rept for Jul-Dec 1984
TUCKER,H B Duke Power Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 26279 112 24X Fiche 50-000,84/08/16,8408270160

--8408270169 Rev 4 to "Offsite Dose Calculation Manual "
BIRCH,M L , HAMPTON,J W Duke Power Co 84/07/18 39pp
26279 114 24X Fiche 50-000,84/08/16,8408270160

8408270464 Forwards list of questions generated during preliminary review of pump & valve inservice testing Conference call should be arranged w/staff able to provide appropriate technical expertise
STOLZ,J F Operating Reactors Branch 4 84/08/17 TUCKER,H B
Duke Power Co 10pp 26277 210 24X Fiche 50-269,84/08/17,
8408270464

8408270499 Forwards request for addl info re NUREG-0737,Item III D 3 4, "Control Room Habitability " Response requested within 30 days of ltr receipt
STOLZ,J F Operating Reactors Branch 3 84/08/17 TUCKER,H B
Duke Power Co 3pp 26277 039 24X Fiche 50-269,84/08/17,
8408270499

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

O Inspection reports, IE Bulletins & correspondence

8408280241 Informs of delay until 860301 to complete mods required by IE Bulletin 79-14 Delay due to increase in total number of mods required
TUCKER,H B Duke Power Co 84/08/21 O'REILLY,J P Region 2, Office of Director 2pp 26262 241 24X Fiche 50-269,84/08/21,
8408280241

8408240414 Forwards Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/19 TUCKER,H B
Duke Power Co 1p 26237 113 24X Fiche 50-269,84/07/19,
8408240414

--8408240421 Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations,maint,surveillance,ESF,emergency drills & fuel handling
BRYANT,J , SASSER,K , BROWNLEE,V L Region 2, Office of Director 84/07/19 6pp 26237 114 24X Fiche 50-269,84/07/19,8408240414

8408280361 Forwards Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified
DANCE,H C Region 2, Office of Director 84/07/20 TUCKER,H B
Duke Power Co 2pp 26282 239 24X Fiche 50-269,84/07/20,
8408280361

--8408280370 Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise
DECKER,T R , STANSBERRY,W W , CLINE,W E Region 2, Office of Director 84/07/06 9pp 26282 241 24X Fiche 50-269,84/07/20,
8408280361

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408280472 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14
LEWIS, R C Region 2, Office of Director 84/08/01 TUCKER, H B
Duke Power Co 1p 26282 045 24X Fiche 50-269, 84/08/01, 8408280472

--8408280476 Responds to NRC 840622 ltr re violations noted in Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 Corrective actions Procedure OP/O/A/1510/10 revised to require neutron shield tank level prior to offsite shipments
TUCKER, H B Duke Power Co 84/07/20 O'REILLY, J P Region 2, Office of Director 4pp 26282 046 24X Fiche 50-269, 84/08/01, 8408280472

--8408280479 Forwards Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 on 840604-08 & notice of violation
LEWIS, R C Region 2, Office of Director 84/06/22 TUCKER, H B
Duke Power Co 2pp 26282 050 24X Fiche 50-269, 84/08/01, 8408280472

--8408280481 Notice of violation from insp on 840604-08
* Region 2, Office of Director 84/06/22 2pp 26282 052 24X Fiche 50-269, 84/08/01, 8408280472

--8408280485 Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 on 840604-08 Noncompliance noted failure to verify presence & condition of neutron radiation moderator prior to shipping & failure to perform neutron radiation surveys
WEDDINGTON, R E , JENKINS, G R Region 2, Office of Director
84/06/19 8pp 26282 054 24X Fiche 50-269, 84/08/01, 8408280472

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/08/07 TUCKER, H B
Duke Power Co 2pp 26007 344 24X Fiche 50-269, 84/08/07, 8408130149

--8408130166 IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 73 21)
MOORE, D E , MCGUIRE, D R Region 2, Office of Director 84/08/07
1p 26007 346 24X Fiche 50-269, 84/08/07, 8408130149

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
ORACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 123pp, 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408220468 Monthly operating repts for Jul 1984 W/840815 ltr
REAVIS, J A , TUCKER, H B Duke Power Co 84/07/31 17pp
26196 033 24X Fiche 50-269, 84/07/31, 8408220468

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8408030052 Forwards SSER concluding that proposed mods for alternate safe shutdown are in accordance w/App R, Section II G 3 & III L requirements w/respect to control room & cable spreading room
VASSALLO, D B Operating Reactors Branch 2 84/07/24 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 25917 341 24X
Fiche 50-271, 84/07/24, 8408030052

--8408030057 SSER concluding that proposed mods for alternate safe shutdown are in accordance w/App R, Section II G 3 & III L requirements w/respect to control room, cable spreading room & switchgear room
* Operating Reactors Branch 2 84/07/24 2pp 25917 343 24X
Fiche 50-271, 84/07/24, 8408030052

8408080041 Requests exemption from requirements of Section IV F of App E to 10CFR50 re annual emergency preparedness exercise Event on 840613 resulted in complete implementation of emergency plan to alert level
MURPHY, W P Vermont Yankee Nuclear Power Corp 84/08/06
EISENHUT, D G Division of Licensing 5pp. 25970 301 24X
Fiche 50-271, 84/08/06, 8408080041

8408270461 Forwards Insp Rept 50-271/84-16 on 840717-19 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/08/08
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp. 26256 230
24X Fiche 50-271, 84/08/08, 8408270461

--8408270465 Insp Rept 50-271/84-16 on 840717-19 No violations noted Major areas inspected changes to emergency preparedness program, shift staffing & augmentation, knowledge & performance of duties & public info program
WOLTNER, E , SMITH, R W Region 1, Office of Director CROCKER, H W
Division of Engineering & Technical Programs 84/08/07 3pp
26256 232 24X Fiche 50-271, 84/08/08, 8408270461

8408240292 Requests addl compensatory measures be documented & sent to Region I ofc for App R deficiencies identified by Insp Rept 50-271/83-26
MARTIN, T T Division of Engineering & Technical Programs 84/08/22
MURPHY, W P Vermont Yankee Nuclear Power Corp. 2pp 26223.190
24X Fiche 50-271, 84/08/22, 8408240292

8408310093 Requests extension of schedule for implementation of upgraded emergency operating procedures until 850601, due to need to complete operator training on procedures, per Suppl 1 to NUREG-0737
MURPHY, W P Vermont Yankee Nuclear Power Corp 84/08/22
VASSALLO, D B Operating Reactors Branch 2 2pp 26323 200 24X
Fiche. 50-271, 84/08/22, 8408310093

8408160357 Rev 5 to emergency plan, "Ltrs of Agreement "
* Yankee Atomic Electric Co 84/08/31 27pp. 26091 206 24X
Fiche 50-271, 84/08/31, 8408160357

I General correspondence

8408310279 Requests that NRC make listed change to "list copies" re License DPR-28 JB Sinclair should be deleted from lists & RW Capstick added
CAPSTICK, R W Vermont Yankee Nuclear Power Corp 84/08/24
Office of Nuclear Reactor Regulation, Director 1p 26333 287 24X
Fiche 50-271, 84/08/24, 8408310279

Operating license stage documents & correspondence

8408150578 Forwards FR notice of environ assessment & finding of no significant impact, in response to 840530 request for exemption to permit 6-month extension for updating FSAR
VASSALLO, D B Operating Reactors Branch 2 84/07/30 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 26104 002 24X
Fiche 50-271, 84/07/30, 8408150578

--8408150585 Notice of environ assessment & finding of no significant impact, based on granting 6-month extension for updating FSAR
EISENHUT, D G Division of Licensing 84/07/30 4pp 26104 004
24X Fiche 50-271, 84/07/30, 8408150578

8408150599 Forwards Amend 82 to License DPR-28 & safety evaluation
Amend deletes requirement for automatic air dump sys
VASSALLO, D B Operating Reactors Branch 2 84/08/01 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 26105 351 24X
Fiche 50-271, 84/08/01, 8408150599

--8408150604 Amend 82 to License DPR-28, deleting requirement for automatic air dump sys
VASSALLO, D B Operating Reactors Branch 2 84/08/01 2pp
26105 353 24X Fiche 50-271, 84/08/01, 8408150599

--8408150606 Safety evaluation supporting Amend 82 to License DPR-28
* Office of Nuclear Reactor Regulation, Director 84/08/01 2pp
26105 355 24X Fiche 50-271, 84/08/01, 8408150599

8408160161 Grants util 840725 request for extension of environ qualification of electrical equipment to 850331
Justifications for continued operation acceptable Unfinished items should be qualified by 851130
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/08/02 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 3pp
26124 359 24X Fiche 50-271, 84/08/02, 8408160161

8408160090 Accepts corrective actions taken to repair recirculation sys piping, per 840726 meeting w/NRC Plant restart authorized
VASSALLO, D B Operating Reactors Branch 2 84/08/03 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 26126 341 24X
Fiche 50-271, 84/08/03, 8408160090

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160052 Forwards Rev 2 to "Environ Qualification Master Equipment List " Requests rev be reflected in SER for purposes of future IE audit of compliance w/10CFR50 49
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 84/08/10
VASSALLO, D B Operating Reactors Branch 2 2pp 26092, 079 24X
Fiche 50-271, 84/08/10, 8408160052

--8408160056 Rev 2 to "Environ Qualification Master Equipment List "
* Vermont Yankee Nuclear Power Corp 84/08/10 26pp 26092 077
24X Fiche 50-271, 84/08/10, 8408160052

8408240004 Requests extension until 841101 for responding to Generic Ltr 84-15 re diesel generator reliability Delay due to extensive engineering efforts associated w/8-wk 1984 refueling outage
MURPHY, W P Vermont Yankee Nuclear Power Corp 84/08/16
EISENHUT, D G Division of Licensing 1p 26228 252 24X
Fiche 50-271, 84/08/16, 8408240004

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & -- licants for OLs re scheduling guidance for licensee ittals of reloads that involve unreviewed safety tions Svc list encl
UT, D G Division of Licensing 84/08/20 Consolidated
Co of New York, Inc 17pp 26276 244 24X
000, 84/08/20, 8408200275

8408280055 Responds to 840508 request for review of applicability of generic studies submitted by Mark I Owners Group re recombiner capability requirements of 10CFR50 44(c)(3)(ii)
Util meets conditions to take credit for studies
KADAK, A C Vermont Yankee Nuclear Power Corp 84/08/24
VASSALLO, D B Operating Reactors Branch 2 3pp 26261 227 24X
Fiche 50-271, 84/08/24, 8408280055

G Inspection reports, IE Bulletins & correspondence

8408090085 Requests NRC withdraw violations noted in IE Insp Rept 50-271/84-02 for listed reasons
MURPHY, W P Vermont Yankee Nuclear Power Corp 84/05/08
MARTIN, T T Division of Engineering & Technical Programs 4pp
25993 254 24X Fiche 50-271, 84/05/08, 8408090085

--8408090098 Ack receipt of 840508 ltr informing NRC of objection to violations noted in IE Insp Rept 50-271/84-02 Violations valid Corrective actions requested within 20 days of ltr date
MARTIN, T T Division of Engineering & Technical Programs
84/07/25 MURPHY, W P Vermont Yankee Nuclear Power Corp 3pp
25993 258 24X Fiche 50-271, 84/05/08, 8408090085

8408030222 Forwards IE Insp Rept 50-271/84-10 on 840508-0604 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/07/12
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 25917 153
24X Fiche 50-271, 84/07/12, 8408030222

--8408030224 Notice of violation from insp on 840508-0604
* Region 1, Office of Director 84/07/12 1p 25917 155 24X
Fiche 50-271, 84/07/12, 8408030222

--8408030229 IE Insp Rept 50-271/84-10 on 840508-0604 Noncompliance noted failure of instrument & control personnel to complete testing in accordance w/OP 4374
RAYMOND, W J , GALLO, R M Region 1, Office of Director 84/06/28
18pp 25917 156 24X Fiche 50-271, 84/07/12, 8408030222

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Past 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408020082 Forwards POE-1021, "1984 Refuel Outage Augmented Inservice Insp Program," final rept Program implemented to address concerns detailed in IE Bulletin 83-02
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 84/07/30
VASSALLO, D M Operating Reactors Branch 2 2pp 25892 009 24X
Fiche 50-271, 84/07/30, 8408020082

--8408020097 "1984 Refuel Outage Augmented Inservice Insp Program," final rept
* Yankee Atomic Electric Co 84/07/30 247pp 25892 011 24X
Fiche 50-271, 84/07/30, 8408020082

8408060226 Forwards supplemental info re refueling outage augmented inservice insp program, addressing concerns of IE Bulletin 83-02 & Generic Ltr 84-11
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 84/07/31
VASSALLO, D B Operating Reactors Branch 2 20pp 25923 335 24X
Fiche 50-271, 84/07/31, 8408060226

8408230139 Forwards IE Insp Rept 50-271/84-13 on 840625-29 & 0712-13
No violations observed
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 26214 019
24X Fiche 50-271, 84/08/01, 8408230139

--8408230143 IE Insp Rept 50-271/84-13 on 840625-29 & 0712-13 No violations identified Major areas inspected augmented ultrasonic exam of recirculation sys piping per Generic Ltr 84-11 & review of inservice insp program
MCBREARTY, R A Region 1, Office of Director DURR, J P Division of Engineering & Technical Programs 84/07/27 7pp 26214 021
24X Fiche 50-271, 84/08/01, 8408230139

8408150261 Summary of 840726 meeting w/util in Bethesda, MD re pipe crack insps performed during 1984 refueling outage Results of insps justify plant operation during 1984/85 operating cycle Licensee presentation & list of attendees encl
ROONEY, V L Operating Reactors Branch 2 84/08/02 Operating
Reactors Branch 2 57pp 26105 011 24X Fiche 50-271, 84/08/02, 8408150261

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 05pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement ' Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408270461 Forwards Insp Rept 50-271/84-16 on 840717-19 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/08/08
MURPHY,W P Vermont Yankee Nuclear Power Corp 2pp 26256 230
24X Fiche 50-271,84/08/08,8408270461

--8408270465 Insp Rept 50-271/84-16 on 840717-19 No violations noted
Major areas inspected changes to emergency preparedness program,shift staffing & augmentation,knowledge & performance of duties & public info program
WOLTNER,E , SMITH,R W Region 1, Office of Director CROCKER,H W Division of Engineering & Technical Programs 84/08/07 3pp
26256 232 24X Fiche 50-271,84/08/08,8408270461

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness * Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408240292 Requests addl compensatory measures be documented & sent to Region 1 ofc for App R deficiencies identified by Insp Rept 50-271/83-26
MARTIN,T T Division of Engineering & Technical Programs 84/08/22
MURPHY,W P Vermont Yankee Nuclear Power Corp 2pp 26223 190
24X Fiche 50-271,84/08/22,8408240292

R Periodic operating reports & related correspondence

8408270152 Monthly operating rept for Jul 1984 W/840810 ltr
BURGER,F J , MURPHY,W P Vermont Yankee Nuclear Power Corp
84/07/31 7pp 26257 299 24X Fiche 50-271,84/07/31,8408270152

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,G G General Electric Co 84/04/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000,84/04/13,8408240348

8408080041 Requests exemption from requirements of Section IV F of App E to 10CFR50 re annual emergency preparedness exercise Event on 840615 resulted in complete implementation of emergency plan to alert level
MURPHY,W P Vermont Yankee Nuclear Power Corp 84/08/06
EISENHUT,D G Division of Licensing 5pp 25970 301 24X
Fiche 50-271,84/08/06,8408080041

8408230534 LER 84-011-01 on 840616,while performing Type C leak rate testing,valves MSIV-86D,CRD-412A,PCAC V16-19-8,FDW-96A & CA-89C found w/seat leakage above Tech Spec limits Maint performed & valves retested W/840816 ltr
PELLETIER,J P Vermont Yankee Nuclear Power Corp 84/08/16 4pp
26212 348 24X Fiche 50-271,84/08/16,8408230534

8408230542 LER 84-012-00 on 840717,contractor failed to properly tag out reactor bldg air conditioning unit,causing supply line 2 to inspire into svc water sys Caused by personnel error Sys isolated W/840816 ltr
PELLETIER,J P Vermont Yankee Nuclear Power Corp 84/08/16 5pp
26212 356 24X Fiche 50-271,84/08/16,8408230542

8408280307 LER 84-013-00 on 840721,during maint on standby liquid control sys,relief valves SR-11-39A & B found to have setpoints below required range Caused by testing technique Valves reset,retested & reinstalled W/840820 ltr
PELLETIER,J P Vermont Yankee Nuclear Power Corp 84/08/20 3pp
26282 163 24X Fiche 50-271,84/08/20,8408280307

8408300478 LER 84-014-00 on 840723,during weekly environ air sample collections,Sample Station AT 1 2 discovered not drawing continuous sample Caused by blown main fuse Fuse replaced & equipment returned to svc W/840820 ltr
PELLETIER,J P Vermont Yankee Nuclear Power Corp 84/08/20 3pp
26314 092 24X Fiche 50-271,84/08/20,8408300478

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA,R General Electric Co 84/08/21 ROSSI,C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000,84/08/21,8408310186

8408300488 LER 84-015-00 on 840724,during second verification that diesel generator B 4 kV bus pot fuse drawer racked in, operator inadvertently withdrew drawer Caused by insufficent instructions W/840823 ltr
PELLETIER,J P Vermont Yankee Nuclear Power Corp 84/08/23 3pp
26314 012 24X Fiche 50-271,84/08/23,8408300488

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408030236 Ack receipt of 840608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10
BELLAMY,R R Division of Engineering & Technical Programs
84/07/18 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp 25917 192 24X Fiche 50-272,84/07/18,8408030236

--8408030247 Responds to NRC 840504 ltr re violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10 Corrective actions revised emergency plan brochure distributed in Feb 1984 & emergency response training program undergoing review & evaluation
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/06/08 MARTIN,T T Region 1, Office of Director 8pp
25917 194 24X Fiche 50-272,84/07/18,8408030236

8408070065 Forwards corrected page to 840612 confirmatory order, confirming Dec 1986 schedule for implementation of Suppl 1 to NUREG-0737 & Generic Ltr 82-33 re completion of structural mods to technical support ctr W/o encl
VARGA,S A Operating Reactors Branch 1 84/07/26 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 3pp 25955 319,
24X Fiche 50-272,84/07/26,8408070065

8408100093 Advises that 840106 Rev 8 to Amend 3 to physical security plan & contingency plan consistent w/provisions of 10CFR50 54(p) & acceptable
MARTIN,T T Division of Engineering & Technical Programs 84/08/02
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 3pp
25991 001 24X Fiche 50-272,84/08/02,8408100093

8408150223 Forwards responses to 840504 ltr re INEL rept on util conformance to Reg Guide 1 97 requirements for emergency response capability & Suppl 1 to NUREG-0737 Changes to 830921 implementation plan listed
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/09 VARGA,S A Operating Reactors Branch 1 9pp 26066 081
24X Fiche 50-272,84/08/09,8408150223

8408210408 Informs that FEMA does not intend to conduct full-scale evaluation of Hope Creek 1985 exercise Since Salem Unit 1 OL issued prior to 820713,full participation in 1985 not required by NRC or FEMA rules
KRIMM,R W Federal Emergency Management Agency 84/08/13
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 26177 296 24X Fiche 50-000,84/08/13,
8408210408

8408220428 Notification of 840906 meeting w/util in Bethesda,MD to discuss addl App R exemptions
FISCHER,D C Operating Reactors Branch 1 84/08/16 VARGA,S A
Operating Reactors Branch 1 2pp 26201 362 24X
Fiche 50-272,84/08/16,8408220428

H General correspondence

8408230056 Responds to 840727 ltr transmitting SL Benavidez 840627 concerns re failure of reactor trip sys of nuclear plants NRC established 10CFR50 62,which requires addl features be installed at each reactor to assure shutdown if sys fails
DIRCKS,W J Office of the Executive Director for Operations
84/08/15 DOMENICI,P V Senate 6pp 26233 275 24X
Fiche 50-000,84/08/15,8408230056

--8408230063 Requests response to encl SL Benavidez 840627 ltr re scram sys in nuclear reactors
DOMENICI,P V Senate 84/07/27 KAMMERER,C C NRC - No Detailed Affiliation Given 8pp 26233 280 24X Fiche 50-000,84/08/15,
8408230056

K Utility Final Safety Analysis Report (FSAR) & amends

8408020100 Forwards Rev 3 to updated FSAR for Salem Generating Station, Units 1 & 2 Changes made per 10CFR50 59,but not previously submitted to NRC,identified in monthly operating repts
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/07/23 VARGA,S A Operating Reactors Branch 1 6pp 25910 076
24X Fiche 50-272,84/07/23,8408020100

--8408020109 Rev 3 to updated FSAR for Salem Generating Station, Units 1 & 2
* Public Service Electric & Gas Co of New Jersey 84/07/22
439pp 25910 082 24X Fiche 50-272,84/07/23,8408020100

P. Operating license stage documents & correspondence

8408150245 Forwards revs to Cycle 2 startup rept & safety evaluation of util rod exchange methodology
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/07/30 VARGA,S Operating Reactors Branch 1 10pp 26075 299
24X Fiche 50-272,84/07/30,8408150245

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues," Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408200343 Forwards drawing of proposed upgraded core exit thermocouple sys showing layout of major components,per TMI Item II F 2
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/13 VARGA,S A Operating Reactors Branch 1 4pp 26131 081
24X Fiche 50-272,84/08/13,8408200343

8408210554 Requests listed addl info re environ qualification of electrical equipment important to safety & remaining outstanding justifications for continued operation Addl info requested by 840827
VARGA,S A Operating Reactors Branch 1 84/08/13 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 2pp 26195 259
24X Fiche 50-272,84/08/13,8408210554

8408210335 Submits addl info to support 840621 request for relief from Articles IWB 5222 & IWC 5200 of ASME Boiler & Pressure Vessel Code,Section XI Relief required because no viable means of heating certain components exists
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/15 VARGA,S A Operating Reactors Branch 1 2pp 26179 340
24X Fiche 50-272,84/08/15,8408210335

8408240117 Forwards suppl to 830422 response to Generic Ltr 83-10D re plan for resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps"
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/15 VARGA,S A Operating Reactors Branch 1 5pp 26228 224
24X Fiche 50-272,84/08/15,8408240117

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408280330 Requests remittance of addl fee for review of 790209 & 810810 applications to amend Licenses DPR-70 & DPR-75
MILLER,W O License Fee Management Branch 84/08/20 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 2pp 26294 081
24X Fiche 50-272,84/08/20,8408280330

Q Inspection reports, IE Bulletins & correspondence

8408030259 Forwards IE Insp Repts 50-272/84-21 & 50-311/84-21 on 840529-0601 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/07/11
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
25917 244 24X Fiche 50-272,84/07/11,8408030259

--8408030267 IE Insp Repts 50-272/84-21 & 50-311/84-21 on 840529-0601 No violations noted Major areas inspected radiation protection program,including ALARA implementation,external exposure control & surveillance & posting
DRAGOUN,T , SHANBAKY,M Region 1, Office of Director 84/07/09
9pp 25917 246 24X Fiche 50-272,84/07/11,8408030259

8408030236 Ack receipt of 840608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10
BELLAMY,R R Division of Engineering & Technical Programs
84/07/18 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp 25917 192 24X Fiche 50-272,84/07/18,8408030236

--8408030247 Responds to NRC 840504 ltr re violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10 Corrective actions revised emergency plan brochure distributed in Feb 1984 & emergency response training program undergoing review & evaluation
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/06/08 MARTIN,T T Region 1, Office of Director 8pp
25917 194 24X Fiche 50-272,84/07/18,8408030236

8408150631 Forwards IE Insp Rept 50-272/84-22 on 840530-0608 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/07/24
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
26079 056 24X Fiche 50-272,84/07/24,8408150631

--8408150634 IE Insp Rept 50-272/84-22 on 840530-0608 No violations noted Major areas inspected licensee action on previous insp findings,inservice insp program & related activities, including observation of work in progress of NDE data
MCBREARTY,R A , DURR,J P Region 1, Office of Director 84/07/09
7pp 26079 058 24X Fiche 50-272,84/07/24,8408150631

8408150366 Forwards IE Insp Repts 50-272/84-23 & 50-311/84-23 on 840609-0706 & notice of violation Both aspects of violation, including failure to include mechanical snubbers in formal snubber surveillance program,should be addressed
STAROSTECKI,R Division of Project & Resident Programs 84/07/25
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
26075 166 24X Fiche 50-272,84/07/25,8408150366

--8408150368 Notice of violation from insp on 840609-0706
* Region 1, Office of Director 84/07/25 1p 26075 168 24X
Fiche 50-272,84/07/25,8408150366

--8408150370 IE Insp Repts 50-272/84-23 & 50-311/84-23 on 840609-0706 Violation noted failure to establish procedure to perform functional testing of safety-related equipment & mechanical snubbers
LINVILLE,J C , SUMMERS,R J , GRAY,E H Region 1, Office of Director 84/07/23 11pp 26075 169 24X Fiche 50-272,84/07/25,
8408150366

8407250229 IE Info Notice 84-57, Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408030027 Forwards IE Mgt Meeting Repts 50-272/84-30 & 50-311/84-29 on 840719
STAROSIECKI,R Division of Project & Resident Programs 84/07/30
UDERITZ,R Public Service Electric & Gas Co of New Jersey 2pp
25907 077 24X Fiche 50-272,84/07/30,8408030027

--8408030031 IE Mgt Meeting Repts 50-272/84-30 & 50-311/84-29 on 840719 Major areas discussed responsiveness of action plan for improvement of nuclear dept operations,submitted to NRC in Aug 1983,to recent insp findings
LINVILLE,J C , NORRHOLM,L J Region 1, Office of Director
84/07/26 3pp 25907 079 24X Fiche 50-272,84/07/30,8408030027

8408200043 Forwards IE Insp Repts 50-272/84-24 & 50-311/84-24 on 840529 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/07/30
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
26140 210 24X Fiche 50-272,84/07/30,8408200043

--8408200052 IE Insp Repts 50-272/84-24 & 50-311/84-24 on 840529 No violations noted Major areas inspected circumstances surrounding transportation accident near Rock Springs,WY, including shipping documentation,waste packaging & shipment
EVERETT,R J , HALL,R E Region 1, Office of Director 84/06/18
3pp 26140 212 24X Fiche 50-272,84/07/30,8408200043

8408070232 Forwards IE Mgt Meeting Repts 50-272/84-30 & 50-311/84-29 on 840719
STAROSTECKI,R Division of Project & Resident Programs 84/08/02
UDERITZ,R Public Service Electric & Gas Co of New Jersey 2pp
25948 233 24X Fiche 50-272,84/08/02,8408070232

--8408070237 IE Mgt Meeting Repts 50-272/84-30 & 50-311/84-29 on 840719 Major areas discussed status of action plan for improvement of nuclear dept operations,including responsiveness to insp findings
LINVILLE,J,C , NORRHOLM,L J Region 1, Office of Director
84/07/26 68pp 25948 235 24X Fiche 50-272,84/08/02,8408070232

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408310131 Responds to 830106 ltr,840131 telcon & 840626 meeting re violation in Insp Repts 50-272/83-29 & 50-311/83-31 Violation will be withdrawn & concern will be classified as open item
MARTIN,T T Division of Engineering & Technical Programs 84/08/21
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
26322 260 24X Fiche 50-272,84/08/21,8408310131

R Periodic operating reports & related correspondence

8408160142 Forwards Nuclear Oversight Committee quarterly rept dtd 840731
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/03 VARGA,S Operating Reactors Branch 1 6pp 26108 075
24X Fiche 50-272,84/08/03,8408160142

S Reportable occurrences, LERs & related correspondence

8408160276 LER 84-018-00 on 840713,inadvertent safety injection signal occurred due to personnel error Caused by failure to follow procedure Technicians counseled about responsibilities W/ 840810 ltr
RUPP,J L , ZUPKO,J M Public Service Electric & Gas Co of New Jersey 84/08/10 5pp 26108 167 24X Fiche 50-272,84/08/10, 8408160276

8408230501 LER 84-017-00 on 840716,insp revealed metal filings in charging pump casings Filings may have caused 840713 seizure of charging pump 12 & seizure of redundant centrifugal charging pump Investigation continuing W/840816 ltr
RUPP,J L , ZUPKO,J W Public Service Electric & Gas Co of New Jersey 84/08/16 5pp 26212 259 24X Fiche 50-272,84/08/16, 8408230501

8408310065 PNS-I-84-017 on 840827,unidentified male telephoned security post at Elevation 100 ft of Unit 1 on internal line & told security guard that bomb planted in containment Bomb search teams deployed No bomb found No explosion occurred
DUNLAP,J , KEIMIG,R , JOYNER,J Region 1, Office of Director
84/08/27 1p 26323 203 24X Fiche 50-272,84/08/27,8408310065

DOCKET 50-274 U S GEOLOGICAL SURVEY RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408200121 Advises of implementation of emergency plan
RUSLING,D H Interior, Dept of, Geological Survey 84/08/08
THOMAS,C O Standardization & Special Projects Branch 1p
26139 306 24X Fiche 50-274,84/08/08,8408200121

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

D, NRC Draft/Final Environmental Statements, supplS & correspondence

8408140273 Forwards 69 photos attesting to serious long-range problems of erosion of siltation on property contiguous to facility Requests name of responsible NRC employee to respond to concerns
BRUNO,G E Affiliation Not Assigned 83/07/11 DENTON,H Office of Nuclear Reactor Regulation, Director 38pp 26051 203 24X Fiche 50-275,83/07/11,8408140273

E NRC Safety Evaluation Report (SER), supplS & correspondence

8407310038 Board Notification 84-137 forwards SSERs 24-27 re IDVP matters,piping & supports,allegations - status & summary & full power license amend matters,respectively No substantive changes made W/o encls
EISENHUT,D G Division of Licensing 84/07/30 PALLADINO, ROBERTS, ASSELSTINE Commissioners 3pp 26011 015 24X
Fiche 50-275,84/07/30,8407310038

DOCKETED ITEMS

8408130002 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT,UNITS 1 & 2 Docket Nos 50-275 & 50-323 (Pacific Gas & Electric Company)
* Division of Licensing NUREG-0675 S24 84/07/31 16pp
26038 295 24X Fiche 50-275,84/07/31,8408130002

8408160080 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT,UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Pacific Gas And Electric Company)
* Division of Licensing NUREG-0675 S25 84/07/31 122pp
Available at NRC $5 50 26124 033 24X Fiche 50-275,84/07/31, 8408160080

8408160250 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT,UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Pacific Gas And Electric Company)
* Division of Licensing NUREG-0675 S27 84/07/31 31pp
Available at NRC $3 50 26122 235 24X Fiche 50-275,84/07/31, 8408160250

8408220346 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT,UNITS 1 AND 2
* Division of Licensing NUREG-0675 S26 84/07/31 204pp
Available at NRC $6 50 26200 001 24X Fiche 50-275,84/07/31, 8408220346

8408230379 Forwards SSERs 24-27 (NUREG-0675) Distribution of svc list includes SSERs 25-27 since Board Notification 84-137 issued
SSER 24 W/o encl
KNIGHTON,G W Licensing Branch 3 84/08/10 SCHUYLER,J O Pacific Gas & Electric Co 4pp 26230 334 24X Fiche 50-275,84/08/10, 8408230379

F Security, medical, emergency & fire protection plans

8408080453 Forwards public version of revs to Vol III of San Luis Obispo County emergency response plan std operating procedures
SCHUYLER,J O Pacific Gas & Electric Co 84/07/16 MARTIN,J B
Region 5, Office of Director 2pp 25976 071 24X
Fiche 50-275,84/07/16,8408080453

--8408080458 Public version of revs to Vol III of San Luis Obispo County emergency response std operating procedures (SOP), including Section III 01, "SOP Emergency Svcs Director" W/Felton 840802 release memo
SCHUYLER,J O Pacific Gas & Electric Co 84/02/29 434pp
25976 073 24X Fiche 50-275,84/07/16,8408080453

8408160267 Forwards public version of emergency plan implementing procedures, including EP R-1 re personnel injury or illness (radiological related) &/or overexposure & EP M-1 re employee injury or illness (nonradiological)
SCHUYLER,J O Pacific Gas & Electric Co 84/07/20 MARTIN,J B
Region 5, Office of Director 4pp 26125 239 24X
Fiche 50-275,84/07/20,8408160267

--8408160273 Public version of emergency plan implementing procedures, including EP R-1 re personnel injury or illness (radiological related) &/or overexposure W/JM Felton 840808 release memo
* Pacific Gas & Electric Co 84/07/20 138pp 26125 243 24X
Fiche 50-275,84/07/20,8408160267

8408230553 Forwards public version of updated emergency plan implementing procedures, including EP R-1 re personnel injury or illness (radiologically related) &/or overexposure & EP O-4 re personnel accountability & assembly
SCHUYLER,J O Pacific Gas & Electric Co 84/08/08 MARTIN,J B
Region 5, Office of Director 1p 26216 206 24X
Fiche 50-275,84/08/08,8408230553

--8408230558 Public version of updated emergency plan implementing procedures, including EP R-1 re personnel injury or illness (radiologically related) &/or overexposure & EP O-4 re personnel accountability & assembly W/840820 release memo
THORNBERRY,R C Pacific Gas & Electric Co 84/08/08 182pp
26216 207 24X Fiche 50-275,84/08/08,8408230553

8408230300 Forwards RW Krimm 840711 ltr transmitting FEMA interim finding in State of CA emergency response plan Plan adequate Areas for improvement identified, including protective action guideline doses
KNIGHTON,G W Licensing Branch 3 84/08/16 SCHUYLER,J O Pacific Gas & Electric Co 3pp 26236 105 24X Fiche 50-275,84/08/16, 8408230300

8408310230 Revised emergency plan implementing procedures, including EP R-2 re release of airborne radioactive matls,EP EI-6 re EARS 9045c controling stations & EP RB-15 * 16 re sentry post accident sampling sys W/840827 ltr
SCHUYLER,J O Pacific Gas & Electric Co 84/08/27 MARTIN,J B
Region 5, Office of Director 363pp 26321 001 21X
Fiche 50-275,84/08/27 8408310230

O Adjudicatory correspondence

8408010235 Forwards affidavit of JL McDermott,per 840729 submittal Supporting brief will be sent to Commission on 840730 along w/O'Neill rebuttal affidavit
DEVINE T Government Accountability Project DSB 681 84/07/30
PALLADINO,N J , ROBERTS,T , ASSELSTINE,J Commissioners 1p
25854 001 24X Fiche 50-275,84/07/30,8408010235

--8408010237 Affidavit of JL McDermott re need for reinsps & systematic retraining of all personnel at facility
MCDERMOTT,J L Government Accountability Project 84/07/30
35pp 25854 002 24X Fiche 50-275,84/07/30,8408010235

8408060046 Motion for leave to withdraw confidential Exhibit 10 filed in support of Joint Intervenors 840214 motion to augment or reopen record Declaration in support of motion & Certificate of Svc encl
REYNOLDS,J R Joint Intervenors - Diablo Canyon REYNOLDS,J R
Center for Law in the Public Interest DSB 696 84/07/30 Atomic
Safety and Licensing Appeal Panel 9pp 25925 298 24X
Fiche 50-275,84/07/30,8408060046

8408060217 Motion for leave to withdraw confidential exhibit previously filed in support of motion to augment or to reopen record Declaration encl Granted on 840731
REYNOLDS,J R Joint Intervenors - Diablo Canyon REYNOLDS,J R
Center for Law in the Public Interest DSB 709 84/07/30 Atomic
Safety and Licensing Appeal Panel 6pp 25927 015 24X
Fiche 50-275,84/07/30,8408060217

8408070297 Motion for leave to withdraw confidential exhibit previously filed in support of 840214 motion to augment or in alternative, to reopen record Declaration & Certificate of Svc encl
REYNOLDS,J R Joint Intervenors - Diablo Canyon DSB 809
84/07/30 Atomic Safety and Licensing Appeal Panel 9pp
25947 297 24X Fiche 50-275,84/07/30,8408070297

8408020152 Forwards suppl supporting T O'Neill 840727 petition under 10CFR2 206 on behalf of J McDermott & T O'Neill Also expands original request for retraining
DEVINE,T Government Accountability Project DSB 701 84/07/31
PALLADINO,N J Commissioners 327pp 25884 139 24X
Fiche 50-275,84/07/31,8408020152

8408020219 Order requiring Joint Intervenors to file reply addressing jurisdictional question in 840716 motion to reopen record on seismic issues Served on 840801
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel DSB 716
84/08/01 Joint Intervenors - Diablo Canyon 1p 25898 009 24X
Fiche 50-275,84/08/01,8408020219

8408020222 Answer opposing Joint Intervenors 840725 application for stay re effectiveness of ASLB 820831 Initial Decision LBP-84-20 & of issuance of full power OL
CHANDLER,L J Hearing Branch 2 DSB 710 84/08/01
Commissioners 11pp 25897 279 24X Fiche 50-275,84/08/01, 8408020222

--8408020227 Answer opposing Joint Intervenors 840717 petition for review of ALAB-775 Petition fails to establish existence of important issue of fact,law or policy warranting Commission review
CHANDLER,L J Hearing Branch 2 84/08/01 Commissioners
10pp 25897 290 24X Fiche 50-275,84/08/01,8408020222

--8408020231 Answer opposing Joint Intervenors 840717 petition for review of ALAB-776 Petition fails to establish existence of important question of fact,law or policy re ALAB-776
CHANDLER,L J Hearing Branch 2 84/08/01 Commissioners
23pp 25897 300 24X Fiche 50-275,84/08/01,8408020222

--8408020233 Answer opposing Joint Intervenors 840716 motion to reopen record on seismic issues Motion fails to satisfy stds for reopening record Certificate of Svc encl
CHANDLER,L J Hearing Branch 2 84/08/01 Atomic Safety and Licensing Appeal Panel 41pp 25897 323 24X
Fiche 50-275,84/08/01,8408020222

--8408020233 Answer opposing Joint Intervenors 840716 motion to reopen record on seismic issues Motion fails to satisfy stds for reopening record Certificate of Svc encl
CHANDLER, L J Hearing Branch 2 84/08/01 Atomic Safety and Licensing Board Panel 41pp 25897 323 24X
Fiche 50-275, 84/08/01, 8408020222

8408030154 Underscores need for prompt & favorable action on Northern California Power Agency 811204 petition under 10CFR2 206 to enforce & modify license conditions, based on recent evidence that util continues to violate license conditions
MCDIARMID, R C Spiegel & McDiarmid 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 592pp 25914 075 24X
Fiche 50-275, 84/08/01, 8408030154

8408020197 Advises that time for Commission to review ALAB-756 expired Commission declined review Decision became final agency action on 840727 Served on 840802
CHILK, S J Office of the Secretary of the Commission DSB 717
84/08/02 REYNOLDS, J R , HAVIAN, E , PHILLIPS, J Center For Law in the Public Interest 1p 25898 001 24X Fiche 50-275, 84/08/02, 8408020197

8408020206 Advises that time for Commission to review ALAB-756 expired Commission declined review Decision became final agency action on 840726 Served on 840802
CHILK, S J Office of the Secretary of the Commission DSB 718
84/08/02 STRUMWASSER, M California, State of 1p 25898 007
24X Fiche 50-275, 84/08/02, 8408020206

8408070265 Order extending time until 840810 for Commission to act to review Director's Decision DD-84-8 Served on 840806
CHILK, S J Office of the Secretary of the Commission DSB 756
84/08/03 Commissioners 1p 25949 239 24X
Fiche 50-275, 84/08/03, 8408070265

8408070361 Order extending time until 840830 for Commission to act to review ALAB-776 Served on 840806
CHILK, S J Office of the Secretary of the Commission DSB 755
84/08/03 Commissioners 1p 25945 177 24X
Fiche 50-275, 84/08/03, 8408070361

8408070467 Order extending time until 840810 for Commission to act to review ALAB-763 Served on 840806
CHILK, S J Office of the Secretary of the Commission DSB 752
84/08/03 Commissioners 1p 25940 341 24X
Fiche 50-275, 84/08/03, 8408070467

8408090183 Order ALAB-775A denying 840628 motion to reopen record on basis of addl info provided by applicant re use of A307 hardware bolts Allegation does not present new evidence Served on 840808
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel DSB 848
84/08/08 Joint Intervenors - Diablo Canyon 2pp 25972 286
24X Fiche 50-275, 84/08/09, 8408090183

8408130389 Reply supporting ASLAB 840801 order establishing jurisdiction of ASLAB to review Joint Intervenor 840716 motion to reopen record on seismic issues Certificate of Svc encl
REYNOLDS, J R Joint Intervenors - Diablo Canyon REYNOLDS, J R
Center for Law in the Public Interest DSB 906 84/08/09 Atomic Safety and Licensing Appeal Panel 8pp 26011 094 24X
Fiche 50-275, 84/08/09, 8408130389

8408140464 Reply re jurisdiction of ASLAB to consider 840716 motion to reopen record on seismic issues Motion should be granted Certificate of Svc encl
REYNOLDS, J R Joint Intervenors - Diablo Canyon REYNOLDS, J R
Center for Law in the Public Interest DSB 017 84/08/09 Atomic Safety and Licensing Appeal Panel 8pp 26061 015 24X
Fiche 50-275, 84/08/09, 8408140464

8408140006 Memorandum & Order CLI-84-13, determining that full power license may be issued by NRR Order effective on 840817, Commissioner Zech statement & Commissioner Asselstine dissenting views encl Served on 840810
CHILK, S J Office of the Secretary of the Commission DSB 940
84/08/10 Office of the Executive Legal Director 25pp
26045 001 24X Fiche 50-275, 84/08/10, 8408140006

8408140009 Decision CLI-84-12, initiating rulemaking re effects of seismic events on emergency planning Addl views of Palladino & Bernthal & dissenting view of Asselstine encl Served on 840810
CHILK, S J Office of the Secretary of the Commission DSB 939
84/08/10 29pp 26044 078 24X Fiche 50-275, 84/08/10, 8408140009

8408140460 Order extending time until 840817 for Commission to act to review ALAB-763 Served on 840814
CHILK, S J Office of the Secretary of the Commission DSB 034
84/08/10 Commissioners 1p 26060 352 24X
Fiche 50-275, 84/08/10, 8408140460

8408140486 Order extending time until 840817 for Commission to act to review Director's Decision DD-84-8 Served on 840814
CHILK, S J Office of the Secretary of the Commission DSB 035
84/08/10 Commissioners 1p 26060 275 24X
Fiche 50-275, 84/08/10, 8408140486

8408160234 Responds to RC McDiarmid petition for enforcement of license conditions to continue moribund enforcement proceeding & interpose Commission in pending contract litigation w/City of Healdsburg, CA NRC involvement unnecessary
FALLIN, J F , SANDERSON, S A Pacific Gas & Electric Co 84/08/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp
26092 154 24X Fiche 50-275, 84/08/10, 8408160234

8408140548 Forwards Commissioner Bernthal 840813 revised addl views to CLI-84-12 Served on 840813
CLEMENTS, W L Docketing & Services Branch DSB 009 84/08/13
Office of the Executive Legal Director 4pp 26060 243 24X
Fiche 50-275, 84/08/13, 8408140548

8408220251 Order denying petitions for review of ALAB-736 subj to reservation re ASLB rationale for excluding joint intervenor & State of CA contentions concerning util QA program Served on 840820
CHILK, S J Office of the Secretary of the Commission DSB 190
84/08/20 3pp 26191 360 24X Fiche 50-275, 84/08/20, 8408220251

8408220323 Order instructing IE to issue reclassified notice of violation re util matl false statement by failing to rept Nuclear Svcs Corp 1977 audit of Pullman Power Products QA program Served on 840820
CHILK, S J Office of the Secretary of the Commission DSB 189
84/08/20 Director's Office, Office of Inspection and Enforcement
5pp 26194 055 24X Fiche 50-275, 84/08/20, 8408220323

8408240424 Staff requirements memo re affirmation/discussion & vote denying 2 206 relief (SECY-84-203), approving order responding to petitions for review of ALAB-763 (SECY-84-254) & approving order denying LILCO 840719 motion (SECY-84-296)
CHILK, S J Office of the Secretary of the Commission 84/08/20
Office of the Secretary of the Commission 3pp 26248 269 24X
Fiche 50-000, 84/08/20, 8408240424

8408230202 Forwards summary of 840726 site visit No new info impacting licensing decision identified Served on 840822
ZECH, L W Commissioners DSB 255 84/08/22 PALLADINO, ROBERTS, ASSELSTINE Commissioners 5pp 26209 209 24X
Fiche 50-275, 84/08/22, 8408230202

8408280217 Order extending time until 840913 for Commission to act to review ALAB-776 Served on 840827
CHILK, S J Office of the Secretary of the Commission DSB 317
84/08/27 Commissioners 1p 26275 143 24X
Fiche 50-275, 84/08/27, 8408280217

8408310247 Notice of withdrawal of appearance in proceeding Related correspondence
AXELRAD, M Newman & Holtzinger DSB 428 84/08/28 Office of the Secretary of the Commission 1p 26319 256 24X
Fiche 50-275, 84/08/28, 8408310247

8408310210 Expresses opposition to util 840820 amend application extending term of license & requests hearing per Atomic Energy Act, to be held prior to Commission decision on application
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
Joint Intervenors - Diablo Canyon DSB 419 84/08/29
PALLADINO, M , ASSELSTINE, J , BERNTHAL, F Commissioners 5pp
26318 067 24X Fiche 50-275, 84/08/29, 8408310210

M Antitrust correspondence

8408130310 Ack receipt of 840801 ltr to HR Denton re request for enforcement of certain antitrust license conditions Allegations contained in ltr under review
VOGLER, B H Hearing Branch 2 DSB 898 84/08/08 MCDIARMID, R C
Spiegel & McDiarmid 1p 26010 250 24X Fiche 50-275, 84/08/08, 8408130310

8408280442 Confirms telcon re petition for enforcement of antitrust license conditions Staff awaits RC McDiarmid comments on util 840810 ltr re petition Staff requests wheel provisions of arbitrated settlement agreement re NCPA Geyser units
VOGLER, B H Hearing Branch 2 DSB 343 84/08/22 MCDIARMID, R C
Spiegel & McDiarmid 1p 26280 294 24X Fiche 50-275, 84/08/22, 8408280442

O Advisory Committee on Reactor Safeguards reports & correspondence

8408020242 Forwards comments on ACRS 840523 tour of plant site, in response to 840515 ltr
MYSINGER, E D Tennessee Valley Authority 84/08/01 MCKINLEY, J C
ACRS - Advisory Committee on Reactor Safeguards 4pp 25898 157
24X Fiche 50-275, 84/08/01, 8408020242

P Operating license stage documents & correspondence

8408310138 FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by PG&E re earthquake on Nacimiento fault & one equal to 1906 San Francisco earthquake
CALSOYAS, C D Affiliation Not Assigned 84/04/07 NRC - No
Detailed Affiliation Given 4pp 26352 011 24X
Fiche 50-275, 84/04/07, 8408310138

8408310142 Responds to FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by PG&E re earthquake Forwards printout of documents re Mothers for Peace Other documents in PDR
FELTON, J M Division of Rules and Records 84/06/01 CALSOYAS, C D
Affiliation Not Assigned 1p 26352 015 24X
Fiche 50-275, 84/06/01, 8408310142

8406150149 Forwards addl info re pipe support design guides per NRC request as result of recent audits connected w/License Condition 2 C (11)
SCHUYLER, J O Pacific Gas & Electric Co 84/06/11 EISENHUT, D G
Division of Licensing 2pp 24951 009 24X Fiche 50-275, 84/06/11, 8406150149

8408300482 Requests exam & test requirements for all presently licensed personnel for Unit 1 be waived for Unit 2 & combined OLs for Units 1 & 2 be issued Supporting documentation encl Related correspondence
SCHUYLER, J O , CRANE, P A Pacific Gas & Electric Co DSN 720
84/07/17 MARTIN, J B , PATE, R J Region 5, Office of Director
88pp 26329 189 24X Fiche 50-275, 84/07/17, 8408300482

8408070531 Informs of completion of staff evaluation of const status & readiness for power ascension testing & full power operation Summaries of reviews & assessments which contributed to conclusion of readiness encl
BISHOP, T W Region 5, Office of Director 84/07/20 EISENHUT, D G
Division of Licensing 2pp 25953 039 24X Fiche 50-275, 84/07/20, 8408070531

--8408070532 Informs of results of 840604 meeting re status of facility & basis for full power license issuance recommendations
BISHOP, T W Region 5, Office of Director 84/06/19 MARTIN, J B
Region 5, Office of Director 18pp 25953 041 24X
Fiche 50-275, 84/07/20, 8408070531

8408140011 Forwards 840713 rept, "June 20, 1984 Santa Maria Offshore Earthquake, Ground Motion at Diablo Canyon Power Plant " Rept contains tabulation of peak accelerations & recorded accelerograms
SCHUYLER, J O Pacific Gas & Electric Co 84/07/20 EISENHUT, D G
Division of Licensing 1p 26044 128 24X Fiche 50-275, 84/07/20, 8408140011

--8408140012 "June 20, 1984 Santa Maria Offshore Earthquake, Ground Motion at Diablo Canyon Power Plant "
* TERA Corp 84/07/13 33pp 26044 129 24X
Fiche 50-275, 84/07/20, 8408140011

408310032 Forwards Ofc of Inspector & Auditor 840801 rept of investigation re allegations against seven NRC employees as result of T Devine 840412 & 0503 10CFR2 206 petitions on NRC misleading or matl false statements to Commission
MESSENGER, G H Office of Inspector & Auditor 84/08/01 PALLADINO, ROBERTS, ASSELSTINE Commissioners 2pp 26349 001 24X
Fiche 50-275, 84/08/01, 8408310032

--8408310035 Investigation rept on 840801 Major areas investigated allegations re NRC misleading or matl false statements to Commission during 840319, 26 & 27 briefings & in SSER 21 & 22 for Dec 1983 & Mar 1984, respectively
SMITH, R M , BOWERS, H , MESSENGER, G H Office of Inspector & Auditor 84/08/01 400pp 26349 003 24X Fiche 50-275, 84/08/01, 8408310032

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche: 50-000, 84/08/06, 8408070110

8408130003 Requests exemption from 10CFR50, App G requirement for revs to curves, per review of pressure-temp limits for reactor vessel Westinghouse finite element stress analysis showed heatup & cool down curves not impacted by App G amend
SCHUYLER, J O Pacific Gas & Electric Co 84/08/08 KNIGHTON, G W
Licensing Branch 3 2pp 26010 047 24X Fiche 50-275, 84/08/08, 8408130003

8408130188 Forwards proposed changes in post-fuel loading initial test program re test scope clarification & conducting existing tests at addl (lower) power plateaus Review & approval required by 840828
SCHUYLER, J O Pacific Gas & Electric Co 84/08/08 KNIGHTON, G W
Licensing Branch 3 3pp 26008 288 24X Fiche 50-275, 84/08/08, 8408130188

8408210639 Forwards SLO-2 work request & work authorization mistakenly omitted from 840801 ltr
PETERS, R J Pacific Gas & Electric Co 84/08/08 MITCHELL-WILSON
California, State of 2pp 26184 351 24X Fiche 50-275, 84/08/08, 8408210639

8408210406 Requests approval for removal of RHR suction valve automatic closure interlock Upon approval, util will install alarms & restore power to RHR suction valve operators during periods of RHR sys operation while aligned to RCS
SCHUYLER, J O Pacific Gas & Electric Co 84/08/15 KNIGHTON, G W
Licensing Branch 3 2pp 26180 336 24X Fiche 50-275, 84/08/15, 8408210406

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

840823000B Forwards application for amend to License DPR-76, extending termination date of license from 3 yrs from date of issuance to 4 yrs from date of issuance Fee encl
SCHUYLER, J O Pacific Gas & Electric Co 84/08/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26209 155 24X
Fiche 50-275, 84/08/20, 8408230008

--8408230012 Application to amend License DPR-76, extending termination date of license from 3 yrs from date of issuance to 4 yrs from date of issuance
SCHUYLER, J O Pacific Gas & Electric Co 84/08/20 2pp
26209 156 24X Fiche 50-275, 84/08/20, 8408230008

0 Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25869 047 24X Fiche 50-000, 84/07/27, 8407250229

8408080491 Forwards IE Insp Repts 50-275/84-13 & 50-323/84-05 on 840430-0504 & notice of violation
BISHOP, T W Region 5, Office of Director 84/07/27 SCHUYLER, J O
Pacific Gas & Electric Co 2pp 25974 244 24X
Fiche 50-275, 84/07/27, 8408080491

--8408080501 Notice of violation from insp on 840430-0504
YOUNG, T Region 5, Office of Director 84/07/27 3pp
25974 246 24X Fiche 50-275, 84/07/27, 8408080491

--8408080513 IE Insp Repts 50-275/84-13 & 50-323/84-05 on 840430-0504 Violation noted failure to follow approved QC procedures for safety-related pipe & electrical raceway supports
DURDOIN, J E , YOUNG, T Region 5, Office of Director 84/07/11
6pp 25974 249 24X Fiche 50-275, 84/07/27, 8408080491

--8408080515 "Technical Assistance for Insp of Diablo Canyon IDVP," progress rept for Feb 1984
WADE, W O , CUMMINGS, G E Lawrence Livermore National Laboratory
FIN B-8552 84/03/14 MORRILL, P J Region 5, Office of Director
6pp 25974 255 24X Fiche 50-275, 84/07/27, 8408080491

--8408080517 "Technical Assistance for Insp of Diablo Canyon IDVP," progress rept for Mar 1984
WADE, W O , CUMMINGS, G E Lawrence Livermore National Laboratory
FIN B-8552 84/04/11 MORRILL, P J Region 5, Office of Director
6pp 25974 261 24X Fiche 50-275, 84/07/27, 8408080491

--8408080521 "Technical Assistance for Insp of Diablo Canyon IDVP," progress rept for Apr 1984
WADE, W O CUMMINGS, G E Lawrence Livermore National Laboratory
FIN B-8552 84/05/14 MORRILL, P J Region 5, Office of Director
6pp 25974 269 24X Fiche 50-275, 84/07/27, 8408080491

8407310035 Board Notification 84-138 forwards Investigation/Insp Rept 50-275/84-08 Subj matter of rept addressed in SSERs 25 & 26
EISENHUT, D G Division of Licensing 84/07/30 PALLADINO, ROBERTS, ASSELSTINE Commissioners 2pp 25885 106 24X
Fiche 50-275, 84/07/30, 8407310035

--8408020131 Forwards Investigation/Insp Rept 50-275/84-08, concluding assignment under NRR
YIN, I T Region 3, Office of Director 84/07/23 VOLLMER, R H
Division of Engineering 1p 25885 108 24X
Fiche 50-275, 84/07/30, 8407310035

--8408020134 Investigation/Insp Rept 50-275/84-08
YIN, I T Region 3, Office of Director 84/07/23 159pp
25885 109 24X Fiche 50-275, 84/07/30, 8407310035

8408130291 Responds to NRC 840628 ltr re violations noted in IE Insp Rept 50-275/84-10 Corrective actions Administrative Procedure (NPAP) C-4S1 revised, training completed & existing jumpers backfitted
SCHUYLER, J O Pacific Gas & Electric Co 84/07/30 MARTIN, J B
Region 5, Office of Director 4pp 26008 345 24X
Fiche 50-275, 84/07/30, 8408130291

8408070324 Ack receipt of 840618 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-275/83-37 & 50-323/83-25
BISHOP, T W Region 5, Office of Director 84/08/01 SCHUYLER, J O
Pacific Gas & Electric Co 1p 25945 130 24X
Fiche 50-275, 84/08/01, 8408070324

--8408070327 Responds to NRC 840229 ltr re violations noted in IE Insp Rpts 50-275/83-37 & 50-323/83-25 Corrective actions reinsp program implemented for welds originally accepted by unqualified inspectors
SCHUYLER, J O Pacific Gas & Electric Co 84/06/18 MARTIN, J B
Region 5, Office of Director 8pp 25945 131 24X
Fiche 50-275, 84/08/01, 8408070324

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408130431 Ack receipt of $50,000 payment of 840517 civil penalty Corrective actions will be examined during future insp
AXELRAD, J A Enforcement Staff 84/08/08 MANEATIS, G A Pacific Gas & Electric Co 1p 26058 358 24X Fiche 50-275, 84/08/08, 8408130431

8408220067 Informs of review of 51 LERs for Jan 1983 - June 1984 in support of ongoing SALP review Review concentrated on completeness, accuracy & consistency of info No major deficiencies identified Summary of criteria & findings encl
BEYFRIT, K V Reactor Operations Analysis Branch 84/08/09
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 26193 248 24X Fiche 50-275, 84/08/09, 8408220067

8408300140 Forwards Insp Rpts 50-275/84-25 & 50-323/84-17 on 840709-13 No violations noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/08/09 SCHUYLER, J O Pacific Gas & Electric Co 1p 26307 324 24X Fiche 50-275, 84/08/09, 8408300140

--8408300149 Insp Rpts 50-275/84-25 & 50-323/84-17 on 840709-13 No violations or deviations noted Major areas inspected allegations re NRC assessment of Pullman Power audit program during Aug 1971 - Dec 1973
WAGNER, W J , KIRSCH, D F Region 5, Office of Director 84/08/09
8pp 26307 325 24X Fiche 50-275, 84/08/09, 8408300140

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408200313 Ack receipt of 840730 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-275/84-10
BISHOP, T W Region 5, Office of Director 84/08/13 SCHUYLER, J O
Pacific Gas & Electric Co 1p 26133 012 24X
Fiche 50-275, 84/08/13, 8408200313

--8408200318 Responds to NRC 840628 ltr re violations noted in IE Insp Rept 50-275/84-10 Corrective actions Procedure C-4S1, "Mechanical Bypass, Jumper & Lifted Circuit Log," revised to include jumpers in clearance package
SCHUYLER, J O Pacific Gas & Electric Co 84/07/30 MARTIN, J B
Region 5, Office of Director 4pp 26133 013 24X
Fiche 50-275, 84/08/13, 8408200313

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100095 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100095

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408080491 Forwards IE Insp Rpts 50-275/84-13 & 50-323/84-05 on 840430-0504 & notice of violation
BISHOP, T W Region 5, Office of Director 84/07/27 SCHUYLER, J O
Pacific Gas & Electric Co 2pp 25974 244 24X
Fiche 50-275, 84/07/27, 8408080491

--8408080515 "Technical Assistance for Insp of Diablo Canyon IDVP," progress rept for Feb 1984
WADE, W O , CUMMINGS, G E Lawrence Livermore National Laboratory
FIN B-8552 84/03/14 MORRILL, P J Region 5, Office of Director
6pp 25974 255 24X Fiche 50-275, 84/07/27, 8408080491

--8408080517 "Technical Assistance for Insp of Diablo Canyon IDVP," progress rept for Mar 1984
WADE, W O , CUMMINGS, G E Lawrence Livermore National Laboratory
FIN B-8552 84/04/11 MORRILL, P J Region 5, Office of Director
8pp 25974 261 24X Fiche 50-275, 84/07/27, 8408080491

--8408080521 "Technical Assistance for Insp of Diablo Canyon IDVP," progress rept for Apr 1984
WADE, W O , CUMMINGS, G E Lawrence Livermore National Laboratory
FIN B-8552 84/05/14 MORRILL, P J Region 5, Office of Director
6pp 25974 269 24X Fiche 50-275, 84/07/27, 8408080491

S Reportable occurrences, LERs & related correspondence

8408060013 PNO-V-84-046 on 840728, w/unit in hot standby, inadvertent safety injection actuation occurred Caused by high steam flow signal resulting from surveillance testing in progress.
JOHNSON, P , MENDONCA, M M Region 5, Office of Director 84/07/30
1p 25933 183 24X Fiche 50-275, 84/07/30, 8408060013

8408070369 LER 84-017-00 on 840629, plant vent iodine & particulate flow rate monitor FIS-24 declared inoperable when monitor failed Functional test On 840709, discovered incorrect action statement entered Flow switch adjusted W/840730 ltr
KELLY, W J , SHIFFER, J D Pacific Gas & Electric Co 84/06/29 3pp 25944 207 24X Fiche 50-275, 84/07/30, 8408070369

8408310038 LER 84-017-00 on 840629, plant personnel did not comply w/correct Tech Spec action statement for period of nine days Caused by typographical error on surveillance test procedure Related correspondence W/840730 ltr
KELLY, W J , SHIFFER, J D Pacific Gas & Electric Co DSB 790
84/07/30 3pp 26350 187 24X Fiche 50-275, 84/07/30, 8408310038

8408160491 LER 84-018-00 on 840706, portion of ESF (control room ventilation sys) actuated in response to spurious radiation monitor alarm signal Caused by failed detector Detector replaced Sys tested & returned to svc W/840806 ltr
SISK, D P , SHIFFER, J D Pacific Gas & Electric Co 84/08/06 3pp 26107 312 24X Fiche 50-275, 84/08/06, 8408160491

8408210226 LER 84-019-00 on 840714, control room ventilation sys activated & transferred to pressurization mode Caused by error in Drawing 45882B showing slave relay K605 as closed contact instead of open W/840813 ltr
SISK, D P , SHIFFER, J D Pacific Gas & Electric Co 84/08/13 3pp 26184 009 24X Fiche 50-275, 84/08/13, 8408210226

8408230476 LER 84-021-00 on 840720, reactor protection sys actuated due to coincidence of steam generator 1-3 low level & steam flow/feed flow mismatch Caused by failed valve operator Valve operator replaced W/840817 ltr
SISK, D P , SHIFFER, J D Pacific Gas & Electric Co 84/08/17 3pp 26212 214 24X Fiche 50-275, 84/08/17, 8408230476

8408270112 LER 84-020-00 on 840719, diesel generator 103 automatically started due to undervoltage on Unit 2 bus F Caused by const workers inadvertently jarring relay panel & actuating undervoltage relay W/840820 ltr
SISK, D P , SHIFFER, J D Pacific Gas & Electric Co 84/08/20 3pp 26258 202 24X Fiche 50-275, 84/08/20, 8408270112

8408310143 LER 84-022-00 on 840728, safety injection & reactor trip occurred due to lo-lo T average & high steam flow signals Caused by personnel not considering effect of low RCS signal on safety injection actuation logic W/840827 ltr
SISK, D P , SHIFFER, J D Pacific Gas & Electric Co 84/08/27 3pp 26322 263 24X Fiche 50-275, 84/08/27, 8408310143

T Hearing transcripts on non-antitrust matters

8408220338 Transcript of 840802 open meeting in Washington, DC re discussion/possible vote on full power OL Pp 1-195
Supporting documentation encl
* Commissioners 84/08/02 222pp 26211 083 24X
Fiche 50-275, 84/08/02, 8408220338

8408200407 Transcript of 840803 Commission meeting in Washington, DC re discussion/possible vote on order concerning earthquakes & emergency planning Pp 1-8
* Commissioners 84/08/03 12pp 26141 178 24X
Fiche 50-275, 84/08/03, 8408200407

8408280020 Transcript of 840816 Commission meeting in Washington, DC re affirmation/discussion & vote Pp 1-7
* Commissioners 84/08/16 10pp 26294 013 24X
Fiche 50-000, 84/08/16, 8408280020

U Congressional/Executive Correspondence

8408010275 Responds to 840208 ltr re concerns over perceived tendency by staff to assume that margins of safety established by criteria need not be adhered to for sys not pivotal to safety
DIRCKS, W J Office of the Executive Director for Operations
84/07/20 PANETTA, L House of Rep 9pp 25872 342 24X
Fiche 50-275, 84/07/20, 8408010275

--8408010277 Requests preparation of response to Panetta 840208 ltr on concerns re QA hearing
PALLADINO, N J Commissioners 84/06/19 DIRCKS, W J Office of the Executive Director for Operations 1p 25872 351 24X
Fiche 50-275, 84/07/20, 8408010275

V Operator Examinations

8408070479 Discusses telcon between J Tinlin & J Elin re arrangements for administration of written & oral exams for senior reactor operators on 840918-28 License applications should be submitted at least 60 days prior to exam
PATE, R J Region 5, Office of Director 84/08/02 SCHUYLER, J O
Pacific Gas & Electric Co 4pp 25941 206 24X
Fiche 50-275, 84/08/02, 8408070479

DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

P Operating license stage documents & correspondence

8408010259 Requests application for amend executed per 10CFR50 30(a)-(c) & info showing all parts of Section 6 1 of Tech Specs being fulfilled before action can be taken on 840524 request for dismantling facilities
THOMAS, C O Standardization & Special Projects Branch 84/07/23
KARAM, R A Georgia Institute of Technology, Atlanta, GA 3pp
25872 339 24X Fiche 50-160, 84/07/23, 8408010259

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8407160090 Forwards public version of revised emergency plan implementing procedures, including EP-103 re alert response, EP-104 re site emergency response, EP-105 re general emergency response & EP-201 re technical support ctr
DALTROFF, S L Philadelphia Electric Co 83/08/29 MURLEY, T E
Region 1, Office of Director 4pp 25623 065 24X
Fiche 50-277, 83/08/29, 8407160090

--8407160091 Public version of revised emergency plan implementing procedures, including EP-103 re alert response, EP-104 re site emergency response, EP-105 re general emergency response & EP-201 re support ctr
* Philadelphia Electric Co 83/08/01 84pp 25623 068 24X
Fiche 50-277, 83/08/29, 8407160090

8408060352 Notification of Significant Licensee Meeting 84-66 on 840731 w/util in King of Prussia, PA to discuss results of recent security insp
BAILEY, R J Region 1, Office of Director 84/07/25 Region 1, Office of Director 2pp 25937 346 24X Fiche 50-277, 84/07/25, 8408060352

8408150409 Forwards IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-29 & 0711 Violations identified Confirms 840731 enforcement conference in Region 1 ofc Insp details withheld (ref 10CFR2 790 & 73 21)
MARTIN, T T Division of Engineering & Technical Programs 84/07/25
DALTROFF, S L Philadelphia Electric Co 2pp 26077 301 24X
Fiche 50-277, 84/07/25, 8408150409

--8408150424 IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-29 & 0711 Violation noted failure to have watchman controlling access & to notify Commission of change of security program Safeguards info deleted (ref 10CFR2 790)
BAILEY, R J , SMITH, G C , DUNLAP, J M Region 1, Office of Director
84/07/25 17pp 26077 303 24X Fiche 50-277, 84/07/25, 8408150409

8408230290 Requests discussion of Lancaster County deficiencies & corrective actions by 840831, per review of FEMA final emergency preparedness exercise rept of 831116 joint exercise of state of local plans for TMI-1
MURLEY, T E Region 1, Office of Director 84/08/13 DALTROFF, S L
Philadelphia Electric Co 2pp 26213 257 24X
Fiche 50-277, 84/08/13, 8408230290

8408210389 Clarifies 830916 ltr re location of alternative control stations, implications of extensive circuit isolation performed at HPCI alternative control stations for alternative safe shutdown & concept of fire safe relays
BOYER, V S Philadelphia Electric Co 84/08/16 EISENHUT, D G
Division of Licensing 5pp 26180 266 24X Fiche 50-277, 84/08/16, 8408210389

P, Operating license stage documents & correspondence

8406220100 Requests notification of analyses utilizing methodology not previously approved in NUREG-0661, "Mark I Containment Long-Term Program" in determining need for logic changes
RIVENBARK, G W Operating Reactors Branch 2 84/06/11 BAUER, E G
Philadelphia Electric Co 3pp 25100 343 24X
Fiche 50-277, 84/06/11, 8406220100

8408060321 Responds to Generic Ltr 84-09 re recombiner capability requirements of 10CFR50 44 Facility complies w/technical criteria established in Generic Ltr 84-09 Recombiner capability not required
DALTROFF,S L Philadelphia Electric Co 84/07/31 EISENHUT,D G
Division of Licensing 3pp 25926 331 24X Fiche 50-277,84/07/31,
8408060321

8408130361 Forwards 830603 & 0426 correspondence from State of PA,Dept of Environ Resources,changing Dec temp confidence limit in Special Condition 9B of ETS App B,Item 7 4 2 B 2 from 1 5 F to 4 F
WILLSEY,W B Philadelphia Electric Co 84/08/03 DENTON,H R NRC - No Detailed Affiliation Given 3pp 26010 115 24X
Fiche 50-277,84/08/03,8408130361

8408220527 Forwards Amends 102 & 104 to Licenses DPR-44 & DPR-56, respectively & safety evaluation Amends revise Tech Specs to implement requirements of App I to 10CFR50 & to revise environ monitoring programs
GEARS,G E Operating Reactors Branch 4 84/08/03 BAUER,E G
Philadelphia Electric Co 5PP 26210 001 24X
Fiche 50-277,84/08/03,8408220527

--8408220530 Amends 102 & 104 to Licenses DPR-44 & DPR-56,respectively, revising Tech Specs to implement requirements of App I to 10CFR50 & revising environ monitoring programs Tech Specs encl
STOLZ,J F Operating Reactors Branch 4 84/08/03 175pp
26210 006 24X Fiche 50-277,84/08/03,8408220527

--8408220531 Safety evaluation supporting Amends 102 & 104 to Licenses DPR-44 & DPR-56,respectively
* Office of Nuclear Reactor Regulation, Director 84/08/03 8pp
26210 173 24X Fiche 50-277,84/08/03,8408220527

--8307010039 "Radiological Effluent Tech Spec Implementation (A-2), Peach Bottom Atomic Power Station Units 2 & 3," technical evaluation rept
FERNANDEZ,C Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5506-108/109 83/06/29 CONGEL,F , WILLIS,C
NRC - No Detailed Affiliation Given 32pp 26210 181 24X
Fiche 50-277,84/08/03,8408220527

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 1, "Seqouyah Nuclear Plant Containment Analysis," for Meeting 3B Rept inconsistent w/four encl repts previously sent
FONTANA,M H Technology for Energy Corp 84/08/07 DENTON,H R ,
CASE,E Office of Nuclear Reactor Regulation, Director HOUSTON,R
NRC - No Detailed Affiliation Given 2pp 26234 001 24X
Fiche 50-000,84/08/07,8408230097

--8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants," technical rept
* Industry Degraded Core Rulemaking Program * Fauske & Associates, Inc FAI/84-9 DRFT 84/07/31 114pp 26234 231
24X Fiche 50-000,84/08/07,8408230097

--8408230131 Draft, "Peach Bottom Atomic Power Station Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/08/07 75pp
26235 269 24X Fiche 50-000,84/08/07,8408230097

8408210389 Clarifies 830916 ltr re location of alternative control stations,implications of extensive circuit isolation performed at HPCI alternative control stations for alternative safe shutdown & concept of fire safe relays
BOYER,V S Philadelphia Electric Co 84/08/16 EISENHUT,D G
Division of Licensing 5pp 26180 266 24X Fiche 50-277,84/08/16,
8408210389

8408230185 Requests extension of final submittal date for response to Generic Ltr 84-15,until 841101 Extension required to allow collection & assessment of diesel testing data & to develop action plan
COONEY,M J Philadelphia Electric Co 84/08/16 EISENHUT,D G
Division of Licensing 1p 26209 301 24X Fiche 50-277,84/08/16,
8408230185

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

G Inspection reports, IE Bulletins & correspondence

8408090036 Forwards IE Insp Repts 50-277/84-14 & 50-278/84-12 on 840507-11 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 84/07/18
DALTROFF,S L Philadelphia Electric Co 2pp 25992 310 24X
Fiche 50-277,84/07/18,8408090036

--8408090039 Notice of violation from insp on 840507-11
* Region 1, Office of Director 84/07/18 2pp 25992 312 24X
Fiche 50-277,84/07/18,8408090036

--8408090051 IE Insp Repts 50-277/84-14 & 50-278/84-12 on 840507-11 Noncompliance noted failure to establish corrective measures for conditions adverse to quality re mechancial outdoor storage area
EAPEN,P K , PRELL,J A , GODY,A T Region 1, Office of Director
84/06/26 10pp 25992 314 24X Fiche 50-277,84/07/18,8408090036

8408060352 Notification of Significant Licensee Meeting 84-66 on 840731 w/util in King of Prussia,PA to discuss results of recent security insp
BAILEY,R J Region 1, Office of Director 84/07/25 Region 1,
Office of Director 2pp 25937 346 24X Fiche 50-277,84/07/25,
8408060352

8408150409 Forwards IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-29 & 0711 Violations identified Confirms 840731 enforcement conference in Region 1 ofc Insp details withheld (ref 10CFR2 790 & 73 21)
MARTIN,T T Division of Engineering & Technical Programs 84/07/25
DALTROFF,S L Philadelphia Electric Co 2pp 26077 301 24X
Fiche 50-277,84/07/25,8408150409

--8408150424 IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-29 & 0711 Violation noted failure to have watchman controlling access & to notify Commission of change of security program Safeguards info deleted (ref 10CFR2 790)
BAILEY,R J , SMITH,O C , DUNLAP,J M Region 1, Office of Director
84/07/25 17pp 26077 303 24X Fiche 50-277,84/07/25,
8408150409

8408150233 Forwards IE Insp Repts 50-277/84-20 & 50-278/84-16 on 840608-0715 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 84/07/26
DALTROFF,S L Philadelphia Electric Co 2pp 26073 332 24X
Fiche 50-277,84/07/26,8408150233

--8408150236 Notice of violation from insp on 840607-0715
* Region 1, Office of Director 84/07/26 2pp 26073 334 24X
Fiche 50-277,84/07/26,8408150233

--8408150244 IE Insp Repts 50-277/84-20 & 50-278/84-16 on 840607-0715 Noncompliance noted failure to maintain access to fire extinguisher,up-to-date control drawings & up-to-date procedures in technical support ctr
BLOUGH,A R , WILLIAMS,J H , MEYER,O W Region 1, Office of
Director 84/07/25 12pp 26073 336 24X Fiche 50-277,84/07/26,
8408150233

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408230130 Forwards IE Insp Rept 50-277/84-18 on 840618-21 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 84/08/03
DALTROFF,S L Philadelphia Electric Co 2pp 26214 145 24X
Fiche 50-277,84/08/03,8408230130

--8408230133 Notice of violation from insp on 840618-21
* Region 1, Office of Director 84/07/23 1p 26214 147 24X
Fiche 50-277,84/08/03,8408230130

--8408230134 IE Insp Rept 50-277/84-21 on 840618-18 Violations noted failure to train health physics technicians & provide specific radiological exposure controls on radiation work permit
BICEHOUSE,H J , DRAGOUN,T F , SHANBAKY,M M Region 1, Office of
Director 84/07/23 9pp 26214 148 24X Fiche 50-277,84/08/03,
8408230130

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 138 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408230070 Ack receipt of 840718 payment of $30,000 for civil penalties noted in NRC 840618 ltr Corrective actions will be examined during future insps
AXELRAD, J A Enforcement Staff 84/08/09 BOYER, V Philadelphia Electric Co 1p 26233 271 24X Fiche 50-277, 84/08/09, 8408230070

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408310004 SupplS response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Concerns in bulletin not applicable to facilities
COONEY, M J Philadelphia Electric Co 84/08/16 MURLEY, T E Region 1, Office of Director 2pp 26323 279 24X Fiche 50-277, 84/08/16, 8408310004

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408210546 Forwards "Environ Radiation Monitoring Program, 1983" & "Regional Radiological Environ Monitoring Program, 1983 "
WILLSEY, W B Philadelphia Electric Co 84/08/09 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 26185 001 24X Fiche 50-171, 84/08/09, 8408210546

--8408210549 "Environ Radiation Monitoring Program, 1983 "
* Chemical Waste Management, Inc 41 83/12/31 124pp 26185 002 24X Fiche 50-171, 84/08/09, 8408210546

--8408210555 "Regional Radiological Environ Monitoring Program, 1983 "
* Teledyne Isotopes 19 83/12/31 129pp 26185 126 24X Fiche 50-171, 84/08/09, 8408210546

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408080535 LER 84-012-00 on 840628, w/unit in cold shutdown for refueling, surveillance testing discovered inoperable horizontal fire damper in cable spreading room Caused by missing spring closure device W/840727 ltr
CLARK, B L , LOGUE, R H Philadelphia Electric Co 84/07/27 4pp 25975 306 24X Fiche 50-277, 84/07/27, 8408080535

8408080533 LER 84-010-01 on 840607, w/unit shutdown for refueling & major mod outage, through-wall crack discovered in loop A jet pump instrumentation penetration reducer to safe-end weld Caused by IGSCC W/840730 ltr
CLARK, B L , LOGUE, R H Philadelphia Electric Co 84/07/30 4pp 25975 302 24X Fiche 50-277, 84/07/30, 8408080533

8408130601 LER 84-011-01 on 840608, acetylene leak occurred during drywell preheat welding Caused by leak where hose crimped to std screw connection Personnel evacuated & addl ventilation used to expel gas W/840806 ltr
CLARK, B L , LOGUE, R H Philadelphia Electric Co 84/08/06 4pp 26030 356 24X Fiche 50-277, 84/08/06, 8408130601

8408290107 LER 84-014-00 on 840716, continuous firewatch removed from cable spreading room w/o realizing that firewatch still needed due to out-of-svc Cardox sys Condition discovered & firewatch reestablished on 840719 W/840817 ltr
CLARK, B L , ULLRICH, W T Philadelphia Electric Co 84/08/17 4pp 26297 274 24X Fiche 50-277, 84/08/17, 8408290107

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000, 84/08/21, 8408310186

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8407160090 Forwards public version of revised emergency plan implementing procedures, including EP-103 re alert response, EP-104 re site emergency response, EP-105 re general emergency response & EP-201 re technical support ctr
DALTROFF, S L Philadelphia Electric Co 83/08/29 MURLEY, T E Region 1, Office of Director 4pp 25823 065 24X Fiche 50-277, 83/08/29, 8407160090

--8407160091 Public version of revised emergency plan implementing procedures, including EP-103 re alert response, EP-104 re site emergency response, EP-105 re general emergency response & EP-201 re support ctr
* Philadelphia Electric Co 83/08/01 84pp 25823 068 24X Fiche 50-277, 83/08/29, 8407160090

8408060352 Notification of Significant Licensee Meeting 84-66 on 840731 w/util in King of Prussia, PA to discuss results of recent security insp
BAILEY, R J Region 1, Office of Director 84/07/25 Region 1, Office of Director 2pp 25937 346 24X Fiche 50-277, 84/07/25, 8408060352

8408150409 Forwards IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-29 & 0711 Violations Identified Confirms 840731 enforcement conference in Region 1 ofc Insp details withheld (ref 10CFR2 790 & 791)
MARTIN, T T Division of Engineering & Technical Programs 84/07/25 DALTROFF, S L Philadelphia Electric Co 2pp 26077 301 24X Fiche 50-277, 84/07/25, 8408150409

--8408150424 IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-29 & 0711 Violation noted Failure to have watchman controlling access & to notify Commission of change of security program Safeguards info deleted (ref 10CFR2 790)
BAILEY, R J , WEIMIO, R R Region 1, Office of Director 84/07/25 17pp 26077 303 24X Fiche 50-277, 84/07/25, 8408150409

8408230290 Requests discussion of Lancaster County deficiencies & corrective actions by 840831, per review of FEMA final emergency preparedness exercise rept of 831116 joint exercise of state of local plans for TMI-1
MURLEY, T E Region 1, Office of Director 84/08/13 DALTROFF, S L
Philadelphia Electric Co 2pp 26213 257 24X
Fiche 50-277, 84/08/13, 8408230290

8408210389 Clarifies 830916 ltr re location of alternative control stations, implications of extensive circuit isolation performed at HPCI alternative control stations for alternative safe shutdown & concept of fire safe relays
BOYER, V S Philadelphia Electric Co 84/08/16 EISENHUT, D G
Division of Licensing 5pp 26180 266 24X Fiche 50-277, 84/08/16, 8408210389

P Operating license stage documents & correspondence

8406220100 Requests notification of analyses utilizing methodology not previously approved in NUREG-0661, "Mark I Containment Long-Term Program" in determining need for logic changes
RIVENBARK, G W Operating Reactors Branch 2 84/06/11 BAUER, E G
Philadelphia Electric Co 3pp 25100 343 24X
Fiche 50-277, 84/06/11, 8406220100

8408060321 Responds to Generic Ltr 84-09 re recombiner capability requirements of 10CFR50 44 Facility complies w/technical criteria established in Generic Ltr 84-09 Recombiner capability not required
DALTROFF, S L Philadelphia Electric Co 84/07/31 EISENHUT, D G
Division of Licensing 3pp 25926 331 24X Fiche 50-277, 84/07/31, 8408060321

8408070303 Forwards Rev 1 to GE Rept MAR 84-27, "Residual Stress Analysis of Peach Bottom, Unit 3 Jet Pump Instrumentation Nozzle Weld Overlay " Rept withheld (ref 10CFR2 790)
DALTROFF, S L Philadelphia Electric Co 84/08/03 EISENHUT, D G
Division of Licensing 2pp 25947 222 24X Fiche 50-278, 84/08/03, 8408070303

8408130361 Forwards 830603 & 0426 correspondence from State of PA, Dept of Environ Resources, changing Dec temp confidence limit in Special Condition 9B of ETS App B, Item 7 4 2 B 2 from 1 5 F to 4 F
WILLSEY, W B Philadelphia Electric Co 84/08/03 DENTON, H R NRC
~ No Detailed Affiliation Given 3pp 26010 115 24X
Fiche 50-277, 84/08/03, 8408130361

8408220527 Forwards Amends 102 & 104 to Licenses DPR-44 & DPR-56, respectively & safety evaluation Amends revise Tech Specs to implement requirements of App I to 10CFR50 & to revise environ monitoring programs
GEARS, G E Operating Reactors Branch 4 84/08/03 BAUER, E G
Philadelphia Electric Co 5PP 26210 001 24X
Fiche 50-277, 84/08/03, 8408220527

--8408220530 Amends 102 & 104 to Licenses DPR-44 & DPR-56, respectively, revising Tech Specs to implement requirements of App I to 10CFR50 & revising environ monitoring programs Tech Specs encl
STOLZ, J F Operating Reactors Branch 4 84/08/03 175pp
26210 006 24X Fiche 50-277, 84/08/03, 8408220527

--8408220531 Safety evaluation supporting Amends 102 & 104 to Licenses DPR-44 & DPR-56, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/03 8pp
26210 173 24X Fiche, 50-277, 84/08/03, 8408220527

--8307010039 "Radiological Effluent Tech Spec Implementation (A-2), Peach Bottom Atomic Power Station Units 2 & 3," technical evaluation rept
FERNANDEZ, C Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5506-108/109 83/06/29 CONGEL, F , WILLIS, C
NRC ~ No Detailed Affiliation Given 32pp 26210 181 24X
Fiche 50-277, 84/08/03, 8408220527

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408210237 Forwards notice of consideration of issuance of amend to License DPR-56 & proposed NSHC determination & opportunity for hearing on 840530 application re increased core flow region rated throughout Cycle 6 Encls in Central Files
GEARS, G Operating Reactors Branch 4 84/08/06 BAUER, E G
Philadelphia Electric Co 2pp 26187 349 24X
Fiche 50-278, 84/08/06, 8408210237

8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 1, "Sequoyah Nuclear Plant Containment Analysis," for Meeting 38 Rept inconsistent w/four encl repts previously sent
FONTANA, M H Technology for Energy Corp 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26234 001
24X Fiche 50-000, 84/08/07, 8408230097

--8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants," technical rept
* Industry Degraded Core Rulemaking Program FAI/84-9 DRFT
84/07/31 114pp 26234 231 24X Fiche 50-000, 84/08/07, 8408230097

--8408230131 Draft, "Peach Bottom Atomic Power Station Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/08/07 75pp
26235 269 24X Fiche 50-000, 84/08/07, 8408230097

8408210389 Clarifies 830916 ltr re location of alternative control stations, implications of extensive circuit isolation performed at HPCI alternative control stations for alternative safe shutdown & concept of fire safe relays
BOYER, V S Philadelphia Electric Co 84/08/16 EISENHUT, D G
Division of Licensing 5pp 26180 266 24X Fiche 50-277, 84/08/16, 8408210389

8408230185 Requests extension of final submittal date for response to Generic Ltr 84-15, until 841101 Extension required to allow collection & assessment of diesel testing data & to develop action plan
COONEY, M J Philadelphia Electric Co 84/08/16 EISENHUT, D G
Division of Licensing 1p 26209 301 24X Fiche 50-277, 84/08/16, 8408230185

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche, 50-000, 84/08/20, 8408200275

8408280272 Forwards application for amend to License DPR-56, revising 840530 application re operation w/increased core flows to provide addl info re BWR thermal hydraulic stability requested by NRC
BRADLEY, E J Philadelphia Electric Co 84/08/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26274 310 24X
Fiche 50-278, 84/08/24, 8408280272

--8408280273 Application for amend to License DPR-56, revising 840530 application re operation w/increased core flows to provide addl info re BWR thermal hydraulic stability requested by NRC
BRADLEY, E J Philadelphia Electric Co 84/08/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26274 311
24X Fiche 50-278, 84/08/24, 8408280272

--8408280278 Proposed Tech Specs, allowing operation w/increased core flows
* Philadelphia Electric Co 84/08/24 7pp 26274 318 24X
Fiche 50-278, 84/08/24, 8408280272

Q Inspection reports, IE Bulletins & correspondence

8408090036 Forwards IE Insp Rpts 50-277/84-14 & 50-278/84-12 on 840507-11 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/18
DALTROFF, S L Philadelphia Electric Co 2pp 25992 310, 24X
Fiche 50-277, 84/07/18, 8408090036

--8408090039 Notice of violation from insp on 840507-11
* Region 1, Office of Director 84/07/18 2pp 25992 312 24X
Fiche 50-277, 84/07/18, 8408090036

--8408090051 IE Insp Rpts 50-277/84-14 & 50-278/84-12 on 840507-11 Noncompliance noted failure to establish corrective measures for conditions adverse to quality re mechancial outdoor storage area
EAPEN, P K , PRELL, J A , GODY, A T Region 1, Office of Director
84/06/26 10pp 25992 314 24X Fiche 50-277, 84/07/18, 8408090036

8408060352 Notification of Significant Licensee Meeting 84-66 on 840731 w/util in King of Prussia, PA to discuss results of recent security insp
BAILEY, R J Region 1, Office of Director 84/07/25 Region 1,
Office of Director 2pp 25937 346 24X Fiche 50-277, 84/07/25, 8408060352

DOCKETED ITEMS

8408150409 Forwards IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-29 & 0711 Violations Identified Confirms 840731 enforcement conference in Region 1 ofc Insp details withheld (ref 10CFR2 790 & 73 21)
MARTIN, T T Division of Engineering & Technical Programs 84/07/25
DALTROFF, S L Philadelphia Electric Co 2pp 26077 301 24X
Fiche 50-277, 84/07/25, 8408150409

--8408150424 IE Safeguards Insp Repts 50-277/84-19 & 50-278/84-10 on 840625-29 & 0711 Violation noted failure to have watchman controlling access & to notify Commission of change of security program Safeguards info deleted (ref 10CFR2 790)
BAILEY, R J , SMITH, G C , DUNLAP, J M Region 1, Office of Director
84/07/25 17pp 26077 303 24X Fiche 50-277, 84/07/25, 8408150409

8408150233 Forwards IE Insp Repts 50-277/84-20 & 50-278/84-16 on 840608-0715 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/07/26
DALTROFF, S L Philadelphia Electric Co 2pp 26073 332 24X
Fiche 50-277, 84/07/26, 8408150233

--8408150236 Notice of violation from insp on 840607-0715
* Region 1, Office of Director 84/07/26 2pp 26073 334 24X
Fiche 50-277, 84/07/26, 8408150233

--8408150244 IE Insp Repts 50-277/84-20 & 50-278/84-16 on 840607-0715 Noncompliance noted failure to maintain access to fire extinguisher, up-to-date control drawings & up-to-date procedures in technical support ctr
BLOUGH, A R , WILLIAMS, J H , MEYER, G W Region 1, Office of Director 84/07/25 12pp 26073 336 24X Fiche 50-277, 84/07/26, 8408150233

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408230070 Ack receipt of 840718 payment of $30,000 for civil penalties noted in NRC 840618 ltr Corrective actions will be examined during future insps
AXELRAD, J A EnForcement Staff 84/08/09 BOYER, V Philadelphia Electric Co 1p 26233 271 24X Fiche 50-277, 84/08/09, 8408230070

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408310004 SupplS response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Concerns in bulletin not applicable to facilities
COONEY, M J Philadelphia Electric Co 84/08/16 MURLEY, T E
Region 1, Office of Director 2pp 26323 279 24X
Fiche 50-277, 84/08/16, 8408310004

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

R Periodic operating reports & related correspondence

8408210546 Forwards "Environ Radiation Monitoring Program, 1983" & "Regional Radiological Environ Monitoring Program, 1983 "
WILLSEY, W B Philadelphia Electric Co 84/08/09 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 1p
26185 001 24X Fiche 50-171, 84/08/09, 8408210546

--8408210549 "Environ Radiation Monitoring Program, 1983 "
* Chemical Waste Management, Inc 41 83/12/31 124pp
26185 002 24X Fiche 50-171, 84/08/09, 8408210546

--8408210555 "Regional Radiological Environ Monitoring Program, 1983 "
* Teledyne Isotopes 19 83/12/31 129pp 26185 126 24X
Fiche 50-171, 84/08/09, 8408210546

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408100048 RO MM-3-01 on 840622 & 25, moisture sensors in recirculation sys moisture monitoring sys functioned improperly Cause unknown Drywell sump collection sys monitored hourly until next outage
* Philadelphia Electric Co 84/07/23 MURLEY, T E Region 1, Office of Director 3pp 25990 073 24X Fiche 50-278, 84/07/23, 8408100048

8408240283 PNO-I-84-071 on 840821, reactor automatically scrammed due to low water level caused by feedwater control sys failure Scram resulted in primary containment isolation sys Group 1 isolation & tripped recirculation pumps
CALLO, R Region 1, Office of Director 84/08/21 1p 26223 196
24X Fiche 50-278, 84/08/21, 8408240283

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R. General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000, 84/08/21, 8408310186

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408310069 Confirms 840524 visit to Region to discuss access control at facilities
LEWIS, R C Region 2, Office of Director 84/05/22 STEWART, W L
Virginia Electric & Power Co 1p 26333 342 24X
Fiche 50-000, 84/05/22, 8408310069

8408310401 Forwards summary of 840524 meeting re security interface activities Meeting beneficial & provided better understanding between security staffs
LEWIS, R C Region 2, Office of Director 84/06/06 STEWART, W L
Virginia Electric & Power Co 4pp 26333 311 24X
Fiche 50-000, 84/06/06, 8408310401

8408300433 Forwards Commonwealth of VA response to comments & proposed corrective actions in reply to FEMA rept of 831001 full-scale emergency exercise
DANCE, H C Region 2, Office of Director 84/06/26 STEWART, W L
Virginia Electric & Power Co 1p 26314 308 24X
Fiche 50-280, 84/06/26, 8408300433

8408020132 Revised emergency plan W/840727 ltr
MILLER, H L , GRADY, W D , STEWART, W L Virginia Electric & Power Co
84/06/28 O'REILLY, J P Region 2, Office of Director 276pp
25890 109 24X Fiche 50-280, 84/06/28, 8408020132

8408070039 Forwards replacement pages to control room design review program plan Adoption of Westinghouse Owners Group emergency response guidelines as basis for task analysis & verification/validation sections principal changes
STEWART, W L Virginia Electric & Power Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 8pp 25949 281 24X Fiche 50-000, 84/07/27, 8408070039

8408270443 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-281/84-15 & 50-281/84-15
DANCE, H C Division of Project & Resident Programs 84/07/31
STEWART, W L Virginia Electric & Power Co 1p 26257 187 24X
Fiche 50-280, 84/07/31, 8408270443

--8408270448 Responds to NRC 840620 ltr re violations noted in Insp Repts 50-280/84-15 & 50-281/84-15 Corrective actions smoke & heat detector periodic tests changed to include up to date testing techniques using heat gun test gas
STEWART, W L Virginia Electric & Power Co 84/07/20
O'REILLY, J P Region 2, Office of Director 5pp 26257 188 24X
Fiche 50-280, 84/07/31, 8408270443

--8408270452 Forwards Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 & notice of violation
DANCE, H C Division of Project & Resident Programs 84/06/20
STEWART, W L Virginia Electric & Power Co 2pp 26257 193 24X
Fiche 50-280, 84/07/31, 8408270443

--8408270454 Notice of violation from insp on 840401-0505
* Region 2, Office of Director 84/06/20 2pp 26257 195 24X
Fiche 50-280, 84/07/31, 8408270443

--8408270456 Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 Violation noted procedures for testing certain components not adequate & fire protection program implementing procedures not properly followed
BURKE, D J , DAVIS, M J , MYERS, D O Region 2, Office of Director
84/06/19 5pp 26257 197 24X Fiche 50-280, 84/07/31, 8408270443

8408310060 Advises that 840412 rev to emergency plan consistent w/ provisions of 10CFR50 47(b) & requirements of App E
DANCE, H C Region 2, Office of Director 84/08/01 STEWART, W L
Virginia Electric & Power Co 2pp 26334 356 24X
Fiche 50-280, 84/08/01, 8408310060

8408100098 Revs to radiation emergency plan W/840803 ltr
STEWART, W L Virginia Electric & Power Co 84/07/19 O'REILLY, J P
Region 2, Office of Director 70pp 25990 280 24X
Fiche 50-280, 84/08/03, 8408100098

8408300429 Ack receipt of 840705 ltr re emergency exercise scheduled for plant during Sept 1984 Scenario & controller messages will be reviewed when received
DANCE, H C Region 2, Office of Director 84/08/08 STEWART, W L
Virginia Electric & Power Co 1p 26314 330 24X
Fiche 50-280, 84/08/08, 8408300429

8408200387 Advises that program plan for conducting detailed control room design review meets intent of Suppl 1 to NUREG-0737 Listed areas should be described in summary rept expected 850830
VARGA, S A Licensing Branch 1 84/08/10 STEWART, W L Virginia
Electric & Power Co 2pp 26141 215 24X Fiche 50-000, 84/08/10, 8408200387

8408160406 Forwards revised emergency plan implementing procedures, including EPIP-2 03 re repts to offsite agencies, EPIP-3 01 re callout of emergency response personnel & EPIP-5 01 re transportation of contaminated injured personnel W/o encl
STEWART, W L Virginia Electric & Power Co 84/08/13 O'REILLY, J P
Region 2, Office of Director 2pp 26092 179 24X
Fiche 50-280, 84/08/13, 8408160406

8408170222 Revised emergency plan implementing procedures, including EPIP-2 03 re repts to offsite agencies, EPIP-3 01 re callout of emergency response personnel & EPIP-5 01 re transport of contaminated injured personnel W/840813 ltr
STEWART, W L Virginia Electric & Power Co 84/08/13 O'REILLY, J P
Region 2, Office of Director 12pp 26118 077 24X
Fiche 50-280, 84/08/13, 8408170222

P Operating license stage documents & correspondence

8408300369 Confirms 840501 telcon w/HC Dance re 840510 mgt meeting in Region II ofc to discuss organizational structure
LEWIS, R C Region 2, Office of Director 84/05/07 STEWART, W L
Virginia Electric & Power Co 1p 26308 230 24X
Fiche 50-000, 84/05/07, 8408300369

8408010161 Notification of 840727 meeting w/util at site to discuss questions re control of heavy loads (Multi-Plant Action C-15)
NEIGHBORS, D Operating Reactors Branch 1 84/07/20 VARGA, S A
Operating Reactors Branch 1 2pp 25873 304 24X
Fiche 50-280, 84/07/20, 8408010161

8408160039 Advises that upgraded in-core thermocouple sys schedule will be completed by 1986 refueling outage, per 840221 commitment & will meet requirements of NUREG-0737, Item II F 2
STEWART, W L Virginia Electric & Power Co 84/08/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 26092 052 24X Fiche 50-280, 84/08/01, 8408160039

8408130585 Notifies that any permanent changes to new fuel container lifting rig will be made per ANSI N14 6-1978 requirements & NUREG-0612
STEWART, W L Virginia Electric & Power Co 84/08/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 26031 359 24X Fiche 50-280, 84/08/03, 8408130585

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408210132 Forwards Generic Ltr 84-15 response schedule, listing 840928 & 850131 as projected dates Justification for extension of responses included
STEWART, W L Virginia Electric & Power Co 84/08/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 3pp 26181 348 24X Fiche 50-000, 84/08/16, 8408210132

8408240280 Forwards response to 840606 request for addl info, to complete review of util 831209 request for relief from ASME Section XI re nonregenerative HX integrally welded support One oversize drawing encl Aperture card in PDR
STEWART, W L Virginia Electric & Power Co 84/08/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 4pp 26227 227 24X
Fiche 50-280, 84/08/17, 8408240280

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

O Inspection reports, IE Bulletins & correspondence

8408010164 EN-84-049 on 840730, notice of violation & proposed imposition of civil penalties in amount of $40,000 will be issued to licensee Action involves failure to adequately implement svc life monitoring program for snubbers
KLINGLER, G , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/07/25 1p 25855 305 24X Fiche 50-280, 84/07/25, 8408010164

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408020041 Forwards insp fees for Surry Power Station & North Anna, Unit 1 for Mar 1983 - Mar 1984 & North Anna, Unit 2 for Apr 1983 - Apr 1984
STEWART, W L Virginia Electric & Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 25880 304 24X Fiche 50-000, 84/07/27, 8408020041

8408070357 Discusses IE insp on 840320-23 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY, J P Region 2, Office of Director 84/07/30 STEWART, W L Virginia Electric & Power Co 4pp 25944 161 24X Fiche 50-280, 84/07/30, 8408070357

--8408070360 Notice of violation & proposed imposition of civil penalty in amount of $40,000 Violation noted svc life commencement date for snubbers incorrect & safety-related snubbers not reviewed, per Tech Specs
O'REILLY, J P Region 2, Office of Director 84/07/31 2pp 25944 165 24X Fiche 50-280, 84/07/31, 8408070357

8408270443 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-281/84-15 & 50-281/84-15
DANCE, H C Division of Project & Resident Programs 84/07/31
STEWART, W L Virginia Electric & Power Co 1p 26257 187 24X Fiche 50-280, 84/07/31, 8408270443

--8408270448 Responds to NRC 840620 ltr re violations noted in Insp Repts 50-280/84-15 & 50-281/84-15 Corrective actions smoke & heat detector periodic tests changed to include up to date testing techniques using heat gun test gas
STEWART, W L Virginia Electric & Power Co 84/07/20
O'REILLY, J P Region 2, Office of Director 5pp 26257 188 24X Fiche 50-280, 84/07/31, 8408270443

--8408270452 Forwards Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 & notice of violation
DANCE, H C Division of Project & Resident Programs 84/06/20
STEWART, W L Virginia Electric & Power Co 2pp 26257 193 24X Fiche 50-280, 84/07/31, 8408270443

--8408270454 Notice of violation from insp on 840401-0505
* Region 2, Office of Director 84/06/20 2pp 26257 195 24X Fiche 50-280, 84/07/31, 8408270443

--8408270456 Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 Violation noted procedures for testing certain components not adequate & fire protection program implementing procedures not properly followed
BURKE, D J , DAVIS, M J , MYERS, D O Region 2, Office of Director 84/06/19. 5pp 26257 197 24X Fiche. 50-280, 84/07/31, 8408270443

8408280150 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " All GE Type HFA relays in safety-related applications will be replaced
STEWART, W L Virginia Electric & Power Co 84/07/31 O'REILLY, J P Region 2, Office of Director 4pp 26259 082 24X Fiche 50-000, 84/07/31, 8408280150

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408220171 Monthly operating repts for Jul 1984 W/840815 ltr
JONES, V H , STEWART, W L Virginia Electric & Power Co 84/07/31
BEEBE, M R Office of Resource Management, Director 40pp 26188 132 24X Fiche 50-280, 84/07/31, 8408220171

S Reportable occurrences, LERs & related correspondence

8408010056 Forwards LERs 84-016-00, 84-017-00 & 83-014/01X-1
SAUNDERS, R F Virginia Electric & Power Co 84/07/19 Record Services Branch (Document Control Desk) 1p 25866 268 24X Fiche 50-280, 84/07/19, 8408010056

--8408010060 LER 84-016-00 on 840619, automatic reactor trip resulted from exceeding 10% power on two of four nuclear power channels, NI 44 & NI 41, w/turbine unlatched Caused by isolation valve malfunction due to broken gear pin
SAUNDERS, R F Virginia Electric & Power Co 84/07/17 3pp 25866 269 24X Fiche 50-280, 84/07/19, 8408010056

--8408010069 LER 84-017-00 on 840620, quadrant power tilt greater than 24 existed longer than 24 h due to control rod B-6 sticking at 56 step position Cause not determined Extensive monitoring being performed until cause determined
SAUNDERS, R F Virginia Electric & Power Co 84/07/17 4pp 25866 272 24X Fiche 50-280, 84/07/19, 8408010056

--8408010074 Updated LER 83-014/01X-1 on 830309, during refueling, abnormal degradation of fuel rods observed Caused by primary hydriding, weld defects, stress-related defects & debris induced fretting Mfg process analysis in progress
SAUNDERS, R F Virginia Electric & Power Co 84/07/17 5pp 25866 276 24X Fiche 50-280, 84/07/19, 8408010056

V Operator Examinations

8408070489 Forwards hot license simulator reactor startup certification program, per NUREG-0094 Program limits student to instructor ratio to four-to-one, conforming to INPO Guide 82-005 W/o encl
STEWART, W L Virginia Electric & Power Co 84/06/06
PERSENSKY, J J NRC - No Detailed Affiliation Given 2pp 25940 347 24X Fiche 50-000, 84/06/06, 8408070489

V Dry Cask Independent Spent Fuel Storage Installations

8408240009 Summary of 840810 meeting w/util, Bechtel & SAI in Silver Spring, MD re dry cask spent fuel storage application
Meeting agenda & attendees list encl
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch, 84/08/20
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 4pp 26252 355 24X Fiche 50-280, 84/08/20, 8408240009

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8408310069 Confirms 840524 visit to Region to discuss access control at facilities
LEWIS,R C Region 2, Office of Director 84/05/22 STEWART,W L
Virginia Electric & Power Co 1p 26333 342 24X
Fiche 50-000,84/05/22,8408310069

8408310401 Forwards summary of 840524 meeting re security interface activities Meeting beneficial & provided better understanding between security staffs
LEWIS,R C Region 2, Office of Director 84/06/06 STEWART,W L
Virginia Electric & Power Co 4pp 26333 311 24X
Fiche 50-000,84/06/06,8408310401

8408300433 Forwards Commonwealth of VA response to comments & proposed corrective actions in reply to FEMA rept of 831001 full-scale emergency exercise
DANCE,H C Region 2, Office of Director 84/06/26 STEWART,W L
Virginia Electric & Power Co 1p 26314 308 24X
Fiche 50-280,84/06/26,8408300433

8408020132 Revised emergency plan W/840727 ltr
MILLER,H L , GRADY,W D , STEWART,W L Virginia Electric & Power Co
84/06/28 O'REILLY,J P Region 2, Office of Director 276pp
25890 109 24X Fiche 50-280,84/06/28,8408020132

8408070039 Forwards replacement pages to control room design review program plan Adoption of Westinghouse Owners Group emergency response guidelines as basis for task analysis & verification/validation sections principal changes
STEWART,W L Virginia Electric & Power Co 84/07/27 DENTON,H R
Office of Nuclear Reactor Regulation, Director EISENHUT,D G
Division of Licensing 8pp 25949 281 24X Fiche 50-000,84/07/27,8408070039

8408270443 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-281/84-15 & 50-281/84-15
DANCE,H C Division of Project & Resident Programs 84/07/31
STEWART,W L Virginia Electric & Power Co 1p 26257 187 24X
Fiche 50-280,84/07/31,8408270443

--8408270448 Responds to NRC 840620 ltr re violations noted in Insp Repts 50-280/84-15 & 50-281/84-15 Corrective actions smoke & heat detector periodic tests changed to include up to date testing techniques using heat gun test gas
STEWART,W L Virginia Electric & Power Co 84/07/20
O'REILLY,J P Region 2, Office of Director 5pp 26257 188 24X
Fiche 50-280,84/07/31,8408270443

--8408270452 Forwards Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 & notice of violation
DANCE,H C Division of Project & Resident Programs 84/06/20
STEWART,W L Virginia Electric & Power Co 2pp 26257 193 24X
Fiche 50-280,84/07/31,8408270443

--8408270454 Notice of violation from insp on 840401-0505
Region 2, Office of Director 84/06/20 2pp 26257 195 24X
Fiche 50-280,84/07/31,8408270443

--8408270456 Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 Violation noted procedures for testing certain components not adequate & fire protection program implementing procedures not properly followed
BURKE,D J Region 2, Office of Director ELROD,S Division of Project & Resident Programs 84/06/19 5pp 26257 197 24X
Fiche 50-280,84/07/31,8408270443

8408310060 Advises that 840412 rev to emergency plan consistent w/ provisions of 10CFR50 47(b) & requirements of App E
DANCE,H C Region 2, Office of Director 84/08/01 STEWART,W L
Virginia Electric & Power Co 2pp 26334 356 24X
Fiche 50-280,84/08/01,8408310060

8408100098 Revs to radiation emergency plan W/840803 ltr
STEWART,W L Virginia Electric & Power Co 84/07/19 O'REILLY,J P
Region 2, Office of Director 70pp 25990 280 24X
Fiche 50-280,84/08/03,8408100098

8408300429 Ack receipt of 840705 ltr re emergency exercise scheduled for plant during Sept 1984 Scenario & controller messages will be reviewed when received
DANCE,H C Region 2, Office of Director 84/08/08 STEWART,W L
Virginia Electric & Power Co 1p 26314 330 24X
Fiche 50-280,84/08/08,8408300429

8408200387 Advises that program plan for conducting detailed control room design review meets intent of Suppl 1 to NUREG-0737 Listed areas should be described in summary rept expected 850830
VARGA,S A Licensing Branch 1 84/08/10 STEWART,W L Virginia Electric & Power Co 2pp 26141 215 24X Fiche 50-000,84/08/10,8408200387

8408160406 Forwards revised emergency plan implementing procedures, including EPIP-2 03 re repts to offsite agencies,EPIP-3 01 re callout of emergency response personnel & EPIP-5 01 re transportation of contaminated injured personnel W/o encl
STEWART,W L Virginia Electric & Power Co 84/08/13 O'REILLY,J P
Region 2, Office of Director 2pp 26092 179 24X
Fiche 50-280,84/08/13,8408160406

8408170222 Revised emergency plan implementing procedures,including EPIP-2 03 re repts to offsite agencies,EPIP-3 01 re callout of emergency response personnel & EPIP-5 01 re transport of contaminated injured personnel W/840813 ltr
STEWART,W L Virginia Electric & Power Co 84/08/13 O'REILLY,J P
Region 2, Office of Director 12pp 26118 077 24X
Fiche 50-280,84/08/13,8408170222

P Operating license stage documents & correspondence

8408300369 Confirms 840501 telcon w/HC Dance re 840510 mgt meeting in Region II ofc to discuss organizational structure
LEWIS,R C Region 2, Office of Director 84/05/07 STEWART,W L
Virginia Electric & Power Co 1p 26308 230 24X
Fiche 50-000,84/05/07,8408300369

8408010161 Notification of 840727 meeting w/util at site to discuss questions re control of heavy loads (Multi-Plant Action C-15)
NEIGHBORS,D Operating Reactors Branch 1 84/07/20 VARGA,S A
Operating Reactors Branch 1 2pp 25873 304 24X
Fiche 50-280,84/07/20,8408010161

8408160039 Advises that upgraded in-core thermocouple sys schedule will be completed by 1986 refueling outage,per 840221 commitment & will meet requirements of NUREG-0737,Item II F 2
STEWART,W L Virginia Electric & Power Co 84/08/01 DENTON,H R
Office of Nuclear Reactor Regulation, Director EISENHUT,D G
Division of Licensing 1p 26092 052 24X Fiche 50-280,84/08/01,8408160039

8408130585 Notifies that any permanent changes to new fuel container lifting rig will be made per ANSI N14 6-1978 requirements & NUREG-0612
STEWART,W L Virginia Electric & Power Co. 84/08/03 DENTON,H R
Office of Nuclear Reactor Regulation, Director EISENHUT,D G
Division of Licensing 1p 26031 359 24X Fiche 50-280,84/08/03,8408130585

8408070110 Generic Ltr 84-19 to all licensees of operating reactors; applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche. 50-000,84/08/06,8408070110

8408210132 Forwards Generic Ltr 84-15 response schedule; listing 840928 & 850131 as projected dates Justification for extension of responses included
STEWART,W L Virginia Electric & Power Co 84/08/16 DENTON,H R
Office of Nuclear Reactor Regulation, Director EISENHUT,D G
Division of Licensing 3pp 26181 348 24X Fiche.50-000,84/08/16,8408210132

8408240280 Forwards response to 840606 request for addl info.to complete review of util 831209 request for relief from ASME Section XI re nonregenerative HX integrally welded support One oversize drawing encl Aperture card in PDR
STEWART,W L Virginia Electric & Power Co 84/08/17 DENTON,H R
Office of Nuclear Reactor Regulation, Director VARGA,S A
Operating Reactors Branch 1 4pp 26227 227. 24X
Fiche 50-280,84/08/17,8408240280

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

G Inspection reports, IE Bulletins & correspondence

8408010164 EN-84-049 on 840730, notice of violation & proposed imposition of civil penalties in amount of $40,000 will be issued to licensee Action involves failure to adequately implement svc life monitoring program for snubbers
KLINGLER, G , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/07/25 1p 25855 309 24X Fiche 50-280, 84/07/25, 8408010164

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408020041 Forwards insp fees for Surry Power Station & North Anna, Unit 1 for Mar 1983 - Mar 1984 & North Anna, Unit 2 for Apr 1983 - Apr 1984
STEWART, W L Virginia Electric & Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 25880 304 24X Fiche 50-000, 84/07/27, 8408020041

8408070357 Discusses IE insp on 840320-23 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY, J P Region 2, Office of Director 84/07/30 STEWART, W L Virginia Electric & Power Co 4pp 25944 161 24X Fiche 50-280, 84/07/30, 8408070357

--8408070360 Notice of violation & proposed imposition of civil penalty in amount of $40,000 Violation noted svc life commencement date for snubbers incorrect & safety-related snubbers not reviewed, per Tech Specs
O'REILLY, J P Region 2, Office of Director 84/07/31 2pp 25944 165 24X Fiche 50-280, 84/07/31, 8408070357

8408270443 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-281/84-15 & 50-281/84-15
DANCE, H C Division of Project & Resident Programs 84/07/31
STEWART, W L Virginia Electric & Power Co 1p 26257 187 24X Fiche 50-280, 84/07/31, 8408270443

--8408270448 Responds to NRC 840620 ltr re violations noted in Insp Repts 50-280/84-15 & 50-281/84-15 Corrective actions smoke & heat detector periodic tests changed to include up to date testing techniques using heat gun test gas
STEWART, W L Virginia Electric & Power Co 84/07/20
O'REILLY, J P Region 2, Office of Director 5pp 26257 188 24X Fiche 50-280, 84/07/31, 8408270443

--8408270452 Forwards Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 & notice of violation
DANCE, H C Division of Project & Resident Programs 84/06/20
STEWART, W L Virginia Electric & Power Co 2pp 26257 193 24X Fiche 50-280, 84/07/31, 8408270443

--8408270454 Notice of violation from insp on 840401-0505
* Region 2, Office of Director 84/06/20 2pp 26257 195 24X Fiche 50-280, 84/07/31, 8408270443

--8408270456 Insp Repts 50-280/84-15 & 50-281/84-15 on 840401-0505 Violation noted procedures for testing certain components not adequate & fire protection program implementing procedures not properly followed
BURKE, D J , DAVIS, M J , MYERS, D O Region 2, Office of Director 84/06/19 5pp. 26257 197 24X Fiche 50-280, 84/07/31, 8408270443

8408280150 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " All GE Type HFA relays in safety-related applications will be replaced
STEWART, W L Virginia Electric & Power Co 84/07/31 O'REILLY, J P Region 2, Office of Director 4pp 26259 082 24X Fiche 50-000, 84/07/31, 8408280150

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc. 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Undetected Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 116pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408220171 Monthly operating repts for Jul 1984 W/840815 ltr
JONES, V H , STEWART, W L Virginia Electric & Power Co 84/07/31
BEEBE, M R Office of Resource Management, Director 40pp
26188 132 24X Fiche 50-280, 84/07/31, 8408220171

V Operator Examinations

8408070489 Forwards hot license simulator reactor startup certification program, per NUREG-0094 Program limits student to instructor ratio to four-to-one, conforming to INPO Guide 82-005 W/o encl
STEWART, W L Virginia Electric & Power Co 84/06/06
PERGENSKY, J J NRC - No Detailed Affiliation Given 2pp
25940 347 24X Fiche 50-000, 84/06/06, 8408070489

Y Dry Cask Independent Spent Fuel Storage Installations

8408240009 Summary of 840810 meeting w/util, Bechtel & SAI in Silver Spring, MD re dry cast spent fuel storage application Meeting agenda & attendees list encl
ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 84/08/20
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 4pp
26252 359 24X Fiche 50-280, 84/08/20, 8408240009

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408200484 Grants exemption from certain requirements of 10CFR50, App R, Subsections III G 2 & III O re reactor coolant pump lube oil collection sys Commitment to protect redundant cabling expected to be completed by 841231
MILLER, J R Operating Reactors Branch 3 84/07/31 MUSOLF, D M
Northern States Power Co 2pp 26143 331 24X
Fiche 50-282, 84/07/31, 8408200484

--8408200489 Exemption from certain requirements of 10CFR50, App R, Subsections III G 2 & III O re Fire Areas 1 & 71 & reactor coolant pump lube oil sys
EISENHUT, D G Division of Licensing 84/07/31 Northern States Power Co 7pp 26143 333 24X Fiche 50-282, 84/07/31, 8408200484

8408300176 Forwards Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan " Rev includes changes resulting from annual internal review, update & certification of emergency plans & agreements
FEY, F L Northern States Power Co 84/08/02 Region 3, Office of Director 4pp 26302 106 24X Fiche 50-000, 84/08/02, 8408300176

--8408300180 Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan "
HUDSON, G , FEY, F L , LARSON, C E Northern States Power Co 84/08/02 116pp 26302 110 24X Fiche 50-000, 84/08/02, 8408300176

--8408300183 Revised "Radiation Environ Monitoring Plan "
CLARK, B W , FEY, F L Northern States Power Co 84/02/29 14pp 26302 226 24X Fiche 50-000, 84/08/02, 8408300176

8408100029 Forwards IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 & notice of noncompliance Notice of noncompliance withheld (ref 10CFR73 21)
AXELSON, W L Region 3, Office of Director 84/08/03 LARSON, C E Northern States Power Co 2pp 25987 068 24X
Fiche 50-282, 84/08/03, 8408100029

--8408100037 IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 Noncompliance noted failure to provide effective barrier in portion of protected area perimeter Details withheld (ref 10CFR73 21)
KNICELEY, J R , BELANGER, J L , CREED, J R Region 3, Office of Director 84/08/03 2pp 25987 070 24X Fiche 50-282, 84/08/03, 8408100029

8408310173 Ack receipt of 840625 Rev 4 to emergency plan Next rev should include description of onsite & offsite environs & radiological monitoring drills & monthly communications check
PAPERIELLO, C J Region 3, Office of Director 84/08/27
LARSON, C E Northern States Power Co 2pp 26319 141 24X
Fiche 50-282, 84/08/27, 8408310173

P Operating license stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160482 Summary of 840724 meeting w/Westinghouse Owners Group re upper plenum injection for two loop plants
DIIANNI, D C Operating Reactors Branch 3 84/08/09 Operating Reactors Branch 3 4pp 26108 327 24X Fiche 50-000, 84/08/09, 8408160482

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070189 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/84-04 & 50-306/84-04 Corrective actions re sys blocking & tagging appropriate
SHAFER, W D Region 3, Office of Director 84/07/31 LARSON, C E
Northern States Power Co 2pp 25949 349 24X
Fiche 50-282, 84/07/31, 8408070189

--8408070197 Responds to NRC 840629 ltr re violations noted in IE Insp Repts 50-282/84-04 & 50-306/84-04 Corrective actions reactor coolant vent sys solenoid valve fuses removed & will not be installed until requirements met
LARSON, C E Northern States Power Co 84/07/13 SHAFER, W D
Region 3, Office of Director 2pp 25949 351 24X
Fiche 50-282, 84/07/31, 8408070189

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408100029 Forwards IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 & notice of noncompliance Notice of noncompliance withheld (ref 10CFR73 21)
AXELSON, W L Region 3, Office of Director 84/08/03 LARSON, C E
Northern States Power Co 2pp 25987 068 24X
Fiche 50-282, 84/08/03, 8408100029

--8408100037 IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 Noncompliance noted failure to provide effective barrier in portion of protected area perimeter Details withheld (ref 10CFR73 21)
KNICELEY, J R , BELANGER, J L , CREED, J R Region 3, Office of Director 84/08/03 2pp 25987 070 24X Fiche 50-282, 84/08/03, 8408100029

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Telethorapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408210298 Part 21 rept re separation of rod eye connected to piston rod from threaded portion of piston rod at approx 750,000 lb stress load Caused by insufficient matl thickness to withstand faulted load Matl certification encl
MILLS,C R Chicago Fluid Power Co 84/08/16 Director's Office, Office of Inspection and Enforcement 4pp 26180 349 24X Fiche 50-282,84/08/16,8408210298

8408240238 LER 84-029-00 on 840718,lockout of 2RY transformer & auto-start of both diesel generators occurred Caused by relay misoperation Relay replaced W/840817 ltr
HUNSTAD,A A , MUSOLF,D Northern States Power Co 84/08/17 3pp 26236 251 24X Fiche 50-282,84/08/17,8408240238

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

8408230526 Advises that operator & senior operator licensing exams scheduled for 841113-15 Matl listed in encl "Ref Matl Requirements for Operator/Senior Operator Licensing Exams" requested by 840913
WALKER,R D Region 3, Office of Director 84/08/17 LARSON,C E Northern States Power Co 5pp 26212 338 24X
Fiche:50-282,84/08/17,8408230526

8408230132 Informs of review of 840705 ltr which clarified interpretation of on-shift training requirements Util will be required to provide documentation that senior reactor operator upgrade candidates comply w/listed requirements
WALKER,R D Region 3, Office of Director 84/08/20 LARSON,C E Northern States Power Co 2pp 26209 061 24X
Fiche 50-000,84/08/20,8408230132

DOCKET 50-284 IDAHO STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8405300696 Requests submittal of revised emergency plan,including info identified in encl,within 60 days of ltr date,based on review of 830914 submittal
THOMAS,C O Standardization & Special Projects Branch 84/05/21
KEOEL,C H Idaho State Univ , Pocatello, ID 4pp 24733 048 24X
Fiche 50-284,84/05/21,8405300696

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408070142 Forwards request for addl info to continue review of 831028 submittal re safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737 Response requested within 60 days
MILLER,J R Operating Reactors Branch 3 84/07/24 JONES,W C
Omaha Public Power District 4pp 25957 134 24X
Fiche 50-285,84/07/24,8408070142

P Operating license stage documents & correspondence

8408070128 Advises that reporting requirements for Tech Spec Sections 3 3(2)e(i) & 3 3(2)e(ii) re steam generators,satisfied by util 840619 ltr.
ANDREWS,R L Omaha Public Power District 84/07/31 MILLER,J R
Operating Reactors Branch 3 1p 25949 276 24X
Fiche 50-285,84/07/31,8408070128

8408100104 Notifies that info requested in NRC 840711 ltr & during 840725 telcon re inadequate core cooling instrumentation sys cannot be furnished until 840930
ANDREWS,R L Omaha Public Power District 84/08/02 MILLER,J R
Operating Reactors Branch 3 1p 25990 277 24X
Fiche:50-285,84/08/02,8408100104.

8408200359 Forwards Amend 82 to License DPR-40 & safety evaluation Amend adds operability & surveillance requirements for containment hydrogen,water & pressure monitors
TOURIGNY,E G Operating Reactors Branch 3 84/08/02 JONES,W C
Omaha Public Power District 1p 26141 220 24X
Fiche,50-285,84/08/02,8408200359.

--8408200360 Amend 82 to License DPR-40,adding operability & surveillance requirements for containment hydrogen,water & pressure monitors
MILLER,J R Operating Reactors Branch 3 84/08/02 5pp
26141 221 24X Fiche 50-285,84/08/02,8408200359

--8408200361 Safety evaluation supporting Amend 82 to License DPR-40
* Office of Nuclear Reactor Regulation, Director 84/08/02 4pp
26141 226 24X Fiche 50-285,84/08/02,8408200359

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408270244 Discusses implementation status of toxic gas monitoring instrumentation sys Sys will be fully operable by 840930, based upon time required for procedure review & approval & training
ANDREWS,R L Omaha Public Power District 84/08/13 MILLER,J R
Operating Reactors Branch 3 2pp 26239 154 24X
Fiche 50-285,84/08/13,8408270244

O Inspection reports, IE Bulletins & correspondence

8408060307 Forwards IE Insp Rept 50-285/84-13 on 840501-31 No violations or deviations noted
JOHNSON,E H Region 4, Office of Director 84/06/29 JONES,W C
Omaha Public Power District 2pp 25936 073 24X
Fiche 50-285,84/06/29,8408060307

--8408060313 IE Insp Rept 50-285/84-13 on 840501-31 No violations or deviations noted Major areas inspected safety verification, surveillance testing,maint activities & followup of steam generator tube failure incident
VANDELL,L A , TOMLINSON,D P , JAUDON,J P Region 4, Office of Director 84/06/27 8pp 25936 075 24X Fiche 50-285,84/06/29, 8408060307

8408230461 Forwards IE Insp Rept 50-285/84-15 on 840623-27 & notice of violation
HUNTER,D R Region 4, Office of Director 84/07/23 JONES,W C
Omaha Public Power District 2pp 26213 123 24X
Fiche 50-285,84/07/23,8408230461

--8408230463 Notice of violation from insp on 840623-27
* Region 4, Office of Director 84/07/23 2pp 26213 125 24X
Fiche 50-285,84/07/23,8408230461

--8408230466 IE Insp Rept 50-285/84-15 on 840623-27 Violation noted failure to follow procedures re insp of matl received
CALDWELL,R A , HALL,R E , MARTIN,L E Region 4, Office of Director 84/07/23 7pp 26213 127 24X Fiche 50-285,84/07/23, 8408230461

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 19pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408100057 Ack receipt of 840629 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/84-10
HUNTER,D R Region 4, Office of Director 84/08/07 ANDREWS,R L
Omaha Public Power District 1p 25987 089 24X
Fiche 50-285,84/08/07,8408100057

--8408100062 Responds to NRC 840530 ltr re violations noted in IE Insp Rept 50-285/84-10 Corrective actions combined electrical/ mechanical/structural critical quality element list will be issued by 840715.
JONES,W C Omaha Public Power District 84/06/29 DENISE,R P
Division of Resident, Reactor Project & Engineering Programs 3pp
25987 060 24X Fiche 50-285,84/08/07,8408100057

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 12Opp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408290140 Forwards reactor operator exam rept on 840605-07 Response describing corrective actions for training program weaknesses requested within 60 days of rept receipt
HUNTER,D R Region 4, Office of Director 84/08/08 ANDREWS,R L
Omaha Public Power District 2pp 26298 116 24X
Fiche 50-285,84/08/08,8408290140

--8408290142 Exam rept on 840605-07 Exam results all three candidates failed
MCCRORY,S L , COOLEY,R A Region 4, Office of Director 84/08/01
56pp 26298 118 24X Fiche 50-285,84/08/08,8408290140

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12Spp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408200589 Monthly operating rept for Jul 1984 W/840803 ltr
MATTHEWS,T P , ANDREWS,R L Omaha Public Power District 84/07/31
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 10pp 26138 128 24X Fiche 50-285,84/07/31,8408200589

S Reportable occurrences, LERs & related correspondence

8408060289 LER 84-009-00 on 840622,penetration assemblies failed Caused by brittle & cracked teflon insulation on lead wires Selected penetration assemblies modified Assemblies remaining will be qualified by Nov 1985 W/840723 ltr
FISICARO,J J , ANDREWS,R L Omaha Public Power District 84/07/23
4pp 25936 048 24X Fiche 50-285,84/07/23,8408060289

8408090401 LER 84-015-00 on 840702,load of approx 250 lbs carried by polar crane over RCS when fluid in pressurizer greater than 225 F Procedure change made to RCS vent & leak test instructions W/840801 ltr
KUSEK,L T , ANDREWS,R L Omaha Public Power District 84/08/01
3pp 25993 270 24X Fiche 50-285,84/08/01,8408090401

8408090405 LER 84-014-00 on 840703,during weekly replacement of iodine collection cartridge on RM-060,actuation of ventilation isolation actuation sys occurred No cause given RM-060 will be out of svc during filter replacement W/840703 ltr
KUSEK,L T , ANDREWS,R L Omaha Public Power District 84/08/02
4pp 25993 263 24X Fiche 50-285,84/08/02,8408090405

8408240230 LER 84-012-00 on 840717,boron concentration in safety injection & refueling water tank below Tech Spec limits Caused by analytical error Boron concentration maintained at higher level W/840816 ltr
FLUEHR,J J , ANDREWS,R L Omaha Public Power District 84/08/16
3pp 26236 316 24X Fiche 50-285,84/08/16,8408240230

8408280343 LER 84-011-00 on 840720,stainless steel woven connection from auxiliary bldg ventilation discharge duct to radiation monitors RM-061/062 found disconnected Caused by loose slip fit connection Connector reattached W/840819 ltr
FLUEHR,J , ANDREWS,R L Omaha Public Power District 84/08/19
4pp 26282 253 24X Fiche 50-285,84/08/19,8408280343

8408280288 LER 84-013-00 on 840722,trip signals received on Channels A & C of thermal margin/low pressure reactor protective sys circuits Caused by noise spikes on calculators Noise suppressors installed W/840821 ltr
MUELLER,R J , ANDREWS,R L Omaha Public Power District 84/08/21
3pp 26282 180 24X Fiche 50-285,84/08/21,8408280288

V Operator Examinations

8408290140 Forwards reactor operator exam rept on 840605-07 Response describing corrective actions for training program weaknesses requested within 60 days of rept receipt
HUNTER,D R Region 4, Office of Director 84/08/08 ANDREWS,R L
Omaha Public Power District 2pp 26298 116 24X
Fiche 50-285,84/08/08,8408290140

--8408290142 Exam rept on 840605-07 Exam results all three candidates failed
MCCRORY,S L , COOLEY,R A Region 4, Office of Director 84/08/01
56pp 26298 118 24X Fiche 50-285,84/08/08,8408290140

8408280075 Confirms scheduling of operator exams for 841106-09 Submission of exam applications at least 60 days prior to exam requested Ref matl & administrative requirements encl
HUNTER,D R Region 4, Office of Director 84/08/24 ANDREWS,R L
Omaha Public Power District 3pp 26261 210 24X
Fiche 50-285,84/08/24,8408280075

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8405240290 Responds to 840424 memo for FEMA review of util request for delay in scheduling next full-scale emergency preparedness exercise at site until 841130 Delay acceptable
KRIMM,R Federal Emergency Management Agency 84/05/18
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 24614 336 24X Fiche 50-003,84/05/18,8405240290

8408090056 Clarifies addl issues raised by NRC in 840626 telcon re New York PIRG petition to suspend OLs due to emergency planning inadequacies FEMA rept & State of NY response to FEMA 840611 ltr encl
KRIMM,R W Federal Emergency Management Agency 84/07/31
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 25992 335 24X Fiche 50-247,84/07/31,8408090056

--8408090059 "Evaluation of Addl Issues Raised by NRC re New York PIRG Petition to Suspend Operation of Indian Point Units 2 & 3 "
* Federal Emergency Management Agency 84/07/26 10pp
25992 336 24X Fiche 50-247,84/07/31,8408090056

--8408090061 "Addl Info Obtained From NY State on New York PIRG Petition Which SupplS FEMA Rept to NRC dtd 840608 "
* Federal Emergency Management Agency 84/07/26 8pp
25992 346 24X Fiche 50-247,84/07/31,8408090056

8408130309 Forwards detailed control room design review program plan, per 840221 emergency response capability confirmatory order Program will be complete before startup from next (Cycle 4/5) refueling outage Schedule for mods will be submitted
DAYNE,J P Power Authority of the State of New York, 84/08/03
VARGA,S A Operating Reactors Branch 1 1p 26009 264 24X
Fiche 50-286,84/08/03,8408130309

--8408130313 "Detailed Control Room Design Review Program Plan "
* Power Authority of the State of New York 84/08/03 101pp
26009 265 24X Fiche 50-286,84/08/03,8408130309

8408150230 Forwards supplemental info re seismic capability of reactor coolant pump oil spillage collection sys & QA program utilized for initial App R, Section III G review Adds mods implemented to enhance seismic capability of collection sys
BAYNE, J P Power Authority of the State of New York 84/08/13
VARGA, S A Operating Reactors Branch 1 43pp 26066 005 24X
Fiche 50-286, 84/08/13, 8408150230

8408230164 Forwards "Reevaluation of App R, Section III G Requirements for Indian Point Nuclear Power Plant Unit 3 " Proposed schedule for implementation of mods encl
BAYNE, J P Power Authority of the State of New York 84/08/16
VARGA, S A Operating Reactors Branch 1 7pp 26215 065 24X
Fiche 50-286, 84/08/16, 8408230164

--8408230171 "Reevaluation of App R, Section III G Requirements for Indian Point Nuclear Power Plant Unit 3 "
* Power Authority of the State of New York 84/08/31 494pp
26215 072 24X Fiche 50-286, 84/08/16, 8408230164

G Adjudicatory correspondence

8408140448 Responses to 840730 unpublished order directing NRC & inviting other parties to submit views on Judge Gleason dissent re ASLB recommendation concerning accident probability Certificate of Svc encl
SHOLLY, S C Union of Concerned Scientists DSB 029 84/08/13
Commissioners 8pp 26061 007 24X Fiche 50-247, 84/08/13, 8408140448

8408140488 Response to Commission 840730 order permitting comments from parties re Chairman Gleason dissent to ASLB recommendations to Commission Certificate of Svc encl
COLARULLI, P F Power Authority of the State of New York
COLARULLI, P F Morgan Associates DSB 030 84/08/13
Commissioners 14pp 26060 261 24X Fiche 50-247, 84/08/13, 8408140488

8408140493 Comments on ASLB Chairman Gleason dissent in recommendations of special proceeding Significant risk reduction already accomplished at facility Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc DSB 031
84/08/13 Commissioners 12pp 26060 249 24X
Fiche 50-247, 84/08/13, 8408140493

8408150111 Response to Commission 840730 order directing NRC to file comments on Judge Gleason dissent to portion of ASLB recommendations Supports Gleason dissent
MOORE, J E Hearing Branch 1 DSB 042 84/08/13 Commissioners
14pp 26066 265 24X Fiche 50-247, 84/08/13, 8408150111

8408170270 Comments on dissenting views of Chairman Gleason re safety of plant mods Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc DSB 083
84/08/13 12pp 26118 041 24X Fiche 50-247, 84/08/13, 8408170270

P Operating license stage documents & correspondence

8408070055 Notification of 840720 meeting w/util in Bethesda, MD to discuss ESF electrical distribution mods
POLK, P J Operating Reactors Branch 1 84/07/18 VARGA, S A
Operating Reactors Branch 1 3pp 25955 333 24X
Fiche 50-286, 84/07/18, 8408070055

408090545 Summary of 840720 meeting w/util & BNL in Bethesda, MD re ESF mods Six solutions being considered & licensee agreed to docket final resolution Util agreed to expedite LER BNL & licensee presentations & attendance list encl
POLK, P J Operating Reactors Branch 3 84/08/02 Operating
Reactors Branch 3 46pp 25983 231 24X Fiche 50-286, 84/08/02, 8408090545

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160528 Forwards listing of info needed to complete review of environ qualification program Response requested within 45 days of ltr receipt W/o encl
VARGA, S A Operating Reactors Branch 1 84/08/07 BAYNE, J P
Power Authority of the State of New York 1p 26122-352 24X
Fiche 50-286, 84/08/07, 8408160528

8408170277 Forwards info on NUREG-0737, Item II B 3 re post-accident sampling sys, supplementing 831026, 1202 & 840323 submittals Results of engineering evaluation of post-accident airborne particulates will be sent by June 1985
BAYNE, J P Power Authority of the State of New York 84/08/13
VARGA, S A Operating Reactors Branch 1 3pp 26115 256 24X
Fiche 50-286, 84/08/13, 8408170277

8408210443 Forwards application for amend to License DPR-64, changing Tech Spec Sections 3 13, 4 11 & 6 10 re snubber surveillance Interim exemption from functional testing for steam generator snubbers also requested
BAYNE J P Power Authority of the State of New York 84/08/13
VARGA, S A Operating Reactors Branch 1 4pp 26181 262 24X
Fiche 50-286, 84/08/13, 8408210443

--8408210449 Application for amend to License DPR-64, changing Tech Spec Sections 3 13, 4 11 & 6 10 re snubber surveillance Safety evaluation of proposed Tech Spec change encl
BAYNE J P Power Authority of the State of New York 84/08/13
VARGA, S A Operating Reactors Branch 1 1p 26181 266 24X
Fiche 50-286, 84/08/13, 8408210443

--8408210451 Proposed Tech Specs, changing Sections 3 13, 4 11 & 6 10 re snubber surveillance
* Power Authority of the State of New York 84/08/13 16pp
26181 267 24X Fiche 50-286, 84/08/13, 8408210443

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408280333 Staff requirements memo re 840816 continuation of 840723 discussion of issues requiring resolution prior to issuance of order in proceeding Commission requested briefing on PRA including discussion of uncertainties & basis of comparison
CHILK, S J Office of the Secretary of the Commission 84/08/21
DIRCKS, W J Office of the Executive Director for Operations 2pp
26294 050 24X Fiche 50-003, 84/08/21, 8408280333

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25965 047 24X Fiche 50-000, 84/07/27, 8407250229

8408150697 Forwards IE Insp Rept 50-286/84-12 on 840521-25 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
BRONS, J C Power Authority of the State of New York 2pp
26079 009 24X Fiche 50-286, 84/07/27, 8408150697

--8408150701 IE Insp Rept 50-286/84-12 on 840521-25 No noncompliance noted Major areas inspected mgt controls, radioactive effluent release records, effluent control procedures, instrument calibrs & testing of air cleaning sys
STRUCKMEYER, R , PASCIAK, W J Region 1, Office of Director
84/07/20 6pp 26079 011 24X Fiche 50-286, 84/07/27, 8408150697

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 138 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New
York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post
830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000 84/08/13, 8408100009

8408100038 IE Info Notice 84-64 "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408310177 Responds to Item 4 of IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller, Inc Existing QA program will provide necessary methods for early detection of potentially fraudulent or deficient products
BRONS, J C Power Authority of the State of New York 84/08/17
EBNETER, S D Region 1, Office of Director 3pp 26318 319 24X Fiche 50-286, 84/08/17, 8408310177

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408310251 Notification of Significant Licensee Meeting 84-79 on 840913 w/util at site to present results of SALP
NORRHOLM, L Division of Project & Resident Programs 84/08/21
Division of Project & Resident Programs 2pp 26350 357 24X Fiche 50-286, 84/08/21, 8408310251

R Periodic operating reports & related correspondence

8408230428 Monthly operating rept for Jul 1984 W/840815 ltr
KELLY, L , BRONS, J L Power Authority of the State of New York
84/07/31 7pp 26213 049 24X Fiche 50-286, 84/07/31, 8408230428

S Reportable occurrences, LERs & related correspondence

8408010317 LER 84-011-00 on 840712, turbine generator trip & subsequent reactor trip initiated automatically due to failure of insulator on 345-kV feeder Caused by deposits on insulator Insulator replaced W/840725 ltr
ANDERSON, J J , BRONS, J C Power Authority of the State of New York
84/07/25 3pp 25866 144 24X Fiche 50-286, 84/07/25, 8408010317

8408240048 LER 84-012-00 on 840712, Westinghouse advised of potential overpressure in component cooling water sys during inleakage & heat load increases due to tube rupture Relief & vent valves modified to ease overpressure concern W/840817 ltr
ANDERSON, J J , BRONS, J C Power Authority of the State of New York
84/08/17 3pp 26236 199 24X Fiche 50-286, 84/08/17, 8408240048

T Hearing transcripts on non-antitrust matters

8408280025 Transcript of 840816 Commission meeting in Washington, DC re continuation of 840723 discussion of adjudicatory proceeding Pp 1-76
* Commissioners 84/08/16 78pp 26293 169 24X Fiche 50-003, 84/08/16, 8408280025

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8408300241 Ack receipt of scope & objectives for 840621 emergency preparedness exercise Submittal fulfills min requirements for small-scale exercise Complete scenario will be reviewed when received & comments transmitted
DANCE, H C Region 2, Office of Director 84/05/21 TUCKER, H B
Duke Power Co 1p 26307 015 24X Fiche 50-269, 84/05/21, 8408300244

8408300427 Forwards FEMA "Oconee Nuclear Power Plant Full-Scale Local Exercise Conducted on 830406," final rept
DANCE, H C Region 2, Office of Director 84/07/11 TUCKER, H B
Duke Power Co 1p 26315 205 24X Fiche 50-269, 84/07/11, 8408300427

8408150326 Forwards public version of Rev 84-02 to "Emergency Plan Implementing Procedures "
TUCKER, H B Duke Power Co 84/07/17 O'REILLY, J P Region 2, Office of Director 1p 26099 001 24X Fiche 50-269, 84/07/17, 8408150326

--8408150335 Public version of Rev 84-02 to "Emergency Plan Implementing Procedures " W/JM Felton 840808 release memo
TUCKMAN, M S Duke Power Co 84/06/07 195pp 26099 002 24X Fiche 50-269, 84/07/17, 8408150326

8408240416 Forwards Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/19 TUCKER, H B
Duke Power Co 1p 26237 113 24X Fiche 50-269, 84/07/19, 8408240416

--8408240421 Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations, maint, surveillance, ESF, emergency drills & fuel handling
BRYANT, J Region 2, Office of Director 84/07/19 6pp
26237 114 24X Fiche 50-269, 84/07/19, 8408240416

8408280361 Forwards Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/07/20 TUCKER, H B
Duke Power Co 2pp 26282 239 24X Fiche 50-269, 84/07/20, 8408280361

--8408280370 Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise
DECKER, T R Region 2, Office of Director 84/07/06 9pp
26282 241 24X Fiche 50-269, 84/07/20, 8408280361

8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/08/07 TUCKER, H B
Duke Power Co 2pp 26007 344 24X Fiche 50-269, 84/08/07, 8408130149

--8408130166 IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 73 21)
MOORE, D E Region 2, Office of Director 84/08/07 1p
26007 346 24X Fiche 50-269, 84/08/07, 8408130149

8408170329 Commits to assure that operators can obtain flashlight to assist in safe passage to standby shutdown facility, per requirements of 10CFR50, App R
TUCKER, H B Duke Power Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 26112 361 24X Fiche 50-269, 84/08/08, 8408170329

8408300357 Confirms 840806 telcon w/JP O'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50, fire protection & 10CFR73, physical protection Agenda encl
LENIS, R C Region 2, Office of Director 84/08/08 TUCKER, H B
Duke Power Co 3pp 26314 222 24X Fiche 50-000, 84/08/08, 8408300357

8408200414 Forwards draft safety evaluation of procedures generation package for emergency operating procedures Response to open items re writers guide & validation/verification programs requested within 30 days of ltr receipt
RIVENBARK, G W Operating Reactors Branch 4 84/08/09 TUCKER, H B
Duke Power Co 2pp 26182 001 24X Fiche 50-269, 84/08/09, 8408200414

--8408200424 Draft safety evaluation of procedures generation package
Package should be revised to address items in Section 2
* NRC - No Detailed Affiliation Given 84/08/09 11pp
26182 003 24X Fiche 50-269,84/08/09,8408200414

8408300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
TUCKER,H B Duke Power Co 84/08/10 Record Services Branch (Document Control Desk) 21pp 26332 353 24X
Fiche 50-000,84/08/10,8408300014

--8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations "
* Duke Power Co 84/08/15 30pp 26333 010 21X
Fiche 50-000,84/08/10,8408300014

--8408300028 Public version of revised crisis mgt plan implementing procedures, including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 memo
* Duke Power Co 84/08/15 170pp 26333 040 24X
Fiche 50-000,84/08/10,8408300014

8408220091 Forwards three exemption requests from 10CFR50,App R,Section III G 2 requirements re fire protection of safe shutdown capability, supplementing 831024 initial request No addl fees necessary
TUCKER,H B Duke Power Co 84/08/14 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 4pp 26193 289 24X Fiche 50-269,84/08/14,8408220091

8408310121 Requests extension of time to respond to 840720 ltr re util plans for establishing emergency operations facility design consistent w/requirements of Suppl 1 to NUREG-0737 Extension requested due to judicial review of util appeal
TUCKER,H B Duke Power Co 84/08/24 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 2pp 26322 243 24X Fiche 50-269,84/08/24,8408310121

I Financial information

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER,H B Duke Power Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26237 137 24X
Fiche 50-000,84/08/16,8408240224

--8408240242 "1983 Annual Rept "
LEE,W S Duke Power Co 83/12/31 4/pp 26237 167 24X
Fiche 50-000,84/08/16,8408240224

K Utility Final Safety Analysis Report (FSAR) & amends

8408220201 Forwards updated FSAR for Oconee Nuclear Station Info brings FSAR up to date as of 831231
TUCKER,H B Duke Power Co 84/08/15 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 1p 26191 023 24X Fiche 50-269,84/08/15,8408220201

--8408220208 Updated FSAR for Oconee Nuclear Station
* Duke Power Co 83/12/31 180pp 26191 024 24X
Fiche 50-269,84/08/15,8408220201

P Operating license stage documents & correspondence

8408070389 Forwards "Extension of Retainer Lifetime to Four Cycles," for Oconee,Unit 3 w/results of exams of two retainers after three cycles Approval of four-cycle retainer usage requested before Dec 1984
TAYLOR,J H Babcock & Wilcox Co 84/07/24 STOLZ,J J Operating Reactors Branch 4 1p 25945 252 24X Fiche 50-000,84/07/24,
8408070389

--8408070392 "Extension of Retainer Lifetime to 4 Cycles "
* Babcock & Wilcox Co 84/07/12 6pp 25945 253 24X
Fiche 50-000,84/07/24,8408070389

8408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 220 24X Fiche 50-000,84/07/27,
8408080288

8408200149 Application for amend to Licenses DPR-38,DPR-47 & DPR-55, updating Tech Spec 4 2 4 re reactor vessel matl surveillance to incorporate changes documented in BAW-1543 W/o stated fee
TUCKER,H B Duke Power Co 84/08/02 DENTON H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 3pp 26133 286 24X Fiche 50-269,84/08/02,8408200149

--8408200155 Proposed Tech Spec 4 2 1 re reactor vessel matl surveillance NSHC evaluation encl
* Duke Power Co 84/08/02 7pp 26133 289 24X
Fiche 50-269,84/08/02,8408200149

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors ' license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408200059 Application for amend to Licenses DPR-38,DPR-47 & DPR-55, revising air lock testing frequency from quarterly to semiannually Fee encl
TUCKER,H B Duke Power Co 84/08/08 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 3pp 26133 296 24X Fiche 50-269,84/08/08,8408200059

--8408200069 Proposed Tech Specs 4 4 1 5 2 (a),revising air lock testing frequency from quarterly to semiannually
* Duke Power Co 84/08/08 6pp 26133 299 24X
Fiche 50-269,84/08/08,8408200059

8408220292 Forwards augmented response to Generic Ltr 83-28, Items 4 1 & 4 2 re reactor trip sys reliability vendor related mods & preventive maint & surveillance program for reactor trip breakers, respectively, per 831104 & 1230 ltrs
TUCKER,H B Duke Power Co 84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 6pp 26194 072 24X Fiche 50-269,84/08/10,8408220292

8408230527 Forwards payment for application fee re 840802 & 08 Tech Spec changes
BARR,S Duke Power Co 84/08/15 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 1p 26236 286 24X Fiche 50-000,84/08/15,8408230527

8408270339 Application for amend to Licenses DPR-38,DPR-47 & DPR-55, revising Tech Specs re reactor bldg purge sys,protection from inadvertent low temp overpressurization & min operator staffing requirements
TUCKER,H B Duke Power Co 84/08/15 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 8pp 26244 307 24X Fiche 50-269,84/08/15,8408270339

--8408270345 Proposed Tech Specs,changing reactor bldg purge sys, protection from inadequate low temp overpressurization & min operator staffing requirements
* Duke Power Co 84/08/15 14pp 26244 315 24X
Fiche 50-269,84/08/15,8408270339

8408270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submittal of semiannual radioactive effluent release rept for Jul-Dec 1984
TUCKER,H B Duke Power Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 26279 112 24X Fiche 50-000,84/08/16,8408270160

--8408270169 Rev 4 to "Offsite Dose Calculation Manual "
BIRCH,H L , HAMPTON,J W Duke Power Co 84/07/18 39pp
26279 114 24X Fiche 50-000,84/08/16,8408270160

8408270464 Forwards list of questions generated during preliminary review of pump & valve inservice testing Conference call should be arranged w/staff able to provide appropriate technical expertise
STOLZ,J F Operating Reactors Branch 4 84/08/17 TUCKER,H B
Duke Power Co 10pp 26277 210 24X Fiche 50-269,84/08/17,
8408270464

8408270499 Forwards request for addl info re NUREG-0737, Item III D 3 4 Control Room Habitability ' Response requested within 30 days of ltr receipt
STOLZ, J F Operating Reactors Branch 3 84/08/17 TUCKER, H B
Duke Power Co 3pp 26277 039 24X Fiche 50-269, 84/08/17, 8408270499

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8408280241 Informs of delay until 860301 to complete mods required by IE Bulletin 79-14 Delay due to increase in total number of mods required
TUCKER, H B Duke Power Co 84/06/21 O'REILLY, J P Region 2, Office of Director 2pp 26262 241 24X Fiche 50-269, 84/06/21, 8408280241

8408240416 Forwards Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/19 TUCKER, H B
Duke Power Co 1p 26237 113 24X Fiche 50-269, 84/07/19, 8408240416

--8408240421 Insp Repts 50-269/84-15, 50-270/84-14 & 50-287/84-18 on 840611-0710 No noncompliance or deviations noted Major areas inspected operations, maint, surveillance, ESF, emergency drills & fuel handling
BRYANT, J , BASSER, K , BROWNLEE, V L Region 2, Office of Director 84/07/19 4pp 26237 114 24X Fiche 50-269, 84/07/19, 8408240416

8408280361 Forwards Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/07/20 TUCKER, H B
Duke Power Co 2pp 26282 239 24X Fiche 50-269, 84/07/20, 8408280361

--8408280370 Insp Repts 50-269/84-14, 50-270/84-13 & 50-287/84-16 on 840619-21 No violations or deviations identified Major area inspected emergency preparedness exercise
DECKER, T R , STANSBERRY, W W , CLINE, W E Region 2, Office of Director 84/07/06 9pp 26282 241 24X Fiche 50-269, 84/07/20, 8408280361

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408280472 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14
LEWIS, R C Region 2, Office of Director 84/08/01 TUCKER, H B
Duke Power Co 1p 26282 049 24X Fiche 50-269, 84/08/01, 8408280472

--8408280476 Responds to NRC 840622 ltr re violations noted in Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 Corrective actions Procedure OP/O/A/1510/10 revised to require neutron shield tank level prior to offsite shipments
TUCKER, H B Duke Power Co 84/07/20 O'REILLY, J P Region 2, Office of Director 4pp 26282 046 24X Fiche 50-269, 84/08/01, 8408280472

--8408280479 Forwards Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 on 840604-08 & notice of violation
LEWIS, R C Region 2, Office of Director 84/06/22 TUCKER, H B
Duke Power Co 2pp 26282 050 24X Fiche 50-269, 84/08/01, 8408280472

--8408280481 Notice of violation from insp on 840604-08
* Region 2, Office of Director 84/06/22 2pp 26282 052 24X Fiche 50-269, 84/08/01, 8408280472

--8408280485 Insp Repts 50-269/84-12, 50-270/84-12 & 50-287/84-14 on 840604-08 Noncompliance noted failure to verify presence & condition of neutron radiation moderator prior to shipping & failure to perform neutron radiation surveys
WEDDINGTON, R E , JENKINS, O R Region 2, Office of Director 84/06/19 8pp 26282 054 24X Fiche 50-269, 84/08/01, 8408280472

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 138 24X Fiche 50-000, 84/08/06, 8408010337

8408130149 Forwards IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/08/07 TUCKER, H B
Duke Power Co 2pp 26007 344 24X Fiche 50-269, 84/08/07, 8408130149

--8408130166 IE Safeguards Insp Repts 50-269/84-17, 50-270/84-16 & 50-287/84-19 on 840716-20 No violation or deviations identified Major areas inspected security sys power supply & alarm station Details withheld (ref 10CFR2 790 & 73 21)
MOORE, D E , MCGUIRE, D R Region 2, Office of Director 84/08/07 1p 26007 346 24X Fiche 50-269, 84/08/07, 8408130149

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 116 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408220468 Monthly operating repts for Jul 1984 W/840815 ltr
REAVIS, J A , TUCKER, H B Duke Power Co 84/07/31 17pp 26196 033 24X Fiche 50-269, 84/07/31, 8408220468

S Reportable occurrences, LERs & related correspondence

8408300497 Suppl to Rev 1 to RO-287/83-13 containment isolation valve 3CS-5 declared inoperable due to leakage past seat. Investigation into valve failure conducted & diaphragm replaced
TUCKER, H B Duke Power Co 84/08/22 Record Services Branch (Document Control Desk) 2pp 26314 071 24X Fiche 50-287, 84/08/22, 8408300497

DOCKETED ITEMS

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical emergency & fire protection plans

8408080243 Forwards IE Insp Rept 50-289/84-06 on 840212-0412 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/18
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
25974 341 24X Fiche 50-289, 84/07/18, 8408080243

--8408080250 Notice of violation from insp on 840212-0412
* Region 1, Office of Director 84/07/18 1p 25974 343 24X
Fiche 50-289, 84/07/18, 8408080243

--8408080256 IE Insp Rpt 50-289/84-06 on 840212-0412 Violation noted failure to document engineering justification for "use-as-is" disposition of nonconforming items in area of fire protection/prevention
NICHOLAS, H H Division of Engineering & Technical Programs
PAOLINO, R J , PAULITZ, F P Region 1, Office of Director
84/07/03 14pp 25974 344 24X Fiche 50-289, 84/07/18, 8408080243

8408030088 Forwards fee for review & approval of fire protection alternate safe shutdown capability, in response to NRC 840625 request Fee encl
HUKILL, H D General Public Utilities - GPU Service Corp 84/07/30
MILLER, W D License Fee Management Branch 1p 25916 042 24X
Fiche 50-289, 84/07/30, 8408030088

8408080131 Notification of 840815 meeting w/util & FEMA in Bethesda, MD to discuss resolution of offsite emergency planning deficiencies identified by FEMA during 831116 exercise
VAN VLIET, J Operating Reactors Branch 4 84/08/01 STOLZ, J F
Operating Reactors Branch 4 2pp 25979 111 24X
Fiche 50-289, 84/08/01, 8408080131

8408090097 Notification of 840814 meeting w/util in Bethesda, MD to discuss fire protection requirements re safe shutdown, fire areas vs fire zones & Rockbestos cable
SILVER, H Operating Reactors Branch 4 84/08/01 STOLZ, J F
Operating Reactors Branch 4 2pp 25991 255 24X
Fiche 50-289, 84/08/01, 8408090097

8408090199 Notification of 840816 meeting w/util & FEMA in Bethesda, MD to discuss resolution of offsite emergency planning deficiencies identified by FEMA during 831116 annual exercise
VAN VLIET, J Operating Reactors Branch 4 84/08/03 STOLZ, J F
Operating Reactors Branch 4 2pp 25991 203 24X
Fiche 50-289, 84/08/03, 8408090199

8408230382 Rev 9 to Emergency Plan Implementing Procedure 1004 27, "Activation of Emergency Operations Facility "
* General Public Utilities - GPU Service Corp 84/08/08 31pp
26205 319 24X Fiche 50-289, 84/08/08, 8408230382

8408160165 Informs of refund of fees from 840727 application for exemption from certain annual exercise requirements of 10CFR50, App E & 840604 application to correct error in Tech Spec 3 & 7 Fee assessment info encl
MILLER, W D License Fee Management Branch 84/08/10 HUKILL, H D
General Public Utilities - GPU Service Corp 3pp 26124 352 24X
Fiche 50-289, 84/08/10, 8408160165

8408280179 Revised Emergency Plan Implementing Procedures 1004 1 re unusual event, 1004 2 re alert & 1004 3 re site emergency w/transmittal & receipt form
BROWN, N D General Public Utilities - GPU Service Corp 84/08/14
22pp 26275 333 24X Fiche 50-289, 84/08/14, 8408280179

8408310166 Revised Emergency Plan Implementing Procedures 1004 15, "Post-Accident RCS Sampling & 1004 33, "Handling High Activity Reactor Coolant Samples Under Accident Conditions " W/transmittal & receipt form
KOUSEL, D J General Public Utilities - GPU Service Corp 84/08/22
63pp 26319 176 24X Fiche 50-289, 84/08/22, 8408310166

O Adjudicatory correspondence

8408020208 Responds to order requesting comments on resolution of mgt concerns affecting restart NRC has not adequately resolved outstanding issues & 1979 shutdown order should remain effective indefinitely Served on 840802
GEKAS, G W House of Rep DSB 714 84/06/05 PALLADINO, N
Commissioners 1p 25898 008 24X Fiche 50-289, 84/06/05, 8408020208

8407130502 GPU V B&W LAWSUIT REVIEW AND ITS EFFECT ON TMI-1 General Public Utilities Corporation et al v The Babcock & Wilcox Company, et al Three Mile Island Nuclear Station, Unit 1, Docket 50-289
* Office of Nuclear Reactor Regulation, Director NUREG-1020LD V01
84/06/30 152pp 25579 089 24X Fiche 50-289, 84/06/30, 8407130502

8408220362 Response to util comments on ASLB 840713 memorandum & order on lead intervenors' motion to partially exclude UCS from participation in mgt remand Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss DSB 195 84/07/13 11pp 26193 032 24X
Fiche 50-289, 84/07/13, 8408220362

8408010194 Comments on ASLB 840713 memorandum & order on lead intervenors Staff has no objection to assignment of lead intervenors provided that issue of NRC exam limited as previously ruled by ASLB Certificate of Svc encl
GOLDBERG, J R Hearing Branch 2 DSB 688 84/07/26 5pp
25855 168 24X Fiche 50-289, 84/07/26, 8408010194

8408020040 Reply to licensee 840611 response to suppl to UCS petition to show cause re emergency feedwater sys Util response evinces continuing ignorance & evasion of substantive requirements Certificate of Svc encl
WEISS, E R Union of Concerned Scientists DSB 691 84/07/31
Office of Nuclear Reactor Regulation, Director 10pp 25983 263
24X Fiche 50-289, 84/07/31, 8408020040

8408020042 Comments on 840713 memorandum & order on lead intervenors & motion to partially exclude UCS from participation in mgt remand ASLB should exclude UCS from participation in Dieckamp mailgram & leak rate issues W/Certificate of Svc
BLAKE, E L Metropolitan Edison Co BLAKE, E L Shaw, Pittman, Potts & Trowbridge DSB 695 84/07/31 Atomic Safety and Licensing Board Panel 30pp 25980 274 24X Fiche 50-289, 84/07/31, 8408020042

8408060201 First request for production of documents on or before 840816 Related correspondence
DOROSHOW, J , BERNABEI, L Three Mile Island Alert DOROSHOW, J
Christic Institute DSB 747 84/07/31 Atomic Safety and Licensing Board Panel 10pp 25925 319 24X Fiche 50-289, 84/07/31, 8408060201

--8408060224 First set of interrogatories to util Certificate of Svc encl
DOROSHOW, J , BERNABEI, L Three Mile Island Alert DOROSHOW, J
Christic Institute 84/07/31 Atomic Safety and Licensing Board Panel 36pp 25925 329 24X Fiche 50-289, 84/07/31, 8408060201

8408080246 Advises that proposed emergency exercise to be conducted on 841003 acceptable Region 1 will not participate in 840905 & 19 full-scale drills W/svc list Related correspondence
MARTIN, T T Division of Engineering & Technical Programs DSB 828
84/08/01 HUKILL, H D General Public Utilities - GPU Service Corp
3pp 25966 297 24X Fiche 50-289, 84/08/01, 8408080246

8408070382 First request for production of documents by 840812 Certificate of Svc encl Related correspondence
DOROSHOW, J , BERNABEI, L Three Mile Island Alert DOROSHOW, J
Christy, W DSB 783 84/08/03 Office of the Executive Legal Director 13pp 25947 074 24X Fiche 50-289, 84/08/03, 8408070382

8408070408 First set of interrogatories Response by 840823 requested Certificate of Svc encl Related correspondence
DOROSHOW, J , BERNABEI, L Three Mile Island Alert BERNABEI, L
Government Accountability Project DSB 786 84/08/03 Office of the Executive Legal Director 18pp 25942 152 24X
Fiche 50-289, 84/08/03, 8408070408

8408070437 Proposed findings of fact, conclusions of law & brief in form of proposed initial decision re steam generator repair Certificate of Svc encl
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge DSB 796 84/08/03 111pp 25944 038
24X Fiche 50-289, 84/08/03, 8408070437

8408270046 Order scheduling oral presentations on 840815 in Washington, DC re whether mgt concerns which led to 1979 shutdown order sufficiently resolved Confirmation of participation requested by 840810 Served on 840806
CHILK, S J Office of the Secretary of the Commission DSB 298
84/08/06 14pp 26247 050 24X Fiche 50-289, 84/08/06, 8408270046

8408090415 Informs that NRC will participate in oral presentation scheduled for 840815, per Commission 840806 order Staff intends to present brief remarks & use remainder of time to respond to questions re restart
GOLDBERG, J R Hearing Branch 2 DSB 886 84/08/08 CHILK, S J
Office of the Secretary of the Commission 1p 25982 217 24X
Fiche 50-289, 84/08/08, 8408090415

8408090423 Advises that WG Kuhns & PR Clark will make principal presentations on util behalf at 840815 Commission meeting, per Commission 840806 order
TROWBRIDGE,G F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE,G F Metropolitan Edison Co DSB 882 84/08/08 CHILK,S J Office of the Secretary of the Commission 1p 25982 216 24X
Fiche 50-289,84/08/08,8408090423

8408100133 Responds to 840607 request to postpone decision on restart until reactor safety & mgt integrity assured Oral argument scheduled for 840815 Restart will not be authorized until plant safety assured
MALSCH,M G Office of the General Counsel DSB 889 84/08/08
SCHINK,A B , MCMANUS,A League of Women Voters of Pennsylvania 1p 25991 024 24X Fiche 50-289,84/08/08,8408100133

--8408100144 Requests restart decision be postponed until reactor safety & mgt integrity can be assured
SCHINK,A B , MCMANUS,A League of Women Voters of Pennsylvania 84/06/07 PALLADINO,N J Commissioners 2pp 25991 025 24X
Fiche 50-289,84/08/08,8408100133

8408130300 Forwards 840725 status rept on licensee progress towards completion of required actions identified in Basic Energy Technology Assoc 830228 rept Svc list encl Related correspondence
BAUSER,D B Shaw, Pittman, Potts & Trowbridge BAUSER,D B Metropolitan Edison Co DSB 902 84/08/09 SMITH,I W , WOLFE,S J , LINENBERGER,G Atomic Safety and Licensing Board Panel 22pp 26010 281 24X Fiche 50-289,84/08/09,8408130300

8408130396 Motion for extension of time until 840817 to reply to licensee 840731 motion to exclude UCS from particiption Certificate of Svc encl
JORDAN,W S Union of Concerned Scientists JORDAN,W S Harmon & Weiss DSB 905 84/08/09 Atomic Safety and Licensing Board Panel 4pp 26011 108 24X Fiche 50-289,84/08/09,8408130396

8408140035 Motion for extension of time to reply to licensee 840731 motion to exclude UCS from participation Granted for ASLB on 840810 Served on 840813
JORDAN,W S Union of Concerned Scientists JORDAN,W S Harmon & Weiss DSB 952 84/08/09 Atomic Safety and Licensing Board Panel 2pp 26044 207 24X Fiche 50-289,84/08/09,8408140035

8408140131 Informs that Commonwealth of PA will not file proposed findings of fact or conclusions of law in proceeding but reserves right to participate on appeal,per 10CRF2 715(c) Certificate of Svc encl
AU,T Y Pennsylvania, Commonwealth of, DSB 960 84/08/09
WOLFE,S J , HETRICK,D L , LAMB,J C Atomic Safety and Licensing Board Panel 3pp 26047 016 24X Fiche 50-289,84/08/09,8408140131

8408200580 Expresses dissatisfaction w/staff conclusions re author in Suppl 5 to NUREG-0680 concerning RCS leak rate tests Conclusion that author involved or implicated in indictment misleading & unfair NRC conclusions should not be adopted
SEELINGER,J L Affiliation Not Assigned DSB 163 84/08/09
PALLADINO,N J Commissioners 2pp 26137 138 24X
Fiche 50-289,84/08/09,8408200580

8408140007 Reply to UCS 840726 comments on restart UCS comments reflect deep misunderstanding of procedural posture of restart proceeding Certificate of Svc encl
TROWBRIDGE,G F Metropolitan Edison Co TROWBRIDGE,G F Shaw, Pittman, Potts & Trowbridge DSB 993 84/08/10 16pp 26044 046 24X Fiche 50-289,84/08/10,8408140007

8408140010 Proposed findings of fact & conclusion of law re issue of steam generator repair Certificate of Svc encl
BRADFORD,L Three Mile Island Alert DSB 954 84/08/10 21pp 26044,107 24X Fiche 50-289,84/08/10,8408140010

8408140449 Petition for revocation of license on basis of deficient character Licensee record of wrongdoing directly related to fundamental character flaws inherent within company Certificate of Svc encl
WAMBACH,P C , SHUMAKER,J Pennsylvania, Commonwealth of;
SORDILL,P Women's International League for Peace & Freedom DSB 007 84/08/13 Commissioners 200pp 26061 023 24X
Fiche 50-000,84/08/13,8408140449

8408140465 Response opposing 840806 order Commission should disqualify itself & refer restart decision to appropriate Federal Court Commission primary concern should not be protecting licensee
LEWIS,M I Lewis, M DSB 016 84/08/13 Commissioners 2pp 26060 350 24X Fiche 50-289,84/08/13,8408140465

8408140474 Informs that ER Weiss will appear to present oral arguments on 840815 on behalf of UCS
WEISS,E R Harmon & Weiss WEISS,E R Union of Concerned Scientists DSB 010 84/08/13 CHILK,S J Office of the Secretary of the Commission 1p 26060 332 24X Fiche 50-289,84/08/13,8408140474

8408140479 Second request for production of documents to GPU Certificate of Svc encl Related correspondence
DOROSHOW,J , BERNABEI,L Three Mile Island Alert DOROSHOW,J Christy W DSB 032 84/08/13 Atomic Safety and Licensing Board Panel 14pp 26060 280 24X Fiche 50-289,84/08/13,8408140479

8408150139 Ack receipt of 840806 ltr presenting questions that ASLB answered during 840716 limited appearance session ASLB answers unchanged except that hearing was concluded on 840718 Served on 840814
WOLFE,S J Atomic Safety and Licensing Board Panel DSB 047 84/08/13 CORRADI,J Affiliation Not Assigned 2pp 26066 279 24X Fiche 50-289,84/08/13,8408150139

8408200521 Protests ref to author in Suppl 5 to NUREG-0680 as one of five util mgt personnel involved or implicated in indictment Staff accusation improper & damaging to author reputation Requests withdrawal of findings
KUNDER,G A Affiliation Not Assigned DSB 162 84/08/13
PALLADINO,N J Commissioners 2pp 26136 341 24X
Fiche 50-289,84/08/13,8408200521

8408200531 Protests treatment of author in Suppl 5 to NUREG-0680 re leak rate tests at TMI-2 US Atty conclusions in statement of fact misleading,out of context or erroneous Requests refusal of staff conclusions
FLOYD,J R Affiliation Not Assigned DSB 161 84/08/13
PALLADINO,N J Commissioners 2pp 26137 026 24X
Fiche 50-289,84/08/13,8408200531

8408150145 Proposed correction to Commission 840806 order Statement & implication in Page 2 footnote inaccurate UCS did not participate in initial hearings on mgt issues or in cheating hearings & was not directed to file findings by ASLB
WEISS,E R Union of Concerned Scientists DSB 041 84/08/14 3pp 26066 319 24X Fiche 50-289,84/08/14,8408150145

8408150458 Transmittal of "Risks to Safe Operation of TMI-1 Posed by Cleanup Operations at TMI-2 " Svc list encl Related correspondence
BLAKE,E L Metropolitan Edison Co DSB 060 84/08/14 14pp 26068 271 24X Fiche 50-289,84/08/14,8408150458

8408150489 Informs of Commissioner Zech 840830-31 visit to facility Each party invited to send representative to accompany Commissioner Response requested by 840824 Served on 840815
MONTGOMERY,J Commissioners DSB 058 84/08/14 Office of the Executive Legal Director 1p 26068 159 24X Fiche 50-289, 84/08/14,8408150489

8408200455 Expresses concern re cleanup of Unit 2 & possible restart of Unit 1 NRC should issue mandatory cleanup schedule & require adequate funding plan,plant demonstration of safe working order & proof of util integrity before restart
FISCHER,D S Lancaster County, PA DSB 167 84/08/14 NRC - No Detailed Affiliation Given 2pp 26136 290 24X
Fiche 50-289,84/08/14,8408200455

8408170311 Forwards Investigation Rept 1-83-010 re TMI-2 alleged falsification of leak rate surveillance test data Served on 840816
HAYES,B B Office of Investigation DSB 096 84/08/15 PALLADINO, ROBERTS, ASSELSTINE Commissioners 727pp 26116 001 24X
Fiche 50-289,84/08/15,8408170311

8408170325 Motion for protective order on documents requested by TMI Alert concerning Dieckamp mailgram which exceed or lie outside scope of mailgram & proceeding Related correspondence
TROWBRIDGE,G F Metropolitan Edison Co TROWBRIDGE,G F. Shaw, Pittman, Potts & Trowbridge DSB 087 84/08/15 Atomic Safety and Licensing Board Panel 12pp 26113 335 24X
Fiche 50-289,84/08/15,8408170325

--8408170330 Request for extension of time until 840904 to respond to TMI Alert 840731 first set of interrogatories Certificate of Svc encl Related correspondence
TROWBRIDGE,G F Metropolitan Edison Co TROWBRIDGE,G F Shaw, Pittman, Potts & Trowbridge 84/08/15 Atomic Safety and Licensing Board Panel 6pp 26113 347 24X Fiche 50-289, 84/08/15,8408170325

8408220296 Urges that Commission not consider issue of restart unless & until all steps completed to ensure complete cleanup of TMI-2 & health & safety of public Served on 840921
HEINZ,J Senate DSB 202 84/08/15 PALLADINO,N J Commissioners 2pp 26193 081 24X Fiche 50-289,84/08/15, 8408220296

8408170335 Proposed correction to Commission 840806 order Statement in Page 2 footnote & implications re UCS participation in hearings inaccurate Footnote should be expunged or modified to fully reflect facts
WEISS,E R Union of Concerned Scientists DSB 092 84/08/16 3pp 26113 360 24X Fiche 50-289,84/08/16,8408170335

8408200468 First set of interrogatories & first request for production of documents re training Certificate of Svc encl Related correspondence
BAUSER,D B Metropolitan Edison Co BAUSER,D B Shaw, Pittman, Potts & Trowbridge DSB 156 84/08/16 Three Mile Island Alert 10pp 26136 296 24X Fiche 50-289,84/08/16,8408200468

8408200515 First set of interrogatories & first request for production of documents re training Certificate of Svc encl Related correspondence
BAUSER,D B Metropolitan Edison Co BAUSER,D B Shaw, Pittman, Potts & Trowbridge DSB 155 84/08/16 Union of Concerned Scientists 9pp 26137 017 24X Fiche 50-289,84/08/16,8408200515

8408200557 Second set of interrogatories & request for production of documents pertaining to reopened hearing on Dieckamp mailgram Certificate of Svc encl Related correspondence
BLAKE,E L Metropolitan Edison Co BLAKE,E L Shaw, Pittman, Potts & Trowbridge DSB 147 84/08/17 Three Mile Island Alert 14pp 26137 030 24X Fiche 50-289,84/08/17,8408200557

8408200561 Memorializes changes to TMI Alert 840731 first request for production of documents & first set of interrogatories to util discussed at 840813 meeting Svc list encl Related correspondence
LEWIS,D R Shaw, Pittman, Potts & Trowbridge LEWIS,D R Metropolitan Edison Co DSB 146 84/08/17 BERNABEI,L Government Accountability Project 6pp 26137 044 24X Fiche 50-289,84/08/17, 8408200561

8408220307 Forwards Harrisburg City Council Resolution 171-1984 objecting to TMI-1 restart & licensure of util to operate facility Served on 840821 W/Certificate of Svc
BERRY,R B Harrisburg, PA DSB 203 84/08/17 PALLADINO,N Commissioners 2pp 26194 067 24X Fiche 50-289,84/08/17, 8408220307

8408220258 Informs of agreement w/wording of 840813 discovery requests re interrogatories Verification that document requests & interrogatories not burdensome,oppressive or overbroad requested
BERNABEI,L Government Accountability Project BERNABEI,L Three Mile Island Alert DSB 193 84/08/20 LEWIS,D R Shaw, Pittman, Potts & Trowbridge 1p 26193 140 24X Fiche 50-289,84/08/20, 8408220258

--8408220263 Opposition to licensee 840815 motion for protective order re TMI Alert first set of interrogatories & first request for production & motion for extension of time to reply to TMI Alert first set of interrogatories W/Certificate of Svc
BERNABEI,L Three Mile Island Alert BERNABEI,L Government Accountability Project 84/08/20 Atomic Safety and Licensing Board Panel 62pp 26193 141 24X Fiche 50-289,84/08/20, 8408220258

8408220366 Forwards RD Parks 840724 ltr re concerns over NRC handling of allegations of mismanagement in cleanup.Ltr referred to in TMI Alert comments on Commission 840601 order
BERNABEI,L Government Accountability Project BERNABEI,L Three Mile Island Alert DSB 204 84/08/20 Atomic Safety and Licensing Board Panel 1p 26189 357 24X Fiche 50-289,84/08/20, 8408220366

--8408220373 Expresses concerns over NRC handling of allegations of mismanagement in cleanup NRC mastered art of obfuscation Response from Commission & forwarding of ltr to ASLB requested
PARKS,R D Affiliation Not Assigned 84/07/24, PALLADINO,N J , ROBERTS,T , ASSELSTINE,J Commissioners 4pp 26189 358 24X Fiche 50-289,84/08/20,8408220366

8408270176 Proposed findings of fact,conclusions of law & order in form of initial decision re steam generator tube repair
WAGNER,M E Hearing Branch 4 DSB 297, 84/08/20 11pp 26243 280 24X Fiche 50-289,84/08/20,8408270176

--8408270183 Brief in support of staff proposed findings of fact re steam generator tube repair
WAGNER,M E Hearing Branch 4 84/08/20 26pp 26243 291 24X Fiche 50-289,84/08/20,8408270176

8408220358 Order extending time until 840827 for Commission to act to review Director's Decision DD-84-18 Served on 840821
CHILK,S J Office of the Secretary of the Commission DSB 194 84/08/21 Commissioners 1p 26191 354 24X Fiche 50-289,84/08/21,8408220358

8408230207 Informs that licensee will make good faith effort to answer TMI Alert Document Request 7 & Interrogatories 2-9 & 42 Licensee reserves right to object to further efforts as burdensome & unreasonable W/svc list Related correspondence
LEWIS,D R Shaw, Pittman, Potts & Trowbridge LEWIS,D R Metropolitan Edison Co DSB 221 84/08/21 BERNABEI,L Government Accountability Project 3pp 26209 215 24X Fiche 50-289,84/08/21, 8408230207

8408230272 Reply to 840810 & 20 proposed findings of fact & conclusions of law filed by TMI Alert & NRC staff, respectively Certificate of Svc encl
CHURCHILL,B W Metropolitan Edison Co CHURCHILL,B W Shaw, Pittman, Potts & Trowbridge DSB 212 84/08/21 20pp 26206 139 24X Fiche 50-289,84/08/21,8408230272

8408240245 Notification of intent to attend 840830-31 site visit & expresses objection to util orientation UCS urges Commissioner to forego orientation Certificate of Svc encl
WEISS,E R Union of Concerned Scientists WEISS,E R Harmon & Weiss DSB 266 84/08/21 4pp 26223 062 24X Fiche 50-289,84/08/21,8408240245

8408240251 Forwards Pages 16A & 16B of TMI Alert second set of interrogatories re training issue Amend to Document Request 36 of second request for production to ref Interrogatories 28,29 & 30 recommended Related correspondence
BERNABEI,L Government Accountability Project BERNABEI,L Three Mile Island Alert DSB 265 84/08/21 BAUSER,D Shaw, Pittman, Potts & Trowbridge 3pp 26222 355 24X Fiche 50-289,84/08/21, 8408240251

8408230325 Notice of withdrawal of appearance in proceeding Certificate of Svc encl
SHOLLY,S C Union of Concerned Scientists DSB 256 84/08/22 3pp 26205 354 24X Fiche 50-289,84/08/22,8408230325

8408240250 Forwards supplemental pages for 840813 petition for revocation of license of GPU on basis of deficient character
DORSHOW,J Three Mile Island Alert DSB 258 84/08/22 Commissioners 1p 26223 018 24X Fiche 50-000,84/08/22, 8408240250

--8408240257 Supplemental pages to petition for revocation of license on basis of deficient character Certificate of Svc encl
R General Public Utilities - GPU Service Corp 84/08/13 Atomic Safety and Licensing Board Panel 43pp 26223 019 24X Fiche 50-000,84/08/22,8408240250

8408270072 Response opposing TMI Alert 840803 first set of interrogatories & motion for protective order re discovery to which staff objected Certificate of Svc encl Related correspondence
GOLDBERG,J R Hearing Branch 2 DSB 307 84/08/22 Three Mile Island Alert 16pp 26247 167 24X Fiche 50-289,84/08/22, 8408270072

8408280175 Order extending time until 840907 for Commission to act to review ALAB-772 Served on 840823
CHILK,S J Office of the Secretary of the Commission DSB 335 84/08/22 Commissioners 1p 26259 055 24X Fiche 50-289,84/08/22,8408280175

8408280412 Comments on SECY-84-237 re TMI-1 restart,per 840727 memo Cutting subcooling margin removes buffer of string error & time operator has to react to reading before problem
LEWIS,M I Lewis, M DSB 348 84/08/22 Office of the Secretary of the Commission 1p 26280 217 24X Fiche 50-289,84/08/22, 8408280412

8408270115 Request for extension of time until 840912 to answer TMI Alert second set of interrogatories Certificate of Svc encl Related correspondence
BAUSER,D B Metropolitan Edison Co BAUSER,D B Shaw, Pittman, Potts & Trowbridge DSB 283 84/08/23 Atomic Safety and Licensing Board Panel 6pp 26247 332 24X Fiche 50-289,84/08/23, 8408270115

8408270145 Forwards TMI Public Health Fund "First Two Yrs Rept to Court & Public," per 840815 meeting re study unreleased by court & petition concerning expenditures from TMI Public Health Fund
CLARK,P R General Public Utilities - GPU Service Corp 84/08/23
DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26245 157 24X Fiche 50-289,84/08/23,8408270145

--8408270149 "First Two Yrs Rept to Court & Public " Related info encl
* TMI Public Health Fund 84/08/23 44pp 26245 161 24X
Fiche 50-289,84/08/23,8408270145

8408270359 Objection to waiver of subcooling criteria & comments on NRC safety evaluation of subcooling criteria for actuating or throttling HPI Certificate of Svc encl
WEISS,E R Union of Concerned Scientists WEISS,E R Harmon & Weiss DSB 316 84/08/24 15pp 26245 040 24X
Fiche 50-289,84/08/24,8408270359

8408280493 Provides corrected date of 840817 to UCS 840713 response re util comments on 830713 memorandum & order on lead intervenors & motion to partially exclude UCS from participation in mgt remand
WEISS,E R Harmon & Weiss WEISS,E R Union of Concerned Scientists DSB 357 84/08/24 SMITH,I W , WOLFE,S J , LINENBERGER,C Atomic Safety and Licensing Board Panel 1p 26280 345 24X Fiche 50-289,84/08/24,8408280493

8408280168 Order extending time until 840907 for Commission to act to review Director's Decision DD-84-18 Served on 840827
CHILK,S J Office of the Secretary of the Commission DSB 320
84/08/27 Commissioners 1p 26262 361 24X
Fiche 50-289,84/08/27,8408280168

8408280409 Responds to 840719 request for list of uncompleted restart short-term actions Licensee action required on emergency planning offsite communications test & integrity of sys outside containment test program Related correspondence
GOLDBERG,J R Hearing Branch 2 DSB 345 84/08/27 WEISS,E R
Union of Concerned Scientists 1p 26280 216 24X
Fiche 50-289,84/08/27,8408280409

8408280427 Ack receipt of 840821 ltr responding to Commissioner Zech 840814 memo re TMI-1 site visit Visit rescheduled for 840831 Clarification re Commission request for orientation concerning util organization provided Served on 840828
ZECH,L W Commissioners DSB 347 84/08/27 WEISS,E R Union of Concerned Scientists WEISS,E R Harmon & Weiss 1p 26280 215
24X Fiche 50-289,84/08/27,8408280427

8408290012 Answer opposing licensee 840731 motion to partially exclude UCS from participation in mgt remand UCS participation on issues re Dieckamp mailgram & leak rate testing recommanded Certificate of Svc encl
GOLDBERG,J R Hearing Branch 2 DSB 346 84/08/27 Atomic Safety and Licensing Board Panel 8pp 26291 273 24X
Fiche 50-289,84/08/27,8408290012

8408310423 Staff requirements memo summarizing 840815 oral presentations by parties re restart Commission requested Aamodt provide names of individuals appropriate to carry out epidemiological study
CHILK,S J Office of the Secretary of the Commission 84/08/27
DIRCKS,W J Office of the Executive Director for Operations 2pp
26363 047 24X Fiche 50-289,84/08/27,8408310423

8408310099 Order extending time until 840907 for Commission to act to review ALAB-774 Served on 840830
CHILK,S J Office of the Secretary of the Commission DSB 391
84/08/28 Commissioners 1p 26323 199 24X
Fiche 50-289,84/08/28,8408310099

8408310207 Informs that steam generator tube plugging issue will be resolved & repairs completed by 841004 Svc list encl Related correspondence
BAUSER,D B Shaw, Pittman, Potts & Trowbridge BAUSER,D B
Metropolitan Edison Co DSB 431 84/08/29 SMITH,I W , WOLFE,S J ,
LINENBERGER,C Atomic Safety and Licensing Board Panel. 3pp
26318 061 24X Fiche 50-289,84/08/29,8408310207

H General correspondence

8408200274 Responds to 840626 ltr re penalties for excessive releases & regulations on effluent releases Purpose of 10CFR50 34a & 50,App I described
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/08/13 TAYLOR,F Z Affiliation Not Assigned 5pp 26142 337
24X Fiche 50-289,84/08/13,8408200274

--8408200282 Questions competence of NRC inspectors,based on alleged failure of NRC inspector to recognize steam generator Concern expressed re release of Kr-85 & other effluents
TAYLOR,F Z Affiliation Not Assigned 84/06/26 DIRCKS,W J
Office of the Executive Director for Operations 3pp 26142 342
24X Fiche 50-289,84/08/13,8408200274

8408220390 Protests unfair treatment indicated in staff rept on NUREG-0680,Suppl 5 re facility restart Conclusions re RCS leak tests unfair Refusal to endorse NRC conclusions requested Memo dtd 781020 to shift supervisors encl
FLOYD,J R Affiliation Not Assigned 84/08/13 PALLADINO,N J
Commissioners 2pp 26189 336 24X Fiche 50-289,84/08/13,
8408220390

8408230436 Responds to 840629 ltr expressing concerns re scope of TMI-1 restart proceedings Issues raised by Inquirer newspaper irrelevant to restart Proceeding addressed adequacy of plant operating,maint & administrative procedures
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/08/16 VANCE,L S Affiliation Not Assigned 10pp 26237 266
24X Fiche 50-289,84/08/16,8408230436

--8408230440 Requests response to encl LS Vance 840629 ltr re TMI-1 restart proceedings
WENGER,N W Pennsylvania, Commonwealth of, 84/07/17
PALLADINO,N Commissioners 9pp 26237 275 24X
Fiche 50-289,84/08/16,8408230436

K Utility Final Safety Analysis Report (FSAR) & amends

8408020137 Forwards Update 3 to TMI-1 updated FSAR Update reflects changes & analyses since 830718 update Chapter 11 update withheld
HUKILL,H D General Public Utilities - GPU Service Corp 84/07/26
DENTON,H R Office of Nuclear Reactor Regulation, Director 1p
25980 148 24X Fiche 50-289,84/07/26,8408020137

--8408020141 Update 3 to TMI-1 updated FSAR
* General Public Utilities - GPU Service Corp 84/07/31 100pp
25980 149 24X Fiche 50-289,84/07/26,8408020137

P Operating license stage documents & correspondence

8408160060 Forwards request for addl info re DHR & technical evaluation rept Response requested within 30 days of ltr receipt
STOLZ,J F Operating Reactors Branch 4 84/07/18 HUKILL,H D
General Public Utilities - GPU Service Corp 6pp 26128 215 24X
Fiche 50-289,84/07/18,8408160060

8408080438 Forwards request for addl info re pipe stresses for high energy lines Response requested by 840730 to maintain VCB 10CFR2 206 petition decision review schedule
STOLZ,J F Operating Reactors Branch 4 84/07/24 HUKILL,H D
General Public Utilities - GPU Service Corp 5pp 25977 177 24X
Fiche 50-289,84/07/24,8408080438

8408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating
Reactors Branch 4 36pp 25978 228 24X Fiche 50-000,84/07/27,
8408080288

8408030006 Forwards responses to NRC questions re emergency feedwater sys seismic interaction,per util 840716 submittal
HUKILL,H D General Public Utilities - GPU Service Corp 84/07/30
STOLZ,J F Operating Reactors Branch 4 4pp 25906 015 24X
Fiche 50-289,84/07/30,8408030006

8408060413 TMI-1 RESTART An Evaluation Of The Licensee's Management Integrity As It Affects Restart Of Three Mile Island Unit 1 Docket 50-289
* Division of Licensing NUREG-0680 S05 84/07/31 179pp
Available at NRC $4 00 25937 102 24X Fiche 50-289,84/07/31,
8408060413

8408070280 Informs of completed mod to intermediate bldg flood protection,allowing 25 minutes o/o operator action before emergency feedwater components affected
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/01
STOLZ,J F Operating Reactors Branch 4 3pp 25948 106 24X
Fiche 50-289,84/08/01,8408070280

8408080477 Informs of approval of request for withholding "Summary Info Package RCS Coolant Inventory Trending W/Reactor Coolant Pumps Operating," from public disclosure (ref 10CFR2 790)
STOLZ,J F Operating Reactors Branch 4 84/08/01 HUKILL,H D
General Public Utilities - GPU Service Corp 5pp 25976 054 24X
Fiche 50-289,84/08/01,8408080477

8408070238 Forwards analysis providing supplemental justification for Tech Spec Change Request 135,Rev 1,as discussed w/C Nichols & D Dilanni of NRC Analysis demonstrates explosion resistance of waste gas holdup sys under worst conditions
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/02
STOLZ,J F Operating Reactors Branch 4 7pp 25948 328 24X
Fiche 50-289,84/08/02,8408070238

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408130343 Advises of intent to revise environ qualification program to include condensate storage tank valves to condenser hotwell & condensate storage tank cross connect valves, in response to NRC 840625 ltr
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/06
STOLZ,J F Operating Reactors Branch 4 2pp 26010 318 24X
Fiche 50-289,84/08/06,8408130343

8408160285 Forwards handwritten notes from 840320-21,0507-08,0625 & 0806 environ qualification file audits All emergency feedwater file deficiencies resolved & sys environmentally qualified
STOLZ,J F Operating Reactors Branch 4 84/08/07 WEISS,E R
Harmon & Weiss 59pp 26126 170 24X Fiche 50-289,84/08/07, 8408160285

8408310305 Forwards Amend 98 to License DPR-50 & safety evaluation Amend revises Tech Spec definition of operable & operability to assure preservation of single failure criterion for safety sys Notice of issuance will be in next FR
STOLZ,J F Operating Reactors Branch 4 84/08/07 HUKILL,H D
General Public Utilities - GPU Service Corp 4pp 26350 240 24X
Fiche 50-289,84/08/07,8408310305

--8408310308 Amend 98 to License DPR-50,revising Tech Spec definition of operable & operability to assure preservation of single failure criterion for safety sys
STOLZ,J F Operating Reactors Branch 4 84/08/07 15pp
26350 244 24X Fiche 50-289,84/08/07,8408310305

--8408310311 Safety evaluation supporting Amend 98 to License DPR-50
* Office of Nuclear Reactor Regulation, Director 84/08/07 3pp
26350 259 24X Fiche 50-289,84/08/07,8408310305

8408130218 Forwards "PRA of Offsite Releases Initiated by Toxic Chemical Release," per NUREG-0737,Item II D 3 4
Transportation of offsite chemicals in vicinity of facility will not pose undue risk to control room operator
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/09
STOLZ,J F Operating Reactors Branch 4 2pp 26008 065 24X
Fiche 50-289,84/08/08,8408130218

--8408130225 "PRA of Offsite Releases Initiated by Toxic Chemical Release," final rept
FENSTERMACHER, HUBBARD,F R , CALABRESE,R V Pickard, Lowe & Garrick, Inc PLG-0370 84/07/30 118pp 26008 067 24X
Fiche 50-289,84/08/08,8408130218

8408140406 Requests immediate implementation of Amend 78 to License DPR-50 to avoid administrative problems in Tech Spec change requests & subsequent amends
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/08
STOLZ,J F Operating Reactors Branch 4 1p 26050 355 24X
Fiche 50-289,84/08/08,8408140406

8408140411 Forwards corrected Tech Spec Section 6 1A, "Post-Accident Sampling Programs" & Table 4 1-1 re instrument surveillance requirements,in response to NRC request for changes to 840604 Tech Spec Change Request 115
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/08
STOLZ,J F Operating Reactors Branch 4 1p 26048 359 24X
Fiche 50-289,84/08/08,8408140411

--8408140415 Corrected Tech Spec Change Request 115,adding phrases to clarify Tech Spec Section 6 1A, "Post-Accident Sampling Programs," (NUREG-0737,II B 3 & II F 1 2) & Table 4 1-1 re instrument surveillance requirements
* General Public Utilities - GPU Service Corp 84/08/08 2pp
[illegible] 84/08/08 8408140411

--8408300237 Mod 2,extending period of performance to 840915,to "Clinical Response to Chronic Stress in TMI "
BAUM,A Uniformed Services Univ of Health Sciences HAGAN,T F
Division of Contracts FIN D-8008 84/08/14 1p 26315 362
24X Fiche 50-289,84/08/14,8408300233

8408220218 Forwards Page 1 of Encl 10 inadvertently omitted from 840629 submittal re policies for employee protection from discrimination per 10CFR50 7 & policies for adequate, accurate corporate communications
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/16
EISENHUT,D G Division of Licensing 2pp 26194 051 24X
Fiche 50-289,84/08/16,8408220218

8408220363 Forwards response to request for addl info re control of heavy loads mods,per NUREG-0612,resulting from discussions w/Frahklin Research Ctr & Rev 0 to *Procedure 1408-6,* "Procedure for Insp of Wire Rope or Synthetic Slings "
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/16
EISENHUT,D G Division of Licensing 6pp 26189 324 24X
Fiche 50-289,84/08/16,8408220363

--8408220365 Rev 0 to Procedure 1408-6, "Procedure for Insp of Wire Rope or Synthetic Slings "
NELSON,M A , TOOLE,R General Public Utilities - GPU Service Corp
03/10/11 5pp 26189 330 24X Fiche 50-289,84/08/16,8408220363

8408240167 Informs of intent to provide response to NRC questions re DHR within 30 days of receipt of technical evaluation rept
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/17
STOLZ,J F Operating Reactors Branch 4 1p 26228 178 24X
Fiche 50-289,84/08/17,8408240167

8408270467 Advises that review of calculations transmitted by 820623 & 840615 ltrs re hot leg restraints under asymmetric LOCA loads completed Calculations resolve NRC 840327 concerns & acceptable
STOLZ,J F Operating Reactors Branch 4 84/08/17 HUKILL,H D
General Public Utilities - GPU Service Corp 4pp 26277 206 24X
Fiche 50-289,84/08/17,8408270467

8408280275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408280275

8408280178 Forwards master list of electrical equipment located in harsh radiation environ,radiation qualification info for components & resolution of equipment items for which radiation documentation incomplete,per 840808 ltr
WILSON,R F General Public Utilities - GPU Service Corp 84/08/23
EISENHUT,D G Division of Licensing 19pp 26275 090 24X
Fiche 50-289,84/08/23,8408280178

8408310238 Forwards "Review of Dose Assessments at TMI & Recommendations for Future Research " Printed rept summaries & 840829 press release encl
BERGER,D Berger, D 84/08/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 26316 293 24X
Fiche 50-289,84/08/27,8408310238

--8408310239 "Review of Dose Assessments at TMI & Recommendations for Future Research "
BEYEA,J TMI Public Health Fund 84/08/15 2/0pp 26316 300
24X Fiche 50-289,84/08/27,8408310238

8408310153 Forwards TMI Public Health Fund rept, "Review of Dose Assessments at TMI & Recommendations for Future Research "
CLARK,P R General Public Utilities - GPU Service Corp 84/08/20
DENTON,H R Office of Nuclear Reactor Regulation, Director 1p
26323 281 24X Fiche 50-289,84/08/20,8408310153

--8408310157 "Review of Dose Assessments at TMI & Recommendations for Future Research "
BEYEA,J TMI Public Health Fund 84/08/15 283pp 26323 283
24X Fiche 50-289,84/08/20,8408310153

G Inspection reports, IE Bulletins & correspondence

8408080243 Forwards IE Insp Rept 50-289/84-06 on 840212-0412 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 84/07/18
HUKILL,H D General Public Utilities - GPU Service Corp 2pp
25974 341 24X Fiche 50-289,84/07/18,8408080243

--8408080250 Notice of violation from insp on 840212-0412
* Region 1, Office of Director 84/07/18 1p 25974 343 24X
Fiche 50-289,84/07/18,8408080243

--8408080256 IE Insp Rept 50-289/84-06 on 840212-0412 Violation noted failure to document engineering justification for "use-as-is" disposition of nonconforming items in area of fire protection/prevention
NICHOLAS,N H Division of Engineering & Technical Programs
PAOLINO,R J , PAULITZ,F P Region 1, Office of Director
84/07/05 14pp 25974 344 24X Fiche 50-289,84/07/18,8408080243

8408080481 Forwards IE Insp Rept 50-289/84-14 on 840521-0601 No violations observed
MARTIN,T T Division of Engineering & Technical Programs 84/07/18
HUKILL,H D General Public Utilities - GPU Service Corp 2pp
25975 172 24X Fiche 50-289,84/07/18,8408080481

--8408080490 IE Insp Rept 50-289/84-14 on 840521-0601 No violations noted Major areas inspected licensee action on previous insp findings,restart preoperational test program,including procedure review & hot functional testing
NICHOLAS,H , WEN,P , FINKEL,A Region 1, Office of Director
84/07/09 7pp 25975 174 24X Fiche 50-289,84/07/18,8408080481

8408150264 Forwards IE Insp Rept 50-289/84-17 on 840605-0703 No violations noted
STAROSTECKI,R Division of Project & Resident Programs 84/07/26
HUKILL,H D General Public Utilities - GPU Service Corp 4pp
26076 335 24X Fiche 50-289,84/07/26,8408150264

--8408150271 IE Insp Rept 50-289/84-17 on 840605-0703 No violations noted Major areas inspected plant operations,inadvertent partial engineered safeguards actuation sys,maint activities,followup of LER & restart valve lineups
YOUNG,F , BAUNACK,W , CONTE,R Region 1, Office of Director
84/07/16 13pp 26076 339 24X Fiche 50-289,84/07/26,8408150264

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408030122 Requests listed design info re mods to RCS head & high point vents as followup to 840723-26 insp (50-289/84-22)
MARTIN,T T Division of Engineering & Technical Programs 84/07/27
HUKILL,H D General Public Utilities - GPU Service Corp 4pp
25916 115 24X Fiche 50-289,84/07/27,8408030122

8408030104 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/84-03 Corrective actions will be examined during future insp
MARTIN,T T Division of Engineering & Technical Programs 84/07/30
HUKILL,H D General Public Utilities - GPU Service Corp 4pp
25904 303 24X Fiche 50-289,84/07/30,8408030104

---8408030107 Supplx response to NRC 840214 ltr re violations noted in IE Insp Rept 50-289/84-03 Forwards update to list of outstanding items & Technical Data Rept 563, "TMI-1,Post-Accident RMA-5 Grab Sampling & MAP-5 Filter Removal "
HUKILL,H D General Public Utilities - GPU Service Corp
84/07/03 MURLEY,T E Region 1, Office of Director 3pp
25904 307 24X Fiche 50-289,84/07/30,8408030104

--8408030108 Rev 0 to "TMI-1,Post-Accident RMA-5 Grab Sampling & MAP-5 Filter Removal Radiological Analyses "
* General Public Utilities - GPU Service Corp TDR 563
84/07/02 26pp 25904 310 24X Fiche 50-289,84/07/30,8408030104

8408200014 Forwards IE Insp Rept 50-289/84-16 on 840604-08 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 84/07/31
HUKILL,H D General Public Utilities - GPU Service Corp 2pp
26140 232 24X Fiche 50-289,84/07/31,8408200014

--8408200017 Notice of violation from insp on 840604-08
* Region 1, Office of Director 84/07/31 3pp 26140 234 24X Fiche 50-289,84/07/31,8408200014

--8408200023 IE Insp Rept 50-289/84-16 on 840604-08 Noncompliance noted chemistry technician entered radiation area w/o dose rate instrument or Xetex
WHITE,J R , BELL,J , KOTTAN,J Region 1, Office of Director
84/07/26 29pp 26140 237 24X Fiche 50-289,84/07/31,8408200014

8408080300 Advises that response to notice of violation re false statements concerning retraining & qualification program will be submitted within 30 days after release of ref info Check for $40,000 re operator cheating encl
HUKILL,H D General Public Utilities - GPU Service Corp 84/08/02
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 1p 25965 306 24X Fiche 50-289,84/08/02,8408080300

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408100123 Informs that util response date incorrectly noted in NRC 840709 transmittal of SALP rept Correct util response date was 840606 TMI hearing svc list encl
STAROSTECKI,R Division of Project & Resident Programs 84/08/06
HUKILL,H D General Public Utilities - GPU Service Corp 5pp
25988 257 24X Fiche 50-289,84/08/06,8408100123

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408130406 Forwards IE Insp Rept 50-289/83-20 on 830711-0909 re RCS leak rate tests during Apr 1978 - Mar 1979 Revised encl insp rept pages include addl info obtained during 840208 site visit
MARTIN,T T Division of Engineering & Technical Programs 84/08/08
HUKILL,H D General Public Utilities - GPU Service Corp 5pp
26007 086 24X Fiche 50-289,84/08/08,8408130406

---8408130410 Errata to IE Insp Rept 50-289/83-20 on 830711-0909 Noncompliance noted failure to follow station procedures & regulatory requirements
CHUNG,J W , WEN,P C , VANTERPOOL,E C Region 1, Office of Director 83/09/21 229pp 26007 091 24X Fiche 50-289, 84/08/08,8408130406

--8408130417 Forwards revised IE Insp Rept 50-289/83-20 re reanalysis of timing charts & understanding of computer data handling during RCS leak rate testing
CHUNG,J W Division of Engineering & Technical Programs
84/02/24 MARTIN,T T Division of Engineering & Technical Programs 1p 26007 316 24X Fiche 50-289,84/08/08,8408130406

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408170311 Forwards Investigation Rept 1-83-010 re TMI-2 alleged falsification of leak rate surveillance test data Served on 840816
HAYES,D D Office of Investigation DSB 096 84/08/15 PALLADINO, ROBERTS, ASSELSTINE Commissioners 727pp 26116 001 24X Fiche 50-289,84/08/15,8408170311

8408200018 Board Notification 84-143 forwards Ofc of Investigation Rept 1-83-010 on alleged falsification of TMI-2 leak rate surveillance test data Rept consistent w/Suppl 5 to NUREG-0680 re TMI-1 restart
EISENHUT,D G Division of Licensing 84/08/15 PALLADINO, ROBERTS, ASSELSTINE Commissioners 9pp 26300 145 24X Fiche 50-289,84/08/15,8408200018

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408240104 Ack receipt of 840802 ltr & partial payment of $40,000 for civil penalty proposed on 830722 Corrective actions will be examined during future insp
AXELRAD, J A Enforcement Staff 84/08/17 CLARK, P R General Public Utilities - GPU Service Corp 2pp 26255 350 24X
Fiche 50-289, 84/08/17, 8408240104

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

K Periodic operating reports & related correspondence

8408090334 "TMI Aquatic Study Monthly Rept for June 1984 " W/GPU 840717 ltr
* EA Engineering, Science & Technology, Inc RESSLER, W C General Public Utilities - GPU Service Corp 84/06/30 HICKEY, C NRC - No Detailed Affiliation Given 14pp 25971 043 24X
Fiche 50-289, 84/06/30, 8408090334

8408240066 Monthly operating rept for Jul 1984 W/840816 ltr
SMYTH, C W , HUKILL, H D General Public Utilities - GPU Service Corp 84/07/31 MCDONALD, W C Office of Resource Management, Director 11pp 26236 141 24X Fiche 50-289, 84/07/31, 8408240066

8408230425 Submits TMI Program Ofc weekly status rept for 840805-11
GRANT, P J TMI Program Office 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 12pp 26230 229 24X Fiche 50-289, 84/08/13, 8408230425

S Reportable occurrences, LERs & related correspondence

8408090144 LER 84-003-00 on 840702, 12 penetrations in instrument shop floor identified as not having fire-rated penetration seals Caused by inadequate supervision of contractor personnel during installation Insp procedure changed W/840801 ltr
OTTO, S M , HUKILL, H D General Public Utilities - GPU Service Corp 84/08/01 6pp 25993 165 24X Fiche 50-289, 84/08/01, 8408090144

8408160182 LER 84-004-00 on 830602, tube A-135-72 not plugged & tube A-134-74 found in tube A-135-72 location Correct tube plugged & all other tubes verified W/840807 ltr
SZCZECH, R A , HUKILL, H D General Public Utilities - GPU Service Corp 84/08/07 6pp 26106 310 24X Fiche 50-289, 84/08/07, 8408160182

8408210383 PNO-1-84-069 on 840716, licensee reported five missing lower head steam generator plugs Licensee working w/ Westinghouse to develop method of testing plugs Evaluation continuing
CONNER, E Region 1, Office of Director 84/08/15 1p 26180 251 24X Fiche 50-289, 84/08/15, 8408210383

8408270195 LER 84-005-00 on 840716, diesel generator differential relays discovered potentially incapable of withstanding seismic event Caused by improper application of relays in original plant design Relays will be replaced W/840815 ltr
KNIGHT, M R , HUKILL, H D General Public Utilities - GPU Service Corp 84/08/15 4pp 26257 332 24X Fiche. 50-289, 84/08/15, 8408270195

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/08/16
EISENHUT, D G Division of Licensing 20pp 26233 249 24X
Fiche 50-000, 84/08/16, 8408230077

8408300503 LER 84-006-00 on 840718 & 19, during performance of surveillance procedure, setpoints for three IIE 27H relays (27) in 4160-volt bus 1E (EA) found out of calibr Caused by drift out of tolerance Faulty relays replaced W/840821 ltr
HUKILL, H D General Public Utilities - GPU Service Corp. 84/08/21 5pp 26314 001 24X Fiche 50-289, 84/08/21, 8408300503

T Hearing transcripts on non-antitrust matters

8408290265 Forwards JR Spang 840820 testimony in conjunction w/840815 hearing re mgt integrity. Testimony illustrates philosophical shortcomings of phrase mgt integrity
SPANG, J R American Society of Utility Investors DSB 375
84/08/24 CHILK, S J Office of the Secretary of the Commission 1p 26290 324 24X Fiche 50-289, 84/08/24, 8408290265

--8408290269 Testimony of American Soc of Util Investors presented by JR Spang re mgt integrity
SPANG, J R American Society of Utility Investors 84/08/20 4pp 26290 325 24X Fiche 50-289, 84/08/24, 8408290265

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408230082 Forwards IE Insp Rept 50-293/84-17 on 840605-0716 No violations noted Possible weakness in radiological controls program noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/03
HARRINGTON, W D Boston Edison Co 2pp 26214 128 24X
Fiche 50-293, 84/08/03, 8408230082

--8408230091 IE Insp Rept 50-293/84-17 on 840605-0716 No violations noted Major areas inspected plant operations including followup of previous findings, operational safety verification, plant events & LERs
JOHNSON, J , MCBRIDE, M , LIPINSKI, D Region 1, Office of Director 84/08/01 15pp 26214 130 24X Fiche 50-293, 84/08/03, 8408230082

8408170179 Notification of Significant Licensee Meeting 84-71 on 840814 w/util in King of Prussia, PA to discuss upgrading site security program
KUSHNER, W L Region 1, Office of Director 84/08/07 Region 1, Office of Director 2pp 26134 326 24X Fiche 50-293, 84/08/07, 8408170179

8408140251 Application for amend to License DPR-35, changing Tech Specs to replace Halon 1301 sys in place of CO2 sys in cable spreading room
HARRINGTON, W D Boston Edison Co 84/08/09 VASSALLO, D B
Operating Reactors Branch 2 2pp 26054 340 24X
Fiche 50-293, 84/08/09, 8408140251

--8408140256 Proposed Tech Spec changes, substituting Halon 1301 sys in place of CO2 sys in cable spreading room
* Boston Edison Co 84/08/09 4pp 26054 342 24X
Fiche 50-293, 84/08/09, 8408140251

8408170011 Notifies of fees due for consideration of requests for exemption from fire protection requirements, including alternate safe shutdown capability Description of 10CFR170 fee requirements & list of applications & fees encl
MILLER, W O License Fee Management Branch 84/08/09
HARRINGTON, W D Boston Edison Co 4pp 26135 351 24X
Fiche 50-293, 84/08/09, 8408170011

8408160374 Forwards proprietary "Conceptual Design Description for Pilgrim Nuclear Power Station Emergency & Plant Info Computer (EPIC) Safety Parameter Display Sys (SPDS)," per 831026 commitment & TMI Action Item I D 2 Rept withheld
HARRINGTON, W D Boston Edison Co 84/08/10 VASSALLO, D B
Operating Reactors Branch 2 1p 26091 192 24X
Fiche 50-293, 84/08/10, 8408160374

8408160368 Forwards Rev 1 to "Detailed Control Room Design Review Program Plan," per NUREG-0737, Item I D 1 & Suppl 1 to NUREG-0737
HARRINGTON, W D Boston Edison Co 84/08/14 VASSALLO, D B
Operating Reactors Branch 2 1p 26090 159 24X
Fiche 50-293, 84/08/14, 8408160368

--8408160369 Rev 1 to "Detailed Control Room Design Review Program Plan "
* Boston Edison Co 84/06/30 120pp 26090 160 24X
Fiche 50-293, 84/08/14, 8408160368

8408280269 "Pilgrim Nuclear Power Station - Joint Emergency Plan Exercise "
* Boston Edison Co 84/08/15 84pp 26282 335 24X
Fiche 50-293, 84/08/15, 8408280269

8408310396 Forwards Amend 76 to License DPR-35 & safety evaluation Amend revises fire protection Tech Specs re penetration fire barriers
LEECH, F H Operating Reactors Branch 2, 84/08/22 HARRINGTON, W D
Boston Edison Co 2pp 26350 228 24X Fiche 50-293, 84/08/22, 8408310396

--8408310430 Amend 76 to License DPR-35, revising fire protection Tech Specs re penetration fire barriers to reflect changes made to station in accordance w/requirements of App R to 10CFR50
VASSALLO, D B Operating Reactors Branch 2 84/08/22 7pp
26350 230 24X Fiche 50-293, 84/08/22, 8408310396

--8408310433 Safety evaluation supporting Amend 76 to License DPR-35
* Office of Nuclear Reactor Regulation, Director 84/08/22 3pp
26350 237 24X Fiche 50-293, 84/08/22, 8408310396

8408270230 Notifies that Rev 6 to security force training & qualification plan acceptable w/changes Requested changes specified in encl Encl withheld (ref 10CFR73 21)
MARTIN, T T Division of Engineering & Technical Programs 84/08/23
HARRINGTON, W D Boston Edison Co 3pp 26240 215 24X
Fiche 50-293, 84/08/23, 8408270230

G Adjudicatory correspondence

8408070491 Order extending time until 840810 for Commission to act to review Director's Decision DD-84-15 Served on 810806
CHILK, S J Office of the Secretary of the Commission DSB 794
84/08/03 Commissioners 1p 25940 096 24X
Fiche 50-293, 84/08/03, 8408070491

8408200608 Advises that time for Commission to review Director's Decision DD-84-15 expired Commission declined review Decision became final agency action on 840810 Served on 840820
CHILK, S J Office of the Secretary of the Commission DSB 152
84/08/17 ERNST, M D Massachusetts Public Interest Research Group
1p 26137 180 24X Fiche 50-293, 84/08/17, 8408200608

P Operating license stage documents & correspondence

8408060157 Forwards exemption from certain requirements of 10CFR50 54(o) & App J, permitting testing of MSIV at pressure of 23 psig All other exemption requests withdrawn or unnecessary Requests update of 760127 & 0604 Tech Specs
VASSALLO, D B Operating Reactors Branch 2 84/07/02
HARRINGTON, W D Boston Edison Co 2pp 25936 274 24X
Fiche 50-293, 84/07/02, 8408060157

--8408060161 Exemption from 10CFR50 54(o) & App J re Type C testing of MSIV at (Pa) test pressure Testing at reduced 23 psig pressure acceptable due to unique valve design
EISENHUT, D G Division of Licensing 84/07/02 Boston Edison Co 4pp 25936 276 24X Fiche 50-293, 84/07/02, 8408060157

--8408060172 Safety evaluation supporting 840702 exemption from certain requirements of 10CFR50 54(o) & App J permitting MSIV leakage rate testing at 23 psig
* Office of Nuclear Reactor Regulation, Director 84/07/02 4pp 25936 280 24X Fiche 50-293, 84/07/02, 8408060157

--8105130143 "Containment Leakage Rate Testing, Pilgrim Unit 1," technical evaluation rept
SCHERRER, J S Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-040 81/05/05 HUANG, Y S NRC - No Detailed Affiliation Given 32pp 25936 284 24X
Fiche 50-293, 84/07/02, 8408060157

--8204150347 "Containment Leakage Rate Testing," technical evaluation rept
DELGAIZA, T J Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-548 82/04/12 HUANG, Y S NRC - No Detailed Affiliation Given 17pp 25936 304 24X
Fiche 50-293, 84/07/02, 8408060157

8408070129 Advises of discontinuation of consideration of proposed Tech Spec change re weekly surveillance testing of CRD, per 840716 ltr
VASSALLO, D B Operating Reactors Branch 2 84/07/23
HARRINGTON, W D Boston Edison Co 2pp 25957 199 24X
Fiche 50-293, 84/07/23, 8408070129

8408020130 Clarifies util positions re NUREG-0737, Item I C 6 concerning tagging authorization, independent verification, post-maint configuration verification & ALARA concerns, in response to NRC 840614 ltr Revised procedures encl
HARRINGTON, W D Boston Edison Co 84/07/27 VASSALLO, D B
Operating Reactors Branch 2 4pp 25885 268 24X
Fiche 50-293, 84/07/27, 8408020130

--8408020139 Rev 15 to Procedure 1 4 5, "Tagging Procedure "
* Boston Edison Co 84/05/30 13pp 25885 272 24X
Fiche 50-293, 84/07/27, 8408020130

--8408020142 Rev 16 to Procedure 1 5 3, "Maint Requests "
* Boston Edison Co 83/03/04 28pp 25885 285 24X
Fiche 50-293, 84/07/27, 8408020130

--8408020144 Rev 4 to Procedure 1 3 34, "Conduct of Operations "
* Boston Edison Co 83/05/31 24pp 25885 313 24X
Fiche 50-293, 84/07/27, 8408020130

--8408020147 Rev 0 to Procedure 1 3 36, "Measurement & Test Equipment "
* Boston Edison Co 83/10/18 18pp 25885 337 24X
Fiche 50-293, 84/07/27, 8408020130

--8408020149 Rev 0 to Procedure 1 3 37, "Post-Trip Reviews "
* Boston Edison Co 84/02/28 18pp 25885 355 24X
Fiche 50-293, 84/07/27, 8408020130

8408160087 Forwards request for addl info re safety relief valve & torus attached piping sys needed to complete plant-unique analysis rept Meeting requested on 840823-24 between NRC, NRC consultants, util & util contractor to discuss response
VASSALLO, D B Operating Reactors Branch 2 84/07/27
HARRINGTON, W D Boston Edison Co 3pp 26126 343 24X
Fiche 50-293, 84/07/27, 8408160087

8408060005 Application for amend to License DPR-35, consisting of Proposed Tech Spec Change 84-07, revising thermal & pressurization limits for reactor pressure vessel before beginning hydro test for restart Fee encl
HARRINGTON, W D Boston Edison Co 84/07/30 VASSALLO, D B
Operating Reactors Branch 2 5pp 25933 060 24X
Fiche 50-293, 84/07/30, 8408060005

--8408060008 Proposed Tech Spec Change 84-07, revising thermal & pressurization limits for reactor pressure vessel before beginning hydro test for restart from current refueling outage
* Boston Edison Co 84/07/30 6pp 25933 065 24X
Fiche 50-293, 84/07/30, 8408060005

8408060016 Rev 2 to "Pilgrim Nuclear Power Station Reactor Pressure Vessel Pressure Temp Limits "
* Teledyne Engineering Services TR-6052-1 R02 84/07/19 26pp 25933 072 24X Fiche 50-293, 84/07/30, 8708060005

8408030121 Forwards response to 840529 request for addl info re Multi-Plant Action F-55 (TMI Item II K 3 28), "Qualification of Automatic Depressurization Sys Accumulators," per 10CFR50 54(f) OE will provide addl info by 841001
HOWARD, J E Boston Edison Co 84/07/31 EISENHUT, D G Division of Licensing 3pp 25916 112 24X Fiche 50-293, 84/07/31, 8408030121

8408060332 Notification of 840823-24 meetings w/utils in Waltham, MA to discuss open items on Mark I containment program
HERMANN, R A Operating Reactors Branch 2 84/07/31 VASSALLO, D B
Operating Reactors Branch 2 2pp 25937 357 24X
Fiche 50-000, 84/07/31, 8408060332

8408150620 Forwards FR notice of consideration of issuance of amend to License DPR-35 & proposed NSHC determination & opportunity for hearing re rev to scram discharge vol sys NSHC available in Central Files
LEECH, P H Operating Reactors Branch 2 84/07/31 HARRINGTON, W D
Boston Edison Co 2pp 26103 300 24X Fiche 50-293, 84/07/31, 8408150620

--8408150623 Notice of consideration of issuance of amend to License DPR-35 & proposed NSHC determination & opportunity for hearing re 840626 request for rev to scram discharge vol sys
HERMANN, R A Operating Reactors Branch 2 84/07/31 7pp. 26103 302 24X Fiche 50-293, 84/07/31, 8408150620

8408090248 Forwards resolutions for environ qualification of safety-related electrical equipment & justification for continued operation for any equipment for which documentation for environ qualification not yet completed
HARRINGTON, W D Boston Edison Co 84/08/03 VASSALLO, D B
Operating Reactors Branch 2 82pp 25972 185 24X
Fiche 50-293, 84/08/03, 8408090248

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140239 Application for amend to License DPR-35, changing Tech Specs to provide redundant temp monitoring sys for suppression pool & responding to portions of TMI action plan requirements of NUREG-0737
HARRINGTON, W D Boston Edison Co 84/08/09 VASSALLO, D B
Operating Reactors Branch 2 1p 26055 316 24X
Fiche 50-293, 84/08/09, 8408140239

--8408140245 Proposed Tech Spec changes, providing redundant temp monitoring sys for suppression pool & responding to portions of TMI action plan requirements of NUREG-0737
* Boston Edison Co 84/08/09 13pp 26055 317 24X
Fiche 50-293, 84/08/09, 8408140239

8408140250 Responds to NRC 840613 request for info re analysis & methodology for Mark I long-term program for safety relief valve actuation not in conformance w/NUREG-0661 Review of procedures reveals complete conformance
HARRINGTON, W D Boston Edison Co 84/08/09 VASSALLO, D B
Operating Reactors Branch 2 1p 26093 358 24X
Fiche 50-293, 84/08/09, 8408140250

8408140251 Application for amend to License DPR-35, changing Tech Specs to replace Halon 1301 sys in place of CO2 sys in cable spreading room
HARRINGTON, W D Boston Edison Co 84/08/09 VASSALLO, D B
Operating Reactors Branch 2 2pp 26054 340 24X
Fiche 50-293, 84/08/09, 8408140251

--8408140256 Proposed Tech Spec changes, substituting Halon 1301 sys in place of CO2 sys in cable spreading room
* Boston Edison Co 84/08/09 4pp 26054 342 24X
Fiche 50-293, 84/08/09, 8408140251

8408150087 Responds to NRC 820809 ltr re guidelines developed to facilitate review following implementation of NUREG-0737, Item II B 3 re post-accident sampling sys Info submitted to assist in SER preparation
HARRINGTON, W D Boston Edison Co 84/08/09 VASSALLO, D B
Operating Reactors Branch 2 9pp 26066 256 24X
Fiche 50-293, 84/08/09, 8408150087

8408160033 Application for amend to License DPR-35, consisting of proposed Tech Spec change re mod to surveillance requirements for containment cooling subsys & bases
HARRINGTON, W D Boston Edison Co 84/08/09 VASSALLO, D B
Operating Reactors Branch 2 1p 26092 044 24X
Fiche 50-293, 84/08/09, 8408160033

--8408160036 Proposed Tech Spec change, modifying surveillance requirements for containment cooling subsys & bases
* Boston Edison Co 84/08/09 5pp 26092 045 24X
Fiche 50-293, 84/08/09, 8408160033

8408160041 Application to amend License DPR-35, changing Tech Specs re standby gas treatment sys & control room high efficiency air filtration sys
HARRINGTON, W D Boston Edison Co 84/08/09 VASSALLO, D B
Operating Reactors Branch 2 1p 26092 053 24X
Fiche 50-293, 84/08/09, 8408160041

--8408160045 Proposed changes to Tech Spec Pages 158, 158A-C, 172, 174 & 174A re standby gas treatment sys & control room high effitiency air filtration sys
* Boston Edison Co 84/08/09 12pp 26092 054 24X
Fiche 50-293, 84/08/09, 8408160041

8408220133 Requests extension to 850131 for responding to Generic Ltr 84-15 re diesel generator surveillance tests & reliability data & programs Justification for extension provided
HARRINGTON, W D Boston Edison Co 84/08/15 EISENHUT, D G
Division of Licensing 2pp 26193 316 24X Fiche 50-293, 84/08/15, 8408220133

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310396 Forwards Amend 76 to License DPR-35 & safety evaluation Amend revises fire protection Tech Specs re penetration fire barriers
LEECH, P H Operating Reactors Branch 2 84/08/22 HARRINGTON, W D
Boston Edison Co 2pp 26350 228 24X Fiche 50-293, 84/08/22, 8408310396

--8408310430 Amend 76 to License DPR-35, revising Fire protection Tech Specs re penetration fire barriers to reflect changes made to station in accordance w/requirements of App R to 10CFR50
VASSALLO, D B Operating Reactors Branch 2 84/08/22 7pp
26350 230 24X Fiche 50-293, 84/08/22, 8408310396

--8408310433 Safety evaluation supporting Amend 76 to License DPR-35
* Office of Nuclear Reactor Regulation, Director 84/08/22 3pp
26350 237 24X Fiche 50-293, 84/08/22, 8408310396

8408300198 Submits "1984 Main Breakwater Surveillance Rept " No damage or major stone movement occurred to structure since 1983 rept Photographs & two oversize drawings encl, Aperture cards available in PDR
HARRINGTON, W D Boston Edison Co 84/08/24 VASSALLO, D B
Operating Reactors Branch 2 56pp 26310 103 24X
Fiche 50-293, 84/08/24, 8408300198

IE Inspection Reports IE Bulletins & correspondence

8408100008 Forwards response to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Class 1E Safety Sys Util experienced failures of GE Type HFA Series 51 AC normally energized relays Status of replacement program encl
HARRINGTON, T E Boston Edison Co 84/07/17 MURLEY, T E Region 1, Office of Director 6pp 25989 280 24X Fiche 50-293, 84/07/17, 8408100008

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 21X Fiche 50-000, 84/07/27, 8407250229

8408230276 Forwards IE Insp Rept 50-293/84-18 on 840611-15 No violations observed
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
HARRINGTON, W D Boston Edison Co 2pp 26213 260 24X
Fiche 50-293, 84/08/01, 8408230276

--8408230289 IE Insp Rept 50-293/84-18 on 840611-15 No violations identified Major areas inspected surveillance & functional tests of snubbers, hangers & supports, records of pipe support mods of torus external piping & modified pipe supports
NARROW, L , BURR, J P Region 1, Office of Director 84/07/20
6pp 26213 262 24X Fiche 50-293, 84/08/01, 8408230276

8408230566 Forwards IE Insp Rept 50-293/84-14 on 840509-11 & 14-16 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/08/02
HARRINGTON, W D Boston Edison Co 2pp 26213 018 24X
Fiche 50-293, 84/08/02, 8408230566

--8408230567 Notice of Violation from Insp on 840509-11 & 14-16
* Region 1, Office of Director 84/08/02 2pp 26213 020 24X
Fiche 50-293, 84/08/02, 8408230566

--8408230569 IE Insp Rept 50-293/84-14 on 840509-11 & 14-16 Violations noted failure to adhere to procedures in accordance w/Tech Spec 6 11, to perform surveys in accordance w/10CFR20 201 & adequately instruct workers in accordance w/10CFR19 12
WHITE, J R , KATTAN, J , SHANBAKY, M M Region 1, Office of Director
84/07/26 11pp 26213 022 24X Fiche 50-293, 84/08/02, 8408230566

8408230082 Forwards IE Insp Rept 50-293/84-17 on 840605-0716 No violations noted Possible weakness in radiological controls program noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/03
HARRINGTON, W D Boston Edison Co 2pp 26214 128 24X
Fiche 50-293, 84/08/03, 8408230082

--8408230091 IE Insp Rept 50-293/84-17 on 840605-0716 No violations noted Major areas inspected plant operations including followup of previous findings, operational safety verification, plant events & LERs
JOHNSON, J , MCBRIDE, M , LIPINSKI, D Region 1, Office of Director
84/08/01 15pp 26214 130 24X Fiche 50-293, 84/08/03, 8408230082

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 156 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408150055 Supplb 840517 response to violation & proposed imposition of civil penalties Procedure 6 1-024 revised on 840718 to provide more specific guidance re labeling radioactive matl containers
HARRINGTON, W D Boston Edison Co 84/08/08 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 2pp
26067 050 24X Fiche 50-293, 84/08/08, 8408150055

8408070376 IE Info Notice 84-62 Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08 10 Consolidated Edison Co of New York, Inc 12Spp 26130 001 24X Fiche 50-000 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 2619/ 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Undetated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408080503 "NPDES Discharge Monitoring Rept for Apr-June 1984 " W/840728 ltr
HARRINGTON, W D , MATHIS, C J Boston Edison Co 84/06/30 17pp 25979 240 24X Fiche 50-293, 84/06/30, 8408080503

8408160094 Monthly operating rept for Jul 1984 W/840809 ltr
HAMILTON, P , HARRINGTON, W D Boston Edison Co 84/07/31 7pp 26108 238 24X Fiche 50-293, 84/07/31, 8408160094

S Reportable occurrences, LERs & related correspondence

8408300348 LER 77-030/03X-1 on 770906, during normal shutdown for Refueling Outage 3, CRD 34-11 remained full-out when reactor scrammed Probably caused by foreign substance restricting normal operation CRD replaced W/840809 ltr
HAMILTON, P J , HARRINGTON, W D Boston Edison Co 77/09/01 MORLEY, T E Region 1, Office of Director 3pp 26308 353 24X Fiche 50-293, 77/09/01, 8408300348

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408090114 Part 21 rept re twisted shielded pair cable in Nutherm Intl, Inc Analog Trip Cabinets C2228A1, C2228A2, C2229D1 & C2229D2 Initially reported on 840713 Caused by poor workmanship Cables exhibiting defects replaced
HARRINGTON, W D Boston Edison Co 84/07/13 MURLEY, T E Region 1, Office of Director 3pp 25992 242 24X Fiche 50-293, 84/07/13, 8408090114

8408100046 LER 82-049/01X-1 on 821102, main steam line safety valve A set w/nitrogen at steam relief setting Caused by personnel error Valve removed & replaced w/properly set spare valve Procedure revised W/840720 ltr
HAMILTON, P J , HARRINGTON, W D Boston Edison Co 84/07/20 MURLEY, T E Region 1, Office of Director 3pp 25990 070 24X Fiche 50-293, 84/07/20, 8408100046

8408100099 LER 77-018/03X-1 on 770502, CRD 46-39 withdrawn beyond full-out position Caused by badly bent uncoupling rod CRD 46-39 removed & replaced on 770901 during Refueling Outage 3 W/840720 ltr
HAMILTON, P J , HARRINGTON, W D Boston Edison Co 84/07/20 MURLEY, T E Region 1, Office of Director 3pp 25990 352 24X Fiche 50-293, 84/07/20, 8408100099

8408030022 Special rept on 840628, during refueling outage, electric fire pump failed while conducting yearly 0-150% capacity test Caused by shorting within motor Motor rewound Fire pump not returned to operable status within required 7-day period
HARRINGTON, W D Boston Edison Co 84/07/26 VASSALLO, D B Operating Reactors Branch 2 1p 25907 087 24X Fiche 50-293, 84/07/26, 8408030022

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSS, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000, 84/08/21, 8408310186

DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR

V Operator Examinations

8408090162 Forwards Rev 4 to "Requalification Program for Licensed Operators," in response to 840711 Generic Ltr 83-12A
WILKINSON, R Michigan State Univ, East Lansing, MI 84/07/24 THOMAS Standardization & Special Projects Branch 1p 25973 124 24X Fiche 50-294, 84/07/24, 8408090162

--8408090165 Rev 4 to "Requalification Program for Licensed Operators "
* Michigan State Univ, East Lansing, MI 84/07/13 3pp 25973 125 24X Fiche 50-294, 84/07/24, 8408090162

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

8408210141 Informs of review of Rev 4 of requalification program for licensed operators Program satisfies criteria of 10CFR55, App A & ANSI/ANS 15 4 & is acceptable
THOMAS, C O Standardization & Special Projects Branch 84/08/13 WILKINSON, R E Michigan State Univ, East Lansing, MI 3pp 26195 311 24X Fiche 50-294, 84/08/13, 8408210141

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408070239 Rev 7 to Emergency Plan Implementing Procedure EPIP 110-1, "Zion Station - Nuclear Accident Reporting Sys Reporting Procedures " W/840719 transmittal memo
NYKIRK, J Commonwealth Edison Co 84/07/19 10pp 25948 353 24X Fiche 50-295, 84/07/19, 8408070239

8408070240 Rev 3 to Emergency Plan Implementing Procedure EPIP 100-1, "Acting Station Director " W/840719 transmittal memo
NYKIRK, J Commonwealth Edison Co 84/07/26 16pp 25949 001 24X Fiche 50-295, 84/07/26, 8408070240

8408010165 Forwards "Safe Shutdown Capability Reassessment & Proposed Mods, 10CFR50, App R," for approval Exemption from schedular requirements of 10CFR50 48(c)(4) until 851231 requested Related tables & notes encl
CASCARANO, R N Commonwealth Edison Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 28pp 25874, 001, 24X Fiche 50-295, 84/07/27, 8408010165

--8408010171 "Safe Shutdown Capability Reassessment & Proposed Mods, 10CFR50, App R "
* Commonwealth Edison Co 84/07/31 499pp 25874 029 24X Fiche 50-295, 84/07/27, 8408010165

8408170398 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EIP 600-A3, "Station Directory "
* Commonwealth Edison Co 84/07/31 Record Services Branch (Document Control Desk) 2pp 26134 171 24X Fiche 50-295, 84/07/31, 8408170398

--8408170399 Public version of Rev 3 to Emergency Plan Implementing Procedure EIP 600-A3, "Station Directory " W/JM Felton 840809 release memo
* Commonwealth Edison Co 84/07/31 10pp 26134 172 24X Fiche 50-295, 84/07/31, 8408170398

8408100060 Determines that, based on evaluation, State of WI & local plans for radiological emergencies adequate
SPECK, S W Federal Emergency Management Agency 84/08/02
DIRCKS, W J Office of the Executive Director for Operations 1p
25989 052 24X Fiche 50-295, 84/08/02, 8408100060

8408140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 84/08/03 Region 3, Office of Director 1p 26044 252 24X Fiche 50-000, 84/08/03, 8408140139

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO, C J Region 3, Office of Director 84/08/07 REED, C Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000, 84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR, D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J Region 3, Office of Director 8pp 26010 131 24X Fiche 50-000, 84/08/07, 8408130401

8408140428 Rev 3 to Emergency Plan Implementing Procedure EPIP 350-2, "Calculation of Post-Accident Noble Gas Release Rates Via Vent Stacks & Quick Estimate of Offsite Dose Using SPING Monitor RIA-PR49 Readings " W/840808 transmittal memo
KASSNER, G , PLIML, G Commonwealth Edison Co 84/08/08 13pp 26051 170 24X Fiche 50-295, 84/08/08, 8408140428

8408200345 Advises that 840803 Rev 13 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/08/14 FARRAR, D L Commonwealth Edison Co 2pp 26132 357 24X Fiche 50-295, 84/08/14, 8408200345

8408310168 Rev 3 to Emergency Plan Implementing Procedure EPIP 550-6, "Monthly Radiological Emergency Equipment Tests & Checks " W/transmittal & receipt form
GRAESSER, K L , PLIML, G Commonwealth Edison Co 84/08/15 6pp 26319 239 24X Fiche 50-295, 84/08/15, 8408310168

8408270309 Informs of FEMA approval of State of WI emergency response & local plan Adequacy of public alerting & notification sys must be verified per FEMA/NRC joint criteria in App 3 of NUREG-0654/FEMA-REP-1
PAPERIELLO, C J Region 3, Office of Director 84/08/22 REED, C Commonwealth Edison Co 2pp 26239 157 24X Fiche 50-295, 84/08/22, 8408270309

P Operating license stage documents & correspondence

8408280360 Ack receipt of 840710 ltr re author criticism of NRC present rules & practices Reponse to NRC seven stages of discussion listed Past tests should be reviewed & leak rate be retested Related info encl
REYTBLATT, Z V Warren Wilson College, Swannanoa, NC 84/07/22
ROSS, D F Office of Nuclear Regulatory Research, Director 6pp 26293 001 24X Fiche 50-000, 84/07/22, 8408280360

--8408280366 Lists basic deficiencies & errors of present leak rate testing methodology as regulated by faulty stds
REYTBLATT, Z V Extran, Inc 84/03/15 ACRS - Advisory Committee on Reactor Safeguards 3pp 26293 009 24X Fiche 50-000, 84/07/22, 8408280360

--8408280373 Requests documents re RFP RS-RES-84-101, submitted on 840110 Author 840220 ltr to EM Gogol, Citizens Against Nuclear Power encl
REYTBLATT, Z V Extran, Inc 84/03/02 Division of Rules and Records 6pp 26293 012 24X Fiche 50-000, 84/07/22, 8408280360

--8408280378 Ack receipt of NRC 830722 response to 830705 ltr re criteria for licensing nuclear containments Normal procedure substituted for handling hazardous situation Response to unsolicited proposals requested
REYTBLATT, Z Extran, Inc 83/07/26 ARNDT, E G Mechanical/Structural Engineering Branch 4pp 26293 019 24X Fiche 50-295, 84/07/22, 8408280360

--8408280380 Discusses author presentation on 840315, G Arndt & ORNL should be heard before committee on faulty leak rate test Requests addl opportunity to present point of view
REYTBLATT, Z Extran, Inc 84/03/18 ACRS - Advisory Committee on Reactor Safeguards 1p 26293 023 24X Fiche 50-000, 84/07/22, 8408280360

-8408280381 Requests that EG Arndt of Mechanical/Structural Engineering Branch be ordered to start evaluation of matls supporting author demand to suspend temporarily all integrated leakage rate tests Brief history of problem listed
REYTBLATT Z Extran, Inc 83/07/26 PALLADINO, N Commissioners 1p 26293 024 24X Fiche 50-295, 84/07/22, 8408280360

--8408280383 Discusses hearings on leak rate matters re proposed changes to 10CFR50, App J
REYTBLATT, Z V Warren Wilson College, Swannanoa NC 84/07/05
SIESS ACRS - Advisory Committee on Reactor Safeguards 3pp 26293 025 24X Fiche 50-295, 84/07/22, 8408280360

--8408280387 Discusses concerns w/leak rate testing situation Draft reg guide on leak rate testing should not be presented to public w/o prior discussion by ACRS or subcommittees Requests that NRC take listed actions
REYTBLATT, Z V Warren Wilson College, Swannanoa, NC 84/07/09
EBERSOLE ACRS - Advisory Committee on Reactor Safeguards 2pp 26293 028 24X Fiche 50-295, 84/07/22, 8408280360

--8408280390 Advises that no proven public health or safety hazard results from integrated leak rate test criteria, per 10CFR50, App J Issue considered resolved Future comments on subj should be directed to Secretary of Commission
ROSS, D F Office of Nuclear Regulatory Research, Director 84/07/10 REYTBLATT, Z Warren Wilson College, Swannanoa, NC 2pp 26293 030 24X Fiche 50-295, 84/07/22, 8408280360

--8408280395 Advises that no schedule planned for debriefing session to discuss technical evaluation results of proposal "Containment Sys Leakage Testing Requirements "
THOMPSON, R D Division of Contracts 84/04/20 REYTBLATT, Z V Extran, Inc 1p 26293 032 24X Fiche 50-295, 84/07/22, 8408280360

--8408280400 Responds to 840302 ltr to Chairman Palladino re proposal on containment sys leakage requirements Proposal not funded since current leak rate test results not significantly altered
BURNS, J J Mechanical/Structural Engineering Branch 84/04/17
REYTBLATT, Z Extran, Inc 2pp 26293 033 24X Fiche 50-295, 84/07/22, 8408280360

--8408280404 Informs that proposals "Improvements to Leak Rate Testing," "Assessment of Past Leakage Rate Tests" & "High Trajectory Turbine Missile Hazard Evaluation" will not be funded due to listed reasons
THOMPSON, R D Division of Contracts 84/03/20 REYTBLATT, Z Extran, Inc 2pp 26293 035 24X Fiche 50-295, 84/07/22, 8408280360

--8408280407 Requests NRC participation in technical discussion re containment leakage rate testing on 840312
REYTBLATT, Z Affiliation Not Assigned 84/03/02 PALLADINO, N Commissioners 1p 26293 037 24X Fiche 50-295, 84/07/22, 8408280360

--8408280411 Requests evaluation of encl memo re integrated leakage rate test
REYTBLATT, Z Extran, Inc 83/08/30 BURNS, J Division of Engineering Technology 3pp 26293 039 24X Fiche 50-295, 84/07/22, 8408280360

--8309220362 Ack receipt of 830726 ltr to Chairman Palladino Response will be provided as soon as review completed
BURNS, J J Mechanical/Structural Engineering Branch 83/08/23
REYTBLATT, Z Extran, Inc 1p 26293 042 24X Fiche 50-295, 84/07/22, 8408280360

--8408280422 Requests that Paragraph 3 of 10CFR50, App J, be immediately revoked, per 10CFR21 ANSI N45 4-1972 may not detect abnormally high leak tests
REYTBLATT, Z Extran, Inc 83/07/26 PALLADINO, N Commissioners 1p 26293 045 24X Fiche 50-295, 84/07/22, 8408280360

--8408280430 Requests that Paragraph 3 of 10CFR50, App J, be immediately revoked, per 10CFR21 ANSI N45 4-1971 may not detect abnormally high leak test because of numerous loopholes for distorting test results
REYTBLATT, Z Extran, Inc 83/07/26 ARNDT, E G NRC - No Detailed Affiliation Given 1p 26293 048 24X Fiche 50-295, 84/07/22, 8408280360

8408060335 Notification of 840802 meeting w/util in Bethesda, MD to discuss insights from review of probabilistic safety study
NORRIS, J A Operating Reactors Branch 1 84/07/27 VARGA, S A Operating Reactors Branch 1 3pp 25937 354 24X Fiche 50-295, 84/07/27, 8408060335

8408130015 Submits summary of conduct of proposed integrated leak rate test Util will suppl normal instrument checkout w/integrated sys check Check will be performed after instruments hung but prior to containment pressurization
CASCARANO,R N Commonwealth Edison Co 84/07/27 KEPPLER,J G
Region 3, Office of Director 2pp 25990 108 24X
Fiche 50-295,84/07/27,8408130015

8408130047 Notification of cancellation of 840802 meeting w/util in Bethesda,MD to discuss NRC review of probabilistic safety study
NORRIS,J A Operating Reactors Branch 1 84/07/27 VARGA,S A
Operating Reactors Branch 1 2pp 26034 360 24X
Fiche 50-295,84/07/27,8408130047

8408130022 Ack receipt of 840605 petition for emergency relief re adequacy of containment leak rate testing NRC conducting insp on allegations Util informed that Unit 1 not in compliance w/10CFR50,App J
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/07/30 GOGAL,E M Citizens Against Nuclear Power 9pp
26036 330 24X Fiche 50-295,84/07/30,8408130022

8408090139 Advises that Class III fee appropriate for review of 830727 submittal of "Comm Ed Topical Rept on Benchmark of PWR Nuclear Design Methods " Exemption from Class I fee granted W/o stated encls
MILLER,W O License Fee Management Branch 84/08/03 FARRAR,D L
Commonwealth Edison Co 2pp 25991 205 24X Fiche 50-295,84/08/03,
8408090139

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408100110 Ack receipt of 840730 ltr re Citizens Against Nuclear Power petition for relief to correct hazardous & illegal situation at facility Data for 1981,1983 & 1984 containment leak rate tests requested
GOGOL,E Citizens Against Nuclear Power 84/08/06 DENTON,H
Office of Nuclear Reactor Regulation, Director 2pp 25991 033
24X Firhe 50-295,84/08/06,8408100110

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR,D L Commonwealth Edison Co 84/08/06 Office of Nuclear
Material Safety & Safeguards,Director 1p 26092 184 24X
Fiche 50-000,84/08/06,8408160345

8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 1, "Sequoyah Nuclear Plant Containment Analysis," for Meeting 38 Rept inconsistent w/four encl repts previously sent
FONTANA,M H Technology for Energy Corp 84/08/07 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 26234 001
24X Fiche 50-000,84/08/07,8408230097

--8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants," technical rept
* Industry Degraded Core Rulemaking Program FAI/84-9 DRFT
84/07/31 114pp 26234 231 24X Fiche 50-000,84/08/07,
8408230097

--8408230116 Draft "Zion Nuclear Generating Station Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/08/07 119pp
26234 335 24X Fiche 50-000,84/08/07,8408230097

8408170033 Notification of 840819 meeting w/util in Bethesda,MD to discuss proposed safety mgt program & integrated living schedule concepts
NORRIS,J A Operating Reactors Branch 1 84/08/08 VARGA,S A
Operating Reactors Branch 1 2pp 26134 361 24X
Fiche 50-295,84/08/08,8408170033

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408280119 Forwards fee for review of util topical rept on benchmark of PWR nuclear design methods in connection w/reloads at facility,per 840803 ltr
ALEXANDER,G L Commonwealth Edison Co 84/08/20 MILLER,W O
License Fee Management Branch 1p 26261 300 24X
Fiche 50-295,84/08/20,8408280119

8408270372 Forwards response to NRC request for clarification of svc water success criteria Adequacy of two svc water pumps to handle safe shutdown components reconfirmed by util corporate engineering dept
CASCARANO,R N Commonwealth Edison Co 84/08/21 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 26240 252
24X Fiche 50-295,84/08/21,8408270372

8408280286 Summary of 840815 meeting w/util re integrated living schedule Attendee list,agenda & viewgraphs encl W/o encls
NORRIS,J Operating Reactors Branch 1 84/08/21 Operating
Reactors Branch 1 2pp 26294 087 24X Fiche 50-295,84/08/21,
8408280286

8408310200 Discusses PRA of proposed mod to auxiliary feedwater sys,per NUREG-0737,Item II E 1 1 Efforts on mod stopped as result of PRA conclusion that installation of addl check valves will not significantly improve availability of sys
CASCARANO,R N Commonwealth Edison Co 84/08/23 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 26318 308
24X Fiche 50-295,84/08/23,8408310200

8408310202 Forwards addl info re inadequate core cooling instrumentation sys,in response to NRC 840530 request Meeting suggested in Bethesda,MD to resolve any questions still outstanding
CASCARANO,R N Commonwealth Edison Co 84/08/24 DENTON,H R
Office of Nuclear Reactor Regulation, Director 7pp 26318 312
24X Fiche 50-295,84/08/24,8408310202

O Inspection reports, IE Bulletins & correspondence

8408080485 Forwards IE Insp Repts 50-295/84-08 & 50-304/84-08 on 840531,0604-08,12-13 & 0702 & notice of violation
PAPERIELLO,C J Region 3, Office of Director 84/07/18 REED,C
Commonwealth Edison Co 2pp 25975 188 24X Fiche 50-295,84/07/18,
8408080485

--8408080488 Notice of violation from insp on 840531,0604-08,12-13 & 0702
PAPERIELLO,C J Region 3, Office of Director 84/07/18 1p
25975 190 24X Fiche 50-295,84/07/18,8408080488

--8408080496 IE Insp Repts 50-295/84-08 & 50-304/84-08 on 840531,0604-08, 12-13 & 0702 Violations noted unauthorized transfer of Am-241 sources to Byron Station
LOVENDALE,P C , NICHOLSON,N A , GREGER,L R Region 3, Office of
Director 84/07/17 11pp 25975 191 24X Fiche 50-295,84/07/18,
8408080485

8408090169 Forwards IE Insp Repts 50-295/84-07 & 50-304/84-07 on 840512-0629 No noncompliance noted
SHAFER,W D Region 3, Office of Director 84/07/20 REED,C
Commonwealth Edison Co 2pp 25995 015 24X Fiche 50-295,84/07/20,
8408090169

--8408090177 IE Insp Repts 50-295/84-07 & 50-304/84-07 on 840512-0629 No noncompliance or deviations noted Major areas inspected maint on nuclear instrumentation,operational safety & ESF walkdown, surveillance & LER followup
WRIGHT,G C Region 3, Office of Director 84/07/19 8pp
25995 017 24X Fiche 50-295,84/07/20,8408090169

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC
NORELIUS,C E Region 3, Office of Director 84/08/03 REED,C
Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000,84/08/03,
8408070066

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,
8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, 84/08/08, 8408140344

8408150098 Supplis 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26067 053 24X
Fiche 50-000, 84/08/08, 8408150098

8408200331 Supplis response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26132 318 24X
Fiche 50-000, 84/08/08, 8408200331

8408170263 Forwards SALP Repts 50-295/84-06 & 50-304/84-06 for Jan 1983 - Apr 1984
KEPPLER, J G Region 3, Office of Director 84/08/09 REED, C
Commonwealth Edison Co 2pp 26118 008 24X Fiche 50-295, 84/08/09, 8408170263

--8408170265 SALP Repts 50-295/84-06 & 50-304/84-06 for Jan 1983 - Apr 1984 Licensing activities assigned Category I rating
* Region 3, Office of Director 84/08/09 31pp 26118 010 24X
Fiche 50-295, 84/08/09, 8408170263

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408220086 Supplis 840626 response to 840511 request for addl info re inservice insp program for second 10-yr interval Addl relief requests & additions to program encl
CASCARANO, R M Commonwealth Edison Co 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 37pp 26193 252
24X Fiche 50-295, 84/08/14, 8408220086

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408270087 Supplis 840607 ltr re check valves in water cooling sys of diesel generators per IE Bulletin 83-03 Valve insp on 840515 revealed no mechanical problems
ALEXANDER, G L Commonwealth Edison Co 84/08/16 KEPPLER, J G
Region 3, Office of Director 2pp 26247 399 24X
Fiche 50-295, 84/08/16, 8408270087

8408100055 IE Info Notice 84-66 "Undetected Unavailability of Turbine Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67 Recent Snubber Inservice Testing Of High Failure Rates Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 009 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408300136 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1984 " W/840803 ltr
GRAESSER, K L Commonwealth Edison Co 84/06/30 KEPPLER, J G
Region 3, Office of Director 47pp 26308 029 24X
Fiche 50-295, 84/06/30, 8408300136

8408160122 Monthly operating repts for Jul 1984 W/840807 ltr
AUSTIN, G , GRAESSER, K L Commonwealth Edison Co 84/07/31 13pp
26108 117 24X Fiche 50-295, 84/07/31, 8408160122

S Reportable occurrences, LERs & related correspondence

8408160150 LER 84-017-01 on 840622, containment air monitor low range noble gas detector failed to respond to check source & declared inoperable Caused by malfunction in check source mechanism Check source mechanism repaired W/840809 ltr
KUECHLE, C , GRAESSER, K L Commonwealth Edison Co 84/07/20 3pp
26109 069 24X Fiche 50-295, 84/07/20 8408160150

8408100109 PNO-III-84-098B on 840718, licensee successfully completed integrated leak rate test following 840710 shutdown for failure to demonstrate integrity of containment Unit expected to start up by 840816
SUERMANN, J , WRIGHT, G , REYES, L Region 3, Office of Director
84/08/02 1p 25990 362 24X Fiche 50-295, 84/08/02, 8408100109

8408090404 LER 84-019-00 on 840621, startup repts for initial use of Westinghouse optimized fuel assemblies submitted to NRC late Caused by misinterpretation of Tech Spec Repts tracked w/commitment list W/840803 ltr
CHIN, R Y , GRAESSER, K L Commonwealth Edison Co 84/08/03 3pp
25993 267 24X Fiche 50-295, 84/08/03, 8408090404

8408130604 LER 84-018-00 on 840621, blower for 10PR03R (vent stack & iodine sampler) found off Cause unknown Blower turned on & verified operational Installation of low flow annunciator initiated Monitors checked shirtly W/840806 ltr
KASSNER, G , GRAESSER, K L Commonwealth Edison Co 84/08/06 3pp
26030 360 24X Fiche 50-295, 84/08/06, 8408130604

8408240042 LER 84-020-00 on 840814, while releasing gas decay tank 1C, loss of pressure occurred in gas decay tank 2 B Caused by improper lineup causing gas decay tank to be cross-tied Work requests written for repair of rods W/840815 ltr
DAHLEN, D , GRAESSER, K L Commonwealth Edison Co 84/08/15 3pp
26236 351 24X Fiche 50-295, 84/08/15, 8408240042

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/08/16
EISENHUT, D G Division of Licensing 20pp 26293 249 24X
Fiche 50-000, 84/08/16, 8408230077

8408230014 LER 84-021-00 on 840718, containment structure failed to meet requirements of 10CFR50, App J after exam of 1981 & 1983 integrated leak tests Cause not stated Evaluation of test adequacy continuing W/840816 ltr
LANE, R E , GRAESSER, K L Commonwealth Edison Co 84/08/16 4pp
26212 279 24X Fiche 50-295, 84/08/16, 8408230014

8408300093 LER 82-038/03L on 8P1015, narrow-range temp cold leg Loop D low level amplifier (TM-4110) failed Caused by incorrect capacitor voltage values Components replaced & module returned W/840822 ltr
WILHITE, M , GRAESSER, K L Commonwealth Edison Co 84/08/22 3pp
26308 096 24X Fiche 50-295, 84/08/22, 8408300093

V Operator Examinations

8408140372 Forwards proposed rev to 'Requalification Program for Licensed Operators Senior Operators * Senior Operators (Limited),' in response to NUREG-0737 Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000, 84/08/07, 8408140372

--8408140369 "Requalification Program for Licensed Operators, Senior Operators * Senior Operators (Limited) '
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X Fiche 50-000, 84/08/07, 8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R L Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency * fire protection plans

8408300402 Forwards summary of 840530 meeting w/TVA, Alabama Power Co, Florida Power Corp, Florida Power & Light * Georgia Power Co re selected emergency preparedness issues
O'REILLY, J P Region 2, Office of Director 84/06/08 PARRIS, H G Tennessee Valley Authority 4pp 26308 116 24X Fiche 50-000, 84/06/08, 8408300402

8408280096 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17
VERRELLI, D M Region 2, Office of Director 84/07/25 PARRIS, H G Tennessee Valley Authority 1p 26281 319 24X Fiche 50-259, 84/07/25, 8408280096

--8408280116 Responds to NRC 840607 ltr re violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 Corrective actions temporary fire load form posted * daily fire load insps performed until removal of combustibles
MILLS, L M Tennessee Valley Authority 84/07/09 O'REILLY, J P Region 2, Office of Director 2pp 26281 320 24X Fiche 50-259, 84/07/25, 8408280096

--8408280124 Forwards Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 & notice of violation
VERRELLI, D M Region 2, Office of Director 84/06/07 PARRIS, H G Tennessee Valley Authority 2pp 26281 322 24X Fiche 50-259, 84/07/25, 8408280096

--8408280134 Notice of violation from insp on 840508-11
* Region 2, Office of Director 84/06/07 1p 26281 324 24X Fiche 50-259, 84/07/25, 8408280096

--8408280140 Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 Violations noted failure to follow fire prevention procedures for control of temporary fire loads
MADDEN, P M Region 2, Office of Director 84/06/01 9pp 26281 325 24X Fiche 50-259, 84/07/25, 8408280096

8408020149 Forwards revs to implementing procedures document, consisting of IP-6, "Activation of Technical Support Ctr," IP-20, "Technical Support Ctr Operation" * Rev 14 to "Radiological Emergency Plan "
MILLS, L M Tennessee Valley Authority 84/07/27 O'REILLY, J P Region 2, Office of Director 1p 25886 011 24X Fiche 50-259, 84/07/27, 8408020145

--8408020151 Revs to radiological emergency plan procedures, consisting of IP-6, "Activation of Technical Support Ctr" & IP-20, "Technical Support Ctr Operation "
* Tennessee Valley Authority 84/07/27 12pp 25886 012 24X Fiche 50-259, 84/07/27, 8408020145

--8408020156 Rev 14 to "Radiological Emergency Plan "
* Tennessee Valley Authority BFN-REP R14 84/06/29 4pp 25886 024 24X Fiche 50-259, 84/07/27, 8408020145

8408030015 Forwards safety analysis, implementation plan & implementation schedule for safety parameter display sys, per DB Vassallo 840612 confirmatory order to HQ Parris
MILLS, L M Tennessee Valley Authority 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 25907 118 24X Fiche 50-259, 84/07/30, 8408030015

8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15
LEWIS, R C Region 2, Office of Director 84/08/13 PARRIS, H G Tennessee Valley Authority 1p 26206 316 24X Fiche 50-259 84/08/13 8408230167

--8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Corrective actions total sys walkdown for control air sys flow diagrams performed by plant personnel
MILLS, L M Tennessee Valley Authority 84/00/01 O'REILLY, J P Region 2, Office of Director 6pp 26206 318 24X Fiche 50-259 84/08/13, 8408230167

--8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Corrective actions Std Practice 14 25 revised to require second party verification in hanging & removing clearance tags
MILLS, L M Tennessee Valley Authority 84/06/29 O'REILLY, J P Region 2, Office of Director 11pp 26206 324 24X Fiche 50-259, 84/08/13, 8408230167

--8408230225 Notice of violation from insp on 840326-0429
* Region 2, Office of Director 84/05/23 5pp 26206 337 24X Fiche 50-259, 84/08/13, 8408230167

--8408230240 IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 on 840326-0429 Violations noted misaligned sys valves on control air compressor, incorrect valve on control air sys & inadequate fire protection surveillance procedures
PAULK, C L Region 2, Office of Director 84/05/17 14pp 26206 342 24X Fiche 50-259, 84/08/13, 8408230167

8408290245 Forwards justification which suppls 840612 schedular exemption request re fire protection mods
MILLS, L M Tennessee Valley Authority 84/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 26290 317 24X Fiche 50-259, 84/08/23, 8408290245

H General correspondence

8408230056 Responds to 840727 ltr transmitting SL Benavides 840627 concerns re failure of reactor trip sys of nuclear plants NRC established 10CFR50 62, which requires addl features be installed at each reactor to assure shutdown if sys fails
DIRKS, W J Office of the Executive Director for Operations 84/08/15 DOMENICI, P V Senate 6pp 26233 279 24X Fiche 50-000, 84/08/15, 8408230056

--8408230063 Requests response to encl SL Benavides 840627 ltr re scram sys in nuclear reactors
DOMENICI, P V Senate 84/07/27 HAMMERER, C C NRC - No Detailed Affiliation Given 8pp 26233 280 24X Fiche 50-000, 84/08/15, 8408230056

P Operating license stage documents & correspondence

8408300434 Confirms 840601 telcon between JA Coffey & RC Lewis re 840621 enforcement conference in Region II ofc to discuss design problems w/power supply & distribution sys Proposed agenda encl
O'REILLY, J P Region 2, Office of Director 84/06/05 PARRIS, H G Tennessee Valley Authority 2pp 26314 328 24X Fiche 50-259, 84/06/05, 8408300434

8408030110 Forwards Amend 70 to License DPR-68 & safety evaluation Amend revises Tech Specs to incorporate limiting safety sys settings & conditions during sixth cycle * reflect changes from thermal power monitor mods during refueling outage
CLARK, R J Operating Reactors Branch 2 84/07/11 PARRIS, H G Tennessee Valley Authority 2pp 25920 326 24X Fiche 50-296, 84/07/11, 8408030110

--8408030125 Amend 70 to License DPR-68, incorporating limiting safety sys settings & conditions during sixth cycle & reflecting changes from thermal power monitor mods during current refueling outage
VASSALLO, D B Operating Reactors Branch 2 84/07/11 23pp 25920 328 24X Fiche 50-296, 84/07/11, 8408030110

--8408030140 Safety evaluation supporting Amend 70 to License DPR-68
* Office of Nuclear Reactor Regulation, Director 84/07/11 6pp 25920 331 24X Fiche 50-296, 84/07/11, 8408030110

8408140026 Forwards requests for addl info re Mark I containment long-term program vent sys analysis & details of seismic lugs Recommends 840910 meeting w/BNL & Franklin Research Ctr to discuss response prior to submittal of formal response
VASSALLO, D B Operating Reactors Branch 2 84/07/26 PARRIS, H G Tennessee Valley Authority 14pp 26061 249 24X Fiche 50-259, 84/07/26, 8408140026

8408010344 Responds to 840613 request for addl info re Mark I containment long-term program analyses Safety relief valve discharge piping sys mods based on most severe reflood conditions predicted by RVRIZ & RVFDR codes
MILLS,L M Tennessee Valley Authority 84/07/27 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 25866 322
24X Fiche 50-259,84/07/27,8408010344

8408150575 Responds to 830422 submittal of Tech Spec amends per TMI Item I A 1 3, "Limit Overtime" & Generic Ltr 83-02 Tech Spec change request to ensure overtime controls implemented, required
VASSALLO,D B Operating Reactors Branch 2 84/07/27 PARRIS,H G
Tennessee Valley Authority 2pp 26080 353 24X
Fiche 50-259,84/07/27,8408150575

8408160155 Forwards SER on NUREG-0737, Item II K 3 22 re automatic switchover of RCIC sys suction Manual switchover of RCIC suction on low water level in condensate storage tank acceptable
VASSALLO,D B Operating Reactors Branch 2 84/07/27 PARRIS,H G
Tennessee Valley Authority 9pp 26126 154 24X
Fiche 50-259,84/07/27,8408160155

8408160424 Forwards Amends 105,99 & 72 to Licenses DPR-33,DPR-52 & DPR-68,respectively & safety evaluation Amends replace word "operator" w/ "reactor operator" to provide consistent nomenclature
CLARK,R J Operating Reactors Branch 2 84/07/30 PARRIS,H G
Tennessee Valley Authority 3pp 26126 229 24X
Fiche 50-259,84/07/30,8408160424

--8408160426 Amends 105,99 & 72 to Licenses DPR-33,DPR-52 & DPR-68, respectively,replacing word "operator" w/ "reactor operator" to provide consistent nomenclature & permitting fuel handling supervised by senior reactor operator
VASSALLO,D B Operating Reactors Branch 2 84/07/30 12pp
26126 232 24X Fiche 50-259,84/07/30,8408160424

--8408160427 Safety evaluation supporting Amends 105,99 & 72 to Licenses DPR-33,DPR-52 & DPR-68,respectively
* Office of Nuclear Reactor Regulation, Director 84/07/30 2pp
26126 244 24X Fiche 50-259,84/07/30,8408160424

8408070370 Suppl 1 to 831027 application for amend to Licenses DPR-33, DPR-52 & DPR-68,consisting of minor revs to Tech Specs in response to NRC 831220 comments & request for addl info
MILLS,L M Tennessee Valley Authority 84/08/01 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 25947 176
24X Fiche 50-259,84/08/01,8408070370

--8408070375 Proposed Tech Spec re radioactive gaseous effluent instrumentation surveillance
* Tennessee Valley Authority 84/08/01 44pp 25947 178 24X
Fiche 50-259,84/08/01,8408070370

8408200264 Forwards Amends 106,100 & 73 to Licenses DPR-33,DPR-52 & DPR-68,respectively & safety evaluation Amends clarify correct operating positions & identify proper action for initiating signal for suppression chamber drain valves
CLARK,R J Operating Reactors Branch 2 84/08/02 PARRIS,H G
Tennessee Valley Authority 2pp 26142 345 24X
Fiche 50-259,84/08/02,8408200264

--8408200269 Amends 106,100 & 73 to Licenses DPR-33,DPR-52 & DPR-68, respectively Amends change Tech Specs re suppression chamber drain valves,clarify operating positions & identify proper action in initiating signal
VASSALLO,D B Operating Reactors Branch 2 84/08/02 12pp
26142 347 24X Fiche 50-259,84/08/02,8408200264

--8408200280 Safety evaluation supporting Amends 106,100 & 73 to Licenses DPR-33,DPR-52 & DPR-68,respectively
* Office of Nuclear Reactor Regulation, Director 84/08/02 2pp
26142 359 24X Fiche 50-259,84/08/02,8408200264

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408140375 Forwards response to NRC 831012 request for addl info re reactor protection sys power monitoring sys design mods Tech Specs will be submitted in future W/12 oversize drawings Aperture cards available in PDR
DOMER,J A Tennessee Valley Authority 84/08/09 DENTON,H R
Office of Nuclear Reactor Regulation, Director 11pp 26051 187
24X Fiche 50-259,84/08/09,8408140375

8408210003 Forwards Amends 10 ,101 & 74 to Licenses DPR-33,DPR-52 & DPR-68,respectively & safety evaluation Amends change Tech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed
CLARK,R J Operating Reactors Branch 2 84/08/09 PARRIS,H G
Tennessee Valley Authority 2pp 26195 194 24X
Fiche 50-259,84/08/09,8408210003

--8408210004 Amends 107,101 & 74 to Licenses DPR-33,DPR-52 & DPR-68, respectively,changing Tech Specs to allow operation for 30 days w/16 main steam tunnel high temp switches bypassed
VASSALLO,D B Operating Reactors Branch 2 84/08/09 12pp
26195 196 24X Fiche 50-259,84/08/09,8408210003

--8408210007 Safety evaluation supporting Amends 107,101 & 74 to Licenses DPR-33,DPR-52 & DPR-68,respectively
* Office of Nuclear Reactor Regulation, Director 84/08/09 5pp
26195 208 24X Fiche 50-259,84/08/09,8408210003

8408200131 Forwards response to 840501 ltr re Criteria 1,2,10 & 11 for permanent post-accident sampling facility Info on interim sys submitted on 840606
DOMER,J A Tennessee Valley Authority 84/08/13 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 26133 255
24X Fiche 50-259,84/08/13,8408200131

8408220137 Application for amend to Licenses DPR-33,DPR-52 & DPR-68, incorporating integrated schedule into license Detailed explanation of methodology utilized,definition of revised integrated schedule & fee encl
MILLS,L M Tennessee Valley Authority 84/08/14 DENTON,H R
Office of Nuclear Reactor Regulation, Director 86pp 26193 318
24X Fiche 50-259,84/08/14,8408220137

8408280257 Forwards Amends 110,103 & 76 to Licenses DPR-33,DPR-52 & DPR-68,respectively & safety evaluation Amends revise Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & maint
CLARK,R J Operating Reactors Branch 2 84/08/15 PARRIS,H G
Tennessee Valley Authority 2pp 26294 090 24X
Fiche 50-259,84/08/15,8408280257

--8408280261 Amends 110,103 & 76 to Licenses DPR-33,DPR-52 & DPR-68, respectively,revising Tech Specs to permit main steam line high temp isolation function to be inoperable for up to 4 h for testing & maint purposes
VASSALLO,D B Operating Reactors Branch 2 84/08/15 15pp
26294 092 24X Fiche 50-259,84/08/15,8408280257

--8408280276 Safety evaluation supporting Amends 110,103 & 76 to Licenses DPR-33,DPR-52 & DPR-68,respectively
* Office of Nuclear Reactor Regulation, Director 84/08/15 2pp
26294 107 24X Fiche 50-259,84/08/15,8408280257

8408310424 Forwards Amends 104 & 77 to Licenses DPR-52 & DPR-68, respectively & safety evaluation Amends revise Tech Specs to change neutron flux trip setting adjustment factor
CLARK,R J Operating Reactors Branch 2 84/08/17 PARRIS,H G
Tennessee Valley Authority 2pp 26350 142 24X
Fiche 50-260,84/08/17,8408310424

--8408310431 Amends 104 & 77 to Licenses DPR-52 & DPR-68,respectively, revising Tech Specs to change neutron flux trip setting adjustment factor from limiting safety sys to limiting condition for operation w/6 h action statement
VASSALLO,D B Operating Reactors Branch 2 84/08/17 32pp
26350 144 24X Fiche 50-260,84/08/17,8408310424

--8408310432 Safety evaluation supporting Amends 104 & 77 to Licenses DPR-52 & DPR-68,respectively
* Office of Nuclear Reactor Regulation, Director 84/08/17 2pp
26350 176 24X Fiche 50-260,84/08/17,8408310424

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408310414 Notification of 840913 meeting w/util & Franklin Research Ctr in Knoxville,TN to discuss resolution of issues identified in request for addl info on structural evaluation in plant-unique analysis rept re Mark I torus mod
CLARK,R J Operating Reactors Branch 2 84/08/24 VASSALLO,D B
Operating Reactors Branch 2 1p 26350 222 24X
Fiche 50 259,84/08/24,8408310414

8408310420 Notification of 840905 meeting w/util & BNL in Knoxville, TN to discuss resolution of issues identified in staff request for addl info on hydrodynamic loads in plant-unique analysis rept re Mark I torus mods
CLARK, R J Operating Reactors Branch 2 84/08/24 VASSALLO, D B
Operating Reactors Branch 2 1p 26350 215 24X
Fiche 50-259, 84/08/24, 8408310420

G Inspection reports, IE Bulletins & correspondence

8407100322 Responds to 840605 ltr providing results of reanalysis of four walls Info resolves concerns re four walls identified in 840116 SER concerning IE Bulletin 83-11, "Masonry Wall Design "
VASSALLO D B Operating Reactors Branch 2 84/06/26 PARRIS, H G
Tennessee Valley Authority 2pp 25513 317 24X
Fiche 50-259, 84/06/26 8407100322

8408310109 Forwards Enforcement Conference Repts 50-259/84-21, 50-260/84-21 & 50-296/84-21 on 840621
O'REILLY, J P Region 2, Office of Director 84/07/09 PARRIS, H G
Tennessee Valley Authority 2pp 26334 227 24X
Fiche 50-259, 84/07/09, 8408310109

--8408310114 Enforcement Conference Repts 50-259/84-21, 50-260/84-21 & 50-296/84-21 on 840621 Major areas discussed design errors associated w/separation of electrical cables, paralleling diesel generators & shutdown board room cooling
BUTCHER, R C Region 2, Office of Director CANTRELL, F S
Division of Project & Resident Programs 84/07/05 6pp
26334 229 24X Fiche 50-259, 84/07/09, 8408310109

8408240338 Forwards Insp Repts 50-259/84-22, 50-260/84-22 & 50-296/84-22 on 840626-29 No violations or deviations noted
VERRELLI, D M Region 2, Office of Director 84/07/12 PARRIS, H G
Tennessee Valley Authority 2pp 26236 131 24X
Fiche 50-259, 84/07/12, 8408240338

--8408240342 Insp Repts 50-259/84-22, 50-260/84-22 & 50-296/84-22 on 840626-29 No violations or deviations noted Major areas inspected licensee action on previous enforcement matters, welding, inservice testing, IE bulletins & LERs
GIRARD, E H , BLAKE, J J Region 2, Office of Director 84/07/12
6pp 26236 133 24X Fiche 50-259, 84/07/12, 8408240338

8408280096 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17
VERRELLI, D M Region 2, Office of Director 84/07/25 PARRIS, H G
Tennessee Valley Authority 1p 26281 319 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280116 Responds to NRC 840607 ltr re violations noted in Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 Corrective actions temporary fire load form posted & daily fire load insps performed until removal of combustibles
MILLS, L M Tennessee Valley Authority 84/07/09 O'REILLY, J P
Region 2, Office of Director 2pp 26281 320 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280124 Forwards Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 & notice of violation
VERRELLI, D M Region 2, Office of Director 84/06/07
PARRIS, H G Tennessee Valley Authority 2pp 26281 322 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280134 Notice of violation from insp on 840508-11
* Region 2, Office of Director 84/06/07 1p 26281 324 24X
Fiche 50-259, 84/07/25, 8408280096

--8408280140 Insp Repts 50-259/84-17, 50-260/84-17 & 50-296/84-17 on 840508-11 Violations noted failure to follow fire prevention procedures for control of temporary fire loads
MADDEN, P M , MILLER, W H , CONLON, T E Region 2, Office of Director 84/06/01 9pp 26281 329 24X Fiche 50-259, 84/07/25, 8408280096

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408270196 Ack receipt of 840719 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-259/84-10, 50-260/84-10 & 50-296/84-10
VERRELLI, D M Region 2, Office of Director 84/07/31 PARRIS, H G
Tennessee Valley Authority 1p 26257 352 24X
Fiche 50-259, 84/07/31 8408270196

--8408270199 Responds to NRC 840509 ltr re violations noted in Insp Repts 50-259/84-10, 50-260/84-10 & 50-296/84-10 Corrective actions Procedures 1053 & 1053A revised to correct procedural violations
MILLS L M Tennessee Valley Authority 84/07/19 O'REILLY, J P
Region 2, Office of Director 2pp 26257 353 24X
Fiche 50 259, 84/07/31, 8408270196

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26057 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408150213 Forwards rept required by Item III C 5 of 830826 order re piping insp Results of IGSCC insp, including pre & post-induction heating stress improvement insps, provided Unacceptable indication found in head spray piping
DOMER, J A Tennessee Valley Authority 84/08/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 100pp 26066 136
24X Fiche 50-296, 84/08/09, 8408150213

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408230167 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15
LEWIS, R C Region 2, Office of Director 84/08/13 PARRIS, H G
Tennessee Valley Authority 1p 26206 316 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230180 Ack receipt of 840629 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Supplemental response expected by 840801
LEWIS, R C Region 2, Office of Director 84/07/12 PARRIS, H G
Tennessee Valley Authority 1p 26206 317 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230192 Responds to NRC 840712 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Corrective actions total sys walkdown for control air sys flow diagrams performed by plant personnel
MILLS, L M Tennessee Valley Authority 84/08/01 O'REILLY, J P
Region 2, Office of Director 6pp 26206 318 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230208 Responds to NRC 840523 ltr re violations noted in IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 Corrective actions Std Practice I4 25 revised to require second party verification in hanging & removing clearance tags
MILLS, L M Tennessee Valley Authority 84/06/29 O'REILLY, J P
Region 2, Office of Director 11pp 26206 324 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230219 Forwards IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 on 840326-0425 & notice of violations Addl attention must be given to Tech Spec maint
LEWIS, R C Region 2, Office of Director 84/05/23 PARRIS, H G
Tennessee Valley Authority 2pp 26206 335 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230225 Notice of violation from insp on 840326-0425
* Region 2, Office of Director 84/05/23 5pp 26206 337 24X
Fiche 50-259, 84/08/13, 8408230167

--8408230240 IE Insp Repts 50-259/84-15, 50-260/84-15 & 50-296/84-15 on 840326-0405 violations noted misaligned sys valves on control air compressor, incorrect valve on control air sys & inadequate fire protection surveillance procedures
PAULK, G L , PATTERSON, C A , CANTRELL, F S Region 2, Office of Director 84/05/17 14pp 26206 342 24x Fiche 50-259, 84/08/13, 8408230167

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24x Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 021 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408240109 Forwards response to NRC 840720 ltr re violations noted in listed insp repts & Proposed Civil Penalty Action EA 84-095 Corrective actions include rev to Plant Instruction FI-74 to upgrade post-trip review Civil penalty fee will be wired
DOMER, J A Tennessee Valley Authority 84/08/20 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 10pp 26228 233 24X Fiche 50-259, 84/08/20, 8408240109

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408060098 "NPDES Discharge Monitoring Rept for Apr 1984 "
* Tennessee Valley Authority 84/04/30 54pp 25935 208 24X Fiche 50-259, 84/04/30, 8408060098

8408270366 Forwards "Effluent & Waste Disposal Semiannual Rept, Supplemental Info, First Half 1984" & revised "Effluent & Waste Disposal Semiannual Rept Liquid Releases for Second Half 1983 Batch Mode "
JONES, O T Tennessee Valley Authority 84/08/21 Director's Office, Office of Inspection and Enforcement 1p 26240 320 24X Fiche 50-259, 84/08/21, 8408270366

--8408270369 "Effluent & Waste Disposal Semiannual Rept Supplemental Info, First Half 1984 "
* Tennessee Valley Authority 84/06/30 15pp 26240 321 24X Fiche 50-259, 84/08/21, 8408270366

--8408270374 Revised "Effluent & Waste Disposal Semiannual Rept Liquid Releases for Second Half 1983 Batch Mode "
* Tennessee Valley Authority 83/12/31 1p 26240 336 24X Fiche 50-259, 84/08/21, 8408270366

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26191 337 24X Fiche 50-000, 84/03/13, 8408220317

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C ector's Office, Office of Inspection and Enforcement 3pp 22 256 24X Fiche 50-000, 84/04/13, 8408240348

8408200412 LER 84-006-01 on 840517, insp of jet pump instrument nozzles found two welds in need of repair Weld overlay procedure completed prior to startup Addl welds will be inspected in upcoming outages W/840810 ltr
SMITH, D L JONES, O T Tennessee Valley Authority 84/08/10 3pp 26138 261 24X Fiche 50-296, 84/08/10, 8408200412

8408270150 LER 84-006-02 on 840517, discovered 2 out of 10 welds inspected on jet pump instrument nozzles in need of repair Caused by intergranular stress corrosion cracking Welds repaired by weld overlay procedure W/840817 ltr
SMITH, D L , JONES, O T Tennessee Valley Authority 84/08/17 3pp 26245 154 24X Fiche 50-296, 84/08/17, 8408270150

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl OL lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSS, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000 84/08/21, 8408310186

V Operator Examinations

8408310036 Confirmation of action ltr re 840521 telcon between RC Lewis & JA Coffey concerning results of operator exams conducted on 840323 Operators who failed exam prohibited from licensed duties until Sections 6 or 7 completed satisfactorily
O'REILLY, J P Region 2, Office of Director 84/05/23 PARRIS, H G Tennessee Valley Authority 3pp 26339 020 24X Fiche 50-259, 84/05/23, 8408310036

DOCKET 50-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR

P Operating license stage documents & correspondence

8408020065 Application for amend to license R-120, changing Tech Specs to incorporate organizational changes
PAULTON, B R North Carolina State Univ , Raleigh, NC 84/07/26 Division of Licensing 9pp 29691 289 24X Fiche 50-297, 84/07/26, 8408020065

-8408020069 Proposed Tech Specs incorporating organizational changes
* North Carolina State Univ , Raleigh, NC 84/07/26 25pp 29691 290 24X Fiche 50-297, 84/07/26, 8408020065

DOCKET 50-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

8408070267 Rev 4 to Emergency Plan Implementing Procedure EPIP 5 / 21, "Emergency Equipment Inventory " W/8408001 ltr
WINDHAM, R , WHITMAN, D , PILANT, J M Nebraska Public Power District 84/08/01 (COLLINS, J T Region 4, Office of Director 30pp 29949 209 24X Fiche 50-298, 84/08/01, 8408070267

8408070316 Revised Pages 5-11, 5-64, 6-6, 6-6, 25-4 & 25-5 & D-2 to station emergency plan W/8408001 ltr
PILANT, J M Nebraska Public Power District 84/08/01 COLLINS, J T Region 4, Office of Director 8pp 29947 108 24X Fiche 50-298, 84/08/01, 8408070316

8408160092 Forwards safety parameter display sys (SPDS) preimplementation audit results & schedule for submittal of addl SPDS info due within 60 days of ltr receipt NUREG 0737, Suppl 1 guidelines require resolution
VASSALLO, D B Operating Reactors Branch 3 84/08/01 PILANT, J M Nebraska Public Power District 13pp 26126 349 24X Fiche 50-298, 84/08/01, 8408160092

8408140431 Responds to NRC 840604 review of detailed control room design review program plan per Suppl 1 to NUREG-0737 Summary rept will be submitted by Dec 1984
PILANT, J M Nebraska Public Power District 84/08/09
VASSALLO, D B Operating Reactors Branch 3 1pp 26050 359 24X Fiche 50-298, 84/08/09, 8408140431

8408240171 "Radiation Protection Plan "
* Nebraska Public Power District 84/08/15 (LIEBENAUT, D G Division of Licensing 98pp 26248 105 24X Fiche 50-298, 84/08/15, 8408240171

8408290101 Forwards Insp Rept 50-298/84-13 on 840612-15 & notices of violation & deviation Notices withheld (ref 10CFR2.201)
JOHNSON, F H Region 4, Office of Director 84/08/16 PILANT, J M Nebraska Public Power District 4pp 26298 320 24X Fiche 50-298, 84/08/16, 8408290101

--8408290104 Insp Rept 50-298/84-13 on 840612-15 re security plan & implementing procedures One violation & four deviations identified Details withheld (ref 10CFR/3 21)
KELLY J A , HALL,R E , JAUDON,J P Region 4, Office of Director
84/08/15 1p 26298 222 24X Fiche 50-298,84/08/16,8408290101

I Financial information

8408150447 Submits info demonstrating ability to obtain funds for payment of deferred premiums within 3-month period Annual rept to Securities ? Exchange Commission for 1983 & uniform forecast form for security analysts encl
PILANT,J M Nebraska Public Power District 84/08/03 Office of Nuclear Reactor Regulation, Director 82pp 26077 157 24X
Fiche 50-298,84/08/03,8408150447

P Operating license stage documents & correspondence

8408100145 Forwards Pages 2-14 & 2-15 which were inadvertently omitted from 840305 Rev 1 to "Cooper Nuclear Station QA Program "
PILANT,J M Nebraska Public Power District 84/04/03 COLLINS,J T Region 4, Office of Director 3pp 25988 273 24X
Fiche 50-298,84/04/03,8408100145

8408010018 Forwards SER & EG&G technical evaluation rept re response to Generic Ltr 81-04 (Rev 1 to NUREG-0313) concerning BWR coolant pressure boundary piping
VASSALLO,D B Operating Reactors Branch 2 84/07/23 PILANT,J M
Nebraska Public Power District 3pp 25867 305 24X
Fiche 50-298,84/07/23,8408010018

--8408010022 Safety evalution re IGSCC in RCPB piping sys,per Generic Ltr 81-04 Licensee response does not meet NUREG-0313 guidelines Further action will depend upon responses to Generic Ltrs 84-07 & 84-11
* Office of Nuclear Reactor Regulation, Director 84/07/23 4pp 25867 308 24X Fiche 50-298,84/07/23,8408010018

--8408010027 "Technical Evaluation of Integrity of Cooper Nuclear Station Reactor Coolant Boundary Piping Sys "
NAGATA,P K EG&G, Inc FIN A-6429 EGG-FM-6521 83/07/31
KOO,W H Division of Engineering 40pp 25867 312 24X
Fiche 50-298,84/07/23,8408010018

8408070295 Forwards response to 840529 request for addl info re TMI Item II K 3 28, "Qualification of Automatic Depressurization Sys Accumulators," per 10CFR50 54(f) AE verified accumulators,components & tubing per Seismic 1 specs
PILANT,J M Nebraska Public Power District 84/07/26
EISENHUT,D G Division of Licensing 5pp 25948 078 24X
Fiche 50-298,84/07/26,8408070295

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

Q Inspection reports, IE Bulletins & correspondence

8408060202 Forwards figures,charts & graphs omitted from 840511 exam rept
JOHNSON,E H Region 4, Office of Director 84/07/03 PILANT,J M
Nebraska Public Power District 10pp 25936 162 24X
Fiche 50-298,84/07/03,8408060202

8408030011 Responds to NRC 840611 ltr re violations noted in IE Insp Rept 50-298/84-09 Corrective actions matls awaiting disposal by destruction or return to vendor identified,tagged & marked Warehouse personnel attended refresher session
PILANT,J M Nebraska Public Power District 84/07/05 JOHNSON,E H Region 4, Office of Director 2pp 25915 315 24X
Fiche 50-298,84/07/05,8408030011

8408090034 Forwards requalification program audit rept from exam conducted in May 1984
JOHNSON,E H Region 4, Office of Director 84/07/05 PILANT,J M,
Nebraska Public Power District 2pp 25992 266 24X
Fiche 50-298,84/07/05,8408090034

--8408090037 Requalification program audit rept from exam conducted in May 1984 Audit results requalification program marginal
PELLET,J L , COOLEY,R A Region 4, Office of Director 84/06/22
42pp 25992 268 24X Fiche 50-298,84/07/05,8408090034

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408030044 Ack receipt of 840705 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/84-09 Corrective actions will be reviewed during future insp
JOHNSON,E H Region 4, Office of Director 84/07/27 PILANT,J M
Nebraska Public Power District 1p 25907 029 24X
Fiche 50-298,84/07/27,8408030044

8408230010 Forwards IE Insp Rept 50-298/84-14 on 840625-29 No violations or deviations noted
JOHNSON,E H Region 4, Office of Director 84/07/31 PILANT,J M
Nebraska Public Power District 2pp 26214 201 24X
Fiche 50-298,84/07/31,8408230010

--8408230013 IE Insp Rept 50-298/84-14 on 840625-29 No violations or deviations noted Major areas inspected mod activities re recirculation loop,core spray loop & reactor water cleanup piping replacement
BARNES,I , JAUDON,J P Region 4, Office of Director 84/07/31
8pp 26214 203 24X Fiche 50-298,84/07/31,8408230010

8408100107 Forwards QA Program Insp Rpts 99900911/84-01,99900715/84-01 & 99900325/84-01 Requests evaluation of significance of reported findings re quality & acceptability of vendor product or svc W/o encls
JOHNSON,E H Region 4, Office of Director 84/08/03 PILANT,J M
Nebraska Public Power District 2pp 25990 200 24X
Fiche 50-298,84/08/03,8408100107

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 12pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408270489 Forwards Insp Rept 50-298/84-11 on 840501-0630 & notice of violation
JOHNSON,E H Region 4, Office of Director 84/08/08 PILANT,J M
Nebraska Public Power District 2pp 26256 170 24X
Fiche 50-298,84/08/08,8408270489

--8408270494 Notice of violation from insp on 840501-0630
* Region 4, Office of Director 84/08/08 2pp 26256 172 24X
Fiche 50-298,84/08/08,8408270489

--8408270500 Insp Rept 50-298/84-11 on 840501-0630 Violations noted failure to have procedures for maint & failure to perform safety review of change made to facility
JOHNSON,E H , DUBOIS,D L , YANDELL,L A Region 4, Office of Director 84/08/08 14pp 26256 174 24X Fiche 50-298,84/08/08, 8408270489

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 11pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408290101 Forwards Insp Rept 50-298/84-13 on 840612-15 & notices of violation & deviation Notices withheld (ref 10CFR73 21)
JOHNSON,E H Region 4, Office of Director 84/08/16 PILANT,J M
Nebraska Public Power District 2pp 26298 220 24X
Fiche 50-298,84/08/16,8408290101

--8408290104 Insp Rept 50-298/84-13 on 840612-15 re security plan & implementing procedures One violation & four deviations identified Details withheld (ref 10CFR73 21)
KELLY,J A , HALL,R E , JAUDON,J P Region 4, Office of Director
84/08/15 1p 26298 222 24X Fiche 50-298,84/08/16,8408290104

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408100014 Forwards errata to "Semiannual Operating Rept - Radioactive Effluents,Jul-Dec 1983," consisting of corrected Tables 5,6,9 & 11 of App C
PILANT,J M Nebraska Public Power District 84/07/09 COLLINS,J T
Region 4, Office of Director 1p 25989 273 24X
Fiche 50-298,84/07/09,8408100014

--8408100017 Errata to "Semiannual Operating Rept - Radioactive Effluents,Jul-Dec 1983 "
* Nebraska Public Power District 83/12/31 6pp 25989 274
24X Fiche 50-298,84/07/09,8408100014

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,G G General Electric Co 84/04/13 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000,84/04/13,8408240348

8408240072 LER 84-009-00 on 840719,operation of APRM flow biased scram & rod block sys inconsistent w/Tech Specs Caused by configuration changes not fully incorporated in Tech Specs Tech Specs revised W/840817 ltr
BALLINGER,P.L , THOMASON,P W Nebraska Public Power District
84/08/17 3pp 26237 014 24X Fiche 50-298,84/08/17,8408240072

8408310355 Forwards "Contamination of Snubber Bleed Screw & Lockup Poppet Valve," technical review rept Event probably unique & does not have generic implications Corrective actions
uate No further action required
Reactor Operations Analysis Branch 84/08/20 BEYFRIT,K V
perations Analysis Branch 1p 26350 313 24X
298,84/08/20,8408310355

ination of Snubber Bleed Screw & Lockup Poppet
l review rept,
perations Analysis Branch 84/08/20 3pp
iche 50-298,84/08/20,8408310355

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA,R General Electric Co 81/08/21 ROSSI,C E Director's
Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000,84/08/21,8408310186

V Operator Examinations

8408060202 Forwards figures,charts & graphs omitted from 840511 exam rept
JOHNSON,E H Region 4, Office of Director 84/07/03 PILANT,J M
Nebraska Public Power District 10pp 25936 162 24X
Fiche 50-298,84/07/03,8408060202

8408090034 Forwards requalification program audit rept from exam conducted in May 1984
JOHNSON,E H Region 4, Office of Director 84/07/05 PILANT,J M
Nebraska Public Power District 2pp 25992 266 24X
Fiche 50-298,84/07/05,8408090034

--8408090037 Requalification program audit rept from exam conducted in May 1984 Audit results requalification program marginal
PELLET,J L , COOLEY,R A Region 4, Office of Director 84/06/22
42pp 25992 268 24X Fiche 50-298,84/07/05,8408090034

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408020150 Ack receipt of 840705 ltr forwarding scope & objectives for 840911 emergency preparedness exercise Proposed objectives acceptable,w/inclusion of assembly/accountability
PAPERIELLO,C J Region 3, Office of Director 84/07/27 FAY,C W
Wisconsin Electric Power Co 1p 25886 028 24X
Fiche 50-266,84/07/27,8408020150

--8408020155 Forwards draft scope for 840911 emergency preparedness exercise Detailed scenario will be provided by first wk of Aug & associated controller packages will be provided by third wk of Aug
BRITT,R W Wisconsin Electric Power Co 84/07/05 KEPPLER,J G
Region 3, Office of Director 10pp 25886 029 24X
Fiche 50-266,84/07/27,8408020150

8408020160 Notifies that review completed re 840629 revs to App C of emergency plan Plan changes do not downgrade effectiveness of emergency plan
PAPLRIELLO,C J Region 3, Office of Director 84/07/27 FAY,C W
Wisconsin Electric Power Co 1p 25886 037 24X
Fiche 50-266,84/07/27,8408020160

8408030167 Forwards Rev 0 to "Control Room Design Review Program Plan," in partial fulfillment of Generic Ltr 82-33, "Suppl 1 to NUREG-0737 - Requirements for Emergency Response Capability "
FAY,C W Wisconsin Electric Power Co 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 25911 193 24X
Fiche 50-266,84/07/31,8408030167

--8408030170 Rev 0 to "Control Room Design Review Program Plan "
* Wisconsin Electric Power Co 84/07/31 180pp 25911 194 24X
Fiche 50-266,84/07/31,8408030167

8408170198 Ack receipt of 840731 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-266/84-00 & 50-301/84-06
AXELSON,W L Region 3, Office of Director 84/08/13 CASSIDY,T J
Wisconsin Electric Power Co 1p 26118 093 24X
Fiche 50-266,84/08/13,8408170198

--8408170203 Forwards response to NRC 840711 ltr re noncompliance noted in IE Insp Repts 50-266/84-00 & 50-301/84-06 Encl withheld (ref 10CFR73 21)
CASSIDY,T J. Wisconsin Electric Power Co 84/07/31 KEPPLER,J G
Region 3, Office of Director 1p 26118 094 24X
Fiche 50-266,84/08/13,8408170198

8408210343 Revised emergency plan maint procedures including 1 1 re routine check,maint,calibr & inventory schedule for health physics equipment & 1 2 re routine check,maint & calibr instructions for emergency plan equipment W/840814 ltr
* Wisconsin Electric Power Co 84/08/14 DENTON,H R Office of Nuclear Reactor Regulation, Director 74pp 26181 043 24X
Fiche 50-266,84/08/14,8408210343

8408290197 Informs that NRC representative will not be available to attend FEMA preexercise briefing W Shell will contact FEMA after NRC 840910 entrance * attend 840913 public critique Region III representation at FY85 public critiques unlikely PAPERIELLO C J Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/24 WEAVER W J Federal Emergency Management Agency 1p 26291 176 24X Fiche 50-266,84/08/24, 8408290197

--8408290206 Forwards schedule for 1984 emergency exercise NRC representation at pre & post-exercise briefings requested WEAVER,W J Federal Emergency Management Agency 84/08/16 KEPPLER,J G Region 3, Office of Director 33p 26291 177 24X Fiche 50-266,84/08/24,8408290197

H General correspondence

8408090514 Informs that NRC deleting organization on distribution for correspondence between NRC & util Correspondence available in LPDR COLBURN,T G Operating Reactors Branch 3 84/07/27 ANDERSON,P Wisconsin's Environmental Decade 1p 25983 115 24X Fiche 50-266,84/07/27,8408090514

K Utility Final Safety Analysis Report (FSAR) & amends

8407310166 Forwards rev to updated FSAR for Point Beach Nuclear Plant,Units 1 & 2 FAY,C W Wisconsin Electric Power Co 84/07/20 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 2pp 25905 001 24X Fiche 50-266,84/07/20,8407310166

--8408020148 Rev to updated FSAR for Point Beach Nuclear Plant,Units 1 & 2 * Wisconsin Electric Power Co 84/07/20 360pp 25905 010 24X Fiche 50-266,84/07/20,8407310166

P Operating license stage documents & correspondence

8408010120 Forwards marked-up radiological ETS for Units 1 & 2 Review of comments requested in preparation for discussion at meeting w/NRC, tentatively scheduled for mid-Aug in Bethesda,MD MILLER,J R Operating Reactors Branch 3 84/07/17 FAY,C W Wisconsin Electric Power Co 81pp 25872 216 24X Fiche 50-266,84/07/17,8408010120

8408070492 Forwards comments on 840502 amend application for Tech Spec changes concerning containment tendon surveillance Mod of application or justification of position requested within 45 days MILLER,J R Operating Reactors Branch 3 84/07/24 FAY,C W Wisconsin Electric Power Co 6pp 25956 249 24X Fiche 50-266,84/07/24,8408070492

8408060127 Advises of revised schedule to install new single-failure-proof auxiliary bldg crane trolley Installation will begin following Spring 1985 Unit 1 refueling outage Final design review & license amend application will be submitted BRITT,R W Wisconsin Electric Power Co 84/07/30 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 1p 25933 057 24X Fiche 50-266,84/07/30,8408060127

8408070328 Forwards Rev 1 to "Process Control Program," listing vendor procedures governing processing & packaging of solid radwaste BRITT,R W Wisconsin Electric Power Co 84/08/01 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 1p 25945 139 24X Fiche 50-266,84/08/01,8408070328

--8408070330 Rev 1 to "Process Control Program " * Wisconsin Electric Power Co 84/08/01 3pp 25945 140 24X Fiche 50-266,84/08/01,8408070328

8408200002 Forwards request for addl info re 830314 & 0906 requests for Tech Spec changes allowing use of Westinghouse optimized fuel W/o encl MILLER,J R Operating Reactors Branch 3 84/08/01 FAY,C W Wisconsin Electric Power Co 1p 26143 264 24X Fiche 50-266,84/08/01,8408200002

8408070030 Responds to 840326 request for periodic updates re progress made toward alleviating shortage of licensed operators Adequate number of licensed operators anticipated after scheduled reactor license exam in Dec 1984 BRITT,R W Wisconsin Electric Power Co 84/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 2pp 25950 036 24X Fiche 50-266,84/08/02,8408070030

8408070245 Requests extension of qualification program completion schedule to end of June 1985 refueling outage for Crosby lift indicating switch assemblies & Veam thermocouple connectors BRITT,R W Wisconsin Electric Power Co 84/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 3pp 25949 017 24X Fiche 50-266,84/08/02,8408070245

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110

8408160482 Summary of 840724 meeting w/Westinghouse Owners Group re upper plenum injection for two loop plants DIIANNI,D C Operating Reactors Branch 3 84/08/09 Operating Reactors Branch 3 4pp 26108 327 24X Fiche 50-000,84/08/09, 8408160482

8408270233 Forwards proprietary & nonproprietary responses to request for addl info re Tech Spec Change Request 87 concerning use of Westinghouse optimized fuel assembly Application for withholding proprietary response (ref 10CFR2 790) encl FAY,C W Wisconsin Electric Power Co 84/08/17 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 3pp 26242 205 24X Fiche 50-266,84/08/17,8408270233

--8408270246 Requests proprietary responses to NRC questions re optimized fuel assembly design be withheld (ref 10CFR2 790) Affidavit encl WIESEMANN,R A Westinghouse Electric Corp 84/08/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 11lpp 26242 208 24X Fiche 50-266,84/08/17,8408270233

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275

8408280216 Forwards addl info re methodology & results of analysis performed to determine impact of parking rod cluster control assemblies at 225 steps withdrawn position, per request FAY,C W Wisconsin Electric Power Co 84/08/22 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Licensing Branch 3 4pp 26279 183 24X Fiche 50-266,84/08/22, 8408280216

8408280128 Confirms 840823 telcon between R Seizert & C Trammel re existence of potential defect in Anker-Holth large bore snubbers Info provided in 840810 ltr presently being evaluated to determine impact upon facility operations FAY,C W Wisconsin Electric Power Co 84/08/24 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 1p 26261 319 24X Fiche 50-266,84/08/24,8408280128

8408310284 Advises that mods to motor operated discharge valves for electric driven auxiliary feedwater pumps completed & tested satisfactorily EISENHUT,D G Division of Licensing 84/08/24 NORELIUS,C E Division of Project & Resident Programs 1p 26351 334 24X Fiche 50-266,84/08/24,8408310284

Q Inspection reports, IE Bulletins & correspondence

8408090184 Forwards IE Insp Repts 50-266/84-12 & 50-301/84-10 on 840711 No noncompliance identified LITTLE,W S Region 3, Office of Director 84/07/23 FAY,C W Wisconsin Electric Power Co 2pp 25992 075 24X Fiche 50-266,84/07/23,8408090184

--8408090189 IE Insp Repts 50-266/84-12 & 50-301/84-10 on 840711 No noncompliance identified Major areas inspected followup of valve shaft insps on main steamline isolation swing check & swing stop valves JONES,D E , DANIELSON,D H Region 3, Office of Director 84/07/23 2pp 25992 077 24X Fiche 50-266,84/07/23,8408090184

8408150399 Forwards IE Insp Repts 50-266/84-10 & 50-301/84-08 on 840625-29 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 84/07/25 FAY,C W Wisconsin Electric Power Co 2pp 26077 320 24X Fiche 50-266,84/07/25,8408150399

--8408150406 IE Insp Repts 50-266/84-10 & 50-301/84-08 on 840625-29 No violations noted Major areas inspected operational radiation protection program, including mgt staffing, exposure control, ALARA, surveys, posting & controls & TMI action items
PAUL, R A ; GREGER, L R Region 3, Office of Director 84/07/25
8pp 26077 322 24X Fiche 50-266 84/07/25, 8408150399

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408160329 Forwards IE Insp Repts 50-266/84-11 & 50-301/84-09 on 840702-03 No noncompliance noted
LITTLE, W G Region 3, Office of Director 84/07/30 Wisconsin Electric Power Co 2pp 26106 094 24X Fiche 50-266, 84/07/30, 8408160329

--8408160331 IE Insp Repts 50-266/84-11 & 50-301/84-09 on 840702-03 No noncompliance or deviations noted Major areas inspected followup action of previously identified insp findings
MILBRDT, W E , GULDEMOND, W G Region 3, Office of Director
84/07/27 5pp 26106 096 24X Fiche 50-266, 84/07/30, 8408160329

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408100044 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-21 & 50-301/83-20, per 840517 request
SPESSARD, R L Region 3, Office of Director 84/08/03 FAY, C W
Wisconsin Electric Power Co 1p 25987 063 24X
Fiche 50-266, 84/08/03, 8408100044

--8408100052 Further response to NRC 840517 ltr re violations noted in IE Insp Repts 50-266/83-21 & 50-301/83-20 Corrective actions drawings received after 840601 stamped w/ "For Info Only" unless updated control drawings Review completed
FAY, C W Wisconsin Electric Power Co 84/07/20 SPESSARD, R L
Region 3, Office of Director 4pp 25987 064 24X
Fiche 50-266, 84/08/03, 8408100044

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408290565 Forwards Insp Repts 50-266/84-07 & 50-301/84-05 on 840601-0731 No noncompliance noted
SHAFER, W D Region 3, Office of Director 84/08/10 FAY, C W
Wisconsin Electric Power Co 2pp 26296 295 24X
Fiche 50-266, 84/08/10, 8408290565

--8408290570 Insp Repts 50-266/84-07 & 50-301/84-05 on 840601-0731 No noncompliance noted Major areas inspected operational safety, maint, surveillance, independent insp & plant trips
JACKIW, I N Region 3, Office of Director 84/08/09 9pp
26296 297 24X Fiche 50-266, 84/08/10, 8408290565

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co. of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408170198 Ack receipt of 840731 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-266/84-08 & 50-301/84-06
AXELSON, N L Region 3, Office of Director 84/08/13 CASSIDY, T J
Wisconsin Electric Power Co 1p 26118 093 24X
Fiche 50-266, 84/08/13, 8408170198

--8408170203 Forwards response to NRC 840711 ltr re noncompliance noted in IE Insp Repts 50-266/84-08 & 50-301/84-06 Encl withheld (ref 10CFR73 21)
CASSIDY, T J Wisconsin Electric Power Co 84/07/31 KEPPLER, J G
Region 3, Office of Director 1p 26118 094 24X
Fiche 50-266, 84/08/13, 8408170198

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Undersized Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408210550 Requests remittance of fee for 840706 application requesting relief from certain ASME Code requirements for second 10-yr insp interval Application subj to 840620 rev to 10CFR170 re fees Discussion of fees encl W/o encl
DIGGS, R M License Fee Management Branch 84/08/16 FAY, C W
Wisconsin Electric Power Co 1p 26195 262 24X
Fiche 50-266, 84/08/16, 8408210550

8408100055 IE Info Notice 84 66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50 000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50 000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408310229 "Semiannual Monitoring Rept, Jan-June 1984 "
* Wisconsin Electric Power Co 84/06/30 17pp 26322 165 24X
Fiche 50-266, 84/06/30, 8408310229

8408210232 Monthly operating repts for Jul 1984 W/840810 ltr
KRAUSE, C W , FAY, C W Wisconsin Electric Power Co 84/07/31 10pp
26184 297 24X Fiche 50-266, 84/07/31, 8408210232

V Operator Examinations

8408070030 Responds to 840326 request for periodic updates re progress made toward alleviating shortage of licensed operators Adequate number of licensed operators anticipated after scheduled reactor license exam in Dec 1984
BRITT, R W Wisconsin Electric Power Co 84/08/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 25950 036
24X Fiche 50 266, 84/08/02, 8408070030

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

8408230521 Advises that operator & senior operator licensing exams scheduled for 841204 Ofc Matl listed in encl "Ref Matl Requirements for Operator/Senior Operator Licensing Exams" requested by 841004
WALKER, R D Region 3, Office of Director 84/08/17 FAY, C W
Wisconsin Electric Power Co 9pp 26212 206 24X
Fiche 50-266, 84/08/17, 8408230521

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical emergency & fire protection plans

8408300208 Forwards FEMA findings on State of FL & associated local emergency plans re plant
DANCE,H C Region 2, Office of Director 84/06/05 WILGUS,W S
Florida Power Corp 1p 26307 044 24X Fiche 50-302,84/06/05,
8408300208

--8408300211 Approves State of FL & local plans & preparedness for alerting & protecting public in event of radiological emergency Approval conditional on verification of alert & notification per App 3 of NUREG-0654/FEMA-REP-1,Rev 1
SPECK,S W Federal Emergency Management Agency 84/02/15
DIRCKS,W J Office of the Executive Director for Operations 1p
26307 045 24X Fiche 50-302,84/06/05,8408300208

8408300417 Forwards summary of 840530 meeting w/utils & INPO re selected emergency preparedness issues Attendance list encl
O'REILLY,J P Region 2, Office of Director 84/06/08 WILGUS,W S
Florida Power Corp 4pp 26314 150 24X Fiche 50-302,84/06/08,
8408300417

8408270428 Forwards Insp Rept 50-302/84-18 on 840611-15 No violations or deviations identified
DANCE,H C Region 2, Office of Director 84/07/10 WILGUS,W S
Florida Power Corp 2pp 26257 019 24X Fiche 50-302,84/07/10,
8408270428

--8408270432 Insp Rept 50-302/84-18 on 840611-15 No violations or deviations identified Major area inspected emergency preparedness
KREH,J L , CLINE,W E Region 2, Office of Director 84/07/06
9pp 26257 021 24X Fiche 50-302,84/07/10,8408270428

8408270206 Ack receipt of 840705 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-302/84-13
LEWIS,R C Region 2, Office of Director 84/08/01 WILGUS,W S
Florida Power Corp 1p 26258 024 24X Fiche 50-302,84/08/01,
8408270206

--8408270211 Responds to NRC 840605 ltr re violations noted in Insp Rept 50-302/84-13 Corrective actions ltr identifying problem & emphasizing importance of use of child thyroid dose sent to dose assessment team members
BAYNARD,P Y Florida Power Corp 84/07/05 O'REILLY,J P Region 2, Office of Director 2pp 26259 025 24X Fiche 50-302,
84/08/01,8408270206

--8408270219 Forwards Insp Rept 50-302/84-13 on 840424-26 & notice of violation
DANCE,H C Region 2, Office of Director 84/06/05 WILGUS,W S
Florida Power Corp 2pp 26258 027 24X Fiche 50-302,84/08/01,
8408270206

--8408270224 Notice of violation from insp on 840424-26
* Region 2, Office of Director 84/06/05 1p 26258 029 24X
Fiche 50-302,84/08/01,8408270206

--8408270227 Insp Rept 50-302/84-13 on 840424-26 Violation noted failure to specify use of child thyroid in radioiodine dose assessment procedures
STODDART,P G , DECKER,T R , CLINE,W Region 2, Office of Director
84/05/30 11pp 26258 030 24X Fiche 50-302,84/08/01,
8408270206

8408200311 Advises that Emergency Operating Procedure OP-404, "DHR Sys," addresses concern raised at 840215 meeting re boron precipitation decay heat sys flow into reactor hot leg
WESTAFER,G R Florida Power Corp 84/08/08 RIVENBARK,G W
Operating Reactors Branch 4 1p 26133 019 24X
Fiche 50-302,84/08/08,8408200311

8408210054 Forwards Amend 71 to License DPR-72 & safety evaluation Amend revises format of physical security plan to be compatible w/NUREG-0908 & changes number of operational & administrative requirements
SILVER,H Operating Reactors Branch 4 84/08/13 WILGUS,W S,
Florida Power Corp 3pp 26195 163 24X Fiche 50-302,84/08/13,
8408210054

--8408210061 Amend 71 to License DPR-72,revising format of physical security plan to be compatible w/NUREG-0908 & changing number of operational & administrative requirements
STOLZ,J F Operating Reactors Branch 4 84/08/13 2pp
26195 166 24X Fiche 50-302,84/08/13,8408210054

--8408210066 Safety evaluation supporting Amend 71 to License DPR-72
* Office of Nuclear Reactor Regulation, Director 84/08/13, 3pp
26195 168 24X Fiche 50-302,84/08/13,8408210054

8408210346 Forwards "Crystal River Nuclear Power Plant Exercise " Few specific NUREG-0654/FEMA-REP-1,Rev 1, deficiencies observed during 840425 emergency exercise State of FL & Citrus & Levy counties participated
KRIMM,R W Federal Emergency Management Agency 84/08/13
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 26179 136 24X Fiche 50-302,84/08/13,
8408210346

--8408210354 "Crystal River Nuclear Power Plant Exercise "
* Federal Emergency Management Agency 84/05/11 42pp
26179 138 24X Fiche 50-302,84/08/13,8408210346

8408240155 Forwards description of how Rev 3 to Reg Guide 1 97, "Instrumentation for LWR Nuclear Power Plants to Assess Plant & Environs Condition During & Following Accident," per Suppl 1 to NUREG-0737 Mods will be implemented by 871231
BAYNARD,P Y Florida Power Corp 84/08/21 RIVENBARK,G W
Operating Reactors Branch 4 85pp 26228 001 24X
Fiche 50-302,84/08/21,8408240155

H General correspondence

8408230355 Responds to 840717 ltr expressing concern re effect of proposed nearby mining operations on plant Calculations indicate resulting ground motion would be small fraction of design values used in plant
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/08/16 SPIVEY,H L Affiliation Not Assigned 13pp 26236 079
24X Fiche 50-302,84/08/16,8408230355

--8408230360 Expresses concern re proposed mining near power plant Residents of Yankeetown fearful of addl damage to homes Requests clarification of NRC regulations concerning const of plant on top of Florida Aquifer
SPIVEY,H L Affiliation Not Assigned 84/07/17 DIRCKS,W
Office of the Executive Director for Operations 5pp 26236 093
24X Fiche 50-302,84/08/16,8408230355

P Operating license stage documents & correspondence

8408310062 Confirms 840501 telcon re 840606 meeting in Region II ofcs to discuss proposed responses to questions on QA program description submittal dtd 830610
LEWIS,R C Region 2, Office of Director 84/05/22 WILGUS,W S
Florida Power Corp 1p 26333 341 24X Fiche 50-302,84/05/22,
8408310062

8408080070 Forwards list of deficiencies noted in inservice testing program Advises that evaluation re 840412 request to test pumps quarterly rather than monthly,separate from overall program,continuing
RIVENBARK,G W Operating Reactors Branch 4 84/07/20 WILGUS,W S
Florida Power Corp 8pp 25981 088 24X Fiche 50-302,84/07/20,
8408080070

8408020010 Application for amend to License DPR-72,consisting of Tech Spec Change Request 103,Rev 2 re safety-related hydraulic snubbers & organizational structure Certificate of Svc encl
WESTAFER,G R Florida Power Corp 84/07/25 DENTON,H R Office of
Nuclear Reactor Regulation, Director 10pp 25883 060 24X
Fiche 50-302,84/07/25,8408020010

--8408020018 Proposed Tech Spec Change Request 103,Rev 2 re safety-related hydraulic snubbers & organizational structure
* Florida Power Corp 84/07/25 18pp 25883 070 24X
Fiche 50-302,84/07/25,8408020010

8408060199 Forwards updated response to Generic Ltr 83-28 & info required on plant-specific basis re post-trip review,for approval Three oversize drawings encl Aperture cards available in PDR
WESTAFER,G R Florida Power Corp 84/07/31 EISENHUT,D G Office
of Nuclear Reactor Regulation, Director 39pp 25927 025 24X
Fiche 50-302,84/07/31,8408060199

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408220203 Forwards corrected pages to Tech Spec 6 5 2 9 re administrative controls,submitted w/Amend 69 to License DPR-72
SILVER,H Operating Reactors Branch 4 84/08/07 WILGUS,W S
Florida Power Corp 4pp 26209 353 24X Fiche 50-302,84/08/07,
8408220203

8408200330 Provides excerpts from Missile Impact Analysis Rept E/L 20622 re turbine-driven emergency feedwater pump missile potential, in response to NUREG-0737, Item II E 1 1 Response satisfies Item 2b of 840501 SER
WESTAFER, G R Florida Power Corp 84/08/08 RIVENBARK, S W Operating Reactors Branch 4 2pp 26133 002 24X
Fiche 50-302, 84/08/08, 8408200330

8408200418 Summary of 840720 meeting w/util in Bethesda, MD re test results & other info concerning requested reactor head vent exemption
SILVER, H Operating Reactors Branch 4 84/08/08 Operating Reactors Branch 4 26pp 26141 135 24X Fiche 50-302, 84/08/08, 8408200418

8408210567 Forwards Amend 70 to License DPR-72 & safety evaluation Amend provides method for controlling personnel access to high radiation areas W/o encls
SILVER, H Operating Reactors Branch 4 84/08/10 WILGUS, W S
Florida Power Corp 2pp 26195 246 24X Fiche 50-302, 84/08/10, 8408210567

--8408210576 Amend 70 to License DPR-72, changing Tech Spec Apps A & B to allow cordoning & conspicuous lighting in lieu of lockable encl for access control to high radiation areas
STOLZ, J F Operating Reactors Branch 4 84/08/10 5pp
26195 248 24X Fiche 50-302, 84/08/10, 8408210567

--8408210582 Safety evaluation supporting Amend 70 to License DPR-72
* Office of Nuclear Reactor Regulation, Director 84/08/10 2pp
26195 253 24X Fiche 50-302, 84/08/10, 8408210567

8408210054 Forwards Amend 71 to License DPR-72 & safety evaluation Amend revises format of physical security plan to be compatible w/NUREG-0908 & changes number of operational & administrative requirements
SILVER, H Operating Reactors Branch 4 84/08/13 WILGUS, W S
Florida Power Corp 3pp 26195 163 24X Fiche, 50-302, 84/08/13, 8408210054

--8408210061 Amend 71 to License DPR-72, revising format of physical security plan to be compatible w/NUREG-0908 & changing number of operational & administrative requirements
STOLZ, J F Operating Reactors Branch 4 84/08/13 2pp
26195 166 24X Fiche 50-302, 84/08/13, 8408210054

--8408210066 Safety evaluation supporting Amend 71 to License DPR-72
* Office of Nuclear Reactor Regulation, Director 84/08/13 3pp
26195 168 24X Fiche 50-302, 84/08/13, 8408210054

8408200278 Requests extension of time to 841130 to respond to 840702 Generic Ltr 84-15, requesting data & commentary re improvement to & maint of diesel generator reliability
WESTAFER, G R Florida Power Corp 84/08/16 EISENHUT, D G
Division of Licensing 2pp 26133 021 24X Fiche 50-302, 84/08/16, 8408200278

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310406 Ack receipt of util 840501 comments re proposal to remove engineered safeguards activation signal from makeup tank isolation valve MUV-64 Removal will not cause unacceptable reactor coolant boron dilution prior to manual isolation
STOLZ, J F Operating Reactors Branch 4 84/08/22 WILGUS, W S
Florida Power Corp 3pp 26350 350 24X Fiche 50-302, 84/08/22, 8408310406

8408280154 Forwards WS O'Brien 840821 ltr transmitting notes of fourth quarterly progress meeting on 840802 re 316 study & corrected salinity figures for third quarterly rept to EPA
WESTAFER, G R Florida Power Corp 84/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 26275 046 24X
Fiche 50-302, 84/08/23, 8408280154

Q Inspection reports, IE Bulletins & correspondence

8408270428 Forwards Insp Rept 50-302/84-18 on 840611-15 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/07/10 WILGUS, W S
Florida Power Corp 2pp 26257 019 24X Fiche 50-302, 84/07/10, 8408270428

--8408270432 Insp Rept 50-302/84-18 on 840611-15 No violations or deviations identified Major area inspected emergency preparedness
KREH, J L , CLINE, W E Region 2, Office of Director 84/07/06
9pp 26257 021 24X Fiche 50-302, 84/07/10, 8408270428

8408280170 Submits revised response to IE Bulletin 84-02, "Failure of GE Type HFA Relays in Use in Class 1E Safety Sys " All HFA relays will be rebuilt or replaced prior to restart following Refuel 9
WESTAFER, G R Florida Power Corp 84/07/18 O'REILLY, J P Region 2, Office of Director 6pp 26259 010 24X Fiche 50-302, 84/07/18, 8408280170

8408280061 Ack receipt of 840710 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-302/84-17
DANCE, H C Region 2, Office of Director 84/07/19 WILGUS, W S
Florida Power Corp 1p 26282 016 24X Fiche 50-302, 84/07/19, 8408280061

--8408280069 Responds to NRC 840613 ltr re violations noted in Insp Rept 50-302/84-17 Corrective actions high radiation area sign relocated to personnel access hatch Radiation protection procedure will be revised, per 10CFR20 203(c)(3)
WESTAFER, G R Florida Power Corp 84/07/10 O'REILLY, J P
Region 2, Office of Director 2pp 26282 017 24X
Fiche 50-302, 84/07/19, 8408280061

--8408280072 Forwards Insp Rept 50-302/84-17 on 840515-18 & notice of violation
DANCE, H C Region 2, Office of Director 84/06/13 WILGUS, W S
Florida Power Corp 2pp 26282 019 24X Fiche 50-302, 84/07/19, 8408280061

--8408280077 Notice of violation from insp on 840515-18
* Region 2, Office of Director 84/06/13 1p 26282 021 24X
Fiche 50-302, 84/07/19, 8408280061

--8408280082 Insp Rept 50-302/84-17 on 840515-18 Violation noted failure to use proper locking device for high radiation area control
COLLINS, T R , JENKINS, O R Region 2, Office of Director
84/06/11 6pp 26282 022 24X Fiche 50-302, 84/07/19, 8408280061

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50 000, 84/07/27, 8407250229

8408270206 Ack receipt of 840705 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-302/84-13
LEWIS, R C Region 2, Office of Director 84/08/01 WILGUS, W S
Florida Power Corp 1p 26258 024 24X Fiche 50-302, 84/08/01, 8408270206

--8408270211 Responds to NRC 840605 ltr re violations noted in Insp Rept 50-302/84-13 Corrective actions ltr identifying problem & emphasizing importance of use of child thyroid dose sent to dose assessment team members
DAYNARD, P Y Florida Power Corp 84/07/05 O'REILLY, J P Region 2, Office of Director 2pp 26258 025 24X Fiche 50-302, 84/08/01, 8408270206

--8408270219 Forwards Insp Rept 50-302/84-13 on 840424-26 & notice of violation
DANCE, H C Region 2, Office of Director 84/06/05 WILGUS, W S
Florida Power Corp 2pp 26258 027 24X Fiche 50-302, 84/08/01, 8408270206

--8408270224 Notice of violation from insp on 840424-26
* Region 2, Office of Director 84/06/05 1p 26258 029 24X
Fiche 50-302, 84/08/01, 8408270206

--8408270227 Insp Rept 50-302/84-13 on 840424-26, Violation noted failure to specify use of child thyroid in radioiodine dose assessment procedures
STODDART, P G , DECKER, T R , CLINE, W Region 2, Office of Director
84/05/30 11pp 26258 030 24X Fiche 50-302, 84/08/01, 8408270206

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408160526 Monthly operating rept for Jul 1984 W/840808 ltr
GRAHAM,D , WESTAFER,G R Florida Power Corp 84/07/31
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 26108 027 24X Fiche 50-302,84/07/31,8408160526

S Reportable occurrences, LERs & related correspondence

8408160410 Special Rept 84-03 on 840424,false low & high pressure injection occurred when Channel 2 low pressure bistable inadvertently actuated Cause not stated Bistable replaced. Plant stabilized w/injection of borated water into RCS
WESTAFER,G R Florida Power Corp 84/07/23 O'REILLY,J P Region 2, Office of Director 3pp 26106 087, 24X Fiche 50-302,84/07/23, 8408160410

8408060306 LER 84-014-00 on 840625 & 0322,auxiliary bldg exhaust fans taken out of svc in order to perform mods to ventilation sys dampers Policy memo issued stating Tech Spec 3.0.3 should not be entered for maint w/o permission W/840725 ltr
BANDHAUER,W K , WESTAFER,G R Florida Power Corp 84/07/25 4pp 25936 069 24X Fiche 50-302,84/07/25,8408060306

8408080189 NPDES noncompliance notification thermograph time data collection,from Dec 1983 - 840615,terminated,per plan of study & on 840726,sample of Discharge 006 could not be obtained for pH
WESTAFER,G R Florida Power Corp 84/08/03 DENTON,H R Office of Nuclear Reactor Regulation, Director 10pp 25960 247 24X Fiche 50-302,84/08/03,8408080189

8408160247 LER 84-010-01 on 840426,non-nuclear instrumentation power supply Y failed,causing erroneous signals to be sent to integrated control sys Caused by capacitor failure Capacitor replaced W/840808 ltr
BANDHAUER,W K , WESTAFER,G R Florida Power Corp 84/08/08 6pp 26106 202 24X Fiche 50-302,84/08/08,8408160247

8408160238 LER 84-004-01 on 840228,six manual isolation valves closed Caused by personnel error & inadequacies in mod approval record All six valves opened Process of sys turnover to be upgraded W/840808 ltr
WILSON,K R , WESTAFER,G R Florida Power Corp 84/08/09 4pp 26106 210 24X Fiche 50-302,84/08/09,8408160238

8408200346 LER 84-015-00 on 840713,drain petcock on air filter in emergency diesel generator B air start sys failed,resulting in start of diesel generator On 840404,similar failure occurred W/840809 ltr
BANDHAUER,W K , WESTAFER,G R Florida Power Corp 84/08/09 3pp 26139 334 24X Fiche 50-302,84/08/09,8408200346

8408230424 LER 84-016-00 on 840720,quality programs audit determined that alarm/trip setpoint for fuel storage pool area gaseous activity process monitor RM-A4 exceeded Tech Spec limit Caused by not following action requirements W/840813 ltr
BANDHAUER,W K , WESTAFER,G R Florida Power Corp 84/08/13 4pp 26213 040 24X Fiche 50-302,84/08/13,8408230424

8408230430 LER 84-016-00 on 840720,quality programs audit determined that alarm/trip setpoint for fuel storage pool area gaseous activity process monitor RM-A4 exceeded Tech Spec limit W/840815 ltr
BANDHAUER,W K , WESTAFER,G R Florida Power Corp 84/08/15 4pp 26213 064 24X Fiche 50-302,84/08/15,8408230430

8408300341 LER 83-043/03X-1 on 831003,fault light on emergency feedwater (EFW) ultrasonic flow indicator for steam generator B (FW-313-FI) discovered illuminated Caused by void in EFW line due to check valve leakage W/840824 ltr
THOMPSON,R H , WESTAFER,G R Florida Power Corp 84/08/24 3pp 26308 337 24X Fiche 50-302,84/08/24,8408300341

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8408070239 Rev 7 to Emergency Plan Implementing Procedure EPIP 110-1, "Zion Station - Nuclear Accident Reporting Sys Reporting Procedures " W/840719 transmittal memo
NYKIRK,J Commonwealth Edison Co 84/07/19 10pp 25948 353 24X Fiche 50-295,84/07/19,8408070239

8408070240 Rev 3 to Emergency Plan Implementing Procedure EPIP 100-1, "Acting Station Director " W/840719 transmittal memo
NYKIRK,J Commonwealth Edison Co 84/07/26 16pp 25949 001 24X Fiche 50-295,84/07/26,8408070240

8408010165 Forwards "Safe Shutdown Capability Reassessment & Proposed Mods, 10CFR50,App R," for approval Exemption from schedular requirements of 10CFR50 48(c)(4) until 851231 requested Related tables & notes encl
CASCARANO,R N Commonwealth Edison Co 84/07/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 28pp 25874 001. 24X Fiche 50-295,84/07/27,8408010165

--8408010171 "Safe Shutdown Capability Reassessment & Proposed Mods, 10CFR50,App R "
* Commonwealth Edison Co 84/07/31 499pp 25874 029 24X Fiche 50-295,84/07/27,8408010165

8408170398 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure BZP 600-A3, "Station Directory "
* Commonwealth Edison Co 84/07/31 Record Services Branch (Document Control Desk) 2pp 26134 171 24X Fiche 50-295, 84/07/31,8408170398

--8408170399 Public version of Rev 3 to Emergency Plan Implementing Procedure BZP 600-A3, "Station Directory " W/JM Felton 840809 release memo
* Commonwealth Edison Co 84/07/31 10pp 26134 172. 24X Fiche 50-295,84/07/31,8408170398

8408100060 Determines that,based on evaluation,State of WI & local plans for radiological emergencies adequate
SPECK,S W Federal Emergency Management Agency 84/08/02.
DIRCKS,W J Office of the Executive Director for Operations 1p 25989 052 24X Fiche 50-295,84/08/02,8408100060

8408140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 84/08/03 Region 3, Office of Director 1p 26044 252 24X Fiche 50-000, 84/08/03, 8408140139

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO, C J Region 3, Office of Director 84/08/07 REED, C Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000, 84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR, D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000, 84/08/07, 8408130401

8408140428 Rev 3 to Emergency Plan Implementing Procedure EPIP 350-2, "Calculation of Post-Accident Noble Gas Release Rates Via Vent Stacks & Quick Estimate of Offsite Dose Using SPING Monitor RIA-PR49 Readings " W/8408081 transmittal memo
KASSNER, G , PLIML, G Commonwealth Edison Co 84/08/08 13pp 26051 170 24X Fiche 50-295, 84/08/08, 8408140428

8408200345 Advises that 840803 Rev 13 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/08/14 FARRAR, D L Commonwealth Edison Co 2pp 26132 357 24X Fiche 50-295, 84/08/14, 8408200345

8408310168 Rev 3 to Emergency Plan Implementing Procedure EPIP 550-6, "Monthly Radiological Emergency Equipment Tests & Checks " W/transmittal & receipt form
GRAESSER, K L , PLIML, G Commonwealth Edison Co 84/08/15 6pp 26319 239 24X Fiche 50-295, 84/08/15, 8408310168

8408270309 Informs of FEMA approval of State of WI emergency response & local plan Adequacy of public alerting & notification sys must be verified per FEMA/NRC joint criteria in App 3 of NUREG-0654/FEMA-REP-1
PAPERIELLO, C J Region 3, Office of Director 84/08/22 REED, C Commonwealth Edison Co 2pp 26239 157 24X Fiche 50-295, 84/08/22, 8408270309

P Operating license stage documents & correspondence

8408280360 Ack receipt of 840710 ltr re author criticism of NRC present rules & practices Reponse to NRC seven stages of discussion listed Past tests should be reviewed & leak rate be retested Related info encl
REYTBLATT, Z V Warren Wilson College, Swannanoa, NC 84/07/22
ROSS, D F Office of Nuclear Regulatory Research, Director 8pp 26293 001 24X Fiche 50-000, 84/07/22, 8408280360

--8408280373 Requests documents re RFP RS-RES-84-101, submitted on 840110 Author 840220 ltr to EM Gogol, Citizens Against Nuclear Power encl
REYTBLATT, Z V Ertran, Inc 84/03/02 Division of Rules and Records 6pp 26293 012 24X Fiche 50-000, 84/07/22, 8408280360

8408060335 Notification of 840802 meeting w/util in Bethesda, MD to discuss insights from review of probabilistic safety study
NORRIS, J A Operating Reactors Branch 1 84/07/27 VARGA, S A Operating Reactors Branch 1 3pp 25937 354 24X
Fiche 50-295, 84/07/27, 8408060335

8408130047 Notification of cancellation of 840802 meeting w/util in Bethesda, MD to discuss NRC review of probabilistic safety study
NORRIS, J A Operating Reactors Branch 1 84/07/27 VARGA, S A Operating Reactors Branch 1 2pp 26034 360 24X
Fiche 50-295, 84/07/27, 8408130047

8408130022 Ack receipt of 840605 petition for emergency relief re adequacy of containment leak rate testing NRC conducting insp on allegations Util informed that Unit 1 not in compliance w/10CFR50, App J
DENTON, H R Office of Nuclear Reactor Regulation, Director 84/07/30 GOGAL, E M Citizens Against Nuclear Power 9pp 26036 330 24X Fiche 50-295, 84/07/30, 8408130022

8408090139 Advises that Class III fee appropriate for review of 830727 submittal of "Comm Ed Topical Rept on Benchmark of PWR Nuclear Design Methods " Exemption from Class I fee granted W/o stated encls
MILLER, W O License Fee Management Branch 84/08/03 FARRAR, D L Commonwealth Edison Co 2pp 25991, 205 24X Fiche 50-295, 84/08/03, 8408090139

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X
Fiche 50-000, 84/08/06, 8408160345

8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 1, "Sequoyah Nuclear Plant Containment Analysis," for Meeting 38 Rept inconsistent w/four encl repts previously sent
FONTANA, M H Technology for Energy Corp 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26234 001 24X Fiche 50-000, 84/08/07, 8408230097

--8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants," technical rept
* Industry Degraded Core Rulemaking Program * Fauske & Associates, Inc FAI/84-9 DRFT 84/07/31 114pp 26234 231 24X Fiche 50-000, 84/08/07, 8408230097

--8408230116 Draft "Zion Nuclear Generating Station Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/08/07 119pp 26234 339 24X Fiche 50-000, 84/08/07, 8408230097

8408170033 Notification of 840815 meeting w/util in Bethesda, MD to discuss proposed safety mgt program & integrated living schedule concepts
NORRIS, J A Operating Reactors Branch 1 84/08/08 VARGA, S A Operating Reactors Branch 1 2pp 26134 361 24X
Fiche 50-295, 84/08/08, 8408170033

8408210592 Requests remittance of fee for 840627 application requesting extension of 10CFR50 49(g) schedular requirements for environ qualification of electrical equipment Application subj to 840620 rev to 10CFR170 re fees
DIGGS, R M License Fee Management Branch 84/08/16 FARRAR, D L Commonwealth Edison Co 1p 26195 261 24X Fiche 50-304, 84/08/16, 8408210592

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408280119 Forwards fee for review of util topical rept on benchmark of PWR nuclear design methods in connection w/reloads at facility, per 840803 ltr
ALEXANDER, G L Commonwealth Edison Co 84/08/20 MILLER, W O License Fee Management Branch 1p 26261 300 24X
Fiche 50-295, 84/08/20, 8408280119

8408270372 Forwards response to NRC request for clarification of svc water success criteria Adequacy of two svc water pumps to handle safe shutdown components reconfirmed by util corporate engineering dept
CABCARAND, R N Commonwealth Edison Co 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26240 252 24X Fiche 50-295, 84/08/21, 8408270372

8408280286 Summary of 840815 meeting w/util re integrated living schedule Attendee list, agenda & viewgraphs encl W/o encls
NORRIS, J Operating Reactors Branch 1 84/08/21 Operating Reactors Branch 1 2pp 26294 087 24X Fiche 50-295, 84/08/21, 8408280286

8408310115 Forwards fee for 840627 application for environ qualification of electrical equipment schedular extension
CABCARAND, R N Commonwealth Edison Co 84/08/22 DIGGS, R M License Fee Management Branch 1p 26382 111 24X
Fiche 50-304, 84/08/22, 8408310115

8408310200 Discusses PRA of proposed mod to auxiliary feedwater sys, per NUREG-0737, Item II E 1 1 Efforts on mod stopped as result of PRA conclusion that installation of addl check valves will not significantly improve availability of sys
CABCARAND, R N Commonwealth Edison Co 84/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26318 308 24X Fiche 50-295, 84/08/23, 8408310200

8408310202 Forwards addl info re inadequate core cooling instrumentation sys, in response to NRC 840530 request Meeting suggested in Bethesda, MD to resolve any questions still outstanding
CASCARANO, R N Commonwealth Edison Co 84/08/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 26318 312
24X Fiche 50-295, 84/08/24, 8408310202

O Inspection reports, IE Bulletins & correspondence

8408080485 Forwards IE Insp Repts 50-295/84-08 & 50-304/84-08 on 840531, 0604-08, 12-13 & 0702 & notice of violation
PAPERIELLO, C J Region 3, Office of Director 84/07/18 REED, C
Commonwealth Edison Co 2pp 25975 188 24X Fiche 50-295, 84/07/18, 8408080485

--8408080488 Notice of violation from insp on 840531, 0604-08, 12-13 & 0702
PAPERIELLO, C J Region 3, Office of Director 84/07/18 1p
25975 190 24X Fiche 50-295, 84/07/18, 8408080485

--8408080496 IE Insp Repts 50-295/84-08 & 50-304/84-08 on 840531, 0604-08, 12-13 & 0702 Violations noted Unauthorized transfer of Am-241 sources to Byron Station
LOVENDALE, P C , NICHOLSON, N A , GREGER, L R Region 3, Office of Director 84/07/17 11pp 25975 191 24X Fiche 50-295, 84/07/18, 8408080485

8408090169 Forwards IE Insp Repts 50-295/84-07 & 50-304/84-07 on 840512-0629 No noncompliance noted
SHAFER, W D Region 3, Office of Director 84/07/20 REED, C
Commonwealth Edison Co 2pp 25995 015 24X Fiche 50-295, 84/07/20, 8408090169

--8408090177 IE Insp Repts 50-295/84-07 & 50-304/84-07 on 840512-0629 No noncompliance or deviations noted Major areas inspected maint on nuclear instrumentation, operational safety & ESF walkdown, surveillance & LER followup
WRIGHT, G C Region 3, Office of Director 84/07/19 8pp
25995 017 24X Fiche 50-295, 84/07/20, 8408090169

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC
NORELIUS, C E Region 3, Office of Director 84/08/03 REED, C
Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000, 84/08/03, 8408070066

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26041 090 24X Fiche 50-000, 84/08/08, 8408140344

8408150098 Supplx 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26067 053 24X
Fiche 50-000, 84/08/08, 8408150098

8408200331 Supplx response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26132 318 24X
Fiche 50-000, 84/08/08, 8408200331

8408170263 Forwards SALP Repts 50-295/84-06 & 50-304/84-06 for Jan 1983 - Apr 1984
KEPPLER, J G Region 3, Office of Director 84/08/09 REED, C
Commonwealth Edison Co 2pp 26118 008 24X Fiche 50-295, 84/08/09, 8408170263

--8408170269 SALP Repts 50-295/84-06 & 50-304/84-06 for Jan 1983 - Apr 1984 Licensing activities assigned Category I rating
* Region 3, Office of Director 84/08/09 31pp 26118 010 24X
Fiche 50-295, 84/08/09, 8408170263

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408220086 Supplx 840626 response to 840511 request for addl info re inservice insp program for second 10-yr interval Addl relief requests & additions to program encl
CASCARANO, R N Commonwealth Edison Co 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 37pp 26193 252
24X Fiche 50-295, 84/08/14, 8408220086

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408270087 Supplx 840607 ltr re check valves in water cooling sys of diesel generators, per IE Bulletin 83-03 Valve insp on 840515 revealed no mechanical problems
ALEXANDER, G L Commonwealth Edison Co 84/08/16 KEPPLER, J G
Region 3, Office of Director 2pp 26247 355 24X
Fiche 50-295, 84/08/16, 8408270087

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408300136 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1984 " W/840803 ltr
GRAESSER, K L Commonwealth Edison Co 84/06/30 KEPPLER, J G
Region 3, Office of Director 47pp 26308 029 24X
Fiche 50-295, 84/06/30, 8408300136

8408160122 Monthly operating repts for Jul 1984 W/840807 ltr
AUSTIN,G , GRAESSER,K L Commonwealth Edison Co 84/07/31 13pp
2610B 117 24X Fiche 50-295,84/07/31,8408160122

S Reportable occurrences, LERs & related correspondence

8408060290 LER 84-014-00 on 840626,five snubbers found inoperable
Caused by poor seal conditions that allowed fluid to leak
out Snubbers overhauled,tested & reinstalled W/840726 ltr
PETROWSKI,S E , GRAESSER,K L Commonwealth Edison Co 84/07/26
3pp 25936 086 24X Fiche 50-304,84/07/26,8408060290

8408090047 LER 84-017-00 on 840704,nuclear instrumentation sys channel
41 remained out of svc for test w/overpower & overtemp delta
T bistables tripped Caused by personnel error Personnel
counseled W/840803 ltr
ROHDE,J E , GRAESSER,K L Commonwealth Edison Co 84/08/03 3pp
25992 133 24X Fiche 50-304,84/08/03,8408090047

8408090326 LER 84-015-00 on 840711,MSIV loop D discovered to have no
closing side hydraulic pressure Caused by internal leakage
of Keane solenoids during shutdown New breaker installed &
independent operation returned W/840803 ltr
WOODS,J , GRAESSER,K L Commonwealth Edison Co 84/08/03 3pp
25994 066 24X Fiche 50-304,84/08/03,8408090326

8408130456 LER 84-016-00 on 840709,reactor tripped from hot standby,
Mode 2 Caused by instrument inverter 212 failure due to
slave output transformer short circuit Damaged transformers
replaced W/840806 ltr
BAILEY,M W , GRAESSER,K L Commonwealth Edison Co 84/08/06 3pp
26031 360 24X Fiche 50-304,84/08/06,8408130456

8408130465 LER 84-018-00 on 840708,turbine tripped & steam & feed flow
channels needed to be calibr Bistables lit due to turbine
trip Operating supervisor reinstructed to use proper
procedure change format W/840807 ltr
BREEN,W , GRAESSER,K L Commonwealth Edison Co 84/08/07 3pp
26010.189 24X Fiche 50-304,84/08/07,8408130465

8408200547 LER 83-044-01 on 831111,during safeguards testing,valve
2MOV-CS0006 failed to stroke when actuated,placing plant in
degraded mode Caused by failed main drive sleeve in
Limitorque operator Operator rebuilt W/840813 ltr
PETROWSKI,S , GRAESSER,K L Commonwealth Edison Co 84/08/13 3pp
26138 204 24X Fiche 50-304,84/08/13,8408200547

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for
Licensed Operators,Senior Operators & Senior Operators
(Limited)," in response to NUREG-0737,Item I A 3 1
MARSHALL,J G Commonwealth Edison Co 84/08/07 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 26051 240
24X Fiche 50-000,84/08/07,8408140372

--8408140389 "Requalification Program for Licensed Operators,Senior
Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X
Fiche.50-000,84/08/07,8408140372

8408140426 Provides address for transmitting all operator licensing
correspondence to Region III ofc;except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan,
Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000,
84/08/10,8408140426

DCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

Security, medical, emergency & fire protection plans

8408060422 Forwards request for addl info re 831228 procedures
generation package for emergency operating procedures
Response requested within 30 days of ltr receipt unless
schedule for response provided
VARGA,S A Operating Reactors Branch 1 84/07/25 GIESLER,C W
Wisconsin Public Service Corp 2pp 25937 338 24X
Fiche.50-305,84/07/25,8408060422

8408070292 Forwards revised index to radiological emergency response
plan implementing procedures
HINTZ,D C Wisconsin Public Service Corp 84/07/31 Record
Services Branch (Document Control Desk) 1p 25948 005 24X
Fiche 50-305,84/07/31,8408070292

-8408070296 Revised emergency plan implementing procedure index
* Wisconsin Public Service Corp 84/07/10 9pp 25948 006. 24X
Fiche 50-305,84/07/31,8408070292.

8408070275 Forwards addl info on safety parameter display sys in
response to 840326 request & suppl to SAR Sys scheduled for
implementation by end of Spring 1985 refueling outage
Rev 1-A to WCAP-7819 & WCAP-7685A encl
HINTZ,D C Washington Public Power Supply System 84/08/01
EISENHUT,D G Division of Licensing 25pp 25948 123 24X
Fiche 50-305,84/08/01,8408070275

--8408070282 Rev 1-A to 'Nuclear Instrumentation Sys Isolation
Amplifier "
LIPCHAK,J B , BARTHOLOMEW,R Westinghouse Electric Corp
WCAP-7819 R01A 75/04/30 33pp 25948 149 24X
Fiche 50-305,84/08/01,8408070275

--8408070288 "Test Rept on Isolation Amplifiers "
GARBER,I Westinghouse Electric Corp WCAP-7685-A 75/05/31
10pp 25948 183 24X Fiche 50-305,84/08/01,8408070275

8408100019 Revised radiological emergency response plan implementing
procedures,including EP-AD-1, "Plant Emergency
Organization" & EP-OP-1, "Control Room Emergency
Organization " W/840806 ltr
HINTZ,D C Wisconsin Public Service Corp 84/08/06 18pp
25989 286 24X Fiche 50-305,84/08/06,8408100019

8408240428 Forwards Insp Rept 50-305/84-07 on 840709-13 & notice of
violation Licensee should address emergency preparedness
weaknesses identified in App B Shift staffing also
questioned W/o notice of violation & App B
HIND,J A Region 3, Office of Director 84/08/06 GIESLER,C W
Wisconsin Public Service Corp 3pp 26237 121 24X
Fiche 50-305,84/08/06,8408240428

--8408240429 Emergency Preparedness Insp Rept 50-305/84-07 on 840709-1
Noncompliance noted failure to perform monthly
communications tests
SNELL,W O , GLOERSEN,W B , PHILLIPS,M P Region 3, Office of
Director 84/08/06 13pp 2623? 124 24X Fiche 50-305,84/08/06,
8408240428

8408280144 Advises that rev to procedures generation program describing
method of developing & upgrading emergency procedures will
be submitted by 841001 Training program on upgraded
emergency operating procedures being finalized
HINTZ,D C Wisconsin Public Service Corp 84/08/23 VARGA,S A
Operating Reactors Branch 1 1p 26275 187 24X
Fiche 50-305,84/08/23,8408280144

K Utility Final Safety Analysis Report (FSAR) & amends

8407260161 Forwards revised pages to updated FSAR for Kewaunee Nuclear
Power Plant Pages revised due to minor typographical errors
& editorial or administrative comments Drawings revised
due to completion of plant design
GIESLER,C W Wisconsin Public Service Corp 84/07/20 DENTON,H R
Office of Nuclear Reactor Regulation, Director 8pp 25823 001
24X Fiche 50-305,84/07/20,8407260161

--8407260166 Revised pages to updated FSAR for Kewaunee Nuclear Power
Plant
* Wisconsin Public Service Corp 84/07/20 300pp 25823 009
24X Fiche 50-305,84/07/20,8407260161

P Operating license stage documents & correspondence

8408010208 Notification of 840731-0801 meetings w/util at site to
discuss radiological ETE
NEIGHBORS,D Operating Reactors Branch 1 84/07/20 VARGA,S A
Operating Reactors Branch 1 3pp 25873 269 24X
Fiche 50-305,84/07/20,8408010208

8408060407 Notification of location & time change for 840731-0801
meetings w/util in Green Bay,WI to discuss radiological ETE
Meeting originally scheduled at site
NEIGHBORS,D Operating Reactors Branch 1 84/07/20 VARGA,S A
Operating Reactors Branch 1 1p 25951 168 24X
Fiche 50-305,84/07/20,8408060407

8408020073 Application for amend to License DPR-43,consisting of
Proposed Amend 62,revising Tech Specs for consistency w/new
reporting requirements of 10CFR50 73, "LER Sys "
GIESLER,C W Wisconsin Public Service Corp 84/07/27 DENTON,H R
Office of Nuclear Reactor Regulation, Director 12pp 25891 335,
24X Fiche 50-305,84/07/27,8408020073

--8408020078 Proposed Tech Specs for consistency w/new reporting
requirements of 10CFR50.73, "LER Sys "
* Wisconsin Public Service Corp 84/07/27 24pp 25891 347
24X Fiche 50-305,84/07/27,8408020073

8408060093 Forwards updated Tech Specs 4 2-1 & 4 5-2 for Amend 55 to License DPR-43 re ASME Code class inservice insp & testing Previous pages inadvertently issued as draft
SAUER,D W Wisconsin Public Service Corp 84/07/27 NEIGHBORS,D NRC - No Detailed Affiliation Given 2pp 25925 315 24X Fiche 50-305,84/07/27,8408060093

8408060212 Requests fee for 840517 application transmitting safety evaluation of RHR sys autoclosure feature within 15 days of receipt of ltr
MILLER,W O License Fee Management Branch 84/07/27 GIESLER,C W Wisconsin Public Service Corp 1p 25950 255 24X Fiche 50-305 84/07/27,8408060212

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06 HOLAHAN,G M Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 50-000,84/08/06,8408090317

8408100078 Forwards review fee for proposed removal of RHR autoclosure feature
HINTZ,D C Wisconsin Public Service Corp 84/08/06 MILLER,W O License Fee Management Branch 1p 25990 196 24X Fiche 50-305,84/08/06,8408100078

8408130372 Ack receipt of 840611 QA program Paragraph 3 of 10CFR50 54 requires listed changes when QA program description reduces prior commitments Revised forwarding ltr which fully complies w/requirement, requested within 30 days
SPESSARD,R L Region 3, Office of Director 84/08/07 GIESLER,C W Wisconsin Public Service Corp 2pp 26010 361 24X Fiche 50-305,84/08/07,8408130372

8408160482 Summary of 840724 meeting w/Westinghouse Owners Group re upper plenum injection for two loop plants
DIANNI,D C Operating Reactors Branch 3 84/08/09 Operating Reactors Branch 3 4pp 26108 327 24X Fiche 50-000,84/08/09, 8408160482

8408220284 Discusses rod position indication for shutdown modes, per NRC 830324 concerns Surveillance procedure performed each shift verifies rod position indication sys meets appropriate acceptance criteria
HINTZ,D C Wisconsin Public Service Corp 84/08/15 VARGA,S A Operating Reactors Branch 1 2pp 26189 315 24X Fiche 50-305,84/08/15,8408220284

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275

8408240199 Forwards "Kewaunee Nuclear Power Plant 1984 Integrated Leak Rate Test & 1981-1984 Local Leak Rate Tests," summary rept
HINTZ,D C Wisconsin Public Service Corp 84/08/20 VARGA,S A Operating Reactors Branch 1 2pp 26227 231 24X Fiche 50-305,84/08/20,8408240199

--8408240205 "Kewaunee Nuclear Power Plant 1984 Integrated Leak Rate Test & 1981-1984 Local Leak Rate Tests," summary rept
* Wisconsin Public Service Corp 84/08/20 90pp 26227 233 24X Fiche 50-305,84/08/20,8408240199

8408280475 Confirms commitments of 840731 meeting re implementation of radiological effluent Tech Specs (RETS) Tech Specs to be implemented & RETS format followed as closely as possible Separation of RETS & existing specs will minimize confusion
HINTZ,D C Wisconsin Public Service Corp 84/08/21 VARGA,S A Operating Reactors Branch 1 2pp 26282 100 24X Fiche 50-305,84/08/21,8408280475

8408310122 Application for amend to License DPR-43, consisting of proposed Amend 60a to Tech Specs, correcting inadvertent deletion in Amend 48 & indicating organizational changes
GIESLER,C W Wisconsin Public Service Corp 84/08/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26322 245 24X Fiche 50-305,84/08/21,8408310122

--8408310126 Proposed Tech Specs correcting inadvertent deletion in Amend 48 & indicating organizational changes
* Wisconsin Public Service Corp 84/08/21 8pp 26322 249 24X Fiche 50-305,84/08/21,8408310122

8408310374 Requests assistance in review of util 840727 proposed amend to OL revising Tech Specs to reflect 10CFR50 73, "LER Sys " SRP & STS should be used as guidance SER & SALP input due by 841001 W/o encl
EISENHUT,D G Office of Nuclear Reactor Regulation, Director 84/08/27 NORELIUS,C E Division of Project & Resident Programs 2pp 26350 325 24X Fiche 50-305,84/08/27,8408310374

8408310451 Advises that MB Fairtile assigned as NRC project manager for facility, effective 840823 Telephone number listed
VARGA,S A Operating Reactors Branch 1 84/08/28 GIESLER,C W Wisconsin Public Service Corp 1p 26350 126 24X Fiche 50-305,84/08/28,8408310451

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408060093 Forwards updated Tech Specs 4 2-1 & 4 5-2 for Amend 55 to License DPR-43 re ASME Code class inservice insp & testing Previous pages inadvertently issued as draft
SAUER,D W Wisconsin Public Service Corp 84/07/27 NEIGHBORS,D NRC - No Detailed Affiliation Given 2pp 25925 315 24X Fiche 50-305,84/07/27,8408060093

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408240428 Forwards Insp Rept 50-305/84-07 on 840709-13 & notice of violation Licensee should address emergency preparedness weaknesses identified in App B Shift staffing also questioned W/o notice of violation & App B
HIND,J A Region 3, Office of Director 84/08/06 GIESLER,C W Wisconsin Public Service Corp 3pp 26237 121 24X Fiche 50-305,84/08/06,8408240428

--8408240429 Emergency Preparedness Insp Rept 50-305/84-07 on 840709-13 Noncompliance noted failure to perform monthly communictions tests
SNELL,W G , GLOERSEN,W D , PHILLIPS,M P Region 3, Office of Director 84/08/06 13pp 26237 124 24X Fiche 50-305,84/08/06, 8408240428

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070374 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070374

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408300192 Forwards Insp Rept 50-305/84-11 on 840801-03 No noncompliance noted
WALKER, R D Region 3, Office of Director 84/08/14 GIESLER, C W
Wisconsin Public Service Corp 2pp 26307 355 24X
Fiche 50-305, 84/08/14, 8408300192

--8408300199 Insp Rept 50-305/84-11 on 840801-03 No noncompliance or deviations noted Major areas inspected previous insp findings
CHOULES, N C , HAWKINS, F C Region 3, Office of Director
84/08/13 4pp 26307 357 24X Fiche 50-305, 84/08/14, 8408300192

8408100038 IE Info Notice 84-64, "BUR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65 Undervated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408310288 Forwards Insp Rept 50-305/84-10 on 840802-03 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/08/17
GIESLER, C W Wisconsin Public Service Corp 2pp 26333 290 24X
Fiche 50-305, 84/08/17, 8408310288

--8408310296 Insp Rept 50-305/84-10 on 840802-03 No noncompliance or deviation identified Major areas inspected implementation of 10CFR20 & 61 & disposal of low level radwaste, including mgt controls & waste form
ROZAK, S , SCHUMACHER, M C Region 3, Office of Director 84/08/17
4pp 26333 292 24X Fiche 50-305, 84/08/17, 8408310288

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

Periodic operating reports & related correspondence

8408160211 Monthly operating rept for Jul 1984 W/840809 ltr
RUITER, G H , HINTZ, D C Wisconsin Public Service Corp 84/07/31
5pp 26106 262 24X Fiche 50-305, 84/07/31, 8408160211

I Reportable occurrences, LERs & related correspondence

8408060244 LER 84-012-00 on 840628, both trains of auxiliary bldg special vent sys inadvertently started during performance of I&C procedure Caused by personnel error Both trains secured & realigned for normal operation W/840727 ltr
BERNHOFT, S , HINTZ, D C Wisconsin Public Service Corp 84/07/27
1p 25935 147 24X Fiche 50-305 84/07/27, 8408060241

8408080510 LER 84-013-00 on 840702, train B of auxiliary bldg special ventilation sys ran for no apparent reason Caused by burnt out Johnson solenoid valve coil in closed position Design change initiated to replace valves W/840801 ltr
BERNHOFT, S , HINTZ, D C Wisconsin Public Service Corp 84/08/01
3pp 25979 259 24X Fiche 50-305, 84/08/01, 8408080510

8408080033 LER 84-014-00 on 840703, loss of power on instrument bus IV resulted in partial loss of instrumentation, alarms & level control problems on steam generators Caused by loose connection of ac output breaker 52 connector W/840802 ltr
MARCHI, M , HINTZ, D C Wisconsin Public Service Corp 84/08/02
3pp 25962 151 24X Fiche 50-305, 84/08/02, 8408080033

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION UNIT 2

F Security, medical, emergency & fire protection plans

8408200484 Grants exemption from certain requirements of 10CFR50, App R, Subsections III G 2 * III O re reactor coolant pump lube oil collection sys Commitment to protect redundant cabling expected to be completed by 841231
MILLER, J R Operating Reactors Branch 3 84/07/31 MUSOLF, D M
Northern States Power Co 2pp 26143 331 24X
Fiche 50-282, 84/07/31, 8408200484

--8408200489 Exemption from certain requirements of 10CFR50, App R, Subsections III G 2 & III O re Fire Areas 1 & 71 & reactor coolant pump lube oil sys
EISENHUT, D G Division of Licensing 84/07/31 Northern States Power Co 7pp 26143 333 24X Fiche 50 282, 84/07/31, 8408200484

8408300176 Forwards Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan " Rev includes changes resulting from annual internal review, update & certification of emergency plans & agreements
FEY, F L Northern States Power Co 84/08/02 Region 3, Office of Director 4pp 26302 106 24X Fiche 50-000, 84/08/02, 8408300176

--8408300180 Rev 7 to "Northern States Power Co Corporate Nuclear Emergency Plan "
HUDSON, G , FEY, F L , LARSON, C E Northern States Power Co
84/08/02 116pp 26302 110 24X Fiche 50-000, 84/08/02, 8408300176

--8408300183 Revised "Radiation Environ Monitoring Plan "
CLARK, B W , FEY, F L Northern States Power Co 84/02/29 14pp
26302 226 24X Fiche 50-000, 84/08/02, 8408300176

8408100029 Forwards IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 & notice of noncompliance Notice of noncompliance withheld (ref 10CFR73 21)
AXELSON, W L Region 3, Office of Director 84/08/03 LARSON, C E
Northern States Power Co 2pp 25987 068 24X
Fiche 50-282, 84/08/03, 8408100029

--8408100037 IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 Noncompliance noted failure to provide effective barrier in portion of protected area perimeter Details withheld (ref 10CFR73 21)
KNICELEY, J R Region 3, Office of Director 84/08/03 2pp
25987 070 24X Fiche 50-282, 84/08/03, 8408100029

8408310173 Ack receipt of 840625 Rev 4 to emergency plan Next rev should include description of onsite & offsite environs & radiological monitoring drills & monthly communications check
PAPERIELLO, C J Region 3, Office of Director 84/08/27
LARSON, C E Northern States Power Co 2pp 26319 141 24X
Fiche 50-282, 84/08/27, 8408310173

P Operating license stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140482 Summary of 840724 meeting w/Westinghouse Owners Group re upper plenum injection for two loop plants
DIFANNI, D C Operating Reactors Branch 3 84/08/09 Operating Reactors Branch 3 4pp 26108 327 24X Fiche 50-000, 84/08/09, 8408160482

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070189 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/84-04 & 50-306/84-04 Corrective actions re sus blocking & tagging appropriate
SHAFER, W D Region 3, Office of Director 84/07/31 LARSON, C E
Northern States Power Co 2pp 25949 349 24X
Fiche 50-282, 84/07/31, 8408070189

--8408070197 Responds to NRC 840629 ltr re violations noted in IE Insp Repts 50-282/84-04 & 50-306/84-04 Corrective actions reactor coolant vent sys solenoid valve fuses removed & will not be installed until requirements met
LARSON, C E Northern States Power Co 84/07/13 SHAFER, W D
Region 3, Office of Director 2pp 25949 351 24X
Fiche 50-282, 84/07/31, 8408070189

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408100029 Forwards IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 & notice of noncompliance Notice of noncompliance withheld (ref 10CFR73 21)
AXELSON, W L Region 3, Office of Director 84/08/03 LARSON, C E
Northern States Power Co 2pp 25987 068 24X
Fiche 50-282, 84/08/03, 8408100029

--8408100037 IE Safeguards Insp Repts 50-282/84-10 & 50-306/84-09 on 840709-13 Noncompliance noted failure to provide effective barrier in portion of protected area perimeter Details withheld (ref 10CFR73 21)
KNICELEY, J R , BELANGER, J L , CREED, J R Region 3, Office of Director 84/08/03 2pp 25987 070 24X Fiche 50-282, 84/08/03, 8408100029

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, 'Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408210298 Part 21 rept re separation of rod eye connected to piston rod from threaded portion of piston rod at approx 750,000 lb stress load Caused by insufficient matl thickness to withstand faulted load Matl certification encl
MILLS, C R Chicago Fluid Power Co 84/08/16 Director's Office, Office of Inspection and Enforcement 4pp 26180 349 24X
Fiche 50-282, 84/08/16, 8408210298

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

8408230526 Advises that operator & senior operator licensing exams scheduled for 841113-15 Matl listed in encl "Ref Matl Requirements for Operator/Senior Operator Licensing Exams" requested by 840913
WALPER, R D Region 3, Office of Director 84/08/17 LARSON, C E
Northern States Power Co 5pp 26212 338 24X
Fiche 50-282, 84/08/17, 8408230526

8408230132 Informs of review of 840705 ltr which clarified interpretation of on-shift training requirements Util will be required to provide documentation that senior reactor operator upgrade candidates comply w/listed requirements
WALKER, R D Region 3, Office of Director 84/08/20 LARSON, C E
Northern States Power Co 2pp 26209 061 24X
Fiche 50-000, 84/08/20, 8408230132

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

8408030008 Forwards fire hazards evaluations for primary auxiliary & svc bldgs Evaluations demonstrate that structures maintain acceptable level of fire protection equivalent to requirements of 10CFR50, App R
WHITTIER, G D Maine Yankee Atomic Power Co 84/07/25 MILLER, J R
Operating Reactors Branch 3 9pp 25906 010 24X
Fiche 50-309, 84/07/25, 8408030008

8408140399 Public version of Change 6 to emergency plan, Vol II
Maine Yankee Atomic Power Co 84/08/01 231pp 26048 090 24X
Fiche 50-309, 84/08/01, 8408140399

8408230487 Forwards IE Insp Rept 50-309/84-12 on 840604-08 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/08/02
RANDAZZA, J B Yankee Atomic Electric Co 2pp 26212 240 24X
Fiche 50-309, 84/08/02, 8408230487

--8408230492 Notice of violation from insp on 840604-08 Safeguards info withheld (ref 10CFR73 21)
Region 1, Office of Director 84/08/02 1p 26212 242 24X
Fiche 50-309, 84/08/02, 8408230487

--8408230495 IE Insp Rept 50-309/84-12 on 840604-08 Noncompliance noted plant security program Safeguards info withheld (ref 10CFR73 21)
STRUCKMEYER, R , PASCIAK, W J Region 1, Office of Director
84/07/20 6pp 26212 243 24X Fiche 50-309, 84/08/02, 8408230487

8408270406 Forwards Insp Rept 50-309/84-06 on 840315-0430 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/08/06
RANDAZZA, J B Maine Yankee Atomic Power Co 3pp 26256 316 24X
Fiche 50-309, 84/08/06, 8408270406

--8408270407 Notice of violation from insp on 840315-0430
* Region 1, Office of Director 84/08/06 2pp 26256 319 24X
Fiche 50-309, 84/08/06, 8408270406

--8408270410 Insp Rept 50-309/84-06 on 840315-0430 Violations noted failure to maintain fire protection procedures, incorrect auxiliary feedwater sys weld data sheets, lack of records of test tank discharge & incomplete weld insp
HOLDEN, C , FERLIC, K , GRAY, E H Region 1, Office of Director
84/08/06 13pp 26255 321 24X Fiche 50-309, 84/08/06, 8408270406

8408230331 Revised emergency plan implementing procedures, including 2 50 4 re general emergency, 2 50 14 re emergency radiation exposure control & 2 50 19 re technical support ctr W/rev transmittal form
* Maine Yankee Atomic Power Co 84/08/09 77pp 26206 054 24X
Fiche 50-309, 84/08/09, 8408230331

8408310204 Rev 6 to Emergency Plan Implementing Procedure 2 50 0, "Declaration & Categorization of Emergency Condition " W/one oversize table Aperture card available in PDR W/840824 transmittal form
* Maine Yankee Atomic Power Co 84/08/09 4pp 26317 223 24X
Fiche 50-309, 84/08/09, 8408310204

8408230304 Requests updated evacuation time estimate study for NRC use in evaluating impact on state of emergency preparedness Update should include listed criteria Response requested within 90 dys of ltr date
MURLEY, T E Region 1, Office of Director 84/08/10 RANDAZZA, J B
Maine Yankee Atomic Power Co 2pp 26213 247 24X
Fiche 50-309, 84/08/10, 8408230304

8408220431 Informs of NRC, util & FEMA efforts to resolve citizen concern re emergency preparedness, in particular, evacuation using State Road 27 Request for addl info issued to util Issue still under review
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/08/20 MILLER, D S Sensible Maine Power 3pp
26209 343 24X Fiche 50-309, 84/08/20, 8408220431

8408280210 Submits status rept of efforts to upgrade & implement plant-specific emergency operating procedures prior to issuance of NUREG-0737, Suppl 1 & before rest of industry
WHITTIER, G D Maine Yankee Atomic Power Co 84/08/22 MILLER, J R
Operating Reactors Branch 3 3pp 26269 354 24X
Fiche 50-309, 84/08/22, 8408280210

K Utility Final Safety Analysis Report (FSAR) & amends

8408020121 Forwards updated FSAR replacement pages for Maine Yankee, per 10CFR50 71(e) Rev reflects Cycle 8 core performance
RANDAZZA, J B Maine Yankee Atomic Power Co 84/07/23 MILLER, J R
Operating Reactors Branch 3 1p 25881 230 24X
Fiche 50-309, 84/07/23, 8408020121

-8408020125 Updated FSAR replacement pages for Maine Yankee
* Maine Yankee Atomic Power Co 84/07/23 358pp 25881 231
24X Fiche 50-309, 84/07/23, 8408020121

P Operating license stage documents & correspondence

8408070367 Provides status on functional testing of post-accident sampling sys (PASS) analytic equipment, per TMI Item II B 3 PASS procedures & methodology discussed & misunderstandings in NRC 831021 ltr corrected
WHITTIER, G D Maine Yankee Atomic Power Co 84/07/30 MILLER, J R
Operating Reactors Branch 3 3pp 25944 281 24X
Fiche 50-309, 84/07/30, 8408070367

8408160167 Informs of review of 840615 ltr re auxiliary feedwater sys (AFW) (TMI Item II E 1 1) Requests Tech Spec for monthly surveillance testing of AFW sys pumps
MILLER, J R Operating Reactors Branch 3 84/08/01 RANDAZZA, J B
Maine Yankee Atomic Power Co 2pp 26124 350 24X
Fiche 50-309, 84/08/01, 8408160167

8408170036 Advises that 830728 seismic & closure analysis acceptable re operability of Masoneilan Intl, Inc 8-inch containment ventilation sys globe valve
MILLER, J R Operating Reactors Branch 3 84/08/01 RANDAZZA, J B
Maine Yankee Atomic Power Co 1p 26134 360 24X
Fiche 50-309, 84/08/01, 8408170036

8408090173 Forwards "Assessment of Original Design Methodology for Seismic Category I Piping Sys at Maine Yankee Atomic Power Station "
WHITTIER, G D Maine Yankee Atomic Power Co 84/08/03 MILLER, J R
Operating Reactors Branch 3 1p 25973 186 24X
Fiche 50-309, 84/08/03, 8408090173

--8408090182 Assessment of Original Design Methodology for Seismic Category I Piping Sys at Maine Yankee Atomic Power Station "
HENRIES, J E Yankee Atomic Electric Co 84/04/30 95pp
259/3 188 24X Fiche 50-309, 84/08/03, 8408090173

8408070110 Generic Ltr 84 19 to all licensees of operating reactors applicants for OL + ' holders of CPs re availability of Suppl 1 to NUREG-0933, 'Prioritization of Generic Safety Issues ' Svc list encl
EISENHUT, D C Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000 84/08/06, 8408070110

8408230291 Requests fees for 840119 & 0522 applications for amends to License DPR-36, changing Tech Specs re steam generator water level & containment integrity respectively
DIGGS, R M License Fee Management Branch 84/08/17 RANDAZZA, J B
Maine Yankee Atomic Power Co 3pp 26236 126 24X
Fiche 50-309, 84/08/17, 8408230291

8408200275 Generic Ltr 84 20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408280227 Responds to NRC request to evaluate impact on safe shutdown equipment due to flooding from non-Class 1 (seismic) sys, component or pipe flooding will not impact safety-related electrical equipment
WHITTIER, G D Maine Yankee Atomic Power Co 84/08/23 MILLER, J R
Operating Reactors Branch 3 1p 26275 361 24X
Fiche 50-309, 84/08/23, 8408280227

0 Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 11pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408230487 Forwards IE Insp Rept 50-309/84-12 on 840604-08 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/08/02
RANDAZZA, J B Yankee Atomic Electric Co 2pp 26212 240 24X
Fiche 50-309, 84/08/02, 8408230487

--8408230492 Notice of violation from insp on 840604-08 Safeguards info withheld (ref 10CFR73 21)
* Region 1, Office of Director 84/08/02 1p 26212 242 24X
Fiche 50-309, 84/08/02, 8408230487

--8408230495 IE Insp Rept 50-309/84-12 on 840604-08 Noncompliance noted plant security program Safeguards info withheld (ref 10CFR73 21)
STRUCKMEYER, R , PASCIAK, R J Region 1, Office of Director
84/07/20 6pp 26212 243 24X Fiche 50-309, 84/08/02, 8408230487

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 12pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84 60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 12pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408270406 Forwards Insp Rept 50-309/84-06 on 840315-0430 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/08/06
RANDAZZA, J B Maine Yankee Atomic Power Co 3pp 26256 316 24X
Fiche 50-309, 84/08/06, 8408270406

--8408270407 Notice of violation from insp on 840315-0430
* Region 1, Office of Director 84/08/06 2pp 26256 319 24X
Fiche 50-309, 84/08/06, 8408270406

--8408270410 Insp Rept 50-309/84-06 on 840315-0430 Violations noted failure to maintain fire protection procedures, incorrect auxiliary feedwater sys weld data sheets, lack of records of test tank discharge & incomplete weld insp
HOLDEN, C , FERLIC, K , GRAY, E H Region 1, Office of Director
84/08/06 13pp 26256 321 24X Fiche 50-309, 84/08/06, 8408270406

8408070120 IE Info Notice 84-61 "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 12Dpp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12Spp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8408030272 LER 84-009-00 on 840622,noise spike in channel provided 2 of 4 coincidence & tripped reactor Control element assembly (CEA) group manually tripped when reactor operator attempted to drive in shutdown CEA group W/840726 ltr
SMITH,S P , WHITTIER,G D Maine Yankee Atomic Power Co 84/07/26
4pp 25917 254 24X Fiche 50-309,84/07/26,8408030272

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8408030236 Ack receipt of 840608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10
BELLAMY,R R Division of Engineering & Technical Programs
84/07/18 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp 25917 192 24X Fiche 50-272,84/07/18,8408030236

--8408030247 Responds to NRC 840504 ltr re violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10 Corrective actions revised emergency plan brochure distributed in Feb 1984 & emergency response training program undergoing review & evaluation
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/06/08 MARTIN,T T Region 1, Office of Director 8pp
25917 194 24X Fiche 50-272,84/07/18,8408030236

8408070065 Forwards corrected page to 840612 confirmatory order, confirming Dec 1986 schedule for implementation of Suppl 1 to NUREG-0737 & Generic Ltr 82-33 re completion of structural mods to technical support ctr W/o encl
VARGA,S A Operating Reactors Branch 1 84/07/26 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 3pp 25955 319
24X Fiche 50-272,84/07/26,8408070065

8408100093 Advises that 840106 Rev 8 to Amend 3 to physical security plan & contingency plan consistent w/provisions of 10CFR50 54(p) & acceptable
MARTIN,T T Division of Engineering & Technical Programs 84/08/02
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 3pp
25991 001 24X Fiche 50-272,84/08/02,8408100093

8408150223 Forwards responses to 840504 ltr re INEL rept on util conformance to Reg Guide 1 97 requirements for emergency response capability & Suppl 1 to NUREG-0737 Changes to 830921 implementation plan listed
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/09 VARGA,S A Operating Reactors Branch 1 9pp 26066 081
24X Fiche 50-272,84/08/09,8408150223

8408210408 Informs that FEMA does not intend to conduct full-scale evaluation of Hope Creek 1985 exercise Since Salem Unit 1 OL issued prior to 820713,full participation in 1985 not required by NRC or FEMA rules
KRIMM,R W Federal Emergency Management Agency 84/08/13
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 26177 256 24X Fiche 50-000,84/08/13,8408210408

8408220428 Notification of 840906 meeting w/util in Bethesda,MD to discuss addl App R exemptions
FISCHER,D C Operating Reactors Branch 1 84/08/16 VARGA,S A
Operating Reactors Branch 1 2pp 26201 362 24X
Fiche 50-272,84/08/16,8408220428

K Utility Final Safety Analysis Report (FSAR) & amends

8408020100 Forwards Rev 3 to updated FSAR for Salem Generating Station, Units 1 & 2 Changes made per 10CFR50 59,but not previously submitted to NRC,identified in monthly operating repts
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/07/23 VARGA,S A Operating Reactors Branch 1 6pp 25910 076
24X Fiche 50-272,84/07/23,8408020100

--8408020108 Rev 3 to updated FSAR for Salem Generating Station, Units 1 & 2
* Public Service Electric & Gas Co of New Jersey 84/07/22
439pp 25910 082 24X Fiche 50-272,84/07/23,8408020100

P Operating license stage documents & correspondence

8408070059 Grants extension until no later than Jul 1984 for submittal of rept re reactor vessel matl surveillance program
EISENHUT,D G Division of Licensing 84/07/13 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 5pp 25955 325
24X Fiche 50-311,84/07/13,8408070059

8408130362 Revised Pages 6 & 7 to Salem,Unit 2 Cycle 2 startup test rept W/840730 ltr
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/07/30 , MURLEY,T E Region 1, Office of Director 5pp
26010 307 24X Fiche 50-311,84/07/30,8408130362

8408150245 Forwards revs to Cycle 2 startup rept & safety evaluation of util rod exchange methodology
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/07/30 VARGA,S Operating Reactors Branch 1 10pp 26075 299
24X Fiche 50-272,84/07/30,8408150245

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408200343 Forwards drawing of proposed upgraded core exit thermocouple sys showing layout of major components,per TMI Item II F 2
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/13 VARGA,S A Operating Reactors Branch 1 4pp 26131 081
24X Fiche 50-272,84/08/13,8408200343

8408210554 Requests listed addl info re environ qualification of electrical equipment important to safety & remaining outstanding justifications for continued operation Addl info requested by 840827
VARGA,S A Operating Reactors Branch 1 84/08/13, UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 2pp 26195 259,
24X Fiche 50-272,84/08/13,8408210554

DOCKETED ITEMS

8210335 Submits addl info to support BVY821 request for relief from rticles IWB 3222 & IWC 5210 of ASME Boiler & Pressure essel Code, Section XI Relief required because no viable eans of heating certain components exists
IDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/15 VARGA,S A Operating Reactors Branch 1 2pp 26179 340
24X Fiche 50-272,84/08/15,8408210335

8240117 Forwards suppl to 830428 response to Generic Ltr 83-10D re lan for resolution of TMI Action Item II K 3 5, 'Automatic Trip of Reactor Coolant Pumps
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/15 VARGA,S A Operating Reactors Branch 1 5pp 26228 224
24X Fiche 50-272,84/08/15,8408240117

8280275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408280275

8280330 Requests remittance of addl fee for review of 790209 & 810810 applications to amend Licenses DPR-70 & DPR-75
MILLER,W O License Fee Management Branch 84/08/20 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 2pp 26294 081
24X Fiche 50-272,84/08/20,8408280330

Inspection Reports, IE Bulletins & correspondence

8408030259 Forwards IE Insp Repts 50-272/84-21 & 50-311/84-21 on 840529-0601 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/07/11
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
25917 244 24X Fiche 50-272,84/07/11,8408030259

--8408030267 IE Insp Repts 50-272/84-21 & 50-311/84-21 on 840529-0601 No violations noted Major areas inspected radiation protection program including ALARA implementation,external exposure control & surveillance & posting
DRAGOUN,T , SHANBAKY,M Region 1, Office of Director 84/07/09
5pp 25917 246 24X Fiche 50-272,84/07/11,8408030267

8408030236 Ack receipt of 840608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10
BELLAMY,R R Division of Engineering & Technical Programs
84/07/18 UDERITZ,R A Public Service Electric & Gas Co of New
Jersey 2pp 25917 192 24X Fiche 50-272,84/07/18,8408030236

--8408030247 Responds to NRC 840504 ltr re violations noted in IE Insp Repts 50-272/84-10 & 50-311/84-10 Corrective actions revised emergency plan brochure distributed in Feb 1984 & emergency response training program undergoing review & evaluation
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/06/08 MARTIN,T T Region 1, Office of Director 8pp
25917 194 24X Fiche 50-272,84/07/18,8408030247

8408160270 Discusses IE enforcement conference on 840627 & forwards notice of violation associated w/IE Insp Rept 50-311/84-22 on 840529-30 Violation classified as Severity level IV
STAROSTECKI,R Division of Project & Resident Programs 84/07/20
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 3pp
26106 172 24X Fiche 50-311,84/07/20,8408160270

--8408160281 Notice of violation from insp on 840529-30 Violation noted on-the-spot change made on 840528 to operating procedure governing method to maintain pressure control,resulting in blockage of automatic isolation function
* Region 1, Office of Director 84/07/20 2pp 26106 175 24X
Fiche 50-311,84/07/20,8408160270

8408150366 Forwards IE Insp Repts 50-272/84-23 & 50-311/84-23 on 840609-0706 & notice of violation Both aspects of violation, including failure to include mechanical snubbers in formal snubber surveillance program,should be addressed
STAROSTECKI,R Division of Project & Resident Programs 84/07/25
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
26075 166 24X Fiche 50-272,84/07/25,8408150366

-8408150368 Notice of violation from insp on 840609-0706
* Region 1, Office of Director 84/07/25 1p 26075 168 24X
Fiche 50-272,84/07/25,8408150368

Insp Repts 50-272/84-23 & 50-311/84-23 on 840609-0706
oted failure to establish procedure to perform
ting of safety-related equipment & mechanical

IMMERS R J GRAY,E H Region 1, Office of
pp 26075 169 24X Fiche 50-272,84/07/25,

8407250[illegible] IE Info Notice 84-59, 'Operating Experience re Moisture Intrusion in Safety Related Electrical Equipment at Commercial Power Plants " w/ list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/20 Consolidated Edison Co of New
York, Inc 119pp 26065 047 24X Fiche 50-000,84/07/27,8407250229

8408030027 Forwards IE Mgt Meeting Repts 50-272/84-30 & 50-311/84-29 on 840719
STAROSIECKI R Division of Project & Resident Programs 84/07/30
UDERITZ R Public Service Electric & Gas Co of New Jersey 2pp
25907 077 24X Fiche 50-272,84/07/30,8408030027

--8408030061 IE Mgt Meeting Repts 50-272/84-30 & 50-311/84-29 on 840719 Major areas discussed response, status of action plan for improvement of nuclear dept operations, submitted to NRC in Aug 1983 to recent insp findings
LINVILLE J C NORRHOLM L J Region 1, Office of Director
84/07/26 3pp 25907 077 24X Fiche 50-272,84/07/30,8408030027

8408200043 Forwards IE Insp Repts 50-272/84-24 & 50-311/84-24 on 840529 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/07/30
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
26140 210 24X Fiche 50-272,84/07/30,8408200043

--8408200052 IE Insp Repts 50-272/84-24 & 50-311/84-24 on 840529 No violations noted Major areas inspected circumstances surrounding transportation accident near Rock Springs,WY, including shipping documentation,waste packaging & shipment
EVERETT,R J , HALE,R E Region 1, Office of Director 84/06/18
3pp 26140 212 24X Fiche 50-272,84/07/30,8408200043

8408070232 Forwards IE Mgt Meeting Repts 50-272/84-30 & 50-311/84-29 on 840719
STAROSIECKI,R Division of Project & Resident Programs 84/08/02
UDERITZ,R Public Service Electric & Gas Co of New Jersey 2pp
25948 243 24X Fiche 50-272,84/08/02,8408070232

--8408070237 IE Mgt Meeting Repts 50-272/84-30 & 50-311/84-29 on 840719 Major areas discussed status of action plan for improvement of nuclear dept operations, including responsiveness to insp findings
LINVILLE,J C , NORRHOLM L J Region 1, Office of Director
84/07/26 68pp 25948 235 24X Fiche 50-272,84/08/02,8408070232

8408010333 IE Info Notice 84 59, 'Deliberate Circumventing of Station Health Physics Procedures ' S c list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84 60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement ' Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 180 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, 'Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New
York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84 62, "Therapy Misadministrations to Patients Undergoing Co 60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
124pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84 64 "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New
York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-63, "BWR HPCI Initiation Seal-In & Indication ' Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New
York, Inc 104pp 26198 077 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New
York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine Trip on Auxiliary Feedwater Train," Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, Recent Snubber Inservice Testing W/ High Failure Rates Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12pp 26276 [illegible] 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 11Spp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408310131 Responds to 830106 ltr,840131 telcon & 840626 meeting re violation in Insp Repts 50-272/83-29 & 50-311/83-31 Violation will be withdrawn & concern will be classified as open item
MARTIN,T T Division of Engineering & Technical Programs 84/08/21
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
26329 260 24X Fiche 50-272,84/08/21,8408310131

R Periodic operating reports & related correspondence

8408200276 Monthly operating rept for Jul 1984 W/840810 ltr
MILLER,L K , ZUPKO,J M Public Service Electric & Gas Co of New Jersey 84/07/31 9pp 26179 105 24X Fiche 50-311,84/07/31, 8408200276

8408160142 Forwards Nuclear Oversight Committee quarterly rept dtd 840731
LIDEN,E A Public Service Electric & Gas Co of New Jersey
84/08/03 VARGA,S Operating Reactors Branch 1 6pp 26108 075
24X Fiche 50-272,84/08/03,8408160142

S Reportable occurrences, LERs & related correspondence

8408090076 LER 84-017-00 on 840703,turtle found impinged on trash bars in circulating water sys intake Caused by debris drawn into plant No corrective action required W/840802 ltr
RUPP,J L , ZUPKO,J M Public Service Electric & Gas Co of New Jersey 84/08/02 4pp 25972 356 24X Fiche 50-311,84/08/02, 8408090076

8408130588 LER 84-016-00 on 840705,leak discovered on common suction line to charging pumps Caused by 3 inch crack in Schedule 10 suction header pumping originating in toe of weld Unit shutdown initiated Piping replaced W/810803 ltr
RUPP,J L , ZUPKO,J M Public Service Electric & Gas Co of New Jersey 84/08/03 5pp 26031 303 24X Fiche 50-311,84/08/03, 8408130588

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/08/16
EISENHUT,D G Division of Licensing 20pp 26233 249 24X
Fiche 50-000,84/08/16,8408230077

8408300349 LER 84-018-00 on 840725,during pressurizer overpressure protection sys functional test,RCS pressure rapidly dropped upon opening PORV block valve 2PR6 Valve failed to close in required time & resulted in reactor trip W/840824 ltr
RUPP,J L , ZUPKO,J M Public Service Electric & Gas Co of New Jersey 84/08/24 8pp 26314 139 24X Fiche 50-311,84/08/24, 8408300349

8408300400 LER 84-019-00 on 840726,during controlled cooldown to Mode 5,both containment spray pumps inadvertently cleared & tagged while unit in Mode 4,contrary to Tech Specs Caused by personnel error Pumps returned to svc W/840824 ltr
RUPP,J L , ZUPKO,J M Public Service Electric & Gas Co of New Jersey 84/08/24 5pp 26308 208 24X Fiche 50-311,84/08/24, 8408300400

8408310065 PNS-1-84-017 on 840827,unidentified male telephoned security post at Elevation 100 ft of Unit 1 on internal line & told security guard that bomb planted in containment Bomb search teams deployed No bomb found No explosion occurred
DUNLAP,J , KEIMIG,R , JOYNER,J Region 1, Office of Director
84/08/27 1p 26329 203 24X Fiche 50-272,84/08/27,8408310065

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8408080397 Forwards request for addl info re emergency operation guidelines in order to continue review of 840131 plant-specific submittal Response requested within 7 days of ltr receipt
RIVENBARK,G Operating Reactors Branch 4 84/07/24 RODRIGUEZ,R J
Sacramento Municipal Utility District 3pp 25978 079 24X
Fiche 50-312,84/07/24,8408080397

8408080445 Forwards request for addl info re safety parameter display sys (SPDS) Contained implementation of SPDS acceptable Response requested within 60 days of ltr receipt
RIVENBARK,G Operating Reactors Branch 4 84/07/27 RODRIGUEZ,R J
Sacramento Municipal Utility District 4pp 25977 152 24X
Fiche 50-312,84/07/27,8408080445

--8408080449 Safety evaluation supporting continued implementation of safety parameter display sys,per Suppl 1 to NUREG-0737
* NRC - No Detailed Affiliation Given 84/07/27 8pp
25977 156 24X Fiche 50-312,84/07/27,8408080445

8408090282 Summary of 840620 meeting w/util & Bechtel in Bethesda,MD re implementation of Reg Guide 1.97 requirements by licensee Util will provide supplemental rept to 840715 submission to address separation problems Viewgraphs encl
MINER,S Operating Reactors Branch 4 84/08/01 Operating
Reactors Branch 4 12pp 25992 001 24X Fiche 50-312,84/08/01, 8408090282

8408300483 Forwards Emergency Preparedness Insp Rept 50-312/84-11 on 840618-22 & notice of violation
SCHUSTER,M D Region 5, Office of Director 84/08/02
RODRIGUEZ,R J Sacramento Municipal Utility District 2pp
26314 015 24X Fiche 50-312,84/08/02,8408300483

--8408300498 Notice of Violation from insp on 840618-22
SCHUSTER,M D Region 5, Office of Director 84/08/02 2pp
26314 017 24X Fiche 50-312,84/08/02,8408300483

--8408300504 Emergency Preparedness Insp Rept 50-312/84-11 on 840618-22
Violations noted failure to provide initial emergency preparedness training to two newly appointed shift supervisors & inadequate meteorological program
FISH,R F , PRENDERGAST,K , SCHUSTER,M D Region 5, Office of Director 84/08/02 12pp 26314 019 24X Fiche 50-312,84/08/02, 8408300483

8408130207 Notifies that response to 840724 request for addl info re emergency operating guidelines will be provided by 841214
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/06
STOLZ,J F Operating Reactors Branch 4 1p 26010 056 24X
Fiche 50-312,84/08/06,8408130207

P Operating license stage documents & correspondence

8408310234 Application for amend to License DPR-54,revising Tech Specs re LER sys NSHC evaluation & description of proposed changes for Amend 105 & Rev 2 to Amend 93 encl
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/25
EISENHUT,D G Division of Licensing 6pp 26320 337 24X
Fiche 50-312,84/08/25,8408310234

--8408310237 Proposed Tech Specs re LER sys
* Sacramento Municipal Utility District 84/08/25 15pp
26320 343 24X Fiche 50-312,84/08/25,8408310234

8408310217 Application for Amend 110 to License DPR-54,addressing changes resulting from B&W integrated reactor vessel matl surveillance program NSHC encl
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/27
EISENHUT,D G Division of Licensing 4pp 26318 117 24X
Fiche 50-312,84/08/27,8408310217

--8408310220 Proposed Tech Specs addressing changes resulting from B&W integrated reactor vessel matl surveillance program
* Sacramento Municipal Utility District 84/08/27 6pp
26318 121 24X Fiche 50-312,84/08/27,8408310217

8408080298 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating
Reactors Branch 4 36pp 25978 228 24X Fiche 50-000,84/07/27, 8408080298

8408060177 Provides supplemental info re NSHC for proposed Amend 106 to License DPR-54 Info augments util 840531 ltr describing living schedule plan
RODRIGUEZ,R J Sacramento Municipal Utility District 84/07/31
EISENHUT,D G Division of Licensing 2pp 25923 359 24X
Fiche 50-312,84/07/31,8408060177

8408080161 Forwards SER & request for addl info for review of BAW-1702 re neutron dosimetry Info requested within 14 days of ltr receipt
STOLZ,J F Operating Reactors Branch 4 84/07/31 RODRIGUEZ,R J
Sacramento Municipal Utility District 3pp 25979 001 24X
Fiche 50-312,84/07/31,8408080161

--8408080170 Safety evaluation from review of BAW-1702 re surveillance of Capsule RSI-B of reactor pressure vessel surveillance program
* Office of Nuclear Reactor Regulation, Director 84/07/31 5pp 25979 004 24X Fiche 50-312,84/07/31,8408080161

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 50-000,84/08/06,8408090317

8408140259 Responds to request for addl info re pressure & temp profiles for pipe breaks outside containment Pressure data encl
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/09
STOLZ,J F Operating Reactors Branch 4 2pp 26053 359 24X
Fiche 50-312,84/08/09,8408140259

8408210062 Forwards Amend 56 to License DPR-54 & safety evaluation Amend revises Tech Specs to incorporate leak testing of 66-inch containment purge & 12-inch containment equalizing valves at 6-month intervals
STOLZ,J F Operating Reactors Branch 4 84/08/10 RODRIGUEZ,R J
Sacramento Municipal Utility District 3pp 26195 152 24X
Fiche 50-312,84/08/10,8408210062

--8408210070 Amend 56 to License DPR-54, revising Tech Specs to incorporate leak testing of 66-inch containment purge & 12-inch containment equalizing valves at 6-month intervals
STOLZ,J F Operating Reactors Branch 4 84/08/10 4pp 26195 155 24X Fiche 50-312,84/08/10,8408210062

--8408210074 Safety evaluation supporting Amend 56 to License DPR-54
* Office of Nuclear Reactor Regulation, Director 84/08/10 3pp 26195 159 24X Fiche 50-312,84/08/10,8408210062

8408210152 Forwards request for addl info re environ qualification of equipment important to safety Response requested within 30 days of ltr receipt
STOLZ,J F Operating Reactors Branch 4 84/08/10 RODRIGUEZ,R J
Sacramento Municipal Utility District 4pp 26195 307 24X
Fiche 50-312,84/08/10,8408210152

8408170362 Responds to recent telcon re effect of differing steam generator level setpoints on results of main steam line break scenario in FSAR, in connection w/IE Bulletin 80-04
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/14
STOLZ,J F Operating Reactors Branch 4 1p 26112 357 24X
Fiche 50-312,84/08/14,8408170362

8408210159 Notification of 840830 meeting w/util in Bethesda,MD to discuss implementation of Reg Guide 1 97 requirements
MINER,S Operating Reactors Branch 4 84/08/15 STOLZ,J F
Operating Reactors Branch 4 2pp 26195 223 24X
Fiche 50-312,84/08/15,8408210159

8408240112 Requests extension until 850115 to respond to Generic Ltr 84-15, "Proposed Staff Actions to Improve & Maintain Diesel Generator Reliability " Extension requested due to scope & magnitude of responses required
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/16
EISENHUT D G Division of Licensing 2pp 26228 229 24X
Fiche 50-312,84/08/16,8408240112

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals or reloads that involve unreviewed safety questions Svc list encl
EISENHUT D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408270061 Notifies that response to NRC 840731 ltr requesting addl info re neutron dosimetry for surveillance capsule program will be submitted by 841001
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/20
STOLZ,J F Operating Reactors Branch 4 1p 26247 068 24X
Fiche 50-312,84/08/20,8408270061

8408310245 Application for Amend 100 to License DPR-54, revising Tech Specs re instrument surveillance requirements for testing high-range noble gas effluent monitors & main steam line radiation monitors Supporting documentation encl
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/21
EISENHUT,D G Division of Licensing 2pp 26319 252 24X
Fiche 50-312,84/08/21,8408310245

--8408310246 Proposed Tech Specs revising instrument surveillance requirements for testing high-range noble gas effluent monitors & main steam line radiation monitors
* Sacramento Municipal Utility District 84/08/21 2pp 26319 254 24X Fiche 50-312,84/08/21,8408310245

8408270401 Requests extension for implementation of NUREG-0737, Item III D 3 4 re control room habitability Existing single train control room HVAC being replaced w/redundant two train HVAC sys Fee paid
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/22
STOLZ,J F Operating Reactors Branch 4 2pp 26238 146 24X
Fiche 50-312,84/08/22,8408270401

8408310113 Forwards correct fee for proposed Amend 109 per 840620 application Refund of fee sent w/proposed Amend 109 application expected per 840820 telcon
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/22
TREMPER,L License Fee Management Branch 1p 26322 114 24X
Fiche 50-312,84/08/22,8408310113

8408280240 Requests reinstatement of Amend 36 re gaseous effluent release point for miscellaneous water evaporator, inadvertently deleted from License DPR-54 on 840222 Safety evaluation & no significant hazards evaluation encl
COLOMBO,R W Sacramento Municipal Utility District 84/08/23
DEAGAZIO,A Office of Nuclear Reactor Regulation, Director 3pp 26279 180 24X Fiche 50-312,84/08/23,8408280240

Q Inspection reports, IE Bulletins & correspondence

8408090086 Forwards IE Insp Rept 50-312/84-16 on 840424-25 No noncompliance noted
WENSLAWSKI,F A Region 5, Office of Director 84/07/23
RODRIGUEZ,R J Sacramento Municipal Utility District 2pp 25992 218 24X Fiche 50-312,84/07/23,8408090086

--8408090091 IE Insp Rept 50-312/84-16 on 840424-25 No noncompliance noted Major areas inspected environ samples for NRC independent verification
HAMADA,G , NORTH,H , YUHAS,G Region 5, Office of Director 84/07/20 7pp 25992 220 24X Fiche 50-312,84/07/23,8408090086

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408060011 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " No check valves in flow path of cooling water for diesel generators found
RODRIGUEZ,R J Sacramento Municipal Utility District 84/07/30
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 1p 25933 184 24X Fiche 50-312,84/07/30,8408060011

8408230078 Forwards IE Insp Rept 50-312/84-08 on 840521-25 No violations noted Matters re post-accident sampling program & offsite dose projection errors unresolved
SCARANO,R A Division of Radiological Safety & Safeguards Program 84/07/30 RODRIGUEZ,R J Sacramento Municipal Utility District
3pp 26213 159 24X Fiche 50-312,84/07/30,8408230078

--8408230087 IE Insp Rept 50-312/84-08 on 840521-25 No violations or deviations noted Major areas inspected unresolved items (NUREG-0737,II B 3 re post-accident sampling sys) & offsite dose calculation code errors
NORTH,H S , YUHAS,G P Region 5, Office of Director 84/07/06
16pp 26213 161 24X Fiche 50-312,84/07/30,8408230078

8408300483 Forwards Emergency Preparedness Insp Rept 50-312/84-11 on 840618-22 & notice of violation
SCHUSTER,M D Region 5, Office of Director 84/08/02
RODRIGUEZ,R J Sacramento Municipal Utility District 2pp
26314 015 24X Fiche 50-312,84/08/02,8408300483

--8408300498 Notice of violation from insp on 840618-22
SCHUSTER,M D Region 5, Office of Director 84/08/02 2pp
26314 017 24X Fiche 50-312,84/08/02,8408300483

--8408300504 Emergency Preparedness Insp Rept 50-312/84-11 on 840618-22
Violations noted Failure to provide initial emergency preparedness training to two newly appointed shift supervisors & inadequate meteorological program
FISH,R F PRENDERGAST,K , SCHUSTER,M D Region 5, Office of Director 84/08/02 12pp 26314 019 24X Fiche 50-312,84/08/02,8408300483

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408300110 Forwards Insp Rept 50-312/84-13 on 840625-29 & notice of violation
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 84/08/08 RODRIGUEZ,R J Sacramento Municipal Utility District 2pp 26308 076 24X Fiche 50-312,84/08/08,8408300110

--8408300114 Notice of violation from insp on 840625-29
YOUNG,T Region 5 Office of Director 84/08/08 2pp
26308 078 24X Fiche 50-312,84/08/08,8408300110

--8408300133 Insp Rept 50-312/84-13 on 840625-29 Violation noted records unavailable re storage & protection of motor control ctrs & unauthorized inspector performed insp on safety-related items in diesel generator bldg
BURDOIN,J F , YOUNG,T Region 5, Office of Director 84/08/07 6pp 26308 080 24X Fiche 50-312,84/08/08,8408300110

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408200339 Responds to NRC 840713 ltr re violations noted in IE Insp Rept 50-312/84-02 Corrective actions personnel instructed to perform calibr at plus or minus 2% deviation
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/10
MARTIN,J B Region 5, Office of Director 4pp 26132 352 24X Fiche 50-312,84/08/10,8408200339

8408300248 Forwards Insp Rept 50-312/84-15 on 840618-0720 & notice of violation
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 84/08/10 RODRIGUEZ,R Sacramento Municipal Utility District 2pp 26307 016 24X Fiche 50-312,84/08/10,8408300248

--8408300250 Notice of violation from insp on 840618-0720
DODDS,R T Region 5, Office of Director 84/08/10 2pp
26307 018 24X Fiche 50-312,84/08/10,8408300248

--8408300254 Insp Rept 50-312/84-15 on 840618-0720 Noncompliance noted design calculation for auxiliary feedwater orifice plates not subj to calculation checking,review & approval process
ECKHARDT,J H , PEREZ,G P., MYERS,C J Region 5, Office of Director 84/08/10 8pp 26307 020 24X Fiche 50-312,84/08/10,8408300248

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408170362 Responds to recent telcon re effect of differing steam generator level setpoints on results of main steam line break scenario in FSAR,in connection w/IE Bulletin 80-04
RODRIGUEZ,R J Sacramento Municipal Utility District 84/08/14
STOLZ,J F Operating Reactors Branch 4 1p 26112 357 24X Fiche 50-312,84/08/14,8408170362

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts,"
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FAAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp
25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10,8408060050

8408310196 LER 84-018-01 on 840601,transient occurred on main feedwater loop B due to spurious closure of main feedwater startup & block valves Caused by intermittent short of pressure switches Switches replaced W/840710 ltr
COLOMBO,R W , RODRIGUEZ,R J Sacramento Municipal Utility District 84/07/10 MARTIN,J B Region 5, Office of Director 3pp
26318 289 24X Fiche 50-312,84/07/10,8408310196

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000,84/07/27,8408060102

8408060123 PNO-V-84-045 on 810710, licensee began evaporating highly purified liquid radwaste to dryness, resulting in airborne release of radioactive tritium Approx 5,500 gallons water processed resulting in release of 1 39 Ci to atmosphere
YUHAS, G , WENSLAWSKI, F Region 5, Office of Director 84/07/27
1p 25933 193 24X Fiche 50-312 84/07/27, 8408060123

8408060156 PNO-V-84-044 on 840723, licensee learned that highly radioactive 2 x 0 6 x 0 1-inch metal object removed from steam generator B primary side inlet source of metal or extent of personnel exposures not identified
YUHAS, G , WENSLAWSKI, F Region 5, Office of Director 84/07/27
1p 25932 198 24X Fiche 50-312, 84/07/27, 8408060156

8408070416 PNO-V-84-047 on 840731, temporary work stoppage occurred following misunderstanding re alleged contamination of const workers on 840730 No contamination found on workers or vehicles Issue resolved by contractor
NORTH, H , WENSLAWSKI, F Region 5, Office of Director 84/07/31
1p 25942 052 24X Fiche 50-312, 84/07/31, 8408070416

8408060324 Forwards "Design Review of Elliott Model 456 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000, 84/08/01, 8408060324

8408140346 PNO-V-84-049 during present outage for steam generator tube plugging repairs, two swagelok fitting leaks identified in process piping installed during 1983 outage All swagelok fittings undergoing insp Outage extended
MYERS, C , ECKHARDT, J Region 5, Office of Director 84/08/08 1p
26042 325 24X Fiche 50-312, 84/08/08, 8408140346

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000, 84/08/10, 8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000, 84/08/10, 8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT, D G Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000, 84/08/13, 8408240115

-8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000, 84/08/13, 8408240115

408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL per NRC request
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24088 163 24X Fiche 50-000, 84/08/14, 8408160395

-8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
24088 165 24X Fiche 50-000, 84/08/14, 8408160395

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CROTCHFIELD, D Assistant Director for Safety Assessment 84/08/16
EISENHUT, D G Division of Licensing 20pp 26233 249 24X
Fiche 50-000, 84/08/16, 8408230077

8408240111 Special Rept 84-03 on 840709, five identically defective switch jaws found on Westinghouse Type MG-6 relay Caused by excessively sharp bend radius on forming die All defective units replaced
RODRIGUEZ, R J Sacramento Municipal Utility District 84/08/23
MARTIN, J B Region 5, Office of Director 2pp 26228 231 24X
Fiche 50-312, 84/08/23, 8408240111

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY, C L TDI (Transamerica Delaval Inc) Owners Group 84/08/23
BERLINGER, L Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000, 84/08/23 8408290179

8408290288 Forwards responses to 840131 questions re TDI diesel generators Remaining responses will be delayed until completion of TDI Owners Group site-specific DR/QR repts, Phase 1 disassembly & insp, Phase 2 testing & Phase 3 insp
RODRIGUEZ, R J Sacramento Municipal Utility District 84/08/24
STOLZ, J F Operating Reactors Branch 4 15pp 26291 161 24X
Fiche 50 312, 84/08/24, 8408290288

V Operator Examinations

8408060006 Provides update rept on progress of training & exam of candidates for operators license per 840620 commitment Sixteen addl licenses issued at end of June
RODRIGUEZ, R J Sacramento Municipal Utility District 84/07/26
STOLZ, J F Operating Reactors Branch 4 2pp 25922 015 24X
Fiche 50-312, 84/07/26, 8408060006

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

8408160498 Forwards IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted
HUNTER, D R Region 4, Office of Director 84/07/23 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26107 318 24X
Fiche 50-313, 84/07/23, 8408160498

--8408160504 IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted Major areas inspected security program audit & physical barriers Details withheld (ref 10CFR73 21)
EVANS, C A , HALL, R E , MARTIN, L E Region 4, Office of Director
84/07/23 1p 26107 320 24X Fiche 50-313, 84/07/23, 8408160498

8408080441 Forwards request for addl info re procedures generation package for emergency operating procedures Response requested within 30 days of ltr receipt
RIVENBARK, G W Operating Reactors Branch 4 84/07/26 GRIFFIN, J M
Arkansas Power & Light Co 3pp 25977 174 24X
Fiche 50-313, 84/07/26, 8408080441

8408280184 Forwards "Reanalysis Against 10CFR50, App R, Sections III G, J & O " per 830328 & 0712 requests for exemption from 10CFR50 48(c) schedule for barriers, penetrations & suppression/detection sys for approx 1 yr
MARSHALL, J R Arkansas Power & Light Co 84/08/15 STOLZ, J F
Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 2pp 26287 144 24X Fiche 50 313, 84/08/15, 8408280184

--8408280188 "Reanalysis Against 10CFR50, App R, Sections III G, J & O "
* Arkansas Power & Light Co 84/08/15 120pp 26287 146 24X
Fiche 50-313, 84/08/15, 8408280184

8408230401 Revised Emergency Procedures 1903 72 re St Marys Hosp, 1903 73 re Millard-Henry clinic & 1903 74 re Pope County ambulance svc
* Arkansas Power & Light Co 84/08/16 7pp 26206 001 24X
Fiche 50-313, 84/08/16, 8408230401

8408230417 Deletion of Rev 0 to Procedure 1903 34, "Administration of Potassium Iodide "
* Arkansas Power & Light Co 84/08/29 3pp 26204 011 24X
Fiche 50 313, 84/08/29, 8408230417

P Operating license stage documents & correspondence

8408070389 Forwards "Extension of Retainer Lifetime to Four Cycles," for Oconee Unit 3 w/results of exams of two retainers after three cycles Approval of four-cycle retainer usage requested before Dec 1984
TAYLOR, J R Babcock & Wilcox Co 84/07/24 STOLZ, J F Operating Reactors Branch 4 1p 25945 292 24X Fiche 50-000, 84/07/24, 8408070389

8408090010 Forwards SER based on util responses to 810210 Generic Ltr 81-14, "Seismic Qualification of Auxiliary Feedwater Sys " Emergency feedwater sys acceptable following upgrade mod
RIVENBARK, G W Operating Reactors Branch 4 84/07/26 GRIFFIN, J M
Arkansas Power & Light Co 2pp 25991 293 24X
Fiche 50-313, 84/07/26, 8408090010

--8408090013 SER re seismic qualification of emergency feedwater (EFW) sys EFW sys will have sufficient capability to withstand SSE & accomplish safety function following upgrade mod Technical evaluation rept encl
* Office of Nuclear Reactor Regulation, Director 84/07/26 9pp 25991 295 24X Fiche 50-313,84/07/26,8408090010

8408080152 Forwards Amend 83 to License DPR-51 & safety evaluation Amend modifies pressure-temp limit curves for hydrostatic test,normal heatup & normal cooldown
RIVENBARK,G W Operating Reactors Branch 4 84/07/27 GRIFFIN,J M
Arkansas Power & Light Co 7pp 25979 011 24X
Fiche 50-313,84/07/27,8408080152

--8408080158 Amend 83 to License DPR-51,modifying pressure-temp limit curves for hydrostatic test,normal heatup & normal cooldown
RIVENBARK,G W Operating Reactors Branch 4 84/07/27 9pp
25979 014 24X Fiche 50-313,84/07/27,8408080152

--8408080165 Safety evaluation supporting Amend 83 to License DPR-51
* Office of Nuclear Reactor Regulation, Director 84/07/27 4pp
25979 023 24X Fiche 50-313,84/07/27,8408080152

8408080288 Summary of 840712 meeting w/BtW Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24X Fiche 50-000,84/07/27,8408080288

8408070483 Forwards Rev 6 to QA manual - operations Return receipt requested
MARSHALL,J Arkansas Power & Light Co 84/07/31 Record Services Branch (Document Control Desk) 1p 25941 215 24X
Fiche 50-313,84/07/31,8408070483

--84080/0485 Rev 6 to QA manual - operations
* Arkansas Power & Light Co 84/05/30 158pp 25941 216 24X
Fiche 50-313,84/07/31,8408070483

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408140335 Forwards corrected cover sheets for Copies 1-6 of Rev 6 to "QA Manual Operations "
MARSHALL,J R Arkansas Power & Light Co 84/08/06 Record Services Branch (Document Control Desk) 7pp 26041 037 24X
Fiche 50-313,84/08/06,8408140335

8408140403 Forwards revised proposed resolutions of environ qualification SER deficiencies,per NRC 840426 comments Info documents results of listed issues not directly related to equipment,per 840426 meeting
MARSHALL,J R Arkansas Power & Light Co 84/08/06 STOLZ,J F
Operating Reactors Branch 4 160pp 26050 162 24X
Fiche 50-313,84/08/06,8408140403

8408140429 Forwards "Analyses of Capsule AN1-A,Arkansas Power & Light Co,Arkansas Nuclear One,Unit 1,Reactor Vessel Matl Surveillance Program "
MARSHALL,J R Arkansas Power & Light Co 84/08/06 STOLZ,J F
Operating Reactors Branch 4 1p 26049 301 24X
Fiche 50-313,84/08/06,8408140429

--8408140433 "Analyses of Capsule AN1-A,Arkansas Power & Light Co, Arkansas Nuclear One,Unit 1,Reactor Vessel Matl Surveillance Program "
LOWE,A L , AADLAND,J D , COLLINS,L L Babcock & Wilcox Co
BAW-1836 84/07/31 93pp 26049 302 24X Fiche 50-313,84/08/06, 8408140429

8408170061 Forwards corrected coversheet for Rev 6 to QA manual operations Revised coversheet reflects Control Copy 7
MARSHALL,J R Arkansas Power & Light Co 84/08/06 ANKRUM,G T QA Branch 4pp 26117 018 24X Fiche 50-313,84/08/06,8408170061

8408200303 Informs that response to Recommendation GL-2 re inadvertent closure to condensate storage tank isolation valve (NUREG-0737,Item II E 1 1) will be delayed until 840824 due to outage preparation work
MARSHALL,J R Arkansas Power & Light Co 84/08/10 STOLZ,J F
Operating Reactors Branch 4 1p 26133 358 24X
Fiche 50-313,84/08/10,8408200303

8408150180 Application to amend License DPR-51,modifying designation of areas in steam generator imperfections found & allowing sleeving of tubes Proprietary affidavit & BAW-1823P, "Once-Through Steam " encl Fee encl
GRIFFIN,J M Arkansas Power & Light Co 84/08/13 STOLZ,J F
Operating Reactors Branch 4 6pp 26067 132 24X
Fiche 50-313,84/08/13,8408150180

--8408150184 Proposed changes to Tech Spec Section 4 18 modifying designation of special areas in steam generator imperfections previously found & allowing sleeving of 10 steam generator tubes as part of demonstration program
* Arkansas Power & Light Co 84/08/13 20pp 26067 138 24X
Fiche 50-313,84/08/13,8408150180

8408220313 Application for amend to License DPR-51,revising Tech Specs to require addl restrictions & testing of low temp overpressure protection sys
GRIFFIN,J M Arkansas Power & Light Co 84/08/15 STOLZ,J F
Operating Reactors Branch 4 4pp 26189 338 24X
Fiche 50-313,84/08/15,8408220313

--8408220316 Proposed Tech Specs changes requiring addl restrictions & testing of low temp overpressure protection sys
* Arkansas Power & Light Co 84/08/15 5pp 26189 341 24X
Fiche 50-313,84/08/15,8408220313

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408310231 Forwards revs to proposed Tech Spec changes for NUREG-0737 items re containment radiation monitors & post-accident sampling,per Generic Ltr 83-37
GRIFFIN,J M Arkansas Power & Light Co 84/08/22 STOLZ,J F
Operating Reactors Branch 4 12pp 26320 314 24X
Fiche 50-313,84/08/22,8408310231

Q Inspection reports, IE Bulletins & correspondence

8408150372 Forwards IE Insp Repts 50-313/84-11 & 50-368/84-11 on 840326-29 & notice of violation One unresolved item re maint program identified in Paragraph 2 of insp rept should be addressed in detail
JOHNSON,E H Region 4, Office of Director 84/05/16 GRIFFIN,J M
Arkansas Power & Light Co 2pp 26075 181 24X
Fiche 50-313,84/05/16,8408150372

--8408150373 Notice of violation from insp on 840326-30
* Region 4, Office of Director 84/05/16 2pp 26075 183 24X
Fiche 50-313,84/05/16,8408150372

--8408150375 IE Insp Repts 50-313/84-11 & 50-368/84-11 on 840326-30 Violations noted failure to document & follow procedures for maint of MSIVs & HPCI valves
BOARDMAN,J R , JOHNSON,W D , JAUDON,J P Region 4, Office of Director 84/05/16 6pp 26075 185 24X Fiche 50-313,84/05/16, 8408150372

8408090150 Forwards IE Insp Repts 50-313/84-18 & 50-368/84-18 on 840801-30 No violations or deviations identified
JOHNSON,E H Region 4, Office of Director 84/07/11 GRIFFIN,J M
Arkansas Power & Light Co 2pp 25993 178 24X
Fiche 50-313,84/07/11,8408090150

--8408090160 IE Insp Repts 50-313/84-18 & 50-368/84-18 on 840601-30 No violations identified Major areas inspected maint, surveillance,operational safety verification & followup on IE bulletins & Generic Ltr 83-28
JOHNSON,W D , HARRELL,P H , MARTIN,L E Region 4, Office of Director 84/07/11 11pp 25993 180 24X Fiche 50-313,84/07/11, 8408090150

8408090121 Forwards IE Insp Repts 50-313/83-35 & 50-368/83-35 on 831205-08 & notice of violation W/o notice of violation
HUNTER,D R Region 4, Office of Director 84/07/17 GRIFFIN,J M
Arkansas Power & Light Co 2pp 25993 148 24X
Fiche 50-313,84/07/17,8408090121

--8408090130 IE Insp Repts 50-313/83-35 & 50-368/83-35 on 831205-08 Noncompliance noted failure to verify that matls conform to procurement documents
ELLERSHAW,L E , JOHNSON,W D , BARNES,I Region 4, Office of Director 84/02/21 9pp 25993 150 24X Fiche 50-313,84/07/17, 8408090121

8408150312 Ack receipt of 840615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/84-11 & 50-368/84-11 Future insp will determine if corrective actions achieve compliance
JOHNSON, E H Region 4, Office of Director 84/07/23 GRIFFIN, J M
Arkansas Power & Light Co 1p 26074 350 24X
Fiche 50-313, 84/07/23, 8408150312

--8408150317 Responds to NRC 840516 ltr re violations noted in IE Insp Repts 50-313/84-11 & 50-368/84-11 Requests add'l time to complete response to items noted in rept Response will be forwarded by 840627
MARSHALL, J R Arkansas Power & Light Co 84/06/15 DENISE, R P
Division of Resident, Reactor Project & Engineering Programs 1p
26074 351 24X Fiche 50-313, 84/07/23, 8408150312

8408160498 Forwards IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted
HUNTER, D R Region 4, Office of Director 84/07/23 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26107 318 24X
Fiche 50-313, 84/07/23, 8408160498

--8408160504 IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted Major areas inspected security program audit & physical barriers Details withheld (ref 10CFR73 21)
EVANS, C A , HULL, R E , MARTIN, L E Region 4, Office of Director
84/07/23 1p 26107 320 24X Fiche 50-313, 84/07/23, 8408160498

8408090022 Discusses IE insp on 831205-08 & forwards notice of violation & proposed imposition of civil penalty Util failed to apply controls for procurement & installation of safety-related fasteners, per App B to 10CFR50 W/o encl
COLLINS, J T Region 4, Office of Director 84/07/25 GRIFFIN, J M
Arkansas Power & Light Co 5pp 25992 089 24X
Fiche 50-313, 84/07/25, 8408090022

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co, of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408300154 Requests withdrawal of 840725 notice of violation & proposed imposition of civil penalty Corrective actions initiated prior to enforcement action, including augmenting QA staff, retraining QC staff & increasing vendor surveys
MARSHALL, J R Arkansas Power & Light Co 84/08/24 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp
26304 257 24X Fiche 50-313, 84/08/24, 8408300154

--8408300160 Licensee response to 840725 notice of violation Violation admitted & corrective actions outlined
Commissioners 84/08/24 12pp 26304 260 24X
Fiche 50-313, 84/08/24, 8408300154

--8408300166 Licensee answer protesting 840725 civil penalty Notice of violation fails to allow for corrective actions initiated prior to enforcement action
Commissioners 84/08/24 10pp 26304 272 24X
Fiche 50-313, 84/08/24, 8408300154

S Reportable occurrences, LERs & related correspondence

8408130190 LER 80-040/99X-1 on 801001, emergency hatch local leak rate test connections found uncapped, causing outer door to be bypassed by 3/4-inch connection Cause not stated Caps replaced & test procedures revised W/840803 ltr
ROGERS, P , MARSHALL, J R Arkansas Power & Light Co 84/08/03 3pp
26008 291 24X Fiche 50-313, 84/08/03, 8408130190

8408130326 LER 80-014/03X-1 on 800415, fire & smoke detector testing not completed within surveillance interval due to high radiation level Detectors tested at cold shutdown Tech Spec 4 19 revised W/840803 ltr
ROGERS, P , MARSHALL, J R Arkansas Power & Light Co 84/08/03 3pp
26006 331 24X Fiche 50-313, 84/08/03, 8408130326

8408240053 LER 82-017/03X-1 on 820714, while performing reactor bldg isolation & valve stroke test, control valve 3807 closed & failed to open due to circuit breaker trip Cause undetermined No action taken W/840810 ltr
ROGERS, P , MARSHALL, J R Arkansas Power & Light Co 82/07/14 2pp
26236 358 24X Fiche 50-313, 84/08/10, 8408240053

DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8408060118 Forwards changes to modified amended security plan Changes withheld (ref 10CFR73 21)
ALEXICH, M P Indiana & Michigan Electric Co 84/07/19
KEPPLER, J G Region 3, Office of Director 1p 25936 029 24X
Fiche 50-315, 84/07/19, 8408060118

8408060348 Forwards revised Page B-14 to modified amended security plan, per 10CFR50 54(p) Page withheld (ref 10CFR73 21)
ALEXICH, M P Indiana & Michigan Electric Co 84/07/19
KEPPLER, J G Region 3, Office of Director 1p 25936 096 24X
Fiche 50-315, 84/07/19, 8408060348

8408020020 Ack receipt of 840719 ltr re formal page changes to modified amended security plan Changes will be included as part of approved plan Future changes should ref 10CFR73 21 when requesting withholding
AXELSON, W L Region 3, Office of Director 84/07/26 ALEXICH, M P
Indiana & Michigan Electric Co 2pp 25883 148 24X
Fiche 50-315, 84/07/26, 8408020020

8408070060 Advises that 840719 changes to physical security plan consistent w/provisions of 10CFR50, 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/08/01 ALEXICH, M P
Indiana & Michigan Electric Co ALEXICH, M P American Electric Power Co , Inc 2pp 25949 335 24X Fiche 50-315, 84/08/01, 84080/0060

8408070272 Rev 3 to Procedure PMP 2080 EPP 012, "Initial Offsite Notification "
KRAUSE, D. Indiana & Michigan Electric Co 84/08/01 6pp
25949 203 24X Fiche 50-315, 84/08/01, 8408070272

8408070307 Rev 6 to Emergency Plan Implementing Procedure PMP 2080 EPP 008, "Initiating Manning of Emergency Response Facilities & Calling Off-Duty Plant Personnel "
* Indiana & Michigan Electric Co 84/08/01 13pp 25947 328 24X Fiche 50-315,84/08/01,8408070307

8408100094 Forwards responses to NRC 840508 request for addl info re detailed control room design review (DCRDR) Encls include functions of DCRDR teams,control room instrumentation & emergency response capability integration plan
ALEXICH,M P Indiana & Michigan Electric Co 84/08/06 DENTON,H R
Office of Nuclear Reactor Regulation, Director 26pp 25988 204 24X Fiche 50-315,84/08/06,8408100094

--8405010079 Summarizes 840329 meeting w/Westinghouse Owners Group re task analysis requirements of Suppl 1 to NUREG-0737 (Generic Ltr 82-33)
CLAYTON,H B Procedures & Systems Review Branch 84/04/05
ZIEMANN,D L Procedures & Systems Review Branch 17pp
25988 230 24X Fiche 50-315,84/08/06,8408100094

8408130321 Revs to Emergency Plan Implementing Procedures PMP 2081 EPP 021, "Activation & Operation of Operations Staging Area & Personnel Accountability" & PMP 2081 EPP 004, "Protective Action Guides (PAGs) & Protective Actions "
* Indiana & Michigan Electric Co 84/08/07 24pp 26006 001 24X Fiche 50-315,84/08/07,8408130321

8408170322 Forwards Suppl 2 to "App R Evaluation of Auxiliary Bldg HVAC Duct Penetration & Containment Seismic Gaps," providing justification for technical exemptions requested in 840615 ltr
ALEXICH,M P Indiana & Michigan Electric Co 84/08/13 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 26113 001 24X Fiche 50-315,84/08/13,8408170322

--8408170327 Suppl 2 to "App R Evaluation of Auxiliary Bldg HVAC Duct Penetration & Containment Seismic Gaps "
* Engineering Planning & Management, Inc 84/08/31 52pp
26113 003 24X Fiche 50-315,84/08/13,8408170322

8408210156 Rev 1 to Procedure PMP 2081 EPP 014, "Offsite Dose Assessments "
* Indiana & Michigan Electric Co 84/08/15 43pp 26147 078 24X Fiche 50-315,84/08/15,8408210156

P Operating license stage documents & correspondence

8405160248 Requests that inservice insp/inservice testing second 10-yr internal for both units begin on 860701,1 yr earlier than stated in 840315 ltr,contingent upon acceptance of listed code relief requests
HERING,R F Indiana & Michigan Electric Co 84/05/11 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 24485 069 24X Fiche 50-315,84/05/11,8405160248

8408010310 Notification of date & location change for 840815 meeting w/util in Bethesda,MD to discuss program for hydrogen control,equipment survivability & containment structural integrity Meeting originally scheduled for 840725
WIGGINTON,D L Operating Reactors Branch 1 84/06/29 VARGA,S A
Operating Reactors Branch 1 2pp 25872 317 24X
Fiche 50-315,84/06/29,8408010310

8408060076 Informs of temporary procedural change to ensure that plant operations consistent w/FSAR analysis assumptions for interim period,until proposed Tech Spec change re reactor coolant pump operability at hot zero power approved
ALEXICH,M P Indiana & Michigan Electric Co 84/07/30 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 25933 125 24X Fiche 50-315,84/07/30,8408060076

8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification
WIGGINTON,D L Operating Reactors Branch 1 84/07/30 Operating Reactors Branch 1 4pp 26143 265 24X Fiche 50-000,84/07/30, 8408160425

8408160188 Forwards results of review of NUREG-0737, Item II B 3 open items re post-accident sampling sys Mods will be completed & sys operational by Sept 1984
ALEXICH,M P Indiana & Michigan Electric Co 84/08/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 26092 036 24X Fiche 50-315,84/08/02,8408160188

8408140164 Responds to 840720 verbal request re effects of superheated steam following postulated main steam line break Util will participate in Westinghouse Owners Group activities & involvement expected to suppl internal review
ALEXICH,M P Indiana & Michigan Electric Co 84/08/03 DENTON,H R
Office of Nuclear Reactor Regulation, Director 7pp 26065 001 24X Fiche 50-315,84/08/03,8408140164

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408160494 Returns 840718 check which accompanied 840723 application for relief from certain ASME Code requirements Application subj to revised 10CFR170 Requests remission of required fee for application Discussion of fees encl
DIGGS,R M License Fee Management Branch 84/08/09 DOLAN,J
American Electric Power Service Corp 4pp 26124 337 24X
Fiche 50-315,84/08/09,8408160494

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408240188 Forwards status rept on inadequate core cooling instrumentation sys per B31219 request Rept addresses reactor vessel instrumentation sys,core exit thermocouples, subcooling margin monitor & NUREG-0737, Item II F 2
ALEXICH,M P Indiana & Michigan Electric Co 84/08/20 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp. 26227 355 24X Fiche 50-315,84/08/20,8408240188

8408230263 Forwards XN-NF-83-61, "DC Cook Unit 1 LOCA-ECCS Analysis for Extended Exposure" & proprietary XN-NF-84-25(P), "Mechanical Design Rept Suppl for DC Cook Unit 1 Extended Burnup Fuel Assemblies " Proprietary rept withheld
CHANDLER,J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
84/08/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 26204 028 24X Fiche 50-315,84/08/21,8408230263

--8408230266 "DC Cook Unit 1 LOCA-ECCS Analysis for Extended Exposure "
TAHVILI,T , KAYSER,W V , STOUT,R B Exxon Nuclear Co , Inc (subs of Exxon Corp) XN-NF-83-61 83/08/03 33pp 26204 033 24X
Fiche 50-315,84/08/21,8408230263

G Inspection reports, IE Bulletins & correspondence

8405160248 Requests that inservice insp/inservice testing second 10-yr internal for both units begin on 860701,1 yr earlier than stated in 840315 ltr,contingent upon acceptance of listed code relief requests
HERING,R F Indiana & Michigan Electric Co 84/05/11 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 24485 069 24X Fiche 50-315,84/05/11,8405160248

8408230204 Forwards IE Insp Repts 50-315/84-11 & 50-316/84-12 on 840604-08 No noncompliance noted
SHAFER,W D Region 3, Office of Director 84/07/24 DOLAN,J E
American Electric Power Service Corp DOLAN,J E Indiana & Michigan Electric Co 2pp 26214 035 24X Fiche 50-315,84/07/24,8408230204

--8408230211 IE Insp Repts 50-315/84-11 & 50-316/84-12 on 840604-08 No noncompliance noted Major areas inspected sys walkdown & print verification,surveillance,maint,inservice testing, work controls,calibr & operations review
WRIGHT,G C Region 3, Office of Director 84/07/24 10pp
26214 037 24X Fiche 50-315,84/07/24,8408230204

8407250227 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250227

8408080084 Submits supplemental response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller,Inc " Piping matls used in fabrication of chemical & vol control sys supplied by Ray Miller,Inc
ALEXICH,M P Indiana & Michigan Electric Co 84/08/01
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 67473 131 24X Fiche 50-315,84/08/01,8408080084

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408010333 IE Info Notice 84 59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 198 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408300181 Forwards Insp Repts 50-315/84-14 & 50-316/84-16 on 840723-27 No noncompliance noted
WALKER, R D Region 3, Office of Director 84/08/14 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 26313 263 24X Fiche 50-315, 84/08/14, 8408300181

--8408300188 Insp Repts 50-315/84-14 & 50-316/84-16 on 840723-27 No noncompliance or deviations noted Major areas inspected LERs, startup test results packages, Unit 2 Cycle 4 core power distribution limits & Unit 2 Cycle 5 core reload analysis
HELLER, J R , MCCORMICK-BARGE, REYES, L A Region 3, Office of Director 84/08/14 6pp 26313 265 24X Fiche 50-315, 84/08/14, 8408300181

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408280147 Discusses 840621 meeting w/util re SALP Repts 50-315/84-08 & 50-316/84-09 for period from Apr 1983 - Mar 1984 Summary of meeting, including list of attendees, encl as App A to SALP repts App final step in SALP assessment process
KEPPLER, J G Region 3, Office of Director 84/08/23 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 26259 078 24X Fiche 50-315, 84/08/23, 8408280147

--8408280155 App to SALP Repts 50-315/84-08 & 50-316/84-09 for period from Apr 1983 - Mar 1984 Summarizing 840621 meeting & including list of attendees
* Region 3, Office of Director 84/08/23 2pp 26259 080 24X Fiche 50-315, 84/08/23, 8408280147

S Reportable occurrences LERs & related correspondence

8408080536 LER 84-013-00 on 840706, discovered that fire watch not maintained in area fire retardant matls removed from previously protected conduit containing safety-related cables Fire watch patrol initiated W/840731 ltr
STIETZEL, J F Indiana & Michigan Electric Co SMITH, W G Midwest Electric Cooperative 84/07/31 3pp 25975 310 24X Fiche 50-315, 84/07/31, 8408080536

8408160527 LER 84 007-01 on 840528 coding error discovered in DETECTOR code analyzing raw flux map data Cause not stated Independent line-by-line review of coding changes will be performed W/840810 ltr
SAUM, M A , SMITH, W G Indiana & Michigan Electric Co 84/08/10 8pp 26108 032 24X Fiche 50-315, 84/08/10, 8408160527

8408210269 PNO III-84-065 on 840814 Unit 1 tripped from 100% due to failure of control room instrument distribution panel Failure caused reactor protection sys to lose flow in one coolant loop Panel replaced Tests performed for operability
WRIGHT, G , SHAFER, W Region 3, Office of Director 84/08/15 1p 26180 344 24X Fiche 50-315, 84/08/15, 8408210269

8408220496 LER 84-014-00 on 840716, nonlicensed operator mistakenly isolated north low head safety injection pump Caused by personnel error Procedure revised W/840815 ltr
BAKER, K R , SMITH, W G Indiana & Michigan Electric Co 84/08/15 3pp 26196 029 24X Fiche 50-315, 84/08/15, 8408220496

8408300505 LER 84-015-00 on 840728 & 29, Tech Spec 3 3 3 1, Action Statement 19 violated due to failure to complete daily survey of spent fuel storage area Caused by personnel error Written instructions improved W/840824 ltr
KRIEGEL, T A , SMITH, W G Indiana & Michigan Electric Co 84/08/24 2pp 26313 362 24X Fiche 50-315, 84/08/24, 8408300505

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

8408240296 Confirms actions to be taken by 840822 re results of 840618 licensed operator & senior operator requalification exams
KEPPLER, J G Region 3, Office of Director 84/08/21 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 3pp 26226 016 24X Fiche 50-315, 84/08/21, 8408240296

DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408060118 Forwards changes to modified amended security plan Changes withheld (ref 10CFR73 21)
ALEXICH, M P Indiana & Michigan Electric Co 84/07/19
KEPPLER, J G Region 3, Office of Director 1p 25936 029 24X Fiche 50-315, 84/07/19, 8408060118

8408060348 Forwards revised Page B-14 to modified amended security plan, per 10CFR50 54(p) Page withheld (ref 10CFR73 21)
ALEXICH, M P Indiana & Michigan Electric Co 84/07/19
KEPPLER, J G Region 3, Office of Director 1p 25936 096 24X Fiche 50-315, 84/07/19, 8408060348

8408020020 Ack receipt of 840719 ltr re formal page changes to modified amended security plan Changes will be included as part of approved plan Future changes should ref 10CFR73 21 when requesting withholding
AXELSON, W L Region 3, Office of Director 84/07/26 ALEXICH, M P Indiana & Michigan Electric Co 2pp 25883 148 24X Fiche 50-315, 84/07/26, 8408020020

8408070060 Advises that 840719 changes to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/08/01 ALEXICH, M P Indiana & Michigan Electric Co ALEXICH, M P American Electric Power Co , Inc 2pp 25949 335 24X Fiche 50-315, 84/08/01, 8408070060

8408070272 Rev 3 to Procedure PMP 2080 EPP 012, "Initial Offsite Notification "
KRAUSE, D Indiana & Michigan Electric Co 84/08/01 6pp 25949 203 24X Fiche 50-315, 84/08/01, 8408070272

8408070307 Rev 6 to Emergency Plan Implementing Procedure PMP 2080 EPP 008, "Initiating Manning of Emergency Response Facilities & Calling Off-Duty Plant Personnel "
* Indiana * Michigan Electric Co 84/08/01 13pp 25947 328 24X Fiche 50-315, 84/08/01, 8408070307

8408100094 Forwards responses to NRC 840508 request for addl info re detailed control room design review (DCRDR) Encls include functions of DCRDR teams, control room instrumentation & emergency response capability integration plan
ALEXICH, M P Indiana & Michigan Electric Co 84/08/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 26pp 25988 204
24X Fiche 50-315, 84/08/06, 8408100094

--8405010079 Summarizes 840329 meeting w/Westinghouse Owners Group re task analysis requirements of Suppl 1 to NUREG-0737 (Generic Ltr 82-33)
CLAYTON, H B Procedures & Systems Review Branch 84/04/05
ZIEMANN, D L Procedures & Systems Review Branch 17pp
25988 230 24X Fiche 50-315, 84/08/06, 8408100094

8408130321 Revs to Emergency Plan Implementing Procedures PMP 2081 EPP 021, "Activation & Operation of Operations Staging Area & Personnel Accountability" & PMP 2081 EPP 004, "Protective Action Guides (PAGs) & Protective Actions "
* Indiana & Michigan Electric Co 84/08/07 24pp 26006 001 24X Fiche 50-315, 84/08/07, 8408130321

8408170322 Forwards Suppl 2 to "App R Evaluation of Auxiliary Bldg HVAC Duct Penetration & Containment Seismic Gaps," providing justification for technical exemptions requested in 840615 ltr
ALEXICH, M P Indiana & Michigan Electric Co 84/08/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26113 001
24X Fiche 50-315, 84/08/13, 8408170322

--8408170327 Suppl 2 to "App R Evaluation of Auxiliary Bldg HVAC Duct Penetration & Containment Seismic Gaps "
* Engineering Planning & Management, Inc 84/08/31 52pp
26113 003 24X Fiche 50-315, 84/08/13, 8408170322

8408210156 Rev 1 to Procedure PMP 2081 EPP 014, "Offsite Dose Assessments "
* Indiana & Michigan Electric Co 84/08/15 43pp 26147 078 24X Fiche 50-315, 84/08/15, 8408210156

P Operating license stage documents & correspondence

8405160248 Requests that inservice insp/inservice testing second 10-yr interval for both units begin on 860701, 1 yr earlier than stated in 840315 ltr, contingent upon acceptance of listed code relief requests
HERING, R F Indiana & Michigan Electric Co 84/05/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 24485 069
24X Fiche 50-315, 81/05/11, 8405160248

8406080109 Forwards corrected Tech Spec Page 3/4 10 5 re position indicator channels shutdown, submitted w/840315 Tech Spec change request
HERING, R F Indiana & Michigan Electric Co 84/06/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 24856 084
24X Fiche 50-316, 84/06/04, 8406080109

--8406080113 Corrected Tech Spec Page 3/4 10 5 re position indicator channels shutdown
* Indiana & Michigan Electric Co 84/06/04 1p 24856 087 24X Fiche 50-316, 84/06/04, 8406080109

8408010310 Notification of date & location change for 840815 meeting w/util in Bethesda, MD to discuss program for hydrogen control, equipment survivability & containment structural integrity Meeting originally scheduled for 840725
WIGGINTON, D L Operating Reactors Branch 1 84/06/29 VARGA, S A
Operating Reactors Branch 1 2pp 25872 317 24X
Fiche 50-315, 84/06/29, 8408010310

8408060076 Informs of temporary procedural change to ensure that plant operations consistent w/FSAR analysis assumptions for interim period, until proposed Tech Spec change re reactor coolant pump operability at hot zero power approved
ALEXICH, M P Indiana & Michigan Electric Co 84/07/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 25933 125
24X Fiche 50-315, 84/07/30, 8408060076

8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification
WIGGINTON, D L Operating Reactors Branch 1 84/07/30 Operating
Reactors Branch 1 4pp 26143 265 24X Fiche 50-000, 84/07/30, 8408160425

8408160188 Forwards results of review of NUREG-0737 Item II B 3 open items re post-accident sampling sys Mods will be completed & sys operational by Sept 1984
ALEXICH, M P Indiana & Michigan Electric Co 84/08/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 26092 036
24X Fiche 50-315, 81/08/02, 8408160188

8408140164 Responds to 840720 verbal request re effects of superheated steam following postulated main steam line break Util will participate in Westinghouse Owners Group activities & involvement expected to suppl internal review
ALEXICH, M P Indiana & Michigan Electric Co 84/08/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 26065 001
24X Fiche 50-315, 84/08/03, 8408140164

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408090198 Forwards nonproprietary version of Rev 2 to XN-NF-84-21, "DC Cook, Unit 2, Cycle 5, 5% Steam Generator Tube Plugging Limiting Break LOCA/ECCS Analysis," per American Electric Power Svc Co request
CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 25972 038 24X Fiche 50-316, 84/08/07, 8408090198

--8408090209 Nonproprietary version of Rev 2 to "DC Cook, Unit 2 Cycle 5, 5% Steam Generator Tube Plugging Limiting Break LOCA/ECCS Analysis "
KAYSER, W V , CHANDLER, J C , STOUT, R B Exxon Nuclear Co , Inc (subs of Exxon Corp) XN-NF-84-21 (NP) R02 84/08/07 75pp
25972 039 24X Fiche 50-316, 84/08/07, 8408090198

8408160494 Returns 840718 check which accompanied 840723 application for relief from certain ASME Code requirements Application subj to revised 10CFR170 Requests remission of required fee for application Discussion of fees encl
DIGGS, R M License Fee Management Branch 84/08/09 DOLAN, J
American Electric Power Service Corp 4pp 26124 337 24X
Fiche 50-315, 84/08/09, 8408160494

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408240121 Notifies of plans to submit listed documents re PTSPWR2 code & ENC transient analysis methodology by 840831, per 840601 ltr App C for four-loop methodology will be initiated following NRC comments re three-loop methodology
ALEXICH, M P Indiana & Michigan Electric Co 84/08/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26228 214
24X Fiche 50-316, 81/08/20, 8408240121

8408240188 Forwards status rept on inadequate core cooling instrumentation sys, per 831219 request Rept addresses reactor vessel instrumentation sys, core exit thermocouples, subcooling margin monitor & NUREG-0737, Item II F 2
ALEXICH, M P Indiana & Michigan Electric Co 84/08/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 26227 355
24X Fiche 50-315, 84/08/20, 8408240188

G Inspection reports, IE Bulletins & correspondence

8405160248 Requests that inservice insp/inservice testing second 10-yr interval for both units begin on 860701, 1 yr earlier than stated in 840315 ltr, contingent upon acceptance of listed code relief requests
HERING, R F Indiana & Michigan Electric Co 84/05/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 24485 069
24X Fiche 50-315, 84/05/11, 8405160248

8408230204 Forwards IE Insp Repts 50-315/84-11 & 50-316/84-12 on 840604-08 No noncompliance noted
SHAFER, W D Region 3, Office of Director 84/07/24 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 2pp 26214 035 24X Fiche 50-315, 84/07/24, 8408230204

--8408230211 IE Insp Repts 50-315/84-11 & 50-316/84-12 on 840604-08 No noncompliance noted Major areas inspected sys walkdown & print verification, surveillance, maint, inservice testing, work controls, calibr & operations review
WRIGHT, G C Region 3, Office of Director 84/07/24 10pp
26214 037 24X Fiche 50-315, 84/07/24, 8408230204

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants ' Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408080084 Submits supplemental response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Piping matls used in fabrication of chemical & vol control sys supplied by Ray Miller, Inc
ALEXICH, M P Indiana & Michigan Electric Co 84/08/01
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5pp 67473 131 24X Fiche 50-315, 84/08/01, 8408080084

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 198 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408300181 Forwards Insp Repts 50-315/84-14 & 50-316/84-16 on 840723-27 No noncompliance noted
WALKER, R D Region 3, Office of Director 84/08/14 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 26313 263 24X Fiche 50-315, 84/08/14, 8408300181

--8408300188 Insp Repts 50-315/84-14 & 50-316/84-16 on 840723-27 No noncompliance or deviations noted Major areas inspected LERs, startup test results packages, Unit 2, Cycle 4 core power distribution limits & Unit 2, Cycle 5 core reload analysis
HELLER, J K , MCCORMICK-BARGE, REYES, L A Region 3, Office of Director 84/08/14 6pp 26313 265 24X Fiche 50-315, 84/08/14, 8408300181

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New [illegible] 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

' Info Notice 84-67, "Recent Snubber Inservice Testing W/ 'e Rates " Svc list encl
Division of Emergency Preparedness & Engineering
'ost 830103) 84/08/17 Consolidated Edison Co of New 122pg 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84 68 Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves ' Svc list encl
JORDAN, E L Division of Emergency Preparedness ? Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408280147 Discusses 840621 meeting w/util re SALP Repts 50-315/84-08 & 50-316/84-09 for period from Apr 1983 Mar 1984 Summary of meeting, including list of attendees encl as App A to SALP repts App final step in SALP assessment process
KEPPLER, J G Region 3, Office of Director 84/08/23 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 26259 078 24X Fiche 50-315, 84/08/23, 8408280147

--8408280155 App to SALP Repts 50-315/84-08 & 50-316/84 09 for period from Apr 1983 - Mar 1984 Summarizing 840621 meeting & including list of attendees
* Region 3, Office or Director 84/08/23 2pp 26259 080 24X Fiche 50-315, 84/08/23, 8408280147

S Reportable occurrences, LERs & related correspondence

8408060151 LER 84-017-00 on 840704, while in Mode 3, surveillance requirements of Tech Spec 3 3 1 1 not performed as required for intermediate-range ex-core detectors shiftly channel checks Procedures revised W/840726 ltr
BAKER, K R , SMITH, W G Indiana & Michigan Electric Co 84/07/26
2pp 25935 167 24X Fiche 50-316, 84/07/26, 8408060151

8408130307 LER 84-018-00 on 840709, following refueling outage, RPI for rods H-8 & K-10 misaligned Caused by variables affecting secondary coil stack voltages Unit placed in Mode 3 W/840808 ltr
BLIND, A A , SMITH, W G Indiana & Michigan Electric Co 84/08/08
2pp 26010 259 24X Fiche 50-316, 84/08/08, 8408130307

8408160127 LER 84-019-00 840710, reactor coolant pump removed from svc due to indication of problems Protective function channel was not tripped within specified time Procedures revised & personnel will be trained W/840809 ltr
BAKER, K R , SMITH, W G Indiana & Michigan Electric Co 84/08/09
2pp 26108 115 24X Fiche 50-316, 84/08/09, 8408160127

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

8408240296 Confirms actions to be taken by 840822 re results of 840618 licensed operator & senior operator requalification exams
KEPPLER, J G Region 3, Office of Director 84/08/21 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 3pp 26226 016 24X Fiche 50-315, 84/08/21, 8408240296

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8408170261 Rev 10 to Emergency Radiological Plan Implementing Procedure ERPIP 4 1 6, "Offsite Monitoring Team "
* Baltimore Gas & Electric Co 84/07/06 11pp 26115 343 24X Fiche 50-317, 84/07/06, 8408170261

8408150711 Forwards IE Safeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
BOWMAKER, N J Baltimore Gas & Electric Co 2pp 26079 017 24X Fiche 50-317, 84/07/27, 8408150711

--8408150715 Notice of violation from insp on 840611-15 Safeguards info deleted (ref 10CFR73 21 & 9 5)
MARTIN, T T Division of Engineering & Technical Programs
84/07/27 1p 26079 019 24X Fiche 50-317, 84/07/27, 8408150711

--8408150721 IE Safeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 Noncompliance noted failure to follow physical security plan implementing procedures Info deleted (ref 10CFR73 21 & 9 5)
BAILEY, R J , KEIMIG, R R Region 1, Office of Director 84/07/27
6pp 26079 020 24X Fiche 50-317, 84/07/27, 8408150711

8408200320 Forwards Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends revise licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan
JAFFE, D H Operating Reactors Branch 3 84/08/01 LUNDVALL, A E
Baltimore Gas & Electric Co 1p 26141 233 24X
Fiche 50-317, 84/08/01, 8408200320

--8408200325 Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively, revising licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan
MILLER, J R Operating Reactors Branch 3 84/08/01 4pp
26141 234 24X Fiche 50-317, 84/08/01, 8408200320

--8408200327 Safety evaluation supporting Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/01 2pp
26141 238 24X Fiche 50-317, 84/08/01, 8408200320

8408240015 Forwards Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends reflect administrative changes, addl fire protection instrumentation & change in area access control
JAFFE, D H Operating Reactors Branch 3 84/08/02 LUNDVALL, A E
Baltimore Gas & Electric Co 1p 26256 034 24X
Fiche 50-317, 84/08/02, 8408240015

--8408240017 Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively, reflecting administrative organization changes, installation of addl fire protection instrumentation & change in control of access to high radiation areas
MILLER, J R Operating Reactors Branch 3 84/08/02 30pp
26256 035 24X Fiche 50-317, 84/08/02, 8408240015

--8408240020 Safety evaluation supporting Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/02 3pp
26256 065 24X Fiche 50-317, 84/08/02, 8408240015

8408070343 Forwards plant-specific technical guidelines, required by Suppl 1 to NUREG-0737, to aid NRC in completing review of emergency procedures generation package, in response to 840614 request
LUNDVALL, A E Baltimore Gas & Electric Co 84/08/03 MILLER, J R
Operating Reactors Branch 3 6pp 25944 154 24X
Fiche 50-317, 84/08/03, 8408070343

8408150628 Notification of Significant Licensee Meeting 84-68 on 840808 in King of Prussia, PA to discuss revs to site security/contingency plans
KUSHNER, P L Region 1, Office of Director 84/08/08 Region 1, Office of Director 2pp 26102 356 24X Fiche 50-317, 84/08/08, 8408150628

8408240361 Forwards Insp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Significant safety concerns re operability of component cooling HX identified Issue resolved pending followup to stated actions per 840517 meeting
STAROSTECKI, R Division of Project & Resident Programs 84/08/08
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 26237 065 24X
Fiche 50-317, 84/08/08, 8408240361

--8408240363 Insp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Major areas inspected control room, accessible parts of plant structures, plant operations, radiation protection, physical security & fire protection
FOLEY, T , TRIMBLE, D C , WENZINGER, E C Region 1, Office of Director 84/07/31 13pp 26237 067 24X Fiche 50-317, 84/08/08, 8408240361

8408170086 Rev 11 to Emergency Response Plan Implementing Procedure ERPIP 3 0, "Immediate Action Procedures " W/840813 Rev 2 to table of contents
* Baltimore Gas & Electric Co 84/08/13 36pp 26119 033 24X
Fiche 50-317, 84/08/13, 8408170086

8408240272 Advises that 840510 Rev 4 to safeguards contingency plan consistent w/provisions of 10CFR50 54(p) & acceptable
MARTIN, T T Division of Engineering & Technical Programs 84/08/16
BOWMAKER, N J Baltimore Gas & Electric Co 3pp 26222 331 24X
Fiche 50-317, 84/08/16, 8408240272

P Operating license stage documents & correspondence

8406230301 THREE-DIMENSIONAL CALCULATIONS OF TRANSIENT FLUID-THERMAL MIXING IN THE DOWNCOMER OF THE CLAVERT CLIFFS-1 PLANT USING 3DLA-PTS
DALY, B J Los Alamos Scientific Laboratory FIN A-7306
NUREG/CR-3704 84/04/30 Division of Accident Evaluation 86pp
25131 319 24X Fiche 50-317, 84/04/30, 8406230301

8408070271 Responds to 840604 request for NRC concurrence in plans to train & qualify six senior control room operators as shift technical advisors Personnel entering program must be degreed or equivalent, per NUREG-0737, Item I A 1 1
MILLER, J R Operating Reactors Branch 3 84/07/26 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 25956 261 24X
Fiche 50-317, 84/07/26, 8408070271

8408020031 Informs of planned mod to C-E control element assembly guide tube wear sleeve Mod includes relocation of sleeve flare, sleeve expansion over full length of sleeve & relocation of crimp, providing resistance to axial motion
SCHERER, A E Combustion Engineering, Inc 84/07/27
RUBENSTEIN, L S Assistant Director for Core & Plant Systems 2pp
25880 258 24X Fiche 50-000, 84/07/27, 8408020031

8408230172 Forwards ORNL draft "Chapter 5 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Sequences," of pressurized thermal shock rept Comments requested by 840822
JOHNSON, C NRC - No Detailed Affiliation Given 84/07/30 WOODS, R
NRC - No Detailed Affiliation Given 1p 26230 028 24X
Fiche 50-317, 84/07/30, 8408230172

--8408230184 Forwards ORNL draft "Chapter 5 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Sequences," of pressurized thermal shock rept Comments requested by 840822
SELBY, D L Oak Ridge National Laboratory 84/07/30 JOHNSON, C E
NRC - No Detailed Affiliation Given KOENIG, J E Los Alamos Scientific Laboratory MIRSKY, S M Baltimore Gas & Electric Co
1p 26230 029 24X Fiche 50-317, 84/07/30, 8408230172

8408230191 Draft "Pressurized Thermal Shock Evaluation of Calvert Cliffs Unit 1 Nuclear Power Plant, Chapter 5 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Sequences "
* Oak Ridge National Laboratory 84/07/27 NRC - No Detailed Affiliation Given 169pp 26230 030 24X Fiche 50-317, 84/07/30, 8408230172

8408200320 Forwards Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends revise licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan
JAFFE, D H Operating Reactors Branch 3 84/08/01 LUNDVALL, A E
Baltimore Gas & Electric Co 1p 26141 233 24X
Fiche 50-317, 84/08/01, 8408200320

--8408200325 Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively, revising licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan
MILLER, J R Operating Reactors Branch 3 84/08/01 4pp
26141 234 24X Fiche 50-317, 84/08/01, 8408200320

--8408200327 Safety evaluation supporting Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/01 2pp
26141 238 24X Fiche 50-317, 84/08/01, 8408200320

8408240015 Forwards Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends reflect administrative changes, addl fire protection instrumentation & change in area access control
JAFFE, D H Operating Reactors Branch 3 84/08/02 LUNDVALL, A E
Baltimore Gas & Electric Co 1p 26256 034 24X
Fiche 50-317, 84/08/02, 8408240015

--8408240017 Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively, reflecting administrative organization changes, installation of addl fire protection instrumentation & change in control of access to high radiation areas
MILLER, J R Operating Reactors Branch 3 84/08/02 30pp
26256 035 24X Fiche 50-317, 84/08/02, 8408240015

--8408240020 Safety evaluation supporting Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/02 3pp
26256 065 24X Fiche 50-317, 84/08/02, 8408240015

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8408150298 Forwards IE Insp Repts 50-317/84-09 & 50-318/84-09 on 840423-27 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/18
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 26074 334 24X
Fiche 50-317, 84/07/18, 8408150298

--8408150301 Notice of violation from insp on 840423-27
* Region 1, Office of Director 84/07/18 2pp 26074 336 24X
Fiche 50-317, 84/07/18, 8408150298

--8408150305 IE Insp Repts 50-317/84-09 & 50-318/84-09 on 840423-27
Noncompliance noted failure to have radiochemistry procedures reviewed by PORC
STRUCKMEYER, R , JANG, J C , HOGAN, R T Region 1, Office of Director 84/07/17 12pp 26074 338 24X Fiche 50-317, 84/07/18, 8408150298

8408160102 Forwards IE Insp Repts 50-317/84-16 & 50-318/84-16 on 840604-08 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/24
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 26108 135 24X
Fiche 50-317, 84/07/24, 8408160102

--8408160107 Notice of violation from insp on 840604-08
* Region 1, Office of Director 84/07/24 1p 26108 137 24X
Fiche 50-317, 84/07/24, 8408160102

--8408160115 IE Insp Repts 50-317/84-16 & 50-318/84-16 on 840604-08
Violation noted failure to establish procedures for incomplete work followup on safety-related mod to auxiliary feedwater sys
BLUMBERG, N , BETTENHAUSEN, L Region 1, Office of Director 84/07/12 12pp 26108 138 24X Fiche 50-317, 84/07/24, 8408160102

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408150711 Forwards IE Safeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
BOWMAKER, N J Baltimore Gas & Electric Co 2pp 26079 017 24X
Fiche 50-317, 84/07/27, 8408150711

--8408150715 Notice of violation from insp on 840611-15 Safeguards info deleted (ref 10CFR73 21 & 9 5)
MARTIN, T T Division of Engineering & Technical Programs
84/07/27 1p 26079 019 24X Fiche 50-317, 84/07/27, 8408150711

--8408150721 IE Safeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 Noncompliance noted failure to follow physical security plan implementing procedures Info deleted (ref 10CFR73 21 & 9 5)
BAILEY, R J , KEIMIG, R R Region 1, Office of Director 84/07/27
6pp 26079 020 24X Fiche 50-317, 84/07/27, 8408150711

8408070074 Forwards check inadvertently omitted from 840306 ltr re inservice insp program
DENTON, R E Baltimore Gas & Electric Co 84/07/30 MILLER, J R
Operating Reactors Branch 3 1p 25949 280 24X
Fiche 50-317, 84/07/30, 8408070074

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830107) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, Overexposure of Diver in PWR Refueling Cavity ' Svc list encl
JORDAN, E L Division of Emergency Preparedness * Engineering
Response (Post 830107) 84 08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408240361 Forwards Insp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Significant safety concerns re operability of component cooling HX identified Issue resolved pending followup to stated actions per 840517 meeting
STAROSTECKI, R Division of Project * Resident Programs 84/08/08
LUNDVALL, A E Baltimore Gas * Electric Co 2pp 26237 065 24X
Fiche 50-317, 84/08/08, 8408240361

--8408240363 Insp Repts 50-317/84-08 * 50-318/84-08 on 840411-0515 Major areas inspected control room, accessible parts of plant structures, plant operations, radiation protection, physical security & fire protection
FOLEY, T , TRIMBLE, D C , WENZINGER, E C Region 1, Office of Director 84/07/31 13pp 26237 067 24X Fiche 50-317, 84/08/08, 8408240361

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness * Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness * Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness * Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, 'Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408270535 Nonroutine radiological environ operating rept re levels of Ag-110m in oyster samples collected during June 1984 Dose rates within acceptable limits
FUHRMAN, G R Baltimore Gas & Electric Co 84/07/31 Region 1, Office of Director 3pp 26279 227 24X Fiche 50-317, 84/07/31, 8408270535

S Reportable occurrences, LERs & related correspondence

8405290354 Forwards LASL draft rept on boron dilution event to determine safety significance of unmitigated boron dilution event Staff completion of review expected by 840515
JAFFE, D H Operating Reactors Branch 3 84/05/04 LUNDVALL, A E
Baltimore Gas & Electric Co 47pp 24695 275 24X
Fiche 50-317, 84/05/04, 8405290354

8408150188 LER 83-009/03X-3 on 830210, review of Units 1 & 2 snubber surveillance test procedures revealed that snubber 2-15-10 not included in Unit 2 Tech Specs & that missed surveillance occurred on snubber 1-15-8 W/840803 ltr
FARRELL, C V , RUSSELL, L D Baltimore Gas & Electric Co 84/07/30
3pp 26075 350 24X Fiche 50-317, 84/07/30, 8408150188

8408310365 Forwards "Events Involving Fires or Other Related Abnormalities in Motor Control Ctrs W/Aluminum Bus Bars," technical review rept Further actions re issue not warranted at present
ASHE, F Reactor Operations Analysis Branch 84/08/06 SEYFRIT, K V Reactor Operations Analysis Branch 1p 26350 295 24X
Fiche 50-317 84/08/06, 8408310365

--8408310370 "Events Involving Fires or Other Related Abnormalities in Motor Control Ctrs W/Aluminum Bus Bars," technical review rept
ASHE, F Reactor Operations Analysis Branch 84/08/06 3pp
26350 296 24X Fiche 50-317 84/08/06 8408310365

8408290258 LER 84-007-00 on 840721, during monthly surveillance test of ESF actuation sys, power lost on 4 160-volt emergency bus Caused by personnel inadvertently depressing incorrect test button Bus reenergized Button relabeled W/8408223 ltr
LOHR, J , RUSSELL, L B Baltimore Gas & Electric Co 84/08/23 3pp
26295 056 24X Fiche 50-317, 84/08/23, 8408290258

DOCKET 50 318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408170261 Rev 10 to Emergency Radiological Plan Implementing Procedure ERPIP 4 1 6, "Offsite Monitoring Team "
* Baltimore Gas & Electric Co 84/07/06 11pp 26115 343 24X
Fiche 50-317, 84/07/06, 8408170261

8408150711 Forwards IE Safeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
BOWMAKER, N J Baltimore Gas & Electric Co 2pp 26079 017 24X
Fiche 50-317, 84/07/27, 8408150711

--8408150715 Notice of violation from insp on 840611-15 Safeguards info deleted (ref 10CFR73 21 & 9 5)
MARTIN, T T Division of Engineering & Technical Programs
84/07/27 1p 26079 019 24X Fiche 50-317, 84/07/27, 8408150711

--8408150721 IE Safeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 Noncompliance noted failure to follow physical security plan implementing procedures Info deleted (ref 10CFR73 21 & 9 5)
BAILEY, R J Region 1, Office of Director 84/07/27 6pp
26079 020 24X Fiche 50-317, 84/07/27, 8408150711

8408200320 Forwards Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends revise licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan
JAFFE, D H Operating Reactors Branch 3 84/08/01 LUNDVALL, A E
Baltimore Gas & Elertric Co 1p 26141 233 24X
Fiche 50-317, 84/08/01, 8408200320

--8408200325 Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively, revising licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan
MILLER, J R Operating Reactors Branch 3 84/08/01 4pp
26141 234 24X Fiche 50-317, 84/08/01, 8408200320

--8408200327 Safety evaluation supporting Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/01 2pp
26141 238 24X Fiche 50-317, 84/08/01, 8408200320

8408240015 Forwards Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends reflect administrative changes, addl fire protection instrumentation & change in area access control Related correspondence
JAFFE, D H Operating Reactors Branch 3 DSB 619 84/08/02
LUNDVALL, A E Baltimore Gas & Electric Co 1p 26256 034 24X
Fiche 50-317, 84/08/02, 8408240015

--8408240017 Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively, reflecting administrative organization changes, installation of addl fire protection instrumentation & change in control of access to high radiation areas
MILLER, J R Operating Reactors Branch 3 84/08/02 30pp
26256 035 24X Fiche 50-317, 84/08/02, 8408240015

--8408240020 Safety evaluation supporting Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/02 3pp
26256 065 24X Fiche 50-317, 84/08/02, 8408240015

8408070343 Forwards plant-specific technical guidelines, required by Suppl 1 to NUREG-0737, to aid NRC in completing review of emergency procedures generation package, in response to 840614 request
LUNDVALL, A E Baltimore Gas & Electric Co 84/08/03 MILLER, J R
Operating Reactors Branch 3 6pp 25944 154 24X
Fiche 50-317, 84/08/03, 8408070343

8408150628 Notification of Significant Licensee Meeting 84-68 on 840808 in King of Prussia, PA to discuss revs to site security/contingency plans
KUSHNER, W L Region 1, Office of Director 84/08/08 Region 1, Office of Director 2pp 26102 356 24X Fiche 50-317, 84/08/08, 8408150628

8408240361 Forwards Insp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Significant safety concerns re operability of component cooling HX identified Issue resolved pending followup to stated actions per 840517 meeting
STAROSTECKI, R Division of Project & Resident Programs 84/08/08
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 26237 065 24X
Fiche 50-317, 84/08/08, 8408240361

--8408240363 Insp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Major areas inspected control room, accessible parts of plant structures, plant operations, radiation protection, physical security & fire protection
FOLEY, T Region 1, Office of Director 84/07/31 13pp
26237 067 24X Fiche 50-317, 84/08/08, 8408240361

8408170086 Rev 11 to Emergency Response Plan Implementing Procedure ERPIP 3 0, "Immediate Action Procedures " W/840813 Rev 2 to table of contents
* Baltimore Gas & Electric Co 84/08/13 36pp 26119 033 24X
Fiche 50-317, 84/08/13, 8408170086

8408240272 Advises that 840510 Rev 4 to safeguards contingency plan consistent w/provisions of 10CFR50 54(p) & acceptable
MARTIN, T T Division of Engineering & Technical Programs 84/08/16
BOWMAKER, N J Baltimore Gas & Electric Co 3pp 26222 331 24X
Fiche 50-317, 84/08/16, 8408240272

P Operating license stage documents & correspondence

8408070271 Responds to 840604 request for NRC concurrence in plans to train & qualify six senior control room operators as shift technical advisors Personnel entering program must be degreed or equivalent, per NUREG-0737, Item I A 1 1
MILLER, J R Operating Reactors Branch 3 84/07/26 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 25956 261 24X
Fiche 50-317, 84/07/26, 8408070271

8408200320 Forwards Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends revise licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan
JAFFE, D H Operating Reactors Branch 3 84/08/01 LUNDVALL, A E
Baltimore Gas & Electric Co 1p 26141 233 24X
Fiche 50-317, 84/08/01, 8408200320

--8408200325 Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively, revising licenses to include latest revs to security plan, safeguards contingency plan & guard training qualification plan
MILLER, J R Operating Reactors Branch 3 84/08/01 4pp
26141 234 24X Fiche 50-317, 84/08/01, 8408200320

--8408200327 Safety evaluation supporting Amends 95 & 76 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/01 2pp
26141 238 24X Fiche 50-317, 84/08/01, 8408200320

8408240015 Forwards Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends reflect administrative changes, addl fire protection instrumentation & change in area access control
JAFFE, D H Operating Reactors Branch 3 84/08/02 LUNDVALL, A E
Baltimore Gas & Electric Co 1p 26256 034 24X
Fiche 50-317, 84/08/02, 8408240015

--8408240017 Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively, reflecting administrative organization changes, installation of addl fire protection instrumentation & change in control of access to high radiation areas
MILLER, J R Operating Reactors Branch 3 84/08/02 30pp
26256 035 24X Fiche 50-317, 84/08/02, 8408240015

--8408240020 Safety evaluation supporting Amends 96 & 77 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/02 3pp
26256 065 24X Fiche 50-317, 84/08/02, 8408240015

DOCKETED ITEMS

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8408150298 Forwards IE Insp Repts 50-317/84-09 & 50-318/84-09 on 840423-27 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/18
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 26074 334 24X
Fiche 50-317, 84/07/18, 8408150298

--8408150301 Notice of violation from insp on 840423-27
* Region 1, Office of Director 84/07/18 2pp 26074 336 24X
Fiche 50-317, 84/07/18, 8408150298

--8408150305 IE Insp Repts 50-317/84-09 & 50-318/84-09 on 840423-27
Noncompliance noted failure to have radiochemistry procedures reviewed by PORC
STRUCKMEYER, R , JANG, J C , NOGAN, R T Region 1, Office of Director 84/07/17 12pp 26074 338 24X Fiche 50-317, 84/07/18, 8408150298

8408160102 Forwards IE Insp Repts 50-317/84-16 & 50-318/84-16 on 840604-08 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/24
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 26108 135 24X
Fiche 50-317, 84/07/24, 8408160102

--8408160107 Notice of violation from insp on 840604-08
* Region 1, Office of Director 84/07/24 1p 26108 137 24X
Fiche 50-317, 84/07/24, 8408160102

--8408160115 IE Insp Repts 50-317/84-16 & 50-318/84-16 on 840604-08
Violation noted failure to establish procedures for incomplete work followup on safety-related mod to auxiliary feedwater sys
BLUMBERG, N , BETTENHAUSEN, L Region 1, Office of Director 84/07/12 12pp 26108 138 24X Fiche 50-317, 84/07/24, 8408160102

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408150711 Forwards IE Safeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
BOWHAKER, N J Baltimore Gas & Electric Co 2pp 26079 017 24X
Fiche 50-317, 84/07/27, 8408150711

--8408150715 Notice of violation from insp on 840611-15 Safeguards info deleted (ref 10CFR73 21 & 9 5)
MARTIN, T T Division of Engineering & Technical Programs
84/07/27 1p 26079 019 24X Fiche 50-317, 84/07/27, 8408150711

--8408150721 IE Safeguards Insp Repts 50-317/84-17 & 50-318/84-17 on 840611-15 Noncompliance noted failure to follow physical security plan implementing procedures Info deleted (ref 10CFR73 21 & 9 5)
BAILEY, R J , KEIMIG, R R Region 1, Office of Director 84/07/27
6pp 26079 020 24X Fiche 50-317, 84/07/27, 8408150711,

8408070074 Forwards check inadvertently omitted from 840306 ltr re inservice insp program
DENTON, R E Baltimore Gas & Electric Co 84/07/30 MILLER, J R
Operating Reactors Branch 3 1p 25949 280 24X
Fiche 50-317, 84/07/30, 8408070074

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408240361 Forwards Insp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Significant safety concerns re operability of component cooling HX identified Issue resolved pending followup to stated actions per 840517 meeting
STAROSTECKI, R Division of Project & Resident Programs 84/08/03
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 26237 065 24X
Fiche 50-317, 84/08/08, 8408240361

--8408240363 Insp Repts 50-317/84-08 & 50-318/84-08 on 840411-0515 Major areas inspected control room, accessible parts of plant structures, plant operations, radiation protection, physical security & fire protection
FOLEY, T , TRIMBLE, D C , WENZINGER, E C Region 1, Office of Director 84/07/31 13pp 26237 067 24X Fiche 50-317, 84/08/08, 8408240361

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408270535 Nonroutine radiological environ operating rept re levels of Ag-110m in oyster samples collected during June 1984 Dose rates within acceptable limits
FUHRMAN, G R Baltimore Gas & Electric Co 84/07/31 Region 1, Office of Director 3pp 26279 227 24X Fiche 50-317, 84/07/31, 8408270535

S Reportable occurrences, LERs & related correspondence

8405290354 Forwards LASL draft rept on boron dilution event to determine safety significance of unmitigated boron dilution event Staff completion of review expected by 840515
JAFFE, D H Operating Reactors Branch 3 84/05/04 LUNDVALL, A E
Baltimore Gas & Electric Co 47pp 24695 275 24X
Fiche 50-317, 84/05/04, 8405290354

8408310343 Forwards Engineering Evaluation Rept AFOD/E415, "Overcooling Transient "
IMBRO,E V Reactor Operations Analysis Branch 84/06/06
SEYFRIT,K V Reactor Operations Analysis Branch 1p 25867 353
24X Fiche 50-318 84/06/06 8408010343

8408010345 Engineering Evaluation Rept AFOD/E415, "Overcooling Transient "
IMBRO E Director s Office 84 06/06 5pp 25867 354 24X
Fiche 50-318,84/06/06,8408010343

8408150395 LER 84-006-00 on 840709,while in Mode 1,unidentified reactor coolant leakage determined greater than 1 0 gpm Caused by inservice fatique induced cracked weld Defective section of control bleedoff pipe replaced W/840806 ltr
DARLING,S S , RUSSELL L B Baltimore Gas & Electric Co 84/08/06
4pp 26077 336 24X Fiche 50-318,84/08/06,8408150395

8408310365 Forwards "Events Involving Fires or Other Related Abnormalities in Motor Control Ctrs W/Aluminum Bus Bars," technical review rept Further actions re issue not warranted at present
ASHE,F Reactor Operations Analysis Branch 84/08/06 SEYFRIT,K V
Reactor Operations Analysis Branch 1p 26350 295 24X
Fiche 50-317,84/08/06,8408310365

--8408310370 "Events Involving Fires or Other Related Abnormalities in Motor Control Ctrs W/Aluminum Bus Bars," technical review rept
ASHE,F Reactor Operations Analysis Branch 84/08/06 3pp
26350 296 24X Fiche 50-317,84/08/06,8408310365

8408200492 LER 83-065/03X-1 on 831202 ' 10,erratic metrascope indication identified failed reed switch position transmitter stacks Stacks declared inoperable Transmitters replaced W/840813 ltr
RAYNOR,J W , RUSSELL,L B Baltimore Gas & Electric Co 84/08/13
2pp 26139 015 24X Fiche 50-318,84/08/13,8408200492

8408200512 LER 83-075/03X-1 on 831210,intermittent failure in metrascope control element assembly position indication sys resulted in out of sequence alarms Caused by reed stack position failure Reed stack replaced W/840813 ltr
RAYNOR,J , RUSSELL,L B Baltimore Gas ? Electric Co 84/08/13
2pp 26138 171 24X Fiche 50-318,84/08/13,8408200512

8408310042 LER 83 019/03L-1 on 830909,pinhole leak discovered in reactor coolant charging line weld Caused by line vibration Restraint installed & repair weld completed W/840823 ltr
PIERINGER,P , REID,K , RUSSELL,L B Baltimore Gas & Electric Co
84/08/23 3pp 26333 360 24X Fiche 50-318,84/08/23,8408310042

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8408090100 Rev 2 to Emergency Plan Implementing Procedure 1054 28, "Activation of Technical Support Ctr " W/840803 transmittal memo
* General Public Utilities - GPU Service Corp 84/07/27 7pp
25973 115 24X Fiche 50-320 84/07/27,8408090100

8408060166 Forwards summary of present or proposed fire protection features for sys required to maintain or monitor cold shutdown,in response to 840518 request Tech Spec change not necessary,as present level of fire protection sufficient
KANGA,D K General Public Utilities - GPU Service Corp 84/07/31
SNYDER,B J TMI Program Office 8pp 25925 277 24X
Fiche 50-320,84/07/31,8408060166

8408140197 Revised emergency plan implementing procedures including Rev 11 to 1054 6 re addl assistance & notification,Rev 6 to 1054 1 re unusual event & Rev 1 to 1054 20 re personnel/ vehicle monitoring & decontamination
BEAVER,J R General Public Utilities - GPU Service Corp 84/08/08
70pp 26044 258 24X Fiche 50-320,84/08/08,8408140197

8408230382 Rev 9 to Emergency Plan Implementing Procedure 1004 27, "Activation of Emergency Operations Facility "
* General Public Utilities - GPU Service Corp 84/08/08 31pp
26205 319 24X Fiche 50-289,84/08/08,8408230382

8408160165 Informs of refund of fees from 840727 application for exemption from certain annual exercise requirements of 10CFR50,App E & 840604 application to correct error in Tech Spec 3 & 7 Fee assessment info encl
MILLER,W D License Fee Management Branch 84/08/10 HUXILL,H D
General Public Utilities - GPU Service Corp 3pp 26124 352 24X
Fiche 50-289,84/08/10 8408160165

8408210320 Revised emergency plan implementing procedures,including 1054 36 re emergency assembly area & 1059 re emergency preparedness drills W/840814 transmittal memo
* General Public Utilities - GPU Service Corp 84/08/14 4pp
26179 127 24X Fiche 50-320,84/08/14,8408210320

G Adjudicatory correspondence

8408010209 Notice of issuance of amend to order modifying license requirements imposed by B00211 order & motion to conform proposed Tech Specs in accordance therewith Certificate of Svc encl
CHANDLER,L J Hearing Branch 2 DSB 675 84/07/25 Atomic Safety and Licensing Board Panel 77pp 25856 056 24X
Fiche 50-320,84/07/25,8408010209

8408030078 Memorandum ' order granting NRC 840718 motion to conform proposed Tech Specs w/Director,NRR 840615 amend of order Served on 840802
WOLFE,J F Atomic Safety and Licensing Board Panel DSB 726
84/07/31 Office of the Executive Legal Director 15pp
25907 001 24X Fiche 50-320,84/07/31,8408030078

8408070418 Response supporting staff 840725 motion to conform to proposed Tech Specs per 840717 amend of B00211 order Certificate of Svc encl
RIDGWAY,D A Metropolitan Edison Co RIDGWAY,D A Shaw, Pittman, Potts & Trowbridge DSB 767 84/08/01 Atomic Safety and Licensing Board Panel 5pp 25942 145 24X Fiche 50-320,84/08/01, 8408070418

8408070470 Response supporting NRC 840718 motion to conform proposed Tech Specs in accordance w/840615 amend of order re retraining & replacement training Certificate of Svc encl
RIDGWAY,D A Metropolitan Edison Co RIDGWAY,D A Shaw, Pittman, Potts & Trowbridge DSB 764 84/08/01 Atomic Safety and Licensing Board Panel 5pp 25941 195 24X Fiche 50-320,84/08/01, 8408070470

8408200580 Expresses dissatisfaction w/staff conclusions re author in Suppl 5 to NUREG-0680 concerning RCS leak rate tests Conclusion that author involved or implicated in indictment misleading & unfair NRC conclusions should not be adopted
SEELINGER,J L Affiliation Not Assigned DSB 163 84/08/09
PALLADINO,N J Commissioners 2pp 26137 138 24X
Fiche 50-289,84/08/09,8408200580

8408140449 Petition for revocation of license on basis of deficient character licensee record of wrongdoing directly related to fundamental character flaws inherent within company Certificate of Svc encl
WAMBACH,P C , SHUMAKER,J Pennsylvania, Commonwealth of,
BORDILL,P Women's International League for Peace & Freedom DSB 007 84/08/13 Commissioners 200pp 26061 023 24X
Fiche 50-000,84/08/13,8408140449

8408200521 Protests ref to author in Suppl 5 to NUREG-0680 as one of five util mgt personnel involved or implicated in indictment Staff accusation improper & damaging to author reputation Requests withdrawal of findings
KUNDER,G A Affiliation Not Assigned DSB 162 84/08/13
PALLADINO,N J Commissioners 2pp 26136 361 24X
Fiche 50-289,84/08/13,8408200521

8408170291 Memorandum & order responding to NRC staff notice of issuance of amend of order & granting NRC staff motion to conform proposed Tech Specs in accordance therewith Served on 840816
WOLF,J F Atomic Safety and Licensing Board Panel DSB 093
84/08/15 Office of the Executive Legal Director 4pp
26115 117 24X Fiche 50-320,84/08/15,8408170291

8408240250 Forwards supplemental pages for 840813 petition for revocation of license of GPU on basis of deficient character
DORSHOW,J Three Mile Island Alert DSB 258 84/08/22
Commissioners 1p 26223 018 24X Fiche 50-000,84/08/22,
8408240250

--8408240257 Supplemental pages to petition for revocation of license on basis of deficient character Certificate of Svc encl
* General Public Utilities - GPU Service Corp 84/08/13
Atomic Safety and Licensing Board Panel 43pp 26223 019 24X
Fiche 50-000,84/08/22,8408240250

H General correspondence

8408080082 Responds to 810611 ltr to Palladino commenting on 10CFR50.54 permitting deviations from Tech Specs in emergency & requesting regulation be canceled lists circumstances which must exist before rule can be used
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/07/26 YOUNG,C Affiliation Not Assigned 14pp 25978 264
24X Fiche 50-320,84/07/26,8408080082

--8408080087 Reaffirms recommendations stated in 840503 ltr re canceling regulations permitting licensee to deviate from Tech Specs in emergency & ensuring that president of facility implement policy to operate in accordance w/OL & Tech Specs
YOUNG,C Affiliation Not Assigned 84/06/14 PALLADINO,N J
Commissioners 8pp 25978 276 24X Fiche 50-320,84/07/26,
8408080082

8408090220 Urges cancellation of 10CFR50.54(y) & (q) Licensees should be required to follow Tech Specs when operating commercial nuclear power plants
YOUNG,C Affiliation Not Assigned 84/06/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25971 241 24X
Fiche 50-320,84/06/06,8408090220

8408220390 Protests unfair treatment indicated in staff rept on NUREG-0680,Suppl 5 re Facility restart Conclusions re RCS leak tests unfair Refusal to endorse NRC conclusions requested Memo dtd 781020 to shift supervisors encl
FLOYD,J R Affiliation Not Assigned 84/06/13 PALLADINO,N J
Commissioners 2pp 26184 336 24X Fiche 50-289,84/06/13,
8408220390

8408240225 Advises that all future correspondence to director of facility should be addressed to FR Standerfer
KANGA,B K General Public Utilities - GPU Service Corp 84/08/14
SNYDER,B J TMI Program Office 1p 26236 313 24X
Fiche 50-320,84/08/14,8408240225

P Operating license stage documents & correspondence

8408310129 Requests exemption from provisions of 10CFR170 Exemption would allow diversion of necessary funds to facilitate expeditious cleanup operation Related correspondence
KANGA,B K General Public Utilities - GPU Service Corp DSB 722
84/07/13 DIRCKS,W J Office of the Executive Director for Operations 2pp 26352 026 24X Fiche 50-320,84/07/13,8408310129

8408010049 Forwards safety review of head removal program,per 840309 request for approval Program acceptable
SNYDER,B J TMI Program Office 84/07/17 KANGA,B K General
Public Utilities - GPU Service Corp 3pp 25870 335 24X
Fiche 50-320,84/07/17,8408010049

--8408010051 Safety review of head removal program Program acceptable
* TMI Program Office 84/07/17 37pp 25870 338 24X
Fiche 50-320,84/07/17,8408010049

8408010105 Concurs w/util request to delete requirement for isolation of reactor bldg air coolers during load handling operations Util should submit,for approval,procedures implementing cooling water & boron limits
GRANT,P J TMI Program Office 84/07/17 KANGA,B K General
Public Utilities - GPU Service Corp 1p 25873 359 24X
Fiche 50-320,84/07/17,8408010105

8408030211 Advises that requests for exemption from 10CFR50,App A, Criterion 56 acceptable w/minor changes Alternate design should be applied to requirements of Criterion 55, "RCPB Penetrating Containment "
SNYDER,B J TMI Program Office 84/07/17 KANGA,B K General
Public Utilities - GPU Service Corp 3pp 25921 279 24X
Fiche 50-320,84/07/17,8408030211

--8408030215 Amend of order modifying proposed Tech Specs by incorporating or modifying specs required to be in place before reactor vessel head removed
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/07/17 General Public Utilities - GPU Service Corp 6pp
25921 282 24X Fiche 50-320,84/07/17,8408030211

--8408030218 Exemption from requirements of 10CFR50,App A,Criteria 2, 50 & 51 Exemption does not authorize change in effluent types or total amounts nor increase in power level & will not result in any significant environ impact
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/07/17 General Public Utilities - GPU Service Corp 5pp
25921 288 24X Fiche 50-320,84/07/17,8408030211

--8408030230 Safety & ajdat of tech sp re use of alternate design for 10CFR50 app A criteria 55 & 56 (closed license prop ed penetration configuration acceptable
* TMI Program Office 84/07/17 7pp 5pcl 243 24X
Fiche 50-320,84/07/17,8408030211

--8408030233 Exemption from requirements of 10CFR50 App A Criterion 57 Exemption does not authorize change in effluent types or total amount nor increase in power level & will not result in any significant environ impact
DENTON,H R Office of Nuclear Reactor Regulation Director
84/07/17 General Public Utilities - GPU Service Corp 6pp
25921 288 24X Fiche 50-320,84/07/17,8408030211

--8408030236 Safety evaluation supporting licensee request for rev of proposed Tech Specs re containment integrity,core alteration,loss-to-ambient boron concentration,control assemblies & neutron monitoring instrumentation
* Office of Nuclear Reactor Regulation Director 84/07/17
11pp 25921 301 24X Fiche 50-320,84/07/17,8408030211

--8408030238 Proposed Tech Specs re containment integrity,channe calibr,channel check,core alteration,loss-to-ambient,boron concentration,control assemblies & neutron monitoring instrumentation
* NRC No Detailed Affiliation Given 84/07/17 27pp
25921 315 24X Fiche 50-320,84/07/17,8408030211

--8408030231 Notice of environ assessment & findings of no significant environ impact transmittal forms encl
* NRC - No Detailed Affiliation Given 84/07/17 10pp
25921 342 24X Fiche 50-320,84/07/17,8408030211

8408010100 Concurs w/licensee assertions re definition of transfer of gaseous radwaste Tech Spec do not require shutdown of air filtration/purification sys when auxiliary & fuel handling sys down
GRANT,P J TMI Program Office 81/07/20 KANGA,B K General
Public Utilities - GPU Service Corp 1p 25873 360 24X
Fiche 50-320,84/07/20,8408010100

8408310090 Forwards Rev 21 to recovery operations plan in response to Recovery Operations Plan Change Requests 20 & 22 re deletion of operating pressure band for standby pressure control sys inservice nitrogen supply bank
GRANT,P J TMI Program Office 84/07/23 KANGA,B K General
Public Utilities - GPU Service Corp 4pp 25897 067 24X
Fiche 50-320,84/07/23,8408310090

8408010212 Responds to 840531 & 0714 ltrs forwarding safety evaluation & addendum describing addl hardware improvements to support proposed operation of internals index fixture water processing sys
GRANT,P J TMI Program Office 84/07/21 KANGA,B K General
Public Utilities - GPU Service Corp 7pp 25897 159 24X
Fiche 50-320,84/07/24,8408010242

8408010328 Informs that licensee mods to reactor bldg polar crane trolley limit switches & bumper stops conform to ANSI B30.2 1976 & acceptable Encl licensee safety evaluation also acceptable
POINDEXTER,T C TMI Program Office 84/07/24 TMI Program
Office 1p 25872 305 24X Fiche 50-320,84/07/24,8408010328

--8408010327 Forwards "Safety Evaluation for Polar Crane Trolley Limit Switch Bypass & Bumper Mod " per NRC request Mods permit reactor vessel head to be centered over storage stand prior to lowering into positioning for storage
ROGAN,R E General Public Utilities - GPU Service Corp 84/06/13
BARRETT,L H TMI Program Office 1p 25872 306 24X
Fiche 50-320,84/07/24,8408010328

--8408010331 "Safety Evaluation for Polar Crane Trolley Switch Bypass & Bumper Mod "
* General Public Utilities - GPU Service Corp 84/06/13 5pp
25872 307 24X Fiche 50-320,84/07/24,8408010328

8408010209 Notice of issuance of amend to order modifying license requirements imposed by 801211 order & motion to conform proposed Tech Specs in accordance the with Certificate of Svc encl
CHANDLER,L Hearing Branch 2 DSB 675 84/07/25 Atomic
Safety and Licensing Board Panel 7/pp 25856 056 24X
Fiche 50-320,84/07/25,8408010209

8408030141 Responds to 840702 ltr requesting Class III fee for polar crane SER approved in NRC 831118 ltr fee encl
KANGA,B K General Public Utilities - GPU Service Corp 84/07/27
DIGGS,R M License Fee Management Branch 1p 25916 136 24X
Fiche 50-320,84/07/27,8408030141

8408060053 Denies 840724 request to exceed 170-ton crane load limit on containment basis
SNYDER, B J TMI Program Office 84/07/27 KANGA, B K General Public Utilities - GPU Service Corp 2pp 25950 347 24X
Fiche 50-320 84/07/27, 8408060053

8408070083 Comments on SER transmitted in 840618 ltr re preparatory activities for plenum assembly removal Environ effects of plenum insp activities small & do not warrant further review
SNYDER, B J TMI Program Office 84/07/31 KANGA, B K General Public Utilities - GPU Service Corp 3pp 25955 254 24X
Fiche 50-320 84/07/31, 8408070083

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000 84/08/06, 8408070110

8408140279 Requests concurrence w/encl mod to SER re Fuel Pool A refurbishment Section 3 1 revised as applied to decontamination of lower tanks tanks currently being flushed & decontaminated
KANGA, B K General Public Utilities - GPU Service Corp 84/08/06
SNYDER, B J TMI Program Office 4pp 26054 360 24X
Fiche 50-320, 84/08/06, 8408140279

8408160035 Informs that util plans to prepare general safety evaluation to expand safe load path boundaries in reactor bldg Evaluation will be submitted for review by 841101
KANGA, B K General Public Utilities - GPU Service Corp 84/08/10
SNYDER, B J TMI Program Office 2pp 26092 050 24X
Fiche 50-320, 84/08/10, 8408160035

8408160042 Advises of review or Rev 4 to general project design criteria for Facility Design criteria does not relieve util from requesting exemptions from 10CFR10
SNYDER, B J TMI Program Office 84/08/10 KANGA, B K General Public Utilities - GPU Service Corp 2pp 26128 171 24X
Fiche 50-320, 84/08/10, 8408160042

8408300233 Notification of contract execution, Mod 2, to "Clinical Response to Chronic Stress in TMI " Contractor Uniformed Svcs Univ of Health Sciences
HOYLE A Administrative Contracts Branch FIN B-8008 84/08/14
VOLLMER, R H Division of Engineering CLEARY, D P NRC - No Detailed Affiliation Given 1p 26315 361 24X
Fiche 50-289, 84/08/14, 8408300233

--8408300237 Mod 2, extending period of performance to 840915, to "Clinical Response to Chronic Stress in TMI "
DAUM, A Uniformed Services Univ of Health Sciences HAGAN, T F Division of Contracts FIN B-8008 84/08/14 1p 26315 362 24X Fiche 50-289 84/08/14, 8408300233

8408280041 Confirms info provided in util 840618 ltr re plenum removal preparatory activities & requests addl info necessary to complete review
SNYDER, B J TMI Program Office 84/08/15 KANGA, B K General Public Utilities - GPU Service Corp 4pp 26294 037 24X
Fiche 50-320, 84/08/15, 8408280041

8408100021 IE Info Notice 84-65, "Undersized Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 11Bpp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408220444 Accepts resignation from Advisory Panel on Decontamination of TMI-2 Expresses appreciation for & recognition of contributions made to activities of panel while serving as member since 1980
PALLADINO, N J Commissioners 84/08/16 WAGNER, H N Johns Hopkins Medical Institutions, Baltimore, MD 3pp 26201 351 24X
Fiche 50-320, 84/08/16, 8408220444

--8408220448 Submits ltr of resignation from Citizen Advisory Panel on Decontamination of TMI-2
WAGNER, H N Johns Hopkins Medical Institutions, Baltimore, MD
WAGNER, H N Advisory Council for Decontamination of TMI Unit 2 84/07/09 PALLADINO, N J Commissioners 1p 26201 354 24X
Fiche 50-320, 84/08/16, 8408220441

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408270493 Returns check remitted in payment of 840713 request for exemption from fee provisions of 10CFR170 Check returned since 10CFR170 does not provide for recovery fees for Part 170 exemption requests
MILLER, W O License Fee Management Branch 84/08/20 KANGA, B K General Public Utilities - GPU Service Corp 1p 26277 061 24X
Fiche 50-320 84/08/20, 8408270493

8408300031 Rev 6 to Emergency Plan Implementing Procedure 1054 8, "Callout of Onsite & Offsite Duty Roster Personnel " W/840823 transmittal ltr
BEAVER, J General Public Utilities - GPU Service Corp 84/08/23 19pp 26306 009 24X Fiche 50-320, 84/08/23, 8408300031

8408310238 Forwards "Review of Dose Assessments at TMI & Recommendations for Future Research " Printed rept summaries & 840829 press release encl
BERGER, D Berger, D 84/08/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 26316 293 24X
Fiche 50-289, 84/08/27, 8408310238

--8408310239 "Review of Dose Assessments at TMI & Recommendations for Future Research "
BEYEA, J TMI Public Health Fund 84/08/15 270pp 26316 300 24X Fiche 50-289, 84/08/27, 8408310238

G Inspection reports, IE Bulletins & correspondence

8408070203 Recommends minor revs after reviewing encl draft info notice W/o encl
HILDEBRAND, J E General Public Utilities - GPU Service Corp 84/04/30 BAER, R L Engineering & Generic Communications Branch 3pp 25957 064 24X Fiche 50-320, 84/04/30, 8408070203

8408100130 Advises that approval & implementation of sys upgrade for tracking specific radiation exposures originally scheduled for completion by 840801 delayed until 840903 because of accelerated reactor vessel head lift schedule
KANGA, B K General Public Utilities - GPU Service Corp 84/07/25
MURLEY, T E Region 1, Office of Director 2pp 25988 279 24X
Fiche 50-320, 84/07/25, 8408100130

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11Bpp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408300374 Forwards Insp Rept 50-320/84-13 on 840525-0619 Apparent violation being considered for appropriate enforcement action Enforcement conference scheduled for 840917 in Region 1 ofc
STAROSTECKI, R Division of Project & Resident Programs 84/08/10
KITNER, E C General Public Utilities - GPU Service Corp 2pp 26308 161 24X Fiche 50-320, 84/08/10, 8408300374

--8408300381 Insp Rept 50-320/84-13 on 840525-0619 Violation noted failure to close & deactivate inboard isolation valve on Purge Train A & continuing to purge though Train A w/outboard isolation valve inoperable
COOK, R , THONUS, L , FASANO, A Region 1, Office of Director 84/07/30 4pp 26308 163 24X Fiche 50-320, 84/08/10, 8408300374

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/03/13 Consolidated Edison Co of New York, Inc 11pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/09/15 Consolidated Edison Co of New York Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408280076 Provides addl response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc," per NRC 840618 ltr Measures taken to identify problems w/vendor QA program outlined
KANGA,B K General Public Utilities - GPU Service Corp 84/08/15
MURLEY,T E Region 1, Office of Director 3pp 26261 207 24X Fiche 50-320,84/08/15,8408280076

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408090334 "TMI Aquatic Study Monthly Rept for June 1984 " W/GPU 840717 ltr
* EA Engineering, Science & Technology, Inc RESSLER,W C General Public Utilities - GPU Service Corp 84/06/30 HICKEY,C NRC - No Detailed Affiliation Given 14pp 25971 043 24X
Fiche 50-289,84/06/30,8408090334

8408010055 Forwards TMI Program Ofc weekly status rept for wk of 840715-21
GRANT,P J TMI Program Office 84/07/23 DENTON,H R Office of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office 11pp 25866 324 24X Fiche 50-320,84/07/23,8408010055

8408070292 Forwards TMI Program Ofc weekly status rept for wk of 840722-28
GRANT,P J TMI Program Office 84/07/30 DENTON,H R Office of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office 8pp 25957 036 24X Fiche 50-320,84/07/30,8408070292

8408090555 Forwards TMI Program Ofc weekly status rept for wk of 840729-0805
GRANT,P J TMI Program Office 84/08/06 DENTON,H R Office of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office 11pp 25983 218 24X Fiche 50-320,84/08/06,8408090555

8408230425 Submits TMI Program Ofc weekly status rept for 840805-11
GRANT,P J TMI Program Office 84/08/13 DENTON,H R Office of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office 12pp 26230 229 24X Fiche 50-289,84/08/13,8408230425

8408240394 Forwards TMI Program Ofc weekly status rept for wk of 840812
TRAVERS,W D TMI Program Office 84/08/20 DENTON,H R Office of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office 8pp 26249 342 24X Fiche 50-320,84/08/20,8408240394

B Reportable occurrences, LERs & related correspondence

8408010170 PNO-TMI-84-008B on 840724,reactor vessel closure head set down on storage stand Placement accomplished by use of pry bar & winch attached to containment wall NRC will be supplied w/24 h/day coverage until fixture in place
FASANO,A , GRANT,P TMI Program Office 84/07/25 1p 25855 320
24X Fiche 50-320,84/07/25,8408010170

8408010174 PNO-TMI-84-008A on 840724,reactor vessel closure head lifted clear of reactor vessel flange Licensee devising means of aligning vessel head w/storage stand guide pins in preparation for lowering head to stand
COOK,R , FASANO,A , GRANT,P TMI Program Office 84/07/25 1p
25855 321 24X Fiche 50-320,84/07/25,8408010174

8408010220 PNO-TMI-84-008D on 840726, lead shield platform put in place over top of internals indexing fixture While lowering shielding,crane failed Licensee manually unscrewed lifting turnbuckles until platform made contact
COOK,R , FASANO,A , GRANT,P TMI Program Office 84/07/26 1p
25855 026 24X Fiche 50-320,84/07/26,8408010220

8408010230 PNO-TMI-84-008C on 840726, licensee lifted internals indexing fixture w/polar crane & lowered fixture into place on reactor vessel flange Containment purging initiated
COOK,R , FASANO,A , GRANT,P TMI Program Office 84/07/26 1p
25856 018 24X Fiche 50-320,84/07/26,8408010230

8408060310 LER 84-010-00 on 840628, several containment isolation valves opened w/o required unit work instruction approvals Personnel will be briefed on event & need to obtain required approvals W/840726 ltr
SWARTZWELDER,R , KANGA,B K General Public Utilities - GPU Service Corp 84/07/26 4pp 25936 044 24X Fiche 50-320,84/07/26,8408060310

8408200115 LER 84-011-00 on 840713,control room air inlet radiation monitor interlock placed in defeat Caused by personnel error Personnel reprimanded W/840810 ltr
CHAPLIN,S D , KANGA,B K General Public Utilities - GPU Service Corp 84/08/10 5pp 26140 225 24X Fiche 50-320,84/08/10,8408200115

T Hearing transcripts on non-antitrust matters

8408020046 Transcript of 840712 meeting in Harrisburg,PA Pp 1-113 Supporting documentation encl
* Advisory Council for Decontamination of TMI Unit 2 84/07/12
183pp 25883 316 24X Fiche 50-320,84/07/12,8408020046

8408270096 Transcript of TMI Advisory Panel on TMI Unit 2 Decontamination on 840809 public meeting in Harrisburg,PA Pp 1-33 Supporting documentation encl
* Advisory Council for Decontamination of TMI Unit 2 84/08/09
138pp 26257 048 24X Fiche 50-320,84/08/09,8408270096

U Congressional/Executive Correspondence

8408290154 Accepts resignation as member of Advisory Panel for Decontamination for TMI-2 Certificate of appreciation encl
PALLADINO,N J Commissioners 84/08/16 WAGNER,H N Affiliation Not Assigned 2pp 26311 360 24X Fiche 50-320,84/08/16,8408290154

DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8408300436 Forwards FEMA exercise rept for 831013 exercise
DANCE,H C Region 2, Office of Director 84/05/07 KELLY,R J
Georgia Power Co 1p 26311 247 24X Fiche 50-321,84/05/07,8408300436

--8404040322 Forwards FEMA 840124 ltr forwarding FEMA Region IV rept of 831013 joint exercise Recommends exercise rept be transmitted to licensee & coordination w/FEMA Region IV be continued to ensure deficiencies identified corrected
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/13 STOHR,J P Division of Emergency Preparedness & Materials Safety 2pp 26314 248 24X Fiche 50-321,84/05/07,8408300436

8408300352 Confirms arrangements made on 840524 between JT Beckham & HC Dance re 840531 enforcement conference in Region II ofc to discuss 840522 security event re access controls & events leading to inoperability of HPCI Agenda encl
O'REILLY,J P Region 2, Office of Director 84/05/25 KELLY,R J
Georgia Power Co 2pp 26314 147 24X Fiche 50-321,84/05/25,8408300352

8408300376 Forwards summary of 840530 meeting w/utils & INPO re selected emergency preparedness issues Attendance list also encl
O'REILLY,J P Region 2, Office of Director 84/06/08 KELLY,R J
Georgia Power Co 4pp 26308 257 24X Fiche 50-000,84/06/08,8408300376

8408310057 Documents training & experience for evaluation team members, per 840723 ltr re training requirements for NRC & contract personnel observing 840802 emergency exercise
DANCE,H C Region 2, Office of Director 84/07/24 KELLY,R J
Georgia Power Co 2pp 26333 332 24X Fiche 50-321,84/07/24,8408310057

8408030163 Revs to emergency plan implementing procedures, consisting of Rev 4 to HNP-8024 "In-Plant Radiation Level Monitoring" & Rev 1 to HNP-8061, 'Eberline Model PCM-1 Portal Monitor Operation ' Calibr ' W/840731 ltr
SORRELL,E C Georgia Power Co 84/07/31 38pp 25912 022 24X
Fiche 50-321,84/07/31,8408030163

8408130302 Responds to 840302 ltr, supplemented by 840413 ltr, requesting exemption from App E to 10CFR50, excluding state & county participation in 840802 exercise Requested exemption unnecessary Rev rule requires participation every 2 yrs
STOLZ,J F Operating Reactors Branch 4 84/08/01 BECKHAM,J T
Georgia Power Co 3pp 26040 331 24X Fiche 50-321,84/08/01,
8408130302

8408090207 Notification or 840808 meeting w/util in Bethesda,MD to discuss approach for interim measures associated w/schedular exemption request for implementation of App R mods
RIVENBARK,G Operating Reactors Branch 4 84/08/03 STOLZ,J F
Operating Reactors Branch 4 2pp 25984 360 24X
Fiche 50-321,84/08/03,8408090207

8408130379 Responds to 840717 request for addl info re submittal of safety parameter display sys info Forboro Procedures QQAAA04 & QQAA844, containing isolation devices pass/fail acceptance criteria, encl
GUCWA,L T Georgia Power Co 84/08/07 STOLZ,J F Operating
Reactors Branch 4 3pp 26008 203 24X Fiche 50-321,84/08/07,
8408130379

8408170258 Rev 7 to Emergency Implementing Procedure HNP-4852, "Offsite Dose Estimations " W/840814 ltr
* Georgia Power Co 84/08/14 46pp 26115 297 24X
Fiche 50-321,84/08/14,8408170258

8408210472 Revised emergency plan implementing procedures, including Rev 2 to HNP-2-4205 re turbine lube oil reservoir, Rev 4 to HNP-4212 re emergency diesel generator bldg & Rev 3 to HNP-1-4216 re reactor bldg Elevation 203 fires W/840816 ltr
NIX,H , SORRELL,E C Georgia Power Co 84/08/16 246pp
26149 084 24X Fiche 50-321,84/08/16,8408210472

8408280233 Revised emergency plan implementing procedures, including Rev 1 to HNP-1-4261 re south CRD & essential MCC area fires & Rev 1 to HNP-1-4263 re reactor water cleanup pump room fire W/840824 ltr
NIX,H , SORRELL,E C Georgia Power Co 84/08/18 75pp 26269 125
24X Fiche 50-321,84/08/18,8408280233

8408270301 Rev 21 to Emergency Plan Implementing Procedure HNP-8008, "Radiation Work Permit " W/840821 ltr
SORRELL,E C Georgia Power Co 84/08/21 28pp 26240 337 24X
Fiche 50-321,84/08/21,8408270301

I Financial information

8408300072 Forwards draft in furtherance certificate Approval requested in order to meet Internal Revenue Svc requirements for tax-exempt pollution control revenue bonds
GUCWA,L T Georgia Power Co 84/08/20 STOLZ,J F Operating
Reactors Branch 4 4pp 26305 357 24X Fiche 50-321,84/08/20,
8408300072

P Operating license stage documents & correspondence

8408310021 Confirms 840514 telcon re 840521 meeting in Region II ofcs to discuss planned mod to rod block monitoring sys at facility
LEWIS,R C Region 2, Office of Director 84/05/16 KELLY,R J
Georgia Power Co 1p 26335 014 24X Fiche 50-321,84/05/16,
8408310021

8408300320 Confirms 840522 telcon between J Padgett & H Dance re arrangements made for R Martin, Region II, Deputy Regional Administrator, to attend 840628 presentation of certificates to licensed operators
LEWIS,R C Region 2, Office of Director 84/05/29 KELLY,R J
Georgia Power Co 1p 26308 328 24X Fiche 50-321,84/05/29,
8408300320

8408310052 Forwards summary of 840531 meeting in Region II ofcs re NPCI sys Meeting beneficial & provided better understanding of issue
LEWIS,R C Region 2, Office of Director 84/06/08 KELLY,R J
Georgia Power Co 3pp 26333 338 24X Fiche 50-321,84/06/08,
8408310052

8408300421 Forwards summary of 840521 meeting w/util in Region II ofc re APRM sys block monitor sys & Tech Spec activities proposed for Licenses DPR-57 & NPF-5 Attendance list encl
LEWIS,R C Region 2, Office or Director 84/06/22 KELLY,R J
Georgia Power Co 4pp 26314 217 24X Fiche 50-321,84/06/22,
8408300421

8408070148 Notifies of potential equipment qualification problems re 10CFR50 49 equipment qualification deadline Problems result from inability of PYCO, Inc to provide qualification for resistance temp detectors in use
GUCWA,L T Georgia Power Co 84/07/19 STOLZ,J F Operating
Reactors Branch 4 3pp 25949 273 24X Fiche 50-321,84/07/19,
8408070148

8408080178 Informs of review of responses to Generic Ltr 83-02 re Tech Specs for NUREG-0737 items which were to be implemented by 831231 Tech Specs for Item II E 4 2 7 have not been provided Response requested within 30 days
STOLZ,J F Operating Reactors Branch 4 84/08/01 BECKHAM,J T
Georgia Power Co 2pp 25978 342 24X Fiche 50-321,84/08/01,
8408080178

8408130561 Application for amend to Licenses DPR-57 & NPF-5, revising radiological effluent Tech Specs (RETS) by transferring RETS from App B to App A & including editorial & administrative changes & changes based on NRC comments
BECKHAM,J T Georgia Power Co 84/08/01 STOLZ,J F Operating
Reactors Branch 4 3pp 26031 001 24X Fiche 50-321,84/08/01,
8408130561

--8408130567 Proposed Tech Spec changes, transferring radiological effluent Tech Specs from App B to App A
* Georgia Power Co 84/08/01 190pp 26031 004 24X
Fiche 50-321,84/08/01,8408130561

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408140106 Application to amend Licenses DPR-57 & NPF-5, changing Tech Specs to reflect implementation of TMI Item II B 3, "Post-Accident Sampling Capability " Fee encl
BECKHAM,J T Georgia Power Co 84/08/07 STOLZ,J F Operating
Reactors Branch 4 2pp 26051 252 24X Fiche 50-321,84/08/07,
8408140106

--8408140124 Proposed Tech Spec changes re post-accident sampling & analysis & iodine monitoring
* Georgia Power Co 84/08/07 5pp 26051 254 24X
Fiche 50-321,84/08/07,8408140106

8408210474 Provides info in support of 840806 request for proposed Tech Spec change re containment isolation valves Request should be treated as emergency request to avoid undue delay in unit startup
GUCWA,L T Georgia Power Co 84/08/14 STOLZ,J F Operating
Reactors Branch 4 2pp 26181 125 24X Fiche 50-321,84/08/14,
8408210474

8408210357 Responds to 840801 ltr re NUREG-0737, Item II E 4 2(7), "Purge & Vent Valve Isolation " Revs to Unit 2 Tech Specs expected to be submitted by 840905 Unit 1 mods will be completed during scheduled Fall 1984 refueling outage
GUCWA,L T Georgia Power Co 84/08/16 STOLZ,J F Operating
Reactors Branch 4 2pp 26180 241 24X Fiche 50-321,84/08/16,
8408210357

8408230251 Requests extension until 841107, to respond to request for info re reliability & upgrading of diesel generators, per Generic Ltr 84-15 Extension due to workload at site for Unit 2 recirculation pipe replacement outage
GUCWA,L T Georgia Power Co 84/08/16 STOLZ,J F Operating
Reactors Branch 4 2pp 26207 293 24X Fiche 50-321,84/08/16,
8408230251

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408300024 Requests mod to distribution for all plant correspondence Distribution page of recent Tech Spec amend w/requested change encl
GUCWA,L T Georgia Power Co 84/08/22 STOLZ,J F Operating Reactors Branch 4 2pp 26335 183 24X Fiche 50-321,84/08/22, 8408300024

G Inspection reports, IE Bulletins & correspondence

8408240356 Forwards Insp Repts 50-321/84-21 & 50-366/84-21 on 840611-15 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/10 KELLY,R J Georgia Power Co 2pp 26237 040 24X Fiche 50-321,84/07/10, 8408240356

--8408240359 Insp Rep's 50-321/84-21 & 50-366/84-21 on 840611-15 No violations or deviations noted Major areas inspected worker concerns re Newport News Industries recirculation pipe replacement project
MERRIWEATHER,N , CONLON,T E Region 2, Office of Director 84/07/09 10pp 26237 042 24X Fiche 50-321,84/07/10,8408240356

8408240364 Forwards Insp Repts 50-321/84-23 & 50-366/84-23 on 840618-22 No violations or deviations noted Unresolved items identified will be pursued during future insps
DANCE,H C Region 2, Office of Director 84/07/11 KELLY,R J Georgia Power Co 2pp 26237 080 24X Fiche 50-321,84/07/11, 8408240364

--8408240366 Insp Repts 50-321/84-23 & 50-366/84-23 on 840618-22 No violations or deviations noted Major areas inspected evaluation of ultrasonic test indications in feedwater weld 2821-1FW-12AA-12 (Unit 2)
CROWLEY,B R , COLEY,J L , BLAKE,J J Region 2, Office of Director 84/07/10 12pp 26237 082 24X Fiche 50-321,84/07/11, 8408240364

8408280239 Advises of plans & schedules for replacing HFA relays in reactor protection & safety sys,per IE Bulletin 84-02
GUCWA,L T Georgia Power Co 84/07/13 O'REILLY,J P Region 2, Office of Director 4pp 26262 237 24X Fiche 50-321,84/07/13, 8408280239

8408270241 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-321/84-13 & 50-366/84-13
LEWIS,R C Division of Project & Resident Programs 84/07/20
KELLY,R J Georgia Power Co 1p 26258 086 24X
Fiche 50-321,84/07/20,8408270241

--8408270247 Responds to NRC 840607 ltr re violations noted in Insp Repts 50-321/84-13 & 50-366/84-13 Corrective actions QC dept will witness significant activities for safety-related major maint
GUCWA,L T Georgia Power Co 84/07/09 O'REILLY,J P Region 2, Office of Director 3pp 26258 087 24X Fiche 50-321,84/07/20, 8408270241

--8408270255 Forwards Insp Repts 50-321/84-13 & 50-366/84-13 on 840321-0420
LEWIS,R C Division of Project & Resident Programs 84/06/07
KELLY,R J Georgia Power Co 2pp 26258 090 24X
Fiche 50-321,84/07/20,8408270241

--8408270269 Insp Repts 50-321/84-13 & 50-366/84-13 on 840321-0420 Violation noted failure to restore sys to original design requirements
CRLENJAK,R V , RAY-HOLMES,P , GARNER,L Region 2, Office of Director 84/06/05 7pp 26258 094 24X Fiche 50-321,84/07/20, 8408270241

--8408270261 Notice of violation from insp on 840321-0421
* Region 2, Office of Director 84/06/07 2pp 26258 092 24X
Fiche 50-321,84/07/20,8408270241

8408270334 Forwards Insp Repts 50-321/84-25 & 50-366/84-25 on 840619-22 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/20 KELLY,R J Georgia Power Co 2pp 26257 206 24X Fiche 50-321,84/07/20, 8408270334

--8408270338 Insp Repts 50-321/84-25 & 50-366/84-25 on 840619-22 No violations or deviations noted Major areas inspected review of local leak rate test program & followup of previous violation
WHITENER,H L , JAPE,F Region 2, Office of Director 84/07/19
6pp 26257 208 24X Fiche 50-321,84/07/20,8408270334

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " S c list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408200001 Monthly operating repts for Jul 1984 W/840802 ltr
NIX,H C Georgia Power Co 84/07/31 15pp 26140 264 24X
Fiche 50-321,84/07/31,8408200001

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,G G General Electric Co 84/04/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348

8408090287 Special Rept 50-321/1984-009 on 840720,level in both fire water storage tanks dropped to less than 270,000 gallons,due to initiation of diesel fire pumps during hydrant flush test Tank levels returned to Tech Spec limit
NIX,H C Georgia Power Co 84/08/01 O'REILLY,J P Region 2, Office of Director 2pp 25994 163 24X Fiche 50-321,84/08/01, 8408090287

8408270229 LER 84-035-00 on 840827, cable leads lifted & improperly tagged * separated in control room Caused by personnel error Procedure HNP-6921 re cable * cable ways installation revised to strengthen administrative control W/840814 ltr
ELTON, T L , NIX, H C Georgia Power Co 84/08/14 3pp 26258 045
24X Fiche 50-321, 84/08/14, 8408270229

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality * separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000 84/08/21, 8408310186

8408300333 LER 84-013-00 on 810729, during Procedure HNP-1-3154, HPCI malfunctioned * injected into reactor Caused by short circuit across 1/2 of HPCI automatic injection logic HPCI test jack E41-J1 inspected & cleaned W/840822 ltr
ELTON, T L , NIX, H C Georgia Power Co 84/08/22 3pp 26308 332
24X Fiche 50-321, 84/09/22 8408300333

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

8407300105 Relates recent exemption decision to Section 185 of Atomic Energy Act, requiring NRC to find plant in conformity w/ provisions * rules & regulations of Commission before issuing OL
PLAINE, H R Office of the General Counsel SECY-84-290A 84/07/24
29pp 25920 001 24X Fiche 50-322, 84/07/24, 8407300105

8408130547 Provides preliminary comments on six items of Commissioner Asselstine 840725 proposal that NRC apply Shoreham Decision CLI-84-8 generically to schedular exemption requests
DIRCKS, W J Office of the Executive Director for Operations
84/08/02 Commissioners 5pp 26294 158 24X
Fiche 50-322, 84/08/02, 8408130547

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs * holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors * license applicants for Jul 1984
TREMBLAY, P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN, G M Operating Reactors Assessment Branch 13pp
25991 390 24X Fiche 50-000, 84/08/06, 8408090317

8408090210 Forwards A Schwencer 840730 memo to E Reis re license conditions & NRC 840731 ltr to util re amend extending expiration date of License SNM-1857 Certificate of Svc encl
Related correspondence
BORDENICK, B M Hearing Branch 3 DSB 868 84/08/07 Atomic
Safety and Licensing Appeal Panel 4pp 25971 211 24X
Fiche 50-322, 84/08/07, 8408090210

--8408090213 Forwards status list of partial initial decision license conditions & details of NRC intended course of action Requests status rept be forwarded to util
SCHWENCER, A Licensing Branch 2 84/07/30 REIS, E Hearing
Branch 3 5pp 25971 215 24X Fiche 50-322, 84/08/07, 8408090210

8408200328 Forwards summary of disposition of generic ltrs for CY83
LEONARD, J D Long Island Lighting Co 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 26133.004
24X Fiche 50-322, 84/08/14, 8408200328

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408270226 Forwards documents re recently conducted integrated electrical test at facility Encl represents summation of actual loads experienced during loss of offsite power/ LOCA simulations for test
LEONARD, J D Long Island Lighting Co 84/08/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 129pp 26243 001
24X Fiche 50-322, 84/08/22, 8408270226

C Utility Environmental Report (ER), amends & correspondence

8408230409 Withdraws util 840309 motion to strike portions of testimony of Suffolk County witnesses Harris & Mayer re Contention 75 Related correspondence
MCCLESKEY, K Hunton & Williams MCCLESKEY, K Long Island Lighting
Co DSB 209 84/08/20 LAURENSON, J A , KLINE, J R , SHON, F J
Atomic Safety and Licensing Board Panel 1p 26205 359 24X
Fiche 50-322, 84/08/20, 8408230409

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408220107 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SHOREHAM NUCLEAR POWER STATION, UNIT NO 1 Docket No 50-322 (Long Island Lighting Company)
* Division of Licensing NUREG-0420 S06 84/07/31 33pp
Available at NRC $3 75 26197 304 24X Fiche 50-322, 84/07/31, 8408220107

F Security, medical, emergency & fire protection plans

8408080473 Forwards IE Insp Rept 50-322/84-22 on 840514-18 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/07/16
LEONARD, J B Long Island Lighting Co 2pp 25975 164 24X
Fiche 50-322, 84/07/16, 8408080473

--8408080478 IE Insp Rept 50-322/84-22 on 840514-18 No violations noted Major areas inspected plant facilities & initial fuel load & startup testing planning Safeguards info deleted (ref 10CFR73 21)
BLUMBERG, N , KUCHARSKI, S , BETTENHAUSEN, L Region 1, Office of
Director 84/07/05 6pp 25975 166 24X Fiche 50-322, 84/07/16, 8408080473

8408290478 Forwards Insp Rept 50-322/84-23 on 840528-0701 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/08
LEONARD, J L Long Island Lighting Co 4pp 26294 189 24X
Fiche 50-322, 84/08/08, 8408290478

--8408290483 Insp Rept 50-322/84-23 on 840528-0701 No violations noted Major areas inspected discharge of security guard weapon, status of Colt diesel generator project, storage of emergency equipment lockers & IE Bulletin 80-06
PETRONE, C , ESELGROTH, P , SHEDLOSKY, J Region 1, Office of
Director 84/07/19 12pp 26294 193 24X Fiche 50-322, 84/08/08, 8408290478

G Adjudicatory correspondence

8408010133 Staff requirements memo re 840516 Commission vote determining that 10CFR50 57(c) should not be read to make GDC 17 inapplicable to low power operation
CHILK, S J Office of the Secretary of the Commission 84/05/18
Office of the Secretary of the Commission 1p 25873 312 24X
Fiche 50-322, 84/05/18, 8408010133

8406040336 Discusses 840517 hearing of Congressional Subcommittee on Energy & Environ re licensing procedure Manner in which attempts made to expedite hearings unprecedented Requests disqualification from further action
HOCHBRUECKNER New York, State of DSB 420 84/05/22
PALLADINO, N J Commissioners 2pp 24802 339 24X
Fiche 50-322, 84/05/22, 8406040336

8408160123 Forwards NRC staff Exhibit 1 from 840424 hearing Related correspondence
RILEY, S L Tayloe Associates 84/06/15 PLEASANT, E
Administrative & Logistical Support Branch 1p 26126 168 24X
Fiche 50-322, 84/06/15, 8408160123

8408160076 Forwards applicant Exhibits 38-47 from 840605-08 hearings Related correspondence
RILEY, S L Tayloe Associates 84/06/26 PLEASANT, E
Administrative & Logistical Support Branch 1p 26126 349, 24X
Fiche 50-322, 84/06/26, 8408160076

8408160118 Forwards intervenor Exhibits 67-74 Related correspondence
RILEY, S L Tayloe Associates 84/06/26 PLEASANT, E
Administrative & Logistical Support Branch 1p 26126 169 24X
Fiche 50-322, 84/06/26, 8408160118

8408060434 Staff requirements memo re 840725 meeting on interpretation of Decision CLI-84-8 & reexam of exemption process
CHILK, S J Office of the Secretary of the Commission 84/07/26
DIRCKS, W J Office of the Executive Director for Operations 2pp
25937 322 24X Fiche 50-322, 84/07/26, 8408060434

8408010254 Informs that NRC testimony prepared by IE on Contention 11 will not be available until next wk Related correspondence
BORDENICK,B M Hearing Branch 3 DSB 677 84/07/27
LAURENSON,J A , SHON,F J KLINE J R Atomic Safety and Licensing Board Panel 2pp 25854 178 24X Fiche 50-322,84/07/27,8408010254

8408010261 Application for issuance of subpoenas to command appearance & testimony by J Hines & FA Cipriani at emergency planning hearings Certificate of Svc encl Related correspondence
CHRISTMAN,J N Long Island Lighting Co CHRISTMAN,J N Hunton & Williams DSB 662 84/07/27 Atomic Safety and Licensing Board Panel 12pp 25854 044 24X Fiche 50-322,84/07/27,8408010261

8408060437 Revised staff requirements memo re 840725 discussion on interpretation of Decision CLI-84-8 & reexam of exemption process
CHILK,S J Office of the Secretary of the Commission 84/07/27
DIRCKS,W J Office of the Executive Director for Operations
PLAINE,H H Office of the Executive Legal Director 1p 25937 316
24X Fiche 50-322,84/07/27,8408060437

8408010169 Answer opposing Suffolk County 840724 motion to compel production of documents Util has substantially complied w/ production of documents requested Certificate of Svc encl Related correspondence
FARLEY,E M Long Island Lighting Co FARLEY,E M Hunton & Williams DSB 685 84/07/30 Atomic Safety and Licensing Board Panel 13pp 25855 307 24X Fiche 50-322,84/07/30,8408010169

8408010239 Response to util motion for partial reconsideration of 840718 security proceedings order Motion should be denied due to util failure to demonstrate basis for motion Certificate of Svc encl
LETSCHE,K J Suffolk County, NY LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips PALOMINO,F D New York, State of DSB 674 84/07/30 Atomic Safety and Licensing Board Panel 4pp 25856 010 24X Fiche 50-322,84/07/30,8408010239

8408020002 Requests to make limited appearance statement at 840804 low power test license hearing Served on 840801
BREDES,N Affiliation Not Assigned DSB 705 84/07/30
Docketing & Services Branch 1p 25882 300 24X
Fiche 50-322,84/07/30,8408020002

8408020024 Motion to admit revised testimony of Phase II emergency planning Contentions 24 O.74 & 75 (relocation ctrs) Certificate of Svc encl Related correspondence
MCCLESKEY,K E Long Island Lighting Co MCCLESKEY,K E Hunton & Williams DSB 698 84/07/30 Atomic Safety and Licensing Board Panel 68pp 25883 150 24X Fiche 50-322,84/07/30,8408020024

8408070274 Response to Suffolk County 840727 notice of execution of affidavits of nondisclosure Suffolk County representation premature Certificate of Svc encl
IRWIN,D P Long Island Lighting Co IRWIN,D P Hunton & Williams DSB 761 84/07/30 Atomic Safety and Licensing Board Panel 4pp 25949 199 24X Fiche 50-322,84/07/30,8408070274

8408020200 Statement of Governor M Cuomo in support of Suffolk County 840723 motion for reconsideration of ASLB limitations on Suffolk County cross-examination of FEMA witness panel Certificate of Svc encl Related correspondence
ZAHNLEUTER,R J New York, State of DSB 715 84/07/31 Atomic Safety and Licensing Board Panel 5pp 25898 002 24X
Fiche 50-322,84/07/31,8408020200

8408030074 Notice to ASLB re schedule for hearing strike issues Schedule too rigorous for parties to meet Truly full & fair hearing may require more realistic schedule Certificate of Svc encl
MCMURRAY,C M Suffolk County, NY MCMURRAY,C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 724 84/07/31 13pp
25907 016 24X Fiche 50-322,84/07/31,8408030074

8408020044 Advises that time for Commission to review ALAB-773 expired Commission declined review Decision became final agency action on 840723 Served on 840801
CHILK,S J Office of the Secretary of the Commission DSB 707
84/08/01 Atomic Safety and Licensing Board Panel 1p
25883 262 24X Fiche 50-322,84/08/01,8408020044

8408030085 Order establishing procedures & schedule for reply to LILCO 840730 answer to motion to compel production of documents, Reply requested by 840807 Courtesy notification encl Served on 840802
BRENNER,L Atomic Safety and Licensing Board Panel DSB 731
84/08/01 Suffolk County, NY 6pp 25906 391 24X
Fiche 50-322,84/08/01,8408030085

8408030086 Memorandum to show cause why Suffolk County 840726 appeal of ASLB 840710 order should not be dismissed Appeal filed late for good cause Certificate of Svc encl Related correspondence
MILLER,M S Suffolk County NY MILLER,M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 730 84/08/01 15pp 25906 336
24X Fiche 50-322,84/08/01,8408030086

8408030105 Motion to admit proposed modified emergency planning Contention 88 & revised testimony of GC Minor on emergency planning Contentions 85 & 88 Related correspondence
MILLER,M S Suffolk County, NY MILLER,M S Kirkpatrick, Lockhart, Hill Christopher & Phillips DSB 725 84/08/01 Atomic Safety and Licensing Board Panel 11pp 25916 055 24X
Fiche 50-322,84/08/01,8408030105

--8408030112 Revised testimony of GC Minor on emergency planning Contentions 85 & 88 re offsite recovery & reentry Prof qualifications statement & Certificate of Svc encl
MINOR,G C Suffolk County, NY MINOR,G C MHB Technical Associates 84/08/01 18pp 25916 066 24X
Fiche 50-322,84/08/01,8408030105

8408070475 Memorandum & order denying motion for disqualification of Judge Cotter Statement of BP Cotter & Certificate of Svc encl Served on 840806
COTTER,B P Atomic Safety and Licensing Board Panel DSB 759
84/08/01 New York, State of 15pp 25940 300 24X
Fiche 50-322,84/08/01,8408070475

8408030090 Motion for directed certification of ASLB 840724 order, granting in part & denying in part,util motion for summary disposition on Phase I & II low power testing Certificate of Svc encl
ROLFE,R M Long Island Lighting Co ROLFE,R M Hunton & Williams
DSB 728 84/08/02 Commissioners 59pp 25906 274 24X
Fiche 50-322,84/08/02,8408030090

8408030099 Order establishing pending appeal as motion for directed certification of ASLB order in question Party views as to whether criteria for granting certification met requested by 840810 Served on 840802
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel DSB 729
84/08/02 Suffolk County, NY 2pp 25904 301 24X
Fiche 50-322,84/08/02,8408030099

8408070256 Response opposing Suffolk County offer of proof for cross-examination of FEMA witnesses & request for reconsideration of ASLB limitation of cross-examination of FEMA witnesses Certificate of Svc encl
MCCLESKEY,K E Long Island Lighting Co MCCLESKEY,K E Hunton & Williams DSB 768 84/08/02 Atomic Safety and Licensing Board Panel 17pp 25949 244 24X Fiche 50-322,84/08/02,8408070256

8408070395 Response opposing Suffolk County 840723 offer of proof & request for reconsideration of ASLB limitations on Suffolk County cross-examination of FEMA witness panel ASLB did not abuse discretion Certificate of Svc encl
BORDENICK,B M Hearing Branch 3 DSB 814 84/08/02 Atomic Safety and Licensing Board Panel 8pp 25945 259 24X
Fiche 50-322,84/08/02,8408070395

8408070399 Motion for referral to Commission of ASLB 840723 order granting in part & denying in part,util 840523 motions for summary disposition on Phase I & Phase II low power testing Certificate of Svc encl
ROLFE,R M Long Island Lighting Co ROLFE,R M Hunton & Williams
DSB 778 84/08/02 Atomic Safety and Licensing Board Panel
12pp 25942 211 24X Fiche 50-322,84/08/02,8408070399

8408070427 Response opposing Suffolk County offer of proof & request for reconsideration of ASLB limitations on Suffolk County cross-examination of FEMA witness panel Certificate of Svc encl
GLASS,S M Federal Emergency Management Agency DSB 784 84/08/02
Atomic Safety and Licensing Board Panel 9pp 25942 014 24X
Fiche 50-322,84/08/02,8408070427

8408070308 Motion to compel util to produce FM Rasbury for deposition during wk of 840806-10 re relocation ctr issues or, in alternative, that FM Rasbury be stricken from util witness panel. Certificate of Svc encl Related correspondence
MCMURRAY,C M Suffolk County, NY MCMURRAY,C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 797 84/08/03
Atomic Safety and Licensing Board Panel 17pp 25947 341 24X
Fiche 50-322,84/08/03,8408070308

8408070358 Memorandum ALAB-779, stating ASLAB intention not to review ASLB 840801 denial of Suffolk County 840622 motion for disqualification ASLAB expresses no view re merit of motion Served on 840803
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel DSB 758
84/08/03 3pp 25945 174 24X Fiche 50-322,84/08/03,8408070358

8408070421 Motion for reconsideration of ASLB 840724 order re schedule for hearing & prohibiting written testimony on strike issues Certificate of Svc encl
MILLER, M S Suffolk County, NY MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 798 84/08/03 Atomic Safety and Licensing Board Panel 13pp 25940 056 24X
Fiche 50-322, 84/08/03, 8408070424

8408070442 Forwards util motion for summary resolution of ASLB determination involving effect of strike on local emergency response organization & proposal of license condition & statement of matl facts Related correspondence
IRWIN, D P Hunton & Williams IRWIN, D P Long Island Lighting Co DSB 804 84/08/03 LAURENSON, J A , KLINE, J R , SHON, F J Atomic Safety and Licensing Board Panel 1p 25940 230 24X
Fiche 50-322, 84/08/03, 8408070442

--8408070448 Motion for summary resolution of ASLB 840724 memorandum & order re effects of strike of local emergency response organization workers on ability to implement offsite emergency preparedness plan & proposal of license condition
IRWIN, D P Long Island Lighting Co IRWIN, D P Hunton & Williams 84/08/03 Atomic Safety and Licensing Board Panel 6pp 25940 231 24X Fiche 50-322, 84/08/03, 8408070442

--8408070458 Statement of matl facts in support of util motion for summary resolution of ASLB 840724 order Unexecuted affidavits & Certificate of Svc encl
* Long Island Lighting Co 84/08/03 Atomic Safety and Licensing Board Panel 95pp 25940 237 24X
Fiche 50-322, 84/08/03, 8408070442

8408070388 Informs that Judge Cotter 840801 memorandum & order denying disqualification motion of Suffolk County & State of NY & ALAB-779, did 840803, affirming subj order, docketed in low power phase of proceeding
CLEMENTS, W L Docketing & Services Branch DSB 757 84/08/06 Office of the Executive Legal Director 1p 25945 279 24X
Fiche 50-322, 84/08/06, 8408070388

8408080338 Motion for reconsideration of ASLB 840727 memorandum & order establishing format & schedule of proposed findings of fact & conclusions of law Certificate of Svc encl
MCMURRAY, C M Suffolk County, NY MCMURRAY, C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 820 84/08/06 Atomic Safety and Licensing Board Panel 20pp 25964 058 24X
Fiche 50-322, 84/08/06, 8408080338

8408080408 Answer opposing Suffolk County 840803 motion to compel util to produce util witness, FM Rasbury, for deposition Certificate of Svc encl Related correspondence
CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunton & Williams DSB 842 84/08/06 Atomic Safety and Licensing Board Panel 6pp 25974 074 24X Fiche 50-322, 84/08/06, 8408080408

8408080417 Motion for summary disposition of Contentions 1-10 re legal authority No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence
CHRISTMAN, W T Long Island Lighting Co CHRISTMAN, W T Hunton & Williams DSB 843 84/08/06 Atomic Safety and Licensing Board Panel 86pp 25973 310 24X Fiche 50-322, 84/08/06, 8408080417

--8408080423 Statement of matl facts as to which there is no genuine issue on Contentions 1-10 re legal authority Certificate of Svc encl
* Long Island Lighting Co 84/08/03 Atomic Safety and Licensing Board Panel 14pp 25974 038 24X
Fiche 50-322, 84/08/06, 8408080417

8408080428 Opposition to Suffolk County dilatory pleadings on strike issues & motion to direct parties to provide timely discovery on direct case Certificate of Svc encl. Related correspondence
IRWIN, D P Long Island Lighting Co IRWIN, D P Hunton & Williams DSB 845 84/08/06 Atomic Safety and Licensing Board Panel 22pp 25973 288 24X Fiche 50-322, 84/08/06, 8408080428

8408090218 Forwards 840801 ltr & affidavit of CS Matthews for docketing Related correspondence
DREIFUS, D Hunton & Williams DREIFUS, D Long Island Lighting Co DSB 860 84/08/06 Docketing & Services Branch 1p 25971 220 24X Fiche 50-322, 84/08/06, 8408090218

--8408090223 Forwards affidavit of C Matthews attesting to accuracy of info contained in 840712 ltr re crankshaft oil passage plug issue Related correspondence
DREIFUS, D Hunton & Williams DREIFUS, D Long Island Lighting Co 84/08/01 BRENNER, L , MORRIS, P A , FERGUSON, G A Atomic Safety and Licensing Board Panel 21pp 25971 221 24X
Fiche 50-322, 84/08/06, 8408090218

8408080410 Joint motion of State of NY & Suffolk County to compel discovery of documents & info sought in 840801 discovery request ASLB requested to give matter expeditious consideration W/Certificate of Svc Related correspondence
MCMURRAY, C M Suffolk County, NY MCMURRAY, C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips ZAHNLEUTER, R J New York, State of DSB 847 84/08/07 Atomic Safety and Licensing Board Panel 20pp 25974 054 24X Fiche 50-322, 84/08/07, 8408080410

8408090161 Informs that NRC has no objection to LILCO motion to admit revised testimony on Phase II emergency planning Contentions 24 O, 74 & 75 (relocation ctrs) & Suffolk County motion to admit Contention 88 Related correspondence
BORDENICK, B M Hearing Branch 3 DSB 869 84/08/07
LAURENSON, J A , SHON, F J , KLINE, J R Atomic Safety and Licensing Board Panel 2pp 25973 008 24X Fiche 50-322, 84/08/07, 8408090161

8408090210 Forwards A Schwencer 840730 memo to E Reis re license conditions & NRC 840731 ltr to util re amend extending expiration date of License SNM-1857 Certificate of Svc encl Related correspondence
BORDENICK, B M Hearing Branch 3 DSB 868 84/08/07 Atomic Safety and Licensing Appeal Panel 4pp 25971 211 24X
Fiche 50-322, 84/08/07, 8408090210

--8408090213 Forwards status list of partial initial decision license conditions & details of NRC intended course of action Requests status rept be forwarded to util
SCHWENCER, A Licensing Branch 2 84/07/30 REIS, E Hearing Branch 3 9pp 25971 213 24X Fiche 50-322, 84/08/07, 8408090210

8408090215 Order scheduling conference of counsel for 840808 Agenda for conference includes scheduling re all pending discovery requests, scheduling of all events in Aug & scheduling & formatting re sua sponte strike issues Served on 840808
LAURENSON, J A Atomic Safety and Licensing Board Panel DSB 853 84/08/07 Office of the Executive Legal Director 1p 25971 244 24X Fiche 50-322, 84/08/07, 8408090215

8408090411 Motion to compel identification of witnesses offering specific elements of testimony re Suffolk County emergency diesel generator contentions Certificate of Svc encl Related correspondence
FARLEY, E M Long Island Lighting Co FARLEY, E M Hunton & Williams DSB 875 84/08/07 Atomic Safety and Licensing Board Panel 6pp 25982 218 24X Fiche 50-322, 84/08/07, 8408090411

8408090431 Motion to strike portions of joint direct testimony of RN Anderson, SG Christensen, GD Eley, A Bakshi, DG Bridenbaugh & RB Hubbard re emergency diesel generators Related correspondence
FARLEY, E M Long Island Lighting Co FARLEY, E M Hunton & Williams DSB 876 84/08/07 Atomic Safety and Licensing Board Panel 37pp 25982 179 24X Fiche 50-322, 84/08/07, 8408090431

8408090242 Memorandum & order granting Suffolk County 840803 motion to compel util to produce FM Rasbury as witness, for deposition Served on 840808
LAURENSON, J A Atomic Safety and Licensing Board Panel DSB 861 84/08/08 Long Island Lighting Co 3pp 25972 166 24X
Fiche 50-322, 84/08/08, 8408090242

8408090490 Order granting LILCO 840807 motion to compel identification of witnesses offering specific elements of testimony re Suffolk County emergency diesel generator contentions Courtesy notification encl Served on 840809
BRENNER, L Atomic Safety and Licensing Board Panel DSB 885 84/08/08 Long Island Lighting Co 4pp 25982 227 24X
Fiche 50-322, 84/08/08, 8408090490

8408130162 Motion to quash subpoenas of FA Cipriani & J Hines to testify on 840822 re ltrs disavowing use of American Red Cross facilities as relocation ctrs Certificate of Svc encl Related correspondence
ZAHNLEUTER, R J New York, State of DSB 931 84/08/08 Atomic Safety and Licensing Board Panel 10pp 26007 354 24X
Fiche 50-322, 84/08/08, 8408130162

8408130264 Statement of MM Cuomo, representing State of NY, in support of Suffolk County 840803 motion to compel LILCO to produce FM Rasbury, LILCO witness, for deposition Certificate of Svc encl Related correspondence
ZAHNLEUTER, R J New York, State of DSB 930 84/08/08 7pp 26006 335 24X Fiche 50-322, 84/08/08, 8408130264

8408130284 Statement of Governor MM Cuomo, representing State of NY, in support of Suffolk County 840803 & 06 motions for reconsideration of ASLB 840724 & 27 scheduling orders Certificate of Svc encl
ZAHNLEUTER, R J New York, State of DSB 932 84/08/08 6pp 26008 282 24X Fiche 50-322, 84/08/08, 8408130284

8408130341 Notice of appearance in proceeding Certificate of Svc encl
BRIGATI,J J Suffolk County, NY DSB 892 84/08/08 4pp
26010 216 24X Fiche 50-322,84/08/08,8408130341

8408130347 Forwards affidavits of MC Cordaro,EP Stergakos,JA Rigert &
JA Scalice,which accompanied util 840803 motion for summary
resolution of ASLB determination & proposal of license
condition Related correspondence
ZEUGIN,L B Hunton & Williams ZEUGIN,L B Long Island Lighting
Co DSB 891 84/08/08 LAURENSON,J A , KLINE,J R , SHON,F J
Atomic Safety and Licensing Board Panel 1p 26010 226 24X
Fiche 50-322,84/08/08,8408130347

--8408130352 Affidavit of MC Cordaro supporting util motion for summary
resolution of issues re effect of Local Emergency Response
Organization strike against util Proposed license condition
re strike issue encl Related correspondence
CORDARO,M C Long Island Lighting Co 84/08/03 4pp 26010 227
24X Fiche 50-322,84/08/08,8408130347

--8408130355 Affidavit of JA Scalice re ASLB 840724 memorandum & order
determining serious safety matter exists Related
correspondence
SCALICE,J A Long Island Lighting Co 84/08/03 4pp 26010 231
24X Fiche 50-322,84/08/08,8408130347

--8408130359 Affidavit of EP Stergakos & JA Rigert in response to ASLB
840724 memorandum & order determining serious safety matter
exists Supports proposition re radiological consequences of
cold shutdown w/normal procedures Related correspondence
STERGAKOS,E P , RIGERT,J A Long Island Lighting Co 84/08/03
8pp 26010 237 24X Fiche 50-322,84/08/08,8408130347

8408130109 Order directing parties to file proposed findings of fact &
conclusions of law by 840831 & giving notice of 840816
conference w/counsel Served on 840810
MILLER,M E Atomic Safety and Licensing Board Panel DSB 896
84/08/09 Office of the Executive Legal Director 2pp
26005 359 24X Fiche 50-322,84/08/09,8408130109

8408140005 Notice of execution of affidavit of nondisclosure re access
to safeguards info relating to util security plan
Certificate of Svc encl Related correspondence
PALOMINO,F G New York, State of DSB 944 84/08/09 Atomic
Safety and Licensing Board Panel 7pp 26044 348 24X
Fiche 50-322,84/08/09,8408140005

8408140003 Memorandum in response to ASLAB 840802 order,asserting that
Suffolk County has not met criteria for granting directed
certification in County 840801 memorandum to show cause
W/Certificate of Svc Related correspondence
IRWIN,D P Long Island Lighting Co IRWIN,D P Hunton & Williams
DSB 959 84/08/10 39pp 26052 265 24X Fiche 50-322,84/08/10,
8408140003

8408140138 Memorandum in support of Suffolk County 840727 motion for
directed certification Criteria for granting directed
certification met & motion should be granted Certificate of
Svc encl Related correspondence
ZAHNLEUTER,R J New York, State of DSB 963 84/08/10 Atomic
Safety and Licensing Appeal Panel 5pp 26044 293 24X
Fiche 50-322,84/08/10,8408140138

8408140466 Requests that 840816 conference re security issues be
postponed until 840820 or other date most convenient to
ASLB
DYNNER,A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips
DYNNER,A R Suffolk County, NY DSB 012 84/08/10 MILLER,M E ,
JOHNSON,E B , BRIGHT,G O Atomic Safety and Licensing Board Panel
2pp. 26060 348 24X Fiche 50-322,84/08/10,8408140466

8408150090 Memorandum in opposition to Suffolk County motion for
directed certification of ASLB 840710 oral order denying
request for production of certain FEMA documents Certificate
of Svc encl Related correspondence
BORDENICK,B M Hearing Branch 3 DSB 044 84/08/10 Atomic
Safety and Licensing Appeal Panel 14pp 26067 033 24X
Fiche 50-322,84/08/10,8408150090

8408150443 Response to Suffolk County motion for directed certification
of ASLB 840710 order which denied Suffolk County request for
production of documents dealt w/in ASLAB 840613 Order
ALAB-773 Certificate of Svc encl Related correspondence
GLASS,B M Federal Emergency Management Agency DSB 063 84/08/10
Atomic Safety and Licensing Appeal Panel 14pp. 26068 235 24X
Fiche 50-322,84/08/10,8408150443

8408140470 Opposition to LILCO 840802 motion for directed certification
of ASLB 840724 order granting in part & denying in part
LILCO motions for summary disposition of Phases I & II low
power testing Related correspondence
LETSCHE,K J Suffolk County, NY LETSCHE,K J Kirkpatrick,
Lockhart, Hill, Christopher & Phillips PALOMINO,F G New York,
State of DSB 008 84/08/13 Commissioners 9pp 26060 333
24X Fiche 50-322,84/08/13,8408140470

--8408140477 Opposition to LILCO 840802 motion for referral of ASLB
840724 order granting in part & denying in part LILCO
motions for summary disposition of Phases I & II low power
testing Certificate of Svc encl Related correspondence
LETSCHE,K J Suffolk County, NY LETSCHE,K J Kirkpatrick,
Lockhart, Hill, Christopher & Phillips PALOMINO,F G New York,
State of 84/08/13 Atomic Safety and Licensing Board Panel
6pp 26060 342 24X Fiche 50-322,84/08/13,8408140470

8408150073 Memorandum & order denying Suffolk County offer of proof &
motion for reconsideration of ASLB limitations on
cross-examination of FEMA witness panel & granting Item 16
on Page 8 Served on 840814
LAURENSON,J A Atomic Safety and Licensing Board Panel DSB 052
84/08/13 Suffolk County, NY 12pp 26067 021 24X
Fiche 50-322,84/08/13,8408150073

8408150142 Forwards memorandum & order denying Suffolk County & State
of NY petition for exemption from regulations precluding
financial qualifications contention & motion for
certification to Commission W/o encl Served on 840814
BRENNER,L Atomic Safety and Licensing Board Panel DSB 051
84/08/13 PLAINE,H H Office of the General Counsel 2pp
26067 016 24X Fiche 50-322,81/08/13,8408150142

8408150155 Memorandum & order denying Suffolk County & State of NY
petition for exemption from regulations precluding financial
qualifications contention 7 motion for certification to
Commission Courtesy notification encl Served on 840814
BRENNER,L Atomic Safety and Licensing Board Panel DSB 050
84/08/13 Suffolk County, NY 30pp 26066 281 24X
Fiche 50-322,84/08/13,8408150155

8408150192 Order denying Suffolk County 840810 request for postponement
of conference w/counsel re security issues,scheduled on
840816 Served on 840814
MILLER,M E Atomic Safety and Licensing Board Panel DSB 053
84/08/13 Suffolk County, NY 3pp 26066 090 24X
Fiche 50-322,84/08/13,8408150192

8408160100 Responds to Suffolk County request for postponement of
840816 conference of counsel Util opposes any postponement
which could prolong low power proceedings Certificate of Svc
encl
ROLFE,R M Hunton & Williams ROLFE,R M Long Island Lighting Co
DSB 070 84/08/13 MILLER,M E , BRIGHT,G O , JOHNSON,E B Atomic
Safety and Licensing Board Panel 4pp 26065 318 24X
Fiche 50-322,84/08/13,8408160100

8408160210 Joint motion for summary disposition of emergency planning
Contentions 24 O,74 & 75 No genuine issue of matl fact
exists & Suffolk County & State of NY entitled to favorable
decision Related correspondence
LETSCHE,K J Suffolk County, NY LETSCHE,K J Kirkpatrick,
Lockhart, Hill, Christopher & Phillips ZAHNLEUTER,R J New York,
State of DSB 076 84/08/13 Atomic Safety and Licensing Board
Panel 12pp 26069 345 24X Fiche 50-322,84/08/13,8408160210

--8408160224 Statement of matl facts as to which there is no genuine
issue re emergency planning Contentions 24 O,74 & 75
Certificate of Svc encl Related correspondence
* Suffolk County, NY * New York, State of 84/08/13 Atomic
Safety and Licensing Board Panel 4pp 26069 357 24X
Fiche 50-322,84/08/13,8408160210

8408150438 Motion for leave to make restricted svc of certain
documents,for protective order & for in camera cross-
examination re documents Certificate of Svc encl Related
correspondence
FARLEY,E M Long Island Lighting Co FARLEY,E M Hunton &
Williams DSB 057 84/08/14 Atomic Safety and Licensing Board
Panel 9pp 26068 262 24X Fiche 50-322,84/08/14,8408150438

8408170315 Opposition to LILCO 840807 motion to strike portions of
joint direct testimony of RN Anderson,et al Certificate of
Svc encl Related correspondence
SCHEIDT,D J Suffolk County, NY SCHEIDT,D J Kirkpatrick,
Lockhart, Hill, Christopher & Phillips DSB 082 84/08/14
Atomic Safety and Licensing Board Panel 43pp 26114 237 24X
Fiche 50-322,84/08/14,8408170315

8408150418 Memorandum & order dismissing Suffolk County 840726 notice of appeal to compel FEMA to produce certain documents Appeal treated as motion to direct certification Directed certification denied Served on 840815
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel DSB 068
84/08/15 Suffolk County, NY 7pp 26068 254 24X
Fiche 50-322,84/08/15,8408150418

8408170332 Memorandum & order denying LILCO 840814 motion for leave to make restricted svc of certain documents for protective order & for in camera cross-examination re documents Served on 840816 Courtesy notification encl
BRENNER,L Atomic Safety and Licensing Board Panel DSB 094
84/08/15 Long Island Lighting Co 5pp 26113 359 24X
Fiche 50-322,84/08/15,8408170332

8408220301 Urges ASLB to rule on emergency generators on basis of technical considerations & to not yield to public hysteria or political pressure to deny low power license w/o technical reason Svc on 840821
MORRIS,T W Citizens for an Orderly Energy Policy, Inc DSB 201
84/08/15 MILLER,M Atomic Safety and Licensing Board Panel 1p
26193 083 24X Fiche 50-322,84/08/15,8408220301

8408200250 Response supporting in part & opposing in part LILCO 840807 motion to strike portions of Suffolk County 840731 joint testimony of RN Anderson,SG Christensen & GD Eley,et al Certificate of Svc encl Related correspondence
GODDARD,R J Hearing Branch 3 DSB 104 84/08/16 Atomic Safety and Licensing Board Panel 16pp 26133 192 24X
Fiche 50-322,84/08/16,8408200250

8408200607 Response supporting early consideration of issues raised in util 840802 motion for directed certification of ASLB 840723 order ruling on util motions for summary disposition of Phase I & II Certificate of Svc encl
PERLIS,R G Hearing Branch 3 DSB 148 84/08/17 Commissioners
9pp 26137 171 24X Fiche 50-322,84/08/17,8408200607

8408210351 Protective order stipulating that authorized persons shall not disclose protected info to anyone except another authorized person,unless info previously disclosed in public record of proceeding Served on 840820
MILLER,M E Atomic Safety and Licensing Board Panel DSB 183
84/08/17 8pp 26177 233 24X Fiche 50-322,84/08/17,8408210351

8408210388 Identification of witnesses offering specific elements of testimony re Suffolk County emergency diesel generator contentions Certificate of Svc encl
BRIGATI,J J Suffolk County, NY BRIGATI,J J Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 187 84/08/17 14pp
26180 252 24X Fiche 50-322,84/08/17,8408210388

8408270082 Forwards affidavit of RJ Goddard re circumstances surrounding filing of NRC staff 840814 response to util motion to strike portions of joint testimony of RN Anderson, SG Christensen,GD Eley,et al Related correspondence
GODDARD,R J Hearing Branch 3 DSB 312 84/08/17 BRENNER,L ,
FERGUSON,G A , MORRIS,P A Atomic Safety and Licensing Board Panel
2pp 26238 133 24X Fiche 50-322,84/08/17,8408270082

--8408270088 Affidavit of RJ Goddard re circumstances surrounding filing of NRC staff 840814 response to util motion to strike portions of joint testimony of RN Anderson,SG Christensen,et al Certificate of Svc encl Related correspondence
GODDARD,R J Hearing Branch 3 84/08/17 6pp 26238 135 24X
Fiche 50-322,84/08/17,8408270082

8408270111 Response supporting util motion for referral of ASLB 840723 order on summary disposition of Phases 1 & 2 of supplemental motion for low power OL Certificate of Svc encl
PERLIS,R G Hearing Branch 3 DSB 313 84/08/17 Atomic Safety and Licensing Board Panel 3pp 26247 326 24X
Fiche 50-322,84/08/17,8408270111

8408270137 Motion for extension of time until 840831 to file direct testimony,as opposed to presently scheduled date of 840821 Related correspondence
GODDARD,R J Hearing Branch 3 DSB 314 84/08/17 Atomic Safety and Licensing Board Panel 2pp 26245 213 24X
Fiche 50-322,84/08/17,8408270137

--8408270143 Affidavit of R Caruso supporting NRC motion for extension of time to file testimony re TDI emergency diesel generators Certificate of Svc encl Related correspondence
CARUSO,R Division of Licensing 84/08/17 7pp 26245 215 24X
Fiche 50-322,84/08/17,8408270137

8408210352 Memorandum & order denying 840719 motion for reconsideration of Commission 840718 order re security contentions Served on 840820
CHILK,S J Office of the Secretary of the Commission DSB 184
84/08/20 Long Island Lighting Co 2pp 26179 198 24X
Fiche 50-322,84/08/20,8408210352

8408230194 Motion to admit new contention addressing issues arising from recent LILCO employee strike Certificate of Svc encl
LETSCHE,K J Suffolk County, NY LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 214 84/08/20
Atomic Safety and Licensing Board Panel 19pp 26209 247 24X
Fiche 50-322,84/08/20,8408230194

8408230199 Clarification of oral argument on matters presented in Suffolk County 840806 motion re proposed findings of fact & conclusions of law Certificate of Svc encl
MCMURRAY,C M Suffolk County, NY MCMURRAY,C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 208 84/08/20
Atomic Safety and Licensing Board Panel 6pp 26207 175 24X
Fiche 50-322,84/08/20,8408230199

8408230264 Response opposing NRC motion for extension of time to file testimony Certificate of Svc encl
DYNNER,A R Suffolk County, NY DYNNER,A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 220 84/08/20 Atomic Safety and Licensing Board Panel 5pp 26209 317 24X
Fiche 50-322,84/08/20,8408230264

8408240424 Staff requirements memo re affirmation/discussion & vote denying 2 206 relief (SECY-84-203),approving order responding to petitions for review of ALAB-763 (SECY-84-254) & approving order denying LILCO 840719 motion (SECY-84-296)
CHILK,S J Office of the Secretary of the Commission 84/08/20
Office of the Secretary of the Commission 3pp 26248 269 24X
Fiche 50-000,84/08/20,8408240424

8408270151 Forwards statements of prof qualifications for TR Quay, MW Hodges & RA Benedict List of witnesses NRC intends to present at 840828 hearing on strike issues include TR Quay, MW Hodges,RA Benedict & JR Sears Related correspondence
HASSELL,D F Hearing Branch 1 DSB 296 84/08/20 LAURENSON,J A ,
SHON,F J , KLINE,J R Atomic Safety and Licensing Board Panel 7pp
26249 146 24X Fiche 50-322,84/08/20,8408270151

8408280249 Forwards affidavit of nondisclosure by LC Lanpher Inclusion of testimony of Suffolk County witnesses Mada & Dirmeir,not bound into 840803 hearing transcript,requested
LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips
LETSCHE,K J Suffolk County, NY DSB 328 84/08/20 MILLER,M E ,
JOHNSON,E B Atomic Safety and Licensing Board Panel 6pp
26261 356 24X Fiche 50-322,84/08/20,8408280249

8408220342 Memorandum & order granting in part NRC 840817 motion for extension of time until 840831 to file testimony Testimony directed to be filed by 840830 Courtesy notification encl Served on 840821
BRENNER,L Atomic Safety and Licensing Board Panel DSB 200
84/08/21 Office of the Executive Legal Director 10pp
26193 043 24X Fiche 50-322,84/08/21,8408220342

8408230231 Forwards list of errata for LILCO testimony on crankshafts, cylinder heads,pistons & cylinder blocks Corrected exhibits & svc list encl Related correspondence
FARLEY,E M Hunton & Williams FARLEY,E M Long Island Lighting Co DSB 211 84/08/21 BRENNER,L , FERGUSON,G A , MORRIS,P A
Atomic Safety and Licensing Board Panel 12pp 26207,260 24X
Fiche 50-322,84/08/21,8408230231

8408230168 Order notifying of 840830 special prehearing conference in Bethesda,MD to consider & rule on security contentions Served on 840822
MILLER,M E Atomic Safety and Licensing Board Panel DSB 253
84/08/22 Office of the Executive Legal Director 2pp
26209 266 24X Fiche 50-322,84/08/22,8408230168

8408270364 Notice of resumption of hearing on 840910 in Hauppauge,NY re emergency diesel engines Served on 840824
BRENNER,L Atomic Safety and Licensing Board Panel DSB 315
84/08/23 3pp 26245 055 24X Fiche 50-322,84/08/23,8408270364

8408280433 Forwards corrections to 840816 transcript of util closing arguments in low power proceeding Corrections noted on transcript Copies provided to any party on svc list at party expense W/o encl Related correspondence
MONAGHAN,J A Hunton & Williams MONAGHAN,J A Long Island Lighting Co DSB 351 84/08/23 MILLER,M E Atomic Safety and Licensing Board Panel 2pp 26280 213 24X Fiche 50-322,84/08/23,8408280433

8408280492 Forwards master table of contents,as requested by Judge Morris,for all testimony filed by LILCO on crankshafts, pistons,cylinder heads & cylinder blocks Related correspondence
FARLEY,E M Hunton & Williams FARLEY,E M Long Island Lighting Co DSB 356 84/08/23 BRENNER,L , FERGUSON,G A , MORRIS,P A
Atomic Safety and Licensing Board Panel 7pp 26280 338 24X
Fiche 50-322,84/08/23,8408280492

8408290317 Forwards LILCO testimony on cylinder heads & pistons W/o encl Related correspondence
FARLEY,E M Hunton & Williams FARLEY,E M Long Island Lighting Co DSB 378 84/08/23 MORRIS,P A Atomic Safety and Licensing Board Panel 1p 26290 337 24X Fiche 50-322,84/08/23,8408290317

8408280405 Informs that HK Brown,KJ Letsche,LC Lanpher,D Kraemer, S Ober & P McGuire designated as authorized persons,per 840817 protective order Related correspondence
LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips LETSCHE,K J Suffolk County, NY DSB 362 84/08/24 MILLER,M E BRIGHT,G O , JOHNSON,E B Atomic Safety and Licensing Board Panel 47pp 26280 129 24X Fiche 50-322,84/08/24,8408280405

8408280424 Informs that staff proposed witnesses include C Berlinger, SJ Bush,AJ Henriksen,WV Laity & A Sarsten,per ASLB 840821 memorandum & order Prof qualifications of witnesses & Certificate of Svc encl Related correspondence
GODDARD,R J Hearing Branch 3 DSB 339 84/08/24 BRENNER,L , MORRIS,P A , FERGUSON,G A Atomic Safety and Licensing Board Panel 72pp 26280 218 24X Fiche 50-322,84/08/24,8408280424

8408300124 Answer in opposition to Suffolk County 840820 motion seeking admission of late-filed contention re recent strike by unions representing LILCO employees Certificate of Svc encl
CHRISTMAN,J N Long Island Lighting Co CHRISTMAN,J N Hunton & Williams DSB 385 84/08/27. Atomic Safety and Licensing Board Panel 27pp 26305 194 24X Fiche 50-322,84/08/27,8408300124

8408300161 Order extending time until 840912 for Commission to act to review ALAB-777 Served on 840829
CHILK,S J Office of the Secretary of the Commission DSB 388 84/08/29 Commissioners 1p 26304 342 24X
Fiche 50-322,84/08/29,8408300161

8408310224 Supplemental motion to strike portions of joint direct testimony of RN Anderson,SG Christensen,GD Eley,A Bakshi, DG Bridenbaugh & RB Hubbard Certificate of Svc encl
Related correspondence
FARLEY,E M Long Island Lighting Co. FARLEY,E M Hunton & Williams DSB 422 84/08/29 Atomic Safety and Licensing Board Panel. 17pp 26319:259 24X Fiche 50-322,84/08/29,8408310224

8408310218 Forwards attachments omitted from applicant motion to strike Incomplete dispositions of RN Anderson,D Eley, RB Hubbard & SG Christensen encl Related correspondence
FARLEY,E M Hunton & Williams FARLEY,E M Long Island Lighting Co DSB 424 84/08/30 BRENNER,L , FERGUSON,G A , MORRIS,P A Atomic Safety and Licensing Board Panel 31pp 26318 127 24X
Fiche 50-322,84/08/30,8408310218

H General correspondence

8408070211 Ack receipt of 840622 ltr to Palladino requesting info re safety questions raised by JW Huber Concerns highlighted in Huber 830309 list,encompassing design,const & testing, involve no violations of NRC regulations
DIRCKS,W J Office of the Executive Director for Operations 84/07/25 CARNEY,W House of Rep 4pp 25957 054 24X
Fiche 50-322,84/07/25,8408070211

--8408070217 Forwards JW Huber 840612 ltr re safety questions noted during employment by util Info addressing Huber contentions requested W/840611 telcon record
CARNEY,W House of Rep 84/06/22 PALLADINO,N J Commissioners 3pp 25957-057 24X Fiche 50-322,84/07/25,8408070211

8408280054 Responds to 840717 ltr re plant completion & startup issues under consideration include adequacy of emergency plan & adequacy of onsite emergency diesel generators
DIRCKS,W J Office of the Executive Director for Operations 84/08/20 SPENCER,F D. House of Rep 7pp 26309 001 24X
Fiche 50-322,84/08/20,8408280054

-8408280056 Forwards WC Putnam ltr urging completion of plant & development of evacuation plan
SPENCE,F D House of Rep 84/07/17 PALLADINO,N J Commissioners 2pp 26309 007 24X Fiche 50-322,84/08/20, 8408280054.

. Inspection reports, IE Bulletins & correspondence

8408080473 Forwards IE Insp Rept 50-322/84-22 on 840514-18 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/07/16
LEONARD,J D Long Island Lighting Co 2pp 25975 164 24X
Fiche 50-322,84/07/16,8408080473

--8408080478 IE Insp Rept 50-322/84-22 on 840514-18 No violations noted Major areas inspected plant facilities & initial fuel load & startup testing planning Safeguards info deleted (ref 10CFR73 21)
BLUMBERG,N , KUCHARSKI,S , BETTENHAUSEN,L Region 1, Office of Director 84/07/05 6pp 25975 166 24X Fiche 50-322,84/07/16, 8408080473

8408090315 Forwards IE Insp Rept 50-322/84-14 on 840416-27 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/07/16
LEONARD,J D Long Island Lighting Co 2pp, 25994 072 24X
Fiche 50-322,84/07/16,8408090315

--8408090330 IE Insp Rept 50-322/84-14 on 840416-27 No violations noted Major areas inspected licensee action on previous insp findings & NRC bulletins & circulars
FINKEL,A , NAPUDA,G , NICHOLAS,H Region 1, Office of Director 84/06/25 40pp 25994 074 24X Fiche 50-322,84/07/16,8408090315

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408160251 Forwards IE Insp Rept 50-322/84-24 on 840626-29 No violations observed
MARTIN,T T Division of Engineering & Technical Programs 84/08/01
LEONARD,J D Long Island Lighting Co 4pp 26106 193 24X
Fiche 50-322,84/08/01,8408160251

--8408160260 IE Insp Rept 50-322/84-24 on 840626-29 No violations identified Major areas inspected civil/structural facilities re const of emergency diesel generator bldg & review of design & observation of const activities
VARELA,A A , DURR,J P Region 1, Office of Director 84/07/20
5pp 26106 197 24X Fiche 50-322,84/08/01,8408160251

8408230242 Forwards IE Insp Rept 50-322/84-25 on 840626-29 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/08/03
LEONARD,J D Long Island Lighting Co 4pp 26213 284 24X
Fiche 50-322,84/08/03,8408230242

--8408230248 IE Insp Rept 50-322/84-25 on 840626-28 No violations noted Major areas inspected licensee action on previous insp findings,bulletins & circulars
NIMITZ,R L Region 1, Office of Director PASCIAK,W J Division of Engineering & Technical Programs 84/08/02 10pp 26213 288 24X Fiche 50-322,84/08/03,8408230242

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408290478 Forwards Insp Rept 50-322/84-23 on 840528-0701 No violations noted
STAROSTECKI,R Division of Project & Resident Programs 84/08/08
LEONARD,J L Long Island Lighting Co 4pp 26294 189 24X
Fiche 50-322,84/08/08,8408290478

--8408290483 Insp Rept 50-322/84-23 on 840528-0701 No violations noted Major areas inspected discharge of security guard weapon,status of Colt diesel generator project,storage of emergency equipment lockers & IE Bulletin 80-06,
PETRONE,C , ESELGROTH,P , SHEDLOSKY,J Region 1, Office of Director 84/07/19 12pp 26294 193 24X Fiche 50-322,84/08/08, 8408290478

--8408290486 Forwards directive & associated procedure for tightening diesel engine reassembly program,in connection w/diesel generator rocker arm incident
POLLOCK,M S Long Island Lighting Co 84/01/13 MURLEY,T E
Region 1, Office of Director 8pp 26294 211 24X
Fiche 50-322,84/08/08,8408290478

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12Spp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408280180 Informs that performance acceptable during period of const completion & readiness for operation, per SALP Util performance & responsiveness to NRC concerns improved during past yr
MURLEY, T E Region 1, Office of Director 84/08/21 LEONARD, J D Long Island Lighting Co 5pp 26275 037 24X Fiche 50-322, 84/08/21, 8408280180

--8408280187 Responds to 840514 ltr forwarding SALP rept for period Feb 1983 - Feb 1984 Details of action being taken on functional areas will be addressed on site w/NRC resident inspector
LEONARD, J D Long Island Lighting Co 84/06/26 STAROSTECKI, R Division of Project & Resident Programs 4pp 26275 042 24X Fiche 50-322, 84/08/21, 8408280180

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000, 84/05/24, 8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000, 84/05/24, 8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000, 84/05/24, 8405290179

--8405290271 "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
* Failure Analysis Associates FAAA-84-3-16 84/05/22 89pp 24692 092 24X Fiche 50-000, 84/05/24, 8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER, M Division of Licensing 158pp 25926 173 24X Fiche 50-000, 84/06/28, 8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/07/10 BERLINGER, C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000, 84/07/10, 8408060050

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000, 84/07/27, 8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000, 84/07/27, 8408060102

8408060324 Forwards "Design Review of Elliott Model 65Q Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24X Fiche 50-000, 84/08/01, 8408060324

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000, 84/08/10, 8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24X Fiche 50-000, 84/08/10, 8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT, D G Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc) Owners Group GEORGE, J B Texas Utilities Electric Co (Formerly Texas Utilities Generating Co)
1p 26255 194 24X Fiche 50-000, 84/08/13, 8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp 26255 195 24X Fiche 50-000, 84/08/13, 8408240115

8408160395 Forwards "Design Review of Elliott Model 90Q Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL, per NRC request
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000, 84/08/14, 8408160395

--8408160397 "Design Review of Elliott Model 90Q Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp 26088 165 24X Fiche 50-000, 84/08/14, 8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/08/23 BERLINGER, C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000, 84/08/23, 8408290179

T Hearing transcripts on non-antitrust matters

8406220259 Board Notification 84-120 forwards transcripts of 840426, 0502 & 24 meetings w/TDI Owners Group re status of program to establish diesel generator reliability
EISENHUT, D G Division of Licensing 84/06/20 PALLADINO, GILINSKY, ROBERTS Commissioners 54pp 25206 099 24X Fiche 50-000, 84/06/20, 8406220259

8408010077 Transcript of R Kessel 840702 deposition in New York,NY Pp 1-93
* Atomic Safety and Licensing Board Panel KESSEL,R New York, State of 84/07/02 94pp 25856 133 24X Fiche 50-322,84/07/02, 8408010077

8408020021 Direct testimony of EP Radford & SC Saegert re Contention 16 E Certificate of Svc encl Related correspondence
RADFORD,E P , SAEGERT,S C Suffolk County, NY RADFORD,E P Pittsburgh, Univ of, Pittsburgh, PA DSB 694 84/07/30 16pp 25882 284 24X Fiche 50-322,84/07/30,8408020021

8408020024 Motion to admit revised testimony of Phase II emergency planning Contentions 24 O,74 & 75 (relocation ctrs) Certificate of Svc encl Related correspondence
MCCLESKEY,K E Long Island Lighting Co MCCLESKEY,K E Hunton & Williams DSB 698 84/07/30 Atomic Safety and Licensing Board Panel 68pp 25883 150 24X Fiche 50-322,84/07/30,8408020024

8408020048 Testimony of CA Clawson,MC Cordaro & RJ Watts on Contention 16 E re public info on radiation Certificate of Svc encl Related correspondence
CLAWSON,C A , CORDARO,M C , WATTS,R J Long Island Lighting Co DSB 697 84/07/30 40pp 25883 275 24X Fiche 50-322,84/07/30, 8408020048

8408060078 Transcript of 840730 hearing in Hauppauge,NY Pp 714-1,027 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/07/30 349pp 25922 017 24X Fiche 50-322,84/07/30,8408060078

8408020129 Joint direct testimony of RN Anderson,SG Christensen, OD Eley,A Bakshi,DG Bridenbaugh & RB Hubbard re Suffolk County emergency diesel generator contentions Certificate of Svc encl Related correspondence
ANDERSON,R N San Jose State Univ , San Jose, CA CHRISTENSEN,S W S Merchant Marine Academy, Kings Point, NY ELEY,G D Ocean Fleets Consultancy Service DSB 709 84/07/31 1326pp 25886 223 24X Fiche 50-322,84/07/31,8408020129

8408060086 Transcript of 840731 hearing in Hauppauge,NY re low power license Pp 1,028-1,349
* Atomic Safety and Licensing Board Panel 84/07/31 321pp 25927 125 24X Fiche 50-322,84/07/31,8408060086

8408030105 Motion to admit proposed modified emergency planning Contention 88 & revised testimony of GC Minor on emergency planning Contentions 85 & 88 Related correspondence
MILLER,M S Suffolk County, NY MILLER,M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 725 84/08/01 Atomic Safety and Licensing Board Panel 11pp 25916 055 24X Fiche 50-322,84/08/01,8408030105

--8408030112 Revised testimony of GC Minor on emergency planning Contentions 85 & 88 re offsite recovery & reentry Prof qualifications statement & Certificate of Svc encl
MINOR,G C Suffolk County, NY MINOR,G C MHB Technical Associates 84/08/01 18pp 25916 066 24X Fiche 50-322,84/08/01,8408030105

8408080039 Transcript of 840801 hearing in Hauppauge,NY Pp 1,350 - 1,676
* Atomic Safety and Licensing Board Panel 84/08/01 328pp 25969 335 24X Fiche 50-322,84/08/01,8408080039

8408080042 Transcript of 840802 hearing in Hauppauge,NY Pp 1,677-1,948
* Atomic Safety and Licensing Board Panel 84/08/02 272pp 25961 061 24X Fiche 50-322,84/08/02,8408080042

8408070352 Testimony of SA Schwartz re emergency preparedness Contention 11 Certificate of Svc encl Related correspondence
SCHWARTZ,S A Division of Emergency Preparedness & Engineering Response (Post 830103) DSB 819 84/08/03 9pp 25945 200 24X Fiche 50-322,84/08/03,8408070352

8408080150 Transcript of 840803 hearing in Hauppauge,NY Pp 1,949-2,196
* Atomic Safety and Licensing Board Panel 84/08/03 250pp 25959 028 24X Fiche 50-322,84/08/03,8408080150

8408080035 Transcript of 840804 hearing in Riverhead,NY Pp 2,197-2,332
* Atomic Safety and Licensing Board Panel 84/08/04 141pp 25962 006 24X Fiche 50-322,84/08/04,8408080035

8408130373 Testimony on training Contentions 39,40,41,44,98,99 & 100 Pp 101-111 Certificate of Svc encl Related correspondence
* Federal Emergency Management Agency DSB 903 84/08/06 14pp 26011 001 24X Fiche 50-322,84/08/06,8408130373

8408140391 Transcript of 840806 hearing in Hauppauge,NY re low power operation Pp 2,333-2 657
* Atomic Safety and Licensing Board Panel 84/08/06 325pp 26053 001 24X Fiche 50-322,84/08/06,8408140391

8408140339 Transcript of 840807 hearing in Hauppauge,NY re low power operation Pp 2,658-2 968
* Atomic Safety and Licensing Board Panel 84/08/07 311pp 26041 165 24X Fiche 50-322,84/08/07,8408140339

8408130209 Transcript of 840808 conference of counsel in Bethesda,MD re emergency planning procedure Pp 13,985-14,041 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/08/08 64pp 26008 001 24X Fiche 50-322,84/08/08,8408130209

8408140255 Transcript of 840808 conference of counsel in Bethesda,MD re emergency planning Pp 13,985-14,041 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/08/08 62pp 26054 276 24X Fiche 50-322,84/08/08,8408140255

8408140013 Forwards table of contents for RN Anderson 840731 joint direct testimony re Model AE pistons,replacement cylinder heads & cylinder blocks,per ASLB 840801 order on miscellaneous prehearing matters Related correspondence
DYNNER,A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DYNNER,A R Suffolk County, NY DSB 955 84/08/09 BRENNER,L J , FERGUSON,G A , MORRIS,P A Atomic Safety and Licensing Board Panel 1p 26044 162 24X Fiche 50-322,84/08/09,8408140013

--8408140017 Table of contents for RN Anderson 840731 joint direct testimony re Model AE pistons,replacement cylinder heads, replacement crankshafts & cylinder blocks
ANDERSON,R N Suffolk County, NY 84/07/31 3pp 26044 163 24X Fiche 50-322,84/08/09,8408140013

8408150473 Forwards direct testimony & supporting exhibits on adequacy & reliability of TDI emergency diesel generators W/o motion for protective order Certificate of Svc encl Related correspondence
TARLETZ,D B Hunton & Williams TARLETZ,D B Long Island Lighting Co DSB 065 84/08/14 BRENNER,L , FERGUSON,G A , MORRIS,P A Atomic Safety and Licensing Board Panel 4pp 26068 295 24X Fiche 50-322,84/08/14,8408150473

--8408150476 Testimony of CH Wells,DP Johnson,HF Wachob,C Seaman,D Cimino & NK Burrell re shotpeening of replacement crankshafts Related correspondence
WELLS,C H , JOHNSON,D P , WACHOB,H F Long Island Lighting Co 84/08/14 36pp 26068 299 24X Fiche 50-322,84/08/14,8408150473

--8408150485 Testimony of RL McCarthy,PR Johnson,EF Montgomery & SK Chen on Suffolk County contention re replacement crankshafts on diesel generators Related correspondence
MCCARTHY,R L , JOHNSON,P R , MONTGOMERY,E F Long Island Lighting Co 84/08/14 62pp 26068 337 24X Fiche 50-322,84/08/14, 8408150473

--8408150498 Testimony of EJ Youngling & FF Pischinger on Suffolk County contention re replacement crankshafts on diesel generators Exhibits encl Related correspondence
YOUNGLING,E J , PISCHINGER,F F Long Island Lighting Co 84/08/14 600pp 26069 036 24X Fiche 50-322,84/08/14, 8408150473

--8408150505 Vols 1,2 & 3 of testimony of RL McCarthy,CA Rau,CH Wells, HF Wachob,D Johnson,RK Taylor,CK Seaman,EJ Youngling, CS Mathews,MH Lourey,JF Wallace & MH Schuster on Suffolk County contention re cylinder blocks Related correspondence
MCCARTHY,R L , RAU,C A , WELLS,C H Long Island Lighting Co 84/08/14 300pp 26070 313 24X Fiche 50-322,84/08/14, 8408150473

--8408150514 Vols 1 & 2 of testimony of DO Harris,DP Johnson,RL McCarthy, FF Pischinger,CK Seaman,LA Swanger & EJ Youngling on Suffolk County contention re AE piston skirts Related correspondence
HARRIS,D O , JOHNSON,D P , MCCARTHY,R L Long Island Lighting Co 84/08/14 450pp 26071 200 24X Fiche 50-322,84/08/14, 8408150473

--8408150530 Vols 1 & 2 of testimony of CK Seaman,EJ Youngling, JC Kammeyer,CH Wells,LA Swanger,JF Wallace,CS Mathews & FC Pischinger on Suffolk County contention re cylinder heads Exhibits 1-26 encl Related correspondence
SEAMAN,C K , YOUNGLING,E J , KAMMEYER,J C Long Island Lighting Co 84/08/14 300pp 26072 327 24X Fiche 50-322,84/08/14, 8408150473

8408210209 Transcript of 840814 hearing in Hauppauge,NY re emergency planning Pp 14,042-14,240
* Atomic Safety and Licensing Board Panel 84/08/14 256pp
26147 121 24X Fiche 50-322 84/08/14,8408210209

8408210035 Transcript of 840815 hearing in Hauppauge,NY re emergency planning Pp 14,214-14,503
* Atomic Safety and Licensing Board Panel 84/08/15 253pp
26146 165 24X Fiche 50-322,84/08/15,8408210035

8408210458 Transcript of 840816 hearing in Hauppauge,NY re emergency planning Pp 14,504-14,688
* Atomic Safety and Licensing Board Panel 84/08/16 187pp
26177 001 24X Fiche 50-322,84/08/16,8408210458

8408280020 Transcript of 840816 Commission meeting in Washington,DC re affirmation/discussion & vote Pp 1-7
* Commissioners 84/08/16 10pp 26294 013 24X
Fiche 50-000,84/08/16,8408280020

8408280135 Transcript of 840821 hearing in Hauppauge,NY
Pp 14,689-14,906A
* Atomic Safety and Licensing Board Panel 84/08/21 288pp
26259 213 24X Fiche 50-322,84/08/21,8408280135

8408280151 Transcript of 840822 hearing in Hauppauge,NY re emergency planning Pp 14,907-15,176 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/08/22 294pp
26264 161 24X Fiche 50-322,84/08/22,8408280151

8408280004 Transcript of 840823 hearing in Hauppauge,NY
Pp 15,178-15,242
* Atomic Safety and Licensing Board Panel 84/08/23 329pp
26260 143 24X Fiche 50-322,84/08/23,8408280004

8408280394 Forwards corrected master table of contents for testimony on crankshafts,pistons,cylinder heads & cylinder blocks Related correspondence
RANGE,J J Hunton & Williams RANGE,J J Long Island Lighting Co
DSB 352 84/08/24 BRENNER,L , MORRIS,P A , FERGUSON,G A Atomic Safety and Licensing Board Panel 1p 26280 038 24X
Fiche 50-322,84/08/24 8408280394

--8408280397 Corrected master table of contents for testimony on crankshafts,pistons,cylinder heads & cylinder blocks Related correspondence
* Long Island Lighting Co 84/08/23 7pp 26280 039 24X
Fiche 50-322,84/08/24,8408280394

V Operator Examinations

8408070385 Forwards shift advisors resumes,per 840702 ltr in response to NRC 840531 request Shift advisors w/o operator license will be examined,per 10CFR55 60,"Exam Form "
LEONARD,J D Long Island Lighting Co 84/07/25 DENTON,H R
Office of Nuclear Reactor Regulation, Director 10pp 25945 269
24X Fiche 50-322 84/07/25,8408070385

8408060323 Forwards response to NRC comments on licensed operator requalification program
LEONARD,J D Long Island Lighting Co 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25933 331
24X Fiche 50-322,84/07/31,8408060323

8408300123 Forwards updates on operating shift staffing submittals dtd 831221 & 840322,per 840531 request Updates include qualification matrices for onsite mgt,operating shift personnel & shift technical advisors
LEONARD,J D Long Island Lighting Co 84/08/21 DENTON,H R
Office of Nuclear Reactor Regulation, Director 11pp 26306 077
24X Fiche 50-322,84/08/21,8408300123

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8408310138 FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by PG&E re earthquake on Nacimiento fault & one equal to 1906 San Francisco earthquake
CALSOYAS,C D Affiliation Not Assigned 84/04/07 NRC - No
Detailed Affiliation Given 4pp 26352 011 24X
Fiche 50-275,84/04/07,8408310138

8408310142 Responds to FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by PG&E re earthquake Forwards printout of documents re Mothers for Peace Other documents in PDR
FELTON,J M Division of Rules and Records 84/06/01 CALSOYAS,C D
Affiliation Not Assigned 1p 26352 015 24X
Fiche 50-275,84/06/01,8408310142

8408300482 Requests exam & test requirements for all presently licensed personnel for Unit 1 be waived for Unit 2 & combined OLs for Units 1 & 2 be issued Supporting documentation encl Related correspondence
SCHUYLER,J O , CRANE,P A Pacific Gas & Electric Co DSB 720
84/07/17 MARTIN,J B , PATE,R J Region 5, Office of Director
88pp 26329 189 24X Fiche 50-275,84/07/17,8408300482

8408140011 Forwards 840713 rept, "June 20,1984 Santa Maria Offshore Earthquake,Ground Motion at Diablo Canyon Power Plant "
Rept contains tabulation of peak accelerations & recorded accelerograms
SCHUYLER,J O Pacific Gas & Electric Co 84/07/20 EISENHUT,D G
Division of Licensing 1p 26044 128 24X Fiche 50-275,84/07/20,
8408140011

--8408140012 "June 20,1984 Santa Maria Offshore Earthquake,Ground Motion at Diablo Canyon Power Plant "
* TERA Corp 84/07/13 33pp 26044 129 24X
Fiche 50-275,84/07/20,8408140011

8408060120 Forwards tube steel review,in response to NRC 840717 verbal request re existence of tube steel of suspect quality Results confirm problem identified in one 20-ft section not used in pipe support installation
SCHUYLER,J O Pacific Gas & Electric Co 84/07/26 MARTIN,J B
Region 5, Office of Director 3pp 25933 194 24X
Fiche 50-323,84/07/26,8408060120

8408060126 Forwards IDVP internal review program summary & status rept, describing scope,methodology & status of resolution of verification issues
SCHUYLER,J O Pacific Gas & Electric Co 84/07/31 KNIGHTON,G W
Licensing Branch 3 49pp 25932 199 24X Fiche 50-323,84/07/31,
8408060126

8408070278 Forwards comparison of safety-related design aspects of Unit 2 relative to Unit 1,in response to NRC request & to support licensing of Unit 2
SCHUYLER,J O Pacific Gas & Electric Co 84/07/31 KNIGHTON,G W
Licensing Branch 3 5pp 25948 101 24X Fiche 50-323,84/07/31,
8408070278

8408310032 Forwards Ofc of Inspector & Auditor 840801 rept of investigation re allegations against seven NRC employees as result of T Devine 840412 & 0503 10CFR2 206 petitions on NRC misleading or matl false statements to Commission
MESSENGER,G H Office of Inspector & Auditor 84/08/01 PALLADINO,
ROBERTS, ASSELSTINE Commissioners 2pp 26349 001 24X
Fiche 50-275,84/08/01,8408310032

--8408310035 Investigation rept on 840801 Major areas investigated allegations re NRC misleading or matl false statements to Commission during 840319,26 & 27 briefings & in SSER 21 & 22 for Dec 1983 & Mar 1984,respectively
SMITH,R M , BOWERS,H , MESSENGER,G H Office of Inspector & Auditor 84/08/01 400pp 26349 003 24X Fiche 50-275,84/08/01,
8408310032

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408130188 Forwards proposed changes in post-fuel loading initial test program re test scope clarification & conducting existing tests at addl (lower) power plateaus Review & approval required by 840828
SCHUYLER,J O Pacific Gas & Electric Co 84/08/08 KNIGHTON,G W
Licensing Branch 3 3pp 26008 288 24X Fiche 50-275,84/08/08,
8408130188

8408210639 Forwards SLO-2 work request & work authorization mistakenly omitted from 840801 ltr
PETERS,R J Pacific Gas & Electric Co 84/08/08 MITCHELL-WILSON
California, State of 2pp 26184 351 24X Fiche 50-275,84/08/08,
8408210639

8408210406 Requests approval for removal of RHR suction valve automatic closure interlock Upon approval,util will install alarms & restore power to RHR suction valve operators during periods of RHR sys operation while aligned to RCS
SCHUYLER,J D Pacific Gas & Electric Co 84/08/15 KNIGHTON,G W Licensing Branch 3 2pp 26180 336 24X Fiche 50-275,84/08/15, 8408210406

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408270396 Forwards request for extension of const completion date until 850930
SCHUYLER,J D Pacific Gas & Electric Co 84/08/22 KNIGHTON,G W Licensing Branch 3 2pp 26238 144 24X Fiche 50-323,84/08/22, 8408270396

D NRC Draft/Final Environmental Statements, supplS & correspondence

8408140273 Forwards 69 photos attesting to serious long-range problems of erosion of siltation on property contiguous to facility Requests name of responsible NRC employee to respond to concerns
BRUNO,G E Affiliation Not Assigned 83/07/11 DENTON,H Office of Nuclear Reactor Regulation, Director 38pp 26051 203 24X
Fiche 50-275,83/07/11,8408140273

E NRC Safety Evaluation Report (SER), supplS & correspondence

8407310038 Board Notification 84-137 forwards SSERs 24-27 re IDVP matters,piping & supports,allegations - status & summary & full power license amend matters,respectively No substantive changes made W/o encls
EISENHUT,D G Division of Licensing 84/07/30 PALLADINO, ROBERTS, ASSELSTINE Commissioners 3pp 26011 015 24X
Fiche 50-275,84/07/30,8407310038

8408130002 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 & 2 Docket Nos 50-275 & 50-323 (Pacific Gas & Electric Company)
* Division of Licensing NUREG-0675 S24 84/07/31 16pp
26038 295 24X Fiche 50-275,84/07/31,8408130002

8408160080 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Pacific Cas And Electric Company)
* Division of Licensing NUREG-0675 S25 84/07/31 122pp
Available at NRC $5 50 26124 033 24X Fiche 50-275,84/07/31, 8408160080

8408160250 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Pacific Cas And Electric Company)
* Division of Licensing NUREG-0675 S27 84/07/31 31pp
Available at NRC $3 50 26122 235 24X Fiche 50-275,84/07/31, 8408160250

8408220346 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2
* Division of Licensing, NUREG-0675 S26 84/07/31 204pp
Available at NRC $6 50 26200 001 24X Fiche 50-275,84/07/31, 8408220346

F Security, medical, emergency & fire protection plans

8408080453 Forwards public version of revs to Vol III of San Luis Obispo County emergency response plan std operating procedures
SCHUYLER,J D Pacific Gas & Electric Co 84/07/16 MARTIN,J B Region 5, Office of Director 2pp 25976 071 24X
Fiche 50-275,84/07/16,8408080453

--8408080458 Public version of revs to Vol III of San Luis Obispo County emergency response std operating procedures (SOP),including Section III 01, "SOP Emergency Svcs Director " W/Felton 840802 release memo
SCHUYLER,J D Pacific Gas & Electric Co 84/02/29 434pp
25976 073 24X Fiche 50-275,84/07/16,8408080453

8408160267 Forwards public version of emergency plan implementing procedures,including EP R-1 re personnel injury or illness (radiological related) &/or overexposure & EP M-1 re employee injury or illness (nonradiological)
SCHUYLER,J D Pacific Gas & Electric Co 84/07/20 MARTIN,J B Region 5, Office of Director 4pp 26125 239 24X
Fiche 50-275,84/07/20,8408160267

--8408160273 Public version of emergency plan implementing procedures, including EP R-1 re personnel injury or illness (radiological related) &/or overexposure W/JM Felton 840808 release memo
* Pacific Gas & Electric Co 84/07/20 178pp 26125 243 24X
Fiche 50-275 84/07/20,8408160267

8408230553 Forwards public version of updated emergency plan implementing procedures,including EP R-1 re personnel injury or illness (radiologically related) &/or overexposure & EP G-4 re personnel accountability & assembly
SCHUYLER,J D Pacific Gas & Electric Co 84/08/08 MARTIN,J B Region 5, Office of Director 1p 26216 206 24X
Fiche 50-275,84/08/08,8408230553

--8408230558 Public version of updated emergency plan implementing procedures,including EP R-1 re personnel injury or illness (radiologically related) &/or overexposure & EP G-4 re personnel accountability & assembly W/840820 release memo
THORNBERRY,R C Pacific Gas & Electric Co 84/08/08 182pp
26216 207 24X Fiche 50-275,84/08/08,8408230553

8408230300 Forwards RW Kriem 840711 ltr transmitting FEMA interim finding in State of CA emergency response plan Plan adequate Areas for improvement identified,including protective action guideline doses
KNIGHTON,G W Licensing Branch 3 84/08/16 SCHUYLER,J D Pacific Gas & Electric Co 3pp 26236 105 24X Fiche 50-275,84/08/16, 8408230300

8408310230 Revised emergency plan implementing procedures,including EP R-2 re release of airborne radioactive matls,EP E1-6 re EARS 9845c controling stations & EP RB-15 & 16 re sentry post-accident sampling sys W/840827 ltr
SCHUYLER,J D Pacific Gas & Electric Co 84/08/27 MARTIN,J B Region 5, Office of Director 363pp 26321 001 24X
Fiche 50-275,84/08/27,8408310230

G Adjudicatory correspondence

8408010235 Forwards affidavit of JL McDermott,per 840729 submittal Supporting brief will be sent to Commission on 840730 along w/O'Neill rebuttal affidavit
DEVINE,T Government Accountability Project DSB 681 84/07/30
PALLADINO,N J , ROBERTS,T , ASSELSTINE,J Commissioners 1p
25854 001 24X Fiche 50-275,84/07/30,8408010235

--8408010237 Affidavit of JL McDermott re need for reinspn & systematic retraining of all personnel at facility
MCDERMOTT,J L Government Accountability Project 84/07/30
35pp 25894 002 24X Fiche 50-275,84/07/30,8408010235

8408060046 Motion for leave to withdraw confidential Exhibit 10 filed in support of Joint Intervenors 840214 motion to augment or reopen record Declaration in support of motion & Certificate of Svc encl
REYNOLDS,J R Joint Intervenors - Diablo Canyon REYNOLDS,J R Center for Law in the Public Interest DSB 696 84/07/30 Atomic Safety and Licensing Appeal Panel 9pp 25925 298 24X
Fiche 50-275,84/07/30,8408060046

8408060217 Motion for leave to withdraw confidential exhibit previously filed in support of motion to augment or to reopen record Declaration encl Granted on 840731
REYNOLDS,J R Joint Intervenors - Diablo Canyon REYNOLDS,J R Center for Law in the Public Interest DSB 708 84/07/30 Atomic Safety and Licensing Appeal Panel 6pp 25927 015 24X
Fiche 50-275,84/07/30,8408060217

8408070297 Motion for leave to withdraw confidential exhibit previously filed in support of 840214 motion to augment or, in alternative, to reopen record Declaration & Certificate of Svc encl
REYNOLDS,J R Joint Intervenors - Diablo Canyon DSB 809
84/07/30 Atomic Safety and Licensing Appeal Panel 9pp
25947 297 24X Fiche 50-275,84/07/30,8408070297

8408020152 Forwards supp1 supporting T O'Neill 840727 petition under 10CFR2 206 on behalf of J McDermott & T O'Neill Also expands original request for retraining
DEVINE,T Government Accountability Project DSB 701 84/07/31
PALLADINO,N J Commissioners 327pp 25884 139 24X
Fiche 50-275,84/07/31,8408020152

8408020219 Order requiring Joint Intervenors to file reply addressing jurisdictional question in 840716 motion to reopen record on seismic issues Served on 840801
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel DSB 716
84/08/01 Joint Intervenors - Diablo Canyon 1p 25898 009 24X
Fiche 50-275,84/08/01,8408020219

8408020222 Answer opposing Joint Intervenors 840725 application for stay re effectiveness of ASLB 820831 Initial Decision LBP-82-70 & of issuance of full power OL
CHANDLER, L J Hearing Branch 2 DSB 710 84/08/01
Commissioners 11pp 25897 279 24X Fiche 50-275, 84/08/01, 8408020222

--8408020227 Answer opposing Joint Intervenors 840717 petition for review of ALAB-775 Petition fails to establish existence of important issue of fact law or policy warranting Commission review
CHANDLER, L J Hearing Branch 2 84/08/01 Commissioners
10pp 25897 290 24X Fiche 50-275, 84/08/01 8408020222

--8408020231 Answer opposing Joint Intervenors 840717 petition for review of ALAB-776 Petition fails to establish existence of important question of fact, law or policy re ALAB-776
CHANDLER, L J Hearing Branch 2 84/08/01 Commissioners
23pp 25897 300 24X Fiche 50-275, 84/08/01, 8408020222

--8408020233 Answer opposing Joint Intervenors 840716 motion to reopen record on seismic issues Motion fails to satisfy stds for reopening record Certificate of Svc encl
CHANDLER, L J Hearing Branch 2 84/08/01 Atomic Safety and Licensing Appeal Panel 11pp 25897 323 24X
Fiche 50-275, 84/08/01, 8408020222

8408030154 Underscores need for prompt & favorable action on Northern California Power Agency 811204 petition under 10CFR2 206 to enforce & modify license conditions, based on recent evidence that util continues to violate license conditions
MCDIARMID, R C Spiegel & McDiarmid 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 592pp 25914 075 24X
Fiche 50-275, 84/08/01, 8408030154

8408020197 Advises that time for Commission to review ALAB-756 expired Commission declined review Decision became final agency action on 840727 Served on 840802
CHILK, S J Office of the Secretary of the Commission DSB 717
84/08/02 REYNOLDS, J R , HAVIAN, C , PHILLIPS, J Center for Law in the Public Interest 1p 25898 001 24X Fiche 50-275, 84/08/02, 8408020197

8408020206 Advises that time for Commission to review ALAB-756 expired Commission declined review Decision became final agency action on 840726 Served on 840802
CHILK, S J Office of the Secretary of the Commission DSB 718
84/08/02 STRUMWASSER, M California, State of 1p 25898 007
24X Fiche 50-275, 84/08/02, 8408020206

8408070265 Order extending time until 840810 for Commission to act to review Director's Decision DD-84-8 Served on 840806
CHILK, S J Office of the Secretary of the Commission DSB 756
84/08/03 Commissioners 1p 25949 239 24X
Fiche 50-275, 84/08/03, 8408070265

8408070361 Order extending time until 840830 for Commission to act to review ALAB-776 Served on 840806
CHILK, S J Office of the Secretary of the Commission DSB 755
84/08/03 Commissioners 1p 25949 177 24X
Fiche 50-275, 84/08/03, 8408070361

8408070467 Order extending time until 840810 for Commission to act to review ALAB-763 Served on 840806
CHILK, S J Office of the Secretary of the Commission DSB 752
84/08/03 Commissioners 1p 25940 341 24X
Fiche 50-275, 84/08/03, 8408070467

8408090183 Order ALAB-775A denying 840628 motion to reopen record on basis of addl info provided by applicant re use of A307 hardware bolts Allegation does not present new evidence Served on 840808
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel DSB 848
84/08/08 Joint Intervenors - Diablo Canyon 2pp 25972 286
24X Fiche 50-275, 84/08/08, 8408090183

8408130389 Reply supporting ASLAB 840801 order establishing jurisdiction of ASLAB to review Joint Intervenor 840716 motion to reopen record on seismic issues Certificate of Svc encl
REYNOLDS, J R Joint Intervenors - Diablo Canyon REYNOLDS, J R
Center for Law in the Public Interest DSB 906 84/08/09 Atomic Safety and Licensing Appeal Panel 8pp 26011 094 24X
Fiche 50-275, 84/08/09, 8408130389

8408140464 Reply re jurisdiction of ASLAB to consider 840716 motion to reopen record on seismic issues Motion should be granted Certificate of Svc encl
REYNOLDS, J R Joint Intervenors - Diablo Canyon REYNOLDS, J R
Center for Law in the Public Interest DSB 917 84/08/09 Atomic Safety and Licensing Appeal Panel 8pp 26061 015 24X
Fiche 50-275, 84/08/09, 8408140464

8408140006 Memorandum & Order CLI-84-13, determining that full power license may be issued by NRR Order effective on 840817 Commissioner Zech statement & Commissioner Asselstine dissenting views encl Served on 840810
CHILK, S J Office of the Secretary of the Commission DSB 940
84/08/10 Office of the Executive Legal Director 25pp
26045 001 24X Fiche 50-275, 84/08/10, 8408140006

8408140009 Decision CLI-84-12, initiating rulemaking re effects of seismic events on emergency planning Addl views of Palladino & Bernthal & dissenting view of Asselstine encl Served on 840810
CHILK, S J Office of the Secretary of the Commission DSB 939
84/08/10 29pp 26044 078 24X Fiche 50-275, 84/08/10, 8408140009

8408140460 Order extending time until 840817 for Commission to act to review ALAB-763 Served on 840814
CHILK, S J Office of the Secretary of the Commission DSB 934
84/08/10 Commissioners 1p 26060 352 24X
Fiche 50-275, 84/08/10, 8408140460

8408140486 Order extending time until 840817 for Commission to act to review Director's Decision DD-84-8 Served on 840814
CHILK, S J Office of the Secretary of the Commission DSB 935
84/08/10 Commissioners 1p 26060 275 24X
Fiche 50-275, 84/08/10, 8408140486

8408160234 Responds to RC McDiarmid petition for enforcement of license conditions to continue moribund enforcement proceeding & interpose Commission in pending contract litigation w/City of Healdsburg, CA NRC involvement unnecessary
FALLIN, J F , SANDERSON, S A Pacific Gas & Electric Co 84/08/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp
26092 154 24X Fiche 50-275, 84/08/10, 8408160234

8408140548 Forwards Commissioner Bernthal 840813 revised addl views to CLI-84-12 Served on 840813
CLEMENTS, W L Docketing & Services Branch DSB 009 84/08/13
Office of the Executive Legal Director 4pp 26060 243 24X
Fiche 50-275, 84/08/13, 8408140548

8408220251 Order denying petitions for review of ALAB-736 subj to reservation re ASLB rationale for excluding joint intervenor & State of CA contentions concerning util QA program Served on 840820
CHILK, S J Office of the Secretary of the Commission DSB 190
84/08/20 3pp 26191 360 24X Fiche 50-275, 84/08/20, 8408220251

8408240424 Staff requirements memo re affirmation/discussion & vote denying 2 206 relief (SECY-84-203), approving order responding to petitions for review of ALAB-763 (SECY-84-254) & approving order denying LILCO 840719 motion (SECY-84-296)
CHILK, S J Office of the Secretary of the Commission 84/08/20
Office of the Secretary of the Commission 3pp 26248 269 24X
Fiche 50-000, 84/08/20, 8408240424

8408230202 Forwards summary of 840726 site visit No new info impacting licensing decision identified Served on 840822
ZECH, L W Commissioners DSB 255 84/08/22 PALLADINO, ROBERTS, ASSELSTINE Commissioners 5pp 26209 209 24X
Fiche 50-275, 84/08/22, 8408230202

8408280217 Order extending time until 840913 for Commission to act to review ALAB-776 Served on 840827
CHILK, S J Office of the Secretary of the Commission DSB 317
84/08/27 Commissioners 1p 26275 143 24X
Fiche 50-275, 84/08/27, 8408280217

8408310247 Notice of withdrawal of appearance in proceeding Related correspondence
AXELRAD, M Newman & Holtzinger DSB 428 84/08/28 Office of the Secretary of the Commission 1p 26319 256 24X
Fiche 50-275, 84/08/28, 8408310247

8408310210 Expresses opposition to util 840820 amend application extending term of license & requests hearing, per Atomic Energy Act, to be held prior to Commission decision on application
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
Joint Intervenors - Diablo Canyon DSB 419 84/08/29
PALLADINO, N , ASSELSTINE, J , BERNTHAL, F Commissioners 5pp
26318 047 24X Fiche 50-275, 84/08/29, 8408310210

M Antitrust correspondence

8408130310 Ack receipt of 840801 ltr to HR Denton re request for enforcement of certain antitrust license conditions Allegations contained in ltr under review
VOGLER, B H Hearing Branch 2 DSB 898 84/08/08 MCDIARMID, R C
Spiegel & McDiarmid 1p 26010 250 24X Fiche 50-275, 84/08/08, 8408130310

8408280442 Confirms telcon re petition for enforcement of antitrust license conditions Staff awaits RC McDiarmid comments on util 840810 ltr re petition Staff requests wheel provisions of arbitrated settlement agreement re NCPA Geyser units
VOGLER,B H Hearing Branch B DSB 343 84/08/22 MCDIARMID,R C Spiegel & McDiarmid 1p 26280 294 24X Fiche 50-275,84/08/22, 8408280442

O Advisory Committee on Reactor Safeguards reports & correspondence

8408020242 Forwards comments on ACRS 840523 tour of plant site, in response to 840515 ltr
MYSINGER,E D Tennessee Valley Authority 84/08/01 MCKINLEY,J C ACRS - Advisory Committee on Reactor Safeguards 4pp 25898 157 24X Fiche 50-275,84/08/01,8408020242

P Operating license stage documents & correspondence

8408140341 Clarifies info previously submitted in 840601 & 26 ltrs re field change request procedure to facilitate field resolution of const problems re pipe supports Procedure revised to allow work to proceed for up to 7 calendar days
SCHUYLER,J D Pacific Gas & Electric Co 84/08/02 MARTIN,J B Region 5, Office of Director 1p 26042 324 24X Fiche 50-323,84/08/02,8408140341

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408080491 Forwards IE Insp Repts 50-275/84-13 & 50-323/84-05 on 840430-0504 & notice of violation
BISHOP,T W Region 5, Office of Director 84/07/27 SCHUYLER,J D Pacific Gas & Electric Co 2pp 25974 244 24X Fiche 50-275,84/07/27,8408080491

--8408080501 Notice of violation from insp on 840430-0504
YOUNG,T Region 5, Office of Director 84/07/27 3pp 25974 246 24X Fiche 50-275,84/07/27,8408080491

--8408080513 IE Insp Repts 50-275/84-13 & 50-323/84-05 on 840430-0504 Violation noted Failure to follow approved QC procedures for safety-related pipe & electrical raceway supports
DURDOIN,J F , YOUNG,T Region 5, Office of Director 84/07/11 6pp 25974 249 24X Fiche 50-275,84/07/27,8408080491

8407310035 Board Notification 84-138 forwards Investigation/Insp Rept 50-275/84-08 Subj matter of rept addressed in SSERs 25 & 26
EISENHUT,D G Division of Licensing 84/07/30 PALLADINO, ROBERTS, ASSELSTINE Commissioners 2pp 25885 106 24X Fiche 50-275,84/07/30,8407310035

8408070324 Ack receipt of 840618 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/83-37 & 50-323/83-25
BISHOP,T W Region 5, Office of Director 84/08/01 SCHUYLER,J D Pacific Gas & Electric Co 1p 25945 130 24X Fiche 50-275,84/08/01,8408070324

--8408070327 Responds to NRC 840229 ltr re violations noted in IE Insp Repts 50-275/83-37 & 50-323/83-25 Corrective actions reinsp program implemented for welds originally accepted by unqualified inspectors
SCHUYLER,J D Pacific Gas & Electric Co 84/06/18 MARTIN,J B Region 5, Office of Director 8pp 25945 131 24X Fiche 50-275,84/08/01,8408070324

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408220067 Informs of review of 51 LERs for Jan 1983 - June 1984 in support of ongoing SALP review Review concentrated on completeness,accuracy & consistency of info No major deficiencies identified Summary of criteria & findings encl
SEYFRIT,R V Reactor Operations Analysis Branch 84/08/09 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 3pp 26153 210 24X Fiche 50-275,84/08/09,8408220067

8408300140 Forwards Insp Repts 50-275/84-25 & 50-323/84-17 on 840709-13 No violations noted
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 84/08/09 SCHUYLER,J D Pacific Gas & Electric Co 1p 26307 324 24X Fiche 50-275,84/08/09,8408300140

--8408300149 Insp Repts 50-275/84-25 & 50-323/84-17 on 840709-13 No violations or deviations noted Major areas inspected allegations re NRC assessment of Pullman Power audit program during Aug 1971 - Dec 1973
WAGNER,W J , HIRSCH D F Region 5 Office of Director 84/08/09 8pp 26307 325 24X Fiche 50-275,84/08/09,8408300140

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408200313 Ack receipt of 840730 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-275/84-10
BISHOP,T W Region 5, Office of Director 84/08/13 SCHUYLER,J D Pacific Gas & Electric Co 1p 26133 012 24X Fiche 50-275,84/08/13,8408200313

--8408200318 Responds to NRC 840628 ltr re violations noted in IE Insp Rept 50-275/84-10 Corrective actions Procedure C-4S1, "Mechanical Bypass,Jumper & Lifted Circuit Log," revised to include jumpers in clearance package
SCHUYLER,J D Pacific Gas & Electric Co 84/07/30 MARTIN,J B Region 5, Office of Director 4pp 26133 013 24X Fiche 50-275,84/08/13,8408200313

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26194 091 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408080491 Forwards IE Insp Repts 50-275/84-13 & 50-323/84-05 on 840430-0504 & notice of violation
BISHOP,T W Region 5, Office of Director 84/07/27 SCHUYLER,J D Pacific Gas & Electric Co 2pp 25974 244 24X Fiche 50-275,84/07/27,8408080491

--8408080515 "Technical Assistance for Insp of Diablo Canyon IDVP," progress rept for Feb 1984
WADE,W O , CUMMINGS,G E Lawrence Livermore National Laboratory FIN D-8552 84/03/14 MORRILL,P J Region 5, Office of Director 6pp 25974 255 24X Fiche 50-275,84/07/27,8408080491

--8408080517 Technical Assistance for Insp of Diablo Canyon IDVP " progress rept for Mar 1984
WADF,W O CUMMINGS,G E Lawrence Livermore National Laboratory
FIN B-8552 84/04/11 MORRILL,R J Region 5, Office of Director
8pp 25774 261 24X Fiche 50-275,84/07/27,8408080491

--8408080521 "Technical Assistance for Insp of Diablo Canyon IDVP," progress rept for Apr 1984
WADF,W O , CUMMINGS,G E Lawrence Livermore National Laboratory
FIN B-8552 84/05/14 MORRILL,R J Region 5, Office of Director
4pp 25974 269 24X Fiche 50-275,84/07/27,8408080491

T Hearing transcripts on non-antitrust matters

8408220338 Transcript of 840802 open meeting in Washington,DC re discussion/possible vote on full power OL Pp 1-195
Supporting documentation encl
* Commissioners 84/08/02 222pp 26211 083 24X
Fiche 50-275,84/08/02,8408220338

8408200407 Transcript of 840807 Commission meeting in Washington,DC re discussion/possible vote on order concerning earthquakes & emergency planning Pp 1-8
* Commissioners 84/08/03 12pp 26141 170 24X
Fiche 50-275,84/08/03,8408200407

8408280020 Transcript of 810816 Commission meeting in Washington,DC re affirmation/discussion & vote Pp 1-7
* Commissioners 84/08/16 10pp 26294 013 24X
Fiche 50-000,84/08/16,8408280020

V Congressional/Executive Correspondence

8408010275 Responds to 840206 ltr re concerns over perceived tendency by staff to assume that margins of safety established by criteria need not be adhered to for sys not pivotal to safety
DIRCKS,W J Office of the Executive Director for Operations
84/07/20 PANETTA,L House of Rep 9pp 25872 342 24X
Fiche 50-275,84/07/20,8408010275

--8408010277 Requests preparation of response to Panetta 840208 ltr on concerns re QA hearing
PALLADINO,N J Commissioners 84/06/19 DIRCKS,W J Office of the Executive Director for Operations 1p 25872 351 24X
Fiche 50-275,84/07/20,8408010275

V Operator Examinations

8408070045 Confirms scheduling of operator written & oral exams for 840918-28 Transmittal of ref matls listed in Encl 1 by 840810 requested list of logistical requirements also encl
PATE,R J Region 5, Office of Director 84/08/02 SCHUYLER,J D
Pacific Gas & Electric Co 4pp 25950 038 24X
Fiche 50-323,84/08/02,8408070045

8408070479 Discusses telcon between J Tinlin & J Elin re arrangements for administration of written & oral exams for senior reactor operators on 840918-28 License applications should be submitted at least 60 days prior to exam
PATE,R J Region 5, Office of Director 84/08/02 SCHUYLER,J D
Pacific Gas & Electric Co 4pp 25941 206 24X
Fiche 50-275,84/08/02,8408070479

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408310411 Forwards summary of 840530 meeting re proposed 10CFR50 54(p) changes to industrial security plans & contractor screening program Meeting beneficial & provided better understanding between security staffs
LEWIS,R C Region 2, Office of Director 84/06/19 UTLEY,E E
Carolina Power & Light Co 3pp 26333 318 24X
Fiche 50-000,84/06/19,8408310411

8408300315 Forwards correspondence from FEMA forwarding evaluation of offsite emergency preparedness for 830517 exercise
LEWIS,R C Region 2, Office of Director 84/07/19 UTLEY,E E
Carolina Power & Light Co 2pp 26313 213 24X
Fiche 50-324,84/07/19,8408300315

--8408300319 Forwards "Brunswick Nuclear Power Plant Exercise on 830517," final rept
PRIMM,R W Federal Emergency Management Agency 84/06/19
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 8pp 26313 215 24X
Fiche 50-324,84/07/19,8408300315

--8408300322 "Brunswick Nuclear Power Plant Exercise on 830517," final rept
* Federal Emergency Management Agency 84/06/03 40pp
26313 223 24X Fiche 50-324 84/07/19 8408300315

8408030034 Revised emergency plan implementing procedures, including Rev 7 to REP-02 2 re unusual event, Rev 7 to PEP-02 3 re alert, Rev 7 to PEP-02 4 re site emergency & Rev 11 to PEP-02 5 re general emergency
* Carolina Power & Light Co 84/07/24 38pp 25906 228 24X
Fiche 50-324,84/07/24,8408030034

8408030040 Rev 15 to radiological emergency response plan
* Carolina Power & Light Co 84/07/24 27pp 25907 034 24X
Fiche 50-324,84/07/24,8408030040

8408160046 Forwards request for addl info re procedures generation package (PGP) Review of PGP conducted per Generic Ltr 82-33 (Suppl 1 to NUREG-0737)
VASSALLO,D B Operating Reactors Branch 2 84/07/27 UTLEY,E E
Carolina Power & Light Co 9pp 26128 162 24X
Fiche 50-324,84/07/27,8408160046

8408230249 Forwards IE Safeguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No violations or deviations identified
VERRELLI,D M Region 2, Office of Director 84/08/20 UTLEY,E E
Carolina Power & Light Co 2pp 26207 290 24X
Fiche 50-324,84/08/20,8408230249

--8408230255 IE Safeguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No noncompliance noted Major areas inspected implementation of approved security plan changes Details withheld (ref 10CFR2 790 & 73 21)
TILLMAN,A , MCGUIRE,D R Region 2, Office of Director 84/08/15
1p 26207 292 24X Fiche 50-324,84/08/20,8408230249

8408240316 Forwards SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
LEWIS,R C Region 2, Office of Director 84/08/21 UTLEY,E E
Carolina Power & Light Co 2pp 26225 230 24X
Fiche 50-000,84/08/21,8408240316

--8408240319 SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
* Region 2, Office of Director 84/04/30 71pp 26225 232 24X
Fiche 50-000,84/08/21,8408240316

8408280235 Vol 13 of Rev 3 to Plant Emergency Procedure PEP-03 3 1, "In-Plant Monitoring & Surveys " W/840824 ltr
HOWE,P W Carolina Power & Light Co 84/08/24 O'REILLY,J P
Region 2, Office of Director 5pp 26262 281 24X
Fiche 50-324,84/08/24,8408280235

K Utility Final Safety Analysis Report (FSAR) & amends

8407260111 Forwards Amend 2 to updated FSAR for Brunswick,Units 1 & 2
UTLEY,E E Carolina Power & Light Co 84/07/20 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 25826 005 24X
Fiche 50-324,84/07/20,8407260111

--8407260112 Amend 2 to updated FSAR for Brunswick,Units 1 & 2
* Carolina Power & Light Co 84/07/20 912pp 25826 006 24X
Fiche 50-324,84/07/20,8407260111

P Operating license stage documents & correspondence

8408070016 Forwards Page 3/4 3-29 to Amend 97 to License DPR-62, correcting error made in Amend 95 on 840328
VASSALLO,D B Operating Reactors Branch 2 84/07/26 UTLEY,E E
Carolina Power & Light Co 3pp 25956 201 24X
Fiche 50-324,84/07/26,8408070016

--8408070018 Errata to Amend 97 to License DPR-62, correcting error made in Amend 95 on 840328 re trip function & instrument number
* NRC - No Detailed Affiliation Given 84/07/26 1p 25956 203
24X Fiche 50-324,84/07/26,8408070016

8408150310 Forwards SER re TMI Items II F 1 1, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor " Design acceptable
VASSALLO,D B Operating Reactors Branch 2 84/07/30 UTLEY,E E
Carolina Power & Light Co 12pp 26099 341 24X
Fiche 50-324,84/07/30,8408150310

8408070218 Notification of 840421 meeting w/util in Bethesda,MD to discuss integrated schedule methodology & preliminary schedule
GROTENHUIS,M Operating Reactors Branch 2 84/07/31 VASSALLO,D B
Operating Reactors Branch 2 2pp 25957 053 24X
Fiche 50-324,84/07/31,8408070218

8408080276 Forwards addl info re reload analysis,per 840717 telcon request concerning 840315 submittal Addl FIBWR compressed model cases run to allow code to calculate core pressure drop
ZIMMERMAN,S R Carolina Power & Light Co 84/07/31 VASSALLO,D B
Operating Reactors Branch 2 8pp 25965 261 24X
Fiche 50-324,84/07/31,8408080276

8408080252 Responds to 840513 request for info re analyses used in determining if setpoint logic changes needed to reduce water clearing thrust loads associated w/second safety relief valve actuations Analyses conducted per NUREG-0661
CUTTER,A B Carolina Power & Light Co 84/08/01 VASSALLO,D B
Operating Reactors Branch 2 2pp 25966 300 24X
Fiche 50-324,84/08/01,8408080252

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408230221 Informs that original startup date of 840925 revised to 840916 NRC action on five applications to amend License DPR-62 required prior to startup
ZIMMERMAN,S R Carolina Power & Light Co 84/08/16 VASSALLO,D B
Operating Reactors Branch 2 2pp 26209 228 24X
Fiche 50-324,84/08/16,8408230221

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25869 047 24X Fiche 50-000,84/07/27,8407250229

8408270426 Ack receipt of 840711 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-324/84-14 & 50-325/84-14
VERRELLI,D M Division of Project & Resident Programs 84/07/31
UTLEY,E E Carolina Power & Light Co 1p 26257 001 24X
Fiche 50-324,84/07/31,8408270426

--8408270431 Responds to NRC 840613 ltr re violations noted in Insp Repts 50-324/84-14 & 50-325/84-14 Corrective actions procedures will be revised to allow tolerance for dead time of Ge(Li) detector geometry calibr not to exceed 5%
DIETZ,C R Carolina Power & Light Co 84/07/11 O'REILLY,J P
Region 2, Office of Director 4pp 26257 002 24X
Fiche 50-324,84/07/31,8408270426

--8408270435 Forwards Insp Repts 50-324/84-14 & 50-325/84-14 on 840521-25 & notice of violation
VERRELLI,D M Division of Project & Resident Programs 84/06/13
UTLEY,E E Carolina Power & Light Co 2pp 26257 006 24X
Fiche 50-324,84/07/31,8408270426

--8408270437 Notice of violation from insp on 840521-25
* Region 2, Office of Director 84/06/13 1p 26257 008 24X
Fiche 50-324,84/07/31,8408270426

--8408270439 Insp Repts 50-324/84-14 & 50-325/84-14 on 840521-25 Violation noted failure to follow procedures for calibr of Ge(Li) detector sys
KUZO,G B , MONTGOMERY,D M Region 2, Office of Director
84/06/11 10pp 26257 009 24X Fiche 50-324,84/07/31,8408270426

8408280166 Supplx response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller,Inc " No subj products in use at facilities
CUTTER,A B Carolina Power & Light Co 84/07/31 O'REILLY,J P
Region 2, Office of Director 2pp 26260 141 24X
Fiche 50-324,84/07/31,8408280166

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " 1 list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26069 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61 "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830107) 84/08/08 Consolidated Edison Co of New York, Inc 12pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62 "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
12Spp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408160129 Forwards Rev 1 to "Analysis of Unrepaired Flow Indications at Brunswick Steam Electric Plant,Unit 2 " Welds acceptable per criteria in Generic Ltr 84-11 Performance capability of Level 1,2 or 3 demonstrated per IE Bulletin 83-02
CUTTER,A B Carolina Power & Light Co 84/08/10 VASSALLO,D B
Operating Reactors Branch 2 2pp 26092 103 24X
Fiche 50-324,84/08/10,8408160129

--8408160132 Rev 1 to "Analysis of Unrepaired Flow Indications at Brunswick Steam Electric Plant,Unit 2 "
KLEINSMITH,M E , SUND,H O NUTECH Engineers, Inc CPL-19-103 R01
84/07/31 25pp 26092 105 24X Fiche 50-324,84/08/10,
8408160129

8408100009 IE Info Notice 84-63 "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 11pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84 64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 10Spp 26198 099 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 11Spp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12Spp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408230249 Forwards IE Safeguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No violations or deviations identified
VERRELLI,D M Region 2, Office of Director 84/08/20 UTLEY,E E
Carolina Power & Light Co 2pp 26207 290 24X
Fiche 50-324,84/08/20,8408230249

--8408230255 IE Safeguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No noncompliance noted Major areas inspected implementation of approved security plan changes Details withheld (ref 10CFR2 790 & 73 21)
TILLMAN,A , MCGUIRE,D R Region 2, Office of Director 84/08/15
1p 26207 292 24X Fiche 50-324,84/08/20,8408230249

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 11Spp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408240316 Forwards SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
LEWIS, R C Region 2, Office of Director 84/08/21 UTLEY, E E
Carolina Power & Light Co 2pp 26225 230 24X
Fiche 50-000, 84/08/21, 8408240316

--8408240319 SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
* Region 2, Office of Director 84/04/30 71pp 26225 232 24X
Fiche 50-000, 84/08/21, 8408240316

S Reportable occurrences LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C
Director s Office Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408100039 Forwards LER 84-019 01T-2
DIETZ, C R Carolina Power & Light Co 84/07/12 O'REILLY, J P
Region 2, Office of Director 1p 24X Fiche 50-324, 84/07/12, 8408100039

8408090390 LER 84-075/03L-1 on 840813, drywell floor drain flow integrator 2-G16-K0-K601 indicated sump flow w/no pumps running Caused by failed solder joint on output connector of integrator square root converter W/840717 ltr
PASIVA, M J , DIETZ, C R Carolina Power & Light Co 84/07/17
O'REILLY, J P Region 2, Office of Director 2pp 25993 284 24X
Fiche 50 324, 84 07 17 8408090390

8408130338 Special Rept 2-SR-84 10 on 840629, fire barrier limiting condition for operation initiated for Fire Door 303 Door would not properly open due to problems w/hinges & interlock device Door repaired
DIETZ, C R Carolina Power & Light Co 84/08/03 O'REILLY, J P
Region 2, Office of Director 1p 26010 215 24X
Fiche 50 324, 84/08/03, 8408130338

8408240227 LER 84-002-00 on 840727, reactor protection sys actuated due to electronic noise spike Caused by section of fallen grating resulting from snagged technician respirator air line Grating replaced W/840820 ltr
PASIVA, M J , DIETZ C R Carolina Power & Light Co 84/08/20 2pp
26236 314 24X Fiche 50-324, 84/08/20, 8408240227

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's
Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000, 84/08/21, 8408310186

V Operator Examinations

8408310014 Confirms 840605 telcon re 840612 mgt meeting in Region II ofcs to discuss upcoming operator exams * requalification of licensed operators following steam generator outage
O'REILLY, J P Region 2, Office of Director 84/06/08 UTLEY, E E
Carolina Power & Light Co 1p 26333 357 24X
Fiche 50-000, 84/06/08, 8408310014

DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8408310411 Forwards summary of 840530 meeting re proposed 10CFR50 54(p) changes to industrial security plans & contractor screening program Meeting beneficial & provided better understanding between security staffs
LEWIS, R C Region 2, Office of Director 84/06/19 UTLEY, E E
Carolina Power & Light Co 3pp 26333 318 24X
Fiche 50-000, 84/06/19, 8408310411

8408300315 Forwards correspondence from FEMA forwarding evaluation of offsite emergency preparedness for 830517 exercise
LEWIS, R C Region 2, Office of Director 84/07/19 UTLEY, E E
Carolina Power & Light Co 2pp 26313 213 24X
Fiche 50-324, 84/07/19, 8408300315

--8408300319 Forwards "Brunswick Nuclear Power Plant Exercise on 830517," final rept
KRIMM, R W Federal Emergency Management Agency 84/06/19
JORDAN, C L Division of Emergency Preparedness & Engineering
Response (Past 830103) 8pp 26313 215 24X
Fiche 50-324, 84/07/19, 8408300315

--8408300323 Brunswick Nuclear Power Plant Exercise on 830517," final rept
* Federal Emergency Management Agency 84/06/03 40pp
26313 223 24X Fiche 50-324, 84/07/19, 8408300315

8408030034 Revised emergency plan implementing procedures, including Rev 7 to REP-02 2 re unusual event, Rev 7 to PEP-02 3 re alert, Rev 7 to PEP-02 4 re site emergency & Rev 11 to PEP-02 5 re general emergency
* Carolina Power & Light Co 84/07/24 38pp 25906 228 24X
Fiche 50-324, 84/07/24, 8408030034

8408030040 Rev 15 to radiological emergency response plan
* Carolina Power & Light Co 84/07/24 27pp 25907 034 24X
Fiche 50-324, 84/07/24, 8408030040

8408160046 Forwards request for addl info re procedures generation package (PGP) Review of PGP conducted per Generic Ltr 82-33 (Suppl 1 to NUREG-0737)
VASSALLO, D B Operating Reactors Branch 2 84/07/27 UTLEY, E E
Carolina Power & Light Co 9pp 26128 162 24X
Fiche 50-324, 84/07/27, 8408160046

8408230249 Forwards IE Safeguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No violations or deviations identified
VERRELLI, D M Region 2, Office of Director 84/08/20 UTLEY, E E
Carolina Power & Light Co 2pp 26207 290 24X
Fiche 50-324, 84/08/20, 8408230249

--8408230255 IE Safeguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No noncompliance noted Major areas inspected implementation of approved security plan changes Details withheld (ref 10CFR2 790 & 73 21)
TILLMAN, A Region 2, Office of Director 84/08/15 1p
26207 292 24X Fiche 50-324, 84/08/20, 8408230249

8408240316 Forwards SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
LEWIS, R C Region 2, Office of Director 84/08/21 UTLEY, E E
Carolina Power & Light Co 2pp 26225 230 24X
Fiche 50-000, 84/08/21, 8408240316

--8408240319 SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
* Region 2, Office of Director 84/04/30 71pp 26225 232 24X
Fiche 50-000, 84/08/21, 8408240316

8408280235 Vol 13 of Rev 3 to Plant Emergency Procedure PEP-03 3 1, "In-Plant Monitoring & Surveys " W/840824 ltr
HOWE, P W Carolina Power & Light Co 84/08/24 O'REILLY, J P
Region 2, Office of Director 5pp 26262 281 24X
Fiche 50-324, 84/08/24, 8408280235

K Utility Final Safety Analysis Report (FSAR) & amends

8407260111 Forwards Amend 2 to updated FSAR for Brunswick, Units 1 & 2
UTLEY, E E Carolina Power & Light Co 84/07/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25826 005 24X
Fiche 50-324, 84/07/20, 8407260111

--8407260112 Amend 2 to updated FSAR for Brunswick, Units 1 & 2
* Carolina Power & Light Co 84/07/20 912pp 25826 006 24X
Fiche 50-324, 84/07/20, 8407260111

P Operating license stage documents & correspondence

8408150310 Forwards SER re TMI Items II F 1 1, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor " Design acceptable
VASSALLO, D B Operating Reactors Branch 2 84/07/30 UTLEY, E E
Carolina Power & Light Co 12pp 26097 341 24X
Fiche 50-324, 84/07/30, 8408150310

8408070218 Notification of 840821 meeting w/util in Bethesda, MD to discuss integrated schedule methodology & preliminary schedule
GROTENHUIS, M Operating Reactors Branch 2 84/07/31 VASSALLO, D B
Operating Reactors Branch 2 2pp 25957 033 24X
Fiche 50-324, 84/07/31, 8408070218

8408080276 Forwards addl info re reload analysis, per 840717 telcon request concerning 840315 submittal Addl FIBWR compressed model cases run to allow code to calculate core pressure drop
ZIMMERMAN, S R Carolina Power & Light Co 84/07/31 VASSALLO, D B
Operating Reactors Branch 2 8pp 25965 261 24X
Fiche 50-324, 84/07/31, 8408080276

8408080252 Responds to 840613 request for info re analyses used in determining if setpoint logic changes needed to reduce water clearing thrust loads associated w second safety relief valve actuations analyses conducted per NUREG-0661
CUTTER, A B Carolina Power & Light Co 84/08/01 VASSALLO, D B
Operating Reactors Branch 2 2pp 25966 300 21X
Fiche 50-324, 84/08/01, 8408080252

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues." Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 10pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408210009 Forwards Amend 72 to License DPR-71 & safety evaluation Amend defers full-stroke cycling of four reactor instrumentation sys isolation valves
GROTENHUIS, M Operating Reactors Branch 2 84/08/10 UTLEY, E E
Carolina Power & Light Co 2pp 26195 184 24X
Fiche 50-325, 84/08/10, 8408210009

--8408210012 Amend 72 to License DPR-71 deferring full-stroke cycling of four reactor instrumentation sys isolation valves
VASSALLO, D B Operating Reactors Branch 2 84/08/10 4pp
26195 186 24X Fiche 50-325, 84/08/10, 8408210009

--8408210013 Safety evaluation supporting Amend 72 to License DPR-71
* Office of Nuclear Reactor Regulation, Director 84/08/10 4pp
26195 190 24X Fiche 50-325, 84/08/10, 8408210009

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408270426 Ack receipt of 840711 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-324/84-14 & 50-325/84-14
VERRELLI, D M Division of Project & Resident Programs 84/07/31
UTLEY, E E Carolina Power & Light Co 1p 26257 001 24X
Fiche 50-324, 84/07/31, 8408270426

--8408270431 Responds to NRC 840613 ltr re violations noted in Insp Repts 50-324/84-14 & 50-325/84-14 Corrective actions procedures will be revised to allow tolerance for dead time of Ge(Li) detector geometry calibr not to exceed 5%
DIETZ, C R Carolina Power & Light Co 84/07/11 O'REILLY, J P
Region 2, Office of Director 4pp 26257 002 24X
Fiche 50-324, 84/07/31, 8408270426

--8408270435 Forwards Insp Repts 50-324/84-14 & 50-325/84-14 on 840521-25 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 84/06/13
UTLEY, E E Carolina Power & Light Co 2pp 26257 006 24X
Fiche 50-324, 84/07/31, 8408270426

--8408270437 Notice of violation from Insp on 840521-25
* Region 2, Office of Director 84/06/13 1p 26257 008 24X
Fiche 50-324, 84/07/31, 8408270426

--8408270439 Insp Repts 50-324/84-14 & 50-325/84-14 on 840521-25 Violation noted Failure to follow procedures for calibr of Ge(Li) detector sys
KUZO, C B , MONTGOMERY, D M Region 2, Office of Director
84/06/11 10pp 26257 009 24X Fiche 50-324, 84/07/31, 8408270426

8408280166 Supplis response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc." No subj products in use at facilities
CUTTER, A B Carolina Power & Light Co 84/07/31 O'REILLY, J P
Region 2, Office of Director 2pp 26260 141 24X
Fiche 50-324, 84/07/31, 8408280166

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-61, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 12pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments." Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
12pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-62, "Defective RHR Replacement Piping." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408230249 Forwards IE Safeguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No violations or deviations identified
VERRELLI, D M Region 2, Office of Director 84/08/20 UTLEY, E E
Carolina Power & Light Co 2pp 26207 290 24X
Fiche 50-324, 84/08/20, 8408230249

--8408230255 IE Safeguards Insp Repts 50-324/84-21 & 50-325/84-21 on 840730-0803 No noncompliance noted Major areas inspected Implementation of approved security plan changes Details withheld (ref 10CFR2.790 & 73.21)
TILLMAN, A , MCGUIRE, D R Region 2, Office of Director 84/08/15
1p 26207 292 24X Fiche 50-324, 84/08/20, 8408230249

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408240316 Forwards SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
LEWIS, R C Region 2, Office of Director 84/08/21 UTLEY, E E
Carolina Power & Light Co 2pp 26225 230 24X
Fiche 50-000, 84/08/21, 8408240316

--8408240319 SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
* Region 2, Office of Director 84/04/30 71pp 26225 232 24X
Fiche 50-000, 84/08/21, 8408240316

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8406070060 NPDES noncompliance notification on 840517-21, one cooling water pump bay has 0 screens Caused by removal of bar trash rack for cleaning Spare rack installed & screens returned to svc
STARKLY R B Carolina Power & Light Co 84/06/04 WAKILD,C North Carolina, State of 1p 21 43 008 24X Fiche 50-325, 84/06/04, 8406070060

8408090432 LER 83-023/03L-1 on 830426, loss of offsite power occurred when 230-kV bus 1B inadvertently tripped Caused by personnel error Trip signal cleared & offsite power restored Transformer E-6 replaced W/840718 ltr
PASTVA, M J , DIETZ C R Carolina Power & Light Co 84/07/18
O'REILLY, J P Region 2, Office of Director 5pp 25993 239 24X Fiche 50 325, 84/07/18, 8408090432

8408060088 NPDES noncompliance notification on 840619 & 20, Flow minimization suspended Flow of 1010 cubic ft per second recorded both days Weather change allowed return to min 200 MW sys reserve
STARKEY, R B Carolina Power & Light Co 84/07/26 WAKILD,C North Carolina, State of 1p 25935 308 24X Fiche 50-325, 84/07/26, 8408060088

8408010295 NPDES noncompliance notification on 840704-11, unit operated w/less than two fine mesh screens on cooling water pump ID bay Caused by scheduled maint & miscommunication Action taken to prevent recurrence
STARKEY, R B Carolina Power & Light Co 84/07/27 WAKILD,C North Carolina, State of 1p 25866 190 24X Fiche 50-325, 84/07/27, 8408010295

8408090032 LER 84-007-00 on 840601, 08 & 13, during power operation, min flow valves of core spray sys pumps closed & declared inoperable Caused by design defect Mods will be implemented
PASTVA, M J , DIETZ, C R Consumers Power Co 84/07/27 5pp 25992 097 24X Fiche 50-325, 84/07/27, 8408090032

8408160075 LER 83-021/03L-1 on 831116, while withdrawing control rods during reactor startup, full-in light lit while rod 50-35 withdrawn Addl position indication problems noted Caused by defective PIP connectors & reed switches W/840727 ltr
PASTVA, M J , DIETZ, C R Carolina Power & Light Co 84/07/28
O'REILLY, J P Region 2, Office of Director 2pp 26108 232 24X Fiche 50-325, 84/07/28, 8408160075

8408060128 LER 84-011-00 on 840711, control bldg emergency air filtration sys Train A automatically started due to spurious fire alarm in back panel area No failures or personnel involvement identified W/840731 ltr
PASTVA, M J , DIETZ, C R Carolina Power & Light Co 84/07/31 2pp 25933 191 24X Fiche 50-325, 84/07/31, 8408060128

8408160133 LER 81-046-01T on 810414, snubber shaft of hydraulic snubber 1-E11-47SS326 broke Caused by water hammer of RHR sys condensing piping due to steam pocket Snubber repaired, tested & returned to svc W/840803 ltr
PASTVA, M J , DIETZ, C R Carolina Power & Light Co 84/08/03
O'REILLY, J P Region 2, Office of Director 3pp 26108 112 24X Fiche 50-325, 84/08/03, 8408160133

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000, 84/08/21, 8408310186

8408300312 NPDES noncompliance rept on 840801-02, unit operated w/less than two fine mesh screens Caused by clogging of circulating water pump by marine growth & back pressure-induced trip due to impinged jellyfish Bar rack replaced & screens cleaned
STARKEY, R B Carolina Power & Light Co 84/08/22 WAKILD,C North Carolina, State of 1p 26314 331 24X Fiche 50-325, 84/08/22, 8408300312

V Operator Examinations

8408310014 Confirms 840605 telcon re 840612 mgt meeting in Region II ofcs to discuss upcoming operator exams & requalification of licensed operators following steam generator outage
O'REILLY, J P Region 2, Office of Director 84/06/08 UTLEY, E E Carolina Power & Light Co 1p 26333 357 24X
Fiche 50-000, 84/06/08, 8408310014

DOCKET 50-326 UNIV OF CALIFORNIA AT IRVINE RES REACTOR

F Security, medical emergency & fire protection plans

8408270091 Ack receipt of 840629 ltr re proposed research reactor emergency plan Sixty-day extension of deadline for response to questions raised by NRC requested
MILLER, G E California, Univ of, Irvine, CA 84/08/20
THOMAS, C O Standardization & Special Projects Branch 1p 26247 357 24X Fiche 50-326, 84/08/20, 8408270091

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8408300316 Ack receipt of 840503 ltr re emergency exercise scheduled for Jul 1984 Review of info submitted re scope & objectives of planned exercise indicates no questions Scenario & controller messages will be reviewed & evaluated
VERRELLI, D M Region 2, Office of Director 84/05/31 PARRIS, H G Tennessee Valley Authority 1p 26308 327 24X
Fiche 50-327, 84/05/31, 8408300316

8408300402 Forwards summary of 840530 meeting w/TVA, Alabama Power Co, Florida Power Corp, Florida Power & Light & Georgia Power Co re selected emergency preparedness issues
O'REILLY, J P Region 2, Office of Director 84/06/08 PARRIS, H G Tennessee Valley Authority 4pp 26308 116 24X
Fiche 50-000, 84/06/08, 8408300402

8408300193 Forwards 840612 ltr detailing overall planning for 840620 French security team visit to facility Biographical info for each team member included
LEWIS, R C Region 2, Office of Director 84/06/15 TUCKER, H B Duke Power Co 1p 26300 139 24X Fiche 50-000, 84/06/15, 8408300193

--8408300204 Requests authorization for six French security experts hosted by NRC to visit McGuire facility on 840620 & Sequoyah facility on 840622 Biographical info & itinerary encl
LAFLEUR, J D Office of International Programs, Director
84/06/12 TUCKER, H B Duke Power Co PARRIS, H G Tennessee Valley Authority 5pp 26300 140 24X Fiche 50-000, 84/06/15, 8408300193

8408300459 Ack receipt of 840620 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/83-13 & 50-328/83-13
VERRELLI, D M Division of Project & Resident Programs 84/07/13
PARRIS, H G Tennessee Valley Authority 1p 26314 095 24X
Fiche 50-327, 84/07/13, 8408300459

--8408300469 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Installation of new communications sys delayed until 840901 due to revised matl delivery date
KAMMER, D S Tennessee Valley Authority 84/06/20 O'REILLY, J P Region 2, Office of Director 1p 26314 096 24X
Fiche 50-327, 84/07/13, 8408300459

--8408300477 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Corrective actions revised emergency monitoring implementing procedures will be completed by 840601
MILLS, L M Tennessee Valley Authority 84/05/01 O'REILLY, J P Region 2, Office of Director 1p 26314 097 24X
Fiche 50-327, 84/07/13, 8408300459

8408300363 Forwards summary of 840711 meeting w/util in Region II ofc re proposed compensatory measures associated w/security power block concept Attendance list also encl
LEWIS, R C Region 2, Office of Director 84/07/17 PARRIS, H G Tennessee Valley Authority 4pp 26308 194 24X
Fiche 50-327, 84/07/17, 8408300363

8408060254 Revs to radiological emergency plan implementing procedures, including Rev 2 to SQN IP-7, "Activation of Operations Support Ctr" & "Rev 3 to SQN IP-15, "Emergency Exposure Guidelines " W/840730 ltr
MILLS, L M Tennessee Valley Authority 84/07/30 O'REILLY, J P Region 2, Office of Director 30pp 25934 078 24X
Fiche 50-327, 84/07/30, 8408060254

8408300519 Confirms 840726 telcon re 840803 mgt meeting to discuss development & implementation of 10CFR50, App R program at Watts Bar & status of Sequoyah program
O'REILLY, J P Region 2, Office of Director 84/07/30 PARRIS, H G Tennessee Valley Authority 2pp 26313 300 24X
Fiche 50-000, 84/07/30, 8408300519

8408100024 Rev 12 to radiological emergency plan W/840806 ltr
MILLS,L M Tennessee Valley Authority 84/08/06 O'REILLY,J P
Region 2, Office of Director 41pp 25990 117 24X
Fiche 50-327,84/08/06,8408100024

P Operating license stage documents & correspondence

8408030019 Forwards responses to J Singh 840522 verbal questions re control of heavy loads
MILLS,L M Tennessee Valley Authority 84/07/27 ADENSAM,E
Licensing Branch 4 2pp 25907 092 24X Fiche 50-327,84/07/27,
8408030019

--8408030025 Rev 3 to Procedure MI-6 22, "Control of Heavy Loads in Critical Lifting Zones - NUREG-0612 "
DOTY,J W , WHEELER,L J Tennessee Valley Authority 84/05/21
23pp 25907 094 24X Fiche 50-327,84/07/27,8408030019

8408030026 Forwards request & justification for relief from hydrostatic test requirements in ASME Code,Section XI,Summer 1978 addenda Expeditious review requested to support Cycle 2 refueling outage scheduled for 840908
MILLS,L M Tennessee Valley Authority 84/07/30 ADENSAM,E
Licensing Branch 4 2pp 25907 082 24X Fiche 50-327,84/07/30,
8408030026

8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification
WIGGINTON,D L Operating Reactors Branch 1 84/07/30 Operating Reactors Branch 1 4pp 26143 265 24X Fiche 50-000,84/07/30,
8408160425

8408070133 Forwards response to 840720 request re postulated event concerning main steam line break inside & outside containment Based on modeling experimental data,containment temps would not approach FSAR values
MILLS,L M Tennessee Valley Authority 84/08/02 ADENSAM,E
Licensing Branch 4 4pp 25949 354 24X Fiche 50-327,84/08/02,
8408070133

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408140532 Forwards Rev 10 to offsite dose calculation manual
MILLS,L M Tennessee Valley Authority 84/08/06 ADENSAM,E
Licensing Branch 4 1p 26064 123 24X Fiche 50-327,84/08/06,
8408140532

--8408140535 Rev 10 to offsite dose calculation manual
* Tennessee Valley Authority 84/08/06 12pp 26064 124 24X
Fiche 50-327,84/08/06,8408140532

'408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 1, "Sequoyah Nuclear Plant Containment Analysis," for Meeting 38 Rept inconsistent w/four encl repts previously sent
FONTANA,M H Technology for Energy Corp 84/08/07 DENTON,H R , CASE,E Office of Nuclear Reactor Regulation, Director. HOUSTON,R NRC - No Detailed Affiliation Given 2pp 26234 001 24X
Fiche 50-000,84/08/07,8408230097

-8408230105 Draft "Sequoyah Nuclear Plant Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/07/31 152pP
26234 003 24X Fiche 50-000,84/08/07,8408230097

8408230108 Draft "Resuspension of Deposited Aerosols Following Primary Sys or Containment Failure," technical rept
* Industry Degraded Core Rulemaking Program 84/07/31 75pp
26234 154 24X Fiche 50-000,84/08/07,8408230097

8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants," technical rept
* Industry Degraded Core Rulemaking Program * Fauske & Associates, Inc FAI/84-9 DRFT 84/07/31 114pp 26234 231
24X Fiche:50-000,84/08/07,8408230097,

8408230116 Draft "Zion Nuclear Generating Station Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/08/07 119pp
26234 335 24X Fiche 50-000,84/08/07,8408230097

--8408230119 Draft "Grand Gulf Nuclear Station Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/08/07 175pp
26235 094 24X Fiche 50-000,84/08/07,8408230097

--8408230131 Draft, "Peach Bottom Atomic Power Station Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/08/07 75pp
26235 269 24X Fiche 50-000,84/08/07,8408230097

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408270156 Application to amend Licenses DPR-77 & DPR-79, changing Tech Specs to allow use of fifth vital battery when one of trained vital batteries out of svc Fee paid
SHELL,R H Tennessee Valley Authority 84/08/20 ADENSAM,E
Licensing Branch 4 1p 26245 227 24X Fiche 50-327,84/08/20,
8408270156

--8408270162 Proposed Tech Specs allowing use of fifth vital battery when trained vital batteries out of svc
* Tennessee Valley Authority 84/08/20 30pp 26245 228 24X
Fiche 50-327,84/08/20,8408270156

Q Inspection reports, IE Bulletins & correspondence

8408300459 Ack receipt of 840620 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/83-13 & 50-328/83-13
VERRELLI,D M Division of Project & Resident Programs 84/07/13
PARRIS,H G Tennessee Valley Authority 1p 26314 095 24X
Fiche 50-327,84/07/13,8408300459

--8408300469 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Installation of new communications sys delayed until 840901 due to revised matl delivery date
KAMMER,D G Tennessee Valley Authority 84/06/20 O'REILLY,J P
Region 2, Office of Director 1p 26314 096 24X
Fiche 50-327,84/07/13,8408300459

--8408300477 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Corrective actions revised emergency monitoring implementing procedures will be completed by 840601
MILLS,L M Tennessee Valley Authority 84/05/01 O'REILLY,J P
Region 2, Office of Director 1p 26314 097 24X
Fiche 50-327,84/07/13,8408300459

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 23865 047 24X Fiche 50-000,84/07/27,8407250229

8408270365 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/84-11 & 50-328/84-11
LEWIS,R C Region 2, Office of Director 84/07/27 PARRIS,H G
Tennessee Valley Authority 1p 26256 248 24X
Fiche 50-327,84/07/27,8408270365

--8408270370 Responds to NRC 840614 ltr re violations noted in Insp Repts 50-327/84-11 & 50-328/84-11 Corrective actions personnel reinstructed on importance of checking limiting condition for operations prior to mode change
MILLS,L M Tennessee Valley Authority 84/07/16 O'REILLY,J P
Region 2, Office of Director 7pp 26256 249 24X
Fiche 50-327,84/07/27,8408270365

--8408270375 Forwards Insp Repts 50-327/84-11 & 50-328/84-11 on 840406-0505 & notice of violation
LEWIS,R C Region 2, Office of Director 84/06/14 PARRIS,H G
Tennessee Valley Authority 2pp 26256 256 24X
Fiche 50-327,84/07/27,8408270365

--8408270378 Notice of violation from insp on 840406-0505
* Region 2, Office of Director 84/06/14 3pp 26256 258 24X
Fiche 50-327,84/07/27,8408270365

--8408270382 Insp Repts 50-327/84-11 & 50-328/84-11 on 840406-0505
Noncompliance noted changing modes w/Tech Spec
instrumentation out of commission, failure to control mods,
failure to retrieve QA records & inadequate testing of mods
FORD, E J , BUTLER, S D , JULIAN, C A Region 2, Office of Director
84/06/13 10pp 26256 261 24X Fiche 50-327, 84/07/27, 8408270365

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station
Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator
Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR
Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New
York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to
Patients Undergoing Co-60 Teletherapy Treatments " Svc
list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post
830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New
York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In &
Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New
York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely
Affect Operation of Essential Electrical Equipment " Svc
list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New
York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of
Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/
High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly
Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New
York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to
drop out on listed undervoltage conditions Problem due to
excessive feedback around operational amplifier U2 Clamping
diode must be added Affected units listed
DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd)
84/03/13. DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 3pp 26191 357 24X Fiche 50-000, 84/03/13, 8408220317

8408060241 LER 84-042-00 on 840627, radiation monitor 0-RE-90-225 would
not provide automatic isolation of direct releases from
neutralization tank Batch releases made on 840624 & 25 w/o
compliance w/limiting conditions W/840726 ltr
KIRK, G B , WALLACE, P R Tennessee Valley Authority 84/07/26 3pp
25935 138 24X Fiche 50-327, 84/07/26, 8408060241.

8408160453 Special Rept 84-03 fire detector rendered inoperable when
water for drill cooling dripped onto detector Hourly roving
fire watch established
WALLACE, P R Tennessee Valley Authority 84/08/02 Record
Services Branch (Document Control Desk) 2pp 26107 276 24X
Fiche 50-327, 84/08/02, 8408160453

8408090156 LER 84-044-00 on 840705, during SI-7 test on diesel generator
1A-A, remaining three diesel generators automatically
started Caused by personnel error Training revised to
emphasize procedures W/840803 ltr
COOPER, M R , WALLACE, P R Tennessee Valley Authority 84/08/03
3pp 25994 327 24X Fiche 50-327, 84/08/03, 8408090156

8408160493 LER 84-045-00 on 840709, w/auxiliary control air compressor
A-A out of svc, compressor B-B removed from svc to
investigate knocking noise Noise caused by disconnected
piston rod due to broken lock-tab washer W/840807 ltr
COOPER, M R , WALLACE, P R Tennessee Valley Authority 84/08/07
3pp 26107 315 24X Fiche 50-327, 84/08/07, 8408160493

8408160522 LER 84-046-00 on 840727, various safety-related sys
interactions found not in compliance w/10CFR50, App R Cause
not stated Fire watches established until compliance
achieved W/840810 ltr
COOPER, M R , WALLACE, P R Tennessee Valley Authority 84/08/10
3pp 26108 018 24X Fiche 50-327, 84/08/10, 8408160522

8408240313 Part 21 rept re fitting leaks at incore probe seal tables at
PWRs, per IE Info Notice 84-55 Subj fittings not used as
instructed
WILSON, B Crawford Fitting Co 84/08/13 JORDAN, E L Division of
Emergency Preparedness & Engineering Response (Post 830103) 2pp
26225 313 24X Fiche 50-327, 84/08/13, 8408240313

8408230509 LER 84-047-00 on 840717, high radiation signal actuated,
causing ventilation isolation in auxiliary & containment
bldgs Caused by radiation monitor wire slipping onto power
supply, tripping breaker All equipment reset W/840815 ltr
DUGGIN, G , WALLACE, P R Tennessee Valley Authority 84/08/15, 3pp
26212 276 24X Fiche 50-327, 84/08/15, 8408230509

8408280267 PNO-II-84-056 Nuclear Safety Review Staff rept assessing TVA
actions re 840419 in-core probe seal table break
received Inspectors will investigate event further on
840827 Util & NRC responding to media inquiries
FREDERICKSON, P , WEISE, S Region 2, Office of Director 84/08/24
1p 26261 341 24X Fiche 50-327, 84/08/24, 8408280267

8408310050 LER 84-048-00 on 840725, during review of instrumentation
drawings, only one RCS pressure channel found existent in
field where two are required Previous design change dictated
moving channel Second channel installed W/840824 ltr
DUGGIN, G E , WALLACE, P R Tennessee Valley Authority 84/08/24
3pp 26335 001 24X Fiche 50-327, 84/08/24, 8408310050

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408300316 Ack receipt of 840503 ltr re emergency exercise scheduled
for Jul 1984 Review of info submitted re scope & objectives
of planned exercise indicates no questions Scenario &
controller messages will be reviewed & evaluated
VERRELLI, D M Region 2, Office of Director 84/05/31 PARRIS, H G
Tennessee Valley Authority 1p 26308 327 24X
Fiche 50-327, 84/05/31, 8408300316

8408300402 Forwards summary of 840530 meeting w/TVA, Alabama Power Co,
Florida Power Corp, Florida Power & Light & Georgia Power Co
re selected emergency preparedness issues
O'REILLY, J P Region 2, Office of Director 84/06/08 PARRIS, H G
Tennessee Valley Authority 4pp 26308 116 24X
Fiche 50-000, 84/06/08, 8408300402

8408300193 Forwards 840612 ltr detailing overall planning for 840620
French security team visit to facility Biographical info
for each team member included
LEWIS, R C Region 2, Office of Director. 84/06/15 TUCKER, H B
Duke Power Co. 1p 26300 139 24X Fiche 50-000, 84/06/15,
8408300193

--8408300204 Requests authorization for six French security experts
hosted by NRC to visit McGuire facility on 840620 & Sequoyah
facility on 840622 Biographical info & itinerary encl
LAFLEUR, J D Office of International Programs, Director
84/06/12 TUCKER, H. B Duke Power Co PARRIS, H G Tennessee
Valley Authority 5pp 26300 140 24X Fiche, 50-000, 84/06/15,
8408300193

8408300459 Ack receipt of 840620 ltr informing NRC of steps taken to
correct violations noted in Insp Repts 50-327/83-13 &
50-328/83-13
VERRELLI, D M. Division of Project & Resident Programs 84/07/13
PARRIS, H G Tennessee Valley Authority 1p 26314 095 24X
Fiche 50-327, 84/07/13, 8408300459

--8408300469 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Installation of new communications sys delayed until 840901 due to revised matl delivery date
KAMMER, D S Tennessee Valley Authority 84/06/20 O'REILLY, J P Region 2, Office of Director 1p 26314 096 24X
Fiche 50-327, 84/07/13, 8408300459

--8408300477 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Corrective actions revised emergency monitoring implementing procedures will be completed by 840601
MILLS, L M Tennessee Valley Authority 84/05/01 O'REILLY, J P Region 2, Office of Director 1p 26314 097 24X
Fiche 50-327, 84/07/13, 8408300459

8408300363 Forwards summary of 840711 meeting w/util in Region II ofc re proposed compensatory measures associated w/security power block concept Attendance list also encl
LEWIS, R C Region 2, Office of Director 84/07/17 PARRIS, H G Tennessee Valley Authority 4pp 26308 194 24X
Fiche 50-327, 84/07/17, 8408300363

8408060254 Revs to radiological emergency plan implementing procedures, including Rev 2 to SQN IP-7, "Activation of Operations Support Ctr" & "Rev 3 to SQN IP-15, "Emergency Exposure Guidelines " W/840730 ltr
MILLS, L M Tennessee Valley Authority 84/07/30 O'REILLY, J P Region 2, Office of Director 30pp 25934 078 24X
Fiche 50-327, 84/07/30, 8408060254

8408300519 Confirms 840726 telcon re 840803 mgt meeting to discuss development & implementation of 10CFR50, App R program at Watts Bar & status of Sequoyah program
O'REILLY, J P Region 2, Office of Director 84/07/30 PARRIS, H G Tennessee Valley Authority 2pp 26313 300 24X
Fiche 50-000, 84/07/30, 8408300519

8408100024 Rev 12 to radiological emergency plan W/840806 ltr
MILLS, L M Tennessee Valley Authority 84/08/06 O'REILLY, J P Region 2, Office of Director 41pp 25990 117 24X
Fiche 50-327, 84/08/06, 8408100024

P Operating license stage documents & correspondence

8408030019 Forwards responses to J Singh 840522 verbal questions re control of heavy loads
MILLS, L M Tennessee Valley Authority 84/07/27 ADENSAM, E Licensing Branch 4 2pp 25907 092 24X Fiche 50-327, 84/07/27, 8408030019

--8408030025 Rev 3 to Procedure MI-6 22, "Control of Heavy Loads in Critical Lifting Zones - NUREG-0612 "
DOTY, J W , WHEELER, L J Tennessee Valley Authority 84/05/21 23pp 25907 094 24X Fiche 50-327, 84/07/27, 8408030019

8408030026 Forwards request & justification for relief from hydrostatic test requirements in ASME Code, Section XI, Summer 1978 addenda Expeditious review requested to support Cycle 2 refueling outage scheduled for 840908
MILLS, L M Tennessee Valley Authority 84/07/30 ADENSAM, E Licensing Branch 4 2pp 25907 082 24X Fiche 50-327, 84/07/30, 8408030026

8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification
WIGGINTON, D L Operating Reactors Branch 1 84/07/30 Operating Reactors Branch 1 4pp 26143 265 24X Fiche 50-000, 84/07/30, 8408160425

8408060220 Forwards final summary Rept WCAP-10509, "Analysis of Capsule T From TVA Sequoyah, Unit 2 Reactor Vessel Radiation Surveillance Program " Change in capsule withdrawal schedule in Tech Spec Table 4 4-5 not required
MILLS, L M Tennessee Valley Authority 84/07/31 ADENSAM, E Licensing Branch 4 2pp 25929 109 24X Fiche 50-328, 84/07/31, 8408060220

8408060231 "Analysis of Capsule T From TVA Sequoyah, Unit 2 Reactor Vessel Radiation Surveillance Program "
BOGGS, R B , VANICHKO, S E , CHENEY, C A Westinghouse Electric Corp WCAP-10509 84/04/30 85pp. 25929:111 24X
Fiche 50-328, 84/07/31, 8408060220

8408070133 Forwards response to 840720 request re postulated event concerning main steam line break inside & outside containment Based on modeling experimental data, containment temps would not approach FSAR values
MILLS, L M Tennessee Valley Authority 84/08/02 ADENSAM, E Licensing Branch 4 4pp 25949 354 24X Fiche 50-327, 84/08/02, 8408070133

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140532 Forwards Rev 10 to offsite dose calculation manual
MILLS, L M Tennessee Valley Authority 84/08/06 ADENSAM, E Licensing Branch 4 1p 26064 123 24X Fiche 50-327, 84/08/06, 8408140532

--8408140535 Rev 10 to offsite dose calculation manual
* Tennessee Valley Authority 84/08/06 12pp 26064 124 24X
Fiche 50-327, 84/08/06, 8408140532

8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 1, "Sequoyah Nuclear Plant Containment Analysis," for Meeting 38 Rept inconsistent w/four encl repts previously sent
FONTANA, M H Technology for Energy Corp 84/08/07 DENTON, H R , CASE, E Office of Nuclear Reactor Regulation, Director HOUSTON, R NRC - No Detailed Affiliation Given 2pp 26234 001 24X
Fiche 50-000, 84/08/07, 8408230097

--8408230105 Draft "Sequoyah Nuclear Plant Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/07/31 132pp 26234 003 24X Fiche 50-000, 84/08/07, 8408230097

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408270156 Application to amend Licenses DPR-77 & DPR-79, changing Tech Specs to allow use of fifth vital battery when one of trained vital batteries out of svc Fee paid
SHELL, R H Tennessee Valley Authority 84/08/20 ADENSAM, E Licensing Branch 4 1p 26245 227 24X Fiche 50-327, 84/08/20, 8408270156

--8408270162 Proposed Tech Specs allowing use of fifth vital battery when trained vital batteries out of svc
* Tennessee Valley Authority 84/08/20 30pp 26245 228 24X
Fiche 50-327, 84/08/20, 8408270156

8408280086 Forwards peaking factor limit rept for Cycle 3 operations
MILLS, L M Tennessee Valley Authority 84/08/23 BERLINGER, C H Division of Licensing 6pp 26261 191 24X Fiche 50-328, 84/08/23, 8408280086

8408300385 Forwards Amend 27 to License DPR-79 & safety evaluation Amend authorizes one-time 36 h extension of time for ECCS operability w/one centrifugal charging pump inoperable
ADENSAM, E G Licensing Branch 4 84/08/23 PARRIS, H G Tennessee Valley Authority 2pp 26315 324 24X Fiche 50-328, 84/08/23, 8408300385

--8408300387 Amend 27 to License DPR-79 Amend authorizes one-time 36 h extension of for ECCS operability w/one centrifugal charging pump inoperable
ADENSAM, E G Licensing Branch 4 84/08/23 5pp 26315 326 24X
Fiche 50-328, 84/08/23, 8408300385

--8408300389 Safety evaluation supporting Amend 27 to License DPR-79
* Office of Nuclear Reactor Regulation, Director 84/08/23 5pp 26315 331 24X Fiche 50-328, 84/08/23, 8408300385

Q Inspection reports, IE Bulletins & correspondence

8408300459 Ack receipt of 840620 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/83-13 & 50-328/83-13
VERRELLI, D M Division of Project & Resident Programs 84/07/13 PARRIS, H G Tennessee Valley Authority 1p 26314 095 24X
Fiche 50-327, 84/07/13, 8408300459

--8408300469 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Installation of new communications sys delayed until 840901 due to revised matl delivery date.
KAMMER, D S Tennessee Valley Authority 84/06/20 O'REILLY, J P Region 2, Office of Director 1p 26314 096 24X
Fiche: 50-327, 84/07/13, 8408300459

--8408300477 Responds to NRC 830913 ltr re violations noted in Insp Repts 50-327/83-13 & 50-328/83-13 Corrective actions revised emergency monitoring implementing procedures will be completed by 840601
MILLS,L M Tennessee Valley Authority 84/05/01 O'REILLY,J P Region 2, Office of Director 1p 26314 097 24X
Fiche 50-327,84/07/13,8408300459

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25845 047 24X Fiche 50-000,84/07/27,8407250229

8408270365 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-327/84-11 & 50-328/84-11
LEWIS,R C Region 2, Office of Director 84/07/27 PARRIS,H G Tennessee Valley Authority 1p 26256 248 24X
Fiche 50-327,84/07/27,8408270365

--8408270370 Responds to NRC 840614 ltr re violations noted in Insp Repts 50-327/84-11 & 50-328/84-11 Corrective actions personnel reinstructed on importance of checking limiting condition for operations prior to mode change
MILLS,L M Tennessee Valley Authority 84/07/16 O'REILLY,J P Region 2, Office of Director 7pp 26256 249 24X
Fiche 50-327,84/07/27,8408270365

--8408270375 Forwards Insp Repts 50-327/84-11 & 50-328/84-11 on 840406-0505 & notice of violation
LEWIS,R C Region 2, Office of Director 84/06/14 PARRIS,H G Tennessee Valley Authority 2pp 26256 256 24X
Fiche 50-327,84/07/27,8408270365

--8408270378 Notice of violation from insp on 840406-0505
* Region 2, Office of Director 84/06/14 3pp 26256 258 24X
Fiche 50-327,84/07/27,8408270365

--8408270382 Insp Repts 50-327/84-11 & 50-328/84-11 on 840406-0505 Noncompliance noted changing modes w/Tech Spec instrumentation out of commmission, failure to control mods, failure to retrieve QA records & inadequate testing of mods
FORD,E J , BUTLER,S D , JULIAN,C A Region 2, Office of Director 84/06/13 10pp 26256 261 24X Fiche 50-327,84/07/27,8408270365

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317

8408160269 LER 84-012-00 on 840710, during surveillance testing for external piping leakage, both RHR sys trains inoperable when valve HCV-74-34 opened Cause not stated Procedure change issued W/8408080 ltr
KIRK,G B , WALLACE,P R Tennessee Valley Authority 84/08/08 3pp 26106 177 24X Fiche 50-328,84/08/08,8408160269

8408170053 LER 84-011-00 on 840713, high radiation alarm actuated, causing containment ventilation isolation Caused by voltage spike resulting from electromagnetic interference generated by low flow alarm switch Alarms reset W/8408016 ltr
DUGGIN,G , WALLACE,P R Tennessee Valley Authority 84/08/10 3pp 26130 053 24X Fiche 50-328,84/08/10,8408170053

8408240313 Part 21 rept re fitting leaks at incore probe seal tables at PWRs, per IE Info Notice 84-55 Subj fittings not used as instructed
WILSON,B Crawford Fitting Co 84/08/13 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26225 313 24X Fiche 50-327,84/08/13,8408240313

8408240286 PNO-II-84-053 on 840820, unit shut down after pressure surge caused opening of ice condenser doors, causing relief tank pressure drop & containment pressure rise Caused by relief tank disc rupture or broken safety valve tailpipe
FREDERICKSON,P , CONTRELL,F S Region 2, Office of Director 84/08/21 2pp 26223 194 24X Fiche 50-328,84/08/21,8408240286

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

8408020015 Forwards response to NRC request for addl info re Vol IX of seismic margin review rept, "Balance-of-Plant Class 1, 2 & 3 Piping, Pipe Supports & Valves "
COOK,J W Consumers Power Co 84/07/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 16pp 25883 120 24X
Fiche 50-329,84/07/11,8408020015

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329,84/07/18,8408010061

--7812070142 Discusses IE Insp Repts 50-329/78-12 & 50-330/78-12 Contributing factors to settlements of diesel generator bldg foundation & generator pedestals include variable properties of random fill matl supporting structure & cooling pond
KEPPLER,J G Region 3, Chicago, Office of the Director BX16 001 78/11/01 THORNBURG,H D Division of Reactor Construction Inspection 2pp 26506 211 24X Fiche 50-329,84/07/18, 8408010061

--7909290119 Forwards outline history of geotechnical engineering problems re plant fill Lists pertinent PSAR & FSAR criteria & summarizes foundation conditions & remedial measures for all Category I structures founded on plant fill
GILLEN,D M Geosciences Branch BX16 015 79/08/28
JACKSON,R E Geosciences Branch 10pp 26510 309. 24X
Fiche 50-329,84/07/18,8408010061

--8004040738 Summary of 800227 & 28 meeting & site visit w/util in Midland,MI re soil settlement problems & related investigation program
GONZALES,R O Hydrology Meteorology Branch BX16 032 80/03/10
DIVINS,W S Hydrology Meteorology Branch 9pp 26511 119 24X
Fiche 50-329,84/07/18,8408010061

--8008130764 Summarizes status of seismological input parameters re geosciences & geotechnical review of facilities as discussed at 800702 & 22 meetings
KIMBALL,J Geosciences Branch BX16 029 80/08/07 JACKSON,R E Geosciences Branch 6pp 26511 095 24X Fiche 50-329,84/07/18,8408010061

--8011240409 Forwards Hydrologic Engineering Section interrogatories re permanent dewatering sys at facilities
LEAR,G E Hydrologic & Geotechnical Engineering Branch BX17 008 80/11/10 TEDESCO,R L Assistant Director for Licensing 3pp 26517 244 24X Fiche 50-329,84/07/18,8408010061

--8105070480 Responds to request re Geosciences Branch estimate of time required to complete site review Approx 30 days are needed to review addl info requested for Part 1 & 3 months are needed for review of Part 2 submittal
KNIGHT,J P Assistant Director for Comp & Structures Engineering (Pre 830201) BX16 057B 81/04/24 PATON,W D Office of the Executive Legal Director 1p 26513 189 24X
Fiche 50-329,84/07/18,8408010061

--8110190801 Forwards topic discussions for inclusion in 1981 annual rept,per B10902 commitment Discussions of technical assistance program for licensing,GETR review & Midland remedial repair info encl
HELLER,L H Hydrologic & Geotechnical Engineering Branch BX16 053 81/09/16 LEAR,G Hydrologic & Geotechnical Engineering Branch 6pp 26512 253 24X Fiche 50-329,84/07/18,8408010061

--8111240064 Informs of 811016 conference call w/util to discuss revised schedule for soils hearing requests revision to better accommodate const schedule Agreed schedule for hearings will be 811201-04 & 1214-18
HOOD,D Licensing Branch 4 BX19 036B 81/10/30 TEDESCO,R L Assistant Director for Licensing 3pp 26535 252 24X
Fiche 50-329,84/07/18,8408010061

--8201050063 Summarizes 811207 telcon re 820105 soils hearing
HOOD,D Licensing Branch 4 BX18 032 81/12/14 ADENSAM,E G Licensing Branch 4 2pp 26526 099 24X Fiche 50-329,84/07/18,8408010061

--8201220049 Advises of 1-month delay in meeting R Tedesco 811214 schedule in support of facility hearing & review Viable schedule must recognize need for iteration w/applicant following each significant submittal
VOLLMER,R H Division of Engineering BX16 074 81/12/28
EISENHUT,D G Division of Licensing 3pp 26514 188 24X
Fiche 50-329,84/07/18,8408010061

--8202040352 Informs that certain SER sections,especially soil remedial actions,will not be complete by 820406 deadline
ADENSAM,E G Licensing Branch 4 BX16 055 82/01/19
EISENHUT,D G Division of Licensing 3pp 26512 266 24X
Fiche 50-329,84/07/18,8408010061

--8203020050 Summary of 811006-07 meeting w/util,Bechtel & consultants in Bethesda,MD re underground piping in inadequately compact plant fill
HOOD,D S Licensing Branch 4 BX21 002 82/02/05 DENTON,H R NRC - No Detailed Affiliation Given 37pp 26549 084 24X
Fiche 50-329,84/07/18,8408010061

--8203050209 Forwards listing of issues to be resolved prior to start of Phase 2 underpinning operations for auxiliary bldg
LEAR,G Hydrologic & Geotechnical Engineering Branch BX16 035. 82/04/28 ADENSAM,E Licensing Branch 4 2pp 26511 200 24X
Fiche 50-329,84/07/18,8408010061

--8205120033 Summarizes technical comments from ACRS subcommittee 820429 meeting re remedial activities for deficient soils
ADENSAM,E G Licensing Branch 4 BX18 035 82/05/04 BOSNAK,R NRC - No Detailed Affiliation Given 4pp 26527 183 24X
Fiche 50-329,84/07/18,8408010061

--8205210467 Notifies that util submittal re Phase 2 of underpinning repair work at facility acceptable,provided that encl mods & requirements are incorporated into Phase 2 program
KNIGHT,J P Assistant Director for Comp & Structures Engineering (Pre 830201) BX16 039 82/05/10 TEDESCO,R L Assistant Director for Licensing 34pp 26511 203 24X
Fiche 50-329,84/07/18,8408010061

--8206020051 Comments on draft of acceptance provisions for Phase 2 Fin transmittal to applicant should move through DE for concurrence
KNIGHT,J P Assistant Director for Comp & Structures Engineering (Pre 830201) BX16 036 82/05/13 KANE,J Assistant Director for Comp & Structures Engineering (Pre 830201) 1p 26511 202
24X Fiche 50-329,84/07/18,8408010061

--8206240401 Forwards comments on 820422 response to NRC request for addl info re borated water storage tank & underpinning of svc water pump structure Contact w/applicant to resolve differences recommended
LEAR,G Hydrologic & Geotechnical Engineering Branch 82/06/16
ADENSAM,E Licensing Branch 4 105pp 66129 031 24X
Fiche 50-329,84/07/18,8408010061

--8206290161 Submits proposed schedule for facility soils review
ADENSAM,E G Licensing Branch 4 BX18 036 82/06/25
EISENHUT,D G Division of Licensing 2pp 26527 187 24X
Fiche 50-329,84/07/18,8408010061

--8207140330 Forwards request for addl info from Structural Engineering Branch re applicant proposed remedial actions
SCHAUER,F P Structural Engineering Branch BX19 029 82/06/15
ADENSAM,E Licensing Branch 4 5pp 26533 206 24X
Fiche 50-329,84/07/18,8408010061

--8210130322 Forwards info re location of data on underpinning dimensions & load transfer procedures
POULOS,S J Geotechnical Engineers, Inc BX16 060 82/10/07
KANE,J Division of Engineering 6pp 26513 234 24X
Fiche 50-329,84/07/18,8408010061

--8210150698 Clarifies NRC/util interaction re QL review Maint of proper control by licensing property managers necessary to manage licensing activities properly Reviewers requested to follow guidelines
ADENSAM,E G Licensing Branch 4 BX16 070 82/09/29
TOMLINSON,E NRC - No Detailed Affiliation Given 2pp
26514 109 24X Fiche 50-329,84/07/18,8408010061

--8305270222 Forwards trip rept of 830510-13 site visit re underpinning contract Other topics discussed include cracks in svc water pump structure,heave over freeze wall,need to stop laying back soil along underpinning drifts & settlements
POULOS,S J Geotechnical Engineers, Inc BX18 022 83/05/23
KANE,J Division of Engineering 19pp 26524 317 24X
Fiche 50-329,84/07/18,8408010061

--8306060387 Trip rept of 830511 & 12 site visits to view pier load test installation & results
KANE,J D Structural & Geotechnical Engineering Branch BX18 021 83/05/27 LEAR,G Structural & Geotechnical Engineering Branch 2pp 26524 315 24X Fiche 50-329,84/07/18,8408010061

--8307130423 Forwards paper entitled "Use of Site Dependent Spectra" to be presented at workshop on "Site-Specific Effects of Soil & Rock on Ground Motion & Implications for Earthquake-Resistant Design" on 830726-28
KIMBALL,J Geosciences Branch BX17 039 83/06/27 JACKSON,R E Geosciences Branch 1p 26520 069 24X Fiche 50-329,84/07/18,8408010061

--8307130425 Speech entitled "Use of Site Dependent Spectra," to be presented at 830726-28 workshop on "Site-Specific Effects of Soil & Rock on Ground Motion & Implications for Earthquake-Resistant Design" in Santa Fe,NM
KIMBALL,J Geosciences Branch BX17 040 83/06/27 25pp
26520 070 24X Fiche 50-329,84/07/18,8408010061

--8310070262 Forwards second phase of Geotechnical Engineering input on findings of fact & conclusions of law in response to OELD request Several areas of significant differences exist re diesel generator bldg
LEAR,G Structural & Geotechnical Engineering Branch BX17 032 83/09/30. PATON,W D Office of the Executive Legal Director 6pp 26519 246 24X Fiche 50-329,84/07/18,8408010061

--8312080185 Forwards technical evaluation of HVAC structural design adequacy,based on findings of Mechanical Engineering Branch design review & audit
KNIGHT,J P Assistant Director for Comp & Structures Engineering (Post 830201) BX18 051 83/11/25 NOVAK,T M Assistant Director for Licensing 27pp 26528 206 24X
Fiche 50-329,84/07/18,8408010061

--8312120393 Requests requisite info re followup action to be taken by Region III to 831108 recommendation for board notification
EISENHUT,D G Division of Licensing BX21 014 83/11/30
WARNICK,R F Region 3, Office of Director 1p 26553 204 24X
Fiche 50-329,84/07/18,8408010061

--8406020280 Trip rept of 840504 site visit to participate in public meeting on mgt appraisal program to be performed on util Comments on independent mgt appraisal encl
MCLAUGHLIN,P Licensee Qualifications Branch BX20 010
84/05/22 BOOHER,H R Licensee Qualifications Branch 5pp
26539 045 24X Fiche 50-329,84/07/18,8408010061

--8408010149 Forwards executive summary re QA program update,per 810331 meeting commitment & NRC 810402 ltr Apps will be transmitted by 810522
COOK,J W Consumers Power Co BX14 007 81/04/30 KEPPLER,J G
Region 3, Chicago, Office of the Director (81/03/01) 19pp
26500 039 24X Fiche 50-329,84/07/18,8408010061

--8408020038 Lists questions asked of util during FSAR & 10CFR50 54(f) review,including questions re geological & seismological matters & intake & discharge structures for svc water sys
KANE,J NRC - No Detailed Affiliation Given BX17 001 84/07/18
19pp 26514 273 24X Fiche 50-329,84/07/18,8408010061

--8408020043 Lists questions & responses re condition of soils onsite, correction to foundation problems & risk in allowing const to continue
* NRC - No Detailed Affiliation Given BX17 002 79/03/05
15pp 26514 322 24X Fiche 50-329,84/07/18,8408010061

--8408020099 Answers to util interrogatories re staff requests directed on determination & justification of acceptance criteria applied to various remedial measures taken on page 3 of Order
KANE,J NRC - No Detailed Affiliation Given BX17 010 84/07/18
Consumers Power Co 31pp 26517 331 24X
Fiche 50-329,84/07/18,8408010061

--8408020112 Question re discrepancy in magnitude of loading stress on Fig 2 of 800714 rept & info on Tables 4-1A & 2 5-14
* NRC - No Detailed Affiliation Given BX17 012 84/07/18 1p
26518 143 24X Fiche 50-329,84/07/18,8408010061

--8408020122 Provides trip rept for 781107 meeting in Urbana,IL re settlement of far east bay of diesel generator bldg List of correction action options provided
CODKE,T C Consumers Power Co BX17 015 78/12/12 Consumers
Power Co 4pp 26518 264 24X Fiche 50-329,84/07/18,8408010061

--8408020188 Responds to Mooney concept theory re SRP 2 5 4 & FSAR review Suggestion to OELD re Mooney testimony encl
HOOD,D NRC - No Detailed Affiliation Given BX17 027 83/11/22
HASSEL,D M NRC - No Detailed Affiliation Given 4pp
26519 153 24X Fiche 50-329,84/07/18,8408010061

--8408020192 Forwards applicant advance copy of meeting notes for 820727-30 design audit of soils remedial activities in Ann Arbor, MI Questions should be referred to J Kane
LEAR,G Hydrologic & Geotechnical Engineering Branch BX17 043
82/09/17 ADENSAM,E Licensing Branch 4 22pp. 26520 224 24X
Fiche 50-329,84/07/18,8408010061

--8408020193 Informs that Structural Mechanics Assoc seismic margin review studies indicate soil layering profiles & soil properties differ from properties previously addressed
KANE,J Structural & Geotechnical Engineering Branch BX17 044
82/05/11 LEAR,G Structural & Geotechnical Engineering Branch
2pp 26520 247 24X Fiche 50-329,84/07/18,8408010061

--8408020195 Summary of 840417 meeting w/TERA,Structural Mechanics Assoc (SMA) & util in Chicago,IL to discuss SMA seismic margins evaluation & potential applicability to disposition of outstanding civil/structural issues
RINALDI,F Structural & Geotechnical Engineering Branch BX17
045 84/07/18 LEAR,G Structural & Geotechnical Engineering
Branch 2pp 26520,249 24X Fiche 50-329,84/07/18,8408010061

--8408020199 Forwards request for addl structural engineering info needed to continue OL review of NPP application as applicable to seismic margins review,svc water pump structure & diesel generator bldg.
LEAR,G Structural & Geotechnical Engineering Branch. BX17 046
84/05/03 ADENSAM Licensing Branch 4 5pp 26521,042 24X
Fiche 50-329,84/07/18,8408010061

--8408030001 Handwritten notes & outline of conference call w/Bechtel & util re review of buried piping,monitoring program & future settlement
MEISENHEIMER,J. NRC - No Detailed Affiliation Given BX17 047
81/12/15 6pp 26515-146 24X Fiche 50-329,84/07/18,8408010061.

--8408030004 Summary of 811006-07 meeting w/util in Bethesda,MD re underground piping in inadequately compacted plant fill Meeting agenda,attendance list & const hydro test viewgraphs encl
HOOD,D S Licensing Branch 4 BX17 048 82/02/05 Licensing
Branch 4 36pp 26515 241 24X Fiche 50-329,84/07/18,8408010061

--8408030009 Summary of 810721 meeting w/applicant in Bethesda,MD re summary of San Onofre meeting on confirmatory analysis of piping sys design Confirmatory analysis encl
HOOD,H Licensing Branch 3 BX17 049 81/08/19 Licensing
Branch 3 29pp 26515 277 24X Fiche 50-329,84/07/18,8408010061

--8408030013 Notification of 820416 meeting w/util in Bethesda,MD to discuss buried piping & related applicant 820316 submittal W/handwritten notes of 820407 conference call & outline of outstanding issues in geotechnical engineering area
HOOD,D S Licensing Branch 4 BX17 050 82/04/13 ADENSAM,E Q
Licensing Branch 4 22pp 26515 306 24X Fiche 50-329,84/07/18, 8408010061

--8408030020 Handwritten notes on 810120 meeting re stress analysis for underground piping Outline of discussion topics for pipe stress analysis encl
KANE,J NRC - No Detailed Affiliation Given BX17 052 81/01/20
NRC - No Detailed Affiliation Given 18pp 26515-355 24X
Fiche 50-329,84/07/18,8408010061

--8408030028 Agenda for 820121-22 meeting to discuss underground piping concerns W/handwritten summary of 820107 conference call re underground piping & 820120 evaluation of sand settlement due to earthquake
KANE,J NRC - No Detailed Affiliation Given BX17 055 82/01/22
NRC - No Detailed Affiliation Given 23pp 26516 017 24X
Fiche 50-329,84/07/18,8408010061

--8408030042 Agenda for 811006 meeting w/Bechtel,util & Army Corps of Engineers to discuss underground piping reprofiling,proposed demonstration solution & 1981 measurement results
* NRC - No Detailed Affiliation Given BX17 058 81/10/06
Office of Nuclear Reactor Regulation, Director 11pp 26516 045
24X Fiche 50-329,84/07/18,8408010061

--8408030051 Handwritten notes re addl boring logs at buried diesel generator fuel oil storage tank location Calculation sheets & boring logs encl
MEISENHEIMER,J. NRC - No Detailed Affiliation Given BX17 060
82/03/29 KANE,J NRC - No Detailed Affiliation Given 13pp
26516 057 24X Fiche 50-329,84/07/18,8408010061

--8408030056 Handwritten notes re 810120 meeting w/applicant on settlement of Category I underground piping
KANE,J NRC - No Detailed Affiliation Given BX17 061, 81/02/09
CAPPUCCI,T NRC - No Detailed Affiliation Given 4pp
26516 070 24X Fiche 50-329,84/07/18,8408010061

--8408030058 Forwards evaluation of general acceptability of effects of settlement in several buried svc piping sys Rept partial response to FSAR Questions 16 through 20 & 34.
KLEIN,H R Bechtel Corp BX17 062 80/08/01 CURTIS,L H
Bechtel Corp 7pp 26516-074 24X Fiche 50-329,84/07/18, 8408010061

--8408030064 Forwards analysis of buried piping background info,in support of proposed demonstration solution & in response to NRC concern re underground piping Addl engineering info encl
KEELEY,G S Consumers Power Co BX17 063 81/12/15 DENTON,H R
Office of Nuclear Reactor Regulation, Director. 76pp. 26516-081
24X Fiche 50-329,84/07/18,8408010061

--8408030068 Forwards stress analysis of several underground pipe lines as profiled in Rev 6 of "Responses to NRC 10CFR50 54(f) Requests re Plant Fill" dtd 800401.
BATES,J D Rockwell International Corp BX17 064 80/10/01
BOSNAK,R J Mechanical Engineering Branch 52pp. 26516 162 24X
Fiche 50-329,84/07/18,8408010061

--8408130227 Contract for consulting svcs between util & Mgt Analysis Co, agreeing to perform technical svcs,including consulting & QA svcs Purchase requisition,internal memos & supporting documentation encl
COOK,J W Consumers Power Co BX15 001 82/01/15 350pp
26500 316 24X Fiche 50-329,84/07/18,8408010061

--8408130230 Discusses 830118 & 26 meetings in Glen Ellyn,IL re Region III insp of diesel generator bldg & independent design review program;respectively Midland project manager will attend 830126 public meeting
ADENSAM,E Q Licensing Branch 4 BX15 002 83/01/05 NOVAK,T M
Assistant Director for Licensing 19pp. 26502-089 24X
Fiche 50-329,84/07/18,8408010061

DOCKETED ITEMS

--8408130234 Draft memo re issues of potential impact on Hearing Board considerations concerning QA program
KEPPLER,J G Region 3, Office of Director BX15 003 82/04/02
EISENHUT,D G Division of Licensing 7pp 26502 121 24X
Fiche 50-329,84/07/18,8408010061

--8408130241 Notification of 821207 mgt meeting w/Region III to discuss implementation of QA & IDVPs
HERNAN,R W Licensing Branch 4 BX15 004 82/11/01 NOVAK,T M
Assistant Director for Licensing 2pp 26502 131 24X
Fiche 50-329,84/07/18,8408010061

--8408130244 Forwards SALP 3 schedule Internal memos,handwritten in-process insp notices,program notes & supporting documentation encl
TAMBLING,T N Region 3, Office of Director BX15 005 82/11/01
Region 3, Office of Director 93pp 26502 133 24X
Fiche 50-329,84/07/18,8408010061

--8408130255 Forwards response to draft SALP rept Requests meeting w/ Keppler to review detailed contents of response Internal memos & handwritten notes encl
COOK,J W Consumers Power Co BX15 006 82/05/17 KEPPLER,J G
Region 3, Office of Director 91pp 26502 188 24X
Fiche 50-329,84/07/18,8408010061

--8408130269 "Const Project Evaluation of Consumers Power Co,Midland Energy Ctr Project,Units 1 & 2 (Observations) "
* Management Analysis Co BX15 007 83/01/31 160pp
26502 311 24X Fiche 50-329,84/07/18,8408010061

--8408130290 Forwards Mgt Analysis Co assessment of Midland QA program Rept endorses program W/o encl
COOK,J W Consumers Power Co BX15 008A 81/06/01 KEPPLER,J G
Region 3, Chicago, Office of the Director (81/03/01) 40pp
26503 178 24X Fiche 50-329,84/07/18,8408010061

--8408130301 Submits changes to be implemented prior to util resuming remedial soils work Draft list of noncompliances & deviations,handwritten notes & list of events since Jul 1981 hearings encl
WARNICK,R F Region 3, Office of Director BX15 010 82/09/20
KEPPLER,J G Region 3, Office of Director 70pp 26504 031 24X
Fiche 50-329,84/07/18,8408010061

--8408130306 "Biennial QA Audit of Midland Plant,Units 1 & 2 " Opening remarks of NRC 830208 meeting w/util & independent review encl.
* Management Analysis Co BX15 011 83/03/01 75pp 26504 131.
24X Fiche 50-329,84/07/18,8408010061

--8408130311 Notification of significant licensee 830315 meeting in Glen Ellyn,IL to present INPO findings
* Region 3, Office of Director BX15 012 83/03/09 Region 3, Office of Director 1p 26504 261 24X Fiche 50-329,84/07/18, 8408010061

--8408130320 Forwards status rept for Midland Project for Jan 1983 W/o encl
WARNICK,R F Region 3, Office of Director BX15 013 83/02/14
KEPPLER,J G Region 3, Office of Director 1p 26504 293 24X
Fiche 50-329,84/07/18,8408010061

--8408130323 Forwards status rept for Jan 1983 Rept contains input from each member of insp site team of Ofc of Special Cases
COOK,R J Region 3, Office of Director BX15 014 83/02/10
SHAFER,W D Region 3, Office of Director 3pp 26504 294 24X
Fiche 50-329,84/07/18,8408010061.

--8408130327 Forwards monthly status repts for Aug-Oct 1982
WARNICK,R F Region 3, Office of Director BX15 015 82/12/20
KEPPLER,J G Region 3, Office of Director 10pp 26504 303 24X
Fiche 50-329,84/07/18,8408010061

--8408130336 Requests approval not to perform SALP 3 assessments,due to widespread recognition of mgt,QA & const problems Draft notice of violation,insp rept & handwritten notes re diesel generator bldg monorail encl
KEPPLER,J G, Region 3, Office of Director, BX15 017 83/04/01
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 98pp. 26505 043 24X Fiche 50-329,84/07/18, 8408010061

--8408130348 Submits issues to be addressed at forthcoming evidentiary session on QA & QC matters
PATON,W D Consumers Power Co BX15 019, 82/08/10 ADENSAM,E G
NRC - No Detailed Affiliation Given 6pp 26505 276 24X
Fiche 50-329,84/07/18,8408010061

--8408130356 Forwards monthly status rept for Midland Project for Jan 1983
COOK,R J Region 3, Office of Director BX15 022 83/02/10
SHAFER,W D Region 3, Office of Director 3pp 26505 302 24X
Fiche 50-329,84/07/18,8408010061

--8408140039 Draft IE Insp Repts 50-329/78-20 & 50-330/78-20 from insp on 781211-20 & 790104-25 Violations noted inadequate control & supervision of plant fill matl placement & const specs not followed
PHILLIP,G A , GALLAGHER,E J , MAXWELL,G F Region 3, Office of Director BX16 002 84/07/18 60pp 26507 112 24X
Fiche 50-329,84/07/18,8408010061

--8408140050 Summary of NRC 790607 site tour & meeting on differential settlement of plant bldgs TC Cooke 790706 ltr to Bechtel re stainless steel pipe deficiency encl
COOKE,T C Consumers Power Co BX16 003 79/06/13 Consumers Power Co 4pp 26507 311 24X Fiche 50-329,84/07/18,8408010061

--8408140055 Preliminary "Discussion of NRC Insp Facts Resulting From NRC Investigation of Diesel Generator Bldg Settlement "
* Consumers Power Co BX16 004 79/03/05 35pp 26507 315
24X Fiche 50-329,84/07/18,8408010061

--8408140060 Forwards synopsis of 800228 presentation, "Remedial Measures for Electrical Penetration Wings of Control Bldg & Isolation Valve Pits" conducted before NRC representatives in Midland, MI
GOULD,C H Affiliation Not Assigned BX16 005 80/03/17
AFIFI,S S Bechtel Corp 22pp 26507 350 24X
Fiche 50-329,84/07/18,8408010061

--8408140065 Forwards general procedures & details employed by contractor to underpin fine arts bldg Sketches encl
MARR,G Bechtel Corp BX16 006 79/04/25 AFIFI,S Bechtel Corp 6pp 26508 010 24X Fiche 50-329,84/07/18,8408010061

--8408140069 Lists areas to be clarified &/or amplified,in responses to 10CFR50 54(f) questions Summary of soils chronology & 790807 internal memo re pre-meeting w/consultants encl
COOKE,T C Consumers Power Co BX16 007 80/01/25
ROTHWELL,M D Bechtel Corp 14pp 26508 016 24X
Fiche 50-329,84/07/18,8408010061

--8408140071 Submits const QC response to 790329 questions re diesel generator bldg No variance exists from QA program requirements
JOHNSON,D R Bechtel Corp BX16 008 79/04/09 RICHARDSON,G L
Bechtel Corp 9pp 26508 030 24X Fiche 50-329,84/07/18, 8408010061

--8408140076 Comments on recommendations given in soils repts prepared by Dames & Moore as compared to Bechtel earthwork specs Plant area fill supporting surrounding structures,Category I slopes & berm fill discussed
AFIFI,S S Bechtel Corp BX16 009, 74/09/13 CASTLEBERRY,R
Bechtel Corp 5pp 26508 039 24X Fiche 50-329,84/07/18, 8408010061

--8408140079 Recommends issuance of revised TPO std specs re large settlement due to incorrectly placed backfill Addl correspondence on problem alert & summary of soils chronology encl
RUMBAUGH,E Bechtel Corp BX16 010 79/12/27 JOHNSON,T E
Bechtel Corp 33pp 26508 044 24X Fiche 50-329,84/07/18, 8408010061

--8408140102 Forwards complete set of all abstracts of transcripts of hearings conducted on 811231-830630 W/listing of entire set of abstracts
HAMPTON,L Isham, Lincoln & Beale BX16 012 83/07/18
PATON,W D Hearing Branch 2 425pp 26508 097 24X
Fiche 50-329,84/07/18,8408010061

--8408140134 Handwritten notes re borings in area of svc water piping that have indicated potential for liquefaction W/Dept of Army memo re Feb 1980 visit to util & review of FSAR
KANE,J NRC - No Detailed Affiliation Given BX16 014 82/10/14
19pp 26510 227 24X Fiche 50-329,84/07/18,8408010061

--8408140144 Testimony of HN Singh re unresolved geotechnical engineering safety issues,including reactor bldg foundation,diesel generator bldg settlement & svc water bldg foundation & borated water tanks
SINGH,H N Army, Dept of, Corps of Engineers BX16 016
84/07/18 13pp 26510 319 24X Fiche 50-329,84/07/18,8408010061

--8408140152 Handwritten notes on admission of facts re plant fill problem & cracking of certain safety-related structures resulting from inadequately compacted fill matls W/ handwritten notes re discussion w/B Paton on hearings
* NRC - No Detailed Affiliation Given BX16 017 81/03/06 2pp 26510 331 24X Fiche 50-329,84/07/18,8408010061

--8408140158 Notifies of plan to take depositions of Bechtel employees in Ann Arbor beginning on 801209 Depositions will address errors made in soil placement
PATON,W D Office of the Executive Legal Director BX16 018 80/11/19 OLMSTEAD,W J Regulations Division 2pp 26510 333 24X Fiche 50-329,84/07/18,8408010061

--8408140163 Presents reasons why Phase II const will not be detrimental to foundation support of auxiliary bldg Phase II primary consists of 3x6 ft hand dug piers & 7x6 ft wide access drifts for access to pier
KANE,J , BARTLETT,D NRC - No Detailed Affiliation Given BX16 019 82/01/19 11pp 26510 335 24X Fiche 50-329,84/07/18, 8408010061

--8408140170 Handwritten notes re general description of extent of plant fill problem Proposed remedial measures, list of viewgraphs & viewgraphs for ACRS presentation encl
KANE,J NRC - No Detailed Affiliation Given BX16 020 82/04/26 37pp 26510 346 24X Fiche 50-329,84/07/18,8408010061

--8408140185 Confirms comments previously provided re Item E on Page 5 of 830715 ltr concerning slope layback during underpinning Item E expresses concern by S&W inspectors that slope layback is greater than in design
POULOS,S J Geotechnical Engineers, Inc BX16 022 83/09/22
KANE,J Office of Nuclear Reactor Regulation, Director 2pp 26511 029 24X Fiche 50-329,84/07/18,8408010061

--8408140196 Summarizes comments re 830914-15 audit of facility underpinning Purpose of audit was to gather info from applicant re effect on design & const of reducing modulus of hard clay foundation from 3000 Ksf to 5000 Ksf
POULOS,S J Geotechnical Engineers, Inc BX16 023 83/09/22
KANE,J Office of Nuclear Reactor Regulation, Director 3pp 26511 031 24X Fiche 50-329,84/07/18,8408010061

--8408140209 Handwritten notes re design details for borated water storage tanks & util position on cause of cracking
KANE,J NRC - No Detailed Affiliation Given BX16 024 81/07/28 2pp 26511 050 24X Fiche 50-329,84/07/18,8408010061

--8408140213 Handwritten summary of 810805 meeting in Ramada Central Inn re borated water storage tank W/810728 handwritten memo re status of review on borated water storage tank
KANE,J NRC - No Detailed Affiliation Given BX16 025 81/08/05
NRC - No Detailed Affiliation Given 2pp 26511 052 24X Fiche 50-329,84/07/18,8408010061

--8408140218 Handwritten notes re discussion w/G Gallagher about surcharging of valve pits near borated water tanks Record of telcon w/util,Bechtel & Geotechnical Engineering on 810715 re surcharging valve pits encl
* NRC - No Detailed Affiliation Given BX16 026 81/07/01 4pp 26511 054 24X Fiche 50-329,84/07/18,8408010061

--8408140223 Handwritten notes reviewing comments on borated water storage tanks & valve pit settlements
KANE,J NRC - No Detailed Affiliation Given BX16 027 81/07/28 1p 26511 074 24X Fiche 50-329,84/07/18,8408010061

--8408140232 Forwards draft comments on info received from applicant through Amend 85 to OL request & Rev 10 to 10CFR50 54(f) requests re borated water tanks Info received addresses all questions raised in 800707 ltr
MCCALLISTER,P Army, Dept of, Corps of Engineers BX16 028 81/03/26 JACKSON,R E NRC - No Detailed Affiliation Given 14pp 26511 075 24X Fiche 50-329,84/07/18,8408010061

--8408140242 Forwards branch position re seismological input parameters Position necessary to resolve differences between applicant & NRC on seismological issues & to provide guidance for inputing vibratory motion in evaluations
JACKSON,R E Geosciences Branch BX16 030 80/07/08
SCHWENCER,A Licensing Branch 3 6pp 26511 101 24X Fiche 50-329,84/07/18,8408010061

--8408140248 Urges studies evaluating soil liquefaction & stability under dynamic loading & using values of acceleration in range of 0 12g to 0 19g at ground surface Also forwards list of strong motion records
ROTHMAN,R L Geosciences Branch BX16 031 80/02/11
JACKSON,R E Geosciences Branch 9pp 26511 107 24X Fiche 50-329,84/07/18,8408010061

--8408140263 Motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sys founded in & on plant fill matl in hearing considering 791206 order
FARNELL,A S Consumers Power Co FARNELL,A S Isham, Lincoln & Beale BX16 034 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24X Fiche 50-329,84/07/18,8408010061

--8408140286 Testimony of H Singh re origin remedial measures proposed by applicant for auxiliary bldg & Corps of Engineers evaluation of remedial measures
SINGH,H NRC - No Detailed Affiliation Given BX16 0388 81/11/12 3pp 26511 242 24X Fiche 50-329,84/07/18,8408010061

--8408140296 Draft testimony of SJ Poulos re remedial underpinning of svc water pump structure
POULOS,S J Geotechnical Engineers, Inc BX16 040 82/03/30 11pp 26511 271 24X Fiche 50-329,84/07/18,8408010061

--8408140300 Testimony of HN Singh re svc water pump structure
SINGH,H N Geotechnical Engineers, Inc BX16 041 82/04/08 7pp 26511 282 24X Fiche 50-329,84/07/18,8408010061

--8408140319 Summary of 810917 meeting w/CPC,US Army Corps of Engineers, NRC,Bechtel & Mueser,Rutledge,Wentworth & Johnson in Bethesda,MD re preliminary design of proposed remedial measures for svc water pumping structure
SINGH,H N Army, Dept of, Corps of Engineers BX16 044 81/09/18 Army, Dept of, Corps of Engineers 3pp 26511 341 24X Fiche 50-329,84/07/18,8408010061

--8408140347 Summary of 820422 meeting w/CPC, consisting of answers to QES questions re permanent dewatering sys, soil stabilization, jacking procedure & draft SER
KANE,J NRC - No Detailed Affiliation Given BX16 046 82/06/25
NRC - No Detailed Affiliation Given 4pp 26511 348 24X Fiche 50-329,84/07/18,8408010061

--8408140392 "Dynamic Cone Penetrometer " Sketches & design calculations of underpinning & settlement analysis study encl
ANDERSON,J NRC - No Detailed Affiliation Given BX16 047 82/03/17 42pp 26512 056 24X Fiche 50-329,84/07/18,8408010061

--8408140359 Handwritten notes re settlement monitoring programs, classification of fines,instrumentation & agenda for 781204 meeting re diesel generator bldg
* NRC - No Detailed Affiliation Given BX16 049 84/07/18 10pp 26512 210 24X Fiche 50-329,84/07/18,8408010061

--8408140367 Draft ltr re Interagency Agreement NRC-03-76-167,Task 1, Subtask 3 concerning comment on Amend 85 List of specific discrepancies re settlement evaluations encl
SINGH,H Army, Dept of, Corps of Engineers BX16 051 81/02/26
KANE,J , JACKSON,R E NRC - No Detailed Affiliation Given 13pp 26512 221 24X Fiche 50-329,84/07/18,8408010061

--8408140513 Summary of R Landsman 810325-27 & 0407-09 insps conducted to verify QA program for util soil borings conducted in response to Corps of Engineers request for addl soil info
* NRC - No Detailed Affiliation Given BX16 054 84/07/18 4pp 26512 259 24X Fiche 50-329,84/07/18,8408010061

--8408140522 Informs that,in preparation for issuance of draft SER in mid-late Jan,section by section review of which sections of draft received by Div of Licensing to date complete
HERNAN,R W Licensing Branch 4 BX16 055A 82/01/12
ADENSAM,E G Licensing Branch 4 3pp 26512 269 24X Fiche 50-329,84/07/18,8408010061

--8408140526 Summarizes 810608 stipulation filed by util & NRC re QA aspects of hearing on soils settlement scheduled to begin 810707
HOOD,D Licensing Branch 4 BX16 056 81/06/08 DENTON,H , CARTER,J Office of Nuclear Reactor Regulation, Director
EISENHUT,D G Division of Licensing 1p 26512 272 24X Fiche 50-329,84/07/18,8408010061

--8408140530 Draft memo providing estimate for completing review & preparing testimony on proposed remedial actions,in response to QELD request for schedule for review
LEAR,J NRC - No Detailed Affiliation Given BX16 057 81/06/19
KNIGHT,J NRC - No Detailed Affiliation Given 3pp 26513 185 24X Fiche 50-329,84/07/18,8408010061

--8408140539 Requests estimate of time required to complete review & prepare testimony re proposed remedial actions Testimony by F Rinaldi,T Cappucci & J Kane needs to be filed by 810915
PATON,W D Office of the Executive Legal Director BX16 057A 81/07/18 KNIGHT,J P Assistant Director for Comp & Structures Engineering (Pre 830201) 1p 26513 188 24X Fiche 50-329,84/07/18,8408010061

--8408140553 Util news ltr re lifting of part of series of stop work orders that halted const of plant
* Consumers Power Co BX16 061 84/01/20 1p 26513 249 24X
Fiche 50-329,84/07/18,8408010061

--8408140556 Documents contacts by Kirkland & Ellis attys representing Dow Chemical in suit against CPC Summary of meeting by Geotechnical Engineering,Inc encl
KANE,J D Structural & Geotechnical Engineering Branch BX16 062
84/01/23 Structural & Geotechnical Engineering Branch 14pp
26513 263 24X Fiche 50-329,84/07/18,8408010061

--8408140557 Forwards comments re applicant submissions concerning cracks in diesel generator,fixation of cracks in borated water storage tanks,underpinnings & effects or cracks on serviceability of structures
MCCALLISTER,P Army, Dept of, Corps of Engineers BX16 063
82/06/15 LEAR,G Division of Engineering 14pp 26513 277
24X Fiche 50-329,84/07/18,8408010061

--8408140562 Handwritten document summarizing util response to NRC Questions 24,45 & 47 on permanent dewatering re geotechnical engineering issues Meeting summaries encl.
* Consumers Power Co BX16 064 81/10/12 32pp 26513 291
24X Fiche 50-329,84/07/18,8408010061

--8408140565 Handwritten document re liquefaction analysis
KANE,J C NRC - No Detailed Affiliation Given BX16 065
82/08/16 5pp 26513 323 24X Fiche 50-329,84/07/18,8408010061

--8408140566 Requests analysis of possible enforcement action re applicant failure to inform NRC of settlement of diesel generator bldg
PALLADINO,N NRC - No Detailed Affiliation Given. BX16 066
84/05/24 DIRCKS,W Office of the Executive Director for Operations 1p 26514 031. 24X Fiche 50-329,84/07/18,8408010061

--8408140570 "Administrative Bldg Foundation Settlements Along Column Line O 4 "
* Bechtel Corp BX16 068 77/12/31 21pp 26514 033. 24X
Fiche 50-329,84/07/18,8408010061

--8408140573 Forwards Bechtel rept, "Administrative Bldg Foundation Settlements Along Column Line O 4 "
BRUNNER,J E Consumers Power Co BX16 067 81/09/14 PATON,W
NRC - No Detailed Affiliation Given 1p 26514 032 24X
Fiche 50-329,84/07/18,8408010061

--8408140575 Handwritten summary of 781204 site meeting re excessive settlement of diesel generator bldg & foundations & other Category I structures
GALLAGHER,G Region 3, Office of Director BX16 069 78/12/07
HOOD,D NRC - No Detailed Affiliation Given 8pp 26514 068
24X Fiche 50-329,84/07/18,8408010061

--8408150015 Requests addl borings & existing soil data. Revised Encl 1 to 800327 ltr encl
MCCALLISTER,P. Army, Dept of, Corps of Engineers BX16 071
84/07/18 JACKSON,R E NRC - No Detailed Affiliation Given 6pp
26514.140 24X Fiche 50-329,84/07/18,8408010061

--8408150019 Handwritten notes re status of ASLB hearings First session, completed 810707-17; covered items re Stamiris Contention I, QA breakdown,NRC-util stipulation on QA managerial attitude & FSAR false statement
KANE,J NRC - No Detailed Affiliation Given BX16 072 81/08/18
11pp 26514 146 24X Fiche 50-329,84/07/18,8408010061.

--8408150022 Handwritten notes re location of sources of important util submittals prior to 791206 Topics outlined include auxiliary bldg,diesel generator bldg,borated water storage tank & permanent dewatering
KANE,J NRC - No Detailed Affiliation Given. BX16 073 81/05/18
31pp 26514 157 24X Fiche 50-329,84/07/18,8408010061

--8408150027 Summary of 840304 meeting w/util re schedules & topics for instant hearing on soils matters Hearing schedule resulting in inefficient reviews due to changing const priorities by applicant.
HOOD,D Licensing Branch 4, BX16 075 82/03/11 TEDESCO,R.L
Assistant Director for Licensing 43pp 26514 191 24X
Fiche 50-329,84/07/18,8408010061

--8408150029 Task Interface agreement re plant remedial soils issue
IPPOLITO,T Region 3, Office of Director. NORELIUS,C Director's Office, Office of Inspection and Enforcement VOLLMER,R Office of Nuclear Reactor Regulation, Director BX16 076 83/04/18
5pp 26514.234 24X Fiche 50-329,84/07/18,8408010061

--8408150033 Discusses 830929 conference call during which D Hood gave verbal approval to allow licensee to proceed w/underpinning through UATs
LANDSMAN,R B Region 3, Office of Director BX16 077 83/09/30
Region 3, Office of Director 1p 26514 241 24X
Fiche 50-329,84/07/18,8408010061

--8408150042 Handwritten notes commenting on Peck 810807 transcript re compaction criteria
KANE,J NRC - No Detailed Affiliation Given BX16 079 81/08/10
2pp 26514 264 24X Fiche 50-329,84/07/18,8408010061

--8408150046 Handwritten notes re electrical penetration area w/comments of H Singh on unresolved issues prior to 791206 & underground utils
SINGH,H NRC - No Detailed Affiliation Given BX16 080
81/05/20 2pp 26514 266 24X Fiche 50-329,84/07/18,8408010061

--8408150560 Comments on licensee draft commitments to improve implementation of quality program in remedial soils area & remaining const activities,per 820907 request Noted changes should be made in program
WARNICK,R F Region 3, Office of Director BX21 001 82/09/24
KEPPLER,J G Region 3, Office of Director 4pp 26549 080 24X
Fiche 50-329,84/07/18,8408010061

--8408150566 "Pier Load Test Data - Load by Carlson vs Load by Jacks " Related info encl
HUNT,S W Bechtel Corp BX21 003 83/04/29 200pp 26549 215
24X Fiche 50-329,84/07/18,8408010061

--8408150571 "Well OBS-4 Subsidence Rept "
HUNT,S W Bechtel Corp BX21 004 82/06/11 50pp 26550 120
24X Fiche 50-329,84/07/18,8408010061

--8408150577 Forwards recent audit repts by Midland QA dept,per request
BRUNNER,J E Consumers Power Co BX21 005 82/01/15
BECHHOEFER,C , HARBOUR,J Atomic Safety and Licensing Board Panel
COWAN,F P Affiliation Not Assigned 26pp 26550 222 24X
Fiche 50-329,84/07/18,8408010061

--8408150586 Forwards recent audit repts by Midland QA dept,per request Related info encl,including notes of CPC/NRC 830208 public meeting re const completion program
BRUNNER,J E Consumers Power Co BX21 006 82/02/05
BECHHOEFER,C , HARBOUR,J Atomic Safety and Licensing Board Panel
COWAN,F P Affiliation Not Assigned 106pp 26550 248 24X
Fiche 50-329,84/07/18,8408010061

--8408150595 Opposes issuance of fuel license (10CFR70) for applicant, based upon extensiveness of remedial soils work & potential for work to impact auxiliary bldg Related info encl
COOK,R J Region 3, Office of Director BX21 007 83/01/25
SHAFER,W D Region 3, Office of Director 19pp 26551 001 24X
Fiche 50-329,84/07/18,8408010061

--8408150608 Rev 4 to "Quality Plan for Underpinning Activities " Related info encl
BIRD,W , BOOS,A J , MOONEY,J Consumers Power Co BX21 009
82/10/12 59pp 26551 316 24X Fiche 50-329,84/07/18,8408010061

--8408150616 Enumerates QA issues to be addressed at evidentiary session in Midland proceeding,per encl 820707 memorandum & order W/o encl
PATON,W D Office of the Executive Legal Director BX21 011
82/08/10 ADENSAM,E G NRC - No Detailed Affiliation Given 2pp
26553 087. 24X Fiche 50-329,84/07/18,8408010061

--8408150617 Forwards further response to FOIA-84-96,consisting of records selected from files of Harrison & Norelius during 840628 visit
ROY,G W. Office of Resource Management, Director BX20 001
84/07/06 RICE,C M Kirkland & Ellis 3pp 26537 339 24X
Fiche 50-329,84/07/18,8408010061

--8408150624 Draft summary of NRC 840229 meeting w/util at Region III offi re results of NRC HVAC insps & investigation of allegations & expansion of QA training,qualification & certification activities Viewgraphs encl
* Region 3, Office of Director BX20 002 84/02/29 Region 3, Office of Director 21pp 26537 342 24X Fiche 50-329,84/07/18, 8408010061

--8408150626 Forwards NR Denton 831219 ltr distinguishing between terms "important to safety" & "safety-related " Related info encl
KEPPLER,J G Region 3, Office of Director BX21 013 83/12/29
Region 3, Office of Director 5pp 26553 163 24X
Fiche 50-329,84/07/18,8408010061

--8408150630 Forwards addl info re Region III inquiries into Ofc of Special Cases concerning Midland & Zimmer Nuclear Power Plant problems in implementing QA programs Nonconformance rept also encl
WARNICK,R F Region 3, Office of Director BX20 003 83/09/16
BOULDEN,H Office of Inspector & Auditor 18pp 26538 001 24X
Fiche 50-329,84/07/18,8408010061

--8408150633 Notifies that commercial operation date of Unit 2 may be delayed until mid-1986 Const schedule for Unit 1 will be revised based on cashflow requirements,need for power,final cost estimates & schedule for Unit 2
KOSCHIK,M G Consumers Power Co BX21 015 83/11/09 STRASMA,J Region 3, Office of Director 2pp 26553 216 24X
Fiche 50-329,84/07/18,8408010061

--8408150643 Forwards listed documentation in response to FOIA 83-397 for reproduction
WARNICK,R F Region 3, Office of Director BX20 006 83/07/20
SMIDTH,P T Region 3, Office of Director 1p 26538 156 24X
Fiche 50-329,84/07/18,8408010061

--8408150648 Draft summary of NRC Caseload Forecast Panel 830419-21 meeting w/util at plant site re basis for util revised estimates of Oct 1984 & Feb 1985 for Unit 2 & 1, respectively Rept on Rev 12 schedule encl
NOVAK,T M Assistant Director for Licensing BX20 007 83/05/25
COOK,J W Consumers Power Co 32pp 26538 157 24X
Fiche 50-329,84/07/18,8408010061

--8408150651 Requests NRC approval to postpone yellowbook update due to inadequate work experience enabling development of definitive project schedule,per 831014 ltr
GUAMME,D L Consumers Power Co BX20 008 84/01/12
HARTFIELD,R A Management Information Branch 1p 26539 002
24X Fiche 50-329,84/07/18,8408010061

--8408150652 Notifies of intent to continue const of plant following recent notification from Dow Chemical Co of decision to terminate agreement to purchase energy Related info encl
FITZPATRICK,R Consumers Power Co BX21 019 83/07/15
STRASMA,J Region 3, Office of Director 72pp 26554 061 24X
Fiche 50-329,84/07/18,8408010061

--8408150656 Responds to 840409 comments re util proposed plan to conduct independent mgt appraisal of Midland Nuclear Project Affidavits of independence of individuals working on audit encl.
REHM,T A Office of the Executive Director for Operations BX20 009 84/06/08 GARDE,B P Government Accountability Project
31pp 26539 014 24X Fiche 50-329,84/07/18,8408010061

--8408150662 Enumerates agreements/understandings reached at 820823 meeting w/NRC re approval for portions of Phase II underpinning work Related info encl
MILLER,D B Consumers Power Co BX21 021 82/08/25 SHAFER,W D Region 3, Office of Director 14pp 26554 241 24X
Fiche: 50-329,84/07/18,8408010061

--8408150665 Comments on util 840307 proposed independent mgt plan Plan does not indicate how Cresap,McCormick & Paget & TERA will function & interface Roles,authorities & responsibilities should be identified Handwritten comments encl
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement BX20 011 84/03/27 KEPPLER,J G Region 3, Office of Director 4pp 26539 052 24X Fiche 50-329,84/07/18, 8408010061

--8408150666 Summary of NRC 840314 meeting w/D Bridenbaugh of MAU Technical Assocs in Region III re info on Midland & Zimmer plants Util 840124 ltr to Atty General of State of MI encl
WARNICK,R F Region 3, Office of Director BX20 012 84/03/20
Region 3, Office of Director 7pp 26539 136 24X
Fiche 50-329,84/07/18,8408010061

--8408150676 Forwards util testimony on cable pulling incident Requests comments Lists questions to be addressed
WILCOVE,M N Office of the Executive Legal Director BX20 014
83/05/13 LANDSMAN,R , COOK,R , GARDNER,R NRC - No Detailed Affiliation Given 7pp 26539 306 24X Fiche 50-329,84/07/18, 8408010061

--8408150681 Discusses policy & procedure changes re communications w/ licensee Related info encl
WARNICK,R F Region 3, Office of Director BX21 027 82/09/17
SPESSARD,R L Division of Project & Resident Programs
NORELIUS,C E Division of Engineering HIND,J A Division of Radiological & Materials Safety Programs 8pp 26555 067 24X
Fiche. 50-329,84/07/18,8408010061

--8408150682 Advises that FOIA Request 82-616 received Matl requested must be submitted to director by 840103 Nonconformance repts & Interim Rept 3 re cable tray support const welding discrepancy encl
SMIDTH,P T Region 3, Office of Director BX20 015 82/12/22
Region 3, Office of Director 2pp 26539 359 24X
Fiche 50-329,84/07/18,8408010061

--8408150685 Discusses QA program re underpinning instrumentation installation Lists steps to follow to implement reclassification of underpinning activities
COOK,J W Consumers Power Co BX21 028 82/03/31 NORELIUS,C E Division of Engineering 2pp 26555 110 24X
Fiche 50-329,84/07/18,8408010061

--8408150686 Advises that allegations received from Dow Chemical & util are treated equally Forwards E Driker 840304 ltr re Dow Chemical vs CPC lawsuit
BERKOVITZ,D M Office of the General Counsel BX20 016
84/05/11 LEWIS,S H Region 3, Office of Director 1p
26540 094 24X Fiche 50-329,84/07/18,8408010061

--8408150689 Submits summary of views re regulatory status of plant Illegible handwritten notes encl
KEPPLER,J G Region 3, Office of Director BX20 016A 84/06/06
FISCHER,R Michigan, State of 12pp 26540 095 24X
Fiche 50-329,84/07/18,8408010061

--8408150692 Forwards newspaper stories indicating representives of Dow Chemical met w/NRC to discuss matters in litigation pending in County Circuit Court w/util JD Selby 840608 ltr to FJ Kelley encl
DRIKER,E Barris, Sott, Denn & Driker BX20 017 84/05/04
BERKOVITZ,D Office of the General Counsel 18pp 26540 160
24X Fiche 50-329,84/07/18,8408010061

--8408150695 "Site Visit to Evaluate Crack Reported 830218 in Roof of Feedwater Isolation Valve Pit Unit 1,Midland Nuclear Power Plant " Draft confirmatory orders,handwritten notes & RF Warnick memo re FOIA Request 84-24 encl
CORLEY,W G Construction Technology Laboratories BX20 019
83/02/28 11pp 26540 178 24X Fiche 50-329,84/07/18, 8408010061

--8408150700 Forwards draft confirmatory order prepared by IE re plan for independent appraisal of site & corporate mgt organizations Requests review prior to meeting
LIEBERMAN,S NRC - No Detailed Affiliation Given BX20 020
83/12/30 KEPPLER, WARNICK, HARRISON NRC - No Detailed Affiliation Given 10pp 26540 335 24X Fiche 50-329,84/07/18, 8408010061

--8408150706 Advises that S Lewis leaving Region III to assume position of Deputy Assistant Chief Hearing Counsel in OELD B Berson replacement Chronological list of reactor holddown bolt encl
KEPPLER,J G Region 3, Office of Director BX20 022 84/05/14
Region 3, Office of Director 12pp 26541 263 24X
Fiche 50-329,84/07/18,8408010061

--8408150709 Summary of 800523 meeting w/util,B&W,Bechtel & Teledyne in Bethesda,MD re preservice failure of three reactor vessel holddown studs List of attendees,agenda & viewgraph slides encl Sketches for underpinning auxiliary bldg encl
HOOD,D B Licensing Branch 3 BX20 023 80/07/07 Licensing Branch 3 82pp 26541 328 24X Fiche 50-329,84/07/18,8408010061

--8408150710 Assessment rept QA program,performed during Mar & Apr 1981
* Management Analysis Co BX21 033 81/06/01 400pp
26555 182 24X Fiche 50-329,84/07/18,8408010061

--8408150712 "Quality Program for Underpinning Activities "
* Consumers Power Co. BX20 024A 82/04/05 22pp 26542 132
24X Fiche 50-329,84/07/18,8408010061

--8408150714 "Independent Assessment of Underpinning 90-Day Rept "
KILBER,W E Stone & Webster, Inc BX21 034 83/04/30 250pp
26556 194 24X Fiche 50-329,84/07/18,8408010061

--8408150716 "Test Program Status & Rev 12 - Test Schedule "
* Consumers Power Co BX21 035 83/04/12 100pp 26557 091
24X Fiche 50-329,84/07/18,8408010061

--8408150718 Documents conclusions & commitments made at 820330 meeting & 820402 telcons re QA applied to remedial foundation work Expansion of QA program recognized in overall success of project "Quality Program for Underpinning Activities" encl
COOK,J W Consumers Power Co BX20 024B 82/04/05 KEPPLER,J G Region 3, Office of Director 4pp 26542 154. 24X
Fiche 50-329,84/07/18,8408010061

--8408150720 "Electrical Raceway Support Tests Rept Part 1 "
NOWAK,A S Bechtel Corp BX21 036 81/11/25 100pp 26557 192
24X Fiche 50-329,84/07/18,8408010061

--8408150723 Forwards CPC testimony on alleged violation of Board order Investigation of violation coming in Future Requests analysis of testimony & comments Handwritten notes encl
WILCOVE,M N Office of the Executive Legal Director BX20 026
83/05/13 LANDSMAN,R , COOK,R , HOOD,D NRC - No Detailed Affiliation Given 99pp 26542 165 24X Fiche 50-329,84/07/18,8408010061

--8408150725 Requests review of attached draft SALP rept in preparation for 830706 SALP Board meeting
WARNICK,R F Region 3, Office of Director BX20 027 83/07/01
HIND,J A , NORELIUS,C E , SPESSARD,R L NRC - No Detailed Affiliation Given 149pp 26542 288 24X Fiche 50-329,84/07/18,8408010061

--8408150727 Summarizes 830227-28 meeting at site re soils settlement issue & effects Handwritten note encl
GALLAGHER,E Region 3, Chicago, Office of the Director BX20 034
83/03/03 FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 46pp 26544 306 24X
Fiche 50-329,84/07/18,8408010061

--8408150728 Forwards advance copy of proposed rev to Manual Chapter 0516, SALP, for review
NORELIUS,C E Division of Project & Resident Programs BX20 035
84/04/13 Region 3, Office of Director 2pp 26545 069 24X
Fiche 50-329,84/07/18,8408010061

--8408150729 Advises of problems concurring w/proposed response to M Cherry 770427 ltr as noted by detailed comments provided Requests redraft be considered
REINMUTH,G W Division of Reactor Construction Inspection BX20
029 77/06/10 HOEFLING,R K Office of the Executive Legal Director 7pp 26543 234 24X Fiche 50-329,84/07/18,8408010061

--8408150731 Advises of possible ex parte contact in facility proceeding Requests memo & attached summary of discussion be served to all parties in proceeding & PDR
GIBSON,T R NRC - No Detailed Affiliation Given BX20 030
80/12/24 CHILK,S J Office of the Secretary of the Commission
2pp 26543 250 24X Fiche 50-329,84/07/18,8408010061

--8408150732 Notifies that incorrect target dates entered in 830219 SALP schedule Correct target dates provided
NORELIUS,C E Division of Project & Resident Programs BX20 035A
84/03/08 HIND,J A Division of Radiological & Materials Safety Programs SPESSARD,R L Division of Engineering DOUGHERTY,D J Office of Resource Management, Director 2pp 26545 117 24X
Fiche 50-329,84/07/18,8408010061

--8408150734 Revises previously issued SALP 4 schedule dtd 831004, by extending assessment to 18 months Rev incorporates addl milestone dates
NORELIUS,C E Division of Project & Resident Programs BX20 035B
83/12/19 Region 3, Office of Director 2pp 26545 119 24X
Fiche 50-329,84/07/18,8408010061

--8408150735 Requests concurrence on proposed auxiliary bldg guideline, "Guidelines for Bldg Movements During Temporary Underpinning " Handwritten notes & communications record w/Warnick re withdrawal of potential 10CFR50 55(e) encl
MOONEY,J A Consumers Power Co BX20 031 84/05/25
HARRISON,J J Region 3, Office of Director 25pp 26543 252
24X Fiche 50-329,84/07/18,8408010061

-8408150737 Forwards NRC Manual Chapter 0516,SALP Evaluation criteria published in FR on 820322 for public comments Comments due by 820701
TAMBLING,T N Region 3, Office of Director BX20 035C 82/05/04
AXELSON,W L , BARRETT,P A , BOYD,D C NRC - No Detailed Affiliation Given 3pp 26545 123 24X Fiche 50-329,84/07/18,8408010061

3408150738 Forwards summary of 840229 meeting in Region III ofc re results of HVAC insps & investigation of allegations & expansion of training,qualification & certification activities Handwritten notes encl
WELLS,R A Consumers Power Co BX20 032 84/03/29
HARRISON,J J Region 3, Office of Director 169pp 26544 014
24X Fiche 50-329,84/07/18,8408010061

108150740 "Chapter 0516 SALP," describing basis structure & overall procedures for implementation of NRC program to assess licensee performance MA Miller marked-up memo re evaluation of SALP encl
* Director's Office, Office of Inspection and Enforcement BX20
0350 82/03/23 47pp 26545 126 24X Fiche 50-329,84/07/18,
8408010061

--8408150741 Forwards "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking "
LEVIN,H A TERA Corp BX20 033 83/01/04 KEPPLER,J G ,
EISENHUT,D G Region 3, Office of Director COOK,J W Consumers Power Co 4pp 26544 212 24X Fiche 50-329,84/07/18,8408010061

--8408150743 Submits reasons for extending SALP III evaluation period to 821231 Rept contains issues being resolved between NRC & licensee Extension can be used as performance motivator Handwritten note & supporting documentation encl
COOK,R J Region 3, Office of Director BX20 036 82/08/06
SPESSARD,R L Division of Project & Resident Programs 350pp
26545 173 24X Fiche 50-329,84/07/18,8408010061

--8408150745 "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking " Handwritten notes encl
* TERA Corp BX20 033A 83/01/04 89pp 26544 216 24X
Fiche 50-329,84/07/18,8408010061

--8408150747 Submits supplemental SALP input for facility Changes required to provide overall Div of Engineering & Technical Insp rating for QA functional area & consolidate comments for recommended increased insp frequency
PIRTLE,G Region 3, Office of Director BX20 037 83/10/01
BOYD,D Region 3, Office of Director 1p 26547 011 24X
Fiche 50-329,84/07/18,8408010061

--8408150749 Forwards list of items reviewed by util & determined ready for review & closure by NRC Handwritten notes & supporting documentation encl
WELLS,R A Consumers Power Co BX20 038A 83/10/04
KEPPLER,J G Region 3, Office of Director 147pp 26547 165
24X Fiche 50-329,84/07/18,8408010061

--8408150750 Forwards SALP input except for Matls & Processes Section
PIRTLE,G Division of Engineering & Technical Inspection BX20
038 81/09/22 BOYD,D Division of Engineering & Technical Inspection 137pp 26547 012 24X Fiche 50-329,84/07/18,
8408010061

--8408150791 Forwards const status rept as of 791001 Handwritten notes re diesel generator bldg & soil settlement & errata to NUREG-0834 encl
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch BX20 041A 79/10/05 KNOP,R C , HAYES,D W ,
DANIELSON,D H NRC - No Detailed Affiliation Given 107pp
26548 359 24X Fiche 50-329,84/07/18,8408010061

--8408150752 Submits QA issues to be addressed at evidentiary session in facility proceeding Summary rept & oral communications record re reinsp requirements based on results of certification testing encl
PATON,W D NRC - No Detailed Affiliation Given BX20 041
82/08/10 ADENSAM,E G NRC - No Detailed Affiliation Given
18pp 26548 075 24X Fiche 50-329,84/07/18,8408010061

--8408170081 "Response to NRC Staff Review Concerns for Underpinning of Auxiliary Bldg "
* Consumers Power Co BX19 001 82/06/03 40pp 26529 122
24X Fiche 50-329,84/07/18,8408010061

--8408170102 Forwards addl documents re facility soils issue, in response to request for info
DREHOBL,K E Consumers Power Co BX19 003 82/04/12
FISCHER,D C ACRS - Advisory Committee on Reactor Safeguards
7pp 26530 009 24X Fiche 50-329,84/07/18,8408010061

--8408170141 Requests review of files to determine documents withholdable under FOIA, per FOIA-84-96
LEWIS,S H NRC - No Detailed Affiliation Given BX19 009
84/05/08 HARRISON,J J , GARDNER,R , LANDSMAN,R NRC - No Detailed Affiliation Given 1p 26530 066 24X
Fiche 50-329,84/07/18,8408010061

--8408170145 Forwards draft ltr to util re review of licensee 830310,0621 & 0712 responses to 830208 & 0523 notice of violation & proposed imposition of civil penalty Recommends imposition of $120,000 civil penalty
SCHULTZ,W H Region 3, Office of Director BX19 010 83/07/28
AXELRAD,J A Director's Office, Office of Inspection and Enforcement 165pp 26530 067 24X Fiche 50-329,84/07/18,
8408010061

--8408170166 Testimony of RN Gardner re allegations concerning qualification of personnel employed by Camstock
GARDNER,R N Region 3, Office of Director BX19 012A 84/07/18
100pp 26530 321 24X Fiche 50-329,84/07/18,8408010061

--8408170187 Forwards rept results re special electrical overinsp requested by NRC to support testimony concerning adequacy of certification/qualification process of Bechtel electrical QC inspectors
SHAEFFER,M J Consumers Power Co BX19 015 82/02/25 COOKE,R NRC - No Detailed Affiliation Given BIRD,W R , COOK,J W Consumers Power Co 14pp 26531 048 24X Fiche 50-329,84/07/18, 8408010061

--8408170195 Draft "Rept on Cable Installation "
* Consumers Power Co BX19 014 82/05/14 111pp 26531 038 24X Fiche 50-329,84/07/18,8408010061

--8408170253 Discusses W Marshal telcon re permanent dewatering well being drilled at northeast corner of diesel generator bldg on 820519 Drilling mud flushed into line when drilling line broke No further comment necessary
LANDSMAN,R B Region 3, Office of Director BX19 031 82/06/14 PATON,W Office of the Executive Legal Director 2pp 26533 325 24X Fiche 50-329,84/07/18,8408010061

--8408170257 Summary of ACRS Subcommittee on Midland Units 1 & 2 820520 & 21 meetings w/util in Midland,MI re review of OL application
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards BX19 032 82/08/09 OKRENT,D ACRS - Advisory Committee on Reactor Safeguards 13pp 26533 359 24X Fiche 50-329,84/07/18, 8408010061

--8408170260 Informs of review of encl allegations re Comstock QC at site Ofc of Investigations responsible for continuing investigation
WARNICK,R F Region 3, Office of Director BX19 033 82/11/16 FOSTER,J E Office of Investigation 125pp 26534 010 24X Fiche 50-329,84/07/18,8408010061

--8408170279 "Structural Stresses Induced by Differential Settlement of Diesel Generator Bldg "
* Consumers Power Co BX19 037 84/07/18 51pp 26535 255 24X Fiche 50-329,84/07/18,8408010061

--8408170284 Summary of 810902-04 meeting w/util & Bechtel in Bethesda,MD re remedial actions & update of soils deficiencies & to review Amend 85 to application
LANDSMAN,R B Region 3, Office of Director BX19 039 81/05/12 WILLIAMS,C C Region 3, Office of Director 65pp 26536 043 24X Fiche 50-329,84/07/18,8408010061

--8408170320 Summary of 840202-05 meeting w/util,Bechtel & consultants in Ann Arbor,MI re discussion & audit of preparations for underpinning southern part of auxiliary bldg Viewgraphs encl
HOOD,D Licensing Branch 4 BX19 045 84/02/22 Licensing Branch 4 81pp 26536 189 24X Fiche 50-329,84/07/18,8408010061

--8408170358 S&W 840209 public meeting re cracking criteria & cracking mapping program
* Consumers Power Co BX19 046 84/02/09 Consumers Power Co 2pp 26536 349 24X Fiche 50-329,84/07/18,8408010061

--8408170360 Submits list of documents supplied or withheld by JJ Harrison & RB Landsman, in response to FOIA Request 84-24
WARNICK,R F Region 3, Office of Director BX19 047 84/01/18 SMITH,P T Region 3, Office of Director 2pp 26536 351 24X Fiche 50-329,84/07/18,8408010061

--8408170365 Handwritten summary of 840104 public meeting w/util,S&W Bechtel re monthly activities,crack rept,crack mapping & open items Supporting documentation & attendance list encl
* Consumers Power Co BX19 048 84/01/13 Consumers Power Co 74pp 26536 356 24X Fiche 50-329,84/07/18,8408010061

--8408170367 Crack mapping monitoring status rept for 831031-1130, including handwritten status rept of 831208 S&W meeting & info re grillage acceptance criteria
* Consumers Power Co BX19 049 84/08/01 10pp 26537 107 24X Fiche 50-329,84/07/18,8408010061

--8408170372 Handuritten summary of 831110 public meeting Re tracking open items of new crack monitoring procedures 831009-1105
* Consumers Power Co BX19 050 83/11/10 Consumers Power Co 3pp 26537 129 24X Fiche 50-329,84/07/18,8408010061

--8408170377 Handuritten notes re auxiliary bldg & underpinning design including settlement stress,results of areas of max stress & rigid body rotation
* Consumers Power Co BX19 053 84/08/01 76pp 26537 253 24X Fiche 50-329,84/07/18,8408010061

--8408210367 Agenda for 780502 site visit w/util Bechtel & NUS Agenda for 781204 meeting w/util & Bechtel on site encl
* NRC - No Detailed Affiliation Given BX18 001 78/05/02 NRC - No Detailed Affiliation Given 6pp 26521 049 24X Fiche 50-329,84/07/18,8408010061

--8408210377 Notification of 780907 meeting w/Midland Technical Reviewers in Washington,DC to discuss project status of facility safety review Reviewers will be asked to summarize review status on problem areas affecting review schedule
HOOD,D Light Water Reactors Branch 4 BX18 003 78/09/06 NRC - No Detailed Affiliation Given 7pp 26521 091 24X Fiche 50-329,84/07/18,8408010061

--8408210379 Provides info in response to B Garde FOIAs 83-451,-452,-454 & -449
HOOD,D Licensing Branch 4 BX18 023 83/08/19 WILSON,V NRC - No Detailed Affiliation Given 2pp 26524 336 24X Fiche 50-329,84/07/18,8408010061

--8408210384 Notification of rescheduled 790718 meeting w/util & Bechtel in Bethesda,MD to discuss abnormal settlement of Fill & structures at site Agenda & attendance list encl
HOOD,D Light Water Reactors Branch 4 BX18 004 79/06/13 VARGA,S A Light Water Reactors Branch 4 7pp 26521 100 24X Fiche 50-329,84/07/18,8408010061

--8408210386 Forwards B Garde FOIA request for documents re meetings between NRC, TERA & util on 830518,0608 & 23 concerning independent design verification W/draft ltr to util re implementation of Ford Amend
WILSON,V H Management Analysis Branch BX18 024 83/08/09 Management Analysis Branch 2pp 26524 338 24X Fiche 50-329,84/07/18,8408010061

--8408210392 Forwards B Garde FOIA 83-452 request for documents re 830615 Commission briefing
WILSON,V H Management Analysis Branch BX18 025 83/08/09 Management Analysis Branch 2pp 26524 354 24X Fiche 50-329,84/07/18,8408010061

--8408210397 Forwards B Garde FOIA 83-454 request for documents re re-review of structural adequacy of diesel generator bldg
WILSON,V H Management Analysis Branch BX18 026 83/08/10 LEAR,G Hydrologic & Geotechnical Engineering Branch BOSNAK,R Mechanical Engineering Branch 2pp 26524 358 24X Fiche 50-329,84/07/18,8408010061

--8408210401 Forwards B Garde FOIA Request 83-449 for documents submitted by util re consideration of candidate companies or methodologies to perform const implementation overview of const completion plan
WILSON,V H Management Analysis Branch BX18 027 84/08/09 Management Analysis Branch 2pp 26525 001 24X Fiche 50-329,84/07/18,8408010061

--8408210404 Determines that info transmitted by 830721 memo should be issued as Board Notification 83-106
EISENHUT,D G Division of Licensing BX18 028 84/07/18 NOVAK,T Assistant Director for Licensing 1p 26525 152 24X Fiche 50-329,84/07/18,8408010061

--8408210410 Board Notification 83-016 forwards notice of violation & proposed imposition of civil penalties,based on util failure to implement adequate QA program for installation of electrical,mechanical & civil components
NOVAK,T M Division of Licensing BX18 029 84/02/15 Atomic Safety and Licensing Board Panel 1p 26525 160 24X Fiche 50-329,84/07/18,8408010061

--8408210411 Handwritten questions for RB Peck re consultant responsibilities & settlement monitoring Handwritten deposition of RB Beck encl
* NRC - No Detailed Affiliation Given BX18 008 81/01/31 NRC - No Detailed Affiliation Given 36pp 26521 228 24X Fiche 50-329,84/07/18,8408010061

--8408210414 Forwards Board Notification 83-16 which supersedes 830215 notification.
NOVAK,T M NRC - No Detailed Affiliation Given BX18 030 84/02/18 Atomic Safety and Licensing Board Panel 1p 26525.184 24X Fiche 50-329,84/07/18,8408010061

--8408210418 Submits package received from B Jones from H Singh, consisting of questions of Dr Peck by H Singh,J Dunnicliff 800208 ltr to S Afifi & summary of J Kane deposition
SINGH,H NRC - No Detailed Affiliation Given BX18 009 84/07/18 JONES,B NRC - No Detailed Affiliation Given 36pp 26521 269 24X Fiche 50-329,84/07/18,8408010061

--8408210421 "Questions for Davisson 810114-15 Deposition " Questions of Dr Peck on testimony, dtd 810725 encl
* NRC - No Detailed Affiliation Given BX18 010 81/01/11
34pp 26521 305 24X Fiche 50-329, 84/07/18, 8408010061

--8408210425 "Questions for Davisson 810114-15 Deposition "
* NRC - No Detailed Affiliation Given BX18 011 81/01/11
43pp 26522 070 24X Fiche 50-329, 84/07/18, 8408010061

--8408210430 Draft memo informing of status of NRC-03-79-16T, Task 1, Subtask 3 Index of Davisson deposition encl
SINGH, H NRC - No Detailed Affiliation Given BX18 012
80/10/16 LEAR, G Hydrologic & Geotechnical Engineering Branch
17pp 26522-116 24X Fiche 50-329, 84/07/18, 8408010061

--8408210433 Recommends issuance of encl matl as Board Notification 84-083 re update on stop work status & NRC staffing changes Related info encl
EISENHUT, D G Division of Licensing BX18 016 84/04/18
NOVAK, T Division of Licensing 2pp 26522 350 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210446 Summary of 820202-05 meeting w/util & Bechtel in Ann Arbor, MI re audit preparations for underpinning southern portion of auxiliary bldg Bechtel meeting notes & viewgraphs encl
HOOD, D Licensing Branch 4 BX18 019 84/02/22 Licensing Branch 4 79pp 26523 232 24X Fiche 50-329, 84/07/18, 8408010061

--8408210450 Determines that encl rept on review of diesel generator bldg should be issued as Board Notification 83-165
EISENHUT, D G Division of Licensing BX18 020 83/10/28
NOVAK, T Assistant Director for Licensing. 4pp 26524 302 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210453 "Observed Settlements (Inches) of Structures, 790930 to Present " Summary of soil properties & summary of soils info encl
WANZEC, T NRC - No Detailed Affiliation Given BX18 037
80/08/27 10pp 26527 199 24X Fiche 50-329, 84/07/18, 8408010061

--8408210455 Agenda for 800930 meeting w/util on site for appeal of NRC position
* NRC - No Detailed Affiliation Given BX18 038 84/07/18
NRC - No Detailed Affiliation Given 1p 26527 209 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210461 Trip rept of 831005-07 site visit re design review & audit of HVAC sys
TERAO, D Mechanical Engineering Branch BX18 052 83/10/28
BOSNAK, R J Mechanical Engineering Branch 17pp 26528 234 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210463 Draft notes recommending that listed actions be considered by Region III in effort to improve licensee regulatory attitude & performance & increase assurance that completed & ongoing const work acceptable
* NRC - No Detailed Affiliation Given BX18 046 82/08/06 4pp 26528 034 24X Fiche 50-329, 84/07/18, 8408010061.

--8408220070 Delineates Control Sys Branch position on identification of protection sys instrument sensing lines & requests position be transmitted to near-term OL applicants
SPEIS, T P. Assistant Director for Reactor Safety BX19 025
84/07/18 TEDESCO, R L Assistant Director for Licensing 3pp
26533 051 24X Fiche 50-329, 84/07/18, 8408010061

--8408220085 Attendance list of 820223 meeting w/util, chronological list events before & after issuance of NRC order modifying CPs, plant underpinning questions re svc water pump structure & review of 1981 technical rept on underpinning
* NRC - No Detailed Affiliation Given BX19 036A 82/02/23
38pp 26534 327. 24X Fiche 50-329, 84/07/18, 8408010061

--8408220090 "Observed Cracks in Walls of Midland Plant Structures "
CORLEY, W G , FIORATO, A E Portland Cement Association BX19 031A
82/06/14 32pp. 26533 327 24X Fiche 50-329, 84/07/18, 8408010061

-8408270315 Draft ltr informing of decision re addl soil borings & testing NRC request for sampling & testing cooling pond embankments reconsidered & relocation of certain borings determined
VOLLMER, R H. Division of Engineering BX18 010A 80/11/03
COOK, J W Consumers Power Co 1p 26522 022 24X
Fiche 50-329, 84/07/18, 8408010061

-8408270323 Submits listed items that inspectors consider to be indicative of questionable licensee performance
COOK, R J Region 3, Office of Director BX19 019 82/07/23
WARNICK, R F Region 3, Office of Director. 11pp 26531-291 24X
Fiche 50-329, 84/07/18, 8408010061.

8408140311 Summary of 810917 meeting w/CPC re preliminary design of mods to svc water pump structure to resolve concerns resulting from inadequate compaction of site fill
KANE, J NRC - No Detailed Affiliation Given BX16 043 81/10/30
NRC - No Detailed Affiliation Given 2pp 26511 339 24X
Fiche 50-329, 84/07/18, 8408060061

8408020014 Advises that util Board of Directors ordered shutdown of design const & testing activities for facilities on 840716 CP & OL applications for both units will be maintained Issuance of SSER 4 (NUREG-0793) requested
COOK, J W Consumers Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 25883 116 24X
Fiche 50-329, 84/07/27, 8408020014

8408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI, P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24X Fiche 50-000, 84/07/27, 8408080288

8408070173 Responds to 840726 request for authorization to complete soils shutdown activities Util authorized to proceed w/activities listed in 840726 ltr
HARRISON, J J Region 3, Office of Director 84/07/31 MOONEY, J A Consumers Power Co 2pp 25949 343 24X Fiche 50-329, 84/07/31, 8408070173

--8408070180 Requests authorization to complete proposed listed soils shutdown activities Updates of stop work activities will be provided to Region III
MOONEY, J A Consumers Power Co 84/07/26 HARRISON, J J Region 3, Office of Director. 4pp 25949 345 24X Fiche 50-329, 84/07/31, 8408070173

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408130399 Finalizes limits for control of movements of control tower & electrical penetration areas during soils shutdown activities, based on review of latest settlement data obtained during 840801-03 site visit List of limits encl
HARRISON, J J Region 3, Office of Director 84/08/08 MOONEY, J A Consumers Power Co 3pp 26010 185 24X Fiche 50-329, 84/08/08, 8408130399

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408270239 Confirms 840824 meeting w/util in Glenn Ellyn, IL to discuss plans for facilities
WARNICK, R F Region 3, Office of Director 84/08/22 COOK, J W Consumers Power Co 1p 26239 156 24X Fiche 50-329, 84/08/22, 8408270239

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records BX14 000 84/07/18
RICE, C M Kirkland & Ellis 2pp 26500 001 24X
Fiche: 50-329, 84/07/18, 8408010061

--8209230536 Forwards discussion of deficiencies noted in Supplemental SER 2 Requests mod to attached draft be provided addressing concerns
NOVAK, T M Assistant Director for Licensing BX18 040 82/08/27
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 3pp 26527 243 24X Fiche 50-329, 84/07/18, 8408010061

--8408150612 Draft final SSER re geotechnical engineering Related info encl
KANE, J D Hydrologic & Geotechnical Engineering Branch BX21 010
82/08/12 78pp 26553 002 24X Fiche 50-329, 84/07/18, 8408010061

--8408210454 Submits marked-up ltr re program for plant soils remedial work, in response to draft SER open items
COOK, J W Consumers Power Co BX18 047 82/09/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 47pp 2652B 039 24X Fiche 50-329, 84/07/18, 8408010061

8408020014 Advises that util Board of Directors ordered shutdown of design const & testing activities for facilities on 840716 CP & OL applications for both units will be maintained Issuance of SSER 4 (NUREG-0793) requested
COOK, J W Consumers Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 25883 116 24X Fiche 50-329, 84/07/27, 8408020014

F Security, medical, emergency & fire protection plans

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records BX14 000 84/07/18 RICE, C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329, 84/07/18, 8408010061

--8408170268 Discusses 830922 off-the-record meeting w/Bechtel employee re allegations concerning inadequacy of plant fire detection sys Concerns raised re copyright laws concerning App R to 10CFR50
BURGESS, B L Region 3, Office of Director BX19 034 83/09/26 ROY, G W Region 3, Office of Director 39pp 26534 246 24X Fiche 50-329, 84/07/18, 8408010061

G Adjudicatory correspondence

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records BX14 000 84/07/18 RICE, C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329, 84/07/18, 8408010061

--8010160005 Submits questions in response to request for interrogatory input re hearing
LEAR, G E Hydrologic & Geotechnical Engineering Branch BX17 013 80/10/06 MIRAGLIA, F Licensing Branch 3 2pp 26518 144 24X Fiche 50-329, 84/07/18, 8408010061

--8104230479 Submits comments on applicant response to NRC Interrogatories 1-3 No results available for review of Interrogatories 1 & 2 since no consolidation tests on samples were obtained from surcharged area of plant fill
MCCALLISTER, P Army, Dept of, Corps of Engineers BX17 014 81/03/27 LEAR, G Hydrologic & Geotechnical Engineering Branch 2pp 26518 150 24X Fiche 50-329, 84/07/18, 8408010061

--8210270126 Forwards input for testimony for 821027-1104 ASLB hearings Stamiris Contention 4 C b re dewatering & svc water pump structure should be addressed by Structural Engineering Branch
LEAR, G Hydrologic & Geotechnical Engineering Branch. BX17 018 82/10/15 ADENSAM, E Licensing Branch 4 4pp 26519 005 24X Fiche: 50-329, 84/07/18, 8408010061

--8211030222 Forwards Hydrdological & Geotechnical Engineering Branch input for testimony at ASLB 821027-1104 hearings re bearing capacity beneath diesel generator bldg, piping svc water pump structure & permanent dewatering
LEAR, G. Hydrologic & Geotechnical Engineering Branch BX17 017 82/10/14 ADENSAM, E G Licensing Branch 4 9pp 26518 358 24X Fiche. 50-329, 84/07/18, 8408010061

--8301190487 Assigns NRC sponsors for each of M Sinclair rewritten contentions for OL hearing Schedule for filing of testimony forthcoming
HOOD, D S Licensing Branch 4 BX17 024 83/01/14 NOVAK, T M Assistant Director for Licensing 1p 26519 072 24X Fiche: 50-329, 84/07/18, 8408010061

--8309270346 Responds to 830523 & 0810 requests for assistance in reviewing util proposed findings of fact & conclusions of law on remedial soils issues Agrees w/findings. Recommends paragraph re occurence of liquefaction be revised
BALLARD, R L Environmental & Hydrologic Engineering Branch. BX17 037 83/09/14 PATON, W D Office of the Executive Legal Director 2pp 26520 062 24X Fiche 50-329, 84/07/18, 8408010061

--8309270518 Forwards comments on util proposed findings of fact & conclusions of law on remedial soils issues
JACKSON, R E. Geosciences Branch BX17 038 83/09/21 PATON, W D. Hearing Branch 2 5pp 26520 064. 24X Fiche 50-329, 84/07/18, 8408010061

--8310050136 Discusses structural engineering review of "Applicants Proposed Findings of Facts & Conclusions of Law on Remedial Soil Issues" along w/related info on seismic models & borated water storage tanks resulting from ASLB hearings
LEAR, G Structural & Geotechnical Engineering Branch BX17 035 83/09/22 PATON, W Office of the Executive Legal Director 5pp 26520 051 24X Fiche 50-329, 84/07/18, 8408010061

--8310070101 Forwards comments on applicant proposed findings of fact & conclusions of law on remedial soil issues
LEAR, G Structural & Geotechnical Engineering Branch BX17 035A 83/09/29 PATON, W Office of the Executive Legal Director 4pp 26520 052 24X Fiche 50-329, 84/07/18, 8408010061

--8310240291 Informs that structural review of document "Applicant Proposed Findings of Facts & Conclusions of Law on Remedial Soil Issues," completed Structures adequate Comments encl
LEAR, G Structural & Geotechnical Engineering Branch BX17 036 83/10/14 PATON, W Office of the Executive Legal Director 5pp 26520 056 24X Fiche 50-329, 84/07/18, 8408010061

--8408020071 Forwards draft answers to util interrogatories re definition of acceptance criteria of 791206 order on mod Opinion as to whether items in brackets should be deleted requested
KANE, J NRC - No Detailed Affiliation Given BX17 006 81/02/24 HOOD, D NRC - No Detailed Affiliation Given 1p 26515 058 24X Fiche 50-329, 84/07/18, 8408010061

--8408020074 Draft answers to util interrogatories re definition of acceptance criteria on Page 3 of 791206 order on mod
* NRC - No Detailed Affiliation Given BX17 006A 84/07/18 Consumers Power Co 87pp 26515 059 24X Fiche 50-329, 84/07/18, 8408010061

--8408020086 Marked-up copy of Rev 1, Vol 4 to FSAR re stability of subsurface matls & foundations, questions re response to Interrogatories 13-16 & interpretations of intent of Interogatory 13
KANE, J NRC - No Detailed Affiliation Given BX17 009 77/11/30 12pp 26517 302 24X Fiche 50-329, 84/07/18, 8408010061

--8408030107 Forwards motions, 1980 audit repts & input re upcoming util QA decision Applicant acceptance of poor quality performance by Bechtel criticized
STAMIRIS, E Stamiris, E BX17 011. 81/05/26 KEPPLER, J G Region 3, Office of Director 2pp 26518 132 24X Fiche 50-329, 84/07/18, 8408010061

--8408020127 Summary of NRC recommendations of ASLB position re Stamiris Contention 2 including draft ASLB proposed findings & input into NRC testimony re Peck 790810 statement on electrical penetration area structures
KANE, J NRC - No Detailed Affiliation Given BX17 016 81/10/19 91pp 26518 268 24X Fiche 50-329, 84/07/18, 8408010061

--8408020171 Summarizes issues to be covered at ASLB 830214-18 hearing, including Stamiris contentions, Warren contention & seismic shakedown for all structures other than diesel generator bldg
* NRC - No Detailed Affiliation Given. BX17 019 83/01/05 9pp 26519 009 24X Fiche 50-329, 84/07/18, 8408010061

--8408020177 Suggests schedule for testimony to answer Warren Contentions 1-3, Stamiris Contention 4, Sinclair Contention 24 & Marhsall Contention 2 in Feb & Mar hearings. Text of contentions encl Suggests inclusion of rebuttals to contentions
BLUME, M NRC - No Detailed Affiliation Given BX17 020 82/01/27 HOOD, D , KANE, J , RINALDI, F NRC - No Detailed Affiliation Given. 7pp 26519 020. 24X Fiche: 50-329, 84/07/18, 8408010061

--8408020180 Forwards input to staff testimony in preparation for ASLB 821115-23 hearings, in response to W Paton verbal request & M Wilcove request Structural Engineering Branch input applicable only to svc water pump structure
SCHAUER, F. P. Structural Engineering Branch BX17 022 82/10/22 ADENSAM, E G Licensing Branch 4 5pp. 26519 050 24X Fiche: 50-329, 84/07/18, 8408010061

--8408020181 Comments on applicant 840805 proposed findings of fact conclusions of law on remedial soils issues, including items re auxiliary bldg & svc water pump structure
POULOS, S J Geotechnical Engineers, Inc BX17 031. 83/09/23 KANE, J Division of Engineering 4pp 26519 242 24X Fiche 50-329, 84/07/18, 8408010061

--8408020182 Responds to M Wilcove verbal request Structural Engineering Branch area of concern identified by Judge Harbour applies only to consideration of structure-to-structure interaction Outstanding contentions encl
SCHAUER, F. P Structural Engineering Branch BX17 023 82/10/28 ADENSAM, E. G Licensing Branch 4 7pp 26519 055 24X Fiche 50-329, 84/07/18, 8408010061

--8408020183 Forwards response to applicant proposed findings of fact & conclusions of law on remedial soil issues Pagination needed Findings will be filed 831115
PATON,W D Hearing Branch 2 BX17 033 83/11/11 KANE,J NRC - No Detailed Affiliation Given 1p 26519 315 24X
Fiche 50-329,84/07/18,8408010061

--8408020184 Forwards marked-up input to staff testimony in preparation for ASLB 821027-1104 hearings re bearing capacity & underground piping,in response to verbal request of W Paton & M Wilcove Response to Stamiris contention encl
LEAR,G E Hydrologic & Geotechnical Engineering Branch BX17 023A 82/10/14 ADENSAM,E G Licensing Branch 4 10pp
26519 062 24X Fiche 50-329,84/07/18,8408010061

--8408020185 Responsive findings to applicant proposed findings of fact & conclusions of law on remedial soil issues
PATON,W D , WILCOVE,M N Hearing Branch 2 BX17 034 83/11/15
100pp 26519 316 24X Fiche 50-329,84/07/18,8408010061

--8408020186 Response to R Landsman 830106 questions re B Stamiris Request 4(b) re excavation of deep "O" duct bans in Freezewall Pit 4 & Tech Spec for static core penetrometer
KANE,J NRC - No Detailed Affiliation Given BX17 026 83/01/06
2pp 26519 146 24X Fiche 50-329,84/07/18,8408010061

--8408020187 Forwards updated version of Stamiris contentions,including addl Stamiris examples for Contentions 1,2 & 3 & changed wording of Contention 4C NRC testimony must address encl additions & changes
BROWN,E M NRC - No Detailed Affiliation Given BX17 025
81/05/19 Consumers Power Co 19pp 26519 124 24X
Fiche 50-329,84/07/18,8408010061

--8408020189 Forwards applicant testimony re alleged violation of ASLB 820430 order for determination of cross-examination List of questions re excavations & fireline piping provided
WILCOVE,M N Hearing Branch 2 BX17 042 83/05/13 LANDSMAN,R , COOK,R , HOOD,D NRC - No Detailed Affiliation Given 2pp
26520 116 24X Fiche 50-329,84/07/18,8408010061

--8408020202 Discusses status of efforts re NRC Midland findings due 831115 Requests meeting at earliest date
HOOD,D NRC - No Detailed Affiliation Given BX17 041 83/09/23
PATON,W D , WILCOVE,M N Hearing Branch 2 7pp 26520 095 24X
Fiche 50-329,84/07/18,8408010061

--8408140102 Forwards complete set of all abstracts of transcripts of hearings conducted on 811231-830630 W/listing of entire set of abstracts
HAMPTON,L Isham, Lincoln & Beale BX16 012 83/07/18
PATON,W D Hearing Branch 2 425pp 26508 097 24X
Fiche 50-329,84/07/18,8408010061

--8408140258 Handwritten notes re ASLB actions on 800527 motion to consolidate for discovery,evidentiary presentation & fact finding purposes issues concerning soil conditions for safety-related structures & sys
KANE,J NRC - No Detailed Affiliation Given BX16 033 80/06/09
1p 26511 158 24X Fiche 50-329,84/07/18,8408010061

-8408140263 Motion to consolidate for discovery,evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sys founded in & on plant fill mat'l in hearing considering 791206 order
FARNELL,A S Consumers Power Co BX16 034 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24X
Fiche 50-329,84/07/18,8408010061

-8408150702 Advises that Region III has no document re discovery request for info concerning alleged violation of ASLB order concerning remedial soils Handwritten notes,internal memos & list of repts,1977 - 1983,encl
HARRISON,J J Region 3, Office of Director BX20 021 83/10/25
WRIGHT,N Office of the Executive Legal Director 199pp
26540 345 24X Fiche 50-329,84/07/18,8408010061

8408170223 Requests Commission review Director's Decisions DD-83-16 & DD-84-02 to require all ongoing activity be included under order of mod of CP & remove util from managerial responsibility of QA/QC function
GARDE,B P Government Accountability Project BX19 022
84/02/10 PALLADINO,N , GILINSKY,V , ASSELSTINE,J Commissioners
72pp 26532 090 24X Fiche 50-329,84/07/18,8408010061

8408210391 Notice of W Ferris,S Afifi & J Wanzeck 801028-29 deposition in Ann Arbor,MI re 791206 order modifying const permits Related info encl
PATON,W D. Office of the General Counsel BX18 005 80/10/06
68pp. 26521 126 24X Fiche 50-329,84/07/18,8408010061

--8408210398 Notice of B Dahr 801217 deposition in Ann Arbor,MI re issues set forth in Licensing Board 791206 order modifying const permits & contentions of intervenors Stamiris & Warren Resume of TR Thiruvengadam encl
* Atomic Safety and Licensing Board Panel BX18 006 80/12/11
5pp 26521 199 24X Fiche 50-329,84/07/18,8408010061

8407300142 Responds to 840210 petition for specific Commission actions under 10CFR2 206 Petition denied per encl Director's Decision DD-84-17
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement DSB 521 84/07/24 GARDE,B P Government Accountability Project GARDE,B P Lone Tree Council 3pp
25807 232 24X Fiche 50-329,84/07/24,8407300142

--8407300151 Director's Decision DD-84-17 denying Govt Accountability Project 840210 petition for three Commission actions re soils work,independent third party responsibility for QA & QC & Region III staffing
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 84/07/24 24pp 25807 235 24X
Fiche 50-329,84/07/24,8407300142

--8407300156 Notice of Issuance of Director's Decision DD-84-17,denying Govt Accountability Project 840210 petition for Commission action
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 84/07/24 69pp 25807 259 24X
Fiche 50-329,84/07/24,8407300142

8408070377 Forwards NRC response to ASLB inquiry re Board Notification 84-115 dtd 840618 which identified specific hearing evidence adversely impacted by discrepancies in original seismic design calculations
PATON,W D Hearing Branch 2 DSB 816 84/08/02 BECHHOEFER,C , HARBOUR,J , COWAN,F P Atomic Safety and Licensing Board Panel
7pp 25947 158 24X Fiche 50-329,84/08/02,8408070377

8408200373 Order extending time until 841020 for Commission to act to review Director's Decision DD-84-17 Served on 840820
CHILK,S J Office of the Secretary of the Commission DSB 154
84/08/17 PALLADINO,N J , ROBERTS,T M , ASSELSTINE,J K Commissioners 1p 26137 051 24X Fiche 50-329,84/08/17,
8408200373

K Utility Final Safety Analysis Report (FSAR) & amends

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329,84/07/18,8408010061

--8408170374 Rev 44 & 47 to FSAR Response to Audit Point 1 & handwritten summaries of S&W 831013 public meeting encl
* Consumers Power Co BX19 051 84/08/01 34pp 26537 170
24X Fiche 50-329,84/07/18,8408010061

O Advisory Committee on Reactor Safeguards reports & correspondence

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329,84/07/18,8408010061

--8205240403 Advises that ad hoc ACRS subcommittee recommendations re foundation problems & related remedial actions at facilities acceptable,per 820429 & 0506-08 meetings Discussion of seismic-related issues tentatively scheduled for 820520-21
FRALEY,R F ACRS - Advisory Committee on Reactor Safeguards BX14 003 82/05/14 DIRCKS,W J Office of the Executive Director for Operations 1p 26500 027 24X Fiche 50-329,84/07/18,8408010061

--8206060008 Summarizes 266th ACRS meeting on 820603-05 Subj to satisfactorily completion of const & staffing & if due regard given to ACRS comments,plant can operate at 5% power w/o undue risk to public Full power recommendation deterred
SHEWMON,P ACRS - Advisory Committee on Reactor Safeguards BX14 004 82/06/08 PALLADINO,N Commissioners 6pp 26500 028
24X Fiche 50-329,84/07/18,8408010061

--8408010132 Forwards TERA Corp 830815 ltr describing four conceptual options for independent quality verification program methodologies.Option 1 integral part of IDCVP at Midland
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards BX14 001 83/11/15. ACRS - Advisory Committee on Reactor Safeguards
2pp 26500 012 24X Fiche 50-329,84/07/18,8408010061

--8408010135 Forwards QA/QC project status rept presented at ACRS 274th meeting on 830210
FISCHER,D C ACRS - Advisory Committee on Reactor Safeguards
BX14 002 83/03/03 ACRS - Advisory Committee on Reactor Safeguards 6pp 26500 021 24X Fiche 50-329,84/07/18, 8408010061

--8408010143 Forwards summary & conclusion of overall effectiveness portion of Region III rept on design & const problems Lack of aggressive QA attitude & overreliance on AE contribute to QA problems
FISCHER,D C ACRS - Advisory Committee on Reactor Safeguards
BX14 005 82/12/09 ACRS - Advisory Committee on Reactor Safeguards 4pp 26500 034 24X Fiche 50-329,84/07/18, 8408010061

--8408010147 Forwards JW Cook 810430 ltr & executive summary re QA program update,per 830215 request
SOMMERS,D A Consumers Power Co BX14 006 83/02/16
FISCHER,D C ACRS - Advisory Committee on Reactor Safeguards 1p 26500 038 24X Fiche 50-329,84/07/18,8408010061

--8408010152 Forwards status rept re QA/QC activities at facility to be presented at ACRS 274th meeting on 830210
FISCHER,D C ACRS - Advisory Committee on Reactor Safeguards
BX14 008 83/02/07 ACRS - Advisory Committee on Reactor Safeguards 7pp 26500 058 24X Fiche 50-329,84/07/18, 8408010061

--8408010153 Discusses major reduction in safety-related work at Midland ACRS comments to NJ Palladino encl
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards BX14 009 82/12/09 ACRS - Advisory Committee on Reactor Safeguards 3pp 26500 065 24X Fiche 50-329,84/07/18,8408010061

--8408010163 Forwards cost estimate for once through steam generator overfill protection mod,per request
DREHOBL,K E Consumers Power Co BX14 012 82/08/17
FISCHER,D C ACRS - Advisory Committee on Reactor Safeguards 2pp 26500 073 24X Fiche 50-329,84/07/18,8408010061

--8408010168 Forwards SSER 1,addressing ACRS recommendations contained in 820608 interim rept Operating license review project status repts for 820520-21 & 0602 encl W/o SSER
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards BX14 013 82/07/19 OKRENT,D ACRS - Advisory Committee on Reactor Safeguards 12pp 26500 075 24X Fiche 50-329,84/07/18, 8408010061

--8408010173 Discusses util approach for satisfying safety review requirements at Big Rock Point,Palisades & Midland Summary of 820504 meeting & viewgraphs encl
FISCHER,D C ACRS - Advisory Committee on Reactor Safeguards
BX14 014 82/05/17 ACRS - Advisory Committee on Reactor Safeguards 45pp 26500 087 24X Fiche 50-329,84/07/18, 8408010061

--8408010178 Forwards summary of ad hoc Subcommittee on Midland Units 1 & 2 820429 meeting Related info encl
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards BX14 016 82/05/06 SIESS,C ACRS - Advisory Committee on Reactor Safeguards 32pp 26500 133 24X Fiche 50-329,84/07/18, 8408010061

--8408010183 Discusses acceptability of Midland reactor pressure vessel anchor bolts,per util 811123 ltr & attached rept Expresses concern re rept sufficiency
SHEWMON,P G ACRS - Advisory Committee on Reactor Safeguards
BX14 017 82/02/03 VOLLMER,R H Division of Engineering 1p 26500 173 24X Fiche 50-329,84/07/18,8408010061

--8408010188 Forwards util 800522 ltr identifying one of many QA problems at facility Incident re fill matl under vital structures noted in P Tam 800516 ltr Incidents should be considered in evaluation of need for subcommittee meeting
YOUNG,G G ACRS - Advisory Committee on Reactor Safeguards BX14 018 80/06/03 SHEWMON,P ACRS - Advisory Committee on Reactor Safeguards 1p 26500 174 24X Fiche 50-329,84/07/18, 8408010061

--8408010191 Summary of 800523 meeting w/util in Bethesda,MD re reactor vessel holddown stud failures at facility
YOUNG,G G ACRS - Advisory Committee on Reactor Safeguards BX14 019 80/05/28 SHEWMON,P ACRS - Advisory Committee on Reactor Safeguards 3pp 26500 184 24X Fiche 50-329,84/07/18, 8408010061

--8408010195 Recommends review of foundation problems at facility Poor quality fill matl used under containment & other vital structures
TAM,P. ACRS - Advisory Committee on Reactor Safeguards BX14 020 80/05/16 SHEWMON,P ACRS - Advisory Committee on Reactor Safeguards 1p 26500 187 24X Fiche 50-329,84/07/18, 8408010061

--8408010198 Advises that unresolved safety issue exists in poor quality of fill matl under containment & other vital structures as evidenced by diesel generator bldg settlement
MCKINLEY,J C ACRS - Advisory Committee on Reactor Safeguards BX14 021 80/05/09 TAM,P ACRS - Advisory Committee on Reactor Safeguards 1p 26500 201 24X Fiche 50-329,84/07/18, 8408010061

--8408010202 Forwards portions of FSAR for review of soil/foundation problems Site visit & subcommittee meeting will be arranged
MCKINLEY,J C ACRS - Advisory Committee on Reactor Safeguards BX14 022 80/03/21 OSTERBERG,J O Northwestern Univ , Evanston, IL 1p 26500 202 24X Fiche 50-329,84/07/18,8408010061

--8408010204 Discusses facility safe shutdown boration capability B&W Water Reactors Subcommittee review to explore proposed fixes suggested
MULLER,R ACRS - Advisory Committee on Reactor Safeguards BX14 023 79/11/14 ETHERINGTON,H ACRS - Advisory Committee on Reactor Safeguards 1p 26500 207 24X Fiche 50-329,84/07/18, 8408010061

--8408010206 Summary of 790718 meeting w/util onsite re abnormal settlement of fill & structures Agenda & viewgraphs encl
ZUKOR,D J ACRS - Advisory Committee on Reactor Safeguards BX14 024 79/07/31 ACRS - Advisory Committee on Reactor Safeguards 78pp 26500 210 24X Fiche 50-329,84/07/18,8408010061

Q Inspection reports, IE Bulletins & correspondence

8408070183 Identifies activation completed &/or in progress,in response to IE Bulletin 83-07 re apparently fraudulent matl supplied by Ray Miller,Inc Final rept planned for 840901
COOK,J W Consumers Power Co 84/07/11 KEPPLER,J G Region 3, Office of Director 4pp 25950 025 24X Fiche 50-329,84/07/11, 8408070183

8408070227 Submits final response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Investigation performed by Bechtel determined three vendors supplied Tube-Line matl All Tube-Line matls removed from log
COOK,J W Consumers Power Co 84/07/11 KEPPLER,J G Region 3, Office of Director 3pp 25948 230 24X Fiche 50-329,84/07/11, 8408070227

8408030071 Forwards IE Insp Repts 50-329/84-21 & 50-330/84-22 on 840601-30 No noncompliance noted
WARNICK,R F Region 3, Office of Director 84/07/12 COOK,J W Consumers Power Co 2pp 25917 315 24X Fiche 50-329,84/07/12, 8408030071

--8408030074 IE Insp Repts 50-329/84-21 & 50-330/84-22 on 840601-30 No noncompliance noted Major areas inspected remedial soil work activities,allegations,turbine roll,status assessment, quality verification programs & progress
HARRISON,J J Region 3, Office of Director 84/07/12 9pp 25917 317 24X Fiche 50-329,84/07/12,8408030071

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329,84/07/18,8408010061

--8309130017 Discusses IE insp on 821012-1125 & 830119-21 & forwards order imposing civil monetary penalties in amount of $120,000 for violation re breakdown in implementation of QA program per 10CFR50,App B
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement BX21 018 83/08/29 SELBY,J D Consumers Power Co 3pp 26554 045 24X Fiche 50-329,84/07/18,8408010061

--8408020190 IE Investigation Rept 3-82-061 on 830103-0330 No noncompliance noted Major areas investigated allegations that util violated ASLB 820430 order re NRC approval for excavating in remedial soils program Investigation closed
WEIL,C H , PAWLICK,E T Region 3, Office of Director BX17 028 83/06/02 17pp 26519 178 24X Fiche 50-329,84/07/18, 8408010061

--8408020194 IE Investigation Rept 3-82-061 on 830711-0808 No noncompliance noted Major areas investigated allegations that util violated ASLB 820430 order re NRC approval for excavating in remedial soils program Investigation reopened
WEIL,C H , PAWLICK,E T Region 3, Office of Director WARD,W J Office of Investigation BX17 029 83/09/12 20pp 26519 199 24X Fiche 50-329,84/07/18, 8408010061

--8408020196 Provides Supplemental Dfc of Investigation Rept 3-82-061 re util alleged violation of ASLB order
HAYES,D B Office of Investigation BX17 030 83/09/12
KEPPLER,J G Region 3, Office of Director 3pp 26519 221 24X Fiche 50-329,84/07/18, 8408010061

--8408140039 Draft IE Insp Repts 50-329/78-20 & 50-330/78-20 from insp on 781211-20 & 790104-25 Violations noted inadequate control & supervision of plant fill matl placement & const specs not followed
PHILLIP, G A Region 3, Office of Director BX16 002 84/07/18 60pp 26507 112 24X Fiche 50-329, 84/07/18, 8408010061

--8408140055 Preliminary "Discussion of NRC Insp Facts Resulting From NRC Investigation of Diesel Generator Bldg Settlement "
* Consumers Power Co BX16 004 79/03/05 35pp 26507 315 24X Fiche 50-329, 84/07/18, 8408010061

--8408140513 Summary of R Landsman 810325-27 & 0407-09 insps conducted to verify QA program for util soil borings conducted in response to Corps of Engineers request for addl soil info
* NRC - No Detailed Affiliation Given BX16 054 84/07/18 4pp 26512 259 24X Fiche 50-329, 84/07/18, 8408010061

--8408150622 Discusses basis for recommendation to extend SALP III evaluation period from 820630 to 821231, per 820719-20 discussions Related info encl
COOK, R J Region 3, Office of Director BX21 012 82/08/06
SPESSARD, R L Division of Project & Resident Programs 13pp. 26553 145 24X Fiche 50-329, 84/07/18, 8408010061

--8408150624 Draft summary of NRC 840229 meeting w/util at Region III ofc re results of NRC HVAC insps & investigation of allegations & expansion of QA training, qualification & certification activities Viewgraphs encl
* Region 3, Office of Director BX20 002 84/02/29. Region 3, Office of Director 21pp 26537 342 24X Fiche 50-329, 84/07/18, 8408010061

--8408150633 Forwards Rev 4 to "Region III SALP Schedule " Schedule changes to listed facilities explained in remarks sections of schedule Addl handwritten notes also encl
NORELIUS, C E Region 3, Office of Director BX20 004 84/06/04
KEPPLER, J G , DAVIS, A B , SPESSARD, R L Region 3, Office of Director 22pp 26538 025 24X Fiche. 50-329, 84/07/18, 8408010061

--8408150639 Discusses Ofc of Special Cases special insp on 821012-1125 & forwards draft notice of violation re significant breakdown in implementation of QA program Handwritten NRR comments also encl
KEPPLER, J G Region 3, Office of Director BX20 005 83/01/05
COOK, J W Consumers Power Co 84pp 26538 049 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150640 Ack receipt of 830926 ltr & payment in amount of $116,500 for civil penalty imposed by 830829 order
AXELRAD, J A Enforcement Staff BX21 016 83/10/04 SELBY, J D Consumers Power Co 2pp 26553 305 24X Fiche. 50-329, 84/07/18, 8408010061

--8408150644 Forwards payment in amount of $116,500 in response to 830829 ltr imposing civil penalty for violations found during Insp 83-23 (EA 83-03). Related info encl, including matl on 830811 public meeting
COOK, J W Consumers Power Co BX21 017 83/09/26 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 29pp 26554 005 24X Fiche 50-329, 84/07/18, 8408010061

-8408150669 Corrects Page 3-1 of Attachment 3 to util 820517 response to draft SALP rept for Jul 1980 - June 1981, clarifying stop work order on drilling
COOK, J W Consumers Power Co BX21 024. 82/05/21 KEPPLER, J G Region 3, Office of Director 31pp 26554 313 24X
Fiche 50-329, 84/07/18, 8408010061

-8408150672 Forwards response to draft SALP rept for Jul 1980 - June 1981, discussed at 820426 meeting w/NRC
COOK, J W Consumers Power Co BX21 025 82/05/17 KEPPLER, J G Region 3, Office of Director 38pp 26554 344 24X
Fiche 50-329, 84/07/18, 8408010061

8408150677 Discusses SALP appraisals for Zimmer & Midland Suggests limited SALP-3 appraisal for Midland to cover remedial soils work, B&W work & HVAC activities
KEPPLER, J G Region 3, Office of Director BX21 026 83/04/18
HIND, J A Division of Radiological & Materials Safety Programs. 1p. 26555 066 24X Fiche 50-329, 84/07/18, 8408010061

8408150690 Lists reasons why SALP III evaluation period should be extended to 821231, per 820719-20 discussion Related info encl.
COOK, R J Region 3, Office of Director BX21 029 82/08/06
SPESSARD, R L Division of Project & Resident Programs 21pp 26555 112 24X Fiche: 50-329, 84/07/18, 8408010061

--8408150738 Forwards summary of 840229 meeting in Region III ofc re results of HVAC insps & investigation of allegations & expansion of training, qualification & certification activities Handwritten notes encl
WELLS, R A Consumers Power Co BX20 032 84/03/29
HARRISON, J J Region 3, Office of Director 169pp 26544 014
24X Fiche 50-329, 84/07/18, 8408010061

--8408150743 Submits reasons for extending SALP III evaluation period to 821231 Rept contains issues being resolved between NRC & licensee Extension can be used as performance motivator Handwritten note & supporting documentation encl
COOK, R J Region 3, Office of Director BX20 036 82/08/06
SPESSARD, R L Division of Project & Resident Programs 350pp 26546 001 24X Fiche 50-329, 84/07/18, 8408010061

--8408150747 Submits supplemental SALP input for facility Changes required to provide overall Div of Engineering & Technical Insp rating for QA functional area & consolidate comments for recommended increased insp frequency
PIRTLE, G Region 3, Office of Director BX20 037 83/10/01
BOYD, D Region 3, Office of Director 1p 26547 011 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150792 Submits QA issues to be addressed at evidentiary session in facility proceeding Summary rept & oral communications record re reinsp requirements based on results of certification testing encl
PATON, W D NRC - No Detailed Affiliation Given BX20 041
82/08/10 ADENSAM, E G NRC - No Detailed Affiliation Given
18pp 26548 075 24X Fiche 50-329, 84/07/18, 8408010061

--8408170119 Confirms that underpinning instrumentation installation will be suspended until procedures & drawings developed & plans & schedules established to inspect & audit activities, per 820319 telcon
KEPPLER, J G Region 3, Office of Director BX19 007 82/03/19
COOK, J W Consumers Power Co 2pp 26530 037 24X
Fiche 50-329, 84/07/18, 8408010061

--8408170152 Forwards redrafted insp rept Rept has been reviewed w/NRC for format & content Rept covers insp made 821129-1210
CHARAK, I Argonne National Laboratory BX19 011 82/01/07
WARNICK, R Region 3, Office of Director 7pp 26530 233 24X
Fiche 50-329, 84/07/18, 8408010061

--8408170157 Forwards draft insp rept re findings of personnel who participated in routine insps on 821129-1203 & 1208-10
CHARAK, I. Argonne National Laboratory BX19 012 82/12/22
WARNICK, R Region 3, Office of Director 14pp 26530 240 24X
Fiche 50-329, 84/07/18, 8408010061

--8408170174 Forwards IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820514
NORELIUS, C E Region 3, Office of Director BX19 013 82/06/28
COOK, J W Consumers Power Co 2pp 26531 033 24X
Fiche 50-329, 84/07/18, 8408010061

--8408170181 IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820514 Major areas discussed licensee disposition of results of electrical overview insps
GARDNER, R N , WILLIAMS, C C Region 3, Office of Director BX19 013A 82/06/24 3pp 26531 035 24X Fiche 50-329, 84/07/18, 8408010061

--8408170205 Forwards IE Insp Repts 50-329/82-07 & 50-330/82-07 on 820421-23 No noncompliance noted Schedule for reinsp program of piping suspension sys requested within 25 days from receipt of ltr
* Region 3, Office of Director BX19 017 82/07/15 Consumers Power Co 2pp 26531 071 24X Fiche 50-329, 84/07/18, 8408010061

--8408170232 Forwards SALP Repts 50-329/82-14 & 50-330/82-14 for period Jul 1980 - June 1981.
KEPPLER, J G Region 3, Office of Director BX19 026 84/07/18
COOK, J W Consumers Power Co 2pp 26533 158 24X
Fiche 50-329, 84/07/18, 8408010061

--8408170236 Ack receipt of 820114 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/81-12 & 50-330/81-12
NORELIUS, C E Division of Engineering BX19 028 82/02/03
COOK, J W Consumers Power Co 4pp 26533 188 24X
Fiche 50-329, 84/07/18, 8408010061

--8408170271 Requests Ofc of Investigations provide investigator to assist Ofc of Special Cases in closeout of unresolved item in Insp Rept 329/82-22-27 re use of unofficial documents for recording nonconformances & deficiencies
WARNICK, R F NRC - No Detailed Affiliation Given BX19 035
83/01/27 PAWLIK, E T. Region 3, Office of Director 1p
26534 295 24X Fiche 50-329, 84/07/18, 8408010061

--8408170274 Discusses 831021 interview w/A Gautam & unnamed individual re allegations concerning Comstock,Bechtel & Zack const activities at plant Details of issues referred to Ofc of Investigation & Ofc of Inspector & Auditor
HAWKINS,F C Region 3, Office of Director 8X19 036 83/10/26
Region 3, Office of Director 1p 26534 296 24X
Fiche 50-329,84/07/18,8408010061

--8408210464 Notifies of 830708 meeting to discuss NRR SALP III assessment based on recent hearing testimony by Region III & several third-party reviewers
NOVAK,T M Assistant Director for Licensing 8X18 055 83/07/07
JOHNSTON,W , KNIGHT,J P , RUBENSTEIN,L NRC - No Detailed Affiliation Given 11pp 26528 262 24X Fiche 50-329,84/07/18, 8408010061

--8408220059 Responds to 830829 ltr re imposition of civil penalty for violations noted during Insp 83-23 Penalty reduced because of prompt corrective actions Check encl
COOK,J W Consumers Power Co 8X19 052 83/09/26 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 2pp
26537 208 24X Fiche 50-329,84/07/18,8408010061

--8408220078 SALP Repts 50-329/82-14 & 50-330/82-14 for Jul 1980 - June 1981
* Region 3, Office of Director 8X19 027 82/03/31 28pp
26533 160 24X Fiche 50-329,84/07/18,8408010061

--8408270330 Forwards summary of 840229 meeting w/Region III & util in Region III re results of insps & investigation into allegations re HVAC work
WELLS,R A Consumers Power Co 8X19 020 84/03/24
HARRISON,J J Region 3, Office of Director 17pp 26532 023
24X Fiche 50-329,84/07/18,8408010061

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408230502 Forwards IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance noted
WARNICK,R F Region 3, Office of Director 84/08/03 COOK,J W
Consumers Power Co 2pp 26212 264 24X Fiche 50-329,84/08/03, 8408230502

--8408230512 IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance or deviations noted Major areas inspected licensee action on 10CFR50 55(e) items
HARRISON,J J Region 3, Office of Director 84/08/03 8pp
26212 266 24X Fiche 50-329,84/08/03,8408230502

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp. 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408240136 Forwards Mgt Meeting Repts 50-329/84-18 & 50-330/84-19 on 840712
WARNICK,R F Region 3, Office of Director 84/08/20 COOK,J W
Consumers Power Co 2pp. 26228 205 24X Fiche 50-329,84/08/20, 8408240136

--8408240144 Mgt Meeting Repts 50-329/84-18 & 50-330/84-19 on 840712 Major areas discussed:work activities for auxiliary bldg underpinning,status of svc water pump structure & QA/QC activities
LANDSMAN,R B , HARRISON,J J Region 3, Office of Director
84/08/20 4pp 26228.207 24X Fiche 50-329,84/08/20,8408240136

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Ould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records 8X14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp. 26500 001 24X
Fiche 50-329,84/07/18,8408010061

--8408150603 Forwards Midland monthly status repts for Aug-Sept & Nov 1982 Related info encl.
WARNICK,R F Region 3, Office of Director 8X21 008 82/12/20
KEPPLER,J G Region 3, Office of Director 23pp 26551 256 24X
Fiche 50-329,84/07/18,8408010061

--8408150698 Forwards monthly status rept for Dec 1983,containing input from insp site team of Ofc of Special Cases
COOK,R J Region 3, Office of Director 8X21 031 83/01/12
WARNICK,R F Region 3, Office of Director. 2pp 26555 161 24X
Fiche: 50-329,84/07/18,8408010061.

8408240132 Forwards minutes of monthly third party assessment 840712 meeting re status of independent assessment of underpinning & remedial soils work & status of const implementation overview program
LUCKS,A S Stone & Webster, Inc 84/08/07. HARRISON,J J. Region 3, Office of Director 43pp. 26226 033 24X Fiche 50-329,84/08/07, 8408240132

--8408240134 Forwards Independent Assessment of Underpinning Weekly Rept 91 for 840610-16 Minutes of daily meetings between members of assessment team & site engineering,const & QA personnel encl
LUCKS,A S Stone & Webster, Inc. 84/06/20 BURGESS,B L NRC - No Detailed Affiliation Given 15pp 26226:178 24X
Fiche 50-329,84/08/07,8408240132.

--8408240138 Forwards Independent Assessment of Underpinning Weekly Rept 92 for 840617-0623.Minutes of daily meetings between members of assessment team & site engineering const & QA personnel encl
LUCKS,A S Stone & Webster, Inc. 84/06/27 BURGESS,B L NRC - No Detailed Affiliation Given 16p 26226 193 24X
Fiche. 50-329,84/08/07,8408240132.

DOCKETED ITEMS

8408240143 Forwards Independent Assessment of Underpinning Weekly Rept 93 for 840624-0630 Minutes of daily meetings between members of assessment team & site engineering, const & QA personnel encl
LUCKS, A S Stone & Webster, Inc 84/07/03 BURGESS, B L NRC - No Detailed Affiliation Given 11pp 26226 209 24X
Fiche 50-329, 84/08/07, 8408240132

8408240148 Forwards Const Implementation Overview Weekly Rept 51 for 840528-0601 Rept includes summary of activities & open items, nonconformance identification repts & hold points
KARR, J E Stone & Webster, Inc 84/06/08 KEPPLER, J G Region 3, Office of Director 18pp 26226 292 24X
Fiche 50-329, 84/08/07, 8408240132

8408240152 Forwards Const Implementation Overview Weekly Rept 53 for 840611-15 Rept includes summary of activities & open items, nonconformance identification repts & hold points
KARR, J E Stone & Webster, Inc 84/06/22 KEPPLER, J G Region 3, Office of Director 18pp 26226 328 24X
Fiche 50-329, 84/08/07, 8408240132

8408240159 Forwards Const Implementation Overview Weekly Rept 54 for 840618-22 Rept includes summary of activities & open items, nonconformance identification repts & hold points
KARR, J E Stone & Webster, Inc 84/07/02 KEPPLER, J G Region 3, Office of Director 18pp 26226 346 24X
Fiche 50-329, 84/08/07, 8408240132

Reportable occurrences, LERs & related correspondence

06010038 Forwards Tracked Action Item 086 re NIR 022 & NIR 023 Requests one reply clarifying initial findings Current replies provide inaccurate & conflicting info
KARR, J E Stone & Webster, Inc 84/05/22 KEPPLER, J G ; HARRISON, J J , BURGESS, B L NRC - No Detailed Affiliation Given
2pp 24757 351 24X Fiche 50-329, 84/05/22, 8406010038

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000, 84/05/24, 8405290062

8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000, 84/05/24, 8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000, 84/05/24, 8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER, M Division of Licensing 158pp
25926 173 24X Fiche 50-000, 84/06/28, 8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER, C Director's Office, Office of Inspection and Enforcement 43pp 25937 133 24X Fiche 50-000, 84/07/10, 8408060050

9310054 Final deficiency rept re concrete embedment design using ear lugs located outside compression zone Initially ported on 821203 Use of shear lugs outside compression ne is proper design technique Related correspondence
DY, J W Consumers Power Co DSB 986 84/07/11 KEPPLER, J G gion 3, Office of Director 1p 26350 186 24X
che 50-329, 84/07/11, 8408310054

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records BX14 000 84/07/18
RICE, C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329, 84/07/18, 8408010061

-8110260082 Informs that licensee taking position that IEEE 279 jurisdiction starts w/transmitter Jurisdiction should start at sensing line connection to process piping
HENDERSON, J B Reactor Projects Sections (Regions 1 & 3) BX19 024 81/10/01 WILLIAMS, C C Plant Systems Section 1p
26533 050 24X Fiche 50-329, 84/07/18, 8408010061

-8408010160 Forwards interim 10CFR50 55(e) rept re QA program & mfg deficiencies affecting radiation monitoring equipment supplied by Victoreen, Inc
FISCHER, D ACRS - Advisory Committee on Reactor Safeguards BX14 011 82/11/15 OKRENT, D ACRS - Advisory Committee on Reactor Safeguards 1p 26500 072 24X Fiche 50-329, 84/07/18, 8408010061

-8408150658 Recommends issuance of board notification for encl potential Part 21 rept from Zack Co (HVAC subcontractor) re accuracy of welder records
WARNICK, R F Region 3, Office of Director BX21 020 82/09/01
EISENHUT, D G Division of Licensing 2pp 26554 179 24X
Fiche 50-329, 84/07/18, 8408010061

-8408150694 PNO-77-035 on 770226, bulge discovered in containment liner plate Caused by water coming through tears in liner plate Addl holes cut in plate to facilitate draining Related info encl
WARNICK, R F , ROY, G W , THOMPSON, D Office of Inspection & Enforcement, Office of the Director BX21 030 77/03/01 7pp
26555 154 24X Fiche 50-329, 84/07/18, 8408010061

-8408170090 Discusses util 820428 telcon notifyng that, while drilling well in G area, electric duct bank struck Drawings indicated duct bank elsewhere Investigation continuing
SHAFER, W D Region 3, Office of Director BX19 001A 82/04/28
WILLIAMS, G C , LANDSMAN, R D NRC - No Detailed Affiliation Given
1p 26529 285 24X Fiche 50-329, 84/07/18, 8408010061

-8408170276 Forwards util repts re auxiliary bldg seismic analysis & cracks in borated water storage tank foundation, per util 810121-22 notifications Const deficiency info may aid in resolution of matter
NORELIUS, C E Division of Engineering BX19 036AB 81/11/24
EISENHUT, D G Division of Licensing 1p 26535 165 24X
Fiche 50-329, 84/07/18, 8408010061

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000, 84/07/27, 8408060102

-8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000, 84/07/27, 8408060102

8408090284 Forwards table indicating status of 10CFR50 55(e) issues Procedures revised to assure proper handling & reporting of addl 10CFR50 55(e) items
COOK, J W Consumers Power Co 84/07/27 KEPPLER, J G Region 3, Office of Director 4pp 25994 036 24X Fiche 50-329, 84/07/27, 8408090284

8408310259 Final deficiency rept re defective capstan springs in Pacific Scientific mechanical shock arrestors Initially reported on 840106 W/o description of investigation & corrective actions Related correspondence
COOK, J W Consumers Power Co DSB 978 84/07/27 KEPPLER, J G Region 3, Office of Director 1p 26350 281 24X
Fiche 50-329, 84/07/27, 8408310259

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000, 84/08/01, 8408060324

-8408060387 "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-6-56 84/07/31 62pp
25927 066 24X Fiche 50-000, 84/08/01, 8408060324

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000, 84/08/10, 8408160394

-8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000, 84/08/10, 8408160394

aids SER re TDI Owners Group program plan SER addresses
y quality revalidation program, testing & insp,
liance & sets forth requirements for operation
letion of program plan
Division of Licensing 84/08/13 GEORGE, J B TDI
Delaval, Inc) Owners Group 1p 26255 194 24X
84/08/13, 8408240115

fety evaluation of TDI Owners Group program plan Based on
tion, plan incorporates essential elements needed
outstanding concerns re reliability of TDI
nuclear svc
Detailed Affiliation Given 84/08/13 21pp
24X Fiche 50-000, 84/08/13, 8408240115

rds "Design Review of Elliott Model 900 Turbocharger
SR-48 & DSRV-16 Emergency Diesel Generator
ting final QA verified rept Addl copy
NWL, per NRC request
(Transamerica Delaval, Inc) Owners Group 84/08/14
ffice of Nuclear Reactor Regulation, Director 2pp
X Fiche 50-000, 84/08/14, 8408160395

sign Review of Elliott Model 900 Turbocharger Used on
DSRV-16 Emergency Diesel Generator Sets "
nalysis Associates FAAA-84-5-7 84/07/31 61pp
24X Fiche 50-000, 84/08/14, 8408160395

rds response to 840723 request for addl info on repts
DI Diesel Generator Owners Group
(Transamerica Delaval, Inc) Owners Group 84/08/23
Office of Nuclear Reactor Regulation, Director 12pp
X Fiche 50-000, 84/08/23, 8408290179

cripts on non-antitrust matters

er response to FOIA request for 16 categories of
ility Documents identified by J Goold &
40514 & 15 (App B) forwarded App A documents
ded Index forthcoming Search continuing
ivision of Rules and Records 8X14 000 84/07/18
kland & Ellis 2pp 26500 001 24X
4/07/18, 8408010061

timony of DS Hood & J Kane re matl false statement
NRC 791206 mod order
NE, J NRC - No Detailed Affiliation Given 8X17 021
3pp 26519 027 24X Fiche 50-329, 84/07/18, 8408010061

timony of JG Keppler re QA problems at facility &
tions taken
Region 3, Office of Director 8X15 012A 84/07/18
262 24X Fiche 50-329, 84/07/18, 8408010061

imony of HN Singh re unresolved geotechnical engineering
, including reactor bldg foundation, diesel
g settlement & svc water bldg foundation &
tanks
rmy, Dept of, Corps of Engineers 8X16 016
pp 26510 319 24X Fiche 50-329, 84/07/18, 8408010061

imony of RB Landsman in Glen Ellyn, IL re QA criteria &
remedial foundation work underway at site
NRC - No Detailed Affiliation Given 8X19 002
p 26529 332 24X Fiche 50-329, 84/07/18, 8408010061

script of B Stamiris 840425 statement re soil settlement
lant
Stamiris, B 8X19 041 84/04/25 3pp 26536 134
-329, 84/07/18, 8408010061

script of M Sinclair 840425 statement re problems w/util
1986 const completion date Documentation encl
Sinclair, M 8X19 042 84/04/25 10pp 26536 137
329, 84/07/18, 8408010061

cript of T Hearron 840425 statement opposing
ensing & operation of plant
he Tree Council 8X19 043 84/04/25 4pp
X Fiche 50-329, 84/07/18, 8408010061

cript of BP Garde 840425 statement re Govt
Project 840210 supplemental 10CFR2 206
reakdown, NRC action problems & adequate
law of complex project
vernment Accountability Project 8X19 044
p 26536 151 24X Fiche 50-329, 84/07/18, 8408010061

--8408220064 Testimony of RN Gardner re qualification of Bechtel QC
personnel Certificate of Svc & related info encl
GARDNER, R N Region 3, Office of Director 8X19 023 82/01/22
120pp 26532 292 24X Fiche 50-329, 84/07/18, 8408010061

--8408270336 Testimony of BP Garde re Midland Nuclear Power Plant
GARDE, B P Government Accountability Project 8X19 021
84/02/13 22pp 26532 040 24X Fiche 50-329, 84/07/18, 8408010061

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing
correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan,
Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000,
84/08/10, 8408140426

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A Application/construction stage documents & correspondence

8408020015 Forwards response to NRC request for addl info re Vol IX of
seismic margin review rept, "Balance-of-Plant Class 1, 2 & 3
Piping, Pipe Supports & Valves "
COOK, J W Consumers Power Co 84/07/11 DENTON, H R Office of
Nuclear Reactor Regulation, Director 16pp 25883 120 24X
Fiche 50-329, 84/07/11, 8408020015

8408010061 Further response to FOIA request for 16 categories of
records re facility Documents identified by J Goold &
M Siebert on 840514 & 15 (App B) forwarded App A documents
already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records 8X14 000 84/07/18
RICE, C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329, 84/07/18, 8408010061

--7812070142 Discusses IE Insp Repts 50-329/78-12 & 50-330/78-12
Contributing factors to settlements of diesel generator bldg
foundation & generator pedestals include variable properties
of random fill matl supporting structure & cooling pond
KEPPLER, J G Region 3, Chicago, Office of the Director 8X16 001
78/11/01 THORNBURG, H D Division of Reactor Construction
Inspection 2pp 26506 211 24X Fiche 50-329, 84/07/18,
8408010061

--7909290119 Forwards outline history of geotechnical engineering
problems re plant fill Lists pertinent PSAR & FSAR criteria
& summarizes foundation conditions & remedial measures for
all Category I structures founded on plant fill
GILLEN, D M Geosciences Branch 8X16 015 79/08/28
JACKSON, R E Geosciences Branch 10pp 26510 309 24X
Fiche 50-329, 84/07/18, 8408010061

--8004040738 Summary of 800227 & 28 meeting & site visit w/util in
Midland, MI re soil settlement problems & related
investigation program
GONZALES, R D Hydrology Meteorology Branch 8X16 032 80/03/10
BIVINS, W S Hydrology Meteorology Branch 9pp 26511 119 24X
Fiche 50-329, 84/07/18, 8408010061

--8008130764 Summarizes status of seismological input parameters re
geosciences & geotechnical review of facilities as discussed
at 800702 & 22 meetings
KIMBALL, J Geosciences Branch 8X16 029 80/08/07 JACKSON, R E
Geosciences Branch 6pp 26511 093 24X Fiche 50-329, 84/07/18,
8408010061

--8011240409 Forwards Hydrologic Engineering Section interrogatories re
permanent dewatering sys at facilities
LEAR, G E Hydrologic & Geotechnical Engineering Branch 8X17 008
80/11/10 TEDESCO, R L Assistant Director for Licensing 3pp
26517 244 24X Fiche 50-329, 84/07/18, 8408010061

--8105070480 Responds to request re Geosciences Branch estimate of time
required to complete site review. Approx 30 days are needed
to review addl info requested for Part 1 & 3 months are
needed for review of Part 2 submittal
KNIGHT, J P Assistant Director for Comp & Structures Engineering
(Pre 830201) 8X16 037B 81/04/24 PATON, W D Office of the
Executive Legal Director 1p 26513 189 24X
Fiche 50-329, 84/07/18, 8408010061

--8110190801 Forwards topic discussions for inclusion in 1981 Annual
rept, per 810902 commitment Discussions of technical
assistance program for licensing, GETR review & Midland
remedial repair info encl
HELLER, L W Hydrologic & Geotechnical Engineering Branch 8X16
053 81/09/16 LEAR, G Hydrologic & Geotechnical Engineering
Branch 6pp 26512 253 24X Fiche 50-329, 84/07/18, 8408010061

-8111240064 Informs of 811016 conference call w/util to discuss revised schedule for soils hearing requests revision to better accommodate const schedule Agreed schedule for hearings will be 811201-04 & 1214-18
HOOD,D Licensing Branch 4 BX19 0368 81/10/30 TEDESCO,R L Assistant Director for Licensing 3pp 26535 252 24X Fiche 50-329,84/07/18,8408010061

-8201050063 Summarizes 811207 telcon re 820105 soils hearing
HOOD,D Licensing Branch 4 BX18 032 81/12/14 ADENSAM,E G Licensing Branch 4 2pp 26526 099 24X Fiche 50-329,84/07/18, 8408010061

-8201220049 Advises of 1-month delay in meeting R Tedesco 811214 schedule in support of facility hearing & review Viable schedule must recognize need for iteration w/applicant following each significant submittal
VOLLMER,R H Division of Engineering BX16 074 81/12/28 EISENHUT,D G Division of Licensing 3pp 26514 188 24X Fiche 50-329,84/07/18,8408010061

-8202040352 Informs that certain SER sections,especially soil remedial actions,will not be complete by 820406 deadline
ADENSAM,E G. Licensing Branch 4 BX16 055 82/01/19 EISENHUT,D G Division of Licensing 3pp 26512 266 24X Fiche 50-329,84/07/18,8408010061

-8203020050 Summary of 811006-07 meeting w/util,Bechtel & consultants in Bethesda,MD re underground piping in inadequately compact plant fill
HOOD,D S Licensing Branch 4 BX21 002 82/02/05 DENTON,H R NRC - No Detailed Affiliation Given 37pp 26549 084 24X Fiche 50-329,84/07/18,8408010061

-8205030209 Forwards listing of issues to be resolved prior to start of Phase 2 underpinning operations for auxiliary bldg
LEAR,G Hydrologic & Geotechnical Engineering Branch BX16 035 82/04/28 ADENSAM,E Licensing Branch 4 2pp 26511 200 24X Fiche 50-329,84/07/18,8408010061

-8205120033 Summarizes technical comments from ACRS subcommittee 820429 meeting re remedial activities for deficient soils
ADENSAM,E G. Licensing Branch 4 BX18 035 82/05/04 BOSNAK,R NRC - No Detailed Affiliation Given 4pp 26527 183 24X Fiche 50-329,84/07/18,8408010061

-8205210467 Notifies that util submittal re Phase 2 of underpinning repair work at facility acceptable,provided that encl mods & requirements are incorporated into Phase 2 program
KNIGHT,J P Assistant Director for Comp & Structures Engineering (Pre 830201) BX16 038 82/05/10 TEDESCO,R L Assistant Director for Licensing 34pp 26511,203 24X Fiche 50-329,84/07/18,8408010061

-8206020051 Comments on draft of acceptance provisions for Phase 2 Final transmittal to applicant should move through DE for concurrence
KNIGHT,J P Assistant Director for Comp & Structures Engineering (Pre 830201) BX16 036 82/05/13 KANE,J. Assistant Director for Comp & Structures Engineering (Pre 830201) 1p 26511 202 24X Fiche.50-329,84/07/18,8408010061

-8206240401 Forwards comments on 820422 response to NRC request for addl info re borated water storage tank & underpinning of svc water pump structure Contact w/applicant to resolve differences recommended
LEAR,G Hydrologic & Geotechnical Engineering Branch 82/06/16. ADENSAM,E Licensing Branch 4 105pp 66129 031. 24X Fiche 50-329,84/07/18,8408010061

-8206290161 Submits proposed schedule for facility soils review
ADENSAM,E G. Licensing Branch 4 BX18 036 82/06/25 EISENHUT,D G Division of Licensing 2pp 26527 187 24X Fiche 50-329,84/07/18,8408010061

-8207140330 Forwards request for addl info from Structural Engineering Branch re applicant proposed remedial actions
SCHAUER,F F. Structural Engineering Branch BX19 029 82/06/15. ADENSAM,E Licensing Branch 4 5pp 26533 206 24X Fiche 50-329,84/07/18,8408010061

-8210130322 Forwards info re location of data on underpinning dimensions & load transfer procedures
POULOS,S J Geotechnical Engineers, Inc. BX16 060 82/10/07 KANE,J Division of Engineering. 6pp 26513 234 24X Fiche 50-329,84/07/18,8408010061

--8210150698 Clarifies NRC/util interaction re QL review Maint of proper control by licensing property managers necessary to manage licensing activities properly Reviewers requested to follow guidelines
ADENSAM,E G Licensing Branch 4 BX16 070 82/09/29 TOMLINSON,E NRC - No Detailed Affiliation Given 2pp 26514 109 24X Fiche 50-329,84/07//18,8408010061

--8305270222 Forwards trip rept of 830510-13 site visit re underpinning contract Other topics discussed include cracks in svc water pump structure,heave over freeze wall,need to stop laying back soil along underpinning drifts & settlements
POULOS,S J Geotechnical Engineers, Inc BX18 022 83/05/23 KANE,J Division of Engineering 19pp 26524 317 24X Fiche 50-329,84/07/18,8408010061

--8306060387 Trip rept of 830511 & 12 site visits to view pier load test installation & results
KANE,J D Structural & Geotechnical Engineering Branch BX18 021 83/05/27 LEAR,G Structural & Geotechnical Engineering Branch 2pp 26524 315 24X Fiche 50-329,84/07/18,8408010061

--8307130423 Forwards paper entitled "Use of Site Dependent Spectra" to be presented at workshop on "Site-Specific Effects of Soil & Rock on Ground Motion & Implications for Earthqauake-Resistant Design" on 830726-28
KIMBALL,J Geosciences Branch BX17 039 83/06/27 JACKSON,R E Geosciences Branch 1p 26520 069 24X Fiche 50-329,84/07/18, 8408010061

--8307130425 Speech entitled "Use of Site Dependent Spectra," to be presented at 830726-28 workshop on "Site-Specific Effects of Soil & Rock on Ground Motion & Implications for Earthquake-Resistant Design" in Santa Fe,NM
KIMBALL,J Geosciences Branch BX17 040 83/06/27 25pp 26520 070 24X Fiche 50-329,84/07/18,8408010061

--8310070262 Forwards second phase of Geotechnical Engineering input on findings of fact & conclusions of law in response to OELD request Several areas of significant differences exist re diesel generator bldg
LEAR,G Structural & Geotechnical Engineering Branch BX17 032 83/09/30 PATON,W D Office of the Executive Legal Director 6pp 26519 246 24X Fiche 50-329,84/07/18,8408010061

--8312080185 Forwards technical evaluation of HVAC structural design adequacy,based on findings of Mechanical Engineering Branch design review & audit
KNIGHT,J P Assistant Director for Comp & Structures Engineering (Post 830201) BX18 051 83/11/25 NOVAK,T M Assistant Director for Licensing 27pp 26528 206 24X Fiche 50-329,84/07/18,8408010061

--8312120393 Requests requisite info re followup action to be taken by Region III to 831108 recommendation for board notification
EISENHUT,D G Division of Licensing BX21 014 83/11/30 WARNICK,R F Region 3, Office of Director 1p 26593 204 24X Fiche 50-329,84/07/18,8408010061

--8406020280 Trip rept of 840504 site visit to participate in public meeting on mgt appraisal program to be performed on util Comments on independent mgt appraisal encl
MCLAUGHLIN,P Licensee Qualifications Branch BX20 010 84/05/22 BOOHER,H R Licensee Qualifications Branch 5pp 26539 045 24X Fiche: 50-329,84/07/18,8408010061

--8408010149 Forwards executive summary re QA program update,per 810331 meeting commitment & NRC 810402 ltr Apps will be transmitted by 810522
COOK,J W Consumers Power Co BX14 007 81/04/30 KEPPLER,J G Region 3, Chicago, Office of the Director (81/03/01) 19pp 26500 039 24X Fiche 50-329,84/07/18,8408010061

--8408020038 Lists questions asked of util during FSAR & 10CFR50 54(f) review,including questions re geological & seismological matters & intake & discharge structures for svc water sys
KANE,J NRC - No Detailed Affiliation Given BX17 001 84/07/18 19pp 26514 273 24X Fiche 50-329,84/07/18,8408010061

--8408020043 Lists questions & responses re condition of soils onsite, correction to foundation problems & risk in allowing const to continue
* NRC - No Detailed Affiliation Given BX17 002 79/03/05 15pp 26514 322 24X Fiche 50-329,84/07/18,8408010061

--8408020099 Answers to util interrogatories re staff requests directed on determination & justification of acceptance criteria applied to various remedial measures taken on page 3 of Order
KANE,J NRC - No Detailed Affiliation Given BX17 010 84/07/18 Consumers Power Co 31pp 26517 331 24X
Fiche 50-329,84/07/18,8408010061

--8408020112 Question re discrepancy in magnitude of loading stress on Fig 2 of B00914 rept & info on Tables 4-1A & 2 5-14
* NRC - No Detailed Affiliation Given BX17 012 84/07/18 1p 26518 143 24X Fiche 50-329,84/07/18,8408010061

--8408020122 Provides trip rept for 781107 meeting in Urbana, IL re settlement of far east bay of diesel generator bldg List of correction action options provided
COOKE,T C Consumers Power Co BX17 015 78/12/12 Consumers Power Co 4pp 26518 264 24X Fiche 50-329,84/07/18,8408010061

--8408020188 Responds to Mooney concept theory re SRP 2 5 4 & PSAR review Suggestion to OELD re Mooney testimony encl
HOOD,D NRC - No Detailed Affiliation Given BX17 027 83/11/22
HASSEL,D M NRC - No Detailed Affiliation Given 4pp 26519 153 24X Fiche 50-329,84/07/18,8408010061

--8408020192 Forwards applicant advance copy of meeting notes for 820727-30 design audit of soils remedial activities in Ann Arbor, MI Questions should be referred to J Kane
LEAR,G Hydrologic & Geotechnical Engineering Branch BX17 043 82/09/17 ADENSAM,E Licensing Branch 4 22pp 26520 224 24X Fiche 50-329,84/07/18,8408010061

--8408020193 Informs that Structural Mechanics Assoc seismic margin review studies indicate soil layering profiles & soil properties differ from properties previously addressed
KANE,J Structural & Geotechnical Engineering Branch BX17 044 82/05/11 LEAR,G Structural & Geotechnical Engineering Branch 2pp 26520 247 24X Fiche 50-329,84/07/18,8408010061

--8408020195 Summary of 840417 meeting w/TERA, Structural Mechanics Assoc (SMA) & util in Chicago, IL to discuss SMA seismic margins evaluation & potential applicability to disposition of outstanding civil/structural issues
RINALDI,F Structural & Geotechnical Engineering Branch BX17 045 84/07/18 LEAR,G Structural & Geotechnical Engineering Branch 2pp 26520 249 24X Fiche 50-329,84/07/18,8408010061

--8408020199 Forwards request for addl structural engineering info needed to continue OL review of NPP application as applicable to seismic margins review, svc water pump structure & diesel generator bldg
LEAR,G Structural & Geotechnical Engineering Branch BX17 046 84/05/03 ADENSAM Licensing Branch 4 5pp 26521 042 24X Fiche 50-329,84/07/18,8408010061

--8408030001 Handwritten notes & outline of conference call w/Bechtel & util re review of buried piping, monitoring program & future settlement
MEISENHEIMER,J NRC - No Detailed Affiliation Given BX17 047 81/12/15 6pp 26515 146 24X Fiche 50-329,84/07/18,8408010061

--8408030004 Summary of 811006-07 meeting w/util in Bethesda, MD re underground piping in inadequately compacted plant fill Meeting agenda, attendance list & const hydro test viewgraphs encl
HOOD,D S Licensing Branch 4 BX17 048 82/02/05 Licensing Branch 4 36pp 26515 241 24X Fiche 50-329,84/07/18,8408010061

--8408030009 Summary of 810721 meeting w/applicant in Bethesda, MD re summary of San Onofre meeting on confirmatory analysis of piping sys design Confirmatory analysis encl
ROOD,H Licensing Branch 3 BX17 049 81/08/19 Licensing Branch 3 29pp 26515 277 24X Fiche 50-329,84/07/18,8408010061

--8408030013 Notification of 820416 meeting w/util in Bethesda, MD to discuss buried piping & related applicant 820316 submittal W/handwritten notes of 820407 conference call & outline of outstanding issues in geotechnical engineering area
HOOD,D S Licensing Branch 4 BX17 050 82/04/13 ADENSAM,E G Licensing Branch 4 22pp 26515 306 24X Fiche 50-329,84/07/18,8408010061

--8408030020 Handwritten notes on 810120 meeting re stress analysis for underground piping Outline of discussion topics for pipe stress analysis encl
KANE,J NRC - No Detailed Affiliation Given BX17 052 81/01/20
NRC - No Detailed Affiliation Given 18pp 26515 355 24X Fiche 50-329,84/07/18,8408010061

--8408030028 Agenda for 820121-22 meeting to discuss underground piping concerns W/handwritten summary of 820107 conference call re underground piping & 820120 evaluation of sand settlement due to earthquake
KANE,J NRC - No Detailed Affiliation Given BX17 059 82/01/22
NRC - No Detailed Affiliation Given 23pp 26516 017 24X Fiche 50-329,84/07/18,8408010061

--8408030042 Agenda for 811006 meeting w/Bechtel, util & Army Corps of Engineers to discuss underground piping reprofiling, proposed demonstration solution & 1981 measurement results
* NRC - No Detailed Affiliation Given BX17 058 81/10/06
Office of Nuclear Reactor Regulation, Director 11pp 26516 045 24X Fiche 50-329,84/07/18,8408010061

--8408030051 Handwritten notes re addl boring logs at buried diesel generator fuel oil storage tank location Calculation sheets & boring logs encl
MEISENHEIMER,J NRC - No Detailed Affiliation Given BX17 060 82/03/29 KANE,J NRC - No Detailed Affiliation Given 13pp 26516 057 24X Fiche 50-329,84/07/18,8408010061

--8408030056 Handwritten notes re 810120 meeting w/applicant on settlement of Category I underground piping
KANE,J NRC - No Detailed Affiliation Given BX17 061 81/02/09
CAPPUCCI,T NRC - No Detailed Affiliation Given 4pp 26516 070 24X Fiche 50-329,84/07/18,8408010061

--8408030058 Forwards evaluation of general acceptability of effects of settlement in several buried svc piping sys Rept partial response to FSAR Questions 16 through 20 & 34
KLEIN,D R Bechtel Corp BX17 062 80/08/01 CURTIS,L H Bechtel Corp 7pp 26516 074 24X Fiche 50-329,84/07/18, 8408010061

--8408030064 Forwards analysis of buried piping background info, in support of proposed demonstration solution & in response to NRC concern re underground piping Addl engineering info encl
KEELEY,G S Consumers Power Co BX17 063 81/12/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 76pp 26516 081 24X Fiche 50-329,84/07/18,8408010061

--8408030068 Forwards stress analysis of several underground pipe lines as profiled in Rev 6 of "Responses to NRC 10CFR50 54(f) Requests re Plant Fill" dtd B00401
BATES,J D Rockwell International Corp BX17 064 80/10/01
BOSNAK,R J Mechanical Engineering Branch 52pp 26516 162 24X Fiche 50-329,84/07/18,8408010061

--8408130227 Contract for consulting svcs between util & Mgt Analysis Co, agreeing to perform technical svcs, including consulting & QA svcs Purchase requisition, internal memos & supporting documentation encl
COOK,J W Consumers Power Co BX15 001 82/01/15 350pp 26500 316 24X Fiche 50-329,84/07/18,8408010061

--8408130230 Discusses 830118 & 26 meetings in Glen Ellyn, IL re Region III insp of diesel generator bldg & independent design review program, respectively Midland project manager will attend 830126 public meeting
ADENSAM,E G Licensing Branch 4 BX15 002 83/01/05 NOVAK,T M Assistant Director for Licensing 19pp 26502 089 24X Fiche 50-329,84/07/18,8408010061

--8408130234 Draft memo re issues of potential impact on Hearing Board considerations concerning QA program
KEPPLER,J G Region 3, Office of Director BX15 003 82/04/02
EISENHUT,D G Division of Licensing 7pp 26502 121 24X Fiche 50-329,84/07/18,8408010061

--8408130241 Notification of 821207 mgt meeting w/Region III to discuss implementation of QA & IDVPs
HERNAN,R W Licensing Branch 4 BX15 004 82/11/01 NOVAK,T M Assistant Director for Licensing 2pp 26502 131 24X Fiche 50-329,84/07/18,8408010061

--8408130244 Forwards SALP 3 schedule Internal memos, handwritten in-process insp notices, program notes & supporting documentation encl
TAMBLING,T N Region 3, Office of Director BX15 005 82/11/01
Region 3, Office of Director 53pp 26502 133 24X Fiche 50-329,84/07/18,8408010061

--8408130255 Forwards response to draft SALP rept Requests meeting w/ Keppler to review detailed contents of response Internal memos & handwritten notes encl
COOK,J W Consumers Power Co BX15 006 82/05/17 KEPPLER,J G Region 3, Office of Director 91pp 26502 188 24X Fiche 50-329,84/07/18,8408010061

--8408130269 "Const Project Evaluation of Consumers Power Co, Midland Energy Ctr Project, Units 1 & 2 (Observations) "
* Management Analysis Co BX15 007 83/01/31 160pp 26502 311 24X Fiche 50-329,84/07/18,8408010061

--8408130290 Forwards Mgt Analysis Co assessment of Midland QA program Rept endorses program W/o encl
COOK,J W Consumers Power Co BX15 008A 81/06/01 KEPPLER,J G Region 3, Chicago, Office of the Director (81/03/01) 40pp 26503 178 24X Fiche 50-329,84/07/18,8408010061

DOCKETED ITEMS

8408130301 Submits changes to be implemented prior to util resuming remedial soils work Draft list of noncompliances & deviations, handuritten notes & list of events since Jul 1981 hearings encl
WARNICK, R F Region 3, Office of Director BX15 010 82/09/20
KEPPLER, J G Region 3, Office of Director 70pp 26504 031 24X
Fiche 50-329, 84/07/18, 8408010061

8408130306 "Biennial QA Audit of Midland Plant, Units 1 & 2 " Opening remarks of NRC 830208 meeting w/util & independent review encl
* Management Analysis Co BX15 011 83/03/01 75pp 26504 131
24X Fiche 50-329, 84/07/18, 8408010061

8408130311 Notification of significant licensee 830315 meeting in Glen Ellyn, IL to present INPO findings
* Region 3, Office of Director BX15 012 83/03/09 Region 3, Office of Director 1p 26504 261 24X Fiche 50-329, 84/07/18, 8408010061

8408130320 Forwards status rept for Midland Project for Jan 1983 W/o encl
WARNICK, R F Region 3, Office of Director BX15 013 83/02/14
KEPPLER, J G Region 3, Office of Director 1p 26504 293 24X
Fiche 50-329, 84/07/18, 8408010061

8408130323 Forwards status rept for Jan 1983 Rept contains input from each member of insp site team of Ofc of Special Cases
COOK, R J Region 3, Office of Director BX15 014 83/02/10
SHAFER, W D Region 3, Office of Director 3pp 26504 294 24X
Fiche 50-329, 84/07/18, 8408010061

8408130327 Forwards monthly status repts for Aug-Oct 1982
WARNICK, R F Region 3, Office of Director BX15 015 82/12/20
KEPPLER, J G Region 3, Office of Director 10pp 26504 303 24X
Fiche 50-329, 84/07/18, 8408010061

8408130336 Requests approval not to perform SALP 3 assessments, due to widespread recognition of mgt, QA & const problems Draft notice of violation, insp rept & handuritten notes re diesel generator bldg monorail encl
KEPPLER, J G Region 3, Office of Director BX15 017 83/04/01
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 98pp 26505 043 24X Fiche 50-329, 84/07/18, 8408010061

8408130348 Submits issues to be addressed at forthcoming evidentiary session on QA & QC matters
PATON, W D Consumers Power Co BX15 019 82/08/10 ADENSAM, E G
NRC - No Detailed Affiliation Given 6pp 26505 276 24X
Fiche 50-329, 84/07/18, 8408010061

8408130356 Forwards monthly status rept for Midland Project for Jan 1983
COOK, R J Region 3, Office of Director BX15 022 83/02/10
SHAFER, W D Region 3, Office of Director 3pp 26505 302 24X
Fiche 50-329, 84/07/18, 8408010061

8408140039 Draft IE Insp Repts 50-329/78-20 & 50-330/78-20 from insp on 781211-20 & 790104-25 Violations noted inadequate control & supervision of plant fill matl placement & const specs not followed
PHILLIP, G A , GALLAGHER, E J , MAXWELL, G F Region 3, Office of Director BX16 002 84/07/18 60pp 26507 112 24X
Fiche 50-329, 84/07/18, 8408010061

8408140050 Summary of NRC 790607 site tour & meeting on differential settlement of plant bldgs TC Cooke 790706 ltr to Bechtel re stainless steel pipe deficiency encl
COOKE, T C Consumers Power Co BX16 003 79/06/13 Consumers Power Co 4pp 26507 311 24X Fiche 50-329, 84/07/18, 8408010061

8408140055 Preliminary "Discussion of NRC Insp Facts Resulting From NRC Investigation of Diesel Generator Bldg Settlement "
* Consumers Power Co BX16 004 79/03/05 35pp 26507 315
24X Fiche 50-329, 84/07/18, 8408010061

8408140060 Forwards synopsis of 800228 presentation, "Remedial Measures for Electrical Penetration Wings of Control Bldg & Isolation Valve Pits" conducted before NRC representatives in Midland, MI
GOULD, C H Affiliation Not Assigned BX16 005 80/03/17
AFIFI, S S Bechtel Corp 22pp 26507 350 24X
Fiche 50-329, 84/07/18, 8408010061

8408140065 Forwards general procedures & details employed by contractor to underpin fine arts bldg Sketches encl
MARR, G Bechtel Corp BX16 006 79/04/25 AFIFI, S Bechtel Corp 6pp 26508 010 24X Fiche 50-329, 84/07/18, 8408010061

8408140069 Lists areas to be clarified &/or amplified, in responses to 10CFR50 54(f) questions Summary of soils chronology & 790807 internal memo re pre-meeting w/consultants encl
COOKE, T C Consumers Power Co BX16 007 80/01/25
ROTHWELL, M G Bechtel Corp 14pp 26508 016 24X
Fiche 50-329, 84/07/18, 8408010061

8408140071 Submits const QC response to 790329 questions re diesel generator bldg No variance exists from QA program requirements
JOHNSON, D R Bechtel Corp BX16 008 79/04/09 RICHARDSON, G L
Bechtel Corp 9pp 26508 030 24X Fiche 50-329, 84/07/18, 8408010061

8408140076 Comments on recommendations given in soils repts prepared by Dames & Moore as compared to Bechtel earthwork specs Plant area fill supporting surrounding structures, Category I slopes & berm fill discussed
AFIFI, S S Bechtel Corp BX16 009 74/09/13 CASTLEBERRY, R
Bechtel Corp 5pp 26508 039 24X Fiche 50-329, 84/07/18, 8408010061

8408140079 Recommends issuance of revised TPO std specs re large settlement due to incorrectly placed backfill Addl correspondence on problem alert & summary of soils chronology encl
RUMBAUGH, E Bechtel Corp BX16 010 79/12/27 JOHNSON, T E
Bechtel Corp 33pp 26508 044 24X Fiche 50-329, 84/07/18, 8408010061

8408140102 Forwards complete set of all abstracts of transcripts of hearings conducted on 811231-830630 W/listing of entire set of abstracts
HAMPTON, L Isham, Lincoln & Beale BX16 012 83/07/18
PATON, W D Hearing Branch 2 425pp 26508 097 24X
Fiche 50-329, 84/07/18, 8408010061

8408140134 Handuritten notes re borings in area of svc water piping that have indicated potential for liquefaction W/Dept of Army memo re Feb 1980 visit to util & review of FSAR
KANE, J NRC - No Detailed Affiliation Given BX16 014 82/10/14
19pp 26510 227 24X Fiche 50-329, 84/07/18, 8408010061

8408140144 Testimony of HN Singh re unresolved geotechnical engineering safety issues, including reactor bldg foundation, diesel generator bldg settlement & svc water bldg foundation & borated water tanks
SINGH, H N Army, Dept of, Corps of Engineers BX16 016
84/07/18 13pp 26510 319 24X Fiche 50-329, 84/07/18, 8408010061

8408140152 Handuritten notes on admission of facts re plant fill problem & cracking of certain safety-related structures resulting from inadequately compacted fill matls W/ handuritten notes re discussion w/B Paton on hearings
* NRC - No Detailed Affiliation Given BX16 017 81/03/06 2pp
26510 331 24X Fiche 50-329, 84/07/18, 8408010061

8408140158 Notifies of plan to take depositions of Bechtel employees in Ann Arbor beginning on 801209 Depositions will address errors made in soil placement
PATON, W D Office of the Executive Legal Director BX16 018
80/11/19 OLMSTEAD, W J Regulations Division 2pp 26510 333
24X Fiche 50-329, 84/07/18, 8408010061

8408140163 Presents reasons why Phase II const will not be detrimental to foundation support of auxiliary bldg Phase II primary consists of 3x6 ft hand dug piers & 7x6 ft wide access drifts for access to pier
KANE, J , BARTLETT, B NRC - No Detailed Affiliation Given BX16 019 82/01/19 11pp 26510 335 24X Fiche 50-329, 84/07/18, 8408010061

8408140170 Handuritten notes re general description of extent of plant fill problem Proposed remedial measures, list of viewgraphs & viewgraphs for ACRS presentation encl
KANE, J NRC - No Detailed Affiliation Given BX16 020 82/04/26
37pp 26510 346 24X Fiche 50-329, 84/07/18, 8408010061

8408140185 Confirms comments previously provided re Item E on Page 5 of 830715 ltr concerning slope layback during underpinning Item E expresses concern by B&W inspectors that slope layback is greater than in design
POULOS, S J Geotechnical Engineers, Inc BX16 022 83/09/22
KANE, J Office of Nuclear Reactor Regulation, Director 2pp
26511 029 24X Fiche 50-329, 84/07/18, 8408010061

8408140196 Summarizes comments re 830914-15 audit of facility underpinning Purpose of audit was to gather info from applicant re effect on design & const of reducing modulus of hard clay foundation from 3000 Ksf to 5000 Ksf
POULOS, S J Geotechnical Engineers, Inc BX16 023 83/09/22
KANE, J Office of Nuclear Reactor Regulation, Director 3pp
26511 031 24X Fiche 50-329, 84/07/18, 8408010061

--8408140209 Handwritten notes re design details for borated water storage tanks & util position on cause of cracking
KANE, J NRC - No Detailed Affiliation Given BX16 024 81/07/28
2pp 26511 050 24X Fiche 50-329,84/07/18,8408010061

--8408140213 Handwritten summary of 810805 meeting in Ramada Central Inn re borated water storage tank W/810728 handwritten memo re status of review on borated water storage tank
KANE, J NRC - No Detailed Affiliation Given BX16 025 81/08/05
NRC - No Detailed Affiliation Given 2pp 26511 052 24X
Fiche 50-329,84/07/18,8408010061

--8408140218 Handwritten notes re discussion w/G Gallagher about surcharging of valve pits near borated water tanks Record of telcon w/util,Bechtel & Geotechnical Engineering on 810715 re surcharging valve pits encl
* NRC - No Detailed Affiliation Given BX16 026 81/07/01 4pp
26511 054 24X Fiche 50-329,84/07/18,8408010061

--8408140223 Handwritten notes reviewing comments on borated water storage tanks & valve pit settlements
KANE, J NRC - No Detailed Affiliation Given BX16 027 81/07/28
1p 26511 074 24X Fiche 50-329,84/07/18,8408010061

--8408140232 Forwards draft comments on info received from applicant through Amend 85 to OL request & Rev 10 to 10CFR50 54(f) requests re borated water tanks Info received addresses all questions raised in 800707 ltr
MCCALLISTER,P Army, Dept of, Corps of Engineers BX16 028
81/03/26 JACKSON,R E NRC - No Detailed Affiliation Given
14pp 26511 075 24X Fiche 50-329,84/07/18,8408010061

--8408140242 Forwards branch position re seismological input parameters Position necessary to resolve differences between applicant & NRC on seismological issues & to provide guidance for inputing vibratory motion in evaluations
JACKSON,R E Geosciences Branch BX16 030 80/07/08
SCHWENCER,A Licensing Branch 3 6pp 26511 101 24X
Fiche 50-329,84/07/18,8408010061

--8408140248 Urges studies evaluating soil liquefaction & stability under dynamic loading & using values of acceleration in range of 0 12g to 0 19g at ground surface Also forwards list of strong motion records
ROTHMAN,R L Geosciences Branch BX16 031 80/02/11
JACKSON,R E Geosciences Branch 9pp 26511 107 24X
Fiche 50-329,84/07/18,8408010061

--8408140263 Motion to consolidate for discovery,evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sys founded in & on plant fill matl in hearing considering 791206 order
FARNELL,A S Consumers Power Co FARNELL,A S Isham, Lincoln & Beale BX16 034 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24X Fiche 50-329,84/07/18,8408010061

--8408140286 Testimony of H Singh re origin remedial measures proposed by applicant for auxiliary bldg & Corps of Engineers evaluation of remedial measures
SINGH,H NRC - No Detailed Affiliation Given BX16 0388
81/11/12 5pp 26511 242 24X Fiche 50-329,84/07/18,8408010061

--8408140296 Draft testimony of SJ Poulos re remedial underpinning of svc water pump structure
POULOS,S J Geotechnical Engineers, Inc BX16 040 82/03/30
11pp 26511 271 24X Fiche 50-329,84/07/18,8408010061

--8408140300 Testimony of HN Singh re svc water pump structure
SINGH,H N Geotechnical Engineers, Inc BX16 041 82/04/08
7pp 26511 282 24X Fiche 50-329,84/07/18,8408010061

--8408140319 Summary of 810917 meeting w/CPC,US Army Corps of Engineers, NRC,Bechtel & Mueser,Rutledge,Wentworth & Johnson in Bethesda,MD re preliminary design of proposed remedial measures for svc water pumping structure
SINGH,H N Army, Dept of, Corps of Engineers BX16 044
81/09/18 Army, Dept of, Corps of Engineers 3pp 26511 341
24X Fiche 50-329,84/07/18,8408010061

--8408140347 Summary of 820422 meeting w/CPC,consisting of answers to GES questions re permanent dewatering sys,soil stabilization,jacking procedure & draft SER
KANE, J NRC - No Detailed Affiliation Given BX16 046 82/06/25
NRC - No Detailed Affiliation Given 4pp 26511 348 24X
Fiche 50-329,84/07/18,8408010061

--8408140352 "Dynamic Cone Penetrometer " Sketchs & design calculations of underpinning & settlement analysis study encl
ANDERSON,J NRC - No Detailed Affiliation Given BX16 047
82/03/17 42pp 26512 056 24X Fiche 50-329,84/07/18,8408010061

--8408140359 Handwritten notes re settlement monitoring programs, classification of fines,instrumentation & agenda for 781204 meeting re diesel generator bldg
* NRC - No Detailed Affiliation Given BX16 049 84/07/18
10pp 26512 210 24X Fiche 50-329,84/07/18,8408010061

--8408140367 Draft ltr re Interagency Agreement NRC-03-76-167,Task 1, Subtask 3 concerning comment on Amend 85 List of specific discrepancies re settlement evaluations encl
SINGH,H Army, Dept of, Corps of Engineers BX16 051 81/02/26
KANE,J , JACKSON,R E NRC - No Detailed Affiliation Given 13pp
26512 221 24X Fiche 50-329,84/07/18,8408010061

--8408140513 Summary of R Landsman 810325-27 & 0407-09 insps conducted to verify QA program for util soil borings conducted in response to Corps of Engineers request for addl soil info
* NRC - No Detailed Affiliation Given BX16 054 84/07/18 4pp
26512 259 24X Fiche 50-329,84/07/18,8408010061

--8408140522 Informs that,in preparation for issuance of draft SER in mid-late Jan,section by section review of which sections of draft received by Div of Licensing to date complete
HERNAN,R W Licensing Branch 4 BX16 055A 82/01/12
ADENSAM,E G Licensing Branch 4 3pp 26512 269 24X
Fiche 50-329,84/07/18,8408010061

--8408140526 Summarizes 810608 stipulation filed by util & NRC re QA aspects of hearing on soils settlement scheduled to begin 810707
HOOD,D Licensing Branch 4 BX16 056 81/06/08 DENTON,H ,
CARTER,J Office of Nuclear Reactor Regulation, Director
EISENHUT,D G Division of Licensing 1p 26512 272 24X
Fiche 50-329,84/07/18,8408010061

--8408140530 Draft memo providing estimate for completing review & preparing testimony on proposed remedial actions,in response to OELD request for schedule for review
LEAR,J NRC - No Detailed Affiliation Given BX16 057 81/06/19
KNIGHT,J NRC - No Detailed Affiliation Given 3pp 26513 185
24X Fiche 50-329,84/07/18,8408010061

--8408140539 Requests estimate of time required to complete review & prepare testimony re proposed remedial actions Testimony by F Rinaldi,T Cappucci & J Kane needs to be filed by 810915
PATON,W D Office of the Executive Legal Director BX16 057A
81/07/18 KNIGHT,J P Assistant Director for Comp & Structures Engineering (Pre 830201) 1p 26513 188 24X
Fiche 50-329,84/07/18,8408010061

--8408140553 Util news ltr re lifting of part of series of stop work orders that halted const of plant
* Consumers Power Co BX16 061 84/01/20 1p 26513 249 24X
Fiche 50-329,84/07/18,8408010061

--8408140556 Documents contacts by Kirkland & Ellis attys representing Dow Chemical in suit against CPC Summary of meeting by Geotechnical Engineering,Inc encl,
KANE,J D Structural & Geotechnical Engineering Branch BX16 062
84/01/23 Structural & Geotechnical Engineering Branch 14pp
26513 263 24X Fiche 50-329,84/07/18,8408010061

--8408140557 Forwards comments re applicant submissions concerning cracks in diesel generator,fixation of cracks in borated water storage tanks,underpinnings & effects or cracks on serviceability of structures
MCCALLISTER,P Army, Dept of, Corps of Engineers BX16 063
82/06/15 LEAR,G Division of Engineering 14pp 26513 277
24X Fiche 50-329,84/07/18,8408010061

--8408140562 Handwritten document summarizing util response to NRC Questions 24,45 & 47 on permanent dewatering re geotechnical engineering issues Meeting summaries encl
* Consumers Power Co BX16 064 81/10/12 32pp 26513 291
24X Fiche 50-329,84/07/18,8408010061

--8408140565 Handwritten document re liquefaction analysis
KANE,J C NRC - No Detailed Affiliation Given BX16 065
82/08/16 3pp 26513 323 24X Fiche 50-329,84/07/18,8408010061

--8408140566 Requests analysis of possible enforcement action re applicant failure to inform NRC of settlement of diesel generator bldg
PALLADINO,N NRC - No Detailed Affiliation Given BX16 066
84/05/24 DIRCKS,W Office of the Executive Director for Operations 1p 26514 031 24X Fiche 50-329,84/07/18,8408010061

--8408140570 "Administrative Bldg Foundation Settlements Along Column Line O 4 "
* Bechtel Corp BX16 068 77/12/31 21pp 26514 033 24X
Fiche 50-329,84/07/18,8408010061

--8408140573 Forwards Bechtel rept, "Administrative Bldg Foundation Settlements Along Column Line O 4 "
BRUNNER, J E Consumers Power Co BX16 067 81/09/14 PATON, W
NRC - No Detailed Affiliation Given 1p 26514 032 24X
Fiche 50-329, 84/07/18, 8408010061

--8408140575 Handuritten summary of 781204 site meeting re excessive settlement of diesel generator bldg & foundations & other Category I structures
GALLAGHER, G Region 3, Office of Director BX16 069 78/12/07
HOOD, D NRC - No Detailed Affiliation Given 8pp 26514 068
24X Fiche 50-329, 84/07/18, 8408010061

--8408150015 Requests addl borings & existing soil data Revised Encl 1 to 800327 ltr encl
MCCALLISTER, P Army, Dept of, Corps of Engineers BX16 071
84/07/18 JACKSON, R E NRC - No Detailed Affiliation Given 6pp
26514 140 24X Fiche 50-329, 84/07/18, 8408010061

--8408150019 Handwritten notes re status of ASLB hearings First session, completed 810707-17, covered items re Stamiris Contention I, QA breakdown, NRC-util stipulation on QA managerial attitude & FSAR false statement
KANE, J NRC - No Detailed Affiliation Given BX16 072 81/08/18
11pp 26514-146 24X Fiche 50-329, 84/07/18, 8408010061

--8408150022 Handwritten notes re location of sources of important util submittals prior to 791204 Topics outlined include auxiliary bldg, diesel generator bldg, borated water storage tank & permanent dewatering
KANE, J NRC - No Detailed Affiliation Given BX16 073 81/05/18
31pp 26514:157 24X Fiche 50-329, 84/07/18, 8408010061

--8408150027 Summary of 840304 meeting w/util re schedules & topics for instant hearing on soils matters Hearing schedule resulting in inefficient reviews due to changing const priorities by applicant
HOOD, D Licensing Branch 4 BX16 075 82/03/11 TEDESCO, R L
Assistant Director for Licensing 43pp 26514 191 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150029 Task interface agreement re plant remedial soils issue
IPPOLITO, T Region 3, Office of Director NORELIUS, C Director's Office, Office of Inspection and Enforcement VOLLMER, R Office of Nuclear Reactor Regulation, Director BX16 076 83/04/18
3pp. 26514 234 24X Fiche 50-329, 84/07/18, 8408010061

--8408150033 Discusses 830929 conference call during which D Hood gave verbal approval to allow licensee to proceed w/underpinning through UATs
LANDSMAN, R B Region 3, Office of Director BX16 077 83/09/30
Region 3, Office of Director 1p 26514 241 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150042 Handwritten notes commenting on Peck 810807 transcript re compaction criteria
KANE, J NRC - No Detailed Affiliation Given BX16 079. 81/08/10
2pp 26514 264 24X Fiche 50-329, 84/07/18, 8408010061

--8408150046 Handuritten notes re electrical penetration area w/comments of H Singh on unresolved issues prior to 791206 & underground utils
SINGH, H NRC - No Detailed Affiliation Given BX16 080
81/05/20 2pp 26514 266 24X Fiche 50-329, 84/07/18, 8408010061

--8408150560 Comments on licensee draft commitments to improve implementation of quality program in remedial soils area & remaining const activities, per 820907 request Noted changes should be made in program
WARNICK, R F Region 3, Office of Director. BX21 001 82/09/24
KEPPLER, J G Region 3, Office of Director 4pp 26549 080 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150566 "Pier Load Test Data - Load by Carlson vs Load by Jacks "
Related info encl
HUNT, S W Bechtel Corp BX21 003 83/04/29 200pp 26549 215
24X Fiche 50-329, 84/07/18, 8408010061

--8408150571 "Well OBS-4 Subsidence Rept "
HUNT, S. W Bechtel Corp BX21 004 82/06/11 50pp 26550 120
24X Fiche 50-329, 84/07/18, 8408010061

--8408150577 Forwards recent audit repts by Midland QA dept, per request
BRUNNER, J E Consumers Power Co BX21 005. 82/01/15
BECHHOEFER, C., HARBOUR, J Atomic Safety and Licensing Board Panel
COWMAN, F P Affiliation Not Assigned. 26pp 26550 222 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150586 Forwards recent audit repts by Midland QA dept, per request Related info encl, including notes of CPC/NRC 830208 public meeting re const completion program
BRUNNER, J E Consumers Power Co BX21 006 82/02/05
BECHHOEFER, C , HARBOUR, J Atomic Safety and Licensing Board Panel
COWMAN, F P Affiliation Not Assigned 106pp 26550 248 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150595 Opposes issuance of fuel license (10CFR70) for applicant, based upon extensiveness of remedial soils work & potential for work to impact auxiliary bldg Related info encl
COOK, R J Region 3, Office of Director BX21 007 83/01/25
SHAFER, W D Region 3, Office of Director 19pp 26551 001 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150608 Rev 4 to "Quality Plan for Underpinning Activities " Related info encl
BIRD, W , BOOS, A J , MOONEY, J Consumers Power Co BX21 009
82/10/12 59pp 26551 316 24X Fiche 50-329, 84/07/18, 8408010061

--8408150616 Enumerates QA issues to be addressed at evidentiary session in Midland proceeding, per encl 820707 memorandum & order W/o encl
PATON, W D Office of the Executive Legal Director BX21 011
82/08/10 ADENSAM, E G NRC - No Detailed Affiliation Given 2pp
26553 087 24X Fiche 50-329, 84/07/18, 8408010061

--8408150617 Forwards further response to FOIA-84-96, consisting of records selected from files of Harrison & Morelius during 840628 visit
ROY, G W Office of Resource Management, Director BX20 001
84/07/06 RICE, C M Kirkland & Ellis 3pp 26537 339 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150624 Draft summary of NRC 840229 meeting w/util at Region III ofc re results of NRC HVAC insps & investigation of allegations & expansion of QA training, qualification & certification activities Viewgraphs encl.
* Region 3, Office of Director BX20 002 84/02/29 Region 3, Office of Director 21pp 26537 342 24X Fiche 50-329, 84/07/18, 8408010061

--8408150626 Forwards HR Denton 831219 ltr distinguishing between terms "important to safety" & "safety-related " Related info encl
KEPPLER, J G Region 3, Office of Director BX21 013 83/12/29
Region 3, Office of Director 5pp 26553 163 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150630 Forwards addl info re Region III inquiries into Ofc of Special Cases concerning Midland & Zimmer Nuclear Power Plant problems in implementing QA programs Nonconformance rept also encl
WARNICK, R F Region 3, Office of Director BX20 003 83/09/16
BOULDEN, H Office of Inspector & Auditor 18pp 26538 001 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150635 Notifies that commercial operation date of Unit 2 may be delayed until mid-1986 Const schedule for Unit 1 will be revised based on cashflow requirements, need for power, final cost estimates & schedule for Unit 2
KOSCHIK, M G Consumers Power Co BX21 015 83/11/09 STRASMA, J
Region 3, Office of Director 2pp 26553 216 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150643 Forwards listed documentation in response to FOIA 83-397 for reproduction
WARNICK, R F Region 3, Office of Director BX20 006 83/07/20
SMIDTH, P T Region 3, Office of Director 1p 26538 156 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150648 Draft summary of NRC Caseload Forecast Panel 830419-21 meeting w/util at plant site re basis for util revised estimates of Oct 1984 & Feb 1985 for Unit 2 & 1, respectively Rept on Rev 12 schedule encl
NOVAK, T. M Assistant Director for Licensing BX20 007 83/05/25
COOK, J W Consumers Power Co 32pp 26538 157 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150651 Requests NRC approval to postpone yellowbook update due to inadequate work experience enabling development of definitive project schedule, per 831014 ltr
GUAMME, D L Consumers Power Co BX20 008 84/01/12
HARTFIELD, R A Management Information Branch 1p 26539 002
24X Fiche 50-329, 84/07/18, 8408010061

--8408150652 Notifies of intent to continue const of plant following recent notification from Dow Chemical Co of decision to terminate agreement to purchase energy Related info encl
FITZPATRICK, R Consumers Power Co BX21 019 83/07/15
STRASMA, J Region 3, Office of Director 72pp 26554 061 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150656 Responds to 840409 comments re util proposed plan to conduct independent mgt appraisal of Midland Nuclear Project Affidavits of independence of individuals working on audit encl
REHM,T A Office of the Executive Director for Operations BX20 009 84/04/08 GARDE,B P Government Accountability Project 31pp 26539 014 24X Fiche 50-329,84/07/18,8408010061

--8408150662 Enumerates agreements/understandings reached at 820823 meeting w/NRC re approval for portions of Phase II underpinning work Related info encl
MILLER,D B Consumers Power Co BX21 021 82/08/25 SHAFER,W D Region 3, Office of Director 14pp 26554 241 24X Fiche 50-329,84/07/18,8408010061

--8408150665 Comments on util 840307 proposed independent mgt plan Plan does not indicate how Cresap,McCormick & Paget & TERA will function & interface Roles,authorities & responsibilities should be identified Handwritten comments encl
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement BX20 011 84/03/27 KEPPLER,J G Region 3, Office of Director 4pp 26539 052 24X Fiche 50-329,84/07/18, 8408010061

--8408150666 Summary of NRC 840314 meeting w/D Bridenbaugh of MAB Technical Assocs in Region III re info on Midland & Zimmer plants Util 840124 ltr to Atty General of State of MI encl
WARNICK,R F Region 3, Office of Director BX20 012 84/03/20 Region 3, Office of Director 7pp 26539 136 24X Fiche 50-329,84/07/18,8408010061

--8408150676 Forwards util testimony on cable pulling incident Requests comments Lists questions to be addressed
WILCOVE,M N Office of the Executive Legal Director BX20 014 83/05/13 LANDSMAN,R , COOK,R , GARDNER,R NRC - No Detailed Affiliation Given 7pp 26539 306 24X Fiche 50-329,84/07/18, 8408010061

--8408150681 Discusses policy & procedure changes re communications w/ licensee Related info encl
WARNICK,R F Region 3, Office of Director BX21 027 82/09/17
SPESSARD,R L Division of Project & Resident Programs
NORELIUS,C E Division of Engineering HIND,J A Division of Radiological & Materials Safety Programs 8pp 26555 067 24X Fiche 50-329,84/07/18,8408010061

--8408150682 Advises that FOIA Request 82-616 received,Matl requested must be submitted to director by 840103 Nonconformance repts & Interim Rept 3 re cable tray support const welding discrepancy encl
SMIDTH,P T Region 3, Office of Director BX20 015 82/12/22 Region 3, Office of Director 2pp 26539 359 24X Fiche 50-329,84/07/18,8408010061

--8408150685 Discusses QA program re Underpinning instrumentation installation Lists steps to follow to implement reclassification of underpinning activities
COOK,J W Consumers Power Co BX21 028 82/03/31 NORELIUS,C E Division of Engineering 2pp 26555 110 24X Fiche 50-329,84/07/18,8408010061

--8408150686 Advises that allegations received from Dow Chemical & util are treated equally Forwards E Driker 840504 ltr re Dow Chemical vs CPC lawsuit
BERKOVITZ,D M Office of the General Counsel BX20 016 84/05/11 LEWIS,S H Region 3, Office of Director 1p 26540 094 24X Fiche 50-329,84/07/18,8408010061

--8408150689 Submits summary of views re regulatory status of plant Illegible handwritten notes encl
KEPPLER,J G Region 3, Office of Director BX20 016A 84/04/06
FISCHER,R Michigan, State of 12pp 26540 095 24X Fiche 50-329,84/07/18,8408010061

--8408150692 Forwards newspaper stories indicating representives of Dow Chemical met w/NRC to discuss matters in litigation pending in County Circuit Court w/util JD Selby 840608 ltr to FJ Kelley encl
DRIKER,E Barris, Sott, Denn & Driker BX20 017 84/05/04
BERKOVITZ,D. Office of the General Counsel 18pp 26540 160 24X Fiche 50-329,84/07/18,8408010061

--8408150695 "Site Visit to Evaluate Crack Reported 830218 in Roof of Feedwater Isolation Valve Pit Unit 1,Midland Nuclear Power Plant " Draft confirmatory orders,handwritten notes & RF Warnick memo re FOIA Request 84-24 encl
CORLEY,W G Construction Technology Laboratories BX20 019 83/02/28 111pp 26540 178 24X Fiche 50-329,84/07/18, 8408010061

--8408150700 Forwards draft confirmatory order prepared by IE re plan for independent appraisal of site & corporate mgt organizations Requests review prior to meeting
LIEBERMAN,S NRC - No Detailed Affiliation Given BX20 020 83/12/30 KEPPLER, WARNICK, HARRISON NRC - No Detailed Affiliation Given 10pp 26540 335 24X Fiche 50-329,84/07/18, 8408010061

--8408150706 Advises that S Lewis leaving Region III to assume position of Deputy Assistant Chief Hearing Counsel in OELD B Derson replacement Chronological list of reactor holddown bolt encl
KEPPLER,J G Region 3, Office of Director BX20 022 84/05/14 Region 3, Office of Director 12pp 26541 263 24X Fiche 50-329,84/07/18,8408010061

--8408150709 Summary of 800523 meeting w/util,B&W,Bechtel & Teledyne in Bethesda,MD re preservice failure of three reactor vessel holddown studs List of attendees,agenda & viewgraph slides encl Sketches for underpinning auxiliary bldg encl
HOOD,D S Licensing Branch 3 BX20 023 80/07/07 Licensing Branch 3 82pp 26541 328 24X Fiche 50-329,84/07/18,8408010061

--8408150710 Assessment rept QA program,performed during Mar & Apr 1981
* Management Analysis Co BX21 033 81/06/01 400pp 26555 182 24X Fiche 50-329,84/07/18,8408010061

--8408150712 "Quality Program for Underpinning Activities "
* Consumers Power Co BX20 024A 82/04/05 22pp 26542 132 24X Fiche 50-329,84/07/18,8408010061

--8408150714 "Independent Assessment of Underpinning 90-Day Rept "
KILBER,W E Stone & Webster, Inc BX21 034 83/04/30 250pp 26556 194 24X Fiche 50-329,84/07/18,8408010061

--8408150716 "Test Program Status & Rev 12 - Test Schedule "
* Consumers Power Co BX21 035 83/04/12 100pp 26557 091 24X Fiche 50-329,84/07/18,8408010061

--8408150718 Documents conclusions & commitments made at 820330 meeting & 820402 telcons re QA applied to remedial foundation work Expansion of QA program recognized in overall success of project "Quality Program for Underpinning Activities" encl
COOK,J W Consumers Power Co BX20 024B 82/04/05 KEPPLER,J G Region 3, Office of Director 4pp 26542 154 24X Fiche 50-329,84/07/18,8408010061

--8408150720 "Electrical Raceway Support Tests Rept,Part 1 "
NOWAK,A S Bechtel Corp BX21 036 81/11/25 100pp 26557 192 24X Fiche 50-329,84/07/18,8408010061

--8408150723 Forwards CPC testimony on alleged violation of Board order Investigation of violation coming in future Requests analysis of testimony & comments Handwritten notes encl
WILCOVE,M N Office of the Executive Legal Director BX20 026 83/05/13, LANDSMAN,R , COOK,R , HOOD,D NRC - No Detailed Affiliation Given 99pp 26542 165 24X Fiche 50-329,84/07/18, 8408010061

--8408150725 Requests review of attached draft SALP rept in preparation for 830706 SALP Board meeting.
WARNICK,R F Region 3, Office of Director BX20 027 83/07/01 HIND,J A , NORELIUS,C E , SPESSARD,R L NRC - No Detailed Affiliation Given. 149pp 26542 288 24X Fiche 50-329,84/07/18, 8408010061

--8408150727 Summarizes 800227-28 meeting at site re soils settlement issue & effects Handwritten note encl
GALLAGHER,E Region 3, Chicago, Office of the Director. BX20 034 80/03/03 FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 46pp 26544 306 24X Fiche 50-329,84/07/18,8408010061

--8408150728 Forwards advance copy of proposed rev to Manual Chapter 0516,SALP,for review
NORELIUS,C E Division of Project & Resident Programs. BX20 035 84/04/13 Region 3, Office of Director 2pp 26545 069 24X Fiche 50-329,84/07/18,8408010061

--8408150729 Advises of problems concurring w/proposed response to M Cherry 770427 ltr as noted by detailed comments provided Requests redraft be considered
REINMUTH,G W Division of Reactor Construction Inspection BX20 029, 77/06/10 HOEFLING,R.K Office of the Executive Legal Director 7pp 26543 234 24X Fiche 50-329,84/07/18,8408010061,

--8408150731 Advises of possible ex parte contact in facility proceeding Requests memo & attached summary of discussion be served to all parties in proceeding & PDR
GIBSON,T.R. NRC - No Detailed Affiliation Given BX20 030 80/12/24 CHILK,S J Office of the Secretary of the Commission 2pp 26543 250 24X Fiche 50-329,84/07/18,8408010061

DOCKETED ITEMS

--8408150732 Notifies that incorrect target dates entered in 830219 SALP schedule Correct target dates provided
NORELIUS,C E Division of Project & Resident Programs BX20 035A 84/03/08 HIND,J A Division of Radiological & Materials Safety Programs SPESSARD,R L Division of Engineering DOUGHERTY,D J Office of Resource Management, Director 2pp 26545 117 24X Fiche 50-329,84/07/18,8408010061

--8408150734 Revises previously issued SALP 4 schedule dtd 831004,by extending assessment to 18 months Rev incorporates addl milestone dates
NORELIUS,C E Division of Project & Resident Programs BX20 035B 83/12/19 Region 3, Office of Director 2pp 26545 119 24X Fiche 50-329,84/07/18,8408010061

--8408150735 Requests concurrence on proposed auxiliary bldg guideline, "Guidelines for Bldg Movements During Temporary Underpinning " Handwritten notes & communications record w/Warnick re withdrawal of potential 10CFR50 55(e) encl
MOONEY,J A Consumers Power Co BX20 031 84/05/25
HARRISON,J J Region 3, Office of Director 25pp 26543 252 24X Fiche 50-329,84/07/18,8408010061

--8408150737 Forwards NRC Manual Chapter 0516,SALP Evaluation criteria published in FR on 820322 for public comments Comments due by 820701
TAMBLING,T N Region 3, Office of Director BX20 035C 82/05/04 AXELSON,W L , BARRETT,P A , BOYD,D C NRC - No Detailed Affiliation Given 3pp 26545 123 24X Fiche 50-329,84/07/18, 8408010061

--8408150738 Forwards summary of 840229 meeting in Region III ofc re results of HVAC insps & investigation of allegations & expansion of training,qualification & certification activities Handwritten notes encl
WELLS,R A Consumers Power Co BX20 032 84/03/29
HARRISON,J J Region 3, Office of Director 169pp 26544 014 24X Fiche 50-329,84/07/18,8408010061

--8408150740 "Chapter 0516 SALP," describing basis structure & overall procedures for implementation of NRC program to assess licensee performance MA Miller marked-up memo re evaluation of SALP encl
* Director's Office, Office of Inspection and Enforcement BX20 035D 82/03/23 47pp 26545 126 24X Fiche 50-329,84/07/18, 8408010061

--8408150741 Forwards "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking "
LEVIN,H A TERA Corp BX20 033 83/01/04 KEPPLER,J G , EISENHUT,D G Region 3, Office of Director COOK,J W Consumers Power Co 4pp 26544 212 24X Fiche 50-329,84/07/18,8408010061

--8408150743 Submits reasons for extending SALP III evaluation period to 821231 Rept contains issues being resolved between NRC & licensee Extension can be used as performance motivator Handwritten note & supporting documentation encl
COOK,R J Region 3, Office of Director BX20 036 82/08/06
SPESSARD,R L Division of Project & Resident Programs 350pp 26545 173 24X Fiche 50-329,84/07/18,8408010061

--8408150745 "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking " Handwritten notes encl
* TERA Corp BX20 033A 83/01/04 89pp 26544 214 24X Fiche 50-329,84/07/18,8408010061

--8408150747 Submits supplemental SALP input for facility Changes required to provide overall Div of Engineering & Technical Insp rating for QA functional area & consolidate comments for recommended increased insp frequency
PIRTLE,G Region 3, Office of Director BX20 037 83/10/01
BOYD,D Region 3, Office of Director 1p 26547 011 24X Fiche 50-329,84/07/18,8408010061

--8408150749 Forwards list of items reviewed by util & determined ready for review & closure by NRC Handwritten notes & supporting documentation encl
HELLS,R A Consumers Power Co BX20 038A 83/10/04
KEPPLER,J G Region 3, Office of Director 147pp 26547 165 24X Fiche 50-329,84/07/18,8408010061

--8408150750 Forwards SALP input except for Matls & Processes Section
PIRTLE,G Division of Engineering & Technical Inspection BX20 038 81/09/22 BOYD,D Division of Engineering & Technical Inspection 137pp 26547 012 24X Fiche 50-329,84/07/18, 8408010061

--8408150751 Forwards const status rept as of 791001 Handwritten notes re diesel generator bldg & soil settlement & errata to NUREG-0834 encl
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch BX20 041A 79/10/05 KNOP,R C , HAYES,D W , DANIELSON,D H NRC - No Detailed Affiliation Given 107pp 26548 359 24X Fiche 50-329,84/07/18,8408010061

--8408150752 Submits QA issues to be addressed at evidentiary session in facility proceeding Summary rept & oral communications record re reinsp requirements based on results of certification testing encl
PATON,W D NRC - No Detailed Affiliation Given BX20 041 82/08/10 ADENSAM,E G NRC - No Detailed Affiliation Given 18pp 26548 075 24X Fiche 50-329,84/07/18,8408010061

--8408170081 "Response to NRC Staff Review Concerns for Underpinning of Auxiliary Bldg "
* Consumers Power Co BX19 001 82/06/03 40pp 26529 122 24X Fiche 50-329,84/07/18,8408010061

--8408170102 Forwards addl documents re facility soils issue,in response to request for info
DREHOBL,K E Consumers Power Co BX19 003 82/04/12
FISCHER,D C ACRS - Advisory Committee on Reactor Safeguards 7pp 26530 009 24X Fiche 50-329,84/07/18,8408010061

--8408170141 Requests review of files to determine documents withholdable under FOIA,per FOIA-84-96
LEWIS,S H NRC - No Detailed Affiliation Given BX19 009
84/05/08 HARRISON,J J , GARDNER,R , LANDSMAN,R NRC - No Detailed Affiliation Given 1p 26530 066 24X Fiche 50-329,84/07/18,8408010061

--8408170145 Forwards draft ltr to util re review of licensee 830310,0624 & 0712 responses to 830208 & 0523 notice of violation & proposed imposition of civil penalty Recommends imposition of $120,000 civil penalty
SCHULTZ,W H Region 3, Office of Director BX19 010 83/07/28
AXELRAD,J A Director's Office, Office of Inspection and Enforcement 165pp 26530 067 24X Fiche 50-329,84/07/18, 8408010061

--8408170166 Testimony of RN Gardner re allegations concerning qualification of personnel employed by Comstock
GARDNER,R N Region 3, Office of Director BX19 012A 84/07/18 100pp 26530 321 24X Fiche 50-329,84/07/18,8408010061

--8408170187 Forwards rept results re special electrical overinsp requested by NRC to support testimony concerning adequacy of certification/qualification process of Bechtel electrical QC inspectors
SHAEFFER,M J Consumers Power Co BX19 015 82/02/25 COOKE,R NRC - No Detailed Affiliation Given BIRD,W R , COOK,J W Consumers Power Co 14pp 26531 048 24X Fiche 50-329,84/07/18, 8408010061

--8408170195 Draft "Rept on Cable Installation "
* Consumers Power Co BX19 014 82/05/14 111pp 26531 038 24X Fiche 50-329,84/07/18,8408010061

--8408170253 Discusses W Marshal telcon re permanent dewatering well being drilled at northeast corner of diesel generator bldg on 820519 Drilling mud flushed into line when drilling line broke No further comment necessary
LANDSMAN,R B Region 3, Office of Director BX19 031 82/06/14
PATON,W Office of the Executive Legal Director 2pp 26533 325 24X Fiche 50-329,84/07/18,8408010061

--8408170257 Summary of ACRS Subcommittee on Midland Units 1 & 2 820520 & 21 meetings w/util in Midland,MI re review of OL application
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards BX19 032 82/08/09 OKRENT,D ACRS - Advisory Committee on Reactor Safeguards 13pp 26533 359 24X Fiche 50-329,84/07/18, 8408010061

--8408170260 Informs of review of encl allegations re Comstock QC at site Ofc of Investigations responsible for continuing investigation
HARNICK,R F Region 3, Office of Director BX19 033 82/11/16
FOSTER,J E Office of Investigation 125pp 26534 010 24X Fiche 50-329,84/07/18,8408010061

--8408170279 "Structural Stresses Induced by Differential Settlement of Diesel Generator Bldg "
* Consumers Power Co BX19 037 84/07/18 51pp 26535 255 24X Fiche 50-329,84/07/18,8408010061

--8408170284 Summary of 810502-04 meeting w/util & Bechtel in Bethesda MD re remedial actions & update of soils deficiencies & to review Amend 85 to application
LANDSMAN,R B Region 3, Office of Director BX19 039 81/05/12
WILLIAMS,C C Region 3 Office of Director 65pp 26536 043
24X Fiche 50-329,84/07/18,8408010061

--8408170320 Summary of 840202-05 meeting w/util,Bechtel & consultants in Ann Arbor,MI re discussion & audit of preparations for underpinning southern part of auxiliary bldg Viewgraphs encl
HOOD,D Licensing Branch 4 BX19 045 84/02/22 Licensing Branch 4 81pp 26536 189 24X Fiche 50-329,84/07/18,8408010061

--8408170358 S&W 840209 public meeting re cracking criteria & cracking mapping program
* Consumers Power Co BX19 046 84/02/09 Consumers Power Co 2pp 26536 349 24X Fiche 50-329,84/07/18,8408010061

--8408170360 Submits list of documents supplied or withheld by JJ Harrison & RB Landsman,in response to FOIA Request 84-24
WARNICK,R F Region 3, Office of Director BX19 047 84/01/18
SMITH,P T Region 3, Office of Director 2pp 26536 351 24X
Fiche 50-329,84/07/18,8408010061

--8408170365 Handwritten summary of 840104 public meeting w/util,S&W Bechtel re monthly activities,crack rept,crack mapping & open items Supporting documentation & attendance list encl
* Consumers Power Co BX19 048 84/01/13 Consumers Power Co 74pp 26536 356 24X Fiche 50-329,84/07/18,8408010061

--8408170367 Crack mapping monitoring status rept for 831031-1130, including handwritten status rept of 831208 S&W meeting & info re grillage acceptance criteria
* Consumers Power Co BX19 049 84/08/01 10pp 26537 107
24X Fiche 50-329,84/07/18,8408010061

--8408170372 Handwritten summary of 831110 public meeting Re tracking open items of new crack monitoring procedures 831009-1105
* Consumers Power Co BX19 050 83/11/10 Consumers Power Co 3pp 26537 129 24X Fiche 50-329,84/07/18,8408010061

--8408170377 Handwritten notes re auxiliary bldg & underpinning design including settlement stress,results of areas of max stress & rigid body rotation
* Consumers Power Co BX19 053 84/08/01 76pp 26537 253
24X Fiche 50-329,84/07/18,8408010061

--8408210367 Agenda for 780502 site visit w/util Bechtel & NUS Agenda for 781204 meeting w/util & Bechtel on site encl
* NRC - No Detailed Affiliation Given BX18 001 78/05/02
NRC - No Detailed Affiliation Given 6pp 26521 049 24X
Fiche 50-329,84/07/18,8408010061

--8408210377 Notification of 780907 meeting w/Midland Technical Reviewers in Washington,DC to discuss project status of facility safety review Reviewers will be asked to summarize review status on problem areas affecting review schedule
HOOD,D Light Water Reactors Branch 4 BX18 003 78/09/06
NRC - No Detailed Affiliation Given 7pp 26521 091 24X
Fiche 50-329,84/07/18,8408010061

--8408210379 Provides info in response to B Garde FOIAs 83-451,-452,-454 & -449
HOOD,D Licensing Branch 4 BX18 023 83/08/19 WILSON,V NRC - No Detailed Affiliation Given 2pp 26524 336 24X
Fiche 50-329,84/07/18,8408010061

--8408210384 Notification of rescheduled 790718 meeting w/util & Bechtel in Bethesda,MD to discuss abnormal settlement of fill & structures at site Agenda & attendance list encl
HOOD,D Light Water Reactors Branch 4 BX18 004 79/06/13
VARGA,S A Light Water Reactors Branch 4 7pp 26521 100 24X
Fiche 50-329,84/07/18,8408010061

--8408210386 Forwards B Garde FOIA request for documents re meetings between NRC,TERA & util on 830518,0608 & 23 concerning independent design verification W/draft ltr to util re implementation of Ford Amend
WILSON,V H Management Analysis Branch BX18 024 83/08/09
Management Analysis Branch 2pp 26524 338 24X
Fiche 50-329,84/07/18,8408010061

--8408210392 Forwards B Garde FOIA 83-452 request for documents re 830615 Commission briefing
WILSON,V H Management Analysis Branch BX18 025 83/08/09
Management Analysis Branch 2pp 26524 354 24X
Fiche 50-329,84/07/18,8408010061

8408210397 Forwards B Garde FOIA 83-454 request for documents re re-review of structural adequacy of diesel generator bldg
WILSON,V H Management Analysis Branch BX18 026 83/08/10
LEAR,G Hydrologic & Geotechnical Engineering Branch BOSNAK,R Mechanical Engineering Branch 2pp 26524 358 24X
Fiche 50-329,84/07/18,8408010061

--8408210401 Forwards B Garde FOIA Request 83-449 for documents submitted by util re consideration of candidate companies or methodologies to perform const implementation overview of const completion plan
WILSON,V H Management Analysis Branch BX18 027 84/08/09
Management Analysis Branch 2pp 26525 001 24X
Fiche 50-329,84/07/18,8408010061

--8408210404 Determines that info transmitted by 830721 memo should be issued as Board Notification 83-106
EISENHUT,D G Division of Licensing BX18 028 84/07/18
NOVAK,T Assistant Director for Licensing 1p 26525 152 24X
Fiche 50-329,84/07/18,8408010061

--8408210410 Board Notification 83-016 forwards notice of violation & proposed imposition of civil penalties,based on util failure to implement adequate QA program for installation of electrical,mechanical & civil components
NOVAK,T M Division of Licensing BX18 029 84/02/15 Atomic Safety and Licensing Board Panel 1p 26525 160 24X
Fiche 50-329,84/07/18,8408010061

--8408210411 Handwritten questions for RB Peck re consultant responsibilities & settlement monitoring Handwritten deposition of RB Beck encl
* NRC - No Detailed Affiliation Given BX18 008 81/01/31
NRC - No Detailed Affiliation Given 36pp 26521 228 24X
Fiche 50-329,84/07/18,8408010061

--8408210414 Forwards Board Notification 83-16 which supersedes 830215 notification
NOVAK,T M NRC - No Detailed Affiliation Given BX18 030
84/02/18 Atomic Safety and Licensing Board Panel 1p
26525 184 24X Fiche 50-329,84/07/18,8408010061

--8408210418 Submits package received from B Jones from H Singh, consisting of questions of Dr Peck by H Singh,J Dunnicliff 800208 ltr to S Afifi & summary of J Kane deposition
SINGH,H NRC - No Detailed Affiliation Given BX18 009
84/07/18 JONES,B NRC - No Detailed Affiliation Given 36pp
26521 269 24X Fiche 50-329,84/07/18,8408010061

--8408210421 "Questions for Davisson 810114-15 Deposition " Questions of Dr Peck on testimony,dtd 810725 encl
* NRC - No Detailed Affiliation Given BX18 010 81/01/11
34pp 26521 305 24X Fiche 50-329,84/07/18,8408010061

--8408210425 "Questions for Davisson 810114-15 Deposition "
* NRC - No Detailed Affiliation Given BX18 011 81/01/11
43pp 26522 070 24X Fiche 50-329,84/07/18,8408010061

--8408210430 Draft memo informing of status of NRC-03-79-16T,Task 1, Subtask 3 Index of Davisson deposition encl
SINGH,H NRC - No Detailed Affiliation Given BX18 012
80/10/16 LEAR,G Hydrologic & Geotechnical Engineering Branch
17pp 26522 116 24X Fiche 50-329,84/07/18,8408010061

--8408210433 Recommends issuance of encl matl as Board Notification 84-083 re update on stop work status & NRC staffing changes Related info encl
EISENHUT,D G Division of Licensing BX18 016 84/04/18
NOVAK,T Division of Licensing 2pp 26522 350 24X
Fiche 50-329,84/07/18,8408010061

--8408210446 Summary of 820202-05 meeting w/util & Bechtel in Ann Arbor, MI re audit preparations for underpinning southern portion of auxiliary bldg Bechtel meeting notes & viewgraphs encl
HOOD,D Licensing Branch 4 BX18 019 84/02/22 Licensing Branch 4 79pp 26523 232 24X Fiche 50-329,84/07/18,8408010061

--8408210450 Determines that encl rept on review of diesel generator bldg should be issued as Board Notification 83-165
EISENHUT,D G Division of Licensing BX18 020 83/10/28
NOVAK,T Assistant Director for Licensing 4pp 26524 302 24X
Fiche 50-329,84/07/18,8408010061

--8408210453 "Observed Settlements (Inches) of Structures,790930 to Present " Summary of soil properties & summary of soils info encl
WANZEC,T NRC - No Detailed Affiliation Given BX18 037
80/08/27 10pp 26527 199 24X Fiche 50-329,84/07/18,8408010061

DOCKETED ITEMS

-8408210455 Agenda for 800930 meeting w/util on site for appeal of NRC position
* NRC - No Detailed Affiliation Given BX18 039 84/07/18
NRC - No Detailed Affiliation Given 1p 26527 209 24X
Fiche 50-329,84/07/18,8408010061

-8408210461 Trip rept of 831005-07 site visit re design review & audit of HVAC sys
TERAO,D Mechanical Engineering Branch BX18 052 83/10/28
BOSNAK,R J Mechanical Engineering Branch 17pp 26528 234 24X
Fiche 50-329,84/07/18,8408010061

--8408210463 Draft notes recommending that listed actions be considered by Region III in effort to improve licensee regulatory attitude & performance & increase assurance that completed & ongoing const work acceptable
* NRC - No Detailed Affiliation Given BX18 046 82/08/06 4pp
26528 034 24X Fiche 50-329,84/07/18,8408010061

--8408220070 Delineates Control Sys Branch position on identification of protection sys instrument sensing lines & requests position be transmitted to near-term OL applicants
SPEIS,T P Assistant Director for Reactor Safety BX19 025
84/07/18 TEDESCO,R L Assistant Director for Licensing 3pp
26533 051 24X Fiche 50-329,84/07/18,8408010061

--8408220085 Attendance list of 820223 meeting w/util,chronological list events before & after issuance of NRC order modifying CPs, plant underpinning questions re svc water pump structure & review of 1981 technical rept on underpinning
* NRC - No Detailed Affiliation Given BX19 036A 82/02/23
38pp 26534,327 24X Fiche 50-329,84/07/18,8408010061

--8408220090 "Observed Cracks in Walls of Midland Plant Structures "
CORLEY,W G , FIORATO,A E Portland Cement Association BX19 031A
82/06/14 32pp 26533 327 24X Fiche 50-329,84/07/18,
8408010061

--8408270315 Draft ltr informing of decision re addl soil borings & testing NRC request for sampling & testing coaling pond embankments reconsidered & relocation of certain borings determined
VOLLMER,R H Division of Engineering BX18 010A 80/11/03
COOK,J W Consumers Power Co 1p 26522 022 24X
Fiche 50-329,84/07/18,8408010061

--8408270323 Submits listed items that inspectors consider to be indicative of questionable licensee performance
COOK,R J Region 3, Office of Director BX19 019 82/07/23
WARNICK,R F Region 3, Office of Director 11pp 26531 291 24X
Fiche 50-329,84/07/18,8408010061

8408140311 Summary of 810917 meeting w/CPC re preliminary design of mods to svc water pump structure to resolve concerns resulting from inadequate compaction of site fill
KANE,J NRC - No Detailed Affiliation Given BX16 043 81/10/30
NRC - No Detailed Affiliation Given 2pp 26511 339 24X
Fiche 50-329,84/07/18,8408060061

8408020014 Advises that util Board of Directors ordered shutdown of design const & testing activities for facilities on 840716 CP & OL applications for both units will be maintained Issuance of SSER 4 (NUREG-0793) requested
COOK,J W Consumers Power Co 84/07/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 25883 116 24X
Fiche 50-329,84/07/27,8408020014

8408070173 Responds to 840726 request for authorization to complete soils shutdown activities Util authorized to proceed w/activities listed in 840726 ltr
HARRISON,J J Region 3, Office of Director 84/07/31 MOONEY,J A
Consumers Power Co 2pp 25949 343 24X Fiche 50-329,84/07/31,
8408070173

--8408070180 Requests authorization to complete proposed listed soils shutdown activities Updates of stop work activities will be provided to Region III
MOONEY,J A Consumers Power Co 84/07/26 HARRISON,J J Region 3, Office of Director 4pp 25949 345 24X Fiche 50-329,
84/07/31,8408070173

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408130399 Finalizes limits for control of movements of control tower & electrical penetration areas during soils shutdown activities,based on review of latest settlement data obtained during 840801-03 site visit List of limits encl
HARRISON,J J Region 3, Office of Director 84/08/08 MOONEY,J A
Consumers Power Co 3pp 26010 185 24X Fiche 50-329,84/08/08,
8408130399

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408270239 Confirms 840824 meeting w/util in Glenn Ellyn,IL to discuss plans for facilities
WARNICK,R F Region 3, Office of Director 84/08/22 COOK,J W
Consumers Power Co 1p 26239 156 24X Fiche 50-329,84/08/22,
8408270239

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329,84/07/18,8408010061

--8209230536 Forwards discussion of deficiencies noted in Supplemental SER 2 Requests mod to attached draft be provided addressing concerns
NOVAK,T M Assistant Director for Licensing BX18 040 82/08/27
KNIGHT,J P Assistant Director for Comp & Structures Engineering (Pre 830201) 3pp 26527 243 24X Fiche 50-329,84/07/18,
8408010061

--8408150612 Draft final SSER re geotechnical engineering Related info encl
KANE,J D Hydrologic & Geotechnical Engineering Branch BX21 010
82/08/12 78pp 26553 002 24X Fiche 50-329,84/07/18,
8408010061

--8408210454 Submits marked-up ltr re program for plant soils remedial work,in response to draft SER open items
COOK,J W Consumers Power Co BX18 047 82/09/07 DENTON,H R
Office of Nuclear Reactor Regulation, Director 47pp 26528 039
24X Fiche 50-329,84/07/18,8408010061

8408020014 Advises that util Board of Directors ordered shutdown of design const & testing activities for facilities on 840716 CP & OL applications for both units will be maintained Issuance of SSER 4 (NUREG-0793) requested
COOK,J W Consumers Power Co BX18 047 84/07/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 25883 116 24X
Fiche 50-329,84/07/27,8408020014

F Security, medical, emergency & fire protection plans

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329,84/07/18,8408010061

--8408170268 Discusses 830922 off-the-record meeting w/Bechtel employee re allegations concerning inadequacy of plant fire detection sys Concerns raised re copyright laws concerning App R to 10CFR50
BURGESS,B L Region 3, Office of Director BX19 034 83/09/26
ROY,G W Region 3, Office of Director 39pp 26534 246 24X
Fiche 50-329,84/07/18,8408010061

0 Adjudicatory correspondence

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18,
RICE,C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329,84/07/18,8408010061

--8010160005 Submits questions in response to request for interrogatory input re hearing
LEAR,G E Hydrologic & Geotechnical Engineering Branch BX17 013
80/10/06 MIRAGLIA,F Licensing Branch 3 2pp 26518 144 24X
Fiche 50-329,84/07/18,8408010061

--8104230479 Submits comments on applicant response to NRC Interrogatories 1-3 No results available for review of Interrogatories 1 & 2 since no consolidation tests on samples were obtained from surcharged area of plant fill
MCCALLISTER,P Army, Dept of, Corps of Engineers BX17 014
81/03/27 LEAR,G Hydrologic & Geotechnical Engineering Branch
2pp 26518 150 24X Fiche 50-329,84/07/18,8408010061

--8210270126 Forwards input for testimony for 821027-1104 ASLB hearings Stamiris Contention 4 C b re dewatering & svc water pump structure should be addressed by Structural Engineering Branch
LEAR,G Hydrologic & Geotechnical Engineering Branch BX17 018
82/10/15 ADENSAM,E Licensing Branch 4 4pp 26519 005 24X
Fiche 50-329,84/07/18,8408010061

--8211030222 Forwards Hydrdological & Geotechnical Engineering Branch input for testimony at ASLB 821027-1104 hearings re bearing capacity beneath diesel generator bldg,piping svc water pump structure & permanent dewatering
LEAR,G Hydrologic & Geotechnical Engineering Branch BX17 017
82/10/14 ADENSAM,E G Licensing Branch 4 9pp 26518 358 24X
Fiche 50-329,84/07/18,8408010061

--8301190487 Assigns NRC sponsors for each of M Sinclair rewritten contentions for OL hearing Schedule for filing of testimony forthcoming
HOOD,D S Licensing Branch 4 BX17 024 83/01/14 NOVAK,T M
Assistant Director for Licensing 1p 26519 072 24X
Fiche 50-329,84/07/18,8408010061

--8309270366 Responds to 830523 & 0910 requests for assistance in reviewing util proposed findings of fact & conclusions of law on remedial soils issues Agrees w/findings Recommends paragraph re occurence of liquefaction be revised
BALLARD,R L Environmental & Hydrologic Engineering Branch BX17
037 83/09/14 PATON,W D Office of the Executive Legal
Director 2pp 26520 062 24X Fiche 50-329,84/07/18,8408010061

--8309270518 Forwards comments on util proposed findings of fact & conclusions of law on remedial soils issues
JACKSON,R E Geosciences Branch BX17 038 83/09/21 PATON,W D
Hearing Branch 2 5pp 26520 064 24X Fiche 50-329,84/07/18,
8408010061

--8310050136 Discusses structural engineering review of "Applicants Proposed Findings of Facts & Conclusions of Law on Remedial Soil Issues" along w/related info on seismic models & borated water storage tanks resulting from ASLB hearings
LEAR,G Structural & Geotechnical Engineering Branch BX17 035
83/09/22 PATON,W Office of the Executive Legal Director 5pp
26520 051 24X Fiche 50-329,84/07/18,8408010061

--8310070101 Forwards comments on applicant proposed findings of fact & conclusions of law on remedial soil issues
LEAR,G Structural & Geotechnical Engineering Branch BX17 035A
83/09/29 PATON,W Office of the Executive Legal Director 4pp
26520 052 24X Fiche 50-329,84/07/18,8408010061

--8310240291 Informs that structural review of document "Applicant Proposed Findings of Facts & Conclusions of Law on Remedial Soil Issues," completed Structures adequate Comments encl
LEAR,G Structural & Geotechnical Engineering Branch BX17 036
83/10/14 PATON,W Office of the Executive Legal Director 5pp
26520 056 24X Fiche 50-329,84/07/18,8408010061

--8408020071 Forwards draft answers to util interrogatories re definition of acceptance criteria of 791206 order on mod Opinion as to whether items in brackets should be deleted requested
KANC,J NRC - No Detailed Affiliation Given BX17 006 81/02/24
HOOD,D NRC - No Detailed Affiliation Given 1p 26515 058
24X Fiche 50-329,84/07/18,8408010061

--8408020074 Draft answers to util interrogatories re definition of acceptance criteria on Page 3 of 791206 order on mod
* NRC - No Detailed Affiliation Given BX17 006A 84/07/18
Consumers Power Co 87pp 26515 059 24X Fiche 50-329,84/07/18,
8408010061

--8408020086 Marked-up copy of Rev 1,Vol 4 to FSAR re stability of subsurface matls & foundations,questions re response to Interrogatories 13-16 & interpretations of intent of Interogatory 13
KANE,J NRC - No Detailed Affiliation Given BX17 009 77/11/30
12pp 26517 302 24X Fiche 50-329,84/07/18,8408010061

--8408020107 Forwards motions,1980 audit repts & input re upcoming util QA decision Applicant acceptance of poor quality performance by Bechtel criticized
STAMIRIS,B Stamiris, B BX17 011 81/05/26 KEPPLER,J G
Region 3, Office of Director 2pp 26518 132 24X
Fiche 50-329,84/07/18,8408010061

--8408020127 Summary of NRC recommendations of ASLB position re Stamiris Contention 2 including draft ASLB proposed findings & input into NRC testimony re Peck 790810 statement on electrical penetration area structures
KANE,J NRC - No Detailed Affiliation Given BX17 016 81/10/19
9ipp 26518 268 24X Fiche 50-329,84/07/18,8408010061

--8408020171 Summarizes issues to be covered at ASLB 830214-18 hearing, including Stamiris contentions,Warren contention & seismic shakedown for all structures other than diesel generator bldg
* NRC - No Detailed Affiliation Given BX17 019 83/01/05 9pp
26519 009 24X Fiche 50-329,84/07/18,8408010061

--8408020177 Suggests schedule for testimony to answer Warren Contentions 1-3,Stamiris Contention 4,Sinclair Contention 24 & Marhsall Contention 2 in Feb & Mar hearings Text of contentions encl Suggests inclusion of rebuttals to contentions
BLUME,M NRC - No Detailed Affiliation Given BX17 020
82/01/27 HOOD,D , KANE,J , RINALDI,F NRC - No Detailed
Affiliation Given 7pp 26519 020 24X Fiche 50-329,84/07/18,
8408010061

--8408020180 Forwards input to staff testimony in preparation for ASLB 821115-23 hearings,in response to W Paton verbal request & M Wilcove request Structural Engineering Branch input applicable only to svc water pump structure
SCHAUER,F P Structural Engineering Branch BX17 022 82/10/22
ADENSAM,E G Licensing Branch 4 5pp 26519 050 24X
Fiche 50-329,84/07/18,8408010061

--8408020181 Comments on applicant 840805 proposed findings of fact conclusions of law on remedial soils issues,including items re auxiliary bldg & svc water pump structure
POULOS,S J Geotechnical Engineers, Inc BX17 031 83/09/23
KANE,J Division of Engineering 4pp 26519 242 24X
Fiche 50-329,84/07/18,8408010061

--8408020182 Responds to M Wilcove verbal request Structural Engineering Branch area of concern identified by Judge Harbour applies only to consideration of structure-to-structure interaction Outstanding contentions encl
SCHAUER,F P Structural Engineering Branch BX17 023 82/10/28
ADENSAM,E G Licensing Branch 4 7pp 26519 059 24X
Fiche 50-329,84/07/18,8408010061

--8408020183 Forwards response to applicant proposed findings of fact & conclusions of law on remedial soil issues Pagination needed Findings will be filed 831115
PATON,W D Hearing Branch 2 BX17 033 83/11/14 KANE,J NRC -
No Detailed Affiliation Given 1p 26519 315 24X
Fiche 50-329,84/07/18,8408010061

--8408020184 Forwards marked-up input to staff testimony in preparation for ASLB 821027-1104 hearings re bearing capacity & underground piping,in response to verbal request of W Paton & M Wilcove Response to Stamiris contention encl
LEAR,G E Hydrologic & Geotechnical Engineering Branch BX17
023A 82/10/14 ADENSAM,E G Licensing Branch 4 10pp
26519 062 24X Fiche 50-329,84/07/18,8408010061

--8408020185 Responsive findings to applicant proposed findings of fact & conclusions of law on remedial soil issues
PATON,W D , WILCOVE,M N Hearing Branch 2 BX17 034 83/11/15
100pp 26519 316 24X Fiche 50-329,84/07/18,8408010061

--8408020186 Response to R Landsman 830106 questions re B Stamiris Request 4(b) re excavation of deep "Q" duct bans in Freezewall Pit 4 & Tech Spec for static core penetrometer
KANE,J NRC - No Detailed Affiliation Given BX17 026 83/01/06
2pp 26519 146 24X Fiche 50-329,84/07/18,8408010061

--8408020187 Forwards updated version of Stamiris contentions,including addl Stamiris examples for Contentions 1,2 & 3 & changed wording of Contention 4C NRC testimony must address encl additions & changes
BROWN,E M NRC - No Detailed Affiliation Given BX17 025
81/05/19 Consumers Power Co 19pp 26519 124 24X
Fiche 50-329,84/07/18,8408010061

--8408020189 Forwards applicant testimony re alleged violation of ASLB 820430 order for determination of cross-examination List of questions re excavations & fireline piping provided
WILCOVE,M N Hearing Branch 2 BX17 042 83/05/13 LANDSMAN,R ,
COOK,R , HOOD,D NRC - No Detailed Affiliation Given 2pp
26520 116 24X Fiche 50-329,84/07/18,8408010061

DOCKETED ITEMS

8408020202 Discusses status of efforts re NRC Midland findings due 831115 Requests meeting at earliest date
HOOD, D NRC - No Detailed Affiliation Given BX17 041 83/09/23
PATON, W D , WILCOVE, M N Hearing Branch 2 7pp 26520 095 24X
Fiche 50-329, 84/07/18, 8408010061

8408140102 Forwards complete set of all abstracts of transcripts of hearings conducted on 811231-830630 W/listing of entire set of abstracts
HAMPTON, L Isham, Lincoln & Beale BX16 012 83/07/18
PATON, W D Hearing Branch 2 425pp 26508 097 24X
Fiche 50-329, 84/07/18, 8408010061

8408140298 Handwritten notes re ASLB actions on 800527 motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues concerning soil conditions for safety-related structures & sys
KANE, J NRC - No Detailed Affiliation Given BX16 033 80/06/09
1p 26511 158 24X Fiche 50-329, 84/07/18, 8408010061

8408140263 Motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sys founded in & on plant fill matl in hearing considering 791206 order
FARNELL, A S Consumers Power Co BX16 034 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24X
Fiche 50-329, 84/07/18, 8408010061

8408150702 Advises that Region III has no document re discovery request for info concerning alleged violation of ASLB order concerning remedial soils Handwritten notes, internal memos & list of repts, 1977 - 1983, encl
HARRISON, J J Region 3, Office of Director BX20 021 83/10/25
WRIGHT, N Office of the Executive Legal Director 199pp
26540 345 24X Fiche 50-329, 84/07/18, 8408010061

8408170223 Requests Commission review Director's Decisions DD-83-16 & DD-84-02 to require all ongoing activity be included under order of mod of CP & remove util from managerial responsibility of QA/QC function
GARDE, B P Government Accountability Project BX19 022
84/02/10 PALLADINO, N , GILINSKY, V , ASSELSTINE, J Commissioners
78pp 26532 090 24X Fiche 50-329, 84/07/18, 8408010061

8408210391 Notice of W Ferris, S Afifi & J Wanzeck 801028-29 deposition in Ann Arbor, MI re 791206 order modifying const permits Related info encl
PATON, W D Office of the General Counsel BX18 005 80/10/06
68pp 26521 126 24X Fiche 50-329, 84/07/18, 8408010061

8408210398 Notice of B Dahr 801217 deposition in Ann Arbor, MI re issues set forth in Licensing Board 791206 order modifying const permits & contentions of intervenors Stamiris & Warren Resume of TR Thiruvengadam encl
* Atomic Safety and Licensing Board Panel BX18 006 80/12/11
5pp 26521 199 24X Fiche 50-329, 84/07/18, 8408010061

07300142 Responds to 840210 petition for specific Commission actions under 10CFR2 206 Petition denied per encl Director's Decision DD-84-17
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement DSB 521 84/07/24 GARDE, B P Government Accountability Project GARDE, B P Lone Tree Council 3pp,
25807 232 24X Fiche 50-329, 84/07/24, 8407300142

8407300151 Director's Decision DD-84-17 denying Govt Accountability Project 840210 petition for three Commission actions re soils work, independent third party responsibility for QA & QC & Region III staffing
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/07/24 24pp 25807 235 24X
Fiche 50-329, 84/07/24, 8407300142

8407300156 Notice of issuance of Director's Decision DD-84-17, denying Govt Accountability Project 840210 petition for Commission action
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/07/24 69pp 25807 259 24X
Fiche 50-329, 84/07/24, 8407300142

08070377 Forwards NRC response to ASLB inquiry re Board Notification 84-115 dtd 840618 which identified specific hearing evidence adversely impacted by discrepancies in original seismic design calculations
PATON, W D Hearing Branch 2 DSB 816 84/08/02 BECHHOEFER, C , HARBOUR, J , COWAN, F P Atomic Safety and Licensing Board Panel
7pp 25947 158 24X Fiche 50-329, 84/08/02, 8408070377

08200573 Order extending time until 841020 for Commission to act to review Director's Decision DD-84-17 Served on 840820
CHILK, S J Office of the Secretary of the Commission DSB 154
84/08/17 PALLADINO, N J , ROBERTS, T M , ASSELSTINE, J K
Commissioners 1p 26137-051 24X Fiche 50-329, 84/08/17,
8408200573

K Utility Final Safety Analysis Report (FSAR) & amends

8408010061 Further response to FOIA request for 16 categories of records re Facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records BX14 000 84/07/18
RICE, C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329, 84/07/18, 8408010061

--8408170074 Rev 44 & 47 to FSAR Response to Audit Point 1 & handwritten summaries of S&W 831013 public meeting encl
* Consumers Power Co BX19 051 84/08/01 34pp 26537 170
24X Fiche 50-329, 84/07/18, 8408010061

O Advisory Committee on Reactor Safeguards reports & correspondence

8408010061 Further response to FOIA request for 16 categories of records re Facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records BX14 000 84/07/18
RICE, C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329, 84/07/18, 8408010061

--8205240603 Advises that ad hoc ACRS subcommittee recommendations re foundation problems & related remedial actions at facilities acceptable, per 820429 & 0506-08 meetings Discussion of seismic-related issues tentatively scheduled for 820520-21
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards BX14
003 82/05/14 DIRCKS, W J Office of the Executive Director for
Operations 1p 26500 027 24X Fiche 50-329, 84/07/18, 8408010061

--8206060008 Summarizes 266th ACRS meeting on 820603-05 Subj to satisfactorily completion of const & staffing & if due regard given to ACRS comments, plant can operate at 5% power w/o undue risk to public Full power recommendation deferred
SHEWMON, P ACRS - Advisory Committee on Reactor Safeguards BX14
004 82/06/08 PALLADINO, N Commissioners 6pp 26500 028
24X Fiche 50-329, 84/07/18, 8408010061

--8408010132 Forwards TERA Corp 830815 ltr describing four conceptual options for independent quality verification program methodologies Option 1 integral part of IDCVP at Midland
FISCHER, D ACRS - Advisory Committee on Reactor Safeguards BX14
001 83/11/15 ACRS - Advisory Committee on Reactor Safeguards
2pp 26500 012 24X Fiche 50-329, 84/07/18, 8408010061

--8408010135 Forwards QA/QC project status rept presented at ACRS 274th meeting on 830210
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards
BX14 002 83/03/03 ACRS - Advisory Committee on Reactor
Safeguards 6pp 26500 021 24X Fiche 50-329, 84/07/18,
8408010061

--8408010143 Forwards summary & conclusion of overall effectiveness portion of Region III rept on design & const problems Lack of aggressive QA attitude & overreliance on AE contribute to QA problems
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards
BX14 005 82/12/09 ACRS - Advisory Committee on Reactor
Safeguards 4pp 26500 034 24X Fiche 50-329, 84/07/18,
8408010061

--8408010147 Forwards JW Cook 810430 ltr & executive summary re QA program update, per 830215 request
SOMMERS, D A Consumers Power Co BX14 006 83/02/16
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards 1p
26500 038 24X Fiche 50-329, 84/07/18, 8408010061

--8408010152 Forwards status rept re QA/QC activities at facility to be presented at ACRS 274th meeting on 830210
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards
BX14 008 83/02/07 ACRS - Advisory Committee on Reactor
Safeguards 7pp 26500 058 24X Fiche 50-329, 84/07/18,
8408010061

--8408010153 Discusses major reduction in safety-related work at Midland ACRS comments to NJ Palladino encl
FISCHER, D ACRS - Advisory Committee on Reactor Safeguards BX14
009 82/12/09 ACRS - Advisory Committee on Reactor Safeguards
3pp 26500 065 24X Fiche 50-329, 84/07/18, 8408010061

--8408010163 Forwards cost estimate for once through steam generator overfill protection mod, per request
DREHOBL, K E Consumers Power Co BX14 012 82/08/17
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards
2pp 26500 073 24X Fiche 50-329, 84/07/18, 8408010061

--8408010168 Forwards SSER 1,addressing ACRS recommendations contained in 820608 interim rept Operating license review project status repts for 820520-21 & 0602 encl W/o SSER
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards BX14 013 82/07/19 OKRENT,D ACRS - Advisory Committee on Reactor Safeguards 12pp 26500 075 24X Fiche 50-329,84/07/18, 8408010061

--8408010173 Discusses util approach for satisfying safety review requirements at Big Rock Point,Palisades & Midland Summary of 820504 meeting & viewgraphs encl
FISCHER,D C ACRS - Advisory Committee on Reactor Safeguards BX14 014 82/05/17 ACRS - Advisory Committee on Reactor Safeguards 45pp 26500 087 24X Fiche 50-329,84/07/18, 8408010061

--8408010178 Forwards summary of ad hoc Subcommittee on Midland Units 1 & 2 820429 meeting Related info encl
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards BX14 016 82/05/06 SIESS,C ACRS - Advisory Committee on Reactor Safeguards 32pp 26500 133 24X Fiche 50-329,84/07/18, 8408010061

--8408010183 Discusses acceptability of Midland reactor pressure vessel anchor bolts,per util 811123 ltr & attached rept Expresses concern re rept sufficiency
SHEWMON,P G ACRS - Advisory Committee on Reactor Safeguards BX14 017 82/02/03 VOLLMER,R H Division of Engineering 1p 26500 173 24X Fiche 50-329,84/07/18,8408010061

--8408010188 Forwards util 800522 ltr identifying one of many QA problems at facility Incident re fill matl under vital structures noted in P Tam 800516 ltr Incidents should be considered in evaluation of need for subcommittee meeting
YOUNG,G G ACRS - Advisory Committee on Reactor Safeguards BX14 018 80/06/03 SHEWMON,P ACRS - Advisory Committee on Reactor Safeguards 1p 26500 174 24X Fiche 50-329,84/07/18,8408010061

--8408010191 Summary of 800523 meeting w/util in Bethesda,MD re reactor vessel holddown stud failures at facility
YOUNG,G G ACRS - Advisory Committee on Reactor Safeguards BX14 019 80/05/28 SHEWMON,P ACRS - Advisory Committee on Reactor Safeguards 3pp 26500 184 24X Fiche 50-329,84/07/18, 8408010061

--8408010195 Recommends review of foundation problems at facility Poor quality fill matl used under containment & other vital structures
TAM,P ACRS - Advisory Committee on Reactor Safeguards BX14 020 80/05/16 SHEWMON,P ACRS - Advisory Committee on Reactor Safeguards 1p 26500 187 24X Fiche 50-329,84/07/18,8408010061

--8408010198 Advises that unresolved safety issue exists in poor quality of fill matl under containment & other vital structures as evidenced by diesel generator bldg settlement
MCKINLEY,J C ACRS - Advisory Committee on Reactor Safeguards BX14 021 80/05/09 TAM,P ACRS - Advisory Committee on Reactor Safeguards 1p 26500 201 24X Fiche 50-329,84/07/18,8408010061

--8408010202 Forwards portions of FSAR for review of soil/foundation problems Site visit & subcommittee meeting will be arranged
MCKINLEY,J C ACRS - Advisory Committee on Reactor Safeguards BX14 022 80/03/21 OSTERBERG,J O Northwestern Univ , Evanston, IL 1p 26500 202 24X Fiche 50-329,84/07/18,8408010061

--8408010204 Discusses facility safe shutdown boration capability B&W Water Reactors Subcommittee review to explore proposed fixes suggested
MULLER,R ACRS - Advisory Committee on Reactor Safeguards BX14 023 79/11/14 ETHERINGTON,H ACRS - Advisory Committee on Reactor Safeguards 1p 26500 207, 24X Fiche 50-329,84/07/18, 8408010061

--8408010206 Summary of 790718 meeting w/util onsite re abnormal settlement of fill & structures Agenda & viewgraphs encl
ZUKOR,D J ACRS - Advisory Committee on Reactor Safeguards BX14 024 79/07/31 ACRS - Advisory Committee on Reactor Safeguards 78pp 26500 210 24X Fiche 50-329,84/07/18,8408010061

0 Inspection reports, IE Bulletins & correspondence

8408070183 Identifies activation completed &/or in progress, in response to IE Bulletin 83-07 re apparently fraudulent matl supplied by Ray Miller,Inc Final rept planned for 840901
COOK,J W Consumers Power Co 84/07/11 KEPPLER,J G Region 3, Office of Director 4pp 25950 025 24X Fiche 50-329,84/07/11, 8408070183

8408070227 Submits final response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Investigation performed by Bechtel determined three vendors supplied Tube-Line matl All Tube-Line matls removed from log
COOK,J W Consumers Power Co 84/07/11 KEPPLER,J G Region 3, Office of Director 3pp 25948 230 24X Fiche 50-329,84/07/11, 8408070227

8408030071 Forwards IE Insp Repts 50-329/84-21 & 50-330/84-22 on 840601-30 No noncompliance noted
WARNICK,R F Region 3, Office of Director 84/07/12 COOK,J W Consumers Power Co 2pp 25917 315 24X Fiche 50-329,84/07/12, 8408030071

--8408030076 IE Insp Repts 50-329/84-21 & 50-330/84-22 on 840601-30 No noncompliance noted Major areas inspected remedial soil work activities,allegations,turbine roll,status assessment, quality verification programs & progress
HARRISON,J J Region 3, Office of Director 84/07/12 5pp 25917 317 24X Fiche 50-329,84/07/12,8408030071

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329,84/07/18,8408010061

--8309130017 Discusses IE insp on 821012-1125 & 830119-21 & forwards order imposing civil monetary penalties in amount of $120,000 for violation re breakdown in implementation of QA program per 10CFR50,App B
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement BX21 018 83/08/29 SELBY,J D Consumers Power Co 3pp 26554 045 24X Fiche 50-329,84/07/18,8408010061

--8408020190 IE Investigation Rept 3-82-061 on 830103-0330 No noncompliance noted Major areas investigated allegations that util violated ASLB 820430 order re NRC approval for excavating in remedial soils program Investigation closed
WEIL,C H , PAWLICK,E T Region 3, Office of Director BX17 028 83/06/02 17pp 26519 178 24X Fiche 50-329,84/07/18,8408010061

--8408020194 IE Investigation Rept 3-82-061 on 830711-0808 No noncompliance noted Major areas investigated allegations that util violated ASLB 820430 order re NRC approval for excavating in remedial soils program Investigation reopened
WEIL,C H , PAWLICK,E T Region 3, Office of Director WARD,W J Office of Investigation BX17 029 83/09/12 20pp 26519 199 24X Fiche 50-329,84/07/18,8408010061

--8408020196 Provides Supplemental Ofc of Investigation Rept 3-82-061 re util alleged violation of ASLB order
HAYES,B B Office of Investigation BX17 030 83/09/12
KEPPLER,J G Region 3, Office of Director 3pp 26519 221 24X Fiche 50-329,84/07/18,8408010061

--8408140039 Draft IE Insp Repts 50-329/78-20 & 50-330/78-20 from insp on 781211-20 & 790104-25 Violations noted inadequate control & supervision of plant fill matl placement & const specs not followed
PHILLIP,D A Region 3, Office of Director BX16 002 84/07/18 60pp 26507 112 24X Fiche 50-329,84/07/18,8408010061

--8408140055 Preliminary "Discussion of NRC Insp Facts Resulting From NRC Investigation of Diesel Generator Bldg Settlement "
* Consumers Power Co BX16 004 79/03/05 35pp 26507 315 24X Fiche 50-329,84/07/18,8408010061

--8408140513 Summary of R Landsman 810325-27 & 0407-09 insps conducted to verify QA program for util soil borings conducted in response to Corps of Engineers request for addl soil info
* NRC - No Detailed Affiliation Given BX16 054 84/07/18 4pp 26512 259 24X Fiche 50-329,84/07/18,8408010061

--8408150622 Discusses basis for recommendation to extend SALP III evaluation period from 820630 to 821231,per 820719-20 discussions Related info encl
COOK,R J Region 3, Office of Director BX21 012 82/08/06
SPESSARD,R L Division of Project & Resident Programs 13pp 26553 145 24X Fiche 50-329,84/07/18,8408010061

--8408150624 Draft summary of NRC 840229 meeting w/util at Region III ofc re results of NRC HVAC insps & investigation of allegations & expansion of QA training,qualification & certification activities Viewgraphs encl
* Region 3, Office of Director BX20 002 84/02/29 Region 3, Office of Director 21pp 26537 342 24X Fiche 50-329,84/07/18, 8408010061

--8408150633 Forwards Rev 4 to "Region III SALP Schedule " Schedule changes to listed facilities explained in remarks sections of schedule Addl handwritten notes also encl
NORELIUS,C E Region 3, Office of Director BX20 004 84/06/04
KEPPLER,J G , DAVIS,A B , SPESSARD,R L Region 3, Office of Director 22pp 26538 025 24X Fiche 50-329,84/07/18,8408010061

--8408150639 Discusses Ofc of Special Cases special insp on 821012-1125 & forwards draft notice of violation re significant breakdown in implementation of QA program Handwritten NRR comments also encl
KEPPLER,J G Region 3, Office of Director BX20 005 83/01/05
COOK,J W Consumers Power Co 84pp 26538 049 24X
Fiche 50-329,84/07/18,8408010061

--8408150640 Ack receipt of 830926 ltr & payment in amount of $116,500 for civil penalty imposed by 830829 order
AXELRAD,J A Enforcement Staff BX21 016 83/10/04 SELBY,J D
Consumers Power Co 2pp 26553 305 24X Fiche 50-329,84/07/18,
8408010061

--8408150644 Forwards payment in amount of $116,500 in response to 830829 ltr imposing civil penalty for violations found during Insp 83-23 (EA 83-03) Related info encl, including matl on 830811 public meeting
COOK,J W Consumers Power Co BX21 017 83/09/26 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 29pp
26554 005 24X Fiche 50-329,84/07/18,8408010061

--8408150669 Corrects Page 3-1 of Attachment 3 to util 820517 response to draft SALP rept for Jul 1980 - June 1981, clarifying stop work order on drilling
COOK,J W Consumers Power Co BX21 024 82/05/21 KEPPLER,J G
Region 3, Office of Director 31pp 26554 313 24X
Fiche 50-329,84/07/18,8408010061

--8408150672 Forwards response to draft SALP rept for Jul 1980 - June 1981, discussed at 820426 meeting w/NRC
COOK,J W Consumers Power Co BX21 025 82/05/17 KEPPLER,J G
Region 3, Office of Director 38pp 26554 344 24X
Fiche 50-329,84/07/18,8408010061

--8408150677 Discusses SALP appraisals for Zimmer & Midland Suggests limited SALP-3 appraisal for Midland to cover remedial soils work, B&W work & HVAC activities
KEPPLER,J G Region 3, Office of Director BX21 026 83/04/18
HIND,J A Division of Radiological & Materials Safety Programs
1p 26555 066 24X Fiche 50-329,84/07/18,8408010061

--8408150690 Lists reasons why SALP III evaluation period should be extended to 821231, per 820719-20 discussion Related info encl
COOK,R J Region 3, Office of Director BX21 029 82/08/06
SPESSARD,R L Division of Project & Resident Programs 21pp
26555 112 24X Fiche 50-329,84/07/18,8408010061

--8408150738 Forwards summary of 840229 meeting in Region III ofc re results of HVAC insps & investigation of allegations & expansion of training, qualification & certification activities Handwritten notes encl
WELLS,R A Consumers Power Co BX20 032 84/03/29
HARRISON,J J Region 3, Office of Director 169pp 26544 014
24X Fiche 50-329,84/07/18,8408010061

8408150743 Submits reasons for extending SALP III evaluation period to 821231 Rept contains issues being resolved between NRC & licensee Extension can be used as performance motivator Handuritten note & supporting documentation encl
COOK,R J Region 3, Office of Director BX20 036 82/08/06
SPESSARD,R L Division of Project & Resident Programs 350pp
26546 001 24X Fiche 50-329,84/07/18,8408010061

8408150747 Submits supplemental SALP input for facility Changes required to provide overall Div of Engineering & Technical Insp rating for QA functional area & consolidate comments for recommended increased insp frequency
PIRTLE,G Region 3, Office of Director BX20 037 83/10/01
BOYD,D Region 3, Office of Director 1p 26547 011 24X
Fiche 50-329,84/07/18,8408010061

8408150752 Submits QA issues to be addressed at evidentiary session in facility proceeding Summary rept & oral communications record re reinsp requirements based on results of certification testing encl
PATON,W D NRC - No Detailed Affiliation Given BX20 041
82/08/10 ADENSAM,E G NRC - No Detailed Affiliation Given
18pp 26548 075 24X Fiche 50-329,84/07/18,8408010061

--8408170119 Confirms that underpinning instrumentation installation will be suspended until procedures & drawings developed & plans & schedules established to inspect & audit activities, per 820319 telcon
KEPPLER,J G Region 3, Office of Director BX19 007 82/03/19
COOK,J W Consumers Power Co 2pp 26530 037 24X
Fiche 50-329,84/07/18,8408010061

--8408170152 Forwards redrafted insp rept Rept has been reviewed w/NRC for format & content Rept covers insp made 821129-1210
CHARAK,I Argonne National Laboratory BX19 011 82/01/07
WARNICK,R Region 3, Office of Director 7pp 26530 233 24X
Fiche 50-329,84/07/18,8408010061

--8408170157 Forwards draft insp rept re findings of personnel who participated in routine insps on 821129-1203 & 1208-10
CHARAK,I Argonne National Laboratory BX19 012 82/12/22
WARNICK,R Region 3, Office of Director 14pp 26530 240 24X
Fiche 50-329,84/07/18,8408010061

--8408170174 Forwards IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820514
NORELIUS,C E Region 3, Office of Director BX19 013 82/06/28
COOK,J W Consumers Power Co 2pp 26531 033 24X
Fiche 50-329,84/07/18,8408010061

--8408170181 IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820514 Major areas discussed licensee disposition of results of electrical overview insps
GARDNER,R N , WILLIAMS,C C Region 3, Office of Director BX19
013A 82/06/24 3pp 26531 035 24X Fiche 50-329,84/07/18,
8408010061

--8408170203 Forwards IE Insp Repts 50-329/82-07 & 50-330/82-07 on 820421-23 No noncompliance noted Schedule for reinsp program of piping suspension sys requested within 25 days from receipt of ltr
* Region 3, Office of Director BX19 017 82/07/15 Consumers
Power Co 2pp 26531 071 24X Fiche 50-329,84/07/18,8408010061

--8408170232 Forwards SALP Repts 50-329/82-14 & 50-330/82-14 for period Jul 1980 - June 1981
KEPPLER,J G Region 3, Office of Director BX19 026 84/07/18
COOK,J W Consumers Power Co 2pp 26533 198 24X
Fiche 50-329,84/07/18,8408010061

--8408170236 Ack receipt of 820114 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/81-12 & 50-330/81-12
NORELIUS,C E Division of Engineering BX19 028 82/02/03
COOK,J W Consumers Power Co 4pp 26533 188 24X
Fiche 50-329,84/07/18,8408010061

--8408170271 Requests Ofc of Investigations provide investigator to assist Ofc of Special Cases in closeout of unresolved item in Insp Rept 329/82-22-27 re use of unofficial documents for recording nonconformances & deficiencies
WARNICK,R F NRC - No Detailed Affiliation Given BX19 035
83/01/27 PAWLIK,E T Region 3, Office of Director 1p
26534 295 24X Fiche 50-329,84/07/18,8408010061

--8408170274 Discusses 831021 interview w/A Gautam & unnamed individual re allegations concerning Comstock,Bechtel & Zack const activities at plant Details of issues referred to Ofc of Investigation & Ofc of Inspector & Auditor
HAWKINS,F C Region 3, Office of Director BX19 036 83/10/26
Region 3, Office of Director 1p 26534 296 24X
Fiche 50-329,84/07/18,8408010061

--8408210464 Notifies of 830708 meeting to discuss NRR SALP III assessment based on recent hearing testimony by Region III & several third-party reviewers
NOVAK,T M Assistant Director for Licensing BX18 055 83/07/07
JOHNSTON,W , KNIGHT,J P , RUBENSTEIN,L NRC - No Detailed
Affiliation Given 11pp 26528 262 24X Fiche 50-329,84/07/18,
8408010061

--8408220059 Responds to 830829 ltr re imposition of civil penalty for violations noted during Insp 83-23 Penalty reduced because of prompt corrective actions Check encl
COOK,J W Consumers Power Co BX19 052 83/09/26 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 2pp
26537 208 24X Fiche 50-329,84/07/18,8408010061

--8408220078 SALP Repts 50-329/82-14 & 50-330/82-14 for Jul 1980 - June 1981
* Region 3, Office of Director BX19 027 82/03/31 28pp
26533 160 24X Fiche 50-329,84/07/18,8408010061

-8408270330 Forwards summary of 840229 meeting w/Region III & util in Region III re results of insps & investigation into allegations re HVAC work
WELLS,R A Consumers Power Co BX19 020 84/03/24
HARRISON,J J Region 3, Office of Director 17pp 26532 023
24X Fiche 50-329,84/07/18,8408010061

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,8408070401

8408230502 Forwards IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance noted
WARNICK,R F Region 3, Office of Director 84/08/03 COOK,J W
Consumers Power Co 2pp 26212 264 24X Fiche 50-329,84/08/03,8408230502

--8408230512 IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance or deviations noted Major areas inspected licensee action on 10CFR50 55(e) items
HARRISON,J J Region 3, Office of Director 84/08/03 8pp
26212 266 24X Fiche 50-329,84/08/03,8408230502

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
ORACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408240136 Forwards Mgt Meeting Repts 50-329/84-18 & 50-330/84-19 on 840712
WARNICK,R F Region 3, Office of Director 84/08/20 COOK,J W
Consumers Power Co 2pp 26228 205 24X Fiche 50-329,84/08/20,8408240136

--8408240144 Mgt Meeting Repts 50-329/84-18 & 50-330/84-19 on 840712 Major areas discussed work activities for auxiliary bldg underpinning,status of svc water pump structure & QA/QC activities
LANDSMAN,R B , HARRISON,J J Region 3, Office of Director
84/08/20 4pp 26228 207 24X Fiche 50-329,84/08/20,8408240136

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

R Periodic operating reports & related correspondence

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329,84/07/18,8408010061

--8408150603 Forwards Midland monthly status repts for Aug-Sept & Nov 1982 Related info encl
WARNICK,R F Region 3, Office of Director BX21 008 82/12/20
KEPPLER,J G Region 3, Office of Director 23pp 26551 256 24X
Fiche 50-329,84/07/18,8408010061

--8408150698 Forwards monthly status rept for Dec 1983,containing input from insp site team of Ofc of Special Cases
COOK,R J Region 3, Office of Director BX21 031 83/01/12
WARNICK,R F Region 3, Office of Director 2pp 26555 161 24X
Fiche 50-329,84/07/18,8408010061

8408240132 Forwards minutes of monthly third party assessment 840712 meeting re status of independent assessment of underpinning & remedial soils work & status of const implementation overview program
LUCKS,A S Stone & Webster, Inc 84/08/07 HARRISON,J J Region 3, Office of Director 43pp 26226 033 24X Fiche 50-329,84/08/07,8408240132

--8408240134 Forwards Independent Assessment of Underpinning Weekly Rept 91 for 840610-16 Minutes of daily meetings between members of assessment team & site engineering,const & QA personnel encl
LUCKS,A S Stone & Webster, Inc 84/06/20 BURGESS,B L NRC -
No Detailed Affiliation Given 19pp 26226 178 24X
Fiche 50-329,84/08/07,8408240132

--8408240138 Forwards Independent Assessment of Underpinning Weekly Rept 92 for 840617-0623 Minutes of daily meetings between members of assessment team & site engineering const & QA personnel encl
LUCKS,A S Stone & Webster, Inc 84/06/27 BURGESS,B L NRC -
No Detailed Affiliation Given 16p 26226 193 24X
Fiche 50-329,84/08/07,8408240132

--8408240143 Forwards Independent Assessment of Underpinning Weekly Rept 93 for 840624-0630 Minutes of daily meetings between members of assessment team & site engineering,const & QA personnel encl
LUCKS,A S Stone & Webster, Inc 84/07/03 BURGESS,B L NRC -
No Detailed Affiliation Given 11pp 26226 209 24X
Fiche 50-329,84/08/07,8408240132

--8408240148 Forwards Const Implementation Overview Weekly Rept 51 for 840528-0601 Rept includes summary of activities & open items,nonconformance identification repts & hold points
KARR,J E Stone & Webster, Inc 84/06/08 KEPPLER,J G Region 3, Office of Director 18pp 26226 292 24X
Fiche 50-329,84/08/07,8408240132

--8408240152 Forwards Const Implementation Overview Weekly Rept 53 for 840611-15 Rept includes summary of activities & open items, nonconformance identification repts & hold points
KARR,J E Stone & Webster, Inc. 84/06/22 KEPPLER,J G Region 3, Office of Director 18pp 26226 328 24X
Fiche 50-329,84/08/07,8408240132

--8408240159 Forwards Const Implementation Overview Weekly Rept 54 for 840618-22 Rept includes summary of activities & open items, nonconformance identification repts & hold points
KARR,J E Stone & Webster, Inc 84/07/02 KEPPLER,J G Region 3, Office of Director 18pp 26226 346 24X
Fiche 50-329,84/08/07,8408240132

S Reportable occurrences, LERs & related correspondence

8406010038 Forwards Tracked Action Item 086 re NIR 022 & NIR 023 Requests one reply clarifying initial findings Current replies provide inaccurate & conflicting info
KARR,J E Stone & Webster, Inc 84/05/22 KEPPLER,J G ,
HARRISON,J J , BURGESS,B L NRC - No Detailed Affiliation Given
2pp 24757 351 24X Fiche 50-329,84/05/22,8406010038

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp
25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/ TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10, 8408060050

8408310054 Final deficiency rept re concrete embedment design using shear lugs located outside compression zone Initially reported on 821203 Use of shear lugs outside compression zone is proper design technique Related correspondence
COOK,J W Consumers Power Co DSB 986 84/07/11 KEPPLER,J G
Region 3, Office of Director 1p 26350 186 24X
Fiche 50-329,84/07/11,8408310054

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329,84/07/18,8408010061

--8110260082 Informs that licensee taking position that IEEE 279 jurisdiction starts w/transmitter Jurisdiction should start at sensing line connection to process piping
HENDERSON,J B Reactor Projects Sections (Regions 1 & 3) BX19 024 81/10/01 WILLIAMS,C C Plant Systems Section 1p
26533 050 24X Fiche 50-329,84/07/18,8408010061

8408010160 Forwards interim 10CFR50 55(e) rept re QA program & mfg deficiencies affecting radiation monitoring equipment supplied by Victoreen,Inc
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards BX14 011 82/11/15 OKRENT,D ACRS - Advisory Committee on Reactor Safeguards 1p 26500 072 24X Fiche 50-329,84/07/18,8408010061

8408150658 Recommends issuance of board notification for encl potential Part 21 rept from Zack Co (HVAC subcontractor) re accuracy of welder records
WARNICK,R F Region 3, Office of Director BX21 020 82/09/01
EISENHUT,D G Division of Licensing 2pp 26554 179 24X
Fiche 50-329,84/07/18,8408010061

8408150694 PNO-77-035 on 770226,bulge discovered in containment liner plate Caused by water coming through tears in liner plate Addl holes cut in plate to facilitate draining Related info encl
WARNICK,R F , ROY,G W , THOMPSON,D Office of Inspection & Enforcement, Office of the Director BX21 030 77/03/01 7pp
26555 154 24X Fiche 50-329,84/07/18,8408010061

-8408170090 Discusses util 820428 telcon notifyng that,while drilling well in G area,electric duct bank struck Drawings indicated duct bank elsewhere Investigation continuing
SHAFER,W D Region 3, Office of Director BX19 001A 82/04/28
WILLIAMS,G C , LANDSMAN,R B NRC - No Detailed Affiliation Given
1p 26529 285 24X Fiche 50-329,84/07/18,8408010061

--8408170276 Forwards util repts re auxiliary bldg seismic analysis & cracks in borated water storage tank roundation per util B10121-22 notifications Const deficiency info may aid in resolution of matter
NORELIUS,C E Division of Engineering BX19 036AB 81/11/24
EISENHUT,D G Division of Licensing 1p 26535 165 24X
Fiche 50-329,84/07/18,8408010061

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000,84/07/27,8408060102

8408090284 Forwards table indicating status of 10CFR50 55(e) issues Procedures revised to assure proper handling & reporting of addl 10CFR50 55(e) items
COOK,J W Consumers Power Co 84/07/27 KEPPLER,J G Region 3, Office of Director 4pp 25994 036 24X Fiche 50-329,84/07/27, 8408090284

8408310259 Final deficiency rept re defective capstan springs in Pacific Scientific mechanical shock arrestors Initially reported on 840106 W/o description of investigation & corrective actions Related correspondence
COOK,J W Consumers Power Co DSB 978 84/07/27 KEPPLER,J G
Region 3, Office of Director 1p 26350 281 24X
Fiche 50-329,84/07/27,8408310259

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000,84/08/01,8408060324

--8408060387 "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-6-56 84/07/31 62pp
25927 066 24X Fiche 50-000,84/08/01,8408060324

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program,testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000,84/08/13,8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation,plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL,per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000,84/08/14,8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche, 50-000,84/08/23,8408290179

I Hearing transcripts on non-antitrust matters

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records 8X14 000 84/07/18
RICE, C M Kirkland & Ellis 2pp 26500 001 24X
Fiche 50-329, 84/07/18, 8408010061

--8408020178 Testimony of DS Hood & J Kane re matl false statement identified in NRC 791206 mod order
HOOD, D S ; KANE, J NRC - No Detailed Affiliation Given 8X17 021
83/01/31 3pp 26519 027 24X Fiche 50-329, 84/07/18, 8408010061

--8408130315 Testimony of JG Keppler re QA problems at facility & corrective actions taken
KEPPLER, J G Region 3, Office of Director 8X15 012A 84/07/18
25pp 26504 262 24X Fiche 50-329, 84/07/18, 8408010061

--8408140144 Testimony of HN Singh re unresolved geotechnical engineering safety issues, including reactor bldg foundation, diesel generator bldg settlement & svc water bldg foundation & borated water tanks
SINGH, H N Army, Dept of, Corps of Engineers 8X16 016
84/07/18 13pp 26510 319 24X Fiche 50-329, 84/07/18, 8408010061

--8408170098 Testimony of RB Landsman in Glen Ellyn, IL re QA criteria & procedures to remedial foundation work underway at site
LANDSMAN, R B NRC - No Detailed Affiliation Given 8X19 002
82/04/19 2pp 26529 332 24X Fiche 50-329, 84/07/18, 8408010061

--8408170292 Transcript of B Stamiris 840425 statement re soil settlement problems at plant
STAMIRIS, B Q Stamiris, B 8X19 041 84/04/25 3pp 26536 134
24X Fiche 50-329, 84/07/18, 8408010061

--8408170297 Transcript of M Sinclair 840425 statement re problems w/util announced Dec 1986 const completion date Documentation encl
SINCLAIR, M Sinclair, M 8X19 042 84/04/25 10pp 26536 137
24X Fiche 50-329, 84/07/18, 8408010061

--8408170304 Transcript of T Hearron 840425 statement opposing completion, licensing & operation of plant
HEARRON, T Lone Tree Council 8X19 043 84/04/25 4pp
26536 147 24X Fiche 50-329, 84/07/18, 8408010061

--8408170312 Transcript of BP Garde 840425 statement re Govt Accountability Project 840210 supplemental 10CFR2 206 petition, mgt breakdown, NRC action problems & adequate Commission review of complex project
GARDE, B P Government Accountability Project 8X19 044
84/04/25 19pp 26536 151 24X Fiche 50-329, 84/07/18, 8408010061

--8408220064 Testimony of RN Gardner re qualification of Bechtel QC personnel Certificate of Svc & related info encl
GARDNER, R N Region 3, Office of Director 8X19 023 82/01/22
120pp 26532 292 24X Fiche 50-329, 84/07/18, 8408010061

--8408270336 Testimony of BP Garde re Midland Nuclear Power Plant
GARDE, B P Government Accountability Project 8X19 021
84/02/13 22pp 26532 040 24X Fiche 50-329, 84/07/18, 8408010061

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408310228 Forwards scope of plant mods & projected completion dates needed to implement 840316 request for Tech Spec changes to incorporate findings of NRC SER
MCGAUGHY, R W Iowa Electric Light & Power Co 84/08/24 DENTON, H
Office of Nuclear Reactor Regulation, Director 3pp 26320 242
24X Fiche 50-331, 84/08/24, 8408310228

F Security, medical, emergency & fire protection plans

8408060001 Forwards changes to security plan Changes withheld (ref 10CFR73 21)
MCGAUGHY, R W Iowa Electric Light & Power Co 84/07/30
KEPPLER, J G Region 3, Office of Director 1p 25933 186 24X
Fiche 50-331, 84/07/30, 8408060001

8408060270 Notification of 840905 meeting w/util in Bethesda, MD to discuss util requests for addl exemptions from fire protection requirements
THADANI, M C Operating Reactors Branch 2 84/07/30 VASSALLO, D B
Operating Reactors Branch 2 2pp 25950 298 24X
Fiche 50-331, 84/07/30, 8408060270

8408070464 Advises that 840730 changes to guard training & qualification plan consistent w/provisions of 10CFR50 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/08/02 LIU, L Iowa
Electric Light & Power Co 2pp 25940 332 24X
Fiche 50-331, 84/08/02, 8408070464

I Financial information

8408210256 Forwards 1983 annual repts for Iowa Electric Light & Power Co, Corn Belt Cooperative & Central Iowa Power Cooperative
MCGAUGHY, R W Iowa Electric Light & Power Co 84/08/14 DENTON, H
Office of Nuclear Reactor Regulation, Director 1p 26177 263 24X
Fiche 50-331, 84/08/14, 8408210256

--8408210263 "Iowa Electric Light & Power Co, 1983 Annual Rept "
LIU, L Iowa Electric Light & Power Co 83/12/31 35pp
26177 264 24X Fiche 50-331, 84/08/14, 8408210256

--8408210268 "Road Ahead, Central Iowa Power Cooperative, Annual Rept 1983 "
BISHOP, E Central Iowa Power Cooperative 83/12/31 25pp
26177 300 24X Fiche 50-331, 84/08/14, 8408210256

--8408210272 "Corn Belt Cooperative, Annual Rept 1983 "
* Corn Belt Power Cooperative 83/12/31 32pp 26177 324 24X
Fiche 50-331, 84/08/14, 8408210256

J Insurance & indemnity information

8408030087 Forwards Endorsement 8 to NELIA Master Policy 1
SHEA, K H Newman & Holtzinger 84/07/30 SALTZMAN, J D Assistant
Director for State & Licensee Relations 2pp 25906 333 24X
Fiche 50-331, 84/07/30, 8408030087

8408030129 Forwards Endorsements 61 & 64 to NELIA Policy NF-214 & Endorsement 50 to MAELU Policy MF-72
SHEA, K H Newman & Holtzinger 84/07/30 SALTZMAN, J D Assistant
Director for State & Licensee Relations 4pp 25916 125 24X
Fiche 50-331, 84/07/30, 8408030129

P Operating license stage documents & correspondence

8408020006 Application for amend to License DPR-49, allowing 18-month implementation period for radiological effluent Tech Specs & deleting App B of Tech Specs
MCGAUGHY, R W Iowa Electric Light & Power Co 84/07/25
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp
25882 302 24X Fiche 50-331, 84/07/25, 8408020006

--8408020009 Proposed Change RTS-115E to radiological effluent & ETS
* Iowa Electric Light & Power Co 84/07/31 113pp 25882 308
24X Fiche 50-331, 84/07/25, 8408020006

8408030038 Responds to Generic Ltr 84-09, "Recombiner Capability Requirements of 10CFR50 44(c)(3)(ii)" & NRC 840522 ltr Hydrogen recombiner capability not required, based on BWR Owners Group generic studies
MCGAUGHY, R W Iowa Electric Light & Power Co 84/07/27 DENTON, H
Office of Nuclear Reactor Regulation, Director 3pp 25907 060
24X Fiche 50-331, 84/07/27, 8408030038

8408160137 Forwards request for addl info re torus attached piping analysis as part of plant-unique rept Participation of authorized representative in 840809-10 meetings to discuss util response to issues requested
VASSALLO, D B Operating Reactors Branch 2 84/07/27 LIU, L Iowa
Electric Light & Power Co 3pp 26126 163 24X
Fiche 50-331, 84/07/27, 8408160137

8408060425 Notification of 840807-10 meetings w/utils,NUTECH,Franklin Research Ctr & BNL in San Jose CA to discuss comments resulting from post-implementation review re plant-unique analysis repts
BEVAN,R B Operating Reactors Branch 2 84/07/31 VASSALLO,D B
Operating Reactors Branch 2 1p 25937 335 24X
Fiche 50-000,84/07/31,8408060425

8408080083 Rev 6 to "Duane Arnold Energy Ctr Inservice Testing Program " W/840801 ltr
HOWARD,K E , MCGAUGHY,R W Iowa Electric Light & Power Co
84/08/01 DENTON,H Office of Nuclear Reactor Regulation, Director
226pp 25963 048 24X Fiche 50-331,84/08/01,8408080083

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408130170 Forwards GE rept, "Reduced RHR Svc Water Flow & Suppression Pool Temp Response Licensing Ltr Rept " Encl replaces proprietary rept
MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/08 DENTON,H
Office of Nuclear Reactor Regulation, Director 1p 26010 030 24X
Fiche 50-331,84/08/08,8408130170

--8408130173 "Reduced RHR Svc Water Flow & Suppression Pool Temp Response Licensing Ltr Rept "
GRIDLEY,R L General Electric Co 84/07/18 5pp 26010 031
24X Fiche 50-331,84/08/08,8408130170

8408140247 Requests permanent relief from individual valve leakage testing requirements of ASME Boiler & Pressure Vessel Code, Section XI for torus-drywell vacuum breakers Fee encl
MCGAUGHY,R W Iowa Electric Light & Power Co. 84/08/09
DENTON,H R Office of Nuclear Reactor Regulation, Director 8pp
26053 350 24X Fiche 50-331,84/08/09,8408140247

8408140435 Forwards 28 oversize piping & instrumentation diagrams, to facilitate NRC review of inservice testing program Aperture cards available in PDR
MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/09 DENTON,H
Office of Nuclear Reactor Regulation, Director 3pp 26051 200
24X Fiche 50-331,84/08/09,8408140435

8408170099 Ack receipt of 830531 & 840531 QA programs Rev to SAR QA program description per 10CFR50 54(a) requirements, requested
SPESSARD,R L Region 3, Office of Director 84/08/14 LIU,L Iowa Electric Light & Power Co 2pp 26119 128 24X
Fiche 50-331,84/08/14,8408170099

8408210499 Revised application for amend to License DPR-49, revising Tech Specs to reflect administrative change
MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/16 DENTON,H
Office of Nuclear Reactor Regulation, Director 2pp 26149 017
24X Fiche 50-331,84/08/16,8408210499

--8408210502 Proposed Tech Specs reflecting administrative changes
* Iowa Electric Light & Power Co 84/08/16 65pp 26149 019
24X Fiche 50-331,84/08/16,8408210499

8408240118 Application for amend to License DPR-49, consisting of proposed Tech Spec Change RTS-168, lowering setpoint for bypass of reactor scrams during turbine trips & generator load rejections at low power levels
MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/17
DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp
26228.217 24X Fiche 50-331,84/08/17,8408240118

-8408240124 Proposed Change RTS-168 to Tech Specs, correcting value of turbine first stage pressure to correspond to 30% of core power instead of 30% of turbine power
* Iowa Electric Light & Power Co 84/08/17 4pp 26228-220
24X Fiche 50-331,84/08/17,8408240118

8408270167 Application to amend License DPR-49, revising Tech Specs to allow power uprate to 1,658 MWt Approval requested prior to startup For Cycle 8 Forwards NEDO-30603 & NEDC-30603-P
NEDC-30603-P withheld (ref 10CFR2 790), Fee paid
MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/17
DENTON,H R Office of Nuclear Reactor Regulation, Director 20pp
26244 081 24X Fiche 50-331,84/08/17,8408270167

--8408270173 Proposed Tech Specs modified for power uprate to 1,658 MWt
* Iowa Electric Light & Power Co 84/06/30 50pp 26244 102
24X Fiche 50-331,84/08/17,8408270167

--8408270175 'D Arnold Power Uprate
BRANDON R J , GRIDLEY,R L General Electric Co NEDO-30603
84/07/31 33pp 26244 153 24X Fiche 50-331,84/08/17,8408270167

8408280202 Application for amend to License DPR-49, revising Tech Specs re operating limits of new bundle types, LOCA design basis, MAPLHGR & min critical power ratio for Cycle 8 reload
MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/17
DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp
26264 067 24X Fiche 50-331,84/08/17,8408280202

--8408280206 Proposed Tech Specs re operating limits of new bundle types, LOCA design basis, MAPLHGR & min critical power ratio for Cycle 8 reload
* Iowa Electric Light & Power Co 84/08/17 19pp 26264 072
24X Fiche 50-331,84/08/17,8408280202

--8408280209 App A to "LOCA Analysis Rept for Duane Arnold Energy Ctr (Lead Plant) "
* General Electric Co NEDO-21082-03 APP A 84/06/30 46pp
26264 091 24X Fiche 50-331,84/08/17,8408280202

--8408280211 Rev 0 to "Supplemental Reload Licensing Submittal for Duane Arnold Atomic Energy Ctr, Unit 1, Reload 7 "
LAMBERT,P A General Electric Co 23A1739 R00 84/06/30 22pp
26264 138 24X Fiche 50-331,84/08/17,8408280202

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408240105 Application for amend to License DPR-49, revising Tech Specs to clarify wording, correct typos & adjust testing requirements for snubbers Fee paid
MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/20
DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp
26223 165 24X Fiche 50-331,84/08/20,8408240105

--8408240235 Proposed Tech Specs clarifying wording, correcting typos & adjusting testing requirements for snubbers
* Iowa Electric Light & Power Co 84/08/20 16pp 26223 169
24X Fiche 50-331,84/08/20,8408240105

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840920 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408150004 Forwards payment of civil penalties assessed in NRC 840717 Order EA-84-9
MCGAUGHY,R W Iowa Electric Light & Power Co 84/08/09 DEYOUNG,R
Director's Office, Office of Inspection and Enforcement 1p
26066 348 24X Fiche 50-331,84/08/09,8408150004

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408240343 Ack receipt of $20,000 check in full payment of civil penalties imposed on 840717 Corrective action will be examined during future insp
AXELRAD, J A Enforcement Staff 84/08/20 LIU, L Iowa Electric Light & Power Co 2pp 26253 313 24X Fiche 50-331, 84/08/20, 8408240343

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408230429 Monthly operating rept for Jul 1984 W/840815 ltr
PUTNAM, K S , MINECK, D L Iowa Electric Light & Power Co 84/07/31 8pp 26213 056 24X Fiche 50-331, 84/07/31, 8408230429

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408240172 LER 84-029-00 on 840718, standby liquid control sys (SBLC) isolated for 5 h after improper manipulation of common suction valve from SBLC tank to SBLC pumps Caused by personnel error Procedures & training revised W/840815 ltr
HARRIS, M S , MINECK, D L Iowa Electric Light & Power Co 84/07/17 7pp 26236 244 24X Fiche 50-331, 84/07/17, 8408240172

8408060141 LER 84-024-00 on 840630, w/reactor critical & plant in startup mode, isolation valve on inlet line to reactor water cleanup sys automatically closed Caused by noise in reactor water cleanup sys W/840730 ltr
PUTNAM, K S , MINECK, D L Iowa Electric Light & Power Co 84/07/30 3pp 25932 250 24X Fiche 50-331, 84/07/30, 8408060141

8408160261 LER 84-029-00 on 840712, w/standby filter unit B inoperable due to inoperable radiation monitor, filter unit A failed to function during testing Caused by malfunction of air pilot positioner Monitors will be replaced W/840810 ltr
KEITH, W R , MINECK, D L Iowa Electric Light & Power Co 84/08/10 3pp 26106 181 24X Fiche 50-331, 84/08/10, 8408160261

8408160471 LER 84-027-00 on 840712, spurious reactor scram occurred due to jarring of instrument rack in reactor bldg Caused by const of scaffolding adjacent to instrument rack IC-56 Multicolored demarcation painted on floor W/840810 ltr
MILLER, W J , MINECK, D L Iowa Electric Light & Power Co 84/08/10 3pp 26107 286 24X Fiche 50-331, 84/08/10, 8408160471

8408220202 LER 84-028-00 on 840714, degraded voltage condition on offsite power grid resulted in automatic switching of essential buses from offsite to onsite power HPCI valve closed Cause unknown & under investigation W/840813 ltr
PROBST, J R , MINECK, D L Iowa Electric Light & Power Co 84/08/13 3pp 26188 209 24X Fiche 50-331, 84/08/13, 8408220202

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000, 84/08/21, 8408310186

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8408100087 Forwards objectives for 840718 full-scale emergency exercise
BAYNE, J P Power Authority of the State of New York 84/05/07
MURLEY, T E Region 1, Office of Director 10pp 25995 353 24X Fiche 50-333, 84/05/07, 8408100087

--8408100105 "Emergency Response Plan Exercise Manual for JA Fitzpatrick Nuclear Power Plant "
* Power Authority of the State of New York 84/07/18 4pp 25995 360 24X Fiche 50-333, 84/05/07, 8408100087

8408030209 Forwards IE Insp Rept 50-333/84-10 on 840521-25 No violations noted Items of concern listed in App A
BELLAMY, R Region 1, Office of Director 84/07/03. FITZPATRICK, J Power Authority of the State of New York 4pp 25917 137 24X Fiche 50-333, 84/07/03, 8408030209

--8408030221 IE Insp Rept 50-333/84-10 on 840521-25 No violations noted Major areas inspected followup insp of items from prior insp & routine IE insp modules on emergency detection & classification
HAWKHURST, J J , COHEN, I , CROCKER, H W Region 1, Office of Director 84/06/15 7pp 25917 141 24X Fiche 50-333, 84/07/03, 8408030209

8408070015 Advises that 800930 description of proposed mods to ensure containment isolation single failure proof during purging satisfies requirements of Item II E 4 1 of NUREG-0737, based on completion of mods by 850701
VASSALLO, D B Operating Reactors Branch 2 84/07/26 BAYNE, J P Power Authority of the State of New York 3pp 25956 204 24X Fiche 50-333, 84/07/26, 8408070015

8408270538 Forwards Insp Rept 50-333/84-08 on 840501-31 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/03 MCNEILL, C A Power Authority of the State of New York 2pp 26256 114 24X Fiche 50-333, 84/08/03, 8408270538

--8408270541 Insp Rept 50-333/84-08 on 840501-31 No violations noted Major areas inspected licensee action on previous insp findings, LER review, operational safety verification & surveillance & maint observations
DOERFLEIN, L T , COLLINS, S J Region 1, Office of Director 84/08/02 10pp 26256 116 24X Fiche 50-333, 84/08/03, 8408270538

P Operating license stage documents & correspondence

8408010140 Notification of 840613 meeting w/util, Teledyne, Franklin Research Ctr, BNL, MIT & Princeton Univ in Waltham, MA to discuss NRC comments re post-implementation review of plant-unique analysis rept
ABELSON, H I Operating Reactors Branch 2 84/05/24 VASSALLO, D B Operating Reactors Branch 2 1p 25873 307 24X Fiche 50-333, 84/05/24, 8408010140

8408030080 Forwards request for addl info re safety relief valve & torus attached piping sys, per Mark I containment long-term program Response requested within 30 days
VASSALLO, D B Operating Reactors Branch 2 84/07/24 BAYNE, J P
Power Authority of the State of New York 3pp 25917 346 24X
Fiche 50-333, 84/07/24, 8408030080

8408010319 Forwards application to amend License DPR-59, changing Tech Specs re NUREG-0737, Item II K 3 18, "Mod of Automatic Depressurization Sys Logic - Feasibility for Increased Diversity for Some Event Sequences "
BAYNE, J P Power Authority of the State of New York 84/07/25
VASSALLO, D B Operating Reactors Branch 2 2pp 25866 129 24X
Fiche 50-333, 84/07/25, 8408010319

--8408010321 Application to amend License DPR-59, changing Tech Specs re NUREG-0737, Item II K 3 18, "Mod of Automatic Depressurization Sys Logic - Feasibility for Increased Diversity for Some Event Sequences "
BAYNE, J P Power Authority of the State of New York 84/07/24
3pp 25866 131 24X Fiche 50-333, 84/07/25, 8408010319

--8408010322 Proposed Tech Spec changes re NUREG-0737, Item II K 3 18 covering implementation of automatic depressurization sys logic mods
* Power Authority of the State of New York 84/07/25 10pp
25866 134 24X Fiche 50-333, 84/07/25, 8408010319

8408070417 Forwards application for amend to License DPR-59, changing Tech Specs to modify surveillance requirements for safety-related hydraulic & mechanical snubbers
BAYNE, J P Power Authority of the State of New York 84/07/27
VASSALLO, D B Operating Reactors Branch 2 2pp 25942 033 24X
Fiche 50-333, 84/07/27, 8408070417

--8408070423 Application for amend to License DPR-59, changing Tech Specs to modify surveillance requirements for safety-related hydraulic & mechanical snubbers
BAYNE, J P Power Authority of the State of New York 84/07/27
1p 25942 035 24X Fiche 50-333, 84/07/27, 8408070417

--8408070428 Proposed Tech Specs, modifying surveillance requirements for safety-related hydraulic & mechanical snubbers
* Power Authority of the State of New York 84/07/27 16pp
25942 036 24X Fiche 50-333, 84/07/27, 8408070417

8408070364 Advises of correction to 810512 response to request for addl info re containment vent & purge valves Fisher Controls confirms valves have off-set discs Investigation in progress
BAYNE, J P Power Authority of the State of New York 84/08/02
VASSALLO, D B Operating Reactors Branch 2 2pp 25945 126 24X
Fiche 50-333, 84/08/02, 8408070364

8408150609 Forwards Amend 82 to License DPR-59 & safety evaluation Amend revises surveillance testing frequency for unit coolers serving ECCS components
ABELSON, H I Operating Reactors Branch 2 84/08/03 BAYNE, J P
Power Authority of the State of New York 2pp 26106 054 24X
Fiche 50-333, 84/08/03, 8408150609

--8408150613 Amend 82 to License DPR-59, revising surveillance testing frequency for unit coolers serving ECCS components
VASSALLO, D B Operating Reactors Branch 2 84/08/03 4pp
26106 056 24X Fiche 50-333, 84/08/03, 8408150609

8408150615 Safety evaluation supporting Amend 82 to License DPR-59
* Office of Nuclear Reactor Regulation, Director 84/08/03 3pp
26106 060 24X Fiche 50-333, 84/08/03, 8408150609

08070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06. Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408220224 Forwards addl info re Mark I program Documentation resolves all open items discussed at 840713 meeting w/exception of justifying 111 F pool temp for Case C3 2, which will be addressed in separate ltr
BAYNE, J P Power Authority of the State of New York 84/08/14
VASSALLO, D B Operating Reactors Branch 2 16pp 26188 266 24X
Fiche 50-333, 84/08/14, 8408220224

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408240145 Requests 60-day extension of time after next refueling outage for response to 840702 Generic Ltr 84-15 requesting info re current programs to avoid cold fast start surveillance tests & diesel generator reliability data
BAYNE, J P Power Authority of the State of New York 84/08/22
VASSALLO, D B Operating Reactors Branch 2 2pp 26227 361 24X
Fiche 50-333, 84/08/22, 8408240145

8408310095 Forwards response to 840724 request for addl info re structural aspects of plant-unique analysis rept for torus attached piping
BAYNE, J P Power Authority of the State of New York 84/08/24
VASSALLO, D B Operating Reactors Branch 2 5pp 26322 224 24X
Fiche 50-333, 84/08/24, 8408310095

G Inspection reports, IE Bulletins & correspondence

8408030209 Forwards IE Insp Rept 50-333/84-10 on 840521-25 No violations noted Items of concern listed in App A
BELLAMY, R Region 1, Office of Director 84/07/03 FITZPATRICK, J
Power Authority of the State of New York 4pp 25917 137 24X
Fiche 50-333, 84/07/03, 8408030209

--8408030221 IE Insp Rept 50-333/84-10 on 840521-25 No violations noted Major areas inspected followup insp of items from prior insp & routine IE insp modules on emergency detection & classification
HAWXHURST, J J , COHEN, I , CROCKER, H W Region 1, Office of
Director 84/06/15 7pp 25917 141 24X Fiche 50-333, 84/07/03, 8408030209

8408150453 Forwards IE Insp Rept 50-333/84-11 on 840618-22 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/07/26
MCNEILL, C A Power Authority of the State of New York 2pp
26077 147 24X Fiche 50-333, 84/07/26, 8408150453

--8408150455 IE Insp Rept 50-333/84-11 on 840618-22 No violations noted Major areas inspected near-term followup of responses to Generic Ltr 83-28, equipment classification, post-maint testing & vendor interfaces
HARPSTER, T L , NAPUDA, G , GODY, A T Region 1, Office of Director
84/07/20 8pp 26077 149 24X Fiche 50-333, 84/07/26, 8408150453

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408150537 Forwards IE Insp Rept 50-333/84-09 on 840521-25 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
MCNEILL, C A Power Authority of the State of New York 2pp
26079 026 24X Fiche 50-333, 84/07/27, 8408150537

--8408150539 Notice of violation from insp on 840521-25
* Region 1, Office of Director 84/07/27 1p 26079 028 24X
Fiche 50-333, 84/07/27, 8408150537

--8408150541 IE Insp Rept 50-333/84-09 on 840521-25 Violations noted failure to have written procedures for waste classification & manifest preparation
HOGAN, R , PASCIAK, W J Region 1, Office of Director 84/07/20
4pp 26079 029 24X Fiche 50-333, 84/07/27, 8408150537

8408270538 Forwards Insp Rept 50-333/84-08 on 840501-31 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/08/03
MCNEILL, C A Power Authority of the State of New York 2pp
26256 114 24X Fiche 50-333, 84/08/03, 8408270538

--8408270541 Insp Rept 50-333/84-08 on 840501-31 No violations noted Major areas inspected licensee action on previous insp findings, LER review, operational safety verification & surveillance & maint observations
DOERFLEIN, L T , COLLINS, S J Region 1, Office of Director
84/08/02 10pp 26256 116 24X Fiche 50-333, 84/08/03, 8408270538

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408270470 Forwards Insp Rept 50-333/84-13 on 840709-13 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/08/08
MCNEILL,C A Power Authority of the State of New York 2pp
26256 217 24X Fiche 50-333,84/08/08,8408270470

--8408270473 Insp Rept 50-333/84-13 on 840709-13 No noncompliance noted
Major areas inspected nonradiological chemical program, including QC of analytical measurements,analytical procedures,staffing & training
ZIBULSKY,H , PASCIAK,W J Region 1, Office of Director 84/08/07
3pp 26256 219 24X Fiche 50-333,84/08/08,8408270470

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408210277 Ack receipt of 840802 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/84-10
MARTIN,T T Division of Engineering & Technical Programs 84/08/15
MCNEILL,C A Power Authority of the State of New York 2pp
26180 215 24X Fiche 50-333,84/08/15,8408210277

--8408210281 Responds to NRC 840703 ltr re violations noted in IE Insp Rept 50-333/84-10 Corrective actions specialized training will be provided to shift supervisors,per Protective Action Decisionmaking EAP-18 between 841021-1201
MCNEILL,C A Power Authority of the State of New York 84/08/02
MARTIN,T T Division of Engineering & Technical Programs 5pp
26180 217 24X Fiche 50-333,84/08/15,8408210277

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408210424 Ack receipt of 840712 ltr informing NRC of steps taken to correct violations noted in IE Operational Assessment Team Insp Rept 50-333/82-24
MARTIN,T T Division of Engineering & Technical Programs 84/08/16
MCNEILL,C A Power Authority of the State of New York 2pp
26181 298 24X Fiche 50-333,84/08/16,8408210424

--8408210436 Responds to NRC 831128 ltr re violations noted in IE Operational Assessment Team Insp Rept 50-333/82-24 Corrective actions administrative records mgt policy revised & records retention index complete
BAYNE,J P Power Authority of the State of New York 84/07/12
MURLEY,T E Region 1, Office of Director 5pp 26181 300 24X Fiche 50-333,84/08/16,8408210424

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408310271 Notification of Significant Licensee Meeting 84-78 on 840913 w/util at site to present results of SALP
COLLINS,S Division of Project & Resident Programs 84/08/22
Division of Project & Resident Programs 2pp 26351 337 24X
Fiche 50-333,84/08/22,8408310271

R Periodic operating reports & related correspondence

8408030287 SPDES discharge monitoring rept for Apr 1984 W/840724 ltr
MCNEILL,C A Power Authority of the State of New York 84/04/30
DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp
25917 262 24X Fiche 50-333,84/04/30,8408030287

8408160311 Monthly operating rept for Jul 1984 W/840806 ltr
COOK,J , MCNEILL,C A Power Authority of the State of New York
84/07/31 14pp 26106 131 24X Fiche 50-333,84/07/31,8408160311

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,G G General Electric Co 84/04/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000,84/04/13,8408240348

8408030254 LER 84-013-00 on 840625,while placing main generator in svc, reactor scram occurred Caused by high reactor pressure resulting when turbine bypass valve failed closed Hydraulic fluid filters replaced,W/840723 ltr
LISENO,R T , MCNEILL,C A Power Authority of the State of New York
84/07/23 3pp 25917 231 24X Fiche 50-333,84/07/23,8408030254

8408030256 LER 84-014-00 on 840623,both inner & outer drywell entry hatch doors open,violating primary containment Caused by failure in mechanical interlock & failure of personnel to recognize integrity violated Doors shut W/840723 ltr
LINDSEY,D J , MCNEILL,C A Power Authority of the State of New York
84/07/23 4pp 25917 237 24X Fiche 50-333,84/07/23,8408030256

8408230356 LER 84-015-00 on 840716,HPCI torus suction valve 23MOV-58 failed to open fully & declared inoperable Cause undetermined Operability surveillance successfully performed daily for 1 wk W/840815 ltr
LISENO,R T , MCNEILL,C A Power Authority of the State of New York
84/08/15 3pp 26213 196 24X Fiche 50-333,84/08/15,8408230356

8408240243 LER 84-016-00 on 840621,both 4 kV emergency bus undervoltage relays on 10500 bus (Div 1) found outside Tech Spec limits Cause not stated Procedure placed in new format highlighting Tech Spec requirements W/840815 ltr
KEITH,H N , MCNEILL,C A Power Authority of the State of New York
84/08/15 4pp 26236 287 24X Fiche 50-333,84/08/15,8408240243

8408270144 LER 84-017-00 on 840720,remote alarm function for east cable tunnel smoke detection sys declared inoperable Hourly patrolling fire watch initiated,but not performed for 2 h period Disciplinary action administered W/840820 ltr
LINDSEY,D J , MCNEILL,C A Power Authority of the State of New York
84/08/20 3pp 26257 340 24X Fiche 50-333,84/08/20,8408270144

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA,R General Electric Co 84/08/21 ROSSI,C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X
Fiche 50-000,84/08/21,8408310186

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408080212 Forwards IE Insp Rept 50-334/84-15 on 840602-0706 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 84/07/17
CAREY,J J Duquesne Light Co 2pp 25975 046 24X
Fiche 50-334,84/07/17,8408080212

--8408080213 Notice of violation from insp on 840602-0706
* Region 1, Office of Director 84/07/17 2pp 25975 048, 24X
Fiche 50-334,84/07/17,8408080212

--8408080448 IE Insp Rept 50-334/84-15 on 840602-0706 Violations noted inadequate control of station battery tests, failure to follow station equipment clearance procedures & missed surveillances
TROSKOSKI,W M , JOHNSON,D M , TRIPP,L E Region 1, Office of Director 84/07/16 16pp 25975 050 24X Fiche 50-334,84/07/17, 8408080212

DOCKETED ITEMS

8408160266 Forwards IE Insp Rept 50-334/84-16 on 840625-28 No violations observed
MARTIN, T T Division of Engineering & Technical Programs 84/07/30
CAREY, J J Duquesne Light Co 2pp 26106 148 24X
Fiche 50-334, 84/07/30, 8408160266

--8408160272 IE Insp Rept 50-334/84-16 on 840625-28 No violations identified Major areas inspected annual full-scale emergency exercise
SMITH, R H , CROCKER, H W Region 1, Office of Director 84/07/26
6pp 26106 150 24X Fiche 50-334, 84/07/30, 8408160266

8408170041 Forwards notice of environ assessment & finding of no significant impact re 831216 & 840530 applications for exemption from requirements of App R to 10CFR50
VARGA, S A Operating Reactors Branch 1 84/07/30 CAREY, J J
Duquesne Light Co 3pp 26135 338 24X Fiche 50-334, 84/07/30, 8408170041

--8408170046 Notice of environ assessment & finding of no significant impact re 831216 & 840530 applications for exemption from 10CRF50, App R requirements for fixed suppression & detection sys, 3 h rated fire barriers or 20-ft separation
EISENHUT, D G Division of Licensing 84/07/30 3pp 26135 341
24X Fiche 50-334, 84/07/30, 8408170041

P Operating license stage documents & correspondence

8408010218 Forwards SER re operation w/two of three reactor coolant loops Changes to proposed Tech Specs necessary N-1 loop operation does not constitute threat to public health & safety.
VARGA, S A Operating Reactors Branch 1 84/07/20 CAREY, J J
Duquesne Light Co 4pp 25897 166 24X Fiche 50-334, 84/07/20, 8408010218

--8408010221 Safety evaluation re operation w/two of three reactor coolant loops N-1 loop operation acceptable
* Office of Nuclear Reactor Regulation, Director 84/07/20
26pp 25897 170 24X Fiche 50-334, 84/07/20, 8408010218

8408090515 Forwards FR notice of environ assessment & finding of no significant impact re 840625 application for exemption from requirements of App J to 10CFR50
VARGA, S A Operating Reactors Branch 1 84/07/30 CAREY, J J
Duquesne Light Co 7pp 25983 108 24X Fiche: 50-334, 84/07/30, 8408090515

--8408090517 Notice of environ assessment & finding of no significant impact re 840625 application for exemption from requirements of App J to 10CFR50 concerning containment integrated leak rate test
EISENHUT, D G Division of Licensing 84/07/30 3pp 25983 112
24X Fiche. 50-334, 84/07/30, 8408090515

8408090521 Forwards FR notice of environ assessment & finding of no significant impact re 831025 application & 840201 ltr requesting relief from requirements of ASME Code Section XI
VARGA, S A Operating Reactors Branch 1 84/07/30 CAREY, J J
Duquesne Light Co 4pp. 25983 116 24X Fiche 50-334, 84/07/30, 8408090521

8408090524 Notice of environ assessment & finding of no significant impact re 831025 application & 840201 ltr requesting relief from requirements of ASME Code Section XI concerning Class 3 piping supports
EISENHUT, D G. Division of Licensing 84/07/30 3pp 25983 120
24X Fiche 50-334, 84/07/30, 8408090521

8130436 Forwards application to amend License DPR-66, deleting ETS & substituting specs w/complete 1983 soil sampling & aerial hotography surveys
AREY, J J Duquesne Light Co 84/07/31 VARGA, S A Operating eactors Branch 1 1p. 26005 344 24X Fiche 50-334, 84/07/31, 8408130436

8408130439 Application for amend to License DPR-66, authorizing deletion of ETS Specs will be replaced w/complete 1983 soil sampling & aerial photography surveys
CAREY, J J. Duquesne Light Co 84/08/02. 2pp. 26005 345 24X
Fiche 50-334, 84/07/31, 8408130436

8408130441 Proposed Tech Specs re soil chemistry
* Duquesne Light Co 84/07/31 12pp 26005 347 24X
Fiche. 50-334, 84/07/31, 8408130436

8408150499 Responds to 840525 request for addl info & Generic Ltr 84-04 re 760114 & 0618 asymmetric LOCA loads analyses Util proceeding w/fracture mechanics evaluation to demonstrate applicability to modeling
CAREY, J J Duquesne Light Co 84/07/31 VARGA, S A Operating Reactors Branch 1 2pp 26079 107 24X Fiche 50-334, 84/07/31, 8408150499

8408130554 Forwards notice of environ assessment & finding of no significant impact re 830714 & 840507 requests for exemption from 10CFR50, App J
VARGA, S A Operating Reactors Branch 1 84/08/01 CAREY, J J
Duquesne Light Co 4pp 26060 020 24X Fiche 50-334, 84/08/01, 8408130554

--8408130559 Notice of environ assessment & finding of no significant impact re 830714 & 840507 requests for exemption from 10CFR50, App J for air lock leak rate test
EISENHUT, D G Division of Licensing 84/08/01 3pp 26060 024
24X Fiche 50-334, 84/08/01, 8408130554

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408150124 Forwards fee for 840628 license amend application, consisting of Proposed Change Request 97, per 10CFR170 Application forwarded separately
SIEBER, J D Duquesne Light Co 84/08/07 License Fee Management
Branch 1p 26066 354 24X Fiche 50-334, 84/08/07, 8408150124

8408210058 Forwards Amend 79 to License DPR-66 & safety evaluation Amend revises Tech Specs to reflect new offsite organization W/o encls
TAM, P Operating Reactors Branch 1 84/08/08 CAREY, J J Duquesne
Light Co 1p 26195 162 24X Fiche 50-334, 84/08/08, 8408210058

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8408080212 Forwards IE Insp Rept 50-334/84-15 on 840602-0706 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/07/17
CAREY, J J Duquesne Light Co 2pp 25975 046 24X
Fiche 50-334, 84/07/17, 8408080212

--8408080213 Notice of violation from insp on 840602-0706
* Region 1, Office of Director 84/07/17 2pp 25975 048 24X
Fiche 50-334, 84/07/17, 8408080212

--8408080448 IE Insp Rept 50-334/84-15 on 840602-0706 Violations noted inadequate control of station battery tests, failure to follow station equipment clearance procedures & missed surveillances
TROSKOSKI, W M , JOHNSON, D M , TRIPP, L E Region 1, Office of
Director 84/07/16 16pp 25975 050 24X Fiche 50-334, 84/07/17, 8408080212

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830109) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408160266 Forwards IE Insp Rept 50-334/84-16 on 840625-28 No violations observed
MARTIN, T T Division of Engineering & Technical Programs 84/07/30
CAREY, J J Duquesne Light Co 2pp 26106 148 24X
Fiche 50-334, 84/07/30, 8408160266

--8408160272 IE Insp Rept 50-334/84-16 on 840625-28 No violations identified Major areas inspected annual full-scale emergency exercise
SMITH, R H , CROCKER, H W Region 1, Office of Director 84/07/26
6pp. 26106 150 24X Fiche 50-334, 84/07/30, 8408160266

8408240071 Forwards IE Insp Rept 50-334/84-17 on 840709-13 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/08/03
CAREY, J J Duquesne Light Co 2pp 26237 006 24X
Fiche 50-334, 84/08/03, 8408240071

--8408240076 IE Insp Rept 50-334/84-17 on 840709-13 No violations noted Major areas inspected radiation protection program, including organization & mgt controls, internal exposure control & assessment, ALARA program & unusual event reviews
DRAGOUN, T , JANG, J , SHANBAKY, M M Region 1, Office of Director 84/08/02 6pp 26237 008 24X Fiche 50-334, 84/08/03, 8408240071

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 198 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408230299 Responds to addl concern re IE Bulletin 83-07 concerning apparently fraudulent matls received from Ray Miller, Inc Program for random & periodic exams or tests on sample of products will be implemented by Jan 1985
CAREY, J J Duquesne Light Co 84/08/15 VARGA, S A Operating Reactors Branch 1 EBNETER, S D Region 1, Office of Director 2pp 26208 003 24X Fiche 50-334, 84/08/15, 8408230299

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408270335 Discusses 840612 meeting w/util re encl SALP Repts 50-334/84-13 & 50-412/84-06 Overall assessment of performance for Unit 1 acceptable Lack of mgt control for Unit 2 identified List of meeting attendees encl
MURLEY, T E Region 1, Office of Director 84/08/21 CAREY, J J Duquesne Light Co 6pp 26244 205 24X Fiche 50-334, 84/08/21, 8408270335

--8408270341 Summarizes discussion at 840612 meeting re SALP Repts 50-334/84-13 & 50-412/84-06 Constructability review group for reviewing engineering output & organizational changes established
CAREY, J J Duquesne Light Co 84/06/29 STAROSTECKI, R Division of Project & Resident Programs 22pp 26244 285 24X
Fiche 50-334, 84/08/21, 8408270335

S Reportable occurrences, LERs & related correspondence

8408100113 LER 82-048/03L-1 on 821018, overcurrent condition detected by station svc transformer 1B primary side overcurrent relay Caused by addl loads on associated busses Relay setting increased W/840718 ltr
DRUGA, R J , LACEY, W S Duquesne Light Co 84/07/18 MURLEY, T E
Region 1, Office of Director 4pp 25991 020 24X
Fiche 50-334, 84/07/18, 8408100113

8408100092 LER 84-006-00 on 840621, 18-month surveillance testing methods used on 120-volt dc station batteries determined inadequate Proposed Tech Spec change delaying test tentatively approved W/840720 ltr
DRUGA, R J , LACEY, W S Duquesne Light Co 84/07/20 MURLEY, T E
Region 1, Office of Director 4pp 25991 004 24X
Fiche 50-334, 84/07/20, 8408100092

8408210016 LER 84-008-00 on 840704, reactor shutdown bank rods tripped on pressurizer low pressure trip signal Caused by surveillance test performed w/reactor trip breakers closed Personnel counseled Procedure to be revised W/840801 ltr
DRUGA, R J , LACEY, W S Duquesne Light Co 84/08/01 MURLEY, T E
Region 1, Office of Director 3pp 26181 332 24X
Fiche 50-334, 84/08/01, 8408210016

8408210023 LER 84-007-00 on 840704, containment recirculation cooling coils chilled water sys outlet isolation valve failed shut, causing containment temp to reach 105 OB F Caused by failed pneumatic valve diaphragm W/840801 ltr
DRUGA, R J , LACEY, W S Duquesne Light Co 84/08/01 MURLEY, T E
Region 1, Office of Director 4pp 26146 161 24X
Fiche 50-334, 84/08/01, 8408210023

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8408010091 Forwards request for addl info re procedures generation package for emergency operating procedures Response requested within 30 days of ltr receipt
MILLER, J R Operating Reactors Branch 3 84/07/17 WILLIAMS, J W
Florida Power & Light Co 3pp 25897 064 24X
Fiche 50-335, 84/07/17, 8408010091

8408010303 Forwards SER re alternate safe post-fire shutdown capability, in response to 830402, 1007 & 840119 submittals Util meets App R, Section III G 3 & III L requirements re alternate safe shutdown capability
MILLER, J R Operating Reactors Branch 3 84/07/17 WILLIAMS, J W
Florida Power & Light Co. 2pp 25872 319 24X
Fiche 50-335, 84/07/17, 8408010303

--8408010306 SER re alternate safe post-fire shutdown capability, in response to 830402, 1007 & 840119 submittals Util meets App R, Section III G 3 & III L requirements re alternate safe shutdown capability
* Office of Nuclear Reactor Regulation, Director 84/07/17 7pp 25872 321 24X Fiche. 50-335, 84/07/17, 8408010303

8408030126 Forwards IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/30 WILLIAMS, J W
Florida Power & Light Co 2pp 25916 120 24X
Fiche 50-335, 84/07/30, 8408030126

--8408030127 IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No noncompliance noted Major areas inspected changes to physical security plan & implementing procedures Details withheld (ref 10CFR2 790 & 10CFR73 21)
TILLMAN, A , MCGUIRE, D R. Region 2, Office of Director 84/07/27
1p 25916 122 24X Fiche 50-335, 84/07/30, 8408030126

8408090009 Forwards response to 840605 request for addl info re Rev 8 to physical security plan Response withheld (ref 10CFR73 21)
WILLIAMS, J W Florida Power & Light Co 84/08/06, MILLER, J R
Operating Reactors Branch 3 1p 25973 113 24X
Fiche. 50-335, 84/08/06, 8408090009

8408100016 Forwards Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization "
WILLIAMS,J W Florida Power & Light Co 84/08/08 O'REILLY,J P
Region 2, Office of Director 1p 25987 006 24X
Fiche 50-000,84/08/08,8408100016

--8408100054 Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization "
JOHNSON,M D Florida Power & Light Co 84/08/08 13pp
25987 007 24X Fiche 50-000,84/08/08,8408100016

8408130215 Notifies that responses to 840717 questions re procedure generation package for emergency operating procedures,will be provided,w/assistance of C-E Owners Group Procedure Subcommittee at 840829 meeting w/NRC reviewers
WILLIAMS,J W Florida Power & Light Co 84/08/08 MILLER,J R
Operating Reactors Branch 3 1p 26005 360 24X
Fiche 50-335,84/08/08,8408130215

8408300303 Forwards FEMA "Exercise Rept on St Lucie Nuclear Power Plant Exercise on 840306 "
DANCE,H C Region 2, Office of Director 84/08/14 WILLIAMS,J W
Florida Power Corp 3pp 26306 151 24X Fiche 50-335,84/08/14,
8408300303

8408280097 Revised emergency plan implementing procedures,including 1-0970031, "Loss of SUPS-Nonsafety Vital AC or Fire & Security Inverters" & 2-0030141, "Control Room Inaccessibility " W/840822 ltr
WETHY,C M Florida Power & Light Co 84/08/22 52pp 26261 128
24X Fiche 50-335,84/08/22,8408280097

H General correspondence

8408010338 Responds to 840608 request for comments & views on contents of BL Wells ltr expressing criticisms of safety re removal of thermal shield & storage capacity of spent fuel pools of nuclear power plants in State of FL
DIRCKS,W J Office of the Executive Director for Operations
84/07/20 CHILES,H L Senate 6pp 25872 297 24X
Fiche 50-335,84/07/20,8408010338

--8408010340 Requests comments & views on encl BL Wells 840602 ltr
CHILES,L Senate 84/06/08 KAMMERER,C Office of Congressional Affairs 1p 25872 302 24X Fiche 50-335,84/07/20,8408010338

--8408010342 Forwards Palm Beach Post 840602 article entitled, "Error Costly at Reactor," which cites criticisms of util re removal of thermal heat shield Expresses concern re reserve capacity of spent fuel pools at all Florida nuclear plants
WELLS,B L Affiliation Not Assigned 84/06/02 PALLADINO,N
Commissioners 2pp 25872 303 24X Fiche 50-335,84/07/20,
8408010338

P Operating license stage documents & correspondence

8408030164 Informs that complete response to 840531 request for addl info re util 800808 ltr concerning RCS asymmetric LOCA loads evaluation expected by 841001 Delay due to detailed nature of response
WILLIAMS,J W Florida Power & Light Co 84/07/31 MILLER,J R
Operating Reactors Branch 3 1p 25912 060 24X
Fiche 50-335,84/07/31,8408030164

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090243 Responds to B Wright question re correlation of data on 48-inch purge valves Henry Pratt Co provided verification model testing for 48-inch RIA included model w/disc structure similar to model installed at plant
WILLIAMS,J W Florida Power & Light Co 84/08/06 MILLER,J R
Operating Reactors Branch 3 1p 25972 169 24X
Fiche 50-335,84/08/06,8408090243

8408160319 Forwards "Maint & Surveillance Program Plan," revised following 840706 NRC/NUMARC meeting
RUSSELL,W T Division of Human Factors Safety 84/08/07
WOODY,C O Florida Power & Light Co 1p 26126 019 24X
Fiche 50-000,84/08/07,8408160319

8408160473 Reiterates 840404 request for remission of Class III fee for review of 830825 application resulting in Amend 65 to License DPR-67,per 10CFR170
MILLER,W O License Fee Management Branch 84/08/09 WILLIAMS,J W
Florida Power & Light Co. 1p 26108 352 24X
Fiche 50-335,84/08/09,8408160473

8408170013 Notifies of Class I & II fees due for 840515 & 21 Tech Spec organizational change requests Discussion of fee requirements encl
MILLER,W O License Fee Management Branch 84/08/10 WILLIAMS,J W
Florida Power & Light Co 3pp 26135 347 24X
Fiche 50-335,84/08/10,8408170013

8408230564 Notification of 840906 & 07 meetings w/util in Bethesda,MD to discuss control room design reviews
MCDONALD,D G Operating Reactors Branch 1 84/08/16 VARGA,S A ,
MILLER,J R Operating Reactors Branch 1 2pp 26230 260 24X
Fiche 50-000,84/08/16,8408230564

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

Q Inspection reports, IE Bulletins & correspondence

8408280236 Submits results of Ebasco Svcs review of Ray Miller,Inc supplied matls,in response to IE Bulletin 83-07,per util 840404 ltr Ray Miller products not installed at facilities
WILLIAMS,J W Florida Power & Light Co 84/06/01 O'REILLY,J P
Region 2, Office of Director 2pp 26262 279 24X
Fiche 50-335,84/06/01,8408280236

8408300395 Informs of incorrect rept number on 840530 rept Rept 50-389/84-18 should read 50-389/84-22
DANCE,H C Region 2, Office of Director 84/06/22 WILLIAMS,J W
Florida Power & Light Co 1p 26308 207 24X Fiche 50-335,
84/06/22,8408300395

8408280182 Informs of completion of balance of actions requested in IE Bulletin 82-02 Rept requested in Action Item 4 encl
WILLIAMS,J W Florida Power & Light Co 84/06/26 O'REILLY,J P
Region 2, Office of Director 3pp 26275 194 24X
Fiche 50-335,84/06/26,8408280182

8408280058 Responds to IE Bulletin 84-02 re failure of GE HFA relays in Class 1E safety sys All Unit 1 relays replaced w/Tefzel series relays & spare part specs upgraded Unit 2 relays mfg w/Tefzel spools
WILLIAMS,J W Florida Power & Light Co 84/07/18 O'REILLY,J P
Region 2, Office of Director 3pp 26261 224 24X
Fiche 50-335,84/07/18,8408280058

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408270192 Ack receipt of 840702 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/84-12 & 50-389/84-14
LEWIS,R C Division of Project & Resident Programs 84/07/27
WILLIAMS,J W Florida Power & Light Co 1p 26258 001 24X
Fiche 50-335,84/07/27,8408270192

--8408270200 Responds to NRC 840601 ltr re violations noted in Insp Repts 50-335/84-12 & 50-389/84-14 Corrective actions calibr program under review & QA auditor counseled
WILLIAMS,J W Florida Power & Light Co 84/07/02 O'REILLY,J P
Region 2, Office of Director 3pp 26258 002 24X
Fiche 50-335,84/07/27,8408270192

--8408270209 Forwards Insp Repts 50-335/84-12 & 50-389/84-14 on 840423-27 & notice of violation
LEWIS,R C Division of Project & Resident Programs 84/06/01
WILLIAMS,J W Florida Power & Light Co 2pp 26258 005 24X
Fiche 50-335,84/07/27,8408270192

--8408270214 Notice of Violation from insp on 840423-27
* Region 2, Office of Director 84/06/01 2pp 26258 007 24X
Fiche 50-335,84/07/27,8408270192

--8408270221 Insp Repts 50-335/84-12 & 50-389/84-14 on 840423-27 Violations noted failure to include gauges in calibr program & failure to audit calibr program sufficiently
BELISLE,G A , FOSTER,L E , UPRIGHT,C M Region 2, Office of Director 84/05/25 15pp 26258 009 24X Fiche 50-335,84/07/27,
8408270192

8408270360 Forwards Insp Repts 50-335/84-21 & 50-389/84-23 on 840510-0714 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/27 WILLIAMS, J W
Florida Power & Light Co 2pp 26257 221 24X
Fiche 50-335, 84/07/27, 8408270360

--8408270363 Insp Repts 50-335/84-21 & 50-389/84-23 on 840610-0714 No violations noted Major areas inspected plant surveillance & maint observations
FEIERABEND, C D , DIBB, H E Region 2, Office of Director
ELROD, S A Division of Project & Resident Programs 84/07/27
4pp 26257 223 24X Fiche 50-335, 84/07/27, 8408270360

8408030126 Forwards IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/30 WILLIAMS, J W
Florida Power & Light Co 2pp 25916 120 24X
Fiche 50-335, 84/07/30, 8408030126

--8408030127 IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No noncompliance noted Major areas inspected changes to physical security plan & implementing procedures Details withheld (ref 10CFR2 790 & 10CFR73 21)
TILLMAN, A , MCGUIRE, D R Region 2, Office of Director 84/07/27
1p 25916 122 24X Fiche 50-335, 84/07/30, 8408030126

8408270291 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/84-18 & 50-389/84-19
DANCE, H C Region 2, Office of Director 84/08/02 WILLIAMS, J W
Florida Power & Light Co 1p 26258 178 24X Fiche 50-335, 84/08/02, 8408270291

--8408270298 Responds to NRC 840608 ltr re violations noted in Insp Repts 50-335/84-18 & 50-389/84-19 Corrective actions installed detectors will be replaced & two spare detectors properly calibr
WILLIAMS, J W Florida Power & Light Co 84/07/09 O'REILLY, J P
Region 2, Office of Director 2pp 26258 179 24X
Fiche 50-335, 84/08/02, 8408270291

--8408270306 Forwards Insp Repts 50-335/84-18 & 50-389/84-19 an 840514-18 & notice of violation
DANCE, H C Region 2, Office of Director 84/06/08 WILLIAMS, J W
Florida Power & Light Co 2pp 26258 181 24X
Fiche 50-335, 84/08/02, 8408270291

--8408270310 Notice of violation from insp on 840514-18
* Region 2, Office of Director 84/06/08 1p 26258 183 24X
Fiche 50-335, 84/08/02, 8408270291

--8408270317 Insp Repts 50-335/84-18 & 50-389/84-19 on 840514-18 Noncompliance noted failure to certify proper vendor calibr of containment high-range radiation monitors prior to initial use
WRAY, J R , JENKINS, O R. Region 2, Office of Director 84/06/08
6pp 26258 184 24X Fiche 50-335, 84/08/02, 8408270291

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118. 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408170233 Forwards inservice insp rept, per ASME Code Section XI
WILLIAMS, J W Florida Power & Light Co 84/08/14 EISENHUT, D G
Division of Licensing 1p 26115 274 24X Fiche 50-335, 84/08/14, 8408170233

--8408170237 Inservice insp rept on 830302-840516, describing exams performed on pressure containment appurtenance for in-core instrumentation flange assembly
* Florida Power & Light Co 84/08/09 29pp 26115 275 24X
Fiche 50-335, 84/08/14, 8408170233

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100035 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100035

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408030235 LER 84-005-00 on 840626, reactor tripped due to failed MSIV Caused by failure of rupture disc in air supply to valve operator Rupture disk replaced & valve tested & returned to svc W/840725 ltr
WEST, D , WILLIAMS, J W Florida Power & Light Co 84/07/25 2pp
25917 190 24X Fiche 50-335, 84/07/25, 8408030235

V Operator Examinations

8408300392 Confirms that operator who failed Section 7 of NRC senior reactor operator upgrade written exam, administered on 840619, has been prohibited from performing licensed duties
O'REILLY, J P Region 2, Office of Director 84/08/13
WILLIAMS, J W Florida Power & Light Co 2pp 26308 120 24X
Fiche 50-335, 84/08/13, 8408300392

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8408010288 Forwards IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/11
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25866 200 24X Fiche 50-245, 84/07/11, 8408010288

--8408010292 IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 Violations noted failure to adhere to Tech Spec 6 11 procedures for radiation work permit preparation
NIMITZ, R L Region 1, Office of Director 84/07/02 12pp
25866 203 24X Fiche 50-245, 84/07/11, 8408010288

8408080353 Forwards IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 & notice of violations Also ack receipt of 840508 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-336/84-02
STAROSTECKI, R Division of Project & Resident Programs 84/07/20
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 25975 021 24X Fiche 50-245, 84/07/20, 8408080353

--8408080403 IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 Violations noted failure to follow radiation protection procedures & fulfill station security plan commitments Safeguards info deleted
SHEDLOSKI, J T Region 1, Office of Director 84/06/26 3pp,
25975 026 24X Fiche 50-245, 84/07/20, 8408080353

8408150608 Forwards IE Safeguards Insp Repts 50-245/84-14 & 50-336/84-14 on 840604-08 No noncompliance noted Steps taken to correct violations discussed in 831107 & 16 ltrs verified
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26079 001 24X Fiche 50-245, 84/07/27, 8408150688

-8408150693 IE Safeguards Insp Repts 50-245/84-14 & 50-336/84-14 on 840604-08 No noncompliance noted Major areas inspected security program audit & organization, testing & maint & assessment aids Safeguards info deleted (ref 10CFR2 790)
MADDEN, W Region 1, Office of Director 84/07/26 4pp
26079 003 24X Fiche 50-245, 84/07/27, 8408150688

8408210494 Forwards IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 & notices of violation & deviation
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities), 2pp 26187 145 24X Fiche 50-245, 84/08/01, 8408210494

-8408210495 Notice of violation from insp on 840611-15
* Region 1, Office of Director 84/08/01 1p 26187 147 24X Fiche 50-245, 84/08/01, 8408210494

-8408210496 Notice of deviation from insp on 840611-15
* Region 1, Office of Director 84/08/01 1p 26187 148 24X Fiche 50-245, 84/08/01, 8408210494

-8408210501 IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 Violations identified failure to perform surveillance testing per Tech Specs & to maintain integrity of fire barriers
KRASOPOULOS, A Region 1, Office of Director 84/07/27 1p
26187 149 24X Fiche 50-245, 84/08/01, 8408210494

8408160350 Forwards revised emergency plan implementation procedures, including CONI 1 02 re corporate organization for nuclear incidents & CONI 4 02 re on-call manager of radiological consequences assessment W/o encls
COUNSIL, W G Northeast Utilities 84/08/13 Record Services Branch (Document Control Desk) 2ppl 26091 193 24X
Fiche 50-000, 84/08/13, 8408160350

8408280171 Responds to 840712 interpretation of order confirming licensee commitments on emergency capability, focusing on Suppl 1 to NUREG-0737 requirements Integrated assessment to be conducted pending Congressional consent
EISENHUT, D G Division of Licensing 84/08/23 COUNSIL, W G
Connecticut Yankee Atomic Power Co 3pp 26279.224 24X
Fiche 50-000, 84/08/23, 8408280171

8408310187 Submits update to corrective actions taken re deficiencies noted during 840512 emergency preparedness exercise Emergency action level procedure revised to place greater emphasis on classification/reclassification of emergencies.
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/08/23 MURLEY, T E Region 1, Office of Director. 3pp 26318 330 24X Fiche 50-000, 84/08/23, 8408310187

General correspondence

08070321 Advises that K McCarthy should appear on license amends as appropriate state official to receive amend applications McCarthy new director of radiation control for State of CT, Dept of Environ Protection
COUNSIL, W G. Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/07/27. MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 1p 25945:128 24X Fiche 50-000, 84/07/27, 8408070321

Operating license stage documents & correspondence

8408070341 Clarifies Figure 7 3-1 of thermal shield damage recovery program final rept Figure shows views of core support barrel before & after milling of insp slot & crack arrestor hole
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/07/27
MILLER, J R Operating Reactors Branch 3 1p 25945-209 24X
Fiche 50-336, 84/07/27, 8408070341

8408100063 Forwards Vols I & II of "NUSCo Thermal Hydraulic Model Qualification," For RETRAN & VIPRE
COUNSIL, W G Connecticut Yankee Atomic Power Co. COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities)
COUNSIL, W G Northeast Utilities. 84/07/30 MILLER, J. R Operating Reactors Branch 3 CRUTCHFIELD, D. Operating Reactors Branch 5
2pp 25987 072 24X Fiche. 50-213, 84/07/30, 8408100063

--8408100070 Vol I of "NUSCo Thermal Hydraulic Model Qualification (RETRAN) "
* Northeast Utilities NUSCO 140-1 84/07/30 262pp
25987 074 24X Fiche 50-213, 84/07/30, 8408100063

--8408100077 Vol II of "NUSCo Thermal Hydraulic Model Qualification (VIPRE) "
* Northeast Utilities NUSCO 140-2 84/07/30 225pp
25987 336 24X Fiche 50-213, 84/07/30, 8408100063

8408070320 Ack receipt of 840608 ltr forwarding Rev 6 to QA program topical rept, per 10CFR50 54 & 50 55 Revs acceptable
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 25945 244
24X Fiche 50-000, 84/08/01, 8408070320

8408150232 Advises that due to extended outage in late 1983, 1984 refueling outage will not occur Next scheduled refueling outage will occur in Feb 1985 All mods scheduled for completion prior to startup following 1985 outage
COUNSIL, W G Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/08/02
MILLER, J R Operating Reactors Branch 3 1p 26066 004 24X
Fiche 50-336, 84/08/02, 8408150232

8408200161 Forwards Amend 96 to License DPR-65 & safety evaluation Amend changes Tech Specs to clarify frequency for visual insps & clarifies requirements for functional testing of snubbers which visually appear inoperable
OSBORNE, D B Operating Reactors Branch 3 84/08/02 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp
26182 177 24X Fiche 50-336, 84/08/02, 8408200161

--8408200164 Amend 96 to License DPR-65, clarifying frequency for visual insps, providing requirements for functional testing of snubbers, revising method of snubber listing to incorporate addl info & clarifying testing acceptance criteria
MILLER, J R Operating Reactors Branch 3 84/08/02 27pp
26182 179 24X Fiche 50-336, 84/08/02, 8408200161

--8408200169 Safety evaluation supporting Amend 96 to License DPR-65
* Office of Nuclear Reactor Regulation, Director 84/08/02 4pp
26182 208 24X Fiche 50-336, 84/08/02, 8408200161

--8408200173 "Technical Evaluation Rept on Proposed Tech Spec Changes for Inservice Surveillance of Safety-Related Hydraulic & Mechanical Snubbers at Millstone Nuclear Power Station, Unit 2 "
BELAN, J C Lawrence Livermore National Laboratory FIN A-0250
UCID-19718 83/08/18 NRC - No Detailed Affiliation Given
15pp 26182 212 24X Fiche 50-336, 84/08/02, 8408200161

8408130316 Clarifies SER of Amend 95 to License DPR-65 re spacing discrepancy in reed switches in CEA position indication sys
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/08/03
MILLER, J R Operating Reactors Branch 3 1p 26010 328 24X
Fiche 50-336, 84/08/03, 8408130316

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200172 Forwards response to 840709 request for addl info re inadequate core cooling instrumentation, per Generic Ltr 82-28 Comments re subcooled margin monitor, core exit thermocouples & heated junction thermocouples encl
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/08/14
MILLER, J R Operating Reactors Branch 3 34pp 26133 025 24X
Fiche 50-336, 84/08/14, 8408200172

8408290298 Requests extension until 841214 to respond to Generic Ltr 84-15 re proposed staff actions to improve & maintain diesel generator reliability Addl time will result in more complete & concise submittal
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 84/08/17 EISENHUT, D G Division of Licensing 2pp 26290 342 24X Fiche 50-000, 84/08/17, 8408290298

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl.
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8408010288 Forwards IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/11
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 25866 200 24X Fiche 50-245, 84/07/11, 8408010288

--8408010292 IE Insp Repts 50-245/84-13 & 50-336/84-13 on 840529-0601
Violations noted failure to adhere to Tech Spec 6 11 procedures for radiation work permit preparation
NIMITZ, R L , SHANBAKY, M M Region 1, Office of Director
84/07/02 12pp 25866 203 24X Fiche 50-245, 84/07/11, 8408010288

8408080353 Forwards IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609 & notice of violations Also ack receipt of 840508 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-336/84-02
STAROSTECKI, R Division of Project & Resident Programs 84/07/20
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 25975 021 24X Fiche 50-245, 84/07/20, 8408080353

--8408080403 IE Insp Repts 50-245/84-11 & 50-336/84-12 on 840506-0609
Violations noted failure to follow radiation protection procedures & fulfill station security plan commitments
Safeguards info deleted
SHEDLOSKY, J T , LIPINSKI, D R Region 1, Office of Director
ELGASSER, T C Division of Project & Resident Programs 84/06/26
3pp 25975 026 24X Fiche 50-245, 84/07/20, 8408080353

--8408080414 Responds to NRC 840213 & 0409 ltrs re violations noted in IE Insp Rept 50-336/84-02 Corrective actions Instrument & Controls Procedure IC 2417M re design changes revised
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/05/08
MURLEY, T E Region 1, Office of Director 5pp 25975 041 24X Fiche 50-245, 84/07/20, 8408080353

8408150107 Forwards IE Insp Rept 50-336/84-16 on 840613-15 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/07/26
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26073 323 24X Fiche 50-336, 84/07/26, 8408150107

--8408150110 IE Insp Rept 50-336/84-16 on 840613-15 No violations noted Major areas inspected repeated failures of coolant charging pumps
WOODARD, C H , ANDERSON, C J Region 1, Office of Director
84/07/12 4pp 26073 325 24X Fiche 50-336, 84/07/26, 8408150107

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408150688 Forwards IE Safeguards Insp Repts 50-245/84-14 & 50-336/84-14 on 840604-08 No noncompliance noted Steps taken to correct violations discussed in 831107 & 16 ltrs verified
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26079 001 24X Fiche 50-245, 84/07/27, 8408150688

--8408150693 IE Safeguards Insp Repts 50-245/84-14 & 50-336/84-14 on 840604-08 No noncompliance noted Major areas inspected, security program audit & organization, testing & maint & assessment aids Safeguards info deleted (ref 10CFR2 790)
MADDEN, W , KEIMIG, R R Region 1, Office of Director 84/07/26
4pp 26079 003 24X Fiche 50-245, 84/07/27, 8408150688

8408100116 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Entry & engineering evaluation for Millstone Unit 2 will be done by Feb 1985 refueling outage No Ray Miller products supplied at Haddam
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Connecticut Yankee Atomic Power Co
COUNSIL, W G Northeast Utilities 84/07/31 MURLEY, T E. Region 1, Office of Director 3pp 25988 247 24X Fiche 50-000, 84/07/31, 8408100116

8408210494 Forwards IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15 & notices of violation & deviation
MARTIN, T T Division of Engineering & Technical Programs. 84/08/01.
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26187 145 24X Fiche 50-245, 84/08/01, 8408210494

--8408210495 Notice of violation from insp on 840611-15
* Region 1, Office of Director 84/08/01 1p 26187 147 24X Fiche 50-245, 84/08/01, 8408210494

--8408210496 Notice of deviation from insp on 840611-15
* Region 1, Office of Director 84/08/01 1p 26187 148 24X Fiche 50-245, 84/08/01, 8408210494

--8408210501 IE Insp Repts 50-245/84-15 & 50-336/84-15 on 840611-15
Violations identified failure to perform surveillance testing per Tech Specs & to maintain integrity of fire barriers
KRASOPOULOS, A , PULLANI, S V , ANDERSON, C J Region 1, Office of Director 84/07/27 1p 26187 149 24X Fiche 50-245, 84/08/01, 8408210494

8408210515 Forwards IE Insp Rept 50-336/84-17 on 840626-28 No violations observed
MARTIN, T T Division of Engineering & Technical Programs 84/08/01
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26185 255 24X Fiche 50-336, 84/08/01, 8408210515

--8408210517 IE Insp Rept 50-336/84-17 on 840626-28 No violations observed Major areas inspected inservice insp program & volumetric exam relief request on reactor coolant pump cast stainless steel welds (TAC 55011)
GRAY, E H , DURR, J P Region 1, Office of Director 84/07/20
5pp 26185 257. 24X Fiche 50-336, 84/08/01, 8408210515

8408200161 Forwards Amend 96 to License DPR-65 & safety evaluation Amend changes Tech Specs to clarify frequency for visual insps & clarifies requirements for functional testing of snubbers which visually appear inoperable
OSBORNE, D B Operating Reactors Branch 3 84/08/02 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26182 177 24X Fiche 50-336, 84/08/02, 8408200161

--8408200164 Amend 96 to License DPR-65, clarifying frequency for visual insps, providing requirements for functional testing of snubbers, revising method of snubber listing to incorporate addl info & clarifying testing acceptance criteria
MILLER, J R Operating Reactors Branch 3 84/08/02 29pp
26182 179 24X Fiche 50-336, 84/08/02, 8408200161

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08. Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche: 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp. 26198 093 24X Fiche: 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co. of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408210468 Ack receipt of 840702 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-336/80-11
MARTIN, T. T Division of Engineering & Technical Programs 84/08/16
COUNSIL, W G Northeast Nuclear Energy Co. (subs of Northeast Utilities) 2pp 26181 117 24X Fiche 50-336, 84/08/16, 8408210468

DOCKETED ITEMS

08210469 Responds to NRC 810319 ltr re violations noted in IE Insp Rept 50-336/80-11 Corrective actions offstream liquid effluent monitors will be installed by 841130
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities 84/07/02
MURLEY,T E Region 1, Office of Director 2pp 26181 119 24X Fiche 50-336,84/08/16,8408210468

100055 IE Info Notice 84-66, "Undetected Unavailability of rbine-Driven Auxiliary Feedwater Train " Svc list encl
RDAN,E L Division of Emergency Preparedness & Engineering sponse (Post 830103) 84/08/17 Consolidated Edison Co of New rk, Inc 12Opp 26276 001 24X Fiche 50-000,84/08/17,8408100055

3140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ gh Failure Rates " Svc list encl
RDAN,E L Division of Emergency Preparedness & Engineering sponse (Post 830103) 84/08/17 Consolidated Edison Co of New rk, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

210142 IE Info Notice 84-68, "Potential Deficiency in Improperly ited Field Wiring to Solenoid Valves " Svc list encl
RDAN,E L Division of Emergency Preparedness & Engineering sponse (Post 830103) 84/08/21 Consolidated Edison Co of New rk, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

Periodic operating reports & related correspondence

8200594 Monthly operating rept for Jul 1984.W/840813 ltr
IBSON,J , MROCZKA,E J Northeast Nuclear Energy Co (subs of rtheast Utilities) MROCZKA,E J Northeast Utilities 84/07/31 1p 26138 122 24X Fiche 50-336,84/07/31,8408200594

Reportable occurrences, LERs & related correspondence

8080531 LER 84-009-00 on 840703,during walk-through fire insp,while lant at 75% power,discovered door between east & west 30-volt switchgear rooms did not have required fire rating or replaced W/840730 ltr
ESLANDES,R D , MROCZKA,E J Northeast Utilities 84/07/30 3pp 5975 290 24X Fiche 50-336,84/07/30,8408080531

NET 50-338 NORTH ANNA POWER STATION, UNIT 1

Security, medical, emergency & fire protection plans

8310069 Confirms 840524 visit to Region to discuss access control at acilities
EWIS,R C Region 2, Office of Director 84/05/22 STEWART,W L irginia Electric & Power Co 1p 26333 342 24X iche 50-000,84/05/22,8408310069

8310401 Forwards summary of 840524 meeting re security interface ctivities Meeting beneficial & provided better nderstanding between security staffs
WIS,R C Region 2, Office of Director 84/06/06 STEWART,W L rginia Electric & Power Co 4pp 26333 311 24X che 50-000,84/06/06,8408310401

140029 Forwards corrected Page 2 to attachment to 840614 order nfirming licensee commitments to implement post-TMI lated items in Suppl 1 to NUREG-0737, "Requirements for ergency Response Capability" (Generic Ltr 82-33)
LLER,J R Operating Reactors Branch 3 84/07/24 STEWART,W L rginia Electric & Power Co 3pp 26061 259 24X che 50-338,84/07/24,8408140029

08140033 Correction to 840414 order confirming licensee commitments to Suppl 1 to NUREG-0737 Completion date for technical support ctr to be fully functional changed to 850731
MILLER,J R Operating Reactors Branch 3 84/07/24 Virginia Electric & Power Co 1p 26061 263, 24X Fiche 50-338,84/07/24, 8408140029

8070039 Forwards replacement pages to control room design review rogram plan Adoption of Westinghouse Owners Group emergency esponse guidelines as basis for task analysis & erification/validation sections principal changes
TEWART,W L Virginia Electric & Power Co 84/07/27 DENTON,H R ffice of Nuclear Reactor Regulation, Director EISENHUT,D G ivision of Licensing 8pp 25949:281, 24X Fiche 50-000,84/07/27, 8408070039

8070400 Forwards "VEPCO North Anna Power Station,Units 1 & 2 OCFR50,App R Rept - App A," per 840515 request Rept ncludes summary comparison of 1984 App R reanalysis & util 20622 post-fire safe shutdown review
TEWART,W L Virginia Electric & Power Co 84/07/27 DENTON,H R ffice of Nuclear Reactor Regulation, Director MILLER,J R erating Reactors Branch 3, 3pp 25942 191 24X iche,50-338,84/07/27,8408070400

--8408070406 "VEPCO North Anna Power Station,Units 1 & 2 10CFR50,App R Rept - App A "
* Virginia Electric & Power Co 84/06/30 17pp 25942 194 24X Fiche 50-338,84/07/27,8408070400

8408020028 Forwards lists of mods & revised schedules re 10CFR50 4B, App R reanalysis Compensatory measures for mods specified Completion of App R reanalysis scheduled for 840812
STEWART,W L Virginia Electric & Power Co 84/07/31 DENTON,H R Office of Nuclear Reactor Regulation, Director EISENHUT,D G Division of Licensing 9pp 25880 265 24X Fiche 50-338,84/07/31, 8408020028

8408130394 Ack receipt of 840710 & 0801 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18
LEWIS,R C Division of Project & Resident Programs 84/08/09
STEWART,W L Virginia Electric & Power Co 1p 26010 124 24X Fiche 50-338,84/08/09,8408130394

--8408130400 Responds to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21)
STEWART,W L Virginia Electric & Power Co 84/07/10
O'REILLY,J P Region 2, Office of Director 1p 26010 125 24X Fiche 50-338,84/08/09,8408130394

--8408130403 Suppls response to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21)
STEWART,W L Virginia Electric & Power Co 84/08/01
O'REILLY,J P Region 2, Office of Director 1p 26010 126 24X Fiche 50-338,84/08/09,8408130394

--8408130408 Forwards IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21)
LEWIS,R C Region 2, Office of Director 84/06/11 STEWART,W L Virginia Electric & Power Co 2pp 26010 127 24X Fiche 50-338,84/08/09,8408130394

--8408130418 IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 Noncompliance noted in area of access control for personnel Details withheld (ref 10CFR2 790 & 10CFR73 21)
ENNIS,J D , MCGUIRE,D R Region 2, Office of Director 84/06/08 1p 26010 129 24X Fiche 50-338,84/08/09,8408130394

8408130433 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25
LEWIS,R C Division of Project & Resident Programs 84/08/09
STEWART,W L Virginia Electric & Power Co 1p 26005 339 24X Fiche 50-338,84/08/09,8408130433

--8408130438 Responds to NRC 840629 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 Corrective actions withheld (ref 10CFR73 21)
STEWART,W L Virginia Electric & Power Co 84/07/27
O'REILLY,J P Region 2, Office of Director 1p 26005 340 24X Fiche 50-338,84/08/09,8408130433

--8408130443 Forwards IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21)
LEWIS,R C Region 2, Office of Director 84/06/29 STEWART,W L Virginia Electric & Power Co 2pp 26005 341 24X Fiche 50-338,84/08/09,8408130433

--8408130446 IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 Violation noted re access to vital area Details withheld (ref 10CFR2 790 & 10CFR73 21)
HALL,B L , MCGUIRE,D R Region 2, Office of Director 84/06/26, 1p 26005 343 24X Fiche 50-338,84/08/09,8408130433

8408200387 Advises that program plan for conducting detailed control room design review meets intent of Suppl 1 to NUREG-0737 Listed areas should be described in summary rept expected 850830
VARGA,S A Licensing Branch 1 84/08/10 STEWART,W L Virginia Electric & Power Co 2pp 26141 215 24X Fiche 50-000,84/08/10, 8408200387

8408290330 Forwards Safeguards Insp Repts 50-338/84-31 & 50-339/84-31 on 840806-10 No violations or deviations noted Repts withheld (ref 10CFR2 790 & 73 21)
DANCE,H C Division of Project & Resident Programs 84/08/27
STEWART,W L Virginia Electric & Power Co 2pp 26289 345 24X Fiche 50-338,84/08/27,8408290330

G Adjudicatory correspondence

8408010250 Informs that util & NRC intend to file response to objectionable contentions by 840817, based on discussions w/ parties
DOUGHERTY, J B Dougherty, J B DOUGHERTY, J B Concerned Citizens of Louisa County, VA DSB 665 84/07/30 WOLFE, S J , FERGUSON, G A , KLINE, J Atomic Safety and Licensing Board Panel
10pp 25854 342 24X Fiche 50-338, 84/07/30, 8408010250

8408150464 Response to 840730 third draft of contentions of Concerned Citizens of Louisa County All but Contention 4 should be denied Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams DSB 056 84/08/14 Atomic Safety and Licensing Board Panel 31pp 26068 165 24X Fiche 50-338, 84/08/14, 8408150464

8408200477 Forwards response to contentions of Concerned Citizens of Louisa County W/o encl Related correspondence
MAUPIN, M W Hunton & Williams MAUPIN, M W Virginia Electric & Power Co DSB 157 84/08/14 Docketing & Services Branch 1p
26134 306 24X Fiche 50-338, 84/08/14, 8408200477

8408200587 Forwards NRC response to Concerned Citizens of Louisa County third draft of contentions Request by NRC for 1-day extension in date for filing response granted by Chairman Wolfe
LEWIS, S H Hearing Branch 2 DSB 173 84/08/15 WOLFE, S J , KLINE, J , FERGUSON, G A Atomic Safety and Licensing Board Panel
1p 26137 140 24X Fiche 50-338, 84/08/15, 8408200587

--8408200593 Response to Concerned Citizens of Louisa County third draft of contentions Certificate of Svc encl
MCGURREN, H J Hearing Branch 1 LEWIS, S H Hearing Branch 2 84/08/15 Atomic Safety and Licensing Board Panel 15pp
26137 141 24X Fiche 50-338, 84/08/15, 8408200587

8408300129 Response supporting admission of Concerned Citizens of Louisa County 840814 revised Contention 4 Certificate of Svc encl
HASSELL, D F Hearing Branch 1 DSB 380 84/08/27 Atomic Safety and Licensing Board Panel 4pp 26304 358 24X
Fiche 50-338, 84/08/27, 8408300129

8408300177 Response to Concerned Citizens of Louisa County, VA (CCLC) revised Contention 4 re physical protection sys for spent fuel shipments Protective order necessary for CCLC access Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams DSB 384 84/08/27 Atomic Safety and Licensing Board Panel 14pp 26305 343 24X Fiche 50-338, 84/08/27, 8408300177

8408310150 Forwards applicant response to Concerned Citizens of Louisa County, VA revised Contention 4 W/o encl Related correspondence
MAUPIN, M W Hunton & Williams MAUPIN, M W Virginia Electric & Power Co DSB 414 84/08/27 Docketing & Services Branch 1p
26322, 202 24X Fiche 50-338, 84/08/27, 8408310150

8408310148 Order scheduling supplemental special prehearing conference on 840907 in Bethesda, MD & directing participants to appear Served on 840830
WOLFE, S J Atomic Safety and Licensing Board Panel DSB 392
84/08/28 Office of the Executive Legal Director 3pp
26320-358 24X Fiche 50-338, 84/08/28, 8408310148

P Operating license stage documents & correspondence

8408300369 Confirms 840501 telcon w/HC Dance re 840510 mgt meeting in Region II ofc to discuss organizational structure
LEWIS, R C Region 2, Office of Director 84/05/07 STEWART, W L
Virginia Electric & Power Co 1p 26308 230 24X
Fiche 50-000, 84/05/07, 8408300369

8408130223 Forwards safety evaluation re util 831104 response to Generic Ltr 83-28, Item 4 3, "Reactor Trip Sys Reliability " Design mods acceptable
MILLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W L
Virginia Electric & Power Co 2pp 26058 313 24X
Fiche, 50-338, 84/07/24, 8408130223

--8408130226 Safety evaluation supporting licensee response to Generic Ltr 83-28, Item 4 3, "Reactor Trip Sys Reliability " Design mods acceptable
* NRC - No Detailed Affiliation Given 84/07/24 10pp
26058 315 24X Fiche 50-338, 84/07/24, 8408130223

8408140063 Forwards comments & questions for review & requests site visit to further discuss inservice testing program NRR should be contacted in approx 4 wks to confirm time & date for meeting
MILLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W L
Virginia Electric & Power Co 9pp 26061 267 24X
Fiche 50-338, 84/07/24, 8408140063

8408090235 Application for amends to Licenses NPF-4 & NPF-7, revising Tech Specs re limiting conditions for operation & surveillance requirements consistent w/STS
STEWART, W L Virginia Electric & Power Co 84/08/01 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 4pp 25972 141 24X
Fiche 50-338, 84/08/01, 8408090235

--8408090239 Proposed Tech Spec changes re limiting conditions for operation & surveillance requirements, to provide consistency w/STS
* Virginia Electric & Power Co 84/08/01 7pp 25972 145 24X
Fiche 50-338, 84/08/01, 8408090235

8408090441 Notification of 840803 meeting w/util in Bethesda, MD to discuss compensatory measures for addressing nonqualification paint on ductwork inside containment
ENGLE, L B Operating Reactors Branch 3 84/08/02 MILLER, J R
Operating Reactors Branch 3 2pp 25982 354 24X
Fiche 50-338, 84/08/02, 8408090441

8408090149 Provides upgraded in-core thermocouple implementation schedule, per 840221 commitment Util proposes to complete Reg Guide 1 97 (ref NUREG-0737, Item II F 2) mods prior to or during 1986 refueling outages
STEWART, W L Virginia Electric & Power Co 84/08/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 2pp 25973 122 24X Fiche 50-338, 84/08/03, 8408090149

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408210575 Summary of 840803 meeting w/util in Bethesda, MD re nonqualified paint inside containment List of attendees & agenda encl
ENGLE, L B Operating Reactors Branch 3 84/08/13 MILLER, J R
Operating Reactors Branch 3 20pp 26195 226 24X
Fiche 50-338, 84/08/13, 8408210575

8408170300 Requests relief from ASME hydrostatic testing requirements No leakage observed from welds on both sides of new valves during recent pressure test of reactor containment
STEWART, W L Virginia Electric & Power Co 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 3pp 26115 070 24X
Fiche 50-338, 84/08/14, 8408170300

8408210132 Forwards Generic Ltr 84-15 response schedule, listing 840928 & 850131 as projected dates Justification for extension of responses included
STEWART, W L Virginia Electric & Power Co 84/08/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 3pp 26181 348 24X Fiche 50-000, 84/08/16, 8408210132

8408210375 Forwards B&W summary technical repts of first capsule from reactor vessel surveillance program, per App H of 10CFR50 Repts delayed due to administrative oversight
STEWART, W L Virginia Electric & Power Co 84/08/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26178 001 24X
Fiche 50-338, 84/08/16, 8408210375

--8408210387 "Analysis of Capsule V, VEPCO, North Anna Unit 2, Reactor Vessel Matls Surveillance Program "
LOWE, A L , COLLINS, L L , PAVINICH, W A Babcock & Wilcox Co
BAW-1794 83/10/31 173pp 26178 002 24X Fiche 50-338, 84/08/16, 8408210375

--8408210393 "Analysis of Capsule V, VEPCO, North Anna Unit 1, Reactor Vessel Matls Surveillance Program "
LOWE, A L , PAVINICH, W A , SCHMOTZER, J K Babcock & Wilcox Co
BAW-1638 81/05/31 76pp 26178 099 24X Fiche 50-338, 84/08/16, 8408210375

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8408270387 Forwards Insp Repts 50-338/84-24 & 50-339/84-24 on 840618-22 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/11 STEWART, W L
Virginia Electric & Power Co 2pp 26256 278 24X
Fiche 50-338, 84/07/11, 8408270387

--8408270388 Insp Repts 50-338/84-24 & 50-339/84-24 on 840618-22 No violations or deviations noted Major areas inspected plant chemistry & employee concerns
ROSS, W J , BLAKE, J J Region 2, Office of Director 84/07/09
15pp 26256 280 24X Fiche 50-338, 84/07/11, 8408270387

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408020041 Forwards insp fees for Surry Power Station & North Anna, Unit 1 for Mar 1983 - Mar 1984 & North Anna, Unit 2 for Apr 1983 - Apr 1984
STEWART, W L Virginia Electric & Power Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25880 304 24X
Fiche 50-000, 84/07/27, 8408020041

8408280150 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " All GE Type HFA relays in safety-related applications will be replaced
STEWART, W L Virginia Electric & Power Co 84/07/31 O'REILLY, J P
Region 2, Office of Director 4pp 26259 082 24X
Fiche 50-000, 84/07/31, 8408280150

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408130394 Ack receipt of 840710 & 0801 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18
LEWIS, R C Division of Project & Resident Programs 84/08/09
STEWART, W L Virginia Electric & Power Co 1p 26010 124 24X
Fiche 50-338, 84/08/09, 8408130394

--8408130400 Responds to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co. 84/07/10
O'REILLY, J P Region 2, Office of Director 1p 26010 125 24X
Fiche 50-338, 84/08/09, 8408130394

--8408130403 Supplis response to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 84/08/01
O'REILLY, J P Region 2, Office of Director. 1p. 26010 126 24X
Fiche 50-338, 84/08/09, 8408130394

-8408130408 Forwards IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21).
LEWIS, R.C Region 2, Office of Director 84/06/11 STEWART, W L
Virginia Electric & Power Co 2pp 26010. 127 24X
Fiche 50-338, 84/08/09, 8408130394

--8408130418 IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 Noncompliance noted in area of access control for personnel Details withheld (ref 10CFR2 790 & 10CFR73 21)
ENNIS, J D , MCGUIRE, D R Region 2, Office of Director 84/06/08
1p 26010 129 24X Fiche 50-338, 84/08/09, 8408130394

8408130433 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25
LEWIS, R C Division of Project & Resident Programs 84/08/09
STEWART, W L Virginia Electric & Power Co 1p 26005 339 24X
Fiche 50-338, 84/08/09, 8408130433

--8408130438 Responds to NRC 840629 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 Corrective actions withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 84/07/27
O'REILLY, J P Region 2, Office of Director 1p 26005 340 24X
Fiche 50-338, 84/08/09, 8408130433

--8408130443 Forwards IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21)
LEWIS, R C Region 2, Office of Director 84/06/29 STEWART, W L
Virginia Electric & Power Co 2pp 26005 341 24X
Fiche 50-338, 84/08/09, 8408130433

--8408130446 IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 Violation noted re access to vital area Details withheld (ref 10CFR2 790 & 10CFR73 21)
HALL, B L , MCGUIRE, D R Region 2, Office of Director 84/06/26
1p 26005 343 24X Fiche 50-338, 84/08/09, 8408130433

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408290330 Forwards Safeguards Insp Repts 50-338/84-31 & 50-339/84-31 on 840806-10 No violations or deviations noted Repts withheld (ref 10CFR2 790 & 73 21)
DANCE, H C Division of Project & Resident Programs 84/08/27
STEWART, W L Virginia Electric & Power Co 2pp 26289 345 24X
Fiche 50-338, 84/08/27, 8408290330

S. Reportable occurrences, LERs & related correspondence

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/08/16
EISENHUT, D G Division of Licensing 20pp 26233 249 24X
Fiche 50-000, 84/08/16, 8408230077

8408230392 PNO-II-84-051 on 840817, earth tremor measuring 3 8 on Richter scale occurred Tremor did not trip plant seismic monitoring equipment
ELROD, S A , DANCE, H C Region 2, Office of Director 84/08/17 1p 26209 303 24X Fiche 50-338, 84/08/17, 8408230392

8408290193 Informs of oil spill on 840816 Two gallons of oil discovered near first storm drain at discharge canal Oil contained in area & cleaned up by use of absorbent pads & Fiber Pearl Caused by separator left running
TAYLOR, J A Virginia Electric & Power Co 84/08/20 KREGLOE, W L
Virginia, Commonwealth of, 1p 26297 222 24X
Fiche 50-338, 84/08/20, 8408290193

V Operator Examinations

8408070489 Forwards hot license simulator reactor startup certification program, per NUREG-0094 Program limits student to instructor ratio to four-to-one, conforming to INPO Guide 82-005 W/o encl
STEWART, W L Virginia Electric & Power Co 84/06/06
PERSENSKY, J J NRC - No Detailed Affiliation Given 2pp 25940 347 24X Fiche 50-000, 84/06/06, 8408070489

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8408310069 Confirms 840524 visit to Region to discuss access control at facilities
LEWIS, R C Region 2, Office of Director 84/05/22 STEWART, W L
Virginia Electric & Power Co 1p 26333 342 24X
Fiche 50-000, 84/05/22, 8408310069

8408310401 Forwards summary of 840524 meeting re security interface activities Meeting beneficial & provided better understanding between security staffs
LEWIS, R C Region 2, Office of Director 84/06/06 STEWART, W L
Virginia Electric & Power Co 4pp 26333 311 24X
Fiche 50-000, 84/06/06, 8408310401

8408140029 Forwards corrected Page 2 to attachment to 840614 order confirming licensee commitments to implement post-TMI related items in Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability" (Generic Ltr 82-33)
MILLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W L
Virginia Electric & Power Co 3pp 26061 259 24X
Fiche 50-338, 84/07/24, 8408140029

--8408140033 Correction to 840614 order confirming licensee commitments to Suppl 1 to NUREG-0737 Completion date for technical support ctr to be fully functional changed to 850731
MILLER, J R Operating Reactors Branch 3 84/07/24 Virginia Electric & Power Co 1p 26061 263, 24X Fiche 50-338, 84/07/24, 8408140029

8408070039 Forwards replacement pages to control room design review program plan Adoption of Westinghouse Owners Group emergency response guidelines as basis for task analysis & verification/validation sections principal changes
STEWART, W L Virginia Electric & Power Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 8pp 25949 281
24X Fiche 50-000, 84/07/27, 8408070039

8408070400 Forwards "VEPCO North Anna Power Station, Units 1 & 2 10CFR50, App R Rept - App A," per 840515 request Rept includes summary comparison of 1984 App R reanalysis & util 820622 post-fire safe shutdown review
STEWART, W L Virginia Electric & Power Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 3pp 25942 191 24X
Fiche 50-338, 84/07/27, 8408070400

--8408070406 "VEPCO North Anna Power Station, Units 1 & 2 10CFR50, App R Rept - App A "
* Virginia Electric & Power Co 84/06/30 17pp 25942 194 24X
Fiche 50-338, 84/07/27, 8408070400

8408020028 Forwards lists of mods & revised schedules re 10CFR50 48, App R reanalysis Compensatory measures for mods specified Completion of App R reanalysis scheduled for 840812
STEWART, W L Virginia Electric & Power Co 84/07/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 9pp 25880 265 24X Fiche 50-338, 84/07/31, 8408020028

8408130394 Ack receipt of 840710 & 0801 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18
LEWIS, R C Division of Project & Resident Programs 84/08/09
STEWART, W L Virginia Electric & Power Co 1p 26010 124 24X
Fiche 50-338, 84/08/09, 8408130394

--8408130400 Responds to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 84/07/10
O'REILLY, J P Region 2, Office of Director 1p 26010 125 24X
Fiche 50-338, 84/08/09, 8408130394

--8408130403 Suppls response to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 84/08/01
O'REILLY, J P Region 2, Office of Director 1p 26010 126 24X
Fiche 50-338, 84/08/09, 8408130394

--8408130408 Forwards IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21)
LEWIS, R C Region 2, Office of Director 84/06/11 STEWART, W L
Virginia Electric & Power Co 2pp 26010 127 24X
Fiche 50-338, 84/08/09, 8408130394

--8408130418 IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 Noncompliance noted in area of access control for personnel Details withheld (ref 10CFR2 790 & 10CFR73 21)
ENNIS, J D Region 2, Office of Director 84/06/08 1p
26010 139 24X Fiche 50-338, 84/08/09, 8408130394

8408130433 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25
LEWIS, R C Division of Project & Resident Programs 84/08/09
STEWART, W L Virginia Electric & Power Co 1p 26005 339 24X
Fiche 50-338, 84/08/09, 8408130433

--8408130438 Responds to NRC 840629 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 Corrective actions withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 84/07/27
O'REILLY, J P Region 2, Office of Director 1p 26005 340 24X
Fiche 50-338, 84/08/09, 8408130433

--8408130443 Forwards IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21)
LEWIS, R C Region 2, Office of Director 84/06/29 STEWART, W L
Virginia Electric & Power Co 2pp 26005 341 24X
Fiche 50-338, 84/08/09, 8408130433

--8408130446 IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 Violation noted re access to vital area Details withheld (ref 10CFR2 790 & 10CFR73 21)
HALL, B L Region 2, Office of Director 84/06/26 1p
26005 343 24X Fiche 50-338, 84/08/09, 8408130433

8408200387 Advises that program plan for conducting detailed control room design review meets intent of Suppl 1 to NUREG-0737 Listed areas should be described in summary rept expected 850830
VARGA, S A Licensing Branch 1 84/08/10 STEWART, W L Virginia Electric & Power Co 2pp 26141 215 24X Fiche 50-000, 84/08/10, 8408200387

8408290330 Forwards Safeguards Insp Repts 50-338/84-31 & 50-339/84-31 on 840806-10 No violations or deviations noted Repts withheld (ref 10CFR2 790 & 73 21)
DANCE, H. C Division of Project & Resident Programs 84/08/27
STEWART, W L Virginia Electric & Power Co 2pp 26289 345 24X
Fiche 50-338, 84/08/27, 8408290330

Q Adjudicatory correspondence

8408010250 Informs that util & NRC intend to file response to objectionable contentions by 840817, based on discussions w/ parties
DOUGHERTY, J B Dougherty, J B DOUGHERTY, J B Concerned Citizens of Louisa County, VA DSB 665, 84/07/30 WOLFE, B J ,
FERGUSON, G A , KLINE, J Atomic Safety and Licensing Board Panel 10pp 25854 342 24X Fiche 50-338, 84/07/30, 8408010250

8408150464 Response to 840730 third draft of contentions of Concerned Citizens of Louisa County All but Contention 4 should be denied Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams DSB 056 84/08/14 Atomic Safety and Licensing Board Panel 31pp 26068 165 24X Fiche 50-338, 84/08/14, 8408150464

8408200477 Forwards response to contentions of Concerned Citizens of Louisa County W/o encl Related correspondence
MAUPIN, M W. Hunton & Williams. MAUPIN, M W Virginia Electric & Power Co DSB 157 84/08/14 Docketing & Services Branch, 1p
26136 306 24X Fiche 50-338, 84/08/14, 8408200477

DOCKETED ITEMS

8408200587 Forwards NRC response to Concerned Citizens of Louisa County third draft of contentions Request by NRC for 1-day extension in date for filing response granted by Chairman Wolfe
LEWIS, S H Hearing Branch 2 DSB 173 84/08/15 WOLFE, S J , KLINE, J , FERGUSON, G A Atomic Safety and Licensing Board Panel
1p 26137 140 24X Fiche 50-338, 84/08/15, 8408200587

8408200593 Response to Concerned Citizens of Louisa County third draft of contentions Certificate of Svc encl
MCGURREN, H J Hearing Branch 1 LEWIS, S H Hearing Branch 2
84/08/15 Atomic Safety and Licensing Board Panel 15pp
26137 141 24X Fiche 50-338, 84/08/15, 8408200587

8408300129 Response supporting admission of Concerned Citizens of Louisa County 840814 revised Contention 4 Certificate of Svc encl
HASBELL, D F Hearing Branch 1 DSB 380 84/08/27 Atomic Safety and Licensing Board Panel 4pp 26304 358 24X
Fiche 50-338, 84/08/27, 8408300129

8408300177 Response to Concerned Citizens of Louisa County, VA (CCLC) revised Contention 4 re physical protection sys for spent fuel shipments Protective order necessary for CCLC access Certificate of Svc encl
MAUPIN, M W Virginia Electric & Power Co MAUPIN, M W Hunton & Williams DSB 384 84/08/27 Atomic Safety and Licensing Board Panel 14pp 26305 343 24X Fiche 50-338, 84/08/27, 8408300177

8408310150 Forwards applicant response to Concerned Citizens of Louisa County, VA revised Contention 4 W/o encl Related correspondence
MAUPIN, M W Hunton & Williams MAUPIN, M W Virginia Electric & Power Co DSB 414 84/08/27 Docketing & Services Branch 1p
26322 202 24X Fiche 50-338, 84/08/27, 8408310150

8408310148 Order scheduling supplemental special prehearing conference on 840907 in Bethesda, MD & directing participants to appear Served on 840830
WOLFE, S J Atomic Safety and Licensing Board Panel DSB 392
84/08/28 Office of the Executive Legal Director 3pp
26320 358 24X Fiche, 50-338, 84/08/28, 8408310148

Operating license stage documents & correspondence

8408300369 Confirms 840501 telcon w/HC Dance re 840510 mgt meeting in Region II ofc to discuss organizational structure
LEWIS, R C Region 2, Office of Director. 84/05/07 STEWART, W L
Virginia Electric & Power Co 1p 26308 230 24X
Fiche 50-000, 84/05/07, 8408300369

8408130223 Forwards safety evaluation re util 831104 response to Generic Ltr 83-28, Item 4 3, "Reactor Trip Sys Reliability " Design mods acceptable
MILLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W L
Virginia Electric & Power Co 2pp 26058 313 24X
Fiche, 50-338, 84/07/24, 8408130223

8408130226 Safety evaluation supporting licensee response to Generic Ltr 83-28, Item 4 3, "Reactor Trip Sys Reliability " Design mods acceptable
* NRC - No Detailed Affiliation Given 84/07/24 10pp
26058 315 24X Fiche 50-338, 84/07/24, 8408130223

8408140063 Forwards comments & questions for review & requests site visit to further discuss inservice testing program NRR should be contacted in approx 4 wks to confirm time & date for meeting
MILLER, J R Operating Reactors Branch 3 84/07/24 STEWART, W L
Virginia Electric & Power Co 9pp 26061 267 24X
iche 50-338, 84/07/24, 8408140063

8090235 Application for amends to Licenses NPF-4 & NPF-7, revising ech Specs re limiting conditions for operation & urveillance requirements consistent w/STS
TEWART, W L Virginia Electric & Power Co 84/08/01 DENTON, H R
ffice of Nuclear Reactor Regulation, Director MILLER, J R
perating Reactors Branch 3 4pp 25972 141 24X
iche 50-338, 84/08/01, 8408090235

8408090239 Proposed Tech Spec changes re limiting conditions for operation & surveillance requirements, to provide consistency w/STS.
* Virginia Electric & Power Co 84/08/01 7pp 25972: 145 24X
Fiche 50-338, 84/08/01, 8408090235

8408090149 Provides upgraded in-core thermocouple implementation schedule, per 840221 commitment Util proposes to complete Reg Guide 1 97 (ref NUREG-0737, Item II F 2) mods prior to or during 1986 refueling outages
STEWART, W L Virginia Electric & Power Co 84/08/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 2pp 25973 122 24X Fiche 50-338, 84/08/03, 8408090149

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408210575 Summary of 840803 meeting w/util in Bethesda, MD re nonqualified paint inside containment List of attendees & agenda encl
ENGLE, L B Operating Reactors Branch 3 84/08/13 MILLER, J R
Operating Reactors Branch 3 20pp 26195 226 24X
Fiche 50-338, 84/08/13, 8408210575

8408210132 Forwards Generic Ltr 84-15 response schedule, listing 840928 & 850131 as projected dates Justification for extension of responses included
STEWART, W L Virginia Electric & Power Co 84/08/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 26181 348
24X Fiche 50-000, 84/08/16, 8408210132

8408210375 Forwards B&W summary technical repts of first capsule from reactor vessel surveillance program, per App H of 10CFR50 Repts delayed due to administrative oversight
STEWART, W L Virginia Electric & Power Co 84/08/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26178 001 24X
Fiche 50-338, 84/08/16, 8408210375

--8408210387 "Analysis of Capsule V, VEPCO, North Anna Unit 2, Reactor Vessel Matls Surveillance Program "
LOWE, A L , COLLINS, L L , PAVINICH, W A Babcock & Wilcox Co
BAW-1794 83/10/31 173pp 26178 002 24X Fiche 50-338, 84/08/16, 8408210375

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8408270387 Forwards Insp Repts 50-338/84-24 & 50-339/84-24 on 840618-22 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/11 STEWART, W L
Virginia Electric & Power Co 2pp 26256 278 24X
Fiche 50-338, 84/07/11, 8408270387

--8408270388 Insp Repts 50-338/84-24 & 50-339/84-24 on 840618-22 No violations or deviations noted Major areas inspected plant chemistry & employee concerns
ROSS, W J , BLAKE, J J Region 2, Office of Director 84/07/09
15pp 26256 280 24X Fiche 50-338, 84/07/11, 8408270387

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408020041 Forwards insp fees for Surry Power Station & North Anna, Unit 1 for Mar 1983 - Mar 1984 & North Anna, Unit 2 for Apr 1983 - Apr 1984
STEWART, W L Virginia Electric & Power Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25880 304 24X
Fiche 50-000, 84/07/27, 8408020041

8408280150 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " All GE Type HFA relays in safety-related applications will be replaced
STEWART, W L Virginia Electric & Power Co 84/07/31 O'REILLY, J P
Region 2, Office of Director 4pp 26259 082 24X
Fiche 50-000, 84/07/31, 8408280150

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408130394 Ack receipt of 840710 & 0801 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18
LEWIS,R C Division of Project & Resident Programs 84/08/09
STEWART,W L Virginia Electric & Power Co 1p 26010 124 24X Fiche 50-338,84/08/09,8408130394

--8408130400 Responds to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21)
STEWART,W L Virginia Electric & Power Co 84/07/10
O'REILLY,J P Region 2, Office of Director 1p 26010 125 24X Fiche 50-338,84/08/09,8408130394

--8408130403 Suppls response to NRC 840611 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 Corrective actions withheld (ref 10CFR73 21)
STEWART,W L Virginia Electric & Power Co 84/08/01
O'REILLY,J P Region 2, Office of Director 1p 26010 126 24X Fiche 50-338,84/08/09,8408130394

--8408130408 Forwards IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21)
LEWIS,R C Region 2, Office of Director 84/06/11 STEWART,W L Virginia Electric & Power Co 2pp 26010 127 24X Fiche 50-338,84/08/09,8408130394

--8408130418 IE Safeguards Insp Repts 50-338/84-18 & 50-339/84-18 on 840521-25 Noncompliance noted in area of access control for personnel Details withheld (ref 10CFR2 790 & 10CFR73 21)
ENNIS,J D , MCGUIRE,D R Region 2, Office of Director 84/06/08 1p 26010 129 24X Fiche 50-338,84/08/09,8408130394

8408130433 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25
LEWIS,R C Division of Project & Resident Programs 84/08/09
STEWART,W L Virginia Electric & Power Co 1p 26005 339 24X Fiche 50-338,84/08/09,8408130433

--8408130438 Responds to NRC 840629 ltr re violations noted in IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 Corrective actions withheld (ref 10CFR73 21)
STEWART,W L Virginia Electric & Power Co 84/07/27
O'REILLY,J P Region 2, Office of Director 1p 26005 340 24X Fiche 50-338,84/08/09,8408130433

--8408130443 Forwards IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 10CFR73 21)
LEWIS,R C Region 2, Office of Director 84/06/29 STEWART,W L Virginia Electric & Power Co 2pp 26005 341 24X Fiche 50-338,84/08/09,8408130433

--8408130446 IE Safeguards Insp Repts 50-338/84-25 & 50-339/84-25 on 840606 Violation noted re access to vital area Details withheld (ref 10CFR2 790 & 10CFR73 21)
HALL,B L , MCGUIRE,D R Region 2, Office of Director 84/06/26 1p 26005 343 24X Fiche 50-338,84/08/09,8408130433

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408290330 Forwards Safeguards Insp Repts 50-338/84-31 & 50-339/84-31 on 840806-10 No violations or deviations noted Repts withheld (ref 10CFR2 790 & 73 21)
DANCE,H C Division of Project & Resident Programs 84/08/27
STEWART,W L Virginia Electric & Power Co 2pp 26289 345 24X Fiche 50-338,84/08/27,8408290330

5 Reportable occurrences, LERs & related correspondence

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/08/16
EISENHUT,D G Division of Licensing 20pp 26233 249 24X Fiche 50-000,84/08/16,8408230077

8408230392 PND-II-84-091 on 840817, earth tremor measuring 3 8 on Richter scale occurred Tremor did not trip plant seismic monitoring equipment
ELROD,S A , DANCE,H C Region 2, Office of Director 84/08/17 1p 26205 303 24X Fiche 50-338,84/08/17,8408230392

8408290193 Informs of oil spill on 840816 Two gallons of oil discovered near first storm drain at discharge canal Oil contained in area & cleaned up by use of absorbent pads & Fiber Pearl Caused by separator left running
TAYLOR,J A Virginia Electric & Power Co 84/08/20 KREGLOE,W L Virginia, Commonwealth of, 1p 26297 222 24X Fiche 50-338,84/08/20,8408290193

V Operator Examinations

8408070489 Forwards hot license simulator reactor startup certification program, per NUREG-0094 Program limits student to instructor ratio to four-to-one, conforming to INPO Guide 82-005 W/o encl
STEWART,W L Virginia Electric & Power Co 84/06/06
PERSENSKY,J J NRC - No Detailed Affiliation Given 2pp 25940 347 24X Fiche 50-000,84/06/06,8408070489

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8406010037 Responds to 840222 request for addl info re postulated failure of HPCI steam line w/o isolation Outboard isolation valve on HPCI steam line maintained in closed position Bypass valve must close against only 1-inch flow
JENS,W H Detroit Edison Co 84/05/25 YOUNGBLOOD,B J Licensing Branch 1 2pp 24756 355 24X Fiche 50-341,84/05/25,8406010037

8408210079 Forwards revised offsite dose calculation manual, reflecting resolution of NRC 840508 questions on draft manual Specific responses encl
JENS,W H Detroit Edison Co 84/07/25 YOUNGBLOOD,B J Licensing Branch 1 4pp 26186 016 24X Fiche 50-341,84/07/25,8408210079

--8408210085 "Offsite Dose Calculation Manual for Enrico Fermi Atomic Power Plant Unit 2 "
* Detroit Edison Co 84/05/31 119pp 26186 020 24X Fiche 50-341,84/07/25,8408210079

8408060388 Forwards proof & review Tech Specs Sections of Tech Specs pertaining to particular areas of responsibility should be reviewed Results of review requested by 840831
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/07/27
NOVAK,T Assistant Director for Licensing JOHNSTON,W V Assistant Director for Matls, Chem & Environ Technology (Post 830201)
RUBENSTEIN,L S Assistant Director for Core & Plant Systems 400pp
26228 256 24X Fiche 50-341,84/07/27,8408060388

8408070440 Advises of plans to implement Option 4 of NUREG-0737, Item II K 3 18, "Mod of Automatic Depressurization Sys Logic," per NRC approval Plans include installation of sys manual inhibit switch
JENS,W H Detroit Edison Co 84/07/31 YOUNGBLOOD,B J Licensing Branch 1 2pp 25942 357 24X Fiche 50-341,84/07/31,8408070440

8408160474 Forwards Certificate of Svc re Amend 58 to amended & substituted application for license
EARLE,O K Detroit Edison Co 84/08/08 YOUNGBLOOD,B J Licensing Branch 1 3pp 26107 289 24X Fiche 50-341,84/08/08,8408160474

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408310264 Notification of 840913 meeting w/util in Bethesda,MD to discuss applicant evaluation of coatings used in containment drywell & wetwell
KINTNER,L L Licensing Branch 1 84/08/23 YOUNGBLOOD,B J Licensing Branch 1 4pp 26350 341 24X Fiche 50-341,84/08/23, 8408310264

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408010216 Discusses control room design review open items status, per SER (NUREG-0798) Encls identify human engineering deficiencies,status &, where possible,ref document to support closure of item
JENS,W H Detroit Edison Co 84/07/25 YOUNGBLOOD,B J Licensing Branch 1 5pp 25856 027 24X Fiche 50-341,84/07/25,8408010216

8408230296 Forwards Rev 1 to Radiation Chemistry Procedure 78 000 15, "Determination of Extent of Core Damage," to resolve SSER 3 (NUREG-0798) open items Procedure supports deletion of license condition proposed in SER
JENS,W H Detroit Edison Co 84/08/16 YOUNGBLOOD,B J Licensing Branch 1 4pp 26208 009 24X Fiche 50-341,84/08/16,8408230296

--8408230301 Rev 1 to Radiation Chemistry Procedure 78 000 15, "Determination of Extent of Core Damage "
HEINS,J Detroit Edison Co 84/06/12 28pp 26208 009 24X
Fiche 50-341,84/08/16,8408230296

F Security, medical, emergency & fire protection plans

8408150638 Forwards IE Insp Rept 50-341/84-15 on 840625-29 No noncompliance noted List of weaknesses identified in emergency preparedness exercise encl Corrective actions requested within 30 day of ltr receipt
PAPERIELLO,C J Region 3, Office of Director 84/07/27 JENS,W H Detroit Edison Co 3pp 26079 065 24X Fiche 50-341,84/07/27, 8408150638

-8408150646 IE Insp Rept 50-341/84-15 on 840625-29, No noncompliance or deviations noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified items re emergency preparedness Scenario encl
PATTERSON,J P , CHRISTOFFER,G , KANTOR,F Region 3, Office of Director 84/07/27 24pp 26079 068 24X Fiche 50-341,84/07/27, 8408150638

8408060024 Forwards IE Safeguards Insp Rept 50-341/84-26 on 840711-13 No noncompliance noted One potential deficiency involving design of certain portion of security sys requires review
AXELSON,W L Region 3, Office of Director 84/07/30 JENS,W H Detroit Edison Co 2pp 25933 099 24X Fiche 50-341,84/07/30, 8408060024

8408060036 IE Safeguards Insp Rept 50-341/84-24 on 840711-13 No noncompliance noted Major areas inspected status of installation & implementation & operability of security program Details withheld (ref 10CFR73 21)
MADEDA,T J , CREED,J R Region 3, Office of Director. 84/07/30, 1p 25933 101 24X Fiche 50-341,84/07/30,8408060024.

8408080305 Forwards discussion of known deviations from 10CFR50, App R (Generic Ltr 83-33) & guidance on App R,except for control ctr complex Deviations include justification showing equivalent level of fire protection provided
JENS,W H Detroit Edison Co 84/08/03 YOUNGBLOOD,B J Licensing Branch 1 113pp 25964 115 24X Fiche 50-341,84/08/03,8408080305

8408080299 Forwards "Analysis of Thermal Response of Junction Between Partially Protected Member Which Protrudes Thermo-Lag 330 Fire Barrier & Cable Tray' & summaries of test results for configurations of 3M fire protection envelope
JENS,W H Detroit Edison Co 84/08/04 YOUNGBLOOD,B J Licensing Branch 1 3pp 25965 195 24X Fiche 50-341,84/08/04,8408080299

--8408080302 "Analysis of Thermal Response of Junction Between Partially Protected Member Which Protrudes Thermo-Lag 330 Fire Barrier & Cable Tray "
* Detroit Edison Co 84/04/30 63pp 25965 198 24X
Fiche 50-341,84/08/04,8408080299

8408090468 Summary of 840711 meeting w/util,Bechtel & consultants in Bethesda,MD re fire protection measures List of attendees & viewgraphs encl
LYNCH,M D Licensing Branch 1 84/08/06 Licensing Branch 1 20pp 25983 178 24X Fiche 50-341,84/08/06,8408090468

8408130153 Ack receipt of 840724 ltr informing NRC of steps taken to correct violations noted in IE Preoperational Safeguards Insp Rept 50-341/84-18 Corrective measures will be examined during subsequent insp
AXELSON,W L Region 3, Office of Director 84/08/08 JENS,W H Detroit Edison Co 1p 26007 350 24X Fiche 50-341,84/08/08, 8408130153

--8408130163 Responds to NRC 840621 ltr re violations noted in IE Preoperational Safeguards Insp Rept 50-341/84-18 Corrective actions re design of main personnel access facility & potential design weakness within warehouse withheld
JENS,W H Detroit Edison Co 84/07/24 KEPPLER,J G Region 3, Office of Director 1p 26007 351 24X Fiche 50-341,84/08/08, 8408130153

8408230274 Informs of intent to use alternative shutdown method described in 10CFR50, App R,Section III L as primary basis for satisfying requirements on fire protection for control ctr complex Review & approval requested
JENS,W H Detroit Edison Co 84/08/16 DENTON,H Office of Nuclear Reactor Regulation, Director 6pp 26206 159 24X
Fiche 50-341,84/08/16,8408230274

8408230389 Forwards,for review, "Control Room Design Review Program Plan for Fermi 2," per Suppl 1 to NUREG-0737 & Generic Ltr 82-33
JENS,W H Detroit Edison Co 84/08/16 YOUNGBLOOD,B J Licensing Branch 1 2pp 26205 249 24X Fiche 50-341,84/08/16,8408230389

--8408230391 "Control Room Design Review Program Plan fo Fermi 2 "
* Detroit Edison Co 84/08/04 48pp 26205 251 24X
Fiche 50-341,84/08/16,8408230389

8408270348 Ack receipt of 840808 ltr informing NRC of steps taken to correct violations noted in Emergency Preparedness Appraisal Rept 50-341/83-24
PAPERIELLO,C J Region 3, Office of Director 84/08/22 JENS,W H Detroit Edison Co 1p 26242 361 24X Fiche 50-341,84/08/22, 8408270348

--8408270352 Responds to NRC 840201 ltr re violations noted in Emergency Preparedness Appraisal Rept 50-341/83-24 Corrective actions numerical values used to determine emergency classification incorporated into equipment air locks
JENS,W H Detroit Edison Co 84/08/08 PAPERIELLO,C J Region 3, Office of Director 1p 26242 362 24X Fiche 50-341,84/08/22, 8408270348

8408310188 Forwards Rev 3A to EPA-99, "Radiological Emergency Response Plan " Rev provided to support resolution of open items in emergency planning area
JENS,W H Detroit Edison Co 84/08/24 YOUNGBLOOD,B J Licensing Branch 1 2pp 26325 046 24X Fiche 50-341,84/08/24,8408310188

--8408310191 Rev 3A to "Radiological Emergency Response Plan "
CONNELL,K Detroit Edison Co 84/08/16 250pp 26325 048 24X
Fiche 50-341,84/08/24,8408310188

K Utility Final Safety Analysis Report (FSAR) & amends

8408020029 Amend 58 to FSAR W/840731 ltr
EARLE,O K Detroit Edison Co 84/07/31 DENTON,H R Office of Nuclear Reactor Regulation, Director 1,000pp 26399 172 24X
Fiche 50-341,84/07/31,8408020029

F Operating license stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110

G Inspection reports, IE Bulletins & correspondence

8408030203 Forwards IE Insp Rept 50-341/84-07 on 840401-0615 No noncompliance noted
WARNICK,R F Region 3, Office of Director 84/07/13 JENS,W H Detroit Edison Co 2pp 25917 122 24X Fiche 50-341,84/07/13, 8408030203

--8408030207 IE Insp Rept 50-341/84-07 on 840401-0615 No noncompliance noted Major areas inspected previous inspector identified items,headquarters request,regional requests,IE bulletins & circulars & preoperational test witnessing
KNOP,R C Region 3, Office of Director 84/07/12 13pp 25917 124 24X Fiche 50-341,84/07/13,8408030203

8408010283 Forwards IE Insp Rept 50-341/84-22 on 840605-15 & 20-22 No noncompliance noted
WALKER,R D Region 3, Office of Director 84/07/16 JENS,W H Detroit Edison Co 2pp 25866 215 24X Fiche 50-341,84/07/16, 8408010283

--8408010285 IE Insp Rept 50-341/84-22 on 840605-15 & 20-22 No noncompliance noted Major areas inspected mgt of preoperational testing QA program & quality verification & training & qualification of QA personnel
MALLOY,J , HASSE,R , HAWKINS,F Region 3, Office of Director 84/07/16 9pp 25866 217 24X Fiche 50-341,84/07/16,8408010283

8408060082 Provides final response to IE Bulletin 83-06, "Nonconforming Matls Supplied by Tube-Line Corp " No Tube-Line Corp products received for use in safety-related sys
JENS,W H Detroit Edison Co 84/07/23 KEPPLER,J G Region 3, Office of Director 3pp 25933 130 24X Fiche 50-341,84/07/23, 8408060082

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408150471 Forwards IE Insp Rept 50-341/84-24 on 840612-0713 No noncompliance noted
SPESSARD,R L Region 3, Office of Director 84/07/27 JENS,W H Detroit Edison Co 2pp 26075 282 24X Fiche 50-341,84/07/27, 8408150471

--8408150475 IE Insp Rept 50-341/84-24 on 840612-0713 No noncompliance or deviations noted Major areas inspected licensee action on previous insp findings,preoperational test procedure verification,review & witnessing
DUPONT,S G , HILLS,D E , O'DWYER,G Region 3, Office of Director, 84/07/26 6pp 26075 284 24X Fiche 50-341,84/07/27,8408150471

8408150638 Forwards IE Insp Rept 50-341/84-15 on 840625-29 No noncompliance noted List of weaknesses identified in emergency preparedness exercise encl Corrective actions requested within 30 day of ltr receipt
PAPERIELLO,C J Region 3, Office of Director 84/07/27 JENS,W H Detroit Edison Co 3pp 26079 065 24X Fiche 50-341,84/07/27, 8408150638

--8408150646 IE Insp Rept 50-341/84-15 on 840625-29 No noncompliance or deviations noted Major areas inspected emergency preparedness exercise & licensee actions on previously identified items re emergency preparedness Scenario encl
PATTERSON,J P , CHRISTOFFER,G , KANTOR,F Region 3, Office of Director 84/07/27 24pp 26079 068 24X Fiche 50-341,84/07/27, 8408150638

8408060024 Forwards IE Safeguards Insp Rept 50-341/84-26 on 840711-13 No noncompliance noted One potential deficiency involving design of certain portion of security sys requires review
AXELSON,W L Region 3, Office of Director 84/07/30 JENS,W H Detroit Edison Co. 2pp 25933 099 24X Fiche 50-341,84/07/30, 8408060024

--8408060036 IE Safeguards Insp Rept 50-341/84-26 on 840711-13 No noncompliance noted Major areas inspected status of installation & implementation & operability of security program Details withheld (ref 10CFR73 21)
MADEDA,T J , CREED,J R Region 3, Office of Director 84/07/30 1p 25933 101 24X Fiche 50-341,84/07/30,8408060024

8408160334 Forwards IE Insp Rept 50-341/84-09 on 840409-0702 & notice of violation
SPESSARD,R L Region 3, Office of Director 84/07/30 JENS,W H Detroit Edison Co 2pp 26106 101 24X Fiche 50-341,84/07/30, 8408160334

--8408160338 Notice of violation from insp on 840409-0702
SPESSARD,R L Region 3, Office of Director 84/07/30 2pp 26106 103 24X Fiche 50-341,84/07/30,8408160334

--8408160341 IE Insp Rept 50-341/84-09 on 840409-0702 Noncompliance noted failure to control rev to design documents & failure to follow listed procedures
KAUFMAN,P D , YIN,I T , CILIMBERG,R L Region 3, Office of Director 84/07/27 21pp 26106 105 24X Fiche 50-341,84/07/30, 8408160334

8408070354 Ack receipt of 840724 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/84-11
SPESSARD,R L Region 3, Office of Director 84/08/02 JENS,W H Detroit Edison Co 1p 25945 144 24X Fiche 50-341,84/08/02, 8408070354

--8408070356 Responds to NRC 840626 ltr re violations noted in IE Insp Rept 50-341/84-11 Corrective actions Test Change Notice 1722 issued to PRET R3202 001,Rev 1 to reconnect battery chargers prior to performance test
JENS,W H Detroit Edison Co 84/07/24 KEPPLER,J G Region 3, Office of Director 5pp 25945 145 24X Fiche 50-341,84/08/02, 8408070354

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408230141 Forwards IE Insp Rept 50-341/84-30 on 840627-29 & 0710-12 & notice of violation
SPESSARD,R L Region 3, Office of Director 84/08/06 JENS,W H Detroit Edison Co 2pp 26214 001 24X Fiche 50-341,84/08/06, 8408230141

--8408230142 Notice of violation from insp on 840627-29 & 0710-12
SPESSARD,R L Region 3, Office of Director 84/08/06 1p 26214 003 24X Fiche 50-341,84/08/06,8408230141

--8408230144 IE Insp Rept 50-341/84-30 on 840627-29 & 0710-12 Noncompliance noted failure to take appropriate corrective action re shore barrier structure configuration deviations
NORTON,J , WILLIAMS,C C Region 3, Office of Director 84/08/03 10pp 26214 004 24X Fiche 50-341,84/08/06,8408230141

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408130153 Ack receipt of 840724 ltr informing NRC of steps taken to correct violations noted in IE Preoperational Safeguards Insp Rept 50-341/84-18 Corrective measures will be examined during subsequent insp
AXELSON,W L Region 3, Office of Director 84/08/08 JENS,W H Detroit Edison Co 1p 26007 350 24X Fiche 50-341,84/08/08, 8408130153.

--8408130163 Responds to NRC 840621 ltr re violations noted in IE Preoperational Safeguards Insp Rept 50-341/84-18 Corrective actions re design of main personnel access facility & potential design weakness within warehouse withheld
JENS, W H Detroit Edison Co 84/07/24 KEPPLER, J G Region 3, Office of Director 1p 26007 351 24X Fiche 50-341, 84/08/08, 8408130153

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408270084 Forwards Insp Rept 50-341/84-27 on 840709-13 & 25 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/08/10 JENS, W H Detroit Edison Co 2pp 26258 210 24X Fiche 50-341, 84/08/10, 8408270084

--8408270090 Insp Rept 50-341/84-27 on 840709-13 & 25 No noncompliance noted Major areas inspected preoperational radiation protection program, facilities, equipment, NUREG-0737 items, status of preoperational sys & drain sys
HUETER, L J , GILL, C F , GREGER, L R Region 3, Office of Director 84/08/10 20pp 26258 212 24X Fiche 50-341, 84/08/10, 8408270084

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408300203 Forwards Insp Rept 50-341/84-17 on 840514-17, 0529-0601 & 29 & notice of violation
LITTLE, W S Region 3, Office of Director 84/08/14 JENS, W H Detroit Edison Co 2pp 26306 246 24X Fiche 50-341, 84/08/14, 8408300203

--8408300207 Notice of violation from insp on 840514-17, 0529-0601 & 29
LITTLE, W S Region 3, Office of Director 84/08/14 1p 26306 248 24X Fiche 50-341, 84/08/14, 8408300203

--8408300220 Insp Rept 50-341/84-17 on 840514-17, 0529-0601 & 29 Noncompliance noted personnel performed Raychem heat shrink application on Valve V4-2080 w/o previous training & inadequate design review performed
NAIDU, K , FALEVITS, Z , GAUTAM, A Region 3, Office of Director 84/08/14 35pp 26306 249 24X Fiche 50-341, 84/08/14, 8408300203

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408310381 Forwards Insp Rept 50-341/84-31 on 840730-0803 No items of noncompliance identified
SPESSARD, R L Region 3, Office of Director 84/08/17 JENS, W H Detroit Edison Co 2pp 26333 303 24X Fiche 50-341, 84/08/17, 8408310381

--8408310394 Insp Rept 50-341/84-31 on 840730-0803 No items of noncompliance or deviations noted Major areas inspected testing of pipe support & restraint sys & quality & design documents of safety-related piping sys in RHR complex
KAUFMAN, P D , DANIELSON, D H Region 3, Office of Director 84/08/16 6pp 26333 305 24X Fiche 50-341, 84/08/17, 8408310381

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408270348 Ack receipt of 840808 ltr informing NRC of steps taken to correct violations noted in Emergency Preparedness Appraisal Rept 50-341/83-24
PAPERIELLO, C J Region 3, Office of Director 84/08/22 JENS, W H Detroit Edison Co 1p 26242 361 24X Fiche 50-341, 84/08/22, 8408270348

--8408270352 Responds to NRC 840201 ltr re violations noted in Emergency Preparedness Appraisal Rept 50-341/83-24 Corrective actions numerical values used to determine emergency classification incorporated into equipment air locks
JENS, W H Detroit Edison Co 84/08/08 PAPERIELLO, C J Region 3, Office of Director 1p 26242 362 24X Fiche 50-341, 84/08/22, 8408270348

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408080511 Final deficiency rept, Item 61 re undersized battery cables Initially reported on 820312 Design changes issued to require larger cables for affected motor operated valves & installation of interposing relays in trip/close circuits
JENS, W H Detroit Edison Co 84/07/23 KEPPLER, J G Region 3, Office of Director 2pp 25975 262 24X Fiche 50-341, 84/07/23, 8408080511

8408080516 Final deficiency rept, Item 87 re possible ITE circuit breaker failures Initially reported on 830304 Replacement solid state trip devices, w/Sprague Type 137D capacitor, obtained Mod request issued
JENS, W H Detroit Edison Co 84/07/23 KEPPLER, J G Region 3, Office of Director 2pp 25975 267 24X Fiche 50-341, 84/07/23, 8408080516

8408090055 Interim deficiency rept, Item 131 re weldolets lacking complete chemical analysis documentation Initially reported on 840627 Corrective action to be determined upon completion of investigation Reported under Part 21 by Guyon Alloys
JENS, W H Detroit Edison Co 84/07/24 KEPPLER, J G Region 3, Office of Director 2pp 25992 333 24X Fiche 50-341, 84/07/24, 8408090055

8408090062 Final deficiency rept, Item 91 re broken/cracked puffer piston rods in Brown Boveri 5HK circuit breakers (IE Info Notice 83-84) Item not reportable under 10CFR50 55(e) as deficiency would not adversely affect safe operation
JENS, W H Detroit Edison Co 84/07/24 KEPPLER, J G Region 3, Office of Director 2pp 25992 141 24X Fiche 50-341, 84/07/24, 8408090062

8408090071 Final deficiency rept, Item 130 re insufficient clearance between main steamlines & containment walls Initially reported on 840626 Pipe whip restraint design mod initiated to reduce gap between main steamline & restraint
JENS, W H Detroit Edison Co 84/07/24 KEPPLER, J G Region 3, Office of Director 2pp 25992 354 24X Fiche 50-341, 84/07/24, 8408090071

8408140016 Final deficiency rept, Item 104 re premature resetting of automatic digital load sequencer sys Initially reported on 831004 Control logic wiring separated from output relay contact wires to reduce voltage & surge assemblies added
JENS, W H Detroit Edison Co 84/08/01 KEPPLER, J G Region 3, Office of Director 2pp 26044 166 24X Fiche 50-341, 84/08/01, 8408140016

8408160444 Final deficiency rept, Item 40 re calibr tolerances for torque wrenches Initially reported on 810303 Corrective actions include audit of site contractor torque wrench calibr programs Wrenches recalibr & tolerances clarified
JENS, W H Detroit Edison Co 84/08/01 KEPPLER, J G Region 3, Office of Director 3pp 26107 273 24X Fiche 50-341, 84/08/01, 8408160444

8408220209 Final deficiency rept, Item 94 re loose pole piece wedges on four emergency diesel generators Initially reported on 830429 Dovetail wedges replaced w/stronger & longer model
JENS, W H Detroit Edison Co 84/08/08 KEPPLER, J G Region 3, Office of Director 3pp 26189 143 24X Fiche 50-341, 84/08/08, 8408220209

8408220135 Final deficiency rept,Item 92 re structural steel sliding connections Initially reported in Apr 1983 Drawings revised to specify torque values Affected connections reworked
JENS,W H Detroit Edison Co 84/08/09 KEPPLER,J G Region 3, Office of Director 2pp 26188 060 24X Fiche 50-341,84/08/09, 8408220135

8408220175 Final deficiency rept,Item 66 re core spray pump motor damage Initially reported in Apr 1982 All damaged parts replaced & equipment inspected to ensure quality at installation
JENS,W H Detroit Edison Co 84/08/09 KEPPLER,J G Region 3, Office of Director 2pp 26188 176 24X Fiche 50-341,84/08/09, 8408220175

8408220193 Final deficiency rept,Item 75 re calibr problems w/Rosemount trip units Initially reported on 820720 Trip unit potentiometers made w/silver contacts replaced,recalibr & installed
JENS,W H Detroit Edison Co 84/08/09 KEPPLER,J G Region 3, Office of Director 2pp 26189 063 24X Fiche 50-341,84/08/09, 8408220193

8408300216 Final deficiency rept,Item 37 re Fisher Controls control valve actuators Initially reported on 801231 Engineering specs revised to include valve natural frequency criteria Actuators replaced
JENS,W H Detroit Edison Co 84/08/14 KEPPLER,J G Region 3, Office of Director 2pp 26307 055 24X Fiche 50-341,84/08/14, 8408300216

8408300045 Final deficiency rept,Item 113 re linear indications in seams of ASTM A500 Grade B tube steel Initially reported on 840123 Supports fabricated from affected tube steel identified & being replaced
JENS,W H Detroit Edison Co 84/08/15 KEPPLER,J G Region 3, Office of Director 2pp 26307 072 24X Fiche 50-341,84/08/15, 8408300045

8408300061 Final deficiency rept,Item 126 re underrated terminal blocks in Limitorque motor operated valve operators Initially reported on 840504 Twelve terminal blocks removed Four motor operators hard wired
JENS,W H Detroit Edison Co 84/08/15 KEPPLER,J G Region 3, Office of Director 3pp 26307 308 24X Fiche 50-341,84/08/15, 8408300061

8408300069 Final deficiency rept,Item 55 re defective spot welds in powerstrut support matl Initially reported on 820211 Purchase & installation of all powerstrut configurations suspended by LK Comstock Supports reinforced or replaced
JENS,W H Detroit Edison Co 84/08/15 KEPPLER,J G Region 3, Office of Director 3pp 26307 175 24X Fiche 50-341,84/08/15, 8408300069

8408300209 Final deficiency rept,Item 74 re sway strut paddles clamped rigid Initially reported on 820702 Installation of strut assembly placed on hold while problem resolved Components modified
JENS,W H Detroit Edison Co 84/08/15 KEPPLER,J G Region 3, Office of Director 2pp 26307 046 24X Fiche 50-341,84/08/15, 8408300209

8408300223 Final deficiency rept,Item 120 re NPS Industries,Inc pipe support components w/same part number Initially reported on 840319 NPS Industries changed physical dimensions of parts, but parts retained same part number
JENS,W H Detroit Edison Co 84/08/15 KEPPLER,J G Region 3, Office of Director 2pp 26306 338 24X Fiche 50-341,84/08/15, 8408300223

8408300251 Final deficiency rept,Item 68 re defective pipe support strut swivel bearings Initially reported on 820514 Engineering hold placed on all rework,pending resolution of problem & development of coordinated corrective action plan
JENS,W H Detroit Edison Co 84/08/15 KEPPLER,J G Region 3, Office of Director 3pp 26307 028 24X Fiche 50-341,84/08/15, 8408300251

8408300257 Final deficiency rept,Item 50 re linear indications in Parker-Hannifin stainless steel tees Initially reported on 820112 All tees from affected heat numbers liquid penetrant tested & accepted or cut out & replaced
JENS,W H Detroit Edison Co 84/08/15 KEPPLER,J G Region 3, Office of Director 3pp 26307 035 24X Fiche 50-341,84/08/15, 8408300257

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA,R General Electric Co 84/08/21 ROSSI,C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000,84/08/21,8408310186

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET 50-344 TROJAN NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8408090017 Forwards IE Insp Rept 50-344/84-13 on 840514-18 & 29-0601 No noncompliance noted
WENSLAWSKI,F A Region 5, Office of Director 84/07/25
WITHERS,B D Portland General Electric Co 2pp 25994 341 24X Fiche 50-344,84/07/25,8408090017

--8408090021 IE Insp Rept 50-344/84-13 on 840514-18 & 29-0601 No violations noted Major areas inspected radiation protection program during refueling outage,including general employee training,organization & staffing & records & repts
CILLIS,M , YUHAS,G P Region 5, Office of Director 84/07/18 19pp 25994 343 24X Fiche 50-344,84/07/25,8408090017

8408060058 Revised radiological emergency response plan implementing procedures,including EP-16, "Drills & Exercise," EP-24 1, "Emergency Reponse Manager," EP-24 2, "Radiological Manager" & EP-25, "Operation of Company " W/840727 ltr
PUZEY,A M Portland General Electric Co 84/07/27 38pp 25923 008 24X Fiche 50-344,84/07/27,8408060058

8408100058 Revs to radiological emergency response plan implementing procedures,including EP-8 8, "Dose Assessment Director" & EP-8 11, "Emergency Operations Facility Dose Assessment Staff " W/840803 transmittal form
PUZEY,A M Portland General Electric Co 84/07/31 23pp 25990 076 24X Fiche 50-344,84/07/31,8408100058

8408130414 Forwards "Trojan Nuclear Plant 10CFR50,App R Review," describing util reassessment of compliance w/App R requirements & requests for exemptions Implementation schedule will be provided by 840915
WITHERS,B D Portland General Electric Co 84/07/31 MILLER,J R Operating Reactors Branch 3 2pp 26109 001 24X Fiche 50-344,84/07/31,8408130414

--8408130416 "Trojan Nuclear Plant 10CFR50,App R Review "
* Portland General Electric Co 84/07/31 600pp 26109 005 24X Fiche 50-344,84/07/31,8408130414

8408280253 Revised radiological emergency response plan implementing procedures,including EP-1 re emergency classification,EP-5 re emergency notification & EP-5 1 re notification of non-Trojan offsite emergencies
* Portland General Electric Co 84/08/07 556pp 26273 109 24X Fiche 50-344,84/08/07,8408280253

8408210292 Revised radiological emergency response plan implementing procedures,including Rev 8 to EP-17 re medical & Rev 1 to EP-24 re long-term emergency organization W/840810 transmittal memo
PUZEY,A M Portland General Electric Co 84/08/10 33pp 26179 241 24X Fiche 50-344,84/08/10,8408210292

8408210415 Requests extension for implementation of upgraded emergency operating procedures from Third Quarter 1985 until Fourth Quarter 1985 Extension will allow all licensed operators to receive training in use of new procedures at simulator
WITHERS,B D Portland General Electric Co 84/08/15 EISENHUT,D G Division of Licensing 5pp 26180 339 24X Fiche 50-344,84/08/15, 8408210415

8408310315 Advises that Amend 4 to radiological emergency response plan acceptable,per 10CFR50 47 & Rev 1 to NUREG-0654
SCHUSTER,M D Region 5, Office of Director 84/08/17 WITHERS,B D Portland General Electric Co 2pp 26333 298 24X Fiche 50-344,84/08/17,8408310315

Q Adjudicatory correspondence

8405250251 Memorandum & order directing parties or counsel to attend 840612 prehearing conference in Portland,OR re spent fuel pool amend Served on 840525
SMITH,I W Atomic Safety and Licensing Board Panel DSB 312 84/05/24 1p 24656-086 24X Fiche 50-344,84/05/24,8405250251

K Utility Final Safety Analysis Report (FSAR) & amends

8408020050 Forwards Amend 2 to updated FSAR for Trojan Nuclear Power Plant Ack of receipt requested
LENTSCH, J W Portland General Electric Co 84/07/20 Record Services Branch (Document Control Desk) 1p 26003 090 24X
Fiche 50-344, 84/07/20, 8408020050

--8408020051 Amend 2 to updated FSAR for Trojan Nuclear Power Plant
* Portland General Electric Co 84/07/31 623pp 26003 091 24X Fiche 50-344, 84/07/20, 8408020050

P Operating license stage documents & correspondence

8408310149 FOIA request for detailed instructions re use of risk assessment techniques & analysis & calculations on which ground accelerations for design & max hypothetical earthquake based
CALSOYAS, C D Affiliation Not Assigned 84/05/12 NRC - No Detailed Affiliation Given 4pp 26351 359 24X
Fiche 50-344, 84/05/12, 8408310149

8408310147 Partial response to FOIA request for detailed instruction re use of risk assessment techniques & analysis & calculations on which ground accelerations for design & max hypothetical earthquake based Documents available in PDR
FELTON, J M Division of Rules and Records 84/06/01 CALSOYAS, L D Affiliation Not Assigned 1p 26351 358 24X
Fiche 50-344, 84/06/01, 8408310147

8408070082 Forwars safety evaluation based on review of 831104 & 840330 submittals re automatic actuation of shunt trip attachment for reactor trip breakers, in response to Item 4 3 of Generic Ltr 83-28 Proposed mods acceptable
MILLER, J R Operating Reactors Branch 3 84/07/26 WITHERS, B D Portland General Electric Co 2pp 25955 259 24X
Fiche 50-344, 84/07/26, 8408070082

--8408070084 Safety evaluation re Item 4 3 of Generic Ltr 83-28 concerning reactor trip breaker automatic shunt trip Proposed mods provided in 831104 & 840330 submittals acceptable
* NRC - No Detailed Affiliation Given 84/07/26 10pp 25955 261 24X Fiche 50-344, 84/07/26, 8408070082

8408020057 Forwards PGE-1021, "Offsite Dose Calculation Manual " Manual revised to reflect LCA 50, Rev 2, "Radiological ETS "
WITHERS, B D Portland General Electric Co 84/07/27 MILLER, J R Operating Reactors Branch 3 1p 25900 290 24X
Fiche 50-344, 84/07/27, 8408020057

--8408020059 Forwards PGE-1021, "Offsite Dose Calculation Manual " Requests ack of receipt
LENTSCH, J W Portland General Electric Co 84/07/27 MILLER, J R Operating Reactors Branch 3 1p 25900 291 24X
Fiche 50-344, 84/07/27, 8408020057

--8408020061 "Offsite Dose Calculation Manual "
* Portland General Electric Co 84/07/31 87pp 25900 292 24X
Fiche 50-344, 84/07/27, 8408020057

8408070508 Forwards Amend 89 to License NPF-1 Amend changes min required load for testing emergency diesel generators & deletes 18-month surveillance test
MILLER, J R Operating Reactors Branch 3 84/07/27 WITHERS, B D Portland General Electric Co 4pp 25956, 226 24X
Fiche 50-344, 84/07/27, 8408070508

--8408070511 Amend 89 to License NPF-1, changing min required load for testing emergency diesel generators & deleting 18-month surveillance test
MILLER, J R Operating Reactors Branch 3 84/07/27 5pp 25956 230 24X Fiche 50-344, 84/07/27, 8408070508

8408090237 Supplis 840608 response to NRC 840508 ltr re electrical separation problem on Panel C-41 Problem isolated incident & not reflective of QA program weakness Addl physical insp of control room panels completed
WITHERS, B D Portland General Electric Co 84/07/27 MARTIN, J B Region 5, Office of Director 3pp 25994 151 24X
Fiche 50-344, 84/07/27, 8408090237

8408090158 Provides status of regulatory requirements verification program, per 830928 commitment Deficiencies found in 19 of 79 items reviewed Evaluation initiated to determine reportability & corrective action
WITHERS, B D Portland General Electric Co. 84/07/31 MARTIN, J B Region 5, Office of Director 2pp 25972, 290 24X
Fiche 50-344, 84/07/31, 8408090158

8408170144 Forwards Amend 90 to License NPF-1 & safety evaluation Amend revises surveillance requirements for verifying reactor shutdown margin when one or more control rods immovable or untrippable & when starting up reactor
TRAMMELL, C M Operating Reactors Branch 3 84/08/02 WITHERS, B D Portland General Electric Co 1p 26134 328 24X
Fiche 50-344, 84/08/02, 8408170144

--8408170147 Amend 90 to License NPF-1, revising surveillance requirements for verifying reactor shutdown margin when one or more control rods immovable or untrippable & when starting up reactor
MILLER, J R Operating Reactors Branch 3 84/08/02 4pp 26134 329 24X Fiche 50-344, 84/08/02, 8408170144

--8408170150 Safety evaluation supporting Amend 90 to License NPF-1
* Office of Nuclear Reactor Regulation, Director 84/08/02 2pp 26134 333 24X Fiche 50-344, 84/08/02, 8408170144

8408070447 Forwards addl info re containment high-range radiation monitors & containment spray pump motors, per 840628 request Request for schedule extension & justification for continued operation previously provided
WITHERS, B D Portland General Electric Co 84/08/03 MILLER, J R Operating Reactors Branch 3 4pp 25942 259 24X
Fiche 50-344, 84/08/03, 8408070447

8408080316 Forwards addl fee for Amend 88 to License NPF-1, increasing storage capacity of spent fuel pool
WITHERS, B D Portland General Electric Co 84/08/03 DIGGS, R M License Fee Management Branch 1p 25964 110 24X
Fiche 50-344, 84/08/03, 8408080316

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140073 Ack receipt of 840612 Class II fee for proposed Tech Spec changes re hydrogen mixing sys CS-8 flow verification value Class III fee required since review involved single safety issue
DIGGS, R M License Fee Management Branch 84/08/06 WITHERS, B D Portland General Electric Co 1p 26061 266 24X
Fiche 50-344, 84/08/06, 8408140073

8408170007 Responds to 840601 request for extension of final environ qualification of equipment until end of next refueling outage Extension granted
DENTON, H R Office of Nuclear Reactor Regulation, Director 84/08/06 WITHERS, B D Portland General Electric Co 2pp 26135 355 24X Fiche 50-344, 84/08/06, 8408170007

8408140202 Forwards clarification of responses to 840504 ltr re proposed snubber Tech Specs Tech Spec LCA 73 will be revised to add quantitative acceptance criteria & resubmitted by 841001
WITHERS, B D Portland General Electric Co 84/08/09 MILLER, J R Operating Reactors Branch 3 4pp 26044 328 24X
Fiche 50-344, 84/08/09, 8408140202

8408140289 Forwards summary of control rod guide tube support pin replacement evaluation, per NRC request Summary of Steam Generator B insp & repair work, as result of damage due to failure of control rod guide tube support pins, also encl
WITHERS, B D Portland General Electric Co 84/08/09 MILLER, J R Operating Reactors Branch 3 10pp 26054 347 24X
Fiche 50-344, 84/08/09, 8408140289

8408210139 Forwards safety evaluation concluding that loose/missing components from control rod guide tube support pins in RCS does not have adverse effect on public health & safety One of two missing sets of nuts, locking disks & pins found
WITHERS, B D Portland General Electric Co 84/08/15 MILLER, J R Operating Reactors Branch 3 15pp 26183 039 24X
Fiche 50-344, 84/08/15, 8408210139

8408210438 Requests extension until 841031 to respond to Generic Ltr 84-15, requesting info on diesel generator reliability & description of diesel generator reliability program Extended refueling outage drained manpower resources
WITHERS, B D Portland General Electric Co 84/08/15 EISENHUT, D G Division of Licensing 1p 26181 255 24X Fiche 50-344, 84/08/15, 8408210438

8408200273 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408280242 Advises of delay in submitting schedule for response to 840606 questions on asymmetric LOCA loads
WITHERS, B D Portland General Electric Co 84/08/24 MILLER, J P
Operating Reactors Branch 3 1p 26261 340 24X
Fiche 50-344, 84/08/24, 8408280242

0 Inspection reports, IE Bulletins & correspondence

8408130304 Requests assistance in assessing 840622 IE Insp Rept 50-344/84-14 Problems encountered in evaluating & reconstructing 840504 RHR loss of cooling event
MARTIN, J B Region 5, Office of Director 84/06/22 WITHERS, B
Portland General Electric Co 1p 26010 256 24X
Fiche 50-344, 84/06/22, 8408130304

8408010278 Ack receipt of 840531 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/84-08 Corrective actions will be verified during future insp
BISHOP, T W Region 5, Office of Director 84/07/16 WITHERS, B D
Portland General Electric Co 1p 25866 196 24X
Fiche 50-344, 84/07/16, 8408010278

--8408010281 Responds to NRC 840507 ltr re violations noted in IE Insp Rept 50-344/84-08 Corrective actions Tech Spec change will be requested, per Generic Ltr 83-43, to replace existing requirements w/documents referencing 10CFR50 72
WITHERS, B D Portland General Electric Co 84/05/31 MARTIN, J B
Region 5, Office of Director 3pp 25866 197 24X
Fiche 50-344, 84/07/16, 8408010278

8408030262 Ack receipt of 840604 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-344/84-10
BISHOP, T W Region 5, Office of Director 84/07/17 Portland General Electric Co 1p 25917 111 24X Fiche 50-344, 84/07/17, 8408030262

8408080494 Forwards IE Insp Rept 50-344/84-15 on 840604-08 No violations noted Weaknesses in oversight of QA program observed Assessment of situation requested within 30 days
BISHOP, T W Region 5, Office of Director 84/07/20 WITHERS, B D
Portland General Electric Co 2pp 25975 205 24X
Fiche 50-344, 84/07/20, 8408080494

--8408080497 IE Insp Rept 50-344/84-15 on 840604-08 No noncompliance or deviations noted Major areas inspected reactor internals mods to reverse bypass flow direction & provide for assessing adequacy of QA program
HAIST, D P , HON, A , DODDS, R T Region 5, Office of Director
84/07/19 13pp 25975 207 24X Fiche 50-344, 84/07/20, 8408080494

8408090075 Forwards IE Insp Rept 50-344/84-16 on 840709-13 No noncompliance noted
WENSLAWSKI, F A Region 5, Office of Director 84/07/23
WITHERS, B D Portland General Electric Co 2pp 25992 212 24X
Fiche 50-344, 84/07/23, 8408090075

--8408090080 IE Insp Rept 50-344/84-16 on 840709-13 No noncompliance or deviations noted Major areas inspected transportation, info notice followup & facility tour
CILLIS, M , NORTH, H , YUHAS, G P Region 5, Office of Director
84/07/20 4pp 25992 214 24X Fiche 50-344, 84/07/23, 8408090075

8408090017 Forwards IE Insp Rept 50-344/84-13 on 840514-18 & 29-0601 No noncompliance noted
WENSLAWSKI, F A Region 5, Office of Director 84/07/25
WITHERS, B D Portland General Electric Co 2pp 25994 341 24X
Fiche 50-344, 84/07/25, 8408090017

--8408090021 IE Insp Rept 50-344/84-13 on 840514-18 & 29-0601 No violations noted Major areas inspected radiation protection program during refueling outage, including general employee training, organization & staffing & records & repts
CILLIS, M , YUHAS, G P Region 5, Office of Director 84/07/18
19pp 25994 343 24X Fiche 50-344, 84/07/25, 8408090017

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co. of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408300373 Forwards Insp Rept 50-344/84-17 on 840604-0711 & notice of violation
BISHOP, T W Region 5, Office of Director 84/08/01 WITHERS, B D
Portland General Electric Co 2pp 26308 244 24X
Fiche 50-344, 84/08/01, 8408300373

--8408300377 Notice of violation from insp on 840604-0706
DODDS, R T Region 5, Office of Director 84/08/01 1p
26308 246 24X Fiche 50-344, 84/08/01, 8408300373

--8408300380 Insp Rept 50-344/84-17 on 840604-0711 Violation noted temporary demineralizer sys from spent fuel cask loading pit to spent fuel pool purification pump installed w/o being controlled or evaluated
RICHARDS, S A , JOHNSTON, G W , DODDS, R T Region 5, Office of Director 84/07/25 10pp 26308 247 24X Fiche 50-344, 84/08/01, 8408300373

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc 122pp 26069 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408130318 Ack receipt of 840622 & 0719 ltrs informing NRC of steps taken to correct violations noted in NRC 840522 & 0629 ltrs Corrective actions will be verified during future insp
WENSLAWSKI, F A Region 5, Office of Director 84/08/07
WITHER, B D Portland General Electric Co 1p 26010 139 24X
Fiche 50-344, 84/08/07, 8408130318

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140289 Forwards summary of control rod guide tube support pin replacement evaluation, per NRC request Summary of Steam Generator B insp & repair work, as result of damage due to failure of control rod guide tube support pins, also encl
WITHERS, B D Portland General Electric Co 84/08/09 MILLER, J R
Operating Reactors Branch 3 10pp 26054 347 24X
Fiche 50-344, 84/08/09, 8408140289

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376.

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197.218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp. 26198.093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16, Consolidated Edison Co. of New York, Inc 118pp. 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/08/17 Consolidated Edison Co. of New York, Inc. 120pp. 26276 001 24X Fiche 50-000, 84/08/17, 8408100055.

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/08/17 Consolidated Edison Co. of New York, Inc. 122pp. 26276:122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves ' Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408090060 Updated special rept on 831022, fire suppression sys in cable spreading room failed electrically Fire watch established. Sys must now be manually actuated instead of automatically Replacement monitoring sys will be operational by 840831
YUNDT, C P Portland General Electric Co 84/07/30 MARTIN, J B Region 5, Office of Director 1p 25973 114 24X
Fiche 50-344, 84/07/30, 8408090060

8408310269 Forwards "Loss of ESF Auxiliary Feedwater Pump Capability at Trojan on 830122," technical review rept Addl study recommended to investigate issue
ZUKOR, D J Reactor Operations Analysis Branch 84/08/01
SEYFRIT, K V Reactor Operations Analysis Branch. 1p 26350 287
24X Fiche 50-344, 84/08/01, 8408310269

--8408310275 "Loss of ESF Auxiliary Feedwater Pump Capability at Trojan on 830122," technical review rept
* Director's Office 84/08/01 3pp 26350 288 24X
Fiche 50-344, 84/08/01, 8408310269

8408240287 PND-V-84-051 on 840818, control rod L-3 bank D, stuck at almost fully withdrawn position during cold rod drop tests Seal weld for control rod guide mechanism will be cut to determine if latching mechanism at fault
DODDS, R T , RICHARDS, S A Region 5, Office of Director 84/08/20
1p 26223 186 24X Fiche 50-344, 84/08/20, 8408240287

8408280149 LER 84-012-00 on 840727, new nuclear fuel assemblies transferred from new fuel storage room to spent fuel pool w/o operable spent fuel pool ventilation train in svc Caused by personnel error Personnel counseled W/840822 ltr
BAIR, G G , YUNDT, C P Portland General Electric Co 84/08/22 4pp
26279 192 24X Fiche 50-344, 84/08/22, 8408280149

V Operator Examinations

8408210415 Requests extension for implementation of upgraded emergency operating procedures from Third Quarter 1985 until Fourth Quarter 1985 Extension will allow all licensed operators to receive training in use of new procedures at simulator
WITHERS, B D Portland General Electric Co 84/08/15 EISENHUT, D G
Division of Licensing 5pp 26180 339 24X Fiche 50-344, 84/08/15, 8408210415

KET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

Security, medical, emergency & fire protection plans

8080031 Forwards exemption from requirements of App E to 10CFR50 re state & local govt participation in emergency preparedness exercise, per 840411 request
RIVENBARK, G W Operating Reactors Branch 4 84/07/26 CROUSE, R P
Toledo Edison Co 3pp 25981 054 24X Fiche 50-346, 84/07/26, 8408080031

8408080037 Exemption from requirements of App E to 10CFR50 re state & local govt participation in emergency preparedness exercise
EISENHUT, D G Division of Licensing 84/07/27 Toledo Edison Co 4pp 25981 057 24X Fiche 50-346, 84/07/26, 8408080031

408100061 Rev 16 to Health Physics Emergency Plan Procedure HP 1602 01, "External Personnel Radiation Exposure Monitoring " W/840801 transmittal form
SCOTT, R , TAPLEY, J. Toledo Edison Co 84/07/26 26pp 25987 033
24X Fiche 50-346, 84/07/26, 8408100061

408060322 Revised emergency plan implementing procedures, including EI 1300. 07, "Technical Support Ctr Activation" & index
* Toledo Edison Co 84/07/31 15pp 25933 316 24X
Fiche 50-346, 84/07/31, 8408060322

408080524 Forwards Amend 74 to License NPF-3 Amend changes Tech Specs to require annual audit of emergency & security plans & implementing procedures
STOLZ, J F Operating Reactors Branch 4 84/07/31 CROUSE, R P
Toledo Edison Co 4pp 25975 360 24X Fiche 50-346, 84/07/31, 8408080524

--8408080527 Amend 74 to License NPF-3, changing Tech Specs to require annual audit of emergency & security plan & implementing procedures
STOLZ, J F Operating Reactors Branch 4 84/07/31 4pp
25976 002 24X Fiche 50-346, 84/07/31, 8408080524

8408200073 Rev 7 to Emergency Plan Implementing Procedure EI 1300 08, "Emergency Control Ctr Activation "
HORVATH, E Toledo Edison Co 84/08/06 6pp 26133 305 24X
Fiche 50-346, 84/08/06, 8408200073

8408130387 Ack receipt of 840723 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-24 Corrective actions will be examined during subsequent insp
SHAFER, W D Region 3, Office of Director 84/08/07 CROUSE, R P
Toledo Edison Co 1p 26011 117 24X Fiche 50-346, 84/08/07, 8408130387

--8408130390 Responds to NRC 840625 ltr re violations noted in IE Insp Rept 50-346/83-24 Corrective actions health physics personnel instructed not to conduct respiratory training outside nuclear training dept w/o approval of director
CROUSE, R P Toledo Edison Co 84/07/23 NORELIUS, C E Division of Project & Resident Programs 2pp 26011 118 24X
Fiche 50-346, 84/08/07, 8408130387

8408160021 Requests justification of emergency operating guidelines by ref to Oconee guideline approved by NRC Response by 840914 requested
STOLZ, J F Operating Reactors Branch 4 84/08/08 CROUSE, R P
Toledo Edison Co 2pp 26128 210 24X Fiche 50-346, 84/08/08, 8408160021

8408280345 Forwards FR notice of issuance of environ assessment & final finding of no significant impact re 830930 & 1230 requests for exemption from requirements of 10CFR50, App R Related correspondence
DEAGAZIO, A Operating Reactors Branch 4 84/08/14 CROUSE, R P
Toledo Edison Co 2pp 26294 024 24X Fiche 50-346, 84/08/14, 8408280345

--8408280348 Notice of environ assessment & final finding of no significant impact re 830930 & 1230 requests for exemption from requirements of 10CFR50, App R Exemption acceptable
EISENHUT, D G Division of Licensing 84/08/14 5pp 26294 026
24X Fiche 50-346, 84/08/14, 8408280345

8408280145 Revised emergency plan implementing procedures, including T-8185 re station response to emergencies & T-8186 re operations support ctr, activation W/840821 transmittal ltr
* Toledo Edison Co 84/08/15 6pp 26275 355 24X
Fiche 50-346, 84/08/15, 8408280145

8408280087 Emergency Plan Implementing Procedure AD 1827 16, "Search & Rescue " W/840821 transmittal ltr
HOWATH, E A Toledo Edison Co 84/08/16 3pp 26261 187 24X
Fiche 50-346, 84/08/16, 8408280087

8408270471 Forwards exemption from requirements of 10CFR50, App R, per 830930 request & 831230 supplemental request
DEAGAZIO, A Operating Reactors Branch 4 84/08/20 CROUSE, R P
Toledo Edison Co 2pp 26277 198 24X Fiche 50-346, 84/08/20, 8408270471

--8408270478 Exemption from requirements of 10CFR50, App R re fire barrier separation, 72 h cold shutdown conditions & lube oil collection sys
EISENHUT, D G Division of Licensing 84/08/20 Toledo Edison Co 6pp 26277 200 24X Fiche 50-346, 84/08/20, 8408270471

8408200126 Rev 221 to emergency plan supporting procedures rev index
* Toledo Edison Co 84/08/31 1p 26133 254 24X
Fiche 50-346, 84/08/31, 8408200126

K Utility Final Safety Analysis Report (FSAR) & amends

8408280197 Forwards corrected pages to Rev 2 to updated FSAR for Davis-Besse Unit 1
CROUSE, R P Toledo Edison Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26275 226 24X
Fiche 50-346, 84/08/17, 8408280197

--8408280198 Corrected pages to Rev 2 to updated FSAR for Davis-Besse Unit 1
* Toledo Edison Co 84/07/31 21pp 26275 227 24X
Fiche 50-346, 84/08/17, 8408280197

P Operating license stage documents & correspondence

8408020172 Forwards Amend 71 to License NPF-3 & safety evaluation Amend modifies Tech Specs re definition of term "operable" as applied to ESF sys to support sys outages
RIVENBARK,G W Operating Reactors Branch 4 84/07/09 CROUSE,R P
Toledo Edison Co 2pp 25898 058 24X Fiche 50-346,84/07/09, 8408020172

--8408020173 Amend 71 to License NPF-3,modifying Tech Specs re definition of term "operable" as applied to ESF sys to support sys outages of redundant components
RIVENBARK,G W Operating Reactors Branch 4 84/07/09 10pp
25898 060 24X Fiche 50-346,84/07/09,8408020172

--8408020174 Safety evaluation supporting Amend 71 to License NPF-3
* Office of Nuclear Reactor Regulation, Director 84/07/09 2pp
25898 070 24X Fiche 50-346,84/07/09,8408020172

8408070499 Forwards Amend 72 to License NPF-3 & safety evaluation Amend modifies Tech Spec Table 3 6-2 to permit delay of surveillance test of MSIVs until after entering Mode 3
DEAGAZIO,A W Operating Reactors Branch 4 84/07/20 CROUSE,R P
Toledo Edison Co 2pp 25956 239 24X Fiche 50-346,84/07/20, 8408070499

--8408070502 Amend 72 to License NPF-3,modifying Tech Spec Table 3 6-2 to permit delay of surveillance test of MSIVs until after entering Mode 3
RIVENBARK,G W Operating Reactors Branch 4 84/07/20 5pp
25956 241 24X Fiche 50-346,84/07/20,8408070499

--8408070505 Safety evaluation supporting Amend 72 to License NPF-3
* Office of Nuclear Reactor Regulation, Director 84/07/20 3pp
25956 246 24X Fiche 50-346,84/07/20,8408070499

8408130530 Forwards Amend 73 to License NPF-3 & safety evaluation Amend revises Tech Specs to add new Sections 3 3 2 3 & 4 3 2 3 & Tables 3 3-15 & 4 3-15 to reflect final anticipatory reactor trip sys
RIVENBARK,G W Operating Reactors Branch 4 84/07/25 CROUSE,R P
Toledo Edison Co 3pp 26038 341 24X Fiche 50-346,84/07/25, 8408130530

--8408130537 Amend 73 to License NPF-3,adding new Tech Spec Sections 3 3 2 3 & 4 3 2 3 & Tables 3 3-15 & 4 3-15 to reflect addition of final anticipatory reactor trip sys
RIVENBARK,G W Operating Reactors Branch 4 84/07/25 11pp
26038 344 24X Fiche 50-346,84/07/25,8408130530

--8408130545 Safety evaluation supporting Amend 73 to License NPF-3 Evaluation of licensee 821115 response to Generic Ltr 82-16 also included
* Office of Nuclear Reactor Regulation, Director 84/07/25 8pp
26038 355 24X Fiche 50-346,84/07/25,8408130530

8408080288 Summary of 840712 meeting w/BLW Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating
Reactors Branch 4 36pp 25978 228 24X Fiche 50-000,84/07/27, 8408080288

8408070335 Supplx 831107 response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events " Program & planned enhancements listed,including commitment to participate in NPRDS
CROUSE,R P Toledo Edison Co 84/07/31 STOLZ,J F Operating
Reactors Branch 4 3pp 25945 230 24X Fiche 50-346,84/07/31, 8408070335

8408080524 Forwards Amend 74 to License NPF-3 Amend changes Tech Specs to require annual audit of emergency & security plans & implementing procedures
STOLZ,J F Operating Reactors Branch 4 84/07/31 CROUSE,R P
Toledo Edison Co 4pp 25975 360 24X Fiche 50-346,84/07/31, 8408080524

--8408080527 Amend 74 to License NPF-3,changing Tech Specs to require annual audit of emergency & security plan & implementing procedures
STOLZ,J F Operating Reactors Branch 4 84/07/31 4pp
25976 002 24X Fiche 50-346,84/07/31,8408080524

8408150565 Forwards SER re 830818 proposed Tech Spec re containment purge & vent valve leak testing to detect excessive resilient seal deterioration Revised matl required by 840907.
STOLZ,J F Operating Reactors Branch 4 84/08/03 CROUSE,R P
Toledo Edison Co 2pp 26080 308 24X Fiche 50-346,84/08/03, 8408150565

--8408150569 SER re 830818 proposed Tech Spec change re containment purge & vent valve leak testing to detect seal deterioration Proposed change unacceptable
GUO,J S Office of Nuclear Reactor Regulation, Director
84/08/03 5pp 26080 311 24X Fiche 50-346,84/08/03,8408150565

8408130421 Forwards application for amend to License NPF-3, incorporating integrated living schedule program
CROUSE,R P Toledo Edison Co 84/08/04 STOLZ,J F Operating
Reactors Branch 4 1p 26011 030 24X Fiche 50-346,84/08/04, 8408130421

--8408130428 Application for amend to License NPF-3, incorporating integrated living schedule program SER & significant hazard consideration rept encl
CROUSE,R P Toledo Edison Co 84/08/04 7pp 26011 031 24X
Fiche 50-346,84/08/04,8408130421

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408230465 Forwards corrected listing of page changes & affected pages of Amend 71 to License NPF-3,submitted on 840718
STOLZ,J F Operating Reactors Branch 4 84/08/09 CROUSE,R P
Toledo Edison Co 2pp 26230 219 24X Fiche 50-346,84/08/09, 8408230465

--8408230470 Corrected listing of page changes & affected pages to Amend 71 to License NPF-3
* Operating Reactors Branch 4 84/08/09 6pp 26230 221 24X
Fiche 50-346,84/08/09,8408230465

8408140410 Forwards "Analyses of Capsule TE1-B,Toledo Edison Co, Davis-Besse Nuclear Power Station,Unit 1 Reactor Vessel Matl Surveillance Program "
CROUSE,R P Toledo Edison Co 84/08/10 EISENHUT,D G Division of
Licensing 1p 26049 001 24X Fiche 50-346,84/08/10,8408140410

--8408140413 "Analyses of Capsule TE1-B,Toledo Edison Co,Davis-Besse Nuclear Power Station,Unit 1 Reactor Vessel Matl Surveillance Program "
LOWE,A , COLLINS,L L , EWING,J W Babcock & Wilcox Co BAW-1834
84/05/31 75pp 26049 002 24X Fiche 50-346,84/08/10,8408140410

8408170002 Notification of 840828 meeting w/util in Bethesda,MD to discuss reliability of auxiliary feedwater sys & pump driver diversity
DEAGAZIO,A Operating Reactors Branch 4 84/08/13 STOLZ,J F
Operating Reactors Branch 4 2pp 26135 357 24X
Fiche 50-346,84/08/13,8408170002

8408210456 Withdraws Item 4 of 810925 application for amend to License NPF-3,per 840419 ltr
CROUSE,R P Toledo Edison Co 84/08/13 STOLZ,J F Operating
Reactors Branch 4 1p 26177 205 24X Fiche 50-346,84/08/13, 8408210456

8408200135 Forwards addl info concerning NUREG-0737,Item II B 3 re post-accident sampling,per 840719 request Rexnord Model 340 portable oxygen monitor used to determine dissolved oxygen in reactor coolant sample
CROUSE,R P Toledo Edison Co 84/08/14 STOLZ,J F Operating
Reactors Branch 4 19pp 26133 260 24X Fiche 50-346,84/08/14, 8408200135

8408230596 Requests mod of 830901 application to amend Tech Spec Section 3 7 7 & Table 3 7-1 re snubbers Util should change insp frequency & testing provisions & review Generic Ltr 84-13 for guidance Revised application requested by 841001
STOLZ,J F Operating Reactors Branch 4 84/08/15 CROUSE,R P
Toledo Edison Co 2pp 26230 266 24X Fiche 50-346,84/08/15, 8408230556

8408280319 Forwards draft technical evaluation rept, "Control of Heavy Loads - Phase II,Davis-Besse Nuclear Power Station Unit 1," for review
STOLZ,J F Operating Reactors Branch 4 84/08/17 CROUSE,R P
Toledo Edison Co 2pp. 26294 053 24X Fiche 50-346,84/08/17, 8408280319

-8409280321 Draft "Control of Heavy Loads - Phase II, Davis-Besse Nuclear Power Station Unit 1," technical evaluation rept
BOMBERGER, C R , WALTER, A J , SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-489
DRFT 84/07/10 SINGH, A NRC - No Detailed Affiliation Given
26pp 26294 055 24X Fiche 50-346, 84/08/17, 8408280319

8408280488 Confirms util 840808 commitment to submit by 841001, revised Tech Specs re instrumentation for containment sump level & containment pressure & equipment for RCS high point vents, per Generic Ltr 83-37 & NUREG-0737
STOLZ, J F Operating Reactors Branch 4 84/08/17 CROUSE, R P
Toledo Edison Co 2pp 26292 355 24X Fiche 50-346, 84/08/17, 8408280488

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408160324 Forwards IE Insp Rept 50-346/84-16 on 840724 No noncompliance noted
LITTLE, W S Region 3, Office of Director 84/07/30 CROUSE, R P,
Toledo Edison Co 2pp 26106 090 24X Fiche 50-346, 84/07/30, 8408160324

--8408160327 IE Insp Rept 50-346/84-16 on 840724 No noncompliance or deviations noted Major areas inspected followup of Titeflex metallic bellows improper attachment design, NDE & qualification testing
JONES, D E , DANIELSON, D H Region 3, Office of Director
84/07/30 2pp 26106 092 24X Fiche 50-346, 84/07/30, 8408160324

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840920 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408130387 Ack receipt of 840723 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-24 Corrective actions will be examined during subsequent insp
SHAFER, W D Region 3, Office of Director 84/08/07 CROUSE, R P
Toledo Edison Co 1p 26011 117 24X Fiche 50-346, 84/08/07, 8408130387

8408130390 Responds to NRC 840625 ltr re violations noted in IE Insp Rept 50-346/83-24 Corrective actions health physics personnel instructed not to conduct respiratory training outside nuclear training dept w/o approval of director
CROUSE, R P Toledo Edison Co 84/07/23 NORELIUS, C E Division of Project & Resident Programs 2pp 26011 118 24X
Fiche 50-346, 84/08/07, 8408130387

8408130407 Ack receipt of 840718 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-346/83-01 & 50-346/84-04
SHAFER, W D Region 3, Office of Director 84/08/07 CROUSE, R P
Toledo Edison Co 1p 26011 018 24X Fiche 50-346, 84/08/07, 8408130407

--8408130411 Responds to NRC 840418 ltr re noncompliance noted in IE Insp Repts 50-346/83-01 & 50-346/84-04 Corrective actions commitment tracking sys established for entire station & sys utilized by maint staff
CROUSE, R P Toledo Edison Co 84/07/18 NORELIUS, C Region 3, Office of Director 11pp 26011 019 24X Fiche 50-346, 84/08/07, 8408130407

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408130391 Ack receipt of 840727 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/84-06
SHAFER, W D Region 3, Office of Director 84/08/08 CROUSE, R P
Toledo Edison Co 1p 26011 102 24X Fiche 50-346, 84/08/08, 8408130391

--8408130395 Responds to NRC 840629 ltr re violations noted in IE Insp Rept 50-346/84-06 Corrective actions licensed personnel reminded to comply w/prompt notification requirements & counseled on requirements for completing commitments
CROUSE, R P Toledo Edison Co 84/07/27 NORELIUS, C E Division of Project & Resident Programs 3pp 26011 103 24X
Fiche 50-346, 84/08/08, 8408130391

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408170214 Forwards SER providing justification re request for relief from quarterly reverse flow testing of various svc water check valves Safety function of check valves to isolate trains will be provided by locked closed gate valves
CROUSE, R P Toledo Edison Co 84/08/14 STOLZ, J F Operating Reactors Branch 4 4pp 26118 098 24X Fiche 50-346, 84/08/14, 8408170214

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408210345 Forwards Relief Request 30 requesting exemption from testing valves DH-11 & DH-12, per requirements of 10CFR50, App J, Section III A 1 d & III C Revised pages to inservice insp valve program, submitted on 800515, also encl W/o rev
CROUSE, R P Toledo Edison Co 84/08/15 STOLZ, J F Operating Reactors Branch 4 3pp 26180 197 24X Fiche 50-346, 84/08/15, 8408210345

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208,

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408230104 "Effluent & Waste Disposal Semiannual Rept,Jan-June 1984 " W/840815 ltr
QUENNOZ,S M Toledo Edison Co 84/06/30 KEPPLER,J G Region 3, Office of Director 88pp 26209 063 24X Fiche 50-346,84/06/30, 8408230104

S Reportable occurrences, LERs & related correspondence

8408010313 LER 84-010-00 on 840624,loss of power to Y4,Channel 4 essential 120-volt ac bus,experienced Caused by failure of YV4 inverter due to failure of zener diode & resistor in logic power supply circuit board W/840724 ltr
NARUS,G E , MURRAY,T D Toledo Edison Co 84/07/24 4pp 25966 147 24X Fiche 50-346,84/07/24,8408010313

8408080506 Forwards revised LER 84-003-01 Revised Page 1 contains NPRDS codes omitted from 840720 submittal & should replace old Page 1
MURRAY,T D Toledo Edison Co 84/07/26 Record Services Branch (Document Control Desk) 1p 25975 257 24X Fiche 50-346,84/07/26, 8408080506

8408080508 Revised LER 84-003-01 on 840302,MSIV 2 closed,isolating steam side of steam generator 2 Caused by failed relay in safety instrumentation channel MSIV replaced Failed relay circuit repaired
SWANGER,F Toledo Edison Co 84/07/26 1p 25975 258 24X Fiche 50-346,84/07/26,8408080508

8408090026 LER 84-003-01 on 840302,w/unit operating at 99% power,MSIV closed,isolating steam side of steam generator 2 Caused by undetected failed relay in safety instrumentation channel Relay replaced W/840727 ltr
SWANGER,F , MURRAY,T D Toledo Edison Co 84/07/26 5pp 25992 259 24X Fiche 50-346,84/07/26,8408090026

8408160199 LER 84-006-01 on 840515,makeup level tank dropped at rate of three gpm Leak discovered in vicinity of pressurized spray control valve Reactor shut down & leak found in spray valve bypass valve Valve replaced W/840809 ltr
NARUS,G E , QUENNOZ,S N Toledo Edison Co 84/08/09 4pp 26106 338 24X Fiche 50-346,84/08/09,8408160199

8408160497 LER 83-074/03X-1 on 831224,borated water storage tank hi fail alarm for safety features actuation sys Channel 1 received Caused by improperly installed heat trace Surveillance Test ST 5031 05 modified W/840809 ltr
ISLEY,T , QUENNOZ,S M Toledo Edison Co 84/08/09 3pp 26129 114 24X Fiche 50-346,84/08/09,8408160497

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

X Onsite Storage of Low Level Waste

8408070301 Forwards addl info re util 830714 request for approval for alternative onsite disposal of very low level radioactively contaminated secondary-side cleanup resins
CROUSE,R P Toledo Edison Co 84/07/30 STOLZ,J F Operating Reactors Branch 4 11pp 25947 240 24X Fiche 50-346,84/07/30, 8408070301

DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8408170386 Requests meeting to discuss detailed control room design review w/respect to Nuclear Util Task Action Committee documents
VARGA,S A Operating Reactors Branch 1 84/05/24 MCDONALD,R P Alabama Power Co 3pp, 26134 193 24X Fiche 50-348,84/05/24, 8408170386

8408300364 Forwards summary of 840530 meeting w/Alabama Power Co, Florida Power Corp,Florida Power & Light,Georgia Power Co & TVA re selected emergency preparedness issues
O'REILLY,J P Region 2, Office of Director 84/06/08, MCDONALD,R P Alabama Power Co 4pp 26308 216 24X Fiche:50-348,84/06/08,8408300364

8408060070 Temporary change notices for Rev 7 to Procedure GO-EIP-111, "Corporate Activation & Notification " W/840727 ltr
MUDD,C H Alabama Power Co 84/07/27 21pp 25933 104 24X Fiche 50-348,84/07/27,8408060070

8408070469 Forwards interim shutdown meaures re App R Eleven sys discussed which could potentially be impacted by cable spreading room fire Mods required to establish compliance w/App R
MCDONALD,C E Alabama Power Co 84/07/27 VARGA,S A Office of Nuclear Reactor Regulation, Director 5pp 25940 336 24X Fiche 50-348,84/07/27,8408070469

8408130374 Submits addl info re 10CFR50,App R schedular exemption for alternative shutdown mods Bases for schedular exemption until Unit 1 seventh & Unit 2 fourth refueling outages to completed mods provided
MCDONALD,R P Alabama Power Co 84/08/06 VARGA,S A Office of Nuclear Reactor Regulation, Director 2pp 26005 337 24X Fiche 50-348,84/08/06,8408130374

8408240229 Summary of 840725 meeting w/util re detailed control room design review,per NUREG-0737,Suppl 1
REEVES,E A Operating Reactors Branch 1 84/08/16 Operating Reactors Branch 1 6pp 26251 227 24X Fiche 50-348,84/08/16, 8408240229

8408230326 Revised emergency plan implementing procedures,including GO-EIP-101 re corporate emergency organization,GO-EIP-135 re emergency plan review & rev & GO-EIP-120 re ref guidance for recovery manager W/840817 ltr
MUDD,C H Alabama Power Co 84/08/17 36pp 26206 018 24X Fiche 50-348,84/08/17,8408230326

M Antitrust correspondence

8408130075 Ack receipt of 840629 petition for enforcement action under 10CFR2 206 re antitrust license conditions Petition will be held in abeyance pending further Commission direction
DENTON,H R Office of Nuclear Reactor Regulation, Director 84/07/30 BOSKEY,B Volpe, Boskey & Lyons 7pp 26034 353 24X Fiche:50-348,84/07/30,8408130075

8408080197 Reiterates 840702 request for notes,memoranda or transcripts of meetings between NRC & util as referenced in Palladino 840626 memo
BOSKEY,B , MACGUINEAS,D B Volpe, Boskey & Lyons BOSKEY,B Alabama Electric Cooperative, Inc DSB 833 84/08/06 DIRCKS,W J Office of the Executive Director for Operations 2pp 25960 259 24X Fiche 50-348,84/08/06,8408080197

8408080202 Reiterates 840702 request for notes,memoranda or transcripts of meetings between NRC & util as referenced in Palladino 840626 memo
BOSKEY,B , MACGUINEAS,D B Volpe, Boskey & Lyons BOSKEY,B Alabama Electric Cooperative, Inc DSB 831 84/08/06 BERNTHAL,F M Commissioners 2pp 25959 022 24X Fiche 50-348,84/08/06,8408080202

8408080241 Reiterates 840702 request for any notes or memoranda or transcripts of meetings u/util near end of June 1984 Certificate of Svc encl
BOSKEY,B , MACGUINEAS,D B Volpe, Boskey & Lyons BOSKEY,B Alabama Electric Cooperative, Inc DSB 832, 84/08/06 ABBELSFINE,J K Commissioners 2pp 25966 291 24X Fiche 50-348,84/08/06,8408080241

8408150120 Responds to 840806 ltr to WJ Dircks requesting any notes, memoranda or transcripts made of meetings between NRC & util No notes taken & no memoranda or transcripts of 840626 meeting prepared Related correspondence
CUNNINGHAM,G H Office of the Executive Legal Director DSB 038 84/08/10 BOSKEY,B , MACGUINEAS,D B Volpe, Boskey & Lyons 2pp 26066 352 24X Fiche 50-348,84/08/10,8408150120

8408200486 Responds to 840806 request for Commission records re 840625 meeting w/util Chairman Palladino 840624 memo accurately reflects conversation W/svc list Served on 840817
BERNTHAL,F Commissioners DSB 166 84/08/16 BOSKEY,B Volpe, Boskey & Lyons 3pp 26136 318 24X Fiche:50-348,84/08/16, 8408200486

P Operating license stage documents & correspondence

8408060277 Requests addl info needed for continuing review of 840203 license amend request,per Generic Ltr 83-43 Deficiencies noted in Tech Specs re deletion of RDs
VARGA,S A Operating Reactors Branch 1 84/07/25 MCDONALD,R P, Alabama Power Co 2pp 25950 294 24X Fiche 50-348,84/07/25, 8408060277

8408130233 Forwards safety evaluation & technical evaluation rept re control of heavy loads, Phase 1
VARGA, S A Operating Reactors Branch 1 84/07/25 MCDONALD, R P
Alabama Power Co 2pp 26060 027 24X Fiche 50-348, 84/07/25, 8408130233

--8408130258 SER re control of heavy loads, Phase 1 Phase 1 acceptable
* NRC - No Detailed Affiliation Given 84/07/25 2pp
26060 029 24X Fiche 50-348, 84/07/25, 8408130233

8408100036 Forwards updated status of 1984 licensing items identified in 840702 ltr Util ready to discuss mod of licensing status to address all licensing issues
MCDONALD, R P Alabama Power Co 84/08/01 VARGA, S A Office of Nuclear Reactor Regulation, Director 7pp 25990 061 24X
Fiche 50-348, 84/08/01, 8408100036

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408230398 Application for amend to Licenses NPF-2 & NPF-8, deleting words during shutdown from Tech Spec 4 7 1 2 2 b 1 re auxiliary feedwater sys Fee encl
MCDONALD, R P Alabama Power Co 84/08/17 VARGA, S A Office of Nuclear Reactor Regulation, Director 3pp 26205 304 24X
Fiche 50-348, 84/08/17, 8408230398

--8408230399 Proposed Tech Spec 4 7 1 2.2 b 1, deleting words during shutdown
* Alabama Power Co 84/08/17 2pp 26205 307 24X
Fiche. 50-348, 84/08/17, 8408230398

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G. Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Inspection reports, IE Bulletins & correspondence

8408280176 Discusses results of diesel generator check valve integrity insp, per IE Bulletin 83-03, during fifth refueling outage on 840210-0424 Inservice testing requirements for valves will be modified as listed
MCDONALD, R P Alabama Power Co 84/06/01 O'REILLY, J P. Region 2, Office of Director 3pp 26279 196 24X Fiche 50-348, 84/06/01, 8408280176

108280048 Forwards response to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Unit 1 relays replaced w/GE Century Series HFA relays Thirty-three Unit 2 relays require replacement
MCDONALD, R P Alabama Power Co 84/07/12 O'REILLY, J P Region 2, Office of Director 5pp 26261 230 24X Fiche 50-348, 84/07/12, 8408280048

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408300169 Requests relief from inservice insp program for ASME Code Class 1, 2 & 3 components by 850301, to allow for performance of insp activities during sixth refueling outage scheduled to begin 850405 Fee paid
MCDONALD, R P Alabama Power Co 84/08/06 VARGA, S A Office of Nuclear Reactor Regulation, Director 6pp 26304 343 24X
Fiche 50-348, 84/08/06, 8408300169

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408200611 Monthly operating rept for Jul 1984 W/840814 ltr
WOODWARD, J D , MCDONALD, R P Alabama Power Co 84/07/31 5pp
26138 117 24X Fiche 50-348, 84/07/31, 8408200611

S Reportable occurrences, LERs & related correspondence

8408230515 LER 84-013-00 on 840716, continuous fire watch not posted in closed cooling water HX & pump room while maint personnel performing grinding & welding operations Watch posted & maintained until no longer required W/840815 ltr
WOODARD, J D , MCDONALD, R P Alabama Power Co 84/08/15 3pp
26212 283 24X Fiche 50-348, 84/08/15, 8408230515

V Operator Examinations

8408070314 Forwards response to Generic Ltr 84-14 re replacement & requalification training program Encl provides outline & description of simulator utilized in training & requalification program
MCDONALD, R P Alabama Power Co 84/07/26 VARGA, S A Office of Nuclear Reactor Regulation, Director 3pp 25948 002 24X
Fiche 50-348, 84/07/26, 8408070314

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

8408070228 Forwards response to 840529 ltr re anonymous allegation on cracked valve of recirculation sys B pump suction valve. Based on results of 840614 visual insp, no crack identified Defect may have been surface irregularity
GALLAGHER, J W Philadelphia Electric Co 84/06/18 MURLEY, T E
Region 1, Office of Director 3pp 25948 225 24X
Fiche 50-352, 84/06/18, 8408070228

8408010199 Notification of 840731 meeting w/util in Pottstown,PA to discuss electrical separation criteria,based on Wyle Labs test results
MARTIN,R E Licensing Branch 2 84/07/23 SCHWENCER,A Licensing Branch 2 6pp 25873 280 24X Fiche 50-352,84/07/23,8408010199

8408080206 Notification of 840807 meeting w/util in Bethesda,MD to discuss outstanding items in detailed control room design review
MARTIN,R E Licensing Branch 2 84/07/26 SCHWENCER,A Licensing Branch 2 5pp 25978 329 24X Fiche 50-352,84/07/26,8408080206

8408020030 Forwards requested info on NUREG-0737,Item II F 1 re interim procedures for quantifying high level accidental radioactive releases Info re Item III D 1 1 will be furnished in Sept 1984
KEMPER,J S Philadelphia Electric Co 84/07/27 SCHWENCER,A Licensing Branch 2 14pp 25883 218 24X Fiche 50-352,84/07/27,8408020030

8408060268 Notification of 840806 meeting w/util in Bethesda,MD to discuss applicant analysis of tornado missile effects on UHS Date changed
MARTIN,R E Licensing Branch 2 84/07/27 SCHWENCER,A Licensing Branch 2 1p 25950 302 24X Fiche 50-352,84/07/27,8408060268

--8408060273 Notifies of 840803 meeting w/util to discuss applicant 840322 analysis of tornado missile effects on UHS
SCHWENCER,A Licensing Branch 2 84/07/26 BAUER,E G
Philadelphia Electric Co 6pp 25950 303 24X
Fiche 50-352,84/07/27,8408060268

8408020058 Forwards Amend 68 to OL application,consisting of Rev 34 to FSAR (Category K),Rev 19 to environ rept - OL stage (Category C),Rev 9 to design assessment rept (DAR),Vols 1,2 & 3 W/o Vol 2 DAR,Vol 3 withheld (ref 10CFR2 790)
BRADLEY,E J Philadelphia Electric Co 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25904 001
24X Fiche 50-352,84/07/31,8408020058

--8408020075 Amend 68 to OL application,consisting of Rev 34 to FSAR,Rev 19 to environ rept - OL stage & Rev 9 to design assessment rept (DAR),Vols 1 & 2 & proprietary Rev 9 to DAR,Vol 3 W/o Vol 2 DAR,Vol 3 withheld (ref 10CFR2 790)
BOYER,V S Philadelphia Electric Co 84/07/31 4pp 25904 004
24X Fiche 50-352,84/07/31,8408020058

--8408020090 Nonproprietary Rev 9 to Vol 1 of "Design Assessment Rept "
* Philadelphia Electric Co 84/07/31 9pp 25904 286 24X
Fiche 50-352,84/07/31,8408020058

8408220333 A REVIEW OF THE LIMERICK GENERATING STATION SEVERE ACCIDENT RISK ASSESSMENT Review of Core Melt Frequency
AZARM,M A ; BARI,R A ; BOCCIO,J L Brookhaven National Laboratory
FIN A-3393 NUREG/CR-3493 84/07/31 Division of Safety Technology 192pp Available at NRC $6 00 26200 205 24X
Fiche 50-352,84/07/31,8408220333

8408070033 Forwards revised FSAR pages reflecting increase of reactor encl design inleakage rate from 50 to 100/ free vol/day & doubling standby gas treatment sys fan flow during drawdown of Unit 1 encl FSAR rev scheduled for Aug 1984
BRADLEY,E J Philadelphia Electric Co 84/08/02 SCHWENCER,A
Licensing Branch 2 39pp 25949 289 24X Fiche 50-352,84/08/02,8408070033

8408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure
KEMPER,J S Philadelphia Electric Co 84/08/02 SCHWENCER,A
Licensing Branch 2 6pp 25949 329 24X Fiche 50-352,84/08/02,8408070037

8408140334 Notification of 840814 meeting w/util in Bethesda,MD to discuss analysis of tornado missile effects on UHS
MARTIN,R E Licensing Branch 2 84/08/05 SCHWENCER,A Licensing Branch 2 4pp 26061 281 24X Fiche 50-352,84/08/05,8408140334

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche: 50-000,84/08/06,8408070110

8408130317 Advises that Preoperational Test 100 3, "Mechanical Snubber Testing," will be deleted from preoperational test program, per 840716 & telcons Insp,exam & testing personnel will be qualified for snubber test per ANSI N45 2 6-1978
KEMPER,J S Philadelphia Electric Co 84/08/07 SCHWENCER,A
Licensing Branch 2 9pp 26010 329 24X Fiche 50-352,84/08/07,8408130317

8408160477 Informs that all comments re risk evaluation rept received & incorporated into final version Rept ready for transmittal to applicant,ACRS & ASLB
EISENHUT,D G Division of Licensing 84/08/09 SPEIS,T NRC - No Detailed Affiliation Given 1p 26108 351 24X
Fiche 50-352,84/08/09,8408160477

8408210051 Notification of 840815 meeting w/util in Bethesda,MD to discuss further development of Tech Specs
MARTIN,R E Licensing Branch 2 84/08/14 SCHWENCER,A Licensing Branch 2 5pp 26195 171 24X Fiche 50-352,84/08/14,8408210051

8408210303 Forwards draft changes to FSAR,Section 15 7 4 & response to Request for Addl Info 410 37 re light loads/fuel handling accident Drop of object would not result in consequences in excess of revised fuel handling accident
KEMPER,J S Philadelphia Electric Co 84/08/14 SCHWENCER,A
Licensing Branch 2 28pp 26179 298 24X Fiche 50-352,84/08/14,8408210303

8408220165 Forwards response to NRC 840716 request for addl info re offsite dose calculation manual & revised offsite dose calculation manual Related correspondence
KEMPER,J S Philadelphia Electric Co 84/08/15 SCHWENCER,A
Licensing Branch 2 7pp 26197 168 24X Fiche 50-352,84/08/15,8408220165

--8408220168 Revised "Offsite Dose Calculation Manual "
* Philadelphia Electric Co 84/08/10 41pp 26197 175 24X
Fiche 50-352,84/08/15,8408220165

8408210513 Forwards Wyle test rept, "Electrical Separation Verification Testing on Terminal Blocks & Panel Meters," raceway separation criteria & design analysis documenting separation criteria rationale
KEMPER,J S Philadelphia Electric Co 84/08/16 SCHWENCER,A
Licensing Branch 2 3pp 26178 254 24X Fiche 50-352,84/08/16,8408210513

--8408210518 "Test Rept on Electrical Separation Verification Testing on Terminal Blocks & Panel Meters for Limerick Generating Station Units 1 & 2 "
HAZELTINE,J , JOHNSON,F R , ROBERTS,W.B Wyle Laboratories 46960-4 84/05/15 62pp. 26178 257. 24X Fiche 50-352,84/08/16,8408210513

--8408210520 Rev 0 to "Raceway Separation Criteria " Raceway separation test program discussion encl
* Philadelphia Electric Co 84/08/09. 46pp 26178 316 24X
Fiche 50-352,84/08/16,8408210513

8408220119 Requests that License Condition 2 re fuel rod pressure limit be closed,based on recent resolution of generic issue between GE & NRC Evaluation demonstrates that bundles meet GE limit for fuel rod internal pressure
KEMPER,J S Philadelphia Electric Co 84/08/17 SCHWENCER,A
Licensing Branch 2 2pp 26193 307 24X Fiche 50-352,84/08/17,8408220119.

8408270568 Summary of 840815 meeting w/util in Bethesda,MD re draft Tech Specs Attendees list encl
MARTIN,R E Licensing Branch 2 84/08/17 Licensing Branch 2
4pp 26277 244 24X Fiche 50-352,84/08/17,8408270568

8408310012 Forwards response to Meteorological & Effluent Treatment Branch 840815 request for addl info re wide-range accident monitor calibr factors Related correspondence
KEMPER,J S Philadelphia Electric Co DSB 271 84/08/17
SCHWENCER,A Licensing Branch 2 3pp 26350 194. 24X
Fiche 50-352,84/08/17,8408310012

8408310018 Requests that License Condition 2 re fuel rod pressure limit be closed,based on resolution of issue between GE & NRC. Related correspondence
KEMPER,J S Philadelphia Electric Co DSB 292 84/08/17
SCHWENCER,A Licensing Branch 2 2pp 26350 192 24X
Fiche 50-352,84/08/17,8408310018

8408310007 Responds to 840206 ltr on SER License Condition 7 re compliance w/NUREG-0612,control of heavy loads,Phase II "Limerick Overhead Handling Sys Final Rept (Rev 3)" revised per 840206 request Related correspondence
KEMPER,J S Philadelphia Electric Co DSB 293 84/08/18.
SCHWENCER,A Licensing Branch 2 3pp 26350 197. 24X
Fiche 50-352,84/08/18,8408310007

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20. Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408220463 Board Notification 84-142 forwards R Starostecki 840731 memo re alleged inadequate design of reactor encl vent stack Stack has no or limited safety significance
NOVAK, T M Division of Licensing 84/08/20 BRENNER, L , COLE, R F ,
MORRIS, P A Atomic Safety and Licensing Board Panel 2pp
26261 316 24X Fiche 50-352, 84/08/20, 8408220463

-8408280101 Informs that on 840718, NRC interviewed confidential alleger re concerns relative to response of reactor encl vent stacks to blast loads following railroad accident
STAROSTECKI, R Division of Project & Resident Programs 84/07/31
EISENHUT, D G Division of Licensing 1p 26261 318 24X
Fiche 50-352, 84/08/20, 8408220463

8408270161 Forwards revised response to Procedures & Sys Review Branch Question 430 72 re diesel oil storage tank lines to include addl info discussed in 840810 telcon
KEMPER, J S Philadelphia Electric Co 84/08/21 SCHWENCER, A
Licensing Branch 2 4pp 26245 259 24X Fiche 50-352, 84/08/21, 8408270161

8408310413 Forwards revised response to Procedure & Sys Review Branch Question 430 72 re diesel oil storage tank vent lines, in response to 840810 request for addl info Related correspondence
KEMPER, J S Philadelphia Electric Co DSB 288 84/08/21
SCHWENCER, A Licensing Branch 2 4pp 26350 224 24X
Fiche 50-352, 84/08/21, 8408310413

8408280130 Forwards Rev 1 to "Solid Radwaste Sys Process Control Program," in response to Meteorological & Effluent Treatment Sys Branch request for addl info, per 840808 telcon Preoperational testing of sys scheduled for end of month
KEMPER, J S Philadelphia Electric Co 84/08/23 SCHWENCER, A
Licensing Branch 2 2pp 26259 064 24X Fiche 50-352, 84/08/23, 8408280130

-8408280132 Rev 1 to "Solid Radwaste Sys Process Control Program "
* Philadelphia Electric Co 84/08/31 11pp 26259 066 24X
Fiche 50-352, 84/08/23, 8408280130

8408310146 Forwards response to 840509 request for addl info re NUREG-0737, Item III D 1 1, "Primary Coolant Outside Containment " Info will be incorporated in Sept 1984 FSAR rev
KEMPER, J S Philadelphia Electric Co 84/08/24 SCHWENCER, A
Licensing Branch 2 9pp 26322 208 24X Fiche 50-352, 84/08/24, 8408310146

8408290158 REVIEW INSIGHTS ON THE PROBABILISTIC RISK ASSESSMENTS FOR THE LIMERICK GENERATING STATION, UNIT 1 AND 2
CHELLIAH, E Division of Safety Technology NUREG-1068 84/08/31
126pp Available at NRC $5 00 26309 151 24X
Fiche 50-352, 84/08/31, 8408290158

Utility Environmental Report (ER), amends & correspondence

8408020058 Forwards Rev 19 to environ rept - OL stage
BRADLEY, E J Philadelphia Electric Co 84/07/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25904 001
24X Fiche 50-352, 84/07/31, 8408020058

-8408020080 Rev 19 to environ rept - OL stage
* Philadelphia Electric Co, 84/07/31 4pp 25904 010 24X
Fiche 50-352, 84/07/31, 8408020058

8408210076 Forwards Affidavit of Svc certifying distribution of Rev 34 to FSAR & Rev 19 to environ rept on 840809
BRADLEY, E J. Philadelphia Electric Co 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 26184 327
24X Fiche 50-352, 84/08/14, 8408210076

NRC Safety Evaluation Report (SER), suppls & correspondence

8408060232 Forwards responses to questions & comments re 840322 analysis of tornado missile effects on UHS, supporting resolution of SER Open Issue 2 Responses do not affect results of prior analysis
KEMPER, J S Philadelphia Electric Co 84/07/27 SCHWENCER, A
Licensing Branch 2 19pp 25934 117 24X Fiche 50-352, 84/07/27, 8408060232

8408070289 Informs that upgrading & mods to RCIC turbine assembly completed, except for installation of threaded taper pins, in response to SER Open Item 6 Justification for interim operation of Unit 1 encl
KEMPER, J S Philadelphia Electric Co 84/08/01, SCHWENCER, A
Licensing Branch 2 5pp, 25948 220 24X Fiche, 50-352, 84/08/01, 8408070289

8408070513 Forwards info to support resolution of SER proposed License Conditions 8, 9, 10 & 12 & to assist in preparation of License Condition 14 Info withheld (ref 10CFR2 790 & 73 21)
Affidavit of withholding encl
KEMPER, J S Philadelphia Electric Co 84/08/01 SCHWENCER, A
Licensing Branch 2 5pp 25941 167 24X Fiche 50-352, 84/08/01, 8408070513

8408130296 Forwards relief requests from ASME Code, Section XI preservice insp requirements to resolve SER Confirmatory Issue 12
KEMPER, J S Philadelphia Electric Co 84/08/07 SCHWENCER, A
Licensing Branch 2 7pp 26008 349 24X Fiche 50-352, 84/08/07, 8408130296

8408140303 Forwards responses to 840611 request for addl info re SER Confirmatory Issues 3, 5 & 6 & SER Open Issue 29 Related draft FSAR & design assessment rept page changes also encl
KEMPER, J S Philadelphia Electric Co 84/08/08 SCHWENCER, A
Licensing Branch 2 27pp 26111 129 24X Fiche 50-352, 84/08/08, 8408140303

--8408140314 "Spec for Test Requirements for Hot Deflection Testing of ASME Section III, Nuclear Class 1, 2, 3 & ANSI B31 1, Bechtel Piping, for Limerick Generating Station, Units 1 & 2 "
* Bechtel Corp 84/05/29 139pp 26111 156 24X
Fiche 50-352, 84/08/08, 8408140303

--8408140320 "Spec for Test Requirements for Steady State Vibration Testing of ASME Section III, Nuclear Class 1, 2, 3 & ANSI B31 1, Bechtel Piping, for Limerick Generating Station, Units 1 & 2 "
* Bechtel Corp 84/05/25 280pp 26111 317 24X
Fiche 50-352, 84/08/08, 8408140303

--8408140326 "Spec for Test Requirements for Dynamic Transient Testing of ASME Section III, Nuclear Class 1, 2, 3 & ANSI B31 1, Bechtel Piping, for Limerick Generating Station, Units 1 & 2 "
* Bechtel Corp 84/05/29 129pp 26112 240 24X
Fiche 50-352, 84/08/08, 8408140303

8408200262 Forwards responses to addl questions raised by Chemical Engineering Branch re structural steel survivability evaluation Info supports final resolution of SER Open Item 14
KEMPER, J S Philadelphia Electric Co 84/08/08 SCHWENCER, A
Licensing Branch 2 26pp 26133 211 24X Fiche 50-352, 84/08/08, 8408200262

8408160379 Forwards draft FSAR pages in response to NRC 820825 request for addl info re instrument setpoint methodology for reactor protection sys & ESF instrumentation setpoints Info should close SER Confirmatory Issue 26
KEMPER, J S Philadelphia Electric Co 84/08/10 SCHWENCER, A
Licensing Branch 2 3pp 26092 173 24X Fiche 50-352, 84/08/10, 8408160379

8408230292 Forwards Rev 3 to "Overhead Handling Sys Review " Rept revised, per NUREG-0612, to address concerns identified in draft technical evaluation rept on control of heavy loads & support resolution of SER License Condition 7
KEMPER, J S Philadelphia Electric Co 84/08/13 SCHWENCER, A
Licensing Branch 2 3pp 26207 001 24X Fiche 50-352, 84/08/13, 8408230292

--8408230297 Rev 3 to final rept "Overhead Handling Sys Review "
* Philadelphia Electric Co 84/06/30 175pp 26207 004 24X
Fiche 50-352, 84/08/13, 8408230292

8408210031 Forwards addl info requested in NRC 840430 ltr re exceptions to conformance to Rev 2 to Reg Guide 1 97 Encls should close Open Item 12 of SER (NUREG-0991)
KEMPER, J S Philadelphia Electric Co 84/08/16 SCHWENCER, A
Licensing Branch 2 11pp 26181 337 24X Fiche 50-352, 84/08/16, 8408210031

8408270376 Forwards addl info re SER Confirmatory Issue 12 concerning preservice insp program, per 840817 request
KEMPER, J S Philadelphia Electric Co 84/08/23 SCHWENCER, A
Licensing Branch 3 62pp 26240 258 24X Fiche 50-352, 84/08/23, 8408270376

8408300215 Requests assistance in reviewing encl app to SER re identification of vital areas Response requested within 10 days of memo date to meet review 840907 completion date App withheld (ref 10CFR73 21)
THOMAS, C O Standardization & Special Projects Branch 84/08/24
PARR, O D Auxiliary Systems Branch 1p 26307 054 24X
Fiche 50-352, 84/08/24, 8408300215

F Security, medical, emergency & fire protection plans

8408160355 Forwards public version of emergency plan implementing procedures, including EP-101 re classification of emergencies, EP-102 re unusual event response, EP-103 re alert response & EP-104 re site emergency response
COONEY, M J Philadelphia Electric Co 84/07/09 MURLEY, T E
Region 1, Office of Director SCHWENCER, A Licensing Branch 2
5pp 26127 001 24X Fiche 50-352, 84/07/09, 8408160355

--8408160360 Public version of revised emergency plan implementing procedures, including EP-101 re classificaton of emergencies, EP-102 re unusual event response & EP-103 re alert response W/JM Felton 840807 release memo
* Philadelphia Electric Co 84/06/08 450pp 26127 006 24X
Fiche 50-352, 84/07/09, 8408160355

8408070336 Emergecy plan exercise manual
* Philadelphia Electric Co 84/07/25 426pp 25946 001 24X
Fiche 50-352, 84/07/25, 8408070336

8408020047 Forwards JL Patton 840723 ltr responding to RC Claypool 840607 ltr to Thornburgh re resources for radiological emergency response planning Related correspondence
PERKIN, Z G Pennsylvania, Commonwealth of, DSB 704 84/07/27
BRENNER, L , COLE, R F , MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 25883 273 24X Fiche 50-352, 84/07/27, 8408020047

8408070513 Forwards info to support resolution of SER proposed License Conditions 8, 9, 10 & 12 & to assist in preparation of License Condition 14 Info withheld (ref 10CFR2 790 & 73 21) Affidavit of withholding encl
KEMPER, J S Philadelphia Electric Co 84/08/01 SCHWENCER, A
Licensing Branch 2 5pp 25941 167 24X Fiche 50-352, 84/08/01, 8408070513

8408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure
KEMPER, J S Philadelphia Electric Co 84/08/02 SCHWENCER, A
Licensing Branch 2 6pp 25949 329 24X Fiche 50-352, 84/08/02, 8408070037

8408230153 Forwards IE Insp Rept 50-352/84-35 on 840702-03 & 05-06 No violations noted
MARTIN, T T Region 1, Office of Director 84/08/03 KEMPER, J S
Philadelphia Electric Co 4pp 26214 047 24X
Fiche 50-352, 84/08/03, 8408230153

--8408230157 IE Insp Rept 50-352/84-35 on 840702-03 & 05-06 No violations noted Major areas inspected chemistry, radioactive effluent control & radiation protection programs
MILLER, M T , KOTTAN, J J , CARSON, B H Region 1, Office of Director 84/08/03 6pp 26214 051 24X Fiche 50-352, 84/08/03, 8408230153

8408150637 Revised notification of 840807, 09 & 10 meetings w/util in Bethesda, MD & Linfield, PA to discuss outstanding items in detailed control room design review
MARTIN, R E Licensing Branch 2 84/08/07 SCHWENCER, A Licensing Branch 2 5pp 26102 339 24X Fiche 50-352, 84/08/07, 8408150637

8408220497 Forwards public version of revised emergency plan implementing procedures, including EP-105, "General Emergency Response" & EP-304, "Partial Plant Evacuation " Release memo dtd 840820 encl
DALTROFF, S L Philadelphia Electric Co 84/08/07 MURLEY, T E
Region 1, Office of Director SCHWENCER, A Licensing Branch 2
7pp 26210 213 24X Fiche 50-352, 84/08/07, 8408220497

--8408220501 Public version of revised emergency plan implementing procedures, including EP-105, "General Emergency Response" & EP-304, "Partial Plant Evacuation "
* Philadelphia Electric Co 84/08/07 25pp 26210 219 24X
Fiche 50-352, 84/08/07, 8408220497

8408200147 Informs of review of schedule for sprinkler design & installation in conjunction w/possible temporary protective measures Installation of permanent sprinkler sys should be expedited
KEMPER, J S Philadelphia Electric Co 84/08/08 SCHWENCER, A
Licensing Branch 2 3pp 26133 283 24X Fiche 50-352, 84/08/08, 8408200147

8408200206 Forwards info re 4-kV penetrations, resolving item questioned during 840409-12 fire protection sys & documentation site audit Info will be incorporated into next rev to fire protection evaluation rept
KEMPER, J S Philadelphia Electric Co 84/08/08 SCHWENCER, A
Licensing Branch 2 30pp 26133 069, 24X Fiche 50-352, 84/08/08, 8408200206

8408150404 Forwards correspondence & documents between applicant, staff, Commonwealth of PA & responsible govt agencies re emergency planning Related correspondence
CULLEN, E J Philadelphia Electric Co DSB 064 84/08/10
MULLIGAN, M Limerick Ecology Action 24pp 26068 196 24X
Fiche 50-352, 84/08/10, 8408150404

8408170381 Forwards supplemental info re Limerick Ecology Action 840806 response to util discovery request on admitted offsite emergency planning contentions Certificate of Svc encl
MULLIGAN, M Limerick Ecology Action DSB 102 84/08/13 RADER
Philadelphia Electric Co 280pp 26137 181 24X
Fiche 50-352, 84/08/13, 8408170381

8408200286 Forwards correspondence & documents among NRC, applicant & Commonwealth of PA re emergency planning, per ASLB 820601 order Matl suppls 840810, 0712 & 30 submittals Related correspondence
CULLEN, E J Philadelphia Electric Co DSB 142 84/08/15
MULLIGAN, M Limerick Ecology Action 50pp 26131 085 24X
Fiche 50-352, 84/08/15, 8408200286

8408210452 Responds to concerns discussed in 840720 telcon re control room design review Final rept Final validation will be performed prior to fuel load Results will be submitted by 841031
KEMPER, J S Philadelphia Electric Co 84/08/16 SCHWENCER, A
Licensing Branch 2 4pp 26177 200 24X Fiche 50-352, 84/08/16, 8408210452

8408240262 Forwards correspondence & documents among applicant, NRC & other parties re emergency planning Documents suppl matl forwarded in 840815 ltr & provide addl correspondence dtd 840411-0808 Related correspondence
CULLEN, E J Philadelphia Electric Co DSB 264 84/08/20
MULLIGAN, M Limerick Ecology Action 652pp 26223 214 24X
Fiche 50-352, 84/08/20, 8408240262

8408280177 Provides resolution of concerns re fusible links on fire doors identified during 840409-12 site audit of fire protection sys & documentation Fusible links provided on hold open mechanisms for hollow metal doors
KEMPER, J S Philadelphia Electric Co 84/08/22 SCHWENCER, A
Licensing Branch 2 2pp 26275 088 24X Fiche 50-352, 84/08/22, 8408280177

8408270376 Forwards addl info re SER Confirmatory Issue 12 concerning preservice insp program, per 840817 request
KEMPER, J S Philadelphia Electric Co 84/08/23 SCHWENCER, A
Licensing Branch 3 62pp 26240 258 24X Fiche 50-352, 84/08/23, 8408270376

8408300215 Requests assistance in reviewing encl app to SER re identification of vital areas Response requested within 10 days of memo date to meet review 840907 completion date App withheld (ref 10CFR73 21)
THOMAS, C O Standardization & Special Projects Branch 84/08/24
PARR, O D Auxiliary Systems Branch 1p 26307 094 24X
Fiche 50-352, 84/08/24, 8408300215

8408310008 Rev 1 to Emergency Plan Implementing Procedure EP-316, "Cumulative Population & Near Real-Time Emergency Dose Calculations for Airborne Releases - Manual Method " W/840824 ltr
DALTROFF, S L Philadelphia Electric Co 84/08/24 MURLEY, T E
Region 1, Office of Director SCHWENCER, A Licensing Branch 2
74pp 26323.206 24X Fiche 50-352, 84/08/24, 8408310008.

G Adjudicatory correspondence

8408310096 Brief of RL Anthony & Friends of the Earth in support of appeal from ASLB 840306 & 21 verbal orders & 840316 written order & request for hearing
ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth DSB 415 84/03/28 4pp 26322 229 24X Fiche 50-352, 84/03/28, 8408310096

8408280491 Suppl to RL Anthony & Friends of the Earth motion vs applicant motion for partial decision & low power license & submission of 840518 contentions on new matter
ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth. DSB 358 84/05/30 Atomic Safety and Licensing Board Panel 2pp. 26280:336 24X Fiche 50-352, 84/05/30, 8408280491

8408160112 Forwards intervenor Exhibits 3, 4, 47-135 & 136 Related correspondence.
RILEY, S L Taylor Associates 84/05/31 PLEASANT, E
Administrative & Logistical Support Branch 1p 26126:325. 24X
Fiche 50-352, 84/05/31, 8408160112

8408160099 Forwards applicant Exhibits 137-151 Related correspondence
RILEY, S L Taylor Associates 84/06/08 PLEASANT, E
Administrative & Logistical Support Branch 1p 26126 328 24X
Fiche 50-352, 84/06/08, 8408160099

8408160103 Forwards NRC staff Exhibit 29 & intervenor Exhibits 1 & 2
Related correspondence
RILEY, S L Taylor Associates 84/06/15 PLEASANT, E
Administrative & Logistical Support Branch 1p 26126 327 24X
Fiche 50-352, 84/06/15, 8408160103

8408160079 Forwards applicant Exhibits 153-173 Related correspondence
RILEY, S L Taylor Associates 84/06/26 PLEASANT, E
Administrative & Logistical Support Branch 1p 26126 346 24X
Fiche 50-352, 84/06/26, 8408160079

8408010223 Forwards suppl to 840523 ltr to ASLB & ASLAB re NRC duties concerning supplemental water Related correspondence
SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware Unlimited, Inc DSB 659 84/07/13 PALLADINO, N Commissioners
2pp. 25856 022 24X Fiche 50-352, 84/07/13, 8408010223

--8408010228 Submits followup to 840523 & 0705 ltrs re position that NRC exhibits pro-applicant bias Position based on Denton 840629 ltr & util 840417 notes Board action requested W/o encls
SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware Unlimited, Inc 84/07/13 BRENNER, L , COLE, R F , MORRIS, P A Atomic Safety and Licensing Board Panel 2pp. 25856 024 24X Fiche 50-352, 84/07/13, 8408010223

8408010233 Response to NRC response to Air & Water Pollution Patrol 840626 contention re gross alpha W/svc list
ROMANO, F R Air and Water Pollution Patrol DSB 658 84/07/25
4pp 25856 014 24X Fiche 50-352, 84/07/25, 8408010233

8408060179 Informs that borough participated in 840725 evacuation drill per Mayor recommendation Drill not sanctioned by borough council & evacuation per Draft 5 of emergency evacuation plans disapproved Served on 840803
AUGUST, B K Phoenixville, PA DSB 735 84/07/25 BRENNER Atomic Safety and Licensing Board Panel 2pp 25932 183 24X
Fiche 50-352, 84/07/25, 8408060179

8408010248 Forwards suppl to 840523 ltr to ASLB & ASLAB re NRC duties concerning supplemental water Certificate of Svc encl
Related correspondence
SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware Unlimited, Inc DSB 663 84/07/26 PALLADINO, N Commissioners
2pp 25855 341 24X Fiche 50-352, 84/07/26, 8408010248.

8408010190 Errata to 840726 proposed findings of fact & conclusions of law on Limerick Ecology Action Contentions DES-1, DES-2, DES-3 & DES-4 Proposed transcript corrections & Certificate of Svc encl
ELLIOTT, C W Limerick Ecology Action DSB 680 84/07/27 5pp
25855-163 24X Fiche 50-352, 84/07/27, 8408010190

8408010255 Answer to Consumer Educ & Protective Assoc 840717 safety contentions Contentions lack basis, concern ratemaking matters outside NRC jurisdiction & should be denied Certificate of Svc encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn DSB 670 84/07/27 Atomic Safety and Licensing Board Panel 9pp 25854 315 24X Fiche 50-352, 84/07/27, 8408010255

8408020047 Forwards JL Patton 840723 ltr responding to RC Claypool 840607 ltr to Thornburgh re resources for radiological emergency response planning. Related correspondence
FERKIN, Z Q Pennsylvania, Commonwealth of, DSB 704 84/07/27.
BRENNER, L , COLE, R F , MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 25883 273 24X Fiche 50-352, 84/07/27, 8408020047

8408070302 Response to Consumer Educ & Protective Assoc (CEPA) safety contentions received on 840716 CEPA contentions provide inadequate basis for concerns & should not be admitted Certificate of Svc encl
WRIGHT, N A Hearing Branch 2 DSB 807 84/07/31 Atomic Safety and Licensing Board Panel 9pp 25947:231 24X
Fiche 50-352, 84/07/31, 8408070302

8408080191 Appeal to Commission from ASLAB 840723 Memorandum & Order ALAB-778 re contentions on nuclear fuel. Immediate stay requested W/svc list.
ANTHONY, R L Anthony, R L. ANTHONY, R L Friends of the Earth, DSB 835 84/07/31 2pp. 25960 257 24X Fiche 50-352, 84/07/31, 8408080191

8408060053 First set of interrogatories & request for production of documents to city of Philadelphia re offsite emergency planning Contentions City-18 & City-19 Certificate of Svc encl Related correspondence
RADER, R M Philadelphia Electric Co RADER, R M Conner & Wetterhahn DSB 743 84/08/01 Philadelphia, PA 12pp
25933 197 24X Fiche 50-352, 84/08/01, 8408060053

8408060170 Second errata to 840726 proposed findings of fact & conclusions of law on Limerick Ecology Action Contentions DES-1, DES-2, DES-3 & DES-4 Certificate of Svc encl
ELLIOTT, C W Limerick Ecology Action DSB 742 84/08/01 3pp
25932 194 24X Fiche 50-352, 84/08/01, 8408060170

8408060182 Confirms points discussed in 840727 telcon, agreements reached & matters in dispute re Limerick Ecology Action answers to Applicant first set of interrogatories & request for production of documents Related correspondence
RADER, R M Conner & Wetterhahn DSB 745 84/08/01 MULLIGAN, M
Limerick Ecology Action 8pp 25932 175 24X Fiche 50-352, 84/08/01, 8408060182

8408060228 Forwards applicant 840727 answer to CEPA safety contentions W/o encl Related correspondence
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co DSB 744 84/08/01 HERSHEY, S P CEPA HERSHEY, S P
Hershey, S P 1p 25933 335 24X Fiche 50-352, 84/08/01, 8408060228

8408070350 Discusses RJ Sugarman correspondence & concerns re ex parte communications Matters raised by RJ Sugarman w/o merit & will be addressed formally by director in decision per 10CFR2 206 Related correspondence
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co DSB 777 84/08/02 CHILK, S J Office of the Secretary of the Commission 3pp 25944 167 24X Fiche 50-352, 84/08/02, 8408070350

8408070363 Motion to compel answers to first set of interrogatories, to compel production of withheld documents & for related relief re destroyed documents Certificate of Svc encl Related correspondence
RADER, R M Philadelphia Electric Co RADER, R M Conner & Wetterhahn DSB 780 84/08/02 Atomic Safety and Licensing Board Panel 16pp 25945 158 24X Fiche 50-352, 84/08/02, 8408070363

8408070366 Transmittal of VS Boyer 840802 affidavit re schedule for fuel loading, per ASLB 840620 order Certificate of Svc encl Related correspondence
WETTERHAHN, M J Philadelphia Electric Co DSB 781 84/08/02 6pp
25945.152 24X Fiche 50-352, 84/08/02, 8408070366

8408070412 Forwards answer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions (Discovery 39) Related correspondence
RADER, R M Conner & Wetterhahn RADER, R M Philadelphia Electric Co DSB 782 84/08/02 MULLIGAN, M Limerick Ecology Action 1p
25942 053 24X Fiche 50-352, 84/08/02, 8408070412

--8408070415 Answer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions (Discovery 39) Certificate of Svc encl
* Philadelphia Electric Co 84/07/31 Limerick Ecology Action
91pp 25942 054 24X Fiche 50-352, 84/08/02, 8408070412

8408070287 Forwards signature page of 840802 motion to compel answers to first set of interrogatories, to compel production of withheld documents & for related relief re destroyed documents
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co DSB 803 84/08/03 Docketing & Services Branch 1p
25948 218 24X Fiche 50-352, 84/08/03, 8408070287

--8408070291 Signature page of 840802 motion to compel answers to first set of interrogatories
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 84/08/02 Atomic Safety and Licensing Board Panel
1p 25948 219 24X Fiche 50-352, 84/08/03, 8408070287

8408070429 Forwards VS Boyer 840802 affidavit re schedule for fuel loading Related correspondence
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co DSB 802 84/08/03 Docketing & Services Branch
1p. 25940 049 24X Fiche 50-352, 84/08/03, 8408070429

--8408070433 Affidavit of VS Boyer re schedule for fuel loading
BOYER, V S Philadelphia Electric Co 84/08/02 2pp 25940 050
24X Fiche 50-352, 84/08/03, 8408070429

8408090226 Forwards motion before ASLAB to set aside partial initial decision based on new evidence
SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware Unlimited, Inc DSB 858 84/08/03 Office of the Secretary of the Commission 1p 25971 114 24X Fiche 50-352, 84/08/03, 8408090226

--8408090233 Motion to set aside partial initial decision based on new evidence & circumstances Certificate of Svc encl
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman & Denworth 84/07/31 Atomic Safety and Licensing Appeal Panel 52pp 25971 115 24X Fiche 50-352, 84/08/03, 8408090226

8408070372 Reply to City of Philadelphia & Limerick Ecology Action 840726 proposed findings of fact & conclusions of law re severe accident risk assessment contentions Certificate of Svc encl
WETTERHAHN, M J , NICHOLS, N N Philadelphia Electric Co
WETTERHAHN, M J Conner & Wetterhahn DSB 795 84/08/06 29pp 25944 170 24X Fiche 50-352, 84/08/06, 8408070372

8408070444 Forwards answer to Limerick Ecology Action second set of interrogatories & request for production of documents re admitted offsite emergency planning contentions Encl replaces 840802 answers Related correspondence
RADER, R M Conner & Wetterhahn RADER, R M Philadelphia Electric Co DSB 789 84/08/06 MULLIGAN, M Limerick Ecology Action 1p 25942 268 24X Fiche 50-352, 84/08/06, 8408070444

--8408070450 Revised answer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions
BOYER, V S Philadelphia Electric Co 84/08/03 Limerick Ecology Action 88pp 25942 269 24X Fiche 50-352, 84/08/06, 8408070444

8408070495 Informs that applicant does not intend to respond to Sugarman 840713 ltr purporting to update earlier ltrs of 840523 & 0605 to ASLAB & ASLB or to any future ltrs to ASLAB or ASLB Related correspondence
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co DSB 794 84/08/06 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 2pp 25941 191 24X
Fiche 50-352, 84/08/06, 8408070495

8408090197 Reply to Limerick Ecology Action & City of Philadelphia proposed findings of fact & conclusions of law re severe accident risk assessment contentions
VOGLER, B H , HODGDON, A P Hearing Branch 2 DSB 871 84/08/06
Atomic Safety and Licensing Board Panel 14pp 25972 001 24X
Fiche 50-352, 84/08/06, 8408090197

--8408090205 Proposed corrections to transcript of hearings on Limerick Ecology Action DCS contentions & City of Philadelphia Contentions 13, 14 & 15 Certificate of Svc encl
* Hearing Branch 2 84/08/06 Atomic Safety and Licensing Board Panel 13pp 25972 015 24X Fiche 50-352, 84/08/06, 8408090197

8408090258 Forwards supplemental info re interrogatories, per util 840727 phone call & 840801 ltr Related correspondence
MULLIGAN, M Limerick Ecology Action DSB 859 84/08/06 RADER
Philadelphia Electric Co 7pp 25972 114 24X
Fiche 50-352, 84/08/06, 8408090258

--8408090263 Amended answers to util first set of interrogatories re offsite emergency planning Contention LEA/FOE 24 Certificate of Svc encl
ANTHONY, R L Anthony, R L 84/07/23 Philadelphia Electric Co 6pp 25972 121 24X Fiche 50-352, 84/08/06, 8408090258

8408080399 Joint rept of parties on schedule proposal for offsite emergency planning matters filed in response to 840723 order Certificate of Svc encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn DSB 837 84/08/07 Atomic Safety and Licensing Board Panel 14pp 25974 087 24X Fiche 50-352, 84/08/07, 8408080399

8408080404 Motion to strike Air & Water Pollution Patrol (AWPP) pleading & reply to AWPP motion re Contention VI-1 Motion filed late & w/o basis Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn DSB 838 84/08/07 Atomic Safety and Licensing Board Panel 7pp 25974 080 24X Fiche 50-352, 84/08/07, 8408080404

8408090238 Forwards NRC 840727 Amend 1 to License SNM-1926 & SER in support of amend Related correspondence
VOGLER, B H Hearing Branch 4 DSB 872 84/08/07 BRENNER, L ,
MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 14pp. 25972 152 24X Fiche 50-352, 84/08/07, 8408090238

8408130368 Replies to 840705 ltr re 840523 ltr to Chairman Palladino All encls to ltr possibly not included to all recipients Comments on encls inconsistent w/practice followed for some time w/o objection
SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware Unlimited, Inc DSB 897 84/08/07 MALSCH, M G Office of the General Counsel 1p 26011 127 24X Fiche 50-352, 84/08/07, 8408130368

8408140450 Forwards new contention re evacuation
ROMANO, F R Air and Water Pollution Patrol DSB 015 84/08/08
Atomic Safety and Licensing Board Panel 6pp 26061-001 24X
Fiche 50-352, 84/08/08, 8408140450

--8408140452 New contention that applicant must provide fully testable & capable emergency evacuation plan prior to receipt of OL
ROMANO, F R Air and Water Pollution Patrol 84/08/08 Atomic Safety and Licensing Board Panel 5pp 26061 092 24X
Fiche 50-352, 84/08/08, 8408140450

8408130158 Order establishing filing date of 840806 for motion to set aside based on new evidence received on 840809 Motion & ltr bear postmark date of 840806 Served on 840810
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel DSB 928
84/08/09 Del-Aware Unlimited, Inc 2pp 26007 352 24X
Fiche 50-352, 84/08/09, 8408130158

8408140484 Forwards amended Certificate of Svc of appellant motion to set aside based on new evidence Amend reflects svc of motion on 840806
LOCKE, R T Sugarman & Denworth LOCKE, R T Del-Aware Unlimited, Inc DSB 013 84/08/09 KOHL, C N , EDLES, G , GOTCHY, R L Atomic Safety and Licensing Board Panel 3pp 26060 276 24X
Fiche 50-352, 84/08/09, 8408140484

8408140540 Reply to applicant & staff answers to CEPA safety contentions Contentions should be admitted Certificate of Svc encl
HERSHEY, S P CEPA DSB 027 84/08/09 Atomic Safety and Licensing Board Panel 7pp 26061 220 24X Fiche 50-352, 84/08/09, 8408140540

8408150404 Forwards correspondence & documents between applicant, staff, Commonwealth of PA & responsible govt agencies re emergency planning Related correspondence
CULLEN, E J Philadelphia Electric Co. DSB 064 84/08/10
MULLIGAN, M Limerick Ecology Action 24pp 26068 196 24X
Fiche 50-352, 84/08/10, 8408150404

8408150477 Responds to 840806 ltr forwarding Limerick Ecology Action supplemental responses to applicant discovery requests Supplemental answers addressed individually Related correspondence
RADER, R M Conner & Wetterhahn RADER, R M Philadelphia Electric Co DSB 062 84/08/10 MULLIGAN, M Limerick Ecology Action 4pp 26068 160 24X Fiche 50-352, 84/08/10, 8408150477

8408150183 Order approving proposed transcript corrections as listed Served on 840814
BRENNER, L Atomic Safety and Licensing Board Panel DSB 049
84/08/13 2pp 26066 245 24X Fiche 50-352, 84/08/13, 8408150183

8408150387 Answer in opposition to Friends of the Earth 840731 petition for review of ALAB-778 No substantial conflict between ASLB & ASLAB presented Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn DSB 061 84/08/13 Commissioners 10pp 26068 285
24X Fiche. 50-352, 84/08/13, 8408150387

8408170381 Forwards supplemental info re Limerick Ecology Action 840806 response to util discovery request on admitted offsite emergency planning contentions Certificate of Svc encl
MULLIGAN, M Limerick Ecology Action DSB 102 84/08/13 RADER
Philadelphia Electric Co 280pp 26137 181 24X
Fiche 50-352, 84/08/13, 8408170381

8408200433 Forwards response to applicant motion re Contention VI-I & further support for reopening Contention VI-I re welding & welding insp infractions
ROMANO, F R Air and Water Pollution Patrol DSB 164 84/08/14
1p 26136 292 24X Fiche 50-352, 84/08/14, 8408200433

--8408200442 Response to applicant motion to strike Air & Water Pollution Patrol (AWPP) pleading & reply to AWPP motion re Contention VI-I Contention VI-I must be litigated
ROMANO, F R Air and Water Pollution Patrol 84/08/10 Atomic Safety and Licensing Board Panel 1p. 26136 293 24X
Fiche 50-352, 84/08/14, 8408200433

--8408200447 Further support for reopening Contention VI-I re welding & welding insp infractions Air & Water Pollution Patrol calls for full-scale reinsp re lack of fusion & Broomstick Affair revelations
ROMANO,F R Air and Water Pollution Patrol 84/08/13 Atomic Safety and Licensing Board Panel 2pp 26136 294 24X Fiche 50-352,84/08/14,8408200433

8408150425 Response opposing Friends of the Earth & R Anthony 840731 petition for review & request for stay of ALAB-778 Motion fails to establish existence of important issues of fact,law or policy & should be denied Certificate of Svc encl
VOLGER,B H , WRIGHT,N A Hearing Branch 2 DSB 067 84/08/15 Commissioners 15pp 26068 220 24X Fiche 50-352,84/08/15, 8408150425

8408170305 Order establishing schedule for admitted offsite emergency planning issues Schedule for deferred contentions will be established Courtesy notification encl Served on 840816
BRENNER,L Atomic Safety and Licensing Board Panel DSB 095 84/08/15 Office of the Executive Legal Director 6pp 26115 246 24X Fiche 50-352,84/08/15,8408170305

8408200286 Forwards correspondence & documents among NRC, applicant & Commonwealth of PA re emergency planning, per ASLB 820601 order Matl suppls 840810,0712 & 30 submittals Related correspondence
CULLEN,E J Philadelphia Electric Co DSB 142 84/08/15
MULLIGAN,M Limerick Ecology Action 50pp 26131 085 24X
Fiche 50-352,84/08/15,8408200286

8408210341 Forwards order establishing schedule for offsite emergency planning issues W/o encl Related correspondence
VOGLER,B H Hearing Branch 2 DSB 186 84/08/16 PERRY,S
Federal Emergency Management Agency 2pp 26179 361 24X
Fiche 50-352,84/08/16,8408210341

8408220354 New info contention re health hazard via polyvinyl chloride fill used in reactor cooling towers W/svc list
ROMANO,F R Air and Water Pollution Patrol DSB 196 84/08/16
Atomic Safety and Licensing Board Panel 4pp 26189 318 24X
Fiche 50-352,84/08/16,8408220354

8408220379 Informs of errors in City of Philadelphia record citations re statement of NRC witness Acharya Also forwards Commonwealth of PA Public Utility Commission 840807 order to show cause Related correspondence
BUSH,M W Philadelphia, PA DSB 199 84/08/16 BRENNER,L Atomic Safety and Licensing Board Panel 5pp 26191 349 24X
Fiche 50-352,84/08/16,8408220379

8408240240 Provides addendum to Air & Water Pollution Patrol 840816 new info contention re polyvinyl chloride Fifth criterion re breakdown of polyvinyl chloride inadvertantly omitted Small delay in proceedings ack for large public good
ROMANO,F R Air and Water Pollution Patrol DSB 271 84/08/20
Atomic Safety and Licensing Board Panel 1p 26222 361 24X
Fiche 50-352,84/08/20,8408240240

8408240262 Forwards correspondence & documents among applicant,NRC & other parties re emergency planning Documents suppl matl forwarded in 840815 ltr & provide addl correspondence dtd 840611-0808 Related correspondence
CULLEN,E J Philadelphia Electric Co DSB 264 84/08/20
MULLIGAN,M Limerick Ecology Action 652pp 26223 214 24X
Fiche 50-352,84/08/20,8408240262

8408240236 Answer opposing late-filed Air & Water Pollution Patrol 840808 new contention re evacuation Contention lacks basis & specificity & fails to show good cause for late filing Certificate of Svc encl
CONNER,T B Philadelphia Electric Co CONNER,T B Conner & Wetterhahn DSB 269, 84/08/21, Atomic Safety and Licensing Board Panel 18pp. 26222.259 24X Fiche 50-352,84/08/21,8408240236

8408240241 Answer opposing Del-Aware Unlimited,Inc 840806 motion to set aside ASLB 830308 partial initial decision re supplementary cooling water sys;based on new evidence Motion should be denied Certificate of Svc encl
CONNER,T B Philadelphia Electric Co CONNER,T B Conner & Wetterhahn DSB 270 84/08/21 Atomic Safety and Licensing Appeal Panel 46pp 26223 066 24X Fiche 50-352,84/08/21, 8408240241

8408240256 Forwards util comments on Del-Aware request under 10CFR2 206,per 840523 & 0713 requests for relief Matters repetitions & inappropriate under 10CFR2 206 & fail to raise significant environ concern
CONNER,T B Conner & Wetterhahn CONNER,T B Philadelphia Electric Co 84/08/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 17pp 26223 001 24X Fiche 50-352,84/08/21,8408240256

8408230200 Memorandun & order denying Citizens Action in Northeast 840625 & Consumers Educ & Protective Assoc 840716 motions to admit or certify financial qualifications contentions Served on 840822
BRENNER,L Atomic Safety and Licensing Board Panel DSB 254
84/08/22 Office of the Executive Legal Director 11pp
26209 198 24X Fiche 50-352,84/08/22,8408230200

8408280415 Motion for reconsideration of ASLB 840815 order establishing schedule for offsite emergency planning issues FEMA should not be required to distribute draft rept by 840901 Certificate of Svc encl
VOGLER,B H , WRIGHT,N A Hearing Branch 2 DSB 344 84/08/23
Atomic Safety and Licensing Board Panel 4pp 26280 290 24X
Fiche 50-352,84/08/23,8408280415

8408280162 Memorandum & order rejecting Friends of the Earth & Air & Water Pollution Patrol (AWPP) late-filed contentions & denying AWPP second request for reconsideration of asbestos contention Courtesy notification encl Served on 840827
BRENNER,L Atomic Safety and Licensing Board Panel DSB 326
84/08/24 Friends of the Earth 27pp 26275 116 24X
Fiche 50-352,84/08/24,8408280162

8408280388 Confirms 840824 telcon informing of 840830 meeting in Philadelphia,PA to discuss matters covered by ASLB scheduling order Related correspondence
RADER,R M Conner & Wetterhahn RADER,R M Philadelphia Electric Co DSB 354 84/08/24 VOGLER,B H Hearing Branch 2 FERKIN,Z G Pennsylvania, Commonwealth of, SMOLLEN,H Philadelphia, PA 2pp 26280 032 24X Fiche 50-352,84/08/24,8408280388

8408280237 Order extending time until 840921 for Commission to act to review ALAB-778 Served on 840827
CHILK,S J Office of the Secretary of the Commission DSB 319
84/08/27 Commissioners 1p 26262 278 24X
Fiche 50-352,84/08/27,8408280237

8408300170 Response opposing Del-Aware 840806 motion to set aside ASLB 830308 partial initial decision on environ effects of supplemental cooling water sys based on new evidence Certificate of Svc encl
VOGLER,B H Hearing Branch 2 DSB 381 84/08/27 Atomic Safety and Licensing Appeal Panel 23pp 26305 320 24X
Fiche 50-352,84/08/27,8408300170

8408300119 Response opposing admission of Air & Water Pollution Patrol 840808 new contention re evacuation, filed by FR Romano Certificate of Svc encl
WRIGHT,N A Hearing Branch 2 DSB 379 84/08/28 Atomic Safety and Licensing Board Panel 12pp 26305 171 24X
Fiche 50-352,84/08/28,8408300119

8408300168 Second Partial Initial Decision LBP-84-31 on listed issues in controversy in favor of applicant Courtesy notification encl Served on 840829
BRENNER,L , COLE,R F , MORRIS,P A Atomic Safety and Licensing Board Panel DSB 386 84/08/29 325pp 26303 158 24X
Fiche 50-352,84/08/29,8408300168

8408310223 Response opposing Air & Water Pollution Patrol 840814 pleading on reopening Contention VI-1 re welding & welding insp infractions Certificate of Svc encl
WETTERHAHN,M J Philadelphia Electric Co WETTERHAHN,M J Conner & Wetterhahn DSB 423 84/08/29 Atomic Safety and Licensing Board Panel 8pp 26319 244 24X Fiche 50-352,84/08/29,8408310223

K Utility Final Safety Analysis Report (FSAR) & amends

8408020058 Forwards Rev 34 to FSAR
BRADLEY,E J Philadelphia Electric Co 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25904 001
24X Fiche 50-352,84/07/31,8408020058

--8408020084 Rev 34 to FSAR
* Philadelphia Electric Co 84/07/31 272pp 25904 014 24X
Fiche 50-352,84/07/31,8408020058

8408210076 Forwards Affidavit of Svc certifying distribution of Rev 34 to FSAR & Rev 19 to environ rept on 840809
BRADLEY,E J Philadelphia Electric Co 84/08/14 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 26184 327
24X Fiche 50-352,84/08/14,8408210076

M Antitrust correspondence

8408020136 Forwards FR notice of finding of no significant antitrust changes & time for filing requests for reevaluation
REGAN,W H Siting Analysis Branch 84/07/20 STUCKY,S W
Docketing & Services Branch 3pp 25898 095 24X
Fiche 50-352,84/07/20,8408020136

Q Inspection reports, IE Bulletins & correspondence

8408080523 Forwards IE Insp Rept 50-352/84-25 on 840516-25 & 30 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/07/17
KEMPER, J S Philadelphia Electric Co 2pp 25975 277 24X
Fiche 50-352, 84/07/17, 8408080523

--8408080526 Notice of violation from insp on 840516-25 & 30
* Region 1, Office of Director 84/07/17 1p 25975 279 24X
Fiche 50-352, 84/07/17, 8408080523

--8408080530 IE Insp Rept 50-352/84-25 on 840516-25 & 30 Violation noted failure to place jurisdictional & boundary tags on RHR svc water sys turned over for startup
BRIGGS, L E , OREGG, H , DETTENHAUSEN, L Region 1, Office of Director 84/07/13 8pp 25975 280 24X Fiche 50-352, 84/07/17, 8408080523

8408310124 Forwards response to NRC 840620 ltr re violations noted in Insp Repts 50-352/84-24 & 50-353/84-08 on 840501-31 Seismic classifications of three piping isometric drawings & four piping field sketches corrected Related correspondence
KEMPER, J S Philadelphia Electric Co DSB 002 84/07/19
MURLEY, T E Region 1, Office of Director 4pp 26392 028 24X
Fiche 50-352, 84/07/19, 8408310124

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408210368 Forwards IE Insp Repts 50-352/84-26 & 50-353/84-09 on 840601-30 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/08/02
KEMPER, J S Philadelphia Electric Co 2pp 26183 109 24X
Fiche 50-352, 84/08/02, 8408210368

--8408210373 Notice of violation from insp on 840601-30
* Region 1, Office of Director 84/08/02 4pp 26183 111 24X
Fiche 50-352, 84/08/02, 8408210368

--8408210381 IE Insp Repts 50-352/84-26 & 50-353/84-09 on 840601-30 Violations identified inadequate diesel generator test program implementation & inadequate calibr procedure for valve position indicating sys
CHAUDHARY, S K , WIGGINS, J T , BAUNACK, W Region 1, Office of Director 84/07/24 19pp 26183 115 24X Fiche 50-352, 84/08/02, 8408210368

--8408210394 Responds to NRC 840321 ltr re violations noted in IE Insp Repts 50-352/84-19 & 50-353/84-06 Corrective actions notice issued to include info on P&ID M-42 & Procedure GADP-27 1 revised
GALLAGHER, J W Philadelphia Electric Co 84/06/20 MURLEY, T E
Region 1, Office of Director 5pp 26183 130 24X
Fiche 50-352, 84/08/02, 8408210368

8408100028 Discusses concerns expressed in IE Insp Rept 50-352/84-29 on timely resolution of NDE van insp findings re lack of fusion indications on pipe welds identified during ASME Code, Section XI preservice exams
MARTIN, T T Division of Engineering & Technical Programs 84/08/03
KEMPER, J S Philadelphia Electric Co 4pp 25989 045 24X
Fiche 50-352, 84/08/03, 8408100028

8408230153 Forwards IE Insp Rept 50-352/84-35 on 840702-03 & 05-06 No violations noted
MARTIN, T T Region 1, Office of Director 84/08/03 KEMPER, J S
Philadelphia Electric Co 4pp 26214 047 24X
Fiche 50-352, 84/08/03, 8408230153

--8408230157 IE Insp Rept 50-352/84-35 on 840702-03 & 05-06 No violations noted Major areas inspected chemistry, radioactive effluent control & radiation protection programs
MILLER, M T , KOTTAN, J J , CARSON, B H Region 1, Office of Director 84/08/03 6pp 26214 051 24X Fiche 50-352, 84/08/03, 8408230153

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408130296 Forwards relief requests from ASME Code, Section XI preservice insp requirements to resolve SER Confirmatory Issue 12
KEMPER, J S Philadelphia Electric Co 84/08/07 SCHWENCER, A
Licensing Branch 2 7pp 26008 349 24X Fiche 50-352, 84/08/07, 8408130296

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
ORACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408210420 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-352/84-16
MARTIN, T T Division of Engineering & Technical Programs 84/08/14
KEMPER, J S Philadelphia Electric Co 4pp 26177 248 24X
Fiche 50-352, 84/08/14, 8408210420

--8408210429 Responds to NRC 840604 ltr re violations noted in IE Insp Rept 50-352/84-16 Corrective actions min requirements needed to start diesel generator documented in checklist for appropriate plant operating personnel
KEMPER, J Philadelphia Electric Co 84/07/09 MURLEY, T E
Region 1, Office of Director 3pp 26177 252 24X
Fiche. 50-352, 84/08/14, 8408210420

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408310417 Responds to Insp Rept 50-352/84-25 Corrective actions, sys startup engineer walked down equipment within boundaries of RHR svc water sys turnover 1-16A-1(F) & assured valves, instruments & components tagged Related correspondence
CODNEY, M J Philadelphia Electric Co DSB 289 84/08/16
MARTIN, T T Division of Engineering & Technical Programs 3pp
26350 218 24X Fiche 50-352, 84/08/16, 8408310417

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001, 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122, 24X Fiche 50-000, 84/08/17, 8408140208

8408310058 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Strong GE & Bechtel quality programs provide homogeneous network of vendor surveillance scrutiny No fraudulent products in use
KEMPER, J S Philadelphia Electric Co 84/08/17 MURLEY, T E
Region 1, Office of Director 2pp 26323 204 24X
Fiche 50-352, 84/08/17, 8408310058

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche. 50-000, 84/08/21, 8408210142

8408240013 Confirms 840824 telcon re 840827-31 insp concerning siesmic design of structures, pipe break analysis & south stack blast load calculations
ZECH, G G, Vendor Program Branch 84/08/21, STRATTON, C D Bechtel Corp, 1p 26228, 248 24X Fiche. 50-352, 84/08/21, 8408240013,

8408270376 Forwards addl info re SER Confirmatory Issue 12 concerning preservice insp program, per 840817 request
KEMPER, J S Philadelphia Electric Co 84/08/23 SCHWENCER, A
Licensing Branch 3 62pp 26240 258 24X Fiche 50-352, 84/08/23, 8408270376

8408150619 Notification of Licensee Meeting 84-299 on 840809 in King of Prussia, PA to resolve preservice exam findings
DURR, J P Region 1, Office of Director 84/08/31 Region 1, Office of Director 1p 26102 358 24X Fiche 50-352, 84/08/31, 8408150619

R Periodic operating reports & related correspondence

8408060419 Forwards fourth status rept re independent design review of core spray sys for 840701-15 Related correspondence
CARPENTER, F D Torrey Pines Technology DSB 719 84/07/16
BOYER, V S Philadelphia Electric Co 7pp 25951 123 24X
Fiche 50-352, 84/07/16, 8408060419

8408310023 Forwards "Independent Design Review of Limerick Generating Station 1 Core Spray Sys, Bi-Monthly Status Rept 5 for Period Ending 840731 " Related correspondence
CARPENTER, F D Torrey Pines Technology DSB 234 84/08/01
BOYER, V S Philadelphia Electric Co 7pp 26350 102 24X
Fiche 50-352, 84/08/01, 8408310023

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408240332 Submits annotated requests for followup on potentially generic problem in encl Part 21 rept from Basler Electric re SCRs on nuclear exciters mounted w/too much pressure
NORELIUS, C E Division of Project & Resident Programs 84/04/25
JORDAN, E L Director's Office, Office of Inspection and Enforcement 1p 26225 303 24X Fiche 50-000, 84/04/25, 8408240332

8408200307 Suppl 7 to Part 21 rept re possible thermostatic valve malfunction fail safe to full cooling position Lower overrun assemblies in Robertshau valves installed on diesel generator sets replaced w/cotter pins to lock nut to stem
MORIARTY, J M Colt Industries, Inc 84/08/08 KEPPLER, J G Region 3, Office of Director 1p 26133 017 24X Fiche 50-352, 84/08/08, 8408200307

8408310110 Significant Deficiency Rept 148 re design calculations made by WJ Woolley Co for doors specified to meet tornado-generated missile criteria Door reanalysis underway
Previously reported under Part 21 by WJ Woolley Co
KEMPER, J S Philadelphia Electric Co 84/08/23 MURLEY, T E
Region 1, Office of Director 1p 26322 239 24X
Fiche 50-352, 84/08/23, 8408310110

T Hearing transcripts on non-antitrust matters

8408090205 Proposed corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13, 14 & 15 Certificate of Svc encl
* Hearing Branch 2 84/08/06 Atomic Safety and Licensing Board Panel 13pp 25972, 015 24X Fiche 50-352, 84/08/06, 8408090197

8408090229 Forwards dated & signed copy of Page 11 of proposed corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13, 14 & 15
VOGLER, B H Hearing Branch 2 DSB 867 84/08/07. BRENNER, L , MORRIS, P A , COLE, R F. Atomic Safety and Licensing Board Panel 2pp. 25971 167 24X Fiche 50-352, 84/08/07, 8408090229

8408090236 Executed Page 11 of corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13, 14 & 15.
VOGLER, B H , HODGDON, A P Hearing Branch 2 84/08/06 1p 25971 169 24X Fiche 50-352, 84/08/07, 8408090229

8408240254 Proposed corrections to transcript of evidentiary hearings on NEPA severe accident contentions. Certificate of Svc encl
WETTERHAHN, M J , NICHOLS, N N Philadelphia Electric Co
WETTERHAHN, M J Conner & Wetterhahn DSB 268 84/08/21 5pp
26222 350. 24X Fiche: 50-352, 84/08/21, 8408240254

U Congressional/Executive Correspondence

8408170094 Responds to 840712 ltr re 840502 Pottstown Mercury article & related petition Low level normal operation releases expected to be well within recognized safety limits Excerpts from DES encl
DIRCKS, W J Office of the Executive Director for Operations
84/08/08 WALKER, R S House of Rep 1p 26135 322 24X
Fiche 50-352, 84/08/08, 8408170094

8408200449 Responds to 840712 request for consideration of constituent H Mayerson 840607 ltr w/840502 Pottstown Mercury article & encl petition Low level normal operation releases expected to be well within recognized safety limits
DIRCKS, W J Office of the Executive Director for Operations
84/08/08 WALKER, R S House of Rep 5pp 26182 313 24X
Fiche 50-352, 84/08/08, 8408200449

--8408200454 Forwards constituent H Mayerson 840607 ltr w/840502 Pottstown Mercury article, "Limerick to Release Very Small Amounts of Radioactivity" & petition & requests investigation of statements
WALKER, R S House of Rep 84/07/12 KAMMERER, C Office of Congressional Affairs 6pp 26182 332 24X Fiche 50-352, 84/08/08, 8408200449

V Operator Examinations

8408230258 Responds to 840531 request for operating shift staffing info Five-shift rotation, staffing schemes, qualifications & training programs encl
DALTROFF, S L Philadelphia Electric Co 84/08/21 EISENHUT, D G
Division of Licensing 45pp 26208 037 24X Fiche 50-352, 84/08/21, 8408230258

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

8408010199 Notification of 840731 meeting w/util in Pottstown, PA to discuss electrical separation criteria, based on Wyle Labs test results
MARTIN, R E Licensing Branch 2 84/07/23 SCHWENCER, A Licensing Branch 2 6pp 25873 280 24X Fiche 50-352, 84/07/23, 8408010199

8408080206 Notification of 840807 meeting w/util in Bethesda, MD to discuss outstanding items in detailed control room design review
MARTIN, R E Licensing Branch 2 84/07/26 SCHWENCER, A Licensing Branch 2 5pp 25978 329 24X Fiche 50-352, 84/07/26, 8408080206

8408020030 Forwards requested info on NUREG-0737, Item II F 1 re interim procedures for quantifying high level accidental radioactive releases Info re Item III D 1 1 will be furnished in Sept 1984
KEMPER, J S Philadelphia Electric Co 84/07/27 SCHWENCER, A
Licensing Branch 2 14pp 25883 218 24X Fiche 50-352, 84/07/27, 8408020030

8408060268 Notification of 840806 meeting w/util in Bethesda, MD to discuss applicant analysis of tornado missile effects on UHS Date changed
MARTIN, R E Licensing Branch 2 84/07/27 SCHWENCER, A Licensing Branch 2 1p 25950 302 24X Fiche 50-352, 84/07/27, 8408060268

--8408060273 Notifies of 840803 meeting w/util to discuss applicant 840322 analysis of tornado missile effects on UHS
SCHWENCER, A Licensing Branch 2 84/07/26 BAUER, E G
Philadelphia Electric Co 6pp 25950 303 24X
Fiche 50-352, 84/07/27, 8408060268

8408020058 Forwards Amend 68 to OL application, consisting of Rev 34 to FSAR (Category K), Rev 19 to environ rept - OL stage (Category C), Rev 9 to design assessment rept (DAR), Vols 1, 2 & 3 W/o Vol 2 DAR, Vol 3 withheld (ref 10CFR2 790)
BRADLEY, E J Philadelphia Electric Co 84/07/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25904 001
24X Fiche 50-352, 84/07/31, 8408020058

--8408020075 Amend 68 to OL application, consisting of Rev 34 to FSAR, Rev 19 to environ rept - OL stage & Rev 9 to design assessment rept (DAR), Vols 1 & 2 & proprietary Rev 9 to DAR, Vol 3 W/o Vol 2 DAR, Vol 3 withheld (ref 10CFR2 790)
BOYER, V S Philadelphia Electric Co 84/07/31 6pp 25904 004
24X Fiche 50-352, 84/07/31, 8408020058

--8408020090 Nonproprietary Rev 9 to Vol 1 of "Design Assessment Rept "
* Philadelphia Electric Co 84/07/31 9pp 25904 286 24X
Fiche 50-352, 84/07/31, 8408020058

8408220333 A REVIEW OF THE LIMERICK GENERATING STATION SEVERE ACCIDENT RISK ASSESSMENT Review of Core Melt Frequency
AZARM,M A , BARI,R A , BOCCIO,J L Brookhaven National Laboratory
FIN A-3393 NUREG/CR-3493 84/07/31 Division of Safety Technology 192pp Available at NRC $6 00 26200 205 24X
Fiche 50-352,84/07/31,8408220333

8408070033 Forwards revised FSAR pages reflecting increase of reactor encl design inleakage rate from 50 to 100% free vol/day & doubling standby gas treatment sys fan flow during draudoun of Unit 1 encl FSAR rev scheduled for Aug 1984
BRADLEY,E J Philadelphia Electric Co 84/08/02 SCHWENCER,A
Licensing Branch 2 39pp 25949 289 24X Fiche 50-352,84/08/02,
8408070033

8408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure
KEMPER,J S Philadelphia Electric Co 84/08/02 SCHWENCER,A
Licensing Branch 2 6pp 25949 329 24X Fiche 50-352,84/08/02,
8408070037

8408140334 Notification of 840814 meeting w/util in Bethesda,MD to discuss analysis of tornado missile effects on UHS
MARTIN,R E Licensing Branch 2 84/08/05 SCHWENCER,A Licensing Branch 2 4pp 26061 281 24X Fiche 50-352,84/08/05,8408140334

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408130317 Advises that Preoperational Test 100 3, "Mechanical Snubber Testing," will be deleted from preoperational test program, per 840716 & telcons Insp, exam & testing personnel will be qualified for snubber test per ANSI N45 2 6-1978
KEMPER,J S Philadelphia Electric Co 84/08/07 SCHWENCER,A
Licensing Branch 2 9pp 26010 329 24X Fiche 50-352,84/08/07,
8408130317

8408160477 Informs that all comments re risk evaluation rept received & incorporated into final version Rept ready for transmittal to applicant,ACRS & ASLB
EISENHUT,D G Division of Licensing 84/08/09 SPEIS,T NRC - No Detailed Affiliation Given 1p 26108 351 24X
Fiche 50-352,84/08/09,8408160477

8408210051 Notification of 840815 meeting w/util in Bethesda,MD to discuss further development of Tech Specs
MARTIN,R E Licensing Branch 2 84/08/14 SCHWENCER,A Licensing Branch 2 5pp 26175 171 24X Fiche 50-352,84/08/14,8408210051

8408210303 Forwards draft changes to FSAR,Section 15 7 4 & response to Request for Addl Info 410 37 re light loads/fuel handling accident Drop of object would not result in consequences in excess of revised fuel handling accident
KEMPER,J S Philadelphia Electric Co 84/08/14 SCHWENCER,A
Licensing Branch 2 28pp 26179 298 24X Fiche 50-352,84/08/14,
8408210303

8408220165 Forwards response to NRC 840716 request for addl info re offsite dose calculation manual & revised offsite dose calculation manual Related correspondence
KEMPER,J S Philadelphia Electric Co 84/08/15 SCHWENCER,A
Licensing Branch 2 7pp 26197 168 24X Fiche 50-352,84/08/15,
8408220165

--8408220168 Revised "Offsite Dose Calculation Manual "
Philadelphia Electric Co 84/08/10 41pp 26197 175 24X
Fiche 50-352,84/08/15,8408220165

8408210513 Forwards Wyle test rept, "Electrical Separation Verification Testing on Terminal Blocks & Panel Meters," raceway separation criteria & design analysis documenting separation criteria rationale
KEMPER,J S Philadelphia Electric Co 84/08/16 SCHWENCER,A
Licensing Branch 2 3pp 26178 254 24X Fiche 50-352,84/08/16,
8408210513,

--8408210518 "Test Rept on Electrical Separation Verification Testing on Terminal Blocks & Panel Meters for Limerick Generating Station Units 1 & 2 "
HAZELTINE,J , JOHNSON,P R , ROBERTS,W B Wyle Laboratories
46960-4 84/09/15 62pp 26178 257 24X Fiche 50-352,84/08/16,
8408210513

--8408210520 Rev 0 to "Raceway Separation Criteria " Raceway separation test program discussion encl
Philadelphia Electric Co 84/08/09 46pp 26178 316 24X
Fiche 50-352,84/08/16,8408210513

8408220119 Requests that License Condition 2 re fuel rod pressure limit be closed,based on recent resolution of generic issue between GE & NRC Evaluation demonstrates that bundles meet GE limit for fuel rod internal pressure
KEMPER,J S Philadelphia Electric Co 84/08/17 SCHWENCER,A
Licensing Branch 2 2pp 26193 307 24X Fiche 50-352,84/08/17,
8408220119

8408310012 Forwards response to Meteorological & Effluent Treatment Branch 840815 request for addl info re wide-range accident monitor calibr factors Related correspondence
KEMPER,J S Philadelphia Electric Co DSB 291 84/08/17
SCHWENCER,A Licensing Branch 2 3pp 26350 194 24X
Fiche 50-352,84/08/17,8408310012

8408310018 Requests that License Condition 2 re fuel rod pressure limit be closed,based on resolution of issue between GE & NRC Related correspondence
KEMPER,J S Philadelphia Electric Co DSB 292 84/08/17
SCHWENCER,A Licensing Branch 2 2pp 26350 192 24X
Fiche 50-352,84/08/17,8408310018

8408310007 Responds to 840206 ltr on SER License Condition 7 re compliance w/NUREG-0612,control of heavy loads,Phase II "Limerick Overhead Handling Sys Final Rept (Rev 3)" revised per 840206 request Related correspondence
KEMPER,J S Philadelphia Electric Co DSB 293 84/08/18
SCHWENCER,A Licensing Branch 2 3pp 26350 197 24X
Fiche 50-352,84/08/18,8408310007

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408220463 Board Notification 84-142 forwards R Starostecki 840731 memo re alleged inadequate design of reactor encl vent stack Stack has no or limited safety significance
NOVAK,T M Division of Licensing 84/08/20 BRENNER,L , COLE,R F , MORRIS,P A Atomic Safety and Licensing Board Panel. 2pp
26261 316 24X Fiche 50-352,84/08/20,8408220463

--8408280101 Informs that on 840710,NRC interviewed confidential alleger re concerns relative to response of reactor encl vent stacks to blast loads following railroad accident
STAROSTECKI,R Division of Project & Resident Programs 84/07/31
EISENHUT,D G Division of Licensing 1p 26261 318 24X
Fiche 50-352,84/08/20,8408220463

8408270161 Forwards revised response to Procedures & Sys Review Branch Question 430 72 re diesel oil storage tank lines to include addl info discussed in 840810 telcon
KEMPER,J S Philadelphia Electric Co 84/08/21 SCHWENCER,A
Licensing Branch 2 4pp 26245 259 24X Fiche 50-352,84/08/21,
8408270161

8408310413 Forwards revised response to Procedure & Sys Review Branch Question 430 72 re diesel oil storage tank vent lines,in response to 840810 request for addl info Related correspondence
KEMPER,J S Philadelphia Electric Co DSB 288 84/08/21
SCHWENCER,A Licensing Branch 2 4pp 26350 224 24X
Fiche 50-352,84/08/21,8408310413

8408280130 Forwards Rev 1 to "Solid Radwaste Sys Process Control Program," in response to Meteorological & Effluent Treatment Sys Branch request for addl info,per 840808 telcon Preoperational testing of sys scheduled for end of month
KEMPER,J S Philadelphia Electric Co 84/08/23 SCHWENCER,A
Licensing Branch 2 2pp 26259 064 24X Fiche 50-352,84/08/23,
8408280130

--8408280132 Rev 1 to "Solid Radwaste Sys Process Control Program "
Philadelphia Electric Co 84/08/31 11pp 26259 066 24X
Fiche 50-352,84/08/23,8408280130

8408310146 Forwards response to 840509 request for addl info re NUREG-0737,Item III D 1 1, "Primary Coolant Outside Containment " Info will be incorporated in Sept 1984 FSAR rev
KEMPER,J S Philadelphia Electric Co 84/08/24, SCHWENCER,A
Licensing Branch 2 9pp, 26322 208 24X Fiche 50-352,84/08/24,
8408310146

8408290158 REVIEW INSIGHTS ON THE PROBABILISTIC RISK ASSESSMENTS FOR THE LIMERICK GENERATING STATION,UNIT 1 AND 2
CHELLIAH,E Division of Safety Technology NUREG-1068 84/08/31
126pp Available at NRC $5 00 26309 151 24X
Fiche 50-352,84/08/31,8408290158

C Utility Environmental Report (ER), amends & correspondence

8408020058 Forwards Rev 19 to environ rept - OL stage
BRADLEY,E J Philadelphia Electric Co 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25904 001
24X Fiche 50-352,84/07/31,8408020058

--8408020080 Rev 19 to environ rept - OL stage
* Philadelphia Electric Co 84/07/31 4pp 25904 010 24X
Fiche 50-352,84/07/31,8408020058

8408210076 Forwards Affidavit of Svc certifying distribution of Rev 34 to FSAR & Rev 19 to environ rept on 840809
BRADLEY,E J Philadelphia Electric Co 84/08/14 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 26184 327
24X Fiche 50-352,84/08/14,8408210076

E NRC Safety Evaluation Report (SER), supplS & correspondence

8408060232 Forwards responses to questions & comments re 840322 analysis of tornado missile effects on UHS, supporting resolution of SER Open Issue 2 Responses do not affect results of prior analysis
KEMPER,J S Philadelphia Electric Co 84/07/27 SCHWENCER,A
Licensing Branch 2 19pp 25934 117 24X Fiche 50-352,84/07/27,
8408060232

8408070289 Informs that upgrading & mods to RCIC turbine assembly completed, except for installation of threaded taper pins, in response to SER Open Item 6 Justification for interim operation of Unit 1 encl
KEMPER,J S Philadelphia Electric Co 84/08/01 SCHWENCER,A
Licensing Branch 2 5pp 25948 220 24X Fiche 50-352,84/08/01,
8408070289

8408070513 Forwards info to support resolution of SER proposed License Conditions 8,9,10 & 12 & to assist in preparation of License Condition 14 Info withheld (ref 10CFR2 790 & 73 21)
Affidavit of withholding encl
KEMPER,J S Philadelphia Electric Co 84/08/01 SCHWENCER,A
Licensing Branch 2 5pp 25941 167 24X Fiche 50-352,84/08/01,
8408070513

8408130296 Forwards relief requests from ASME Code, Section XI preservice insp requirements to resolve SER Confirmatory Issue 12
KEMPER,J S Philadelphia Electric Co 84/08/07 SCHWENCER,A
Licensing Branch 2 7pp 26008 349 24X Fiche 50-352,84/08/07,
8408130296.

8408140303 Forwards responses to 840611 request for addl info re SER Confirmatory Issues 3,5 & 6 & SER Open Issue 29 Related draft FSAR & design assessment rept page changes also encl
KEMPER,J S Philadelphia Electric Co 84/08/08 SCHWENCER,A
Licensing Branch 2 27pp 26111 129 24X Fiche 50-352,84/08/08,
8408140303

--8408140314 "Spec for Test Requirements for Hot Deflection Testing of ASME Section III, Nuclear Class 1,2,3 & ANSI B31 1, Bechtel Piping, for Limerick Generating Station, Units 1 & 2 "
* Bechtel Corp 84/05/29 159pp 26111 156 24X
Fiche 50-352,84/08/08,8408140303

--8408140320 "Spec for Test Requirements for Steady State Vibration Testing of ASME Section III, Nuclear Class 1,2,3 & ANSI B31 1, Bechtel Piping, for Limerick Generating Station, Units 1 & 2 "
* Bechtel Corp 84/05/25 280pp 26111 317 24X
Fiche 50-352,84/08/08,8408140303

--8408140326 "Spec for Test Requirements for Dynamic Transient Testing of ASME Section III, Nuclear Class 1,2,3 & ANSI B31 1, Bechtel Piping, for Limerick Generating Station, Units 1 & 2 "
* Bechtel Corp 84/05/29 129pp 26112 240 24X
Fiche 50-352,84/08/08,8408140303

8408200262 Forwards responses to addl questions raised by Chemical Engineering Branch re structural steel survivability evaluation Info supports final resolution of SER Open Item 14
KEMPER,J S Philadelphia Electric Co 84/08/08 SCHWENCER,A
Licensing Branch 2 26pp 26133 211 24X Fiche,50-352,84/08/08,
8408200262

1379 Forwards draft FSAR pages in response to NRC 820825 request ddl info re instrument setpoint methodology for reactor sys & ESF instrumentation setpoints Info should Confirmatory Issue 26
Philadelphia Electric Co 84/08/10 SCHWENCER,A
Branch 2 3pp 26092 173 24X Fiche 50-352,84/08/10,

8408230292 Forwards Rev 3 to "Overhead Handling Sys Review " Rept revised, per NUREG-0612, to address concerns identified in draft technical evaluation rept on control of heavy loads & support resolution of SER License Condition 7
KEMPER,J S Philadelphia Electric Co 84/08/13 SCHWENCER,A
Licensing Branch 2 3pp 26207 001 24X Fiche 50-352,84/08/13,
8408230292

--8408230297 Rev 3 to final rept "Overhead Handling Sys Review "
* Philadelphia Electric Co 84/06/30 175pp 26207 004 24X
Fiche 50-352,84/08/13,8408230292

8408210031 Forwards addl info requested in NRC 840430 ltr re exceptions to conformance to Rev 2 to Reg Guide 1 97 Encls should close Open Item 12 of SER (NUREG-0991)
KEMPER,J S Philadelphia Electric Co 84/08/16 SCHWENCER,A
Licensing Branch 2 11pp 26181 337 24X Fiche 50-352,84/08/16,
8408210031

8408270376 Forwards addl info re SER Confirmatory Issue 12 concerning preservice insp program, per 840817 request
KEMPER,J S Philadelphia Electric Co 84/08/23 SCHWENCER,A
Licensing Branch 3 42pp 26240 258 24X Fiche 50-352,84/08/23,
8408270376

8408300215 Requests assistance in reviewing encl app to SER re identification of vital areas Response requested within 10 days of memo date to meet review 840907 completion date App withheld (ref 10CFR73 21)
THOMAS,C O Standardization & Special Projects Branch 84/08/24
PARR,O D Auxiliary Systems Branch 1p 26307 054 24X
Fiche 50-352,84/08/24,8408300215

F Security, medical, emergency & fire protection plans

8408160355 Forwards public version of emergency plan implementing procedures, including EP-101 re classification of emergencies, EP-102 re unusual event response, EP-103 re alert response & EP-104 re site emergency response
COONEY,M J Philadelphia Electric Co 84/07/09 MURLEY,T E
Region 1, Office of Director SCHWENCER,A Licensing Branch 2
5pp 26127 001 24X Fiche 50-352,84/07/09,8408160355

--8408160360 Public version of revised emergency plan implementing procedures, including EP-101 re classificaton of emergencies, EP-102 re unusual event response & EP-103 re alert response W/JM Felton 840807 release memo
* Philadelphia Electric Co 84/06/08 450pp 26127 006 24X
Fiche 50-352,84/07/09,8408160355

8408070336 Emergecy plan exercise manual
* Philadelphia Electric Co 84/07/25 426pp 25946 001 24X
Fiche 50-352,84/07/25,8408070336

8408020047 Forwards JL Patton 840723 ltr responding to RC Claypool 840607 ltr to Thornburgh re resources for radiological emergency response planning Related correspondence
FERKIN,Z Q Pennsylvania, Commonwealth of, DSB 704 84/07/27
BRENNER,L Atomic Safety and Licensing Board Panel 2pp
25883 273 24X Fiche 50-352,84/07/27,8408020047

8408070513 Forwards info to support resolution of SER proposed License Conditions 8,9,10 & 12 & to assist in preparation of License Condition 14 Info withheld (ref 10CFR2 790 & 73 21)
Affidavit of withholding encl
KEMPER,J S Philadelphia Electric Co 84/08/01 SCHWENCER,A
Licensing Branch 2 5pp 25941 167 24X Fiche 50-352,84/08/01,
8408070513

8408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure
KEMPER,J S Philadelphia Electric Co 84/08/02 SCHWENCER,A
Licensing Branch 2 6pp 25949 329 24X Fiche 50-352,84/08/02,
8408070037.

8408150637 Revised notification of 840807,09 & 10 meetings w/util in Bethesda,MD & Linfield,PA to discuss outstanding items in detailed control room design review
MARTIN,R E Licensing Branch 2 84/08/07 SCHWENCER,A Licensing
Branch 2 5pp 26102 339 24X Fiche 50-352,84/08/07,8408150637

8408220497 Forwards public version of revised emergency plan implementing procedures, including EP-105, "General Emergency Response" & EP-304, "Partial Plant Evacuation " Release memo dtd 840820 encl
DALTROFF,S L Philadelphia Electric Co 84/08/07 MURLEY,T E
Region 1, Office of Director SCHWENCER,A Licensing Branch 2
7pp 26210 213 24X Fiche 50-352,84/08/07,8408220497

--8408220501 Public version of revised emergency plan implementing procedures, including EP-105, "General Emergency Response" & EP-304, "Partial Plant Evacuation "
* Philadelphia Electric Co 84/08/07 25pp 26210 219 24X Fiche 50-352, 84/08/07, 8408220497

8408200147 Informs of review of schedule for sprinkler design & installation in conjunction w/possible temporary protective measures Installation of permanent sprinkler sys should be expedited
KEMPER, J S Philadelphia Electric Co 84/08/08 SCHWENCER, A Licensing Branch 2 3pp 26133 283 24X Fiche 50-352, 84/08/08, 8408200147

8408200206 Forwards info re 4-kV penetrations, resolving item questioned during 840409-12 fire protection sys & documentation site audit Info will be incorporated into next rev to Fire protection evaluation rept
KEMPER, J S Philadelphia Electric Co 84/08/08 SCHWENCER, A Licensing Branch 2 30pp 26133 069 24X Fiche 50-352, 84/08/08, 8408200206

8408150404 Forwards correspondence & documents between applicant, staff, Commonwealth of PA & responsible govt agencies re emergency planning Related correspondence
CULLEN, E J Philadelphia Electric Co DSB 064 84/08/10
MULLIGAN, M Limerick Ecology Action 24pp 26068 196 24X Fiche 50-352, 84/08/10, 8408150404

8408170381 Forwards supplemental info re Limerick Ecology Action 840806 response to util discovery request on admitted offsite emergency planning contentions Certificate of Svc encl
MULLIGAN, M Limerick Ecology Action DSB 102 84/08/13 RADER Philadelphia Electric Co 200pp 26137 181 24X Fiche 50-352, 84/08/13, 8408170381

8408200286 Forwards correspondence & documents among NRC, applicant & Commonwealth of PA re emergency planning, per ASLB 820601 order Matl suppls 840810, 0712 & 30 submittals Related correspondence
CULLEN, E J Philadelphia Electric Co DSB 142 84/08/15
MULLIGAN, M Limerick Ecology Action 50pp 26131 085 24X Fiche 50-352, 84/08/15, 8408200286

8408210452 Responds to concerns discussed in 840720 telcon re control room design review final rept final validation will be performed prior to fuel load Results will be submitted by 841031
KEMPER, J S Philadelphia Electric Co 84/08/16 SCHWENCER, A Licensing Branch 2 4pp 26177 200 24X Fiche 50-352, 84/08/16, 8408210452

8408240262 Forwards correspondence & documents among applicant, NRC & other parties re emergency planning Documents suppl matl forwarded in 840815 ltr & provide addl correspondence dtd 840611-0808 Related correspondence
CULLEN, E J Philadelphia Electric Co DSB 264 84/08/20
MULLIGAN, M Limerick Ecology Action 652pp 26223 214 24X Fiche 50-352, 84/08/20, 8408240262

8408280177 Provides resolution of concerns re fusible links on fire doors identified during 840409-12 site audit of fire protection sys & documentation Fusible links provided on hold open mechanisms for hollow metal doors
KEMPER, J S Philadelphia Electric Co 84/08/22 SCHWENCER, A Licensing Branch 2 2pp 26275 088 24X Fiche 50-352, 84/08/22, 8408280177

8408300215 Requests assistance in reviewing encl app to SER re identification of vital areas Response requested within 10 days of memo date to meet review 840907 completion date App withheld (ref 10CFR73 21)
THOMAS, C O Standardization & Special Projects Branch 84/08/24
PARR, O D Auxiliary Systems Branch 1p 26307 054 24X Fiche 50-352, 84/08/24, 8408300215

8408310008 Rev 1 to Emergency Plan Implementing Procedure EP-316, "Cumulative Population & Near Real-Time Emergency Dose Calculations for Airborne Releases - Manual Method." W/840824 ltr
DALTROFF, S L Philadelphia Electric Co 84/08/24 MURLEY, T E Region 1, Office of Director SCHWENCER, A Licensing Branch 2 74pp 26323 206 24X Fiche 50-352, 84/08/24, 8408310008

G Adjudicatory correspondence

8408310096 Brief of RL Anthony & Friends of the Earth in support of appeal from ASLB 840306 & 21 verbal orders & 840316 written order & request for hearing
ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth DSB 415 84/03/28 4pp 26322 229 24X Fiche 50-352, 84/03/28, 8408310096

8408280491 Suppl to RL Anthony & Friends of the Earth motion vs applicant motion for partial decision & low power license & submission of 840518 contentions on new matter
ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth DSB 358 84/05/30 Atomic Safety and Licensing Board Panel 2pp 26280 336 24X Fiche 50-352, 84/05/30, 8408280491

8408160112 Forwards intervenor Exhibits 3, 4, 47-135 & 136 Related correspondence
RILEY, S L Taylor Associates 84/05/31 PLEASANT, E Administrative & Logistical Support Branch 1p 26126 325 24X Fiche 50-352, 84/05/31, 8408160112

8408160099 Forwards applicant Exhibits 137-151 Related correspondence
RILEY, S L Taylor Associates 84/06/08 PLEASANT, E Administrative & Logistical Support Branch 1p 26126 328 24X Fiche 50-352, 84/06/08, 8408160099

8408160103 Forwards NRC staff Exhibit 29 & intervenor Exhibits 1 & 2 Related correspondence
RILEY, S L Taylor Associates 84/06/15 PLEASANT, E Administrative & Logistical Support Branch 1p 26126 327 24X Fiche 50-352, 84/06/15, 8408160103

8408160079 Forwards applicant Exhibits 153-173 Related correspondence
RILEY, S L Taylor Associates 84/06/26 PLEASANT, E Administrative & Logistical Support Branch 1p 26126 346 24X Fiche 50-352, 84/06/26, 8408160079

8408010223 Forwards suppl to 840523 ltr to ASLB & ASLAB re NRC duties concerning supplemental water Related correspondence
SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware Unlimited, Inc DSB 659 84/07/13 PALLADINO, N Commissioners 2pp 25856 022 24X Fiche 50-352, 84/07/13, 8408010223

--8408010228 Submits followup to 840523 & 0705 ltrs re position that NRC exhibits pro-applicant bias Position based on Denton 840629 ltr & util 840417 notes Board action requested W/o encls
SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware Unlimited, Inc 84/07/13 BRENNER, L , COLE, R F , MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 25856 024 24X Fiche 50-352, 84/07/13, 8408010223

8408010233 Response to NRC response to Air & Water Pollution Patrol 840626 contention re gross alpha W/svc list
ROMANO, F R Air and Water Pollution Patrol DSB 658 84/07/25 4pp 25856 014 24X Fiche 50-352, 84/07/25, 8408010233

8408060179 Informs that borough participated in 840725 evacuation drill per Mayor recommendation Drill not sanctioned by borough council & evacuation per Draft 5 of emergency evacuation plans disapproved Served on 840803
AUGUST, B K Phoenixville, PA DSB 735 84/07/25 BRENNER Atomic Safety and Licensing Board Panel 2pp 25932 183 24X Fiche 50-352, 84/07/25, 8408060179

8408010248 Forwards suppl to 840523 ltr to ASLB & ASLAB re NRC duties concerning supplemental water Certificate of Svc encl Related correspondence
SUGARMAN, R J Sugarman & Denworth SUGARMAN, R J Del-Aware Unlimited, Inc DSB 663 84/07/26 PALLADINO, N Commissioners 2pp 25859 341 24X Fiche 50-352, 84/07/26, 8408010248

8408010190 Errata to 840726 proposed findings of fact & conclusions of law on Limerick Ecology Action Contentions DES-1, DES-2, DES-3 & DES-4 Proposed transcript corrections & Certificate of Svc encl
ELLIOTT, C W Limerick Ecology Action DSB 680 84/07/27 5pp 25855 163 24X Fiche 50-352, 84/07/27, 8408010190

8408010255 Answer to Consumer Educ & Protective Assoc 840717 safety contentions Contentions lack basis, concern ratemaking matters outside NRC jurisdiction & should be denied Certificate of Svc encl.
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn DSB 670, 84/07/27 Atomic Safety and Licensing Board Panel, 9pp 25854 315 24X Fiche 50-352, 84/07/27, 8408010255

8408020047 Forwards JL Patton 840723 ltr responding to RC Claypool 840607 ltr to Thornburgh re resources for radiological emergency response planning Related correspondence
FERKIN, Z G Pennsylvania, Commonwealth of, DSB 704 84/07/27
BRENNER, L , COLE, R F , MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 25883 273 24X Fiche 50-352, 84/07/27, 8408020047

8408070302 Response to Consumer Educ & Protective Assoc (CEPA) safety contentions received on 840716 CEPA contentions provide inadequate basis for concerns & should not be admitted Certificate of Svc encl
WRIGHT, N A Hearing Branch 2 DSB 807 84/07/31 Atomic Safety and Licensing Board Panel 9pp 25947 231 24X Fiche 50-352, 84/07/31, 8408070302

8408080191 Appeal to Commission from ASLAB 840723 Memorandum & Order ALAB-778 re contentions on nuclear fuel Immediate stay requested W/svc list
ANTHONY,R L Anthony, R L ANTHONY,R L Friends of the Earth DSB 835 84/07/31 2pp 25960 257 24X Fiche 50-352,84/07/31, 8408080191

8408060053 First set of interrogatories & request for production of documents to city of Philadelphia re offsite emergency planning Contentions City-18 & City-19 Certificate of Svc encl Related correspondence
RADER,R M Philadelphia Electric Co RADER,R M Conner & Wetterhahn DSB 743 84/08/01 Philadelphia, PA 12pp 25933 197 24X Fiche 50-352,84/08/01,8408060053

8408060170 Second errata to 840726 proposed findings of fact & conclusions of law on Limerick Ecology Action Contentions DES-1,DES-2,DES-3 & DES-4 Certificate of Svc encl
ELLIOTT,C W Limerick Ecology Action DSB 742 84/08/01 3pp 25932 194 24X Fiche 50-352,84/08/01,8408060170

8408060182 Confirms points discussed in 840727 telcon,agreements reached & matters in dispute re Limerick Ecology Action answers to Applicant first set of interrogatories & request for production of documents Related correspondence
RADER,R M Conner & Wetterhahn DSB 745 84/08/01 MULLIGAN,M Limerick Ecology Action 8pp 25932 175 24X Fiche 50-352, 84/08/01,8408060182

8408060228 Forwards applicant 840727 answer to CEPA safety contentions W/o encl Related correspondence
WETTERHAHN,M J Conner & Wetterhahn WETTERHAHN,M J Philadelphia Electric Co DSB 744 84/08/01 HERSHEY,S P CEPA HERSHEY,S P Hershey, S P ip 25933 335 24X Fiche 50-352,84/08/01,8408060228

8408070350 Discusses RJ Sugarman correspondence & concerns re ex parte communications Matters raised by RJ Sugarman w/o merit & will be addressed formally by director in decision per 10CFR2 206 Related correspondence
CONNER,T B Conner & Wetterhahn CONNER,T B Philadelphia Electric Co DSB 777 84/08/02 CHILK,S J Office of the Secretary of the Commission 3pp 25944 167 24X Fiche 50-352,84/08/02,8408070350

8408070363 Motion to compel answers to first set of interrogatories,to compel production of withheld documents & for related relief re destroyed documents Certificate of Svc encl Related correspondence
RADER,R M Philadelphia Electric Co RADER,R M Conner & Wetterhahn DSB 780 84/08/02 Atomic Safety and Licensing Board Panel 16pp 25945 158 24X Fiche 50-352,84/08/02,8408070363

8408070366 Transmittal of VS Boyer 840802 affidavit re schedule for fuel loading,per ASLB 840620 order Certificate of Svc encl Related correspondence
WETTERHAHN,M J Philadelphia Electric Co DSB 781 84/08/02 6pp 25945 152 24X Fiche 50-352,84/08/02,8408070366

8408070412 Forwards answer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions (Discovery 35) Related correspondence
RADER,R M Conner & Wetterhahn RADER,R M Philadelphia Electric Co DSB 782 84/08/02 MULLIGAN,M Limerick Ecology Action 1p 25942 053 24X Fiche 50-352,84/08/02,8408070412

-8408070415 Answer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions (Discovery 35) Certificate of Svc encl
* Philadelphia Electric Co 84/07/31 Limerick Ecology Action 91pp 25942 054 24X Fiche 50-352,84/08/02,8408070412

108070287 Forwards signature page of 840802 motion to compel answers to first set of interrogatories,to compel production of withheld documents & for related relief re destroyed documents
CONNER,T B Conner & Wetterhahn CONNER,T B Philadelphia Electric Co DSB 803 84/08/03 Docketing & Services Branch 1p 25948 218 24X Fiche 50-352,84/08/03,8408070287

7408070291 Signature page of 840802 motion to compel answers to first set of interrogatories
CONNER,T B Philadelphia Electric Co CONNER,T B Conner & Wetterhahn 84/08/02 Atomic Safety and Licensing Board Panel 1p 25948 219 24X Fiche 50-352,84/08/03,8408070287

8070429 Forwards VS Boyer 840802 affidavit re schedule for fuel oading Related correspondence
ETTERHAHN,M J Conner & Wetterhahn WETTERHAHN,M J Philadelphia lectric Co DSB 802 84/08/03 Docketing & Services Branch 1p 25940 049 24X Fiche 50-352,84/08/03,8408070429

--8408070433 Affidavit of VS Boyer re schedule for fuel loading
BOYER,V S Philadelphia Electric Co 84/08/02 2pp 25940 050 24X Fiche 50-352,84/08/03,8408070429

8408090226 Forwards motion before ASLAB to set aside partial initial decision based on new evidence
SUGARMAN,R J Sugarman & Denworth SUGARMAN,R J Del-Aware Unlimited, Inc DSB 858 84/08/03 Office of the Secretary of the Commission 1p 25971 114 24X Fiche 50-352,84/08/03, 8408090226

--8408090233 Motion to set aside partial initial decision based on new evidence & circumstances Certificate of Svc encl
SUGARMAN,R J Del-Aware Unlimited, Inc SUGARMAN,R J Sugarman & Denworth 84/07/31 Atomic Safety and Licensing Appeal Panel 52pp 25971 115 24X Fiche 50-352,84/08/03,8408090226

8408070372 Reply to City of Philadelphia & Limerick Ecology Action 840726 proposed findings of fact & conclusions of law re severe accident risk assessment contentions Certificate of Svc encl
WETTERHAHN,M J , NICHOLS,N N Philadelphia Electric Co WETTERHAHN,M J Conner & Wetterhahn DSB 795 84/08/06 29pp 25944 170 24X Fiche 50-352,84/08/06,8408070372

8408070444 Forwards answer to Limerick Ecology Action second set of interrogatories & request for production of documents re admitted offsite emergency planning contentions Encl replaces 840802 answers Related correspondence
RADER,R M Conner & Wetterhahn RADER,R M Philadelphia Electric Co DSB 789 84/08/06 MULLIGAN,M Limerick Ecology Action 1p 25942 268 24X Fiche 50-352,84/08/06,8408070444

--8408070450 Revised answer to second set of interrogatories & request for production of documents on Limerick Ecology Action admitted offsite emergency planning contentions
BOYER,V S Philadelphia Electric Co 84/08/03 Limerick Ecology Action 88pp 25942 269 24X Fiche 50-352,84/08/06, 8408070444

8408070495 Informs that applicant does not intend to respond to Sugarman 840713 ltr purporting to update earlier ltrs of 840523 & 0605 to ASLAB & ASLB or to any future ltrs to ASLAB or ASLB Related correspondence
CONNER,T B Conner & Wetterhahn CONNER,T B Philadelphia Electric Co DSB 794 84/08/06 BRENNER,L , MORRIS,P A , COLE,R F Atomic Safety and Licensing Board Panel 2pp 25941 191 24X Fiche 50-352,84/08/06,8408070495

8408090197 Reply to Limerick Ecology Action & City of Philadelphia proposed findings of fact & conclusions of law re severe accident risk assessment contentions
VOGLER,B H , HODGDON,A P Hearing Branch 2 DSB 871 84/08/06 Atomic Safety and Licensing Board Panel 14pp 25972 001 24X Fiche 50-352,84/08/06,8408090197

8408090258 Forwards supplemental info re interrogatories,per util 840727 phone call & 840801 ltr Related correspondence
MULLIGAN,M Limerick Ecology Action DSB 859 84/08/06 RADER Philadelphia Electric Co 7pp 25972 114 24X Fiche 50-352,84/08/06,8408090258

--8408090263 Amended answers to util first set of interrogatories re offsite emergency planning Contention LEA/FOE 24 Certificate of Svc encl
ANTHONY,R L Anthony, R L 84/07/23 Philadelphia Electric Co 6pp 25972 121 24X Fiche 50-352,84/08/06,8408090258

8408080399 Joint rept of parties on schedule proposal for offsite emergency planning matters Filed in response to 840723 order Certificate of Svc encl
CONNER,T B Philadelphia Electric Co CONNER,T B Conner & Wetterhahn DSB 837 84/08/07 Atomic Safety and Licensing Board Panel 14pp 25974 087 24X Fiche 50-352,84/08/07,8408080399

8408080404 Motion to strike Air & Water Pollution Patrol (AWPP) pleading & reply to AWPP motion re Contention VI-1 Motion filed late & w/o basis Certificate of Svc encl
WETTERHAHN,M J Philadelphia Electric Co WETTERHAHN,M J Conner & Wetterhahn DSB 838 84/08/07 Atomic Safety and Licensing Board Panel 7pp 25974 080 24X Fiche 50-352,84/08/07,8408080404

8408090238 Forwards NRC 840727 Amend 1 to License SNM-1926 & SER in support of amend Related correspondence
VOGLER,B H Hearing Branch 4 DSB 872 84/08/07 BRENNER,L , MORRIS,P A , COLE,R F Atomic Safety and Licensing Board Panel 14pp 25972 152 24X Fiche 50-352,84/08/07,8408090238

8408130368 Replies to 840705 ltr re 840523 ltr to Chairman Palladino All encls to ltr possibly not included to all recipients Comments on encls inconsistent w/practice followed for some time w/o objection
SUGARMAN,R J Sugarman & Denworth SUGARMAN,R J Del-Aware Unlimited, Inc DSB 897 84/08/07 MALSCH,M G Office of the General Counsel 1p 26011 127 24X Fiche 50-352,84/08/07, 8408130368

8408140450 Forwards new contention re evacuation
ROMANO,F R Air and Water Pollution Patrol DSB 015 84/08/08 Atomic Safety and Licensing Board Panel 6pp 26061 001 24X Fiche 50-352,84/08/08,8408140450

--8408140452 New contention that applicant must provide fully testable & capable emergency evacuation plan prior to receipt of OL
ROMANO,F R Air and Water Pollution Patrol 84/08/08 Atomic Safety and Licensing Board Panel 5pp 26061 002 24X Fiche 50-352,84/08/08,8408140450

8408130158 Order establishing filing date of 840806 for motion to set aside based on new evidence received on 840809 Motion & ltr bear postmark date of 840806 Served on 840810
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel DSB 928 84/08/09 Del-Aware Unlimited, Inc 2pp 26007 352 24X Fiche 50-352,84/08/09,8408130158

8408140484 Forwards amended Certificate of Svc of appellant motion to set aside based on new evidence Amend reflects svc of motion on 840806
LOCKE,R T Sugarman & Denworth LOCKE,R T Del-Aware Unlimited, Inc DSB 013 84/08/09 KOHL,C N , EDLES,G , GOTCHY,R L Atomic Safety and Licensing Board Panel 3pp 26060 276 24X Fiche 50-352,84/08/09,8408140484

8408140540 Reply to applicant & staff answers to CEPA safety contentions Contentions should be admitted Certificate of Svc encl
HERSHEY,S P CEPA DSB 027 84/08/09 Atomic Safety and Licensing Board Panel 7pp 26061 220 24X Fiche 50-352,84/08/09, 8408140540

8408150404 Forwards correspondence & documents between applicant,staff, Commonwealth of PA & responsible govt agencies re emergency planning Related correspondence
CULLEN,E J Philadelphia Electric Co DSB 064 84/08/10 MULLIGAN,M Limerick Ecology Action 24pp 26068 196 24X Fiche 50-352,84/08/10,8408150404

8408150477 Responds to 840806 ltr forwarding Limerick Ecology Action supplemental responses to applicant discovery requests Supplemental answers addressed individually Related correspondence
RADER,R M Conner & Wetterhahn RADER,R M Philadelphia Electric Co DSB 062 84/08/10 MULLIGAN,M Limerick Ecology Action 4pp 26068 160 24X Fiche 50-352,84/08/10,8408150477

8408150183 Order approving proposed transcript corrections as listed Served on 840814
BRENNER,L Atomic Safety and Licensing Board Panel DSB 049 84/08/13 2pp 26066 245 24X Fiche 50-352,84/08/13,8408150183

8408150387 Answer in opposition to Friends of the Earth 840731 petition for review of ALAB-778 No substantial conflict between ASLB & ASLAB presented Certificate of Svc encl
WETTERHAHN,M J Philadelphia Electric Co WETTERHAHN,M J Conner & Wetterhahn DSB 061 84/08/13 Commissioners 10pp 26068 285 24X Fiche 50-352,84/08/13,8408150387

8408170381 Forwards supplemental info re Limerick Ecology Action 840806 response to util discovery request on admitted offsite emergency planning contentions Certificate of Svc encl
MULLIGAN,M Limerick Ecology Action DSB 102 84/08/13 RADER Philadelphia Electric Co 280pp 26137 181 24X
Fiche 50-352,84/08/13,8408170381

8408200433 Forwards response to applicant motion re Contention VI-I & further support for reopening Contention VI-I re welding & welding insp infractions
ROMANO,F R Air and Water Pollution Patrol DSB 164 84/08/14 1p 26136 292 24X Fiche 50-352,84/08/14,8408200433

--8408200442 Response to applicant motion to strike Air & Water Pollution Patrol (AWPP) pleading & reply to AWPP motion re Contention VI-I Contention VI-I must be litigated
ROMANO,F R Air and Water Pollution Patrol 84/08/10 Atomic Safety and Licensing Board Panel 1p 26136 293 24X
Fiche 50-352,84/08/14,8408200433

--8408200447 Further support for reopening Contention VI-I re welding & welding insp infractions Air & Water Pollution Patrol calls for full-scale reinsp re lack of fusion & Broomstick Affair revelations
ROMANO,F R Air and Water Pollution Patrol 84/08/13 Atomic Safety and Licensing Board Panel 2pp 26136 294 24X
Fiche 50-352,84/08/14,8408200433

8408150425 Response opposing Friends of the Earth & R Anthony 840731 petition for review & request for stay of ALAB-778 Motion fails to establish existence of important issues of fact,law or policy & should be denied Certificate of Svc encl
VOLGER,B H , WRIGHT,N A Hearing Branch 2 DSB 067 84/08/15 Commissioners 15pp 26068 220 24X Fiche 50-352,84/08/15, 8408150425

8408170305 Order establishing schedule for admitted offsite emergency planning issues Schedule for deferred contentions will be established Courtesy notification encl Served on 840816
BRENNER,L Atomic Safety and Licensing Board Panel DSB 095 84/08/15 Office of the Executive Legal Director 6pp 26115 246 24X Fiche 50-352,84/08/15,8408170305

8408200286 Forwards correspondence & documents among NRC,applicant & Commonwealth of PA re emergency planning,per ASLB 820601 order Mail supplS 840810,0712 & 30 submittals Related correspondence
CULLEN,E J Philadelphia Electric Co DSB 142 84/08/15
MULLIGAN,M Limerick Ecology Action 50pp 26131 085 24X
Fiche 50-352,84/08/15,8408200286

8408210341 Forwards order establishing schedule for offsite emergency planning issues W/o encl Related correspondence
VOGLER,B H Hearing Branch 2 DSB 186 84/08/16 PERRY,S Federal Emergency Management Agency 2pp 26179 361 24X
Fiche 50-352,84/08/16,8408210341

8408220354 New info contention re health hazard via polyvinyl chloride fill used in reactor cooling towers W/svc list
ROMANO,F R Air and Water Pollution Patrol DSB 196 84/08/16 Atomic Safety and Licensing Board Panel 4pp 26189 318 24X
Fiche 50-352,84/08/16,8408220354

8408220379 Informs of errors in City of Philadelphia record citations re statement of NRC witness Acharya Also forwards Commonwealth of PA Public Utility Commission 840807 order to show cause Related correspondence
BUSH,M W Philadelphia, PA DSB 199 84/08/16 BRENNER,L Atomic Safety and Licensing Board Panel 5pp 26191 349 24X
Fiche 50-352,84/08/16,8408220379

8408240240 Provides addendum to Air & Water Pollution Patrol 840816 new info contention re polyvinyl chloride Fifth criterion re breakdown of polyvinyl chloride inadvertantly omitted Small delay in proceedings ack for large public good
ROMANO,F R Air and Water Pollution Patrol DSB 271 84/08/20 Atomic Safety and Licensing Board Panel 1p 26222 361 24X
Fiche 50-352,84/08/20,8408240240

8408240262 Forwards correspondence & documents among applicant,NRC & other parties re emergency planning Documents suppl matl forwarded in 840815 ltr & provide addl correspondence dtd 840611-0808 Related correspondence
CULLEN,E J Philadelphia Electric Co DSB 264 84/08/20
MULLIGAN,M Limerick Ecology Action 652pp 26223 214 24X
Fiche 50-352,84/08/20,8408240262

8408240236 Answer opposing late-Filed Air & Water Pollution Patrol 840808 new contention re evacuation Contention lacks basis & specificity & fails to show good cause for late filing Certificate of Svc encl
CONNER,T B Philadelphia Electric Co CONNER,T B Conner & Wetterhahn DSB 269 84/08/21. Atomic Safety and Licensing Board Panel 18pp 26222 259 24X Fiche 50-352,84/08/21,8408240236

8408240241 Answer opposing Del-Aware Unlimited,Inc 840806 motion to set aside ASLB 830308 partial initial decision re supplementary cooling water sys,based on new evidence Motion should be denied Certificate of Svc encl
CONNER,T B Philadelphia Electric Co CONNER,T B Conner & Wetterhahn DSB 270 84/08/21 Atomic Safety and Licensing Appeal Panel 46pp 26223 066 24X Fiche 50-352,84/08/21, 8408240241

8408240256 Forwards util comments on Del-Aware request under 10CFR2 206,per 840523 & 0713 requests for relief Matters repetitions & inappropriate under 10CFR2 206 & fail to raise significant environ concern
CONNER,T B Conner & Wetterhahn CONNER,T B Philadelphia Electric Co 84/08/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 17pp 26223 001 24X Fiche 50-352,84/08/21,8408240256

8408230200 Memorandum & order denying Citizens Action in Northeast 840625 & Consumers Educ & Protective Assoc 840716 motions to admit or certify financial qualifications contentions Served on 840822
BRENNER,L Atomic Safety and Licensing Board Panel DSB 254
84/08/22 Office of the Executive Legal Director 11pp
26209 198 24X Fiche 50-352,84/08/22,8408230200

8408280415 Motion for reconsideration of ASLB 840815 order establishing schedule for offsite emergency planning issues FEMA should not be required to distribute draft rept by 840901 Certificate of Svc encl
VOGLER,B H , WRIGHT,N A Hearing Branch 2 DSB 344 84/08/23
Atomic Safety and Licensing Board Panel 4pp 26280 290 24X
Fiche 50-352,84/08/23,8408280415

8408280162 Memorandum & order rejecting Friends of the Earth & Air & Water Pollution Patrol (AWPP) late-filed contentions & denying AWPP second request for reconsideration of asbestos contention Courtesy notification encl Served on 840827
BRENNER,L Atomic Safety and Licensing Board Panel DSB 326
84/08/24 Friends of the Earth 27pp 26275 116 24X
Fiche 50-352,84/08/24,8408280162

8408280388 Confirms 840824 telcon informing of 840830 meeting in Philadelphia,PA to discuss matters covered by ASLB scheduling order Related correspondence
RADER,R M Conner & Wetterhahn RADER,R M Philadelphia Electric Co DSB 354 84/08/24 VOGLER,B H Hearing Branch 2 FERKIN,Z G Pennsylvania, Commonwealth of, SMOLLEN,M Philadelphia, PA 2pp 26280 032 24X Fiche 50-352,84/08/24,8408280388

8408280237 Order extending time until 840921 for Commission to act to review ALAB-778 Served on 840827
CHILK,S J Office of the Secretary of the Commission DSB 319
84/08/27 Commissioners 1p 26262 278 24X
Fiche 50-352,84/08/27,8408280237

8408300170 Response opposing Del-Aware 840806 motion to set aside ASLB 830308 partial initial decision on environ effects of supplemental cooling water sys based on new evidence Certificate of Svc encl
VOGLER,B H Hearing Branch 2 DSB 381 84/08/27 Atomic Safety and Licensing Appeal Panel 23pp 26305 320 24X
Fiche 50-352,84/08/27,8408300170

8408300119 Response opposing admission of Air & Water Pollution Patrol 840808 new contention re evacuation,filed by FR Romano Certificate of Svc encl
WRIGHT,N A Hearing Branch 2 DSB 379 84/08/28 Atomic Safety and Licensing Board Panel 12pp 26305 171 24X
Fiche 50-352,84/08/28,8408300119

8408300168 Second Partial Initial Decision LBP-84-31 on listed issues in controversy in favor of applicant Courtesy notification encl Served on 840829
BRENNER,L , COLE,R F , MORRIS,P A Atomic Safety and Licensing Board Panel DSB 386 84/08/29 325pp 26303 158 24X
Fiche 50-352,84/08/29,8408300168

8408310223 Response opposing Air & Water Pollution Patrol 840814 pleading on reopening Contention VI-1 re welding & welding insp infractions Certificate of Svc encl
WETTERHAHN,M J Philadelphia Electric Co WETTERHAHN,M J Conner & Wetterhahn DSB 423 84/08/29 Atomic Safety and Licensing Board Panel 8pp 26319 244 24X Fiche 50-352,84/08/29,8408310223

C Utility Final Safety Analysis Report (FSAR) & amends

8408020058 Forwards Rev 34 to FSAR
BRADLEY,E J Philadelphia Electric Co 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25904 001
24X Fiche 50-352,84/07/31,8408020058

-8408020084 Rev 34 to FSAR
* Philadelphia Electric Co 84/07/31 272pp 25904 014 24X
Fiche 50-352,84/07/31,8408020058

8408210076 Forwards Affidavit of Svc certifying distribution of Rev 34 to FSAR & Rev 19 to environ rept on 840809
BRADLEY,E J Philadelphia Electric Co 84/08/14 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 26184 327
24X Fiche,50-352,84/08/14,8408210076

G Inspection reports, IE Bulletins & correspondence

8408310124 Forwards response to NRC 840620 ltr re violations noted in Insp Repts 50-352/84-24 & 50-353/84-08 on 840501-31 Seismic classifications of three piping isometric drawings & four piping field sketches corrected Related correspondence
KEMPER,J S Philadelphia Electric Co DSB 002 84/07/19
MURLEY,T E Region 1, Office of Director 4pp 26352 028 24X
Fiche 50-352,84/07/19,8408310124

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408210368 Forwards IE Insp Repts 50-352/84-26 & 50-353/84-09 on 840601-30 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 84/08/02
KEMPER,J S Philadelphia Electric Co 2pp 26183 109 24X
Fiche 50-352,84/08/02,8408210368

--8408210373 Notice of violation from insp on 840601-30
* Region 1, Office of Director 84/08/02 4pp 26183 111 24X
Fiche 50-352,84/08/02,8408210368

--8408210381 IE Insp Repts 50-352/84-26 & 50-353/84-09 on 840601-30 Violations identified inadequate diesel generator test program implementation & inadequate calibr procedure for valve position indicating sys
CHAUDHARY,S K , WIGGINS,J T , BAUNACK,W Region 1, Office of Director 84/07/24 15pp 26183 115 24X Fiche 50-352,84/08/02, 8408210368

--8408210394 Responds to NRC 840321 ltr re violations noted in IE Insp Repts 50-352/84-19 & 50-353/84-06 Corrective actions notice issued to include info on P&ID M-42 & Procedure OADP-27 1 revised
GALLAGHER,J W Philadelphia Electric Co 84/06/20 MURLEY,T E
Region 1, Office of Director 5pp 26183 130 24X
Fiche 50-352,84/08/02,8408210368

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408130296 Forwards relief requests from ASME Code,Section XI preservice insp requirements to resolve SER Confirmatory Issue 12
KEMPER,J S Philadelphia Electric Co 84/08/07 SCHWENCER,A
Licensing Branch 2 7pp 26008 349 24X Fiche 50-352,84/08/07, 8408130296

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408240013 Confirms 840824 telcon re 840827-31 insp concerning siesmic design of structures, pipe break analysis & south stack blast load calculations
ZECH, G G Vendor Program Branch 84/08/21 STRATTON, C D Bechtel Corp 1p 26228 248 24X Fiche 50-352, 84/08/21, 8408240013

8408270376 Forwards addl info re SER Confirmatory Issue 12 concerning preservice insp program, per 840817 request
KEMPER, J S Philadelphia Electric Co 84/08/23 SCHWENCER, A Licensing Branch 3 62pp 26240 258 24X Fiche 50-352, 84/08/23, 8408270376

R Periodic operating reports & related correspondence

8408060419 Forwards fourth status rept re independent design review of core spray sys for 840701-15 Related correspondence
CARPENTER, F D Torrey Pines Technology DSB 719 84/07/16
BOYER, V S Philadelphia Electric Co 7pp 25951 123 24X
Fiche 50-352, 84/07/16, 8408060419

8408310023 Forwards "Independent Design Review of Limerick Generating Station 1 Core Spray Sys, Bi-Monthly Status Rept 5 for Period Ending 840731 " Related correspondence
CARPENTER, F D Torrey Pines Technology DSB 234 84/08/01
BOYER, V S Philadelphia Electric Co 7pp 26350, 102 24X
Fiche 50-352, 84/08/01, 8408310023

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated.
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408240332 Submits annotated requests for followup on potentially generic problem in encl Part 21 rept from Basler Electric re SCRs on nuclear exciters mounted w/too much pressure.
NORELIUS, C E Division of Project & Resident Programs 84/04/25
JORDAN, E L Director's Office, Office of Inspection and Enforcement 1p 26225 303 24X Fiche 50-000, 84/04/25, 8408240332

8408310110 Significant Deficiency Rept 149 re design calculations made by WJ Woolley Co for doors specified to meet tornado-generated missile criteria Door reanalysis underway Previously reported under Part 21 by WJ Woolley Co
KEMPER, J S Philadelphia Electric Co 84/08/23 MURLEY, T E Region 1, Office of Director 1p 26322 239 24X
Fiche 50-352, 84/08/23, 8408310110

T Hearing transcripts on non-antitrust matters

8408090205 Proposed corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13, 14 & 15 Certificate of Svc encl
* Hearing Branch 2 84/08/06 Atomic Safety and Licensing Board Panel 13pp 25972 015 24X Fiche 50-352, 84/08/06, 8408090197

8408090229 Forwards dated & signed copy of Page 11 of proposed corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13, 14 & 15
VOGLER, B H Hearing Branch 2 DSB 867 84/08/07 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 2pp 25971 167 24X Fiche 50-352, 84/08/07, 8408090229

--8408090236 Executed Page 11 of corrections to transcript of hearings on Limerick Ecology Action DES contentions & City of Philadelphia Contentions 13, 14 & 15
VOGLER, B H , HODGDON, A P Hearing Branch 2 84/08/06 1p 25971 169 24X Fiche 50-352, 84/08/07, 8408090229

8408240254 Proposed corrections to transcript of evidentiary hearings on NEPA severe accident contentions Certificate of Svc encl
WETTERHAHN, M J , NICHOLS, N N Philadelphia Electric Co
WETTERHAHN, M J Conner & Wetterhahn DSB 268 84/08/21 5pp 26222 350 24X Fiche 50-352, 84/08/21, 8408240254

U Congressional/Executive Correspondence

8408170094 Responds to 840712 ltr re 840502 Pottstown Mercury article & related petition Low level normal operation releases expected to be well within recognized safety limits Excerpts from DES encl
DIRCKS, W J Office of the Executive Director for Operations
84/08/08 WALKER, R S House of Rep 1p 26135 322 24X
Fiche 50-352, 84/08/08, 8408170094

8408200449 Responds to 840712 request for consideration of constituent H Mayerson 840607 ltr w/840502 Pottstown Mercury article & encl petition Low level normal operation releases expected to be well within recognized safety limits
DIRCKS, W J Office of the Executive Director for Operations
84/08/08 WALKER, R S House of Rep 5pp 26182 313 24X
Fiche 50-352, 84/08/08, 8408200449

--8408200454 Forwards constituent H Mayerson 840607 ltr w/840502 Pottstown Mercury article, "Limerick to Release Very Small Amounts of Radioactivity" & petition & requests investigation of statements
WALKER, R S House of Rep 84/07/12 KAMMERER, C Office of Congressional Affairs 6pp 26182 332 24X Fiche 50-352, 84/08/08, 8408200449

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8408010212 Notification of time change for 840731 meeting w/util in Bethesda, MD to discuss riverborne missiles during PMH
WAGNER, D H Licensing Branch 2 84/07/17 SCHWENCER, A Licensing Branch 2 3pp 25872 360 24X Fiche 50-354, 84/07/17, 8408010212

8408010227 Requests addl info needed to complete FSAR review, including info re fire protection for solid waste product in storage area & justification for departure from/Reg Guide 1 52 Response should be provided by 840813
SCHWENCER, A Licensing Branch 3 84/07/24 MITTL, R L Public Service Electric & Gas Co of New Jersey 3pp 25873 277 24X
Fiche 50-354, 84/07/24, 8408010227

8408080344 Forwards nonproprietary "Use of Code Case N-192 " & proprietary repts, including "Documentation of Compliance of MBC P/N 73989 " & "Hose Assembly " qualification test procedures, per Reg Guide 1 84 Proprietary repts withheld
MITTL, R L Public Service Electric & Gas Co of New Jersey
84/07/30 SCHWENCER, A Licensing Branch 2 10pp 25963, 276 24X
Fiche 50-354, 84/07/30, 8408080344

--8408080346 Nonproprietary "Use of Code Case N-192 (Compliance W/Addl Requirements of Reg Guide 1 84) "
* Public Service Electric & Gas Co of New Jersey 84/06/30 3pp 25963, 284 24X Fiche 50-354, 84/07/30, 8408080344

8408130201 Provides procedures for developing plant-specific Tech Specs
SCHWENCER, A Licensing Branch 2 84/08/01 MITTL, R L Public Service Electric & Gas Co of New Jersey 2pp 26058 359 24X
Fiche 50-354, 84/08/01, 8408130201

8408060279 Forwards responses to QA Branch open items discussed at 840718 QA meeting. Mods to FSAR, Sections 1 8 & 17 2, Table 3 2-1 & 260 series question/responses will be incorporated into FSAR, Amend 8
MITTL, R L Public Service Electric & Gas Co of New Jersey
84/08/03 SCHWENCER, A Licensing Branch 2 170pp 25926, 003 24X
Fiche 50-354, 84/08/03, 8408060279

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408150170 Summary of 840718 meeting w/util in Bethesda,MD re QA program List of attendees,agenda & licensee responses to outstanding QA issues encl
WAGNER,D H Licensing Branch 2 84/08/07 Licensing Branch 2
53pp 26104 139 24X Fiche 50-354,84/08/07,8408150170

8408160336 Forwards FSAR commitment status through June & Jul 1984 & responses to NRC request for addl info re FSAR Amend 7
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/13 SCHWENCER,A Licensing Branch 2 51pp 26090 283 24X Fiche 50-354,84/08/13,8408160336

8408200463 Summary of 840626-28 meetings w/util & Bechtel in San Francisco,CA re Instrumentation & Control Sys Branch open items not resolved since Jan 1984 meeting Summary of OL review status encl
WAGNER,D Licensing Branch 2 84/08/13 Licensing Branch 2
150pp 26182 014 24X Fiche 50-354,84/08/13,8408200463

8408210442 Forwards Pages 19 & 41 omitted from master listing of seismic & dynamic qualification summary & status of safety-related equipment submitted w/840705 ltr Meeting requested
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/13 SCHWENCER,A Licensing Branch 2 4pp 26181 258 24X Fiche 50-354,84/08/13,8408210442

8408170337 Forwards mods to FSAR Chapter 13 & Section 1 10 discussed at 840723-25 meetings Mods will be included in future FSAR amend
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/15 SCHWENCER,A Licensing Branch 2 115pp 26114 115 24X Fiche 50-354,84/08/15,8408170337

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408230352 Forwards Amend 7 to FSAR (filed in PDR Category K) & Amend 4 to environ rept - OL stage (filed in PDR Category C)
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/20 SCHWENCER,A Licensing Branch 2 3pp 26325 298 24X
Fiche 50-354,84/08/20,8408230352

8408310276 Notification of Significant Licensee Meeting 84-76 on 841022 w/util at site to discuss status of const & preoperational testing (Module 303018)
KELLY,E Division of Project & Resident Programs 84/08/21
Division of Project & Resident Programs 2pp 26351 335 24X
Fiche 50-354,84/08/21,8408310276

8408290098 Forwards Rev 0 to "Environ Qualification Summary Rept," per FSAR Question 270 2
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/24 SCHWENCER,A Licensing Branch 2 2pp 26291 307 24X
Fiche 50-354,84/08/24,8408290098

8408290102 Rev 0 to "Environ Qualification Summary Rept "
* Public Service Electric & Gas Co of New Jersey 84/08/02
501pp 26291 309 24X Fiche 50-354,84/08/24,8408290098

8408290513 Notification of 840906 & 07 meetings w/util in Bethesda,MD to discuss Power Sys Branch mechanical issues
WAGNER,D H Licensing Branch 2 84/08/24 SCHWENCER,A Licensing Branch 2 3pp 26299 355 24X Fiche 50-354,84/08/24,8408290513

8408300101 Notification of 840830 meeting w/util in Bethesda,MD to discuss geotechnical issues
WAGNER,D H Licensing Branch 2 84/08/24 SCHWENCER,A Licensing Branch 2 3pp 26329 360 24X Fiche 50-354,84/08/24,8408300101

8408300153 Forwards correction to FSAR Figure 13 1-9 re organization & rev to FSAR Page 1 10-21 re TMI Item I C 6,resulting from licensee Qualifications Branch 840723,24 & 25 meetings
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/24 SCHWENCER,A Licensing Branch 2 134pp 26304 123 24X
Fiche 50-354,84/08/24,8408300153

Utility Environmental Report (ER), amends & correspondence

8408230352 Forwards Amend 4 to environ rept - OL stage
(filed in PDR Category C)
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/20 SCHWENCER,A Licensing Branch 2 3pp 26325 298 24X
Fiche 50-354,84/08/20,8408230352

--8408230365 Amend 4 to environ rept - OL stage (filed in PDR Category C)
* Public Service Electric & Gas Co of New Jersey 84/08/31
65pp 26325 301 24X Fiche 50-354,84/08/20,8408230352

8408280448 Forwards "Environ Qualification Summary Rept " Related correspondence
CONNER,T B Conner & Wetterhahn CONNER,T B Public Service Electric & Gas Co of New Jersey DSB 363 84/08/22 MILLER,M E , MORRIS,P A , SCHINK,D R Atomic Safety and Licensing Board Panel
143pp 26281 123 24X Fiche 50-354,84/08/22,8408280448

8408310198 Forwards affidavit certifying distribution of Amend 7 to FSAR for Hope Creek Generating Station & Amend 4 to environ rept - OL stage,per 10CFR2 101 Environ rept - OL distribution list & ack receipt forms encl
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/28 Office of Nuclear Reactor Regulation, Director
SCHWENCER,A Licensing Branch 2 16pp 26318 292 24X
Fiche 50-354,84/08/28,8408310198

D NRC Draft/Final Environmental Statements, suppls & correspondence

8408060090 Requests 60-day extension to allow public advocate to review & comment on DES Extension necessary due to delay in assigning new counsel
REMIS,S C New Jersey, State of 84/07/31 SCHWENCER,A Licensing Branch 2 4pp 25922 007 24X Fiche 50-354,84/07/31,8408060090

8408080019 Responds to S Remis 840730 request for 60-day extension of deadline for comments on DES S Remis has not shown basis or identified particular matter of concern to warrant extension
CONNER,T B Conner & Wetterhahn 84/08/06 SCHWENCER,A Division of Licensing 1p 25970 308 24X Fiche 50-354,84/08/06,8408080019

8408160486 Comments on DES Operation of facility will have no major impact upon agriculture in area
BRANCO,J C Agriculture, Dept of 84/08/08 SCHWENCER,A Licensing Branch 2 1p 26107 311 24X Fiche 50-354,84/08/08, 8408160486

8408160454 Comments on DES re benthic & fish populations,endangered & threatened species,aquatic,water,terrestrial & aquatic resources & exposure pathways
HIGGINS,B E Commerce, Dept of, Natl Oceanographic & Atmospheric Administration 84/08/10 WAGNER,D H Office of Nuclear Reactor Regulation, Director 2pp 26107 278 24X Fiche 50-354,84/08/10, 8408160454

8408200386 Forwards DES (NUREG-1074),per 840810 telcon w/D Wagner W/o encl
SCHWENCER,A Licensing Branch 2 84/08/10 ALS,E Environmental Protection Agency 3pp 26141 217 24X Fiche 50-354,84/08/10, 8408200386

8408210205 Requests 30-day review period be established for DES soon to be reissued in entirety due to printing errors in original documents Review period of 30 days believed appropriate in view of familiarity w/original
WALKA,R M Environmental Protection Agency 84/08/14 SCHWENCER,A Licensing Branch 2 1p 26184 236 24X Fiche 50-354,84/08/14, 8408210205

8408210326 Requests 30 days from date of receipt to review & comment on reissued DES
WALKA,R M Environmental Protection Agency 84/08/14 SCHWENCER,A Licensing Branch 2 1p 26180 200 24X Fiche 50-354,84/08/14, 8408210326

8408220432 Denies 840731 request for 60-day extension of DES comment period State of NJ desire to obtain consultants for DES review not sufficient justification
SCHWENCER,A Licensing Branch 2 84/08/14 REMIS,S C New Jersey, State of 4pp 26209 339 24X Fiche 50-354,84/08/14,8408220432

8408240165 Offers no comment on DES re transportation aspects
KESSLER,J J , LARIVIERE,P Transportation, Dept of, Federal Highway Administration 84/08/14 Division of Licensing 1p 26236 319
24X Fiche 50-354,84/08/14,8408240165

8408210213 Recommends that groundwater monitoring during plant operation be addressed more thoroughly,per review of DES transmitted on 840629 Statement should indicate which aquifers monitored at wells listed
BLANCHARD,B Interior, Dept of 84/08/15 SCHWENCER,A Licensing Branch 2 1p 26184 012 24X Fiche 50-354,84/08/15,8408210213

DOCKETED ITEMS

8408290005 Forwards comments on DES W/o encl
WOOD, J M Commerce, Dept of, Natl Oceanographic & Atmospheric Administration 84/08/15 WAGNER, D H Office of Nuclear Reactor Regulation, Director 1p 26291 243 24X Fiche 50-354, 84/08/15, 8408290005

8408230083 Confirms 840817 telcon informing that Bournia would grant Dept of Public Advocate 2-day extension for filing comments on DES Comments will be submitted by 840822
REMIS, S C New Jersey, State of 84/08/17 SCHWENCER A Licensing Branch 2 1p 26209 039 24X Fiche 50-354, 84/08/17, 8408230083

--8408230090 Requests 2-day extension for response to DES, based on continuing effort to complete review & provide appropriate comments
REMIS, S C New Jersey, State of 84/08/16 SCHWENCER, A Licensing Branch 2 1p 26209 040 24X Fiche 50-354, 84/08/17, 8408230083

8408240293 Comments on DES (NUREG-1074) Water treatment intake sys, cooling water sys, power transmission sys, groundwater, water use, terrestrial resources, aquatic resources & historical & archaeological sites discussed
MITTL, R L Public Service Electric & Gas Co of New Jersey 84/08/17 SCHWENCER, A Licensing Branch 2 8pp 26236 271 24X Fiche 50-354, 84/08/17, 8408240293

8408270136 Comments on DES DES fails to evaluate cumulative risks & overall environ impacts of Hope Creek & Salem Nuclear Generating Stations Certificate of Svc encl Related correspondence
RODRIGUEZ, J H , REMIS, S , SHAPIRO, R E New Jersey, State of 84/08/21 SCHWENCER, A Licensing Branch 2 4pp 26257 284 24X Fiche 50-354, 84/08/21, 8408270136

8408300304 Ack receipt of DES (NUREG-1074) Future submissions should be sent to Commissioner, State of NJ, Dept of Environ Protection
SILVER, N S New Jersey, State of 84/08/24 SCHWENCER, A Licensing Branch 2 1p 26306 359 24X Fiche 50-354, 84/08/24, 8408300304,

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408060204 Notification of rescheduled 840802 meeting w/util in Bethesda, MD to discuss draft SER items re seismology
WAGNER, D H Licensing Branch 2 84/07/09 SCHWENCER, A Licensing Branch 2 3pp 25936 198 24X Fiche 50-354, 84/07/09, 8408060204

8408010126 Summary of 840531 meeting w/util, Bechtel, MES, Inc, Dames & Moore & AD Little, Inc in Bethesda, MD re riverborne missiles identified as open item in Section 3 5 1 4 of draft SER
WAGNER, D H Licensing Branch 2 84/07/18 Licensing Branch 2 302pp 25873 317 24X Fiche 50-354, 84/07/18, 8408010126

8408010124 Summary of 840713 meeting w/util, Bechtel & GE in Bethesda, MD re draft SER open items identified by Core Performance Branch List of attendees encl
WAGNER, D H Licensing Branch 2 84/07/24 Licensing Branch 2 7pp 25897 134 24X Fiche 50-354, 84/07/24, 8408010124

--8312020297 Forwards proprietary description of fuel performance verification program Description withheld (ref 10CFR2 790)
CHARNLEY, J S General Electric Co 83/11/23 BERLINGER, C H Power Systems Branch 5pp 25897 141 24X Fiche 50-354, 84/07/24, 8408010124

--8402020372 Responds to 831123 ltr proposing substitution of generic vendor surveillance on lead test assemblies for routine licensee surveillance Proposal considered inadequate due to possibility of short- & long-term fuel damage
RUBENSTEIN, L S Assistant Director for Core & Plant Systems 84/01/18 GRIDLEY, R L General Electric Co 3pp 25897 146 24X Fiche 50-354, 84/07/24, 8408010124

8408010219 Forwards resolution to draft SER open items in Sections 2 4 5.3 4 1 & 3 5 1 4 re floating missiles, for review & approval Repts supporting resolution encl
MITTL, R L Public Service Electric & Gas Co of New Jersey 84/07/27 SCHWENCER, A Licensing Branch 2 4pp 25855 075 24X Fiche 50-354, 84/07/27, 8408010219

--8408010224 "Analysis of Likelihood of Waterborne Traffic on Delaware River Impacting Hope Creek Generating Station in Severe Storms "
* Arthur D Little, Inc C-50918 84/07/31 43pp 25855 079 24X Fiche 50-354, 84/07/27, 8408010219

--8408010231 "Hope Creek Generating Station Extreme Event Site Flooding Meteorology "
SMITH, M E , CASTELLI, F P Meteorological Evaluation Services, Inc 84/07/06 23pp 25855 122 24X Fiche 50-354, 84/07/27, 8408010219

--8408010234 "Storm Surge Calculations, Hope Creek Generating Station, Lower Alloways Creek, NJ "
* Public Service Electric & Gas Co of New Jersey 84/07/27 14pp 25855 145 24X Fiche 50-354, 84/07/27, 8408010219

8408080290 Forwards status update of open items identified in draft SER, Section 1 7, current list of items not yet addressed & responses to other open items
MITTL, R L Public Service Electric & Gas Co of New Jersey 84/07/27 SCHWENCER, A Licensing Branch 2 11pp 25965 329 24 Fiche 50-354, 84/07/27, 8408080290

8408080149 Summary of 840628 meeting w/util, Bechtel & Dames & Moore in Bethesda, MD re hydrology open items addressed in draft SER
WAGNER, D Licensing Branch 2 84/07/30 Licensing Branch 2 16pp 25979 027 24X Fiche 50-354, 84/07/30, 8408080149

8408030069 Forwards status of open issues identified in draft SER Section 1 7, list of draft SER sections not provided & resolution of open items & comments received during Power Sys Branch 840417-18 meeting
MITTL, R L Public Service Electric & Gas Co of New Jersey 84/08/01 SCHWENCER, A Licensing Branch 2. 504pp 25907 246 24X Fiche 50-354, 84/08/01, 8408030069

8408080140 Summary of 840724 meeting w/util, Bechtel, GE, Intl Energy Assoc & Conner & Wetterhahn in Bethesda, MD re draft SER open items identified by Matls Engineering Branch
WAGNER, D Licensing Branch 2 84/08/01 Licensing Branch 2 22pp 25979 083 24X Fiche 50-354, 84/08/01, 8408080140

8408130050 Summary of 840711 meeting w/util & Bechtel in Bethesda, MD re draft SER open items identified by Reactor Sys Branch
WAGNER, D Licensing Branch 2 84/08/01 Licensing Branch 2 12pp 26038 317 24X Fiche 50-354, 84/08/01, 8408130050

8408060176 Forwards status of open items identified in Section 1 7 of draft SER & current list identifying draft SER sections not yet provided
MITTL, R L Public Service Electric & Gas Co of New Jersey 84/08/03 SCHWENCER, A Licensing Branch 2 297pp 25929 331 24X Fiche 50-354, 84/08/03, 8408060176

8408090452 Forwards draft SER Sections 17 1-17 5 re QA Updated version of util 840718 ltr re draft SER outstanding sections encl
SCHWENCER, A Licensing Branch 2 84/08/03 MITTL, R L Public Service Electric & Gas Co of New Jersey 11pp 25983 198 24X Fiche 50-354, 84/08/03, 8408090452

8408150173 Summary of 840712 meeting w/util & Bechtel in Bethesda, MD re Radiological Assessment Branch draft SER open items
WAGNER, D H Licensing Branch 2 84/08/07 Licensing Branch 2 21pp 26104 118 24X Fiche 50-354, 84/08/07, 8408150173

8408160170 Forwards listed draft SER sections resulting from review of OL application, per 840305 ltr Remaining open items listed
SCHWENCER, A Licensing Branch 2 84/08/07 MITTL, R L Public Service Electric & Gas Co of New Jersey 48pp 26126 277 24X Fiche 50-354, 84/08/07, 8408160170

8408160487 Summary of 840717 meeting w/util & GE in Bethesda, MD re draft SER open items identified by Matls Engineering Branch in Sections 5 3 1 2, 5 3 1 3 & 5 3 4 List of attendees encl
WAGNER, D H Licensing Branch 2 84/08/07 Licensing Branch 2 25pp 26108 302 24X Fiche 50-354, 84/08/07, 8408160487

8408140336 Forwards status rept of draft SER Section 1 7 open items, draft SER sections not yet provided, draft SER open items & resolutions to items Items identified as complete considered closed Description of unresolved issues requested
MITTL, R L Public Service Electric & Gas Co. of New Jersey 84/08/10 SCHWENCER, A Licensing Branch 2 182pp 26042 117 24X Fiche 50-354, 84/08/10, 8408140336

8408170403 Summary of 840801 meeting w/util, Bechtel, NUTECH & Impell in Bethesda, MD re Structural & Geotechnical Engineering Branch structural audit open items identified in draft SER List of attendees & draft responses encl
WAGNER, D H Licensing Branch 2 84/08/10 Licensing Branch 2 140pp 26134-013 24X Fiche 50-354, 84/08/10, 8408170403

8408160348 Forwards status of open items in Section 1.7 of draft SER, list of draft SER sections not provided, resolutions of open items & FSAR question responses
MITTL, R L Public Service Electric & Gas Co of New Jersey 84/08/13 SCHWENCER, A Licensing Branch 2 150pp 26090 001 24X Fiche 50-354, 84/08/13, 8408160348

8408170336 Forwards GE Design Memos 170-107 & 170-109 & Bechtel Stress Rept Calculation SR10855-SS27 re stiff pipe clamps described in IE Info Notice 83-80 Submittal addresses draft SER Open Item 96
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/14 SCHWENCER,A Licensing Branch 2 2pp 26114 062 24X
Fiche 50-354,84/08/14,8408170336

--8408170339 "Clamp Induced Stress on Hope Creek Recirculation Piping "
FARRELL,C A , ZALIZNYAK,M , THOMPSON,J L General Electric Co
170-107 84/07/27 18pp 26114 064 24X Fiche 50-354,84/08/14,
8408170336

--8408170342 "Clamp Induced Stress on Hope Creek Main Steam Piping Lines C & D "
ZALIZNYAK,M A , FARRELL,C A , THOMPSON,J L General Electric Co
170-109 84/07/27 22pp 26114 082 24X Fiche 50-354,84/08/14,
8408170336

--8408170343 "Study Calculation for Stiff Pipe Clamp Calculation SR10855-SS27 "
HU,C K , CHOI,K , KHLAFALLAH,M Z Bechtel Corp 84/07/31 10pp
26114 104 24X Fiche 50-354,84/08/14,8408170336

8408170103 Forwards resolutions to draft SER open items & responses to FSAR questions.List identifying draft SER sections not yet provided encl
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/15 SCHWENCER,A Licensing Branch 2 578pp 26119 130 24X
Fiche 50-354,84/08/15,8408170103

8408240273 Forwards "Basis for Cable Sys Design,Power Generating Stations " Rept provides basis for 18-inch vertical & 12-inch horizontal cable tray separation criteria,in response to Question 430 51 & draft SER Open Item 245
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/15 SCHWENCER,A Licensing Branch 2 2pp 26225 146 24X
Fiche 50-354,84/08/15,8408240273

--8408240288 "Basis for Cable Sys Design,Power Generating Stations "
* Public Service Electric & Gas Co of New Jersey 71/07/16.
80pp. 26225 148 24X Fiche 50-354,84/08/15,8408240273

8408280201 Forwards status of open items identified in draft SER Section 1 7,list of sections not provided,resolutions to open items & FSAR responses to questions W/64 oversize drawings Aperture cards available in PDR
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/20 SCHWENCER,A Licensing Branch 2 412pp 26270 264 24X
Fiche 50-354,84/08/20,8408280201

8408290134 Forwards "Cold Shutdown/Power Bus Failure Analysis Rept," "High Energy Line Break/Control Sys Failure Analysis," "Common Power/Control Sys Failures Evaluation Rept" & "Common Sensor Failure ," per draft SER open items
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/24 SCHWENCER,A Licensing Branch 2 57pp 26290 001 24X
Fiche 50-354,84/08/24,8408290134

--8408290138 "Cold Shutdown/Power Bus Failure Analysis Rept "
* Public Service Electric & Gas Co of New Jersey 84/08/31
24pp 26290 058 24X Fiche 50-354,84/08/24,8408290134

-8408290144 "High Energy Line Break/Control Sys Failure Analysis "
* Public Service Electric & Gas Co of New Jersey 84/08/31
100pp 26290 082 24X Fiche 50-354,84/08/24,8408290134

8408290149 "Common Power/Control Sys Failures Evaluation Rept "
* Public Service Electric & Gas Co of New Jersey 84/08/31
53pp 26290 194 24X Fiche 50-354,84/08/24,8408290134

408290160 "Common Sensor Failure Evaluation Rept "
* Public Service Electric & Gas Co of New Jersey 84/08/31
60pp. 26290 247 24X Fiche 50-354,84/08/24,8408290134

Security, medical, emergency & fire protection plans

)100065 Forwards revised emergency plan,incorporating resolution of 'C comments from 840621 emergency preparedness meeting fidavit encl
TTL,R L Public Service Electric & Gas Co of New Jersey.
/07/20 SCHWENCER,A Licensing Branch 2 2pp 25989 053 24X
che 50-354,84/07/20,8408100065

08100067 Revised "Hope Creek Generating Station Emergency Plan. "
* Public Service Electric & Gas Co of New Jersey 84/07/20
08pp 25989.055 24X Fiche 50-354,84/07/20,8408100065

8408010227 Requests addl info needed to complete FSAR review,including info re fire protection for solid waste product in storage area & justification for departure from/Reg Guide 1 52
Response should be provided by 840813
SCHWENCER,A Licensing Branch 3 84/07/24 MITTL,R L Public Service Electric & Gas Co of New Jersey 3pp 25873 277 24X
Fiche 50-354,84/07/24,8408010227

8408070147 Advises that 840521 Rev 2 to security plan re proposed vital area identification program does not satisfy criteria contained in encl Review Guidelines 17 Amended plan should be submitted by 840810
SCHWENCER,A Licensing Branch 2 84/08/01 MITTL,R L Public Service Electric & Gas Co of New Jersey 14pp 25957 120 24X
Fiche 50-354,84/08/01,8408070147

8408200151 Notification of 840822 meeting w/util in Silver Spring,MD to discuss vital areas submittal & safeguards matl Meeting closed to public
WAGNER,D H Licensing Branch 2 84/08/10 SCHWENCER,A Licensing Branch 2 4pp 26142 325 24X Fiche 50-354,84/08/10,8408200151

8408210408 Informs that FEMA does not intend to conduct full-scale evaluation of Hope Creek 1985 exercise Since Salem Unit 1 OL issued prior to 820713,full participation in 1985 not required by NRC or FEMA rules
KRIMM,R W Federal Emergency Management Agency 84/08/13
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 26177 256 24X Fiche 50-000,84/08/13,
8408210408

8408170052 Forwards "Control Room Design Review Summary Rept - Hope Creek Generating Station," in response to Generic Ltr 82-33, Item 5 (NUREG-0737,Suppl 1) Meeting requested
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/14 SCHWENCER,A Licensing Branch 2 2pp 26118 133 24X
Fiche 50-354,84/08/14,8408170052

--8408170056 "Control Room Design Review Summary Rept - Hope Creek Generating Station "
* Essex Corp 84/08/06 210pp 26118 135 24X
Fiche 50-354,84/08/14,8408170052

8408290002 Updates status of safety parameter display sys,per 840402 commitment re Generic Ltr 82-33 Plant-specific displays & analysis will be available for NRC review in Dec 1984
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/24 SCHWENCER,A Licensing Branch 2 2pp 26338 164 24X
Fiche 50-354,84/08/24,8408290002

E Adjudicatory correspondence

8408010246 Motion to compel designation of witnesses & availability for depositions &/or to dismiss proceeding ASLB should set date for Public Advocate to furnish info re expert witnesses Certificate of Svc encl Related correspondence
CONNER,T B Public Service Electric & Gas Co of New Jersey
CONNER,T B Conner & Wetterhahn DSB 671 84/07/30 Atomic Safety and Licensing Board Panel 20pp 25855 347 24X
Fiche 50-354,84/07/30,8408010246

8408090255 Motion for extension of time to respond to applicant motion to compel designation of witnesses & availability for depositions &/or dismiss proceeding Certificate of Svc encl Related correspondence
REMIS,S C New Jersey, State of DSB 857 84/08/03 Atomic Safety and Licensing Board Panel 5pp 25972 280 24X
Fiche 50-354,84/08/03,8408090255

8408080389 Answer opposing Public Advocate motion for extension of time to respond to applicant 840730 motion to compel Public Advocate to designate expert witnesses & make available for depositions W/Certificate of Svc Related correspondence
RADER,R M Public Service Electric & Gas Co. of New Jersey
RADER,R M Conner & Wetterhahn DSB 836 84/08/07 Atomic Safety and Licensing Board Panel 132pp 25974 103 24X
Fiche 50-354,84/08/07,8408080389

8408140543 Confirms 840807 telcon re Superior Court of NJ opinion authorizing Public Advocate of NJ to intervene in OL proceeding Related correspondence
REMIS,S C New Jersey, State of DSB 823 84/08/07 MILLER,M E
Atomic Safety and Licensing Board Panel 9pp 26061 227 24X
Fiche 50-354,84/08/07,8408140543

8408130102 Response to intervenor 840803 motion for extension of time to respond to applicant 840730 motion to compel designation of witnesses Extension of 30 days sufficient Certificate of Svc encl
DEWEY,L S Hearing Branch 3 DSB 909 84/08/08 Atomic Safety and Licensing Board Panel 4pp 26007 329 24X
Fiche 50-354,84/08/08,8408130102

8408140024 Order denying Public Advocate of NJ 840730 request for 60-day extension of time to respond to applicant 840730 motion Public Advocate of NJ witnesses must be identified by 840820 Served on 840813
MILLER,M E Atomic Safety and Licensing Board Panel DSB 951
84/08/10 New Jersey, State of 3pp 26044 191 24X
Fiche 50-354,84/08/10,8408140024

8408280447 Response to ASLB 840810 order establishing 840820 as date to identify witnesses & to make witnesses available for depositions within 2 wks Addl time requested Certificate of Svc encl
SHAPIRO,R E , REMIS,S C New Jersey, State of DSB 359 84/08/20
4pp 26280 330 24X Fiche 50-354,84/08/20,8408280447

8408290014 Petition for addl time to make expert witnesses available for depositions Scheduling of depositions in Oct requested Certificate of Svc encl Related correspondence
SHAPIRO,R E , REMIS,S C New Jersey, State of DSB 360 84/08/20
Atomic Safety and Licensing Board Panel 18pp 26291 217 24X
Fiche 50-354,84/08/20,8408290014

8408280448 Forwards "Environ Qualification Summary Rept " Related correspondence
CONNER,T B Conner & Wetterhahn CONNER,T B Public Service Electric & Gas Co of New Jersey DSB 363 84/08/22 MILLER,M E , MORRIS,P A , SCHINK,D R Atomic Safety and Licensing Board Panel
143pp 26281 123 24X Fiche 50-354,84/08/22,8408280448

8408280449 Notice of appearance in proceeding
SHAPIRO,R E New Jersey, State of DSB 355 84/08/23 1p
26280 346 24X Fiche 50-354,84/08/23,8408280449

8408280223 Motion to dismiss proceeding as result of default by public advocate in not complying w/ASLB 840810 order to identify witnesses by 840820 & answer opposing Intervenor motion for addl delay Certificate of Svc encl
RADER,R M Public Service Electric & Gas Co of New Jersey
RADER,R M Conner & Wetterhahn DSB 323 84/08/24 Atomic Safety and Licensing Board Panel 17pp 26274 347 24X
Fiche 50-354,84/08/24,8408280223

H General correspondence

8408070284 Submits change of address & telephone numbers for documentation re facility
OTTO,H W Delaware, State of 84/07/31 WAGNER,D M Division of Licensing 1p 25948 109 24X Fiche 50-354,84/07/31,8408070284

8408100003 Requests that author & FM Parkowski be removed from facility svc list & RJ Touhey be added
VASUKI,N C Delaware Solid Waste Authority 84/08/08 WAGNER,D Licensing Branch 2 1p 25987 307 24X Fiche 50-354,84/08/08, 8408100003

8408280353 Requests deletion of deputy atty general,State of NJ, from mailing list to eliminate redundant copies
KIMMELMAN,I I , ENGEL,R F New Jersey, State of 84/08/20 NRC - No Detailed Affiliation Given 1p 26282 252 24X
Fiche 50-354,84/08/20,8408280353

K Utility Final Safety Analysis Report (FSAR) & amends

8408230352 Forwards Amend 7 to FSAR (filed in PDR Category K)
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/20 SCHWENCER,A Licensing Branch 2 3pp 26325 298 24X
Fiche 50-354,84/08/20,8408230352

--8408230371 Amend 7 to FSAR for Hope Creek Generating Station (filed in PDR Category K) W/167 oversize drawings Aperture cards available in PDR
* Public Service Electric & Gas Co of New Jersey 84/08/20
357pp 26326 006 24X Fiche 50-354,84/08/20,8408230352

8408310198 Forwards affidavit certifying distribution of Amend 7 to FSAR for Hope Creek Generating Station & Amend 4 to environ rept - OL stage,per 10CFR2 101 Environ rept - OL distribution list & ack receipt forms encl
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/28 Office of Nuclear Reactor Regulation, Director
SCHWENCER,A Licensing Branch 2 16pp 26318 292 24X
Fiche 50-354,84/08/28,8408310198

O Inspection reports, IE Bulletins & correspondence

8408150650 Forwards IE Insp Rept 50-354/84-08 on 840605-08 No violations noted
MARTIN,T T. Division of Engineering & Technical Programs. 84/07/24
MARTIN,T T Public Service Electric & Gas Co of New Jersey 2pp.
26079 092 24X Fiche 50-354,84/07/24,8408150650

--8408150653 IE Insp Rept 50-354/84-08 on 840605-08 No violations noted Major areas inspected power block heave/settlement measurement program records & review of corrective actions associated w/previously identified const deficiency
VARELA,A A , DURR,J P Region 1, Office of Director 84/07/06
5pp 26079 094 24X Fiche 50-354,84/07/24,8408150650

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408200364 Forwards IE Insp Rept 50-354/84-05 on 840514-0624 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 84/07/31
MARTIN,T J Public Service Electric & Gas Co of New Jersey 2pp
26140 001 24X Fiche 50-354,84/07/31,8408200364

--8408200365 Notice of violation from insp on 840514-0624
* Region 1, Office of Director 84/07/31 2pp 26140 003 24X
Fiche 50-354,84/07/31,8408200364

--8408200366 IE Insp Rept 50-354/84-05 on 840514-0624 Noncompliance noted improper tie-wrapping of safety-related cable, unauthorized mod of torquing of anchor bolts for conduit support & improper installation of control room shims
BATEMAN,W H , MCCABE,E C Region 1, Office of Director 84/07/23
11pp 26140 005 24X Fiche 50-354,84/07/31,8408200364

8408070323 Ack receipt of 840629 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/84-06 Corrective actions will be examined during future insp
MARTIN,T T Division of Engineering & Technical Programs 84/08/01
MARTIN,T J Public Service Electric & Gas Co of New Jersey 4pp
25945 238 24X Fiche 50-354,84/08/01,8408070323

--8408070326 Responds to NRC 840531 ltr re violations noted in IE Insp Rept 50-354/84-06 Corrective actions rear bracket attachments on pipe supports reinspected & QC engineers given addl training in spec requirements
MARTIN,T J Public Service Electric & Gas Co of New Jersey
84/06/29 MURLEY,T E Region 1, Office of Director 2pp
25945 242 24X Fiche 50-354,84/08/01,8408070323

8408200495 Forwards IE Insp Rept 50-354/84-09 on 840611-15 No violations noted.
MARTIN,T T Division of Engineering & Technical Programs 84/08/01
MARTIN,J T Public Service Electric & Gas Co of New Jersey 4pp
26138-290 24X Fiche 50-354,84/08/01,8408200495

--8408200504 IE Insp Rept 50-354/84-09 on 840611-15 No violations noted Major areas inspected previously identified items, electrical cables, termination, HVAC & related QA/QC activities
FINKEL,A , CHEH,U , CHEUNG,L Region 1, Office of Director
84/07/19 8pp 26138 294. 24X Fiche 50-354,84/08/01,8408200495

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp. 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067:158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120

8408280066 Responds to IE Bulletin 83-07 re fraudulent products from Ray Miller Inc Procedures for assuring quality of vendor-supplied items outlined
MARTIN,T J Public Service Electric & Gas Co of New Jersey
84/08/08 MURLEY,T E Region 1, Office of Director 3pp
26261.217 24X Fiche 50-354,84/08/08,8408280066

8408280089 Responds to 840312 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " Century series relays used.Magnetic coil assemblies replaced w/Tefzel coil spools
MARTIN,T T Public Service Electric & Gas Co of New Jersey,
84/08/08 MURLEY,T E. Region 1, Office of Director. 3pp
26261.184 24X Fiche 50-354,84/08/08,8408280089

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12Spp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408170336 Forwards GE Design Memos 170-107 & 170-109 & Bechtel Stress Rept Calculation SR10855-SS27 re stiff pipe clamps described in IE Info Notice 83-80 Submittal addresses draft SER Open Item 96
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/08/14 SCHWENCER,A Licensing Branch 2 2pp 26114 062 24X Fiche 50-354,84/08/14,8408170336

--8408170339 "Clamp Induced Stress on Hope Creek Recirculation Piping " FARRELL,C A , ZALIZNYAK,M , THOMPSON,J L General Electric Co 170-107 84/07/27 18pp 26114 064 24X Fiche 50-354,84/08/14, 8408170336

--8408170342 "Clamp Induced Stress on Hope Creek Main Steam Piping Lines C & D "
ZALIZNYAK,M A , FARRELL,C A , THOMPSON,J L General Electric Co 170-109 84/07/27 22pp 26114 082 24X Fiche 50-354,84/08/14, 8408170336

--8408170343 "Study Calculation for Stiff Pipe Clamp Calculation SR10855-SS27 "
HU,C K , CHOI,K , KHLAFALLAH,M Z Bechtel Corp 84/07/31 10pp 26114 104 24X Fiche 50-354,84/08/14,8408170336

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

I Reportable occurrences, LERs & related correspondence

8408240332 Submits annotated requests for followup on potentially generic problem in encl Part 21 rept from Basler Electric re SCRs on nuclear exciters mounted w/too much pressure
NORELIUS,C E Division of Project & Resident Programs 84/04/25
JORDAN,E L Director's Office, Office of Inspection and Enforcement 1p 26225 303 24X Fiche 50-000,84/04/25,8408240332

08100085 Interim deficiency rept re cracked bosses on Colt Industries diesel generator lube oil pump discharge nozzles Initially reported on 840425 Design for tapered thread adapter changed Next rept expected by 840807 Reportable per Part 21
MARTIN,T J Public Service Electric & Gas Co. of New Jersey
84/07/18 MURLEY,T E Region 1, Office of Director 2pp 25990 198 24X Fiche 50-354,84/07/18,8408100085

08100140 Final deficiency rept re economizing resistors supplied by Basler Electric on emergency diesel generator exciters Initially reported on 840627 Corrective actions implemented by supplier & documented in NonconPormance Rept 4040
MARTIN,T J Public Service Electric & Gas Co. of New Jersey
84/07/24 MURLEY,T E Region 1, Office of Director 3pp 25988 267 24X Fiche 50-354,84/07/24,8408100140

8408100096 Interim deficiency rept re defective ITT Grinnell capstan springs in mechanical shock arrestors Initially reported on 831024 Springs replaced in 25 of 86 snubbers at Pacific Scientific Final rept will be submitted on 840831
MARTIN,T J Public Service Electric & Gas Co of New Jersey
84/07/25 MURLEY,T E Region 1, Office of Director 2pp 25990 278 24X Fiche 50-354,84/07/25,8408100096

8408300342 Significant const deficiency rept re cracked bosses on diesel generator lube oil pump discharge nozzles Initially reported on 840425 Colt Industries rescheduled onsite insp of diesel generators Next rept expected by 840928
MARTIN,T J Public Service Electric & Gas Co of New Jersey
84/08/07 MURLEY,T E Region 1, Office of Director 2pp 26308 340 24X Fiche 50-354,84/08/07,8408300342

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

S Reportable occurrences, LERs & related correspondence

8408240332 Submits annotated requests for followup on potentially generic problem in encl Part 21 rept from Basler Electric re SCRs on nuclear exciters mounted w/too much pressure
NORELIUS,C E Division of Project & Resident Programs 84/04/25
JORDAN,E L Director's Office, Office of Inspection and Enforcement 1p 26225 303 24X Fiche 50-000,84/04/25,8408240332

8408100085 Interim deficiency rept re cracked bosses on Colt Industries diesel generator lube oil pump discharge nozzles Initially reported on 840425 Design for tapered thread adapter changed Next rept expected by 840807 Reportable per Part 21
MARTIN,T J Public Service Electric & Gas Co of New Jersey
84/07/18 MURLEY,T E Region 1, Office of Director 2pp 25990 198 24X Fiche 50-354,84/07/18,8408100085

DOCKET 50-356 UNIV OF ILLINOIS RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408010302 Forwards IE Insp Repts 50-151/84-01 & 50-356/84-01 on 840619-22 No noncompliance noted
NORELIUS,C E Region 3, Office of Director 84/07/19 MILEY,G H Illinois, Univ of, Urbana, IL 2pp 25866 117 24X
Fiche 50-151,84/07/19,8408010302

--8408010308 IE Insp Repts 50-151/84-01 & 50-356/84-01 on 840619-22 No noncompliance noted Major areas inpected requalification training fuel handling & surveillance activities,radiation control practices & emergency planning
TAUBLING,T N Region 3, Office of Director 84/07/18 10pp 25866 119 24X Fiche 50-151,84/07/19,8408010302

8408030276 Certifies nuclear reactor committee formal approval of additions & changes to emergency plan on 840723 Last sentence in Section 3 4 3 changed for clarity
BECK,G P , HOPKE,P K , MILEY,G H Illinois, Univ of, Urbana, IL
84/07/24 THOMAS,C O Standardization & Special Projects Branch
1p 25917 258 24X Fiche 50-151,84/07/24,8408030276

Q Inspection reports, IE Bulletins & correspondence

8408010302 Forwards IE Insp Repts 50-151/84-01 & 50-356/84-01 on 840619-22 No noncompliance noted
NORELIUS,C E Region 3, Office of Director 84/07/19 MILEY,G H Illinois, Univ of, Urbana, IL 2pp 25866 117 24X
Fiche 50-151,84/07/19,8408010302

--8408010308 IE Insp Repts 50-151/84-01 & 50-356/84-01 on 840619-22 No noncompliance noted Major areas inpected requalification training fuel handling & surveillance activities,radiation control practices & emergency planning
TAUBLING,T N Region 3, Office of Director THOMAS,C C , HYDER,J E Los Alamos Scientific Laboratory 84/07/18 10pp 25866 119 24X Fiche 50-151,84/07/19,8408010302

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET 50 358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, 'Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

G Adjudicatory correspondence

8408070461 Transmittal of info re util 840320 motion for withdrawal of OL application Fuel removed from site, steam supply sys modified & CRD mechanisms removed Certificate of Svc encl
WETTERHAHN, M J Cincinnati Gas & Electric Co WETTERHAHN, M J
Conner & Wetterhahn DSB 775 84/08/02 4pp 25940 296 24X
Fiche 50-358, 84/08/02, 8408070461

8408080201 Ack receipt of 840802 info re motion for withdrawal of application in proceeding ASLB will act promptly on motion upon receipt of staff recommendations Served on 840807
FRYE, J H Atomic Safety and Licensing Board Panel DSB 822
84/08/07 WETTERHAHN, M J Conner & Wetterhahn 1p 25960 265
24X Fiche 50-358, 84/08/07, 8408080201

8408210366 Further answer in support of applicant 840320 motion for withdrawal of application Termination order conditioned on implementation of applicant 840601 restoration plan, recommended Insp summary encl
TREBY, S A Hearing Branch 1 DSB 185 84/08/17 Atomic Safety and Licensing Board Panel 11pp 26181 001 24X
Fiche 50-358, 84/08/17, 8408210366

--8408210374 Affidavit of GE LaRoche in support of NRC further answer to applicant 840320 motion for withdrawal of application Certificate of Svc encl
LAROCHE, G E Environmental & Hydrologic Engineering Branch
84/08/14 6pp 26181 012 24X Fiche 50-358, 84/08/17, 8408210366

8408310104 Memorandum & order granting applicant 840320 motion to withdraw application for OL & to dismiss proceeding subj to implementation of util 840601 site restoration plan Served on 840830
LINENBERGER, C , FRYE, J H Atomic Safety and Licensing Board Panel
DSB 393 84/08/29 Cincinnati Gas & Electric Co 9pp
26322 234 24X Fiche 50-358, 84/08/29, 8408310104

H General correspondence

8405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
DIRCKS, W J Office of the Executive Director for Operations
84/05/04 LUGAR, R G Senate 7pp 24524 325 24X
Fiche 50-000, 84/05/04, 8405180145

--8405180152 Requests response to encl W & V Smelser 840210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
LUGAR, R G Senate 84/03/14 PALLADINO, N Commissioners 3pp
24524 331 24X Fiche 50-000, 84/05/04, 8405180145

I Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408230474 Forwards IE Insp Rept 50-358/84-05 on 840427-0716 No noncompliance noted
WARNICK, R F Region 3, Office of Director 84/08/03 SCHOTT, J R
Cincinnati Gas & Electric Co 2pp 26212 206 24X
Fiche 50-358, 84/08/03, 8408230474

--8408230480 IE Insp Rept 50-358/84-05 on 840427-0716 No noncompliance or deviations noted Major areas inspected verification of actions re proposed withdrawal of application & transfer, packaging & shipment of irradiated fuels
GRANT, W B , FORNEY, W L Region 3 Office of Director 84/08/02
6pp 26212 208 24X Fiche 50-358, 84/08/03, 8408230474

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210366 Further answer in support of applicant 840320 motion for withdrawal of application Termination order conditioned on implementation of applicant 840601 restoration plan, recommended Insp summary encl
TREBY, S A Hearing Branch 1 DSB 185 84/08/17 Atomic Safety and Licensing Board Panel 11pp 26181 001 24X
Fiche 50-358, 84/08/17, 8408210366

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000, 84/08/21, 8408210142

R Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000, 84/04/13, 8408240348

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8408130220 Forwards list of open items requiring resolution before low power operation can be endorsed by region
ENGELKEN, R H Region 5, San Francisco, Office of the Director (81/03/01) 82/01/04 EISENHUT, D G Division of Licensing 9pp 26008 185 24X Fiche 50-361, 82/01/04, 8408130220

F Security, medical, emergency & fire protection plans

8408030123 Forwards Rev 2 to physical security plan & description of changes Encls withheld (ref 10CFR73 21)
HAYNES, J G Southern California Edison Co 84/07/25 MARTIN, J B
Region 5, Office of Director 1p 25916 119 24X
Fiche 50-206, 84/07/25, 8408030123

8408170130 Forwards Amends 78, 23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas
PAULSON, W A Operating Reactors Branch 5 84/08/07 BASKIN, K
Southern California Edison Co 5pp 26134 302 24X
Fiche 50-206, 84/08/07, 8408170130

--8408170143 Amends 78, 23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively, approving security plan revs which consolidate & reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary
PAULSON, W A Operating Reactors Branch 5 84/08/07 6pp
26134 307 24X Fiche 50-206, 84/08/07, 8408170130

--8408170155 Safety evaluation supporting Amends 78, 23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/07 5pp
26134 313 24X Fiche 50-206, 84/08/07, 8408170130

8408200335 Forwards responses to IE Emergency Appraisal Repts 50-361/84-08 & 50-362/84-07 Documents re verification of computer dose projection program available for exam Encl describes test sequence & parameters, hand calculations
RAY, H B Southern California Edison Co 84/08/07 MARTIN, J B
Region 5, Office of Director 16pp 26133 359 24X
Fiche 50-361, 84/08/07, 8408200335

8408130450 Advises that 840523 Revs 1-13 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
MCQUEEN, A D Region 5, Office of Director 84/08/08 HAYNES, J G
Southern California Edison Co 4pp 26004 359 24X
Fiche 50-206, 84/08/08, 8408130450

8408230306 Advises that 840131 submittal on detailed control room design review does not meet all requirements of Suppl 1 to NUREG-0737 Review did not include task analysis Addl significant concerns listed
KNIGHTON, G W Licensing Branch 3 84/08/09 BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co
3pp 26236 102 24X Fiche 50-361, 84/08/09, 8408230306

8408310285 Forwards Safeguards Insp Repts 50-206/84-18, 50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 10CFR2 790 & 73 21)
SCHUSTER, M D Region 5, Office of Director 84/08/15 BASKIN, K B
Southern California Edison Co 2pp 26333 288 24X
Fiche 50-206, 84/08/15, 8408310285

8408230114 Informs that 840613 rev to emergency plan compatible w/provisions of 10CFR50 47, App E & Rev 1 to NUREG-0654
SCHUSTER, M D Region 5, Office of Director 84/08/16 MEDFORD, M O
Southern California Edison Co 3pp 26347 274 24X
Fiche 50-206, 84/08/16, 8408230114

P Operating license stage documents & correspondence

8408210042 Notification of contract execution, Mod 4, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " Contractor MIT
HOPPER, A Administrative Contracts Branch FIN B-6898 84/06/12
VOLLMER, R Division of Engineering JACKSON, R NRC - No Detailed Affiliation Given 1p 26195 176 24X Fiche: 50-206, 84/06/12, 8408210042

--8408210046 Mod 4, deobligating unliquidated fee remaining in contract, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station "
AKI, K Massachusetts Institute of Technology, Cambridge, MA
HAGAN, T F Division of Contracts FIN B-6898 84/06/12 1p
26195 177 24X Fiche 50-206, 84/06/12, 8408210042

8408010240 Forwards C-E nonproprietary & proprietary "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station Units 2 & 3" & "CPC/CEAC Software Mods " Proprietary repts withheld (ref 10CFR2 790)
MEDFORD, M O Southern California Edison Co 84/07/20
KNIGHTON, G W Licensing Branch 3 13pp 25855 001 24X
Fiche 50-361, 84/07/20, 8408010240

--8408010247 Nonproprietary "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station, Units 2 & 3 " Info deleted
* Combustion Engineering, Inc CEN-284(S)-NP 84/06/30 35pp
25855 014 24X Fiche 50-361, 84/07/20, 8408010240

--8408010256 Nonproprietary "CPC/CEAC Software Mods for San Onofre Nuclear Generating Station Units 2 & 3 " Info deleted
* Combustion Engineering, Inc CEN-281(S)-NP 84/07/31 24pp
25855 050 24X Fiche 50-361, 84/07/20, 8408010240

8408090208 Forwards draft memo re boron injection test, which will be finalized after comments received Final memo will satisfy final milestone defined in 189, "Boron Mixing & Cooldown Under Accident Conditions "
PRATT, W T Brookhaven National Laboratory FIN A-3368 84/07/30
LIANG, C Y Reactor Systems Branch 18pp 25971 193 24X
Fiche 50-206, 84/07/30, 8408090208

8408060080 Forwards response to questions re Proposed Change NPF-10/15-138 re CEA position & insertion limits CEA software changes conducted per Rev 2 to CEN-39(A)
MEDFORD, M O Southern California Edison Co 84/08/01
KNIGHTON, G W Licensing Branch 3 6pp 25933 209 24X
Fiche 50-361, 84/08/01, 8408060080

8408090424 Forwards request for addl info re procedures generation package
KNIGHTON, G W Licensing Branch 3 84/08/01 BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co
5pp. 25984 305 24X Fiche 50-361, 84/08/01, 8408090424

8408270409 Forwards proprietary & nonproprietary Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept," Rev 0 to "CPC/CEAC Sys Phase II ," & Rev 0 to "SONGS-2 Cycle 1 " Proprietary repts withheld (ref 10CFR2 790)
MEDFORD, M O Southern California Edison Co 84/08/01
KNIGHTON, G W Licensing Branch 1 2pp 26238 001 24X
Fiche 50-361, 84/08/01, 8408270409

--8408270412 Nonproprietary version of Rev 0 to "CPC/CEAC Sys Phase II Software Verification Test Rept "
* Combustion Engineering, Inc CEN-269(S)-NP R00 84/03/31
25pp 26238 003 24X Fiche 50-361, 84/08/01, 8408270409

--8408270416 Nonproprietary version of Rev 0 to "SONGS-2 Cycle 1, CPC & CEAC Data Base "
* Combustion Engineering, Inc CEN-266(S)-NP R00 84/03/31
66pp 26238 029 24X Fiche 50-361, 84/08/01, 8408270409

--8408270418 Nonproprietary version of Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept "
* Combustion Engineering, Inc CEN-176(S)-NP R02 84/03/31
27pp 26238 096 24X Fiche 50-361, 84/08/01, 8408270409

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche: 50-000, 84/08/06, 8408070110

8408090187 Forwards application for Amends 27 & 13 to Licenses NPF-10 & NPF-15, respectively, revising Tech Specs re refueling machines, reactor protective instrumentation & ECCS subsys
BASKIN, K P Southern California Edison Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25971 245
24X Fiche 50-361, 84/08/07, 8408090187

--8408090194 Application for amends to Licenses NPF-10 & NPF-15, revising Tech Specs re refueling machine, reactor protective instrumentation, ECCS subsys & steam generators
BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co HOYT, G W Anaheim, CA 84/08/02 14pp
25971 249 24X Fiche 50-361, 84/08/07, 8408090187

--8408090201 Proposed Tech Spec changes, adding note which exempts use of refueling machine for coupling/uncoupling & verification of coupling/uncoupling of control element assemblies
* Southern California Edison Co 84/08/07 100pp 25971 264
24X Fiche 50-361, 84/08/07, 8408090187

DOCKETED ITEMS

8408100091 Resubmits info re proposed changes to Licenses NPF-10 & NPF-15 Tech Specs in form specified by NRC 840416 request for addl info Info extracted rrom original submittals
MEDFORD,M O Southern California Edison Co 84/08/07
KNIGHTON,G W Licensing Branch 3 73pp 25990 202 24X
Fiche 50-361,84/08/07,8408100091

8408170130 Forwards Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15,respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas
PAULSON,W A Operating Reactors Branch 5 84/08/07 BASKIN,K
Southern California Edison Co HOLCOMBE,J C San Diego Gas & Electric Co 5pp 26134 302 24X Fiche 50-206,84/08/07,8408170130

--8408170143 Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15, respectively,approving security plan revs which consolidate & reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary
PAULSON,W A Operating Reactors Branch 5 84/08/07 6pp 26134 307 24X Fiche 50-206,84/08/07,8408170130

--8408170155 Safety evaluation supporting Amends 78,23 & 12 to Licenses DPR-13,NPF-10 & NPF-15,respectively
* Office of Nuclear Reactor Regulation, Director 84/08/07 5pp 26134 313 24X Fiche 50-206,84/08/07,8408170130

8408100115 Documents 840723 discussion re design of proposed gravity-feed auxiliary feedwater pump motor lube oil cooling sys as alternate to forced-feed design described in util 830307 ltr Formal endorsement requested by 840821
MEDFORD,M O Southern California Edison Co 84/08/08
KNIGHTON,G W Licensing Branch 3 3pp 25988 262 24X
Fiche 50-361,84/08/08,8408100115

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408240267 Forwards fee balance to complete required remittance for 840125 Proposed Change NPF-10/15-144
MEDFORD,M O Southern California Edison Co 84/08/21 MILLER,W O
License Fee Management Branch 1p 26222 358 24X
Fiche 50-361,84/08/21,8408240267

8408240294 Application for amend to License NPF-10,revising Tech Specs re refueling water storage tank vol required in Modes 5 & 6 & boric acid storage tank concentration/vol required in Modes 1-6 Fee paid
MEDFORD,M O Southern California Edison Co 84/08/21
KNIGHTON,G W Licensing Branch 3 4pp 26226 019 24X
Fiche 50-361,84/08/21,8408240294

--8408240297 Proposed Tech Specs revising refueling water storage tank vol required in Modes 5 & 6 & boric acid storage tank concentration/vol required in Modes 1-6
* Southern California Edison Co 84/08/21 10pp 26226 023
24X Fiche 50-361,84/08/21,8408240294

8408270325 Advises that Amend 7 to Topical Rept SCE-1-A, "QA Program," consistent w/provisions of 10CFR50 54(a) & acceptable
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 84/08/21 BASKIN,K P Southern California Edison Co 1p 26244 187 24X Fiche 50-206,84/08/21,8408270325

8408300163 Application for amend to Licenses NPF-10 & NPF-15,revising Tech Specs re reactivity control sys Fee paid
MEDFORD,M O Southern California Edison Co 84/08/27
KNIGHTON,G W Licensing Branch 3 1p 26305 291 24X
Fiche 50-361,84/08/27,8408300163

--8408300165 Proposed Tech Specs re reactivity control sys
* Southern California Edison Co 84/08/27 28pp 26305 297
24X Fiche 50-361,84/08/27,8408300163

G Inspection reports, IE Bulletins & correspondence

8408130293 Forwards recommended additions/revs to license conditions & comments on draft low power license re results of insp efforts Util preparations to implement QA program adequate
ENGELKEN,R H Region 5, San Francisco, Office of the Director (81/03/01) 82/02/10 EISENHUT,D G Division of Licensing 3pp 26010 004 24X Fiche 50-361,82/02/10,8408130293

8408090001 Forwards IE Insp Repts 50-361/84-20 & 50-362/84-20 84061B-21 No violations noted
WENSLAWSKI,F A Region 5, Office of Director 84/07/23
BASKIN,K P Southern California Edison Co 2pp 25994 330
Fiche 50-361,84/07/25,8408090001

--8408090004 IE Insp Repts 50-361/84-20 & 50-362/84-20 on 8406 violations noted Major areas inspected confirmatory measurements for radioactivity
HAMADA,G, NORTH,H , YUHAS,G Region 5, Office of Director 84/07/24 9pp 25994 332 24X Fiche 50-361,84/07/25,8408

8407250229 IE Info Notice 84-57, "Operating Experience re Mois Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineerin Response (Post 830103) 84/07/27 Consolidated Edison Co York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,840

8408090043 Forwards IE Insp Repts 50-361/84-19 & 50-362/84-19 c 840605-08 No violations noted
BISHOP,T W Region 5, Office of Director 84/07/27 BASKIN
Southern California Edison Co 1p 25992 123 24X
Fiche 50-361,84/07/27,8408090043

--8408090045 IE Insp Repts 50-361/84-19 & 50-362/84-19 on 84060 violations noted Major areas inspected precritical,low powe & power ascension test results data
PEREIRA,D B , PATE,R J Region 5, Office of Director 84/
8pp 25992 124 24X Fiche 50-361,84/07/27,8408090043

8408140056 Forwards latest facility attachment prepared by IAEA including all review & insp results Encls withheld (ref 10CFR2 790)
KNIGHTON,G W Licensing Branch 3 84/07/27 BASKIN,K P S
California Edison Co HOLCOMBE,J C San Diego Gas & Electri
2pp 26061 264 24X Fiche 50-361,84/07/27,8408140056

8408070411 Responds to IE Bulletin 84-02, "Failures of GE Type Relays in Use in Class IE Safety Sys " Thirty-one relays found at Unit 1 will be replaced by 860312
MEDFORD,M O Southern California Edison Co 84/07/30 MART
Region 5, Office of Director 3pp 25942 170 24X
Fiche 50-206,84/07/30,8408070411

8408060112 Proposes method of insp of low pressure turbine disc ultrasonic indications Discs will be inspected prior to startup following second refueling outage;per License Condition 2 C (15) & 2 C (13)
MEDFORD,M O Southern California Edison Co 84/08/01
KNIGHTON,G W Licensing Branch 3 2pp 25925 307 24X
Fiche 50-361,84/08/01,8408060112

8408140260 Provides addl response to IE Insp Repts 50-361/84-14 50-362/84-14 on 840504 & 07 Evaluation & actions taken as result of 840503 increase in RCS radioactivity described
RAY,H B Southern California Edison Co 84/08/01 MARTIN,J
Region 5, Office of Director 3pp 26055 330 24X
Fiche 50-361,84/08/01,8408140260

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of St Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respi Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408

8408200335 Forwards responses to IE Emergency Appraisal Repts 50-361/84-08 & 50-362/84-07 Documents re verification of computer dose projection program available for exam Encl describes test sequence & parameters;hand calculations
RAY,H B Southern California Edison Co 84/08/07 MARTIN,J
Region 5, Office of Director 16pp 26133 359 24X
Fiche 50-361,84/08/07,8408200335

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (830103) 84/08/10 Consolidated Edison Co of New York, In 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, 'Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408310285 Forwards Safeguards Insp Repts 50-206/84-18, 50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 10CFR2 790 & 73 21)
SCHUSTER, M D Region 5, Office of Director 84/08/15 BASKIN, K D
Southern California Edison Co 2pp 26333 288 24X
Fiche 50-206, 84/08/15, 8408310285

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408230223 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/84-14 & 50-362/84-14 Ltr dtd 840801 adequately responds to NRC 840725 request
SCARANO, R A Division of Radiological Safety & Safeguards Program
84/08/17 BASKIN, K P Southern California Edison Co 1p
26207 183 24X Fiche 50-361, 84/08/17, 8408230223

08210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

? Periodic operating reports & related correspondence

3408220098 Forwards monthly rept describing occurrences resulting in degradation of auxiliary feedwater sys covering 840616-0715, per License Condition 2 C(26) Next rept will cover 840716-0815
MEDFORD, M O Southern California Edison Co 84/08/17
KNIGHTON, G W Licensing Branch 3 4pp 26193 301 24X
Fiche 50-361, 84/08/17, 8408220098

S Reportable occurrences, LERs & related correspondence

8408010304 Revised LER 84-009-01 on 840214, analysis of startup test data for Units 2 & 3 established that calculated thermal power may become decalibr relative to secondary calometric power Procedure S023-5-1 revised W/840723 ltr
HAYNES, J G Southern California Edison Co 84/07/23 3pp
25866 099 24X Fiche 50-361, 84/07/23, 8408010304

8408060034 Forwards LER 84-041-00 On 840724, discrepancies discovered during updated fire hazards analysis Corrective actions described in 840425 ltr implemented
HAYNES, J G Southern California Edison Co 84/07/25 Record Services Branch (Document Control Desk) 2pp 25935 275 24X
Fiche 50-361, 84/07/25, 8408060034

--8408060039 LER 84-041-00 on 840724, fire hazards analysis updated per License Condition 2 G, resulted in issuance of two nonconformance repts identifying discrepancies involving cable separation & fire wraps Corrected action implemented
HAYNES, J G, Southern California Edison Co 84/07/25 1p
25935 277 24X Fiche 50-361, 84/07/25, 8408060034

8408060223 LER 84-035-00 on 840625, containment area radiation monitor 2RE-7804(EIIS Identifier RT) reached alarm setpoint & initiated train A containment purge isolation sys Cause under investigation, New setpoint installed W/840725 ltr
HAYNES, J G Southern California Edison Co 84/07/25 2pp
25936 178 24X Fiche 50-361, 84/07/25, 8408060223

8408080489 LER 84-037-00 on 840627, spurious actuation of toxic gas isolation sys occurred Caused by overly conservative alarm setpoints Tech Spec amend submitted 840427 requesting more appropriate settings W/840727 ltr
HAYNES, J G Southern California Edison Co 84/07/27 3pp
25975 185 24X Fiche 50-361, 84/07/27, 8408080489

8408060387 "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-6-56 84/07/31 62pp
25927 066 24X Fiche 50-000, 84/08/01, 8408060324

8408170059 LER 84-038-00 on 840708, 23 & 26, control room isolation sys train A spuriously actuated from noise spike on control room airborne radiation monitor 2IRE-7824 Caused by electrical noise spikes of unknown origin W/840802 ltr
HAYNES, J G Southern California Edison Co 84/08/02 2pp
26130 056 24X Fiche 50-361, 84/08/02, 8408170059

8408240084 LER 84-039-00 on 840712, inservice insp test of Unit 2 & 3 component cooling water outlet valves (HV-6500 & HV-6501) missed Caused by administrative oversight Procedural controls validated W/840813 ltr
HAYNES, J G Southern California Edison Co 84/08/13 3pp
26237 034 24X Fiche 50-361, 84/08/13, 8408240084

8408220139 PNO-V-84-050 on 840815, influx of seaweed caused reduction in circulating water flow Power reduced as condenser vacuum degraded High differential pressure observed on train B component cooling water HX while train A inoperable
KIRSCH, D , HAIST, D Region 5, Office of Director 84/08/15 1p
26194 048 24X Fiche 50-361, 84/08/15, 8408220139

8408280225 Special Rept on 840804, purge/vent stack wide range monitor 2RE-7865 removed from svc for performance of 92-day surveillance Monitor not restored to operable status within 72 h to permit corrective maint on sys valve
HAYNES, J G Southern California Edison Co 84/08/17 MARTIN, J B
Region 5, Office of Director 2pp 26274 307 24X
Fiche 50-361, 84/08/17, 8408280225

8408280296 LER 84-036-00 on 840629, HPSI isolation valve 34V9327 failed to stroke during surveillance on HPSI check valves Caused by excessive wear on stem & retaining ring Valves showing free stem movement repaired & returned to svc W/840817 ltr
HAYNES, J G Southern California Edison Co 84/08/17 5pp
26282 153 24X Fiche 50-361, 84/08/17, 8408280296

8408300492 LER 84-040-00 on 840723, main steam isolation sys inadvertently actuated Caused by technician error & weakness w/procedural precautions Procedure S023-II-1 6 amended W/840822 ltr
HAYNES, J G Southern California Edison Co 84/08/22 3pp
26314 083 24X Fiche 50-361, 84/08/22, 8408300492

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8408030123 Forwards Rev 2 to physical security plan & description of changes Encls withheld (ref 10CFR73 21)
HAYNES, J G Southern California Edison Co 84/07/25 MARTIN, J B
Region 5, Office of Director 1p 25916 119 24X
Fiche 50-206, 84/07/25, 8408030123

8408170130 Forwards Amends 78, 23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas
PAULSON, W A Operating Reactors Branch 5 84/08/07 BASKIN, K
Southern California Edison Co 5pp 26134 302 24X
Fiche 50-206, 84/08/07, 8408170130

--8408170143 Amends 78, 23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively, approving security plan revs which consolidate & reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary
PAULSON, W A Operating Reactors Branch 5 84/08/07 4pp
26134 307 24X Fiche 50-206, 84/08/07, 8408170130

--8408170155 Safety evaluation supporting Amends 78, 23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/07 5pp
26134 313 24X Fiche 50-206, 84/08/07, 8408170130

8408200335 Forwards responses to IE Emergency Appraisal Repts 50-361/84-08 & 50-362/84-07 Documents re verification of computer dose projection program available for exam Encl describes test sequence & parameters, hand calculations
RAY, H B Southern California Edison Co 84/08/07 MARTIN, J B
Region 5, Office of Director 14pp 26134 001 24X
Fiche 50-361, 84/08/07, 8408200335

DOCKETED ITEMS

8408130450 Advises that 840523 Revs 1-13 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
MCGUCEN, A D Region 5, Office of Director 84/08/08 HAYNES, J G
Southern California Edison Co 4pp 26004 359 24X
Fiche 50-206, 84/08/08, 8408130450

8408230306 Advises that 840131 submittal on detailed control room design review does not meet all requirements of Suppl 1 to NUREG-0737 Review did not include task analysis Addl significant concerns listed
KNIGHTON, G W Licensing Branch 3 84/08/09 BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co
3pp 26236 102 24X Fiche 50-361, 84/08/09, 8408230306

8408310285 Forwards Safeguards Insp Repts 50-206/84-18, 50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 10CFR2 790 & 73 21)
SCHUSTER, M D Region 5, Office of Director 84/08/15 BASKIN, K B
Southern California Edison Co 2pp 26333 288 24X
Fiche 50-206, 84/08/15, 8408310285

8408230114 Informs that 840613 rev to emergency plan compatible w/provisions of 10CFR50 47, App E & Rev 1 to NUREG-0654
SCHUSTER, M D Region 5, Office of Director 84/08/16 MEDFORD, M O
Southern California Edison Co 3pp 26347 274 24X
Fiche 50-206, 84/08/16, 8408230114

P Operating license stage documents & correspondence

8408210042 Notification of contract execution, Mod 4, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " Contractor MIT
HOPPER, A Administrative Contracts Branch FIN B-6898 84/06/12
VOLLMER, R Division of Engineering 1p 26195 176 24X
Fiche 50-362, 84/06/12, 8408210042

--8408210046 Mod 4, deobligating unliquidated fee remaining in contract, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station "
AKI, K Massachusetts Institute of Technology, Cambridge, MA FIN B-6898 84/06/12 1p 26195 177 24X Fiche 50-362, 84/06/12, 8408210042

8408010240 Forwards C-E nonproprietary & proprietary "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station Units 2 & 3" & "CPC/CEAC Software Mods "
Proprietary repts withheld (ref 10CFR2 790)
MEDFORD, M O Southern California Edison Co 84/07/20
KNIGHTON, G W Licensing Branch 3 13pp 25895 001 24X
Fiche 50-361, 84/07/20, 8408010240

--8408010247 Nonproprietary "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station, Units 2 & 3 " Info deleted
* Combustion Engineering, Inc CEN-284(S)-NP 84/06/30 35pp
25895 014 24X Fiche 50-361, 84/07/20, 8408010240

--8408010256 Nonproprietary "CPC/CEAC Software Mods for San Onofre Nuclear Generating Station Units 2 & 3 " Info deleted
* Combustion Engineering, Inc CEN-281(S)-NP 84/07/31 24pp
25895 050 24X Fiche 50-361, 84/07/20, 8408010240

8408090208 Forwards draft memo re boron injection test, which will be finalized after comments received Final memo will satisfy final milestone defined in 189, "Boron Mixing & Cooldown Under Accident Conditions "
PRATT, W T Brookhaven National Laboratory FIN A-3368 84/07/30
LIANG, C Y Reactor Systems Branch 18pp 25971 193 24X
Fiche 50-206, 84/07/30, 8408090208

8408060080 Forwards response to questions re Proposed Change NPF-10/15-138 re CEA position & insertion limits CEA software changes conducted per Rev 2 to CEN-39(A)
MEDFORD, M O Southern California Edison Co 84/08/01
KNIGHTON, G W Licensing Branch 3 6pp 25933 209 24X
Fiche 50-361, 84/08/01, 8408060080

8408090424 Forwards request for addl info re procedures generation package
KNIGHTON, G W Licensing Branch 3 84/08/01 BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co
5pp 25984 305 24X Fiche 50-361, 84/08/01, 8408090424

8408270409 Forwards proprietary & nonproprietary Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept," Rev 0 to "CPC/CEAC Sys Phase II " & Rev 0 to "SONGS-2 Cycle 1 "
Proprietary repts withheld (ref 10CFR2 790)
MEDFORD, M O Southern California Edison Co. 84/08/01
KNIGHTON, G W Licensing Branch 1 2pp 26238 001 24X
Fiche 50-361, 84/08/01, 8408270409

--8408270412 Nonproprietary version of Rev 0 to "CPC/CEAC Sys Phase II Software Verification Test Rept "
* Combustion Engineering, Inc CEN-269(S)-NP R00 84/03/31
25pp 26238 003 24X Fiche 50-361, 84/08/01, 8408270409

--8408270416 Nonproprietary version of Rev 0 to "SONGS-2 Cycle 1, CPC & CEAC Data Base "
* Combustion Engineering, Inc CEN-266(S)-NP R00 84/03/31
66pp 26238 029 24X Fiche 50-361, 84/08/01, 8408270409

--8408270418 Nonproprietary version of Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept "
* Combustion Engineering, Inc CEN-176(S)-NP R02 84/03/31
27pp 26238 096 24X Fiche 50-361, 84/08/01, 8408270409

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408090187 Forwards application for Amends 27 & 13 to Licenses NPF-10 & NPF-15, respectively, revising Tech Specs re refueling machines; reactor protective instrumentation & ECCS subsys
BASKIN, K P Southern California Edison Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25971 245
24X Fiche 50-361, 84/08/07, 8408090187

--8408090194 Application for amends to Licenses NPF-10 & NPF-15, revising Tech Specs re refueling machine, reactor protective instrumentation, ECCS subsys & steam generators
BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co HOYT, G W Anaheim, CA 84/08/02 14pp
25971 249 24X Fiche 50-361, 84/08/07, 8408090187

--8408090201 Proposed Tech Spec changes, adding note which exempts use of refueling machine for coupling/uncoupling & verification of coupling/uncoupling of control element assemblies
* Southern California Edison Co 84/08/07 100pp 25971 264
24X Fiche 50-361, 84/08/07, 8408090187

8408100091 Resubmits info re proposed changes to Licenses NPF-10 & NPF-15 Tech Specs in form specified by NRC 840416 request for addl info Info extracted from original submittals
MEDFORD, M O Southern California Edison Co 84/08/07
KNIGHTON, G W Licensing Branch 3 73pp 25990 202 24X
Fiche 50-361, 84/08/07, 8408100091

8408170130 Forwards Amends 78, 23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively & safety evaluation Amends approve security plan revs which consolidate & reduce size of adjacent vital areas
PAULSON, W A Operating Reactors Branch 5 84/08/07 BASKIN, K
Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 5pp 26134 302 24X Fiche 50-206, 84/08/07, 8408170130

--8408170143 Amends 78, 23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively, approving security plan revs which consolidate & reduce size of adjacent vital areas & move equipment not required for safety outside vital boundary
PAULSON, W A Operating Reactors Branch 5 84/08/07 6pp
26134 307 24X Fiche 50-206, 84/08/07, 8408170130

--8408170155 Safety evaluation supporting Amends 78, 23 & 12 to Licenses DPR-13, NPF-10 & NPF-15, respectively
* Office of Nuclear Reactor Regulation, Director 84/08/07 5pp
26134 313 24X Fiche 50-206, 84/08/07, 8408170130

8408100115 Documents 840723 discussion re design of proposed gravity-feed auxiliary feedwater pump motor lube oil cooling sys as alternate to forced-feed design described in util 830307 ltr Formal endorsement requested by 840821
MEDFORD, M O. Southern California Edison Co 84/08/08
KNIGHTON, G W Licensing Branch 3 3pp 25988 262 24X
Fiche 50-361, 84/08/08, 8408100115

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl.
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408240267 Forwards fee balance to complete required remittance for 840125 Proposed Change NPF-10/15-144
MEDFORD, M O Southern California Edison Co. 84/08/21 MILLER, W O
License Fee Management Branch 1p 26222 358 24X
Fiche 50-361, 84/08/21, 8408240267.

8408270325 Advises that Amend 7 to Topical Rept SCE-1-A, "QA Program, consistent w/provisions of 10CFR50 54(a) & acceptable
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/08/21 BASKIN, K P Southern California Edison Co
1p 26244 187 24X Fiche 50-206, 84/08/21, 8408270325

8408300163 Application for amend to Licenses NPF-10 & NPF-15, revising Tech Specs re reactivity control sys Fee paid
MEDFORD, M O Southern California Edison Co 84/08/27
KNIGHTON, G W Licensing Branch 3 1p 26305 291 24X
Fiche 50-361, 84/08/27, 8408300163

--8408300165 Proposed Tech Specs re reactivity control sys
* Southern California Edison Co 84/08/27 28pp 26305 297
24X Fiche 50-361, 84/08/27, 8408300163

G Inspection reports, IE Bulletins & correspondence

8408090001 Forwards IE Insp Repts 50-361/84-20 & 50-362/84-20 on 840618-21 No violations noted
WENSLAWSKI, F A Region 5, Office of Director 84/07/25
BASKIN, K P Southern California Edison Co 2pp 25994 330 24X
Fiche 50-361, 84/07/25, 8408090001

--8408090004 IE Insp Repts 50-361/84-20 & 50-362/84-20 on 840618-21 No violations noted Major areas inspected confirmatory measurements for radioactivity
HAMADA, G, NORTH, H , YUHAS, G Region 5, Office of Director
84/07/24 9pp 25994 332 24X Fiche 50-361, 84/07/25, 8408090001

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408090043 Forwards IE Insp Repts 50-361/84-19 & 50-362/84-19 on 840605-08 No violations noted
BISHOP, T W Region 5, Office of Director 84/07/27 BASKIN, K B
Southern California Edison Co 1p 25992 123 24X
Fiche 50-361, 84/07/27, 8408090043

--8408090045 IE Insp Repts 50-361/84-19 & 50-362/84-19 on 840605-08 No violations noted Major areas inspected precritical, low power & power ascension test results data
PEREIRA, D D , PATE, R J Region 5, Office of Director 84/06/27
8pp 25992 124 24X Fiche 50-361, 84/07/27, 8408090043

J408140056 Forwards latest facility attachment prepared by IAEA, including all review & insp results Encls withheld (ref 10CFR2 790)
KNIGHTON, G W Licensing Branch 3 84/07/27 BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co
2pp 26061 264 24X Fiche 50-361, 84/07/27, 8408140056

8408070411 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Thirty-one relays found at Unit 1 will be replaced by 860312
MEDFORD, M O Southern California Edison Co 84/07/30 MARTIN, J B
Region 5, Office of Director 3pp 25942 170 24X
Fiche 50-206, 84/07/30, 8408070411

8408060112 Proposes method of insp of low pressure turbine discs for ultrasonic indications Discs will be inspected prior to startup following second refueling outage, per License Condition 2 C (15) & 2 C (13)
MEDFORD, M O Southern California Edison Co 84/08/01
KNIGHTON, G W Licensing Branch 3 2pp 25925 307 24X
Fiche 50-361, 84/08/01, 8408060112

8408140260 Provides addl response to IE Insp Repts 50-361/84-14 & 50-362/84-14 on 840506 & 07 Evaluation & actions taken as result of 840505 increase in RCS radioactivity described
RAY, H B Southern California Edison Co 84/08/01 MARTIN, J B
Region 5, Office of Director 3pp 26055 330 24X
Fiche 50-361, 84/08/01, 8408140260

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26069 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408200335 Forwards responses to IE Emergency Appraisal Repts 50-361/84-08 & 50-362/84-07 Documents re verification of computer dose projection program available for exam Encl describes test sequence & parameters, hand calculations
RAY, H B Southern California Edison Co 84/08/07 MARTIN, J B
Region 5, Office of Director 16pp 26133 359 24X
Fiche 50-361, 84/08/07, 8408200335

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408210479 Provides addl response to notice of violation & proposed imposition of civil penalties Systematic mgt monitoring & feedback program implemented to identify & correct deficiencies
FOGARTY, D J Southern California Edison Co 84/08/13 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 6pp
26181 137 24X Fiche 50-362, 84/08/13, 8408210479

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408310285 Forwards Safeguards Insp Repts 50-206/84-18, 50-361/84-23 & 50-362/84-23 on 840723-27 No violations noted Repts withheld (ref 10CFR2 790 & 73 21)
SCHUSTER, M O Region 5, Office of Director 84/08/15 BASKIN, K B
Southern California Edison Co 2pp 26333 288 24X
Fiche 50-206, 84/08/15, 8408310285

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408230223 Ack receipt of 840801 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/84-14 & 50-362/84-14 Ltr dtd 840801 adequately responds to NRC 840725 request
SCARANO, R A Division of Radiological Safety & Safeguards Program
84/08/17 BASKIN, K P Southern California Edison Co 1p
26207 183 24X Fiche 50-361, 84/08/17, 8408230223

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 113pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408220098 Forwards monthly rept describing occurrences resulting in degradation of auxiliary feedwater sys covering 840616-0715, per License Condition 2 C(26) Next rept will cover 840716-0815
MEDFORD, M O Southern California Edison Co 84/08/17
KNIGHTON, G W Licensing Branch 3 4pp 26193 301 24X
Fiche 50-361, 84/08/17, 8408220098

S Reportable occurrences, LERs & related correspondence

8408060387 Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets
* Failure Analysis Associates FAAA-84-6-56 84/07/31 62pp
25927 066 24X Fiche 50-000,84/08/01,8408060324

8408090418 LER 84-020-01 on 840527,8 h grab sample due at 0800 not taken until 0945 Low range flow at sample conditioning skid diverted from filter A to filter B,causing blown fuse Alternate flow path established W/840801 ltr
HAYNES,J G Southern California Edison Co 84/08/01 3pp
25993 244 24X Fiche 50-362,84/08/01,8408090418

8408240200 LER 84-029-00 on 840709,high level excursion occurred resulting in closure of extraction steam valves & isolation of second & first point heaters from steam supply Caused by steam loss W/840814 ltr
HAYNES,J G Southern California Edison Co 84/08/14 3pp
26236 283 24X Fiche 50-362,84/08/14,8408240200

8408220139 PNO-V-84-050 on 840815,influx of seaweed caused reduction in circulating water flow Power reduced as condenser vacuum degraded High differential pressure observed on train B component cooling water HX while train A inoperable
KIRSCH,D , HAIST,D Region 5, Office of Director 84/08/15 1p
26194 048 24X Fiche 50-361,84/08/15,8408220139

8408280078 PNO-V-84-052 on 840821,licensee determined that HPSI potentially degraded due to component cooling water HX mini flow bypass open for subgroup relay testing Formal investigation being conducted
MORRILL,P , HAIST,D Region 5, Office of Director 84/08/22 1p
26261 206 24X Fiche 50-362,84/08/22,8408280078

DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408170386 Requests meeting to discuss detailed control room design review w/respect to Nuclear Util Task Action Committee documents
VARGA,S A Operating Reactors Branch 1 84/05/24 MCDONALD,R P
Alabama Power Co 3pp 26134 193 24X Fiche 50-348,84/05/24,
8408170386

8408300364 Forwards summary of 840530 meeting w/Alabama Power Co, Florida Power Corp,Florida Power & Light,Georgia Power Co & TVA re selected emergency preparedness issues
O'REILLY,J P Region 2, Office of Director 84/06/08
MCDONALD,R P Alabama Power Co 4pp 26308 216 24X
Fiche 50-348,84/06/08,8408300364

8408060070 Temporary change notices for Rev 7 to Procedure GO-EIP-111, "Corporate Activation & Notification " W/840727 ltr
MUDD,C H Alabama Power Co 84/07/27 21pp 25933 104 24X
Fiche 50-348,84/07/27,8408060070

8408070469 Forwards interim shutdown meaures re App R Eleven sys discussed which could potentially be impacted by cable spreading room fire Mods required to establish compliance w/App R
MCDONALD,C E Alabama Power Co 84/07/27 VARGA,S A Office of Nuclear Reactor Regulation, Director 5pp 25940 336 24X
Fiche 50-348,84/07/27,8408070469

8408130374 Submits addl info re 10CFR50,App R schedular exemption for alternative shutdown mods Bases for schedular exemption until Unit 1 seventh & Unit 2 fourth refueling outages to completed mods provided
MCDONALD,R P Alabama Power Co 84/08/06 VARGA,S A Office of Nuclear Reactor Regulation, Director 2pp 26005 337 24X
Fiche 50-348,84/08/06,8408130374

8408210417 Rev 13 to Emergency Plan Implementing Procedure FNP-0-EIP-16, "Emergency Equipment & Supplies " W/840814 ltr
HUDSPETH,J B Alabama Power Co 84/08/14 MCKNIGHT,J Record Services Branch (Document Control Desk) 7pp 26177 241 24X
Fiche 50-364,84/08/14,8408210417

8408240229 Summary of 840725 meeting w/util re detailed control room design review,per NUREG-0737, Suppl 1
REEVES,E A Operating Reactors Branch 1 84/08/16 Operating Reactors Branch 1 6pp 26251 227 24X Fiche 50-348,84/08/16,
8408240229

8408230326 Revised emergency plan implementing procedures,including GO-EIP-101 re corporate emergency organization,GO-EIP-135 re emergency plan review & rev & GO-EIP-120 re ref guidance for recovery manager W/840817 ltr
MUDD,C H Alabama Power Co 84/08/17 36pp 26206 018 24X
Fiche 50-348,84/08/17,8408230326

M Antitrust correspondence

8408130075 Ack receipt of 840629 petition for enforcement action under 10CFR2 206 re antitrust license conditions Petition will be held in abeyance pending further Commission direction
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/07/30 BOSKEY,B Volpe, Boskey & Lyons 7pp 26034 353 24X
Fiche 50-348,84/07/30,8408130075

8408080197 Reiterates 840702 request for notes,memoranda or transcripts of meetings between NRC & util as referenced in Palladino 840626 memo
BOSKEY,B , MACGUINEAS,D B Volpe, Boskey & Lyons BOSKEY,B
Alabama Electric Cooperative, Inc DSB 833 84/08/06 DIRCKS,W J
Office of the Executive Director for Operations 2pp 25960 259
24X Fiche 50-348,84/08/06,8408080197

8408080202 Reiterates 840702 request for notes,memoranda or transcripts of meetings between NRC & util as referenced in Palladino 840626 memo
BOSKEY,B , MACGUINEAS,D B Volpe, Boskey & Lyons BOSKEY,B
Alabama Electric Cooperative, Inc DSB 831 84/08/06
BERNTHAL,F M Commissioners 2pp 25959 022 24X
Fiche 50-348,84/08/06,8408080202

8408080241 Reiterates 840702 request for any notes or memoranda or transcripts of meetings w/util near end of June 1984 Certificate of Svc encl
BOSKEY,B , MACGUINEAS,D B Volpe, Boskey & Lyons BOSKEY,B
Alabama Electric Cooperative, Inc DSB 832 84/08/06
ASSELSTINE,J K Commissioners 2pp 25966 291 24X
Fiche 50-348,84/08/06,8408080241

8408150120 Responds to 840806 ltr to WJ Dircks requesting any notes, memoranda or transcripts made of meetings between NRC & util No notes taken & no memoranda or transcripts of 840626 meeting prepared Related correspondence
CUNNINGHAM,G H Office of the Executive Legal Director DSB 038
84/08/10 BOSKEY,B , MACGUINEAS,D B Volpe, Boskey & Lyons 2pp
26066 352 24X Fiche 50-348,84/08/10,8408150120

8408200486 Responds to 840806 request for Commission records re 840625 meeting w/util Chairman Palladino 840624 memo accurately reflects conversation W/svc list Served on 840817
BERNTHAL,F Commissioners DSB 166 84/08/16 BOSKEY,B Volpe, Boskey & Lyons 3pp 26136 318 24X Fiche 50-348,84/08/16,
8408200486

P Operating license stage documents & correspondence

8408060277 Requests addl info needed for continuing review of 840203 license amend request,per Generic Ltr 83-43 Deficiencies noted in Tech Specs re deletion of ROs
VARGA,S A Operating Reactors Branch 1 84/07/25 MCDONALD,R P
Alabama Power Co 2pp 25950 294 24X Fiche 50-348,84/07/25,
8408060277

8408130233 Forwards safety evaluation & technical evaluation rept re control of heavy loads,Phase 1
VARGA,S A Operating Reactors Branch 1 84/07/25 MCDONALD,R P
Alabama Power Co 2pp 26060 027 24X Fiche 50-348,84/07/25,
8408130233

--8408130258 SER re control of heavy loads,Phase 1 Phase 1 acceptable
* NRC - No Detailed Affiliation Given 84/07/25 2pp
26060 029 24X Fiche 50-348,84/07/25,8408130233

8408100036 Forwards updated status of 1984 licensing items identified in 840702 ltr Util ready to discuss mod of licensing status to address all licensing issues
MCDONALD,R P Alabama Power Co 84/08/01 VARGA,S A Office of Nuclear Reactor Regulation, Director 7pp 25990 061 24X
Fiche 50-348,84/08/01,8408100036

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408210412 Forwards list of accident monitoring equipment to be replaced within extended schedule of 10CFR50 49,per Reg Guide 1 97
MCDONALD,R P Alabama Power Co 84/08/17 VARGA,S A Office of Nuclear Reactor Regulation, Director 4pp 26179 211 24X
Fiche 50-364,84/08/17,8408210412

8408230398 Application for amend to Licenses NPF-2 & NPF-8,deleting words during shutdown from Tech Spec 4 7 1 2 2 b 1 re auxiliary feedwater sys Fee encl
MCDONALD,R P Alabama Power Co 84/08/17 VARGA,S A Office of Nuclear Reactor Regulation, Director 3pp 26205 304 24X
Fiche 50-348,84/08/17,8408230398

--8408230399 Proposed Tech Spec 4 7 1 2 2 b 1,deleting words during shutdown
* Alabama Power Co 84/08/17 2pp 26205 307 24X
Fiche 50-348,84/08/17,8408230398

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

Q Inspection reports, IE Bulletins & correspondence

8408280176 Discusses results of diesel generator check valve integrity insp,per IE Bulletin 83-03,during fifth refueling outage on 840210-0424 Inservice testing requirements for valves will be modified as listed
MCDONALD,R P Alabama Power Co 84/06/01 O'REILLY,J P Region 2, Office of Director 3pp 26279 196 24X Fiche 50-348,84/06/01, 8408280176

8408280048 Forwards response to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " Unit 1 relays replaced w/GE Century Series HFA relays Thirty-three Unit 2 relays require replacement
MCDONALD,R P Alabama Power Co 84/07/12 O'REILLY,J P Region 2, Office of Director 3pp 26261 230 24X Fiche 50-348,84/07/12, 8408280048

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408130345 Requests revised relief from ASME Code,Section XI requirements re volumetric exam of charging pump casing welds & hydrostatic test of Class 2 portions of steam generators,per review of inservice insp program Fee encl
MCDONALD,R P Alabama Power Co 84/07/27 VARGA,S A Office of Nuclear Reactor Regulation, Director 3pp 26010 312 24X
Fiche 50-364,84/07/27,8408130345

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 113pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

V Operator Examinations

8408070314 Forwards response to Generic Ltr 84-14 re replacement & requalification training program Encl provides outline & description of simulator utilized in training & requalification program
MCDONALD,R P Alabama Power Co 84/07/26 VARGA,S A Office of Nuclear Reactor Regulation, Director 3pp 25948 002 24X
Fiche 50-348,84/07/26,8408070314

DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408300436 Forwards FEMA exercise rept for 831013 exercise
DANCE,H C Region 2, Office of Director 84/05/07 KELLY,R J
Georgia Power Co 1p 26314 247 24X Fiche 50-321,84/05/07, 8408300436

--8404040322 Forwards FEMA 840124 ltr forwarding FEMA Region IV rept of 831013 joint exercise Recommends exercise rept be transmitted to licensee & coordination w/FEMA Region IV be continued to ensure deficiencies identified corrected
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/03/13 STOHR,J P Division of Emergency Preparedness & Materials Safety 2pp 26314 248 24X
Fiche 50-321,84/05/07,8408300436

8408300352 Confirms arrangements made on 840524 between JT Beckham & HC Dance re 840531 enforcement conference in Region II ofc to discuss 840522 security event re access controls & events leading to inoperability of HPCI Agenda encl
O'REILLY,J P Region 2, Office of Director 84/05/25 KELLY,R J
Georgia Power Co 2pp 26314 147 24X Fiche 50-321,84/05/25, 8408300352

8408300376 Forwards summary of 840530 meeting w/utils & INPO re selected emergency preparedness issues Attendance list also encl
O'REILLY,J P Region 2, Office of Director 84/06/08 KELLY,R J
Georgia Power Co 4pp 26308 257 24X Fiche 50-000,84/06/08, 8408300376

8408310057 Documents training & experience for evaluation team members, per 840723 ltr re training requirements for NRC & contract personnel observing 840802 emergency exercise
DANCE,H C Region 2, Office of Director 84/07/24 KELLY,R J
Georgia Power Co 2pp 26333 332 24X Fiche 50-321,84/07/24, 8408310057

8408030163 Revs to emergency plan implementing procedures, consisting of Rev 4 to HNP-8024, "In-Plant Radiation Level Monitoring" & Rev 1 to HNP-8061, Eberline Model PCM-1 Portal Monitor Operation & Calibr " W/840731 ltr
SORRELL, E C Georgia Power Co 84/07/31 38pp 25912 022 24X
Fiche 50-321, 84/07/31, 8408030163

8408130302 Responds to 840302 ltr, supplemented by 840413 ltr, requesting exemption from App E to 10CFR50, excluding state & county participation in 840802 exercise Requested exemption unnecessary New rule requires participation every 2 yrs
STOLZ, J F Operating Reactors Branch 4 84/08/01 BECKHAM, J T
Georgia Power Co 3pp 26040 334 24X Fiche 50-321, 84/08/01,
8408130302

8408090207 Notification of 840808 meeting w/util in Bethesda, MD to discuss approach for interim measures associated w/schedular exemption request for implementation of App R mods
RIVENBARK, G Operating Reactors Branch 4 84/08/03 STOLZ, J F
Operating Reactors Branch 4 2pp 25984 360 24X
Fiche 50-321, 84/08/03, 8408090207

8408130379 Responds to 840717 request for addl info re submittal of safety parameter display sys info Foxboro Procedures GOAAA04 & GOAAB44, containing isolation devices pass/fail acceptance criteria, encl
GUCWA, L T Georgia Power Co 84/08/07 STOLZ, J F Operating
Reactors Branch 4 3pp 26008 203 24X Fiche 50-321, 84/08/07,
8408130379

8408170258 Rev 7 to Emergency Implementing Procedure HNP-4892, "Offsite Dose Estimations " W/840814 ltr
* Georgia Power Co 84/08/14 46pp 26115 297 24X
Fiche 50-321, 84/08/14, 8408170258

8408210472 Revised emergency plan implementing procedures, including Rev 2 to HNP-2-4205 re turbine lube oil reservoir, Rev 4 to HNP-4212 re emergency diesel generator bldg & Rev 3 to HNP-1-4216 re reactor bldg Elevation 203 fires W/840816 ltr
NIX, H , SORRELL, E C Georgia Power Co 84/08/16 246pp
26149 084 24X Fiche 50-321, 84/08/16, 8408210472

8408280233 Revised emergency plan implementing procedures, including Rev 1 to HNP-1-4261 re south CRD & essential MCC area fires & Rev 1 to HNP-1-4263 re reactor water cleanup pump room fire W/840824 ltr
NIX, H , SORRELL, E C Georgia Power Co 84/08/18 75pp 26269 125
24X Fiche 50-321, 84/08/18, 8408280233

8408270301 Rev 21 to Emergency Plan Implementing Procedure HNP-8008, "Radiation Work Permit " W/840821 ltr
SORRELL, E C Georgia Power Co 84/08/21 28pp 26240 337 24X
Fiche 50-321, 84/08/21, 8408270301

I Financial information

8408300072 Forwards draft in furtherance certificate Approval requested in order to meet Internal Revenue Svc requirements for tax-exempt pollution control revenue bonds
GUCWA, L T Georgia Power Co 84/08/20 STOLZ, J F Operating
Reactors Branch 4 4pp 26305 357 24X Fiche 50-321, 84/08/20,
8408300072

3. Operating license stage documents & correspondence

8408310398 Forwards summary of 840424 meeting re feedwater nozzle ultrasonic test indications & corrective action necessary for future unit operations Meeting beneficial & provided better understanding of issues.
LEWIS, R C Region 2, Office of Director 84/05/15 KELLY, R J
Georgia Power Co 7pp 26333 321 24X Fiche 50-366, 84/05/15,
8408310398

8408310021 Confirms 840514 telcon re 840521 meeting in Region II ofcs to discuss planned mod to rod block monitoring sys at facility
LEWIS, R C Region 2, Office of Director 84/05/16 KELLY, R J
Georgia Power Co 1p 26335 014 24X Fiche 50-321, 84/05/16,
8408310021

8408300320 Confirms 840522 telcon between J Gadgett & H Dance re arrangements made for R Martin, Region II, Deputy Regional Administrator, to attend 840628 presentation of certificates to licensed operators
LEWIS, R C Region 2, Office of Director 84/05/29 KELLY, R J
Georgia Power Co 1p 26308 328 24X Fiche 50-321, 84/05/29,
8408300320

8408300238 Forwards BNL-NUREG-34709 re cracked vent header pipe Rept supports conclusion that failure caused by impingement of torus inerting nitrogen on vent header W/o encl
DANCE, H C Region 2, Office of Director 84/06/19 KELLY, R J
Georgia Power Co 1p 26307 014 24X Fiche 50-366, 84/06/19,
8408300238

8408300421 Forwards summary of 840521 meeting w/util in Region II ofc re APRM sys block monitor sys & Tech Spec activities proposed for Licenses DPR-57 & NPF-5 Attendance list encl
LEWIS, R C Region 2, Office of Director 84/06/22 KELLY, R J
Georgia Power Co 4pp 26314 217 24X Fiche 50-321, 84/06/22,
8408300421

8408010122 Returns fee submitted w/840712 license amend application re operation w/recirculation loop out of svc Only $150 due under revised fee rule, per 10CFR170 Remittance of $150 requested
DIGGS, R M License Fee Management Branch 84/07/23 BECKHAM, J T
Georgia Power Co 2pp 25873 267 24X Fiche 50-366, 84/07/23,
8408010122

8408080178 Informs of review of responses to Generic Ltr 83-02 re Tech Specs for NUREG-0737 items which were to be implemented by 811231 Tech Specs for Item II E 4 2 7 have not been provided Response requested within 30 days
STOLZ, J F Operating Reactors Branch 4 84/08/01 BECKHAM, J T
Georgia Power Co 2pp 25978 342 24X Fiche 50-321, 84/08/01,
8408080178

8408130561 Application for amend to Licenses DPR-57 & NPF-5, revising radiological effluent Tech Specs (RETS) by transferring RETS from App B to App A & including editorial & administrative changes & changes based on NRC comments
BECKHAM, J T Georgia Power Co 84/08/01 STOLZ, J F Operating
Reactors Branch 4 3pp 26031 001 24X Fiche 50-321, 84/08/01,
8408130561

--8408130567 Proposed Tech Spec changes, transferring radiological effluent Tech Specs from App B to App A
* Georgia Power Co 84/08/01 190pp 26031 004 24X
Fiche 50-321, 84/08/01, 8408130561

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY, P F Operating Reactors Assessment Branch 84/08/06
HOLAHAN, G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000, 84/08/06, 8408090317

8408100045 Application for amend to License NPF-5, revising Tech Specs to change isolation actuation setpoint for six valves Fee encl
BECKHAM, J T Georgia Power Co 84/08/06 STOLZ, J F Operating
Reactors Branch 4 6pp 25990 044 24X Fiche 50-366, 84/08/06,
8408100045

--8408100049 Proposed Tech Spec Table 3 & 3-1 re primary containment isolation valves, changing isolation actuation setpoint for six valves
* Georgia Power Co 84/08/06 3pp 25990 050 24X
Fiche 50-366, 84/08/06, 8408100045

8408130242 Grants extension for qualification of H2O2 analyzer sys until 850331 & for qualification of valves & operations until 851130
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/08/06 BECKHAM, J T Georgia Power Co 4pp 26040 354 24X
Fiche 50-366, 84/08/06, 8408130242

8408140106 Application to amend Licenses DPR-57 & NPF-5, changing Tech Specs to reflect implementation of TMI Item II B 3, "Post-Accident Sampling Capability " Fee encl
BECKHAM, J T Georgia Power Co 84/08/07 STOLZ, J F Operating
Reactors Branch 4 2pp 26051 252 24X Fiche 50-321, 84/08/07,
8408140106

--8408140124 Proposed Tech Spec changes re post-accident sampling & analysis & iodine monitoring
* Georgia Power Co 84/08/07 5pp 26051 254 24X
Fiche 50-321, 84/08/07, 8408140106

8408150242 Responds to 840806 request for addl info re change to isolation actuation setpoint in Tech Specs for six valves Proposed amend revises Tech Spec isolation setpoint for each valve making setpoint consistent w/original design of plant
GUCWA,L T Georgia Power Co 84/08/10 STOLZ,J F Operating Reactors Branch 4 5pp 26067 061 24X Fiche 50-366,84/08/10, 8408150242

8408210474 Provides info in support of 840806 request for proposed Tech Spec change re containment isolation valves Request should be treated as emergency request to avoid undue delay in unit startup
GUCWA,L T Georgia Power Co 84/08/14 STOLZ,J F Operating Reactors Branch 4 2pp 26181 125 24X Fiche 50-321,84/08/14, 8408210474

8408210175 Application for amend to License NPF-5,consisting of corrected pages to Tech Specs on containment isolation valves submitted w/840806 amend request Reactor water level isolation signal changed
GUCWA,L T Georgia Power Co 84/08/16 STOLZ,J F Operating Reactors Branch 4 1p 26147 121 24X Fiche 50-366,84/08/16, 8408210175

--8408210235 Corrected proposed Tech Spec Table 3 6 3-1 re primary containment isolation valves
* Georgia Power Co 84/08/16 2pp 26147 122 24X Fiche 50-366,84/08/16,8408210175

8408210357 Responds to 840801 ltr re NUREG-0737,Item II E 4 2(7), "Purge & Vent Valve Isolation " Revs to Unit 2 Tech Specs expected to be submitted by 840905 Unit 1 mods will be completed during scheduled Fall 1984 refueling outage
GUCWA,L T Georgia Power Co 84/08/16 STOLZ,J F Operating Reactors Branch 4 2pp 26180 241 24X Fiche 50-321,84/08/16, 8408210357

8408230251 Requests extension until 841107,to respond to request for info re reliability & upgrading of diesel generators,per Generic Ltr 84-15 Extension due to workload at site for Unit 2 recirculation pipe replacement outage
GUCWA,L T Georgia Power Co 84/08/16 STOLZ,J F Operating Reactors Branch 4 2pp 26207 293 24X Fiche 50-321,84/08/16, 8408230251

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275

8408300024 Requests mod to distribution for all plant correspondence Distribution page of recent Tech Spec amend w/requested change encl
GUCWA,L.T Georgia Power Co 84/08/22 STOLZ,J F Operating Reactors Branch 4 2pp 26305 183 24X Fiche 50-321,84/08/22, 8408300024

8408300197 Forwards Amend 40 to License NPF-5,safety evaluation & initial & final NSHC determinations NSHC determinations available in Central Files
STOLZ,J F Operating Reactors Branch 4 84/08/22 BECKHAM,J T Georgia Power Co 2pp 26331 307 24X Fiche 50-366,84/08/22, 8408300197

--8408300217 Amend 40 to License NPF-5,requiring certain containment isolation valves to automatically close upon receipt of lo-lo-lo reactor water level signal,rather than upon receipt of low reactor water level signal
STOLZ,J F Operating Reactors Branch 4 84/08/22 7pp 26331 315 24X Fiche 50-366,84/08/22,8408300197

--8408300219 Safety evaluation supporting Amend 40 to License NPF-5
PICKETT,D , BUTCHER,E Office of Nuclear Reactor Regulation, Director 84/08/22 4pp 26331 322 24X Fiche 50-366,84/08/22, 8408300197

8408300115 Informs that during startup following current recirculation pipe replacement outage,util will invoke special test exception Tech Spec 3 10 4 re operability of recirculation loop
GUCWA,L T Georgia Power Co, 84/08/23 STOLZ,J F Operating Reactors Branch 4 2pp 26305 169 24X Fiche 50-366,84/08/23, 8408300115

G Inspection reports, IE Bulletins ' correspondence

8408280183 Responds to IE Bulletin 80-13, "Cracking in Core Spray Spargers " No cracking observed in spargers or in-vessel piping during 1984 maint/refueling outage insp
GUCWA,L T Georgia Power Co 84/05/07 O'REILLY,J P Region 2 Office of Director 1p 26269 359 24X Fiche 50-366,84/05/07, 8408280183

8408240356 Forwards Insp Repts 50-321/84-21 & 50-366/84-21 on 840611-15 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/10 KELLY,R J Georgia Power Co 2pp 26237 040 24X Fiche 50-321,84/07/10, 8408240356

--8408240359 Insp Repts 50-321/84-21 & 50-366/84-21 on 840611-15 No violations or deviations noted Major areas inspected worker concerns re Newport News Industries recirculation pipe replacement project
MERRIWEATHER,N , CONLON,T E Region 2, Office of Director 84/07/09 10pp 26237 042 24X Fiche 50-321,84/07/10,8408240356

8408240364 Forwards Insp Repts 50-321/84-23 & 50-366/84-23 on 840618-22 No violations or deviations noted Unresolved items identified will be pursued during future insps
DANCE,H C Region 2, Office of Director 84/07/11 KELLY,R J Georgia Power Co 2pp 26237 080 24X Fiche 50-321,84/07/11, 8408240364

--8408240366 Insp Repts 50-321/84-23 & 50-366/84-23 on 840618-22 No violations or deviations noted Major areas inspected evaluation of ultrasonic test indications in feedwater weld 2B21-1FW-12AA-12 (Unit 2)
CROWLEY,B R , COLEY,J L , BLAKE,J J Region 2, Office of Director 84/07/10 12pp 26237 082 24X Fiche 50-321,84/07/11, 8408240364

8408280239 Advises of plans & schedules for replacing HFA relays in reactor protection & safety sys,per IE Bulletin 84-02
GUCWA,L T Georgia Power Co 84/07/13 O'REILLY,J P Region 2, Office of Director 4pp 26262 237 24X Fiche 50-321,84/07/13, 8408280239

8408270241 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-321/84-13 & 50-366/84-13
LEWIS,R C Division of Project & Resident Programs 84/07/20
KELLY,R J Georgia Power Co 1p 26258 086 24X
Fiche 50-321,84/07/20,8408270241

--8408270247 Responds to NRC 840607 ltr re violations noted in Insp Repts 50-321/84-13 & 50-366/84-13 Corrective actions QC dept will witness significant activities for safety-related major maint
GUCWA,L T Georgia Power Co 84/07/09 O'REILLY,J P Region 2, Office of Director 3pp 26258 087 24X Fiche 50-321,84/07/20, 8408270241

--8408270255 Forwards Insp Repts 50-321/84-13 & 50-366/84-13 on 840321-0420 & notice of violation
LEWIS,R C Division of Project & Resident Programs 84/06/07
KELLY,R J Georgia Power Co 2pp 26258 090 24X
Fiche 50-321,84/07/20,8408270241

--8408270269 Insp Repts 50-321/84-13 & 50-366/84-13 on 840321-0420 Violation noted Failure to restore sys to original design requirements
CRLENJAK,R V , RAY-HOLMES,P , GARNER,L. Region 2, Office of Director 84/06/05 7pp 26258 094 24X Fiche 50-321,84/07/20, 8408270241

--8408270261 Notice of violation from insp on 840321-0421
* Region 2, Office of Director 84/06/07 2pp 26258 092 24X Fiche 50-321,84/07/20,8408270241

8408270334 Forwards Insp Repts 50-321/84-25 & 50-366/84-25 on 840619-22 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/20 KELLY,R J Georgia Power Co 2pp 26257 206 24X Fiche 50-321,84/07/20, 8408270334

--8408270338 Insp Repts 50-321/84-25 & 50-366/84-25 on 840619-22 No violations or deviations noted Major areas inspected review of local leak rate test program & followup of previous violation
WHITENER,H L , JAPE,F Region 2, Office of Director 84/07/19, 6pp 26257 208 24X Fiche 50-321,84/07/20,8408270334

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070141 Forwards discussion of exams conducted on six inlet & outlet nozzles & safe-end & recirculation sys jet pump instrumentation Inconel 182 nozzles Exams prompted by cracking problems discussed in IE Info Notice 84-41
GUCWA, L T Georgia Power Co 84/07/27 STOLZ, J F Operating Reactors Branch 4 5pp 25950 029 24X Fiche 50-366, 84/07/27, 8408070141

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830107) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 12Opp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12Spp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 11Spp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "OUR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 11Bpp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17, Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408200001 Monthly operating repts for Jul 1984 W/840802 ltr
NIX, H C Georgia Power Co 84/07/31 15pp 26140 266 24X Fiche 50-321, 84/07/31, 8408200001

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408070076 Advises of completion of review of AEOD/C403, "Case Study Rept for El Hatch, Unit 2 Plant Sys Interaction Event on 820825 " Case study recommends event be considered in developing final positions relative to NUREG-0803
DENTON, H R Office of Nuclear Reactor Regulation, Director 84/07/30 HELTEMES, C J Director's Office 2pp 25935 272 24X Fiche 50-366, 84/07/30, 8408070076

--8406010162 Forwards case study rept of 820825 plant sys interaction event Comments requested W/o encl
HELTEMES, C J Director's Office 84/05/18 DENTON, H R Office of Nuclear Reactor Regulation, Director DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 25955 273 24X Fiche 50-366, 84/07/30, 8408070076

8408200438 LER 84-009-00 on 840711, unplanned automatic activation logic of more than one ESF occurred Caused by defective rev to HNP-2-3191 Procedure revised to prevent unplanned logic actuation W/840810 ltr
ELTON, T L , NIX, H C Georgia Power Co 84/08/10 3pp 26139 060 24X Fiche 50-366, 84/08/10, 8408200438

8408220491 LER 84-006-00 on 840716, control rod hoist operation performed w/o demonstration operation of hoist interlock All hoist use suspended Procedure revised W/840814 ltr
ELTON, T L , NIX, H C Georgia Power Co 84/08/14 3pp 26196 026 24X Fiche 50-366, 84/08/14, 8408220491

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA, R General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000, 84/08/21, 8408310186

8408300517 LER 84-008-01 on 840327, personnel found turbine bldg area temp FT&C Procedure HNP-2-3725 inadequate in meeting monthly channel functional test in Tech Specs Caused by procedural inadequacy due to personnel error W/840823 ltr
TIPPS, S D , NIX, H C Georgia Power Co 84/08/23 3pp 26313 348 24X Fiche 50-366, 84/08/23, 8408300517

DOCKET 50-367 BAILLY GENERATING STATION

O Adjudicatory correspondence

8408280194 Requests response re resolution of 820604 application for fees & expenses under Equal Access to Justice Act Payment clearly authorized by 5USC504(d)(1) No issue exists to Commission granting petition Related correspondence
WHICHER, J M Businessmen for the Public Interest WHICHER, J M Whicher, J M DSB 329 84/08/22 CRANE, P Office of the General Counsel 2pp 26275 192 24X Fiche 50-367, 84/08/22, 8408280194

H General correspondence

8405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
DIRCKS, W J Office of the Executive Director for Operations 84/05/04 LUGAR, R G Senate 7pp 24524 325 24X Fiche 50-000, 84/05/04, 8405180145

--8405180152 Requests response to encl W & V Smelser 840210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
LUGAR, R G Senate 84/03/14 PALLADINO, N Commissioners 3pp 24524 331 24X Fiche 50-000, 84/05/04, 8405180145

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F Security, medical, emergency & fire protection plans

8408160498 Forwards IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted
HUNTER, D R Region 4, Office of Director 84/07/23 GRIFFIN, J M Arkansas Power & Light Co 2pp 26107 318 24X Fiche 50-313, 84/07/23, 8408160498

--8408160504 IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted Major areas inspected security program audit & physical barriers Details withheld (ref 10CFR73 21)
EVANS, C A Region 4, Office of Director 84/07/23 1p, 26107 320 24X Fiche 50-313, 84/07/23, 8408160498

8408280184 Forwards "Reanalysis Against 10CFR50, App R, Sections III G, J & O," per 830328 & 0712 requests for exemption from 10CFR50 48(c) schedule for barriers, penetrations & suppression/detection sys for approx 1 yr
MARSHALL, J R Arkansas Power & Light Co 84/08/15 STOLZ, J F Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 2pp 26287 144 24X Fiche 50-313, 84/08/15, 8408280184

--8408280188 "Reanalysis Against 10CFR50, App R, Sections III G, J & O "
* Arkansas Power & Light Co 84/08/15 120pp 26287 146 24X Fiche 50-313, 84/08/15, 8408280184

8408230401 Revised Emergency Procedures 1903 72 re St Marys Hosp, 1903 73 re Millard-Henry clinic & 1903 74 re Pope County ambulance svc
* Arkansas Power & Light Co 84/08/16 7pp 26206 001 24X Fiche 50-313, 84/08/16, 8408230401

8408230417 Deletion of Rev 0 to Procedure 1903 34, "Administration of Potassium Iodide "
* Arkansas Power & Light Co 84/08/29 3pp 26204 011 24X Fiche 50-313, 84/08/29, 8408230417

P Operating license stage documents & correspondence

8408020031 Informs of planned mod to C-E control element assembly guide tube wear sleeve Mod includes relocation of sleeve flare, sleeve expansion over full length of sleeve & relocation of crimp, providing resistance to axial motion
SCHERER, A E Combustion Engineering, Inc 84/07/27
RUBENSTEIN, L S Assistant Director for Core & Plant Systems 2pp 25880 258 24X Fiche 50-000, 84/07/27, 8408020031

8408070483 Forwards Rev 6 to QA manual - operations Return receipt requested
MARSHALL, J Arkansas Power & Light Co 84/07/31 Record Services Branch (Document Control Desk) 1p 25941 215 24X
Fiche 50-313, 84/07/31, 8408070483

--8408070485 Rev 6 to QA manual - operations
* Arkansas Power & Light Co 84/05/30 158pp 25941 216 24X Fiche 50-313, 84/07/31, 8408070483

8408130367 Summarizes 840712 meeting w/NRC, Technology for Energy Corp & Bcan Power in Bethesda, MD re inadequate core cooling instrument installation Supporting documentation encl
MARSHALL, J R Arkansas Power & Light Co 84/08/01 MILLER, J R Operating Reactors Branch 3 35pp 26005 302 24X
Fiche 50-368, 84/08/01, 8408130367

08200219 Denies 830927 request to revise Tech Specs re containment hydrogen analyzers Present calibr requirement preferred because of more accurate hydrogen concentration measurement
MILLER, J R Operating Reactors Branch 3 84/08/01 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26142 286 24X
Fiche 50-368, 84/08/01, 8408200219

408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140328 Documents resolution of environ qualification deficiencies identified in SER & discussed at 840426 meeting Matrix of qualification deficiencies & proposed resolution & justification for continued operation encl
MARSHALL, J R Arkansas Power & Light Co 84/08/06 MILLER, J R
Operating Reactors Branch 3 80pp 26043 317 24X
Fiche 50-368, 84/08/06, 8408140328

8408140355 Forwards corrected cover sheets for Copies 1-6 of Rev 6 to "QA Manual Operations "
MARSHALL, J R Arkansas Power & Light Co 84/08/06 Record Services Branch (Document Control Desk) 7pp 26041 037 24X
Fiche 50-313, 84/08/06, 8408140355

8408170061 Forwards corrected coversheet for Rev 6 to QA manual operations Revised coversheet reflects Control Copy 7
MARSHALL, J R Arkansas Power & Light Co 84/08/06 ANKRUM, G T QA Branch. 4pp 26119 018 24X Fiche 50-313, 84/08/06, 8408170061

8408200303 Informs that response to Recommendation GL-2 re inadvertent closure to condensate storage tank isolation valve (NUREG-0737, Item II E 1 1) will be delayed until 840824 due to outage preparation work
MARSHALL, J R Arkansas Power & Light Co 84/08/10 STOLZ, J F,
Operating Reactors Branch 4 1p 26133 358 24X
Fiche 50-313, 84/08/10, 8408200303

8408280033 Summary of 840712 meeting w/util, Technology for Energy Corp & Scandpower in Bethesda, MD re inadequate core cooling monitoring sys, installation schedule, project status & preliminary test results Viewgraphs encl
LEE, R S Operating Reactors Branch 3 84/08/17 Operating Reactors Branch 3 35pp 26293 121 24X Fiche 50-368, 84/08/17, 8408280033

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310231 Forwards revs to proposed Tech Spec changes for NUREG-0737 items re containment radiation monitors & post-accident sampling, per Generic Ltr 83-37
GRIFFIN, J M Arkansas Power & Light Co 84/08/22 STOLZ, J F
Operating Reactors Branch 4 12pp 26320 314 24X
Fiche 50-313, 84/08/22, 8408310231

0 Inspection reports, IE Bulletins & correspondence

8408150372 Forwards IE Insp Repts 50-313/84-11 & 50-368/84-11 on 840326-29 & notice of violation One unresolved item re maint program identified in Paragraph 2 of insp rept should be addressed in detail
JOHNSON, E H Region 4, Office of Director 84/05/16 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26075 181 24X
Fiche 50-313, 84/05/16, 8408150372

--8408150375 IE Insp Repts 50-313/84-11 & 50-368/84-11 on 840326-30
Violations noted failure to document & follow procedures for maint of MSIVs & HPCI valves
BOARDMAN, J R , JOHNSON, W D , JAUDON, J P Region 4, Office of Director 84/05/16 4pp 26075 185 24X Fiche 50-313, 84/05/16, 8408150372

8408090150 Forwards IE Insp Repts 50-313/84-18 & 50-368/84-18 on 840601-30 No violations or deviations identified
JOHNSON, E H Region 4, Office of Director 84/07/11 GRIFFIN, J M
Arkansas Power & Light Co 2pp 25993 178 24X
Fiche 50-313, 84/07/11, 8408090150

--8408090160 IE Insp Repts 50-313/84-18 & 50-368/84-18 on 840601-30 No violations identified Major areas inspected maint, surveillance, operational safety verification & followup on IE bulletins & Generic Ltr 83-28
JOHNSON, W D , HARRELL, P H , MARTIN, L E Region 4, Office of Director 84/07/11 11pp 25993 180 24X Fiche 50-313, 84/07/11, 8408090150

8408090121 Forwards IE Insp Repts 50-313/83-35 & 50-368/83-35 on 831205-08 & notice of violation W/a notice of violation
HUNTER, D R Region 4, Office of Director 84/07/17 GRIFFIN, J M
Arkansas Power & Light Co 2pp 25993 148 24X
Fiche 50-313, 84/07/17, 8408090121

--8408090130 IE Insp Repts 50-313/83-35 & 50-368/83-35 on 831205-08
Noncompliance noted failure to verify that matls conform to procurement documents
ELLERSHAW, L E , JOHNSON, W D , BARNES, I Region 4, Office of Director 84/02/21 9pp 25993 150 24X Fiche 50-313, 84/07/17, 8408090121

8408150312 Ack receipt of 840615 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/84-11 & 50-368/84-11 Future insp will determine if corrective actions achieve compliance
JOHNSON, E H Region 4, Office of Director 84/07/23 GRIFFIN, J M
Arkansas Power & Light Co 1p 26074 350 24X
Fiche 50-313, 84/07/23, 8408150312

--8408150317 Responds to NRC 840516 ltr re violations noted in IE Insp Repts 50-313/84-11 & 50-368/84-11 Requests addl time to complete response to items noted in rept Response will be forwarded by 840629
MARSHALL, J R Arkansas Power & Light Co 84/06/15 DENISE, R P
Division of Resident, Reactor Project & Engineering Programs 1p 26074 351 24X Fiche 50-313, 84/07/23, 8408150312

8408160498 Forwards IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted
HUNTER, D R Region 4, Office of Director 84/07/23 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26107 318 24X
Fiche 50-313, 84/07/23, 8408160498

--8408160504 IE Insp Repts 50-313/84-20 & 50-368/84-20 on 840619-22 No violations or deviations noted Major areas inspected security program audit & physical barriers Details withheld (ref 10CFR73 21)
EVANS, C A , HULL, R E , MARTIN, L E Region 4, Office of Director
84/07/23 1p 26107 320 24X Fiche 50-313, 84/07/23, 8408160498

8408090022 Discusses IE insp on 831205-08 & forwards notice of violation & proposed imposition of civil penalty Util failed to apply controls for procurement & installation of safety-related fasteners, per App B to 10CFR50 W/o encl
COLLINS, J T Region 4, Office of Director 84/07/25 GRIFFIN, J M
Arkansas Power & Light Co 5pp 25992 089 24X
Fiche 50-313, 84/07/25, 8408090022

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11Spp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408080055 Forwards summary statement of IAEA insp activities from Oct 1983 to Mar 1984, for review Requests confirmation in 30 days concerning proprietary status of documents Info withheld (ref 10CFR2 790)
MILLER, J R Operating Reactors Branch 3 84/07/27 GRIFFIN, J M
Arkansas Power & Light Co 2pp 25981 070 24X
Fiche 50-368, 84/07/27, 8408080055

8408290113 Forwards exam rept of exam administered on 840718
HUNTER, D R Region 4, Office of Director 84/08/01 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26297 250 24X
Fiche 50-368, 84/08/01, 8408290113

--8408290115 Exam rept administered on 840718 Exam results senior reactor operator & reactor operator passed
MCCRORY, S L , COOLEY, R A Region 4, Office of Director 84/08/01
22pp 26297 252 24X Fiche 50-368, 84/08/01, 8408290113

8408290172 Forwards exam rept administered on 840614-15
HUNTER, D R Region 4, Office of Director 84/08/01 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26297 001 24X
Fiche 50-368, 84/08/01, 8408290172

--8408290176 Exam rept administered on 840614-15 Exam results all candidates passed
MCCRORY, S L , COOLEY, R A Region 4, Office of Director 84/08/01
19pp 26297 003 24X Fiche 50-368, 84/08/01, 8408290172

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408300154 Requests withdrawal of 840725 notice of violation & proposed imposition of civil penalty Corrective actions initiated prior to enforcement action, including augmenting QA staff, retraining QC staff & increasing vendor surveys
MARSHALL, J R Arkansas Power & Light Co 84/08/24 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp.
26304 257 24X Fiche 50-313, 84/08/24, 8408300154

--8408300160 Licensee response to 840725 notice of violation Violation admitted & corrective actions outlined
* Commissioners 84/08/24 12pp 26304 260 24X
Fiche 50-313, 84/08/24, 8408300154

--8408300166 Licensee answer protesting 840725 civil penalty Notice of violation fails to allow for corrective actions initiated prior to enforcement action
* Commissioners 84/08/24. 10pp 26304 272 24X
Fiche 50-313, 84/08/24, 8408300154

S Reportable occurrences, LERs & related correspondence

8408060187 LER 84-014-00 on 840618, reactor turbine trip occurred at approx 8% full power due to high level in steam generator A Caused by main feedwater bypass regulating valve E/P converter malfunction W/840717 ltr
MARSHALL, J R , ROGERS, P C Arkansas Power & Light Co 84/07/17
3pp 25935 187 24X Fiche 50-368, 84/07/17, 8408060187

8408080528 LER 84-013-00 on 840617, reactor tripped from full power on low DNBR due to penalty factors generated by core protection calculators Caused by dropped control element assembly W/840717 ltr
ROGERS, P C , MARSHALL, J R Arkansas Power & Light Co 84/07/17
3pp 25975 295 24X Fiche 50-368, 84/07/17, 8408080528

8408080500 LER 84-016-00 on 840621, penetration fire barrier damper mfg by American Warming & Ventilating, Inc, failed to completely close upon fusible link removal Caused by metal shaving on pivot section of damper blades W/840723 ltr
LOMAX, D B , MARSHALL, J R Arkansas Power & Light Co 84/07/23
3pp 25975 237 24X Fiche 50-368, 84/07/23, 8408080500

8408080512 LER 84-015-00 on 840302, breach of required fire barrier identified Addl breach identified on 840622 Caused by inadequate evaluation during original review Fire watches established Repairs underway W/840723 ltr
CAMPBELL, P L , MARSHALL, J R Arkansas Power & Light Co 84/07/23
3pp 25975 264 24X Fiche 50-368, 84/07/23, 8408080512

8408080493 Updated LER 80-026/03X-1 on 800514, control room emergency air conditioner compressor trip occured on freeze protection Caused by insufficient load when providing cooling from core protection calculator room W/840724 ltr
ROGERS, P , MARSHALL, J R Arkansas Power & Light Co 84/07/24 3pp
25975 202 24X Fiche 50-368, 84/07/24, 8408080493

8408240077 LER 84-017-00 on 840713, fire barrier penetration 2124-0004 discovered degraded by engineering personnel while working on HVAC mods Fire watch established Barrier repaired W/840813 ltr
CAMPBELL, P L , MARSHALL, J R Arkansas Power & Light Co 84/08/13
2pp 26236 139 24X Fiche 50-368, 84/08/13, 8408240077

8408240080 LER 79-086/03X-2 on 791013, during Mode 6 shutdown cooling HX 2E35B radiation monitor increased & small vol tube leak indicated in HX Cause not stated HX examined & plugged W/ 840815 ltr
MARSHALL, J R Arkansas Power & Light Co 84/08/15 5pp
26237 018 24X Fiche 50-368, 84/08/15, 8408240080

8408300475 LER 84-018-00 on 840718, operator discovered train B sodium hydroxide pump (2P136B) manual discharge isolation valve (2B6-110) in locked closed position Caused by failure to reposition valve following 840618 surveillance W/840820 ltr
LOMAX, B B , MARSHALL, J R Arkansas Power & Light Co 84/08/20
3pp 26314 006 24X Fiche 50-368, 84/08/20, 8408300475

8408300496 LER 84-019-00 840720, manual reactor trip initiated from 100% full power following spurious half-leg trip Caused by operator inadvertently pressing alternate source to load button instead of reset button W/840820 ltr
ROGERS, P , MARSHALL, J R Arkansas Power & Light Co 84/08/20 2pp
26314 069 24X Fiche 50-368, 84/08/20, 8408300496

V Operator Examinations

8408290113 Forwards exam rept of exam administered on 840718
HUNTER, D R Region 4, Office of Director 84/08/01 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26297 250 24X
Fiche 50-368, 84/08/01, 8408290113

--8408290115 Exam rept administered on 840718 Exam results senior reactor operator & reactor operator passed
MCCRORY, S L , COOLEY, R A Region 4, Office of Director 84/08/01
22pp 26297 252 24X Fiche 50-368, 84/08/01, 8408290113

8408290172 Forwards exam rept administered on 840614-15
HUNTER, D R Region 4, Office of Director 84/08/01 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26297 001 24X
Fiche 50-368, 84/08/01, 8408290172

--8408290176 Exam rept administered on 840614-15 Exam results all candidates passed
MCCRORY, S L , COOLEY, R A Region 4, Office of Director 84/08/01
19pp 26297 003 24X Fiche 50-368, 84/08/01, 8408290172

DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

Security, medical, emergency & fire protection plans

08300193 Forwards 840612 ltr detailing overall planning for 840620 French security team visit to facility Biographical info for each team member included
LEWIS, R C Region 2, Office of Director 84/06/15 TUCKER, H B
Duke Power Co 1p 26300 139 24X Fiche 50-000, 84/06/15, 8408300193

8408300204 Requests authorization for six French security experts hosted by NRC to visit McGuire facility on 840620 & Sequoyah facility on 840622 Biographical info & itinerary encl
LAFLEUR, J D Office of International Programs, Director
84/06/12 TUCKER, H B Duke Power Co PARRIS, H G Tennessee Valley Authority 5pp 26300 140 24X Fiche 50-000, 84/06/15, 8408300193

8408270444 Forwards Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/24 TUCKER, H B
Duke Power Co 2pp 26256 353 24X Fiche 50-369, 84/07/24, 8408270444

--8408270447 Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted Major areas inspected health physics organizations, staff qualifications solid radwaste mgt, transportation of radioactive matls & ALARA program
WRAY, J R , JENKINS, G R Region 2, Office of Director 84/07/24
6pp 26256 355 24X Fiche 50-369, 84/07/24, 8408270444

8408070298 Informs that requested info re detailed control room design review provided in licensee 840409, 0525 & 0216 submittals, per Suppl 1 to NUREG-0737 Task analyses for inadequate core cooling & ATWS event conducted during control room review
TUCKER, H B Duke Power Co 84/07/27 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
4 2pp 25947 295 24X Fiche 50-369, 84/07/27, 8408070298

8408200100 Forwards deviations & technical justifications from App R criteria, per fire protection program review
TUCKER, H B Duke Power Co 84/08/03 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
4 26133 311 24X Fiche 50-369, 84/08/03, 8408200100

8408300357 Confirms 840806 telcon w/JP O'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50, fire protection & 10CFR73, physical protection Agenda encl
LEWIS, R C Region 2, Office of Director 84/08/08 TUCKER, H B
Duke Power Co 3pp 26314 222 24X Fiche 50-000, 84/08/08, 8408300357

8408300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
TUCKER, H B Duke Power Co 84/08/10 Record Services Branch
(Document Control Desk) 21pp 26332 353 24X
Fiche 50-000, 84/08/10, 8408300014

--8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations "
Duke Power Co 84/08/15 30pp 26333 010 24X
Fiche 50-000, 84/08/10, 8408300014

--8408300028 Public version of revised crisis mgt plan implementing procedures, including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 memo
Duke Power Co 84/08/15 170pp 26333 040 24X
Fiche 50-000, 84/08/10, 8408300014

I Financial information

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
4 2pp 26237 137 24X Fiche 50-000, 84/08/16, 8408240224

--8408240239 "1983 Annual Rept "
CLAY, G W , SHAW, R W North Carolina Municipal Power Agencies
83/12/31 27pp 26237 139 24X Fiche 50-000, 84/08/16, 8408240224

--8408240242 "1983 Annual Rept "
LEE, W S , BOOTH, D W Duke Power Co 83/12/31 47pp 26237 167
24X Fiche 50-000, 84/08/16, 8408240224

J Insurance & indemnity information

8408220148 Forwards Endorsement 13 to NELIA Policy NF-281 & Endorsement 7 to MAELU Policy MF-112
DJEMAL, A Marsh & McLennan, Inc 84/08/14 DINITZ, I Assistant
Director for State & Licensee Relations 3pp 26188 071 24X
Fiche 50-369, 84/08/14, 8408220148

P Operating license stage documents & correspondence

8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification
WIGGINTON, D L Operating Reactors Branch 1 84/07/30 Operating
Reactors Branch 1 4pp 26143 265 24X Fiche 50-000, 84/07/30, 8408160425

8408030130 Application for amend to Licenses NPF-9 & NPF-17, changing Tech Specs to provide operability & surveillance requirements for addl subcooling margin monitor sys channel & reactor vessel level instrumentation sys
TUCKER, H B Duke Power Co 84/07/31 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
4 3pp 25916 129 24X Fiche 50-369, 84/07/31, 8408030130

--8408030139 Proposed Tech Specs providing operability & surveillance requirements for addl subcooling margin monitor sys channel & reactor vessel level instrumentation sys
Duke Power Co 84/07/31 4pp 25916 132 24X
Fiche 50-369, 84/07/31, 8408030130

8408130169 Forwards description & justification for proposed piping seismic analysis changes, adopting damping values & spectra shifting methods for piping sys, per NRC recommendations, for review/approval
TUCKER, H B Duke Power Co 84/08/01 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
4 3pp 26010 027 24X Fiche 50-369, 84/08/01, 8408130169

8408070468 Forwards proprietary addl info re spent fuel pool two region rerack mods, addressing concerns raised during 840731 meeting Affidavit will be submitted by Westinghouse Info withheld (ref 10CFR2 790)
TUCKER, H B Duke Power Co 84/08/02 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
4 1p 25941 194 24X Fiche 50-369, 84/08/02, 8408070468

8408070110 Generic Ltr 84-19 to all licensees or operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, 'Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160050 Forwards summary evaluation of main steam line break analysis for both inside containment & in doghouse Plant safety would not be adversely affected in event of design basis main line break in doghouse or inside containment
TUCKER, H B Duke Power Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 7pp 26092 068 24X Fiche 50-369, 84/08/08, 8408160050

8408160174 Forwards corrected page to 840802 addl info attachment re spent fuel pool two region rerack mods Only Page 1 of attachment considered proprietary to Westinghouse
TUCKER, H B Duke Power Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 26092 034 24X Fiche 50-369, 84/08/13, 8408160174

8408230527 Forwards payment for application fee re 840802 & 08 Tech Spec changes
BARR, S Duke Power Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26236 286 24X
Fiche 50-000, 84/08/15, 8408230527

8408270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submittal of semiannual radioactive effluent release rept for Jul-Dec 1984
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26279 112 24X
Fiche 50-000, 84/08/16, 8408270160

--8408270169 Rev 4 to "Offsite Dose Calculation Manual "
BIRCH, M L Duke Power Co 84/07/18 39pp 26279 114 24X
Fiche 50-000, 84/08/16, 8408270160

8408210396 Forwards info documenting results of review & implementation of required changes & mods, per Generic Ltr 81-07, "Control of Heavy Loads" & NUREG-0612 Minor error noted in B01222 ltr corrected
TUCKER, H B Duke Power Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 36pp 26180 271 24X Fiche 50-369, 84/08/17, 8408210396

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8408300356 Confirms 840502 telcon between GE Vaughn & HC Dance re 840509 enforcement meeting to discuss improper restoration of centrifugal charging pump & failure to perform local independent verification at site Proposed agenda encl
O'REILLY, J P Region 2, Office of Director 84/05/07 TUCKER, H B
Duke Power Co 2pp 26308 201 24X Fiche 50-369, 84/05/07, 8408300356

8408280230 Forwards rept required by Action Item 4 of IE Bulletin 82-02 providing info re Action Items 1 & 2 IE Insp Repts 50-369/84-06 & 50-370/84-06 addressed work on threaded fasteners & joints
TUCKER, H B Duke Power Co 84/07/19 O'REILLY, J P Region 2, Office of Director 2pp 26262 349 24X Fiche 50-369, 84/07/19, 8408280230

8408270383 Forwards Insp Repts 50-369/84-18 & 50-370/84-15 on 840709-11 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/20 TUCKER, H B
Duke Power Co 2pp 26256 271 24X Fiche 50-369, 84/07/20, 8408270383

--8408270386 Insp Repts 50-369/84-18 & 50-370/84-15 on 840709-11, No violations or deviations noted Major areas inspected: gaseous & liquid waste sys, radiological effluent accountability & reactor coolant & secondary water Tech Spec requirements
KUZO, G B , WRAY, J R , MONTGOMERY, D M Region 2, Office of Director 84/07/18 5pp 26256 273 24X Fiche 50-369, 84/07/20, 8408270383

8408270444 Forwards Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/24 TUCKER, H B
Duke Power Co 2pp 26256 353 24X Fiche 50-369, 84/07/24, 8408270444

--8408270447 Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted Major areas inspected health physics organizations, staff qualifications solid radwaste mgt, transportation of radioactive matls & ALARA program
WRAY, J R , JENKINS, G R Region 2, Office of Director 84/07/24 6pp 26256 355 24X Fiche 50-369, 84/07/24, 8408270444

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408270249 Ack receipt of 840725 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/84-11 & 50-370/84-09
LEWIS, R C Region 2, Office of Director 84/08/09 TUCKER, H B
Duke Power Co 1p 26258 108 24X Fiche 50-369, 84/08/09, 8408270249

--8408270259 Responds to NRC 840625 ltr re violations noted in Insp Repts 50-369/84-11 & 50-370/84-09 Corrective actions containment integrity reviewed at end of each outage to assure mods have not affected containment integrity
TUCKER, H B Duke Power Co 84/07/25 O'REILLY, J P Region 2, Office of Director 4pp 26258 109 24X Fiche 50-369, 84/08/09, 8408270249

--8408270266 Forwards Insp Repts 50-369/84-11 & 50-370/84-09 on 840220-0420 & notice of violation
LEWIS, R C Region 2, Office of Director 84/06/25 TUCKER, H B
Duke Power Co 2pp 26258 113 24X Fiche 50-369, 84/08/09, 8408270249

--8408270270 Notice of violation from insp on 840220-0420
* Region 2, Office of Director 84/06/25 2pp 26258 115 24X
Fiche 50-369, 84/08/09, 8408270249

--8408270279 Insp Repts 50-369/84-11 & 50-370/84-09 on 840220-0420 Noncompliance noted one procedure for ESF test inadequate & one procedure not followed, resulting in inadvertent Train A blackout & failure to perform required testing
ORDERS, W , PIERSON, R , BROWNLEE, V L Region 2, Office of Director 84/06/21 12pp 26258 117 24X Fiche 50-369, 84/08/09, 8408270249

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408280234 Submits supplemental response to IE Bulletin 84-02 re failure of GE Type HFA relays in use in Class 1E safety sys Relays not in use in safety-related sys
TUCKER, H B Duke Power Co 84/08/13 O'REILLY, J P Region 2, Office of Director 1p 26262 284 24X Fiche 50-369, 84/08/13, 8408280234

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

Periodic operating reports & related correspondence

8408220465 Monthly operating repts for Jul 1984 W/840815 ltr
REAVIS, J A , TUCKER, H B Duke Power Co 84/07/31 15pp
26196 050 24X Fiche 50-369, 84/07/31, 8408220465

Reportable occurrences, LERs & related correspondence

8408150221 LER 84-021-00 on 840702, reactor trip breaker of train A (RTB-A) inadvertently opened during testing Caused by misreading of instrumental & electrical procedure & deficiency in instructions Procedure rewritten W/840807 ltr
GEWEHR, S , TUCKER, H B Duke Power Co. 84/08/07 3pp 26073 361
24X Fiche 50-369, 84/08/07, 8408150221

8408240329 PNO-II-84-054: on 840821, after Unit 1 reactor tripped, operators manually isolated MSIVs to prevent overcooling, resulting in water hammer in secondary sys Damage being assessed
IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director
84/08/22 2pp 26225 306 24X Fiche 50-369, 84/08/22, 8408240329

8408280389 LER 84-023-00 on 840723, unit tripped from 100% power on lo-lo steam generator level indication Caused by feedwater sys solenoid valve failure Chart recorder added to feedwater valves by hydraulic pump motor W/840822 ltr
GEWEHR, S , TUCKER, H B Duke Power Co. 84/08/22 4pp 26282 104
24X Fiche 50-369, 84/08/22, 8408280389

8408280158 PNO-II-84-054A on 840821, reactor trip occurred due to partial loss of offsite power Caused by inadvertent opening of switchyard computer operated breakers Reactors restarted
IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director
84/08/23 1p 26259 212 24X Fiche 50-369, 84/08/23, 8408280158

U Congressional/Executive Correspondence

8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far
ASSELSTINE, J K Commissioners. 84/08/10 MARKEY, E J House of Rep , Interior & Insular Affairs 4pp 26141 244 24X
Fiche: 50-000, 84/08/10, 8408200225

--8408200279 Requests further info re Tech Spec errors for specs approved since TMI-2 episode Info re near-term OL activities also requested
MARKEY, E J House of Rep , Interior & Insular Affairs 84/07/12
PALLADINO, N J Commissioners 1p 26142 002 24X
Fiche 50-000, 84/08/10, 8408200225

DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8408300193 Forwards 840612 ltr detailing overall planning for 840620 French security team visit to facility Biographical info for each team member included
LEWIS, R C Region 2, Office of Director 84/06/15 TUCKER, H B
Duke Power Co 1p 26300 139 24x Fiche 50-000, 84/06/15, 8408300193

--8408300204 Requests authorization for six French security experts hosted by NRC to visit McGuire facility on 840620 & Sequoyah facility on 840622 Biographical info & itinerary encl
LAFLEUR, J D Office of International Programs, Director
84/06/12 TUCKER, H B Duke Power Co 5pp 26300 140 24X
Fiche 50-000, 84/06/15, 8408300193

8408270444 Forwards Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/24 TUCKER, H B
Duke Power Co 2pp 26256 353 24X Fiche 50-369, 84/07/24, 8408270444

--8408270447 Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted Major areas inspected health physics organizations, staff qualifications solid radwaste mgt, transportation of radioactive matls & ALARA program
WRAY, J R Region 2, Office of Director 84/07/24 6pp
26256 355 24X Fiche 50-369, 84/07/24, 8408270444

8408070298 Informs that requested info re detailed control room design review provided in licensee 840409, 0525 & 0216 submittals, per Suppl 1 to NUREG-0737 Task analyses for inadequate core cooling & ATWS event conducted during control room review
TUCKER, H B Duke Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 25947 295 24X Fiche 50-369, 84/07/27, 8408070298

8408200100 Forwards deviations & technical justifications from App R criteria, per fire protection program review
TUCKER, H B Duke Power Co 84/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 4pp 26133 311 24X Fiche 50-369, 84/08/03, 8408200100

8408300357 Confirms 840806 telcon w/JP O'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50, fire protection & 10CFR73, physical protection Agenda encl
LEWIS, R C Region 2, Office of Director 84/08/08 TUCKER, H B
Duke Power Co 3pp 26314 222 24X Fiche 50-000, 84/08/08, 8408300357

8408300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
TUCKER, H B Duke Power Co 84/08/10 Record Services Branch
(Document Control Desk) 21pp 26332 353 24X
Fiche 50-000, 84/08/10, 8408300014

--8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations "
* Duke Power Co 84/08/15 30pp 26333 010 24X
Fiche 50-000, 84/08/10, 8408300014

--8408300028 Public version of revised crisis mgt plan implementing procedures, including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 memo.
* Duke Power Co 84/08/15 170pp 26333 040 24X
Fiche 50-000, 84/08/10, 8408300014

I Financial Information

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R, Office of Nuclear Reactor Regulation, Director 2pp 26237 137 24X
Fiche 50-000, 84/08/16, 8408240224

--8408240239 "1983 Annual Rept "
CLAY, G W North Carolina Municipal Power Agencies 83/12/31
27pp 26237 139 24X Fiche 50-000, 84/08/16, 8408240224

--8408240242 "1983 Annual Rept "
LEE, W S Duke Power Co 83/12/31 47pp 26237 167 24X
Fiche 50-000, 84/08/16, 8408240224

P Operating license stage documents & correspondence

8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification
WIGGINTON,D L Operating Reactors Branch 1 84/07/30 Operating Reactors Branch 1 4pp 26143 269 24X Fiche 50-000,84/07/30, 8408160425

8408030130 Application for amend to Licenses NPF-9 & NPF-17, changing Tech Specs to provide operability & surveillance requirements for addl subcooling margin monitor sys channel & reactor vessel level instrumentation sys
TUCKER,H B Duke Power Co 84/07/31 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 3pp 25916 129 24X Fiche 50-369,84/07/31,8408030130

--8408030135 Proposed Tech Specs providing operability & surveillance requirements for addl subcooling margin monitor sys channel & reactor vessel level instrumentation sys
* Duke Power Co 84/07/31 4pp 25916 132 24X
Fiche 50-369,84/07/31,8408030130

8408130169 Forwards description & justification for proposed piping seismic analysis changes, adopting damping values & spectra shifting methods for piping sys, per WRC recommendations, for review/approval
TUCKER,H B Duke Power Co 84/08/01 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 3pp 26010 027 24X Fiche 50-369,84/08/01,8408130169

8408070468 Forwards proprietary addl info re spent fuel pool two region rerack mods, addressing concerns raised during 840731 meeting Affidavit will be submitted by Westinghouse Info withheld (ref 10CFR2 790)
TUCKER,H B Duke Power Co 84/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 1p 25941 194 24X Fiche 50-369,84/08/02,8408070468

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408160050 Forwards summary evaluation of main steam line break analysis for both inside containment & in doghouse Plant safety would not be adversely affected in event of design basis main line break in doghouse or inside containment
TUCKER,H B Duke Power Co 84/08/08 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 7pp 26092 068 24X Fiche 50-369,84/08/08,8408160050

8408160174 Forwards corrected page to 840802 addl info attachment re spent fuel pool two region rerack mods Only Page 1 of attachment considered proprietary to Westinghouse
TUCKER,H B Duke Power Co 84/08/13 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 26092 034 24X Fiche 50-369,84/08/13,8408160174

8408230527 Forwards payment for application fee re 840802 & 08 Tech Spec changes
BARR,G Duke Power Co 84/08/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 26236 286 24X
Fiche 50-000,84/08/15,8408230527

8408270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submittal of semiannual radioactive effluent release rept for Jul-Dec 1984
TUCKER,H B Duke Power Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26279 112 24X
Fiche 50-000,84/08/16,8408270160

--8408270169 Rev 4 to "Offsite Dose Calculation Manual "
BIRCH,M L Duke Power Co 84/07/18 39pp 26279 114 24X
Fiche 50-000,84/08/16,8408270160

8408210396 Forwards info documenting results of review & implementation of required changes & mods, per Generic Ltr 81-07, "Control of Heavy Loads" & NUREG-0612 Minor error noted in 801222 ltr corrected
TUCKER,H B Duke Power Co 84/08/17 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 36pp 26180 271 24X Fiche 50-369,84/08/17,8408210396

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

O Inspection reports, IE Bulletins & correspondence

8408270383 Forwards Insp Repts 50-369/84-18 & 50-370/84-15 on 840709-11 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/20 TUCKER,H B Duke Power Co 2pp 26256 271 24X Fiche 50-369,84/07/20, 8408270383

--8408270386 Insp Repts 50-369/84-18 & 50-370/84-15 on 840709-11 No violations or deviations noted Major areas inspected gaseous & liquid waste sys radiological effluent accountability & reactor coolant & secondary water Tech Spec requirements
KUZO,G B , WRAY,J R , MONTGOMERY,D M Region 2, Office of Director 84/07/18 5pp 26256 273 24X Fiche 50-369,84/07/20, 8408270383

8408270444 Forwards Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/24 TUCKER,H B Duke Power Co 2pp 26256 353 24X Fiche 50-369,84/07/24, 8408270444

--8408270447 Insp Repts 50-369/84-19 & 50-370/84-16 on 840709-13 No violations or deviations noted Major areas inspected health physics organizations, staff qualifications solid radwaste mgt, transportation of radioactive matls & ALARA program
WRAY,J R , JENKINS,G R. Region 2, Office of Director 84/07/24 6pp 26256 355 24X Fiche 50-369,84/07/24,8408270444

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25869 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp. 26067 158. 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche. 50-000,84/08/08,8408070120

8408270249 Ack receipt of 840725 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-369/84-11 & 50-370/84-09
LEWIS,R C Region 2, Office of Director 84/08/09 TUCKER,H B Duke Power Co 1p 26258 108 24X Fiche 50-369,84/08/09, 8408270249

--8408270259 Responds to NRC 840625 ltr re violations noted in Insp Repts 50-369/84-11 & 50-370/84-09 Corrective actions' containment integrity reviewed at end of each outage to assure mods have not affected containment integrity
TUCKER,H B Duke Power Co. 84/07/25 O'REILLY,J P Region 2, Office of Director 4pp 26258 109 24X Fiche 50-369,84/08/09, 8408270249

--8408270266 Forwards Insp Repts 50-369/84-11 & 50-370/84-09 on 840220-0420 & notice of violation
LEWIS,R C Region 2, Office of Director 84/06/25 TUCKER,H B Duke Power Co. 2pp 26258 113 24X Fiche 50-369,84/08/09, 8408270249

--8408270270 Notice of violation from insp on 840220-0420.
* Region 2, Office of Director 84/06/25 2pp. 26258 115 24X
Fiche 50-369,84/08/09,8408270249

DOCKETED ITEMS

8408270279 Insp Repts 50-369/84-11 & 50-370/84-09 on 840220-0420
Noncompliance noted one procedure for ESF test inadequate &
one procedure not followed, resulting in inadvertent Train A
blackout & failure to perform required testing
ORDERS, W , PIERSON, R , BROWNLEE, V L Region 2, Office of Director
84/06/21 12pp 26238 117 24X Fiche 50-369, 84/08/09,
8408270249

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to
Patients Undergoing Co-60 Teletherapy Treatments " Svc
list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post
830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New
York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408280234 Submits supplemental response to IE Bulletin 84-02 re
failure of GE Type HFA relays in use in Class 1E safety
sys Relays not in use in safety-related sys
TUCKER, H B Duke Power Co 84/08/13 O'REILLY, J P Region 2,
Office of Director 1p 26262 286 24X Fiche 50-369, 84/08/13,
8408280234

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In &
Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New
York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely
Affect Operation of Essential Electrical Equipment " Svc
list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New
York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of
Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/
High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly
Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New
York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

Periodic operating reports & related correspondence

8408220465 Monthly operating repts for Jul 1984 W/840815 ltr
REAVIS, J A , TUCKER, H B Duke Power Co 84/07/31 15pp
26196 050 24X Fiche 50-369, 84/07/31, 8408220465

8408300509 Corrected monthly operating rept for Jul 1984 W/840823 ltr
REAVIS, J A , TUCKER, H B Duke Power Co 84/07/31 3pp 26313 308
24X Fiche 50-370, 84/07/31, 8408300509

Reportable occurrences, LERs & related correspondence

8408090274 LER 84-015-00 on 840703, test indicator lamp on MSIV failed
to light, leading to inadvertent MSIV closure & automatic ESF
actuation Caused by personnel error Personnel cautioned
W/840802 ltr
GEWEHR, S , TUCKER, H B Duke Power Co 84/08/02 3pp 25994 148
24X Fiche 50-370, 84/08/02, 8408090274

8408140324 PNO-II-84-046 on 830806, w/unit in cold shutdown, packing ring
blew out from chemical & vol control sys letdown line valve
connected to RHR sys Line break occurred in auxiliary bldg
room socket weld, discharging 3,500 gallons water
IGNATONIS, A , BROWNLEE, V L Region 2, Office of Director 84/08/06
2pp 26042 351 24X Fiche 50-370, 84/08/06, 8408140324

8408230001 PNO-II-84-052 on 840820, leak developed inside containment
while upper head injection sys filled & checked for air
entrapment Caused by glass on upper head injection sys
ng pressurization No environ release occurred
BROWNLEE, V L Region 2, Office of Director
26209 158 24X Fiche 50-370, 84/08/20, 8408230001

8408290094 LER 84-016-00 on 840719, reactor tripped during testing
Caused by operation of reactor trip breaker from control
room rather than test cabinet Test procedure to be
rewritten Event reviewed by personnel W/840817 ltr
GEWEHR, S , TUCKER, H B Duke Power Co 84/08/20 4pp 26298 001
24X Fiche 50-370, 84/08/20, 8408290094

8408240290 PNO-II-84-052A on 840820, 4,800 gallons reactor coolant
inventory spilled into reactor bldg sump area Caused by
sight glass being blown out of upper head injection sys
Alarm printer reviewed & sight glass replaced
IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director
84/08/21 2pp 26223 191 24X Fiche 50-370, 84/08/21, 8408240290

8408240329 PNO-II-84-054 on 840821, after Unit 1 reactor tripped,
operators manually isolated MSIVs to prevent overcooling,
resulting in water hammer in secondary sys Damage being
assessed
IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director
84/08/22 2pp 26225 306 24X Fiche 50-369, 84/08/22, 8408240329

8408280158 PNO-II-84-054A on 840821, reactor trip occurred due to
partial loss of offsite power Caused by inadvertent opening
of switchyard computer operated breakers Reactors restarted
IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director
84/08/23 1p 26259 212 24X Fiche 50-369, 84/08/23, 8408280158

U Congressional/Executive Correspondence

8408200225 Discusses Tech Spec errors discovered subsequent to NRC
approval Susquehanna Tech Spec amends had no safety
significance McGuire Tech Specs still under review w/no
identified safety significance thus far
ASSELSTINE, J K Commissioners 84/08/10 MARKEY, E J House of
Rep , Interior & Insular Affairs 4pp 26141 244 24X
Fiche 50-000, 84/08/10, 8408200225

--8408200279 Requests further info re Tech Spec errors for specs approved
since TMI-2 episode Info re near-term OL activities also
requested
MARKEY, E J House of Rep , Interior & Insular Affairs 84/07/12
PALLADINO, N J Commissioners 1p 26142 002 24X
Fiche 50-000, 84/08/10, 8408200225

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8404040169 Forwards exercise repts for LaSalle & Dresden offsite
radiological emergency preparedness exercises conducted
820414-15 & 0629-30, respectively
KRIMM, R W Federal Emergency Management Agency 84/03/26
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 22883 122 24X Fiche 50-000, 84/03/26,
8404040169

--8404040172 Evaluation of State of IL Full-scale emergency preparedness
exercise plan, final rept
* Federal Emergency Management Agency 82/05/31 68pp
22883 124 24X Fiche 50-000, 84/03/26, 8404040169

8408010289 Forwards IE Insp Repts 50-373/84-14 & 50-374/84-18 on
840512-0618 & notice of violation
BHAFER, W D Region 3, Office of Director 84/07/10 REED, C
Commonwealth Edison Co 2pp 25866 103 24X Fiche 50-373, 84/07/10,
8408010289

--8408010294 IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618
Noncompliance noted failure to control access to high
radiation area & failure to follow reactor vessel lo-lo
water level recirculation pump trip calibr test procedure
CHRISSOTIMOS, N Region 3, Office of Director 84/07/02 10pp
25866 107 24X Fiche 50-373, 84/07/10, 8408010289

8408140179 Rev 4 to Offsite Emergency Procedure LZP-1550-2, "Environs
Sampling Supplies Inventory " Revised index & 840808
transmittal form encl
* Commonwealth Edison Co 84/07/25 16pp 26044 332 24X
Fiche 50-373, 84/07/25, 8408140179

8408060095 Ack receipt of scope & objectives for 841010 emergency
preparedness exercise Objectives acceptable & unchanged from
840718 scenario development meeting
PAPERIELLO, C J Region 3, Office of Director 84/08/01 REED, C
Commonwealth Edison Co 1p 25922 001 24X Fiche 50-373, 84/08/01,
8408060095

--8408060101 Forwards scope & objectives for 841010 emergency preparedness exercise, per NRC/FEMA requirements
GREENE, T R Commonwealth Edison Co 84/07/25 HIND, J Division of Emergency Preparedness & Operational Support 5pp 25922 002
24X Fiche 50-373, 84/08/01, 8408060095

8408140139 Forwards listed revs to security plans Revs address fence height requirements Revs withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 84/08/03 Region 3, Office of Director 1p 26044 252 24X Fiche 50-000, 84/08/03, 8408140139

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO, C J Region 3, Office of Director 84/08/07 REED, C Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000, 84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR, D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000, 84/08/07, 8408130401

8408200230 Advises that 840803 Rev 19 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/08/14 FARRAR, D L Commonwealth Edison Co 2pp 26133 188 24X Fiche 50-373, 84/08/14, 8408200230

8408310233 Rev 1 to Emergency Plan Implementing Procedure LZP-1510-1, "Generating Station Emergency Procedure Operational Readiness " W/840824 transmittal memo
* Commonwealth Edison Co 84/08/17 10pp 26322 269 24X
Fiche 50-373, 84/08/17, 8408310233

8408270358 Forwards "Technical Basis of LaSalle County Station Fire Damper Surveillance Program," per 840328 agreement
RYBAK, B Commonwealth Edison Co 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26239 228 24X
Fiche 50-373, 84/08/21, 8408270358

--8408270362 "Technical Basis of LaSalle County Station Fire Damper Surveillance Program "
* Commonwealth Edison Co 84/08/31 326pp 26239 229 24X
Fiche 50-373, 84/08/21, 8408270358

P Operating license stage documents & correspondence

8408080148 Forwards Amends 17 & 2 to Licenses NPF-11 & NPF-18, respectively & safety evaluation Amends change Tech Specs re main line temp difference trip setpoints & allowable values
SCHWENCER, A Licensing Branch 2 84/07/03 FARRAR, D Commonwealth Edison Co 2pp, 25979 043 24X Fiche 50-373, 84/07/03, 8408080148

--8408080155 Amends 17 & 2 to Licenses NPF-11 & NPF-18, respectively, changing Tech Specs re main steamline temp difference trip setpoints & allowable values
SCHWENCER, A Licensing Branch 2 84/07/03 8pp 25979 045 24X
Fiche 50-373, 84/07/03, 8408080148

--8408080159 Safety evaluation supporting Amends 17 & 2 to Licenses NPF-11 & NPF-18, respectively
* Office of Nuclear Reactor Regulation, Director 84/07/03 2pp
25979 053 24X Fiche 50-373, 84/07/03, 8408080148

8408280360 Ack receipt of 840710 ltr re author criticism of NRC present rules & practices Reponse to NRC seven stages of discussion listed Past tests should be reviewed & leak rate be retested Related info encl
REYTBLATT, Z V Warren Wilson College, Swannanoa, NC 84/07/22
ROSS, D F Office of Nuclear Regulatory Research, Director 8pp
26293 001 24X Fiche 50-000, 84/07/22, 8408280360

--8408280366 Lists basic deficiencies & errors of present leak rate testing methodology as regulated by faulty stds
REYTBLATT, Z V Extran, Inc. 84/03/15 ACRS - Advisory Committee on Reactor Safeguards 3pp 26293 009 24X
Fiche 50-000, 84/07/22, 8408280360

--8408280373 Requests documents re RFP RS-RES-84-101, submitted on 840110 Author 840220 ltr to EM Gogol, Citizens Against Nuclear Power encl
REYTBLATT, Z V Extran, Inc 84/03/02 Division of Rules and Records 6pp 26293 012 24X Fiche 50-000, 84/07/22, 8408280360

--8408280380 Discusses author presentation on 840315 @ Arndt & ORNL should be heard before committee on faulty leak rate test Requests addl opportunity to present point of view
REYTBLATT, Z Extran, Inc 84/05/18 ACRS - Advisory Committee on Reactor Safeguards 1p 26293 023 24X Fiche 50-000, 84/07/22, 8408280360

8408010107 Forwards request for addl info re NUREG-0737, Item II D 1, including basis for application of findings of NEDE-24988-P, "Analysis of Generic BWR Safety & Relief Valve Operability Test Results," submitted by BWR Owners Group
SCHWENCER, A Licensing Branch 2 84/07/24 FARRAR, D L
Commonwealth Edison Co 4pp 25873 355 24X Fiche 50-373, 84/07/24, 8408010107

8408060145 Application for amend to Licenses NPF-11 & NPF-18, changing Tech Specs re accident monitoring instrumentation (NUREG-0737, Items II F 1 1, II F 1 3 & II F 1 6) Fee encl
MARSHALL, J G Commonwealth Edison Co 84/07/25 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25925 285
24X Fiche 50-373, 84/07/25, 8408060145

--8408060153 Proposed Tech Spec changes re accident monitoring instrumentation limiting conditions for operation for noble gas effluent monitors, containment high radiation monitors & containment hydrogen monitor
* Commonwealth Edison Co 84/07/25 9pp 25925 289 24X
Fiche 50-373, 84/07/25, 8408060145

8408300508 Forwards radioactive effluent monitoring rept for Jan-June 1984 & revised process control procedure
DIEDERICH, G J Commonwealth Edison Co 84/07/25 KEPPLER, J G
Region 3, Office of Director 1p 26313 311 24X
Fiche 50-373, 84/07/25, 8408300508

--8408300516 Rev 2 to LAP-200-6, "LaSalle County Station Process Control Program "
* Commonwealth Edison Co 83/12/29 15pp 26313 329 24X
Fiche 50-373, 84/07/25, 8408300508

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY, P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN, G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000, 84/08/06, 8408090317

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X
Fiche 50-000, 84/08/06, 8408160345

8408160364 Requests authorization to use ASME Code Case N-389 Licensee will use ASME Code 1980 edition, Winter 1980 &/or Winter 1981 addenda for work during upcoming outage
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26091 236 24X
Fiche 50-373, 84/08/07, 8408160364

8408160387 Forwards revised pump & valve inservice testing plans, reflecting Relief Requests RI-19 & RV-38 from certain ASME Section XI Code requirements for containment isolation & RCIC injection outboard valves
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 26085 350
24X Fiche 50-373, 84/08/07, 8408160387

8408170227 Forwards Amend 18 to License NPF-11 & safety evaluation Amend changes Tech Specs, in response to util 840113, 0322 & 0405 ltrs, to reflect changes incorporated into Unit 2 Tech Specs
SCHWENCER, A Licensing Branch 2 84/08/08 FARRAR, D L
Commonwealth Edison Co 3pp 26135 001 24X Fiche 50-373, 84/08/08, 8408170227

--8408170243 Amend 18 to License NPF-11, reflecting changes incorporated into Unit 2 Tech Specs
SCHWENCER, A Licensing Branch 2 84/07/27 172pp 26135.004
24X Fiche 50-373, 84/08/08, 8408170227

--8408170247 Safety evaluation supporting Amend 18 to License NPF-11
* Office of Nuclear Reactor Regulation, Director 84/08/08
10pp 26135 176 24X Fiche 50-373, 84/08/08, 8408170227

8408140323 Informs that util no longer participating in instrument setpoint methodology program conducted by BWR Licensing Review Group
MARSHALL, J G Commonwealth Edison Co 84/08/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26042 350 24X
Fiche 50-373, 84/08/09, 8408140323

8408270479 Forwards request for addl info re safety relief valve (SRV) blowdown test Util rept re SRV test & evaluation of suppression pool temp measurements fails to satisfy NUREG-0487 & NUREG-0783 criteria
SCHWENCER, A Licensing Branch 2 84/08/17 FARRAR, D L
Commonwealth Edison Co 4pp 26277 194 24X Fiche 50-373, 84/08/17, 8408270479

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310439 Forwards errata to Amend 18 to License NPF-11, consisting of corrected Tech Specs
SCHWENCER, A Licensing Branch 2 84/08/27 FARRAR, D L
Commonwealth Edison Co 2pp 26350 135 24X Fiche 50-373, 84/08/27, 8408310439

--8408310442 Errata to Amend 18 to License NPF-11, consisting of corrected Tech Specs
* NRC - No Detailed Affiliation Given 84/08/21 3pp
26350 137 24X Fiche 50-373, 84/08/27, 8408310439

8408310450 Responds to 840807 request for authorization to use ASME Code Case N-389, "Alternate Rules for Repairs, Replacements or Mods, Section XI, Div 1 " Use of Code Case N-389 acceptable Next update to FSAR should document usage
SCHWENCER, A Licensing Branch 2 84/08/28 FARRAR, D L
Commonwealth Edison Co 2pp 26350 127 24X Fiche 50-373, 84/08/28, 8408310450

O Inspection reports, IE Bulletins & correspondence

8408010289 Forwards IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 & notice of violation
SHAFER, W D Region 3, Office of Director 84/07/10 REED, C
Commonwealth Edison Co 2pp 25866 103 24X Fiche 50-373, 84/07/10, 8408010289

--8408010291 Notice of violation from insp on 840512-0618
SHAFER, W D Region 3, Office of Director 84/07/05 2pp
25866 105 24X Fiche 50-373, 84/07/10, 8408010289

--8408010294 IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 Noncompliance noted failure to control access to high radiation area & failure to follow reactor vessel lo-lo water level recirculation pump trip calibr test procedure
CHRISSOTIMOS, N Region 3, Office of Director 84/07/02 10pp
25866 107 24X Fiche 50-373, 84/07/10, 8408010289

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408060085 Forwards revs to baseline insp rept (ASME Section XI) Deficiencies noted during util audit corrected W/o encl
MARSHALL, J G Commonwealth Edison Co 84/07/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25922 011 24X
Fiche 50-373, 84/07/30, 8408060085

8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC
NORELIUS, C E Region 3, Office of Director 84/08/03 REED, C
Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000, 84/08/03, 8408070066

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement ' Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408230293 Forwards IE Insp Repts 50-373/84-19 & 50-374/84-25 on 840724-26 No noncompliance noted
WALKER, R D Region 3, Office of Director 84/08/06 REED, C
Commonwealth Edison Co 2pp 26213 251 24X Fiche 50-373, 84/08/06, 8408230293

--8408230298 IE Insp Repts 50-373/84-19 & 50-374/84-25 on 840724-26 No noncompliance or deviations noted Major areas inspected previous insp findings & startup testing audit program
CHOULES, N C , HAWKINS, F C Region 3, Office of Director
84/08/06 4pp 26213 253 24X Fiche 50-373, 84/08/06, 8408230293

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, 84/08/08, 8408140344

8408150098 SupplS 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26067 053 24X
Fiche 50-000, 84/08/08, 8408150098

8408200331 SupplS response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26132 318 24X
Fiche 50-000, 84/08/08, 8408200331

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408160198 Discusses IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 & forwards corrected notice of violation Response within 30 days requested
SHAFER, W D Region 3, Office of Director 84/08/10 REED, C
Commonwealth Edison Co 1p 26092 133 24X Fiche 50-373, 84/08/10, 8408160198

--8408160206 Corrected notice of violation from insp on 840512-0618 Violations identified surveillance of unlocked high radiation area inattentive & failure to adhere to instrument surveillance procedures
SHAFER, W D Region 3, Office of Director 84/08/10 2pp
26092 134 24X Fiche 50-373, 84/08/10, 8408160198

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12Opp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates ' Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves ' Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408300388 Forwards errata to "Rept of Radioactive Effluents," Jul-Dec 1983 Part 1 of 1984 operating rept for Jan-June 1984 will be submitted in Aug 1984
DIEDERICH, G J Commonwealth Edison Co 84/07/23 KEPPLER, J G Region 3, Office of Director 1p 26308 151 24X Fiche 50-373, 84/07/23, 8408300388

--8408300393 Errata to "Rept of Radioactive Effluents," Jul-Dec 1983
* Commonwealth Edison Co 83/12/31 8pp 26308 152 24X Fiche 50-373, 84/07/23, 8408300388

8408300508 Forwards radioactive effluent monitoring rept for Jan-June 1984 & revised process control procedure
DIEDERICH, G J Commonwealth Edison Co 84/07/25 KEPPLER, J G Region 3, Office of Director 1p 26313 311 24X Fiche 50-373, 84/07/25, 8408300508

--8408300513 "Rept of Radioactive Effluents," Jan-June 1984
* Commonwealth Edison Co 84/06/30 13pp 26313 312 24X Fiche 50-373, 84/07/25, 8408300508

--8408300516 Rev 2 to LAP-200-6, "LaSalle County Station Process Control Program "
* Commonwealth Edison Co 83/12/29 15pp 26313 325 24X Fiche 50-373, 84/07/25, 8408300508

8408160140 Monthly operating repts for Jul 1984 W/840806 ltr
DUS, R S , DIEDERICH, G J Commonwealth Edison Co 84/07/31 27pp 26108 081 24X Fiche 50-373, 84/07/31, 8408160140

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408060063 LER 84-040-00 on 840625, in startup mode, reactor water cleanup sys isolated on high differential flow Caused by temp & pressure differences between startup operations & instrument calibr Procedure revised W/840719 ltr
SHIELDS, J M , DIEDERICH, G J Commonwealth Edison Co 84/07/19 3pp 25935 283 24X Fiche 50-373, 84/07/19, 8408060063

8408060055 LER 84-041-00 on 840628, three mechanical penetrations on fire-rated walls/floors not sealed properly Caused by personnel not identifying on sleeve schedule Fire watch established Penetration sealed W/840723 ltr
MCVEY, E A , DIEDERICH, G J Commonwealth Edison Co 84/07/23 3pp 25935 263 24X Fiche 50-373, 84/07/23, 8408060055

8408060255 LER 84-043-00 on 840627, during reactor water cleanup filter deisolation, reactor water cleanup sys isolated on high differential flow Possibly caused by draining of demineralizer Investigation underway W/840725 ltr
ARAND, J , DIEDERICH, G J Commonwealth Edison Co 84/07/25 3pp 25935 150 24X Fiche 50-373, 84/07/25, 8408060255

8408060207 LER 84-044-00 on 840702, HPCS quarterly inservice test check valve 1E22-F006 & stop check valve 1E22-F007 failed to prevent reverse flow Caused by scoring of disc seats Valves repaired W/840727 ltr
MASTERSON, V , DIEDERICH, G J Commonwealth Edison Co 84/07/27 4pp 25923 358 24X Fiche 50-373, 84/07/27, 8408060207

8408090324 LER 84-042-00 on 840703, reactor water cleanup outboard isolation valve room area overlooked in routine surveys up to 840703 Posting on entrance door 463 upgraded to "Danger High Radiation Area" & security level upgraded W/840730 ltr
ALDRICH, L R , DIEDERICH, G J Commonwealth Edison Co 84/07/30 3pp 25994 069 24X Fiche 50-373, 84/07/30, 8408090324

8408310361 Forwards "Excessive Cooldown Rate Event at La Salle Unit 1," technical review rept No further evaluation of problem considered necessary
SALAH, S Reactor Operations Analysis Branch 84/08/02
SEYFRIT, K V Reactor Operations Analysis Branch 1p 26350 265
24X Fiche 50-373, 84/08/02, 8408310361

--8408310362 "Excessive Cooldown Rate Event at La Salle Unit 1," technical review rept
SALAH, S Reactor Operations Analysis Branch 84/08/02 5pp 26350 266 24X Fiche 50-373, 84/08/02, 8408310361

8408200526 LER 84-023-01 on 840415, reactor water cleanup sys isolated due to high differential flow Caused by losses through open relief valve on shell side of regenerative HX HX A string isolated W/840803 ltr
SHIELDS, J M , DIEDERICH, G J Commonwealth Edison Co 84/08/03 4pp 26138 321 24X Fiche 50-373, 84/08/03, 8408200526

8408200323 LER 84-045-00 on 840715, while deisolating reactor water cleanup filter/demineralizer during precoat cycle, reactor water cleanup sys isolated Action Item Record 1-84-67113 issued for further investigation W/840809 ltr
SMYTHE, D R , DIEDERICH, G J Commonwealth Edison Co 84/08/09 3pp 26140 082 24X Fiche 50-373, 84/08/09, 8408200323

8408310160 Part 21 rept re ground fault failures of actuation solenoids for Crosby safety relief valves PRC 84-24 Problem still considered germane condition Memo of 840808 telcon updating 840615 interim rept encl
GIAMBALVO, E W General Electric Co 84/08/21 ROSSI, C E Director's Office, Office of Inspection and Enforcement 4pp 26322 230 24X Fiche 50-373, 84/08/21, 8408310160

8408310047 LER 84-046-00 on 840727 & 28, reactor water cleanup sys isolated on high differential flow while deisolating filter demineralizer C Caused by partial loss of sys flow through open filter drain valves Valves closed W/840823 ltr
SMYTHE, D R , DIEDERICH, G J Commonwealth Edison Co 84/08/23 4pp 26334 360 24X Fiche 50-373, 84/08/23, 8408310047

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240
24X Fiche 50-000, 84/08/07, 8408140372

--8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X Fiche 50-000, 84/08/07, 8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8404040169 Forwards exercise repts for LaSalle & Dresden offsite radiological emergency preparedness exercises conducted 820414-15 & 0629-30, respectively
KRIMM, R W Federal Emergency Management Agency 84/03/26
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22883 122 24X Fiche 50-000, 84/03/26, 8404040169

--8404040172 Evaluation of State of IL full-scale emergency preparedness exercise plan, final rept
* Federal Emergency Management Agency 82/05/31 68pp 22883 124 24X Fiche 50-000, 84/03/26, 8404040169

8408010289 Forwards IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 & notice of violation
SHAFER, W D Region 3, Office of Director 84/07/10 REED, C Commonwealth Edison Co 2pp 25866 103 24X Fiche 50-373, 84/07/10, 8408010289

DOCKETED ITEMS

0294 IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618
ompliance noted failure to control access to high
ation area & failure to follow reactor vessel lo-lo
r level recirculation pump trip calibr test procedure
SSOTIMOS,N Region 3, Office of Director 84/07/02 10pp
6 107 24X Fiche 50-373,84/07/10,8408010289

79 Rev 4 to Offsite Emergency Procedure LZP-1550-2, "Environs
ng Supplies Inventory " Revised index & 840808
ittal form encl
mmonwealth Edison Co 84/07/25 16pp 26044 332 24X
50-373,84/07/25,8408140179

)95 Ack receipt of scope & objectives for 841010 emergency
edness exercise Objectives acceptable & unchanged from
scenario development meeting
IELLO,C J Region 3, Office of Director 84/08/01 REED,C
nwealth Edison Co 1p 25922 001 24X Fiche 50-373,84/08/01,
50095

0101 Forwards scope & objectives for 841010 emergency
aredness exercise,per NRC/FEMA requirements
INE,T R Commonwealth Edison Co 84/07/25 HIND,J Division
Emergency Preparedness & Operational Support 5pp 25922 002
Fiche 50-373,84/08/01,8408060095

139 Forwards listed revs to security plans Revs address fence
s requirements Revs withheld (ref 10CFR73 21)
t,D L Commonwealth Edison Co 84/08/03 Region 3, Office
rector 1p 26044 252 24X Fiche 50-000,84/08/03,8408140139

101 Responds to 840705 clarification of info re util means of
fying annual regulatory requirement to review emergency
levels w/offsite emergency support organizations Info
table
IELLO,C J Region 3, Office of Director 84/08/07 REED,C
nwealth Edison Co 1p 26010 130 24X Fiche 50-000,84/08/07,
30401

30413 Responds to 840604 ltr re means for satisfying requirements
10CFR50,App E,Paragraph IV B Proposal for satisfying
uirements to review emergency action levels by offsite
ncies clarified
RAR,D L Commonwealth Edison Co 84/07/05 PAPERIELLO,C J
ion 3, Office of Director 8pp 26010 131 24X
he 50-000,84/08/07,8408130401

230 Advises that 840803 Rev 19 to physical security plan
stent w/provisions of 10CFR50 54(p) & acceptable
ON,W L Region 3, Office of Director 84/08/14 FARRAR,D L
nwealth Edison Co 2pp 26133 188 24X Fiche 50-373,84/08/14,
00230

233 Rev 1 to Emergency Plan Implementing Procedure LZP-1510-1,
rating Station Emergency Procedure Operational
ness " W/840824 transmittal memo
mmonwealth Edison Co 84/08/17 10pp 26322 269 24X
50-373,84/08/17,8408310233

358 Forwards "Technical Basis of LaSalle County Station Fire
r Surveillance Program," per 840328 agreement
,B Commonwealth Edison Co 84/08/21 DENTON,H R Office of
ar Reactor Regulation, Director 1p 26239 228 24X
50-373,84/08/21,8408270358

70362 "Technical Basis of LaSalle County Station Fire Damper
veillance Program "
Commonwealth Edison Co 84/08/31 326pp 26239 229 24X
he 50-373,84/08/21,8408270358

ating license stage documents & correspondence
---

148 Forwards Amends 17 & 2 to Licenses NPF-11 & NPF-18,
ctively & safety evaluation Amends change Tech Specs
in line temp difference trip setpoints & allowable
s
NCER,A Licensing Branch 2 84/07/03 FARRAR,D Commonwealth
n Co 2pp 25979 043 24X Fiche 50-373,84/07/03,8408080148

80155 Amends 17 & 2 to Licenses NPF-11 & NPF-18,respectively,
nging Tech Specs re main steamline temp difference trip
points & allowable values
WENCER,A Licensing Branch 2 84/07/03 8pp 25979 045 24X
he 50-373,84/07/03,8408080148

80159 Safety evaluation supporting Amends 17 & 2 to Licenses
-11 & NPF-18,respectively
Office of Nuclear Reactor Regulation, Director 84/07/03 2pp
979 053 24X Fiche 50-373,84/07/03,8408080148

8408280360 Ack receipt of 840710 ltr re author criticism of NRC
present rules & practices Reponse to NRC seven stages of
discussion listed Past tests should be reviewed & leak rate
be retested Related info encl
REYTBLATT J V Warren Wilson College, Swannanoa NC 84/07/22
ROSS,D F Office of Nuclear Regulatory Research, Director 8pp
26293 001 24X Fiche 50-000 84/07/22,8408280360

8408010107 Forwards request for addl info re NUREG-0737, Item II D 1,
including basis for application or findings of NEDE-24988-P,
"Analysis of Generic BWR Safety & Relief Valve Operability
Test Results," submitted by BWR Owners Group
SCHWENCER,A Licensing Branch 2 84/07/24 FARRAR,D L
Commonwealth Edison Co 4pp 25873 355 24X Fiche 50-373,84/07/24,
8408010107

8408080314 Forwards Amend 3 to License NPF-18 & safety evaluation Amend
deletes License Condition 2 c (7) & changes Tech Specs to
incorporate reactor scram on low CRD pump discharge pressure
mod
SCHWENCER,A Licensing Branch 2 84/07/24 FARRAR,D Commonwealth
Edison Co 5pp 25978 208 24X Fiche 50-374,84/07/24,8408080314

--8408080319 Amend 3 to License NPF-18,deleting License Condition 2 c (7)
& changing Tech Specs to incorporate reactor scram on low
CRD pump discharge pressure mod
SCHWENCER,A Licensing Branch 2 84/07/24 11pp 25978 213
24X Fiche 50-374,84/07/24,8408080314

--8408080322 Safety evaluation supporting Amend 3 to License NPF-18
* Office of Nuclear Reactor Regulation, Director 84/07/24 2pp
25978 224 24X Fiche 50-374,84/07/24,8408080314

8408060145 Application for amend to Licenses NPF-11 & NPF-18,changing
Tech Specs re accident monitoring instrumentation
(NUREG-0737,Items II F 1 1,II F 1 3 & II F 1 6) Fee encl
MARSHALL,J G Commonwealth Edison Co 84/07/25 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25925 285
24X Fiche 50-373,84/07/25,8408060145

--8408060153 Proposed Tech Spec changes re accident monitoring
instrumentation limiting conditions for operation for noble
gas effluent monitors,containment high radiation monitors
& containment hydrogen monitor
* Commonwealth Edison Co 84/07/25 9pp 25925 289 24X
Fiche 50-373,84/07/25,8408060145

8408300508 Forwards radioactive effluent monitoring rept for Jan-June
1984 & revised process control procedure
DIEDERICH,G J Commonwealth Edison Co 84/07/25 KEPPLER,J G
Region 3, Office of Director 1p 26313 311 24X
Fiche 50-373,84/07/25,8408300508

--8408300516 Rev 2 to LAP-200-6, "LaSalle County Station Process Control
Program "
* Commonwealth Edison Co 83/12/29 15pp 26313 325 24X
Fiche 50-373,84/07/25,8408300508

8408060144 Application for amend relaxing requirements of Amend 3 to
License NPF-18,to meet requirements of License Condition
2 C (7) re effective amend date before completion of startup
test program For CRD discharge pressure mod Fee encl
RYBAK,B Commonwealth Edison Co 84/07/31 DENTON,H R Office of
Nuclear Reactor Regulation, Director 2pp 25923 302 24X
Fiche 50-374,84/07/31,8408060144

8408060168 Requests NRC vacate Amend 3 to License NPF-18 to allow
licensee time to determine proper low discharge setpoint on
low CRD pump Setpoint setting mandated by Amend 3 may be too
conservative
RYBAK,B Commonwealth Edison Co 84/08/01 DENTON,H R Office of
Nuclear Reactor Regulation, Director 2pp 25932 192 24X
Fiche 50-374,84/08/01,8408060168

8408140405 Application to amend License NPF-18,changing Tech Specs re
reactor scram on low CRD pump discharge pressure mod
Requests for emergency amend,dtd 840731 & 0801,unwarranted
in that derating or shutdown not imminent
RYBAK,B Commonwealth Edison Co 84/08/02 DENTON,H R Office of
Nuclear Reactor Regulation, Director 3pp 26050 356 24X
Fiche 50-374,84/08/02,8408140405

8408070110 Generic Ltr 84-19 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
Suppl 1 to NUREG-0933, "Prioritization of Generic Safety
Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY, P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN, G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000, 84/08/06, 8408090317

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X
Fiche 50-000, 84/08/06, 8408160345

8408160364 Requests authorization to use ASME Code Case N-389 Licensee will use ASME Code 1980 edition, Winter 1980 &/or Winter 1981 addenda for work during uptoming outage
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26091 236 24X
Fiche 50-373, 84/08/07, 8408160364

8408160387 Forwards revised pump & valve inservice testing plans, reflecting Relief Requests RI-19 & RV-38 from certain ASME Section XI Code requirements for containment isolation & RCIC injection outboard valves
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 26085 350
24X Fiche 50-373, 84/08/07, 8408160387

8408140323 Informs that util no longer participating in instrument setpoint methodology program conducted by BWR Licensing Review Group
MARSHALL, J G Commonwealth Edison Co 84/08/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26042 350 24X
Fiche 50-373, 84/08/09, 8408140323

8408220435 Forwards paid public notice re licensee 840802 application to amend OL Time constraints preclude FR publication Comment period expires 840827
SCHWENCER, A Licensing Branch 2 84/08/13 FARRAR, D L
Commonwealth Edison Co 5pp 26201 357 24X Fiche 50-374, 84/08/13, 8408220435

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310450 Responds to 840807 request for authorization to use ASME Code Case N-389, "Alternate Rules for Repairs, Replacements or Mods, Section XI, Div 1 " Use of Code Case N-389 acceptable Next update to FSAR should document usage
SCHWENCER, A Licensing Branch 2 84/08/28 FARRAR, D L
Commonwealth Edison Co 2pp 26350 127 24X Fiche 50-373, 84/08/28, 8408310450

G Inspection reports, IE Bulletins & correspondence

8408010289 Forwards IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 & notice of violation
SHAFER, W D Region 3, Office of Director 84/07/10 REED, C
Commonwealth Edison Co 2pp 25866 103 24X Fiche 50-373, 84/07/10, 8408010289

--8408010291 Notice of violation from insp on 840512-0618
SHAFER, W D Region 3, Office of Director 84/07/05 2pp
25866 105 24X Fiche 50-373, 84/07/10, 8408010289

--8408010294 IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 Noncompliance noted failure to control access to high radiation area & failure to follow reactor vessel lo-lo water level recirculation pump trip calibr test procedure
CHRISSOTIMOS, N Region 3, Office of Director 84/07/02 10pp
25866 107 24X Fiche 50-373, 84/07/10, 8408010289

8408010312 Forwards IE Insp Rept 50-374/84-23 on 840606-22 & notice of violation
NORELIUS, C E Region 3, Office of Director 84/07/13 REED, C
Commonwealth Edison Co 2pp 25866 151 24X Fiche 50-374, 84/07/13, 8408010312

--8408010314 Notice of violation from insp on 840606-22
NORELIUS, C E Region 3, Office of Director 84/07/13 1p
25866 153 24X Fiche 50-374, 84/07/13, 8408010312

8408010316 IE Insp Rept 50-374/84-23 on 840606-22 Noncompliance noted reactor water cleanup isolation functions for temp, differential temp or differential flow inoperable & sys not isolated for approx 7 5 h
CHRISSOTIMOS, N Region 3, Office of Director 84/07/10 5pp
25866 154 24X Fiche 50-374, 84/07/13, 8408010312

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25885 047 24X Fiche 50-000, 84/07/27, 8407250229

8408060085 Forwards revs to baseline insp rept (ASME Section XI) Deficiencies noted during util audit corrected W/o encl
MARSHALL, J G Commonwealth Edison Co 84/07/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25922 011 24X
Fiche 50-373, 84/07/30, 8408060085

8408070066 Notifies of 840823 meeting w/util at Region III ofc to review findings of SALP assessment re util performance Encourages mgt representation to ensure mutual understanding of issues & findings presented by NRC
NORELIUS, C E Region 3, Office of Director 84/08/03 REED, C
Commonwealth Edison Co 2pp 25949 337 24X Fiche 50-000, 84/08/03, 8408070066

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408230293 Forwards IE Insp Repts 50-373/84-19 & 50-374/84-25 on 840724-26 No noncompliance noted
WALKER, R D Region 3, Office of Director 84/08/06 REED, C
Commonwealth Edison Co 2pp 26213 251 24X Fiche 50-373, 84/08/06, 8408230293

-8408230298 IE Insp Repts 50-373/84-19 & 50-374/84-25 on 840724-26 No noncompliance or deviations noted Major areas inspected previous insp findings & startup testing audit program
CHOULES, N C , HAWKINS, F C Region 3, Office of Director
84/08/06 4pp 26213 253 24X Fiche 50-373, 84/08/06, 8408230293

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director, 84/08/08 REED, C
Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, 84/08/08, 8408140344

8408150098 Suppls 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26067 053 24X
Fiche 50-000, 84/08/08, 8408150098

8408200331 Suppls response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26132 318 24X
Fiche 50-000, 84/08/08, 8408200331

8408140156 Ack receipt of 840803 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-374/84-04
LITTLE, W S Region 3, Office of Director 84/08/09 REED, C
Commonwealth Edison Co 1p 26048 322 24X Fiche 50-374, 84/08/09
8408140156

--8408140169 Documents commitment made during meeting re Item 2 C of 840424 ltr on colors of control indicating lights (IE Insp Rept 50-374/84-04) Procedure & training program revs will be completed by 841001
FARRAR, D L Commonwealth Edison Co 84/08/03 KEPPLER, J G
Region 3, Office of Director 4pp 26048 323 24X
Fiche 50-374, 84/08/09, 8408140156

--8408140180 Supplis 840522 response to violations noted in IE Insp Rept 50-374/84-04 Corrective actions Aperture Card M-5444 corrected & station Procedure LAP-810-5 revised
FARRAR, D L Commonwealth Edison Co 84/06/14 KEPPLER, J G
Region 3, Office of Director 4pp 26048 327 24X
Fiche 50-374, 84/08/09, 8408140156

--8408140190 Responds to NRC 840424 ltr re violations noted in IE Insp Rept 50-374/84-04 Corrective actions jumper added to drawing, relay cleaned & labeled & wiring of indicating control lights verified
FARRAR, D L Comnonwealth Edison Co 84/08/03 KEPPLER, J G
Region 3, Office of Director 3pp 26048 331 24X
Fiche 50-374, 84/08/09, 8408140156

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408160198 Discusses IE Insp Repts 50-373/84-14 & 50-374/84-18 on 840512-0618 & forwards corrected notice of violation Response within 30 days requested
SHAFER, W D Region 3, Office of Director 84/08/10 REED, C
Commonwealth Edison Co 1p 26092 133 24X Fiche 50-373, 84/08/10, 8408160198

--8408160206 Corrected notice of violation from insp on 840512-0618 Violations identified surveillance of unlocked high radiation area inattentive & failure to adhere to instrument surveillance procedures
SHAFER, W D Region 3, Office of Director 84/08/10 2pp
26092 134 24X Fiche 50-373, 84/08/10, 8408160198

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408210193 Ack receipt of 840731 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-374/84-23 Corrective actions will be examined during subsequent insp
NORELIUS, C E Region 3, Office of Director 84/08/14 REED, C
Commonwealth Edison Co 1p 26181 316 24X Fiche 50-374, 84/08/14, 8408210193

-8408210203 Responds to NRC 840713 ltr re violations noted in IE Insp Rept 50-374/84-23 Corrective actions personnel counseled, reactor water cleanup sys revised & efficient Tech Spec timeclock tracking method researched
FARRAR, D L Commonwealth Edison Co 84/07/31 KEPPLER, J G
Region 3, Office of Director 3pp 26181 317 24X
Fiche 50-374, 84/08/14, 8408210193

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408300388 Forwards errata to "Rept of Radioactive Effluents," Jul-Dec 1983 Part 1 of 1984 operating rept for Jan-June 1984 will be submitted in Aug 1984
DIEDERICH, G J Commonwealth Edison Co 84/07/23 KEPPLER, J G
Region 3, Office of Director 1p 26308 151 24X
Fiche 50-373, 84/07/23, 8408300388

--8408300393 Errata to "Rept of Radioactive Effluents," Jul-Dec 1983
* Commonwealth Edison Co 83/12/31 8pp 26308 152 24X
Fiche 50-373, 84/07/23, 8408300388

8408300508 Forwards radioactive effluent monitoring rept for Jan-June 1984 & revised process control procedure
DIEDERICH, G J Commonwealth Edison Co 84/07/25 KEPPLER, J G
Region 3, Office of Director 1p 26313 311 24X
Fiche 50-373, 84/07/25, 8408300508

--8408300513 "Rept of Radioactive Effluents," Jan-June 1984
* Commonwealth Edison Co 84/06/30 13pp 26313 312 24X
Fiche 50-373, 84/07/25, 8408300508

8408160140 Monthly operating repts for Jul 1984 W/840806 ltr
DUS, R S , DIEDERICH, G J Commonwealth Edison Co 84/07/31 27pp
26108 081 24X Fiche 50-373, 84/07/31, 8408160140

S Reportable occurrences, LERs & related correspondence

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408060283 LER 84-032-00 on 840626, reactor water cleanup sys isolated on spurious high differential temp Div 1 leak detection (JM) trip Caused apparently by induced signal while performing RCIC functional test Isolation reset W/840719 ltr
WITTENBURG, K C , DIEDERICH, G J Commonwealth Edison Co 84/07/19
4pp 25936 092 24X Fiche 50-374, 84/07/19, 8408060283

8408060042 LER 84-033-00 on 840608, during Startup Test 2-31, containment isolation valve did not close upon receipt of containment isolation signal Caused by solenoid valve improperly positioned Solenoid valve repositioned W/840723 ltr
BRUCIAK, J D , DIEDERICH, G J Commonwealth Edison Co 84/07/23
4pp 25935 266 24X Fiche 50-374, 84/07/23, 8408060042

8408060107 LER 84-035-00 on 840709, while troubleshooting problem w/ electrohydraulic sys signal, technician probe slipped, causing momentary loss of 30-volt power supply to sys High pressure scram occurred Trouble shooting stopped W/840724 ltr
HAMMERICH, T , DIEDERICH, G J Commonwealth Edison Co 84/07/24
4pp 25935 204 24X Fiche 50-374, 84/07/24, 8408060107

8408060227 LER 84-034-00 on 840703, survey of offgas carbon bed vault identified high radiation area Warning signs posted on Door 565 & security status level upgraded to high radiation status W/840724 ltr
ALDRICH, L R , DIEDERICH, G J Commonwealth Edison Co 84/07/24
4pp 25935 137 24X Fiche 50-374, 84/07/24, 8408060227

8408070391 LER 84-036-00 on 840706, alarm received when reactor water cleanup sys isolated on high differential flow Caused by leakage past valve seat Valve 2033-2001-378 closed W/840730 ltr
SPRUNGER, C K , DIEDERICH, G J Commonwealth Edison Co 84/07/30
4pp 25945 248 24X Fiche 50-374, 84/07/30, 8408070391

8408070490 LER 84-037-00 on 840718, reactor water cleanup sys isolated on high differential flow Caused by damaged sys boundary valve operator & improper fill & vent of vessel Valve operator will be repaired W/840731 ltr
SHIELDS, J , DIEDERICH, G J Commonwealth Edison Co 84/07/31 4pp
25940 343 24X Fiche 50-374, 84/07/31, 8408070490

8408230524 LER 84-038-00 on 840717, Door 430 to reactor water cleanup HX B room left open Security alerted but checked wrong door Door immediately secured on 840718 Engineering controls investigated W/840810 ltr
EISELE, W F , DIEDERICH, G J Commonwealth Edison Co 84/08/10 4pp
26212 334 24X Fiche 50-374, 84/08/10, 8408230524

8408230533 LER 84-039-00 on 840719, at 80% power, pressure switches 2E31-N022A, B, C & D found out-of-tolerance in nonconservative direction Cause not determined Switches recalibr & will be replaced during environ qualification W/840813 ltr
BRUCIAK, J D , DIEDERICH, G J Commonwealth Edison Co 84/08/13 4pp 26212 344 24X Fiche 50-374, 84/08/13, 8408230533

8408240044 LER 84-040-00 on 840725, during review of procedures, discovered drywell crane circuits not included in Tech Specs Specs Caused by circuits not being included in Tech Specs & erroneous investigation Procedure revised W/840814 ltr
KLIKA, J C , DIEDERICH, G J Commonwealth Edison Co 84/08/14 4pp 26236 354 24X Fiche 50-374, 84/08/14, 8408240044

8408310053 LER 84-042-00 on 840728, rod sequence control sys declared inoperable & reactor manually scrammed Primary containment isolation sys Group 1 isolation also occurred Caused by failure of pressure transmitter & vacuum W/840815 ltr
KALMON, K J , DIEDERICH, G J Commonwealth Edison Co 84/08/15 4pp 26335 004 24X Fiche 50-374, 84/08/15, 8408310053

8408240179 LER 84-043-00 on 840812, primary containment vent & purge exceeded allowable time by 1 5 h Unit in hot shutdown at 300 F throughout purge Caused by personnel error Purge secured when violation observed W/840816 ltr
SNIHART, G L , DIEDERICH, G J Commonwealth Edison Co 84/08/16 4pp 26248 222 24X Fiche 50-374, 84/08/16, 8408240179

8408240114 PND-III-84-066 on 840816, RHR B loop full flow test valve failed to completely close manually, rendering low pressure injection, shutdown cooling & suppression pool cooling inoperable Unit in cold shutdown pending repairs & maint
CHRISSOTIMOS, N , SHAFER, W Region 3, Office of Director 84/08/20 1p 26228 216 24X Fiche 50-374, 84/08/20, 8408240114

U Congressional/Executive Correspondence

8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far
ASSELSTINE, J K Commissioners 84/08/10 MARKEY, E J House of Rep , Interior & Insular Affairs 4pp 26141 244 24X
Fiche 50-000, 84/08/10, 8408200225

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000, 84/08/07, 8408140372

--8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X
Fiche 50-000, 84/08/07, 8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

8408020033 Forwards revised program for resolution of 23 issues described in NRC 840613 ltr Plan examines cause, generic implications & significance of issues & programmatic & mgt changes designed to preclude recurrence
CAIN, J M Louisiana Power & Light Co 84/07/27 EISENHUT, D G Division of Licensing 2pp 25883 232 24X Fiche 50-382, 84/07/27, 8408020033

--8408020035 Revised program plan & schedule for resolution of 23 issues described in NRC 840613 ltr
* Louisiana Power & Light Co 84/07/23 28pp 25883 234 24X
Fiche 50-382, 84/07/27, 8408020033

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140401 Forwards resumes for NUS personnel involved w/preliminary issues task force support group Inspector & auditor certificates also encl
JUDD, P V NUS Corp 84/08/09 CRUTCHFIELD, D NRC - No Detailed Affiliation Given 128pp 26050 034 24X Fiche 50-382, 84/08/09, 8408140401

8408230179 Forwards update re toxic chemical survey of industries surrounding plant Protective features will provide adequate protection for control room operators Probability of immediately dangerous levels being reached unlikely
COOK, K W Louisiana Power & Light Co 84/08/09 KNIGHTON, G W Licensing Branch 3 11pp 26209 302 24X Fiche 50-382, 84/08/09, 8408230179

8408140284 Forwards response to NRC 840613 ltr re missing NI instrument line documentation, instrumentation expansion loop separation, visual exam of shop welds during hydrostatic testing & surveys & exit interviews of QA personnel
CAIN, J M Louisiana Power & Light Co 84/08/10 EISENHUT, D G Division of Licensing 73pp 26055 001 24X Fiche 50-382, 84/08/10, 8408140284

8408230334 Notification of 840817 meeting w/util in Bethesda, MD to discuss status & schedule of program plan for resolving 23 areas of concern identified in NRC 840613 ltr re prelicensing issues
WILSON, J Licensing Branch 3 84/08/10 KNIGHTON, G W Licensing Branch 3 3pp 26230 359 24X Fiche 50-382, 84/08/10, 8408230334

8408210378 Application to amend CPPR-103, extending completion date to 841231
LEDDICK, R S Louisiana Power & Light Co 84/08/15 EISENHUT, D G Division of Licensing 3pp 26180 245 24X Fiche 50-382, 84/08/15, 8408210378

8408210403 Forwards "NUS Project Plan for Prelicensing Issues Task Force Support Group "
JUDD, P V NUS Corp 84/08/15 CRUTCHFIELD, D NRC - No Detailed Affiliation Given 2pp 26180 308 24X Fiche 50-382, 84/08/15, 8408210403

--8408210409 "NUS Project Plan for Prelicensing Issues Task Force Support Group "
* NUS Corp 84/08/14 7pp 26180 310 24X
Fiche 50-382, 84/08/15, 8408210403

8408230374 Ack receipt of 840725 comments re 840628 proposed program plan Comments will be considered during evaluation of util responses to 23 areas of concern
EISENHUT, D G Division of Licensing 84/08/15 BERNABEI, L Government Accountability Project 2pp 26230 342 24X
Fiche 50-382, 84/08/15, 8408230374

8408210305 Submits addl info re radwaste solidification process control programs NUS Process Svcs Corp will perform initial solidification Expeditious review requested to facilitate interim approval to process wet radwastes
COOK, K W Louisiana Power & Light Co 84/08/16 KNIGHTON, G W Licensing Branch 3 5pp 26181 018 24X Fiche 50-382, 84/08/16, 8408210305

---8408210361 Rev 1 to Surveillance Procedure RW-2-210, "Radwaste Solidification "
ALLEN, J A , BARKHURST, R P Louisiana Power & Light Co 84/05/19 20pp 26181.023 24X Fiche 50-382, 84/08/16, 8408210305

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408270303 Forwards revised program plan for resolution of prelicensing issues, formalizing changes discussed during 840817 meeting
LEDDICK, R S Louisiana Power & Light Co 84/08/20 EISENHUT, D G Division of Licensing 27pp 26239 127 24X Fiche 50-382, 84/08/20, 8408270303

8408310236 Responds to request for addl info re shutdown cooling sys relief valve operability Valves will operate correctly, providing required pressure relief capacity & reclosing under actual svc conditions
COOK, K W Louisiana Power & Light Co 84/08/27 KNIGHTON, G W Licensing Branch 3 4pp 26320 330 24X Fiche 50-382, 84/08/27, 8408310236

Security, medical, emergency & fire protection plans

8408030266 Forwards IE Insp Rept 50-382/84-19 on 840430-0504 No violations or deviations noted
GAGLIARDO,J E Region 4, Office of Director 84/05/31
LEDDICH,R S Louisiana Power & Light Co 2pp 25917 251 24X
Fiche 50-382,84/05/31,8408030266

-8408030275 IE Insp Rept 50-382/84-19 on 840430-0504 No violations or deviations noted Major areas inspected security plan & implementing procedures,records & repts & physical barriers Details withheld (ref 10CFR73 21)
EVANS,C A , KELLY,J A , CROSSMAN,W A Region 4, Office of Director 84/05/29 1p 25917 253 24X Fiche 50-382,84/05/31, 8408030266

8408060054 Forwards IE Insp Rept 50-382/84-22 on 840508-11 No violations or deviations noted
GAGLIARDO,J E Region 4, Office of Director 84/06/12
LEDDICK,R S Louisiana Power & Light Co 3pp 25935 278 24X
Fiche 50-382,84/06/12,8408060054

--8408060057 IE Insp Rept 50-382/84-22 on 840508-11 No violations or deviations noted Major areas inspected security-related testing & maint,communications,contingency response & emergency power supply Details withheld (ref 10CFR73 21)
KELLY,J , HALL,R E , CROSSMAN,W A Region 4, Office of Director 84/06/12 1p 25935 280 24X Fiche 50-382,84/06/12,8408060054

8408060317 Forwards IE Insp Rept 50-382/84-20 on 840409-13 & notice of deviation Proposed corrective actions & completion milestones to bring plant into conformance w/10CFR50,App R acceptable,per 840502 meeting Commitments listed
GAGLIARDO,J E Region 4, Office of Director 84/07/09
LEDDICK,R S Louisiana Power & Light Co 5pp 25936 131 24X
Fiche 50-382,84/07/09,8408060317

--8408060320 Notice of deviation from insp on 840409-13
* Region 4, Office of Director 84/07/09 2pp 25936 136 24X
Fiche 50-382,84/07/09,8408060317

--8408060325 IE Insp Rept 50-382/84-20 on 840409-13 Deviations noted failure to provide adequate surveillance procedure to ensure min inventory of personnel protective equipment verified
MURPHY,M E Region 4, Office of Director ANAND,R Office of Nuclear Reactor Regulation, Director MAURA,F Region 3, Office of Director 84/07/06 24pp 25936 138 24X
Fiche 50-382,84/07/09,8408060317

8408070230 Forwards revised procedures generation package,per 840507 & 30 requests Submittal completes requirements of NUREG-0737, Suppl 1 re upgrade of emergency operating procedures
COOK,K W Louisiana Power & Light Co 84/07/31 KNIGHTON,G W
Licensing Branch 3 2pp 25948 228 24X Fiche 50-382,84/07/31, 8408070230

8408220494 Forwards IE Insp Rept 50-382/84-28 on 840611-15 No violations or deviations noted
GAGLIARDO,J E Region 4, Office of Director 84/07/31
LEDDICK,R S Louisiana Power & Light Co 2pp 26196 015 24X
Fiche 50-382,84/07/31,8408220494

--8408220500 IE Insp Rept 50-382/84-28 on 840611-15 No violations or deviations noted Major areas inspected actions taken on previously identified insp findings re fire protection/prevention
HARBUCK,C C , MURPHY,M E , JAUDON,J P Region 4, Office of Director 84/07/19 9pp 26196 017 24X Fiche 50-382,84/07/31, 8408220494

8408100117 Forwards transportation support ltrs of agreement between State of LA,Ofc of Emergency Preparedness,util & state support svcs Encl withheld (ref 10CFR2 790)
COOK,K W Louisiana Power & Light Co 84/08/01 KNIGHTON,G W
Licensing Branch 2 3pp 25988 201 24X Fiche 50-382,84/08/01, 8408100117

8408070109 Notifies of intention to move location of backup emergency operations facility from Gretna to New Orleans,LA during Oct 1984
COOK,K W Louisiana Power & Light Co 84/08/02 EISENHUT,D G
Division of Licensing 3pp 25949 277 24X Fiche 50-382,84/08/02, 8408070109

8408230295 Forwards request for addl info re proposed safety parameter display sys Response requested 30 days prior to exceeding 5% rated power
KNIGHTON,G W Licensing Branch 3 84/08/06 LEDDICK,R S
Louisiana Power & Light Co 7pp 26236 119 24X
Fiche 50-382,84/08/06,8408230295

8408130342 Discusses installation,testing & associated training for diesel generator panel isolation switches Commits to complete installation prior to 5% power Commitment obviates need for App R exemption requests
COOK,K W Louisiana Power & Light Co 84/08/09 KNIGHTON,G W
Licensing Branch 3 2pp 26010 220 24X Fiche 50-382,84/08/09, 8408130342

8408310225 Forwards detailed response to Question 420 01 re verification of adequate safety parameter display sys isolation from safety-related sys No Tech Spec changes needed NUREG-0737,Suppl 1 requirements met
COOK,K W Louisiana Power & Light Co 84/08/27 KNIGHTON,G W
Licensing Branch 3 5pp 26319 276 24X Fiche 50-382,84/08/27, 8408310225

G Adjudicatory correspondence

8408070299 Discusses facts re Harstead Engineering Assoc, Inc, consultants on basemat issues at facility G Harstead participated as member of staff structural audit team during 1-wk audit at Waterford in Apr 1981
TURK,S E Hearing Branch 1 DSB 813 84/08/02 KOHL,C N , JOHNSON,W R , WILBER,H A Atomic Safety and Licensing Appeal Panel
9pp 25947 286 24X Fiche 50-382,84/08/02,8408070299

8408090178 Forwards SE Turk 840802 ltr re Harstead Engineering Assoc, Inc evaluation of foundation basemat Possibility of conflict of interest arises in light of Harstead acting as consultant to util & NRC
KOHL,C N , JOHNSON,W R , WILBER,H A Atomic Safety and Licensing Appeal Panel DSB 850 84/08/07 PLAINE,H H Office of the General Counsel 2pp 25973 172 24X Fiche 50-382,84/08/07, 8408090178

8408130248 Answer opposing Joint Intervenor 831212 amended & supplemental motion to reopen Contention 22 re adequacy of foundation basemat Joint Intervenor motion fails to raise significant safety or environ issue
TURK,S E Hearing Branch 1 DSB 900 84/08/07 Atomic Safety and Licensing Appeal Panel 9pp 26009 194 24X
Fiche 50-382,84/08/07,8408130248

--8408130251 Affidavit of DM Crutchfield re NRC review & evaluation of adequacy of foundation basemat Concrete cracks & related allegations do not present significant safety or environ issue Prof qualifications encl
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/08/07 11pp 26009 163 24X Fiche 50-382,84/08/07,8408130248

--8408130256 Affidavit of RE Shewmaker re insp efforts,technical assessment & conclusions reached concerning April/May 1984 insp Allegations re foundation basemat do not raise significant safety/environ issue Prof qualifications encl
SHEWMAKER,R E Engineering & Generic Communications Branch 84/08/07 17pp 26009 174 24X Fiche 50-382,84/08/07,8408130248

--8408130260 Affidavit of JP Knight re design adequacy & structural integrity of common foundation basemat Cracking observed does not affect safety of facility Prof qualifications, supporting documents & Certificate of Svc encl
KNIGHT,J P Assistant Director for Comp & Structures Engineering (Post 830201) 84/08/07 73pp 26009 191 24X
Fiche 50-382,84/08/07,8408130248

8408100001 Requests affidavit in response to listed questions re violation of federal conflict-of-interest regulations by G Harstead Response by 840827 requested Served on 840809
MALSCH,M G Office of the General Counsel DSB 888 84/08/09
CUNNINGHAM,G H Office of the Executive Legal Director 2pp
25990 040 24X Fiche 50-382,84/08/09,8408100001

8408100011 Requests affidavit in response to listed questions re violation of federal conflict-of-interest regulations by G Harstead Response by 840827 requested Served on 840809
MALSCH,M G Office of the General Counsel DSB 887 84/08/09
CHURCHILL,B Shaw, Pittman, Potts & Trowbridge 2pp 25990 103
24X Fiche 50-382,84/08/09,8408100011

8408130319 Forwards memo re transcript of meeting between Commissioner Asselstine & util,for svc on parties Served on 840810
DAVIS,P Commissioners DSB 933 84/08/09 CLEMENTS,W Docketing & Services Branch 1p 26010 142 24X Fiche 50-382,84/08/09, 8408130319

--8408130324 Informs that transcript of meeting between Commissioner Asselstine & util available in PDR & LPDR
DAVIS,P R Commissioners 84/08/09 Atomic Safety and Licensing Board Panel 1p 26010 143 24X Fiche 50-382,84/08/09, 8408130319

--8408130328 Responds to 840723 request for review of encl transcript of briefing w/Charnoff & Kane Svc on transcript recommended
MALSCH,M G Office of the General Counsel 84/08/08
ASSELSTINE,J K Commissioners 1p 26010 144 24X
Fiche 50-382,84/08/09,8408130319

--8408130333 Forwards transcript of meeting w/Charnoff & Kane Svc on parties unnecessary Review & opinion re svc on parties requested
ASSELSTINE,J K Office of the General Counsel 84/07/23
PLAINE,H Office of the General Counsel 1p 26010 145 24X
Fiche 50-382,84/08/09,8408130319

--8408130339 Transcript of 840716 meeting in Washington,DC re plan for responding to allegations about problems at plant Pp 1-21
* Commissioners 84/07/16 22pp 26010 146 24X
Fiche 50-382,84/08/09,8408130319

8408150081 Forwards revised Page 22 of JP Knight 840807 affidavit Proper executed affidavit confirming clarification will be submitted to ASLAB upon JP Knight return Related correspondence
TURK,S E Hearing Branch 1 DSB 045 84/08/09 KOHL,C N , JOHNSON,W R , WILBER,H A Atomic Safety and Licensing Appeal Panel 3pp 26067 047 24X Fiche 50-382,84/08/09,8408150081

8408280219 Responds to 840809 ltr re work done by Gunnar Harstead at facility Affidavits of KW Cook & G Harstead & svc list encl
CHURCHILL,B W Shaw, Pittman, Potts & Troubridge CHURCHILL,B W Louisiana Power & Light Co DSB 325 84/08/24 MALSCH,M G Office of the General Counsel 8pp 26274 335 24X Fiche 50-382,84/08/24, 8408280219

8408310106 Requests Commission act immediately in oversight of Ofc of Investigations,to ensure no further disclosure of info about targets & substance of investigation to util Svc list encl
BERNABEI,L Government Accountability Project BERNABEI,L Sierra Club BERNABEI,L Citizens for Safe Energy DSB 390 84/08/29
PALLADINO,N J , ROBERTS,T M , ASSELSTINE,J K Commissioners 18pp 26322 183 24X Fiche 50-382,84/08/29,8408310106

G Inspection reports, IE Bulletins & correspondence

8408030266 Forwards IE Insp Rept 50-382/84-19 on 840430-0504 No violations or deviations noted
GAGLIARDO,J E Region 4, Office of Director 84/05/31
LEDDICH,R S Louisiana Power & Light Co 2pp 25917 251 24X
Fiche 50-382,84/05/31,8408030266

--8408030275 IE Insp Rept 50-382/84-19 on 840430-0504 No violations or deviations noted Major areas inspected security plan & implementing procedures,records & repts & physical barriers Details withheld (ref 10CFR73 21)
EVANS,C A , KELLY,J A , CROSSMAN,W A Region 4, Office of Director 84/05/29 1p 25917 253 24X Fiche 50-382,84/05/31, 8408030266

8408100006 Informs of changes to 830902 commitment on IE Bulletin 83-05 re control of Hayward Tyler Pump Co supplied spare parts Only parts ordered on Purchase Orders A84407-D,A84244-D or A84406-D affected
COOK,K W Louisiana Power & Light Co 84/06/08 COLLINS,J T
Region 4, Office of Director 2pp 25990 099 24X
Fiche 50-382,84/06/08,8408100006

8408060054 Forwards IE Insp Rept 50-382/84-22 on 840508-11 No violations or deviations noted
GAGLIARDO,J E Region 4, Office of Director 84/06/12
LEDDICK,R S Louisiana Power & Light Co 3pp 25935 278 24X
Fiche 50-382,84/06/12,8408060054

--8408060057 IE Insp Rept 50-382/84-22 on 840508-11 No violations or deviations noted Major areas inspected security-related testing & maint;communications,contingency response & emergency power supply Details withheld (ref 10CFR73 21)
KELLY,J , HALL,R E , CROSSMAN,W A Region 4, Office of Director 84/06/12 1p 25935 280 24X Fiche 50-382,84/06/12,8408060054

8408160220 Forwards IE Insp Rept 50-382/84-21 on 840514-18 No violations or deviations noted
GAGLIARDO,J E Region 4, Office of Director 84/06/28
LEDDICK,R S Louisiana Power & Light Co 2pp 26106.237 24X
Fiche 50-382,84/06/28,8408160220

--8408160226 IE Insp Rept 50-382/84-21 on 840514-18 No violations or deviations noted Major areas inspected previously identified insp findings & selected TMI action plan requirements
CHANEY,H D , MURRAY,B , CROSSMAN,W A Region 4, Office of Director 84/06/28 9pp 26106 239 24X Fiche 50-382,84/06/28, 8408160220

8408060317 Forwards IE Insp Rept 50-382/84-20 on 840409-13 & notice of deviation Proposed corrective actions & completion milestones to bring plant into conformance w/10CFR50,App R acceptable,per 840502 meeting Commitments listed
GAGLIARDO,J E Region 4, Office of Director 84/07/09
LEDDICK,R S Louisiana Power & Light Co 5pp 25936 131 24X
Fiche 50-382,84/07/09,8408060317

--8408060320 Notice of deviation from insp on 840409-13
* Region 4, Office of Director 84/07/09 2pp 25936 136 24X
Fiche 50-382,84/07/09,8408060317

--8408060325 IE Insp Rept 50-382/84-20 on 840409-13 Deviations noted failure to provide adequate surveillance procedure to ensure min inventory of personnel protective equipment verified
MURPHY,M E Region 4, Office of Director ANAND,R Office of Nuclear Reactor Regulation, Director MAURA,F Region 3, Office of Director 84/07/06 24pp 25936 138 24X
Fiche 50-382,84/07/09,8408060317

8408100007 Discusses IE Bulletin 84-02 re failure of GE Type HFA relays Bulletin concerns inapplicable to facility relays, based on manufacturer review util will replace Lexan coil spools w/Century Series coil spools
COOK,K W Louisiana Power & Light Co 84/07/13 COLLINS,J T
Region 4, Office of Director 4pp 25990 053 24X
Fiche 50-382,84/07/13,8408100007

8408090070 Forwards exam rept of exam administered during wk of 840624
JOHNSON,C H Region 4, Office of Director 84/07/20 LEDDICK,R S
Louisiana Power & Light Co 2pp 25992 147 24X
Fiche 50-382,84/07/20,8408090070

--8408090073 Exam rept of exam administered during wk of 840624 Exam results all five candidates passed exam
PELLET,J L , COOLEY,R A Region 4, Office of Director 84/07/16
63pp 25992 149 24X Fiche 50-382,84/07/20,8408090070

8408150510 Forwards Waterford 3 Task Force Insp Rept 50-382/84-34 on 840402-13,0423-0504 & 14-25,executive summary,potential enforcement actions & unresolved items Insp conducted to examine adequacy of QA program activities
GAGLIARDO,J E Region 4, Office of Director 84/07/20
LEDDICK,R S Louisiana Power & Light Co 9pp 26079 234 24X
Fiche 50-382,84/07/20,8408150510

--8408150515 Waterford 3 Task Force Insp Rept 50-382/84-34 on 840402-13, 0423-0504 & 14-25 Insp conducted to examine allegations re adequacy of QA program activities Potential enforcement actions include failure to maintain QA records
PERANICH,M Director's Office, Office of Inspection and Enforcement MULLIKIN,R , TOMLINSON,D Region 4, Office of Director 84/07/17 133pp 26079 243 24X Fiche 50-382, 84/07/20,8408150510

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408220247 Forwards IE Insp Rept 50-382/84-25 on 840604-08 & notice of violation
GAGLIARDO,J E Region 4, Office of Director 84/07/31
LEDDICK,R S Louisiana Power & Light Co 2pp 26189.202 24X
Fiche 50-382,84/07/31,8408220247

--8408220252 Notice of violation from insp on 840604-08
* Region 4, Office of Director 84/07/31 2pp 26189 204, 24X
Fiche 50-382,84/07/31,8408220247

--8408220256 IE Insp Rept 50-382/84-25 on 840604-08 Violations noted, failure to require procedures to be issued to assure Ebasco review & to approve vendor manuals & technical data prior to use
BOARDMAN,J R , JAUDON,J P Region 4, Office of Director
84/07/30 10pp 26189 206 24X Fiche 50-382,84/07/31,8408220247

8408220494 Forwards IE Insp Rept 50-382/84-28 on 840611-15 No violations or deviations noted
GAGLIARDO,J E Region 4, Office of Director 84/07/31
LEDDICK,R S Louisiana Power & Light Co, 2pp 26196.015 24X
Fiche 50-382,84/07/31,8408220494,

---8408220500 IE Insp Rept 50-382/84-28 on 840611-15 No violations or deviations noted Major areas inspected actions taken on previously identified insp findings re fire protection/prevention
HARBUCK,C C , MURPHY,M E , JAUDON,J P Region 4, Office of Director 84/07/19 9pp 26196 017 24X Fiche 50-382,84/07/31, 8408220494

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26058 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408100131 Forwards vendor insp repts for evaluating significance of reported findings re quality & acceptability of product or svc provided by vendor Ack of receipt requested W/o encl
JOHNSON, E H Region 4, Office of Director 84/08/06 LEDDICK, R S
Louisiana Power & Light Co 2pp 25988 281 24X
Fiche 50-382, 84/08/06, 8408100131

8408100141 Discusses IE Insp Rept 50-382/84-34 re insp on 840402-13, 23-0504 & 14-25 Info re eight unresolved items requested to allow resolution prior to fuel load
COLLINS, J T Region 4, Office of Director 84/08/07 LEDDICK, R S
Louisiana Power & Light Co 2pp 25988 270 24X
Fiche 50-382, 84/08/07, 8408100141

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

408240021 Forwards Grand Gulf 1984 IE insp repts, per 840705 request NRC repts on allegations of falsification of training records forwarded to DOJ Rept contents withheld from public disclosure W/o encl
DEYOUNG, R D Director's Office, Office of Inspection and Enforcement 84/08/16 WALDRUM, R L Alaska, State of 4pp 26255 353 24X Fiche 50-000, 84/08/16, 8408240021

-8408240026 Requests NRC safety investigation repts for past 8 months & notification of current investigations Info needed to determine possible financial effect on State of AK, which may need to fund & buy energy from facilities.
WALDRUM, R L Alaska, State of 84/07/05 PALLADINO, N
Commissioners 1p 26255 354 24X Fiche 50-000, 84/08/16, 8408240021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408230275 Ack receipt of 840808 ltr informing NRC of steps taken to correct deviation noted in IE Insp Rept 50-382/84-20 Corrective actions will be reviewed during future insp
GAGLIARDO, J E Region 4, Office of Director 84/08/17
LEDDICK, R S Louisiana Power & Light Co 2pp 26206 135 24X
Fiche 50-382, 84/08/17, 8408230275

--8408230284 Responds to NRC 840709 ltr re violations noted in IE Insp Rept 50-382/84-20 Corrective actions Procedure MM-7-010 revised to add check for hydrostatic tests & for fire brigade operations equipment supplied
COOK, K W Louisiana Power & Light Co 84/08/08 COLLINS, J T
Region 4, Office of Director 2pp 26206 137 24X
Fiche 50-382, 84/08/17, 8408230275

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408010399 Second interim rept of Significant Const Deficiency 105 re electrical separation defects (Reg Guide 1 75) Next rept will be submitted on 840817
GERRETS, T F Louisiana Power & Light Co 84/07/19 COLLINS, J T
Region 4, Office of Director 2pp 25866 051 24X
Fiche 50-382, 84/07/19, 8408010399

8408030296 Ninth Interim Significant Const Deficiency 60 rept re turnover documentation & inadequate hanger weld problems Addl walkdowns, engineering evaluations & minor rework scheduled for completion by Aug 1984 Next rept by 840810
GERRETS, T F Louisiana Power & Light Co 84/07/19 COLLINS, J T
Region 4, Office of Director 2pp 25917 287 24X
Fiche 50-382, 84/07/19, 8408030296

8408060032 Second interim rept of Significant Const Deficiency 108 re potential failure to comply w/FSAR safe shutdown commitment RCS pressure indication cabling rerouted from containment penetration to LCP-43 Final rept expected by 840810
GERRETS, T F Louisiana Power & Light Co 84/07/19 Region 4, Office of Director 2pp 25935 270 24X Fiche 50-382, 84/07/19, 8408060032

8408060061 Tenth interim Significant Const Deficiency 88 rept re American Bridge structural steel Investigation incomplete Next rept will be submitted by 840810
GERRETS, T F Louisiana Power & Light Co 84/07/20 COLLINS, J T
Region 4, Office of Director 2pp 25935 281 24X
Fiche 50-382, 84/07/20, 8408060061

8408090029 Supplemental rept of Potentially Reportable Deficiency 172 re changes to emergency feedwater control sys not supporting Chapter 15 of FSAR Initially reported on 840711 Final rept will be submitted by 840803
GERRETS, T F Louisiana Power & Light Co 84/07/25 COLLINS, J T
Region 4, Office of Director 2pp 25992 257 24X
Fiche 50-382, 84/07/25, 8408090029

8408160221 Interim Deficiency Rept 112 re design changes Contractors reviewing design Final rept to be submitted 840823
GERRETS, T F Louisiana Power & Light Co 84/07/31 COLLINS, J T
Region 4, Office of Director 2pp 26106 235 24X
Fiche 50-382, 84/07/31, 8408160221

8408160180 Interim potentially reportable Deficiency 172 re changes t emergency feedwater control sys that may not support FSAR Chapter 15 Initially reported on 840611 Condition not reportable per 10CFR50 55(e)
GERRETS, T F Louisiana Power & Light Co 84/08/02 COLLINS, J T
Region 4, Office of Director 2pp 26106 308 24X
Fiche 50-382, 84/08/02, 8408160180

8408160228 First interim Deficiency Rept 114 re possible damage to safety-related equipment due to water hammers Questionable or damaged seismic restraints reworked Final rept will be submitted by 840831
GERRETS, T F Louisiana Power & Light Co 84/08/02 COLLINS, J T
Region 4, Office of Director 5pp 26106 230 24X
Fiche 50-382, 84/08/02, 8408160228

8408240407 Amended final Significant Const Deficiency Rept 96 re failure of Charging Pump A to start on safety injection actuation signal All relays subj to prerequisite & preoperational functional tests
GERRETS, T F Louisiana Power & Light Co 84/08/09 COLLINS, J T
Region 4, Office of Director 7pp 26237 106 24X
Fiche 50-382, 84/08/09, 8408240407

8408290131 Eleventh interim Significant Const Deficiency Rept 78 re American Bridge structural steel defects Initially reported on 840720 Corrective action incomplete Final rept will be submitted by 840831
GERRETS, T F Louisiana Power & Light Co 84/08/10 COLLINS, J T
Region 4, Office of Director 2pp 26277 344 24X
Fiche 50-382, 84/08/10, 8408290131

8408290139 Third interim Significant Const Deficiency Rept 108 re failure to comply w/FSAR safe shutdown commitment Initially reported on 840719 Verification of corrective action supporting documentation incomplete Final rept by 840831
GERRETS,T F Louisiana Power & Light Co 84/08/10 COLLINS,J T
Region 4, Office of Director 2pp 26297 346 24X
Fiche 50-382,84/08/10,8408290139

8408290145 Tenth interim Significant Const Deficiency Rept 60 re turnover documentation & inadequate hanger weld Problems T & B Initially reported on 840719 Walkdowns & rework incomplete Final rept will be submitted by 840831
GERRETS,T F Louisiana Power & Light Co 84/08/13 COLLINS,J T
Region 3, Office of Director 2pp 26297 348 24X
Fiche 50-382,84/08/13,8408290145

8408280440 Fourth interim Significant Const Deficiency Rept 90 re overstressed electrical conduit Initially reported on 840716 Corrective action incomplete Final rept will be submitted by 840830
GERRETS,T F Louisiana Power & Light Co 84/08/16 COLLINS,J T
Region 4, Office of Director 2pp 26282 132 24X
Fiche 50-382,84/08/16,8408280440

8408280436 Third interim Significant Const Deficiency Rept 105 re electrical separation defects (Reg Guide 1 75) Initially reported on 840719 Rework generated by evaluations of walkdown results incomplete Next rept expected by 840831
GERRETS,T F Louisiana Power & Light Co 84/08/17 COLLINS,J T
Region 4, Office of Director 2pp 26282 130 24X
Fiche 50-382,84/08/17,8408280436

8408300521 Final rept,Significant Const Deficiency 115 re unacceptably high fluoride levels in Micro-Lok insulation supplied by Johns-Manville Condition not reportable under 10CFR50 55(e) Apparently reported under Part 21 by Johns-Manville
GERRETS,T F Louisiana Power & Light Co 84/08/20 COLLINS,J T
Region 4, Office of Director 3pp 26313 359 24X
Fiche 50-382,84/08/20,8408300521

T Hearing transcripts on non-antitrust matters

8408130319 Forwards memo re transcript of meeting between Commissioner Asselstine & util,for svc on parties Served on 840810
DAVIS,P Commissioners DBD 933 84/08/09 CLEMENTS,W Docketing & Services Branch 1p 26010 142 24X Fiche 50-382,84/08/09, 8408130319

--8408130339 Transcript of 840716 meeting in Washington,DC re plan for responding to allegations about problems at plant Pp 1-21
* Commissioners 84/07/16 22pp 26010 146 24X
Fiche 50-382,84/08/09,8408130319

V Operator Examinations

8408090070 Forwards exam rept of exam administered during wk of 840624
JOHNSON,E H Region 4, Office of Director 84/07/20 LEDDICK,R S
Louisiana Power & Light Co 2pp 25992 147 24X
Fiche 50-382,84/07/20,8408090070

--8408090073 Exam rept of exam administered during wk of 840624 Exam results all five candidates passed exam
PELLET,J L , COOLEY,R A Region 4, Office of Director 84/07/16
63pp 25992 149 24X Fiche 50-382,84/07/20,8408090070

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

E NRC Safety Evaluation Report (SER), suppls & correspondence

8406190069 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SUSQUEHANNA STEAM ELECTRIC STATION,UNITS 1 AND 2 Docket Nos 50-387 And 50-388 (Pennsylvania Power And Light Company, Allegheny Electric Cooperative,Incorporated)
* Division of Licensing NUREG-0776 807 84/05/31 19pp
Available at NRC $3 00 25025 253 24X Fiche 50-387,84/05/31, 8406190069

F Security, medical, emergency & fire protection plans

8408200032 Forwards IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 84/07/31
KENYON,B D Pennsylvania Power & Light Co 2pp 26140 292 24X
Fiche 50-387,84/07/31,8408200032

--8408200036 Notice of violation from insp on 840609-0715
* Region 1, Office of Director 84/07/31 1p 26140 294 24X
Fiche 50-387,84/07/31,8408200032

8408200041 IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 Noncompliance noted two chemistry grab samples missed & fire detection instrumentation surveillance not performed within Tech Spec limits
JACOBS,R H , PLISCO,L R Region 1, Office of Director
MCCABE,E C Division of Project & Resident Programs 84/07/23
26pp 26140 295 24X Fiche 50-387,84/07/31,8408200032

8408100125 Revs to Emergency Plan Implementing Procedures EP-IP-002 re emergency mgt notifications,EP-IP-028 re downgrade & termination & EP-IP-030 re actuation & functional operation of emergency operations facility W/840807 ltr
KENYON,B D Pennsylvania Power & Light Co 84/08/07 34pp
25991 166 24X Fiche 50-387,84/08/07,8408100125

8408130129 Responds to 840602 SER re safety parameter display sys,per Suppl 1 to NUREG-0737 Secondary displays may be called up temporarily,but display always returns to primary display automatically
CURTIS,N W Pennsylvania Power & Light Co 84/08/08 SCHWENCER,A
Licensing Branch 2 9pp 26007 335 24X Fiche 50-387,84/08/08, 8408130129

8408310214 Revised emergency implementing procedures,including EP-IP-007 re personnel assembly & accountability,EP-IP-003 re dose assessment & protective actions & tables of content W/840824 ltr
KENYON,B D Pennsylvania Power & Light Co 84/08/24 114pp
26318 170 24X Fiche 50-387,84/08/24,8408310214

I Financial information

8408060143 Forwards Allegheny Electric Cooperative, Inc audited financial statements for FY ending Oct 1983
CURTIS,N W Pennsylvania Power & Light Co 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 16pp 25933 353
24X Fiche 50-387,84/07/31,8408060143

P Operating license stage documents & correspondence

8408010099 Forwards request for addl info re applicability of generic test results for safety/relief valves submitted in NEDE-24988-P by BWR Owners Group Info needed for review of response to NUREG-0737,Item II D 1
YOUNGBLOOD,B J Licensing Branch 1 84/07/20 CURTIS,N W
Pennsylvania Power & Light Co 3pp 25897 057 24X
Fiche 50-387,84/07/20,8408010099

8408070342 Forwards viewgraphs used during 840719 meeting w/NRC re fifth diesel generator project
CURTIS,N W Pennsylvania Power & Light Co 84/08/02 SCHWENCER,A
Licensing Branch 2 19pp 25945 210 24X Fiche 50-387,84/08/02, 8408070342

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129,238 24X
Fiche 50-000,84/08/06,8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408310426 Requests publication of FR notice of consideration of issuance of amends to Licenses NPF-14 & NPF-22 & proposed NSHC determination & opportunity for hearing re security
SCHWENCER,A Licensing Branch 2 84/08/27 MILLER,J R Operating Reactors Branch 3 4pp 26350 178 24X Fiche 50-387,84/08/27, 8408310426

Q Inspection reports, IE Bulletins & correspondence

8408010395 Forwards IE Insp Repts 50-387/84-23 & 50-388/84-29 on 840620 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/07/09
KENYON,B D Pennsylvania Power & Light Co 2pp 25866 056 24X
Fiche,50-387,84/07/09,8408010395

--8408010398 IE Insp Repts 50-387/84-23 & 50-388/84-29 on 840620 No violations noted Major areas inspected results of whole body counting phantom analysis comparison,procedures & QA & calibr data for bioassay whole body counting program
KOTTAN,J J , JANG,J C , PASCIAK,W J Region 1, Office of Director
84/07/05 4pp 25866 058 24X Fiche 50-387,84/07/09,8408010395

8408080157 Forwards IE Insp Repts 50-387/84-21 & 50-388/84-26 on 840611-14 No violations noted Three nonconformance repts issued in 1982 & 1983 remain resolved
MARTIN, T T Division of Engineering & Technical Programs 84/07/18
KENYON, B D Pennsylvania Power & Light Co 2pp 25974 300 24X
Fiche 50-387, 84/07/18, 8408080157

--8408080166 IE Insp Repts 50-387/84-21 & 50-388/84-26 on 840611-14 No violations noted Major areas inspected previous insp findings, nonlicensed technical training & QA program review
BISSETT, P , OLIVERIA, W , SHAUB, E Region 1, Office of Director
84/07/13 12pp 25974 302 24X Fiche 50-387, 84/07/18, 8408080157

8408090040 Forwards IE Insp Repts 50-387/84-18 & 50-388/84-22 on 840508-0608 & notice of violation Insp covered Unit 1 840221 excessive heatup rate & Unit 2 840528 turbine bypass transient
STAROSTECKI, R Division of Project & Resident Programs 84/07/19
KENYON, B D Pennsylvania Power & Light Co 2pp 25994 005 24X
Fiche 50-387, 84/07/19, 8408090040

--8408090048 Notice of violation from insp on 840508-0608.
* Region 1, Office of Director 84/07/19 2pp 25994 007 24X
Fiche 50-387, 84/07/19, 8408090040

--8408090053 IE Insp Repts 50-387/84-18 & 50-388/84-22 on 840508-0608 Violations noted RCIC flow controller on Unit 2 not returned to automatic following surveillance & secondary containment integrity on Unit 1 not maintained for 2 days
JACOBS, R , PLISCO, L , MANOLY, K Region 1, Office of Director
84/06/28 23pp 25994 009 24X Fiche 50-387, 84/07/19, 8408090040

8408030173 Ack receipt of 840320 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-30 & 50-388/83-25
MARTIN, T T Division of Engineering & Technical Programs 84/07/26
KENYON, B D Pennsylvania Power & Light Co 2pp 25915 317 24X
Fiche 50-387, 84/07/26, 8408030173

--8408030178 Responds to NRC 840126 ltr re violations noted in IE Insp Repts 50-387/83-30 & 50-388/83-25 Corrective actions G-list revised & B-list will be revised by 840428 to provide programmatic control for safety impact item program
KENYON, B D Pennsylvania Power & Light Co 84/03/20 MARTIN, T T
Division of Engineering & Technical Programs 6pp 25915 319
24X Fiche 50-387, 84/07/26, 8408030173

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408200032 Forwards IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/07/31
KENYON, B D Pennsylvania Power & Light Co 2pp 26140 292 24X
Fiche 50-387, 84/07/31, 8408200032

--8408200036 Notice of violation from insp on 840609-0715
* Region 1, Office of Director 84/07/31 1p. 26140 294 24X
Fiche 50-387, 84/07/31, 8408200032

--8408200041 IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 Noncompliance noted two chemistry grab samples missed & fire detection instrumentation surveillance not performed within Tech Spec limits
JACOBS, R H , PLISCO, L R Region 1, Office of Director
MCCABE, E C Division of Project & Resident Programs 84/07/23
26pp 26140:295 24X Fiche 50-387, 84/07/31, 8408200032

8408080269 Forwards response to Enforcement Action 84-5 & payment in amount of $75,000 Corrective actions HPCI topaz inverter energized & HPCI steam supply valves & drain valves repositioned W/o check
KENYON, B D Pennsylvania Power & Light Co 84/08/03 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 11pp
25965 314 24X Fiche 50-387, 84/08/03, 8408080269

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
esponse (Post 830103) 84/08/06 Consolidated Edison Co of New
ork, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New
York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New
York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New
York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New
York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408240108 Ack receipt of 840803 ltr & payment of $75,000 for civil penalty proposed on 840706 Corrective actions will be examined during future insps
AXELRAD, J A Enforcement Staff 84/08/17 CALHOUN, J Pennsylvania
Power & Light Co 2pp 26255 348 24X Fiche 50-387, 84/08/17, 8408240108

8408310118 Responds to request for addl info re IE Bulletin 83-07, "Apparently Fraudulent Products sold by Ray Miller, Inc " Fraudulent practices by natl suppliers will not adversely affect safe rigorous QA program
KENYON, B D Pennsylvania Power & Light Co 84/08/17 EBNETER, S D
Region 1, Office of Director 6pp 26322 132 24X
Fiche 50-387, 84/08/17, 8408310118

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New
York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408090395 LER 84-030-00 on 840627, boron concentration in standby liquid control tank fell to 0 4% below Tech Spec limit Cause unknown Tank level & concentration returned to within limits W/840803 ltr
KUCZYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
84/08/02 3pp 25993 278 24X Fiche 50-387, 84/08/02, 8408090395

8408090396 LER 84-031-00 on 840703, HPCI sys declared inoperable for 15 minutes Method used to seat check valve not adequate Procedural changes being evaluated W/840802 ltr
KUCZYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
84/08/02 3pp 25993 275 24X Fiche 50-387, 84/08/02, 8408090396

8408090421 LER 84-029-00 on 840703, startup transformer T-10 isolated, causing trip in Unit 1 & Unit 2 reactor protection sys A, Caused by lightning strike on 230-kV transmission line, W/ 840802 ltr
STANLEY, R W , KEISER, H W Pennsylvania Power & Light Co 84/08/02
4pp 25993 228 24X Fiche 50-387, 84/08/02, 8408090421

8408210290 LER 83-046/03X-1 on 830319 during monthly surveillance on diesel generator D, fuel oil leak developed on cylinder 1L Diesel shut down Caused by fuel oil leaking around injection pump metering shaft Pump replaced W/840802 ltr
WILKS, B L , KEISER, H W Pennsylvania Power & Light Co 84/08/02
MURLEY, T E Region 1, Office of Director 2pp 26180 347 24X
Fiche 50-387, 84/08/02, 8408210290

8408090439 LER 84-032-00 on 840323, staff determined that surveillance testing of ionization fire detectors not performed within time allowed by Tech Specs Caused by inconsistency between Unit 1 & 2 Tech Specs Tests performed W/840803 ltr
BAILEYS, T P , KEISER, H W Pennsylvania Power & Light Co 84/08/03
3pp 25993 236 24X Fiche 50-387, 84/08/03, 8408090439

8408200283 LER 84-034-00 on 840715, while operating at 100% power, 230-kV transmission line experienced phase-to-phase fault, resulting in generator load rejection & turbine trip Caused by line sagging into tree W/840814 ltr
KUZCYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
84/08/14 3pp 26139 331 24X Fiche 50-387, 84/08/14, 8408200283

8408240246 LER 84-033-00 on 840716, reactor scrammed on turbine valve fast closure Caused by loss of condenser vacuum breaker valve HV-10742C Operation procedures revised W/840815 ltr
STANLEY, R W , KEISER, H W Pennsylvania Power & Light Co 84/08/15
3pp 26236 280 24X Fiche 50-387, 84/08/15, 8408240246

8408240065 LER 84-035-00 on 840718, turbine control valve fast closure initiated by low condenser vacuum pressure resulting in reactor trip Caused by actions taken to established valve lineup to transfer water fuel pool tank W/840817 ltr
WILKS, B L , KEISER, H W Pennsylvania Power & Light Co 84/08/17
3pp 26236 360 24X Fiche 50-387, 84/08/17, 8408240065

8408300489 LER 84-036-00 on 840724, short circuit to ground developed, tripping motor-generator set & resulting in start of standby gas treatment sys Caused by grease buildup in motor of reactor protection sys A motor-generator set W/840821 ltr
KUCZYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
84/08/21 3pp 26314 080 24X Fiche 50-387, 84/08/21, 8408300489

8408300340 NPDES noncompliance notification on 840818-22, total suspended solids (TSS) in cooling tower blowdown exceeded 200 mg/l limit Caused by high TSS levels in Susquehanna River & effects of cooling sys
FIELDS, J S Pennsylvania Power & Light Co 84/08/23 KOVAL, P
Pennsylvania, Commonwealth of, 2pp 26308 335 24X
Fiche 50-387, 84/08/23, 8408300340

U Congressional/Executive Correspondence

8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far
ASSELSTINE, J K Commissioners 84/08/10 MARKEY, E J House of Rep , Interior & Insular Affairs 4pp 26141 244 24X
Fiche 50-000, 84/08/10, 8408200225

--8408200279 Requests further info re Tech Spec errors for specs approved since TMI-2 episode Info re near-term OL activities also requested
MARKEY, E J House of Rep , Interior & Insular Affairs 84/07/12
PALLADINO, N J Commissioners 1p 26142 002 24X
Fiche 50-000, 84/08/10, 8408200225

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

E NRC Safety Evaluation Report (SER), suppls & correspondence

8406190069 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SUSQUEHANNA STEAM ELECTRIC STATION, UNITS 1 AND 2 Docket Nos 50-387 And 50-388 (Pennsylvania Power And Light Company, Allegheny Electric Cooperative, Incorporated)
* Division of Licensing NUREG-0776 807 84/05/31 19pp
Available at NRC $3 00 25025 253 24X Fiche 50-387, 84/05/31, 8406190069

F Security, medical, emergency & fire protection plans

8408200032 Forwards IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/07/31
KENYON, B D Pennsylvania Power & Light Co 2pp 26140 292 24X
Fiche 50-387, 84/07/31, 8408200032

--8408200041 IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 Noncompliance noted two chemistry grab samples missed & fire detection instrumentation surveillance not performed within Tech Spec limits
JACOBS, R H Region 1, Office of Director 84/07/23 26pp
26140 295 24X Fiche 50-387, 84/07/31, 8408200032

8408100125 Revs to Emergency Plan Implementing Procedures EP-IP-002 re emergency mgt notifications, EP-IP-028 re downgrade & termination & EP-IP-030 re actuation & functional operation of emergency operations facility W/840807 ltr
KENYON, B D Pennsylvania Power & Light Co 84/08/07 34pp
25991 166 24X Fiche 50-387, 84/08/07, 8408100125

8408130129 Responds to 840602 SER re safety parameter display sys, per Suppl 1 to NUREG-0737 Secondary displays may be called up temporarily, but display always returns to primary display automatically
CURTIS, N W Pennsylvania Power & Light Co 84/08/08 SCHWENCER, A
Licensing Branch 2 9pp 26007 335 24X Fiche 50-387, 84/08/08, 8408130129

8408310214 Revised emergency implementing procedures, including EP-IP-007 re personnel assembly & accountability, EP-IP-003 re dose assessment & protective actions & tables of content W/840824 ltr
KENYON, B D Pennsylvania Power & Light Co 84/08/24 114pp
26318 170 24X Fiche 50-387, 84/08/24, 8408310214

I Financial information

8408060143 Forwards Allegheny Electric Cooperative, Inc audited financial statements for FY ending Oct 1983
CURTIS, N W Pennsylvania Power & Light Co 84/07/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 16pp 25933 353
24X Fiche 50-387, 84/07/31, 8408060143

P Operating license stage documents & correspondence

8408010099 Forwards request for addl info re applicability of generic test results for safety/relief valves submitted in NEDE-24988-P by BWR Owners Group Info needed for review of response to NUREG-0737, Item II D 1
YOUNGBLOOD, B J Licensing Branch 1 84/07/20 CURTIS, N W
Pennsylvania Power & Light Co 3pp 25897 057 24X
Fiche 50-387, 84/07/20, 8408010099

8408070342 Forwards viewgraphs used during 840719 meeting w/NRC re fifth diesel generator project
CURTIS, N W Pennsylvania Power & Light Co 84/08/02 SCHWENCER, A
Licensing Branch 2 19pp 25945 210 24X Fiche: 50-387, 84/08/02, 8408070342

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G, Division of Licensing 84/08/20, Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310426 Requests publication of FR notice of consideration of issuance of amends to Licenses NPF-14 & NPF-22 & proposed NSHC determination & opportunity for hearing re security
SCHWENCER, A Licensing Branch 2 84/08/27 MILLER, J R Operating
Reactors Branch 3 4pp 26350 178 24X Fiche: 50-387, 84/08/27, 8408310426

Q Inspection reports, IE Bulletins & correspondence

8408010395 Forwards IE Insp Repts 50-387/84-23 & 50-388/84-29 on 840620 No violations noted.
MARTIN, T T Division of Engineering & Technical Programs 84/07/09,
KENYON, B D Pennsylvania Power & Light Co 2pp 25866 056 24X
Fiche 50-387, 84/07/09, 8408010395

--8408010398 IE Insp Repts 50-387/84-23 & 50-388/84-29 on 840620 No violations noted Major areas inspected: results of whole body counting phantom analysis comparison, procedures & QA & calibr data for bioassay whole body counting program
KOTTAN, J J , JANO, J C , PASCIAK, W J Region 1, Office of Director
84/07/05 4pp 25866 058 24X Fiche 50-387, 84/07/09, 8408010395

8408080157 Forwards IE Insp Repts 50-387/84-21 & 50-388/84-26 on 840611-14 No violations noted Three nonconformance repts issued in 1982 & 1983 remain resolved
MARTIN, T T Division of Engineering & Technical Programs 84/07/18
KENYON, B D Pennsylvania Power & Light Co 2pp 25974 300 24X
Fiche 50-387, 84/07/18, 8408080157

--8408080166 IE Insp Repts 50-387/84-21 & 50-388/84-26 on 840611-14 No violations noted Major areas inspected previous insp findings, nonlicensed technical training & QA program review
BISSETT, P , OLIVERIA, W , SHAUB, E Region 1, Office of Director
84/07/13 12pp 25974 302 24X Fiche 50-387, 84/07/18, 8408080157

8408090040 Forwards IE Insp Repts 50-387/84-18 & 50-388/84-22 on 840508-0608 & notice of violation Insp covered Unit 1 840221 excessive heatup rate & Unit 2 840528 turbine bypass transient
STAROSTECKI, R Division of Project & Resident Programs 84/07/19
KENYON, B D Pennsylvania Power & Light Co 2pp 25994 005 24X
Fiche 50-387, 84/07/19, 8408090040

--8408090048 Notice of violation from insp on 840508-0608
* Region 1, Office of Director 84/07/19 2pp 25994 007 24X
Fiche 50-387, 84/07/19, 8408090040

--8408090053 IE Insp Repts 50-387/84-18 & 50-388/84-22 on 840508-0608 Violations noted RCIC flow controller on Unit 2 not returned to automatic following surveillance & secondary containment integrity on Unit 1 not maintained for 2 days
JACOBS, R , PLISCO, L , MANOLY, K Region 1, Office of Director
84/06/28 23pp 25994 009. 24X Fiche 50-387, 84/07/19, 8408090040

8408030173 Ack receipt of 840320 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-30 & 50-388/83-25
MARTIN, T T Division of Engineering & Technical Programs 84/07/26
KENYON, B D Pennsylvania Power & Light Co 2pp 25915 317 24X
Fiche 50-387, 84/07/26, 8408030173

--8408030178 Responds to NRC 840126 ltr re violations noted in IE Insp Repts 50-387/83-30 & 50-388/83-25 Corrective actions Q-list revised & S-list will be revised by 840428 to provide programmatic control for safety impact item program
KENYON, B D Pennsylvania Power & Light Co 84/03/20 MARTIN, T T
Division of Engineering & Technical Programs 6pp 25915 319
24X Fiche 50-387, 84/07/26, 8408030173

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010162 EN-84-050 on 840727, confirmatory order issued to util confirming commitment for immediate cold shut down Action taken because of loss of ac power due to diesel generators not recieving start signal
FARRON, P , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/07/30 1p 25853 304 24X Fiche 50-388, 84/07/30, 8408010162

8408200032 Forwards IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/07/31
KENYON, B D Pennsylvania Power & Light Co 2pp 26140 292 24X
Fiche 50-387, 84/07/31, 8408200032

--8408200041 IE Insp Repts 50-387/84-22 & 50-388/84-28 on 840609-0715 Noncompliance noted two chemistry grab samples missed & fire detection instrumentation surveillance not performed within Tech Spec limits
JACOBS, R H , PLISCO, L R Region 1, Office of Director
MCCABE, E C Division of Project & Resident Programs 84/07/23
26pp 26140 295 24X Fiche 50-387, 84/07/31, 8408200032

8408080269 Forwards response to Enforcement Action 84-5 & payment in amount of $75,000 Corrective actions HPCI topaz inverter energized & HPCI steam supply valves & drain valves repositioned W/o check
KENYON, B D Pennsylvania Power & Light Co 84/08/03 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 11pp
25965:314 24X Fiche 50-387, 84/08/03, 8408080269

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408240108 Ack receipt of 840803 ltr & payment of $75,000 for civil penalty proposed on 840706 Corrective actions will be examined during future insps
AXELRAD, J A Enforcement Staff 84/08/17 CALHOUN, J Pennsylvania Power & Light Co 2pp 26255 348 24X Fiche 50-387, 84/08/17, 8408240108

8408310118 Responds to request for addl info re IE Bulletin 83-07, "Apparently Fraudulent Products sold by Ray Miller, Inc " Fraudulent practices by natl suppliers will not adversely affect safe rigorous QA program
KENYON, B D Pennsylvania Power & Light Co 84/08/17 EDNETER, S D
Region 1, Office of Director 6pp 26322 132 24X
Fiche 50-387, 84/08/17, 8408310118

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408090265 Confirmatory action ltr re 840726 telcon w/J Calhoun on loss of ac power during certain tests Actions should include taking unit to cold shutdown & thorough investigation into causes & implications
MURLEY, T E Region 1, Office of Director 84/07/26 CALHOUN, J
Pennsylvania Power & Light Co 2pp 25994 202 24X
Fiche 50-388, 84/07/26, 8408090265

8408030157 PNO-I-84-062A on 840726, during planned loss of offsite ac power startup test at 30% reactor power, backup emergency diesel generators did not automatically start Caused by incorrectly positioned dc power switches
ESELGROTH, P. , GREENMAN, E Region 1, Office of Director 84/07/27
1p 25912.018. 24X Fiche 50-388, 84/07/27, 8408030157

8408080142 LER 84-010-00 on 840627, HPCI sys declared inoperable for 22 h to facilitate removal of startup strainer Caused by blockage in startup during heatup plateau review Startup strainer removed & ring spacer installed W/840730 ltr
STANLEY, R W , KEISER, H W Pennsylvania Power & Light Co 84/07/30
3pp 25974 334 24X Fiche 50-388, 84/07/30, 8408080142

8408090393 LER 84-011-00 on 840705 & 06, four spurious actuations of standby gas treatment sys & control room emergency outside air supply sys experienced Caused by malfunctioning output breaker Breaker replaced W/840803 ltr
KUCZYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
84/08/03 3pp 25993 281 24X Fiche 50-388, 84/08/03, 8408090393

8408160164 LER 84-012-00 840709, core spray logic control power fuses removed since fuses thought to be possible blocking point for personnel protection Removal affected listed equipment Fuses reinstalled W/840809 ltr
STANLEY, R W , KEISER, H W Pennsylvania Power & Light Co 84/08/09
5pp 26108 060 24X Fiche 50-388, 84/08/09, 8408160164

8408300189 Special rept on 840528, during Startup Test 14 2, "Reactor Vessel Injections," two RCIC sys actuations resulted in injection of water into RCS Current usage for affected nozzles less than 0 70
KEISER, H W Pennsylvania Power & Light Co 84/08/15 MURLEY, T E
Region 1, Office of Director 1p 26308 028 24X
Fiche 50-388, 84/08/15, 8408300189

8408230077 Summary of 840807 operating reactor events meeting re occurrences since 840719 meeting List of attendees, significant elements & status of previous assignments encl
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/08/16
EISENHUT, D G Division of Licensing 20pp 26233 249 24X
Fiche 50-000, 84/08/16, 8408230077

8408300484 LER 84-014-00 on 840723, reactor water cleanup inlet outboard board isolation valve (2F004) closed due to high temp in filter demineralizer room Caused by problems w/reactor bldg chilled water sys W/840822 ltr
STANLEY, R W , KEISER, H W Pennsylvania Power & Light Co 84/08/22
3pp 26314 089 24X Fiche 50-388, 84/08/22, 8408300484

8408300340 NPDES noncompliance notification on 840818-22, total suspended solids (TSS) in cooling tower blowdown exceeded 200 mg/l limit Caused by high TSS levels in Susquehanna River & effects of cooling sys
FIELDS, J S Pennsylvania Power & Light Co 84/08/23 KOVAL, P
Pennsylvania, Commonwealth of, 2pp 26308 335 24X
Fiche 50-387, 84/08/23, 8408300340

8408300399 LER 84-013-00 on 840726, during scram due to turbine control valve fast closure & deenergization of 13 8 kV & 14 16 kV buses, control rods did not fully insert Caused by failure of diesel generators to start automatically W/840824 ltr
STANLEY, R W , KEISER, H W Pennsylvania Power & Light Co 84/08/24
97pp 26314 158 24X Fiche 50-388, 84/08/24, 8408300399

U Congressional/Executive Correspondence

8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far
ASSELSTINE, J K Commissioners 84/08/10 MARKEY, E J House of Rep , Interior & Insular Affairs 4pp 26141 244 24X
Fiche 50-000, 84/08/10, 8408200225

--8408200235 Forwards technical evaluation rept re Tech Spec audit Only discrepancy involved lack of quantitative criteria for limit switch setting & calibr for suppression chamber vacuum breakers Util should resolve rept recommendations
STAROSTECKI, R Division of Project & Resident Programs 84/04/10
EISENHUT, D G Division of Licensing 3pp 26141 262 24X
Fiche 50-000, 84/08/10, 8408200225

--8404040095 Forwards "Audit of Susquehanna Unit 2 Tech Specs," technical evaluation rept
PANDEY, S Franklin Institute/Franklin Research Center
NRC-03-81-130 84/03/30 CARRINGTON, M NRC - No Detailed
Affiliation Given 1p 26141 265 24X Fiche 50-000, 84/08/10, 8408200225

--8404040098 "Audit of Susquehanna Unit 2 Tech Specs" technical evaluation rept
DACANSKAS, V P , MURPHY, J A Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-524 84/03/30
BETTENHAUSEN, L , MCCABE, E NRC - No Detailed Affiliation Given
26pp 26141 266 24X Fiche 50-000, 84/08/10, 8408200225

--8408200279 Requests further info re Tech Spec errors for specs approved since TMI-2 episode Info re near-term OL activities also requested
MARKEY, E J House of Rep , Interior & Insular Affairs 84/07/12
PALLADINO, N J Commissioners 1p 26142 002 24X
Fiche 50-000, 84/08/10, 8408200225

DOCKET 50-389 ST LUCIE PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408010091 Forwards request for addl info re procedures generation package for emergency operating procedures Response requested within 30 days of ltr receipt
MILLER, J R Operating Reactors Branch 3 84/07/17 WILLIAMS, J W
Florida Power & Light Co 3pp 25897 064 24X
Fiche 50-335, 84/07/17, 8408010091

8408020123 Rev 1 to Off-Normal Operating Procedure 2-0970031, "Loss of SUPS - Nonsafety Vital AC or Fire & Security Inverters " W/840724 ltr
WETHY, C M Florida Power & Light Co 84/07/24 5pp 25891 025
24X Fiche 50-389, 84/07/24, 8408020123

8408030126 Forwards IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/30 WILLIAMS, J W
Florida Power & Light Co 2pp 25916 120 24X
Fiche 50-335, 84/07/30, 8408030126

--8408030127 IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No noncompliance noted Major areas inspected changes to physical security plan & implementing procedures Details withheld (ref 10CFR2 790 & 10CFR73 21)
TILLMAN, A Region 2, Office of Director 84/07/27 1p.
25916 122 24X Fiche 50-335, 84/07/30, 8408030126

8408090009 Forwards response to 840605 request for addl info re Rev 8 to physical security plan Response withheld (ref 10CFR73 21)
WILLIAMS, J W Florida Power & Light Co 84/08/06 MILLER, J R
Operating Reactors Branch 3 1p 25973 113 24X
Fiche 50-335, 84/08/06, 8408090009

8408100016 Forwards Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization "
WILLIAMS, J W Florida Power & Light Co 84/08/08 O'REILLY, J P
Region 2, Office of Director 1p 25987 006 24X
Fiche 50-000, 84/08/08, 8408100016

--8408100054 Emergency Plan Implementing Procedure EPIP-1301, "Emergency Roster - Offsite Emergency Organization "
JOHNSON, H D Florida Power & Light Co 84/08/08 13pp
25987 007 24X Fiche 50-000, 84/08/08, 8408100016

8408130219 Notifies that responses to 840717 questions re procedure generation package for emergency operating procedures, will be provided, w/assistance of C-E Owners Group Procedure Subcommittee at 840829 meeting w/NRC reviewers
WILLIAMS, J W Florida Power & Light Co 84/08/08 MILLER, J R
Operating Reactors Branch 3 1p 26005 360 24X
Fiche. 50-335, 84/08/08, 8408130219

8408300303 Forwards FEMA "Exercise Rept on St Lucie Nuclear Power Plant Exercise on 840306 "
DANCE, H C Region 2, Office of Director 84/08/14 WILLIAMS, J W
Florida Power Corp 3pp 26306 151 24X Fiche 50-335, 84/08/14, 8408300303

P Operating license stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl.
EISENHUT, D G. Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp. 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408090096 Forwards addl info re crack growth rates & Westinghouse methodology for determining temps for calculating crack growth rates, in response to NRC 840409 request Info will be included in next FSAR update
WILLIAMS, J W Florida Power & Light Co 84/08/06 MILLER, J R.
Operating Reactors Branch 3 4pp 25972 295 24X
Fiche 50-389, 84/08/06, 8408090096

8408160319 Forwards "Maint & Surveillance Program Plan," revised following 840706 NRC/NUMARC meeting
RUSSELL,W T Division of Human Factors Safety 84/08/07
WOODY,C O Florida Power & Light Co 1p 26126 019 24X
Fiche 50-000,84/08/07,8408160319

8408170013 Notifies of Class I & II fees due for 840515 & 21 Tech Spec organizational change requests Discussion of fee requirements encl
MILLER,W O License Fee Management Branch 84/08/10 WILLIAMS,J W
Florida Power & Light Co 3pp 26135 347 24X
Fiche 50-335,84/08/10,8408170013

8408170385 Responds to util 840329 ltr arguing for Class II rather than Class III fee Class III charge still holds,as technical review effort was expended
MILLER,W O License Fee Management Branch 84/08/10 WILLIAMS,J W
Florida Power & Light Co 1p 26134 196 24X
Fiche 50-389,84/08/10,8408170385

8408170054 Forwards info re Cycle 2 reload,per 840621 request
WILLIAMS,J W Florida Power & Light Co 84/08/14 MILLER,J R
Operating Reactors Branch 3 10pp 26119 006 24X
Fiche 50-389,84/08/14,8408170054

8408200143 Advises that permanent refueling canal sump pump will not be installed,per 821008 commitment Mod determined unnecessary
WILLIAMS,J W Florida Power & Light Co 84/08/14 EISENHUT,D G
Division of Licensing 1p 26133 282 24X Fiche 50-389,84/08/14,8408200143

8408200200 Submits results of recalculated figures of offsite doses for fuel handling accident Calculations remain same as presented in Table 5-7 of spent fuel pool repack SAR except no credit taken for filters
WILLIAMS,J W Florida Power & Light Co 84/08/14 MILLER,J R
Operating Reactors Branch 3 1p 26131 080 24X
Fiche 50-389,84/08/14,8408200200

8408230564 Notification of 840906 & 07 meetings w/util in Bethesda,MD to discuss control room design reviews
MCDONALD,D Q Operating Reactors Branch 1 84/08/16 VARGA,S A
Operating Reactors Branch 1 2pp 26230 260 24X
Fiche 50-000,84/08/16,8408230564

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408310145 Forwards addl info re spent fuel rack submittal & summary of 840816 meeting re fuel rack structural analysis,in response to 840713 request
WILLIAMS,J W Florida Power & Light Co 84/08/29 MILLER,J R
Operating Reactors Branch 3 63pp 26318 337 24X
Fiche 50-389,84/08/29,8408310145

G Inspection reports, IE Bulletins & correspondence

8408280236 Submits results of Ebasco Svcs review of Ray Miller,Inc supplied matls,in response to IE Bulletin 83-07,per util 840404 ltr Ray Miller products not installed at facilities
WILLIAMS,J W Florida Power & Light Co 84/06/01 O'REILLY,J P
Region 2, Office of Director 2pp 26262 279 24X
Fiche 50-335,84/06/01,8408280236

8408300395 Informs of incorrect rept number on 840530 rept.Rept 50-389/84-18 should read 50-389/84-22
DANCE,H C Region 2, Office of Director 84/06/22 WILLIAMS,J W
Florida Power & Light Co 1p 26308 207 24X Fiche 50-335, 84/06/22,8408300395

8408280106 Responds to Item 2 of IE Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature Design margin available to open breakers sufficient to justify current maint & surveillance program
WILLIAMS,J W Florida Power & Light Co 84/07/02 O'REILLY,J P
Region 2, Office of Director 6pp 26261 290 24X
Fiche 50-389,84/07/02,8408280106

8408280058 Responds to IE Bulletin 84-02 re failure of GE HFA relays in Class 1E safety sys All Unit 1 relays replaced w/Tefzel series relays & spare part specs upgraded Unit 2 relays mfg w/Tefzel spools
WILLIAMS,J W Florida Power & Light Co 84/07/18 O'REILLY,J P
Region 2, Office of Director 3pp 26261 224 24X
Fiche 50-335,84/07/18,8408280058

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408270192 Ack receipt of 840702 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/84-12 & 50-389/84-14
LEWIS,R C Division of Project & Resident Programs 84/07/27
WILLIAMS,J W Florida Power & Light Co 1p 26258 001 24X
Fiche 50-335,84/07/27,8408270192

--8408270200 Responds to NRC 840601 ltr re violations noted in Insp Repts 50-335/84-12 & 50-389/84-14 Corrective actions calibr program under review & QA auditor counseled
WILLIAMS,J W Florida Power & Light Co 84/07/02 O'REILLY,J P
Region 2, Office of Director 3pp 26258 002 24X
Fiche 50-335,84/07/27,8408270192

--8408270209 Forwards Insp Repts 50-335/84-12 & 50-389/84-14 on 840423-27 & notice of violation
LEWIS,R C Division of Project & Resident Programs 84/06/01
WILLIAMS,J W Florida Power & Light Co 2pp 26258 005 24X
Fiche 50-335,84/07/27,8408270192

--8408270214 Notice of violation from insp on 840423-27
* Region 2, Office of Director 84/06/01 2pp 26258 007 24X
Fiche 50-335,84/07/27,8408270192

--8408270221 Insp Repts 50-335/84-12 & 50-389/84-14 on 840423-27 Violations noted failure to include gauges in calibr program & failure to audit calibr program sufficiently
BELISLE,G A , FOSTER,L E , UPRIGHT,C M Region 2, Office of Director 84/05/25 15pp 26258 009 24X Fiche 50-335,84/07/27, 8408270192

8408270360 Forwards Insp Repts 50-335/84-21 & 50-389/84-23 on 840610-0714 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/27 WILLIAMS,J W
Florida Power & Light Co 2pp 26257 221 24X
Fiche 50-335,84/07/27,8408270360

--8408270363 Insp Repts 50-335/84-21 & 50-389/84-23 on 840610-0714 No violations noted Major areas inspected plant,surveillance & maint observations
FEIERABEND,C D , BIBB,H E Region 2, Office of Director
ELROD,S A Division of Project & Resident Programs 84/07/27
4pp 26257 223 24X Fiche 50-335,84/07/27,8408270360

8408030126 Forwards IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/30 WILLIAMS,J W
Florida Power & Light Co 2pp 25916 120 24X
Fiche 50-335,84/07/30,8408030126

--8408030127 IE Safeguards Insp Repts 50-335/84-24 & 50-389/84-26 on 840709-13 No noncompliance noted Major areas inspected changes to physical security plan & implementing procedures Details withheld (ref 10CFR2 790 & 10CFR73 21)
TILLMAN,A , MCGUIRE,D R Region 2, Office of Director 84/07/27
1p 25916 122 24X Fiche 50-335,84/07/30,8408030126

8408270291 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/84-18 & 50-389/84-19
DANCE,H C Region 2, Office of Director 84/08/02 WILLIAMS,J W
Florida Power & Light Co 1p 26258 178 24X Fiche 50-335, 84/08/02,8408270291

--8408270298 Responds to NRC 840608 ltr re violations noted in Insp Repts 50-335/84-18 & 50-389/84-19 Corrective actions installed detectors will be replaced & two spare detectors properly calibr
WILLIAMS,J W Florida Power & Light Co 84/07/09 O'REILLY,J P
Region 2, Office of Director 2pp 26258 179 24X
Fiche 50-335,84/08/02,8408270291

--8408270306 Forwards Insp Repts 50-335/84-18 & 50-389/84-19 on 840514-18 & notice of violation
DANCE,H C Region 2, Office of Director 84/06/08 WILLIAMS,J W
Florida Power & Light Co 2pp 26258 181 24X
Fiche 50-335,84/08/02,8408270291

--8408270310 Notice of violation from insp on 840514-18
* Region 2, Office of Director 84/06/08 1p 26258 183 24X
Fiche 50-335,84/08/02,8408270291

--8408270317 Insp Repts 50-335/84-18 & 50-389/84-19 on 840514-18
Noncompliance noted Failure to certify proper vendor
calib" of containment high-range radiation monitors prior
to initial use
WRAY, J R , JENKINS, C R Region 2, Office of Director 84/06/08
6pp 26258 184 24X Fiche 50-335, 84/08/02, 8408270291

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station
Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator
Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR
Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New
York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to
Patients Undergoing Co-60 Teletherapy Treatments " Svc
list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post
830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New
York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In &
Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New
York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely
Affect Operation of Essential Electrical Equipment " Svc
list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New
York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of
Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/
High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly
Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New
York, Inc 119pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to
drop out on listed undervoltage conditions Problem due to
excessive feedback around operational amplifier U2 Clamping
diode must be added Affected units listed
DUVALI, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd)
84/03/13 DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 3pp 26191 357 24X Fiche 50-000, 84/03/13, 8408220317

V Operator Examinations

8408300392 Confirms that operator who failed Section 7 of NRC senior
reactor operator upgrade written exam, administered on
840619, has been prohibited from performing licensed duties
O'REILLY, J P Region 2, Office of Director 84/08/13
WILLIAMS, J W Florida Power & Light Co 2pp 26308 120 24X
Fiche 50-335, 84/08/13, 8408300392

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8408010172 Forwards updated environ info re electrical equipment
qualification Evaluation assessing addl equipment
qualification in progress & info will be provided by 840803,
for review
MILLS, L M Tennessee Valley Authority 84/07/24 ADENSAM, E
Licensing Branch 4 1780pp 25875 168 24X Fiche 50-390, 84/07/24,
8408010172

8408030128 Requests meeting to discuss proposed mod to draft App A Tech
Specs Mod changes Tech Specs to increase allowable RCS
isolation valve leakage from current draft Tech Spec
limitation of 1 gpm to 9 gpm
MILLS, L M Tennessee Valley Authority 84/07/27 ADENSAM, E
Licensing Branch 4 2pp 25916 123 24X Fiche 50-390, 84/07/27,
8408030128

8408130375 Forwards summary rept of util intent to use addl diesel
generator, including info re design & const of diesel
generator & associated structure
MILLS, L M Tennessee Valley Authority 84/07/30 O'REILLY, J P
Region 2, Office of Director 2pp 26010 305 24X
Fiche 50-390, 84/07/30, 8408130375

8408160425 Summary of 840720 meeting w/utils & Westinghouse re
containment analysis & superheat effects on environ
qualification
WIGGINTON, D L Operating Reactors Branch 1 84/07/30 Operating
Reactors Branch 1 4pp 26143 265 24X Fiche 50-000, 84/07/30,
8408160425

8408090428 Notification of 840807-08 meetings w/util in Bethesda, MD to
discuss util comments on Tech Specs
KENYON, T J Licensing Branch 4 84/08/03 ADENSAM, E G Licensing
Branch 4 3pp 25984 302 24X Fiche 50-390, 84/08/03, 8408090428

8408070110 Generic Ltr 84-19 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
Suppl 1 to NUREG-0933, "Prioritization of Generic Safety
Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408130275 Forwards "Reactor Bldg Containment Integrated Leak Rate
Test, Suppl," conducted on 830519-20 Info fulfills B30818
commitment & completes requirement to provide summary rept
to NRC re leak rate testing
MILLS, L M Tennessee Valley Authority 84/08/07 ADENSAM, E
Licensing Branch 4 1p 26008 272 24X Fiche 50-390, 84/08/07,
8408130275

--8408130280 "Reactor Bldg Containment Integrated Leak Rate Test, Suppl,"
conducted on 830519-20
* Tennessee Valley Authority 84/08/07 9pp 26008 273 24X
Fiche 50-390, 84/08/07, 8408130275

8408300424 Confirms 840712 telcon re NRR & Region II mgt visit to site
on 840816 to evaluate const & readiness for operation of
plant
LEWIS, R C Region 2, Office of Director 84/08/08 PARRIS, H G
Tennessee Valley Authority 2pp 26313 305 24X
Fiche 50-390, 84/08/08, 8408300424

8408210435 Forwards environ qualification of nonsafety-related
equipment, per 10CFR50 49(b)(2), for incorporation into
840724 submittal of updated environ qualification of
safety-related electrical equipment
MILLS, L M Tennessee Valley Authority 84/08/14 ADENSAM, E
Licensing Branch 4 47pp 26181 208 24X Fiche 50-390, 84/08/14,
8408210435

8408200275 Generic Ltr 84-20 to all licensees of operating reactors &
applicants for OLs re scheduling guidance for licensee
submittals of reloads that involve unreviewed safety
questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408290250 Forwards marked-up Table 3 4-1 indicating addl RCB pressure
isolation valves & corresponding functions, for use in
development of Unit 1 Tech Specs
MILLS, L M Tennessee Valley Authority 84/08/23 ADENSAM, E
Licensing Branch 4 4pp 26290 347 24X Fiche 50-390, 84/08/23,
8408290250

8408290355 Discusses results of radiological analysis Acceptance criteria specified by SRP 15 7 4 inappropriate for application to fuel handling accident Proposed mods to Tech Specs encl
MILLS,L M Tennessee Valley Authority 84/08/23 ADENSAM,E
Licensing Branch 4 8pp 26289 239 24X Fiche 50-390,84/08/23,
8408290355

F Security, medical, emergency & fire protection plans
---------- ----------

8408240360 Forwards Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Unresolved items identified in insp rept will be pursued during future insps
VERRELLI,D M Region 2, Office of Director 84/07/13 PARRIS,H G
Tennessee Valley Authority 2pp 26237 052 24X
Fiche 50-390,84/07/13,8408240360

--8408240362 Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Major areas inspected licensee action on previous enforcement items,permanent plant fire protection features & licensee identified items
MADDEN,P M , MILLER,W H , CONLON,T E Region 2, Office of Director 84/07/11 11pp 26237 054 24X Fiche 50-390,84/07/13, 8408240360

8408030032 Confirms that Westinghouse has completed review of listed power ascension & emergency procedures,per 810914 ltr Util reviewed Westinghouse comments & appropriate revs will be made before Unit 1 startup
MILLS,L M Tennessee Valley Authority 84/07/27 ADENSAM,E
Licensing Branch 4 2pp 25907 068 24X Fiche 50-390,84/07/27,
8408030032

8408300519 Confirms 840726 telcon re 840803 mgt meeting to discuss development & implementation of 10CFR50,App R program at Watts Bar & status of Sequoyah program
O'REILLY,J P Region 2, Office of Director 84/07/30 PARRIS,H G
Tennessee Valley Authority 2pp 26313 300 24X
Fiche 50-000,84/07/30,8408300519

8408070405 Forwards IE Insp Rept 50-390/84-54 on 840709-13 No violations or deviations noted
VERRELLI,D M Region 2, Office of Director 84/08/03 PARRIS,H G
Tennessee Valley Authority 2pp 25942 174 24X
Fiche 50-390,84/08/03,8408070405

--8408070409 IE Insp Rept 50-390/84-54 on 840709-13 No violations ordeviations noted Major areas inspected security plan & implementing procedures,security organization & physical barriers Details withheld (ref 10CFR2 790 & 73 21)
HALL,B L , MCGUIRE,D R Region 2, Office of Director 84/07/26
1p 25942 176 24X Fiche 50-390,84/08/03,8408070405

O Inspection reports, IE Bulletins & correspondence
---------- ----------

8408270417 Forwards Insp Repts 50-390/84-47 & 50-391/84-39 on 840619-22 No violations or deviations noted
VERRELLI,D M Region 2, Office of Director 84/07/09 PARRIS,H G
Tennessee Valley Authority 2pp 26256 348 24X
Fiche 50-390,84/07/09,8408270417

--8408270419 Insp Repts 50-390/84-47 & 50-391/84-39 on 840619-22 No violations or deviations noted Major areas inspected preoperational test results review,followup on previous enforcement items & plant tour
THOMAS,M , JAPE,F Region 2, Office of Director 84/07/03 3pp
26256 350 24X Fiche 50-390,84/07/09,8408270417

8408300353 Confirms 840706 telcon between R Shell & P Fredrickson re 840713 mgt meeting in Region II ofc to discuss implementation of IE Bulletin 79-02 concerning pipe support base plate designs using concrete expansion anchor bolts
LEWIS,R C Region 2, Office of Director 84/07/09 PARRIS,H G
Tennessee Valley Authority 1p 26314 149 24X
Fiche 50-390,84/07/09,8408300353

8408280030 Forwards Insp Rept 50-390/84-49 on 840619-22 No violations or deviations identified
VERRELLI,D M Region 2, Office of Director 84/07/11 PARRIS,H G
Tennessee Valley Authority 2pp 26282 009 24X
Fiche 50-390,84/07/11,8408280030

--8408280049 Insp Rept 50-390/84-49 on 840619-22 No violations or deviations noted Major areas inspected preoperational test performed after fuel load,review of proposed startup tests & review of preoperational tests of cranes
BURNETT,P T , JAPE,F Region 2, Office of Director 84/07/10
5pp 26282 011 24X Fiche 50-390,84/07/11,8408280030

8408240360 Forwards Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Unresolved items identified in insp rept will be pursued during future insps
VERRELLI,D M Region 2, Office of Director 84/07/13 PARRIS,H G
Tennessee Valley Authority 2pp 26237 052 24X
Fiche 50-390,84/07/13,8408240360

--8408240362 Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Major areas inspected licensee action on previous enforcement items,permanent plant fire protection features & licensee identified items
MADDEN,P M , MILLER,W H , CONLON,T E Region 2, Office of Director 84/07/11 11pp 26237 054 24X Fiche 50-390,84/07/13, 8408240360

8408270463 Forwards Insp Rept 50-390/84-48 on 840626-29 No violations or deviations identified
VERRELLI,D M Region 2, Office of Director 84/07/13 PARRIS,H G
Tennessee Valley Authority 2pp 26256 222 24X
Fiche 50-390,84/07/13,8408270463

--8408270469 Insp Rept 50-390/84-48 on 840626-29 No violations or deviations identified Major areas inspected safety-related pipe support & restraint sys & licensee action on previous enforcement matters
LIU,W C , YORK,J W , BLAKE,J J Region 2, Office of Director
84/07/12 6pp 26256 224 24X Fiche 50-390,84/07/13,8408270463

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408070405 Forwards IE Insp Rept 50-390/84-54 on 840709-13 No violations or deviations noted
VERRELLI,D M Region 2, Office of Director 84/08/03 PARRIS,H G
Tennessee Valley Authority 2pp 25942 174 24X
Fiche 50-390,84/08/03,8408070405

--8408070409 IE Insp Rept 50-390/84-54 on 840709-13 No violations ordeviations noted Major areas inspected security plan & implementing procedures,security organization & physical barriers Details withheld (ref 10CFR2 790 & 73 21)
HALL,B L , MCGUIRE,D R Region 2, Office of Director 84/07/26
1p 25942 176 24X Fiche 50-390,84/08/03,8408070405

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26069 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12Opp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408280215 Forwards QA Insp Rept 999000255/83-01 re defective capstan spring tangs in PSA-1 & PSA-3 mechanical snubbers mfg by Pacific Scientific Co Process requiring vendor to form spring before age hardening specified
ZECH, G C Vendor Program Branch 84/08/22 LEWIS, R C Division of Project & Resident Programs 6pp 26274 301 24X
Fiche 50-000, 84/08/22, 8408280215

S Reportable occurrences LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000, 84/03/13, 8408220317

8408090065 Final deficiency rept for Unit 1 & first interim deficiency rept for Unit 2 re RHR pump miniflow low flow rate Initially reported on 840618 Caused by design error Two 3 to 2-inch reducers & 2-inch control valves replaced
MILLS, L M Tennessee Valley Authority 84/07/18 O'REILLY, J P
Region 2, Office of Director 2pp 25992 143 24X
Fiche 50-390, 84/07/18, 8408090065

8408090078 First interim deficiency rept re thermal overload relay heater elements for fan motors failing to start Initially reported on 840622 Investigation continuing Next rept will be submitted by 840815
MILLS, L M Tennessee Valley Authority 84/07/20 O'REILLY, J P
Region 2, Office of Director 2pp 25992 360 24X
Fiche 50-390, 84/07/20, 8408090078

8408160173 Final deficiency rept re generic implication reviews for const projects Rev 4 to QAP 16 1 issued to more clearly define intra-ofc responsibility for determining generic implications of nonconformance
MILLS, L M Tennessee Valley Authority 84/07/24 O'REILLY, J P
Region 2, Office of Director 2pp 26108 045 24X
Fiche 50-000, 84/07/24, 8408160173

8408160154 Final deficiency rept for Unit 1 & third interim rept for Unit 2 re moisture intrusion into safety-related equipment Initially reported on 840229 Devices in Unit 1 sealed Next rept for Unit 2 will be submitted by 850124
MILLS, L M Tennessee Valley Authority 84/07/27 O'REILLY, J P
Region 2, Office of Director 2pp 26108 065 24X
Fiche 50-390, 84/07/27, 8408160154

8408030023 PNO-II-84-045 on 840729, senior resident inspector W Swan fatally injured in traffic accident Funeral svcs held 840801 in Athens, TN
JULIAN, C A , VERRELLI, D M Region 2, Office of Director 84/07/30
1p 25907 086 24X Fiche 50-390, 84/07/30, 8408030023

8408160179 Final deficiency rept re retrievability of QA records Initially reported on 840301 QA procedures revised on 840608 to incorporate handling requirements for supplier QC records
MILLS, L M Tennessee Valley Authority 84/08/01 O'REILLY, J P
Region 2, Office of Director 2pp 26108 042 24X
Fiche 50-000, 84/08/01, 8408160179

V Operator Examinations

8408300378 Forwards summary of 840405 meeting w/util in Region II ofc re individual candidate licensing requirements & cold license candidate training program
LEWIS, R C Region 2, Office of Director 84/05/08 PARRIS, H G
Tennessee Valley Authority 3pp 26308 261 24X
Fiche 50-390, 84/05/08, 8408300378

8408300354 Confirms 840803 conversation between WT Cattle & DM Verrelli re 840808 mgt meeting in Region II ofc to discuss results of operator licensing exams
LEWIS, R C Region 2, Office of Director 84/08/07 PARRIS, H G
Tennessee Valley Authority 1p 26314 221 24X
Fiche 50-390, 84/08/07, 8408300354

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8408010172 Forwards updated environ info re electrical equipment qualification Evaluation assessing addl equipment qualification in progress & info will be provided by 840803, for review
MILLS, L M Tennessee Valley Authority 84/07/24 ADENSAM, E
Licensing Branch 4 178Opp 25875 168 24X Fiche 50-390, 84/07/24, 8408010172

8408030128 Requests meeting to discuss proposed mod to draft App A Tech Specs Mod changes Tech Specs to increase allowable RCS isolation valve leakage from current draft Tech Spec limitation of 1 gpm to 9 gpm
MILLS, L M Tennessee Valley Authority 84/07/27 ADENSAM, E
Licensing Branch 4 2pp 25916 123 24X Fiche 50-390, 84/07/27, 8408030128

8408130375 Forwards summary rept of util intent to use addl diesel generator, including info re design & const of diesel generator & associated structure
MILLS, L M Tennessee Valley Authority 84/07/30 O'REILLY, J P
Region 2, Office of Director 2pp 26010 305 24X
Fiche 50-390, 84/07/30, 8408130375

8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification
WIGGINTON, D L Operating Reactors Branch 1 84/07/30 Operating Reactors Branch 1 4pp 26143 265 24X Fiche 50-000, 84/07/30, 8408160425

8408090428 Notification of 840807-08 meetings w/util in Bethesda, MD to discuss util comments on Tech Specs
KENYON, T J Licensing Branch 4 84/08/03 ADENSAM, E G Licensing Branch 4 3pp 25984 302 24X Fiche 50-390, 84/08/03, 8408090428

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408130275 Forwards "Reactor Bldg Containment Integrated Leak Rate Test, Suppl," conducted on 830519-20 Info fulfills 830818 commitment & completes requirement to provide summary rept to NRC re leak rate testing
MILLS, L M Tennessee Valley Authority 84/08/07 ADENSAM, E
Licensing Branch 4 1p 26008 272 24X Fiche 50-390, 84/08/07, 8408130275

--8408130280 "Reactor Bldg Containment Integrated Leak Rate Test, Suppl, conducted on 830519-20
* Tennessee Valley Authority 84/08/07 9pp 26008 273 24X
Fiche 50-390, 84/08/07, 8408130275

8408210435 Forwards environ qualification of nonsafety-related equipment, per 10CFR50 49(b)(2), for incorporation into 840724 submittal of updated environ qualification of safety-related electrical equipment
MILLS, L M Tennessee Valley Authority 84/08/14 ADENSAM, E
Licensing Branch 4 47pp 26181 208 24X Fiche 50-390, 84/08/14, 8408210435

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408290250 Forwards marked-up Table 3 4-1 indicating addl RCS pressure isolation valves & corresponding functions, for use in development of Unit 1 Tech Specs
MILLS, L M Tennessee Valley Authority 84/08/23 ADENSAM, E
Licensing Branch 4 4pp 26290 347 24X Fiche 50-390, 84/08/23, 8408290250

8408290355 Discusses results of radiological analysis Acceptance criteria specified by SRP 15 7 4 inappropriate for application to fuel handling accident Proposed mods to Tech Specs encl
MILLS,L M Tennessee Valley Authority 84/08/23 ADENSAM,E Licensing Branch 4 8pp 26289 239 24X Fiche 50-390,84/08/23, 8408290355

F Security, medical, emergency & fire protection plans

8408240360 Forwards Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Unresolved items identified in insp rept will be pursued during future insps
VERRELLI,D M Region 2, Office of Director 84/07/13 PARRIS,H G Tennessee Valley Authority 2pp 26237 052 24X
Fiche 50-390,84/07/13,8408240360

--8408240362 Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Major areas inspected licensee action on previous enforcement items,permanent plant fire protection features & licensee identified items
MADDEN,P M Region 2, Office of Director 84/07/11 11pp 26237 054 24X Fiche 50-390,84/07/13,8408240360

8408030032 Confirms that Westinghouse has completed review of listed power ascension & emergency procedures,per B10914 ltr Util reviewed Westinghouse comments & appropriate revs will be made before Unit 1 startup
MILLS,L M Tennessee Valley Authority 84/07/27 ADENSAM,E Licensing Branch 4 2pp 25907 068 24X Fiche 50-390,84/07/27, 8408030032

8408300519 Confirms 840726 telcon re 840803 mgt meeting to discuss development & implementation of 10CFR50,App R program at Watts Bar & status of Sequoyah program
O'REILLY,J P Region 2, Office of Director 84/07/30 PARRIS,H G Tennessee Valley Authority 2pp 26313 300 24X
Fiche 50-000,84/07/30,8408300519

Q Inspection reports, IE Bulletins & correspondence

8408270417 Forwards Insp Repts 50-390/84-47 & 50-391/84-39 on 840619-22 No violations or deviations noted
VERRELLI,D M Region 2, Office of Director 84/07/09 PARRIS,H G Tennessee Valley Authority 2pp 26256 348 24X
Fiche 50-390,84/07/09,8408270417

--8408270419 Insp Repts 50-390/84-47 & 50-391/84-39 on 840619-22 No violations or deviations noted Major areas inspected preoperational test results review,followup on previous enforcement items & plant tour
THOMAS,M , JAPE,F Region 2, Office of Director 84/07/03 3pp 26256 350 24X Fiche 50-390,84/07/09,8408270417

8408300353 Confirms 840706 telcon between R Shell & P Fredrickson re 840713 mgt meeting in Region II ofc to discuss implementation of IE Bulletin 79-02 concerning pipe support base plate designs using concrete expansion anchor bolts
LEWIS,R C Region 2, Office of Director 84/07/09 PARRIS,H G Tennessee Valley Authority 1p 26314 149 24X
Fiche 50-390,84/07/09,8408300353

8408240360 Forwards Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Unresolved items identified in insp rept will be pursued during future insps
VERRELLI,D M Region 2, Office of Director 84/07/13 PARRIS,H G Tennessee Valley Authority 2pp 26237 052 24X
Fiche 50-390,84/07/13,8408240360

--8408240362 Insp Repts 50-390/84-46 & 50-391/84-38 on 840619-22 No violations or deviations noted Major areas inspected licensee action on previous enforcement items,permanent plant fire protection features & licensee identified items
MADDEN,P M , MILLER,W H , CONLON,T E Region 2, Office of Director 84/07/11 11pp 26237 054 24X Fiche 50-390,84/07/13, 8408240360

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142

8408280215 Forwards QA Insp Rept 999000255/83-01 re defective capstan spring tangs in PSA-1 & PSA-3 mechanical snubbers mfg by Pacific Scientific Co Process requiring vendor to form spring before age hardening specified
ZECH,G G Vendor Program Branch 84/08/22 LEWIS,R C Division of Project & Resident Programs 6pp 26274 301 24X
Fiche 50-000,84/08/22,8408280215

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317

8408090065 Final deficiency rept for Unit 1 & first interim deficiency rept for Unit 2 re RHR pump miniflow low flow rate Initially reported on 840618 Caused by design error Two 3 to 2-inch reducers & 2-inch control valves replaced
MILLS,L M Tennessee Valley Authority 84/07/18 O'REILLY,J P Region 2, Office of Director 2pp 25992 143 24X
Fiche 50-390,84/07/18,8408090065

8408090078 First interim deficiency rept re thermal overload relay heater elements for fan motors failing to start Initially reported on 840622 Investigation continuing Next rept will be submitted by 840815
MILLS,L M Tennessee Valley Authority 84/07/20 O'REILLY,J P Region 2, Office of Director 2pp 25992 360 24X
Fiche 50-390,84/07/20,8408090078

8408160173 Final deficiency rept re generic implication reviews for const projects Rev 4 to QAP 16 1 issued to more clearly define intra-ofc responsibility for determining generic implications of nonconformance
MILLS,L M Tennessee Valley Authority 84/07/24 O'REILLY,J P
Region 2, Office of Director 2pp 26108 045 24X
Fiche 50-000,84/07/24,8408160173

8408160154 Final deficiency rept for Unit 1 & third interim rept for Unit 2 re moisture intrusion into safety-related equipment Initially reported on 840229 Devices in Unit 1 sealed Next rept for Unit 2 will be submitted by 850124
MILLS,L M Tennessee Valley Authority 84/07/27 O'REILLY,J P
Region 2, Office of Director 2pp 26108 065 24X
Fiche 50-390,84/07/27 8108160154

8408030023 PNO-II-84-045 on 840729,senior resident inspector W Swan fatally injured in traffic accident Funeral svcs held 840801 in Athens,TN
JULIAN,C A , VERRELLI,D M Region 2, Office of Director 84/07/30
ltr 25907 086 24X Fiche 50-390,84/07/30,8408030023

8408160179 Final deficiency rept re retrievability of QA records Initially reported on 840301 QA procedures revised on 840608 to incorporate handling requirements for supplier QC records
MILLS,L M Tennessee Valley Authority 84/08/01 O'REILLY,J P
Region 2, Office of Director 2pp 26108 042 24X
Fiche 50-000,84/08/01,8408160179

DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8408100002 Forwards emergency operating procedure generation package,in response to requirements of Generic Ltr 82-33, "Suppl 1 to NUREG-0737 - Requirements for Emergency Response Capability," Section 7
DIXON,D W South Carolina Electric & Gas Co 84/07/30 DENTON,H R
Office of Nuclear Reactor Regulation, Director 11pp 25989 310
24X Fiche 50-395,84/07/30,8408100002

--8408100012 Rev 0 to Station Administrative Procedure SAP-207, "Development of Emergency Operating Procedure "
* South Carolina Electric & Gas Co 84/04/02 77pp 25989 321
24X Fiche 50-395,84/07/30,8108100002

8408130194 Forwards IE Insp Rept 50-395/84-19 on 840723-27 No violations or deviations noted
VERRELLI,D M Region 2, Office of Director 84/08/07 DIXON,D W
South Carolina Electric & Gas Co 2pp 26008 294 24X
Fiche 50-395,84/08/07,8408130194

--8408130204 IE Insp Rept 50-395/84-19 on 840723-27 No violations or deviations noted Major areas inspected security organization,security program audit & physical barriers Details withheld (ref 10CFR2 790 & 73 21)
ENNIS,J D , MCGUIRE,D R Region 2, Office of Director 84/08/03
ltr 26008 296 24X Fiche 50-395,84/08/07,8408130194

8408130364 Revs to emergency plan procedures, including EPP-002, "Communication & Notifications," EPP-003, "In-Plant Radiological Surveying" & EPP-004, "Out-of-Plant Radiological Surveying " W/840809 ltr
DIXON,D W South Carolina Electric & Gas Co 84/08/09
O'REILLY,J P Region 2, Office of Director 299pp 26005 001 24X
Fiche 50-395,84/08/09,8408130364

K Utility Final Safety Analysis Report (FSAR) & amends

8408080187 Forwards updated FSAR for VC Summer,incorporating all procedure changes,safety evaluations & license amends
DIXON,D W South Carolina Electric & Gas Co 84/08/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 26012 001
24X Fiche 50-395,84/08/02,8408080187

--8408080192 Updated FSAR for VC Summer
* South Carolina Electric & Gas Co 84/08/02 6,388pp
26012 004 24X Fiche 50-395,84/08/02,8408080187

--8408080196 Chapter 1 to VC Summer updated FSAR, "Introduction & General Description of Plant "
* South Carolina Electric & Gas Co 84/08/02 213pp 26012 005
24X Fiche 50-395,84/08/02,8408080187

--8408080200 Chapter 2 to VC Summer updated FSAR, "Site Characteristics "
* South Carolina Electric & Gas Co 84/08/02 1,315pp
26012 218 24X Fiche 50-395,84/08/02,8408080187

--8408080207 Chapter 3 to VC Summer updated FSAR, "Design of Structures, Components,Equipment & Sys "
* South Carolina Electric & Gas Co 84/08/02 1,201pp
26016 089 24X Fiche 50-395,84/08/02,8408080187

--8408080214 Chapter 4 to VC Summer updated FSAR, "Reactor "
* South Carolina Electric & Gas Co 84/08/02 289pp 26019 210
24X Fiche 50-395,84/08/02,8408080187

--8408080221 Chapter 5 to VC Summer updated FSAR, "RCS & Connected Sys
* South Carolina Electric & Gas Co 84/08/02 313pp 26020 139
24X Fiche 50-395,84/08/02,8408080187

--8408080226 Chapter 6 to VC Summer updated FSAR, "ESF "
* South Carolina Electric & Gas Co 84/08/02 609pp 26021 092
24X Fiche 50-395,84/08/02,8408080187

--8408080228 Chapter 7 to VC Summer updated FSAR, "Instrumentation & Controls "
* South Carolina Electric & Gas Co 84/08/02 328pp 26022 337
24X Fiche 50-395,84/08/02,8408080187

--8408080232 Chapter 8 to VC Summer updated FSAR, "Electric Power "
* South Carolina Electric & Gas Co 84/08/02 251pp 26023 305
24X Fiche 50-395,84/08/02,8408080187

--8408080237 Chapter 9 to VC Summer updated FSAR, "Auxiliary Sys "
* South Carolina Electric & Gas Co 84/08/02 486pp 26024 196
24X Fiche 50-395,84/08/02,8408080187

--8408080240 Chapter 10 to VC Summer updated FSAR, "Steam & Power Conversion Sys "
* South Carolina Electric & Gas Co 84/08/02 163pp 26025 322
24X Fiche 50-395,84/08/02,8408080187

--8408080244 Chapter 11 to VC Summer updated FSAR, "Radwaste Mgt "
* South Carolina Electric & Gas Co 84/08/02 208pp 26026 125
24X Fiche 50-395,84/08/02,8408080187

--8408080248 Chapter 12 to VC Summer updated FSAR, "Radiation Protection "
* South Carolina Electric & Gas Co 84/08/02 227pp 26026 333
24X Fiche 50-395,84/08/02,8408080187

--8408080251 Chapter 13 to VC Summer updated FSAR, "Conduct of Operations "
* South Carolina Electric & Gas Co 84/08/02 101pp 26027 200
24X Fiche 50-395,84/08/02,8408080187

--8408080254 Chapter 14 to VC Summer updated FSAR, "Initial Tests & Operation "
* South Carolina Electric & Gas Co 84/08/02 101pp 26027 313
24X Fiche 50-395,84/08/02,8408080187

--8408080260 Chapter 15 to VC Summer updated FSAR, "Accident Analyses "
* South Carolina Electric & Gas Co 84/08/02 437pp 26028 102
24X Fiche 50-395,84/08/02,8408080187

--8408080262 Chapter 16 to VC Summer updated FSAR, "Tech Specs "
* South Carolina Electric & Gas Co 84/08/02 101pp 26029 179
24X Fiche 50-395,84/08/02,8408080187

--8408080265 Chapter 17 to VC Summer updated FSAR, "QA "
* South Carolina Electric & Gas Co 84/08/02 101pp 26029 180
24X Fiche 50-395,84/08/02,8408080187

P Operating license stage documents & correspondence

8408060103 Advises that 820929 summary of analysis to justify continuing operation w/thermal sleeves removed from selected nozzles in RCS sufficient to meet requirements of License Condition 2 C 7
DIXON,D W South Carolina Electric & Gas Co 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 25933 180
24X Fiche 50-395,84/07/31,8408060103

8408060140 Submits response to NRC question re effect of extended burnup fuel in postulated fuel handling accident outlined in Section 15 7 4 of SRP,as result of review of proposal to rerack spent fuel pool
DIXON,D W South Carolina Electric & Gas Co 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 25932 248
24X Fiche 50-395,84/07/31,8408060140

8408070373 Submits addl analysis & clarifications re spent fuel pool rerack structural mods, in response to concerns raised at 840725 meeting
DIXON, O W South Carolina Electric & Gas Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 25947 171
24X Fiche 50-395, 84/07/31, 8408070373

8408060134 Requests relief from ASME Code, Section XI hydrostatic testing requirements for feedwater sys Relief needed to support baffle-plate insp performed during refueling outage currently scheduled for Sept 1984 Fee encl
DIXON, O W South Carolina Electric & Gas Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 26067 056
24X Fiche 50-395, 84/08/01, 8408060134

8408080124 Forwards updated FSAR Pages 12 1-72, 13 1-17, 13 1-18, 13 1-19 & 13 1-20 FSAR updated as of 840301, to include facility or procedure changes, licensee performed safety evaluations & analyses of new safety issues
DIXON, O W South Carolina Electric & Gas Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 26276 270
24X Fiche 50-395, 84/08/02, 8408080124

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408140265 Forwards response to NRC request for addl numerical analysis to support info contained in 840731 ltr re effect of increased fuel burnup on fuel handling accident Requests NRC resolution so Sept 1984 refueling schedule can be met
DIXON, O W South Carolina Electric & Gas Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 26055 339
24X Fiche 50-395, 84/08/08, 8408140265

8408220427 Summary of 840725 meeting w/util & J Oat Corp in Bethesda, MD re structural analysis performed for rerack of spent fuel pool
HOPKINS, J Licensing Branch 4 84/08/15 Licensing Branch 4
78pp 26211 001 24X Fiche 50-395, 84/08/15, 8408220427

8408240002 Clarifies present fuel storage capabilities using high density racks, per 840123 application to amend License NPF-12 to modify spent fuel pool rerack Mod would accommodate higher initial enrichment
DIXON, O W South Carolina Electric & Gas Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26228 254
24X Fiche 50-395, 84/08/17, 8408240002

8200275 Generic Ltr 84-20 to all licensees of operating reactors & pplicants for OLs re scheduling guidance for licensee ubmittals of reloads that involve unreviewed safety uestions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

408280104 Application for amend to License NPF-12, revising Tech Spec Tables 2 2-1 & 3 3-4 re reactor trip sys instrumentation trip setpoints & ESF actuation sys instrumentation trip setpoints, respectively Fee paid
DIXON, O W South Carolina Electric & Gas Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26259 056
24X Fiche 50-395, 84/08/24, 8408280104

--8408280114 Proposed Tech Specs, revising Tables 2 2-1 & 3 3-4 re reactor trip sys instrumentation trip setpoints & ESF actuation sys instrumentation trip setpoints, respectively
* South Carolina Electric & Gas Co 84/08/24 3pp 26259 058
24X Fiche 50-395, 84/08/24, 8408280104

O Inspection reports, IE Bulletins & correspondence

8408280287 Responds to IE Bulletin 84-02, "Failure of GE Type HFA Relays in Use in Class 1E Sarety Sys " Switchgear relays replaced w/GE Century Series HFA relays Failure potential of other safety-related relays reviewed
DIXON, O W South Carolina Electric & Gas Co 84/07/09
O'REILLY, J P Region 2, Office of Director 3pp 26274 332 24X
Fiche 50-395, 84/07/09, 8408280287

8408270561 Forwards Insp Rept 50-395/84-20 on 840601-30 No violations or deviations identified
VERRELLI, D M Region 3, Office of Director 84/07/23 DIXON, O W
South Carolina Electric & Gas Co 2pp 26256 103 24X
Fiche 50-395, 84/07/23, 8408270561

--8408270572 Insp Rept 50-395 61-20 on 840601-30 No violations or deviations identified Major areas inspected operational safety verification, monthly surveillance & maint observations, followup items, design mods & training
HEHL, C W , BENIS, P , CANTRELL, F S Region 2, Office of Director
84/07/20 9pp 26256 105 24X Fiche 50-395, 84/07/23, 8408270561

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408060134 Requests relief from ASME Code, Section XI hydrostatic testing requirements for feedwater sys Relief needed to support baffle-plate insp performed during refueling outage currently scheduled for Sept 1984 Fee encl
DIXON, O W South Carolina Electric & Gas Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 26067 056
24X Fiche 50-395, 84/08/01, 8408060134

8408070402 Forwards changes to valve inservice insp program Non-ASME Code valves added to program as Category B valves Relief request to perform stroke testing of valves during cold shutdown in lieu of quarterly encl
DIXON, O W South Carolina Electric & Gas Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 25942 184
24X Fiche 50-395, 84/08/02, 8408070402

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408130194 Forwards IE Insp Rept 50-395/84-19 on 840723-27 No violations or deviations noted
VERRELLI, D M Region 2, Office of Director 84/08/07 DIXON, O W
South Carolina Electric & Gas Co 2pp 26008 294 24X
Fiche 50-395, 84/08/07, 8408130194

--8408130204 IE Insp Rept 50-395/84-19 on 840723-27 No violations or deviations noted Major areas inspected security organization, security program audit & physical barriers Details withheld (ref 10CFR2 790 & 73 21)
ENNIS, J D , MCGUIRE, D R Region 2, Office of Director 84/08/03
1p 26008 296 24X Fiche 50-395, 84/08/07, 8408130194

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408270168 Ack receipt of 840724 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-395/84-12
VERRELLI, D M Division of Project & Resident Programs 84/08/10
DIXON, O W South Carolina Electric & Gas Co 1p 26257 306 24X
Fiche 50-395, 84/08/10, 8408270168

--8408270174 Responds to NRC 840629 ltr re violations noted in Insp Rept 50-395/84-12 Corrective actions Area Radiation Monitors RMG-2, 3 & 12 included in preventive maint program & calibr completed
DIXON, O W South Carolina Electric & Gas Co 84/07/24
O'REILLY, J P Region 2, Office of Director 2pp 26257 307 24X
Fiche 50-395, 84/08/10, 8408270168

--8408270178 Forwards Insp Rept 50-395/84-12 on 840501-31 & notice of deviation
VERRELLI, D M Division of Project & Resident Programs 84/08/29
DIXON, O W South Carolina Electric & Gas Co 2pp 26257 309
24X Fiche 50-395, 84/08/10, 8408270168

--8408270182 Notice of deviation from insp on 840501-31
* Region 2, Office of Director 84/08/29 1p 26257 311 24X
Fiche 50-395, 84/08/10, 8408270168

DOCKETED ITEMS

--8408270187 Insp Rept 50-395/84-12 on 840501-31 Deviation noted failure to incorporate area radiation monitors in routine calibr program
HEHL, C W , CANTRELL, F Region 2, Office of Director 84/06/27
10pp 26257 312 24X Fiche 50-395,84/08/10,8408270168

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8408090143 Special Rept SPR 84-010 on 831204, grooves found etched into copper recording plates of seismic instrument IYM 01789 by diamond stylus Caused by vibration of pressurizer surge line piping Instrument relocated
DIXON, O W South Carolina Electric & Gas Co 84/07/16
O'REILLY, J P Region 2, Office of Director 2pp 25993 163 24X Fiche 50-395,84/07/16,8408090143

8408090241 NPDES noncompliance notification on 840725, total suspended solids for Discharge Points 005 & 010 exceeded 45-mg/P limit Caused by loss of power to aerator at Point 005 & clogged aerator diffuser at Point 010 Conditions corrected
DIXON, O W South Carolina Electric & Gas Co 84/08/01 STANLEY, A South Carolina, State of 2pp 25994 285 24X Fiche 50-395,84/08/01,8408090241

8408130340 Special Rept SPR 84-011 on 840703 & 11, invalid failures experienced on diesel generator XEG-0001A, unit A Caused by high jacket water temp resulting from control valve malfunction Cooling sys drained, disassembled & cleaned
DIXON, O W South Carolina Electric & Gas Co 84/08/02
O'REILLY, J P Region 2, Office of Director 3pp 26010 320 24X Fiche 50-395,84/08/02,8408130340

8408200340 LER 84-029-00 on 840713, three speed & transfer switch hinge stud assemblies on svc water pump torqued to recommended valve failed, Util contacting Brown Boveri for corrective action W/840810 ltr
CLARK, N E , DIXON, O W South Carolina Electric & Gas Co 84/08/10
3pp 26139 130 24X Fiche 50-395,84/08/10,8408200340

8408200344 LER 84-030 00 on 840421, ESF cooling unit 1DB found w/o coil V-brace structural member Coil V-brace installed on 840418 W/840810 ltr
CLARK, N E , DIXON, O W South Carolina Electric & Gas Co 84/08/10
3pp 26139 120 24X Fiche 50-395,84/08/10,8408200344

8408230507 LER 84-031-00 on 840717, seven electrical circuits identified that penetrate containment which are not included in Tech Spec Table 3 8-1 Surveillance satisfactory Plant mod to install overcurrent protection initiated W/840816 ltr
KOON, A R , DIXON, O W South Carolina Electric & Gas Co 84/08/16
2pp 26212 274 24X Fiche 50-395,84/08/16,8408230507

8408300514 LER 84-034-00 on 840724 discovered that Electrical Maint Procedure 300 012, "Agastat Relay Replacement," did not require delay time calibr of relays in installed position Related event on 840821 Procedure revised W/840823 ltr
KOON, A R , DIXON, O W South Carolina Electric & Gas Co 84/08/23
5pp 26313 343 24X Fiche 50-395,84/08/23,8408300514

V Operator Examinations

8408170308 Forwards instruction lesson plans for simulator training fo senior reactor operators & reactor operator candidates re accidents analysis/assessment training & simulator training
DIXON, O W South Carolina Electric & Gas Co 84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26113 057
24X Fiche 50-395,84/08/10,8408170308

--8408170313 "Instructor Lesson Plan Simulator Training For Senior Reactor Operators Operating Practices Training, Accident Analysis/Assessment Training "
* South Carolina Electric & Gas Co 84/05/18 36pp 26113 058
24X Fiche 50-395,84/08/10,8408170308

--8408170318 "Instructor Lesson Plan Simulator Training for Reactor Operators "
* South Carolina Electric & Gas Co 84/07/18 240pp 26113 094
24X Fiche 50-395,84/08/10,8408170308

DOCKET 50-396 UNIV OF VIRGINIA CAVALIER REACTOR

F Security, medical, emergency & fire protection plans

8408010391 Forwards revised emergency plan, incorporated addl info, per request Info should resolve plan prior deficiencies Univ of Virginia reactor safety committee will review plan Approval expected
MULDER, R W Virginia, Univ of, Charlottesville, VA 84/07/12
THOMAS, C O Standardization & Special Projects Branch 1p
25866 063 24X Fiche 50-062,84/07/12,8408010391

8408010350 Resubmits 840712 request for approval of emergency plan Ltr notarized per request Univ of Virginia reactor safety committee reviewed & approved emergency plan on 840725
MULDER, R W Virginia, Univ of, Charlottesville, VA 84/07/26
THOMAS, C O Standardization & Special Projects Branch 1p
25866 307 24X Fiche 50-062,84/07/26,8408010350

P Operating license stage documents & correspondence

8408060445 Forwards notice of consideration of renewal of License R-123 for 20 yrs from issuance date, based on 840622 application
THOMAS, C O Standardization & Special Projects Branch 84/07/24
MULDER, R W Virginia, Univ of, Charlottesville, VA 3pp
25937 095 24X Fiche 50-396,84/07/24,8408060445

--8408070011 Notice of consideration of application for renewal of License R-123 for 20 yrs from date of issuance
THOMAS, C O Standardization & Special Projects Branch 84/07/24
4pp 25937 098 24X Fiche 50-396,84/07/24,8408060445

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

F Security, medical, emergency & fire protection plans

8408080119 Advises that 840515 revs to guard training & qualification plan consistent w/provisions of 10CFR50 54(p) & acceptable
SCHUSTER, M D Region 5, Office of Director 84/08/03
SORENSEN, G C Washington Public Power Supply System 2pp
25964 361 24X Fiche 50-397,84/08/03,8408080119

P Operating license stage documents & correspondence

8408090262 Forwards emergency operating procedures generation package requested at mgt meeting re 840716 insp Guidelines will be used for addl verification of response to TMI Item I C 1 re development of procedures for transients & accidents
SORENSEN, G C Washington Public Power Supply System 84/07/26
BISHOP, T W Region 5, Office of Director 1p 25994 204 24X
Fiche 50-397,84/07/26,8408090262

8408090407 Forwards Amend 3 to License NPF-21, safety evaluation, notice of environ assessment & exemption Amend changes Tech Spec Special Test Requirement 3 10 5 to allow suspension of containment inerting during test program
SCHWENCER, A Licensing Branch 2 84/07/27 SORENSEN, G C
Washington Public Power Supply System 2pp 25984 310 24X
Fiche 50-397,84/07/27,8408090407

--8408090409 Exemption from requirements of 10CFR50 44, allowing continued operation w/nonmetd containment during balance of initial startup test program
EISENHUT, D G Division of Licensing 84/07/26 Washington Public Power Supply System 5pp 25984 312 24X
Fiche 50-397, 84/07/27, 8408090407

--8408090410 Amend 3 to License NPF-21, changing Tech Spec Special Test Requirement 3 10 5 to allow suspension of containment inerting during power ascension test program
SCHWENCER, A Licensing Branch 2 84/07/27 4pp 25984 317 24X
Fiche 50-397, 84/07/27, 8408090407

--8408090412 Safety evaluation supporting Amend 3 to License NPF-21
* Office of Nuclear Reactor Regulation, Director 84/07/26 5pp 25984 321 24X Fiche 50-397, 84/07/27, 8408090407

--8408090414 Notice of environ assessment & finding of no significant impact re Amend 3 to License NPF-21
EISENHUT, D G Division of Licensing 84/07/19 5pp 25984 326 24X Fiche 50-397, 84/07/27, 8408090407

8408070325 Forwards fee for review of util 840717 application re enhancement of control room floor
SORENSEN, G C Washington Public Power Supply System 84/08/01
SCHWENCER, A Licensing Branch 2 1p 25945 237 24X
Fiche 50-397, 84/08/01, 8408070325

8408070333 Requests confirmation of CRGR review re specific uncertainties conservatively treated in GE instrument setpoint methodology for BWRs Concern should be treated as generic
SORENSEN, G C Washington Public Power Supply System 84/08/02
SCHWENCER, A Licensing Branch 2 3pp 25945 189 24X
Fiche 50-397, 84/08/02, 8408070333

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408280339 Forwards request for addl info re safety parameter display sys Response requested within 60 days of ltr receipt
SCHWENCER, A Licensing Branch 2 84/08/10 SORENSEN, G C
Washington Public Power Supply System 5pp 26294 043 24X
Fiche 50-397, 84/08/10, 8408280339

8408270498 Forwards Amend 4 to License NPF-21 & safety evaluation Amend modifies Tech Specs as listed
SCHWENCER, A Licensing Branch 2 84/08/14 SORENSEN, G C
Washington Public Power Supply System 3pp 26277 042 24X
Fiche 50-397, 84/08/14, 8408270498

--8408270501 Amend 4 to License NPF-21, changing Tech Specs editorial & procedural content
SCHWENCER, A Licensing Branch 2 84/08/13 12pp 26277 045 24X Fiche 50-397, 84/08/14, 8408270498.

--8408270506 Safety evaluation supporting Amend 4 to License NPF-21
* Office of Nuclear Reactor Regulation, Director 84/08/14 4pp 26277 057 24X Fiche 50-397, 84/08/14, 8408270498

8408270073 Application to amend License NPF-21, revising Condition 2 C(11) re shield wall deferral Change would allow ongoing ALARA reviews to identify need for addl shielding
SORENSEN, G C Washington Public Power Supply System 84/08/15,
SCHWENCER, A Licensing Branch 2 5pp 26247 183 24X
Fiche. 50-397, 84/08/15, 8408270073

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408270153 Concurs w/clarification re piping failures outside primary containment, allowing credit for offsite power to mitigate consequences of pipe failure causing scram or turbine trip Offsite power assumed lost when undervoltage occurs
SORENSEN, G C Washington Public Power Supply System 84/08/20
SCHWENCER, A Licensing Branch 2 1p 26245 153. 24X
Fiche 50-397, 84/08/20, 8408270153

G Inspection reports, IE Bulletins & correspondence

8408090016 Forwards IE Insp Rept 50-397/84-15 on 840529-0608 No violations noted Weaknesses or opportunities for improvements observed Assessment of observations requested within 30 days
BISHOP, T W Region 5, Office of Director 84/07/24 SORENSEN, G C
Washington Public Power Supply System 2pp 25995 001 24X
Fiche 50-397, 84/07/24, 8408090016

--8408090019 IE Insp Rept 50-397/84-15 on 840529-0608 No violations noted Major areas inspected operating crews, awareness of plant/sys status & adherence to procedures & administrative controls Identified weaknesses listed
WILLETT, D J , JOHNSON, A D , WAITE, R Region 5, Office of Director 84/07/24 8pp 25995 003 24X Fiche 50-397, 84/07/24, 8408090016

8408070247 Responds to NRC 840629 ltr re violations noted in IE Insp Rept 50-397/84-13 Corrective actions specific instructions provided to operating crews to ensure airlock operation performed per regulatory requirements
SORENSEN, G C Washington Public Power Supply System 84/07/26
BISHOP, T W Region 5, Office of Director 4pp 25949 020 24X
Fiche 50-397, 84/07/26, 8408070247

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408300446 Forwards Insp Rept 50-397/84-18 on 840606-0706 & notice of violation
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/08/07 SORENSEN, G C Washington Public Power Supply System 2pp 26314 098 24X Fiche 50-397, 84/08/07, 8408300446

--8408300451 Notice of violation from insp on 840606-0706
DODDS, R T Region 5, Office of Director 84/08/07 2pp 26314 100 24X Fiche 50-397, 84/08/07, 8408300446

--8408300464 Insp Rept 50-397/84-18 on 840606-0706 Noncompliance noted shift manager not notified prior to installation & removal of jumpers & prompt corrective action not taken re malfunctions & deficiencies in ECCS logic
TOTH, A D , WAITE, R S , DODDS, R T Region 5, Office of Director 84/07/27 25pp 26314 102 24X Fiche 50-397, 84/08/07, 8408300446

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

DOCKETED ITEMS

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408290168 Ack receipt of 840726 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-397/84-13 Reply disagrees w/citation re undocumented approval of clearance order based on mgt purposes & intentions
BISHOP, T W Region 5, Office of Director 84/08/24 SORENSEN, G C
Washington Public Power Supply System 1p 26291 302 24X
Fiche 50-397, 84/08/24, 8408290168

R Periodic operating reports & related correspondence

8406070192 Monthly operating rept for Apr 1984 W/840515 ltr
COWAN, K D , MARTIN, J D Washington Public Power Supply System
84/04/30 4pp 24747 050 24X Fiche 50-397, 84/04/30, 8406070192

8408280320 "Semiannual Effluent Rept, Jan-June 1984 " W/840816 ltr
MARTIN, J D Washington Public Power Supply System 84/06/30
MARTIN, J B Region 5, Office of Director 56pp 26282 279. 24X
Fiche 50-397, 84/06/30, 8408280320

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd)
84/03/13 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000, 84/03/13, 8408220317

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD, G G General Electric Co 84/04/13 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp
26222 256 24X Fiche 50-000, 84/04/13, 8408240348

8408030280 LER 84-034-01 on 840703, drywell temp monitor CMS-TI-55 indicated temps above 150 F in upper drywell area return duct for over 8 h Initially identified in 840511 LER
No corrective action initiated W/840726 ltr
POWERS, C M , MARTIN, J D Washington Public Power Supply System
84/07/26 3pp 25917 259 24X Fiche 50-397, 84/07/26, 8408030280

8408060233 LER 84-072-00 on 840705-06, reactor water cleanup sys (RWCU) isolations occurred Caused by erroneous RWCU high delta flow trips Reactor vessel transmitter replaced & blowdown flow transmitter sensing lines refilled & vented W/840726 ltr
POWERS, C M , MARTIN, J D Washington Public Power Supply System
84/07/26 3pp 25935 135 24X Fiche 50-397, 84/07/26, 8408060233

8408060235 LER 84-061-01 on 840614, open floor drain found on 522-ft elevation of reactor bldg Plant walkdown revealed two other drains Fire watches instituted Drains will be piped into floor drain sys & not sealed as first planned W/840726 ltr
POWERS, C M , MARTIN, J D Washington Public Power Supply System
84/07/26 3pp 25935 144 24X Fiche 50-397, 84/07/26, 8408060235

8408060301 LER 84-071-00 on 840716, loss of power to portion of failsafe relaying resulted in 1/2 RDP containment isolation
Caused by inadvertent shorting of reactor protection sys branch circuit Containment isolation reset W/840726 ltr
POWERS, C M , MARTIN, J D Washington Public Power Supply System
84/07/26 3pp, 25936 041 24X Fiche 50-397, 84/07/26, 8408060301

8408070135 PNS-V-84-012 on 840727, routine safety patrol discovered suspicious-looking device near control room Device determined not explosive Technician identified device as electrical test equipment
SCHWAN, C A , SCHUSTER, M D Region 5, Office of Director 84/07/30
1p 25949 342 24X Fiche 50-397, 84/07/30, 8408070135

8408090443 LER 84-075-00 on 840709 & 13, standby diesel generator 1B incurred high vibration alarm Caused by slip ring end bearing turning on shaft insulation Bearing insulation modified W/840802 ltr
KOENIGS, R L , MARTIN, J D Washington Public Power Supply System
84/08/02 4pp 25993 232 24X Fiche 50-397, 84/08/02, 8408090443

8408090450 LER 84-074-00 on 840712, results of sample from radwaste tan EDR-TK-4B inadvertently recorded on EDR-TK-9 data sheet & EDR-TK-9 released Caused by contractor error Discharge stopped Procedure for tank release modified W/840802 ltr
KOENIGS, R L , MARTIN, J D Washington Public Power Supply System
84/08/02 3pp 25993 221 24X Fiche 50-397, 84/08/02, 8408090450

8408090458 LER 84-073-00 on 840308, spurious hi chlorine alarm from WDA-SR-15 caused control room emergency filtration sys to auto start Caused by component failure in electronics module on chlorine analyzer Alarm reset W/840802 ltr
KOENIGS, R L , MARTIN, J D Washington Public Power Supply System
84/08/02 3pp 25993 214 24X Fiche 50-397, 84/08/02, 8408090458

8408200132 LER 84-076-00 on 840728, during declaration of unusual event subsequent to finding possible bomb, hourly fire watch tour not performed Tours resumed immediately upon termination of unusual event status Only one tour missed W/840808 ltr
KOENIGS, R L , MARTIN, J D Washington Public Power Supply System
84/08/08 3pp 26139 117 24X Fiche 50-397, 84/08/08, 8408200132

8408200341 LER 84-077-00 on 840720 & 21, control room emergency filtration unit automatically actuated, Caused by spikes on corresponding control room outside air radiation monitor Emergency filtration unit reset W/840808 ltr
KOENIGS, R L , MARTIN, J D Washington Public Power Supply System
84/08/08 3pp 26139 123 24X Fiche 50-397, 84/08/08, 8408200341

8408170369 PNO-V-84-049 on 840812, unusual event declared when prairie brush fire led to potential for loss of offsite 230-kV startup powerlines & 115-kV backup power lines Plant diesel generators started as contingency
TOTH, A D , DODDS, R T Region 5, Office of Director 84/08/13 1p
26112 358 24X Fiche 50-397, 84/08/13, 8408170369

8408290036 PNO-V-84-053 on 840822, thermal transient occurred in reactor feedwater sys downstream of high pressure feedwater heaters 6A & 6B Transient caused pipe hanger & support damage resulting in leakage of approx 20 gallons water
DODDS, R T , TOTH, A D Region 5, Office of Director 84/08/23 1p
26291 213 24X Fiche 50-397, 84/08/23, 8408290036

8408290017 LER 84-034-02 on 840804, drywell temp monitor CMS-TI-55 indicated temps above 150 F in upper drywell area return duct Cause not stated Mods to design of drywell heating & ventilation being completed W/840824 ltr
KOENIGS, R L , MARTIN, J D Washington Public Power Supply System
84/08/24 3pp 26291 270 24X Fiche 50-397, 84/08/24, 8408290017

8408290024 LER 84-080-00 on 840801, turbine stop valve closure reactor trip occurred as result of pressurizing turbine first-stage shell above 30% power Plant recovered per Operating Procedure PPM 3 3 1 W/840824 ltr
KOENIGS, R L , MARTIN, J D Washington Public Power Supply System
84/08/24 3pp 26291 267 24X Fiche 50-397, 84/08/24, 8408290024

8408290030 LER 84-079-00 on 840809, reactor scram occurred automatically on low reactor water level after reactor feed water pump tripped due to loss of control power Reactor water level restored using RCIC sys W/840824 ltr
KOENIGS, R L , MARTIN, J D Washington Public Power Supply System
84/08/24 3pp 26291 214 24X Fiche 50-397, 84/08/24, 8408290030

8408290116 LER 84-078-00, on 840801, 07 & 08, control room emergency filtration units automatically actuated Caused by spikes on corresponding control room outside air radiation monitors Filtration units & radiation monitors reset W/840824 ltr.
KOENIGS, R L , MARTIN, J D Washington Public Power Supply System
84/08/24 3pp 26291 286 24X Fiche 50-397, 84/08/24, 8408290116

8408290143 LER 84-072-01 on 840705 & 06, reactor water cleanup sys (RWCU) isolations occurred Caused by erroneous reactor water cleanup sys high delta flow trips Isolation signals reset & RWCU returned to svc W/840824 ltr
POWERS, C M , MARTIN, J D Washington Public Power Supply System
84/08/24 4pp 26291 209 24X Fiche 50-397, 84/08/24, 8408290143

U Congressional/Executive Correspondence

8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far
ASSELSTINE, J K Commissioners 84/08/10 MARKEY, E J House of Rep , Interior & Insular Affairs 4pp 26141 244 24X
Fiche 50-000, 84/08/10, 8408200225

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8408020012 Forwards info in response to Eddleman Contention 9 re environ qualification program FSAR will be amended to provide description of program
WATSON, R A Carolina Power & Light Co 84/07/25 DENTON, H R
Office of Nuclear Reactor Regulation, Director 15pp 25883 100
24X Fiche 50-400, 84/07/25, 8408020012

8408060192 Forwards "Class IE Equipment Environ Qualification Master List," containing safety-related equipment in locations w/total integrated dose greater than stated rads
ZIMMERMAN, S R Carolina Power & Light Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25930 268 24X
Fiche 50-400, 84/07/27, 8408060192

--8408060196 "Class IE Equipment Environ Qualification Master List "
* Carolina Power & Light Co 84/07/27 588pp 25930 269 24X
Fiche 50-400, 84/07/27, 8408060192

8408080271 Submits restatement of cold license training program to meet NRC guidance for combined observation/simulator training, in response to Generic Ltr 84-10 Request for exemption from 10CFR55 25(b) will be submitted
ZIMMERMAN, S R Carolina Power & Light Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 25966 289
24X Fiche 50-400, 84/07/27, 8408080271

8408060257 Forwards marked-up Tech Specs, based on Rev 4 to NUREG-0452, "STS for Westinghouse Pressurized Reactors " Offsite dose calculation manual will be submitted by 840831 Future submittals will address listed subjs
CUTTER, A B Carolina Power & Light Co 84/07/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 636pp 25924 001
24X Fiche 50-400, 84/07/30, 8408060257

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda, MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH, B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 130 24X Fiche 50-000, 84/07/31, 8408090497

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408230364 Notification of 840817 meeting w/util in Bethesda, MD to discuss functional capability of Class 1 auxiliary piping sys
BUCKLEY, B Licensing Branch 3 84/08/06 KNIGHTON, G W Licensing
Branch 3 4pp 26230 354 24X Fiche 50-400, 84/08/06, 8408230364

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408280207 Clarifies 840725 response to Eddleman Contention 9 re environ qualification program Response to 9B refs verification performed by onsite QA organization Commitment to ensure required equipment installed not diminished
ZIMMERMAN, S R Carolina Power & Light Co 84/08/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26279 191 24X
Fiche 50-400, 84/08/24, 8408280207

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408070381 Forwards Amend 16 to FSAR, describing environ qualification program & providing addl info re SER Open Item 5
MCDUFFIE, M A Carolina Power & Light Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25947 085 24X
Fiche 50-400, 84/07/27, 8408070381

--8408070384 Amend 16 to FSAR
* Carolina Power & Light Co 84/07/27 71pp 25947 086 24X
Fiche 50-400, 84/07/27, 8408070381

8408080285 Forwards replacement pages for emergency planning public info brochure, in response to SER Open Item 12 Pages correct minor editorial errors
ZIMMERMAN, S R Carolina Power & Light Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25965 325
24X Fiche 50-400, 84/07/27 8408080285

8408080337 Forwards addl info re turbine bldg vent radiation monitors, in response to SER Confirmatory Item 26, identified by Meteorological & Effluent Treatment Sys Branch
ZIMMERMAN, S R Carolina Power & Light Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 25964 078
24X Fiche 50-400, 84/07/27, 8408080337

F Security, medical, emergency & fire protection plans

8408080285 Forwards replacement pages for emergency planning public info brochure, in response to SER Open Item 12 Pages correct minor editorial errors
ZIMMERMAN, S R Carolina Power & Light Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25965 325
24X Fiche 50-400, 84/07/27, 8408080285

8408090473 Notification of 840814 meeting w/util in Bethesda, MD to discuss resolution of emergency preparedness issues
BUCKLEY, B Licensing Branch 3 84/07/27 KNIGHTON, G W Licensing
Branch 3 4pp 25983 174 24X Fiche 50-400, 84/07/27, 8408090473

8408280026 Forwards Insp Rept 50-400/84-20 on 840709-12 No violations or deviations identified
VERRELLI, D M Region 2, Office of Director 84/07/27 UTLEY, E E
Carolina Power & Light Co 2pp 26281 344 24X
Fiche 50-400, 84/07/27, 8408280026

--8408280028 Insp Rept 50-400/84-20 on 840709-12 No violations or deviations noted Major areas inspected fire protection
WISEMAN, G R , CONLON, T E Region 2, Office of Director 84/07/24
4pp 26281 346 24X Fiche 50-400, 84/07/27, 8408280026

8408150137 Forwards NRC comments on design evaluation rept program plan elements for detailed control room design review, including info re control room inventory & selection of design improvements Response by 850101 requested
KNIGHTON, G W Licensing Branch 3 84/08/01 UTLEY, E E Carolina
Power & Light Co 11pp 26104 203 24X Fiche 50-400, 84/08/01, 8408150137

--8404230171 Audit rept, "Human Factors Engineering Detailed Control Room Design Review In-Progress Audit "
ELAYAT, H Laurence Livermore National Laboratory 84/03/28
33pp 26104 214 24X Fiche 50-400, 84/08/01, 8408150137

8408300297 Confirms 840802 telcon between DB Waters & PR Bemis re 840809 mgt meeting in Atlanta, GA to discuss emergency plans, action levels & emergency operating procedures
LEWIS, R C Region 2, Office of Director 84/08/07 UTLEY, E E
Carolina Power & Light Co 1p 26306 353 24X
Fiche 50-400, 84/08/07, 8408300297

8408240316 Forwards SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
LEWIS, R C Region 2, Office of Director 84/08/21 UTLEY, E E
Carolina Power & Light Co 2pp 26225 230 24X
Fiche 50-000, 84/08/21, 8408240316

--8408240319 SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-18 for Feb 1983 - Apr 1984
* Region 2, Office of Director 84/04/30 71pp 26225 232 24X
Fiche 50-000, 84/08/21, 8408240316

O Adjudicatory correspondence

8408160128 Forwards NRC staff Exhibits 1-3 & Intervenor Exhibit 1 Related correspondence
RILEY, S L Taylor Associates 84/06/25 PLEASANT, C
Administrative & Logistical Support Branch 1p 26126 167 24X
Fiche 50-400, 84/06/25, 8408160128

8408010264 Joint Intervenors findings of fact on Joint Contentions II(a) re concentration of radionuclides through interaction w/fine particles & II(c) re calculations of radiological doses from normal releases Certificate of Svc encl
RUNKLE, J Joint Intervenors - Shearon Harris DSB 655 84/07/24
13pp 25854 056 24X Fiche 50-400, 84/07/24, 8408010264

DOCKETED ITEMS

8408030070 Response opposing applicant motion for reconsideration or clarification of Joint Contention IV Certificate of Svc encl
EDDLEMAN,W Eddleman, W EDDLEMAN,W Joint Intervenors - Shearon Harris DSB 727 84/07/30 BRIGHT,G O , CARPENTER,J H , KELLEY,J L Atomic Safety and Licensing Board Panel 6pp 25904 295 24X Fiche 50-400,84/07/30,8408030070

8408020054 Provides requested info re schedule for testing & insps of two TDI diesel generators for standby emergency power Operational testing scheduled for Last Quarter 1984 & early 1985 Svc list encl Related correspondence
O'NEILL,J H Shaw, Pittman, Potts & Trowbridge O'NEILL,J H Carolina Power & Light Co DSB 700 84/07/31 KELLY,J L , BRIGHT,G O , CARPENTER,J H Atomic Safety and Licensing Board Panel 5pp 25891 330 24X Fiche 50-400,84/07/31,8408020054

8408070397 Response in support of applicant 840718 motion for reconsideration or clarification of ASLB 840413 memorandum & order on Joint Contention IV Certificate of Svc encl
MOORE,J E Hearing Branch 1 DSB 811 84/07/31 Atomic Safety and Licensing Board Panel 9pp 25942 237 24X
Fiche 50-400,84/07/31,8408070397

8408070459 Informs of agreement to negotiate w/applicant counsel D Hollar re adequacy of various responses in applicant 840725 discovery responses on emergency planning, including document identification Related correspondence
EDDLEMAN,W Eddleman, W DSB 762 84/08/01 KELLEY,J Atomic Safety and Licensing Board Panel 1p 25940 295 24X
Fiche 50-400,84/08/01,8408070459

8408090224 Informs that NRC consultant T Urbanik will not be available until 840813 to respond to interrogatories re Contentions 215 & 224 Related correspondence
BARTH,C A Hearing Branch 1 DSB 865 84/08/01 EDDLEMAN,W Eddleman, W 1p 25971 243 24X Fiche 50-400,84/08/01,8408090224

8408070293 Order providing final set of rulings on admissibility of offsite emergency planning contentions, ruling on petition for waiver of need for power rule & notice of upcoming telcon call Served on 840806
BRIGHT,G O , CARPENTER,J H , KELLEY,J L Atomic Safety and Licensing Board Panel DSB 771 84/08/03 62pp 25948 011 24X
Fiche 50-400,84/08/03,8408070293

8408090170 Further response to 840329 interrogatories re Joint Intervenor Contention 1 concerning mgt qualifications Affidavits of FS Cantrell & PR Bemis & Certificate of Svc encl Related correspondence
BARTH,C A Hearing Branch 1 DSB 866 84/08/03 Atomic Safety and Licensing Board Panel 43pp 25973 129 24X
Fiche 50-400,84/08/03,8408090170

8408090455 Response to applicant motion to establish procedure for requesting extensions of time Certificate of Svc encl
RUNKLE,J Conservation Council of North Carolina DSB 884 84/08/09 Atomic Safety and Licensing Board Panel 3pp 25982-224 24X Fiche 50-400,84/08/05,8408090455

8408080217 Proposed findings of fact in reply to proposed findings of fact & conclusions of law submitted by W Eddleman on Contention 8F(1) & by Joint Intervenors on joint Contentions II(E) & (G) Certificate of Svc encl
BAUSER,D B Carolina Power & Light Co BAUSER,D B Shaw, Pittman, Potts & Trowbridge DSB 821 84/08/06 10pp 25967 053 24X
Fiche 50-400,84/08/06,8408080217

8408090172 Reply findings re Eddleman Contention 8F(1) & Joint Contention II(e) & II(c) Eddleman proposed Findings 11 & 14 & portions of Joint Intervenor Findings 8,9,22 & 27 should not be adopted Certificate of Svc encl
MOORE,J E Hearing Branch 1 DSB 864 84/08/06 Atomic Safety and Licensing Board Panel 7pp 25973 010 24X
Fiche 50-400,84/08/06,8408090172

8408130288 Supplemental answer to Eddleman Interrogatory 57-C-10-3(a)-(d) requesting identification of all documents, methodologies, data, equations, calculations & info Certificate of Svc encl Related correspondence
HOLLAR,D E Carolina Power & Light Co DSB 904 84/08/08 Eddleman, W 6pp 26009 356. 24X Fiche 50-400,84/08/08,8408130288

8408140002 Proposed Eddleman exhibits on Contention 116 re fire protection Certificate of Svc encl
EDDLEMAN,W Eddleman, W DSB 943 84/08/09 33pp 26052 304 24X Fiche 50-400,84/08/09,8408140002

8408140004 First set of emergency planning interrogatories & request for production of documents Certificate of Svc encl, Related correspondence
RIDGWAY,D A Carolina Power & Light Co RIDGWAY,D A Shaw, Pittman, Potts & Trowbridge. DSB 945 84/08/09 Wilson, R 11pp 26050 322 24X Fiche 50-400,84/08/09,8408140004

8408140008 First set of emergency planning interrogatories & request for production of documents Certificate of Svc encl Related correspondence
RIDGWAY,D A Carolina Power & Light Co RIDGWAY,D A Shaw, Pittman, Potts & Trowbridge DSB 947 84/08/09 Conservation Council of North Carolina 14pp 26044 064 24X
Fiche 50-400,84/08/09,8408140008

8408140022 First set of emergency planning interrogatories & request for production of documents Certificate of Svc encl Related correspondence
RIDGWAY,D A Carolina Power & Light Co RIDGWAY,D A Shaw, Pittman, Potts & Trowbridge DSB 949 84/08/09 Chapel Hill Anti-Nuclear Group Effort 21pp 26044 168 24X
Fiche 50-400,84/08/09,8408140022

8408140048 First set of emergency planning interrogatories & request for production of documents Certificate of Svc encl Related correspondence
RIDGWAY,D A Carolina Power & Light Co RIDGWAY,D A Shaw, Pittman, Potts & Trowbridge DSB 946 84/08/09 Joint Intervenors - Shearon Harris 16pp 26044 209 24X
Fiche 50-400,84/08/09,8408140048

8408140057 First set of emergency planning interrogatories & request for production of documents Certificate of Svc encl Related correspondence
RIDGWAY,D A Carolina Power & Light Co RIDGWAY,D A Shaw, Pittman, Potts & Trowbridge DSB 948 84/08/09 Eddleman, W 27pp 26060 216 24X Fiche 50-400,84/08/09,8408140057

8408140119 Notice of documents relied upon & previously served as testimony in chief & case in chief of joint Contention I re mgt & Contention 65 Related correspondence
EDDLEMAN,W Eddleman, W DSB 942 84/08/09 Atomic Safety and Licensing Board Panel 2pp 26051 259 24X Fiche 50-400,84/08/09,8408140119

--8408140122 Fifth set of interrogatories. Related correspondence
EDDLEMAN,W Eddleman, W 84/08/09 Office of the Executive Legal Director 12pp 26051 260 24X Fiche 50-400,84/08/09,8408140119

--8408140125 Tenth set of general interrogatories Related correspondence
EDDLEMAN,W Eddleman, W 84/08/09 Carolina Power & Light Co 119pp 26051 272 24X Fiche 50-400,84/08/09,8408140119

8408160105 Eddleman contentions on emergency plan brochure, "Safety Info for Shearon Harris Nuclear Power Plant " Certificate of Svc encl
EDDLEMAN,W Eddleman, W DSB 077 84/08/10 Atomic Safety and Licensing Board Panel 750pp 26086 001. 24X Fiche 50-400, 84/08/10,8408160105

8408280186 Affidavit of BJ Furr stating that answers to Interrogatory 57-C-10-3(a) - (d) correct & true to best of info & knowledge Notice of appearance of EM Roach & Certificate of Svc encl
FURR,B J Carolina Power & Light Co DSB 321 84/08/13 4pp 26279 199 24X Fiche 50-400,84/08/13,8408280186

8408200490 Forwards FEMA responses to 840629 interrogatories Certificate of Svc encl Related correspondence
MOORE,J E Hearing Branch 1 DSB 174 84/08/14 EDDLEMAN,W Eddleman, W 3pp 26136 321 24X Fiche 50-400,84/08/14,8408200490

--8408200497 Response to interrogatories propounded by intervenor W Eddleman Related correspondence
HAWKINS,T I , ROCHLIS,S M Federal Emergency Management Agency. 84/08/07 EDDLEMAN,W Eddleman, W 31pp 26136-324 24X
Fiche 50-400,84/08/14,8408200490

8408200498 Forwards subpoena forms for listed witnesses not called by util & NRC re Contentions 41 & 65 Subpoenas should be issued under provisions of 10CFR2 790 W/o forms Certificate of Svc encl Related correspondence
EDDLEMAN,W Eddleman, W DSB 145 84/08/17 3pp 26136 355 24X
Fiche 50-400,84/08/17,8408200498

8408210323 Request for subpoenas for listed witnesses on joint Contention I re mgt capability Certificate of Svc encl Related correspondence.
RUNCKLE,J Joint Intervenors - Shearon Harris DSB 181. 84/08/17 Atomic Safety and Licensing Board Panel 4pp 26179 132 24X
Fiche 50-400,84/08/17,8408210323

8408270122 Forwards SER re TDI Diesel Generator Owners Group program plan Rept discussed during 840810 conference call Related correspondence
MOORE,J E Hearing Branch 1 DSB 308 84/08/21 KELLEY,J L , CARPENTER,J H , BRIGHT,G O Atomic Safety and Licensing Board Panel 30pp 26248 002 24X Fiche 50-400,84/08/21,8408270122

8408230160 Notice of evidentiary hearing on Joint Contention 1, commencing on 840905 in Raleigh, NC Served on 840822
KELLEY, J L Atomic Safety and Licensing Board Panel DSB 210
84/08/22 Office of the Executive Legal Director 1p 26209 298
24X Fiche 50-400, 84/08/22, 8408230160

8408280439 Forwards SALP rept for 800701-811231 & NRC Manual Chapter NRC-0516 Page 9 of Clewitt prefiled testimony refers to SALP rept Figures on Page 9 of Clewitt attachment came from Page 2 of rept Related correspondence
BARTH, C A Hearing Branch 1 DSB 342 84/08/22 PAYNE, T
Affiliation Not Assigned 1p 26280 295 24X Fiche 50-400, 84/08/22, 8408280439

J Insurance & indemnity information

8408210027 Forwards Endorsements 1-5 to NELIA Policy NF-288
BARHAM, C D Carolina Power & Light Co 84/08/15 SALTZMAN, J
Assistant Director for State & Licensee Relations 13pp 26181 351
24X Fiche 50-400, 84/08/15, 8408210027

K Utility Final Safety Analysis Report (FSAR) & amends

8408070381 Forwards Amend 16 to FSAR, describing environ qualification program & providing addl info re SER Open Item 5
MCDUFFIE, M A Carolina Power & Light Co 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25947 085 24X
Fiche 50-400, 84/07/27, 8408070381

--8408070384 Amend 16 to FSAR
* Carolina Power & Light Co 84/07/27 71pp 25947 086 24X
Fiche 50-400, 84/07/27, 8408070381

8408090509 Forwards affidavit certifying distribution of Amend 16 to FSAR on 840727
ZIMMERMAN, S R Carolina Power & Light Co 84/08/02 EISENHUT, D G
Division of Licensing 4pp 25993 012 24X Fiche 50-400, 84/08/02, 8408090509

O Inspection reports, IE Bulletins & correspondence

8408300347 Acl receipt of 831110 supplemental ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-400/83-29
LEWIS, R C Division of Project & Resident Programs 84/06/08
UTLEY, E E Carolina Power & Light Co 1p 26308 350 24X
Fiche 50-400, 84/06/08, 8408300347

-8408300350 Provides addl response to NRC 831110 ltr re violations noted in Insp Rept 50-400/83-29 Corrective actions procedure for control of non-ASME bolting matls will be implemented by mid-June
PARSONS, R M Carolina Power & Light Co 84/06/01 O'REILLY, J P
Region 2, Office of Director 2pp 26308 351 24X
Fiche 50-400, 84/06/08, 8408300347

8408280088 Forwards Insp Rept 50-400/84-19 on 840710-13 No violations or deviations identified
VERRELLI, D M Region 2, Office of Director 84/07/24 UTLEY, E E
Carolina Power & Light Co 2pp 26282 028 24X
Fiche 50-400, 84/07/24, 8408280088

--8408280091 Insp Rept 50-400/84-19 on 840710-13 No violations or deviations noted Major areas inspected action on previous enforcement matters, const progress, RCPD piping, visual exam, safety-related components & IE bulletins
KLEINSORGE, W P , BLAKE, J J Region 2, Office of Director
84/07/20 10pp 26282 030 24X Fiche 50-400, 84/07/24, 8408280088

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408280026 Forwards Insp Rept 50-400/84-20 on 840709-12 No violations or deviations identified
VERRELLI, D M Region 2, Office of Director 84/07/27 UTLEY, E E
Carolina Power & Light Co 2pp 26281 344 24X
Fiche 50-400, 84/07/27, 8408280026

--8408280028 Insp Rept 50-400/84-20 on 840709-12 No violations or deviations noted Major areas inspected fire protection
WISEMAN, G R , CONLON, T E Region 2, Office of Director. 84/07/24,
4pp 26281 346 24X Fiche 50-400, 84/07/27, 8408280026

8408010333 IE Info Notice 84-59, Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of RA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408280456 Acl receipt of 840726 supplemental response informing NRC of steps taken to correct violations noted in Insp Repts 50-400/83-25, 50-400/83-26 & 50-400/83-29
LEWIS, R C Region 2, Office of Director 84/08/10 UTLEY, E E
Carolina Power & Light Co 1p 26282 141 24X
Fiche 50-400, 84/08/10, 8408280456

--8408280460 Responds to NRC 831019 ltr re violations noted in Insp Rept 50-400/83-25 Corrective actions evaluation performed to identify fasteners in motor control ctrs under scope of Reg Guide 1 29
PARSONS, R M Carolina Power & Light Co 84/07/26 O'REILLY, J P
Region 2, Office of Director 3pp 26282 142 24X
Fiche 50-400, 84/08/10, 8408280456

--8408280465 Responds to NRC 830922 ltr re violations noted in Insp Rept 50-400/83-26 Corrective actions implementation of FCR-P-1366 rerouted pipe & resolved interference problem
PARSONS, R M Carolina Power & Light Co 84/07/26 O'REILLY, J P
Region 2, Office of Director 3pp 26282 145 24X
Fiche 50-400, 84/08/10, 8408280456

--8408280469 Updates 840601 response to NRC 830922 ltr re violations noted in Insp Rept 50-400/83-29 Corrective actions site administrative procedure governing identification of bolting matl issued
PARSONS, R M Carolina Power & Light Co 84/07/25 O'REILLY, J P
Region 2, Office of Director 2pp 26282 148 24X
Fiche 50-400, 84/08/10, 8408280456

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408240316 Forwards SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-16 for Feb 1983 - Apr 1984
LEWIS, R C Region 2, Office of Director 84/08/21 UTLEY, E E
Carolina Power & Light Co 2pp 26225 230 24X
Fiche 50-000, 84/08/21, 8408240316

--8408240319 SALP Repts 50-261/84-24, 50-324/84-16, 50-325/84-16 & 50-400/84-16 for Feb 1983 - Apr 1984
* Region 2, Office of Director 84/04/30 71pp 26225 232 24X
Fiche 50-000, 84/08/21, 8408240316

8408280215 Forwards QA Insp Rept 999000255/83-01 re defective capstan spring tangs in PSA-1 & PSA-3 mechanical snubbers mfg by Pacific Scientific Co Process requiring vendor to form spring before age hardening specified
ZECH, G G Vendor Program Branch 84/08/22 LEWIS, R C Division of Project & Resident Programs 6pp 26274 301 24X
Fiche 50-000, 84/08/22, 8408280215

8408280439 Forwards SALP rept for 800701-811231 & NRC Manual Chapter NRC-0516 Page 9 of Clewitt prefiled testimony refers to SALP rept Figures on Page 9 of Clewitt attachment came from Page 2 of rept Related correspondence
BARTH, C A Hearing Branch 1 DSB 342 84/08/22 PAYNE, T
Affiliation Not Assigned 1p 26280 295 24X Fiche 50-400, 84/08/22, 8408280439

8408300243 Forwards responses to written & verbal questions raised by Equipment Qualification Branch reviewers during insp conducted on 840809 & 10
ZIMMERMAN, S R Carolina Power & Light Co 84/08/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 8pp 26300 129
24X Fiche 50-400, 84/08/24, 8408300243

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000, 84/05/24, 8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000, 84/05/24, 8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000, 84/05/24, 8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER, M Division of Licensing 158pp
25926 173 24X Fiche 50-000, 84/06/28, 8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER, C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000, 84/07/10, 8408060050

8408090291 Second interim deficiency rept, Item 162 re inadequate tack welds in fire barrier panels Initially reported on 840314 Sections of cable tray will be protected by covers by 850531 Final rept will be issued by 850531
PARSONS, R M Carolina Power & Light Co 84/07/11 O'REILLY, J P
Region 2, Office of Director 4pp 25994 032 24X
Fiche 50-400, 84/07/11, 8408090291

8408090018 Second interim deficiency rept, Item 160 re defective shop welds on seismic restraint structures Initially reported on 840306 Next rept anticipated by 850331
PARSONS, R M Carolina Power & Light Co 84/07/13 O'REILLY, J P
Region 2, Office of Director 4pp 25993 250 24X
Fiche 50-400, 84/07/13, 8408090018

8408090131 Interim deficiency & Part 21 repts, Item 178 re stainless steel sockolettes & weldolettes supplied by Guyon Alloys, Inc not in accordance w/NCA 3800 Initially reported on 840619 Next rept by 840915
PARSONS, R M Carolina Power & Light Co 84/07/16 O'REILLY, J P
Region 2, Office of Director 4pp 25994 320 24X
Fiche 50-400, 84/07/16, 8408090131

8408090031 Interim deficiency rept, Item 176 re Kerite Co single conductor power cables damaged, but undetected by insp & testing Initially reported on 840619 Final rept by 841215
PARSONS, R M Carolina Power & Light Co 84/07/19 O'REILLY, J P
Region 2, Office of Director 4pp 25992 251 24X
Fiche 50-400, 84/07/19, 8408090031

8408090066 Deficiency & Part 21 repts, Item 179 re Westinghouse not considering interaction scenario when postulating in-core flux mapping sys Initially reported on 840622 Reportability to be determined by 840930
PARSONS, R M Carolina Power & Light Co 84/07/19 O'REILLY, J P
Region 2, Office of Director 1p 25992 146 24X
Fiche 50-400, 84/07/19, 8408090066

8408160438 Interim deficiency rept, Item 175 re exceeding max bolt hardness values Initially reported on 840517 Corrective action & submission of final rept will be accomplished by 840926 Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 84/07/24 O'REILLY, J P
Region 2, Office of Director 4pp 26106 343 24X
Fiche 50-400, 84/07/24, 8408160438

8408160416 Interim deficiency rept, Item 180 re welds in emergency air cleaning units Initially reported on 840628 Analysis of weld connections underway Next rept will be submitted by 840628
PARSONS, R M Carolina Power & Light Co 84/07/25, O'REILLY, J P
Region 2, Office of Director 1p 26106 073 24X
Fiche 50-400, 84/07/25, 8408160416

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000, 84/07/27, 8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000, 84/07/27, 8408060102

8408160168 Fifth interim rept, Item 41 re potentially significant failure of reactor protection sys following high energy line rupture Initially reported on 800707 Steam generator ref legs will be insulated. Final rept to be issued 841002
PARSONS, R M Carolina Power & Light Co 84/07/30 O'REILLY, J P
Region 2, Office of Director 4pp 26108 056 24X
Fiche 50-400, 84/07/30, 8408160168

8408160408 Interim deficiency rept, Item 104 re defective welds on 480-volt switchgear, purchase order NY-435171 Initially reported on 830304 Major defective welds repaired Final rept will be submitted by 850401
PARSONS, R M Carolina Power & Light Co 84/07/30 O'REILLY, J P
Region 2, Office of Director 4pp 26106 126 24X
Fiche 50-400, 84/07/30, 8408160408

8408160443 Interim deficiency rept, Item 168 re 4.9-kV switchgear circuit breakers Initially reported on 840420 Corrective action & submission of final report will be accomplished by 841001 Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 84/07/30 O'REILLY, J P
Region 2, Office of Director 5pp 26107 268 24X
Fiche 50-400, 84/07/30, 8408160443

8408160437 Interim deficiency rept, Item 165 re reactor vessel support anchor bolt nuts Initially reported on 840312 Procedure TP-28 rewritten Corrective action & submission of final rept will be accomplished by 841002
PARSONS, R M Carolina Power & Light Co 84/07/31 O'REILLY, J P
Region 2, Office of Director 5pp 26106 347 24X
Fiche 50-400, 84/07/31, 8408160437

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000, 84/08/01, 8408060324

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche. 50-000, 84/08/10, 8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines, "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000, 84/08/10, 8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT, D G Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000, 84/08/13, 8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000, 84/08/13, 8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL, per NRC request
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000, 84/08/14, 8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000, 84/08/14, 8408160395

8408200196 Advises that item re possible linear type indications on surface of SA-500 Grade B matl pipe hangers mfg by Bergen Paterson closed w/o action Item considered not reportable per 10CFR50 55(e) & Part 21
ZECH, G G Vendor Program Branch 84/08/16 LEWIS, R C Region 2, Office of Director 1p 26133 068 24X Fiche 50-400, 84/08/16, 8408200196

8408210399 Informs that VITS 83-048 & 83-099 re possible defective welds in C&D battery racks closed w/o action based on util 830418 final rept Items not reportable per 10CFR50 55(e) or Part 21
ZECH, G G Vendor Program Branch 84/08/16 LEWIS, R C Region 2, Office of Director DANIELSON, D H Region 3, Office of Director
1p 26180 307 24X Fiche 50-400, 84/08/16, 8408210399

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER, C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000, 84/08/23, 8408290179

T Hearing transcripts on non-antitrust matters

8408140014 Forwards testimony & exhibits to be offered into evidence at hearings on safety contentions, to begin on 840905 & 1010
Related correspondence
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A
Carolina Power & Light Co DSB 950 84/08/09 KELLEY, J L ,
BRIGHT, G O , CARPENTER, J H Atomic Safety and Licensing Board Panel
3pp 26082 130 24X Fiche 50-400, 84/08/09, 8408140014

--8408140018 Testimony of MJ Hitchler on Joint Intervenor Contention VII (4) re steam generator tube rupture analysis Related correspondence
HITCHLER, M J Carolina Power & Light Co HITCHLER, M J
Westinghouse Electric Corp 84/08/09 Atomic Safety and Licensing Board Panel 27pp 26082 133. 24X
Fiche 50-400, 84/08/09, 8408140014

--8408140023 Testimony of JF Nevill, AG Fuller, DR Timberlake & KV Hate on Eddleman Contention 41 re pipe hanger welding Related correspondence
NEVILL, J F , FULLER, A G , TIMBERLAKE, D R Carolina Power & Light Co 84/08/09 Atomic Safety and Licensing Board Panel 35pp
26082 160 24X Fiche 50-400, 84/08/09, 8408140014

--8408140027 Testimony of GA Kanakaris, RM Parsons & LF Garner on Eddleman Contention 65 re concrete containment structure Related correspondence
KANAKARIS, G A , PARSONS, R M Carolina Power & Light Co
KANAKARIS, G A Ebasco Services, Inc (subs of Enserch Corp)
84/08/09 Atomic Safety and Licensing Board Panel 156pp
26082 195 24X Fiche 50-400, 84/08/09, 8408140014

--8408140031 Testimony of MA Serbanescu on Eddleman Contention 116 re fire protection Prof qualifications encl Related correspondence
SERBANESCU, M A Consumers Power Co SERBANESCU, M A Ebasco Services, Inc (subs of Enserch Corp) 84/08/09 Atomic Safety and Licensing Board Panel 42pp 26082 351 24X
Fiche 50-400, 84/08/09, 8408140014

--8408140036 Testimony of DB Waters on Eddleman Contention 116 re fire protection Related correspondence
WATERS, D B Carolina Power & Light Co 84/08/09 Atomic Safety and Licensing Board Panel 200pp 26083 031 24X
Fiche 50-400, 84/08/09, 8408140014

8408140064 Forwards listed NRC testimony on safety issues of hearings on 840905 & 1010 SER & SSER 1 Related correspondence
BARTH, C A Hearing Branch 1 DSB 941 84/08/09 KELLEY, J L ,
BRIGHT, G O , CARPENTER, J H Atomic Safety and Licensing Board Panel
2pp 26052 029 24X Fiche 50-400, 84/08/09, 8408140064

--8408140070 Testimony of PR Bemis on Joint Intervenor Contention 1 re mgt qualifications Related correspondence
BEMIS, P R Region 2, Office of Director 84/08/09 43pp
26052 031 24X Fiche 50-400, 84/08/09, 8408140064

--8408140075 Testimony of LB Marsh & HF Conrad re Joint Contention VII, Part (4) Prof qualifications encl Related correspondence
MARSH, L B Reactor Systems Branch CONRAD, H F Materials Engineering Branch 84/08/09 9pp 26052 074 24X
Fiche 50-400, 84/08/09, 8408140064

--8408140081 Testimony of PR Bemis, GA Hallstrom & JJ Blake on Eddleman Contention 41 re pipe hanger welds Related correspondence
BEMIS, P R , HALLSTROM, G A , BLAKE, J J Region 2, Office of Director 84/08/09 57pp 26052 083 24X Fiche 50-400, 84/08/09, 8408140064

--8408140086 Testimony of JR Harris, JJ Lenahan & PR Bemis on Eddleman Contention 65 re concrete placement Related correspondence
HARRIS, J R , LENAHAN, J J , BEMIS, P R Region 2, Office of Director 84/08/09 51pp 26052 140 24X Fiche 50-400, 84/08/09, 8408140064

--8408140093 Testimony of R Eberly & RL Ferguson on Eddleman Contention 116 re fire protection program Related correspondence
EBERLY, R , FERGUSON, R L Chemical Engineering Branch 84/08/09
74pp 26052 191 24X Fiche 50-400, 84/08/09, 8408140064

8408140146 Forwards joint testimony re Joint Intervenor Contention I concerning mgt capability FSAR sections, as exhibits, encl
Related correspondence
FLYNN, S F Carolina Power & Light Co DSB 956 84/08/09
KELLEY, J L , BRIGHT, G O , CARPENTER, J H Atomic Safety and Licensing Board Panel 2pp 26046 001 24X Fiche 50-400, 84/08/09, 8408140146

--8408140151 Joint testimony of EE Utley, MA McDuffie, T Elleman, HR Banks, PW Howe, CR Dietz, GP Beatty, RC Morgan, RA Watson, JL Willis, JM Davis & AW Powell on Joint Intervenor Contention I re mgt capability FSAR exhibits encl Related correspondence
UTLEY, E E , MCDUFFIE, M A , ELLEMAN, T S Carolina Power & Light Co
84/08/09 365pp 26046 003 24X Fiche 50-400, 84/08/09, 8408140146

8408140478 Testimony of J Clewett re joint Contention 1 Svc list encl Related correspondence
CLEWETT, J Joint Intervenors - Shearon Harris DSB 025 84/08/09
38pp 26060 294 24X Fiche 50-400, 84/08/09, 8408140478

8408140293 Transcript of 840810 telcon in Bethesda, MD w/util & North Carolina Eastern Municipal Power Agency Pp 2, 205-2, 277
* Atomic Safety and Licensing Board Panel 84/08/10 72pp
26043 073 24X Fiche 50-400, 84/08/10, 8408140293

8408300158 Transcript of 840827 hearing in Bethesda, MD Pp 2, 278-2, 345
* Atomic Safety and Licensing Board Panel 84/08/27 70pp
26305 221 24X Fiche 50-400, 84/08/27, 8408300158

V Operator Examinations

8408310014 Confirms 840605 telcon re 840612 mgt meeting in Region II ofcs to discuss upcoming operator exams & requalification of licensed operators following steam generator outage
O'REILLY, J P Region 2, Office of Director 84/06/08 UTLEY, E E
Carolina Power & Light Co 1p 26333 357 24X
Fiche 50-000, 84/06/08, 8408310014

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8408300297 Confirms 840802 telcon between DB Waters & PR Bemis re 840809 mgt meeting in Atlanta, GA to discuss emergency plans, action levels & emergency operating procedures
LEWIS, R C Region 2, Office of Director 84/08/07 UTLEY, E E
Carolina Power & Light Co 1p 26306 353 24X
Fiche: 50-400, 84/08/07, 8408300297

G Adjudicatory correspondence

8408160128 Forwards NRC staff Exhibits 1-3 & intervenor Exhibit 1 Related correspondence
RILEY, S L Tayloe Associates 84/06/25 PLEASANT, E Administrative & Logistical Support Branch 1p 26126 167 24X Fiche 50-400, 84/06/25, 8408160128

8408070397 Response in support of applicant 840718 motion for reconsideration or clarification of ASLB 840413 memorandum & order on Joint Contention 1V Certificate of Svc encl
MOORE, J E Hearing Branch 1 DSB 811 84/07/31 Atomic Safety and Licensing Board Panel 9pp 25942 237 24X Fiche 50-400, 84/07/31, 8408070397

8408090224 Informs that NRC consultant T Urbanik will not be available until 840813 to respond to interrogatories re Contentions 215 & 224 Related correspondence
BARTH, C A Hearing Branch 1 DSB 865 84/08/01 EDDLEMAN, W Eddleman, W 1p 25971 243 24X Fiche 50-400, 84/08/01, 8408090224

8408070293 Order providing final set of rulings on admissibility of offsite emergency planning contentions, ruling on petition for waiver of need for power rule & notice of upcoming telcon call Served on 840806
BRIGHT, G O , CARPENTER, J H , KELLEY, J L Atomic Safety and Licensing Board Panel DSB 771 84/08/03 62pp 25948 011 24X Fiche 50-400, 84/08/03, 8408070293

8408090170 Further response to 840329 interrogatories re Joint Intervenor Contention 1 concerning mgt qualifications Affidavits of FS Cantrell & PR Bemis & Certificate of Svc encl Related correspondence
BARTH, C A Hearing Branch 1 DSB 866 84/08/03 Atomic Safety and Licensing Board Panel 43pp 25973 129 24X Fiche 50-400, 84/08/03, 8408090170

8408090172 Reply findings re Eddleman Contention 8F(1) & Joint Contention II(b) & II(c) Eddleman proposed Findings 11 & 14 & portions of Joint Intervenor Findings 8, 9, 22 & 27 should not be adopted Certificate of Svc encl
MOORE, J E Hearing Branch 1 DSB 864 84/08/06 Atomic Safety and Licensing Board Panel 7pp 25973 010 24X Fiche 50-400, 84/08/06, 8408090172

8408200490 Forwards FEMA responses to 840629 interrogatories Certificate of Svc encl Related correspondence
MOORE, J E Hearing Branch 1 DSB 174 84/08/14 EDDLEMAN, W Eddleman, W 3pp 26135 321 24X Fiche 50-400, 84/08/14, 8408200490

--8408200497 Response to interrogatories propounded by intervenor W Eddleman Related correspondence
HAWKINS, T I , ROCHLIS, S M Federal Emergency Management Agency 84/08/07 EDDLEMAN, W Eddleman, W 31pp 26136 324 24X Fiche 50-400, 84/08/14, 8408200490

8408270122 Forwards SER re TDI Diesel Generator Owners Group program plan Rept discussed during 840810 conference call Related correspondence
MOORE, J E Hearing Branch 1 DSB 308 84/08/21 KELLEY, J L , CARPENTER, J H , BRIGHT, G O Atomic Safety and Licensing Board Panel 30pp 26248 002 24X Fiche 50-400, 84/08/21, 8408270122

8408230160 Notice of evidentiary hearing on Joint Contention 1, commencing on 840905 in Raleigh, NC Served on 840822
KELLEY, J L Atomic Safety and Licensing Board Panel DSB 210 84/08/22 Office of the Executive Legal Director 1p 26209 298 24X Fiche 50-400, 84/08/22, 8408230160

8408280439 Forwards SALP rept for 800701-811231 & NRC Manual Chapter NRC-0516 Page 9 of Clewitt prefiled testimony refers to SALP rept Figures on Page 9 of Clewitt attachment came from Page 2 of rept Related correspondence
BARTH, C A Hearing Branch 1 DSB 342 84/08/22 PAYNE, T Affiliation Not Assigned 1p 26280 295 24X Fiche 50-400, 84/08/22, 8408280439

G Inspection reports, IE Bulletins & correspondence

8408280215 Forwards QA Insp Rept 999000255/83-01 re defective capstan spring tangs in PSA-1 & PSA-3 mechanical snubbers mfg by Pacific Scientific Co Process requiring vendor to form spring before age hardening specified
ZECH, G G Vendor Program Branch 84/08/22 LEWIS, R C Division of Project & Resident Programs 6pp 26274 301 24X Fiche 50-000, 84/08/22, 8408280215

8408280439 Forwards SALP rept for 800701-811231 & NRC Manual Chapter NRC-0516 Page 9 of Clewitt prefiled testimony refers to SALP rept Figures on Page 9 of Clewitt attachment came from Page 2 of rept Related correspondence
BARTH, C A Hearing Branch 1 DSB 342 84/08/22 PAYNE, T Affiliation Not Assigned 1p 26280 295 24X Fiche 50-400, 84/08/22, 8408280439

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000, 84/05/24, 8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000, 84/05/24, 8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000, 84/05/24, 8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER, M Division of Licensing 158pp 25926 173 24X Fiche 50-000, 84/06/28, 8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group. 84/07/10 BERLINGER, C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000, 84/07/10, 8408060050

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000, 84/07/27, 8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000, 84/07/27, 8408060102

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24X Fiche 50-000, 84/08/01, 8408060324

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000, 84/08/10, 8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24X Fiche 50-000, 84/08/10, 8408160394

8408240115 Forwards SER re TDI Owners Group program plan. SER addresses design review/quality revalidation program; testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT, D G Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X Fiche 50-000, 84/08/13, 8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation; plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13. 21pp 26255 195 24X Fiche: 50-000, 84/08/13, 8408240115.

DOCKETED ITEMS

160395 Forwards "Design Review of Elliott Model 900 Turbocharger
ed on TDI DSR-48 & DSRV-16 Emergency Diesel Generator
ts," representing final QA verified rept Addl copy
rwarded to BNWL per NRC request
Y,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
NTON,H R Office of Nuclear Reactor Regulation, Director 2pp
088 163 24X Fiche 50-000,84/08/14,8408160395

08160397 "Design Review of Elliott Model 900 Turbocharger Used on
TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
- Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

210399 Informs that VITS 83-048 & 83-099 re possible defective
lds in C&D battery racks closed w/o action based on util
3418 final rept Items not reportable per 10CFR50 55(e) or
rt 21
2H,G G Vendor Program Branch 84/08/16 LEWIS,R C Region 2,
Fice of Director DANIELSON,D H Region 3, Office of Director
26180 307 24X Fiche 50-400,84/08/16,8408210399

290179 Forwards response to 840723 request for addl info on repts
mitted by TDI Diesel Generator Owners Group
/,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
LINGER,C Office of Nuclear Reactor Regulation, Director 12pp
289 221 24X Fiche 50-000,84/08/23,8408290179

'aring transcripts on non-antitrust matters
---------- ---- ----------

40064 Forwards listed NRC testimony on safety issues of hearings
840905 & 1010 SER & SSER 1 Related correspondence
ITH,C A Hearing Branch 1 DSB 941 84/08/09 KELLEY,J L ,
GHT,G O , CARPENTER,J M Atomic Safety and Licensing Board Panel
p 26052 029 24X Fiche 50-400,84/08/09,8408140064

8140070 Testimony of PR Bemis on Joint Intervenor Contention 1 re
gt qualifications Related correspondence
EMIS,P R Region 2, Office of Director 84/08/09 43pp
6052 031 24X Fiche 50-400,84/08/09,8408140064

8140075 Testimony of LB Marsh & HF Conrad re Joint Contention VII,
art (4) Prof qualifications encl Related correspondence
ARSH,L B Reactor Systems Branch CONRAD,H F Materials
ngineering Branch 84/08/09 9pp 26052 074 24X
iche 50-400,84/08/09,8408140064

8140081 Testimony of PR Bemis,GA Hallstrom & JJ Blake on Eddleman
ontention 41 re pipe hanger welds Related correspondence
EMIS,P R , HALLSTROM,G A , BLAKE,J J Region 2, Office of
irector 84/08/09 57pp 26052 083 24X Fiche 50-400,84/08/09,
408140064

8140086 Testimony of JR Harris,JJ Lenahan & PR Bemis on Eddleman
ntention 65 re concrete placement Related correspondence
RRIS,J R , LENAHAN,J J , BEMIS,P R Region 2, Office of
irector 84/08/09 51pp 26052 140 24X Fiche 50-400,84/08/09,
408140064

8140093 Testimony of R Eberly & RL Ferguson on Eddleman Contention
6 re fire protection program Related correspondence.
BERLY,R , FERGUSON,R L Chemical Engineering Branch 84/08/09
pp 26052 191 24X Fiche 50-400,84/08/09,8408140064

0478 Testimony of J Cleveit re Joint Contention 1 Svc list encl
ted correspondence
ETT,J Joint Intervenors - Shearon Harris DSB 025 84/08/09
26060 294 24X Fiche 50-400,84/08/09,8408140478

0293 Transcript of 840810 telcon in Bethesda,MD w/util & North
lina Eastern Municipal Power Agency Pp 2,205-2,277
omic Safety and Licensing Board Panel 84/08/10 72pp
3 073 24X Fiche 50-400,84/08/10,8408140293

0158 Transcript of 840827 hearing in Bethesda,MD Pp 2,278-2,345
omic Safety and Licensing Board Panel 84/08/27. 70pp
221 24X Fiche 50-400,84/08/27,8408300158

'ator Examinations
---------- -

0014 Confirms 840605 telcon re 840612 mgt meeting in Region II
to discuss upcoming operator exams & requalification of
sed operators following steam generator outage
LLY,J P Region 2, Office of Director 84/06/08 UTLEY,E E
ina Power & Light Co 1p 26333 357 24X
50-000,84/06/08,8408310014

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR
---------- -- ----- --- - ------- ----------

F Security, medical, emergency & fire protection plans
---------- ---- ---------- ----- ---

8408010297 Forwards IE Insp Rept 50-409/84-06 on 840618-19 No
noncompliance noted however emergency plan weaknesses
identified List of weaknesses encl
PAPERIELLO,C J Region 3, Office of Director 84/07/10
LINDER,F W Dairyland Power Cooperative 4pp 25866 162 24X
Fiche 50-409,84/07/10,8408010297

--8408010299 IE Insp Rept 50-409/84-06 on 840618-19 No noncompliance
noted,however weaknesses identified in emergency
preparedness exercise conducted on 840619 Narrative summary
of instial plant conditions encl
SNELL,W G , GLOERSEN,W D , LERS,L L Region 3, Office of Director
84/07/10 9pp 25866 166 24X Fiche 50-409,84/07/10,8408010297

8408220105 Forwards response to 830517 comments on Sections 5 2 2 &
1 4 1 of security plan & Section 1 12 of guard training &
qualification plan Meeting requested w/NRC on 840920-21
Response withheld
LINDER,F Dairyland Power Cooperative 84/08/08 Office of
Nuclear Reactor Regulation, Director 2pp 26193 305 24X
Fiche 50-409,84/08/08,8408220105

8408210333 Submits safety analysis of safety parameter display sys &
operational support ctr as required by Generic Ltr 82-33 re
emergency response capability (Suppl 1 to NUREG-0737)
LINDER,F Dairyland Power Cooperative 84/08/13 CRUTCHFIELD,D
Operating Reactors Branch 5 8pp 26179 332 24X
Fiche 50-409,84/08/13,8408210333

P Operating license stage documents & correspondence
---------- ------- ----- ------------ ---- ----------

8408070099 Forwards Generic Ltr 84-13, "Tech Specs for Snubbers,"
mitted from 840503 ltr to all SEP licensees NRC position
that issue of Tech Specs for snubbers will be resolved on
generic basis restated
CRUTCHFIELD,D Assistant Director for Safety Assessment 84/07/31
KAY,J A Yankee Atomic Electric Co LINDER,F Dairyland Power
Cooperative FIEDLER,P B General Public Utilities - GPU Service
Corp 4pp 25955 227 24X Fiche 50-000,84/07/31,8408070099

8408150212 Requests exemption from NUREG-0737,Table II f 1-2,design
basis shielding envelope criteria of 100 uCi/cc of gaseous
radioiodine & particulates deposited on sampling media
LINDER,F Dairyland Power Cooperative 84/08/01 CRUTCHFIELD,D
Operating Reactors Branch 5 4pp 26066 241 24X
Fiche 50-409,84/08/01,8408150212

8408140287 Submits addl info supporting 800714 request for relief from
performing inservice testing on alternate core spray sys
check valves & boron injection outlet check valve,per
10CFR50 55 a(g)(6)(i)
LINDER,F Dairyland Power Cooperative 84/08/02 CRUTCHFIELD,D
Operating Reactors Branch 5 3pp 26054 357 24X
Fiche 50-409,84/08/02,8408140287

8408070110 Generic Ltr 84-19 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
Suppl 1 to NUREG-0933, "Prioritization of Generic Safety
Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408140098 Informs that 840306 QA program description not in accordance
w/Paragraph (3)(i) of 10CFR50 54(a) Requests revised
submittal within 30 days of ltr receipt,incorporating listed
info
SPESSARD,R L Region 3, Office of Director 84/08/09 LINDER,F W
Dairyland Power Cooperative 2pp 26044 355 24X
Fiche 50-409,84/08/09,8408140098

8408270080 Forwards fees for 840716 & 20 applications for amend to
License DPR-45
LINDER,F Dairyland Power Cooperative 84/08/14 MILLER,W D
License Fee Management Branch 1p 26246 361 24X
Fiche 50-409,84/08/14,8408270080

8408210547 Requests remittance of Class II fee for 830404 application
to amend License DPR-45,changing Tech Specs re reporting
requirements for safety valve operations & overtime
restrictions Changes considered administrative
DIGGS,R M License Fee Management Branch 84/08/16 LINDER,F
Dairyland Power Cooperative 1p 26195 263 24X
Fiche 50-409,84/08/16,8408210547

8408210029 Advises that mods to containment pressure monitoring sys to increase sys range & sys mod to measure vacuum up to 5 psig satisfy NUREG-0737 requirements & are acceptable
PAULSON,W A Operating Reactors Branch 5 84/08/17 LINDER,F
Dairyland Power Cooperative 2pp 26181 335 24X
Fiche 50-409,84/08/17,8408210029

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals or reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408220093 Forwards notice of environ assessment & finding of no significant impact re 800926 request for exemption from 10CFR50,App J requirements concerning reactor containment bldg airlock door seal testings
PAULSON,W A Operating Reactors Branch 5 84/08/20 LINDER,F
Dairyland Power Cooperative 4pp 26193 293 24X
Fiche 50-409,84/08/20,8408220093

--8408220099 Notice of environ assessment & finding of no significant impact re 800926 request for exemption from 10CFR50,App J requirements concerning reactor containment bldg airlock door seal testings
EISENHUT,D G Division of Licensing 84/08/20 4p 26193 297 24X Fiche 50-409,84/08/20,8408220093

8408230418 Informs that original approval of program re NUREG-0737, Item I A 1 1, "Shift Technical Advisor," remains unchanged All new hires must meet training requirements specified in 790913 & 1030 ltrs
PAULSON,W A Operating Reactors Branch 5 84/08/22 LINDER,F
Dairyland Power Cooperative 2pp 26204 009 24X
Fiche: 50-409,84/08/22,8408230418

8408310176 Application for amend to License DPR-45, changing Tech Specs to modify overtime spec
LINDER,F Dairyland Power Cooperative 84/08/23 CRUTCHFIELD,D
Operating Reactors Branch 5 3pp 26318 333 24X
Fiche 50-409,84/08/23,8408310176

--8408310179 Proposed Tech Spec re overtime
* Dairyland Power Cooperative 84/08/23 1p 26318 336 24X
Fiche 50-409,84/08/23,8408310176

G Inspection reports, IE Bulletins & correspondence

8408010297 Forwards IE Insp Rept 50-409/84-06 on 840618-19 No noncompliance noted, however emergency plan weaknesses identified List of weaknesses encl
PAPERIELLO,C J Region 3, Office of Director 84/07/10
LINDER,F W Dairyland Power Cooperative 4pp 25866 162 24X
Fiche 50-409,84/07/10,8408010297

--8408010299 IE Insp Rept 50-409/84-06 on 840618-19 No noncompliance noted, however weaknesses identified in emergency preparedness exercise conducted on 840619 Narrative summary of initial plant conditions encl
SNELL,W G , GLOERSEN,W B , LERS,L L Region 3, Office of Director 84/07/10 9pp 25866 166 24X Fiche 50-409,84/07/10,8408010297

8408060004 Responds to IE Bulletin 84-02 re failures of GE Type HFA relays in use in Class IE safety sys Relays tested annually No deterioration or malfunctions noted Replacement of all six HFA relays will be completed within 2 yrs
LINDER,F Dairyland Power Cooperative 84/07/17 KEPPLER,J G
Region 3, Office of Director 3pp 25933 187 24X
Fiche 50-409,84/07/17,8408060004

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408230227 Forwards IE Insp Rept 50-409/84-07 on 840516-0715 & notice of violation
SHAFER,W D Region 3, Office of Director 84/07/31 LINDER,F W
Dairyland Power Cooperative 2pp 26213 177 24X
Fiche 50-409,84/07/31,8408230227

--8408230234 Notice of violation from insp on 840516-0715
SHAFER,W D Region 3, Office of Director 84/07/31 1p
26213 179 24X Fiche 50-409,84/07/31,8408230227

--8408230238 IE Insp Rept 50-409/84-07 on 840516-0715 Noncompliance noted failure to provide positive control over area w/ radiation levels greater than 1,000 mrem/h
BDYD,D C Region 3, Office of Director 84/07/31 11pp
26213 180 24X Fiche 50-409,84/07/31,8408230227

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26048 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26047 158 24X Fiche 50-000,84/08/06,8408010337

8408230146 Forwards IE Insp Rept 50-409/84-10 on 840717-25 No noncompliance noted
WALKER,R D Region 3, Office of Director 84/08/06 LINDER,F W
Dairyland Power Cooperative 2pp 26214 028 24X
Fiche 50-409,84/08/06,8408230146

--8408230149 IE Insp Rept 50-409/84-10 on 840717-25 No noncompliance or deviations noted Major areas inspected licensee actions re unusual events
LANKSBURY,R D , BROWN,C H , REYES,L A Region 3, Office of Director 84/08/06 5pp 26214 030 24X Fiche 50-409,84/08/06,8408230146

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070374 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408270287 Ack receipt of 840801 ltr informing NRC of steps taken to comply w/840717 confirmatory action ltr
NORELIUS,C E Region 3, Office of Director 84/08/21 LINDER,F W
Dairyland Power Cooperative 1p 26241 008 24X
Fiche 50-409,84/08/21,8408270287

--8408270294 Responds to NRC 840717 confirmatory action ltr Corrective actions lower mechanism from CRD 29 removed, tested & replaced after normal functioning determined & CRD 13 lower mechanism repaired
LINDER,F Dairyland Power Cooperative 84/08/01 KEPPLER,J G
Region 3, Office of Director 6pp 26241 009 24X
Fiche 50-409,84/08/21,8408270287

R Periodic operating reports & related correspondence

8408220190 "Semiannual Radioactive Effluent Rept for LACBWR, Jan-June 1984 " W/840810 ltr
LINDER,F Dairyland Power Cooperative 84/06/30 KEPPLER,J G
Region 3, Office of Director 25pp 26188 184 24X
Fiche 50-409,84/06/30,8408220190

S Reportable occurrences, LERs & related correspondence

8408160186 LER 84-011-00 on 840716, switchyard potential transformer shorted out, causing protective devices to operate & opening breakers, resulting in loss of offsite power Emergency diesel generator 1B output breaker failed to close W/840808 ltr
GOODMAN,L S , LINDER,F Dairyland Power Cooperative 84/08/08
5pp 26106 329 24X Fiche 50-409,84/08/08,8408160186

8408160309 LER 84-010-00 on 840716, during reactor shutdown, control rod 29 found unable to insert electrically or hydraulically from fully withdrawn position Caused by rod jamming due to loosely assembled roller bearing assemblies W/840808 ltr
GOODMAN,L S , LINDER,F Dairyland Power Cooperative 84/08/08
7pp 26106 156 24X Fiche 50-409,84/08/08,8408160309

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8408060260 Forwards certification of compliance w/State of NY coastal mgt program, per Section 307(C)(3)(A) of Coastal Zone Mgt Act of 1972 & 15CFR930 57
MANGAN,C V Niagara Mohawk Power Corp 84/07/31 EISENHUT,D G
Division of Licensing 13pp 25933 336 24X Fiche 50-410,84/07/31, 8408060260

8408060284 Forwards response to 840521 request for info re QA program Revised FSAR writeups & updated organizational charts will be incorporated in next FSAR amend
MANGAN,C V Niagara Mohawk Power Corp 84/07/31 SCHWENCER,A
Licensing Branch 2 50pp 25933 256 24X Fiche 50-410,84/07/31, 8408060284

8408150632 Notification of Significant Licensee Meeting 84-65 on 840807 in King of Prussia,PA to discuss NRC involvement in monitoring preoperational program at facility
COLLINS,S J Region 1, Office of Director 84/08/02 Region 1, Office of Director 1p 26102 344 24X Fiche 50-410,84/08/02, 8408150632

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408170079 Informs of review of 840610 & 11 QA program description changes Changes acceptable Concerns in unrevised portions of program noted
MARTIN,T T Division of Engineering & Technical Programs 84/08/09
HOOTEN,B J Niagara Mohawk Power Corp 2pp 26119 022 24X
Fiche 50-220,84/08/09,8408170079

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408310267 Notification of 840912 meeting w/util in Bethesda,MD to discuss instrumentation & control
HAUGHEY,M F Licensing Branch 2 84/08/20 SCHWENCER,A Licensing Branch 2 3pp 26350 327 24X Fiche 50-410,84/08/20,8408310267

8408300300 Forwards SM Rodgers affidavit of svc indicating that FSAR Amend 13 & Suppl 7 to environ rept - OL stage provided to appropriate parties Svc list encl
MANGAN,C V Niagara Mohawk Power Corp 84/08/23 EISENHUT,D G
Division of Licensing 5pp 26306 354 24X Fiche 50-410,84/08/23, 8408300300

C Utility Environmental Report (ER), amends & correspondence

8408080054 Forwards updated distribution list for environ rept, deleting DOT
SCHWENCER,A Licensing Branch 2 84/08/01 HOOTEN,B J Niagara Mohawk Power Corp 5pp 25981 073 24X Fiche 50-410,84/08/01, 8408080054

8408300300 Forwards SM Rodgers affidavit of svc indicating that FSAR Amend 13 & Suppl 7 to environ rept - OL stage provided to appropriate parties Svc list encl
MANGAN,C V Niagara Mohawk Power Corp 84/08/23 EISENHUT,D G
Division of Licensing 5pp 26306 354 24X Fiche 50-410,84/08/23, 8408300300

D NRC Draft/Final Environmental Statements, suppls & correspondence

8408220318 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF NINE MILE POINT NUCLEAR STATION, UNIT NO 2 Docket No 50-410 (Niagara Mohawk Power Corporation, Rochester Gas & Electric Corporation And Central Hudson Gas & Electric Corporation)
* Division of Licensing 84/07/31 313pp 26201 037 24X
Fiche 50-410,84/07/31,8408220318

8408160163 Forwards DES (NUREG-1085) & FR notice of availability W/o DES
SCHWENCER,A Licensing Branch 2 84/08/09 HIRSCH,A
Environmental Protection Agency 2pp 26124 355 24X
Fiche 50-410,84/08/09,8408160163

--8408160166 Notice of availability of DES (NUREG-1085)
SCHWENCER,A Licensing Branch 2 84/08/09 2pp 26124 357 24X
Fiche 50-410,84/08/09,8408160163

8408160431 Forwards DES (NUREG-1085) & FR notice of availability W/o DES
SCHWENCER,A Licensing Branch 2 84/08/09 HOOTEN,B J Niagara Mohawk Power Corp 2pp 26122 355 24X Fiche 50-410,84/08/09, 8408160431

8408170104 Forwards FR notice of availability of DES (NUREG-1085) Svc list encl
SCHWENCER,A Licensing Branch 2 84/08/09 Library of Congress
3pp 26134 359 24X Fiche 50-410,84/08/09,8408170104

8408170107 Forwards DES (NUREG-1085) Comments due 45 days after publication of FR notice of availability W/o encl
SCHWENCER,A Licensing Branch 2 84/08/09 New York, State of
1p 26134 352 24X Fiche 50-410,84/08/09,8408170107

8408170110 Forwards DES (NUREG-1085) Comments due 45 days after publication of FR notice of availability W/o encl
SCHWENCER,A Licensing Branch 2 84/08/09 WOOD,J M Commerce, Dept of, Natl Oceanographic & Atmospheric Administration 5pp
26134 345 24X Fiche 50-410,84/08/09,8408170110

8408230024 Ack receipt of DES Review produced no comments
MIRANOWSKI,J A Agriculture, Dept of, Research Center 84/08/17
SCHWENCER,A Licensing Branch 2 1p 26209 035 24X
Fiche 50-410,84/08/17,8408230024

E NRC Safety Evaluation Report (SER) supplS & correspondence

8408080164 Summary of 840320-22 meetings w/util in Bethesda,MD re draft SER open items
HAUGHEY,M F Licensing Branch 2 84/07/30 Licensing Branch 2
9pp 25978 353 24X Fiche 50-410,84/07/30,8408080164

8408200148 Summary of 840705 & 06 meetings w/util in Bethesda,MD re open items in draft SER Summary of items discussed encl
HAUGHEY,M F Licensing Branch 2 84/08/02 Licensing Branch 2
9pp 26142 330 24X Fiche 50-410,84/08/02,8408200148

8408280163 Forwards updated status list of SER open items,based on meetings to close out items Concurrence requested
MANGAN,C V Niagara Mohawk Power Corp 84/08/23 SCHWENCER,A
Licensing Branch 2 20pp 26261 320 24X Fiche 50-410,84/08/23,
8408280163

8408280001 Forwards responses to listed SER open items Info will be included in next FSAR amend
MANGAN,C V Niagara Mohawk Power Corp 84/08/24 SCHWENCER,A
Licensing Branch 2 49pp 26261 241 24X Fiche 50-410,84/08/24,
8408280001

8408310351 Summary of 840719 meeting w/util re open items in draft SER & revs to format of FSAR Chapter 14,Rev 12
HAUGHEY,M F Licensing Branch 2 84/08/27 Licensing Branch 2
8pp 26350 333 24X Fiche 50-410,84/08/27,8408310351

F Security, medical, emergency & fire protection plans

8408030188 Forwards IE Insp Rept 50-410/84-10 on 840521-24 No violations noted
JOYNER,J H Region 1, Office of Director 84/07/13 SUNSER,J
Niagara Mohawk Power Corp 2pp 25917 293 24X
Fiche 50-410,84/07/13,8408030188

--8408030192 IE Insp Rept 50-410/84-10 on 840521-24 No violations noted
Major areas inspected evaluation of progress at site,site orientation,physical security plan & implementing procedures & security organization
BAILEY,R J , DUNLAP,J M , KEIMIG,R R Region 1, Office of
Director 84/07/12 7pp 25917 295 24X Fiche 50-410,84/07/13,
8408030188

8408060409 Summary of 840508 meeting w/util & S&W in Bethesda,MD re emergency preparedness
HAUGHEY,M F Licensing Branch 2 84/07/20 Licensing Branch 2
12pp 25951 142 24X Fiche 50-410,84/07/20,8408060409

8408210447 Requests that updated emergency plan & procedures be withheld from public disclosure due to unlisted telephone numbers & communications radio frequencies provided,per Generic Ltr 81-27
MANGAN,C V Niagara Mohawk Power Corp 84/08/17 SCHWENCER,A
Licensing Branch 2 1p 26177 199 24X Fiche 50-410,84/08/17,
8408210447

8408310292 Forwards request for addl info re 840619 revs to physical security plan Response to comments should be made by amending plan within 30 days of receipt of ltr Encl withheld (ref 10CFR73 21)
SCHWENCER,A Licensing Branch 2 84/08/17 SUNSER,J J Niagara
Mohawk Power Corp 1p 26333 296 24X Fiche 50-410,84/08/17,
8408310292

K Utility Final Safety Analysis Report (FSAR) & amends

8407090212 Amend 12 to FSAR W/840621 ltr
MANGAN,C V Niagara Mohawk Power Corp 84/06/30 EISENHUT,D G
Division of Licensing 1054pp 25446 001 24X
Fiche 50-410,84/06/30,8407090212

Q Inspection reports, IE Bulletins & correspondence

8408030188 Forwards IE Insp Rept 50-410/84-10 on 840521-24 No violations noted
JOYNER,J H Region 1, Office of Director 84/07/13 SUNSER,J
Niagara Mohawk Power Corp 2pp 25917 293 24X
Fiche 50-410,84/07/13,8408030188

--8408030192 IE Insp Rept 50-410/84-10 on 840521-24 No violations noted. Major areas inspected evaluation of progress at site,site orientation,physical security plan & implementing procedures & security organization
BAILEY,R J , DUNLAP,J M , KEIMIG,R R Region 1, Office of
Director 84/07/12 7pp 25917 295 24X Fiche 50-410,84/07/13,
8408030188

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408240233 Forwards Insp Rept 50-410/84-09 on 840514-0615 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 84/08/06
HOOTEN,W G Niagara Mohawk Power Corp 2pp 26236 254 24X
Fiche 50-410,84/08/06,8408240233

--8408240237 Notice of violation from insp on 840514-0615
* Region 1, Office of Director 84/08/06 2pp 26236 256 24X
Fiche 50-410,84/08/06,8408240233

--8408240253 Insp Rept 50-410/84-09 on 840514-0615 Noncompliance noted inadequate corrective action for QC-identified deficiencies & failure to perform requisite NDE of electrical penetration welds
GRAMM,R A , CHAUDHARY,S K , COLLINS,S J Region 1, Office of
Director 84/08/03 13pp 26236 258 24X Fiche 50-410,84/08/06,
8408240233

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New
York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408270234 Forwards Insp Rept 50-410/84-08 on 840430-0525 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 84/08/08
HOOTEN,W G Niagara Mohawk Power Corp 2pp 26258 056 24X
Fiche 50-410,84/08/08,8408270234

--8408270237 Notice of violation from insp on 840514-25
* Region 1, Office of Director 84/08/08 2pp 26258 058 24X
Fiche 50-410,84/08/08,8408270234

--8408270242 Insp Rept 50-410/84-08 on 840430-0525 Violations noted unacceptable radiographs & min weld thickness requirements
KERCH,H W , HARRIS,R H , CAMPBELL,R M Region 1, Office of
Director 84/08/02 26pp 26258 060 24X Fiche 50-410,84/08/08,
8408270234

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post
830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New
York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New
York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New
York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408310235 Provides addl info to Item 4 of IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller, Inc Approved vendor list & surveillance program reduce probability of receipt of fraudulent product
MANGAN,C V Niagara Mohawk Power Corp 84/08/17 STAROSTECKI,R Division of Project & Resident Programs 2pp 26320 328 24X Fiche 50-410,84/08/17,8408310235

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

B Reportable occurrences, LERs & related correspondence

8408100071 Final Deficiency Rept 55(e)-84-16 re std swing check valve in RCIC turbine exhaust Valves will be replaced w/special design lift check valve prior to preoperational testing
MANGAN,C V Niagara Mohawk Power Corp 84/07/30 STAROSTECKI,R Division of Project & Resident Programs 2pp 25989 308 24X Fiche 50-410,84/07/30,8408100071

8408100118 Final deficiency rept re excessive wear on Pacific Air Products linear converters Initially reported on 840213 Design of converters satisfactory for dampers Also reportable per Part 21 Not reportable per 10CFR50 55(e)
MANGAN,C V Niagara Mohawk Power Corp 84/07/30 STAROSTECKI,R Division of Project & Resident Programs 2pp 25988 253 24X Fiche 50-410,84/07/30,8408100118

8408210439 Final deficiency rept re qualification of 40 mil 1,000-volt fire resistant control cable supplied by Kerite Initially reported on 830829 Use of control cable prohibited for safety-related circuits in primary containment
MANGAN,C V Niagara Mohawk Power Corp 84/08/02 STAROSTECKI,R Division of Project & Resident Programs 2pp 26181 295 24X Fiche 50-410,84/08/02,8408210439

8408300365 Final Deficiency Rept (55(e)-84-24) re sizing of RHR sys safety valves Initially reported on 840706 Pressure control valve internals will be modified Mod will be completed by 841203
MANGAN,C V Niagara Mohawk Power Corp 84/08/06 STAROSTECKI,R Division of Project & Resident Programs 2pp 26308 192 24X Fiche 50-410,84/08/06,8408300365

8408300345 Final Deficiency Rept (55(e)-84-14) re power generation control complex separation Initially reported on 840323 S&W will rework panel wiring Corrective actions expected to be completed by 841231
MANGAN,C V Niagara Mohawk Power Corp 84/08/09 STAROSTECKI,R Division of Project & Resident Programs 3pp 26308 347 24X Fiche 50-410,84/08/09,8408300345

8408300362 Final Deficiency Rept (55(e)-84-21) re svc life of relays in safety-related sys Initially reported on 840613 Replacement parts program will be developed to replace relays in interval based on svc life determined by GE & Amerace
MANGAN,C V Niagara Mohawk Power Corp 84/08/10 STAROSTECKI,R Division of Project & Resident Programs 2pp 26308 214 24X Fiche 50-410,84/08/10,8408300362

X Onsite Storage of Low Level Waste

8408230237 Forwards certificate re pollution control facilities for NRC signature per Internal Revenue Svc requirements Info re radwaste solidification & storage bldg, radioactive solid waste & spent fuel storage encl for approval
MANGAN,C V Niagara Mohawk Power Corp 84/08/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 26207 278 24X Fiche 50-220,84/08/21,8408230237

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda,MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH,B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp. 25983 130 24X Fiche 50-000,84/07/31,8408090497

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26189 238 24X Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06 HOLAHAN,G M Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 50-000 84/08/06,8408090317

8408230373 Notification of 840816 meeting w/util in Bethesda,MD to discuss seismology open items
LEY,M Licensing Branch 3 84/08/06 KNIGHTON,G W Licensing Branch 3 4pp 26230 344 24X Fiche 50-412,84/08/06,8408230373

8408210437 Forwards State of PA Dept of Environ Resources permits for facility effective Jul 1984 & various permits issued for const activities W/three oversize drawings Aperture cards in PDR
WOOLEVER,E J Duquesne Light Co 84/08/13 KNIGHTON,G W Licensing Branch 3 154pp 26148 026 24X Fiche 50-412,84/08/13, 8408210437

8408230377 Forwards request for addl info re internally generated missile protection inside & outside containment, per 830518 application for OL Info requested within 30 days of ltr receipt
KNIGHTON,G W Licensing Branch 3 84/08/14 WOOLEVER,E J Duquesne Light Co 4pp 26230 338 24X Fiche 50-412,84/08/14, 8408230377

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000,84/08/20,8408200275

8408230246 Recommends that NRC formally submit specifically defined concerns in order to receive equally defined responses & to facilitate productive meetings Lack of communication cited as cause for NRC dissatisfaction w/FSAR Amends 6 & 7
WOOLEVER,E J Duquesne Light Co 84/08/20 KNIGHTON,G W Licensing Branch 3 3pp 26207 285 24X Fiche 50-412,84/08/20, 8408230246

8408290336 Forwards agenda for 840830 meeting at site w/NRR, IE & S&W Engineering Co re electrical separation & Rev 2 to Reg Guide 1 75 implementation program
WOOLEVER,E J Duquesne Light Co 84/08/24 KNIGHTON,G W Licensing Branch 3 2pp 26289 234 24X Fiche 50-412,84/08/24, 8408290336

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8408020011 Forwards responses to draft SER Outstanding Issues 65, 72, 115 & 120 re IE Bulletins 80-06 & 79-27, regional climatology & containment vacuum sys exhaust, respectively
WOOLEVER,E J Duquesne Light Co 84/07/27 KNIGHTON,G W Licensing Branch 3 12pp 25883 088 24X Fiche 50-412,84/07/27, 8408020011

8408020019 Forwards responses to outstanding draft SER Issues 65, 72, 115 & 120 Ltr originally issued on 840727 w/o date or ltr numbers
WOOLEVER,E J Duquesne Light Co 84/07/30 KNIGHTON,G W Licensing Branch 3 12pp 25883 136 24X Fiche 50-412,84/07/30, 8408020019

8408070432 Forwards responses to Geotechnical Engineering Section draft SER Open Items 180 & 181 re soils effective strength parameters & accuracy of SIDES program, respectively
WOOLEVER,E J Duquesne Light Co 84/08/01 KNIGHTON,G W Licensing Branch 3 4pp 25939 217 24X Fiche 50-412,84/08/01, 8408070432

8408130005 Forwards responses to Geotechnical Engineering Section draft SER Open Item 177 re settlement monitoring program & FSAR Section 2 5 4 13 re surface & subsurface instrumentation
WOOLEVER,E J Duquesne Light Co 84/08/08 KNIGHTON,G W Licensing Branch 3 7pp 26010 049 24X Fiche 50-412,84/08/08, 8408130005

8408130312 Forwards response to draft SER Open Item 150, "Seismic & Dynamic Qualification" & Open Item 151, "Pump & Valve Operability Assurance "
WOOLEVER,E J Duquesne Light Co 84/08/08 DENTON,H R Office of Nuclear Reactor Regulation, Director KNIGHTON,G W Licensing Branch 3 6pp 26010 118 24X Fiche 50-412,84/08/08,8408130312

8408140088 Forwards addl info on draft SER, Outstanding Issue 56 on TMI Item II K 3 12 Issue 58 re undetected failure of on-line ESF relays & Issue 77 on control sys failures caused by malfunction of instrument line
WOOLEVER,E J Duquesne Light Co 84/08/09 KNIGHTON,G W Licensing Branch 3 5pp 26045 354 24X Fiche 50-412,84/08/09, 8408140088

8408140127 Forwards responses to draft Matls Engineering Branch SER Open Item 196 re weld cladding of ferritic steel components & Confirmatory Item 22 re RCPB components of austenitic steel
WOOLEVER,E J Duquesne Light Co 84/08/10 KNIGHTON,G W Licensing Branch 3 3pp 26045 359 24X Fiche 50-412,84/08/10, 8408140127

8408150199 Forwards responses to draft SER Open Items 103,108-111, 158-163 & 200-203, per Reactor Sys Branch 840530 & 0608 ltrs
WOOLEVER,E J Duquesne Light Co 84/08/10 KNIGHTON,G W Licensing Branch 3 9pp 26066 217 24X Fiche 50-412,84/08/10, 8408150199

8408160333 Forwards responses to Parts 2 & 3 of Accident Evaluation Branch draft SER Open Item 53 re control room habitability
WOOLEVER,E J Duquesne Light Co 84/08/13 KNIGHTON,G W Licensing Branch 3 3pp 26085 338 24X Fiche 50-412,84/08/13, 8408160333

8408160399 Forwards responses to Auxiliary Sys Branch draft SER Open Items 125,127-130,133,135,139 & 148
WOOLEVER,E J Duquesne Light Co 84/08/13 KNIGHTON,G W Licensing Branch 3 7pp 26092 136 24X Fiche 50-412,84/08/13, 8408160399

8408230329 Forwards current list of outstanding & confirmatory issues identified in Tables 1 2 & 1 3 of draft SER Requests any differing opinion of status described on attached list
WOOLEVER,E J Duquesne Light Co 84/08/17 KNIGHTON,G W Licensing Branch 3 10pp 26206 000 24X Fiche 50-412,84/08/17, 8408230329

8408270165 Forwards responses to draft SER Outstanding Issues 3 & 165, list of emergency plan changes & instructions & evacuation maps for public Responses to FSAR questions will be incorporated in future amend
WOOLEVER,E J Duquesne Light Co 84/08/21 KNIGHTON,G W Licensing Branch 3 19pp 26242 186 24X Fiche 50-412,84/08/21, 8408270165

8408280200 Forwards "ASME Code Baseline Document" re NRC Unresolved Item 83-07-02 & draft SER Open Item 42, presented to NRC at 840726 meeting in Bethesda, MD Document will be referenced in sections of future FSAR amend
WOOLEVER,E J Duquesne Light Co 84/08/21 KNIGHTON,G W Licensing Branch 3 2pp 26275 248 24X Fiche 50-412,84/08/21, 8408280200

--8408280203 "ASME Code Baseline Document "
BLAKE,R , CHAMBERLAIN,D , FIORENTA,A J Stone & Webster Engineering Corp 20VM-179 84/08/21 76pp 26275 250 24X Fiche 50-412,84/08/21,8408280200

8408270141 Forwards responses to Containment Sys Branch draft SER Open Items 166-171 All draft open items addressed
WOOLEVER,E J Duquesne Light Co 84/08/22 KNIGHTON,G W Licensing Branch 3 17pp 26243 345 24X Fiche 50-412,84/08/22, 8408270141

--8408270147 "Experimental Evaluation of Reactor Containment Sump "
PENNINO,R J , HECKER,G E Alden Research Laboratory 83/08/31 82pp 26244 001 24X Fiche 50-412,84/08/22,8408270141

8408290222 Forwards response to Geotechnical Engineering Section draft SER Open Item 179 re soil damping values Variations of soil properties & dampings discussed
WOOLEVER,E J Duquesne Light Co 84/08/24 KNIGHTON,G W Licensing Branch 3 2pp 26290 344 24X Fiche 50-412,84/08/24, 8408290222

F Security, medical, emergency & fire protection plans

8408010151 Forwards "Procedures Generation Package For Beaver Valley Power Station, Unit 2 " in response to Generic Ltr 82-33, describing methods for developing function oriented emergency operating procedures, per NUREG-0737, Item II C 1
WOOLEVER,E J Duquesne Light Co 84/07/26 EISENHUT,D G Division of Licensing 3pp 25855 184 24X Fiche 50-412,84/07/26, 8408010154

--8408010156 "Procedures Generation Package For Beaver Valley Power Station, Unit 2 "
CLEMENTS,R H , JONES,D T Duquesne Light Co 84/08/01 116pp 25855 187 21X Fiche 50-412,84/07/26,8408010154

8408020011 Forwards responses to draft SER Outstanding Issues 65,72,115 & 120 re IE Bulletins 80-06 & 79-27, regional climatology & containment vacuum sys exhaust, respectively
WOOLEVER,E J Duquesne Light Co 84/07/27 KNIGHTON,G W Licensing Branch 3 12pp 25883 088 24X Fiche 50-412,84/07/27, 8408020011

8408070414 Forwards nonproprietary Rev 0 to WCAP-10170, "Key Safety Parameter Selection " & proprietary Rev 1 to WCAP-10170, "Key Safety Parameter Selection " (Generic Ltr 82-33) Proprietary rept withheld (ref 10CFR2 790)
WOOLEVER,E J Duquesne Light Co 84/08/01 EISENHUT,D G Division of Licensing 4pp 25938 001 24X Fiche 50-412,84/08/01, 8408070414

--84080/0419 Nonproprietary Rev 0 to App C to Suppl 1 to "Key Safety Parameter Selection for Beaver Valley, Unit 2 Safety Parameter Display Sys (SPDS) "
MORLEY,R C Westinghouse Electric Corp WCAP-10170 APC S1 R0 84/07/30 11pp 25933 005 24X Fiche 50-412,84/08/01,8408070414

8408270165 Forwards responses to draft SER Outstanding Issues 3 & 165, list of emergency plan changes & instructions & evacuation maps for public Responses to FSAR questions will be incorporated in future amend
WOOLEVER,E J Duquesne Light Co 84/08/21 KNIGHTON,G W Licensing Branch 3 19pp 26242 186 24X Fiche 50-412,84/08/21, 8408270165

8408310208 Forwards Amend 2 to "Fire Protection Evaluation Rept for Beaver Valley Power Station, Unit 2 "
WOOLEVER,E J Duquesne Light Co 84/08/27 KNIGHTON,G W Licensing Branch 3 2pp 26324 206 24X Fiche 50-412,84/08/27, 8408310208

--8408310213 Amend 2 to "Fire Protection Evaluation Rept for Beaver Valley Power Station, Unit 2 "
* Stone & Webster Engineering Corp 84/03/31 209pp 26324 208 24X Fiche 50-412,84/08/27,8408310208

P Operating license stage documents & correspondence

8408270071 Forwards responses to Action Items 1,2,3,4,6 & 7, per environ site visit meeting summary ltr
WOOLEVER,E J Duquesne Light Co 84/08/21 KNIGHTON,G W Licensing Branch 3 17pp 26247 150 24X Fiche 50-412,84/08/21, 8408270071

Q Inspection reports, IE Bulletins & correspondence

8408240275 Informs that addl info re pipe-to-fitting welds requested at 840522 meeting re Violation 82-01-01 will be provided by 840706 Clarification of Item 5 provided
WOOLEVER,E J Duquesne Light Co 84/08/27 STAROSTECKI,R Division of Project & Resident Programs 3pp 26223 187 24X Fiche 50-412,84/08/27,8408240275

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408020011 Forwards responses to draft SER Outstanding Issues 65,72,115 & 120 re IE Bulletins 80-06 & 79-27, regional climatology & containment vacuum sys exhaust, respectively
WOOLEVER,E J Duquesne Light Co 84/07/27 KNIGHTON,G W Licensing Branch 3 12pp 25883 088 24X Fiche 50-412,84/07/27, 8408020011

8408070353 Ack receipt of 840625 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/84-04
MARTIN,T T Division of Engineering & Technical Programs 84/08/01
WOOLEVER,E J Duquesne Light Co 2pp 25944 199 24X Fiche 50-412,84/08/01,8408070353

--8408070355 Responds to NRC 840531 ltr re violations noted in IE Insp Rept 50-412/84-04 Corrective actions completion of electrical encl/barrier scheduled for Fourth Quarter 1985
WOOLEVER,E J Duquesne Light Co 84/06/25 STAROSTECKI,R Division of Project & Resident Programs 6pp 25944 201 24X Fiche 50-412,84/08/01,8408070353

8408010333 IE Info Notice 84-59, Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, 'Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

)8140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

)8210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

)8270335 Discusses 840612 meeting w/util re encl SALP Repts 50-334/84-13 & 50-412/84-06 Overall assessment of performance for Unit 1 acceptable Lack of mgt control for Unit 2 identified List of meeting attendees encl
TURLEY,T E Region 1, Office of Director 84/08/21 CAREY,J J Duquesne Light Co 6pp 26244 205 24X Fiche 50-334,84/08/21,8408270335

-8408270341 Summarizes discussion at 840612 meeting re SALP Repts 50-334/84-13 & 50-412/84-06 Constructability review group for reviewing engineering output & organizational changes established
CAREY,J J Duquesne Light Co 84/06/29 STAROSTECKI,R Division of Project & Resident Programs 22pp 26244 285 24X Fiche 50-334,84/08/21,8408270335

S Reportable occurrences, LERs & related correspondence

8408060259 Interim Significant Deficiency Rept 81-06 re removed, dismantled or partially dismantled pipe supports Rework control program under development to assure QC insp status reflects most recent changes Addl rept expected by 840831
WOOLEVER,E J Duquesne Light Co 84/07/12 MURLEY,T E Region 1, Office of Director 3pp 25935 153 24X Fiche 50-412,84/07/12, 8408060259

8408210476 Final Deficiency Rept 84-04 re potential for undetectable failure of Westinghouse solid state protection sys Hardware changes described in encl Westinghouse technical bulletin will be incorporated prior to 840701
WOOLEVER,E J Duquesne Light Co 84/08/13 MURLEY,T E Region 1, Office of Director 10pp 26181 127 24X Fiche 50-412,84/08/13, 8408210476

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8408310428 Forwards summary of NRC 840418 meeting w/util in Region II ofc & 840419 meeting at facility re followup to 840313 meeting concerning welding irregularity findings
LEWIS,R C Region 2, Office of Director 84/05/01 TUCKER,H B Duke Power Co 5pp 26335 029 24X Fiche 50-413,84/05/01, 8408310428

8408300440 Confirms 840517 arrangements between JW Hampton,VL Brownlee & NA Rutherford re 840524 mgt meeting w/util in Region II ofc to discuss readiness for operation of facility Proposed agenda encl
LEWIS,R C Region 2, Office of Director 84/05/22 TUCKER,H B Duke Power Co 3pp 26314 244 24X Fiche 50-413,84/05/22, 8408300440

8408060072 Requests exemption from GDC 4 re fuel load & precritical testing activities Exemption would allow completion of RHR pump/motor analyses & seismic qualification of electrical isolation sys prior to initial criticality
THIES,A C Duke Power Co 84/07/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 25922 012 24X Fiche 50-413,84/07/11,8408060072

E NRC Safety Evaluation Report (SER), supplS & correspondence

8408080275 Forwards proprietary & nonproprietary "Westinghouse Setpoint Methodology for Protection Sys,Catawba Station," in response to Section 7 3 24 of SER Application for withholding proprietary rept encl
TUCKER,H B Duke Power Co 84/07/30 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 25964 228 24X Fiche 50-413,84/07/30,8408080275

--8408080280 Requests withholding of proprietary "Westinghouse Setpoint Methodology for Protection Sys,Catawba Station" (ref 10CFR2 790)
WIEBEMANN,R A Westinghouse Electric Corp 84/07/20 DENTON,H Office of Nuclear Reactor Regulation, Director 8pp 25964 230 24X Fiche 50-413,84/07/30,8408080275

--8408080284 Nonproprietary "Westinghouse Setpoint Methodology for Protection Sys,Catawba Station " Two oversize tables encl Aperture cards available in PDR
JANSEN,R L , TULEY,C R Westinghouse Electric Corp 84/06/30 71pp 25964 239 24X Fiche 50-413,84/07/30,8408080275

8408070009 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAWBA NUCLEAR STATION,UNITS 1 AND 2 DOCKET Nos 50-413 And 50-414 (Duke Power Company,et al)
* Division of Licensing NUREG-0954 S03 84/07/31 140pp Available at NRC $5 50 25954 334 24X Fiche 50-413,84/07/31, 8408070009

F Security, medical, emergency & fire protection plans

8408300358 Forwards FEMA "Exercise Rept,Catawba Nuclear Station, 840215-16 "
DANCE,H C Region 2, Office of Director 84/06/25 TUCKER,H B Duke Power Co 1p 26308 264 24X Fiche 50-413,84/06/25, 8408300358

8408070487 Forwards Rev 1 to storage & in-transit security plan for SNM of low strategic significance Rev withheld (ref 10CFR73 21)
TUCKER,H B Duke Power Co 84/07/02 O'REILLY,J P Region 2, Office of Director 1p 25941 193 24X Fiche 50-413,84/07/02, 8408070487

8408270367 Forwards Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No deviations or violations noted
DANCE,H C Division of Project & Resident Programs 84/07/17
TUCKER,H B Duke Power Co 2pp 26257 227 24X
Fiche 50-413,84/07/17,8408270367

--8408270371 Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No violations or deviations noted Major areas inspected fire protection
WISEMAN,G R , CONLON,T E Region 2, Office of Director 84/07/13
6pp 26257 229 24X Fiche 50-413,84/07/17,8408270367

8408090042 Forwards States of NC & SC responses to regional assistance committee findings on offsite radiological emergency response preparedness & exercise on 840215-16 State & local emergency plans adequate
KRIMM,R W Federal Emergency Management Agency 84/07/27
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 6pp 25992 324 24X Fiche 50-413,84/07/27,8408090042

8408020060 Motion for changes to transcript of emergency planning hearing to correct matl errors ASLB requested to issue order directing that evidentiary record be amended, incorporating encl changes
MCGARRY,J M Duke Power Co DSB 702 84/07/30 Atomic Safety and Licensing Board Panel 1p 25892 271 24X
Fiche 50-413,84/07/30,8408020060

8408090007 Forwards safeguards implementation ltrs Ltrs withheld (ref 10CFR73 21)
TUCKER,H B Duke Power Co 84/07/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25973 005 24X
Fiche 50-413,84/07/30,8408090007

8408070322 Responds to NRC concern re false opening of MSIVs or steam generator PORVs for Steam Generators A,B & D due to fire Mod will be implemented on Unit 1 prior to entry into Mode 3
TUCKER,H B Duke Power Co 84/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 1p 25945 129 24X Fiche 50-413,84/08/02,8408070322

8408070351 Advises that sufficient manpower available onsite to perform required manual operations in timely manner to achieve safe hot standby conditions w/o reliance on fire brigade members, per NRC request during App R review
TUCKER,H B Duke Power Co 84/08/03 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 1p 25944 149 24X Fiche 50-413,84/08/03,8408070351

8408280372 Forwards public version of revised emergency plan implementing procedures, including HP/0/B/1009/07 re in-plant particulate & iodine monitoring under accident conditions & HP/0/B/1009/05 re personnel monitoring
TUCKER,H B Duke Power Co 84/08/06 Record Services Branch (Document Control Desk) 2pp 26293 049 24X Fiche 50-413, 84/08/06,8408280372

--8408280377 Public version of revised emergency plan implementing procedures, including HP/0/B/1009/07 re in-plant particulate & iodine monitoring under accident conditions & HP/0/B/1009/05 re personnel monitoring W/Felton 840821 memo
TUCKER,H B Duke Power Co 84/08/06 74pp 26293 051 24X
Fiche 50-413,84/08/06,8408280372

8408300357 Confirms 840806 telcon w/JP O'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50, fire protection & 10CFR73, physical protection Agenda encl
LEWIS,R C Region 2, Office of Director 84/08/08 TUCKER,H B Duke Power Co 3pp 26314 222 24X Fiche 50-000,84/08/08, 8408300357

8408300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
TUCKER,H B Duke Power Co 84/08/10 Record Services Branch (Document Control Desk) 21pp 26332 353 24X
Fiche 50-000,84/08/10,8408300014

--8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations "
* Duke Power Co 84/08/15 30pp 26333 010 24X
Fiche 50-000,84/08/10,8408300014

--8408300028 Public version of revised crisis mgt plan implementing procedures, including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 memo
* Duke Power Co 84/08/15 170pp 26333 040 24X
Fiche 50-000,84/08/10,8408300014

8408290041 Board Notification 84-151 forwards FEMA interim findings on offsite radiological emergency response preparedness, State of SC 840424 ltr & State of NC 840522 ltr
NOVAK,T M Assistant Director for Licensing 84/08/29
MARGULIES,M , LAZO,R , HOOPER,F Atomic Safety and Licensing Board Panel 4pp 26322 115 24X Fiche 50-413,84/08/29,8408290041

--8408140090 Requests addl info & supplemental interim findings re status of offsite radiological plans & preparedness Statement indicating adequacy of state & local emergency plans should be provided by 840615
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/07 KRIMM,R W Federal Emergency Management Agency 1p 26322 127 24X Fiche 50-413,84/08/29, 8408290041

Q Adjudicatory correspondence

8408150524 Forwards applicant Exhibits EP 18-20, intervenor Exhibits EP 42, 43, 44, 45, 46, 47, 50, 48 & 49 & NRC Exhibit EP 5 re emergency planning Related correspondence
EYSTER,R Taylor Associates 84/05/31 PLEASANT,E Administrative & Logistical Support Branch 1p 26105 363 24X
Fiche 50-413,84/05/31,8408150524

8408160109 Forwards intervenor Exhibits 51-54 & 15, NRC staff Exhibit 3A & applicant Exhibits 21A & 21 Related correspondence
RILEY,S L Taylor Associates 84/06/15 PLEASANT,E Administrative & Logistical Support Branch 1p 26126 326 24X
Fiche 50-413,84/06/15,8408160109

8408010211 Responds to Judge Kelley 840716 request for applicant 840222 responses to NRC questions on emergency diesel generators W/o encls Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 678 84/07/27 KELLY,J L , PURDOM,P W , FOSTER,R F Atomic Safety and Licensing Board Panel 1p 25856 052 24X Fiche 50-413,84/07/27,8408010211

8408020062 Forwards Ofc of Investigation Rept 2-83-038, "Catawba Nuclear Station Alleged Harassment & Intimidation of QC Welding Inspectors "
KELLEY,J L Atomic Safety and Licensing Board Panel DSB 693
84/07/27 Office of the Executive Legal Director 1p 25898 201
24X Fiche 50-413,84/07/27,8408020062

--8408020068 Investigation Rept 2-83-038, "Duke Power Co Catawba Nuclear Station Harassment & Intimidation of QC Welding Inspectors "
WILLIAMSON,E L Office of Investigation 84/07/11 808pp
25898 202 24X Fiche 50-413,84/07/27,8408020062

8408070443 Joint proposed findings of fact & conclusions of law in form of partial initial decision re emergency planning contentions Certificate of Svc encl
GUILD,R Palmetto Alliance GUILD,R Guild, R GUILD,R Carolina Environmental Study Group DSB 776 84/07/27 195pp 25943 206
24X Fiche 50-413,84/07/27,8408070443

8408020060 Motion for changes to transcript of emergency planning hearing to correct matl errors ASLB requested to issue order directing that evidentiary record be amended, incorporating encl changes
MCGARRY,J M Duke Power Co MCGARRY,J M Bishop, Liberman, Cook, Purcell & Reynolds DSB 702 84/07/30 Atomic Safety and Licensing Board Panel 1p 25892 271 24X Fiche 50-413,84/07/30, 8408020060

--8408020066 Errata to transcript of 840501-0608 emergency planning hearing, correcting matl errors Certificate of Svc encl
* Duke Power Co 84/07/30 23pp 25892 272 24X
Fiche 50-413,84/07/30,8408020060

8408020013 Order extending time until 840904 for Commission to act to review Director's Decision DD-84-16 Served on 840801
CHILK,S J Office of the Secretary of the Commission DSB 692
84/07/31 Commissioners 1p 25883 115 24X
Fiche 50-413,84/07/31,8408020013

8408060035 Response to Palmetto Alliance & Carolina Environ Study Group seven interrogatories for which ASLB granted motion to compel Certificate of Svc encl Related correspondence
CARR,A V Duke Power Co DSB 746 84/08/01 Palmetto Alliance
53pp 25928 087 24X Fiche 50-413,84/08/01,8408060035

8408200548 Expresses opinion that ASLB 840720 order imposes burdens on Palmetto Alliance & Carolina Environ Study Group solely as consequence of util & staff tardiness in discovery of safety problems w/diesel generators Related correspondence
GUILD,R Guild, R GUILD,R Palmetto Alliance GUILD,R Carolina Environmental Study Group DSB 159 84/08/01 KELLEY,J L , FOSTER,R F , PURDOM,P W Atomic Safety and Licensing Board Panel 2pp 26137 028 24X Fiche 50-413,84/08/01,8408200548

8408070422 Summarizes 840803 agreement to 2-day extension to serve diesel generator technical evaluation rept Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 912 84/08/03 KELLEY,J L Atomic Safety and Licensing Board Panel 1p 26042 025 24X Fiche 50-413,84/08/03,8408070422

8408080339 Forwards util 'Investigation of Issues Raised by NRC in Insp Repts 50-413/84-31 & 50-414/84-17,' in response to NRC concerns re allegations of Welder B Related correspondence
CARR,A V Duke Power Co DSB 826 84/08/03 KELLEY,J L , FOSTER,R F , PURDOM,P Atomic Safety and Licensing Board Panel 120pp 25963 311 24X Fiche 50-413 84/08 03,8408080339

8408090191 Forwards technical evaluation rept per ASLB 840720 order establishing schedule leading to 840827 hearing on diesel generator contention W/o encl Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 863 84/08/07 KELLEY,J L , PURDOM,P W , FOSTER,R F Atomic Safety and Licensing Board Panel 150pp 26130 189 24X Fiche 50-413,84/08,07,8408090191

8408130270 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on emergency planning Certificate of Svc encl
MCGURREN,H J Hearing Branch 1 JOHNSON,G E Hearing Branch 4 DSB 910 84/08/09 149pp 26009 001 21X Fiche 50-413,84/08/08, 8408130270

8408140103 Supplemental response to joint interrogatories & requests to produce documents on diesel generator contentions & to Carolina Environ Study Group interrogatories Prof qualifications encl Related correspondence
CARR,A V Duke Power Co DSB 957 84/08/10 Palmetto Alliance 17pp 26048 334 24X Fiche 50-413,84/08/10,8408140103

--8408140110 Forwards interrogatories to Palmetto Alliance & Carolina Environ Study Group re identity of expert witness on diesel generator problems
CARR,A V Duke Power Co 84/08/10 KELLEY,J L , PURDOM,P W , FOSTER,R F Atomic Safety and Licensing Board Panel 1p 26048 351 24X Fiche 50-413 84/08/10,8408140103

--8408140115 Interrogatories re identification,qualifications & role of expert on diesel generator contention Certificate of Svc encl Related correspondence
CARR,A V Duke Power Co 84/08/10 Palmetto Alliance 7pp 26048 352 24X Fiche 50-413,84/08/10,8408140103

8408160121 Forwards Attachment A to Section VII, "Repair of Drill Holes," of 810803 transmittal Corrections to errors listed Related correspondence
CARR,A V Duke Power Co DSB 069 84/08/13 KELLEY,J L , FOSTER,R F , PURDOM,R Atomic Safety and Licensing Board Panel 4pp 26085 180 24X Fiche 50-413,84/08/13,8408160121

8408200481 Forwards SER re reliability of diesel generators Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 175 84/08/14 GUILD,R Palmetto Alliance RILEY,J L Carolina Environmental Study Group 11pp 26136 307 24X Fiche 50-413,84/08/14,8408200481

08200508 Forwards SER re reliability of diesel generators Technical evaluation rept,which forms part of SER,previously forwarded W/o encl Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 176 84/08/14 KELLY,J L , FOSTER,R F , PURDOM,P W Atomic Safety and Licensing Board Panel 1p 26136 360 24X Fiche 50-413,84/08/14,8408200508

108200499 Forwards addl info re NRC witnesses on intervenor diesel generator contention & two addl comments Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 172 84/08/15 GUILD,R Palmetto Alliance RILEY,J L Carolina Environmental Study Group 1p 26137 001 24X Fiche 50-413,84/08/15,8408200499

-8408200511 Supplemental responses to Palmetto Alliance & Carolina Environ Study Group 840318 general interrogatories Certificate of Svc encl Related correspondence
JOHNSON,G E Hearing Branch 4 84/08/15 Palmetto Alliance 15pp 26137 002 24X Fiche 50-413,84/08/15,8408200499

8408310205 Expresses disagreement w/conclusions expressed in util,BNWL & NRC staff repts re reliability of TDI emergency diesel generators Pattern of deficiencies exists which precludes findings Related correspondence
GUILD,R Guild, R GUILD,R Palmetto Alliance GUILD,R Carolina Environmental Study Group DSB 430 84/08/16 KELLEY,J L , PURDOM,P W , FOSTER,R F Atomic Safety and Licensing Board Panel 193pp 26317 228 24X Fiche 50-413,84/08/16,8408310205

8408270115 Discusses intervenors intention to rely on prefiled testimony as statement of detailed technical position per ASLB 840720 order & 840810 telcon P Lauzecky added to staff panel Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 303 84/08/17 GUILD,R Palmetto Alliance RILEY,J L Carolina Environmental Study Group 4pp 26247 340 21X Fiche 50-413,84/08/17,8408270115

8408220347 Reply to proposed findings of fact & conclusions of law of Palmetto Alliance,Carolina Environ Study Group re NRC Certificate of Svc encl
MCGARRY,J M Duke Power Co McGARRY,J M Bishop, Liberman, Cook, Purcell & Reynolds DSB 188 84/08/20 Atomic Safety and Licensing Board Panel 125pp 26192 001 24X Fiche 50-413, 84/08/20,8408220347

8408270092 Forwards transcript of NRC staff testimony of CH Berlinger, BJ Kirkwood,PJ Lauzecky & JF Newbitt re operability & reliability of facility emergency diesel generators Certificate of Svc encl Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 309 84/08/20 KELLY,J L , FOSTER,R F , PURDOM,P W Atomic Safety and Licensing Board Panel 46pp 26247 004 24X Fiche 50 413,84/08/20,8408270092

8408270109 Forwards SER re TDI Diesel Generator Owners Group program plan W/o encl Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 310 84/08/20 KELLEY,J L , PURDOM,P W , FOSTER,R F Atomic Safety and Licensing Board Panel 1p 26247 325 24X Fiche 50-413,84/08/20,8408270109

8408230280 Order dismissing diesel generator contention & canceling 840827 evidentiary hearing Intervenor submission & staff & applicant testimony accepted as proof of positions had contention gone to hearing Served on 840822
KELLEY,J L Atomic Safety and Licensing Board Panel DSB 225 84/08/22 Palmetto Alliance 2pp 26205 360 24X Fiche 50-413,84/08/22,8408230280

8408280455 Forwards License NPF-24 & SSER 3, including pertinent FR notice, environ protection plan,Amend 1 to Indemnity Agreement B-100 & antitrust conditions W/o encls Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 341 84/08/24 ROSENTHAL,A S , MOORE,J S , WILBER,H A Atomic Safety and Licensing Appeal Panel 2pp 26280 331 24X Fiche 50-413,84/08/24,8408280455

I Financial information

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER,H B Duke Power Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 26237 137 24X Fiche 50-000,84/08/16,8408240224

--8408240239 "1983 Annual Rept "
CLAY,G W , SHAW R W North Carolina Municipal Power Agencies 83/12/31 27pp 26237 134 21X Fiche 50-000,84/08/16,8408240224

--8408240242 "1983 Annual Rept "
LEE,W S , BODTH,D W Duke Power Co 83/12/31 47pp 26237 167 24X Fiche 50-000,84/08/16,8408240224

J Insurance & indemnity information

8408060218 Unexpected Amend 1 to Indemnity Agreement B-100
SALTZMAN,J Assistant Director for State & Licensee Relations 84/07/06 2pp 25950 253 24X Fiche 50-413,84/07/06,8408060218

8408130164 Forwards License NPF-24,notice of issuance,Amend 1 to Indemnity Agreement B-100,SSER 3 & environ protection plan (nonradiological) W/o SSER 3
EISENHUT,D G Division of Licensing 84/07/18 TUCKER,H B Duke Power Co 4pp 26059 314 24X Fiche 50-413,84/07/18,8408130164

8408160344 Forwards Endorsement 1 to NELIA Certificate N-97 & MAELU Certificate M-97
HOFFMAN,J Marsh & McLennan, Inc 84/08/13 DINITZ,I Assistant Director for State & Licensee Relations 3pp 26092 181 24X Fiche 50-413,84/08/13,8408160344

P Operating license stage documents & correspondence

8408130161 Forwards License NPF-24,notice of issuance,Amend 1 to Indemnity Agreement B-100,SSER 3 & environ protection plan (nonradiological) W/o SSER 3
EISENHUT,D G Division of Licensing 84/07/18 TUCKER,H B Duke Power Co 4pp 26059 314 24X Fiche 50-413,84/07/18,8408130164

DOCKETED ITEMS

--8408130168 License NPF-24 for facility
DENTON,H R Office of Nuclear Reactor Regulation Director
84/07/18 18pp 26059 317 24X Fiche 50-413 84/07/18,8408130164

--8408130177 Notice of issuance of License NPF 24
ADENSAM,E G Licensing Branch 3 84/07/18 5pp 26059 335 24X
Fiche 50-413,84/07/18 8408130164

--8408130179 Environ protection plan (nonradiological) for facilities
* Office of Nuclear Reactor Regulation, Director 84/07/18
22pp 26059 340 24X Fiche 50-413,84/07/18 8408130164

8408060117 Forwards Rev 5 to pump & valve inservice testing program
TUCKER,H B Duke Power Co 84/07/27 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
4 1p 25933 053 24X Fiche 50-413,84/07/27,8408060117

--8408060119 Rev 5 to inservice testing program for pumps & valves
* Duke Power Co 84/07/27 3pp 25933 054 24X
Fiche 50-413,84/07/27,8408060117

8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification
WIGGINTON,D L Operating Reactors Branch 1 84/07/30 Operating
Reactors Branch 1 4pp 26143 265 24X Fiche 50-000,84/07/30,
8408160425

8408060097 Application for amend to License NPF-24,changing Tech Specs to revise surveillance requirement & acceptance criteria for auxiliary feedwater pumps
TUCKER,H B Duke Power Co 84/07/31 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
4 3pp 25925 309 24X Fiche 50-413,84/07/31,8408060097

--8408060104 Proposed Tech Specs,changing surveillance requirement & acceptance criteria for auxiliary feedwater pumps
* Duke Power Co 84/07/31 3pp 25925 312 24X
Fiche 50-413,84/07/31,8408060097

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda,MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH,B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497

8408130011 TECHNICAL SPECIFICATIONS FOR CATAWBA NUCLEAR STATION,Unit 1 Docket No 50-413
ANDERSON,F D Division of Licensing NUREG-1072 84/07/31 525pp
Available at NRC $10 00 26039 001 24X Fiche 50-413,84/07/31,
8408130011

8408070263 Forwards addl changes to 840625 revised FSAR Chapter 14 test abstracts,consisting of auxiliary feedwater sys functional test & rod control sys alignment test Changes will appear in Rev 12 to FSAR
TUCKER,H B Duke Power Co 84/08/01 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
4 4pp 25949 240 24X Fiche 50-413,84/08/01,8408070263

8408140430 Submits info re load history associated w/operation of Diesel Engine 1B
TUCKER,H B, Duke Power Co 84/08/03 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
4 3pp 26051 184 24X Fiche 50-413,84/08/03,8408140430

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408310016 Forwards listed documents re facilities,per 840515 stipulation of parties in proceeding W/o encl
LEWIS,R C Region 2, Office of Director 84/08/06 PURDOM,P W
Atomic Safety and Licensing Board Panel 2pp 26335 012 24X
Fiche 50-413,84/08/06,8408310016

8408310028 Forwards listed documents re facilities,per 840515 stipulation of parties in proceeding W/o encls
LEWIS,R C Region 2, Office of Director 84/08/06 RILEY,J L,
Carolina Environmental Study Group 2pp 26335 015 24X
Fiche 50-413,84/08/06,8408310028

8408310241 Advises of decision to include individuals who receive copy under 840515 stipulation on cc list Documents covered by stipulation encl W/o encl
LEWIS,R C Region 2, Office of Director 84/08/06 FOSTER,R F
Affiliation Not Assigned 2pp 26333 334 24X
Fiche 50-413,84/08/06,8408310241

8408310242 Advises of decision to include individuals who receive copy under 840515 stipulation on cc list Documents covered by stipulation encl W/o encl
LEWIS,R C Region 2, Office of Director 84/08/06 KELLEY,J L
Atomic Safety and Licensing Board Panel 2pp 26333 336 24X
Fiche 50-413,84/08/06,8408310242

8408230051 Forwards response to TDI emergency diesel generator issues raised by NRC & Battelle personnel during 840726 visit Identification of cylinder heads addressed
TUCKER,H B Duke Power Co 84/08/08 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
4 4pp 26204 014 24X Fiche 50-413,84/08/08,8408230051

8408210365 Forwards "Torsiograph Test of Emergency Diesel Generator 1A at Catawba Nuclear Power Station," in response to 840809 telcon request Start 61 should show run duration of 35 h rather than 43
TUCKER,H B Duke Power Co 84/08/14 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
4 3pp 26178 175 24X Fiche 50-413,84/08/14,8408210365

--8408210370 "Torsiograph Test of Emergency Diesel Generator 1A at Catawba Nuclear Power Station "
* Failure Analysis Associates FAAA-84-5-23 84/05/29 19pp
26178 178 24X Fiche 50-413,84/08/14,8408210365

8408220303 Forwards Rev 12 to FSAR Table 14 2 12-1, "Heat Tracing Sys Test " Test method & acceptance criteria revised to verify proper operation of heat tracing sys under current conditions
TUCKER,H B Duke Power Co 84/08/14 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
4 3pp 26194 069 24X Fiche 50-413,84/08/14,8408220303

8408270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submittal of semiannual radioactive effluent release rept for Jul-Dec 1984
TUCKER,H B Duke Power Co 84/08/16 DENTON,H R Office of
Nuclear Reactor Regulation, Director 2pp 26279 112 24X
Fiche 50-000,84/08/16,8408270160

--8408270169 Rev 4 to "Offsite Dose Calculation Manual "
BIRCH,M L Duke Power Co 84/07/18 39pp 26279 114 24X
Fiche 50-000,84/08/16,8408270160

8408210362 Application for amend to License NPF-24,revising Tech Specs 4 6 2 & 4 6 5 6 2 re containment pressure control sys Marked-up Tech Specs encl
TUCKER,H B Duke Power Co 84/08/17 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
4 14pp 26180 227 24X Fiche 50-413,84/08/17,8408210362

8408280281 Requests that amend to License NPF-24 re Tech Spec surveillance requirements for auxiliary feedwater pumps be granted by 840905 Delay may result in startup schedule for facility & have substantial financial impact
TUCKER,H B Duke Power Co 84/08/17 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch
4 5pp 26274 327 24X Fiche 50-413,84/08/17,8408280281

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

G Inspection reports, IE Bulletins & correspondence

8408270184 Forwards Insp Repts 50-413/84-71 & 50-414/84-31 on 840612-15 No violations or deviations identified
DANCE,H C Region 2, Office of Director 84/07/09 TUCKER,H B
Duke Power Co 2pp 26257 322 24X Fiche 50-413,84/07/09,
8408270184

--8408270191 Insp Repts 50-413/84-71 & 50-414/84-31 on 840612-15,No violations or deviations noted Major areas inspected action on previously identified enforcement matters & 10CFR50 55(e) items
RUFF,A B , CONLON,T E Region 2, Office of Director 84/07/03
5pp 26257 324 24X Fiche 50-413,84/07/09,8408270184

8408280386 Forwards Insp Repts 50-413/84-73 & 50-414/84-32 on 840619-20 & 28 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/11 TUCKER,H B
Duke Power Co 2pp 26294 353 24X Fiche 50-413,84/07/11,
8408280386

--8408280393 Insp Repts 50-413/84-73 & 50-414/84-32 on 840619-20 & 28 No violations or deviations noted Major areas inspected corrective actions re worker concerns on socket weld fabrication & unauthorized removal of arc strikes
ECONOMOS,N , BLAKE,J J Region 2, Office of Director 84/07/10
3pp 26294 355 24X Fiche 50-413,84/07/11,8408280386

8408270367 Forwards Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No deviations or violations noted
DANCE,H C Division of Project & Resident Programs 84/07/17
TUCKER,H B Duke Power Co 2pp 26257 227 24X
Fiche 50-413,84/07/17,8408270367

--8408270371 Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No violations or deviations noted Major areas inspected fire protection
WISEMAN,G R , CONLON,T E Region 2, Office of Director 84/07/13
6pp 26257 229 24X Fiche 50-413,84/07/17,8408270367

8408270474 Forwards Insp Rept 50-413/84-75 on 840625-29 No violations or deviations identified
DANCE,H C Region 2, Office of Director 84/07/17 TUCKER,H B
Duke Power Co 2pp 26256 211 24X Fiche 50-413,84/07/17,
8408270474

--8408270480 Insp Rept 50-413/84-75 on 840625-29 No violations or deviations noted Major areas inspected licensee action on previous insp findings & preoperational test results evaluation for solid-state protection sys functional test
TAYLOR,P A , JAPE,F Region 2, Office of Director 84/07/12
4pp 26256 213 24X Fiche 50-413,84/07/17,8408270474

8408280327 Forwards Insp Rept 50-413/84-76 on 840626-28 No violations or deviations identified
DANCE,H C Region 2, Office of Director 84/07/19 TUCKER,H B
Duke Power Co 2pp 26282 261 24X Fiche 50-413,84/07/19,
8408280327

--8408280329 Insp Rept 50-413/84-76 on 840626-29 No violations or deviations noted Major areas inspected review of counting room & chemistry procedures,review of chemistry lab facilities & results of capability tests
KUZO,G B , MONTGOMERY,D M Region 2, Office of Director
84/07/16 10pp 26282 263 24X Fiche 50-413,84/07/19,8408280327

8408270484 Forwards Insp Rept 50-413/84-72 on 840618-22 No violations or deviations identified
DANCE,H C Region 2, Office of Director 84/07/23 TUCKER,H B
Duke Power Co 3pp 26256 188 24X Fiche 50-413,84/07/23,
8408270484

-8408270492 Insp Rept 50-413/84-72 on 840618-22 No violations or deviations identified Major areas inspected actions on previous enforcement matters & previously identified insp findings
BELISLE,G A , FOSTER,L E , UPRIGHT,C M Region 2, Office of
Director 84/07/18 12pp 26256 191 24X Fiche 50-413,84/07/23,
8408270484

07250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

08020062 Forwards Ofc of Investigation Rept 2-83-038, "Catawba Nuclear Station Alleged Harassment & Intimidation of QC Welding Inspectors "
KELLEY,J L Atomic Safety and Licensing Board Panel 0SB 693
84/07/27 Office of the Executive Legal Director 1p 25898 201
24X Fiche 50-413,84/07/27,8408020062

--8408020068 Investigation Rept 2-83-038, "Duke Power Co Catawba Nuclear Station Harassment & Intimidation of QC Welding Inspectors "
WILLIAMSON,E L Office of Investigation 84/07/11 80Bpp
25898-202 24X Fiche 50-413,84/07/27,8408020062

8408080339 Forwards util "Investigation of Issues Raised by NRC in Insp Repts 50-413/84-31 & 50-414/84-17," in response to NRC concerns re allegations of Welder B Related correspondence
CARR,A V Duke Power Co 0SB 826 84/08/03 KELLY,J L ,
FOSTER,R F , PURDOM,P Atomic Safety and Licensing Board Panel
120pp 25963 311 24X Fiche 50-413,84/08/03,8408080339

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Static Health Physics Procedures Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of N
York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirato Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of N
York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,84080103

8408300408 Forwards listed insp repts & related correspondence per 840515 stipulation of parties in proceeding W/o encls
LEWIS,R C Region 2, Office of Director 84/08/06 GUILD,R
Palmetto Alliance 2pp 26314 242 24X Fiche 50-413,84/08/06,
8408300408

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of N
York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,84080701

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of N
York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,84081000

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of N
York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,84081000

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversel Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of N
York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,84081000

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of N
York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,84081000

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of N
York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,84081402

8408270391 Provides status of actions taken re Diesel Engine 1A component revalidation insp
TUCKER,H B Duke Power Co 84/08/17 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Bran
4 5pp 26238 282 24X Fiche 50-413,84/08/17,8408270391

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of N
York, Inc 115pp 26329,008 24X Fiche 50-000,84/08/21,84082101

R Periodic operating reports & related correspondence

8408300406 Monthly operating rept for Jul 1984 W/840823 ltr
REAVIS,J A , TUCKER,H B Duke Power Co 84/07/31 3pp 26313 30
24X Fiche 50-413,84/07/31,8408300406

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 198pp
25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10,8408060050

8408090278 Final significant deficiency rept re seismic design criteria not applied to fire protection piping serving ESF filters Initially reported on 840628 Fire protection spray water piping upgraded to Class F piping
TUCKER,H B Duke Power Co 84/07/18 O'REILLY,J P Region 2, Office of Director 3pp 26030 200 24X Fiche 50-413,84/07/18,8408090278

8408160159 Interim deficiency rept re testing of valves modified by Borg-Warner Testing temporarily halted until electric motor operated valves modified Corrective action will be completed by 841001
TUCKER,H B Duke Power Co 84/07/25 O'REILLY,J P Region 2, Office of Director 1p 26106 342 24X Fiche 50-413,84/07/25,8408160159

8408160468 Interim Deficiency Rept SD 413/84-01 re addl vibration testing Next rept will be provided by 841101
TUCKER,H B Duke Power Co 84/07/26 O'REILLY,J P Region 2, Office of Director 1p 26107 285 24X Fiche 50-413,84/07/26,8408160468

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000,84/07/27,8408060102

8408160429 Interim deficiency rept re cracking of two cast iron subcovers in pedestal at junction of intake rocker arm shaft & subcover Initially reported on 840624 Cracked subcovers replaced Final report will be provided on 850115
TUCKER,H B Duke Power Co 84/07/27 O'REILLY,J P Region 2, Office of Director 3pp 26106 066 24X Fiche 50-413,84/07/27,8408160429

8408160517 Significant Deficiency Rept SD 413-414/84-18 re residual stress in Type AN piston skirts of TDI diesels Initially reported on 840628 Skirt cracks being evaluated Next rept by 850115
TUCKER,H B Duke Power Co 84/07/27 O'REILLY,J P Region 2, Office of Director 3pp 26108 012 24X Fiche 50-413,84/07/27,8408160517

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000,84/08/01,8408060324

8408070445 Forwards response to several TDI emergency diesel engine issues raised during NRC & Battelle 840726 visit Jacket water sys parameters show no evidence of flow resistance increase
TUCKER,H B Duke Power Co 84/08/01 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENBAM,E G Licensing Branch 4 3pp 25942 263 24X Fiche 50-413,84/08/01,8408070445

8408160183 Supplemental deficiency rept re evaluation of const flushing program Flush boundary for upper head injection pipe incorporated into const flushing program
TUCKER,H B Duke Power Co 84/08/03 O'REILLY,J P Region 2, Office of Director 3pp 26106 316 24X Fiche 50-413,84/08/03,8408160183

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program,testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X Fiche 50-000,84/08/13,8408240115

--8409240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation,plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000,84/08/14,8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets."
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

8408300501 LER 84-001-00 on 840721,boric acid transfer pumps 1A & 1B discovered damaged & inoperable due to extended operation w/o suction or discharge flow path Caused by improper valve lineup Procedure will be revised W/840822 ltr
OUELLETTE,R W , TUCKER,H B Duke Power Co 84/08/22 4pp
26314 064 24X Fiche 50-413,84/08/22,8408300501

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000,84/08/23,8408290179

T Hearing transcripts on non-antitrust matters

8408020060 Motion for changes to transcript of emergency planning hearing to correct matl errors ASLB requested to issue order directing that evidentiary record be amended,incorporating encl changes
MCGARRY,J M Duke Power Co MCGARRY,J M Bishop, Liberman, Cook, Purcell & Reynolds DSB 702 84/07/30 Atomic Safety and Licensing Board Panel 1p 25892 271 24X Fiche 50-413,84/07/30,8408020060

--8408020066 Errata to transcript of 840501-0608 emergency planning hearing,correcting matl errors Certificate of Svc encl
* Duke Power Co 84/07/30 23pp 25892 272 24X
Fiche 50-413,84/07/30,8408020060

8408130360 Transcript of 840808 telcon conference in Bethesda,MD Pp 12,771-12,807
* Atomic Safety and Licensing Board Panel 84/08/08 41pp,
26010 074 24X Fiche 50-413,84/08/08,8408130360,

8408140243 Transcript of 840810 telcon in Bethesda,MD Pp 12,808-12,836
* Atomic Safety and Licensing Board Panel 84/08/10 31pp
26055 355 24X Fiche 50-413,84/08/10,8408140243

8408280205 Testimony of OW Hallman,RP Muschick,SR Ward,JA Gorman, CA Wells,LA Swanger,SK Chen,JO Barbour,JM Curtis & RC Oamberg re problems encountered in diesel generator qualification program,Related correspondence
HALLMAN,O W , MUSCHICK,R P , WARD,S R Duke Power Co DSB 322
84/08/18 444pp 26271 316 24X Fiche 50-413,84/08/18,8408280205

U Congressional/Executive Correspondence

8408090508 Responds to 840706 ltr re NRC reply to R Guild, atty for Palmetto Alliance, 840627 ltr concerning mod or suspension of facility CP
DIRCKS, W J Office of the Executive Director for Operations
84/07/31 MARTIN, J G House of Rep 2pp 25982 334 24X
Fiche 50-413, 84/07/31, 8408090508

--8407100397 Informs of R Guild of Palmetto Alliance request urging NRC to provide Alliance w/expeditious response to 840627 ltr
Progress update & response requested
MARTIN, J G House of Rep , Ways and Means 84/07/06
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 25982 341 24X Fiche 50-413, 84/07/31, 8408090508

V Operator Examinations

8408300375 Forwards summary of 840416 meeting w/util in Region II ofc re info developed by NRC re conduct of reactor/senior operator training & recent written license exam Attendance list also encl
O'REILLY, J P Region 2, Office of Director 84/05/09 TUCKER, H B
Duke Power Co 5pp 26308 167 24X Fiche 50-413, 84/05/09, 8408300375

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8408310428 Forwards summary of NRC 840418 meeting w/util in Region II ofc & 840419 meeting at facility re followup to 840313 meeting concerning welding irregularity findings
LEWIS, R C Region 2, Office of Director 84/05/01 TUCKER, H B
Duke Power Co 5pp 26335 029 24X Fiche 50-413, 84/05/01, 8408310428

8408130164 Forwards License NPF-24, notice of issuance, Amend 1 to Indemnity Agreement B-100, SSER 3 & environ protection plan (nonradiological) W/o SSER 3
EISENHUT, D G Division of Licensing 84/07/18 TUCKER, H B Duke Power Co 4pp 26059 314 24X Fiche 50-413, 84/07/18, 8408130164

--8408130179 Environ protection plan (nonradiological) for facilities
* Office of Nuclear Reactor Regulation, Director 84/07/18
22pp 26059 340 24X Fiche 50-413, 84/07/18, 8408130164

8408160425 Summary of 840720 meeting w/utils & Westinghouse re containment analysis & superheat effects on environ qualification
WIGGINTON, D L Operating Reactors Branch 1 84/07/30 Operating Reactors Branch 1 4pp 26143 265 24X Fiche 50-000, 84/07/30, 8408160425

08090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda, MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
BINGH, B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 130 24X Fiche 50-000, 84/07/31, 8408090497

08070263 Forwards addl changes to 840625 revised FSAR Chapter 14 test abstracts, consisting of auxiliary feedwater sys functional test & rod control sys alignment test Changes will appear in Rev 12 to FSAR
TUCKER, H B Duke Power Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 4pp 25949 240 24X Fiche 50-413, 84/08/01, 8408070263

8408140430 Submits info re load history associated w/operation of Diesel Engine 1B
TUCKER, H B Duke Power Co 84/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 26051 184 24X Fiche 50-413, 84/08/03, 8408140430

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408310016 Forwards listed documents re facilities, per 840515 stipulation of parties in proceeding W/o encl
LEWIS, R C Region 2, Office of Director 84/08/06 PURDOM, P W
Atomic Safety and Licensing Board Panel 2pp 26335 012 24X
Fiche 50-413, 84/08/06, 8408310016

8408310028 Forwards listed documents re facilities, per 840515 stipulation of parties in proceeding W/o encls
LEWIS, R C Region 2, Office of Director 84/08/06 RILEY, J L
Carolina Environmental Study Group 2pp 26335 015 24X
Fiche 50-413, 84/08/06, 8408310028

8408310241 Advises of decision to include individuals who receive copy under 840515 stipulation on cc list Documents covered by stipulation encl W/o encl
LEWIS, R C Region 2, Office of Director 84/08/06 FOSTER, R F
Affiliation Not Assigned 2pp 26333 334 24X
Fiche 50-413, 84/08/06, 8408310241

8408310242 Advises of decision to include individuals who receive copy under 840515 stipulation on cc list Documents covered by stipulation encl W/o encl
LEWIS, R C Region 2, Office of Director 84/08/06 KELLEY, J L
Atomic Safety and Licensing Board Panel 2pp 26333 336 24X
Fiche 50-413, 84/08/06, 8408310242

8408230051 Forwards response to TDI emergency diesel generator issues raised by NRC & Battelle personnel during 840726 visit Identification of cylinder heads addressed
TUCKER, H B Duke Power Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 4pp 26204 014 24X Fiche 50-413, 84/08/08, 8408230051

8408210365 Forwards "Torsiograph Test of Emergency Diesel Generator 1A at Catawba Nuclear Power Station," in response to 840809 telcon request Start 61 should show run duration of 35 h rather than 43
TUCKER, H B Duke Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 26178 175 24X Fiche 50-413, 84/08/14, 8408210365

--8408210370 "Torsiograph Test of Emergency Diesel Generator 1A at Catawba Nuclear Power Station "
* Failure Analysis Associates FAAA-84-5-23 84/05/29 19pp
26178 178 24X Fiche 50-413, 84/08/14, 8408210365

8408220303 Forwards Rev 12 to FSAR Table 14 2 12-1, "Heat Tracing Sys Test " Test method & acceptance criteria revised to verify proper operation of heat tracing sys under current conditions
TUCKER, H B Duke Power Co 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 26194 067 24X Fiche 50-413, 84/08/14, 8408220303

8408270160 Forwards Rev 4 to "Offsite Dose Calculation Manual," incorporating Catawba calculation info Rev submitted prior to submittal of semiannual radioactive effluent release rept for Jul-Dec 1984
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26279 112 24X
Fiche 50-000, 84/08/16, 8408270160

--8408270169 Rev 4 to "Offsite Dose Calculation Manual "
BIRCH, M L Duke Power Co 84/07/18 39pp 26279 114 24X
Fiche 50-000, 84/08/16, 8408270160

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408080275 Forwards proprietary & nonproprietary "Westinghouse Setpoint Methodology for Protection Sys, Catawba Station," in response to Section 7 3 24 of SER Application for withholding proprietary rept encl
TUCKER, H B Duke Power Co 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 25964 228 24X Fiche 50-413, 84/07/30, 8408080275

--8408080280 Requests withholding of proprietary "Westinghouse Setpoint Methodology for Protection Sys, Catawba Station"
(ref 10CFR2 790)
WIESEMANN, R A Westinghouse Electric Corp 84/07/20 DENTON, H
Office of Nuclear Reactor Regulation, Director 8pp 25964 230
24X Fiche 50-413, 84/07/30, 8408080275

--8408080284 Nonproprietary "Westinghouse Setpoint Methodology for Protection Sys, Catawba Station " Two oversize tables encl
Aperture cards available in PDR
JANSEN, R L , TULEY, C R Westinghouse Electric Corp 84/06/30
71pp 25964 238 24X Fiche 50-413, 84/07/30, 8408080275

8408070009 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAWBA NUCLEAR STATION, UNITS 1 AND 2 DOCKET Nos 50-413 And 50-414 (Duke Power Company, et al)
* Division of Licensing NUREG-0954 S03 84/07/31 140pp
Available at NRC $5 50 25954 334 24X Fiche 50-413,84/07/31, 8408070009

F Security, medical, emergency & fire protection plans

8408300358 Forwards FEMA "Exercise Rept, Catawba Nuclear Station, 840215-16 "
DANCE, H C Region 2, Office of Director 84/06/25 TUCKER, H B
Duke Power Co 1p 26308 264 24X Fiche 50-413,84/06/25, 8408300358

8408270367 Forwards Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No deviations or violations noted
DANCE, H C Division of Project & Resident Programs 84/07/17
TUCKER, H B Duke Power Co 2pp 26257 227 24X
Fiche 50-413,84/07/17,8408270367

--8408270371 Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No violations or deviations noted Major areas inspected fire protection
WISEMAN, G R Region 2, Office of Director 84/07/13 6pp
26257 229 24X Fiche 50-413,84/07/17,8408270367

8408090042 Forwards States of NC & SC responses to regional assistance committee findings on offsite radiological emergency response preparedness & exercise on 840215-16 State & local emergency plans adequate
KRIMM, R W Federal Emergency Management Agency 84/07/27
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 8pp 25992 324 24X Fiche 50-413,84/07/27, 8408090042

8408020060 Motion for changes to transcript of emergency planning hearing to correct matl errors ASLB requested to issue order directing that evidentiary record be amended, incorporating encl changes
MCGARRY, J M Duke Power Co DSB 702 84/07/30 Atomic Safety and Licensing Board Panel 1p 25892 271 24X
Fiche 50-413,84/07/30,8408020060

--8408020066 Errata to transcript of 840501-0608 emergency planning hearing, correcting matl errors Certificate of Svc encl
* Duke Power Co 84/07/30 23pp 25892 272 24X
Fiche 50-413,84/07/30,8408020060

8408090007 Forwards safeguards implementation ltrs Ltrs withheld (ref 10CFR73 21)
TUCKER, H B Duke Power Co 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25973 005 24X
Fiche 50-413,84/07/30,8408090007

8408070322 Responds to NRC concern re false opening of MSIVs or steam generator PORVs for Steam Generators A, B & D due to fire Mod will be implemented on Unit 1 prior to entry into Mode 3
TUCKER, H B Duke Power Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 25945 129 24X Fiche 50-413,84/08/02,8408070322

8408070351 Advises that sufficient manpower available onsite to perform required manual operations in timely manner to achieve safe hot standby conditions w/o reliance on fire brigade members, per NRC request during App R review
TUCKER, H B Duke Power Co 84/08/03 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 25944 149 24X Fiche 50-413,84/08/03,8408070351

8408280372 Forwards public version of revised emergency plan implementing procedures, including HP/0/B/1009/07 re in-plant particulate & iodine monitoring under accident conditions & HP/0/B/1009/05 re personnel monitoring
TUCKER, H B Duke Power Co 84/08/06 Record Services Branch (Document Control Desk) 2pp 26293 049 24X Fiche 50-413, 84/08/06,8408280372

--8408280377 Public version of revised emergency plan implementing procedures, including HP/0/B/1009/07 re in-plant particulate & iodine monitoring under accident conditions & HP/0/B/1009/05 re personnel monitoring W/Felton 840821 memo
TUCKER, H B Duke Power Co 84/08/06 74pp 26293 051 24X
Fiche 50-413,84/08/06,8408280372

8408300357 Confirms 840806 telcon w/JP O'Reilly re 840815 meeting in Region II ofc to discuss design & operation of standby shutdown facility concerning App R to 10CFR50, fire protection & 10CFR73, physical protection Agenda encl
LEWIS, R C Region 2, Office of Director 84/08/08 TUCKER, H B
Duke Power Co 3pp 26314 222 24X Fiche 50-000,84/08/08, 8408300357

8408300014 Forwards public version of Rev 13 to crisis mgt plan & revised emergency plan implementing procedures
TUCKER, H B Duke Power Co 84/08/10 Record Services Branch (Document Control Desk) 21pp 26332 353 24X
Fiche 50-000,84/08/10,8408300014

--8408300021 Public version of Rev 13 to "Crisis Mgt Plan for Nuclear Stations "
* Duke Power Co 84/08/15 30pp 26333 010 24X
Fiche 50-000,84/08/10,8408300014

--8408300028 Public version of revised crisis mgt plan implementing procedures, including 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group W/Felton 840823 memo
* Duke Power Co 84/08/15 170pp 26333 040 24X
Fiche 50-000,84/08/10,8408300014

8408290041 Board Notification 84-151 forwards FEMA interim findings on offsite radiological emergency response preparedness, State of SC 840424 ltr & State of NC 840522 ltr
NOVAK, T M Assistant Director for Licensing 84/08/29
MARGULIES, M , LAZO, R , HOOPER, F Atomic Safety and Licensing Board Panel 4pp 26322 115 24X Fiche 50-413,84/08/29,8408290041

--8406140090 Requests addl info & supplemental interim findings re status of offsite radiological plans & preparedness Statement indicating adequacy of state & local emergency plans should be provided by 840615
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/06/07 KRIMM, R W Federal Emergency Management Agency 1p 26322 127 24X Fiche 50-413,84/08/29, 8408290041

G Adjudicatory correspondence

8408150524 Forwards applicant Exhibits EP 18-20, Intervenor Exhibits EP 42, 43, 44, 45, 46, 47, 50, 48 & 49 & NRC Exhibit EP 5 re emergency planning Related correspondence
EYSTER, R Taylor Associates 84/05/31 PLEASANT, E Administrative & Logistical Support Branch 1p 26105 363 24X
Fiche 50-413,84/05/31,8408150524

8408160109 Forwards Intervenor Exhibits 51-54 & 15, NRC staff Exhibit 3A & applicant Exhibits 21A & 21 Related correspondence.
RILEY, S L Taylor Associates 84/06/15 PLEASANT, E
Administrative & Logistical Support Branch 1p 26126 326 24X
Fiche 50-413,84/06/15,8408160109

8408010211 Responds to Judge Kelley 840716 request for applicant 840222 responses to NRC questions on emergency diesel generators W/o encls Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 678 84/07/27 KELLY, J L ,
PURDOM, P W , FOSTER, R F Atomic Safety and Licensing Board Panel
1p 25856 052 24X Fiche 50-413,84/07/27,8408010211

8408020062 Forwards Ofc of Investigation Rept 2-83-038, "Catawba Nuclear Station Alleged Harassment & Intimidation of QC Welding Inspectors "
KELLEY, J L Atomic Safety and Licensing Board Panel DSB 693
84/07/27 Office of the Executive Legal Director 1p 25898 201
24X Fiche 50-413,84/07/27,8408020062

8408070443 Joint proposed findings of fact & conclusions of law in form of partial initial decision re emergency planning contentions Certificate of Svc encl
GUILD, R Palmetto Alliance GUILD, R Guild, R GUILD, R Carolina Environmental Study Group DSB 776 84/07/27 195pp 25943 206
24X Fiche 50-413,84/07/27,8408070443

8408020060 Motion for changes to transcript of emergency planning hearing to correct matl errors ASLB requested to issue order directing that evidentiary record be amended, incorporating encl changes
MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds DSB 702 84/07/30 Atomic Safety and Licensing Board Panel 1p 25892 271 24X Fiche 50-413,84/07/30, 8408020060

--8408020066 Errata to transcript of 840501-0608 emergency planning hearing, correcting matl errors Certificate of Svc encl
* Duke Power Co 84/07/30 23pp 25892 272 24X
Fiche 50-413,84/07/30,8408020060

8408020013 Order extending time until 840904 for Commission to act to review Director's Decision DD-84-16 Served on 840801
CHILK, S J Office of the Secretary of the Commission DSB 692
84/07/31 Commissioners 1p 25883 115 24X
Fiche 50-413,84/07/31,8408020013

8408060035 Response to Palmetto Alliance & Carolina Environ Study Group seven interrogatories for which ASLB granted motion to compel Certificate of Svc encl Related correspondence
CARR, A V Duke Power Co DSB 746 84/08/01 Palmetto Alliance 53pp 25928 087 24X Fiche 50-413, 84/08/01, 8408060035

8408200548 Expresses opinion that ASLB 840720 order imposes burdens on Palmetto Alliance & Carolina Environ Study Group solely as consequence of util & staff tardiness in discovery of safety problems w/diesel generators Related correspondence
GUILD, R Guild, R GUILD, R Palmetto Alliance GUILD, R Carolina Environmental Study Group DSB 159 84/08/01 KELLEY, J L , FOSTER, R F , PURDOM, P W Atomic Safety and Licensing Board Panel
2pp 26137 028 24X Fiche 50-413, 84/08/01, 8408200548

8408070422 Summarizes 840802 agreement to 2-day extension to serve diesel generator technical evaluation rept Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 818 84/08/03 KELLEY, J L Atomic Safety and Licensing Board Panel 1p 25942 025 24X Fiche 50-413, 84/08/03, 8408070422

8408080339 Forwards util "Investigation of Issues Raised by NRC in Insp Repts 50-413/84-31 & 50-414/84-17," in response to NRC concerns re allegations of Welder B Related correspondence
CARR, A V Duke Power Co DSB 826 84/08/03 KELLY, J L , FOSTER, R F , PURDOM, P Atomic Safety and Licensing Board Panel
120pp 25963 311 24X Fiche 50-413, 84/08/03, 8408080339

8408090191 Forwards technical evaluation rept, per ASLB 840720 order establishing schedule leading to 840827 hearing on diesel generator contention W/o encl Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 863 84/08/07 KELLEY, J L , PURDOM, P W , FOSTER, R F Atomic Safety and Licensing Board Panel
150pp 26130 189 24X Fiche 50-413, 84/08/07, 8408090191

8408130270 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on emergency planning Certificate of Svc encl
MCGURREN, H J Hearing Branch 1 JOHNSON, G E Hearing Branch 4 DSB 910 84/08/08 149pp 26009 001 24X Fiche 50-413, 84/08/08, 8408130270

8408140103 Supplemental response to joint interrogatories & requests to produce documents on diesel generator contentions & to Carolina Environ Study Group interrogatories Prof qualifications encl Related correspondence
CARR, A V Duke Power Co DSB 937 84/08/10 Palmetto Alliance 17pp 26048 334 24X Fiche 50-413, 84/08/10, 8408140103

--8408140110 Forwards interrogatories to Palmetto Alliance & Carolina Environ Study Group re identity of expert witness on diesel generator problems
CARR, A V Duke Power Co 84/08/10 KELLEY, J L , PURDOM, P W , FOSTER, R F Atomic Safety and Licensing Board Panel 1p
26048 351 24X Fiche 50-413, 84/08/10, 8408140103

--8408140115 Interrogatories re identification, qualifications & role of expert on diesel generator contention Certificate of Svc encl Related correspondence
CARR, A V Duke Power Co 84/08/10 Palmetto Alliance 7pp
26048 352 24X Fiche 50-413, 84/08/10, 8408140103

108160121 Forwards Attachment A to Section VII, "Repair of Drill Holes;" of 840803 transmittal Corrections to errors listed Related correspondence
CARR, A V Duke Power Co DSB 069 84/08/13 KELLEY, J L , FOSTER, R F , PURDOM, R Atomic Safety and Licensing Board Panel
4pp 26085 180 24X Fiche 50-413, 84/08/13, 8408160121

108200481 Forwards SER re reliability of diesel generators Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 175 84/08/14 GUILD, R Palmetto Alliance RILEY, J L Carolina Environmental Study Group
11pp 26136 307 24X Fiche 50-413, 84/08/14, 8408200481

08200508 Forwards SER re reliability of diesel generators Technical evaluation rept, which forms part of SER, previously forwarded W/o encl Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 176 84/08/14 KELLY, J L , FOSTER, R F , PURDOM, P W Atomic Safety and Licensing Board Panel
1p 26136 360 24X Fiche 50-413, 84/08/14, 8408200508

408200499 Forwards addl info re NRC witnesses on intervenor diesel generator contention & two addl comments Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 172 84/08/15 GUILD, R Palmetto Alliance RILEY, J L Carolina Environmental Study Group
1p 26137 001 24X Fiche 50-413, 84/08/15, 8408200499

--8408200511 Supplemental responses to Palmetto Alliance & Carolina Environ Study Group 840318 general interrogatories Certificate of Svc encl Related correspondence
JOHNSON, G E Hearing Branch 4 84/08/15 Palmetto Alliance
15pp 26137 002 24X Fiche 50-413, 84/08/15, 8408200499

8408310205 Expresses disagreement w/conclusions expressed in util, BNL & NRC staff repts re reliability of TDI emergency diesel generators Pattern of deficiencies exists which precludes findings Related correspondence
GUILD, R Guild, R GUILD, R Palmetto Alliance GUILD, R Carolina Environmental Study Group DSB 430 84/08/16 KELLEY, J L , PURDOM, P W , FOSTER, R F Atomic Safety and Licensing Board Panel
193pp 26317 228 24X Fiche 50-413, 84/08/16, 8408310205

8408270119 Discusses intervenors intention to rely on prefiled testimony as statement of detailed technical position, per ASLB 840720 order & 840810 telcon PJ Louzecky added to staff panel Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 303 84/08/17 GUILD, R Palmetto Alliance RILEY, J L Carolina Environmental Study Group
4pp 26247 340 24X Fiche 50-413, 84/08/17, 8408270119

8408220347 Reply to proposed findings of fact & conclusions of law of Palmetto Alliance, Carolina Environ Study Group & NRC Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds DSB 188 84/08/20 Atomic Safety and Licensing Board Panel 125pp 26192 001 24X Fiche 50-413, 84/08/20, 8408220347

8408270092 Forwards transcript of NRC staff testimony of CH Berlinger, BJ Kirkwood, PJ Louzecky & JF Nesbitt re operability & reliability of facility emergency diesel generators Certificate of Svc encl Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 309 84/08/20 KELLY, J L , FOSTER, R F , PURDOM, P W Atomic Safety and Licensing Board Panel
46pp 26247 004 24X Fiche 50-413, 84/08/20, 8408270092

8408270109 Forwards SER re TDI Diesel Generator Owners Group program plan W/o encl Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 310 84/08/20 KELLEY, J L , PURDOM, P W , FOSTER, R F Atomic Safety and Licensing Board Panel
1p 26247 325 24X Fiche 50-413, 84/08/20, 8408270109

8408230280 Order dismissing diesel generator contention & canceling 840827 evidentiary hearing Intervenor submission & staff & applicant testimony accepted as proof of positions had contention gone to hearing Served on 840822
KELLEY, J L Atomic Safety and Licensing Board Panel DSB 225
84/08/22 Palmetto Alliance 2pp 26205 360 24X
Fiche 50-413, 84/08/22, 8408230280

8408280455 Forwards License NPF-24 & SSER 3, including pertinent FR notice, environ protection plan, Amend 1 to Indemnity Agreement B-100 & antitrust conditions W/o encls Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 341 84/08/24 ROSENTHAL, A S , MOORE, T S , WILBER, H A Atomic Safety and Licensing Appeal Panel
2pp 26280 334 24X Fiche 50-413, 84/08/24, 8408280455

I Financial information
--------- -------------

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 26237 137 24X Fiche 50-000, 84/08/16, 8408240224

--8408240239 "1983 Annual Rept "
CLAY, G W , SHAW, R W North Carolina Municipal Power Agencies
83/12/31 27pp 26237 139 24X Fiche 50-000, 84/08/16, 8408240224

--8408240242 "1983 Annual Rept "
LEE, W S , BOOTH, D W Duke Power Co 83/12/31 47pp 26237 167
24X Fiche 50-000, 84/08/16, 8408240224

J Insurance & indemnity information
---------- ------------

8408160344 Forwards Endorsement 1 to NELIA Certificate N-97 & MAELU Certificate M-97
HOFFMAN, J Marsh & McLennan, Inc 84/08/13 DINITZ, I Assistant Director for State & Licensee Relations 3pp 26092 181 24X
Fiche, 50-413, 84/08/13, 8408160344

Q Inspection reports, IE Bulletins & correspondence

8408270184 Forwards Insp Repts 50-413/84-71 & 50-414/84-31 on 840612-15 No violations or deviations identified
DANCE, H C Region 2, Office of Director 84/07/09 TUCKER, H B
Duke Power Co 2pp 26257 322 24X Fiche 50-413, 84/07/09, 8408270184

--8408270191 Insp Repts 50-413/84-71 & 50-414/84-31 on 840612-15 No violations or deviations noted Major areas inspected action on previously identified enforcement matters & 10CFR50 55(e) items
RUFF, A B , CONLON, T E Region 2, Office of Director 84/07/03
5pp 26257 324 24X Fiche 50-413, 84/07/09, 8408270184

8408280386 Forwards Insp Repts 50-413/84-73 & 50-414/84-32 on 840619-20 & 28 No violations or deviations noted
DANCE, H C Region 2, Office of Director 84/07/11 TUCKER, H B
Duke Power Co 2pp 26294 353 24X Fiche 50-413, 84/07/11, 8408280386

--8408280393 Insp Repts 50-413/84-73 & 50-414/84-32 on 840619-20 & 28 No violations or deviations noted Major areas inspected corrective actions re worker concerns on socket weld fabrication & unauthorized removal of arc strikes
ECONOMOS, N , BLAKE, J W Region 2, Office of Director 84/07/10
3pp 26294 355 24X Fiche 50-413, 84/07/11, 8408280386

8408270367 Forwards Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No violations or violations noted
DANCE, H C Division of Project & Resident Programs 84/07/17
TUCKER, H B Duke Power Co 2pp 26257 227 24X
Fiche 50-413, 84/07/17, 8408270367

--8408270371 Insp Repts 50-413/84-77 & 50-414/84-33 on 840625-29 No violations or deviations noted Major areas inspected fire protection
WISEMAN, O R , CONLON, T E Region 2, Office of Director 84/07/13
6pp 26257 229 24X Fiche 50-413, 84/07/17, 8408270367

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408020062 Forwards Ofc of Investigation Rept 2-83-038, "Catawba Nuclear Station Alleged Harassment & Intimidation of QC Welding Inspectors "
KELLEY, J L Atomic Safety and Licensing Board Panel DSB 693
84/07/27 Office of the Executive Legal Director 1p 25898 201
24X Fiche 50-413, 84/07/27, 8408020062

--8408020068 Investigation Rept 2-83-038, "Duke Power Co Catawba Nuclear Station Harassment & Intimidation of QC Welding Inspectors "
WILLIAMSON, E L Office of Investigation 84/07/11 808pp
25898 202 24X Fiche 50-413, 84/07/27, 8408020062

8408080339 Forwards util "Investigation of Issues Raised by NRC in Insp Repts 50-413/84-31 & 50-414/84-17," in response to NRC concerns re allegations of Welder B Related correspondence
CARR, A V Duke Power Co DSB 826 84/08/03 KELLY, J L Atomic Safety and Licensing Board Panel 120pp 25963 311 24X
Fiche 50-413, 84/08/03, 8408080339

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 198 24X Fiche 50-000, 84/08/06, 8408010337

8408300408 Forwards listed insp repts & related correspondence per 840515 stipulation of parties in proceeding W/o encls.
LEWIS, R C Region 2, Office of Director 84/08/06 GUILD, R
Palmetto Alliance 2pp 26314 242 24X Fiche 50-413, 84/08/06, 8408300408

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408270391 Provides status of actions taken re Diesel Engine 1A component revalidation insp
TUCKER, H B Duke Power Co 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 5pp 26238 282 24X Fiche 50-413, 84/08/17, 8408270391

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000, 84/05/24, 8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000, 84/05/24, 8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000, 84/05/24, 8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER, M Division of Licensing 158pp
25926 173 24X Fiche 50-000, 84/06/28, 8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER, C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000, 84/07/10, 8408060050

8408090278 Final significant deficiency rept re seismic design criteria not applied to fire protection piping serving ESF filters. Initially reported on 840628 Fire protection spray water piping upgraded to Class F piping
TUCKER, H B Duke Power Co. 84/07/18 O'REILLY, J P Region 2, Office of Director 3pp. 26030 200 24X Fiche 50-413, 84/07/18, 8408090278

8408160159 Interim deficiency rept re testing of valves modified by Borg-Warner Testing temporarily halted until electric motor operated valves modified corrective action will be completed by 841001
TUCKER, H B Duke Power Co 84/07/25 O'REILLY, J P Region 2, Office of Director 1p 26106 342 24X Fiche 50-413, 84/07/25, 8408160159

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000, 84/07/27, 8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000, 84/07/27, 8408060102

8408160429 Interim deficiency rept re cracking of two cast iron subcovers in pedestal at junction of intake rocker arm shaft & subcover Initially reported on 840624 Cracked subcovers replaced Final report will be provided on 850115
TUCKER, H B Duke Power Co 84/07/27 O'REILLY, J P Region 2, Office of Director 3pp 26106 066 24X Fiche 50-413, 84/07/27, 8408160429

8408160517 Significant Deficiency Rept SD 413-414/84-18 re residual stress in Type AN piston skirts of TDI diesels Initially reported on 840628 Skirt cracks being evaluated Next rept by 850115
TUCKER, H B Duke Power Co 84/07/27 O'REILLY, J P Region 2, Office of Director 3pp 26108 012 24X Fiche 50-413, 84/07/27, 8408160517

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000, 84/08/01, 8408060324

8408070445 Forwards response to several TDI emergency diesel engine issues raised during NRC & Battelle 840726 visit Jacket water sys parameters show no evidence of flow resistance increase
TUCKER, H B Duke Power Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 5pp 25942 263 24X Fiche 50-413, 84/08/01, 8408070445

8408160183 Supplemental deficiency rept re evaluation of const flushing program Flush boundary for upper head injection pipe incorporated into const flushing program
TUCKER, H B Duke Power Co 84/08/03 O'REILLY, J P Region 2, Office of Director 3pp 26106 316 24X Fiche 50-413, 84/08/03, 8408160183

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000, 84/08/10, 8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000, 84/08/10, 8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT, D G Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255, 194 24X Fiche 50-000, 84/08/13, 8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000, 84/08/13, 8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept. Addl copy forwarded to BNWL, per NRC request
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000, 84/08/14, 8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000, 84/08/14, 8408160395

8408290179 Forwards response to 840723 request for addl info on rpts submitted by TDI Diesel Generator Owners Group
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER, C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000, 84/08/23, 8408290179

T Hearing transcripts on non-antitrust matters

8408020060 Motion for changes to transcript of emergency planning hearing to correct matl errors ASLB requested to issue order directing that evidentiary record be amended, incorporating encl changes
MCGARRY, J M Duke Power Co DSR 702 84/07/30 Atomic Safety and Licensing Board Panel 1p 25892 271 24X
Fiche 50-413, 84/07/30, 8408020060

--8408020066 Errata to transcript of 840501-0608 emergency planning hearing, correcting matl errors Certificate of Svc encl
* Duke Power Co 84/07/30 23pp 25892 272 24X
Fiche 50-413, 84/07/30, 8408020060

8408130360 Transcript of 840808 telcon conference in Bethesda, MD Pp 12, 771-12, 807
* Atomic Safety and Licensing Board Panel 84/08/08 41pp
26010 074 24X Fiche 50-413, 84/08/08, 8408130360

8408140243 Transcript of 840810 telcon in Bethesda, MD Pp 12, 808-12, 836
* Atomic Safety and Licensing Board Panel 84/08/10 31pp
26055 355 24X Fiche 50-413, 84/08/10, 8408140243

8408280205 Testimony of GW Hallman, RP Muschick, SR Ward, JA Gorman, CA Wells, LA Swanger, SK Chen, JO Barbour, JM Curtis & RC Gamberg re problems encountered in diesel generator qualification program Related correspondence
HALLMAN, G W , MUSCHICK, R P , WARD, S R Duke Power Co DSB 322
84/08/10 444pp 26271 316 24X Fiche 50-413, 84/08/10, 8408280205

U Congressional/Executive Correspondence

8408090508 Responds to 840706 ltr re NRC reply to R Guild, atty for Palmetto Alliance, 840627 ltr concerning mod or suspension of facility CP
DIRCKS, W J Office of the Executive Director for Operations
84/07/31 MARTIN, J G House of Rep 2pp 25982 334 24X
Fiche 50-413, 84/07/31, 8408090508

--8407100397 Informs of R Guild of Palmetto Alliance request urging NRC to provide Alliance w/expeditious response to 840627 ltr Progress update & response requested
MARTIN, J G House of Rep , Ways and Means 84/07/06
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 25982 341 24X Fiche 50-413, 84/07/31, 8408090508

V Operator Examinations

8408300375 Forwards summary of 840416 meeting w/util in Region II ofc re info developed by NRC re conduct of reactor/senior operator training & recent written license exam Attendance list also encl
O'REILLY, J P Region 2, Office of Director 84/05/09 TUCKER, H B Duke Power Co 5pp 26308 167 24X Fiche 50-413, 84/05/09, 8408300375

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8408280143 Revised emergency plan procedures, including 10-S-01-23 re emergency plan training & drills safety-related, & 2 re alert nonsafety-related & & 3 re site emergency nonsafety-related W/840820 ltr
HURLEY, J Mississippi Power & Light Co 84/07/27 O'REILLY, J P Region 2, Office of Director 27pp 26279 153 24X
Fiche. 50-416, 84/07/27, 8408280143

8408080138 Forwards "Grand Gulf Nuclear Power Station Exercise," of offsite radiological emergency conducted on 840411 Meeting held on 840531 w/util & State of MS to discuss deficiency re coordination of issuance of public info
KRIMM, R W Federal Emergency Management Agency 84/07/30
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 25960 266 24X Fiche 50-416, 84/07/30, 8408080138

--8408080141 Grand Gulf Nuclear Power Station Exercise," conducted on 840411
* Federal Emergency Management Agency 84/04/24 69pp
25960 249 24X Fiche 50-416 B1/07 30,8408080138

8408130335 Advises that 840511 Re, 10 to physical security plan consistent w/provisions of 10CFR50 51(p) & acceptable
LEWIS R C Region 2, Office of Director 84/08/07 DALE,L F
Mississippi Power & Light Co 2pp 26010 323 24X
Fiche 50 416 84/08/07,8408130335

8408210151 Rev 1 to Vol 10 to Procedure 10-S-01-25, "Onsite Personnel Response " W/840813 ltr
DALE,L F Mississippi Power & Light Co 84/08/13 O'REILLY,J P
Region 2, Office of Director 9pp 26181 307 24X
Fiche 50-416 84/08/13,8408210151

8408210484 Submits revised commitments & proposed changes to Tech Specs & emergency procedures re meteorological sys,per NUREG-0654, App 2 Quarterly meteorological sensor calibr should be performed semiannually
DALE,L F Mississippi Power & Light Co 84/08/14 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 26177 358
24X Fiche 50-416,84/08/14 8408210484

3 Adjudicatory correspondence

8408130150 Forwards addl info re Commission 840717 responses to Questions 1(B) & 1(F) of EJ Markey 840313 ltr Addl info on development of Tech Specs encl
RICHARD,J B Mississippi Power & Light Co DSB 929 84/07/23
PALLADINO,N J Commissioners 20pp 26010 338 24X
Fiche 50-416,84/07/23,8408130150

8408010196 Expresses official position of State of LA that decision to license facility should be made by NRC based on safety rules & regulations & scientific findings Representations by state atty general should be disregarded
EDWARDS,E W Louisiana, State of DSB 683 84/07/27
PALLADINO,N J Commissioners 1p 25854 353 24X
Fiche 50-416,84/07/27,8408010196

8408020027 First set of interrogatories to Jacksonians United for Livable Energy Policies Certificate of Svc encl Related correspondence
KNOTTS,J B Mississippi Power & Light Co DSB 703 84/07/30
Jacksonians United for Livable Energy Policies 12pp 25882 272
24X Fiche 50-416,84/07/30,8408020027

8408030081 Informs that discovery requests not received from Jacksonians United for Livable Energy Policies,per ASLB 840423 order Intervenor withdrawing request for hearing Related correspondence
REYNOLDS,N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS,N S Mississippi Power & Light Co DSB 723 84/08/01
GROSSMAN,H , CARPENTER,J H , MORRIS,P A Atomic Safety and Licensing Board Panel 2pp 25905 361 24X Fiche 50-416,84/08/01,8408030081

8408070477 Status rept advising ASLP of all unresolved matters preparatory to hearing & suggesting date for scheduling final prehearing conference & hearing,in response to 840423 order Certificate of Svc encl Related correspondence
YOUNG,M A Hearing Branch 4 DSB 812 84/08/01 6pp 25941 200
24X Fiche 50-416,84/08/01,8408070477

8408090145 Responds to 840630 ltr indicating decision against filing formal petition in proceeding Commission authorized issuance of full power license for util at Commission 840731 meeting Served on 840808
MALSCH,M G Office of the General Counsel DSB 862 84/08/07
GUSTE,W J Louisiana, State of 1p 25972 292 24X
Fiche 50 416,84/08/07,8408090145

-8408090154 Informs of decision not to file formal petition until receipt of NRC documentation of licensee resolution of all safety items Response to MK Udall 840726 ltr requested
GUSTE,W J Louisiana, State of 84/07/30 PALLADINO,N J
Commissioners 2pp 25972 293 24X Fiche 50-416,84/08/07, 8408090145

General correspondence

8408070041 Discusses NRC actions taken to resolve concerns expressed in constituent WC Smith 840518 ltr re NRC licensing procedures, in response to 840531 inquiry Licensing proceeding as expeditiously as possible
DIRCKS,W J Office of the Executive Director for Operations
84/07/26 JOHNSTON,J B Senate 5pp 25955 340 24X
Fiche 50-416,84/07/26,8408070041

--8408070048 Forwards constituent WC Smith 840518 ltr urging expeditious licensing of facility Response & comments requested by 840626
JOHNSTON,J B Senate 84/05/31 KAMMERER,C Office of Congressional Affairs 7pp 25955 314 24X Fiche 50-416, 84/07/26,8408070041

P Operating license stage documents & correspondence

8408300413 Confirms 840503 telcon re 840510 mgt meeting in Region II ofc to discuss depth & scope of QA audit & nuclear plant engineering review of safety issues
LEWIS,R C Region 2, Office of Director 84/05/04 RICHARD,J B
Mississippi Power & Light Co 1p 26308 206 24X
Fiche 50-416,84/05/04 8408300413

8408300371 Forwards summary of 840510 mgt meeting w/util in Region II ofc re depth & scope of QA audits & safety-related engineering evaluations by nuclear plant engineering Attendance list encl
O'REILLY,J P Region 2, Office of Director 84/05/25 RICHARD,J B
Mississippi Power & Light Co 4pp 26308 240 24X
Fiche 50-416,84/05/25,8408300371

8408300435 Confirms 840606 telcon w/SH Hobbs re 840608 mgt meeting in Region II ofc to discuss resolution of Tech Spec questions
LEWIS,R C Region 2, Office of Director 84/06/07 RICHARD,J B
Mississippi Power & Light Co 1p 26314 307 24X
Fiche 50-416,84/06/07,8408300435

8408060174 Forwards results of DBA test & detailed comparison of GE Nine Mile Point qualification requirements vs requirements for util GE safety relief valve solenoid failure inapplicable to Grand Gulf
DALE,L F Mississippi Power & Light Co 84/07/30 EISENHUT,D G
Division of Licensing 7pp 25932 185 24X Fiche 50-416,84/07/30, 8408060174

8408080216 Staff requirements memo re 840731 discussion/possible vote on full power OL in Washington,DC Commission voted 4-0 to authorize staff to issue full power OL amend
CHILK,S J Office of the Secretary of the Commission 84/08/01
DIRCKS,W J Office of the Executive Director for Operations 1p
25978 326 24X Fiche 50-416,84/08/01,8408080216

8408030075 Submits supplemental info in support of util 840728 request for schedular exemption from 10CFR50,App A,GDC 17 for Items II C,D & E re Divs I,II & III diesel generators
DALE,L F Mississippi Power & Light Co 84/08/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 25904 355
24X Fiche 50-416,84/08/02,8408030075

8408030095 Provides schedule for submittal of turbocharger inlet temp info Installation of temp measuring instrumentation & data retrieval & evaluation will be completed by Aug 1984 Results will be submitted within 30 days
DALE,L F Mississippi Power & Light Co 84/08/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 25904 358
24X Fiche 50-416,84/08/02,8408030095

8408030103 Forwards addl info re design of combustion air intake & exhaust sys for standby diesel generators Design provides assurance that sys capable of performing function
DALE,L F Mississippi Power & Light Co 84/08/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 25904 339
24X Fiche 50-416,84/08/02,8408030103

8408060249 Forwards supplemental info re standby diesel generator combustion air intake & exhaust sys,per 840802 discussions, superseding info in 840802 ltr (AECM-84/0389)
DALE,L F Mississippi Power & Light Co 84/08/03 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 25933 350
24X Fiche 50-416,84/08/03,8408060249

8408070404 Forwards supplemental info re qualification of safety relief valves (SRV),Seitz solenoid valves Interim operation justified until SRV solenoid valves fully qualified,per NUREG-0588 & 10CFR50 49
DALE,L F Mississippi Power & Light Co 84/08/05 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 25942 177
24X Fiche 50-416,84/08/05,8408070404

8408070436 Submits clarification re procedural changes concerning diesel generator loading Standby diesel generators will be loaded in excess of 5,740/kW only if action necessary to achieve or maintain plant in safe shutdown condition
DALE,L F Mississippi Power & Light Co 84/08/05 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 25942 359
24X Fiche 50-416,84/08/05,8408070436

8408070486 Forwards comments on draft Amend 13 to Tech Specs re principal gamma emitters, in response to 840803 request for review Amend acceptable
RICHARD, J B Mississippi Power & Light Co 84/08/05 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25940 327
24X Fiche 50-416, 84/08/05, 8408070486

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408070430 Submits addl info requested in NRC 840604 ltr re review assignments & responsibilities for senior reactor operators & description of steps taken during Tech Spec review program
DALE, L F Mississippi Power & Light Co 84/08/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25940 092
24X Fiche 50-416, 84/08/06, 8408070430

8408140116 Forwards "Potential Environ Impact Associated W/Requested Exemptions" re 840728 & 0802 App J & diesel generator electrical protection exemption requests
DALE, L F Mississippi Power & Light Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp 26065 134
24X Fiche 50-416, 84/08/07, 8408140116

8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 1, "Sequoyah Nuclear Plant Containment Analysis," for Meeting 3B Rept inconsistent w/four encl repts previously sent
FONTANA, M H Technology for Energy Corp 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26234 001
24X Fiche 50-000, 84/08/07, 8408230097

--8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants," technical rept
* Industry Degraded Core Rulemaking Program FAI/84-9 DRFT 84/07/31 114pp 26234 231 24X Fiche 50-000, 84/08/07, 8408230097

--8408230119 Draft "Grand Gulf Nuclear Station Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/08/07 175pp 26235 094 24X Fiche 50-000, 84/08/07, 8408230097

8408300428 Grants 840727 request for extension to 841029 for correction of improper use of words should & must in plant administrative procedures
LEWIS, R C Region 2, Office of Director 84/08/10 DALE, L F
Mississippi Power & Light Co 2pp 26314 333 24X
Fiche 50-416, 84/08/10, 8408300428

8408150160 Responds to 840808 request for review of proposed Amend 13 to License NPF-13 Schedules consistant w/previous commitments Lists three addl comments
RICHARD, J B Mississippi Power & Light Co 84/08/11 NOVAK, T M
Assistant Director for Licensing 2pp 26066 314 24X
Fiche 50-416, 84/08/11, 8408150160

8408150201 Requests schedular exemption from 10CFR50, App J Justification & environ assessment encl
DALE, L F Mississippi Power & Light Co 84/08/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 17pp 26066 119
24X Fiche 50-416, 84/08/13, 8408150201

8408150151 Forwards additions to Tech Spec Table 3 8 4 1-1 re primary containment penetration conductor overcurrent protective devices, per 840805 final draft of Amend 13 to License NPF-13
DALE, L F Mississippi Power & Light Co 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 26066 316 24X
Fiche 50-416, 84/08/14, 8408150151

--8408150154 Additions to Tech Spec Table 3 8 4 1-1 re primary containment penetration conductor overcurrent protective devices
* Mississippi Power & Light Co 84/08/14 2pp 26066 317 24X
Fiche 50-416, 84/08/14, 8408150151

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408310222 Withdraws 840813 request for exemption from requirements of App J to 10CFR50 Updated feedwater isolation valve leak rate test results meet requirements of App J for Types B & C testing Exemption unnecessary
DALE, L F Mississippi Power & Light Co 84/08/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26319 257
24X Fiche 50-416, 84/08/30, 8408310222

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408280137 Responds to IE Bulletin 84-02 re failures of GE Type HFA relays in Class 1E safety sys All normally energized safety-related HFA relays w/Lexan coil spools replaced w/Tefzel spools
MCGAUGHY, J P Mississippi Power & Light Co 84/07/27
O'REILLY, J P Region 2, Office of Director 3pp 26279 184 24X
Fiche 50-416, 84/07/27, 8408280137

8408270257 Ack receipt of 840706 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-417/84-04
LEWIS, R C Region 2, Office of Director 84/08/01 DALE, L F
Mississippi Power & Light Co 1p 26258 143 24X
Fiche 50-417, 84/08/01, 8408270257

--8408270268 Forwards Insp Repts 50-416/84-19 & 50-417/84-04 on 840515-18 & notice of violation
LEWIS, R C Region 2, Office of Director 84/06/08 RICHARD, J B
Mississippi Power & Light Co 2pp 26258 146 24X
Fiche 50-417, 84/08/01, 8408270257

--8408270275 Insp Repts 50-416/84-19 & 50-417/84-04 on 840515-18 Violation noted failure to control welding in accordance w/applicable specs, criteria & other special requirements
CROWLEY, B R , BLAKE, J J Region 2, Office of Director 84/06/04
10pp 26258 149 24X Fiche 50-417, 84/08/01, 8408270257

8408270313 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-416/84-16
LEWIS, R C Division of Project & Resident Programs 84/08/02
DALE, L F Mississippi Power & Light Co 1p 26257 235 24X
Fiche 50-416, 84/08/02, 8408270313

--8408270321 Responds to NRC 840614 ltr re violations noted in Insp Rept 50-416/84-16 Corrective actions safety & environ evaluation performed, procedures for work control to be revised & site QA audit rept reviewed
DALE, L F Mississippi Power & Light Co 84/07/13 O'REILLY, J P
Region 2, Office of Director 10pp 26257 236 24X
Fiche 50-416, 84/08/02, 8408270313

--8408270326 Forwards Insp Rept 50-416/84-16 on 840326-0427 & notice of violation & deviation
LEWIS, R C Division of Project & Resident Programs 84/06/14
RICHARD, J B Mississippi Power & Light Co 2pp 26257 246 24X
Fiche 50-416, 84/08/02, 8408270313

--8408270333 Notice of violation from insp on 840326-0427
* Region 2, Office of Director 84/06/14 2pp 26257 248 24X
Fiche 50-416, 84/08/02, 8408270313

--8408270340 Notice of deviation from insp on 840326-0427,
* Region 2, Office of Director 84/06/14 1P 26257 250 24X
Fiche 50-416, 84/08/02, 8408270313

--8408270347 Insp Rept 50-416/84-16 on 840326-0427 Violations noted failure to perform procedure change safety evaluation, to follow procedures, to provide implementing procedure, to conduct audit & to train technician
WAGNER, A G , CALDWELL, J L , CARROLL, R Region 2, Office of Director 84/05/31 12pp 26257 251 24X Fiche 50-416, 84/08/02, 8408270313

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 12Opp 26127 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far
ASSELSTINE, J K Commissioners 84/08/10 MARKEY, E J House of Rep , Interior & Insular Affairs 4pp 26141 244 24X Fiche 50-000, 84/08/10, 8408200225

--8408200263 Forwards IE Insp Rept 50-416/84-11 on 840328-30 & notice of deviation
LEWIS, R C Division of Project & Resident Programs 84/04/24 RICHARD, J B Mississippi Power & Light Co 2pp 26141 330 24X Fiche 50-000, 84/08/10, 8408200225

--8408200267 Notice of deviation from insp on 840328-30
* Region 2, Office of Director 84/04/24 1p 26141 332 24X Fiche 50-000, 84/08/10, 8408200225

--8408200271 IE Insp Rept 50-416/84-11 on 840328-30 Deviation noted no surveillance procedure established to periodically test remote shutdown control components & components not tested since preoperational testing
CALDWELL, J L , HEHL, C W , JULIAN, C A Region 2, Office of Director 84/04/24 7pp 26141 333 24X Fiche 50-000, 84/08/10, 8408200225

8408280196 Provides supplemental response to IE Bulletin 81-01 Six snubbers reported as having excessive noise during stroke or requiring above average force to complete stroke functionally tested on Bergen-Paterson test machine
RICHARD, J B Mississippi Power & Light Co 84/08/10 O'REILLY, J P Region 2, Office of Director 5pp 26275 221 24X Fiche 50-416, 84/08/10, 8408280196

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26147 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408240021 Forwards Grand Gulf 1984 IE insp repts, per 840705 request NRC repts on allegations of falsification of training records forwarded to DOJ Rept contents withheld from public disclosure W/o encl
DEYOUNG, R D Director's Office, Office of Inspection and Enforcement 84/08/16 WALDRUM, R L Alaska, State of 4pp 26235 353 24X Fiche 50-000, 84/08/16, 8408240021

--8408240026 Requests NRC safety investigation repts for past 8 months & notification of current investigations Info needed to determine possible financial effect on State of AK, which may need to fund & buy energy from facilities
WALDRUM, R L Alaska, State of 84/07/05 PALLADINO, N Commissioners 1p 26235 354 24X Fiche 50-000, 84/08/16, 8408240021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408210105 Monthly operating rept for Jul 1984 W/840813 ltr
CESARE, J G , DALE, L F Mississippi Power & Light Co 84/07/31 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 7pp 26184 202 24X Fiche 50-416, 84/07/31, 8408210105

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000, 84/05/24, 8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000, 84/05/24, 8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000, 84/05/24, 8405290179

--8405290271 "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
* Failure Analysis Associates FAAA-84-3-16 84/05/22 89pp 24692 092 24X Fiche 50-000, 84/05/24, 8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER, M Division of Licensing 158pp 25926 173 24X Fiche 50-000, 84/06/28, 8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/ TDI Diesel Generator Owners Group 840622 meeting
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/07/10 BERLINGER, C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000, 84/07/10, 8408060050

8408090163 Special Rept 84-026/0 on 840613 & 0616-0703, upper control room temp exceeded Tech Spec limit of 77 F for 8 h Control room equipment suffered no effects
DALE, L F Mississippi Power & Light Co 84/07/12 O'REILLY, J P Region 2, Office of Director 2pp 25994 324 24X Fiche 50-416, 84/07/12, 8408090163

8408090137 Special Rept 84-027/0 on 840615, fire-rated penetrations AE-258D, AE-257D & AE-6D opened to implement design change package Seven-day limiting condition for operation time limit exceeded Fire watch established
DALE, L F Mississippi Power & Light Co 84/07/18 O'REILLY, J P Region 2, Office of Director 1p 25993 162 24X Fiche 50-416, 84/07/18, 8408090137

8408060030 LER 84-032-00 on 840628, during reactor vessel nuclear heatup, data taken to determine condensate pot movement on vessel level instrumentation Revised calibr procedures found three transmitters outside Tech Spec limits W/840727 ltr
BYRD, R W , DALE, L F Mississippi Power & Light Co 84/07/27 3pp 25935 272 24X Fiche 50-416, 84/07/27, 8408060030

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group RAY, C L Duke Power Co 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000, 84/07/27, 8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000, 84/07/27, 8408060102

8408060185 Forwards LER 84-031 01 & Rept on Investigation Performed to Determine Unit 1 Dependence on Unit 2 Sys,Structures & Components "
DALE,L F Mississippi Power & Light Co 84/07/27 Record Services Branch (Document Control Desk) 1p 25935 178 24X Fiche 50-416,84/07/27,8408060185

--8408060193 LER 84-031-01 on 840601,plant shutdown commenced following notification to NRC of deficiency re low flow rate in standby svc water sys due to higher than anticipated frictional pressure drops through component loop
BYRD,R W Mississippi Power & Light Co 84/07/27 2pp 25935 179 24X Fiche 50-416,84/07/27,8408060185

--8408060200 Rev 2 to "Rept on Investigation Performed to Determine Unit 1 Dependence on Unit 2 Sys,Structures & Components "
BLACK,K M Mississippi Power & Light Co 84-M-004 R02 84/07/17 6pp 25935 181 24X Fiche 50-416,84/07/27 8408060185

8408130371 Special Rept 84-028/0 on 840627,Div 1 diesel generator tripped at 50% load Caused by grounding of Phase B linear reactor of voltage transformer Div 1 diesel generator A,B & C phase reactors replaced
DALE,L F Mississippi Power & Light Co 84/07/27 O'REILLY,J P Region 2, Office of Director 2pp 26005 300 24X Fiche 50-416,84/07/27,8408130371

8408030120 Supplemental RO on 840726,while performing routine maint on Div 1 TDI diesel engine,water observed coming from open cylinder cock on left bank cylinder head 7 Caused by 2-inch crack in right exhaust port casting Head replaced
DALE,L F Mississippi Power & Light Co 84/07/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25916 110 24X Fiche 50-416,84/07/30,8408030120

8408130365 Updated Special Rept 84-022/1 on 840429,auxiliary main steam tunnel temps exceeded 125 F limit of Tech Spec 3 7 8 Task cards will be issued to track new qualified life of each affected component
DALE,L F Mississippi Power & Light Co 84/07/30 O'REILLY,J P Region 2, Office of Director 2pp 26011 089 24X Fiche 50-416,84/07/30,8408130365

8408080538 LER 84-033-00 on 840702,reactor scram & secondary containment isolation occurred Caused by closed air dryer outlet valve P53-F496 Instructions will be revised to require locked open valve W/840731 ltr
BYRD,R W , DALE,L F Mississippi Power & Light Co 84/07/31 3pp 25975 313 24X Fiche 50-416,84/07/31,8408080538

8408160421 Final Deficiency Rept PRD-81/17 re flow rate in standby svc water sys loops A & B & loss of standby svc water basin transfer capability Initially reported on 810303 Also reportable per Part 21
RICHARD,J B Mississippi Power & Light Co 84/07/31 O'REILLY,J P Region 2, Office of Director 5pp 26106 076 24X Fiche 50-416,84/07/31,8408160421

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group RAY,C L Duke Power Co 84/08/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24X Fiche 50-000,84/08/01, 8408060324

8408060189 Confirms completion of listed 840720 & 26 commitments re TDI diesel generators Correction of deficiencies noted during confirmatory walkdown of engine fuel oil lines completed
DALE,L F Mississippi Power & Light Co 84/08/03 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25932 286 24X Fiche 50-416,84/08/03,8408060189

8408160061 Final Deficiency Rept PRD-84/10 re possible swelling of GH Bettis valve actuator ethylene propylene rubber elastomer seals in contact w/hydrocarbon lubricant Initially reported on 840730 Reportable under Part 21 for Unit 1
RICHARD,J B Mississippi Power & Light Co 84/08/03 O'REILLY,J P Region 2, Office of Director 5pp 26108 219 24X Fiche 50-416,84/08/03,8408160061

8408160175 LER 84-024-01 on 840502,shutdown occurred Caused by inoperability of both independent containment spray loops of RHR sys Operating procedures changed & two pipe supports reworked W/840808 ltr
BYRD,R W , DALE,L F Mississippi Power & Light Co 84/08/08 4pp 26108 051 24X Fiche 50-416,84/08/08,8408160175

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group RAY,C L Duke Power Co 84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10, 8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp 26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program testing & insp, maint & surveillance " sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval Inc) Owners Group GEORGE,J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 1p 26255 194 24X Fiche 50-000,84/08/13,8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation,plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp 26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final GA verified rept Addl copy forwarded to BNWL,per NRC request
RAY,C L TDI (Transamerica Delaval Inc) Owners Group RAY,C L Duke Power Co 84/08/14 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000,84/08/14, 8408160395

--8408160397 "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA 84-5-7 84/07/31 61pp 26088 165 24X Fiche 50-000,84/08/14,8408160395

8408240210 LER 84-034-00 on 840719,during nonroutine test,reactor protection sys motor generator set A output breaker tripped, resulting in isolation of both shutdown cooling loops Caused by personnel clumsiness Power restored W/840820 ltr
BYRD,R W , DALE,L F Mississippi Power & Light Co 84/08/20 3pp 26236 294 24X Fiche 50-416,84/08/20,8408240210

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group RAY,C L Duke Power Co 84/08/23 BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000,84/08/23, 8408290179

8408300490 LER 84-035-00 on 840519,analyses performed on radioactive gaseous waste samples discovered to be inadequate,causing surveillance test frequency to be exceeded Caused by personnel error Software to be modified W/840824 ltr
DALE,L F , BYRD,R W Mississippi Power & Light Co 84/08/24 3pp 26314 086 24X Fiche 50-416,84/08/24,8408300490

T Hearing transcripts on non-antitrust matters

8406220259 Board Notification 84-120 Forwards transcripts of 840426, 0502 & 24 meetings w/TDI Owners Group re status of program to establish diesel generator reliability
EISENHUT,D G Division of Licensing 84/06/20 PALLADINO, GILINSKY, ROBERTS Commissioners 54pp 25206 099 24X Fiche 50-000,84/06/20,8406220259

8408130013 Transcript of 840731 open meeting in Washington,DC re discussion & vote on full power OL Pp 1-114 Supporting documentation encl
* Commissioners 84/07/31 129pp 26059 102 24X Fiche 50-416,84/07/31,8408130013

U Congressional/Executive Correspondence

8408080430 Responds to 840531 ltr raising concerns re NRC 840522 order & continued low power operation in spite of outstanding issues of compliance w/GDC 17 Asselstine opinion encl
PALLADINO,N J Commissioners 84/07/23 MARKEY,E J House of Rep , Interior & Insular Affairs 3pp 25977 184 24X Fiche 50-416,84/07/23,8408080430

--8408080432 Expresses concern re NRC apparent abandonment of agency regulations w/licensing of plant Overwhelming weight of evidence treates impression that operation of plant constitutes violation of NRC regulations
MARKEY,E J House of Rep Interior & Insular Affairs 84/05/31
PALLADINO,N J Commissioners 2pp 25977 187 24X
Fiche 50-416,84/07/23,8408080430

8408070201 Responds to 840522 ltr re plant problems & estimate of when plant fully operational Commission meeting for briefing & possible vote on full-power OL scheduled on 840731
DIRCKS,W J Office of the Executive Director for Operations
84/07/27 BETHUNE,E House of Rep 3pp 25957 066 24X
Fiche 50-416,84/07/27,8408070201

--8408070207 Requests encl Insert A re minor plant problems not delaying full power licensing be placed in Dircks 840727 ltr draft
SCINTO,J NRC - No Detailed Affiliation Given 84/07/02
ADENSAM,E NRC - No Detailed Affiliation Given 3pp 25957 071
24X Fiche 50-416,84/07/27,8408070201

--8408070215 Requests info re spec & surveillance problems at plant & estimate of when plant will be fully operational
BETHUNE,E House of Rep 84/03/22 PALLADINO,N Commissioners
1p 25957 075 24X Fiche 50-416,84/07/27,8408070201

8408130202 Responds to 840330 ltr re deficiencies at facility NRC unaware of serious defects at plant Enforcement action still pending re matl false statements in operator records
DIRCKS,W J Office of the Executive Director for Operations
84/07/31 ANTHONY,B House of Rep 46pp 26060 166 24X
Fiche 50-416,84/07/31,8408130202

--8408130210 Requests info re deficiencies in design & const of plant & in qualification & training of staff Raises concerns on possibility of higher costs being passed on to constituents
ANTHONY,B House of Rep 84/03/30 PALLADINO,N J
Commissioners 4pp 26060 213 24X Fiche 50-416,84/07/31,
8408130202

8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far
ASSELSTINE,J K Commissioners 84/08/10 MARKEY,E J House of
Rep , Interior & Insular Affairs 4pp 26141 244 24X
Fiche 50-000,84/08/10,8408200225

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8408030106 Forwards summary of environ protection program re const of station for 2-month period ending 840630,per Exhibit 2-A referenced in Subsection 3 E 1 of CPPR-119
DALE,L F Mississippi Power & Light Co 84/07/30 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 25916 084
24X Fiche 50-417,84/07/30,8408030106

8408060174 Forwards results of DBA test & detailed comparison of GE Nine Mile Point qualification requirements vs requirements for util GF safety relief valve solenoid failure inapplicable to Grand Gulf
DALE,L F Mississippi Power & Light Co 84/07/30 EISENHUT,D G
Division of Licensing 7pp 25932 185 24X Fiche 50-416,84/07/30,
8408060174

8408030075 Submits supplemental info in support of util 840728 request for schedular exemption from 10CFR50,App A,GDC 17 for Items II C,D & E re Divs I,II & III diesel generators
DALE,L F Mississippi Power & Light Co 84/08/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 25904 355
24X Fiche 50-416,84/08/02,8408030075

8408030095 Provides schedule for submittal of turbocharger inlet temp info Installation of temp measuring instrumentation & data retrieval & evaluation will be completed by Aug 1984 Results will be submitted within 30 days
DALE,L F Mississippi Power & Light Co 84/08/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 25904 358
24X Fiche 50-416,84/08/02,8408030095

8408030103 Forwards addl info re design of combustion air intake & exhaust sys for standby diesel generators Design provides assurance that sys capable of performing function
DALE,L F Mississippi Power & Light Co 84/08/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 25904 339
24X Fiche 50-416,84/08/02,8408030103

8408060249 Forwards supplemental info re standby diesel generator combustion air intake & exhaust sys,per 840802 discussions, superseding info in 840802 ltr (AECM-84/0389)
DALE,L F Mississippi Power & Light Co 84/08/03 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 25933 350
24X Fiche 50-416,84/08/03,8408060249

8408070404 Forwards supplemental info re qualification of safety relief valves (SRV),Seitz solenoid valves Interim operation justified until SRV solenoid valves fully qualified,per NUREG-0588 & 10CFR50 49
DALE,L F Mississippi Power & Light Co 84/08/05 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 25942 177
24X Fiche 50-416,84/08/05,8408070404

8408070436 Submits clarification re procedural changes concerning diesel generator loading Standby diesel generators will be loaded in excess of 5,740/kW only if action necessary to achieve or maintain plant in safe shutdown condition
DALE,L F Mississippi Power & Light Co 84/08/05 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 25942 359
24X Fiche 50-416,84/08/05,8408070436

8408070486 Forwards comments on draft Amend 13 to Tech Specs re principal gamma emitters,in response to 840803 request for review Amend acceptable
RICHARD,J D Mississippi Power & Light Co 84/08/05 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25940 327
24X Fiche 50-416,84/08/05,8408070486

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408070430 Submits addl info requested in NRC 840604 ltr re review assignments & responsibilities for senior reactor operators & description of steps taken during Tech Spec review program
DALE,L F Mississippi Power & Light Co 84/08/06 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25940 052
24X Fiche 50-416,84/08/06,8408070430

8408140116 Forwards "Potential Environ Impact Associated W/Requested Exemptions" re 840728 & 0802 App J & diesel generator electrical protection exemption requests
DALE,L F Mississippi Power & Light Co 84/08/07 DENTON,H R
Office of Nuclear Reactor Regulation, Director 11pp 26065 134
24X Fiche 50-416,84/08/07,8408140116

8408230097 Forwards draft Industry Degraded Core Rulemaking Program Technical Rept 23 1, "Sequoyah Nuclear Plant Containment Analysis," re Meeting 38 Rept inconsistent w/four encl repts previously sent
FONTANA,M H Technology For Energy Corp 84/08/07 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 26234 001
24X Fiche 50-000,84/08/07,8408230097

--8408230112 Draft "Evaluation of Containment Bypass & Failure to Isolate Sequences for Industry Degraded Core Rulemaking Program Ref Plants," technical rept
* Industry Degraded Core Rulemaking Program FAI/84-9 DRFT
84/07/31 114pp 26234 231 24X Fiche 50-000,84/08/07,
8408230097

--8408230119 Draft "Grand Gulf Nuclear Station Integrated Containment Analysis," technical rept
* Industry Degraded Core Rulemaking Program 84/08/07 175pp
26235 094 24X Fiche 50-000,84/08/07,8408230097

8408300428 Grants 840727 request for extension to 841029 for correction of improper use of words should & must in plant administrative procedures
LEWIS,R C Region 2, Office of Director 84/08/10 DALE,L F
Mississippi Power & Light Co 2pp 26314 333 24X
Fiche 50-416,84/08/10,8408300428

8408150201 Requests schedular exemption from 10CFR50,App J Justification & environ assessment encl
DALE,L F Mississippi Power & Light Co 84/08/13 DENTON,H R
Office of Nuclear Reactor Regulation, Director 17pp 26066 119
24X Firhe 50-416,84/08/13,8408150201

8408200127 Application to amend CPPR-119,extending latest const completion date to 910430 Fee for Class II CP amend encl
RICHARD,J B Mississippi Power & Light Co 84/08/15 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 26132 305
24X Fiche 50-417,84/08/15,8408200127

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408310222 Withdraws 840813 request for exemption from requirements of App J to 10CFR50 Updated Feedwater isolation valve leak rate test results meet requirements of App J for Types B & C testing Exemption unnecessary
DALE,L F Mississippi Power & Light Co 84/08/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26319 257 24X Fiche 50-416,84/08/30,8408310222

F Security, medical, emergency & fire protection plans

8408280143 Revised emergency plan procedures, including 10-S-01-23 re emergency plan training & drills safety-related,& 2 re alert nonsafety-related & & 3 re site emergency nonsafety-related W/840820 ltr
HURLEY,J Mississippi Power & Light Co 84/07/27 O'REILLY,J P Region 2, Office of Director 27pp 26279 153 24X Fiche 50-416,84/07/27,8408280143

8408080138 Forwards "Grand Gulf Nuclear Power Station Exercise," of offsite radiological emergency conducted on 840411 Meeting held on 840531 w/util & State of MS to discuss deficiency re coordination of issuance of public info
KRIMM,R W Federal Emergency Management Agency 84/07/30 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 25960 266 24X Fiche 50-416,84/07/30, 8408080138

--8408080141 "Grand Gulf Nuclear Power Station Exercise," conducted on 840411
* Federal Emergency Management Agency 84/04/24 69pp 25960 269 24X Fiche 50-416,84/07/30,8408080138

8408210151 Rev 4 to Vol 10 to Procedure 10-S-01-25, "Onsite Personnel Response " W/840813 ltr
DALE,L F Mississippi Power & Light Co 84/08/13 O'REILLY,J P Region 2, Office of Director 9pp 26181 307 24X Fiche 50-416,84/08/13,8408210151

G Adjudicatory correspondence

8408130150 Forwards addl info re Commission 840717 responses to Questions 1(B) & 1(F) of EJ Markey 840313 ltr Addl info on development of Tech Specs encl
RICHARD,J B Mississippi Power & Light Co DSB 929 84/07/23 PALLADINO,N J Commissioners 20pp 26010 338 24X Fiche 50-416,84/07/23,8408130150

8408010196 Expresses official position of State of LA that decision to license facility should be made by NRC based on safety, rules & regulations & scientific findings Representations by state atty general should be disregarded
EDWARDS,E W Louisiana, State of DSB 683 84/07/27 PALLADINO,N J Commissioners 1p 25854 353 24X Fiche 50-416,84/07/27,8408010196

8408070477 Status rept advising ASLP of all unresolved matters preparatory to hearing & suggesting date for scheduling final prehearing conference & hearing, in response to 840423 order Certificate of Svc encl Related correspondence
YOUNG,M A Hearing Branch 4 DSB 812 84/08/01 6pp 25941 200 24X Fiche 50-416,84/08/01,8408070477

8408090145 Responds to 840630 ltr indicating decision against filing formal petition in proceeding Commission authorized issuance of full power license for util at Commission 840731 meeting Served on 840808
MALSCH,M G Office of the General Counsel DSB 852 84/08/07 GUSTE,W J Louisiana, State of 1p 25972 292 24X Fiche 50-416,84/08/07,8408090145

--8408090154 Informs of decision not to file formal petition until receipt of NRC documentation of licensee resolution of all safety items Response to MK Udall 840726 ltr requested
GUSTE,W J Louisiana, State of 84/07/30 PALLADINO,N J Commissioners 2pp 25972 293 24X Fiche 50-416,84/08/07, 8408090145

O Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408280137 Responds to IE Bulletin 84-02 re failures of GE Type HFA relays in Class 1E safety sys All normally energized safety-related HFA relays w/Lexan coil spools replaced w/Tefzel spools
MCGAUGHY,J F Mississippi Power & Light Co 84/07/27 O'REILLY,J P Region 2, Office of Director 3pp 26275 184 24X Fiche 50-416,84/07/27,8408280137

8408270257 Ack receipt of 840706 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-417/84-04
LEWIS,R C Region 2, Office of Director 84/08/01 DALE,L F Mississippi Power & Light Co 1p 26258 143 24X Fiche 50-417,84/08/01,8408270257

--8408270263 Responds to NRC 840608 ltr re violations noted in Insp Rept 50-417/84-04 Corrective actions Bechtel Field Welding Engineering & QC halted work on Field Weld 31 Nonconformance Rept NRC 6784 initiated to track cited condition
DALE L F Mississippi Power & Light Co 84/07/06 O'REILLY,J P Region 2, Office of Director 2pp 26258 144 24X Fiche 50-417,84/08/01,8408270257

--8408270268 Forwards Insp Repts 50-416/84-19 & 50-417/84-04 on 840515-18 & notice of violation
LEWIS,R C Region 2, Office of Director 84/06/08 RICHARD,J B Mississippi Power & Light Co 2pp 26258 146 24X Fiche 50-417,84/08/01,8408270257

--8408270272 Notice of violation from Insp on 840515-18
* Region 2, Office of Director 84/06/08 1p 26258 148 24X Fiche 50-417,84/08/01,8408270257

--8408270275 Insp Repts 50-416/84-19 & 50-417/84-04 on 840515-18 Violation noted failure to control welding in accordance w/applicable specs,criteria & other special requirements
CROWLEY,B R , BLAKE,J J Region 2, Office of Director 84/06/04 10pp 26258 149 24X Fiche 50-417,84/08/01,8408270257

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 198 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408240021 Forwards Grand Gulf 1984 IE insp repts,per 840705 request NRC repts on allegations of falsification of training records forwarded to DOJ Rept contents withheld from public disclosure W/o encl
DEYOUNG,R D Director's Office, Office of Inspection and Enforcement 84/08/16 WALDRUM,R L Alaska, State of 4pp 26255 353 24X Fiche 50-000,84/08/16,8408240021

--8408240026 Requests NRC safety investigation repts for past 8 months & notification of current investigations Info needed to determine possible financial effect on State of AK, which may need to fund & buy energy from facilities
WALDRUM, R L Alaska State of 84/07/05 PALLADINO, N Commissioners 1p 26255 354 24X Fiche 50-000, 84/08/16, 8408240021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12Opp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12Zpp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000, 84/05/24, 8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000, 84/05/24, 8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000, 84/05/24, 8405290179

--8405290271 "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
* Failure Analysis Associates FAAA-84-3-16 84/05/22 89pp
24692 092 24X Fiche 50-000, 84/05/24, 8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER, M Division of Licensing 158pp
25926 173 24X Fiche 50-000, 84/06/28, 8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER, C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000, 84/07/10, 8408060050

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000, 84/07/27, 8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000, 84/07/27, 8408060102

8408060185 Forwards LER 84-031-01 & "Rept on Investigation Performed to Determine Unit 1 Dependence on Unit 2 Sys, Structures & Components "
DALE, L F Mississippi Power & Light Co 84/07/27 Record Services Branch (Document Control Desk) 1p 25935 178 24X
Fiche 50-416, 84/07/27, 8408060185

--8408060200 Rev 2 to "Rept on Investigation Performed to Determine Unit 1 Dependence on Unit 2 Sys, Structures & Components "
BLACK, K M Mississippi Power & Light Co 84-M-004 R02 84/07/17
6pp 25935 181 24X Fiche 50-416, 84/07/27, 8408060185

8408030120 Supplemental RO on 840726 while performing routine maint on Div 1 TDI diesel engine, water observed coming from open cylinder cock on left bank cylinder head 7 Caused by 2-inch crack in right exhaust port casting Head replaced
DALE, L F Mississippi Power & Light Co 84/07/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 25916 110
24X Fiche 50-416, 84/07/30, 8408030120

8408160421 Final Deficiency Rept PRD-81/17 re flow rate in standby svc water sys loops A & B & loss of standby svc water basin transfer capability Initially reported on 810303 Also reportable per Part 21
RICHARD, J B Mississippi Power & Light Co 84/07/31 O'REILLY, J P
Region 2, Office of Director 5pp 26106 076 24X
Fiche 50-416, 84/07/31, 8408160421

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000, 84/08/01, 8408060324

8408060189 Confirms completion of listed 840720 & 26 commitments re TDI diesel generators Correction of deficiencies noted during confirmatory walkdown of engine fuel oil lines completed
DALE, L F Mississippi Power & Light Co 84/08/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 25932 286
24X Fiche 50-416, 84/08/03, 8408060189

8408160061 Final Deficiency Rept PRD-84/10 re possible swelling of GH Bettis valve actuator ethylene propylene rubber elastomer seals in contact w/hydrocarbon lubricant Initially reported on 840730 Reportable under Part 21 for Unit 1
RICHARD, J B Mississippi Power & Light Co 84/08/03 O'REILLY, J P
Region 2, Office of Director 5pp 26108 219 24X
Fiche 50-416, 84/08/03, 8408160061

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000, 84/08/10, 8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000, 84/08/10, 8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT, D G Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000, 84/08/13, 8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000, 84/08/13, 8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL per NRC request
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14,
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000, 84/08/14, 8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp,
26088 165 24X Fiche 50-000, 84/08/14, 8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER, C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000, 84/08/23, 8408290179

U Congressional/Executive Correspondence

8408080430 Responds to 840531 ltr raising concerns re NRC 840522 order & continued low power operation in spite of outstanding issues of compliance w/OIC 17 Asselstine opinion encl
PALLADINO, N J Commissioners 84/07/23 MARKEY, E J House of Rep , Interior & Insular Affairs 3pp 25977 184 24X
Fiche 50-416, 84/07/23, 8408080430

--8408080432 Expresses concern re NRC apparent abandonment of agency regulations w/licensing of plant Overwhelming weight of evidence creates impression that operation of plant constitutes violation of NRC regulations
MARKEY,E J House of Rep Interior & Insular Affairs 84/05/31
PALLADINO,N J Commissioners 2pp 25977 187 24X
Fiche 50-416,84/07/23,8408080430

8408070201 Responds to 840522 ltr re plant problems & estimate of when plant fully operational Commission meeting for briefing & possible vote on full-power OL scheduled on 840731
DIRCKS,W J Office of the Executive Director for Operations
84/07/27 BETHUNE,E House of Rep 3pp 25957 066 24X
Fiche 50-416,84/07/27,8408070201

--8408070215 Requests info re spec & surveillance problems at plant & estimate of when plant will be fully operational
BETHUNE,E House of Rep 84/03/22 PALLADINO,N Commissioners
1p 25957 075 24X Fiche 50-416,84/07/27,8408070201

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8408070220 Forwards FSAR Table 3 9B-9B re loading combinations for ASME III Class 1,2 & 3 component supports,per 840713 telcon commitment to provide addl info Table will be incorporated in FSAR amend
COUNSIL,W G , OPEKA,J F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities Service Co (subs of Northeast Utilities) 84/07/20 YOUNGBLOOD,B J
Licensing Branch 1 3pp 25948 323 24X Fiche 50-423,84/07/20,
8408070220

8408090082 Forwards addl info in response to NRC 840619 request re Amend 2 to probabilistic safety study
COUNSIL,W G , SEARS,C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities 84/07/31
YOUNGBLOOD,B J Licensing Branch 1 50pp 25973 017 24X
Fiche 50-423,84/07/31,8408090082

--8408090092 "Sensitivity of Seismic Hazard Results at Millstone to LLL Study Assumptions on Attenuation & Seismicity Final Rept to Northeast Utils "
* Dames & Moore 84/06/15 45pp 25973 067 24X
Fiche 50-423,84/07/31,8408090082

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda,MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH,B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497

8408090438 Notification of 840807 meeting w/util & SMA in Bethesda,MD to discuss confirmatory program status re seismic capability beyond design basis
DOOLITTLE,E L Licensing Branch 1 84/08/02 YOUNGBLOOD,B J
Licensing Branch 1 4pp 25982 356 24X Fiche 50-423,84/08/02,
8408090438

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408200533 Forwards request for addl info re equipment qualification program Completed master equipment list should be submitted 6 wks before audit & 85% of all safety-related equipment installed & qualified
YOUNGBLOOD,B J Licensing Branch 1 84/08/07 COUNSIL,W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 29pp
26143 291 24X Fiche 50-423,84/08/07,8408200533

8408200306 Requests plans for assuring that facility designed & constructed in accordance w/FSAR commitments Response requested within 60 days of ltr date
EISENHUT,D G Division of Licensing 84/08/13 COUNSIL,W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp
26141 242 24X Fiche 50-423,84/08/13,8408200306

8408240229 Forwards request for info to be included in program to determine capability of facility to withstand seismic excitation above design SSE
YOUNGBLOOD,B J Licensing Branch 1 84/08/15 COUNSIL,W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 52pp
26251 233 24X Fiche 50-423,84/08/15,8408240222

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions 5 c list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 21X
Fiche 50-000,84/08/20,8408200275

8408300017 Requests addl info re design of ASME Code,Class 1,2 & 3 component supports Encl evaluation describes review of component support design & clarifies staff position on issues that require further justification
YOUNGBLOOD,B J Licensing Branch 1 84/08/23 COUNSIL,W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 13pp
26331 327 24X Fiche 50-423,84/08/23,8408300017

D NRC Draft/Final Environmental Statements, supplts & correspondence

8408010129 Forwards DES (NUREG-1064) & notice of availability for Millstone 3 Comments due within 45 days after publication of FR notice of issuance W/o NUREG
YOUNGBLOOD,B J Licensing Branch 1 84/07/24 Connecticut, State of 2pp 25873 313 24X Fiche 50-423,84/07/24,8408010129

--8408010131 Notice of availability of DES (NUREG-1064) for Millstone 3
YOUNGBLOOD,B J Licensing Branch 1 84/07/24 2pp 25873 315
24X Fiche 50-423,84/07/24,8408010129

8408010197 Forwards DES (NUREG-1064) & FR notice of issuance W/o NUREG
YOUNGBLOOD,B J Licensing Branch 1 84/07/24 COUNSIL,W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp
25873 272 24X Fiche 50-423,84/07/24,8408010197

8408010252 Forwards DES (NUREG-1064) & FR notice of availability, for review & comment Comments due within 45 days after publication in FR W/o NUREG
YOUNGBLOOD,B J Licensing Branch 1 84/07/24 WOOD,J M Commerce, Dept of, Natl Oceanographic & Atmospheric Administration 6pp
25872 331 24X Fiche 50-423,84/07/24,8408010252

8408020140 Forwards FR notice of issuance & DES (NUREG-1064)W/o DES
YOUNGBLOOD,B J Licensing Branch 1 84/07/24 HIRSCH,A
Environmental Protection Agency 2pp 25898 091 24X
Fiche 50-423,84/07/24,8408020140

8408010148 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF MILLSTONE NUCLEAR POWER STATION,UNIT 3 DOCKET NO 50-423 (NORTHEAST NUCLEAR ENERGY COMPANY, et al)
* Division of Licensing NUREG-1064 84/07/31 335pp Available at NRC $8 00 25871 012 24X Fiche 50-423,84/07/31,8408010148

8408230189 Offers no comments on DES re OL issuance
MIRANOSWKI,J A Agriculture, Dept of 84/08/17 YOUNGBLOOD,B J
Licensing Branch 1 1p 26209 214 24X Fiche 50-423,84/08/17,
8408230189

E NRC Safety Evaluation Report (SER), supplts & correspondence

8408160262 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF MILLSTONE NUCLEAR POWER STATION,UNIT NO 3 Docket No 50-423 (Northeast Nuclear Energy Company)
* Division of Licensing NUREG-1031 84/07/31 591pp Available at NRC $11 00 26121 001 24X Fiche 50-423,84/07/31,8408160262

8408090323 Forwards SER re util application for OL Fewer than 20 open items,summarized in SER,remain unresolved W/o encl
NOVAK,T M Assistant Director for Licensing 84/08/01
EBERSOLE,J C ACRS - Advisory Committee on Reactor Safeguards 3pp
25984 344 24X Fiche 50-423,84/08/01,8408090323

8408150526 Forwards NUREG-1031, "SER re Operation of Millstone Nuclear Power Station,Unit 3 "
YOUNGBLOOD,B J Licensing Branch 1 84/08/02 COUNSIL,W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 454pp
26094,167 24X Fiche 50-423,84/08/02,8408150526

8408200469 Forwards SER (NUREG 1031) re operation & FR notice of availability W/o SER
YOUNGBLOOD,B J Licensing Branch 1 84/08/13 COUNSIL,W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp
26143 356 24X Fiche 50-423,84/08/13,8408200469

--8408200471 Notice of availability of SER (NUREG-1031)
YOUNGBLOOD,B J Licensing Branch 1 84/08/13 2pp 26143 359
24X Fiche 50-423,84/08/13,8408200469

8405210339 Forwards response t FR open item re internally generated missile from nonsafety-related equipment * effect on safety-related equipment, per 840802 ltr
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL W G Northeast Utilities 84/08/14
YOUNGBLOOD,B J Licensing Branch 1 5pp 26177 258 24X
Fiche 50-423 84/08/14 8408210339

8408280258 Forwards plant-specific procedures for estimating core damage as required by NUREG-0737, Item II B 3 Criterion 2, per SER confirmatory item
COUNSIL,W G , FEE,W F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL W G Northeast Utilities 84/08/16
YOUNGBLOOD,B J Licensing Branch 1 2pp 26262 070 24X
Fiche 50-423,84/08/16,8408280258

--8408280262 Rev 0 to Emergency Plan Implementing Procedure EPIP 4226, "Unit 3 Core Damage Estimate Procedure "
MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/08/16 26pp 26262 072 24X
Fiche 50-423 84/08/16,8408280258

8408280159 Forwards response to SER Open Item 2 re adequacy of tornado missile protection for emergency diesel generator stacks, per NRC 840802 submittal
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities 84/08/20
YOUNGBLOOD,B J Licensing Branch 1 7pp 26275 081 24X
Fiche 50-423,84 08/20,8408280159

F Security, medical, emergency & fire protection plans

8408280258 Forwards plant-specific procedures for estimating core damage as required by NUREG-0737, Item II B 3,Criterion 2, per SER confirmatory item
COUNSIL,W G , FEE,W F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL W G Northeast Utilities 84/08/16
YOUNGBLOOD,B J Licensing Branch 1 2pp 26262 070 24X
Fiche 50-423,84/08/16,8408280258

--8408280262 Rev 0 to Emergency Plan Implementing Procedure EPIP 4226, "Unit 3 Core Damage Estimate Procedure "
MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/08/16 26pp 26262 072 24X
Fiche 50-423,84/08/16 8408280258

O Advisory Committee on Reactor Safeguards reports & correspondence

8408310027 Transcript of ACRS Subcommittee on Reliability & Probabilistic Assessment 840827 meeting in Windsor Locks,CT Pp 1-230 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/08/28
321pp 26319 281 24X Fiche 50-423,84/08/28,8408310227

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84 07 27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408100116 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller,Inc " Entry & engineering evaluation for Millstone Unit 2 will be done by Feb 1985 refueling outage No Ray Miller products supplied at Haddam
COUNSIL,W G , SEARS,C F Northeast Nuclear Energy Co (subs of Northeast Utilities) SEARS,C F Connecticut Yankee Atomic Power Co 84/07/31 MURLEY,T E Region 1, Office of Director 3pp
25988 247 24X Fiche 50-000,84/07/31,8408100116

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26048 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26057 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62 Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments ' Svc list encl
GRACE,J N Division of Qm Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 031 24X Fiche 50-000,84/08/10,8408070376

8408290003 Forwards Insp Rept 50-423/84-08 on 840520-0707 No violations noted
STAROSTECKI,R Division of Project ? Resident Programs 84/08/10
COUNSIL,W Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 26298 241 24X Fiche 50-423,84/08/10,8408290003

--8408290007 Insp Rept 50-423/84-08 on 840520-0707 No violations noted Major areas inspected document control,plant maint,training of test personnel,observation of electrical & hydrostatic testing & flushing program & unauthorized duct mod
REBELOWSKI,T A , ROBERTSON,J Region 1, Office of Director
ELSASSER,T Division of Project & Resident Programs 84/08/07
13pp 26298 243 24X Fiche 50-423,84/08/10,8408290003

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26327 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8408100064 Potential significant deficiency rept re NAMCO Model EA-180 limit switches provided as accessories on valves supplied by Pacific Valves & Fisher Controls Initially reported on 840131 Next rept expected by 841023
COUNSIL,W G , SEARS,C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities 84/07/17
MURLEY,T E Region 1, Office of Director 3pp 25990 172 24X
Fiche 50-423,84/07/17,8408100064

T Hearing transcripts on non-antitrust matters

8408310227 Transcript of ACRS Subcommittee on Reliability & Probabilistic Assessment 840827 meeting in Windsor Locks,CT Pp 1-230 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/08/28
321pp 26319 281 24X Fiche 50-423,84/08/28,8408310227

DOCKET 50-424 VOGTLE ELECTRIC GENERATING PLANT

A Application/construction stage documents & correspondence

8408300366 Forwards summary of 840627 meeting w/util in Atlanta,GA re program to acquire operating experience for cold license candidates Attendance list & agenda encl
LEWIS,R C Region 2, Office of Director 84/07/23 KELLY,R J
Consumers Power Co 10pp 26308 220 24X Fiche 50-424 84/07/23, 8408300366

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda,MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH,B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 139 24X Fiche 50-000,84/07/31,8408090497

8408130412 Responds to request for info re archaeological & historical resources Repts identify sites which may be eligible for nomination for inclusion in Natl Register of Historic Places Rept withheld (ref 10CFR2 790)
FOSTER,D O Georgia Power Co 84/08/03 ADENSAM,E G Licensing Branch 4 2pp 26011 087 24X Fiche 50-424,84/08/03,8408130412

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408150494 Advises that util in process of developing evaluation of environ impact of routing transmission line across Ebenezer Creek area Evaluation will be submitted by 840822 Clearing in area will not be done until evaluation reviewed
FOSTER,D O Georgia Power Co 84/08/06 ADENSAM,E G Licensing Branch 4 2pp 26079 186 24X Fiche 50-424,84/08/06,8408150494

8408170301 Forwards results of confirmatory lab testing program for Category 1 backfill,described in util 840613 ltr & results of onsite soil testing
FOSTER,D O Georgia Power Co 84/08/10 ADENSAM,E G Licensing Branch 4 106pp 26115 130 24X Fiche 50-424,84/08/10,8408170301

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408280208 Forwards "Vogtle Electric Generating Plant Units 1 & 2, Ebenezer Creek Swamp - Evaluation of Transmission Line Crossing " NRC review of evaluation requested within 30 days
FOSTER,D O Georgia Power Co 84/08/24 ADENSAM,E G Licensing Branch 4 2pp 26264 037 24X Fiche 50-424,84/08/24,8408280208

--8408280213 "Vogtle Electric Generating Plant Units 1 & 2,Ebenezer Creek Swamp - Evaluation of Transmission Line Crossing "
* Georgia Power Co 84/08/24 27pp 26264 039 24X
Fiche 50-424,84/08/24,8408280208

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408310448 Advises that draft SER input due to project manager by 841001 as indicated in review schedule attached to D Eisenhut 831129 memo Input to project manager must include vehicle for CRESS to access SER matl
ADENSAM,E G Licensing Branch 4 84/08/24 BOSNAK,R Mechanical Engineering Branch REITER,L Geosciences Branch BALLARD,R Environmental & Hydrologic Engineering Branch 2pp 26348 358 24X
Fiche 50-424,84/08/24,8408310448

F Security, medical, emergency & fire protection plans

8408300376 Forwards summary of 840530 meeting w/utils & INPO re selected emergency preparedness issues Attendance list also encl
O'REILLY,J P Region 2, Office of Director 84/06/08 KELLY,R J
Georgia Power Co 4pp 26308 257 24X Fiche 50-000,84/06/08,
8408300376

8408300344 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-09 & 50-425/84-09
DANCE,H C Division of Project & Resident Programs 84/07/19
KELLY,R J Georgia Power Co 1p 26308 343 24X
Fiche 50-424,84/07/19,8408300344

--8408300346 Responds to NRC 840611 ltr re violations noted in Insp Repts 50-424/84-09 & 50-425/84-09 Corrective actions procedure for documentation of surveillance insp on fire water protection sys will be revised/implemented by 840801
FOSTER,D O Georgia Power Co 84/07/03 LEWIS,R C Region 2, Office of Director 3pp 26308 344 24X Fiche 50-424,84/07/19, 8408300344

8408060003 Forwards Amend 1 to physical security plan & nuclear training & qualification plan Amends withheld (ref 10CFR2 790)
FOSTER,D O Georgia Power Co 84/07/31 ADENSAM,E G Licensing Branch 4 1p 25933 185 24X Fiche 50-424,84/07/31,8408060003

G Adjudicatory correspondence

8408010189 Forwards Encl 2 to staff response to ASLB 840712 ltr entitled, "Interim Position on Charleston Earthquake for Licensing Proceeding " accidentally omitted from original submittal Related correspondence
PERLIS,R G Hearing Branch 3 DSB 686 84/07/26 MARGULIES,M B , LINENBERGER,C , PARIS,O H Atomic Safety and Licensing Board Panel
4pp 25855 159 24X Fiche 50-424,84/07/26,8408010189

8408010253 Response to ASLB 840712 inquiry whether NUREG/CR-3756 constitutes substantial new info to lead to redetermination of adequacy of seismic design Inquiry fully warranted Certificate of Svc encl
JOHNSON,T Campaign for Prosperous Georgia DSB 664 84/07/26
17pp 25854 324 24X Fiche 50-424,84/07/26,8408010253

8408010267 Informs of withdrawal of Contention CPG-9,based upon review of Westinghouse proprietary rept re mod of primary loop sys Related correspondence
FOWLER,L Legal Environmental Assistance Foundation FOWLER,L Campaign for Prosperous Georgia DSB 657 84/07/26
MARGULIES,M B , LINENBERGER,C , PARIS,O H Atomic Safety and Licensing Board Panel 2pp 25854 069 24X Fiche 50-424,84/07/26, 8408010267

H General correspondence

8408010336 Authorizes WT Nickerson to sign future NRC correspondence which does not require signature of duly authorized util officer
FOSTER,D O Georgia Power Co 84/07/23 ADENSAM,E G Licensing Branch 4 1p 25864 074 24X Fiche 50-424,84/07/23,8408010336

O Inspection reports, IE Bulletins & correspondence

8408310419 Confirms 840507 telcon re 840518 meeting to discuss status of insp program for diesel generators
LEWIS,R C Region 2, Office of Director 84/05/16 KELLY,R J
Georgia Power Co 1p 26335 023 24X Fiche 50-424,84/05/16, 8408310419

8408310405 Forwards summary of 840518 meeting re insp program for diesel generators Meeting beneficial & provided better understanding of issues
LEWIS,R C Region 2, Office of Director 84/06/12 KELLY,R J
Georgia Power Co 3pp 26333 315 24X Fiche 50-424,84/06/12, 8408310405

8408270408 Forwards Insp Repts 50-424/84-15 & 50-425/84-15 on 840619-22 No violations or deviations
DANCE,H C Division of Project & Resident Programs 84/07/12
KELLY,R J Georgia Power Co 2pp 26256 295 24X
Fiche 50-424,84/07/12,8408270408

--8408270414 Insp Repts 50-424/84-15 & 50-425/84-15 on 840619-22 No violations or deviations noted Major areas inspected unresolved items,licensee identified items,IE bulletin, electrical components & sys work & work activities
GIBBONS,T D , CONLON,T E Region 2, Office of Director 84/07/10
5pp 26256 297 24X Fiche 50-424,84/07/12,8408270408

8408270342 Forwards Insp Repts 50-424/84-16 & 50-425/84-16 on 840514-0625 No violations or deviations noted
DANCE,H C Division of Project & Resident Programs 84/07/17
KELLY,R J Georgia Power Co 2pp 26257 214 24X
Fiche 50-424,84/07/17,8408270342

--8408270351 Insp Repts 50-424/84-16 & 50-425/84-16 on 840514-0625 No violations or deviations noted Major areas inspected diesel generator verification program,HVAC support program & Unit 2 primary containment & Unit 1 containment
SANDERS,W F , PANCIERA,V Region 2, Office of Director 84/07/16
5pp 26257 216 24X Fiche 50-424,84/07/17,8408270342

8408300344 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-09 & 50-425/84-09
DANCE,H C Division of Project & Resident Programs 84/07/19,
KELLY,R J Georgia Power Co 1p 26308 343 24X
Fiche 50-424,84/07/19,8408300344

--8408300346 Responds to NRC 840511 ltr re violations noted in Insp Repts 50-424/84-09 & 50-425/84-09 Corrective actions procedure for documentation of surveillance insp on fire water protection sys will be revised/implemented by 840801
FOSTER,D O Georgia Power Co 84/07/03 LEWIS,R C Region 2, Office of Director 3pp 26308 344 24X Fiche 50-424,84/07/19, 8408300344

8408240365 Ack receipt of 840711 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-11 & 50-425/84-11
LEWIS,R C Region 2, Office of Director 84/07/24 KELLY,R J Georgia Power Co 1p 26237 094 24X Fiche 50-424,84/07/24, 8408240365

--8408240367 Responds to NRC ltr re violations noted in Insp Repts 50-424/84-11 & 50-425/84-11 Corrective actions sys being developed for areas of plant which will provide controls as implemented in control room area
FOSTER,D O Georgia Power Co 84/07/11 LEWIS,R C Region 2, Office of Director 2pp 26237 095 24X Fiche 50-424,84/07/24, 8408240365

--8408240368 Forwards Insp Repts 50-424/84-11 & 50-425/84-11 on 840413-0514 & notice of violation
LEWIS,R C Region 2, Office of Director 84/06/14 KELLY,R J Georgia Power Co 2pp 26237 097 24X Fiche 50-424,84/07/24, 8408240365

--8408240370 Notice of violation from insp on 840413-0514
* Region 2, Office of Director 84/06/14 1p 26237 099, 24X Fiche 50-424,84/07/24,8408240365

--8408240371 Insp Repts 50-424/84-11 & 50-425/84-11 on 840413-0514 Violation noted failure to protect electrical equipment during installation
SANDERS,W F , PANCIERA,V W Region 2, Office of Director 84/06/07 5pp 26237 100 24X Fiche 50-424,84/07/24,8408240365

8408270429 Ack receipt of 840710 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-10 & 50-425/84-10
DANCE,H C Region 2, Office of Director 84/07/25 KELLY,R J Georgia Power Co 1p 26257 031 24X Fiche 50-424,84/07/25, 8408270429

--8408270430 Responds to NRC 840611 ltr re violations noted in Insp Repts 50-424/84-10 & 50-425/84-10 Corrective actions formal training program for contract QC inspectors developed & implemented in Apr 1984
FOSTER,D O Georgia Power Co 84/07/10 LEWIS,R C Region 2, Office of Director 3pp 26257 032 24X Fiche 50-424,84/07/25, 8408270429

--8408270433 Forwards Insp Repts 50-424/84-10 & 50-425/84-10 on 840501-04 & notice of violation
DANCE,H C Division of Project & Resident Programs 84/06/11
KELLY,R J Georgia Power Co 2pp 26257 035 24X
Fiche 50-424,84/07/25,8408270429

--8408270436 Notice of violation from insp on 840501-04
* Region 2, Office of Director 84/06/11 2pp 26257 037 24X Fiche 50-424,84/07/25,8408270429

--8408270440 Insp Repts 50-424/84-10 & 50-425/84-10 on 840501-04 Violation noted training provided electrical contract QC inspectors informal & did not assure that suitable proficiency achieved on site procedures
RUFF,A B , MERRIWEATHER,N , CONLON,T E Region 2, Office of Director 84/06/07 9pp 26257 039 24X Fiche 50-424,84/07/25, 8408270429

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co, of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp 25926 173 24X Fiche,50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10, 8408060050

8408090023 Interim significant deficiency rept re lack of full penetration welds on Pullman Const Industries duct supports Initially reported on 840614 Next rept will be submitted by 840829
FOSTER,D O Georgia Power Co 84/07/13 O'REILLY,J P Region 2, Office of Director 2pp 25992 094 24X Fiche 50-424,84/07/13, 8408090023

8408060102 Forwards Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to DNWL
RAY,C L TDI (Transamerica Delaval Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000 84/07/27 8408060102

--8408060138 'Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review '
* Stone & Webster Engineering Corp 84 07/31 36pp 25932 139
24X Fiche 50-000 84/07/27 8408060102

8408060324 Forwards 'Design Review of Elliott Model 65G Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000 84/08/01,8408060324

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines '
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program,testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000,84/08/13,8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation,plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final GA verified rept Addl copy forwarded to DNWL,per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000,84/08/14,8408160395

--8408160397 "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000,84/08/23,8408290179

8408280152 PNO-II-84-055 on 840823,util announced that seven employees dismissed due to alleged unauthorized bid disclosures in procurement of small tools & expendable const supplies
Dealings w/one vendor terminated
PANCIERA,V , DANCE,H C Region 2, Office of Director 84/08/24
1p 26274 309 24X Fiche 50-424,84/08/24,8408280152

DOCKET 50-425 VOGTLE ELECTRIC GENERATING PLANT

Application/construction stage documents & correspondence

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda,MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH,B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497

8408130412 Responds to request for info re archaeological & historical resources Repts identify sites which may be eligible for nomination for inclusion in Natl Register of Historic Places Rept withheld (ref 10CFR2 790)
FOSTER,D O Georgia Power Co 84/08/03 ADENSAM,E G Licensing Branch 4 2pp 26011 087 24X Fiche 50-424,84/08/03,8408130412

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933 Prioritization of Generic Safety Issues " List encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000 84/08/06,8408070110

8408150491 Advises that util in process of developing evaluation of environ impact of routing transmission line across Ebenezer Creek area Evaluation will be submitted by 840822 Clearing in area will not be done until evaluation reviewed
FOSTER,D O Georgia Power Co 84/08/06 ADENSAM,E G Licensing Branch 4 2pp 24077 186 24X Fiche 50-421,84/08/06,8408150494

8408170301 Forwards results of confirmatory lab testing program for Category 1 backfill,described in util 840613 ltr & results of onsite soil testing
FOSTER,D O Georgia Power Co 84/08/10 ADENSAM,E G Licensing Branch 4 106pp 26115 130 24X Fiche 50-424,84/08/10,8408170301

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000 84/08/20 8408200275

8408280208 Forwards "Vogtle Electric Generating Plant Units 1 & 2, Ebenezer Creek Swamp - Evaluation of Transmission Line Crossing " NRC review of evaluation requested within 30 days
FOSTER,D O Georgia Power Co 84/08/24 ADENSAM,E G Licensing Branch 4 2pp 26264 037 24X Fiche 50-424,84/08/24,8408280208

--8408280213 "Vogtle Electric Generating Plant Units 1 & 2,Ebenezer Creek Swamp - Evaluation of Transmission Line Crossing "
* Georgia Power Co 84/08/24 2/pp 26264 039 24X
Fiche 50-421,84/08/24,8408280208

E NRC Safety Evaluation Report (SER), supplS & correspondence

8408310448 Advises that draft SER input due to project manager by 841001 as indicated in review schedule attached to D Eisenhut 831129 memo Input to project manager must include vehicle for CRESS to access SER matl
ADENSAM,E G Licensing Branch 4 84/08/24 BOSNAK,R Mechanical Engineering Branch REITER,L Geosciences Branch BALLARD,R Environmental & Hydrologic Engineering Branch 2pp 26348 358 24X
Fiche 50-424,84/08/24,8408310448

F Security, medical, emergency & fire protection plans

8408300376 Forwards summary of 840530 meeting w/utils & INPO re selected emergency preparedness issues Attendance list also encl
O'REILLY,J P Region 2, Office of Director 84/06/08 KELLY,R J
Georgia Power Co 4pp 26308 257 24X Fiche 50-000,84/06/08, 8408300376

8408300344 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-09 & 50-425/84-09
DANCE,H C Division of Project & Resident Programs 84/07/19
KELLY,R J Georgia Power Co 1p 26308 343 24X
Fiche 50-424,84/07/19,8408300344

--8408300348 Responds to NRC 840611 ltr re violations noted in Insp Repts 50 424/84-09 & 50-425/84-07 Corrective actions procedure for documentation of surveillance insp on fire water protection sys Util be revised/implemented by 840801
FOSTER,D O Georgia Power Co 84/07/03 LEWIS,R C Region 2, Office of Director 3pp 26308 344 24X Fiche 50-424,84/07/19, 8408300344

8408060003 Forwards Amend 1 to physical security plan & nuclear training & qualification plan Amends withheld (ref 10CFR2 790)
FOSTER,D O Georgia Power Co 84/07/31 ADENSAM,E G Licensing Branch 4 1p 25933 185 24X Fiche 50-424,84/07/31,8408060003

G Adjudicatory correspondence

8408010189 Forwards Encl 2 to staff response to ASLB 840712 ltr entitled, "Interim Position on Charleston Earthquake for Licensing Proceeding," accidentally omitted from original submittal Related correspondence
PERLIS,R G Hearing Branch 3 DSB 686 84/07/26 MARGULIES,M B , LINENBERGER,C , PARIS,O H Atomic Safety and Licensing Board Panel
4pp 25855 159 24X Fiche 50-424,84/07/26,8408010189

8408010253 Response to ASLB 840712 inquiry whether NUREG/CR-3756 constitutes substantial new info to lead to redetermination of adequacy of seismic design Inquiry fully warranted Certificate of S c encl
JOHNSON, T Campaign for Prosperous Georgia DSB 664 84/07/26 17pp 25854 324 24X Fiche 50-424, 84/07/26, 8408010253

8408010267 Informs of withdrawal of Contention CPG-9, based upon review of Westinghouse proprietary rept re mod of primary loop sys Related correspondence
FOWLER, L Legal Environmental Assistance Foundation FOWLER, L Campaign for Prosperous Georgia DSB 657 84/07/26
MARGULIES, M B , LINENBERGER G , PARIS, D H Atomic Safety and Licensing Board Panel 2pp 25854 069 24X Fiche 50-424, 84/07/26, 8408010267

H General correspondence

8408010336 Authorizes WT Nickerson to sign future NRC correspondence which does not require signature of duly authorized util officer
FOSTER, D O Georgia Power Co 84/07/23 ADERSAN, E G Licensing Branch 4 1p 25866 074 24X Fiche 50-424, 84/07/23, 8408010336

G Inspection reports, IE Bulletins & correspondence

8408310419 Confirms 840507 telcon re 840518 meeting to discuss status of insp program for diesel generators
LEWIS, R C Region 2, Office of Director 84/05/16 KELLY, R J Georgia Power Co 1p 26335 023 24X Fiche 50-424, 84/05/16, 8408310419

8408310405 Forwards summary of 840518 meeting re insp program for diesel generators Meeting beneficial & provided better understanding of issues
LEWIS, R C Region 2, Office of Director 84/06/12 KELLY, R J Georgia Power Co 3pp 26333 315 24X Fiche 50-424, 84/06/12, 8408310405

8408270408 Forwards Insp Repts 50-424/84-15 & 50-425/84-15 on 840619-22 No violations or deviations
DANCE, H C Division of Project & Resident Programs 84/07/12
KELLY, R J Georgia Power Co 2pp 26256 295 24X
Fiche 50-424, 84/07/12, 8408270408

--8408270414 Insp Repts 50-424/84-15 & 50-425/84-15 on 840619-22 No violations or deviations noted Major areas inspected unresolved items, licensee identified items, IE bulletin, electrical components & sys work & work activities
GIBBONS, T D , CONLON, T E Region 2, Office of Director 84/07/10 5pp 26256 297 24X Fiche 50-424, 84/07/12, 8408270408

8408270342 Forwards Insp Repts 50-424/84-16 & 50-425/84-16 on 840514-0625 No violations or deviations noted
DANCE, H C Division of Project & Resident Programs 84/07/17
KELLY, R J Georgia Power Co 2pp 26257 214 24X
Fiche 50-424, 84/07/17, 8408270342

--8408270351 Insp Repts 50-424/84-16 & 50-425/84-16 on 840514-0625 No violations or deviations noted Major areas inspected diesel generator verification program, HVAC support program & Unit 2 primary containment & Unit 1 containment
SANDERS, W F , PANCIERA, V Region 2, Office of Director 84/07/16 5pp 26257 216 24X Fiche 50-424, 84/07/17, 8408270342

8408300344 Ack receipt of 840703 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-09 & 50-425/84-09
DANCE, H C Division of Project & Resident Programs 84/07/19
KELLY, R J Georgia Power Co 1p 26308 343 24X
Fiche 50-424, 84/07/19, 8408300344

--8408300346 Responds to NRC 840611 ltr re violations noted in Insp Repts 50-424/84-09 & 50-425/84-09 Corrective actions procedure for documentation of surveillance insp on fire water protection sys will be revised/implemented by 840801
FOSTER, D O Georgia Power Co 84/07/03 LEWIS, R C Region 2, Office of Director 3pp 26308 344 24X Fiche 50-424, 84/07/19, 8408300344

8408240365 Ack receipt of 840711 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-11 & 50-425/84-11
LEWIS, R C Region 2, Office of Director 84/07/24 KELLY, R J Georgia Power Co 1p 26237 094 24X Fiche 50-424, 84/07/24, 8408240365

--8408240367 Responds to NRC ltr re violations noted in Insp Repts 50-424/84-11 & 50-425/84-11 Corrective actions sys being developed for areas of plant which will provide controls as implemented in control room area
FOSTER, D O Georgia Power Co 84/07/11 LEWIS, R C Region 2, Office of Director 2pp 26237 095 24X Fiche 50-424, 84/07/24, 8408240365

--8408240368 Forwards Insp Repts 50-424/84-11 & 50-425/84-11 on 840413-0514 & notice of violation
LEWIS, R C Region 2, Office of Director 84/06/14 KELLY, R J Georgia Power Co 2pp 26237 097 24X Fiche 50-424, 84/07/24, 8408240365

--8408240371 Insp Repts 50-424/84-11 & 50-425/84-11 on 840413-0514 Violation noted failure to protect electrical equipment during installation
SANDERS, W F , PANCIERA, V W Region 2, Office of Director 84/06/07 5pp 26237 100 24X Fiche 50-424, 84/07/24, 8408240365

8408270429 Ack receipt of 840710 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-424/84-10 & 50-425/84-10
DANCE, H C Region 2, Office of Director 84/07/25 KELLY, R J Georgia Power Co 1p 26257 031 24X Fiche 50-424, 84/07/25, 8408270429

--8408270430 Responds to NRC 840611 ltr re violations noted in Insp Repts 50-424/84-10 & 50-425/84-10 Corrective actions formal training program for contract QC inspectors developed & implemented in Apr 1984
FOSTER, D O Georgia Power Co 84/07/10 LEWIS, R C Region 2, Office of Director 3pp 26257 032 24X Fiche 50-424, 84/07/25, 8408270429

--8408270433 Forwards Insp Repts 50-424/84-10 & 50-425/84-10 on 840501-04 & notice of violation
DANCE, H C Division of Project & Resident Programs 84/06/11
KELLY, R J Georgia Power Co 2pp 26257.035 24X
Fiche 50-424, 84/07/25, 8408270429

--8408270436 Notice of violation from insp on 840501-04
* Region 2, Office of Director 84/06/11. 2pp 26257 037 24X
Fiche 50-424, 84/07/25, 8408270429

--8408270440 Insp Repts 50-424/84-10 & 50-425/84-10 on 840501-04 Violation noted training provided electrical contract QC inspectors informal & did not assure that suitable proficiency achieved on site procedures
RUFF, A B , MERRIWEATHER, N , CONLON, T E Region 2, Office of Director 84/06/07 9pp 26257 039 24X Fiche 50-424, 84/07/25, 8408270429

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009.

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp
25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10,8408060050

8408090023 Interim significant deficiency rept re lack of full penetration welds on Pullman Const Industries duct supports Initially reported on 840614 Next rept will be submitted by 840829
FOSTER,D O Georgia Power Co 84/07/13 O'REILLY,J P Region 2, Office of Director 2pp 25992 094 24X Fiche 50-424,84/07/13,8408090023

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000,84/07/27,8408060102

8408060324 Forwards "Design Review of Elliott Model 65G Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000,84/08/01,8408060324

8408160394 Forwards 'Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 'Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J D TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X Fiche 50-000,84/08/13,8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation,plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL,per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000,84/08/14,8408160395

--8408160397 "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000,84/08/23,8408290179

8408280152 PNO-II-84-055 on 840823,util announced that seven employees dismissed due to alleged unauthorized bid disclosures in procurement of small tools & expendable const supplies
Dealings w/one vendor terminated
PANCIERA,V , DANCE,H C Region 2, Office of Director 84/08/24
1p 26274 309 24X Fiche 50-424,84/08/24,8408280152

DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8408130091 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IE insp rept
WENSLAWSKI,F A Region 5, Office of Director 84/08/07 KROES,R J
California, Univ of, Santa Barbara, CA 1p 26010 040 24X
Fiche 50-433,84/08/07,8408130091

--8408130094 Responds to NRC 840706 ltr re violations noted in IE insp rept Corrective actions application for operator requalification submitted & written & operating exam will be administered in Aug
KROES,R J California, Univ of, Santa Barbara, CA 84/07/13
YUHAS,G P Region 5, Office of Director 1p 26010 041 24X
Fiche 50-433,84/08/07,8408130091

V Operator Examinations

8408130091 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in IE insp rept
WENSLAWSKI,F A Region 5, Office of Director 84/08/07 KROES,R J
California, Univ of, Santa Barbara, CA 1p 26010 040 24X
Fiche 50-433,84/08/07,8408130091

--8408130094 Responds to NRC 840706 ltr re violations noted in IE insp rept Corrective actions application for operator requalification submitted & written & operating exam will be administered in Aug
KROES,R J California, Univ of, Santa Barbara, CA 84/07/13
YUHAS,G P Region 5, Office of Director 1p 26010 041 24X
Fiche 50-433,84/08/07,8408130091

DOCKET STN-50 437 FLOATING NUCLEAR PLANT

A Application construction stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000 84/08/06 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

O Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8408030155 Documents K Mali 840628 telcon w/C Stable advising that review of tube rupture analysis using RELAP 5 computer code, per TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pump," will be delayed Info expected by 841115
MILLS, L M Tennessee Valley Authority 84/07/27 ADENSAM, E Operating Reactors Branch 4 1p 25912 015 24X
Fiche 50-438, 84/07/27, 8408030155

8408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI, P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 38pp 25978 228 24X Fiche 50-000, 84/07/27, 8408080288

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408270098 Forwards response to NRC 831229 ltr re TDI emergency diesel generators Includes procurement & performance specs & insp results
SHELL, R H Tennessee Valley Authority 84/08/17 ADENSAM, E G Licensing Branch 4 167pp 26248 052 24X Fiche 50-438, 84/08/17, 8408270098

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

O Inspection reports, IE Bulletins & correspondence

8408280100 Forwards supplemental response to IE Bulletin 81-03 re flow blockage of cooling water to safety sys components by Corbicula Sp (Asiatic clam) & Mytilus Sp (mussel)
MILLS, L M Tennessee Valley Authority 84/07/23 O'REILLY, J P Region 2, Office of Director 2pp 26261 305 24X
Fiche 50-438, 84/07/23, 8408280100

8408270232 Forwards Insp Repts 50-438/84-13 & 50-439/84-13 on 840709-10 No violations or deviations noted
VERRELLI, D M Division of Project & Resident Programs 84/07/26
PARRIS, H G Tennessee Valley Authority 2pp 26258 048 24X
Fiche 50-438, 84/07/26, 8408270232

--8408270240 Insp Repts 50-438/84-13 & 50-439/84-13 No violations or deviations noted Major areas inspected licensee action on previous enforcement matters, safety-related components & licensee identified items
GIRARD, C H , BLAKE, J J Region 2, Office of Director 84/07/20 5pp 26258 050 24X Fiche 50-438, 84/07/26, 8408270232

8408270460 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-438/83-05 & 50-439/83-05 Response meets requirements of 10CFR2 201 Corrective actions will be examined during future insps
VERRELLI, D M Region 2, Office of Director 84/07/26 PARRIS, H G Tennessee Valley Authority 1p 26256 235 24X
Fiche 50-438, 84/07/26, 8408270460

--8408270468 Forwards supplemental response to NRC 830412 ltr re violations noted in Insp Repts 50-438/83-05 & 50-439/83-05 Corrective actions BNP-QCP-6 3 revised to clarify listing of attributes inspected on thermal expansion devices,
MILLS, L M Tennessee Valley Authority 84/07/13 O'REILLY, J P Region 2, Office of Director 3pp 26256 236 24X
Fiche 50-438, 84/07/26, 8408270460

--8408270475 Supplemental response to violations noted in Insp Repts 50-438/83-05 & 50-439/83-05 Corrective action const QC unit waiting for computer printout to verify insp of all affected equipment under Revs 0 & 1 to QCP 6 3,
MILLS, L M Tennessee Valley Authority 84/01/04 O'REILLY, J P Region 2, Office of Director 1p 26256 239 24X
Fiche 50-438, 84/07/26, 8408270460

--8408270483 Supplemental response to violations noted in Insp Repts 50-438/83-05 & 50-439/83-05 Corrective actions will be completed by 831216
MILLS,L M Tennessee Valley Authority 83/09/12 O'REILLY,J P
Region 2, Office of Director 1p 26256 240 24X
Fiche 50-438,84/07/26,8408270460

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

B Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc.) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards 'Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp 25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director s Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10,8408060050

8408090025 Third interim deficiency rept re backflow not considered for ERCW sys booster pump shutoff Initially reported on 821230 Engineering change notice issued Next rept by 850215
MILLS,L M Tennessee Valley Authority 84/07/16 O'REILLY,J P
Region 2, Office of Director 2pp 25992 264 24X
Fiche 50-438,84/07/16,8408090025

8408090028 Third interim deficiency rept re B&W reactor bldg sump pH values not considering dead vol Initially reported on 830623 Analysis underway Next rept will be submitted by 851127
MILLS,L M Tennessee Valley Authority 84/07/16 O'REILLY,J P
Region 2, Office of Director 2pp 25992 255 24X
Fiche 50-438,84/07/16,8408090028

8408090268 Final deficiency rept re contaminated makeup & purification piping Initially reported on 840405 Caused by water flushed into auxiliary bldg 2-inch diameter equipment drain piping sys NV sys piping will be reflushed by 840912
MILLS,L M Tennessee Valley Authority 84/07/16 O'REILLY,J P
Region 2, Office of Director 2pp 25994 040 24X
Fiche 50-438,84/07/16,8408090268

8408090024 Supplemental deficiency rept re defect in steam generator support bolts Initially reported on 820723 Thirty-six bolts still need to be pulled out & shims remachined Corrective actions will be completed by 840829
MILLS,L M Tennessee Valley Authority 84/07/17 O'REILLY,J P
Region 2, Office of Director 1p 25992 096 24X
Fiche 50-438,84/07/17,8408090024

8408090057 Fifth interim deficiency rept re incorrect installation of pressure relief & safety valves Initially reported on 830305 Caused by waste disposal header not sized to accommodate both relief valves Next rept expected by 860114
MILLS,L M Tennessee Valley Authority 84/07/18 O'REILLY,J P
Region 2, Office of Director 2pp 25992 139 24X
Fiche 50-438,84/07/18,8408090057

8408090033 Fifth interim deficiency rept re environ qualification of safety-related electrical components Initially reported on 811021 Caused by util failure to develop procedural controls on qualification program Next rept expected by 850621
MILLS,L M Tennessee Valley Authority 84/07/20 O'REILLY,J P
Region 2, Office of Director 21pp 25992 102 24X
Fiche 50-438,84/07/20,8408090033

8408090279 Fourth interim deficiency rept re makeup HPI pump vibration Initially reported on 830622 Cause not stated Pumps balanced & vibration level measured Next rept expected by 841119 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 84/07/20 O'REILLY,J P
Region 2, Office of Director 2pp 25994 161 24X
Fiche 50-438,84/07/20,8408090279

8408090416 First interim deficiency rept re incomplete review of design change requests for piping analyses Initially reported on 840622 Investigation continuing Next rept will be submitted by 850419
MILLS,L M Tennessee Valley Authority 84/07/20 O'REILLY,J P
Region 2, Office of Director 2pp 25993 261 24X
Fiche 50-438,84/07/20,8408090416

8408160173 Final deficiency rept re generic implication reviews for const projects Rev 4 to QAP 16 1 issued to more clearly define intra-org responsibility for determining generic implications or nonconformance
MILLS,L M Tennessee Valley Authority 84/07/24 O'REILLY,J P
Region 2, Office of Director 2pp 26108 045 24X
Fiche 50-000 84/07/24,8408160173

8408160434 First interim deficiency rept re control room pressurization boundary loss through drain & vent lines Initially reported on 840629 Seismic support mods will be made Next rept will be provided on or about 850215
MILLS,L M Tennessee Valley Authority 84/07/25 O'REILLY,J P
Region 2, Office of Director 2pp 26106 352 24X
Fiche 50-438,84/07/25,8408160434

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000,84/07/27,8408060102

8408160200 Final deficiency rept re field cables not terminated in penetrations properly Initially reported on 830614 Personnel trained to splice cables per manufacturer instructions Corrective actions will be completed by 841001
MILLS,L M Tennessee Valley Authority 84/07/30 O'REILLY,J
Region 2, Office of Director 5pp 26106 303 24X
Fiche 50-438,84/07/30,8408160200

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000,84/08/01,8408060324

8408160058 Final deficiency rept re water damage to reactor bldg normal sump isolation valve motor operator Initially reported on 830609 Motor operator shipped to vendor for repair Reinstallation expected by 850419
MILLS,L M Tennessee Valley Authority 84/08/01 O'REILLY,J P
Region 2, Office of Director 2pp 26108 217 24X
Fiche 50-438,84/08/01,8408160058

8408160179 Final deficiency rept re retrievability of QA records Initially reported on 840301 QA procedures revised on 840508 to incorporate handling requirements for supplier QC records
MILLS,L M Tennessee Valley Authority 84/08/01 O'REILLY,J P
Region 2, Office of Director 2pp 26108 042 24X
Fiche 50-000,84/08/01,8408160179

8408160066 Final deficiency rept re loose drive hubs on overspeed governor drive shaft on TDI diesel engines Initially reported on 840203 Hubs acceptable Also reportable under Part 21
MILLS,L M Tennessee Valley Authority 84/08/03 O'REILLY,J P
Region 2, Office of Director 2pp 26108 224 24X
Fiche 50-438,84/08/03,8408160066

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000,84/08/13,8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation,plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000,84/08/14,8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

8408290179 Forwards response to 840723 request for addl info on rpts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000,84/08/23,8408290179

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8408030155 Documents K Mali 840628 telcon w/C Stable advising that review of tube rupture analysis using RELAP 5 computer code, per TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pump," will be delayed Info expected by 841115
MILLS,L M Tennessee Valley Authority 84/07/27 ADENSAM,E
Operating Reactors Branch 4 1p 25912 015 24X
Fiche 50-438,84/07/27,8408030155

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408270098 Forwards response to NRC 831229 ltr re TDI emergency diesel generators Includes procurement & performance specs & insp results
SHELL,R H Tennessee Valley Authority 84/08/17 ADENSAM,E G
Licensing Branch 4 167pp 26248 052 24X Fiche 50-438, 84/08/17, 8408270098

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

Q Inspection reports, IE Bulletins & correspondence

8408280100 Forwards supplemental response to IE Bulletin 81-03 re flow blockage of cooling water to safety sys components by Corbicula Sp (Asiatic clam) & Mytilus Sp (mussel)
MILLS,L M Tennessee Valley Authority 84/07/23 O'REILLY,J P
Region 2, Office of Director 2pp 26261 305 24X
Fiche 50-438,84/07/23,8408280100

8408270232 Forwards Insp Rpts 50-438/84-13 & 50-439/84-13 on 840709-10 No violations or deviations noted
VERRELLI,D M Division of Project & Resident Programs 84/07/26
PARRIS,H G Tennessee Valley Authority 2pp 26258 048 24X
Fiche 50-438,84/07/26,8408270232

--8408270240 Insp Rpts 50-438/84-13 & 50-439/84-13 No violations or deviations noted Major areas inspected licensee action on previous enforcement matters,safety-related components & licensee identified items
GIRARD,E H , BLAKE,J J Region 2, Office of Director, 84/07/20
8pp 26258 050 24X Fiche 50-438,84/07/26,8408270232

8408270460 Ack receipt of 840713 ltr informing NRC of steps taken to correct violations noted in Insp Rpts 50-438/83-05 & 50-439/83-05 Response meets requirements of 10CFR2 201 Corrective actions will be examined during future insps
VERRELLI,D M Region 2, Office of Director 84/07/26 PARRIS,H G
Tennessee Valley Authority 1p 26256 235 24X
Fiche 50-438,84/07/26,8408270460

--8408270468 Forwards supplemental response to NRC 830412 ltr re violations noted in Insp Rpts 50-438/83-05 & 50-439/83-05 Corrective actions BNP-QCP-6 3 revised to clarify listing of attributes inspected on thermal expansion devices
MILLS,L M Tennessee Valley Authority 84/07/13 O'REILLY,J P
Region 2, Office of Director 3pp 26256 236 24X
Fiche 50-438,84/07/26,8408270460

-8408270475 Supplemental response to violations noted in Insp Repts 50-438/83-05 & 50-439/83-05 Corrective action const QC unit waiting for computer printout to verify insp of all affected equipment under Revs 0 & 1 to QCP 6 3
MILLS,L M Tennessee Valley Authority 84/01/04 O'REILLY,J P
Region 2, Office of Director 1p 26256 239 24X
Fiche 50-438,84/07/26,8408270460

-8408270483 Supplemental response to violations noted in Insp Repts 50-438/83-05 & 50-439/83-05 Corrective actions will be completed by 831216
MILLS,L M Tennessee Valley Authority 83/09/12 O'REILLY,J P
Region 2, Office of Director 1p 26256 240 24X
Fiche 50-438,84/07/26,8408270460

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/13 DEYOUNG,R L Director s Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317

8405290062 Forwards Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290079 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000,84/05/24 8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp 25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/ TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10, 8408060050

8408090025 Third interim deficiency rept re backflow not considered for ERCW sys booster pump shutoff Initially reported on 821230 Engineering change notice issued Next rept by 850215
MILLS,L M Tennessee Valley Authority 84/07/16 O'REILLY,J P
Region 2, Office of Director 2pp 25992 264 24X
Fiche 50-438,84/07/16,8408090025

8408090028 Third interim deficiency rept re B&W reactor bldg sump pH values not considering dead vol Initially reported on 830623 Analysis underway Next rept will be submitted by 851127
MILLS,L M Tennessee Valley Authority 84/07/16 O'REILLY,J P
Region 2, Office of Director 2pp 25992 255 24X
Fiche 50-438,84/07/16,8408090028

8408090024 Supplemental deficiency rept re defect in steam generator support bolts Initially reported on 820723 Thirty-six bolts still need to be pulled out & shims remachined Corrective actions will be completed by 840829
MILLS,L M Tennessee Valley Authority 84/07/17 O'REILLY,J P
Region 2, Office of Director 1p 25992 096 24X
Fiche 50-438,84/07/17,8408090024

8408090057 Fifth interim deficiency rept re incorrect installation of pressure relief & safety valves Initially reported on 830305 Caused by waste disposal header not sized to accommodate both relief valves Next rept expected by 860114
MILLS,L M Tennessee Valley Authority 84/07/18 O'REILLY,J P
Region 2, Office of Director 2pp 25992 139 24X
Fiche 50-438,84/07/18,8408090057

8408090033 Fifth interim deficiency rept re environ qualification of safety-related electrical components Initially reported on 811021 Caused by util failure to develop procedural controls on qualification program Next rept expected by 850621
MILLS,L M Tennessee Valley Authority 84/07/20 O'REILLY,J P
Region 2, Office of Director 21pp 25992 102 24X
Fiche 50-438,84/07/20,8408090033

8408090416 First interim deficiency rept re incomplete review of design change requests for piping analyses Initially reported on 840622 Investigation continuing Next rept will be submitted by 850419
MILLS,L M Tennessee Valley Authority 84/07/20 O'REILLY,J P
Region 2, Office of Director 2pp 25993 261 24X
Fiche 50-438,84/07/20,8408090416

8408160173 Final deficiency rept re generic implication reviews for const projects Rev 4 to QAP 16 1 issued to more clearly define intra-ofc responsibility for determining generic implications of nonconformance
MILLS,L M Tennessee Valley Authority 84/07/24 O'REILLY,J P
Region 2, Office of Director 2pp 26108 045 24X
Fiche 50-000,84/07/24,8408160173

8408160434 First interim deficiency rept re control room pressurization boundary loss through drain & vent lines Initially reported on 840625 Seismic support mods will be made Next rept will be provided on or about 850215
MILLS,L M Tennessee Valley Authority 84/07/25 O'REILLY,J P
Region 2, Office of Director 2pp 26106 352 24X
Fiche 50-438,84/07/25 8408160434

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000,84/07/27,8408060102

8408160200 Final deficiency rept re field cables not terminated in penetrations properly Initially reported on 830614 Personnel trained to splice cables per manufacturer instructions Corrective actions will be completed by 841001
MILLS,L M Tennessee Valley Authority 84/07/30 O'REILLY,J
Region 2, Office of Director 5pp 26106 303 24X
Fiche 50-438,84/07/30,8408160200

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000,84/08/01,8408060324

8408160179 Final deficiency rept re retrievability of QA records Initially reported on 840301 QA procedures revised on 840608 to incorporate handling requirements for supplier QC records
MILLS,L M Tennessee Valley Authority 84/08/01 O'REILLY,J P
Region 2, Office of Director 2pp 26108 042 24X
Fiche 50-000,84/08/01,8408160179

8408160066 Final deficiency rept re loose drive hubs on overspeed governor drive shaft on TDI diesel engines Initially reported on 840203 Hubs acceptable Also reportable under Part 21
MILLS,L M Tennessee Valley Authority 84/08/03 O'REILLY,J P
Region 2, Office of Director 2pp 26108 224 24X
Fiche 50-438,84/08/03,8408160066

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000,84/08/13,8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL, per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000,84/08/14,8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000,84/08/23,8408290179

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8408030145 Forwards summary forms on equipment for SQRT & pump & valve operability review team audits by Equipment Qualification Branch Floor response spectra & valve qualification program description encl
EDELMAN,M R Cleveland Electric Illuminating Co 84/07/25
YOUNGBLOOD,B J Licensing Branch 1 400pp 25912 061 24X
Fiche 50-440,84/07/25,8408030145

8408070137 Forwards request for addl info & forms for use in preparation for 840813-17 audits by pump & valve operability review team & SQRT Opening & closeout meetings open to public
YOUNGBLOOD,B J Licensing Branch 1 84/07/25 EDELMAN,M R
Cleveland Electric Illuminating Co 18pp 25957 138 24X
Fiche 50-440,84/07/25,8408070137

8408070184 Forwards summary forms for one NSSS & one balance-of-plant item identified for upcoming SQRT audit Forms provide supplemental info to 840725 ltr
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/02
YOUNGBLOOD,B J Licensing Branch 1 15pp 25950 001 24X
Fiche 50-440,84/08/02,8408070184

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26127 238 24X
Fiche 50-000,84/08/06,8408070110

8408100005 Requests rev to QA program submitted on 830602, to fully comply w/requirements of Paragraph (3)(iii) of 10CFR50 55(f) Response requested within 30 days of ltr receipt
SPESSARD,R L Region 3, Office of Director 84/08/06 EDELMAN,M R
Cleveland Electric Illuminating Co 2pp 25990 101 24X
Fiche 50-440,84/08/06,8408100005

8408130492 Forwards lists of equipment selected for onsite audit of pump & valve operability assurance & seismic qualification of mechanical & electrical equipment programs scheduled for wk of 840813 Forms requested by 840808
YOUNGBLOOD,B J Licensing Branch 1 84/08/07 EDELMAN,M R
Cleveland Electric Illuminating Co 6pp 26058 346 24X
Fiche 50-440,84/08/07,8408130492

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408270320 Forwards addl clarifications to Rev 3 to Emergency Plan OM-15A submitted on 840428 Clarifications include changes to plan per SSER 4 & will be incorporated into Rev 4
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/20
DENTON,H R Office of Nuclear Reactor Regulation, Director. 12pp
26243 266 24X Fiche 50-440,84/08/20,8408270320

8408290396 Summary of 840619 meeting w/util, TERA, Illinois Power Co & Govt Accountability Project in Bethesda,MD re plant-specific responses to hydrogen control SER License Condition 5 List of attendees & viewgraphs encl
STEFANO,J J Licensing Branch 1 84/08/20 YOUNGBLOOD,B J
Licensing Branch 1 13pp 26310 001 24X Fiche: 50-440,84/08/20,
8408290396

F Security, medical, emergency & fire protection plans

8408150380 Forwards IE Insp Rept 50-440/84-13 on 840709-12 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 84/07/27
EDELMAN,M R Cleveland Electric Illuminating Co 2pp 26078 002
24X Fiche 50-440,84/07/27,8408150380

--8408150381 IE Insp Rept 50-440/84-13 on 840709-12 No violations or deviations noted Major areas inspected radiation protection program,including organization & staffing,training & procedures & radiography incident on 840616
MILLER,D E , GREGER,L R Region 3, Office of Director 84/07/27
6pp 26078 004 24X Fiche 50-440,84/07/27,8408150380

8408270320 Forwards addl clarifications to Rev 3 to Emergency Plan OM-15A submitted on 840428 Clarifications include changes to plan per SSER 4 & will be incorporated into Rev 4
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/20
DENTON,H R Office of Nuclear Reactor Regulation, Director 12pp
26243 266 24X Fiche 50-440,84/08/20,8408270320

8408310171 Forwards IV Haven,NOAA,comments re emergency meteorological capabilities Comments based on review of NUS-4338, "Description of Perry Nuclear Power Plant Emergency Offsite Dose Calculations " Comments should be reviewed
YOUNGBLOOD,B J Licensing Branch 1 FIN B-7527 84/08/22
EDELMAN,M R Cleveland Electric Illuminating Co 10pp 26351 340
24X Fiche 50-440,84/08/22,8408310171

Q Adjudicatory correspondence

8408140482 Informs that Jefferson Township Trustees request & support installation & maint of independent monitoring facilities & procedures at & around facility Served on 840814
WISE,C L Ashtabula County, OH DSB 028 84/07/18 NRC - No
Detailed Affiliation Given 1p 26060 279 24X
Fiche 50-440,84/07/18,8408140482

8408010229 Forwards State of OH emergency response plan & attached ltr from governor Ltr pertains to 840716 opposition to particularization of Issue 1 W/o encls W/svc list Related correspondence
SILBERG,J E Shaw, Pittman, Potts & Trowbridge SILBERG,J E
Sunflower Alliance DSB 653 84/07/25 BLOCH,P B , KLINE,J R ,
BRIGHT,G O Atomic Safety and Licensing Board Panel 3pp
25856 019 24X Fiche 50-440,84/07/25,8408010229

8408010214 Answer in opposition to Ohio Citizens for Responsible Energy 840706 motion for summary disposition of Issue 6 re installation of automated standby liquid control sys Related correspondence
SILBERG,J E Cleveland Electric Illuminating Co SILBERG,J E
Shaw, Pittman, Potts & Trowbridge DSB 672 84/07/30 Atomic
Safety and Licensing Board Panel 5pp 25856 032 24X
Fiche 50-440,84/07/30,8408010214

--8408010217 Statement of matl facts as to which there is no genuine issue Certificate of Svc encl
* Cleveland Electric Illuminating Co 84/07/30 Atomic Safety
and Licensing Board Panel 3pp 25856 037 24X
Fiche 50-440,84/07/30,8408010214

8408070498 Response opposing Ohio Citizens for Responsible Energy 840706 motion for summary disposition of Issue 6 Motion based on misinterpretation of 10CFR50 62(c)(4) Certificate of Svc encl Related correspondence
WOODHEAD,C P Hearing Branch 4 DSB 806 84/07/30 Atomic
Safety and Licensing Board Panel 6pp 25941 185 24X
Fiche 50-440,84/07/30,8408070498

8408090231 Thirteenth set of interrogatories pertaining to Issue 8 re hydrogen control Interrogatories concern generation,release & combustion of hydrogen gas in degraded core accident Certificate of Svc encl Related correspondence
HIATT,S L Ohio Citizens for Responsible Energy DSB 855
84/07/30 Cleveland Electric Illuminating Co 20pp 25971 170
24X Fiche 50-440,84/07/30,8408090231

8408090245 Motion to reopen discovery on Issue 8 re hydrogen control Certificate of Svc encl Related correspondence
HIATT,S L Ohio Citizens for Responsible Energy DSB 854
84/07/30 Atomic Safety and Licensing Board Panel 15pp
25972 170 24X Fiche 50-440,84/07/30,8408090245

8408090196 Motion for leave to reply to applicant & NRC responses to Ohio Citizens for Responsible Energy 840706 motion for summary disposition of Issue 6 Related correspondence
HIATT,S L Ohio Citizens for Responsible Energy DSB 851
84/08/03 Atomic Safety and Licensing Board Panel 1p
25972 028 24X Fiche 50-440,84/08/03,8408090196

--8408090202 Reply to applicant & NRC responses to Ohio Citizens for Responsible Energy 840706 motion for summary disposition of Issue 6 re automated liquid control sys W/svc list
HIATT,S L Ohio Citizens for Responsible Energy 84/08/03
Atomic Safety and Licensing Board Panel 9pp 25972 029 24X
Fiche 50-440,84/08/03,8408090196

8408150467 Answer opposing Ohio Citizens for Responsible Energy 840730 motion to reopen discovery on Issue 8 re hydrogen control Applicant will discuss specific discovery needs at 840905 meeting Certificate of Svc encl Related correspondence
SWIGER,M A Cleveland Electric Illuminating Co SWIGER,M A Shaw,
Pittman, Potts & Trowbridge DSB 066 84/08/14 Atomic Safety
and Licensing Board Panel 5pp 26068 249 24X
Fiche 50-440,84/08/14,8408150467

8408270057 Response opposing Ohio Citizens for Responsible Energy 840730 motion to reopen discovery on Issue 8 Motion should be denied in light of applicant duty to suppl responses to requests W/Certificate of Svc Related correspondence
WOODHEAD,C P Hearing Branch 4 DSB 300 84/08/20 Atomic
Safety and Licensing Board Panel 4pp 26247 064 24X
Fiche 50-440,84/08/20,8408270057

8408280437 Particularized objections to proposed emergency plan supporting Issue 1,per ASLB 840726 memorandum & order ASLB urged to waylay action on emergency preparations as contention & dismiss application for OL Svc list encl
LODGE,T J Sunflower Alliance DSB 361 84/08/20 30pp
26280 183 24X Fiche 50-440,84/08/20,8408280437

I Financial information

8408020118 Forwards Annual Financial Repts 1983 For Duquesne Light Co, Ohio Edison Co,Pennsylvania Power Co,Toledo Edison Co & Cleveland Electric Illuminating Co
EDELMAN,M R Cleveland Electric Illuminating Co 84/07/27
DENTON,H Office of Nuclear Reactor Regulation, Director 1p
25886 041 24X Fiche 50-440,84/07/20,8408020118

--8408020126 Annual Financial Rept 1983
ROGERS,J T , COLE,A W Pennsylvania Power Co 83/12/31 27pp
25886 170 24X Fiche 50-440,84/07/20,8408020118

O Inspection reports, IE Bulletins & correspondence

8408090293 Forwards IE Insp Repts 50-440/84-09 & 50-441/84-09 on 840501-0630 & notice of violation
WARNICK,R F Region 3, Office of Director 84/07/18 EDELMAN,M R
Cleveland Electric Illuminating Co 2pp 25994 173 24X
Fiche 50-440,84/07/18,8408090293

--8408090298 Notice of violation from insp on 840501-0630
WARNICK,R F Region 3, Office of Director 84/07/18 1p
25994 175 24X Fiche 50-440,84/07/18,8408090293

--8408090304 IE Insp Repts 50-440/84-09 & 50-441/84-09 on 840501-0630 Noncompliance noted Failure to follow tagging procedure
KNOP,R C Region 3, Office of Director 84/07/18 8pp
25994 176 24X Fiche 50-440,84/07/18,8408090293

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408150380 Forwards IE Insp Rept 50-440/84-13 on 840709-12 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 84/07/27
EDELMAN,M R Cleveland Electric Illuminating Co 2pp 26078 002
24X Fiche 50-440,84/07/27,8408150380

--8408150381 IE Insp Rept 50-440/84-13 on 840709-12 No violations or deviations noted Major areas inspected radiation protection program,including organization & staffing,training & procedures & radiography incident on 840616
MILLER,D E , GREGER,L R Region 3, Office of Director 84/07/27
6pp 26078 004 24X Fiche 50-440,84/07/27,8408150380

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03,
8408070401

8408010333 IE Info Notice 84-59, Deliberate Circumventing of Station Health Physics Procedures ' Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, 'Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24/ Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, 'Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408270278 Forwards Insp Repts 50-440/84-16 & 50-441/84-15 on 840717-20 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 84/08/10
EDELMAN,M R Cleveland Electric Illuminating Co 2pp 26258 159 24X Fiche 50-440,84/08/10,8408270278

--8408270288 Insp Repts 50-440/84-16 & 50-441/84-15 on 840717-20 No violations or deviations noted Major areas inspected preoperational radiological environ monitoring program & review of chemistry & radiochemistry program
OESTMANN,M J , SCHUMACHER,M C Region 3, Office of Director 84/08/10 6pp 26258 161 24X Fiche 50-440,84/08/10,8408270278

8408100009 IE Info Notice 84-63, 'Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408300179 Forwards Insp Repts 50-440/84-07 & 50-441/84-07 on 840409-12 & 0604-07 & notice of violation Requests audit of records to assure insp repts contain adequate info re identification of item inspected & results of insp
LITTLE,W S Region 3, Office of Director 84/08/14 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 26313 271 24X Fiche 50-440,84/08/14,8408300179

--8408300186 Notice of Violation from insp on 840409-12 & 0604-07
LITTLE,W S Region 3, Office of Director 84/08/14 2pp 26313 273 24X Fiche 50-440,84/08/14,8408300179

--8408300196 Insp Repts 50-440/84-07 & 50-441/84-07 on 840409-12 & 0604-07 Noncompliance noted failure to assure that Gilbert Assoc adequately reviewed & verified safety-related schematic & wiring diagrams re standby liquid control
NAIDU,K R , CHRISTNOT,E , FALEVITS,Z Region 3, Office of Director 84/08/14 25pp 26313 275 24X Fiche 50-440,84/08/14,8408300179

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408280129 Ack receipt of 840817 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/84-09 & 50-441/84-09
* Region 3, Office of Director 84/08/23 Cleveland Electric Illuminating Co 1p 26274 343 24X Fiche 50-440,84/08/23,8408280129

--8408280131 Responds to NRC 840718 ltr re violations noted in IE Insp Repts 50-440/84-09 & 50-441/84-09 Corrective actions mechanical foreign items identified w/properly initiated tag & placement of tag documented in log book
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/17
WARNICK,R F Region 3, Office of Director 3pp 26274 344 24X Fiche 50-440,84/08/23,8408280129

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp 25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/ TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10,8408060050

8408090261 Final Deficiency Rept (ROC 81(83)) re Westinghouse Class IE penetrations (1R72) Initially reported on 830824 Engineering Change Notice 21802-363-05 initiated to revise procurement spec to permit use of ASME Code Case N242
EDELMAN,M R Cleveland Electric Illuminating Co 84/07/26
KEPPLER,J G Region 3, Office of Director 2pp 25994 283 24X Fiche 50-440,84/07/26,8408090261

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diese) Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000,84/07/27,8408060102

8408090148 Final Deficiency Rept (ROC 92(84)) re potential problem w/standby diesel generator loose flexible coupling drive hubs supplied by TDI Initially reported on 840120 Also reported per Part 21
EDELMAN,M R Cleveland Electric Illuminating Co 84/07/27
KEPPLER,J G Region 3, Office of Director 2pp 25993 176 24X Fiche 50-440,84/07/27,8408090148

8408060324 Forwards "Design Review of Elliott Model 4SG Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24X Fiche 50-000,84/08/01,8408060324

8408130393 Final Deficiency Rept (RDC 49(82)) re GE water level transmitters of incorrect range in reactor pressure vessels Initially reported on 820312 GE issued field disposition instructions to change to narrow-range transmitters
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/01
KEPPLER,J G Region 3, Office of Director 2pp 26011 106 24X
Fiche 50-440,84/08/01,8408130393

8408220498 Final deficiency rept re condition of Div 1 Class 1E bus during loss of offsite power Initially reported on 840709 Design change providing contacts closed in remote position & open in local position initiated
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/07
KEPPLER,J G Region 3, Office of Director 2pp 26196 013 24X
Fiche 50-440,84/08/07,8408220498

8408220502 Supplemental final deficiency rept re poor workmanship in two HPCS diesel generator local panels Discrepancies in nonconformance repts will be resolved by 840830
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/09
KEPPLER,J G Region 3, Office of Director 1p 26196 012 24X
Fiche 50-440,84/08/09,8408220502

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000,84/08/13,8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000,84/08/14,8408160395

--8408160397 "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

8408300054 Interim deficiency rept re concave 2 1 unequal leg filler welds installed in reactor bldg by Johnson Controls,Inc Initially reported on 840718 Indoctrination & training given to personnel Final rept expected by 850111
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/17
KEPPLER,J G Region 3, Office of Director 2pp 26307 238 24X
Fiche 50-440,84/08/17,8408300054

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000,84/08/23,8408290179

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000,
84/08/10,8408140426

DOCKET 50-441 PERRY NUCLEAR POWER PLANT UNIT 2

A Application/construction stage documents & correspondence

8408030145 Forwards summary forms on equipment for SQRT & pump & valve operability review team audits by Equipment Qualification Branch Floor response spectra & valve qualification program description encl
EDELMAN,M R Cleveland Electric Illuminating Co 84/07/25
YOUNGBLOOD,B J Licensing Branch 1 400pp 25912 061 24X
Fiche 50-440,84/07/25,8408030145

8408070184 Forwards summary forms for one NSSS & one balance-of-plant item identified for upcoming SQRT audit Forms provide supplemental info to 840725 ltr
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/02
YOUNGBLOOD,B J Licensing Branch 1 15pp 25950 001 24X
Fiche 50-440,84/08/02,8408070184

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408100005 Requests rev to QA program submitted on 830602, to fully comply w/requirements of Paragraph (3)(iii) of 10CFR50 55(f) Response requested within 30 days of ltr receipt
SPESSARD,R L Region 3, Office of Director 84/08/06 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 25990 101 24X
Fiche 50-440,84/08/06,8408100005

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

E NRC Safety Evaluation Report (SER), supple & correspondence

8408270320 Forwards addl clarifications to Rev 3 to Emergency Plan OM-15A submitted on 840428 Clarifications include changes to plan per SSER 4 & will be incorporated into Rev 4
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/20
DENTON,H R Office of Nuclear Reactor Regulation, Director 12pp
26243 266 24X Fiche 50-440,84/08/20,8408270320

8408290396 Summary of 840619 meeting w/util,TERA, Illinois Power Co & Govt Accountability Project in Bethesda,MD re plant-specific responses to hydrogen control SER License Condition 5 List of attendees & viewgraphs encl
STEFANO,J J Licensing Branch 1 84/08/20 YOUNGBLOOD,B J
Licensing Branch 1 13pp 26310 001 24X Fiche 50-440,84/08/20,
8408290396

F Security, medical, emergency & fire protection plans

8408270320 Forwards addl clarifications to Rev 3 to Emergency Plan OM-15A submitted on 810428 Clarifications include changes to plan per SSER 4 & will be incorporated into Rev 4
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/20
DENTON,H R Office of Nuclear Reactor Regulation, Director 12pp
26243 266 24X Fiche 50-440,84/08/20,8408270320

8408310171 Forwards IV Hoven,NOAA,comments re emergency meteorological capabilities Comments based on review of NUS-4336, "Description of Perry Nuclear Power Plant Emergency Offsite Dose Calculations " Comments should be reviewed
YOUNGBLOOD,B J Licensing Branch 1 TIN B-7527 84/08/22
EDELMAN,M R Cleveland Electric Illuminating Co 10pp 26351 340
24X Fiche 50-440,84/08/22,8408310171

G Adjudicatory correspondence

8408140482 Informs that Jefferson Township Trustees request & support installation & maint of independent monitoring facilities & procedures at & around facility Served on 840814
WISE,C L Ashtabula County, OH DSB 028 84/07/18 NRC - No Detailed Affiliation Given 1p 26060 279 24X
Fiche 50-440,84/07/18,8408140482

--8408020126 Annual Financial Rept 1983
ROGERS, J T ; COLE, A W Pennsylvania Power Co 83/12/31 27pp
25986 170 24X Fiche 50-440, 84/07/20, 8408020118

Q Inspection reports, IE Bulletins & correspondence

8408090293 Forwards IE Insp Repts 50-440/84-09 & 50-441/84-09 on
840501-0630 & notice of violation
WARNICK, R F Region 3, Office of Director 84/07/18 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 25994 173 24X
Fiche 50-440, 84/07/18, 8408090293

--8408090304 IE Insp Repts 50-440/84-09 & 50-441/84-09 on 840501-0630
Noncompliance noted failure to follow tagging procedure
KNOP, R C Region 3, Office of Director 84/07/18 8pp
25994 176 24X Fiche 50-440, 84/07/18, 8408090293

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture
Intrusion in Safety-Related Electrical Equipment at
Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070401 Informs that new sys of acknowledging receipt of licensee
correspondence re noncompliance found during insp
instituted, effective 840920 Preprinted form will be used
rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03,
8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station
Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator
Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New
York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR
Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New
York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to
Patients Undergoing Co-60 Teletherapy Treatments " Svc
list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post
830103) 84/08/10 Consolidated Edison Co of New York, Inc.
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408270278 Forwards Insp Repts 50-440/84-16 & 50-441/84-15 on
840717-20 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/08/10
EDELMAN, M R Cleveland Electric Illuminating Co 2pp 26258 159
24X Fiche 50-440, 84/08/10, 8408270278

--8408270288 Insp Repts 50-440/84-16 & 50-441/84-15 on 840717-20 No
violations or deviations noted Major areas inspected:
preoperational radiological environ monitoring program &
review of chemistry & radiochemistry program
OESTMANN, M J ; SCHUMACHER, M C Region 3, Office of Director
84/08/10 6pp 26258 161 24X Fiche 50-440, 84/08/10, 8408270278

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New
York, Inc 119pp 26197.218 24X Fiche 50-000, 84/08/13, 8408100009

8408300179 Forwards Insp Repts 50-440/84-07 & 50-441/84-07 on
840409-12 & 0604-07 & notice of violation Requests audit of
records to assure insp repts contain adequate info re
identification of item inspected & results of insp
LITTLE, W S Region 3, Office of Director 84/08/14 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 26313 271 24X
Fiche 50-440, 84/08/14, 8408300179

--8408300186 Notice of violation from insp on 840409-12 & 0604-07
LITTLE, W S Region 3, Office of Director 84/08/14 2pp
26313 273 24X Fiche 50-440, 84/08/14, 8408300179

--8409300196 Insp Repts 50-440/84-07 & 50-441/84-07 on 840409-12 & 0504-07 Noncompliance noted failure to assure that Gilbert Assoc adequately reviewed & verified safety-related schematic & wiring diagrams re standby liquid control
NAIDU K R , CHRISTNOT E FALEVITS Z Region 3 Office of Director 84/08/14 25pp 26313 275 24X Fiche 50-440,84/08/14, 8408300179

8408100038 IE Info Notice 84-64, BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408280129 Ack receipt of 840817 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/84-09 & 50-441/84-09
* Region 3, Office of Director 84/08/23 Cleveland Electric Illuminating Co 1p 26274 343 24X Fiche 50-440,84/08/23, 8408280129

--8408280131 Responds to NRC 840718 ltr re violations noted in IE Insp Repts 50-440/84-09 & 50-441/84-09 Corrective actions mechanical foreign items identified w/properly initiated tag & placement of tag documented in log book
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/17
WARNICK,R F Region 3, Office of Director 3pp 26274 344 24X Fiche 50-440,84/08/23,8408280129

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp 24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp 25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/ TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10, 8408060050

8408090261 Final Deficiency Rept [RDC 81(85)] re Westinghouse Class 1E penetrations (1R72) Initially reported on 830814 Engineering Change Notice 21802-363-05 initiated to revise procurement spec to permit use of ASME Code Case N242
EDELMAN,M R Cleveland Electric Illuminating Co 84/07/26
KEPPLER,J G Region 3, Office of Director 2pp 25994 283 24X Fiche 50-440,84/07/26,8408090261

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000 84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139 24X Fiche 50-000,84/07/27 8108060102

8408090148 Final Deficiency Rept [RDC 92(84)] re potential problem w/standby diesel generator loose flexible coupling drive hubs supplied by TDI Initially reported on 840120 Also reported per Part 21
EDELMAN,M R Cleveland Electric Illuminating Co 84/07/27
KEPPLER,J G Region 3, Office of Director 2pp 25993 176 24X Fiche 50-440,84/07/27,8408090148

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV 20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24X Fiche 50-000,84/08/01,8408060324

8408130393 Final Deficiency Rept [RDC 49(82)] re GE water level transmitters of incorrect range in reactor pressure vessels Initially reported on 820312 GE issued field disposition instructions to change to narrow-range transmitters
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/01
KEPPLER,J G Region 3, Office of Director 2pp 26011 106 24X Fiche 50-440,84/08/01,8408130393

8408220498 Final deficiency rept re condition of Div 1 Class 1E bus during loss of offsite power Initially reported on 840709 Design change providing contacts closed in remote position & open in local position initiated
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/07
KEPPLER,J G Region 3, Office of Director 2pp 26196 013 24X Fiche 50-440,84/08/07,8408220498

8408220502 Supplemental final deficiency rept re poor workmanship in two HPCS diesel generator local panels Discrepancies in nonconformance repts will be resolved by 840830
EDELMAN,M R Cleveland Electric Illuminating Co 84/08/09
KEPPLER,J G Region 3, Office of Director 1p 26196 012 24X Fiche 50-440,84/08/09,8408220502

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84 6-93 84/08/31 44pp 26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program,testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X Fiche 50-000,84/08/13,8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation,plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp 26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL,per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000,84/08/14,8408160395

DOCKETED ITEMS

--8408160397 "Design Review of Elliott Model 90s Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAA-84-5-7 84/07/31 61pp 26088 165 24X Fiche 50-000 84/08/14 8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000,84 08/23,8408290179

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ore,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8408070332 Forwards correspondence from two cable manufacturers re apparent deviation from FSAR concerning cable tray loading criteria for heavy power cables Effect on ampacity insignificant Proposed FSAR change encl
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 84/07/12 KNIGHTON,G W Licensing Branch 3 10pp 25945 179 24X Fiche 50-443,84/07/12,8408070332

8408130217 Accepts conditionally util 840622 request to use ASME Code Case N-368 for application in pressure testing of piping associated w/discharge side of Code Classes 2 & 3 centrifugal pumps Case should be documented in FSAR
KNIGHTON,G W Licensing Branch 3 84/07/30 HARRISON,R J Public Service Co of New Hampshire 5pp 26058 329 24X Fiche 50-443,84/07/30,8408130217

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda,MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH,B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000,84/08/06,8408070110

8408160371 Forwards nonproprietary WCAP-10566 & proprietary WCAP-10567, "Technical Bases for Eliminating Large Primary Loop Pipe Rupture ," per Generic Ltr 84-04 & application for withholding info Proprietary rept withheld (ref 10CFR2 790)
DE VINCENTIS,J Yankee Atomic Electric Co DE VINCENTIS,J Public Service Co of New Hampshire 84/08/09 KNIGHTON,G W Licensing Branch 3 2pp 26091 099 24X Fiche 50-443,84/08/09,8408160371

--8408160373 Requests withholding of stated proprietary rept from public disclosure (ref 10CFR2 790) Affidavit CAW-83-80 encl
WIESEMANN,R A Westinghouse Electric Corp 84/08/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26091 101 24X Fiche 50-443,84/08/09,8408160371

--8408160378 Nonproprietary "Technical Bases For Eliminating Large Primary Loop Pipe Rupture as Structural Design Basis for Seabrook Units 1 & 2 " Info deleted (ref 10CFR2 790)
SWAMY,S A , CLARK,H F , LEE,Y S Westinghouse Electric Corp
WCAP-10566 84/08/30 40pp 26091 107 24X
Fiche 50-443,84/08/09,8408160371

8408230381 Summary of 840809 mgt meeting w/util in Bethesda,MD re status of facility engineering,const licensing,startup, operations & QA Viewgraphs & attendence list encl
NERSES,V Licensing Branch 3 84/08/16 Licensing Branch 3 67pp 26230 268 24X Fiche 50-443,84/08/16,8408230381

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408070362 Responds to NRC review of util conformance to NUREG-0737, Suppl 1 SER Outstanding Issue 19 NRC concerns re sys function,task analysis & control room inventory addressed Emergency response procedure program encl
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 84/07/30 KNIGHTON,G W Licensing Branch 3 202pp 25944 284 24X Fiche 50-443,84/07/30,8408070362

F Security, medical, emergency & fire protection plans

8407300089 Summary of 840711 meeting w/util in Bethesda,MD re revs to fire protection rept Meeting notice & attendance roster encl
SINGH,B K Licensing Branch 3 84/07/19 Licensing Branch 3 5pp 25816 333 24X Fiche 50-443,84/07/19,8407300089

8408070362 Responds to NRC review of util conformance to NUREG-0737, Suppl 1,SER Outstanding Issue 19 NRC concerns re sys function,task analysis & control room inventory addressed Emergency response procedure program encl
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 84/07/30 KNIGHTON,G W Licensing Branch 3 202pp 25944 284 24X Fiche 50-443,84/07/30,8408070362

--8408070365 Rev 1 to Emergency Response Procedure 0S1300, "Reactor Tr or Safety Injection "
* Yankee Atomic Electric Co 84/06/05 25pp 25945 100 24X Fiche 50-443,84/07/30,8408070362

G Adjudicatory correspondence

8408010201 Ack receipt of 840723 ltr inviting comments on rept describing visit to facility Staff will not file comments on rept
PERLIS,R G Hearing Branch 3 DSB 684 84/07/31 ASSELSTINE,J K Commissioners 2pp 25854 354 24X Fiche 50-443,84/07/31, 8408010201

8408070403 Informs that NRC will not be filing any comments on rept describing Asselstine visit to util
PERLIS,R G Hearing Branch 3 DSB 808 84/07/31 ASSELSTINE,J K Commissioners 2pp 25942 182 24X Fiche 50-443,84/07/31, 8408070403

8408140456 Informs that Town of Durham will not file comments on rept describing visit to facility Related correspondence
STILES,N W Durham, NH DSB 022 84/08/06 ASSELSTINE,J K Commissioners 1p 26060 360 24X Fiche 50-443,84/08/06, 8408140456

8408240234 Petition for enforcement & motion for suspension of const Commission cannot find that const at plant can be conducted w/reasonable assurance of safety & must suspend authority for const until owners obtain amend to CP
CURRAN,D , JORDAN,W S New England Coalition on Nuclear Pollution
JORDAN,W S Harmon & Weiss DSB 262 84/08/22 Office of Nuclear Reactor Regulation, Director 23pp 26227 331 24X
Fiche 50-443,84/08/22,8408240234

Q Inspection reports, IE Bulletins & correspondence

8408170109 Forwards IE Const Appraisal Team Insp Rept 50-443/84-07 on 840423-0504 & 14-25 Communication deficiencies resulting from ineffective mgt of interfaces demonstrated Executive summary & list of potential enforcement actions encl
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 84/07/18 HARRISON,R J Public Service Co of New Hampshire 9pp 26130 078 24X Fiche 50-443,84/07/18,8408170109

--8408170117 IE Const Appraisal Team Insp Rept 50-443/84-07 on 840423-0504 & 14-25 Violations noted failure to identify nonconformances & take corrective action for control of cable identification & markings
BEACH,A B , GEORGIEV,O B , ROHRBACHER,R A Reactor Construction Branch 84/06/28 101pp 26130 087 24X Fiche 50-443,84/07/18, 8408170109

--8408170117 IE Const Appraisal Team Insp Rept 50-443/84-07 on 840423-0504 & 14-25 Violations noted failure to identify nonconformances & take corrective action for control of cable identification & markings
BEACH,A B , PHILLIPS,H W , WONG,H J Reactor Construction Branch 84/06/28 101pp 26130 087 24X Fiche 50-443,84/07/18, 8408170109

--8408170117 IE Const Appraisal Team Insp Rept 50-443/84-07 on 840423-0504 & 14-25 Violations noted failure to identify nonconformances & take corrective action for control of cable identification & markings
BEACH, A B Reactor Construction Branch GRAY, E H Region 1, Office of Director NIGHTINGALE, E Region 3, Office of Director 84/06/28 101pp 26130 087 21X Fiche 50-443, 84/07/18, 8408170109

8408150256 Forwards IE Insp Repts 50-443/84-08 & 50-444/84-03 on 840529-0625 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/07/24
HARRISON, R J Public Service Co of New Hampshire 2pp 26076 352 24X Fiche 50-443, 84/07/24, 8408150256

--8408150258 Notice of violation from insp on 840529-0625
* Region 1, Office of Director 84/07/24 1p 26076 354 24X Fiche 50-443, 84/07/24, 8408150256

--8408150262 IE Insp Repts 50-443/84-08 & 50-444/84-03 on 840529-0625 Violation noted inadequate storage & preservation of NSSS components at Unit 2
CERNE, A C , WESCOTT, H M Region 1, Office of Director GALLO, R M Division of Project & Resident Programs 84/07/11 9pp 26076 355 24X Fiche 50-443, 84/07/24, 8408150256

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Undersized Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68 Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 048 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LER, & related correspondence

8408240332 Submits annotated requests for followup on potentially generic problem in encl Part 21 rept from Basler Electric re SCRs on nuclear exciters mounted w/too much pressure
NORELIUS, C E Division of Project & Resident Programs 84/04/25
JORDAN, E L Director s Office, Office of Inspection and Enforcement 1p 26225 303 24X Fiche 50-000, 84/04 25, 8408240332

8408100013 Interim deficiency rept re cracked concrete pedestals supporting diesel generator exhaust silencer tank Initially reported on 840702 Support sys for exhaust silencers & diesel generator trains redesigned
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/07/30 STAROSTECKI, R Division of Project & Resident Programs 3pp 25990 105 24X Fiche 50-443, 84/07/30, 8408100013

8408100136 Interim deficiency rept re Limitorque motor operators Initially reported on 840525 Limitorque improved design by replacing fiber shims w/metal shims Next rept will be submitted by 841031
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/07/30 STAROSTECKI, R Division of Project & Resident Programs 4pp 25996 344 24X Fiche 50-443, 84/07/30, 8408100136

8408100083 Interim deficiency rept re cracked capstan springs in Pacific Scientific mechanical shock arresters Initially reported on 831024 Caused by improper forming of spring tangs during mfg Suspect shock arresters returned for exam
DEVINCENTIS, J Public Service Co of New Hampshire 84/07/31
STAROSTECKI, R Division of Project & Resident Programs 4pp 25990 184 24X Fiche 50-443, 84/07/31, 8408100083

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8408070332 Forwards correspondence from two cable manufacturers re apparent deviation from FSAR concerning cable tray loading criteria for heavy power cables Effect on ampacity insignificant Proposed FSAR change encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/07/12 KNIGHTON, G W Licensing Branch 3 10pp 25945 179 24X Fiche 50-443, 84/07/12, 8408070332

8408130217 Accepts conditionally util 840622 request to use ASME Code Case N-368 for application in pressure testing of piping associated w/discharge side of Code Classes 2 & 3 centrifugal pumps Case should be documented in FSAR
KNIGHTON, G W Licensing Branch 3 84/07/30 HARRISON, R J Public Service Co of New Hampshire 5pp 26058 325 24X Fiche 50-443, 84/07/30, 8408130217

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda, MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH, B K Licensing Branch 3 84/07/31 Licensing Branch 3 18pp 25983 130 24X Fiche 50-000, 84/07/31, 8408090497

8408070110 Generic ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000, 84/08/06, 8408070110

8408160371 Forwards nonproprietary WCAP-10566 & proprietary WCAP-10567, "Technical Bases for Eliminating Large Primary Loop Pipe Rupture ," per Generic Ltr 84-04 & application for withholding info Proprietary rept withheld (ref 10CFR2 790)
DE VINCENTIS, J Yankee Atomic Electric Co DE VINCENTIS, J Public Service Co of New Hampshire 84/08/09 KNIGHTON, G W Licensing Branch 3 2pp 26091 099 24X Fiche 50-443, 84/08/09, 8408160371

--8408160373 Requests withholding of stated proprietary rept from public disclosure (ref 10CFR2 790) Affidavit CAW-83-80 encl
NIPSEMANN, R A Westinghouse Electric Corp 84/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 26091 101 24X Fiche 50-443, 84/08/09, 8408160371

--8408160378 Nonproprietary Technical Bases For Eliminating Large Primary Loop Pipe Rupture as Structural Design Basis for Seabrook Units 1 & 2 " Info deleted (ref 10CFR2 790)
SWAMY S A CLARK H F , LEE,Y S Westinghouse Electric Corp
WCAP-10566 84/06/30 40pp 26091 107 24X
Fiche 50-443 84/08/09,8408160371

8408200275 Generic ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 241 24X
Fiche 50-000,84/08/20,8408200275

E NRC Safety Evaluation Report (SER), suppls & correspondence

84080/0362 Responds to NRC review of util conformance to NUREG-0737, Suppl 1,SER Outstanding Issue 19 NRC concerns re sys function,task analysis & control room inventory addressed Emergency response procedure program encl
DEVINCENTIS,J Yankee Atomic Electric Co 84/07/30 KNIGHTON,G W Licensing Branch 3 202pp 25944 284 24X Fiche 50-443,84/07/30, 8408070362

F Security, medical, emergency & fire protection plans

8407300089 Summary of 840711 meeting w/util in Bethesda,MD re revs to fire protection rept Meeting notice & attendance roster encl
SINGH,B K Licensing Branch 3 84/07/19 Licensing Branch 3
5pp 25816 333 24X Fiche 50-443,84/07/19,8407300089

8408070362 Responds to NRC review of util conformance to NUREG-0737, Suppl 1,SER Outstanding Issue 19 NRC concerns re sys function,task analysis & control room inventory addressed Emergency response procedure program encl
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 84/07/30 KNIGHTON,G W Licensing Branch 3 202pp 25944 284 24X Fiche 50-443,84/07/30,8408070362

--8408070365 Rev 1 to Emergency Response Procedure OS1300, "Reactor Trip or Safety Injection "
* Yankee Atomic Electric Co 84/06/05 25pp 25945 100 24X
Fiche 50-443,84/07/30,8408070362

G Adjudicatory correspondence

8408010201 Ack receipt of 840723 ltr inviting comments on rept describing visit to facility Staff will not file comments on rept
PERLIS,R G Hearing Branch 3 DSB 684 84/07/31 ASSELSTINE,J K
Commissioners 1pp 25914 754 24X Fiche 50-443,84/07/31, 8408010201

8408070103 Informs that NRC will not be filing any comments on rept describing Asselsline visit to util
PERLIS,R G Hearing Branch 3 DSB 808 84/07/31 ASSELSTINE,J K
Commissioners 2pp 25942 182 24X Fiche 50-443,84/07/31, 8408070403

8408140456 Informs that Town of Durham will not file comments on rept describing visit to facility Related correspondence
STILES,N W Durham, NH DSB 822 84/08/06 ASSELSTINE,J K
Commissioners 1p 26060 360 24X Fiche 50-443,84/08/06, 8408140456

8408240234 Petition for enforcement & motion for suspension of const Commission cannot find that const at plant can be conducted w/reasonable assurance of safety & must suspend authority for const until owners obtain amend to CP
CURRAN,D , JORDAN,W S New England Coalition on Nuclear Pollution
JORDAN,W S Harmon & Weiss DSB 262 84/08/22 Office of Nuclear Reactor Regulation, Director 23pp 26227 331 24X
Fiche 50-443,84/08/22,8408240234

H Inspection reports IE Bulletins & correspondence

8408150256 Forwards IE Insp Rpts 50-443/84-08 & 50-444/84-03 on 840529-0625 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 84/07/24
HARRISON,R J Public Service Co of New Hampshire 2pp 26076 352
24X Fiche 50-443,84/07/24,8408150256

--8408150258 Notice of Violation from insp on 840529-0625
* Region 1, Office of Director 84/07/24 1p 26076 354 24X
Fiche 50-443,84/07/24,8408150256

--8408150262 IE Insp Rpts 50-443/84-08 & 50-444/84-03 on 840529-0625 Violation noted inadequate storage & preservation of NSSS components at Unit 2
CERNE,A C NECOLOTI,R M Region 1, Office of Director GALLO,R M
Division of Project & Resident Programs 84/07/11 9pp
26076 355 24X Fiche 50-443,84/07/24,8408150256

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
ORACL,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

B Reportable occurrences, LERs & related correspondence

8408240332 Submits annotated requests for followup on potentially generic problem in encl Part 21 rept from Basler Electric re SCRs on nuclear exciters mounted w/too much pressure
NORELIUS,C E Division of Project & Resident Programs 84/04/25
JORDAN,E L Director's Office, Office of Inspection and Enforcement
1p 26225 303 24X Fiche 50-000,84/04/25,8408240332

8408100013 Interim deficiency rept re cracked concrete pedestals supporting diesel generator exhaust silencer tank Initially reported on 840702 Support sys for exhaust silencers & diesel generator trains redesigned
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 84/07/30 STAROSTECKI,R Division of Project & Resident Programs 3pp 25990 105 24X
Fiche 50-443,84/07/30,8408100013

8408100136 Interim deficiency rept re Limitorque motor operators Initially reported on 840525 Limitorque improved design by replacing fiber shims w/metal shims Next rept will be submitted by 841031
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 84/07/30 STAROSTECKI,R Division of Project & Resident Programs 4pp 25996 344 24X
Fiche 50-443,84/07/30,8408100136

8408100083 Interim deficiency rept re cracked capstan springs in Pacific Scientific mechanical shock arresters Initially reported on 831024 Caused by improper forming of spring tangs during mfg Suspect shock arresters returned for exam
DEVINCENTIS,J Public Service Co of New Hampshire 84/07/31
STAROSTECKI,R Division of Project & Resident Programs 4pp
25990 184 24X Fiche 50-443,84/07/31,8408100083

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 1

A Application/construction stage documents & correspondence

8309130110 Forwards FR notice & Director's Decision DD-83-11 denying CASE 830128 10CFR2 206 petition for show cause order re ITT Grinnell & NPS Industries,Inc design criteria for pipe supports
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/08/18 ELLIS,J Citizens Association for Sound Energy 2pp 25975 323 24X Fiche 50-445,83/08/18,8309130110

--8309130112 Notice of denial of CASE 10CFR2 206 petition requesting util be required to provide documents re ITT Grinnel & NPA Industries,Inc design criteria for pipe supports
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/08/19 1p 25975 325 24X Fiche 50-445, 83/08/18,8309130110

--8309130117 Director's Decision DD-83-11,denying CASE 830128 10CFR2 206 petition for show cause order re production of ITT Grinnell & NPS Industries,Inc design criteria for pipe supports
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/08/19 8pp 25975 326 24X
Fiche 50-445,83/08/18,8309130110

8311020513 Ack receipt of 830928 response to notice of violation & proposed imposition of civil penalty dtd 830829 Final determination re imposition of civil penalty deferred until resolution of DOL Case 82 ERA-9
DEYOUNG,R Director's Office, Office of Inspection and Enforcement
83/10/17 GARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 25975 334 24X
Fiche 50-445,83/10/17,8311020513

8303300734 Ack receipt of Citizens Assoc for Sound Energy petition for show cause order or,in alternative,why util should not provide requested documents re component design
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/03/03 ELLIS,J Citizens Association for Sound Energy 1p 25951 358 24X Fiche 50-445,84/03/03,8303300734

--8303300736 Notice of receipt of petition under 10CFR2 206 for order to show cause or,in alternative,why util should not provide requested documents re component design
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/03/03 2pp 25951 359 24X
Fiche 50-445,84/03/03,8303300734

8408010078 Informs that licensee responses to NUREG-0737,Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling," acceptable SSER input & milestones encl
YOUNGBLOOD,B J Licensing Branch 1 84/07/19 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
12pp 25897 225 24X Fiche 50-445,84/07/19,8408010078

8408010112 Informs that licensee updates to QA organization documented in FSAR Amends 42-49 acceptable Evaluation rept for inclusion in SSER,prior to Unit 1 licensing,encl
YOUNGBLOOD,B J Licensing Branch 1 84/07/19 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
3pp 25873 336 24X Fiche 50-445,84/07/19,8408010112

8408060155 Notification of 840627 meeting w/util in Bethesda,MD to discuss studies re protective coatings inside containment & impact of coating failures on sump performance under accident conditions
BURWELL S B Licensing Branch 1 84/07/26 YOUNGBLOOD,B J
Licensing Branch 1 1pp 25976 130 24X Fiche 50-445,84/07/26, 8408060155

8408130449 Forwards "Control of Heavy Loads (Phase II-NUREG-0612) for Commanche Peak,Units 1 & 2 " draft technical evaluation rept
YOUNGBLOOD,B J Licensing Branch 1 84/07/26 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
3pp 26059 271 24X Fiche 50-445,84/07/26,8408130449

--8408130455 Control of Heavy Loads (Phase II-NUREG-0612),Commanche Peak,Units 1 & 2,' draft technical evaluation rept
YEN,T C EG&G, Inc FIN A-6457 84/04/30 NRC - No Detailed Affiliation Given 40pp 26059 274 24X Fiche 50-445,84/07/26, 8408130449

8408060165 Responds to Generic Ltr 83-10C re resolution of NUREG-0737, Item II K 3 5, 'Automatic Trip of Reactor Coolant Pumps " Facilities bound by results of Westinghouse Owners Group manual pump trip justification rept
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/27 YOUNGBLOOD,B J Licensing Branch 1
1p 25932 197 24X Fiche 50-445,84/07/27,8408060165

8408090479 Notification of 840809 meeting w/BNL in Glen Rose,TX to discuss util responses to allegations re protective coating practices
VIETTI,A Licensing Branch 3 84/07/27 IPPOLITO,T A Division of Licensing 14pp 25983 160 24X Fiche 50-445,84/07/27,8408090479

8408030153 Responds to agenda for 840808 meeting at site re protective coatings practices Requests permission to respond to NRC questions in writing by 840813
GEORGE,J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/31 IPPOLITO,J A Division of Licensing
1p 25912 014 24X Fiche 50-445,84/07/31,8408030153

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda,MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH,B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497

8408090445 Notification of cancellation of 840808 meeting w/BNL in Bethesda,MD to discuss util responses to allegations re protective coating practices
VIETTI,A Licensing Branch 3 84/08/01 IPPOLITO,T A Division of Licensing 3pp 25983 215 24X Fiche 50-445,84/08/01,8408090445

8408090505 Ack receipt of 840731 request for opportunity to respond to 840727 meeting notice on 840808 meeting w/util re protective coating practices in writing by 840813 Meeting schedule canceled
IPPOLITO,T A Division of Licensing 84/08/02 GEORGE,J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
1p 25983 127 24X Fiche 50-445,84/08/02,8408090505

8408070455 Board Notification 84-124 forwards info re allegations of improper const practices on main condensers
EISENHUT,D G Division of Licensing 84/08/03 BLOCH,P ,
JORDAN,W , MCCOLLOM,K Atomic Safety and Licensing Board Panel
2pp 25971 001 24X Fiche 50-445,84/08/03,8408070455

--8408090105 Responds to NRC 840619 ltr re alleged improper const practices involving main condensers QA program not invoked because main condenser not safety-related,but activities monitored closely Leakage testing & detection discussed
CLEMENTS,B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/09 BANGART,R L Region 4, Office of Director 2pp 25971 032 24X Fiche 50-445,84/08/03, 8408070455

8408140383 Discusses confirmatory measurements performed by util radiochemistry lab on liquid "unknown" sample supplied to NRC ref lab w/known isotopic activities Isotopic activities in liquid sample traceable to NBS lab intercomparison
BANGART,R L Region 4, Office of Director 84/08/04 SPENCE,M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26052 343 24X Fiche 50-445,84/08/04,8408140383

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090451 Board Notification 84-132 transmits NRC Special Review Team rept re 840403-13 site re lack of mgt control of const, insp & test programs
EISENHUT D G Division of Licensing 84/08/06 PALLADINO Consolidated Edison Co of New York Inc ROBERTS, ASSELSTINE Commissioners 72pp 26031 214 24X Fiche 50-445, 84/08/06, 8408070495

8408100050 Informs that documents re Mar 1984 T-shirt incident returned to T Vega on 840720 following reproduction
BANDART, R L Region 4, Office of Director 84/08/06 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 25990 038 24X Fiche 50-445, 84/08/06, 8408100050

8408160157 Forwards table providing description of Amend 51 to FSAR
MARSHALL, J S Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 84/08/08 BURWELL, S B Office of Nuclear Reactor Regulation, Director 3pp 26085 169 24X Fiche 50-445, 84/08/08, 8408160157

8408170138 Forwards evaluation re resolution of SER Confirmatory Issue 5, TMI action plan items & status of review of steam generator tube rupture event
YOUNGBLOOD, B J Licensing Branch 1 84/08/09 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 10pp 26134 335 24X Fiche 50-445, 84/08/09, 8408170138

8408160335 Responds to 840809 request for addl info re environ qualification concerning FSAR data for MS-78, MS-76, ESE-27 & ESE-40 & forwards "Radiation Analysis of Barton Model 288A Differential Pressure Indicating Switch ," test rept
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/10 YOUNGBLOOD, B J Licensing Branch 1 2pp 26085 341 24X Fiche 50-445, 84/08/10, 8408160335

--8408160340 "Radiation Analysis of Barton Model 288A Differential Pressure Indicating Switch for Texas Utils Generating Co "
RIEDL, T J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) EQ/IES(84)-164 84/08/10 7pp 26085 343 24X Fiche 50-445, 84/08/10, 8408160335

8408160412 Submits list of items for which cable splicing in raceways justified, per requirement of Rev 1 to Reg Guide 1 75
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/10 YOUNGBLOOD, B J Licensing Branch 1 2pp 26085 356 24X Fiche 50-445, 84/08/10, 8408160412

8408200156 Notification of 840814 & 15 meetings w/util in New York, NY to conduct audit review of structural analysis on upper lateral restraint beam prepared for motions for summary disposition
BURWELL, S B Licensing Branch 1 84/08/13 YOUNGBLOOD, B J Licensing Branch 1 3pp 26142 322 24X Fiche 50-445, 84/08/13, 8408200156

8408280342 Forwards SSER re deferral of listed preoperational tests Proposed deferrals acceptable
YOUNGBLOOD, B J Licensing Branch 1 84/08/17 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26294 031 24X Fiche 50-445, 84/08/17, 8408280342

--8408280346 SSER re deferral of listed preoperational tests Proposed deferrals acceptable
* NRC - No Detailed Affiliation Given 84/08/17 3pp 26294 034 24X Fiche 50-445, 84/08/17, 8408280342

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000, 84/08/20, 8408200275

8408270030 Advises of adoption of Westinghouse generic core damage assessment methodology, in response to NUREG-0737, Item II B 3, "Post-Accident Sampling Capability "
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/20 YOUNGBLOOD, B J Licensing Branch 1 1p 26245 058 24X Fiche 50-445, 84/08/20, 8408270030

8408270075 Application to amend CPPR-126, reflecting partial exemption from 10CFR50, App A requirements (GDC-4) Fee paid Affidavit encl
SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/20 YOUNGBLOOD, B J Licensing Branch 1 3pp 26247 188 24X Fiche 50-445, 84/08/20, 8408270075

8408270965 Notification of 840823 & 24 meetings w/util in Glen Rose, TX to discuss detailed technical data supporting motions for summary dispositions
BURWELL, S B Licensing Branch 1 84/08/20 YOUNGBLOOD, B J Licensing Branch 1 5pp 26277 248 24X Fiche 50-445, 84/08/20, 8408270565

8408270067 Informs that qualification maint program described in FSAR Section 2 4, App 3A will be fully implemented prior to Unit 1 fuel load
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/21 YOUNGBLOOD, B J Licensing Branch 1 1p 26247 149 24X Fiche 50-445, 84/08/21, 8408270067

8408270123 Forwards response to NRC 840613 questions re reactor vessel heatup & cooldown Tech Specs
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/22 YOUNGBLOOD, B J Licensing Branch 1 11pp 26247 344 24X Fiche 50-445, 84/08/22, 8408270123

8408270132 Informs that steam generator tube rupture reevaluation will include calculations to determine margin to overfill & equilibrium breakflow showing time to overfill is greater than time to equalization, per NRC 840409 request
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/22 YOUNGBLOOD, B J Licensing Branch 1 2pp 26245 059 24X Fiche 50-445, 84/08/22, 8408270132

8408280218 Forwards 830216 memo of telcon between util, NRR & BNL re action required to close out Specifit Item 12, MS34 concerning diesel generator control panel
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/22 YOUNGBLOOD, B J Licensing Branch 1 3pp 26279 188 24X Fiche 50-445, 84/08/22, 8408280218

8408280461 Notifies that CAW-84-9 re setpoint methodology for reactor protection sys is proprietary & will be withheld from public disclosure per 10CFR2 790
YOUNGBLOOD, B J Licensing Branch 1 84/08/22 WIESEMANN, R A, Westinghouse Electric Corp 3pp 26292 357 24X Fiche 50-445, 84/08/22, 8408280461

8408270124 Requests exemption from Section III D 2 b ii of App J to 10CFR50 requiring leakage testing of airlock Overall airlock leakage rate will be measured every 6 months regardless of airlock operating or maint history
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/23 YOUNGBLOOD, B J Licensing Branch 1 2pp 26246 359 24X Fiche 50-445, 84/08/23, 8408270124

8408280142 Advises that concerns re radiation of BIW silicone insulated cable resolved Calculations examined show lower postulated dose acceptable FSAR will be updated to reflect new valves in next amend
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/23 YOUNGBLOOD, B J Licensing Branch 1 1p 26259 077 24X Fiche 50-445, 84/08/23, 8408280142

8408280190 Forwards response to NRC 840807 request for addl info re safety parameter display sys List of parameters available in each mode of operation (normal, heat up/cool down &/or cold shutdown) encl
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/24 YOUNGBLOOD, B J Licensing Branch 1 24pp 26275 197 24X Fiche 50-445, 84/08/24, 8408280190

8408300239 Forwards response to 840827 request for info re status of human engineering deficiencies & clarifications to control room design review implementation audit
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/24 YOUNGBLOOD, B J Licensing Branch 1 6pp 26300 123 24X Fiche 50-445, 84/08/24, 8408300239

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408140066 Advises of delay in schedule for submitting SSER, per plan for completion of outstanding regulatory actions SSER addresses resolution of outstanding const quality issues from late Aug to end of Sept 1984
IPPOLITO, T A Division of Licensing 84/07/27 BLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel. 5pp 26061 276 24X Fiche 50-445, 84/07/27, 8408140066

8408170138 Forwards evaluation re resolution of SER Confirmatory Issue 5, TMI action plan items & status of review of steam generator tube rupture event
YOUNGBLOOD, B J Licensing Branch 1 84/08/09 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 10pp 26134 335 24X Fiche 50-445, 84/08/09, 8408170138

F Security, medical, emergency & fire protection plans

8408230257 Forwards Gibbs & Hill, Inc "Evaluation of Paint & Insulation Debris Effects on Containment Emergency Sump Performance " Related correspondence
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 222 84/07/05 BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 150pp
26206 166 24X Fiche 50-445, 84/07/05, 8408230257

8408230147 Forwards IE Safeguards Insp Rept 50-445/84-19 on 840529-0606 No violations or deviations noted
BANGART, R L Region 4, Office of Director 84/07/20 SPENCE, M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26213 359 24X Fiche 50-445, 84/07/20, 8408230147

--8408230152 IE Safeguards Insp Rept 50-445/84-19 on 840529-0606 No violations noted Major areas inspected security plan & implementing procedures, mgt effectiveness & security organization Details withheld (ref 10CFR2 790)
CALDWELL, R A , HALL, R E , HUNNICUTT, D Region 4, Office of Director 84/07/19 1p 26213 361 24X Fiche 50-445, 84/07/20, 8408230147

8408090451 Notification of 840803 meeting w/util in Bethesda, MD to discuss fire protection program
BURWELL, S B Licensing Branch 1 84/08/02 YOUNGBLOOD, B J
Licensing Branch 1 4pp 25983 209 24X Fiche 50-445, 84/08/02, 8408090451

8408130267 Forwards request for addl info re Suppl 1 to NUREG-0737 concerning safety parameter display sys Project manager should be prepared to address info request within 5 days of ltr receipt
YOUNGBLOOD, B J Licensing Branch 1 84/08/07 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
5pp 26040 345 24X Fiche 50-445, 84/08/07, 8408130267

8408210158 Forwards status rept re control room design review, per Suppl 1 to NUREG-0737 If plan not fully resolved by fuel load, licensing will be accomplished on PDA basis
YOUNGBLOOD, B J Licensing Branch 1 84/08/13 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
20pp 26195 287 24X Fiche 50-445, 84/08/13, 8408210158

8408210148 Forwards exercise rept for joint offsite radiological emergency preparedness 831214 exercise Cooperation w/state & local officials to correct deficiencies requested
BANGART, R L Region 4, Office of Director 84/08/16 SPENCE, M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 1p 26147 077 24X Fiche 50-445, 84/08/16, 8408210148

8408230390 Forwards "Comanche Peak Steam Electric Station Fire Protection Program Deviations," Rev 1 to "Design Basis Document, Comanche Fire Hazard Analysis" & FSAR Section 9 5 1 W/40 oversize drawings Aperture cards in PDR
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/16 YOUNGBLOOD, B J Licensing Branch 1
2pp 26204 069 24X Fiche 50-445, 84/08/16, 8408230390

--8408230397 "Comanche Peak Steam Electric Station Fire Protection Program Deviations "
* Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/15 248pp 26204 071 24X
Fiche 50-445, 84/08/16, 8408230390

--8408230400 Rev 1 to "Design Basis Document, Comanche Peak Steam Electric Station Fire Hazard Analysis "
* Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DBD-SY-1 R01 84/08/15 287pp 26204 319 24X
Fiche 50-445, 84/08/16, 8408230390

8408270368 Forwards marked-up proposed Tech Spec changes re remote shutdown instrumentation, fire detection instrumentation, fire suppression sys & liquid effluents
CLEMENTS, D R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/20 YOUNGBLOOD, B J Licensing Branch 1
521pp 26241 028 24X Fiche 50-445, 84/08/20, 8408270368

G Adjudicatory correspondence

8408230257 Forwards Gibbs & Hill, Inc "Evaluation of Paint & Insulation Debris Effects on Containment Emergency Sump Performance " Related correspondence
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 222 84/07/05 BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 150pp
26206 166 24X Fiche 50-445, 84/07/05, 8408230257

8408090200 Forwards 840801 ltr re breach of confidentiality involving CASE witness who gave deposition in proceedings under protective order Name of witness openly available to public in PDR for at least 6 days Related correspondence
ROISMAN, A Z Trial Lawyers for Public Justice ROISMAN, A Z
Citizens Association for Sound Energy DSB 852 84/08/01
BLOCH, P B Atomic Safety and Licensing Board Panel 1p 25971 190
24X Fiche 50-445, 84/08/01, 8408090200

--8408090206 Requests info re breach of confidentiality involving CASE witness who gave deposition in proceedings under protective order Name of witness openly available to public in PDR for at least 6 days Related correspondence
ROISMAN, A Z Trial Lawyers for Public Justice ROISMAN, A Z
Citizens Association for Sound Energy 84/08/01 CHILK Office of the Secretary of the Commission 2pp 25971 191 24X
Fiche 50-445, 84/08/01, 8408090200

8408090435 Notification of 840808 & 09 meetings w/util in Bethesda, MD to discuss detailed technical data in motions for summary disposition filed by applicant
BURWELL, S B Licensing Branch 1 84/08/02 YOUNGBLOOD, B J
Licensing Branch 1 4pp 25984 295 24X Fiche 50-445, 84/08/02, 8408090435

8408130093 Forwards sixth biweekly update on status of important schedule related issues for fuel loading Related correspondence
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 894 84/08/03 BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 12pp
26007 317 24X Fiche 50-445, 84/08/03, 8408130093

8408130305 Submits info in response to discovery requests re applicant motion for summary disposition Pertinent documentation re A500 steel pleading encl W/o encl Related correspondence
HORIN, W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN, W A
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 895 84/08/04 ELLIS, J Citizens Association for Sound Energy 2pp 26010 257 24X Fiche 50-445, 84/08/04, 8408130305

8408090408 Forwards answers to applicant motion for summary disposition re alleged errors made in determining damping factors, allegations re AWS & ASME Code provisions & friction force in pipe design Related correspondence
ELLIS, J Citizens Association for Sound Energy DSB 877 84/08/06
BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 1p 25982 231 24X Fiche 50-445, 84/08/06, 8408090408

--8408090420 Answer opposing applicant 840516 motion for summary disposition re alleged errors made in determining damping factors for OBE & SSE loading conditions Related correspondence
ELLIS, J Citizens Association for Sound Energy 84/08/06
Atomic Safety and Licensing Board Panel 2pp 25982 232 24X
Fiche 50-445, 84/08/06, 8408090408

--8408090426 Affidavit of M Walsh in support of CASE answer to applicant statement of matl facts as to which no genuine issue exists re consideration of damping factors for OBE & SSE loading conditions
WALSH, M Citizens Association for Sound Energy 84/08/04 13pp
25982 234 24X Fiche 50-445, 84/08/06, 8408090408

--8408090434 Forwards M Walsh affidavit on CASE 840806 answer to applicant motion for summary disposition re alleged errors made in determining damping factors for OBE & SSE loading conditions W/o encl Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 84/08/06
Docketing & Services Branch 3pp 25982 247 24X
Fiche 50-445, 84/08/06, 8408090408

--8408090463 Answer opposing applicant 840517 motion for summary disposition of certain CASE allegations on AWS & ASME Code provisions re design issues Related correspondence
ELLIS, J Citizens Association for Sound Energy 84/08/06
Atomic Safety and Licensing Board Panel 2pp 25982 250 24X
Fiche 50-445, 84/08/06, 8408090408

--8408090471 Affidavit of M Walsh in support of CASE answer to applicant statement of matl facts as to which no genuine issue exists on certain CASE allegations re AWS & ASME Code provisions related to design issues
WALSH, M Citizens Association for Sound Energy 84/08/04 35pp
25982 252 24X Fiche 50-445, 84/08/06, 8408090408

--8408090480 Forwards M Walsh affidavit on CASE 840806 answer to applicant motion for summary disposition of certain CASE allegations on AWS & ASME Code provisions re design issues W/o encl Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 84/08/06
Docketing & Services Branch 3pp 25982 287 24X
Fiche 50-445, 84/08/06, 8408090408

840488 Answer opposing applicant motion for summary disposition re consideration of friction forces in design of pipe supports small thermal movements Related correspondence
LIS,J Citizens Association for Sound Energy 84/08/06
mic Safety and Licensing Board Panel 2pp 25982 290 24X
che 50-445 84/08/06,8408090408

840503 Affidavit of J Doyle & M Walsh in support of CASE answer to plicant statement or matl facts as to which no genuine sue exists re consideration of friction forces in design pipe supports d/small thermal movements
YLE,J ; WALSH,M Citizens Association for Sound Energy
/08/04 39pp 25982 292 24X Fiche 50-445,84/08/06,8408090408

840512 Forwards J Doyle & M Walsh affidavit re CASE 840806 answer applicant motion for summary disposition re consideration friction forces in design of pipe supports w/small ermal movement W/o encl Certificate of Svc encl
LIS,J Citizens Association for Sound Energy 84/08/06
fice of the Secretary of the Commission 3pp 25982 331 24X
che 50-445,84/08/06,8408090408

840162 Motion for authorization to issue license to load fuel & uct certain precritical testing
(CLOS,N S Texas Utilities Electric Co (formerly Texas Utilities rating Co) REYNOLDS,N S Bishop, Liberman, Cook, Purcell & olds DSB 825 84/08/07 Atomic Safety and Licensing Board 1. 12pp 25960 208 24X Fiche 50-445,84/08/07,8408080162

840168 Affidavit of E Alarcon in support of applicant motion for thorization to issue license to load fuel & conduct rtain precritical testing Prof qualifications & rtificate of Svc encl
ARCON,E Texas Utilities Electric Co (formerly Texas Utilities nerating Co) 84/08/03 10pp 25960 220 24X
che 50-445,84/08/07,8408080162

840413 Forwards correction sheet to affidavit of JC Finneran, otti & RP Deubler re design of Richmond inserts & ication to support design Related correspondence
N,W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN,W A s Utilities Electric Co (formerly Texas Utilities Generating DSB 846 84/08/07 BLOCH,P B , MCCOLLOM,K A , JORDAN,W H ic Safety and Licensing Board Panel 2pp 25974 052 24X e 50-445,84/08/07,8408080413

840495 Forwards copy of list re CASE requests for documents arising of depositions taken in Glen Rose,TX Related espondence
MAN,A Z Trial Lawyers for Public Justice DSB 026 84/08/13
ER,L Bishop, Liberman, Cook, Purcell & Reynolds 3pp
O 246 24X Fiche 50-445,84/08/13,8408140495

840106 Forwards affidavit of M Walsh 840813 answer to applicant on for summary disposition re effects of gaps on ctural behavior under seismic loading conditions Related espondence
S,J Citizens Association for Sound Energy DSB 074 84/08/13
cketing & Services Branch 1p 26085 197 24X
e: 50-445,84/08/13,8408160106

840113 Answer to applicant motion for summary disposition re fects of gaps on structural behavior under seismic loading nditions Related correspondence
LIS,J Citizens Association for Sound Energy, 84/08/13
mic Safety and Licensing Board Panel 2pp 26085 198 24X
che 50-445,84/08/13,8408160106

840131 Affidavit of M Walsh in support of answer to applicant atement of matl facts re effects of gaps on structural havior under seismic loading conditions W/Certificate of c. Related correspondence
LSH,M Citizens Association for Sound Energy 84/08/13
mic Safety and Licensing Board Panel 114pp 26085 200 24X
che 50-445,84/08/13,8408160106

840114 Confirms recent discussions re info requested by CASE for in answering various applicant motions for summary osition Telcon exchanges were in response to ASLB 840726 r. Related correspondence
S,J Citizens Association for Sound Energy DSB 071 84/08/13
IN,W A Bishop, Liberman, Cook, Purcell & Reynolds 13pp
5: 184 24X Fiche 50-445,84/08/13,8408160114.

840141 Forwards answers to applicant 840518 motion for summary osition of CASE allegations re section property values & sh affidavit Related correspondence
S,J Citizens Association for Sound Energy DSB 072 84/08/13
cketing & Services Branch 1p 26091 243 24X
e: 50-445,84/08/13,8408160141

--8408160153 Answer to applicant 840518 motion for summary disposition o CASE allegations re section property values ASLB should decide in CASE favor Related correspondence
ELLIS,J Citizens Association for Sound Energy 84/08/13
Atomic Safety and Licensing Board Panel 2pp 26091 244 24X
Fiche 50-445,84/08/13,8408160141

--8408160158 Affidavit of M Walsh in support of CASE answer to applicant statement of matl facts as to which no genuine issue exists on CASE allegations re section property values Certificate of Svc encl Related correspondence
WALSH,M Citizens Association for Sound Energy 84/08/12 13pp
26091 246 24X Fiche 50-445,84/08/13,8408160141

8408160171 Forwards CASE 840813 motion for addl time to respond to applicant motions for summary disposition on design/design QA issues M Walsh affidavit encl Related correspondence
ELLIS,J Citizens Association for Sound Energy DSB 073 84/08/13
Docketing & Services Branch 1p 26092 015 24X
Fiche 50-445,84/08/13,8408160171

--8408160178 Motion for addl time to respond to applicant motions for summary disposition of design/design QA issues Related correspondence
ELLIS,J Citizens Association for Sound Energy 84/08/13.
Atomic Safety and Licensing Board Panel 10pp 26092:016 24X
Fiche 50-445,84/08/13,8408160171

--8408160187 Affidavit of M Walsh in support of CASE motion for addl time to respond to applicant motions for summary disposition on design/design QA issues Certificate of Svc encl Related correspondence
WALSH,M Citizens Association for Sound Energy 84/08/12. 8pp
26092 026 24X Fiche 50-445,84/08/13,8408160171

8408310102 Provides promised info re applicant motion for summary disposition on gaps Related correspondence
ELLIS,J Citizens Association for Sound Energy DSB 406 84/08/14
MIZUNO,G S Hearing Branch 1 2pp 26322.281 24X
Fiche 50-445,84/08/14,8408310102

--8408310105 Motion for admission of encl ANI documents into record of proceedings Certificate of Svc encl Related correspondence
ELLIS,J Citizens Association for Sound Energy. 84/08/14
Atomic Safety and Licensing Board Panel 276pp. 26322.283. 24X
Fiche 50-445,84/08/14,8408310102

8408200605 Forwards list of documents necessary for adequate answer to 840703 motion for summary disposition re allegations concerning QA program for design of piping & piping supports,per 840806 telcon Related correspondence.
ELLIS,J Citizens Association for Sound Energy DSB 144 84/08/15
HORIN,W A Bishop, Liberman, Cook, Purcell & Reynolds 10pp.
26137 161 24X Fiche 50-445,84/08/15,8408200605

8408210561 Forwards transcripts of 840806,08 & 09 meetings re motions for summary dispositions,per request W/o encl
BURWELL,S B Licensing Branch 1 84/08/15 ELLIS,J Citizens Association for Sound Energy 1p 26195 256 24X
Fiche 50-445,84/08/15,8408210561

8408220331 Responds to 840813 ltr re CASE document requests. R Tolson 800131 memo to T Vega & R Klimist 800206 ltr to R Tolson forwarded Transcript of meeting between util & JJ Lipinsky expected shortly W/o encls Related correspondence
BELTER,L W Bishop, Liberman, Cook, Purcell & Reynolds BELTER,L W
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 197 84/08/16 ROISMAN,A Z Trial Lawyers for Public Justice 2pp 26194 060 24X Fiche 50-445,84/08/16,8408220331

8408230187 Forwards seventh biweekly update of important schedule-related issues for fuel load Related correspondence
REYNOLDS,N S Bishop, Liberman, Cook, Purcell & Reynolds.
REYNOLDS,N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 215 84/08/16 BLOCH,P B , JORDAN,W H , MCCOLLOM,K A Atomic Safety and Licensing Board Panel. 12pp.
26209 232 24X Fiche 50-445,84/08/16,8408230187

8408270065 Forwards Insp Repts 50-445/84-17 re disassembly, insp & reassembly of TDI emergency diesel generator; 50-445/84-05 re allegations on fabrication of pipe supports & restraints & 50-445/84-10 re walkdown Related correspondence.
MIZUNO,G S Hearing Branch 1 DSB 304 84/08/16 BLOCH,P B , JORDAN,W H , MCCOLLOM,K A Atomic Safety and Licensing Board Panel.
1p 26247 069 24X Fiche 50-445,84/08/16,8408270065

8408270097 Forwards 840621 Insp Repts 50-445/84-11 & 50-446/84-05, consisting of title page & summary portion of Ofc of Investigation Rept 4-84-006 Related correspondence.
MIZUNO,G S Hearing Branch 1 DSB 302 84/08/16 BLOCH,P B,, GROSSMAN,H , JORDAN,W H Atomic Safety and Licensing Board Panel.
1p 26247 358 24X Fiche 50-445,84/08/16,8408270097

8408220336 Forwards 791218 memo re Item 3 of list of items due omitted from 840816 package W/o encl Related correspondence
BELTER, L W Bishop Liberman, Cook Purcell & Reynolds DSB 198
84/08/17 ROISMAN, A Z Trial Lawyers for Public Justice 1p
26194 063 24X Fiche 50-445, 84/08/17, 8408220336

8408230311 Informs of 840817 docketing & in camera filing of ML Speckter 840815 ltr to M Davidson re documents request from Witness F D/exhibit containing 15 documents
CLEMENTS, W L Docketing & Services Branch DSB 251 84/08/17
Docketing & Services Branch 1p 26209 335 24X
Fiche 50-445, 84/08/17, 8408230311

8408280232 Forwards Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 re status of 10CFR50 55(e) repts & 50-445/84-08 & 50-446/84-04 on 831114-840331 re polar crane shim gaps Related correspondence
MIZUNO, G S Hearing Branch 1 DSB 318 84/08/17 BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 62pp 26262 287 24X Fiche 50-445, 84/08/17, 8408280232

8408240244 Partial answer in opposition to applicant 840807 motion for authorization to issue license to load fuel & conduct certain precritical testing Insp repts & Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy DSB 267 84/08/18
Atomic Safety and Licensing Board Panel 54pp 26222 277 24X
Fiche 50-445, 84/08/18, 8408240244

8408230319 Submits matl re cinching of U-bolts, axial restraints, Richmond inserts & stability, per 840806 telcon between util, CASE & NRC staff
HORIN, W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN, W A
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 213 84/08/20 ELLIS, J Citizens Association for Sound Energy 2pp 26205 357 24X Fiche 50-445, 84/08/20, 8408230319

8408270179 Forwards testimony of D Hunnicutt re T-shirt incident Hunnicutt testimony provided by agreement of counsel, to suppl deposition of Cummins Related correspondence
TREBY, S A Hearing Branch 1 DSB 301 84/08/20 BLOCH, P B , JORDAN, W H , GROSSMAN, H Atomic Safety and Licensing Board Panel 23pp 26243 317 24X Fiche 50-445, 84/08/20, 8408270179

--8408270186 Motion to strike testimony of D Hunnicutt & JE Cummins as being beyond scope of harassment & intimidation issue & therefore not relevant to proceeding Certificate of Svc encl Related correspondence
BACHMANN, R G Hearing Branch 1 84/08/20 Atomic Safety and Licensing Board Panel 5pp 26243 340 24X Fiche 50-445, 84/08/20, 8408270179

8408280136 Forwards M Walsh 840819 statement & CASE 840820 answer to applicant motion for summary disposition of CASE allegations re U-bolts acting as two-way restraints Related correspondence
ELLIS, J Citizens Association for Sound Energy DSB 295 84/08/20
Docketing & Services Branch 1p 26275 146 24X
Fiche 50-445, 84/08/20, 8408280136

--8408280141 Answer to applicant 840523 motion for summary disposition of CASE allegations re U-bolts acting as two-way restraints Applicant statements should be considered as matl false statements
ELLIS, J Citizens Association for Sound Energy 84/08/20
Atomic Safety and Licensing Board Panel 2pp 26275 147 24X
Fiche 50-445, 84/08/20, 8408280136

--8408280146 Answer to applicant statement of matl facts as to which there is no genuine issue re CASE allegations regarding U-bolts acting as two-way restraints Statement in form of affidavit of M Walsh Certificate of Svc encl
WALSH, M Citizens Association for Sound Energy 84/08/19
Atomic Safety and Licensing Board Panel 35pp 26275 149 24X
Fiche 50-445, 84/08/20, 8408280136

8408230173 Requests Hartman be informed of error in interpretation re filing of documents in proceeding Documents should be filed per procedures established by ASLB Related correspondence
ROISMAN, A Z Trial Lawyers for Public Justice ROISMAN, A Z
Citizens Association for Sound Energy DSB 223 84/08/21
CLEMENTS, W L Docketing & Services Branch 2pp 26209 271 24X
Fiche 50-445, 84/08/21, 8408230173

8408270058 Documents receipt & docketing on 840820 of in camera deposition taken on 840815
CLEMENTS, W L Docketing & Services Branch DSB 272 84/08/21
Docketing & Services Branch 1p 26238 141 24X
Fiche 50-445, 84/08/21, 8408270058

8408230305 Informs of 840822 in camera filing of ML Speckter 840820 response to M Davidson 840820 ltr
CLEMENTS, W L Docketing & Services Branch DSB 252 84/08/22
Docketing & Services Branch 1p 26209 334 24X
Fiche 50-445, 84/08/22 8408230305

8408270094 Response supporting util 840807 motion for authorization to issue license to conduct fuel load & precritical testing
MIZUNO, G S Hearing Branch 1 DSB 306 84/08/22 Atomic Safety and Licensing Board Panel 9pp 26217 305 24X
Fiche 50-445, 84/08/22, 8408270094

--8408270103 Response supporting util 840802 motion for directed certification of ASLB 840723 order ruling on util motions for summary disposition of Phases I & II Certificate of Svc encl
PERLIS, R G Hearing Branch 3 84/08/17 Commissioners 10pp
26247 314 24X Fiche 50-445, 84/08/22, 8408270094

8408280083 Forwards matl requested in 840806 conference call re applicant motions for summary disposition Matl identified as Item 3 in 840820 ltr re drawing & calculations for support FW-1-18-703-C52R W/o encls
HORIN, W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN, W A
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 285 84/08/22 ELLIS, J Citizens Association for Sound Energy 2pp 26261 197 24X Fiche 50-445, 84/08/22, 8408280083

8408270154 Forwards response to Item 6 of things due re transcript of plant personnel meeting 0/JJ Lipinsky Travelers requested during S Neumeyer deposition expected shortly W/o encl Related correspondence
BELTER, L W Bishop, Liberman, Cook, Purcell & Reynolds BELTER, L W
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 282 84/08/23 ROISMAN, A Z Trial Lawyers for Public Justice 1p 26245 145 24X Fiche 50-445, 84/08/23, 8408270154

8408280221 Exhibit to G Purdy deposition re QC personnel interview
PURDY, G Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 299 84/08/23 12pp 26269 342 24X
Fiche 50-445, 84/08/23, 8408280221

8408280157 Motion to strike listed portions of applicant testimony as impermissible redirect of witnesses Certificate of Svc encl
Related correspondence
ROISMAN, A Z Trial Lawyers for Public Justice DSB 336 84/08/24
Atomic Safety and Licensing Board Panel 6pp 26275 075 24X
Fiche 50-445, 84/08/24, 8408280157

8408280255 Memorandum directing util to supply requested evidence to facilitate further consideration of 840807 motion for authorization to issue license to load fuel & conduct certain precritical testing Served on 840827
BLOCH, P B Atomic Safety and Licensing Board Panel DSB 327
84/08/24 Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26261 342 24X Fiche 50-445, 84/08/24, 8408280255

8408280265 Response to ASLB 840615 request for addl info re TDI diesel generators ASLB should conclude that TDI QA program adequate at all times Related correspondence
REYNOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds DSB 334 84/08/25 29pp 26262 008 24X
Fiche 50-445, 84/08/25, 8408280265

--8408280268 Affidavit of EJ Kreh re evaluation of TDI QA program TDI QA program acceptable prior to Jul 1980 discovery of auxiliary skid deficiency Prof qualifications & Certificate of Svc encl Related correspondence
KREH, E J O'Donnell & Associates, Inc 84/08/24 10pp
26262 037 24X Fiche, 50-445, 84/08/25, 8408280265

8408280156 Motion to strike testimony of IL Goldstein Testimony unreliable, incompetent & w/o foundation to resolve issues Certificate of Svc encl Related correspondence
DOWNEY, B L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DOWNEY, B L Bishop, Liberman, Cook, Purcell & Reynolds DSB 331 84/08/27 Atomic Safety and Licensing Board Panel 9pp 26275 066 24X Fiche 50-445, 84/08/27, 8408280156

8408280165 Motion to open record to receive into evidence, matls re reasons for & circumstances surrounding termination of R Hamilton employment Certificate of Svc encl
WATKINS, M Texas Utilities Electric Co (formerly Texas Utilities Generating Co) WATKINS, M Bishop, Liberman, Cook, Purcell & Reynolds DSB 332 84/08/27 Atomic Safety and Licensing Board Panel 10pp 26262 351 24X Fiche 50-445, 84/08/27, 8408280165

DOCKETED ITEMS

8408280251 Response opposing staff 840820 motion to strike testimony of D Hunnicutt & JE Cummins Testimony relevant to questions re T-shirt incident * intervenor contentions concerning incident Certificate of Svc encl Related correspondence DOWNEY, B L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DOWNEY, B L Bishop, Liberman, Cook, Purcell & Reynolds DSB 323 84/08/27 Atomic Safety and Licensing Board Panel 8pp 26261 348 24X Fiche 50-445, 84/08/27, 8408280251

8408280398 Lists documents redocketed in Docketing & Svc Branch on 840821 Served on 840827
CHILK, S J Office of the Secretary of the Commission DSB 349 84/08/27 Atomic Safety and Licensing Board Panel 1p 26280 031 24X Fiche 50-445, 84/08/27, 8408280398

8408290319 Motion to strike listed portions of applicant testimony Certificate of Svc encl Related correspondence
ROISMAN, A Z Citizens Association for Sound Energy ROISMAN, A Z Trial Lawyers for Public Justice DSB 377 84/08/27 Atomic Safety and Licensing Board Panel 6pp 26289 349 24X Fiche 50-445, 84/08/27, 8408290319

8408300139 Forwards original & Rev 2 to Reg Guide 1 75, per Q Berry commitment Rev 1 to Reg Guide 1 75 bound in Disposition Exhibit Disclosure F-9a W/o encl Related correspondence
MIZUNO, G S Hearing Branch 1 DSB 382 84/08/27 SPEKTER, M L Affiliation Not Assigned 1p 26304 362 24X Fiche 50-445, 84/08/27, 8408300139

8408310216 Forwards transcript of 831110-11 meetings at facility re protective coatings & Lipinsky memorandum W/o encl Related correspondence
HORIN, W A Bishop, Liberman Cook, Purcell & Reynolds HORIN, W A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 420 84/08/29 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 26318 116 24X Fiche 50-445, 84/08/29, 8408310216

K Utility Final Safety Analysis Report (FSAR) & amends

8408140393 Amend 51 to FSAR for Comanche Peak W/840810 ltr
SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 60pp 26048 019 24X Fiche 50-445, 84/08/08, 8408140393

8408290208 Forwards Amend 52 to FSAR Affidavit encl
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26287 254 24X Fiche 50-445, 84/08/27, 8408290208

--8408290211 Amend 52 to FSAR
* Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/27 681pp 26287 260 24X Fiche 50-445, 84/08/27, 8408290208

O Inspection reports, IE Bulletins & correspondence

8408010098 Discusses 830827-0902 insp of BIW Cable Sys, Inc (BIW) equipment qualification testing program Environ qualification of silicone insulated cable inadequate Requests verification of BIW qualification matl
YOUNGBLOOD, B J Licensing Branch 1 84/07/19 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 4pp 25897 060 24X Fiche 50-445, 84/07/19, 8408010098

8408230147 Forwards IE Safeguards Insp Rept 50-445/84-19 on 840529-0606 No violations or deviations noted
BANGART, R L Region 4, Office of Director 84/07/20 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26213 359 24X Fiche 50-445, 84/07/20, 8408230147

--8408230152 IE Safeguards Insp Rept 50-445/84-19 on 840529-0606 No violations noted Major areas inspected security plan & implementing procedures, mgt effectiveness & security organization Details withheld (ref 10CFR2 790)
CALDWELL, R A , HALL, R E , HUNNICUTT, D Region 4, Office of Director 84/07/19 1p 26213 361, 24X Fiche 50-445, 84/07/20, 8408230147

8408150649 Forwards IE Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 No violations or deviations noted
BANGART, R L Region 4, Office of Director 84/07/23 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26079 188 24X Fiche 50-445, 84/07/23, 8408150649

8408150655 IE Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 N violations noted Major areas inspected plant status, licensee action on previous findings, 10CFR50 55(e) rept followup, IE bulletin followup & plant tours
CUMMINS, J E , MCNEILL, W M , TOMLINSON, D P Region 4, Office of Director 84/06/21 18pp 26079 190 24X Fiche 50-445, 84/07/23, 8408150649

8408160201 Ack receipt of 840529 response to 840430 ltr re insp techniques for assessing extent of unauthorized weld repairs Response inadequate Requests detailed sampling plan & procedure within 20 days
BANGART, R L Region 4, Office of Director 84/07/23 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26106 300 24X Fiche 50-445, 84/07/23, 8408160201

--8408160204 Responds to 840430 ltr re plug welds in spread room Visual insp will be performed using methods similar to those described in addendum to 840424 testimony Program requiring repair instructions & QC insp followed
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/05/29 BANGART, R L Region 4, Office of Director 1p 26106 302 24X Fiche 50-445, 84/07/23, 8408160201

8408150091 Forwards IE Insp Repts 50-445/84-08 & 50-446/84-04 on 831114-840331 & notices of violation & deviation Major areas inspected Part 21 followup & training of protective coatings inspectors
BANGART, R L Region 4, Office of Director 84/07/26 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26073 306 24X Fiche 50-445, 84/07/26, 8408150091

--8408150094 Notice of violation from insp on 831114-840331
* Region 4, Office of Director 84/07/26 2pp 26073:309 24X Fiche 50-445, 84/07/26, 8408150091

--8408150097 Notice of deviation from insp on 831114-840331
* Region 4, Office of Director 84/07/26 2pp 26073.311 24X Fiche 50-445, 84/07/26, 8408150091

--8408150102 IE Insp Repts 50-445/84-08 & 50-446/84-04 on 831114-840331 Violations & deviations noted unshimmed gaps exceed 1/16 inch on polar crane bracket & seismic connections & licensee did not incorporate objectives of ANSI N45 2 11 into design
CUMMINS, J E , SMITH, W F , MARTIN, L E Region 4, Office of Director 84/07/26 10pp 26073 313 24X Fiche 50-445, 84/07/26, 8408150091

8408150414 Forwards IE Insp Rept 50-445/84-18 on 840501-31 & notice of violation Areas inspected include preoperational test witnessing, followup of TDI diesel generator insp & plant tours
BANGART, R L Region 4, Office of Director 84/07/26 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26077 252 24X Fiche 50-445, 84/07/26, 8408150414

--8408150417 Notice of violation from insp on 840501-31
* Region 4, Office of Director 84/07/26 2pp 26077 254 24X Fiche 50-445, 84/07/26, 8408150414

--8408150440 IE Insp Rept 50-445/84-18 on 840501-31 Violations noted failure to follow procedure during Train A emergency diesel generator auxiliary sys retest & hold tags improperly removed from Train A diesel engine
KELLEY, D L , SMITH, W F , HUNNICUTT, D M Region 4, Office of Director 84/07/06 10pp 26077 256 24X Fiche 50-445, 84/07/26, 8408150414

8408160026 Forwards IE Insp Rept 50-445/84-20 on 840503-0619 No violations or deviations identified
BANGART, R L Region 4, Office of Director 84/07/26 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26108 150 24X Fiche 50-445, 84/07/26, 8408160026

--8408160037 IE Insp Rept 50-445/84-20 on 840503-0619 No violations or deviations noted Major areas inspected work & documentation associated w/site portion of recertification program implemented on Train B TDI emergency diesel generator
SMITH, W F , HUNNICUTT, D M Region 4, Office of Director, 84/07/05 9pp 26108 152 24X Fiche 50-445, 84/07/26, 8408160026

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

T Hearing transcripts on non-antitrust matters

8407310383 Transcript of 840723 telcon in Glen Rose, TX Pp 38,567-38,654
* Atomic Safety and Licensing Board Panel 84/07/23 91pp 25830 173 24X Fiche 50-445,81/07/23,8407310383

8408080027 Transcript of L Barnes 840728 deposition in Glen Rose, TX, re harassment & intimidation at facility Pp 59,000-59,246 Supporting documentation encl
* Atomic Safety and Licensing Board Panel BARNES, L Brown & Root, Inc (subs of Halliburton Co) 84/07/28 269pp 25969 066 24X Fiche 50-445,84/07/28,8408080027

8408070273 Transcript of M Rhodes, W Sims, M Todd & S Burns 840730 deposition Pp 72,000-72,160
* Atomic Safety and Licensing Board Panel RHODES, M L Ebasco Services, Inc (subs of Enserch Corp) SIMS, W T Brown & Root, Inc (subs of Halliburton Co) 84/07/30 175pp 25949 024 24X Fiche 50-445,84/07/30,8408070273

8408080257 Transcript of C Biggs, G Fanning, R Whitman & J Uehlein 840730 depositions in Glen Rose, TX Pp 71,500-71,659 Supporting documentation encl
* Atomic Safety and Licensing Board Panel BIGGS, C , FANNING, G Brown & Root, Inc (subs of Halliburton Co) 84/07/30 170pp 25967 257 24X Fiche 50-445,84/07/30,8408080257

8408070105 Vol II of transcript of M Gregory 840731 deposition in Glen Rose, TX Pp 54,559-54,718 Supporting documentation encl
* Atomic Safety and Licensing Board Panel GREGORY, M Texas Utilities Electric Co (formerly Texas Utilities Generating Co) GREGORY, M Brown & Root, Inc (subs of Halliburton Co) 84/07/31 204pp 25950 045 24X Fiche 50-445,84/07/31,8408070105

8408080051 Transcript of J Pitts 840731 deposition in Glen Rose, TX Pp 73,500-73,553
* Atomic Safety and Licensing Board Panel PITTS, J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) PITTS, J Ebasco Services, Inc (subs of Enserch Corp) 84/07/31 55pp 25960 338 24X Fiche 50-445,84/07/31,8408080051

8408080100 Transcript of DL Anderson 840731 deposition in Glen Rose, TX re intimidation by QA personnel Pp 73,000-73,042 Supporting documentation encl
* Atomic Safety and Licensing Board Panel ANDERSON, D L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/31 48pp 25965 117 24X Fiche 50-445,84/07/31,8408080100

8408080245 Transcript of D Anderson, S Spencer & A Boren 840731 depositions in Glen Rose, TX Pp 72,500-72,681 Supporting documentation encl
* Atomic Safety and Licensing Board Panel SPENCER, S , BOREN, A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/31 188pp 25967 065 24X Fiche 50-445,84/07/31, 8408080245

8408080023 Transcript of ST Hoggard 840801 deposition in Glen Rose, TX Pp 74,000-74,016 Supporting documentation encl
* Atomic Safety and Licensing Board Panel HOGGARD, S T Brown & Root, Inc (subs of Halliburton Co) 84/08/01 24pp 25961 339 24X Fiche 50-445,84/08/01,8408080023

8408080032 Transcript of HF Gunn 840801 deposition in Glen Rose, TX Pp 73,000-75,008
* Atomic Safety and Licensing Board Panel GUNN, H F Texas Utilities Electric Co (formerly Texas Utilities Generating Co) GUNN, H F Brown & Root, Inc (subs of Halliburton Co) 84/08/01 11pp 25967 023 24X Fiche 50-445,84/08/01,8408080032

8408080089 Transcript of JN Scarbrough & D Ethridge depositions in Glen Rose, TX Pp 74,500-74,521 Supporting documentation encl
* Atomic Safety and Licensing Board Panel SCARBROUGH, J N , ETHRIDGE, D Brown & Root, Inc (subs of Halliburton Co) 84/08/01 26pp 25965 167 24X Fiche 50-445,84/08/01,8408080089

8408080272 Transcript of SA Neumeyer 840801 deposition in Glen Rose, TX Pp 59,500-59,683 Supporting documentation encl
* Atomic Safety and Licensing Board Panel NEUMEYER, S A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/01 207pp 25966 080 24X Fiche 50-445,84/08/01,8408080272

8408080146 Transcript of DN Chapman 840802 deposition in Glen Rose, TX Pp 76,500-76,631 Supporting documentation encl
* Atomic Safety and Licensing Board Panel CHAPMAN, D N Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/02 280pp 25959 278 24X Fiche 50-445,84/08/02,8408080146

8408080296 Transcript of 840802 telcon in Glen Rose, TX Pp 38,690-38,726
* Atomic Safety and Licensing Board Panel 84/08/02 39pp 25964 321 24X Fiche 50-445,84/08/02,8408080296

8408160501 Forwards transcript of 840727 meeting in Bethesda MD re containment sump performance
BURWELL, S B Licensing Branch 1 84/08/03 ELLIS, J Citizens Association for Sound Energy 1p 26124 159 24X
Fiche 50-445,84 08/03,8408160501

--8408160502 Transcript of 840727 meeting in Bethesda,MD re containment sump performance Pp 1-113 Supporting documentation encl
* Commissioners 84/07/27 113pp 26124 160 24X
Fiche 50-445,84/08/03,8408160501

8408080026 Transcript of W Oats 840803 deposition in Glen Rose, TX Pp 77,500-77,558 Supporting documentation encl
* Atomic Safety and Licensing Board Panel OATS, W L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/03 81pp 25966 302 24X Fiche 50-445,84/08/03,8408080026

8408080294 Transcript of JC Keller 840803 deposition in Glen Rose, TX Pp 78,000-78,026 Supporting documentation encl
* Atomic Safety and Licensing Board Panel KELLER, J C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) KELLER, J C Westinghouse Electric Corp 84/08/03 36pp 25969 270 24X Fiche 50-445,84/08/03,8408080294

8408220173 Board Notification 84-139 forwards transcript of 840607 meeting w/applicant re 840604 proposed FSAR amend on protective coatings
EISENHUT, D G Division of Licensing 84/08/17 BLOCH, P , JORDAN, W , MCCOLLOM, D Atomic Safety and Licensing Board Panel 3pp 26262 098 24X Fiche 50-445,84/08/17,8408220173

--8408220266 Transcript of 840607 meeting w/applicant in Bethesda,MD re protective coating inside containment Pp 1-100
* Commissioners 84/06/07 100pp 26262 101 24X
Fiche 50-445,84/08/17,8408220173

8408230432 Notice of filing in Docketing & Svc Branch of O Purdy in camera deposition in Glen Rose,TX
PURDY, G Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 207 84/08/18 2pp 26204 007 24X
Fiche 50-445,84/08/19,8408230432

8408220367 Forwards prefiled testimony of RM Duncan, RD McBee, R Simpson, DR Wright, JE Zwahr, DT Wilterding & JF Brown, depositions of JN Scarbough et al & affidavit of DK Egbert Certificate of Svc encl
HARTMAN, S L Bishop, Liberman, Cook, Purcell & Reynolds
HARTMAN, S L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 206 84/08/20 CLEMENTS, W L Docketing & Services Branch 1pp 26192 126 24X Fiche 50-445,84/08/20, 8408220367

--8408220371 Prefiled testimony of AD Justice on 840816 in Glen Rose,TX
Pp 1-20
JUSTICE, A D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) JUSTICE, A D Brown & Root, Inc (subs of Halliburton Co) 84/08/16 20pp 26192 130 24X
Fiche 50-445,84/08/20,8408220367

--8408220374 Prefiled testimony of RM Duncan on 840815 in Glen Rose,TX
Pp 1-17
DUNCAN, R M Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DUNCAN, R M Brown & Root, Inc (subs of Halliburton Co) 84/08/15 23pp 26192 150 24X
Fiche 50-445,84/08/20,8408220367

--8408220380 Prefiled testimony of RD McBee on 840816 in Glen Rose,TX
Pp 1-24
MCBEE, R D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) MCBEE, R D Brown & Root, Inc (subs of Halliburton Co) 84/08/16 25pp 26192 173 24X
Fiche 50-445,84/08/20,8408220367

--8408220381 Prefiled testimony of RW Simpson on 840815 in Glen Rose,TX
Pp 1-38
SIMPSON, R W Texas Utilities Electric Co (formerly Texas Utilities Generating Co) SIMPSON, R W Brown & Root, Inc (subs of Halliburton Co) 84/08/15 42pp 26192 208 24X
Fiche 50-445,84/08/20,8408220367

--8408220385 Prefiled testimony of DR Wright on 840816 in Glen Rose,TX
Pp 1-9
WRIGHT, D R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) WRIGHT, D R Brown & Root, Inc (subs of Halliburton Co) 84/08/16 9pp 26192 260 24X
Fiche 50-445,84/08/20,8408220367

--8408220388 Prefiled testimony of JE Zwahr & DT Wilterding on 840815 in Glen Rose,TX Pp 1-21
ZWAHR, J E , WILTERDING, D T Texas Utilities Electric Co (formerly Texas Utilities Generating Co) ZWAHR, J E Brown & Root, Inc (subs of Halliburton Co) 84/08/15 29pp 26192 269 24X
Fiche 50-445,84/08/20,8408220367

--8408220393 Prefiled testimony of JE Brown on 840815 in Glen Rose, TX Pp 1-21
BROWN, J E Texas Utilities Electric Co (formerly Texas Utilities Generating Co) BROWN, J E Brown & Root, Inc (subs of Halliburton Co) 84/08/15 29pp 26192 298 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220396 Deposition of ST Hoggard on 840801 in Glen Rose, TX Pp 74,000-74,016 Personal resume encl
HOGGARD, S T Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/01 23pp 26192 327 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220399 Affidavit of DK Egbert re discussion w/DK Stiner in Oct 1982 concerning employee benefits
EGBERT, D K Brown & Root, Inc (subs of Halliburton Co)
84/08/01 7pp 26192 350 24X Fiche 50-445, 84/08/20, 8408220367

--8408220403 Deposition of JN Scarbrough & D Ethridge on 840801 in Glen Rose, TX Pp 74,500-74,521
SCARBROUGH, J N , EIHRIDGE, D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) SCARBROUGH, J N Brown & Root, Inc (subs of Halliburton Co) 84/08/01 27pp
26192 357 24X Fiche 50-445, 84/08/20, 8408220367

--8408220405 Deposition of HF Gunn on 840801 in Glen Rose, TX Pp 75,000-75,008
GUNN, H F Texas Utilities Electric Co (formerly Texas Utilities Generating Co) GUNN, H F Brown & Root, Inc (subs of Halliburton Co) 84/08/01 10pp 26193 022 24X
Fiche 50-445, 84/08/20, 8408220367

8408240247 Forwards CASE 840820 prefiled testimony of IL Goldstein re harassment & intimidation
ROISMAN, A Z Trial Lawyers for Public Justice ROISMAN, A Z
Citizens Association for Sound Energy DSB 257 84/08/20
BLOCH, P B , GROSSMAN, H , JORDAN, W H Atomic Safety and Licensing Board Panel 1p 26223 119 24X Fiche 50-445, 84/08/20, 8408240247

--8408240248 Written testimony of IL Goldstein re harassment & intimidation
GOLDSTEIN, I L Citizens Association for Sound Energy
GOLDSTEIN, I L Maryland, Univ of, College Park, MD 84/08/20
45pp 26223 120 24X Fiche 50-445, 84/08/20, 8408240247

8408240302 Transcript of 840822 hearing in Bethesda, MD Pp 13,965-14,014
* Atomic Safety and Licensing Board Panel 84/08/22 51pp
26225 321 24X Fiche 50-445, 84/08/22, 8408240302

8408300103 Transcript of 840827 hearing in Bethesda, MD Pp 14,015-14,180
* Atomic Safety and Licensing Board Panel 84/08/27 168pp
26305 001 24X Fiche 50-445, 84/08/27, 8408300103

V Operator Examinations

8408140266 Lists ref matl required for administration of written exams scheduled for 840910 & operator exams scheduled for wks of 840909 & 16 Matl should be submitted by 840815
HUNTER, D R Region 4, Office of Director 84/08/08 CLEMENTS, B R
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 6pp 26055 333 24X Fiche 50-445, 84/08/08, 8408140266

X Onsite Storage of Low Level Waste

8408270271 Advises of executed Contract DE-CR01-84RW00012 w/DOE for disposal of spent nuclear fuel from facilities Related info encl
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/21 YOUNGBLOOD, B N Licensing Branch 1
3pp 26241 015 24X Fiche 50-445, 84/08/21, 8408270271

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 2

A Application/construction stage documents & correspondence

8309130110 Forwards FR notice & Director's Decision DD-83-11 denying CASE 830128 10CFR2 206 petition for show cause order re ITT Grinnell & NPS Industries, Inc design criteria for pipe supports
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/08/18 ELLIS, J Citizens Association for Sound Energy 2pp 25975 323 24X Fiche 50-445, 83/08/18, 8309130110

--8309130112 Notice of denial of CASE 10CFR2 206 petition requesting util be required to provide documents re ITT Grinnel & NPA Industries, Inc design criteria for pipe supports
DEYOUNG R C Director's Office, Office of Inspection and Enforcement 83/09/19 1p 25975 325 24X Fiche 50-445, 83/08/18, 8309130110

--8309130117 Director's Decision DD-83-11, denying CASE 830128 10CFR2 206 petition for show cause order re production of ITT Grinnell & NPS Industries, Inc design criteria for pipe supports
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/09/19 8pp 25975 326 24X
Fiche 50-445, 83/08/18, 8309130110

8311020513 Ack receipt of 830928 response to notice of violation & proposed imposition of civil penalty dtd 830829 Final determination re imposition of civil penalty deferred until resolution of DOL Case 82 ERA-9
DEYOUNG, R Director's Office, Office of Inspection and Enforcement
83/10/17 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 25975 334 24X
Fiche 50-445, 83/10/17, 8311020513

8303300734 Ack receipt of Citizens Assoc for Sound Energy petition for show cause order or, in alternative, why util should not provide requested documents re component design
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/03 ELLIS, J Citizens Association for Sound Energy 1p 25951 338 24X Fiche 50-445, 84/03/03, 8303300734

--8303300736 Notice of receipt of petition under 10CFR2 206 for order to show cause or, in alternative, why util should not provide requested documents re component design
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/03 2pp 25951 339 24X
Fiche 50-445, 84/03/03, 8303300734

8408010078 Informs that licensee responses to NUREG-0737, Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling," acceptable SSER input & milestones encl
YOUNGBLOOD, B J Licensing Branch 1 84/07/19 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
12pp 25897 225 24X Fiche 50-445, 84/07/19, 8408010078

8408010112 Informs that licensee updates to QA organization documented in FSAR Amends 42-49 acceptable Evaluation rept for inclusion in SSER, prior to Unit 1 licensing, encl
YOUNGBLOOD, B J Licensing Branch 1 84/07/19 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
9pp 25873 336 24X Fiche 50-445, 84/07/19, 8408010112

8408130449 Forwards "Control of Heavy Loads (Phase II-NUREG-0612) for Commanche Peak, Units 1 & 2," draft technical evaluation rept
YOUNGBLOOD, B J Licensing Branch 1 84/07/26 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
3pp 26059 271 24X Fiche 50-445, 84/07/26, 8408130449

--8408130455 "Control of Heavy Loads (Phase II-NUREG-0612), Commanche Peak, Units 1 & 2," draft technical evaluation rept
YEN, T C EG&G, Inc FIN A-6457 84/04/30 NRC -- No Detailed Affiliation Given 40pp 26059 274 24X Fiche 50-445, 84/07/26, 8408130449

8408060165 Responds to Generic Ltr 83-10C re resolution of NUREG-0737, Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Facilities bound by results of Westinghouse Owners Group manual pump trip justification rept
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/27 YOUNGBLOOD, B J Licensing Branch 1
1p 25932 197 24X Fiche 50-445, 84/07/27, 8408060165

8408090479 Notification of 840808 meeting w/BNL in Glen Rose, TX to discuss util responses to allegations re protective coating practices
VIETTI, A Licensing Branch 3 84/07/27 IPPOLITO, T A Division of Licensing 14pp 25983 160 24X Fiche 50-445, 84/07/27, 8408090479

8408030153 Responds to agenda for 840808 meeting at site re protective coatings practices Requests permission to respond to NRC questions in writing by 840813
GEORGE, J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/31 IPPOLITO, J A Division of Licensing
1p 25912 014 24X Fiche 50-445, 84/07/31, 8408030153

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda, MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH, B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 130 24X Fiche 50-000, 84/07/31, 8408090497

8408090449 Notification of cancellation of 840908 meeting w/BNL in Bethesda,MD to discuss util responses to allegations re protective coating practices
VIETTI,A Licensing Branch 3 84/08/01 IPPOLITO,T A Division of Licensing 3pp 25983 215 24X Fiche 50-445,84/08/01,8408090445

8408090505 Ack receipt of 840731 request for opportunity to respond to 840727 meeting notice on 840803 meeting w/util re protective coating practices in writing by 840813 Meeting schedule canceled
IPPOLITO,T A Division of Licensing 84/08/02 GEORGE,J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
1p 25983 127 24X Fiche 50-445,84/08/02,8408090505

8408070455 Board Notification 84-124 forwards info re allegations of improper const practices on main condensers
EISENHUT,D G Division of Licensing 84/08/03 BLOCH,P ,
JORDAN,W , MCCOLLOM,K Atomic Safety and Licensing Board Panel
2pp 25971 001 24X Fiche 50-445,84/08/03,8408070455

--8408090105 Responds to NRC 840619 ltr re alleged improper const practices involving main condensers QA program not invoked because main condenser not safety-related,but activities monitored closely Leakage testing & detection discussed
CLEMENTS,B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/09 BANGART,R L Region 4, Office of Dire to 2pp 25971 032 24X Fiche 50-445,84/08/03, 8408070455

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408080454 Board Notification 84-132 transmits NRC Special Review Team rept re 840403-13 site review of mgt control of const,insp & test programs
EISENHUT,D G Division of Licensing 84/08/06 PALLADINO Consolidated Edison Co of New York, Inc ROBERTS, ASSELSTINE Commissioners 2pp 26031 214 24X Fiche 50-445,84/08/06, 840F07v455

8408100050 Informs that documents re Mar 1984 T-shirt incident returned to T Vega on 840720 following reproduction
BANGART,R L Region 4, Office of Director 84/08/06 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 25990 038 24X Fiche 50-445,84/08/06,8408100050

8408160157 Forwards table providing description of Amend 51 to FSAR
MARSHALL,J S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/08 BURWELL,S B Office of Nuclear Reactor Regulation, Director 3pp 26085 169 24X Fiche 50-445,84/08/08, 8408160157

8408170138 Forwards evaluation re resolution of SER Confirmatory Issue 5,TMI action plan items & status of review of steam generator tube rupture event
YOUNGBLOOD,B J Licensing Branch 1 84/08/09 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
10pp 26134 335 24X Fiche 50-445,84/08/09,8408170138

8408160335 Responds to 840809 request for addl info re environ qualification concerning FSAR data for MS-78,MS-76,ESE-27 & ESE-40 & forwards "Radiation Analysis of Barton Model 288A Differential Pressure Indicating Switch ," test rept
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/10 YOUNGBLOOD,B J Licensing Branch 1
2pp 26085 341 24X Fiche 50-445,84/08/10,8408160335

--8408160340 "Radiation Analysis of Barton Model 288A Differential Pressure Indicating Switch for Texas Utils Generating Co "
RIEDL,T J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) E0/IES(84)-164 84/08/10 7pp 26085 343 24X
Fiche 50-445,84/08/10,8408160335

8408160412 Submits list of items for which cable splicing in raceways justified,per requirement of Rev 1 to Reg Guide 1 75
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/10 YOUNGBLOOD,B J Licensing Branch 1
2pp 26085 356 24X Fiche 50-445,84/08/10,8408160412

8408200156 Notification of 840814 & 15 meetings w/util in New York,NY to conduct audit review of structural analysis on upper lateral restraint beam prepared for motions for summary disposition
BURWELL,S B Licensing Branch 1 84/08/13 YOUNGBLOOD,B J Licensing Branch 1 3pp 26142 322 24X Fiche 50-445,84/08/13, 8408200156

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408270030 Advises of adoption of Westinghouse generic core damage assessment methodology,in response to NUREG-0737, Item II B 3, "Post-Accident Sampling Capability "
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/20 YOUNGBLOOD,B J Licensing Branch 1
1p 26245 098 24X Fiche 50-445,84/08/20,8408270030

8408270565 Notification of 840823 & 24 meetings w/util in Glen Rose,TX to discuss detailed technical data supporting motions for summary dispositions
BURWELL,S B Licensing Branch 1 84/08/20 YOUNGBLOOD,B J Licensing Branch 1 5pp 26277 248 24X Fiche 50-445,84/08/20, 8408270565

8408270067 Informs that qualification maint program described in FSAR Section 2 4,App 3A will be fully implemented prior to Unit 1 fuel load
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/21 YOUNGBLOOD,B J Licensing Branch 1
1p 26247 149 24X Fiche 50-445,84/08/21,8408270067

8408270123 Forwards response to NRC 840613 questions re reactor vessel heatup & cooldown Tech Specs
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/22 YOUNGBLOOD,B J Licensing Branch 1
11pp 26247 344 24X Fiche 50-445,84/08/22,8408270123

8408270132 Informs that steam generator tube rupture reevaluation will include calculations to determine margin to overfill & equilibrium breakflow showing time to overfill is greater than time to equalization,per NRC 840409 request
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/22 YOUNGBLOOD,B J Licensing Branch 1
2pp 26245 059 24X Fiche 50-445,84/08/22,8408270132

8408280218 Forwards 830216 memo of telcon between util,NRR & BNL re action required to close out Specific Item 12,MB34 concerning diesel generator control panel
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/22 YOUNGBLOOD,B J Licensing Branch 1
3pp 26279 188 24X Fiche 50-445,84/08/22,8408280218

8408280461 Notifies that CAW-84-9 re setpoint methodology for reactor protection sys is proprietary & will be withheld from public disclosure per 10CFR2 790
YOUNGBLOOD,B J Licensing Branch 1 84/08/22 WIESEMANN,R A Westinghouse Electric Corp 3pp 26292 357 24X
Fiche 50-445,84/08/22,8408280461

8408280142 Advises that concerns re radiation of DIW silicone insulated cable resolved Calculations examined show lower postulated dose acceptable FSAR will be updated to reflect new values in next amend
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/23 YOUNGBLOOD,B J Licensing Branch 1
1p 26259 077 24X Fiche 50-445,84/08/23,8408280142

8408280190 Forwards response to NRC 840807 request for addl info re safety parameter display sys List of parameters available in each mode of operation (normal,heat up/cool down &/or cold shutdown) encl
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/24 YOUNGBLOOD,B J Licensing Branch 1
24pp 26275 197 24X Fiche 50-445,84/08/24,8408280190

8408300239 Forwards response to 840827 request for info re status of human engineering deficiencies & clarifications to control room design review implementation audit
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/24 YOUNGBLOOD,B J Licensing Branch 1
6pp 26300 123 24X Fiche 50-445,84/08/24,8408300239

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408140066 Advises of delay in schedule for submitting SSER,per plan for completion of outstanding regulatory actions SSER addresses resolution of outstanding const quality issues from late Aug to end of Sept 1984
IPPOLITO,T A Division of Licensing 84/07/27 BLOCH,P B ,
JORDAN,W H , MCCOLLOM,K A Atomic Safety and Licensing Board Panel
5pp 26061 276 24X Fiche 50-445,84/07/27,8408140066

8408170138 Forwards evaluation re resolution of SEP Confirmatory Issue 5 TMI action plan items & status of review of steam generator tube rupture event
YOUNGBLOOD, B J Licensing Branch 1 84/08/09 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
10pp 26134 335 24X Fiche 50-445, 84/08/09, 8408170138

F Security medical, emergency & fire protection plans

8408230257 Forwards Gibbs & Hill, Inc "Evaluation of Paint & Insulation Debris Effects on Containment Emergency Sump Performance " Related correspondence
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds DSB 222 84/07/05 BLOCH, P B Atomic Safety and Licensing Board Panel
150pp 26206 166 24X Fiche 50-445, 84/07/05, 8408230257

8408090451 Notification of 840803 meeting w/util in Bethesda, MD to discuss fire protection program
BURNELL, S B Licensing Branch 1 84/08/02 YOUNGBLOOD, B J
Licensing Branch 1 4pp 25983 209 24X Fiche 50-445, 84/08/02, 8408090451

8408130267 Forwards request for addl info re Suppl 1 to NUREG-0737 concerning safety parameter display sys Project manager should be prepared to address info request within 5 days of ltr receipt
YOUNGBLOOD, B J Licensing Branch 1 84/08/07 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
5pp 26040 349 24X Fiche 50-445, 84/08/07, 8408130267

8408210158 Forwards status rept re control room design review, per Suppl 1 to NUREG-0737 If plan not fully resolved by fuel load, licensing will be accomplished on PDA basis
YOUNGBLOOD, B J Licensing Branch 1 84/08/13 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
20pp 26195 287 24X Fiche 50-445, 84/08/13, 8408210158

8408210148 Forwards exercise rept for joint offsite radiological emergency preparedness 831214 exercise Cooperation w/state & local officials to correct deficiencies requested
BANGART, R L Region 4, Office of Director 84/08/16 SPENCE, M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 1p 26147 077 24X Fiche 50-445, 84/08/16, 8408210148

8408270368 Forwards marked-up proposed Tech Spec changes re remote shutdown instrumentation, fire detection instrumentation, fire suppression sys & liquid effluents
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/20 YOUNGBLOOD, B J Licensing Branch 1
521pp 26211 025 24X Fiche 50-445, 84/08/20, 8408270368

O Adjudicatory correspondence

8408230257 Forwards Gibbs & Hill, Inc "Evaluation of Paint & Insulation Debris Effects on Containment Emergency Sump Performance " Related correspondence
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 222 84/07/05 BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 150pp
26206 166 24X Fiche 50-445, 84/07/05, 8408230257

8408090200 Forwards 840801 ltr re breach of confidentiality involving CASE witness who gave deposition in proceedings under protective order Name of witness openly available to public in PDR for at least 6 days Related correspondence
ROISMAN, A Z Trial Lawyers for Public Justice ROISMAN, A Z
Citizens Association for Sound Energy DSB 852 84/08/01
BLOCH, P B Atomic Safety and Licensing Board Panel 1p 25971 190
24X Fiche 50-445, 84/08/01, 8408090200

--8408090206 Requests info re breach of confidentiality involving CASE witness who gave deposition in proceedings under protective order Name of witness openly available to public in PDR for at least 6 days Related correspondence
ROISMAN, A Z Trial Lawyers for Public Justice ROISMAN, A Z
Citizens Association for Sound Energy 84/08/01 CHILK Office of the Secretary of the Commission 2pp 25971 191 24X
Fiche 50-445, 84/08/01, 8108090200

8408130093 Forwards sixth biweekly update on status of important schedule related issues for fuel loading Related correspondence
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 894 84/08/03 BLOCH, P B , MCCOLLOM, K A , JORDAN W H Atomic Safety and Licensing Board Panel 12pp
26007 317 24X Fiche 50-445, 84/08/03, 8408130093

8408130305 Submits info in response to discovery requests re applicant motion for summary disposition Pertinent documentation re A500 steel pleading encl W/o encl Related correspondence
HORIN, W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN, W A
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 895 84/08/04 ELLIS, J Citizens Association for Sound Energy 2pp 26010 257 24X Fiche 50-445, 84/08/04, 8408130305

8408090408 Forwards answers to applicant motion for summary disposition re alleged errors made in determining damping factors allegations re AWS & ASME Code provisions & friction force in pipe design Related correspondence
ELLIS, J Citizens Association for Sound Energy DSB 877 84/08/06
BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 1p 25982 231 24X Fiche 50-445, 84/08/06, 8408090408

--8408090420 Answer opposing applicant 840516 motion for summary disposition re alleged errors made in determining damping factors for OBE & SSE loading conditions Related correspondence
ELLIS, J Citizens Association for Sound Energy 84/08/06
Atomic Safety and Licensing Board Panel 2pp 25982 232 24X
Fiche 50-445, 84/08/06, 8408090408

--8408090426 Affidavit of M Walsh in support of CASE answer to applicant statement of matl facts as to which no genuine issue exists re consideration of damping factors for OBE & SSE loading conditions
WALSH, M Citizens Association for Sound Energy 84/08/04 13pp
25982 234 24X Fiche 50-445, 84/08/06, 8408090408

--8408090434 Forwards M Walsh affidavit on CASE 840806 answer to applicant motion for summary disposition re alleged errors made in determining damping factors for OBE & SSE loading conditions W/o encl Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 84/08/06
Docketing & Services Branch 3pp 25982 247 24X
Fiche 50-445, 84/08/06, 8408090408

--8408090463 Answer opposing applicant 840517 motion for summary disposition of certain CASE allegations on AWS & ASME Code provisions re design issues Related correspondence
ELLIS, J Citizens Association for Sound Energy 84/08/06
Atomic Safety and Licensing Board Panel 2pp 25982 250 24X
Fiche 50-445, 84/08/06, 8408090408

--8408090471 Affidavit of M Walsh in support of CASE answer to applicant statement of matl facts as to which no genuine issue exists on certain CASE allegations re AWS & ASME Code provisions related to design issues
WALSH, M Citizens Association for Sound Energy 84/08/04 35pp
25982 252 24X Fiche 50-445, 84/08/06, 8408090408

--8408090480 Forwards M Walsh affidavit on CASE 840806 answer to applicant motion for summary disposition of certain CASE allegations on AWS & ASME Code provisions re design issues W/o encl Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 84/08/06
Docketing & Services Branch 3pp 25982 287 24X
Fiche 50-445, 84/08/06, 8408090408

--8408090188 Answer opposing applicant motion for summary disposition re consideration of friction forces in design of pipe supports w/small thermal movements Related correspondence
ELLIS, J Citizens Association for Sound Energy 84/08/06
Atomic Safety and Licensing Board Panel 2pp 25982 290 24X
Fiche 50-445, 84/08/06, 8408090408

--8408090503 Affidavit of J Doyle & M Walsh in support of CASE answer to applicant statement of matl facts as to which no genuine issue exists re consideration of friction forces in design of pipe supports w/small thermal movements
DOYLE, J WALSH, M Citizens Association for Sound Energy
84/08/04 39pp 25982 292 24X Fiche 50-445, 84/08/06, 8408090408

--8408090512 Forwards J Doyle & M Walsh affidavit re CASE 840806 answer to applicant motion for summary disposition re consideration of friction forces in design of pipe supports w/small thermal movement W/o encl Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 84/08/06
Office of the Secretary of the Commission 3pp 25982 331 24X
Fiche 50-445, 84/08/06, 8408090408

8408080162 Motion for authorization to issue license to load fuel & conduct certain precritical testing
REYNOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds DSB 825 84/08/07 Atomic Safety and Licensing Board Panel 12pp 25960 208 24X Fiche 50-445, 84/08/07, 8408080162

--8408080168 Affidavit of E Alarcon in support of applicant motion for authorization to issue license to load fuel & conduct certain precritical testing Prof qualifications & Certificate of Svc encl
ALARCON, E Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/03 18pp 25960 220 24X
Fiche 50-445, 84/08/07, 8408080162

8408080413 Forwards correction sheet to affidavit of JC Finneran, RC Iotti & RP Deubler re design of Richmond inserts & application to support design Related correspondence
HORIN, W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN, W A
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 846 84/08/07 BLOCH, P B , MCCOLLOM, K A , JORDAN, W H
Atomic Safety and Licensing Board Panel 2pp 25974 052 24X
Fiche 50-445, 84/08/07, 8408080413

8408140495 Forwards copy of list re CASE requests for documents arising out of depositions taken in Glen Rose, TX Related correspondence
ROISMAN, A Z Trial Lawyers for Public Justice DSB 026 84/08/13
BELTER, L Bishop, Liberman, Cook, Purcell & Reynolds 3pp
26060 246 24X Fiche 50-445, 84/08/13, 8408140495

8408160106 Forwards affidavit of M Walsh 840813 answer to applicant motion for summary disposition re effects of gaps on structural behavior under seismic loading conditions Related correspondence
ELLIS, J Citizens Association for Sound Energy DSB 074 84/08/13
Docketing & Services Branch 1p 26085 197 24X
Fiche 50-445, 84/08/13, 8408160106

--8408160113 Answer to applicant motion for summary disposition re effects of gaps on structural behavior under seismic loading conditions Related correspondence
ELLIS, J Citizens Association for Sound Energy 84/08/13
Atomic Safety and Licensing Board Panel 2pp 26085 198 24X
Fiche 50-445, 84/08/13, 8408160106

--8408160131 Affidavit of M Walsh in support of answer to applicant statement of matl facts re effects of gaps on structural behavior under seismic loading conditions W/Certificate of Svc Related correspondence
WALSH, M Citizens Association for Sound Energy 84/08/13
Atomic Safety and Licensing Board Panel 114pp 26085 200 24X
Fiche 50-445, 84/08/13, 8408160106

8408160114 Confirms recent discussions re info requested by CASE for use in answering various applicant motions for summary disposition Telcon exchanges were in response to ASLB 840726 order Related correspondence
ELLIS, J Citizens Association for Sound Energy DSB 071 84/08/13
HORIN, W A Bishop, Liberman, Cook, Purcell & Reynolds 13pp
26085 184 24X Fiche 50-445, 84/08/13, 8408160114

8408160141 Forwards answers to applicant 840518 motion for summary disposition of CASE allegations re section property values & M Walsh affidavit Related correspondence
ELLIS, J Citizens Association for Sound Energy DSB 072 84/08/13
Docketing & Services Branch 1p 26091 243, 24X
Fiche 50-445, 84/08/13, 8408160141

--8408160153 Answer to applicant 840518 motion for summary disposition of CASE allegations re section property values ASLB should decide in CASE favor Related correspondence
ELLIS, J Citizens Association for Sound Energy 84/08/13
Atomic Safety and Licensing Board Panel 2pp 26091 244 24X
Fiche 50-445, 84/08/13, 8408160141

--8408160158 Affidavit of M Walsh in support of CASE answer to applicant statement of matl facts as to which no genuine issue exists on CASE allegations re section property values Certificate of Svc encl Related correspondence
WALSH, M Citizens Association for Sound Energy 84/08/12 13pp
26091 246 24X Fiche 50-445, 84/08/13, 8408160141

8408160171 Forwards CASE 840813 motion for addl time to respond to applicant motions for summary disposition on design/design QA issues M Walsh affidavit encl Related correspondence.
ELLIS, J Citizens Association for Sound Energy DSB 073 84/08/13
Docketing & Services Branch 1p 26092 015 24X
Fiche, 50-445, 84/08/13, 8408160171

--8408160178 Motion for addl time to respond to applicant motions for summary disposition of design/design QA issues Related correspondence
ELLIS, J Citizens Association for Sound Energy 84/08/13
Atomic Safety and Licensing Board Panel 10pp 26092 016 24X
Fiche 50-445, 84/08/13, 8408160171

--8408160187 Affidavit of M Walsh in support of CASE motion for addl time to respond to applicant motions for summary disposition on design/design QA issues Certificate of Svc encl Related correspondence
WALSH, M Citizens Association for Sound Energy 84/08/12 8pp
26092 026 24X Fiche 50-445, 81/08/13, 8408160171

8408310102 Provides promised info re applicant motion for summary disposition on gaps Related correspondence
ELLIS, J Citizens Association for Sound Energy DSB 406 84/08/14
MIZUNO, G S Hearing Branch 1 2pp 26322 281 24X
Fiche 50-445, 84/08/14, 8408310102

--8408310105 Motion for admission of encl ANI documents into record of proceedings Certificate of Svc encl Related correspondence
ELLIS, J Citizens Association for Sound Energy 84/08/14
Atomic Safety and Licensing Board Panel 276pp 26322 283 24X
Fiche 50-445, 84/08/14 8408310102

8408200605 Forwards list of documents necessary for adequate answer to 840703 motion for summary disposition re allegations concerning QA program for design of piping & piping supports, per 840806 telcon Related correspondence
ELLIS, J Citizens Association for Sound Energy DSB 144 84/08/15
HORIN, W A Bishop, Liberman, Cook, Purcell & Reynolds 10pp
26137 161 24X Fiche 50-445, 84/08/15, 8408200605

8408220331 Responds to 840813 ltr re CASE document requests R Tolson 800131 memo to T Vega & R Klimist 800206 ltr to R Tolson forwarded Transcript of meeting between util & JJ Lipinsky expected shortly W/o encls Related correspondence
BELTER, L W Bishop, Liberman, Cook, Purcell & Reynolds BELTER, L W
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 197 84/08/16 ROISMAN, A Z Trial Lawyers for Public Justice 2pp 26194 060 24X Fiche 50-445, 84/08/16, 8408220331

8408230187 Forwards seventh biweekly update of important schedule-related issues for fuel load Related correspondence
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 215 84/08/16 BLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 12pp
26209 232 24X Fiche 50-445, 84/08/16, 8408230187

8408270065 Forwards Insp Repts 50-445/84-17 re disassembly, insp & reassembly of TDI emergency diesel generator, 50-445/84-05 re allegations on fabrication of pipe supports & restraints & 50-445/84-10 re walkdown Related correspondence
MIZUNO, G S Hearing Branch 1 DSB 304 84/08/16 BLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel
1p 26247 069 24X Fiche 50-445, 84/08/16, 8408270065

8408270097 Forwards 840621 Insp Repts 50-445/84-11 & 50-446/84-05, consisting of title page & summary portion of OFC of Investigation Rept 4-84-006 Related correspondence
MIZUNO, G S Hearing Branch 1 DSB 302 84/08/16 BLOCH, P B , GROSSMAN, H , JORDAN, W H Atomic Safety and Licensing Board Panel
1p 26247 358 24X Fiche 50-445, 84/08/16, 8408270097

8408220336 Forwards 791218 memo re Item 3 of list of items due omitted from 840816 package W/o encl Related correspondence
BELTER, L W Bishop, Liberman, Cook, Purcell & Reynolds DSB 198
84/08/17 ROISMAN, A Z Trial Lawyers for Public Justice 1p
26194 063 24X Fiche 50-445, 84/08/17, 8408220336

8408230311 Informs of 840817 docketing & in camera filing of ML Speckter 840815 ltr to M Davidson re documents request from Witness F w/exhibit containing 15 documents
CLEMENTS, W L Docketing & Services Branch DSB 251 84/08/17
Docketing & Services Branch 1p 26209 335 24X
Fiche 50-445, 84/08/17, 8408230311

8408280232 Forwards Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 re status of 10CFR50 55(e) repts & 50-445/84-08 & 50-446/84-04 on 831114-840331 re polar crane shim gaps Related correspondence
MIZUNO, G S Hearing Branch 1 DSB 318 84/08/17 BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel
62pp 26262 287 24X Fiche 50-445, 84/08/17, 8408280232

8408240244 Partial answer in opposition to applicant 840807 motion for authorization to issue license to load fuel & conduct certain precritical testing Insp repts & Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy DSB 267 84/08/18
Atomic Safety and Licensing Board Panel 54pp 26222 277 24X
Fiche 50-445, 84/08/18, 8408240244

DOCKETED ITEMS

8408230319 Submits matl re clinching of U-bolts axial restraints, Richmond inserts & stability per 840806a telcon between util, CASE & NRC staff
HORIN,W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN,W A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 213 84/08/20 ELLIS,J Citizens Association for Sound Energy 2pp 26205 357 24X Fiche 50-445,84/08/20,8408230319

8408270179 Forwards testimony of D Hunnicutt re T-shirt incident Hunnicutt testimony provided by agreement of counsel, to suppl deposition of Cummins Related correspondence
TREBY,S A Hearing Branch 1 DSB 301 84/08/20 BLOCH,P B , JORDAN,W H , GROSSMAN,H Atomic Safety and Licensing Board Panel 23pp 26243 317 24X Fiche 50-445 84/08/20,8408270179

--8408270186 Motion to strike testimony of D Hunnicutt & JE Cummins as being beyond scope of harassment & intimidation issue & therefore not relevant to proceeding Certificate of Svc encl Related correspondence
BACHMANN,R G Hearing Branch 1 84/08/20 Atomic Safety and Licensing Board Panel 5pp 26243 340 24X Fiche 50-445, 84/08/20,8408270179

8408280136 Forwards M Walsh 840919 statement & CASE 840820 answer to applicant motion for summary disposition of CASE allegations re U-bolts acting as two-way restraints Related correspondence
ELLIS,J Citizens Association for Sound Energy DSB 295 84/08/20 Docketing & Services Branch 1p 26275 146 24X
Fiche 50-445,84/08/20,8408280136

--8408280141 Answer to applicant 840523 motion for summary disposition of CASE allegations re U-bolts acting as two-way restraints Applicant statements should be considered as matl false statements
ELLIS,J Citizens Association for Sound Energy 84/08/20 Atomic Safety and Licensing Board Panel 2pp 26275 147 24X
Fiche 50-445,84/08/20,8408280136

--8408280146 Answer to applicant statement of matl facts as to which there is no genuine issue re CASE allegations regarding U-bolts acting as two-way restraints Statement in form of affidavit of M Walsh Certificate of Svc encl
WALSH,M Citizens Association for Sound Energy 84/08/19 Atomic Safety and Licensing Board Panel 35pp 26275 149 24X
Fiche 50-445,84/08/20,8408280136

8408230173 Requests Hartman be informed of error in interpretation re filing of documents in proceeding Documents should be filed per procedures established by ASLB Related correspondence
ROISMAN,A Z Trial Lawyers for Public Justice ROISMAN,A Z Citizens Association for Sound Energy DSB 223 84/08/21
CLEMENTS,W L Docketing & Services Branch 2pp 26209 271 24X
Fiche 50-445,84/08/21,8408230173

8408270058 Documents receipt & docketing on 840820 of in camera deposition taken on 840815
CLEMENTS,W L Docketing & Services Branch DSB 272 84/08/21
Docketing & Services Branch 1p 26238 141 24X
Fiche 50-445,84/08/21,8408270058

8408230305 Informs of 840822 in camera filing of ML Speckter 840820 response to M Davidson 840820 ltr
CLEMENTS,W L Docketing & Services Branch DSB 252 84/08/22
Docketing & Services Branch 1p 26209 334 24X
Fiche 50-445,84/08/22 8408230305

8408270094 Response supporting util 840807 motion for authorization to issue license to conduct fuel load & precritical testing
MIZUNO,G S Hearing Branch 1 DSB 306 84/08/22 Atomic Safety and Licensing Board Panel 9pp 26247 305 24X
Fiche 50-445,84/08/22,8408270094

--8408270103 Response supporting util 840802 motion for directed certification of ASLB 840723 order ruling on util motions for summary disposition of Phases I & II Certificate of Svc encl
PERLIS,R G Hearing Branch 3 84/08/17 Commissioners 10pp 26247 314 24X Fiche 50-445,84/08/22,8408270094

8408280093 Forwards matl requested in 840806 conference call re applicant motions for summary disposition Matl identified as Item 3 in 840820 ltr re drawing & calculations for Support FW-1-18-703-C52R W/o encls
HORIN,W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN,W A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 285 84/08/22 ELLIS,J Citizens Association for Sound Energy 2pp 26261 197 24X Fiche 50-445,84/08/22,8408280083

8408270154 Forwards response to Item 6 of things due re transcript of plant personnel meeting C/JJ Lipinsky Travelers requested during S Neumeyer deposition expected shortly W/o encl Related correspondence
BELTER L W Bishop, Liberman, Cook, Purcell & Reynolds BELTER,L W Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 282 84/08/23 ROISMAN,A Z Trial Lawyers for Public Justice 1p 26245 145 24X Fiche 50-445,84/08/23,8408270154

8408280221 Exhibit to G Purdy deposition re QC personnel interview
PURDY,G Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 299 84/08/23 12pp 26269 342 24X
Fiche 50-445,84/08/23,8408280221

8408280157 Motion to strike listed portions of applicant testimony as impermissible redirect of witnesses Certificate of Svc encl Related correspondence
ROISMAN,A Z Trial Lawyers for Public Justice DSB 336 84/08/24
Atomic Safety and Licensing Board Panel 6pp 26275 075 24X
Fiche 50-445,84/08/24,8408280157

8408280255 Memorandum directing util to supply requested evidence to facilitate further consideration of 840807 motion for authorization to issue license to load fuel & conduct certain precritical testing Served on 840827
BLOCH,P B Atomic Safety and Licensing Board Panel DSB 327 84/08/24 Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26261 342 24X Fiche 50-445,84/08/24, 8408280255

8408280265 Response to ASLB 840615 request for addl info re TDI diesel generators ASLB should conclude that TDI QA program adequate at all times Related correspondence
REYNOLDS,N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) REYNOLDS,N S Bishop, Liberman, Cook, Purcell & Reynolds DSB 334 84/08/25 29pp 26262 008 24X
Fiche 50-445,84/08/25,8408280265

--8408280268 Affidavit of EJ Kreh re evaluation of TDI QA program TDI QA program acceptable prior to Jul 1980 discovery of auxiliary skid deficiency Prof qualifications & Certificate of Svc encl Related correspondence
KREH,E J O'Donnell & Associates, Inc 84/08/24 10pp
26262 037 24X Fiche 50-445,84/08/25,8408280265

8408280156 Motion to strike testimony of IL Goldstein Testimony unreliable, incompetent & w/o foundation to resolve issues Certificate of Svc encl Related correspondence
DOWNEY,B L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DOWNEY,B L Bishop, Liberman, Cook, Purcell & Reynolds DSB 331 84/08/27 Atomic Safety and Licensing Board Panel 9pp 26275 066 24X Fiche 50-445,84/08/27,8408280156

8408280165 Motion to open record to receive into evidence, matls re reasons for & circumstances surrounding termination of R Hamilton employment Certificate of Svc encl
WATKINS,M Texas Utilities Electric Co (formerly Texas Utilities Generating Co) WATKINS,M Bishop, Liberman, Cook, Purcell & Reynolds DSB 332 84/08/27 Atomic Safety and Licensing Board Panel 10pp 26262 351 24X Fiche 50-445,84/08/27,8408280165

8408280251 Response opposing staff 840820 motion to strike testimony D Hunnicutt & JE Cummins Testimony relevant to questions re T-shirt incident & intervenor contentions concerning incident Certificate of Svc encl Related correspondence
DOWNEY,B L Texas Utilities Electric Co (formerly Texas Utilit' Generating Co) DOWNEY,B L Bishop, Liberman, Cook, Purcell & Reynolds DSB 333 84/08/27 Atomic Safety and Licensing Bc Panel 8pp 26261 348 24X Fiche 50-445,84/08/27,8408280251

8408310216 Forwards transcript of 831110-11 meetings at facility re protective coatings & Lipinsky memorandum W/o encl Related correspondence
HORIN, W A Bishop Liberman Cook, Purcell & Reynolds HORIN, W A
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 420 84/08/29 BLOCH P B Atomic Safety and Licensing Board Panel 1p 26318 116 24X Fiche 50-445 84/08/29, 8408310216

K Utility Final Safety Analysis Report (FSAR) & amends

8408140393 Amend 51 to FSAR for Comanche Peak W/840810 ltr
SPENCE M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 60pp 26048 019 24X Fiche 50-445, 84/08/08, 8408140393

8408290208 Forwards Amend 52 to FSAR Affidavit encl
CLEMENTS, S R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26287 254 24X Fiche 50-445, 84/08/27, 8408290208

--8408290211 Amend 52 to FSAR
* Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/27 681pp 26287 260 24X
Fiche 50-445, 84/08/27, 8408290208

Q Inspection reports, IE Bulletins & correspondence

8408010098 Discusses 830829-0903 insp of BIW Cable Sys, Inc (BIW) equipment qualification testing program Environ qualification of silicone insulated cable inadequate Requests verification of BIW qualification matl
YOUNGBLOOD, B J Licensing Branch 1 84/07/19 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 4pp 25897 060 24X Fiche 50-445, 84/07/19, 8408010098

8408150649 Forwards IE Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 No violations or deviations noted
BANGART, R L Region 4, Office of Director 84/07/23 SPENCE, M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26079 188 24X Fiche 50-445, 84/07/23, 8408150649

--8408150655 IE Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 No violations noted Major areas inspected plant status, licensee action on previous findings, 10CFR50 55(e) rept followup, IE bulletin followup & plant tours
CUMMINS, J E , MCNEILL, W M , TOMLINSON, D P Region 4, Office of Director 84/06/21 18pp 26079 190 24X Fiche 50-445, 84/07/23, 8408150649

8408160201 Ack receipt of 840529 response to 840430 ltr re insp techniques for assessing extent of unauthorized weld repairs Response inadequate Requests detailed sampling plan & procedure within 20 days
BANGART, R L Region 4, Office of Director 84/07/23 SPENCE, M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26106 300 24X Fiche 50-445, 84/07/23, 8408160201

8408150091 Forwards IE Insp Repts 50-445/84-08 & 50-446/84-04 on 831114-840331 & notices of violation & deviation Major areas inspected Part 21 followup & training of protective coatings inspectors
BANGART, R L Region 4, Office of Director 84/07/26 SPENCE, M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26073 306 24X Fiche 50-445, 84/07/26, 8408150091

--8408150102 IE Insp Repts 50-445/84-08 & 50-446/84-04 on 831114-840331
Violations & deviations noted unshimmed gaps exceed 1/16 inch on polar crane bracket & seismic connections & licensee did not incorporate objectives of ANSI N45 2 11 into design
CUMMINS, J E , SMITH, W F , MARTIN, L E Region 4, Office of Director 84/07/26 10pp 26073 313 24X Fiche 50-445, 84/07/26, 8408150091

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408100042 Advises that IE Insp Repts 50-445/83-42 & 50-446/83-20 canceled No insp rept will be issued for listed numbers
BANGART, R L Region 4, Office of Director 84/08/01 SPENCE, M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 25990 068 24X Fiche 50-445, 84/08/01, 8408100042

8408100097 Forwards QA Program Insp Repts 99900387/84-01 & 99900404/84-02 Requests evaluation of significance of reported findings re quality & acceptability of product or svc provided by vendor W/o encl
HUNTER, D R Region 4, Office of Director 84/08/03 SPENCE, M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 25991 014 24X Fiche 50-445, 84/08/03, 8408100097

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26048 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26047 158 24X Fiche 50-000, 84/08/06, 8408010337

8408090454 Board Notification 84-132 transmits NRC Special Review Team rept re 840403-13 site review of mgt control of const, insp & test programs
EISENHUT, D G Division of Licensing 84/08/06 PALLADINO
Consolidated Edison Co of New York, Inc 72pp 26031 214 24X
Fiche 50-445, 84/08/06, 8408070455

8408160313 Board Notification 84-136 Forwards util 840622 responses to protective coating, BNL 840613 ltr forwarding draft "Status Rept on Protective Coatings Allegations" & 840624 ltr forwarding IE Insp Repts 50-445/84-03 & 50-446/84-01
EISENHUT, D G Division of Licensing 84/08/07 BLOCH, P ,
JORDAN, W , MCCOLLOM, K Atomic Safety and Licensing Board Panel 2pp 26190 001 24X Fiche 50-445, 84/08/07, 8408160313

--8408220412 Forwards responses to 840518 & 23 ltrs re 60 allegations concerning protective coating practices at facility Responses based on technical knowledge & review of existing documentation Supporting documentation encl
FIKAR, L F Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/06/22 BANGART, R L Region 4, Office of Director 320pp 26190 003 24X Fiche 50-445, 84/08/07, 8408160313

--8408220415 Forwards draft "Status Rept on Protective Coatings Allegations "
TAYLOR, J H Brookhaven National Laboratory 84/06/13
BANGART, R L Region 4, Office of Director 50pp 26190 323 24X
Fiche 50-445, 84/08/07, 8408160313,

--8408220419 Forwards IE Insp Repts 50-445/84-03 & 50-446/84-01 on 840130-0203
LETTIERI, V Brookhaven National Laboratory 84/02/24
HUNNICUTT, D M Region 4, Office of Director 1p 26191 010 24X
Fiche 50-445, 84/08/07, 8408160313

--8408220424 IE Insp Repts 50-445/84-03 & 50-446/84-01 on 840130-0203
No violations or deviation identified Major areas inspected protective coatings programs
HIGGINS, J C , LETTIERI, V Region 4, Office of Director 84/02/23 12pp 26191 011 24X Fiche 50-445, 84/08/07, 8408160313

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408160330 Forwards summaries of two addl BIW cable environ qualification repts, per 840719 request to address concerns resulting from NRC insp Cable adequately qualified
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/10 YOUNGBLOOD, B J Licensing Branch 1, 16pp 26085 322 24X Fiche 50-445, 84/08/10, 8408160330

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Undernated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 11Bpp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408270065 Forwards Insp Repts 50-445/84-17 re disassembly, insp & reassembly of TDI emergency diesel generator, 50-445/84-05 re allegations on fabrication of pipe supports & restraints & 50-445/84-10 re walkdown Related correspondence
MIZUNO, G S Hearing Branch 1 DSB 304 84/08/16 BLOCH, P B
Atomic Safety and Licensing Board Panel 1p 26247 069 24X
Fiche 50-445, 84/08/16, 8408270065

8408270097 Forwards 840621 Insp Repts 50-445/84-11 & 50-446/84-05, consisting of title page & summary portion of Ofc of Investigation Rept 4-84-006 Related correspondence
MIZUNO, G S Hearing Branch 1 DSB 302 84/08/16 BLOCH, P B
Atomic Safety and Licensing Board Panel 1p 26247 358 24X
Fiche 50-445, 84/08/16, 8408270097

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408280232 Forwards Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 re status of 10CFR50 55(e) repts & 50-445/84-08 & 50-446/84-04 on 831114-840331 re polar crane shim gaps Related correspondence
MIZUNO, G S Hearing Branch 1 DSB 318 84/08/17 BLOCH, P B
Atomic Safety and Licensing Board Panel 62pp 26262 287 24X
Fiche 50-445, 84/08/17, 8408280232

8408240244 Partial answer in opposition to applicant 840807 motion for authorization to issue license to load fuel & conduct certain precritical testing Insp repts & Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy DSB 267 84/08/18
Atomic Safety and Licensing Board Panel 54pp 26222 277 24X
Fiche 50-445, 84/08/18, 8408240244

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

R Periodic operating reports & related correspondence

8408060184 Submits sixth biweekly update on status, through 840721, of important schedule-related issues for fuel load in late Sept 1984 Control room HVAC testing incomplete Schedule slippage of 3 wks cannot be recovered
GEORGE, J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/30 EISENHUT, D G Division of Licensing
COLLINS, J T Region 4, Office of Director 11pp 25923 324 24X
Fiche 50-445, 84/07/30, 8408060184

8408170065 Provides seventh biweekly status rept re schedular issues for fuel load Info current through 840804 Project approx 3 wks behind schedule
GEORGE, J B Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/13 EISENHUT, D G Division of Licensing
COLLINS, J T Region 4, Office of Director 11pp 26119 112 24X
Fiche 50-445, 84/08/13, 8408170065

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000, 84/05/24, 8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000, 84/05/24, 8405290062

8405290177 Forwards Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000, 84/05/24, 8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts, Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER, J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER, M Division of Licensing 158pp
25926 173 24X Fiche 50-000, 84/06/28 8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/TDI Diesel Generator Owners Group 840622 meeting
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER, C Director's Office Office of Inspection and Enforcement 43pp 25934 153 24X Fiche 50-000, 84/07/10, 8408060050

8408030115 Responds to 840529 ltr re problems identified at Bahnson Co, Winston-Salem facility Re HVAC equipment received from subj facility Bahnson Co solicited to assess or to take any needed actions to improve QA program
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/23 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 25916 104 24X
Fiche 50-445, 84/07/23, 8408030115

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000 84/07/27, 8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000, 84/07/27, 8408060102

8408090044 Interim Significant Deficiency Rept SDAR-129 re error in tolerances used in calibr of adhesion tester Evaluation continuing Completion anticipated by 840901
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/07/31 JOHNSON, E H Region 4, Office of Director 1p 25992 132 24X Fiche 50-445, 84/07/31, 8408090044

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000, 84/08/01, 8408060324

8408160510 Final Deficiency Rept SDAR-129 re error in tolerances used in calibr of adhesion tester Initially reported on 840116 Investigation complete Matter not reportable under 10CFR50 55(e)
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/06 JOHNSON, E H Region 4, Office of Director 1p 26107 360 24X Fiche 50-445, 84/08/06, 8408160510

8408160185 Interim Deficiency Rept SDAR-140 re qualification of main steam relief valves for actual loading conditions Initially reported on 840710 Evaluation in progress & should be completed by 840831
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/08 JOHNSON, E H Region 4, Office of Director 1p 26106 328 24X Fiche 50-445, 84/08/08, 8408160185

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000, 84/08/10, 8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000, 84/08/10, 8408160394

8408200295 Interim Significant Deficiency Rept SDAR-132 re installation of curtain fire dampers w/o proper provisions for thermal expansion Initially reported on 840330 Review revealed 50 dampers required rework or mod Next rept by 840817
FIKAR, L F Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/13 JOHNSON, E H Region 4, Office of Director 5pp 26140 101 24X Fiche 50-445, 84/08/13, 8408200295

8408310216 Forwards transcript of 831110-11 meetings at facility re protective coatings ' Lipinsky memorandum W/o encl Related correspondence
HORIN,W A Bishop Liberman, Coor, Purcell & Reynolds HORIN,W A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 420 84/08/29 BLOCH,P B Atomic Safety and Licensing Board Panel 1p 26318 116 24X Fiche 50-445,84/08/29,8408310216

K Utility Final Safety Analysis Report (FSAR) & amends

8408140393 Amend 51 to FSAR for Comanche Peak W/840810 ltr
SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/08 DENTON,H R Office of Nuclear Reactor Regulation, Director 60pp 26048 019 24X Fiche 50-445,84/08/08, 8408140393

8408290208 Forwards Amend 52 to FSAR Affidavit encl
CLEMENTS,B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26287 254 24X Fiche 50-445,84/08/27, 8408290208

--8408290211 Amend 52 to FSAR
* Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/27 681pp 26287 260 24X
Fiche 50-445,84/08/27,8408290208

Q Inspection reports, IE Bulletins & correspondence

8408010098 Discusses 830829-0902 insp of BIW Cable Sys,Inc (BIW) equipment qualification testing program Environ qualification of silicone insulated cable inadequate Requests verification of BIW qualification matl
YOUNGBLOOD,B J Licensing Branch 1 84/07/19 SPENCE,M D Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 4pp 25897 060 24X Fiche 50-445,84/07/19,8408010098

8408150649 Forwards IE Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 No violations or deviations noted
BANGART,R L Region 4, Office of Director 84/07/23 SPENCE,M D Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 2pp 26079 188 24X Fiche 50-445,84/07/23,8408150649

--8408150655 IE Insp Repts 50-445/84-12 & 50-446/84-06 on 840320-0518 No violations noted Major areas inspected plant status,licensee action on previous findings,10CFR50 55(e) rept followup, IE bulletin followup & plant tours
CUMMINS,J E , MCNEILL,W M , TOMLINSON,D P Region 4, Office of Director 84/06/21 18pp 26079 190 24X Fiche 50-445,84/07/23, 8408150649

408160201 Ack receipt of 840529 response to 840430 ltr re insp techniques for assessing extent of unauthorized weld repairs Response inadequate Requests detailed sampling plan & procedure within 20 days
BANGART,R L Region 4, Office of Director 84/07/23 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26106 300 24X Fiche 50-445,84/07/23,8408160201

8408150091 Forwards IE Insp Repts 50-445/84-08 & 50-446/84-04 on 831114-840331 & notices of violation & deviation Major areas inspected Part 21 followup ' training of protective coatings inspectors
BANGART,R L Region 4, Office of Director 84/07/26 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26073 306 24X Fiche 50-445,84/07/26,8408150091

--8408150102 IE Insp Repts 50-445/84-08 & 50-446/84-04 on 831114-840331 Violations & deviations noted unshimmed gaps exceed 1/16 inch on polar crane bracket & seismic connections & licensee did not incorporate objectives of ANSI N45 2 11 into design
CUMMINS,J E , SMITH,W F , MARTIN,L E Region 4, Office of Director 84/07/26 10pp 26073 313 24X Fiche 50-445,84/07/26, 8408150091

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408100042 Advises that IE Insp Repts 50-445/83-42 & 50-446/83-20 canceled No insp rept will be issued for listed numbers
BANGART,R L Region 4, Office of Director 84/08/01 SPENCE,M D Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 2pp 25990 068 24X Fiche 50-445,84/08/01,8408100042

8408100097 Forwards QA Program Insp Repts 99900387/84-01 & 99900404/84-02 Requests evaluation of significance of reported findings re quality & acceptability of product or svc provided by vendor W/o encl
HUNTER,D R Region 4, Office of Director 84/08/03 SPENCE,M D Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 2pp 25991 014 24X Fiche 50-445,84/08/03,8408100097

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408080454 Board Notification 84-132 transmits NRC Special Review Team rept re 840403-13 site review of mgt control of const,insp & test programs
EISENHUT,D G Division of Licensing 84/08/06 PALLADINO Consolidated Edison Co of New York, Inc 72pp 26031 214 24X Fiche 50-445,84/08/06,8408070455

8408160313 Board Notification 84-136 forwards util 840622 responses to protective coating,BNL B10613 ltr forwarding draft "Status Rept on Protective Coatings Allegations" & 840624 ltr forwarding IE Insp Repts 50-445/84-03 & 50-446/84-01
EISENHUT,D G Division of Licensing 84/08/07 BLOCH,P , JORDAN,W , MCCOLLOM,K Atomic Safety and Licensing Board Panel 2pp 26190 001 24X Fiche 50-445,84/08/07,8408160313

--8408220412 Forwards responses to 840518 & 23 ltrs re 60 allegations concerning protective coating practices at facility Responses based on technical knowledge & review of existing documentation Supporting documentation encl
FIKAR,L F Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 84/06/22 BANGART,R L Region 4, Office of Director 320pp 26190 003 24X Fiche 50-445,84/08/07, 8408160313

--8408220415 Forwards draft "Status Rept on Protective Coatings Allegations "
TAYLOR,J H Brookhaven National Laboratory 84/06/13
BANGART,R L Region 4, Office of Director 50pp 26190 323. 24X Fiche 50-445,84/08/07,8408160313

--8408220419 Forwards IE Insp Repts 50-445/84-03 & 50-446/84-01 on 840130-0203
LETTIERI,V Brookhaven National Laboratory 84/02/24
HUNNICUTT,D M Region 4, Office of Director 1p 26191 010 24X Fiche 50-445,84/08/07,8408160313

--8408220424 IE Insp Repts 50-445/84-03 & 50-446/84-01 on 840130-0203 No violations or deviation identified Major areas inspected protective coatings programs
HIGGINS,J C , LETTIERI,V Region 4, Office of Director 84/02/23 12pp 26191 011 24X Fiche 50-445,84/08/07,8408160313

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co. of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408160330 Forwards summaries of two addl BIW cable environ qualification repts,per 840719 request to address concerns resulting from NRC insp Cable adequately qualified
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/10 YOUNGBLOOD,B J Licensing Branch 1 16pp 26085 322 24X Fiche 50-445,84/08/10,8408160330

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping, " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

E Info Notice 84-65, "Underrated Fuses Which May Adversely
ration of Essential Electrical Equipment " Svc

Division of Emergency Preparedness & Engineering
Post 830103) 84/08/16 Consolidated Edison Co of New
118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

orwards Insp Repts 50-445/84-17 re disassembly, insp &
of TDI emergency diesel generator, 50-445/84-05 re
s on fabrication of pipe supports & restraints &
10 re walkdown Related correspondence
Hearing Branch 1 DSB 304 84/08/16 BLOCH,P B
ety and Licensing Board Panel 1p 26247 069 24X
45, 84/08/16,8408270065

orwards 840621 Insp Repts 50-445/84-11 & 50-446/84-05,
of title page & summary portion of Ofc of
ion Rept 4-84-006 Related correspondence
Hearing Branch 1 DSB 302 84/08/16 BLOCH,P B
ety and Licensing Board Panel 1p 26247 358 24X
45, 84/08/16,8408270097

E Info Notice 84-66, "Undetected Unavailability of
iven Auxiliary Feedwater Train " Svc list encl
Division of Emergency Preparedness & Engineering
Post 830103) 84/08/17 Consolidated Edison Co of New
120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

E Info Notice 84-67, "Recent Snubber Inservice Testing W/
re Rates " Svc list encl
Division of Emergency Preparedness & Engineering
Post 830103) 84/08/17 Consolidated Edison Co of New
122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

orwards Insp Repts 50-445/84-12 & 50-446/84-06 on
3 re status of 10CFR50 55(e) repts & 50-445/84-08
4-04 on 831114-840331 re polar crane shim gaps
rrespondence
Hearing Branch 1 DSB 318 84/08/17 BLOCH,P B
ety and Licensing Board Panel 62pp 26262 287 24X
45, 84/08/17,8408280232

artial answer in opposition to applicant 840807 motion for
ion to issue license to load fuel & conduct
critical testing Insp repts & Certificate of Svc

Citizens Association For Sound Energy DSB 267 84/08/18
Safety and Licensing Board Panel 54pp 26222 277 24X
45, 84/08/18,8408240244

E Info Notice 84-68, "Potential Deficiency in Improperly
l Wiring to Solenoid Valves " Svc list encl
Division of Emergency Preparedness & Engineering
Post 830103) 84/08/21 Consolidated Edison Co of New
115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

perating reports & related correspondence

bmits sixth biweekly update on status, through 840721, of
chedule-related issues for fuel load in late
ontrol room HVAC testing incomplete Schedule
3 Uks cannot be recovered
Texas Utilities Electric Co (formerly Texas Utilities
Co) 84/07/30 EISENHUT,D G Division of Licensing
Region 4, Office of Director 11pp 25923 324 24X
5, 84/07/30,8408060184

ovides seventh biweekly status rept re schedular issues
ad. Info current through 840804 Project approx 3
schedule
Texas Utilities Electric Co (formerly Texas Utilities
Co.). 84/08/13 EISENHUT,D G Division of Licensing
Region 4, Office of Director 11pp 26119 112 24X
5, 84/08/13,8408170065

occurrences, LERs & related correspondence

rwards "Investigation of Types AF & AE Piston Skirts "
edes 840227 submittal
DI (Transamerica Delaval, Inc) Owners Group 84/05/24
Office of Nuclear Reactor Regulation, Director 2pp
24X Fiche 50-000,84/05/24,8405290062

"Investigation of Types AF & AE Piston Skirts "
s Analysis Associates FAAA-84-2-14 84/05/23 120pp
50-000,84/05/24,8405290062

8405290179 Forwards Evaluation of Emergency Diesel Generator
Crankshafts at Shoreha & Grand Gulf Nuclear Power
Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24492 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from
FaAA & TDI Owners Group at 840622 meeting Draft "Overview of
Repts, Analysis & Recommendations re Main Propulsion Engines
M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest
Laboratories 84/06/28 MILLER,M Division of Licensing 158pp
25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/
TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and
Enforcement 43pp 25934 133 24X Fiche 50-000,84/07/10,
8408060050

8408330115 Responds to 840529 ltr re problems identified at Bahnson Co,
Winston-Salem Facility No HVAC equipment received from subj
facility Bahnson Co solicited to assess or to take any
needed actions to improve QA program
CLEMENTS,B R Texas Utilities Electric Co (formerly Texas Utilities
Generating Co) 84/07/23 DEVOUNG,R C Director's Office, Office
of Inspection and Enforcement 2pp 25916 104 24X
Fiche 50-445,84/07/23,8408030115

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module
Control Wiring & Termination Qualification Review " Addl
copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring
& Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000,84/07/27,8408060102

8408090044 Interim Significant Deficiency Rept SDAR-129 re error in
tolerances used in calibr of adhesion tester Evaluation
continuing Completion anticipated by 840901
CLEMENTS,B R Texas Utilities Electric Co (formerly Texas Utilities
Generating Co) 84/07/31 JOHNSON,E H Region 4, Office of
Director 1p 25992 132 24X Fiche 50-445,84/07/31,8408090044

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger
Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator
Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000,84/08/01,8408060324

8408160510 Final Deficiency Rept SDAR-129 re error in tolerances used
in calibr of adhesion tester Initially reported on 840116
Investigation complete Matter not reportable under
10CFR50 55(e)
CLEMENTS,B R Texas Utilities Electric Co (formerly Texas Utilities
Generating Co) 84/08/06 JOHNSON,E H Region 4, Office of
Director 1p 26107 360 24X Fiche 50-445,84/08/06,8408160510

8408160185 Interim Deficiency Rept SDAR-140 re qualification of main
steam relief valves for actual loading conditions Initially
reported on 840710 Evaluation in progress & should be
completed by 840831
CLEMENTS,B R Texas Utilities Electric Co (formerly Texas Utilities
Generating Co) 84/08/08 JOHNSON,E H Region 4, Office of
Director 1p 26106 328 24X Fiche 50-445,84/08/08,8408160185

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for
TDI DERV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI
DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000,84/08/10,8408160394

8408200295 Interim Significant Deficiency Rept SDAR-132 re installation
of curtain fire dampers u/o proper provisions for thermal
expansion Initially reported on 840330 Review revealed 50
dampers required rework or mod Next rept by 840817
FIKAR,L F Texas Utilities Electric Co (formerly Texas Utilities
Generating Co) 84/08/13 JOHNSON,E H Region 4, Office of
Director 5pp 26140 101 24X Fiche 50-445,84/08/13,8408200295

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance " sets forth requirements for operation prior to completion of program plan
EISENHUT, D G Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000, 84/08/13, 8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50 000, 84/08/13, 8408240115

8408160395 Forwards "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-4B & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL per NRC request
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000, 84/08/14, 8408160395

--8408160397 "Design Review of Elliott Model 90G Turbocharger Used on TDI DSR-4B & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000, 84/08/14, 8408160395

8408280468 Final deficiency rept re flooding levels in electrical control bldg resulting from fire suppression Initially reported on 840717 Engineering resolutions to isolate affected drains will be implemented by 840830
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/16 JOHNSON, E H Region 4, Office of Director 2pp 26282 098 24X Fiche 50-445, 84/08/16, 8408280468

8408290125 Interim Deficiency Rept SDAR-142 re unqualified Limitorque electric motors Initially reported on 840720 Evaluation will be completed by 840921
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/16 JOHNSON, E H Region 4, Office of Director 1p 26297 343 24X Fiche 50-445, 84/08/16, 8408290125

8408280375 Final deficiency rept re defective diesel generator valve springs Initially reported on 840720 Condition not reportable under 10CFR50 55(e)
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/20 JOHNSON, E H Region 4, Office of Director 1p 26282 278 24X Fiche 50-445, 84/08/20, 8408280375

8408280384 Interim deficiency rept re matl defect in diesel generator fuel injection pump delivery valve holder Initially reported on 840720 Evaluation will be completed by 840921
CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/20 JOHNSON, E H Region 4, Office of Director 1p 26282 103 24X Fiche 50-445, 84/08/20, 8408280384

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER, C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000, 84/08/23, 8408290179

T Hearing transcriots on non-antitrust matters

8407310383 Transcript of 840723 telcon in Glen Rose, TX Pp 38, 567-38, 651
* Atomic Safety and Licensing Board Panel 84/07/23 91pp
25830 173 24X Fiche 50-445 84/07/23, 8407310383

8408080027 Transcript of L Barnes 840728 deposition in Glen Rose, TX, re harassment & intimidation at facility Pp 59, 000-59, 246 Supporting documentation encl
* Atomic Safety and Licensing Board Panel BARNES, L Brown & Root, Inc (subs of Halliburton Co) 84/07/28 269pp 25969 066 24X
Fiche 50-445, 84/07/28, 8408080027

8408070273 Transcript of M Rhodes W Sims, M Todd & S Burns 840730 deposition Pp 72, 000-72, 160
* Atomic Safety and Licensing Board Panel RHODES, M L Ebasco Services, Inc (subs of Enserch Corp) SIMS, W T Brown & Root, Inc (subs of Halliburton Co) 84/07/30 175pp 25949 024 24X
Fiche 50-445, 84/07/30, 8408070273

8408080257 Transcript of C Biggs, G Fanning, R Whitman & J Uehlein 840730 depositions in Glen Rose, TX Pp 71, 500-71, 659 Supporting documentation encl
* Atomic Safety and Licensing Board Panel BIGGS, C , FANNING, G Brown & Root, Inc (subs of Halliburton Co) 84/07/30 170pp
25967 257 24X Fiche 50-445, 84/07/30, 8408080257

8408070105 Vol II of transcript of M Gregory 840731 deposition in Glen Rose, TX Pp 54, 559-54, 718 Supporting documentation encl
* Atomic Safety and Licensing Board Panel GREGORY, M Texas Utilities Electric Co (Formerly Texas Utilities Generating Co)
GREGORY, M Brown & Root, Inc (subs of Halliburton Co) 84/07/31
204pp 25950 045 24X Fiche 50-445, 84/07/31, 8408070105

8408080051 Transcript of J Pitts 840731 deposition in Glen Rose, TX Pp 73, 500-73, 553
* Atomic Safety and Licensing Board Panel PITTS, J Texas Utilities Electric Co (Formerly Texas Utilities Generating Co)
PITTS, J Ebasco Services, Inc (subs of Enserch Corp) 84/07/31
55pp 25960 338 24X Fiche 50-445, 84/07/31, 8408080051

8408080100 Transcript of DL Anderson 840731 deposition in Glen Rose, TX re intimidation by QA personnel Pp 73, 000-73, 042 Supporting documentation encl
* Atomic Safety and Licensing Board Panel ANDERSON, D L Texas Utilities Electric Co (Formerly Texas Utilities Generating Co)
84/07/31 48pp 25965 117 24X Fiche 50-445, 84/07/31, 8408080100

8408080245 Transcript of D Anderson, S Spencer & A Boren 840731 depositions in Glen Rose, TX Pp 72, 500-72, 681 Supporting documentation encl
* Atomic Safety and Licensing Board Panel SPENCER, S , BOREN, A Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 84/07/31 188pp 25967 065 24X Fiche 50-445, 84/07/31, 8408080245

8408080023 Transcript of ST Haggard 840801 deposition in Glen Rose, TX Pp 74, 000-74, 016 Supporting documentation encl
* Atomic Safety and Licensing Board Panel HUGGARD, S T Brown & Root, Inc (subs of Halliburton Co) 84/08/01 24pp 25961 339
24X Fiche 50-445, 84/08/01, 8408080023

8408080032 Transcript of HF Gunn 840801 deposition in Glen Rose, TX Pp 75, 000-75, 008
* Atomic Safety and Licensing Board Panel GUNN, H F Texas Utilities Electric Co (Formerly Texas Utilities Generating Co)
GUNN, H F Brown & Root, Inc (subs of Halliburton Co) 84/08/01
11pp 25967 023 24X Fiche 50-445, 84/08/01, 8408080032

8408080089 Transcript of JN Scarbrough & D Ethridge depositions in Glen Rose, TX Pp 74, 500-74, 521 Supporting documentation encl
* Atomic Safety and Licensing Board Panel SCARBROUGH, J N ,
ETHRIDGE, D Brown & Root, Inc (subs of Halliburton Co)
84/08/01 26pp 25965 167 24X Fiche 50-445, 84/08/01, 8408080089

8408080272 Transcript of SA Neumeyer 840801 deposition in Glen Rose, TX Pp 59, 500-59, 683 Supporting documentation encl
* Atomic Safety and Licensing Board Panel NEUMEYER, S A Texas Utilities Electric Co (Formerly Texas Utilities Generating Co)
84/08/01 207pp 25966 080 24X Fiche 50-445, 84/08/01, 8408080272

8408080146 Transcript of DN Chapman 840802 deposition in Glen Rose, TX Pp 76, 500-76, 631 Supporting documentation encl
* Atomic Safety and Licensing Board Panel CHAPMAN, D N. Texas Utilities Electric Co (Formerly Texas Utilities Generating Co)
84/08/02 280pp 25959 278 24X Fiche 50-445, 84/08/02, 8408080146

8408080296 Transcript of 840802 telcon in Glen Rose, TX Pp 38, 690-38, 725
* Atomic Safety and Licensing Board Panel 84/08/02 39pp
25964 321 24X Fiche 50-445, 84/08/02, 8408080296

8408080026 Transcript of ML Coats 840803 deposition in Glen Rose, TX Pp 77, 500-77, 558 Supporting documentation encl
* Atomic Safety and Licensing Board Panel COATS, M L Texas Utilities Electric Co (Formerly Texas Utilities Generating Co)
84/08/03 81pp 25966 302 24X Fiche 50-445, 84/08/03, 8408080026

8408080294 Transcript of JC Keller 840803 deposition in Glen Rose, TX Pp 78, 000-78, 026 Supporting documentation encl
* Atomic Safety and Licensing Board Panel KELLER, J C Texas Utilities Electric Co (Formerly Texas Utilities Generating Co)
KELLER, J C Westinghouse Electric Corp 84/08/03 36pp
25965 270 24X Fiche 50-445, 84/08/03, 8408080294

8408220173 Board Notification 84-139 forwards transcript of 840607 meeting w/applicant re 840604 proposed FSAR amend on protective coatings
EISENHUT, D G Division of Licensing 84/08/17 BLOCH, P ,
JORDAN, W , MCCOLLOM, W Atomic Safety and Licensing Board Panel
3pp 26262 098 24X Fiche 50-445, 84/08/17, 8408220173

--8408280266 Transcript of 840607 meeting w/applicant in Bethesda, MD re protective coating inside containment Pp 1-100
* Commissioners 84/06/07 120pp 26262 101 24X
Fiche 50-445, 84/08/17, 8408220173

8408230432 Notice of filing in Docketing & Svc Branch of G Purdy in camera deposition in Glen Rose, TX
PURDY, G Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 207 84/08/18 2pp 26204 007 24X
Fiche 50-445, 84/08/18, 8408230432

8408220367 Forwards prefiled testimony of RM Duncan, RD McBee, R Simpson, DR Wright, JE Zwahr DT Wilterding & JE Brown, depositions of JN Scarbough et al & affidavit of DK Egbert Certificate of Svc encl
HARTMAN, S L Bishop, Liberman, Cook, Purcell & Reynolds
HARTMAN, S L Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 206 84/08/20 CLEMENTS, W L Docketing & Services Branch 4pp 26192 126 24X Fiche 50-445, 84/08/20, 8408220367

--8408220371 Prefiled testimony of AD Justice on 840816 in Glen Rose, TX Pp 1-20
JUSTICE A D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) JUSTICE, A D Brown & Root, Inc (subs of Halliburton Co) 84/08/16 20pp 26192 130 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220374 Prefiled testimony of RM Duncan on 840815 in Glen Rose, TX Pp 1-17
DUNCAN, R M Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DUNCAN, R M Brown & Root, Inc (subs of Halliburton Co) 84/08/15 23pp 26192 150 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220380 Prefiled testimony of RD McBee on 840816 in Glen Rose, TX Pp 1-24
MCBEE, R D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) MCBEE, R D Brown & Root, Inc (subs of Halliburton Co) 84/08/16 35pp 26192 173 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220381 Prefiled testimony of RW Simpson on 840815 in Glen Rose, TX Pp 1-38
SIMPSON, R W Texas Utilities Electric Co (formerly Texas Utilities Generating Co) SIMPSON, R W Brown & Root, Inc (subs of Halliburton Co) 84/08/15 42pp 26192 208 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220385 Prefiled testimony of DR Wright on 840816 in Glen Rose, TX Pp 1-9
WRIGHT, D R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) WRIGHT, D R Brown & Root, Inc (subs of Halliburton Co) 84/08/16 9pp 26192 260 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220388 Prefiled testimony of JC Zwahr & DT Wilterding on 840815 in Glen Rose, TX Pp 1-21
ZWAHR, J E , WILTERDING, D T Texas Utilities Electric Co (formerly Texas Utilities Generating Co) ZWAHR, J E Brown & Root, Inc (subs of Halliburton Co) 84/08/15 29pp 26192 269 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220393 Prefiled testimony of JE Brown on 840815 in Glen Rose, TX Pp 1-21
BROWN, J E Texas Utilities Electric Co (formerly Texas Utilities Generating Co) BROWN, J E Brown & Root, Inc (subs of Halliburton Co) 84/08/15 29pp 26192 298 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220396 Deposition of ST Haggard on 840801 in Glen Rose, TX Pp 74,000-74,016 Personal resume encl
HOGGARD, S T Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/01 23pp 26192 327 24X
Fiche 50-445, 84/08/20, 8408220367

--8408220399 Affidavit of DK Egbert re discussion w/DK Stiner in Oct 1982 concerning employee benefits
EGBERT, D K Brown & Root, Inc (subs of Halliburton Co)
84/08/01 7pp 26192 350 24X Fiche 50-445, 84/08/20, 8408220367

--8408220403 Deposition of JN Scarbrough & D Ethridge on 840801 in Glen Rose, TX Pp 74,500-74,521
SCARBROUGH, J N , EIHRIDGE, D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) SCARBROUGH, J N Brown & Root, Inc (subs of Halliburton Co) 84/08/01 27pp
26192 357 24X Fiche 50-445, 84/08/20, 8408220367

--8408220405 Deposition of HF Gunn on 840801 in Glen Rose, TX Pp 75,000-75,008
GUNN, H F Texas Utilities Electric Co (formerly Texas Utilities Generating Co) GUNN, H F Brown & Root, Inc (subs of Halliburton Co) 84/08/01 10pp 26193 022 24X
Fiche 50-445, 84/08/20, 8408220367

8408240247 Forwards CASE 840820 prefiled testimony of IL Goldstein re harassment / intimidation
ROISMAN, A Z Trial Lawyers for Public Justice ROISMAN, A Z Citizens Association for Sound Energy DSB 257 84/08/20
BLOCH, P B GROSSMAN, H , JORDAN W H Atomic Safety and Licensing Board Panel 1p 26223 119 24X Fiche 50-445, 84/08/20, 8408240247

--8408240248 Written testimony of IL Goldstein re harassment & intimidation
GOLDSTEIN, I L Citizens Association for Sound Energy
GOLDSTEIN, I L Maryland, Univ of, College Park, MD 84/08/20
45pp 26223 120 24X Fiche 50-445, 84/08/20, 8408240247

8408240302 Transcript of 840822 hearing in Bethesda, MD Pp 13,965-14,014
* Atomic Safety and Licensing Board Panel 84/08/22 51pp
26225 321 24X Fiche 50-445 84/08/22, 8408240302

8408300103 Transcript of 840827 hearing in Bethesda, MD Pp 14,015-14,180
* Atomic Safety and Licensing Board Panel 84/08/27 168pp
26305 001 24X Fiche 50-445, 84/08/27, 8408300103

X Onsite Storage of Low Level Waste

8408270271 Advises of executed Contract DE-CR01-84RW00012 w/DOE for disposal of spent nuclear fuel from facilities Related info encl
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/08/21 YOUNGBLOOD, B W Licensing Branch 1
3pp 26241 015 24X Fiche 50-445, 84/08/21, 8408270271

DOCKET STN-50-417 GESSAR-238

A Application/construction stage documents & correspondence

8408010324 Notification of 840801 meeting w/GE in Bethesda, MD to discuss status of GESSAR II severe accident review & to focus attention on remaining issues re review
SCALETTI, D C Standardization & Special Projects Branch 84/07/26
THOMAS, C O Standardization & Special Projects Branch 3pp
25872 314 24X Fiche 50-447, 84/07/26, 8408010324

8408090203 Notification of 840808 meeting w/GE in San Jose, CA to discuss seismic hazard analysis for GESSAR II
SCALETTI, D C Standardization & Special Projects Branch 84/08/02
THOMAS, C O Standardization & Special Projects Branch 3pp
25991 200 24X Fiche 50-447, 84/08/02, 8408090203

8408090429 Reissued notification of 840809 meeting w/GE & JBA in Bethesda, MD to discuss seismic hazard analysis of GESSAR II
SCALETTI, D C Standardization & Special Projects Branch 84/08/02
THOMAS, C O Standardization / Special Projects Branch 3pp
25984 299 24X Fiche 50-447, 84/08/02, 8408090429

8408160339 Forwards BNL 830727 review of GESSAR PRA W/o encl
NIEMCZYK, S J Union of Concerned Scientists 84/08/06 QUIRK, J
General Electric Co 1p 26059 341 24X Fiche 50-447, 84/08/06, 8408160339

8408230209 Forwards draft amend to GESSAR II Sections 19 12 & 19 21, in response to 10CFR50 34(f), Items (1)(xii) & (2)(ix) re evaluation of alternate hydrogen control sys (HCS) & HCS preliminary design, respectively
SHERWOOD, G G General Electric Co 84/08/20 EISENHUT, D G,
Division of Licensing 10pp 26209 218 24X Fiche 50-447, 84/08/20, 8408230209

H General correspondence

8408070025 Responds to 840705 ltr to W Dircks requesting info re GESSAR-II meeting notifications Practice identified in OH Cunningham 840620 ltr remains intact GESSAR-II meeting notices will be posted shortly after receipt by PDR
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/07/25 NIEMCZYK, S J Union of Concerned Scientists 2pp
25956 188 24X Fiche 50-447, 84/07/25, 8408070025

--8408070027 Informs of difficulty in obtaining scheduling info re OE/NRC meetings concerning GESSAR-II Alt applicant/NRC meetings should be announced 10 days in advance by posting notices in PDR & including notices in NRC tapes
NIEMCZYK, S J Union of Concerned Scientists 84/07/05 DIRCKS, W
Office of the Executive Director for Operations 4pp 25956 190,
24X Fiche 50-447, 84/07/25, 8408070025

--8408070029 Responds to 840514 & 0604 ltrs re timely notice of GE/NRC meetings concerning GESSAR-II All meetings will be noticed at least 10 days in advance For NRC to convince GE to share proprietary data would be inappropriate
CUNNINGHAM, G H Office of the Executive Legal Director 84/06/20
NIEMCZYK, S J Union of Concerned Scientists 3pp 25956 194
24X Fiche 50-447, 84/07/25, 8408070025

P Operating license stage documents & correspondence

8408270155 Requests exemption to revise 10CFR170 license fee schedule re GESSAR II review Exemption to schedule appropriate since review of GESSAR II design committed under regulations & policies in existence in early 1982
SHERWOOD, G G General Electric Co 84/08/10 DIRCKS, W J Office of the Executive Director for Operations 2pp 26245 222 24X
Fiche 50-447, 84/08/10, 8408270155

DOCKET STN-50-454 BYRON STATION, UNIT 1

A Application/construction stage documents & correspondence

8408130409 Forwards, for review & comment, marked-up preliminary test procedure re functional & spring rate testing of steam generator snubbers, in response to 840308 concerns in IE Insp Repts 50-454/84-08 & 50-455/84-06
SWARTZ, E D Commonwealth Edison Co 84/04/26 KEPPLER, J G Region 3, Office of Director 23pp 26010 192 24X Fiche 50-454, 84/04/26, 8408130409

8408010116 Forwards request for addl info re Tech Specs on relief valves & ESF response time Response requested within 7 days of ltr date
YOUNGBLOOD, B J Licensing Branch 1 84/07/19 FARRAR, D L
Commonwealth Edison Co 7pp 25873 327 24X Fiche 50-454, 84/07/19, 8408010116

8408070034 Requests addl info to support rescheduled fuel load date of 840915 Response requested within 10 days of ltr receipt
YOUNGBLOOD, B J Licensing Branch 1 84/07/25 FARRAR, D L
Commonwealth Edison Co 4pp 25955 356 24X Fiche 50-454, 84/07/25, 8408070034

8408060136 Forwards response to 840719 request for addl info re Tech Specs Complete package of comments & suggestions to Section 3/4 8 of proof & review version of Unit 1 Tech Specs also encl
SWARTZ, E D Commonwealth Edison Co 84/07/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 65pp 25934 013 24X
Fiche 50-454, 84/07/26, 8408060136

8408140380 Forwards responses to FSAR Questions 10 57, 10 63, 10 64, 10 65 & 10 66 Revised response to Question 10 57 based on revised safe shutdown analysis Info will be included in next FSAR amend
SWARTZ, E D Commonwealth Edison Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 26041 132 24X
Fiche 50-000, 84/08/02, 8408140380

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X
Fiche 50-000, 84/08/06, 8408160345

8408160415 Advises that main hook & lower load block on fuel handling bldg crane will be temporarily replaced to meet requirement of replacing Unit 1 reactor coolant pump motor assembly, per B30426 commitment
ALEXANDER, G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26085 358 24X
Fiche 50-454, 84/08/07, 8408160415

8408170069 Application to amend CPPR-30, extending permit to 850101 to cover time for OL hearings & issuance
FARRAR, D L Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26119 031 24X
Fiche 50-454, 84/08/13, 8408170069

8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in NUREG-0737, Item II B 3 High radiation sampling sys described in FSAR will be operational on each unit prior to initial criticality
TRAMM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Offi of Nuclear Reactor Regulation, Director 1p 26193 139 24X
Fiche 50-000, 84/08/13, 8408220239

8408220368 Suppls 831216 comments re proof & review Tech Specs Refs three loop operation during Modes 1-4 should be removed due to lack of Westinghouse analyses
SWARTZ, E D Commonwealth Edison Co 84/08/15 DENTON, H R Off of Nuclear Reactor Regulation, Director 1p 26191 346 24X
Fiche 50 454, 84/08/15, 8408220368

8408270113 Informs of schedule for resolving concerns re provisions for sampling gaseous radioiodine OL should be conditioned to require resolution of NUREG-0737 requirements for sampling gaseous effluent steam prior to refueling outage
TRAMM, T R Commonwealth Edison Co 84/08/17 DENTON, H R Off of Nuclear Reactor Regulation, Director 1p 26247 329 24X
Fiche 50-454, 84/08/17, 8408270113

8408200275 Generic Ltr 84-20 to all licensees of operating reactors applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408270118 Submits addl inro re basis for proposed Tech Spec requirements on availability of Diesel Generator 2A during time Unit 2 under const
TRAMM, T R Commonwealth Edison Co 84/08/21 DENTON, H R Off of Nuclear Reactor Regulation, Director 2pp 26247 338 24X
Fiche 50-000, 84/08/21, 8408270118

8408290365 Forwards request for addl info re answer to Question 12 concerning reactor sys areas Due to lack of clarity in original response, response should be revised Revised response requested within 15 days of ltr receipt
YOUNGBLOOD, B J Licensing Branch 1 84/08/22 FARRAR, D L
Commonwealth Edison Co 2pp 26310 359 24X Fiche 50-454, 84/0 8408290365

8408310163 Provides addl info to support proposed Tech Spec change diesel oil sampling containment pressure Hi-1 & detector plateau curves, per NRC/util 840813-16 meetings
TRAMM, T R Commonwealth Edison Co 84/08/23 DENTON, H R Off of Nuclear Reactor Regulation, Director 3pp 26319 173 24X
Fiche 50-454, 84/08/23, 8408310163

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408010185 Forwards request for addl info for review of vol reduct sys (Outstanding Item 15 of Byron SER) Response requested within 30 days of ltr date
OLSHAN, L N Licensing Branch 1 84/07/19 FARRAR, D L
Commonwealth Edison Co 10pp 25873 292 24X Fiche 50-000, 84/07/19, 8408010185

8408140371 Forwards compliance review against GDC 51 for reactor containment pressure boundary components Review for Braidwood Station should resolve SER Outstanding Item 4
SWARTZ, E D Commonwealth Edison Co 84/08/09 DENTON, H R Of of Nuclear Reactor Regulation, Director 17pp 26042 299 24X
Fiche 50-000, 84/08/09, 8408140371

8408270265 Forwards addl documentation re preliminary site work pl placement & composition in Area of Concern 12 Info should close SER Outstanding Item 1 Test results encl
TRAMM, T R Commonwealth Edison Co 84/08/10 DENTON, H R Off of Nuclear Reactor Regulation, Director 5pp. 26240, 202 24X
Fiche 50-454, 84/08/10, 8408270265

--8408270276 "Field Density Test Results "
NELSON, R E H H Holmes Testing Laboratories, Inc 20 75/
1p 26240 207 24X Fiche 50-454, 84/08/10, 8408270265

--8408270284 "Rept of Field Compaction Tests "
HOLMES, H H H H Holmes Testing Laboratories, Inc 37 75/
1p 26240 208 24X Fiche 50-454, 84/08/10, 8408270265

--8408270292 "Rept of Field Compaction Tests, "
HOLMES, H H H H Holmes Testing Laboratories, Inc 81 75/
2pp 26240 209 24X Fiche 50-454, 84/08/10, 8408270265

--8408270296 "Rept of Field Compaction Tests "
HOLMES, H H H H Holmes Testing Laboratories, Inc 97 75/
4pp 26240 211 24X Fiche 50-454, 84/08/10, 8408270265.

8408270204 Forwards addl info re monitoring of leakage from sys outside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close SER Confirmatory Issue 28(a)
TRAMM,T R Commonwealth Edison Co 84/08/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 26245 103 24X
Fiche 50-000,84/08/11,8408270204

8408220306 Forwards proprietary & nonproprietary responses to NRC ltr re improved thermal design procedure Response should close Byron SER Outstanding Item 8 Info deleted Proprietary response withheld (ref 10CFR2 790)
TRAMM,T R Commonwealth Edison Co 84/08/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 20pp 26193 053 24X
Fiche 50-000,84/08/13,8408220306

--8408220321 Requests withholding proprietary response to NRC questions on improved thermal design procedures & rod bow,per 10CFR2 790 Affidavit AW-76-60 encl
WIESEMANN,R A Westinghouse Electric Corp 83/12/27 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 8pp 26193 073 24X Fiche 50-000,84/08/13, 8408220306

8408270373 Forwards addl info re instrumentation being installed for detection of inadequate core cooling Info should close SER Outstanding Item 9 w/o any license conditions
TRAMM,T R Commonwealth Edison Co 84/08/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26240 254 24X
Fiche 50-000,84/08/20,8408270373

8408280301 Requests addl info to complete review of environ qualification of equipment (SER Outstanding Item 7) Response expected within 10 days of ltr date
YOUNGBLOOD,B J Licensing Branch 1 84/08/22 FARRAR,D L Commonwealth Edison Co 3pp 26294 083 24X Fiche 50-454,84/08/22, 8408280301

8408310226 Forwards addl info re vol reduction sys,in response to 840710 request NRC review of info necessary to close SER Outstanding Item 15
TRAMM,T R Commonwealth Edison Co 84/08/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 27pp 26322 138 24X
Fiche 50-000,84/08/24,8408310226

F Security, medical, emergency & fire protection plans

8408150386 Forwards IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 84/07/27 REED,C Commonwealth Edison Co 2pp 26077 357 24X Fiche 50-454,84/07/27, 8408150386

--8408150394 IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance or deviations identified Major areas inspected selected open & improvement items identified during emergency preparedness implementation appraisal
PLOSKI,T J , CHRISTOFFER,G , SMITH,M J Region 3, Office of Director 84/07/27 5pp 26077 359 24X Fiche 50-454,84/07/27, 8408150386

8408220243 Summary of 840731 meeting w/util in Silver Spring,MD re security plan implementation
* NRC - No Detailed Affiliation Given 84/07/31 NRC - No Detailed Affiliation Given 2pp 26203 311 24X
Fiche 50-000,84/07/31,8408220243

8408080198 Forwards Amend 4 to "Fire Protection Rept," including detailed comparison of design,const,testing & maint practices against NFPA stds
SWARTZ,E D Commonwealth Edison Co 84/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 25985 001 24X
Fiche,50-000,84/08/02,8408080198

--8408080205 Amend 4 to "Fire Protection Rept "
* Commonwealth Edison Co 84/07/31 125pp 25985 004 24X
Fiche 50-000,84/08/02,8408080198

8408140234 Revised emergency plan implementing procedures,including BZP 100-T2, "Operations Director-Checklist," BZP 100-T3, "Technical Director-Checklist" & BZP 100-T4, "Maint Director-Checklist " W/transmittal & receipt form
* Commonwealth Edison Co 84/08/03 252pp 26056 077 24X
Fiche 50-454,84/08/03,8408140234

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO,C J Region 3, Office of Director 84/08/07 REED,C Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000,84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50,App E,Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR,D L Commonwealth Edison Co 84/07/05 PAPERIELLO,C J Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000,84/08/07,8408130401

8408240139 Rev 1 to Emergency Plan Implementing Procedure BZP 500-T7, "Checklist - Operational Support Ctr " W/840817 transmittal form
* Commonwealth Edison Co 84/08/15 6pp 26228 168 24X
Fiche 50-454,84/08/15,8408240139

8408220106 Forwards evacuation time estimates incorporating changes re employment ctr shutdown times,per ASLB 840113 initial decision Review of addl info should obviate need for license conditions
TRAMM,T R Commonwealth Edison Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 26191 194 24X
Fiche 50-454,84/08/16,8408220106

--8408220112 "Evacuation Time Estimates Within Plume Exposure Pathway Emergency Planning Zone for Byron Nuclear Generating Station "
* Commonwealth Edison Co 84/06/30 113pp 26191 195 24X
Fiche 50-454,84/08/16,8408220106

8408240173 Rev 1 to Procedure BZP 380-A3, "Locations of Fixed Environ Radiological Monitoring Station Air Samplers " W/840907 transmittal memo
* Commonwealth Edison Co 84/08/17 3pp 26228 165 24X
Fiche 50-454,84/08/17,8408240173

8408270218 Forwards advanced revs to fire protection rept included in Amend 5 & addl info re other fire protection issues for station Resumes of fire protection engineers involved in program will be included in Amend 5
TRAMM,T R Commonwealth Edison Co 84/08/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 35pp 26245 110 24X
Fiche 50-454,84/08/20,8408270218

O Adjudicatory correspondence

8405290241 First set of interrogatories to intervenors,requesting list of witnesses to be presented on intervenors behalf at reopened hearings & summary of testimony Certificate of Svc encl Related correspondence
BECKER,B D Commonwealth Edison Co BECKER,B D Isham, Lincoln & Beale DSB 311 84/05/18 3pp 24656 202 24X
Fiche 50-454,84/05/18,8405290241

8406260276 Submits partial response to 840619 ltr Transparent effort not being made to stall proceeding Method of responding to discovery request prohibits orderly discovery of case Certificate of Svc encl Related correspondence
WHICHER,J M Businessmen for the Public Interest WHICHER,J M Whicher, J M DSB 862 84/06/20 MILLER,M I Isham, Lincoln & Beale MILLER,M I Commonwealth Edison Co 3pp 25150 041 24X
Fiche 50-454,84/06/20,8406260276

8408010177 Notice of appearance in proceeding Certificate of Svc encl
LEARNER,H A League of Women Voters of Rockford, IL LEARNER,H A DeKalb Area Alliance for Responsible Energy LEARNER,H A Sinnissippi Alliance for the Environment (SAFE) DSB 669 84/07/24 4pp 25855 322 24X Fiche 50-454,84/07/24,8408010177

8408010181 Notices of appearance in proceeding Certificate of Svc encl
JUDSON,V A , WRIGHT,T W League of Women Voters of Rockford, IL JUDSON,V A DeKalb Area Alliance for Responsible Energy DSB 668 84/07/24 6pp 25854 356 24X Fiche 50-454,84/07/24,8408010181

8408070463 Order extending time until 840810 for Commission to act to review ALAB-770 Served on 840806
CHILK,B J Office of the Secretary of the Commission DSB 753 84/08/03 Commissioners 1p 25940 331 24X
Fiche 50-454,84/08/03,8408070463

8408080390 Request for suppls to util amended responses to Interrogatories 11 & 12 Certificate of Svc encl Related correspondence
JUDSON,V A DeKalb Area Alliance for Responsible Energy
JUDSON,V A Sinnissippi Alliance for the Environment (SAFE)
JUDSON,V A League of Women Voters of Rockford, IL DSB 840
84/08/06 Atomic Safety and Licensing Board Panel 4pp
25973 284 24X Fiche,50-454,84/08/06,8408080390

8408080395 Forwards request for suppls to util amended responses to Interrogatories 11 & 12 of intervenor first set of interrogatories W/o encl Related correspondence
JUDSON,V A Businessmen for the Public Interest DSB 841
84/08/06 MILLER,M I Isham, Lincoln & Beale 2pp 25974 101
24X Fiche 50-454,84/08/06,8408080395

8408090164 Forwards 840421 deposition of WD Ward W/o encl Related correspondence
WILCOVE,M N Hearing Branch 2 DSB 870 84/08/07 WESTHALL,M Taylor Associates 1p 25473 128 24X Fiche 50-454,84/08/07, 8408090164

8408130299 Forwards six documents for proposed inclusion w/board notification Documents include RL Spessard 840723 ltr to C Reed W/o encl Related correspondence
LEWIS,S H Hearing Branch 2 DSB 908 84/08/08 OLSHAN,L N Licensing Branch 1 2pp 26010 279 24X Fiche 50-454,84/08/08, 8408130299

8408290303 Expresses concern & opposition to licensing of plant ASLB should listen to concern of workers Facilities not needed & being put on line for convenience & profit of util
SCHRADER,D Affiliation Not Assigned DSB 372 84/08/09 SMITH,I Atomic Safety and Licensing Board Panel 2pp 26289 360 24X Fiche 50-454,84/08/09,8408290303

8408290308 Requests NRC review of outstanding items re licensing of plant
PETERSON,T Affiliation Not Assigned DSB 365 84/08/11 SMITH Atomic Safety and Licensing Board Panel 1p 26289 362 24X Fiche 50-454,84/08/11,8408290308

8408140454 Informs that Commission declined to review ALAB-770 Time within which Commission may act to review has expired & decision becare final agency action on 840810 Served on 840813
CHILK,S J Office of the Secretary of the Commission DSB 011 84/08/13 Atomic Safety and Licensing Appeal Panel 1p 26060 361 24X Fiche 50-454,84/08/13,8408140454

8408170382 Forwards corrections & attachments to CC Stokes written testimony W/o encls Related correspondence
WRIGHT,T W Businessmen for the Public Interest DSB 101 84/08/15 SMITH,I W , COLE,R F , CALLIHAN,A D Atomic Safety and Licensing Board Panel 1p 26128 259 24X Fiche 50-454,84/08/15, 8408170382

8408290310 Expresses concern that plant will go on line before proven safe Performance of NRC has caused puzzlement & disappointment NRC supports util position even in face of serious allegations re plant safety
PEWDLE,J A Affiliation Not Assigned DSB 366 84/08/15 SMITH,I W Atomic Safety and Licensing Board Panel 2pp 26289 355 24X Fiche 50-454,84/08/15,8408290310

8408210336 Memorandum opposing intervenor 840813 motion for leave to file testimony of WH Bleuel Bleuel qualifications not of expert caliber to assist ASLB Related correspondence
MILLER,M Commonwealth Edison Co MILLER,M Isham, Lincoln & Beale DSB 182 84/08/16 Atomic Safety and Licensing Board Panel 8pp 26179 342 24X Fiche 50-454,84/08/16,8408210336

-8408210344 Affidavit of GT Klopp re WH Bleuel proposed testimony concerning need for failure modes & effects analysis Certificate of Svc & svc list encl Related correspondence
KLOPP,G T Commonwealth Edison Co 84/08/16 8pp 26179 350 24X Fiche 50-454,84/08/16,8408210336

8408280443 Forwards 840718 Ofc of Investigation (OI) Rept 3-83-006, transmitted for placement in PDR OI reviewed document & made deletions to protect confidentiality & privacy Related correspondence
LEWIS,S H Office of the Executive Legal Director DSB 337 84/08/16 CLEMENTS,W L Docketing & Services Branch 138pp 26280 347 24X Fiche 50-454,84/08/16,8408280443

8408290307 Expresses concern re licensing of plant & 6,000 discrepancies in bldg of plant labeled nonsignificant Review of NRC outstanding items requested
GRUMLEY,J E Affiliation Not Assigned DSB 364 84/08/16 SMITH,I W Atomic Safety and Licensing Board Panel 1p 26290 341 24X Fiche 50-454,84/08/16,8408290307

8408290313 Expresses concern re licensing of plant ASLB should listen to concerns of workers wishing to testify Facilities not needed & being put on line for convenience of util
STILES,J M Mount Morris Times, Mount Morris, IL DSB 368 84/08/16 SMITH Atomic Safety and Licensing Board Panel 1p 26290 336 24X Fiche 50-454,84/08/16,8408290313

8408290275 Expresses concerns re safety of facility & citizens paying for util miscalculation
DANIELSEN,D C Affiliation Not Assigned DSB 370 84/08/17 SMITH,I W Atomic Safety and Licensing Board Panel 1p 26290 357 24X Fiche 50-454,84/08/17,8408290275

8408270163 Motion to exclude portions of prefiled testimony of CC Stokes, filed on 840816 Related correspondence
GALLO,J Commonwealth Edison Co GALLO,J Isham, Lincoln & Beale DSB 286 84 08/19 Atomic Safety and Licensing Board Panel 9pp 26245 263 24x Fiche 50 154 84/08/19,8408270163

--8408270172 Affidavit of KJ Kostal re prefiled testimony of C Stokes Certificate of Svc encl Related correspondence
KOSTAL,K T Commonwealth Edison Co KOSTAL,K T Sargent & Lundy, Inc 84/08/18 Atomic Safety and Licensing Board Panel 5pp 26245 272 24X Fiche 50 154,84/08/19,8408270163

8408290309 Questions sanity & political persuasion of members of Sinnissippi Alliance for opposing start up of facilities Delays cost millions Urges startup
LIGHTCAP J B Affiliation Not Assigned DSB 371 84/08/20 SMITH,I Atomic Safety and Licensing Board Panel 2pp 26290 339 24X Fiche 50-454,84/08/20,8408290305

8408290328 Expresses concern re licensing of plant Urges NRC to review outstanding points or contention about safety & make sure reinsp evidence not merely testimony convincing of safety
EMMETT,J Affiliation Not Assigned DSB 373 84/08/20 SMITH Atomic Safety and Licensing Board Panel 2pp 26289 347 24X Fiche 50-454,84/08/20,8408290328

8408290309 Commends IW Smith for decision to withhold licensing of plant until safety issues resolved Open discussion re addl safety concerns requested
HOLMBERG,J Illinois, State of DSB 367 84/08/22 SMITH,I W Atomic Safety and Licensing Board Panel 1p 26290 360 24X Fiche 50-454,84/08/22,8408290309

8408290281 Expresses concerns re licensing & opening of plant In Jan 1984,when util was denied license,ruling considered final NRC issuance of license to plant so obviously defective as to be beyond belief
POZDOLSKI,A Affiliation Not Assigned DSB 374 84/08/28 SMITH,I Atomic Safety and Licensing Board Panel 4pp 26290 329 24X Fiche 50-454,84/08/28,8408290281

8408310201 Notice of withdrawal of appearance in proceeding Related correspondence
WHITCHER,J M Businessmen for the Public Interest DSB 421 84/08/28 SMITH,I W , COLE,R F , CALLIHAN,A D Atomic Safety and Licensing Board Panel 1p 26318 311 24X Fiche 50-454,84/08/28, 8408310201

H General correspondence

8405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
DIRCKS,W J Office of the Executive Director for Operations 84/05/04 LUGAR,R G Senate 7pp 24524 325 24X Fiche 50-000,84/05/04,8405180145

--8405180152 Requests response to encl W & V Smelser 840210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation,withdrawal of util application for Zimmer & denial of license for Byron facility
LUGAR,R G Senate 84/03/14 PALLADINO,N Commissioners 3pp 24524 331 24X Fiche 50-000,84/05/04,8405180145

K Utility Final Safety Analysis Report (FSAR) & amends

8408300053 Forwards affidavit attesting to distribution of FSAR Amends 44 & 45
TRAMM,T R Commonwealth Edison Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26307 236 24X Fiche 50-000,81/08/16,8408300053

Q Inspection reports, IE Bulletins & correspondence

8408130415 Forwards,for review,Rev 1 to "Evaluation of Energy Absorbing Matl for Pipe Whip Restraints," in response to IE Insp Repts 50 454/83-06 & 50-455/83-05
SWARTZ,E D Commonwealth Edison Co 84/04/13 KEPPLER,J G Region 3, Office of Director 2pp 26011 038 24X Fiche 50-000,84/04/13, 8408130415

--8408130420 Rev 1 to "Evaluation of Energy Absorbing Matl for Pipe Whip Restraints "
KAO,G C , YANG,M S , SU,T Y Sargent & Lundy, Inc SAD-431 R01 84/04/30 47pp 26011 040 24X Fiche 50-000,84/04/13,8408130415

8408130409 Forwards, for review & comment marked-up preliminary test procedure re functional & spring rate testing of steam generator snubbers, in response to 840308 concerns in IE Insp Repts 50-454/84-08 & 50-455/84-06
SWARTZ, E D Commonwealth Edison Co 84/04/26 KEPPLER, J G Region 3, Office of Director 23pp 26010 192 24X Fiche 50-454, 84/04/26, 8408130409

8408010332 Forwards IE Insp Repts 50-454/84-33, 50-455/84-26 & 30-17034/84-01 on 840521-23, 29-31 & 0601 & 05-06 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/07/10 REED, C
Commonwealth Edison Co 2pp 25866 077 24X Fiche 50-454, 84/07/10, 8408010332

--8408010341 IE Insp Repts 50-454/84-33, 50-455/84-26 & 30-17034/84-01 on 840521-23, 29-31 & 0601 & 05-06 No noncompliance noted Major areas inspected preoperational radiation protection program & status of preoperational sys demonstrations
HUETER, L J , GILL, C F , GREGER, L R Region 3, Office of Director 84/07/10 20pp 25866 079 24X Fiche 50-454, 84/07/10, 8408010332

8408080188 Forwards IE Insp Repts 50-454/84-25, 50-455/84-18, 50-456/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted
SPESSARD, R L Region 3, Office of Director 84/07/18 REED, C
Commonwealth Edison Co 2pp 25974 327 24X Fiche 50-000, 84/07/18, 8408080188

--8408080195 IE Insp Repts 50-454/84-25, 50-455/84-18, 50-456/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted Major areas inspected design calculations re primary shield wall & reactor pressure shield wall
MUFFETT, J W , KAUFMAN, P D , NORTON, J F Region 3, Office of Director 84/07/18 4pp 25974 329 24X Fiche 50-000, 84/07/18, 8408080188

8408090212 Forwards IE Insp Repts 50-454/84-29 & 50-455/84-21 on 840514-0710 No noncompliance identified
SPESSARD, R L Region 3, Office of Director 84/07/23 REED, C
Commonwealth Edison Co 2pp 25994 165 24X Fiche 50-454, 84/07/23, 8408090212

--8408090217 IE Insp Repts 50-454/84-29 & 50-455/84-21 on 840514-0710 No noncompliance identified Major areas inspected licensee action on 10CFR50 55(e) item re butt splices in electrical conductors
CHRISTNOT, E F , MENDEZ, R , WILLIAMS, C C Region 3, Office of Director 84/07/23 6pp 25994 167 24X Fiche 50-454, 84/07/23, 8408090212

8407250229 IE Inro Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8407310032 Board Notification 84-135 Forwards SALP Repts 50-454/84-22 & 50-455/84-19 for Jan 1983 - Apr 1984 Any util comments on rept will be forwarded for review
NOVAK, T M Assistant Director for Licensing 84/07/27 SMITH, I W , CALLIHAN, D Atomic Safety and Licensing Board Panel ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 2pp 25926 334 24X Fiche 50-454, 84/07/27, 8407310032

8408150386 Forwards IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/07/27 REED, C
Commonwealth Edison Co 2pp 26077 357 24X Fiche 50-454, 84/07/27, 8408150386

--8408150394 IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance or deviations identified Major areas inspected selected open & improvement items identified during emergency preparedness implementation appraisal
PLOSKI, T J , CHRISTOFFER, G , SMITH, M J Region 3, Office of Director 84/07/27 5pp 26077 359 24X Fiche 50-454, 84/07/27, 8408150386

8408150482 Forwards IE Insp Rept 50-454/84-48 on 840713, 16 & 17 No noncompliance noted
SPESSARD, R L Region 3, Office of Director 84/07/27 REED, C
Commonwealth Edison Co 2pp 26078 171 24X Fiche 50-454, 84/07/27, 8408150482

--8408150487 IE Insp Rept 50-454/84-48 on 840713, 16 & 17 No noncompliance or deviations noted Major areas inspected followup on previous insp findings re testing of pipe support & restraint sys
KAUFMAN, P D , DANIELSON, D H Region 3, Office of Director 84/07/27 4pp 26078 173 24X Fiche 50-454, 84/07/27, 8408150482

8408070213 Forwards IE Insp Repts 50-454/84-32 & 50-455/84-25 on 840426-0717 & notice of violation
STREETER, J F Region 3, Office of Director 84/07/30 REED, C
Commonwealth Edison Co 2pp 25948 337 24X Fiche 50-454, 84/07/30, 8408070213

--8408070216 Notice of violation from insp on 840426-0717
STREETER, J F Region 3, Office of Director 84/07/30 3pp 25948 339 24X Fiche 50-454, 84/07/30, 8408070213

--8408070221 IE Insp Repts 50-454/84-32 & 50-455/84-25 on 840426-0717 Noncompliance noted failure to document nonconforming conditions, failure to control nonconforming items & failure to take effective corrective actions re weld problems
HAYES, D W CONNAUGHTON, K , STREETER, J F Region 3, Office of Director 84/07/30 11pp 25948 342 24X Fiche 50-454, 84/07/30, 8408070213

8408160212 Forwards IE Insp Rept 50-454/84-44 on 840611-15, 22 & 25-28 & notice of violation
SPESSARD, R L Region 3, Office of Director 84/07/30 REED, C
Commonwealth Edison Co 2pp 26106 248 24X Fiche 50-454, 84/07/30, 8408160212

--8408160216 Notice of violation from insp on 840611, 22 & 25-28
SPESSARD, R L Region 3, Office of Director 84/07/30 2pp 26106 250 24X Fiche 50-454, 84/07/30, 8408160212

--8408160217 IE Insp Rept 50-454/84-44 on 840611-15, 22 & 25-28 Noncompliance noted failure to implement corrective action on nonconformance identified during receipt insp & failure to store components per supplier instructions
KROPP, W , HAWKINS, F Region 3, Office of Director 84/07/26 10pp 26106 252 24X Fiche 50-454, 84/07/30, 8408160212

8408070204 Ack receipt of 840712 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/84-23 & 50-455/84-16
SPESSARD, R L Region 3, Office of Director 84/08/01 REED, C
Commonwealth Edison Co 2pp 25949 262 24X Fiche 50-454, 84/08/01, 8408070204

--8408070212 Responds to NRC 840612 ltr re violations noted in IE Insp Repts 50-454/84-23 & 50-455/84-16 Corrective actions &O equipment installation repts w/o ref to rev researched Rev dates determined & attached to repts
FARRAR, D L Commonwealth Edison Co 84/07/12 KEPPLER, J G
Region 3, Office of Director 4pp 25949 264 24X
Fiche 50-454, 84/08/01, 8408070204

8408090528 Notification of 840814 public meeting w/util in Bethesda, MD to discuss util response to integrated design insp rept
OLSHAN, L N Licensing Branch 1 84/08/02 YOUNGBLOOD, B J
Licensing Branch 1 4pp 25983 336 24X Fiche 50-454, 84/08/02, 8408090528

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408200221 Forwards IE Insp Rept 50-454/84-37 on 840514-0713 No noncompliance noted
SPESSARD, R L Region 3, Office of Director 84/08/03 REED, C
Commonwealth Edison Co 2pp 26139 142 24X Fiche 50-454, 84/08/03, 8408200221

--8408200227 IE Insp Rept 50-454/84-37 on 840514-0713 No noncompliance noted Major areas inspected as-built program & installation of electrical & instrumentation equipment to as-built drawings & review of hanger & conduit tray installation.
MENDEZ, R , CHRISTNOT, E , WILLIAMS, C C Region 3, Office of Director 84/07/31 15pp 26139 144 24X Fiche 50-454, 84/08/03, 8408200221

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408130103 Ack receipt of 840803 ltr informing NRC of steps taken to correct open items noted in IE Insp Repts 50-454/83-14, 50-455/83-12, 50-454/83-46 & 50-455/83-34
PAPERIELLO, C J Region 3, Office of Director 84/08/06 REED, C Commonwealth Edison Co 1p 26010 042 24X Fiche 50-454, 84/08/06, 8408130103

--8408130108 Responds to NRC 840426 ltr re open items noted in IE Insp Repts 50-454/83-14, 50-455/83-12, 50-454/83-46 & 50-455/83-34 Revised page to Teledyne analytical procedures manual encl
WEAVER, K T Commonwealth Edison Co 84/08/03 KEPPLER, J G Region 3, Office of Director 4pp 26010 043 24X Fiche 50-454, 84/08/06, 8408130103

8408230245 Forwards IE Insp Repts 50-454/84-38 & 50-455/84-33 on 840605-0713 No noncompliance noted
SPESSARD, R L Region 3, Office of Director 84/08/06 REED, C Commonwealth Edison Co 2pp 26213 273 24X Fiche 50-454, 84/08/06, 8408230245

--8408230252 IE Insp Repts 50-454/84-38 & 50-455/84-33 on 840605-0713 No noncompliance or deviations noted Major areas inspected action on previous insp findings, preoperational test procedures & results & surveillance tracking
RING, M , DUNLOP, A , WILLIAMS, D Region 3, Office of Director 84/07/28 9pp 26213 275 24X Fiche 50-454, 84/08/06, 8408230245

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, 84/08/08, 8408140344

8408150098 Suppls 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G Region 3, Office of Director 3pp 26067 053 24X Fiche 50-000, 84/08/08, 8408150098

8408200331 Suppls response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G Region 3, Office of Director 3pp 26132 318 24X Fiche 50-000, 84/08/08, 8408200331

8408140229 Ack receipt of 840723 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-454/84-27 & 50-455/84-19
SPESSARD, R L Region 3, Office of Director 84/08/09 REED, C Commonwealth Edison Co 1p 26055 310 24X Fiche 50-454, 84/08/09, 8408140229

--8408140241 Suppls response to NRC 840606 ltr re noncompliance noted in IE Insp Repts 50-454/84-27 & 50-455/84-19 Changes to Pages 5 & 6 of 840710 ltr re deficient hangers listed
FARRAR, D L Commonwealth Edison Co 84/07/23 KEPPLER, J G Region 3, Office of Director 2pp 26055 311 24X Fiche 50-454, 84/08/09, 8408140229

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408170039 Forwards IE insp rept on 840611-0713 No noncompliance identified W/o encl
SPESSARD, R L Region 3, Office of Director 84/08/10 REED, C Commonwealth Edison Co 2pp 26119 083 24X Fiche 50-454, 84/08/10, 8408170039

8408270245 Forwards Insp Repts 50-454/84-53 & 50-455/84-36 on 840724-26 No noncompliance noted
SPESSARD, R L Region 3, Office of Director 84/08/10 REED, C Commonwealth Edison Co 2pp 26258 101 24X Fiche 50-454, 84/08/10, 8408270245

--8408270271 Insp Repts 50-454/84-53 & 50-455/84-36 on 840724-26 No noncompliance noted Major areas inspected licensee action on previously identified item IE bulletins & 10CFR50 55(e) items
MENDEZ, R , CHRISTNOT, E BUTLER D Region 3, Office of Director 84/08/09 5pp 26258 103 24X Fiche 50-454, 84/08/10, 8408270245

8408100009 IE Info Notice 84 63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408220079 Documents schedule for submitting inservice insp (ISI) programs Commitment will be incorporated into FSAR in next amend ISI program will be submitted within 6 months after issuance of OLs
TRAHM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26193 251 24X Fiche 50-000, 84/08/13 8408220079

8408240196 Notifies of 840915 potential date for first use of respiratory protective equipment for fuel load Program complete & ready for insp
SWARTZ, E D Commonwealth Edison Co 84/08/14 KEPPLER, J G Region 3, Office of Director 1p 26228 104 24X Fiche 50-454, 84/08/14, 8408240196

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408280443 Forwards 840718 Ofc of Investigation (OI) Rept 3-83-006, transmitted for placement in PDR OI reviewed document & made deletions to protect confidentiality & privacy Related correspondence
LEWIS, S H Office of the Executive Legal Director DSB 337 84/08/16 CLEMENTS, W L Docketing & Services Branch 138pp 26280 347 24X Fiche 50-454, 84/08/16, 8408280443

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408230247 Board Notification 84-140 forwards NRC 840801 ack of response to Insp Repts 50-454/84-23 & 50-455/84-16 & util 840712 response to insp repts
NOVAK, T M Assistant Director for Licensing 84/08/22 SMITH, I W , CALLIHAN, D , COLE, R F Atomic Safety and Licensing Board Panel 3pp 26261 307 24X Fiche 50-454, 84/08/22, 8408230247

8408280274 Submits clarifying info to 840703 ltr re results of QC inspector reinsp program per Insp Repts 50-454/82-05 & 50-455/82-04 Reinsps of equipment setting & equipment mod clarified
DELOEDRGE, L O Commonwealth Edison Co 84/08/22 KEPPLR, J G Region 3, Office of Director 2pp 26274 325 24X Fiche 50-454, 84/08/22, 8408280274

8408300155 Forwards Attachments 1, 2, 3, 4 & 6 omitted from Board Notification 84-140
* NRC - No Detailed Affiliation Given 84/08/22 NRC - No Detailed Affiliation Given 1p 26304 282 24X Fiche 50-454, 84/08/22, 8408300155

8 Reportable occurrences, LERs & related correspondence

8407310030 Board Notification 84-134 forwards JF Streeter 840711 memo to DG Eisenhut re steam generator snubber testing failures Insp repts documenting results of testing & applicant reevaluation efforts will be forwarded to Board
NOVAK, T M Assistant Director for Licensing 84/07/27 SMITH, I W , CALLIHAN, D , COLE, R F Atomic Safety and Licensing Board Panel 2pp 25936 033 24X Fiche 50-000, 84/07/27, 8407310030

--8408060341 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE insp repts
STREETER, J F Region 3, Office of Director 84/07/11
EISENHUT, D G Division of Licensing 1p 25936 039 24X
Fiche 50-000 84/07/27, 8407310030

8408130231 Interim Deficiency Repts 84-05 & 84-11 re unsatisfactory operation during qualification testing of steam generator snubbers supplied by Boeing Co Initially reported on 840628 Next rept expected by 840901
SWART, E D Commonwealth Edison Co 84/07/31 KEPPLER, J G Region 3, Office of Director 4pp 26008 194 24X Fiche 50-000, 84/07/31, 8408130231

T Hearing transcripts on non-antitrust matters

8408020023 Transcript of 840727 hearing in Rockford, IL Vol II Pp 9,401-9,438 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/07/27 280pp
25880 305 24X Fiche 50-454, 84/07/27, 8408020023

8408020135 Transcript of 840727 hearing in Rockford, IL Vol I Pp 9,226-9,400 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/07/27 249pp
25891 034 24X Fiche 50-454, 84/07/27, 8408020135

8408010249 Forwards testimony filed during 840724 hearings in Rockford, IL W/o encls Related correspondence
GAYLEY, J Isham, Lincoln & Beale DSB 660 84/07/30 Docketing & Services Branch 1p 25855 340 24X Fiche 50-454, 84/07/30, 8408010249

8408060133 Transcript of 840730 hearing in Rockford, IL Pp 9,439-9,674 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/07/30 84pp
25928 140 24X Fiche 50-454, 84/07/30, 8408060133

8408060198 Transcript of 840731 hearing in Rockford, IL Pp 9,675-9,915
* Atomic Safety and Licensing Board Panel 84/07/31 242pp
25923 059 24X Fiche 50-454, 84/07/31, 8408060198

8408080043 Transcript of 840801 hearing in Rockford, IL Pp 9,916-10,145 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/08/01 234pp
25962 154 24X Fiche 50-454, 84/08/01, 8408080043

8408080022 Transcript of 840802 hearing in Rockford, IL
Pp 10,146-10,350
* Atomic Safety and Licensing Board Panel 84/08/02 360pp
25968 066 24X Fiche 50-454, 84/08/02, 8408080022

8408100030 Forwards transcript of KD Ward 840621 deposition in Glen Ellyn, IL Related correspondence
RILEY, A Taylor Associates DSB 890 84/08/07 PLEASANT, E Docketing & Services Branch 1p 25997 086 24X
Fiche 50-454, 84/08/07, 8408100030

--8408100040 Transcript of KD Ward 840621 deposition in Glen Ellyn, IL Related correspondence
* Atomic Safety and Licensing Board Panel WARD, K D
Commonwealth Edison Co 84/06/21 175pp 25997 087 24X
Fiche 50-454, 84/08/07, 8408100030

8408150119 Forwards summary of testimony & testimony of NRC re equipment by Sys Control Corp, to be presented on 840820 Related correspondence
WILCOVE, M N Hearing Branch 2 DSB 046 84/08/13 SMITH, I W, CALLIHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel
2pp 26066 322 24X Fiche 50-454, 84/08/13, 8408150119

--8408150127 Summary of testimony of NRC staff re equipment supplied to facility by Sys Control Corp Testimony discusses info acquired since Aug 1983 re corrective actions & steps taken to establish adequacy Related correspondence
* Office of the Executive Legal Director 84/08/13 2pp
26066 324 24X Fiche 50-454, 84/08/13, 8408150119

--8408150132 Testimony of NRC re equipment supplied to facility by Sys Control Corp Related correspondence
* Office of the Executive Legal Director 84/08/13 22pp
26066 326 24X Fiche 50-454, 84/08/13, 8408150119

8408170319 Motion for leave to file testimony of WH Bleuel on Contention 1 re reinsp program Related correspondence
CASSEL, D W DeKalb Area Alliance for Responsible Energy DSB 085
84/08/13 Atomic Safety and Licensing Board Panel 4pp
26114 317 24X Fiche 50-454, 84/08/13, 8408170319

--8408170321 Summary of testimony & testimony of WH Bleuel on Contention 1 re reinsp program Resume encl Related correspondence
BLEUEL, W H Affiliation Not Assigned 84/08/13 47pp
26114 321 24X Fiche 50-454, 84/08/13, 8408170319

--8408170326 Summary of testimony & testimony of EP Erickson on Contention 1 re reinsp program-inspector qualification & work quality Resume & Certificate of Svc encl Related correspondence
ERICKSEN, E P Temple Univ, Philadelphia, PA ERICKSEN, E P
Businessmen for the Public Interest 84/08/13 33pp 26115 007
24X Fiche 50-454, 84/08/13, 8408170319

8408170298 Forwards corrected Pages 6,11 & 17 to EP Erickson testimony re reinsp program Related correspondence
JUDSON, V A Businessmen for the Public Interest DSB 090
84/08/14 SMITH, J W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 4pp 26115 124 24X Fiche 50-454, 84/08/14, 8408170298

8408170307 Summary of testimony & testimony of DS Kochhar on Contention 1 re reinsp program Certificate of Svc encl Related correspondence
KOCHHAR, D S Michigan, Univ of, Ann Arbor, MI DSB 091 84/08/14
24pp 26115 040 24X Fiche 50-454, 84/08/14, 8408170307

8408170296 Direct testimony of CC Stokes re engineering evaluations performed & use of engineering judgement by Sargent & Lundy Suggests need for independent engineering analysis of safety significance of reinsp program Related correspondence
STOKES, C C Affiliation Not Assigned DSB 084 84/08/16 36pp
26115 073 24X Fiche 50-454, 84/08/16, 8408170296

8408170380 Summary of testimony & direct testimony of CC Stokes on reinsp program Related correspondence
STOKES, C C, STOKES, C C Businessmen for the Public Interest DSB
100 84/08/17 98pp 26128 260 24X Fiche 50-454, 84/08/17, 8408170380

8408200446 Forwards transcript of CC Stokes 840817 deposition Related correspondence
WESTHALL, M Ann Riley & Associates DSB 177 84/08/20
PLEASANT, E Docketing & Services Branch 1p 26136 114 24X
Fiche 50-454, 84/08/20, 8408200446

--8408200458 Transcript of CC Stokes 840817 deposition in Chicago, IL Pp 1-173 Vol II Related correspondence
STOKES, C C Commonwealth Edison Co 84/08/17 175pp 26136 115
24X Fiche 50-454, 84/08/20, 8408200446

8408270023 Transcript of 840820 hearing in Rockford, IL Pp 10,351-10,458
* Atomic Safety and Licensing Board Panel 84/08/20 108pp
26247 195 24X Fiche 50-454, 84/08/20, 8408270023

8408270025 Transcript of hearing in Rockford, IL Pp 10,459-10,682
* Atomic Safety and Licensing Board Panel 84/08/21 266pp
26246 093 24X Fiche 50-454, 84/08/21, 8408270025

8408280228 Transcript of 840822 hearing in Rockford, IL Pp 10,683-10,931 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/08/22 396pp
26263 001 24X Fiche 50-454, 84/08/22, 8408280228

8408280153 Transcript of 840823 hearing in Rockford, IL
Pp 10,932-11,139
* Atomic Safety and Licensing Board Panel 84/08/23 263pp
26270 001 24X Fiche 50-454, 84/08/23, 8408280153

8408280138 Transcript of 840824 hearing in Rockford, IL Pp 11,140-11,179 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/08/24 124pp
26259 088 24X Fiche 50-454, 84/08/24, 8408280138

8408310192 Rebuttal testimony of G Erler re Stokes allegations concerning evaluations of discrepancies in calculated actual stress performed by Sargent & Lundy Related correspondence
ERLER, G Sargent & Lundy, Inc DSB 389 84/08/30 10pp
26319 043 24X Fiche 50-454, 84/08/30, 8408310192

--8408310194 Summary of rebuttal testimony & testimony of ML Somsag, EB Branch, D DeMoss, MR Frankel, BF Maurer & JK Buchanan re plant QC inspector reinsp program & C Stokes allegations re welds Related correspondence
BRANCH, E B, DEMOSS, D M Sargent & Lundy, Inc FRANKEL, M R City College of New York 84/08/30 83pp 26319 053 24X
Fiche 50-454, 84/08/30, 8408310192

--8408310199 Rebuttal testimony of RW Hooks re validity of info in Attachment 7 to Stokes testimony concerning design assumption for plant Stokes info inapplicable to plant Related correspondence
HOOKS, R W Sargent & Lundy Inc 84/08/30 5pp 26319 136 24X Fiche 50-454, 84/08/30, 8408310192

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26051 240 24X Fiche 50-000, 84/08/07, 8408140372

--8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X Fiche 50-000, 84/08/07, 8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET STN-50-455 BYRON STATION, UNIT 2

A Application/construction stage documents & correspondence

8408130409 Forwards, for review & comment, marked-up preliminary test procedure re functional & spring rate testing of steam generator snubbers, in response to 840308 concerns in IE Insp Repts 50-454/84-08 & 50-455/84-06
SWARTZ, E D Commonwealth Edison Co 84/04/26 KEPPLER, J G Region 3, Office of Director 23pp 26010 192 24X Fiche 50-454, 84/04/26, 8408130409

8408010116 Forwards request for addl info re Tech Specs on relief valves & ESF response time Response requested within 7 days of ltr date
YOUNGBLOOD, B J Licensing Branch 1 84/07/19 FARRAR, D L Commonwealth Edison Co 7pp 25873 327 24X Fiche 50-454, 84/07/19, 8408010116

8408060136 Forwards response to 840719 request for addl info re Tech Specs Complete package of comments & suggestions to Section 3/4 8 of proof & review version of Unit 1 Tech Specs also encl
SWARTZ, E D Commonwealth Edison Co 84/07/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 65pp 25934 013 24X Fiche 50-454, 84/07/26, 8408060136

8408140380 Forwards responses to FSAR Questions 10 57.10 63, 10 64, 10 65 & 10 66 Revised response to Question 10 57 based on revised safe shutdown analysis Info will be included in next FSAR amend
SWARTZ, E D Commonwealth Edison Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 26041 132 24X Fiche 50-000, 84/08/02, 8408140380

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000, 84/08/06, 8408070110

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X Fiche 50-000, 84/08/06, 8408160345

8408160415 Advises that main hook & lower load block on fuel handling bldg crane will be temporarily replaced to meet requirement of replacing Unit 1 reactor coolant pump motor assembly, per 830426 commitment
ALEXANDER, G Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26085 358 24X Fiche 50-454, 84/08/07, 8408160415

8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in NUREG-0737, Item II B 3 High radiation sampling sys described in FSAR will be operational on each unit prior to initial criticality
TRAMM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26193 139 24X Fiche 50-000, 84/08/13, 8408220239

8408220368 Supplis 831214 comments re proof & review Tech Specs Refs to three loop operation during Modes 1-4 should be removed due to lack of Westinghouse analyses
SWARTZ, E D Commonwealth Edison Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26191 346 24X Fiche 50-454, 84/08/15, 8408220368

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000, 84/08/20, 8408200275

8408270118 Submits addl info re basis for proposed Tech Spec requirements on availability of Diesel Generator 2A during time Unit 2 under const
TRAMM, T R Commonwealth Edison Co 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26247 338 24X Fiche 50-000, 84/08/21, 8408270118

8408310163 Provides addl info to support proposed Tech Spec changes re diesel oil sampling containment pressure Hi-1 & detector plateau curves, per NRC/util 840813-16 meetings
TRAMM, T R Commonwealth Edison Co 84/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26319 173 24X Fiche 50-454, 84/08/23, 8408310163

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408010185 Forwards request for addl info for review of vol reduction sys (Outstanding Item 15 of Byron SER) Response requested within 30 days of ltr date
OLSHAN, L N Licensing Branch 1 84/07/19 FARRAR, D L Commonwealth Edison Co 10pp 25873 292 24X Fiche 50-000, 84/07/19, 8408010185

8408140371 Forwards compliance review against GDC 51 for reactor containment pressure boundary components Review for Braidwood Station should resolve SER Outstanding Item 4
SWARTZ, E D Commonwealth Edison Co 84/08/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 26042 299 24X Fiche 50-000, 84/08/09, 8408140371

8408270265 Forwards addl documentation re preliminary site work fill placement & composition in Area of Concern 12 Info should close SER Outstanding Item 1 Test results encl
TRAMM, T R Commonwealth Edison Co 84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 26240 202 24X Fiche 50-454, 84/08/10, 8408270265

--8408270276 "Field Density Test Results "
NELSON, R E H H Holmes Testing Laboratories, Inc 20 75/05/30
1p 26240 207 24X Fiche 50-454, 84/08/10, 8408270265

--8408270284 "Rept of Field Compaction Tests "
HOLMES, H R H H Holmes Testing Laboratories, Inc 37 75/06/20
1p 26240 208 24X Fiche 50-454, 84/08/10, 8408270265

--8408270292 "Rept of Field Compaction Tests "
HOLMES, H H H H Holmes Testing Laboratories, Inc 81 75/07/22
2pp 26240 209 24X Fiche 50-454, 84/08/10, 8408270265

--8408270296 "Rept of Field Compaction Tests "
HOLMES, H H H H Holmes Testing Laboratories, Inc 97 75/08/11
4pp 26240 211 24X Fiche 50-454, 84/08/10, 8408270265

8408270204 Forwards addl info re monitoring of leakage from sys outside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close SER Confirmatory Issue 28(a)
TRAMM, T R Commonwealth Edison Co 84/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 26245 103 24X Fiche 50-000, 84/08/11, 8408270204

8408220306 Forwards proprietary & nonproprietary responses to NRC ltr re improved thermal design procedure Response should close Byron SER Outstanding Item 8 Info deleted Proprietary response withheld (ref 10CFR2 790)
TRAMM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 26193 053 24X Fiche 50-000, 84/08/13, 8408220306

--8408220321 Requests withholding proprietary response to NRC questions on improved thermal design procedures & rod bow, per 10CFR2 790 Affidavit AW-76-40 encl
WIESEMANN, R A Westinghouse Electric Corp 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 8pp 26193 073 24X Fiche 50-000, 84/08/13, 8408220306

8408270373 Forwards addl info re instrumentation being installed for detection of inadequate core cooling Info should close SER Outstanding Item 9 w/o any license conditions
TRAMM, T R Commonwealth Edison Co 84/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26240 254 24X
Fiche 50-000 84/08/20 8408270373

8408310226 Forwards addl info re vol reduction sys, in response to 840710 request NRC review of info necessary to close SER Outstanding Item 15
TRAMM, T R Commonwealth Edison Co 84/08 24 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 26322 138 24X
Fiche 50-000, 84/08/24, 8408310226

F Security, medical, emergency & fire protection plans

8408150386 Forwards IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/07/27 REED, C Commonwealth Edison Co 2pp 26077 357 24X Fiche 50-454, 84/07/27, 8408150386

--8408150394 IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance or deviations identified Major areas inspected selected open & improvement items identified during emergency preparedness implementation appraisal
PLOSKI, T J , PHILLIPS, M P Region 3, Office of Director 84/07/27 5pp 26077 359 24X Fiche 50-454, 84/07/27, 8408150386

8408220243 Summary of 840731 meeting w/util in Silver Spring, MD re security plan implementation
* NRC - No Detailed Affiliation Given 84/07/31 NRC - No Detailed Affiliation Given 2pp 26203 311 24X
Fiche 50-000, 84/07/31, 8408220243

8408080198 Forwards Amend 4 to "Fire Protection Rept," including detailed comparison of design, const, testing & maint practices against NFPA stds
SWAR17, C D Commonwealth Edison Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 25985 001 24X
Fiche 50-000, 84/08/02, 8408080198

--8408080205 Amend 4 to Fire Protection Rept "
* Commonwealth Edison Co 84/07/31 125pp 25985 004 24X
Fiche 50-000, 84/08/02, 8408080198

8408140234 Revised emergency plan implementing procedures, including BZP 100-T2, "Operations Director-Checklist," BZP 100-T3, "Technical Director-Checklist" & BZP 100 T4, "Maint Director-Checklist " W/transmittal & receipt form
* Commonwealth Edison Co 84/08/03 252pp 26056 077 24X
Fiche 50-454, 84/08/03, 8408140231

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO, C J Region 3, Office of Director 84/08/07 REED, C Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000, 84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR, D L Commonwealth Edison Co 84/07/05 PAPERIELLO, C J Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000, 84/08/07, 8408130401

8408240139 Rev 1 to Emergency Plan Implementing Procedure BZP 500-T7, "Checklist - Operational Support Ctr " W/840817 transmittal form
* Commonweal*h Edison Co 84/08/15 6pp 26228 168 24X
Fiche 50-454, 84/08/15, 8408240139

8408220106 Forwards evacuation time estimates incorporating changes re employment ctr shutdown times, per ASLB 840113 initial decision Review of addl info should obviate need for license conditions
TRAMM, T R Commonwealth Edison Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26191 194 24X
Fiche 50-454, 84/08/16, 8408220106

--8408220112 "Evacuation Time Estimates Within Plume Exposure Pathway Emergency Planning Zone for Byron Nuclear Generating Station "
* Commonwealth Edison Co 84/06/30 113pp 26191 195 24X
Fiche 50-454, 84/08/16, 8408220106

8408240173 Rev 1 to Procedure BZP 380-A3, "Locations of Fixed Environ Radiological Monitoring Station Air Samplers " W/840907 transmittal memo
* Commonwealth Edison Co 84/08/17 3pp 26228 165 24X
Fiche 50-454, 84/08/17, 8408240173

8408270218 Forwards advanced revs to fire protection rept included in Amend 5 & addl info re other fire protection issues for station Resumes of fire protection engineers involved in program will be included in Amend 5
TRAMM, T R Commonwealth Edison Co 84/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 35pp 26245 110 24X
Fiche 50-454, 84/08/20, 8408270218

G Adjudicatory correspondence

8405250241 First set of interrogatories to intervenors, requesting list of witnesses to be presented on intervenors behalf at reopened hearings & summary of testimony Certificate of Svc encl Related correspondence
BECKER, B D Commonwealth Edison Co BECKER, B D Isham, Lincoln & Beale DSB 311 84/05/18 3pp 24656 202 24X
Fiche 50-454, 84/05/18, 8405250241

8406260276 Submits partial response to 840619 ltr Transparent effort not being made to stall proceeding Method of responding to discovery request prohibits orderly discovery of case Certificate of Svc encl Related correspondence
WHICHER, J M Businessmen for the Public Interest WHICHER, J M Whicher, J M DSB 862 84/06/20 MILLER, M I Isham, Lincoln & Beale MILLER, M I Commonwealth Edison Co 3pp 25150 041 24X
Fiche 50-454, 84/06/20, 8406260276

8408010177 Notice of appearance in proceeding Certificate of Svc encl LEARNER, H A League of Women Voters of Rockford, IL LEARNER, H A DeKalb Area Alliance for Responsible Energy LEARNER, H A Binnissippi Alliance for the Environment (SAFE) DSB 669 84/07/24 4pp 25855 322 24X Fiche 50-454, 84/07/24, 8408010177

8408010181 Notices of appearance in proceeding Certificate of Svc encl JUDSON, V A , WRIGHT, T W League of Women Voters of Rockford, IL JUDSON, V A DeKalb Area Alliance for Responsible Energy DSB 668 84/07/24 6pp 25854 356 24X Fiche 50-454, 84/07/24, 8408010181

8408070463 Order extending time until 840810 for Commission to act to review ALAB-770 Served on 840806
CHILK, S J Office of the Secretary of the Commission DSB 753 84/08/03 Commissioners 1p 25940 331 24X
Fiche 50-454, 84/08/03, 8408070463

8408080390 Request for supplS to util amended responses to Interrogatories 11 & 12 Certificate of Svc encl Related correspondence
JUDSON, V A DeKalb Area Alliance for Responsible Energy
JUDSON, V A Binnissippi Alliance for the Environment (SAFE)
JUDSON, V A League of Women Voters of Rockford, IL DSB 840 84/08/06 Atomic Safety and Licensing Board Panel 4pp 25973 284 24X Fiche 50-454, 84/08/06, 8408080390

8408080395 Forwards request for supplS to util amended responses to Interrogatories 11 & 12 of intervenor first set of interrogatories W/o encl Related correspondence
JUDSON, V A Businessmen for the Public Interest DSB 841 84/08/06 MILLER, M I Isham, Lincoln & Beale 2pp 25974 101 24X Fiche 50-454, 84/08/06, 8408080395

8408090164 Forwards 840621 deposition of KD Ward W/o encl Related correspondence
WILCOVE, M N Hearing Branch 2 DSB 870 84/08/07 WESTHALL, M Taylor Associates 1p 25973 128 24X Fiche 50-454, 84/08/07, 8408090164

8408130299 Forwards six documents for proposed inclusion w/board notification Documents include RL Spessard 840723 ltr to C Reed W/o encl Related correspondence
LEWIS, S H Hearing Branch 2 DSB 908 84/08/08 OLSHAN, L N Licensing Branch 1 2pp 26010 279 24X Fiche 50-454, 84/08/08, 8408130299

8408290303 Expresses concern & opposition to licensing of plant ASLB should listen to concern of workers Facilities not needed & being put on line for convenience & profit of util
SCHRADER, D Affiliation Not Assigned DSB 372 84/08/09 SMITH, I Atomic Safety and Licensing Board Panel 2pp 26289 360 24X
Fiche 50-454, 84/08/09, 8408290303

8408290308 Requests NRC review of outstanding items re licensing of plant
PETERSON, T Affiliation Not Assigned DSB 365 84/08/11 SMITH Atomic Safety and Licensing Board Panel 1p 26289 362 24X
Fiche 50-454, 84/08/11, 8408290308

8408140454 Informs that Commission declined to review ALAB-770 Time within which Commission may act to review has expired & decision became final agency action on 840810 Served on 840813
CHILK, S J Office of the Secretary of the Commission DSB 011
84/08/13 Atomic Safety and Licensing Appeal Panel 1p
26060 361 24X Fiche 50-454, 84/08/13, 8408140454

8408170382 Forwards corrections & attachments to CC Stokes written testimony W/o encls Related correspondence
WRIGHT, T W Businessmen for the Public Interest DSB 101
84/08/15 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 26128 259 24X Fiche 50-454, 84/08/15, 8408170382

8408290310 Expresses concern that plant will go on line before proven safe Performance of NRC has caused puzzlement & disappointment NRC supports util position even in face of serious allegations re plant safety
PEWBLE, J A Affiliation Not Assigned DSB 366 84/08/15
SMITH, I W Atomic Safety and Licensing Board Panel 2pp
26289 355 24X Fiche 50-454, 84/08/15, 8408290310

8408210336 Memorandum opposing intervenor 840813 motion for leave to file testimony of WH Bleuel Bleuel qualifications not of expert caliber to assist ASLB Related correspondence
MILLER, M Commonwealth Edison Co MILLER, M Isham, Lincoln & Beale DSB 182 84/08/16 Atomic Safety and Licensing Board Panel 8pp 26179 342 24X Fiche 50-454, 84/08/16, 8408210336

--8408210344 Affidavit of GT Klopp re WH Bleuel proposed testimony concerning need for failure codes * effects analysis Certificate of Svc & svc list encl Related correspondence
KLOPP, G T Commonwealth Edison Co 84/08/16 8pp 26179 350
24X Fiche 50-454, 84/08/16, 8408210336

8408280443 Forwards 840718 Ofc of Investigation (OI) Rept 3-83-006, transmitted for placement in PDR OI reviewed document & made deletions to protect confidentiality & privacy Related correspondence
LEWIS, S H Office of the Executive Legal Director DSB 337
84/08/16 CLEMENTS, W L Docketing & Services Branch 138pp
26280 347 24X Fiche 50-454, 84/08/16, 8408280443

8408290307 Expresses concern re licensing of plant & 6,000 discrepancies in bldg of plant labeled nonsignificant Review of NRC outstanding items requested
GRUMLEY, J E Affiliation Not Assigned DSB 364 84/08/16
SMITH, I W Atomic Safety and Licensing Board Panel 1p 26290 341
24X Fiche 50-454, 84/08/16, 8408290307

8408290313 Expresses concern re licensing of plant ASLB should listen to concerns of workers wishing to testify Facilities not needed & being put on line for convenience of util
STILES, J M Mount Morris Times, Mount Morris, IL DSB 368
84/08/16 SMITH Atomic Safety and Licensing Board Panel 1p
26290 336 24X Fiche 50-454, 84/08/16, 8408290313

8408290275 Expresses concerns re safety of facility & citizens paying for util miscalculation
DANIELSEN, D C Affiliation Not Assigned DSB 370 84/08/17
SMITH, I W Atomic Safety and Licensing Board Panel 1p 26290 357
24X Fiche 50-454, 84/08/17, 8408290275

8408270163 Motion to exclude portions of prefiled testimony of CC Stokes, filed on 840816 Related correspondence
GALLO, J Commonwealth Edison Co GALLO, J Isham, Lincoln & Beale
DSB 286 84/08/19 Atomic Safety and Licensing Board Panel 9pp
26245 263 24X Fiche 50-454, 84/08/19, 8408270163

--8408270172 Affidavit of KT Kostal re prefiled testimony of C Stokes Certificate of Svc encl Related correspondence
KOSTAL, K T Commonwealth Edison Co KOSTAL, K T Sargent & Lundy, Inc 84/08/18 Atomic Safety and Licensing Board Panel 9pp
26245 272 24X Fiche 50-454, 84/08/19, 8408270163

8408290305 Questions sanity & political persuasion of members of Sinnissippi Alliance for opposing start up of facilities Delays cost millions Urges startup
LIGHTCAP, J R Affiliation Not Assigned DSB 371 84/08/20
SMITH, I Atomic Safety and Licensing Board Panel 2pp 26290 339
24X Fiche 50-454, 84/08/20, 8408290305

8408290328 Expresses concern re licensing of plant Urges NRC to review outstanding points of contention about safety & make sure reinsp evidence not merely testimony convincing of safety
EMMETT, J Affiliation Not Assigned DSB 373 84/08/20 SMITH
Atomic Safety and Licensing Board Panel 2pp 26289 347 24X
Fiche 50-454, 84/08/20, 8408290328

8408290309 Commends IW Smith for decision to withhold licensing of plant until safety issues resolved Open discussion re addl safety concerns requested
HOLMBERG, J Illinois State of DSB 367 84/08/22 SMITH, I W
Atomic Safety and Licensing Board Panel 1p 26290 360 24X
Fiche 50-454, 84/08/22, 8408290309

8408290281 Expresses concerns re licensing * opening of plant In Jan 1984, when util was denied license, ruling considered final NRC issuance of license to plant so obviously defective as to be beyond belief
POZDULSKI, A Affiliation Not Assigned DSB 374 84/08/28
SMITH, I Atomic Safety and Licensing Board Panel 4pp 26290 329
24X Fiche 50-454 84/08/28, 8408290281

8408310201 Notice of withdrawal of appearance in proceeding Related correspondence
WHICHER, J M Businessmen for the Public Interest DSB 421
84/08/28 SMITH, I W , COLE R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 26318 311 24X Fiche 50-454, 84/08/28, 8408310201

H General correspondence

8405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
DIRCKS, W J Office of the Executive Director for Operations
84/05/04 LUGAR, R G Senate 7pp 24524 325 24X
Fiche 50-000, 84/05/04, 8405180145

--8405180152 Requests response to encl W & V Smelser 840210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
LUGAR, R G Senate 84/03/14 PALLADINO, N Commissioners 3pp
24524 331 24X Fiche 50-000, 84/05/04, 8405180145

K Utility Final Safety Analysis Report (FSAR) & amends

8408300093 Forwards affidavit attesting to distribution of FSAR Amends 44 & 45
TRAMM, T R Commonwealth Edison Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26307 236 24X
Fiche 50-000, 84/08/16, 8408300093

Q Inspection Reports, IE Bulletins & Correspondence

8408130415 Forwards, for review, Rev 1 to "Evaluation of Energy Absorbing Matl for Pipe Whip Restraints," in response to IE Insp Repts 50-454/83-06 & 50-455/83-09
SWARTZ, E D Commonwealth Edison Co 84/04/13 KEPPLER, J G Region 3, Office of Director 2pp 26011 038 24X Fiche 50-000, 84/04/13, 8408130415

--8408130420 Rev 1 to "Evaluation of Energy Absorbing Matl for Pipe Whip Restraints "
KAO, G C , YANG, M S , SU, T Y Sargent & Lundy, Inc SAD-431 R01
84/04/30 47pp 26011 040 24X Fiche 50-000, 84/04/13, 8408130415

8408130409 Forwards, for review & comment, marked-up preliminary test procedure re functional & spring rate testing of steam generator snubbers, in response to 840308 concerns in IE Insp Repts 50-454/84-08 & 50-455/84-06
SWARTZ, E D Commonwealth Edison Co 84/04/26 KEPPLER, J G Region 3, Office of Director 23pp 26010 192 24X Fiche 50-454, 84/04/26, 8408130409

8408010332 Forwards IE Insp Repts 50-454/84-33, 50-455/84-26 & 30-17034/84-01 on 840521-23, 29-31 & 0601 & 05-06 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/07/10 REED, C
Commonwealth Edison Co 2pp 25866 077 24X Fiche 50-454, 84/07/10, 8408010332

--8408010341 IE Insp Repts 50-454/84-33, 50-455/84-26 & 30-17034/84-01 on 840521-23, 29-31 & 0601 & 05-06 No noncompliance noted Major areas inspected preoperational radiation protection program & status of preoperational sys demonstrations
HUETER, L J , GILL, C F , GREGER L R Region 3, Office of Director
84/07/10 20pp 25866 079 24X Fiche 50-454, 84/07/10, 8408010332

8408080188 Forwards IE Insp Repts 50-454/84-25, 50-455/84-18, 50-456/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted
SPESSARD, R L Region 3, Office of Director 84/07/18 REED, C
Commonwealth Edison Co 2pp 25974 327 24X Fiche 50-000, 84/07/18, 8408080188

--8408080195 IE Insp Repts 50-454/84-25,50-455/84-18,50-456/84-11 & 50-457/84-11 on 840425 - 0522-23 No noncompliance noted Major areas inspected design calculations re primary shield wall - reactor pressure shield wall MUFFETT,J W , KAUFMAN,P D , NORTON J F Region 3, Office of Director 84/07/18 4pp 25974 329 24X Fiche 50-000,84/07/18, 8408080188

8408090212 Forwards IE Insp Repts 50-454/84-29 & 50-455/84-21 on 840514-0710 No noncompliance identified SPESSARD,R L Region 3, Office of Director 84/07/23 REED,C Commonwealth Edison Co 2pp 25994 165 24X Fiche 50-454,84/07/23, 8408090212

--8408090217 IE Insp Repts 50-454/84-29 & 50-455/84-21 on 840514-0710 No noncompliance identified Major areas inspected licensee action on 10CFR50 55(e) item re butt splices in electrical conductors CHRISTNOT,E F , MENDEZ,R , WILLIAMS C L Region 3, Office of Director 84/07/23 6pp 25994 167 24X Fiche 50-454,84/07/23, 8408090212

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25855 047 24X Fiche 50-000,84/07/27,8407250229

8407310032 Board Notification 84-135 forwards SALP Repts 50-454/84-22 & 50-455/84-15 for Jan 1983 - Apr 1984 Any util comments on rept will be forwarded for review NOVAK,T M Assistant Director for Licensing 84/07/27 SMITH,I W , CALLIHAN,D Atomic Safety and Licensing Board Panel ROSENTHAL,A S Atomic Safety and Licensing Appeal Panel 2pp 25926 334 24X Fiche 50-454,84/07/27,8407310032

8408150386 Forwards IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 84/07/27 REED,C Commonwealth Edison Co 2pp 26077 357 24X Fiche 50-454,84/07/27, 8408150786

--8408150394 IE Insp Repts 50-454/84-46 & 50-455/84-31 on 840711-13 No noncompliance or deviations identified Major areas inspected selected open & improvement items identified during emergency preparedness implementation appraisal PLOSKI,T J , CHRISTOFFER,G SMITH,M J Region 3, Office of Director 84/07/27 5pp 26077 359 24X Fiche 50-454,84/07/27, 8408150386

8408070213 Forwards IE Insp Repts 50-454/84-32 & 50-455/84-25 on 840426-0717 & notice of violation STREETER,J F Region 3, Office of Director 84/07/30 REED,C Commonwealth Edison Co 2pp 25948 337 24X Fiche 50-454,84/07/30, 8408070213

--8408070216 Notice of violation from insp on 840426-0717 STREETER,J F Region 3, Office of Director 84/07/30 3pp 25948 339 24X Fiche 50-454,84/07/30,8408070213

--8408070221 IE Insp Repts 50-454/84-32 & 50-455/84-25 on 840426-0717 Noncompliance noted Failure to document nonconforming conditions,failure to control nonconforming items & failure to take effective corrertive actions re weld problems HAYES,D W , CONNAUGHTON,K , STREETER,J F Region 3, Office of Director 84/07/30 11pp 25948 342 24X Fiche 50-454,84/07/30, 8408070213

8408070204 Ack receipt of 810712 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/84-23 & 50-455/84-16 SPESSARD,R L Region 3, Office of Director 84/08/01 REED,C Commonwealth Edison Co 2pp 25949 262 24X Fiche 50-454,84/08/01, 8408070204

--8408070212 Responds to NRC 840612 ltr re violations noted in IE Insp Repts 50-454/84-23 & 50 455/84-16 Corrective actions &0 equipment installation repts w/o ref to rev researched Rev dates determined & attached to repts FARRAR,D L Commonwealth Edison Co 84/07/12 KEPPLER,J G Region 3, Office of Director 4pp 25949 264 24X Fiche 50-454,84/08/01,8408070204

8408090528 Notification of 840814 public meeting w/util in Bethesda,MD to discuss util response to integrated design insp rept OLSHAN,L N Licensing Branch 1 84/08/02 YOUNGBLOOD,B J Licensing Branch 1 4pp 25983 336 24X Fiche 50-454,84/08/02, 8408090528

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr KEPPLER,J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26069 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408130103 Ack receipt of 840803 ltr informing NRC of steps taken to correct open items noted in IE Insp Repts 50-454/83-14, 50-455/83-12,50-454/83-46 & 50-455/83-34 PAPERIELLO,C J Region 3, Office of Director 84/08/06 REED,C Commonwealth Edison Co 1p 26010 042 24X Fiche 50-454,84/08/06, 8408130103

--8408130108 Responds to NRC 840426 ltr re open items noted in IE Insp Repts 50-454/83-14,50-455/83-12,50-454/83-46 & 50-455/83-34 Revised page to Teledyne analytical procedures manual encl WEAVER,K T Commonwealth Edison Co 84/08/03 KEPPLER,J G Region 3, Office of Director 4pp 26010 043 24X Fiche 50-454,84/08/06,8408130103

8408230245 Forwards IE Insp Repts 50-454/84-38 & 50-455/84-33 on 840605-0713 No noncompliance noted SPESSARD,R L Region 3, Office of Director 84/08/06 REED,C Commonwealth Edison Co 2pp 26213 273 24X Fiche 50-454,84/08/06, 8408230245

--8408230252 IE Insp Repts 50-454/84-38 & 50-455/84-33 on 840605-0713 No noncompliance or deviations noted Major areas inspected action on previous insp findings,preoperational test procedures & results & surveillance tracking RING,M , DUNLOP,A , WILLIAMS,D Region 3, Office of Director 84/07/28 9pp 26213 275 24X Fiche 50-454,84/08/06,8408230245

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 110 24X Fiche 50-000,84/08/08,8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn,IL to discuss regulatory improvement program NORELIUS,C E Region 3, Office of Director 84/08/08 REED,C Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000,84/08/08, 8408140344

8408150098 SupplS 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays ALEXANDER,G L Commonwealth Edison Co 84/08/08 KEPPLER,J G Region 3, Office of Director 3pp 26067 053 24X Fiche 50-000,84/08/08,8408150098

8408200331 SupplS response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays ALEXANDER,G L Commonwealth Edison Co 84/08/08 KEPPLER,J G Region 3, Office of Director 3pp 26132 318 24X Fiche 50-000,84/08/08,8408200331

8408140229 Ack receipt of 840723 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-454/84-27 & 50-455/84-19 SPESSARD,R L Region 3, Office of Director 84/08/09 REED,C Commonwealth Edison Co 1p 26055 310 24X Fiche 50-454,84/08/09, 8408140229

--8408140241 SupplS response to NRC 840606 ltr re noncompliance noted in IE Insp Repts 50-454/84-27 & 50-455/84-19 Changes to Pages 5 & 6 of 840710 ltr re deficient hangers listed FARRAR,D L Commonwealth Edison Co 84/07/23 KEPPLER,J G Region 3, Office of Director 2pp 26055 311 24X Fiche 50-454,84/08/09,8408140229

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408270245 Forwards Insp Repts 50-454/84-53 & 50-455/84-36 on 840724-26 No noncompliance noted
SPESSARD,R L Region 3, Office of Director 84/08/10 REED,C
Commonwealth Edison Co 2pp 26256 101 24X Fiche 50-454,84/08/10, 8408270245

--8408270277 Insp Repts 50-454/84-53 & 50-455/84-36 on 840724-26 No noncompliance noted Major areas inspected licensee action on previously identified item, IE bulletins & 10CFR50 55(e) items
MENDEZ,R , CHRISTNOT,E , BUTLER,D Region 3, Office of Director
84/08/09 5pp 26259 103 24X Fiche 50-454,84/08/10,8408270245

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408220079 Documents schedule for submitting inservice insp (ISI) programs Commitment will be incorporated into FSAR in next amend ISI program will be submitted within 6 months after issuance of OLs
TRAMM,T R Commonwealth Edison Co 84/08/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 26193 251 24X
Fiche 50-000,84/08/13,8408220079

8408240196 Notifies of 840915 potential date for first use of respiratory protective equipment for fuel load Program complete & ready for insp
SWARTZ,E D Commonwealth Edison Co 84/08/14 KEPPLER,J G Region 3, Office of Director 1p 26228 104 24X Fiche 50-454,84/08/14, 8408240196

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408280443 Forwards 840718 Ofc of Investigation (OI) Rept 3-83-006, transmitted for placement in PDR OI reviewed document & made deletions to protect confidentiality & privacy Related correspondence
LEWIS,S H Office of the Executive Legal Director DSB 337
84/08/16 CLEMENTS,W L Docketing & Services Branch 138pp
26280 347 24X Fiche 50-454,84/08/16,8408280443

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408230247 Board Notification 84-140 forwards NRC 840801 ack of response to Insp Repts 50-454/84-23 & 50-455/84-16 & util 840712 response to insp repts
NOVAK,T M Assistant Director for Licensing 84/08/22 SMITH,I W ,
CALLIHAN,D , COLE,R F Atomic Safety and Licensing Board Panel
3pp 26241 307 24X Fiche 50-454,84/08/22,8408230247

8408280274 Submits clarifying info to 840703 ltr re results of QC inspector reinsp program, per Insp Repts 50-454/82-05 & 50-455/82-04 Reinsps of equipment setting & equipment mod clarified
DELOEORGE,L O Commonwealth Edison Co 84/08/22 KEPPLR,J G
Region 3, Office of Director 2pp 26274 325 24X
Fiche 50-454,84/08/22,8408280274

8408300155 Forwards Attachments 1,2,3,4 & 6 omitted from Board Notification 84-140
* NRC - No Detailed Affiliation Given 81/08/22 NRC - No Detailed Affiliation Given 1p 26304 082 24X
Fiche 50-454,84/08/22,8408300155

S Reportable occurrences (LERs) & related correspondence

8407310030 Board Notification 84-134 Forwards JF Streeter 840711 memo to DG Eisenhut re steam generator snubber testing failures Insp repts documenting results of testing & applicant reevaluation efforts will be forwarded to Board
NOVAK,T M Assistant Director for Licensing 84/07/27 SMITH,I W ,
CALLIHAN,D , COLE,R F Atomic Safety and Licensing Board Panel
2pp 25936 033 24X Fiche 50-000,84/07/27,8407310030

--8408060344 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE insp repts
STREETER,J F Region 3 Office of Director 84/07/11
EISENHUT,D G Division of Licensing 1p 25936 035 24X
Fiche 50-000,84/07/27,8407310030

8408130231 Interim Deficiency Repts 84-05 & 84-11 re unsatisfactory operation during qualification testing of steam generator snubbers supplied by Boeing Co Initially reported on 840628 Next rept expected by 840901
SWARTZ,E D Commonwealth Edison Co 84/07/31 KEPPLER,J G Region 3, Office of Director 4pp 26008 194 24X Fiche 50-000,84/07/31, 8408130231

T Hearing transcripts on non-antitrust matters

8408020023 Transcript of 840727 hearing in Rockford, IL Vol II Pp 9,401-9,438 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/07/27 280pp
25880 305 24X Fiche 50-454,84/07/27,8408020023

8408020135 Transcript of 840727 hearing in Rockford, IL Vol I Pp 9,226-9,400 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/07/27 249pp
25891 034 24X Fiche 50-454,84/07/27,8408020135

8408010249 Forwards testimony filed during 840724 hearings in Rockford, IL W/o encls Related correspondence
GAYLEY,J Isham, Lincoln & Beale DSB 660 84/07/30 Docketing & Services Branch 1p 25855 340 24X Fiche 50-454,84/07/30, 8408010249

8408060133 Transcript of 840730 hearing in Rockford, IL Pp 9,439-9,674 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/07/30 84pp
25928 140 24X Fiche 50-454,84/07/30,8408060133

8408060198 Transcript of 840731 hearing in Rockford, IL Pp 9,675-9,915
* Atomic Safety and Licensing Board Panel 84/07/31 242pp
25923 059 24X Fiche 50-454 84/07/31,8408060198

8408080043 Transcript of 840801 hearing in Rockford, IL Pp 9,916-10,145 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/08/01 254pp
25962 154 24X Fiche 50-454,84/08/01,8408080043

8408080022 Transcript of 840802 hearing in Rockford, IL
Pp 10,146-10,350
* Atomic Safety and Licensing Board Panel 84/08/02 360pp
25968 066 24X Fiche 50-454,84/08/02,8408080022

8408100030 Forwards transcript of KD Ward 840621 deposition in Glen Ellyn, IL Related correspondence
RILEY,A Taylor Associates DSB 890 84/08/07 PLEASANT,E
Docketing & Services Branch 1p 25997 086 24X
Fiche 50-454,84/08/07,8408100030

--8408100040 Transcript of KD Ward 840621 deposition in Glen Ellyn, IL Related correspondence
* Atomic Safety and Licensing Board Panel WARD,K D
Commonwealth Edison Co 84/06/21 175pp 25997 087 24X
Fiche 50-454,84/08/07,8408100030

8408150119 Forwards summary of testimony & testimony of NRC re equipment by Sys Control Corp, to be presented on 840820 Related correspondence
WILCOVE,M N Hearing Branch 2 DSB 046 84/08/13 SMITH,I W ,
CALLIHAN,A D , COLE,R F Atomic Safety and Licensing Board Panel
2pp 26066 322 24X Fiche 50-454,84/08/13,8408150119

--8408150127 Summary of testimony of NRC staff re equipment supplied to facility by Sys Control Corp Testimony discusses info acquired since Aug 1983 re corrective actions & steps taken to establish adequacy Related correspondence
* Office of the Executive Legal Director 84/08/13 2pp
26066 324 24X Fiche 50-451 84/08/13,8408150119

--8408150132 Testimony of NRC re equipment supplied to facility by Sys Control Corp Related correspondence
* Office of the Executive Legal Director 84/08/13 22pp
26066 326 24X Fiche 50-454,84/08/13,8408150119

8408170319 Motion for leave to file testimony of WH Bleuel on Contention 1 re reinsp program Related correspondence
CASSEL,D W DeKalb Area Alliance for Responsible Energy DSB 085
84/08/13 Atomic Safety and Licensing Board Panel 4pp
26114 317 24X Fiche 50-454,84/08/13,8408170319

--8408170321 Summary of testimony & testimony of WH Bleuel on Contention 1 re reinsp program Resume encl Related correspondence
BLEUEL,W H Affiliation Not Assigned 84/08/13 47pp
26114 321 24X Fiche 50-454,84/08/13,8408170319

--8408170326 Summary of testimony & testimony of EP Erickson on Contention 1 re reinsp program-inspector qualification & work quality Resume & Certificate of Svc encl Related correspondence
ERICKSEN,E P Temple Univ , Philadelphia, PA ERICKSEN,E P
Businessmen for the Public Interest 84/08/13 33pp 26115 007
24X Fiche 50-454,84/08/13,8408170319

8408170298 Forwards corrected Pages 6,11 & 17 to EP Erickson testimony re reinsp program Related correspondence
JUDSON,V A Businessmen for the Public Interest DSB 090
84/08/14 SMITH,J W , COLE,R F , CALLIHAN,A D Atomic Safety and Licensing Board Panel 4pp 26115 124 24X Fiche 50-454,84/08/14, 8408170298

8408170307 Summary of testimony & testimony of DS Kochhar on Contention 1 re reinsp program Certificate of Svc encl Related correspondence
KOCHHAR,D S Michigan, Univ of, Ann Arbor, MI DSB 091 84/08/14
24pp 26115 040 24X Fiche 50-454,84/08/14,8408170307

8408170296 Direct testimony of CC Stokes re engineering evaluations performed & use of engineering judgement by Sargent & Lundy Suggests need for independent engineering analysis of safety significance of reinsp program Related correspondence
STOKES,C C Affiliation Not Assigned DSB 084 84/08/16 38pp
26115 073 24X Fiche 50-454,84/08/16,8408170296

8408170380 Summary of testimony & direct testimony of CC Stokes on reinsp program Related correspondence
STOKES,C C , STOKES,C C Businessmen for the Public Interest DSB 100 84/08/17 98pp 26128 260 24X Fiche 50-454,84/08/17, 8408170380

8408200446 Forwards transcript of CC Stokes 840817 deposition Related correspondence
WESTHALL M Ann Riley & Associates DSB 177 84/08/20
PLEASANT,E Docketing & Services Branch 1p 26136 114 24X Fiche 50-454,84/08/20,8108200446

--8408200458 Transcript of CC Stokes 840817 deposition in Chicago,IL Pp 1-173 Vol II Related correspondence
STOKES,C C Commonwealth Edison Co 84/08/17 175pp 26136 115
24X Fiche 50-454,84/08/20,8408200446

8408270023 Transcript of 840820 hearing in Rockford,IL Pp 10,351-10,458
* Atomic Safety and Licensing Board Panel 84/08/20 108pp
26247 195 24X Fiche 50-454,84/08/20,8408270023

8408270025 Transcript of hearing in Rockford,IL Pp 10,459-10,682
* Atomic Safety and Licensing Board Panel 84/08/21 266pp
26246 093 24X Fiche 50-454,84/08/21,8408270025

8408280228 Transcript of 840822 hearing in Rockford,IL Pp 10,683-10,931 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/08/22 396pp
26263 001 24X Fiche 50-454,84/08/22,8408280228

8408280153 Transcript of 840823 hearing in Rockford,IL
Pp 10,932-11,139
* Atomic Safety and Licensing Board Panel 84/08/23 263pp
26270 001 24X Fiche 50-454,84/08/23,8408280153

8408280138 Transcript of 840824 hearing in Rockford,IL Pp 11,140-11,179 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/08/24 124pp
26259 088 24X Fiche 50-454,84/08/24,8408280138

8408310192 Rebuttal Testimony of B Erler re Stokes allegations concerning evaluations of discrepancies in calculated actual stress performed by Sargent & Lundy Related correspondence
ERLER B Sargent & Lundy, Inc DSB 189 84/08/30 10pp
26319 043 24X Fiche 50-454,84/08/30,8408310192

--8408310194 Summary of rebuttal testimony & testimony of ML Somsag, EB Branch,D DeMoss,MR Frankel,BF Maurer & JK Buchanan re plant QC inspector reinsp program & C Stokes allegations re welds Related correspondence
BRANCH,E B , DEMOSS,D M Sargent & Lundy, Inc FRANKEL,M R City College of New York 84/08/30 83pp 26319 053 24X
Fiche 50-454,84/08/30,8408310192

--8408310199 Rebuttal testimony of RW Hooks re validity of info in Attachment 7 to Stokes testimony concerning design assumption for plant Stokes info inapplicable to plant Related correspondence
HOOKS,R W Sargent & Lundy, Inc 84/08/30 5pp 26319 136 24X
Fiche 50-454,84/08/30,8408310192

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators,Senior Operators & Senior Operators (Limited)," in response to NUREG-0737,Item I A 3 1
MARSHALL,J G Commonwealth Edison Co 84/08/07 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 26051 240
24X Fiche 50-000,84/08/07,8408140372

--8408140389 "Requalification Program for Licensed Operators,Senior Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X
Fiche 50-000,84/08/07,8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners.
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1

A Application/construction stage documents & correspondence

8408010185 Forwards request for addl info for review of vol reduction sys (Outstanding Item 15 of Byron SER) Response requested within 30 days of ltr date
OLSHAN,L N Licensing Branch 1 84/07/19 FARRAR,D L
Commonwealth Edison Co 10pp 25873 292 24X Fiche 50-000, 84/07/19,8408010185

8408140376 Informs that Archaeological Site 11Ka179 retains integrity & expected to yield evidence sufficient for inclusion in Natl Register,in response to 840713 inquiry Recommends delay until revised form re std of significance received
SCULLE,K A Illinois, State of 84/07/23 YOUNGBLOOD,B J
Licensing Branch 1 1p 26042 316 24X Fiche 50-456,84/07/23, 8408140376

8408080539 Forwards review of proposed const assessment plan Plan acceptable,subj to incorporation of NRC comments Suggested protocol for communication between Independent Expert Overview Group & util contractors encl
KEPPLER,J G Region 3, Office of Director 84/07/27 O'CONNOR,J J
Commonwealth Edison Co 5pp 25979 316 24X Fiche 50-456, 84/07/27,8408080539

8408140380 Forwards responses to FSAR Questions 10 57,10 63,10 64, 10 65 & 10 66 Revised response to Question 10 57 based on revised safe shutdown analysis Info will be included in next FSAR amend
SWARTZ,E D Commonwealth Edison Co 84/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 32pp 26041 132 24X
Fiche 50-000,84/08/02,8408140380

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR,D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards,Director 1p 26092 184 24X
Fiche 50-000,84/08/06,8408160345

8408140386 Advises of decision to organize & implement project startup organization Transfer of preoperational testing responsibilities will be implemented gradually FSAR Chapters 13 & 14 will be amended
SWARTZ,E D Commonwealth Edison Co 84/08/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 20pp 26053 328 24X
Fiche 50-456,84/08/07,8408140386

8408140335 Forwards revised Natl Register nomination for Archaeological Site 11KA179 Cause for designating 11KA179 based on revised nomination Nomination satisfies Natl Register evaluation documentation W/o encl
SCULLE,K A Illinois, State of 84/08/08 YOUNGBLOOD,B J
Licensing Branch 1 1p 26042 355 24X Fiche 50-456,84/08/08,
8408140335

8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in NUREG-0737, Item II B 3 High radiation sampling sys described in FSAR will be operational on each unit prior to initial criticality
TRAMM,T R Commonwealth Edison Co 84/08/13 DENTON,H R Office of Nuclear Reactor Regulation Director 1p 26193 139 24X
Fiche 50-000,84/08/13,8408220239

8408220306 Forwards proprietary & nonproprietary responses to NRC ltr re improved thermal design procedure Response should close Byron SER Outstanding Item 8 Info deleted Proprietary response withheld (ref 10CFR2 790)
TRAMM,T R Commonwealth Edison Co 84/08/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 20pp 26193 053 24X
Fiche 50-000,84/08/13,8408220306

--8408220321 Requests withholding proprietary response to NRC questions on improved thermal design procedures & rod bow,per 10CFR2 790 Affidavit AW-76-60 encl
WIESEMANN,R A Westinghouse Electric Corp 83/12/27 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G
Licensing Branch 4 8pp 26193 073 24X Fiche 50-000,84/08/13,
8408220306

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408270118 Submits addl info re basis for proposed Tech Spec requirements on availability of Diesel Generator 2A during time Unit 2 under const
TRAMM,T R Commonwealth Edison Co 84/08/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26247 338 24X
Fiche 50-000,84/08/21,8408270118

8408300230 Requests determination of eligibility of Site 11Ka179 for inclusion in Natl Register of Historic Places Detailed info provided on encl Natl Register of Historic Places inventory nomination forms W/o encl
YOUNGBLOOD,B J Licensing Branch 1 84/08/22 ROGERS,J Interior, Dept of, National Park Service 2pp 26330 360 24X
Fiche 50-456,84/08/22,8408300230

F NRC Draft/Final Environmental Statements, supplts & correspondence

8408220151 Comments on FES for facilities Spoil islands in cooling pond should be revegetated if agreement between util & Field Museum of Natural History not renewed
FRANZ,W D Environmental Protection Agency 84/08/14
YOUNGBLOOD,B J Licensing Branch 1 2pp 26188 074 24X
Fiche 50-456,84/08/14,8408220151

E NRC Safety Evaluation Report (SER), supplts & correspondence

8408140371 Forwards compliance review against GDC 51 for reactor containment pressure boundary components Review for Braidwood Station should resolve SER Outstanding Item 4
SWARTZ,E D Commonwealth Edison Co 84/08/09 DENTON,H R Office of Nuclear Reactor Regulation, Director 17pp 26042 299 24X
Fiche 50-000,84/08/09,8408140371

8408270204 Forwards addl info re monitoring of leakage from sys outside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close SER Confirmatory Issue 28(a)
TRAMM,T R Commonwealth Edison Co 84/08/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 26245 103 24X
Fiche 50-000,84/08/11,8408270204

8408270373 Forwards addl info re instrumentation being installed for detection of inadequate core cooling Info should close SER Outstanding Item 9 w o any license conditions
TRAMM,T R Commonwealth Edison Co 84/08/20 DENTON,H R Office of Nuclear Reactor Regulation Director 4pp 26240 254 24X
Fiche 50-000,84/08/20,8408270373

8408310226 Forwards addl info re pool reduction sys in response to 840710 request NRC review of info necessary to close SER Outstanding Item 15
TRAMM,T R Commonwealth Edison Co 84/08/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26322 138 24X
Fiche 50-000,84/08/24,8408310226

F Security, medical, emergency & fire protection plans

8406140101 Forwards IE Insp Repts 50-456/84-08 & 50-457/84-08 on 840401-30 & notice of violation
WARNICK,R F Region 3, Office of Director 84/05/22 REED,C
Commonwealth Edison Co 3pp 24928 284 24X Fiche 50-456,84/05/22,
8406140101

--8406140104 IE Insp Rpts 50-456/84-08 & 50-457/84-08 on 840401-30
Noncompliance noted failure to perform required fit-up insp & take corrective action re welding insp
FORNEY,W Region 3, Office of Director 84/05/22 15pp
24928 289 24X Fiche 50-456,84/05/22,8406140101

8408060210 Notification of 840731 meeting w/util in Silver Spring,MD to discuss safeguards info & security plan
STEVENS,J A Licensing Branch 1 84/07/26 YOUNGBLOOD,B J
Licensing Branch 1 4pp 25936 183 24X Fiche 50-456,84/07/26,
8408060210

8408220243 Summary of 840731 meeting w/util in Silver Spring,MD re security plan implementation
* NRC - No Detailed Affiliation Given 84/07/31 NRC - No
Detailed Affiliation Given 2pp 26203 311 24X
Fiche 50-000,84/07/31,8408220243

8408080198 Forwards Amend 4 to "Fire Protection Rept," including detailed comparison of design, const, testing & maint practices against NFPA stds
SWARTZ,E D Commonwealth Edison Co 84/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 25985 001 24X
Fiche 50-000,84/08/02,8408080198

--8408080205 Amend 4 to "Fire Protection Rept "
* Commonwealth Edison Co 84/07/31 129pp 25985 004 24X
Fiche 50-000,84/08/02,8408080198

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO,C J Region 3, Office of Director 84/08/07 REED,C
Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000,84/08/07,
8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR,D L Commonwealth Edison Co 84/07/05 PAPERIELLO,C J
Region 3, Office of Director 8pp 26010 131 24X
Fiche 50-000,84/08/07,8408130401

Q Adjudicatory correspondence

8408010200 Responds to request for listing of all attys not presently employed by NRC but who once worked for Commission & had responsibilites re facilities J Gallo was chief hearing counsel during CP process Related correspondence
KARMAN,M Hearing Branch 1 DSB 689 84/07/25 BOCK,C A
Affiliation Not Assigned 1p 25854 352 24X Fiche 50-456,
84/07/25,8408010200

8408140028 Motion for leave to file response to Intervenor B Neiner Farms,Inc 840705 status rept re Contention 4 concerning transport of hazardous matl near facility Contention admissibility still pending before ASLB
COPELAND,V G Commonwealth Edison Co COPELAND,V G Isham, Lincoln & Beale DSB 958 84/08/09 Atomic Safety and Licensing Board Panel 1p 26044 194 24X Fiche 50-456,84/08/09,8408140028

--8408140034 Response to Neinel Farms 840705 status rept re Contention 4 concerning transport of hazardous matl near facility Intervenor offers no new substantial info Contention 4 should be dismissed
COPELAND,V G Commonwealth Edison Co COPELAND,V G Isham, Lincoln & Beale 84/08/09 Atomic Safety and Licensing Board Panel 6pp 26044 195 24X Fiche 50-456,84/08/09,8408140028

--8408140098 Affidavit of D Ferro re possible future reactivation of Joliet Army Ammunitions Plant Notice of appearance & Certificate of Svc encl
DENIS D Commonwealth Edison Co 84/08/08 6pp 26044 201 24X Fiche 50-456 84/08/09 8408140098

K Utility Final Safety Analysis Report (FSAR) & amends

8408300053 Forwards affidavit attesting to distribution of FSAR Amends 44 & 45
TRAMM,T R Commonwealth Edison Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26307 236 24X Fiche 50-000,84/08/16,8408300053

Q Inspection reports, IE Bulletins & correspondence

8408130415 Forwards, for review, Rev 1 to "Evaluation of Energy Absorbing Matl for Pipe Whip Restraints," in response to IE Insp Repts 50-454/83-06 & 50-455/83-05
SWARTZ,E D Commonwealth Edison Co 84/04/13 KEPPLER,J G Region 3, Office of Director 2pp 26011 038 24X Fiche 50-000,84/04/13, 8408130415

--8408130420 Rev 1 to "Evaluation of Energy Absorbing Matl for Pipe Whip Restraints"
KAO,G C , YANG,M S , SU,T Y Sargent & Lundy, Inc SAD-431 R01 84/04/30 47pp 26011 040 24X Fiche 50-000,84/04/13,8408130415

8406140101 Forwards IE Insp Repts 50-456/84-08 & 50-457/84-08 on 840401-30 & notice of violation
WARNICK,R F Region 3, Office of Director 84/05/22 REED,C Commonwealth Edison Co 3pp 24928 284 24X Fiche 50-456,84/05/22, 8406140101

--8406140102 Notice of violation from insp on 840401-30
WARNICK,R F Region 3, Office of Director 84/05/22 2pp 24928 287 24X Fiche 50-456,84/05/22,8406140101

--8406140104 IE Insp Repts 50-456/84-08 & 50-457/84-08 on 840401-30
Noncompliance noted failure to perform required fit-up insp & take corrective action re welding insp
FORNEY,W Region 3, Office of Director 84/05/22 15pp 24928 289 24X Fiche 50-456,84/05/22,8406140101

8408070338 Forwards IE Insp Repts 50-456/84-14 & 50-457/84-14 on 840612,15,20 & 21 No noncompliance noted
LITTLE,W S Region 3, Office of Director 84/07/18 REED,C Commonwealth Edison Co 2pp 25953 093 24X Fiche 50-456,84/07/18, 8408070338

--8408070340 IE Insp Repts 50-456/84-14 & 50-457/84-14 on 840612,15,20 & 21 No noncompliance or deviations noted Major areas inspected allegations re deficiencies in design & installation of HVAC sys
KEY,W J , DANIELSON,D H Region 3, Office of Director 84/07/17 14pp 25953 095 24X Fiche 50-456,84/07/18,8408070338

8408080188 Forwards IE Insp Repts 50-454/84-25,50-455/84-18, 50-456/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted
SPESSARD,R L Region 3, Office of Director 84/07/18 REED,C Commonwealth Edison Co 2pp 25974 327 24X Fiche 50-000,84/07/18, 8408080188

--8408080195 IE Insp Repts 50-454/84-25,50-455/84-18,50-456/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted Major areas inspected design calculations re primary shield wall & reactor pressure shield wall
MUFFETT,J W , KAUFMAN,P D , NORTON,J F Region 3, Office of Director 84/07/18 4pp 25974 329 24X Fiche 50-000,84/07/18, 8408080188

8408060302 Forwards IE Insp Repts 50-456/84-07 & 50-457/84-07 on 840326-0531 & notice of violation
WALKER,R D Region 3, Office of Director 84/07/20 REED,C Commonwealth Edison Co 2pp 25936 056 24X Fiche 50-456,84/07/20, 8408060302

--8408060303 Notice of violation from insp on 840326-0531
WALKER,R D Region 3, Office of Director 84/07/20 2pp 25936 058 24X Fiche 50-456,84/07/20,8408060302

--8408060309 IE Insp Repts 50-456/84-07 & 50-457/84-07 on 840326-0531
Noncompliances noted failure to establish & implement personnel training, failure to provide adequate training & failure to identify & correct nonconforming conditions
SCHULZ,R , MALLOY,J , KROPP,W Region 3, Office of Director 84/07/20 9pp 25936 060 24X Fiche 50-456,84/07/20,8408060302

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408090049 Informs that 840730 const appraisal team insp postponed NRC will notify licensee of new insp date
NORELIUS,C Region 3, Office of Director 84/07/27 REED,C Commonwealth Edison Co 1p 25992 332 24X Fiche 50-456,84/07/27, 8408090049

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408100112 Ack receipt of 840723 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-456/83-09 & 50-457/83-09
WARNICK,R F Region 3, Office of Director 84/08/03 REED,C Commonwealth Edison Co 1p 25991 030 24X Fiche 50-456,84/08/03, 8408100112

--8408100119 Responds to NRC 840507 ltr re nonconformance noted in IE Insp Repts 50-456/83-09 & 50-457/83-09 Corrective actions nonconformance rept will be written, requesting engineering disposition of lack of fit-up insp of duct hanger welds
SWARTZ,E D Commonwealth Edison Co 84/07/23 KEPPLER,J G Region 3, Office of Director 2pp 25991.031 24X Fiche 50-456,84/08/03,8408100112

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408290549 Forwards Insp Repts 50-456/84-13 & 50-457/84-13 on 840605-0706 & notice of violation
WARNICK,R F Region 3, Office of Director 84/08/07 REED,C Commonwealth Edison Co 2pp 26296 156 24X Fiche 50-456,84/08/07, 8408290549

--8408290553 Notice of violation from insp on 840605-0706
WARNICK,R F Region 3, Office of Director 84/08/07 2pp 26296 158 24X Fiche 50-456,84/08/07,8408290549

--8408290561 Insp Repts 50-456/84-13 & 50-457/84-13 on 840605-0706 Noncompliance noted procurement documents did not specify that provisions of Part 21 apply for heat shrink tubing & failure to control weld rod for cable pan welding
FORNEY,W L Region 3, Office of Director 84/08/06 28pp 26296 160 24X Fiche 50-456,84/08/07,8408290549

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn,IL to discuss regulatory improvement program
NORELIUS,C E Region 3, Office of Director 84/08/08 REED,C Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000,84/08/08, 8408140344

8408150098 Supplx 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays Exemptions requested for listed relays
ALEXANDER,G L Commonwealth Edison Co 84/08/08 KEPPLER,J G Region 3, Office of Director 3pp 26067 053 24X Fiche,50-000,84/08/08,8408150098

8408200331 Supplx response to IE Bulletin 84-02 re failure of GE Type HFA relays.Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER,G L Commonwealth Edison Co 84/08/08 KEPPLER,J G, Region 3, Office of Director 3pp 26132 318 24X Fiche 50-000,84/08/08,8408200331

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408220079 Documents schedule for submitting inservice insp (ISI) programs Commitment will be incorporated into FSAR in next amend ISI program will be submitted within 6 months after issuance of OLs
TRAMM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26193 231 24X
Fiche 50-000, 84/08/13, 8408220079

8408300118 Forwards Insp Repts 50-456/84-19 & 50-457/84-18 on 840711-12 No noncompliance noted
SPESSARD, R L Region 3, Office of Director 84/08/14 REED, C
Commonwealth Edison Co 2pp 26307 215 24X Fiche 50-456, 84/08/14, 8408300118

--8408300121 Insp Repts 50-456/84-19 & 50-457/84-18 on 840711-12 No noncompliance or deviations noted Major areas inspected licensee action on previously identified items
GAUTAM, A S , TANI, K , HAWKINS, F Region 3, Office of Director
84/08/14 8pp 26307 217 24X Fiche 50-456, 84/08/14, 8408300118

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408210342 Ack receipt of 840731 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/84-09 & 50-457/84-09
WARNICK, R F Region 3, Office of Director 84/08/15 REED, C
Commonwealth Edison Co 2pp 26180 189 24X Fiche 50-456, 84/08/15, 8408210342

--8408210358 Responds to NRC 840702 ltr re violations noted in IE Insp Repts 50-456/84-09 & 50-457/84-09 Corrective actions util & Sargent & Lundy developing qualitative & quantitative clearance info to be included in contractor spec
FARRAR, D L Commonwealth Edison Co 84/07/31 KEPPLER, J G
Region 3, Office of Director 6pp 26180 191 24X
Fiche 50-456, 84/08/15, 8408210342

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8407100002 Final Deficiency Rept 84-07 re concrete expansion anchor installation Initially reported on 840511 Deficiencies will be reworked per Sargent & Lundy requirements & contractors will contact company for installation instructions
SWARTZ, E D Commonwealth Edison Co 84/06/11 KEPPLER, J G Region 3, Office of Director 2pp 25512 146 24X Fiche 50-456, 84/06/11, 8407100002

8407310030 Board Notification 84-134 forwards JF Streeter 840711 memo to DG Eisenhut re steam generator snubber testing failures Insp repts documenting results of testing & applicant reevaluation efforts will be forwarded to Board
NOVAK, T M Assistant Director for Licensing 84/07/27 SMITH, I W ,
CALLIHAN, D , COLE, R F Atomic Safety and Licensing Board Panel
2pp 25936 033 24X Fiche 50-000, 84/07/27, 8407310030

--8408060344 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE insp repts
STREETER, J F Region 3, Office of Director 84/07/11
EISENHUT, D G Division of Licensing 1p 25936 035 24X
Fiche 50-000, 84/07/27, 8407310030

8408130231 Interim Deficiency Repts 84-05 & 84-11 re unsatisfactory operation during qualification testing of steam generator snubbers supplied by Boeing Co Initially reported on 840628 Next rept expected by 840901
SWARTZ, E D Commonwealth Edison Co 84/07/31 KEPPLER, J G Region 3, Office of Director 4pp 26008 194 24X Fiche 50-000, 84/07/31, 8408130231

8408300044 Interim Deficiency Rept 84-04 re out of tolerance radiographic film densities Initially reported on 840306 Pipe welds w/radiographic film records exceeding density requirements are being reradiographed & repaired
SWARTZ, E D Commonwealth Edison Co 84/08/16 KEPPLER, J G Region 3, Office of Director 3pp 26307 069 24X Fiche 50-456, 84/08/16, 8408300044

8408300214 Final rept of Deficiency 84-06, NCR 604 re leak in recycle holdup tanks OABO1TA & OABO1TB Initially reported on 840413 Rev of tank design procedures to utilize butt weld const for tank bottom underway
SWARTZ, E D Commonwealth Edison Co 84/08/16 KEPPLER, J G Region 3, Office of Director 2pp 26307 052 24X Fiche 50-456, 84/08/16, 8408300214

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26051 240
24X Fiche 50-000, 84/08/07, 8408140372

--8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited) "
* Commonwealth Edison Co 84/07/19 10pp 26051 242 24X
Fiche 50-000, 84/08/07, 8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

A Application/construction stage documents & correspondence

8408010185 Forwards request for addl info for review of vol reduction sys (Outstanding Item 15 of Byron SER) Response requested within 30 days of ltr date
OLSHAN, L N Licensing Branch 1 84/07/19 FARRAR, D L
Commonwealth Edison Co 10pp 25873 292 24X Fiche 50-000, 84/07/19, 8408010185

8408140376 Informs that Archaeological Site 11Ka179 retains integrity & expected to yield evidence sufficient for inclusion in Natl Register, in response to 840713 inquiry Recommends delay until revised form re std of significance received.
SCULLE, K. A Illinois, State of 84/07/23 YOUNGBLOOD, B J
Licensing Branch 1 1p 26042 316 24X Fiche 50-456, 84/07/23, 8408140376

8408080539 Forwards review of proposed const assessment plan Plan acceptable, subj to incorporation of NRC comments Suggested protocol for communication between Independent Expert Overview Group & util contractors encl
KEPPLER, J G Region 3, Office of Director 84/07/27 O'CONNOR, J J
Commonwealth Edison Co 5pp 25975 316 24X Fiche 50-456, 84/07/27, 8408080539

8408140380 Forwards responses to FSAR Questions 10 57, 10 63, 10.64, 10 65 & 10 66 Revised response to Question 10 57 based on revised safe shutdown analysis Info will be included in next FSAR amend
SWARTZ, E D Commonwealth Edison Co 84/08/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 26041 132 24X
Fiche 50-000, 84/08/02, 8408140380

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160345 Advises that QA program applicable to all nuclear generating stations & satisfies provisions of 10CFR71 Fee remitted per 10CFR170 31
FARRAR, D L Commonwealth Edison Co 84/08/06 Office of Nuclear Material Safety & Safeguards, Director 1p 26092 184 24X
Fiche 50-000, 84/08/06, 8408160345

8408140386 Advises of decison to organize & implement project startup organization Transfer of preoperational testing responsibilities will be implemented gradually FSAR Chapters 13 & 14 will be amended
SWARTZ, E D Commonwealth Edison Co 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 26053 328 24X
Fiche 50-456, 84/08/07, 8408140386

8408140335 Forwards revised Natl Register nomination for Archaeological Site 11KA179 Cause for designating 11KA179 based on revised nomination Nomination satisfies Natl Register evaluation documentation W/o encl
SCULLE, K A Illinois, State of 84/08/08 YOUNGBLOOD, B J Licensing Branch 1 1p 26042 353 24X Fiche 50-456, 84/08/08, 8408140335

8408220306 Forwards proprietary & nonproprietary responses to NRC ltr re improved thermal design procedure Response should close Byron SER Outstanding Item B Info deleted Proprietary response withheld (ref 10CFR2.790)
TRAMM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 26193 053 24X
Fiche 50-000, 84/08/13, 8408220306

--8408220321 Requests withholding proprietary response to NRC questions on improved thermal design procedures & rod bow, per 10CFR2 790 Affidavit AW-76-60 encl
WIESEMANN, R A Westinghouse Electric Corp 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 26193 073 24X Fiche 50-000, 84/08/13, 8408220306

8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in NUREG-0737, Item II B 3 High radiation sampling sys described in FSAR will be operational on each unit prior to initial criticality
TRAMM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26193 139 24X
Fiche, 50-000, 84/08/13, 8408220239

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408270118 Submits addl info re basis for proposed Tech Spec requirements on availability of Diesel Generator 2A during time Unit 2 under const
TRAMM, T R Commonwealth Edison Co 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26247 338 24X
Fiche 50-000, 84/08/21, 8408270118

8408300230 Requests determination of eligibility of Site 11Ka179 for inclusion in Natl Register of Historic Places Detailed info provided on encl Natl Register of Historic Places inventory nomination forms W/o encl.
YOUNGBLOOD, B J Licensing Branch 1, 84/08/22 ROGERS, J Interior, Dept of, National Park Service 2pp 26330.360 24X
Fiche 50-456, 84/08/22, 8408300230

D NRC Draft/Final Environmental Statements, suppls & correspondence

8408220151 Comments on FES for facilities Spoil islands in cooling pond should be revegetated if agreement between util & Field Museum of Natural History not renewed
FRANZ, W D. Environmental Protection Agency 84/08/14
YOUNGBLOOD, B, J Licensing Branch 1 2pp 26188 074 24X
Fiche 50-456, 84/08/14, 8408220151

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408140371 Forwards compliance review against GDC 51 for reactor containment pressure boundary components Review for Braidwood Station should resolve SER Outstanding Item 4
SWARTZ, E D Commonwealth Edison Co 84/08/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 26042 299 24X
Fiche 50-000, 84/08/09, 8408140371

8408270204 Forwards addl info re monitoring of leakage from sys outside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close SER Confirmatory Issue 28(a)
TRAMM, T R Commonwealth Edison Co 84/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 26245 103 24X
Fiche 50-000, 84/08/11, 8408270204

8408270373 Forwards addl info re instrumentation being installed for detection of inadequate core cooling Info should close SER Outstanding Item 9 w/o any license conditions.
TRAMM, T R Commonwealth Edison Co. 84/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26240 254 24X
Fiche 50-000, 84/08/20, 8408270373

8408310226 Forwards addl info re vol reduction sys, in response to 840710 request NRC review of info necessary to close SER Outstanding Item 15
TRAMM, T R Commonwealth Edison Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 26322.138 24X
Fiche 50-000, 84/08/24, 8408310226

F Security, medical, emergency & fire protection plans

8406140101 Forwards IE Insp Repts 50-456/84-08 & 50-457/84-08 on 840401-30 & notice of violation
WARNICK, R F Region 3, Office of Director 84/05/22 REED, C Commonwealth Edison Co 3pp 24928 284 24X Fiche 50-456, 84/05/22, 8406140101

--8406140104 IE Insp Repts 50-456/84-08 & 50-457/84-08 on 840401-30 Noncompliance noted failure to perform required fit-up insp & take corrective action re welding insp.
FORNEY, W Region 3, Office of Director 84/05/22 15pp 24928 289 24X Fiche 50-456, 84/05/22, 8406140101

8408060210 Notification of 840731 meeting w/util in Silver Spring, MD to discuss safeguards info & security plan
STEVENS, J A Licensing Branch 1. 84/07/26 YOUNGBLOOD, B J Licensing Branch 1 4pp. 25938.183 24X Fiche 50-456, 84/07/26, 8408060210

8408220243 Summary of 840731 meeting w/util in Silver Spring, MD re security plan implementation
* NRC - No Detailed Affiliation Given 84/07/31 NRC - No Detailed Affiliation Given. 2pp 26203 311 24X
Fiche: 50-000, 84/07/31, 8408220243

8408080198 Forwards Amend 4 to "Fire Protection Rept," including detailed comparison of design, const, testing & maint practices against NFPA stds
SWARTZ, E D Commonwealth Edison Co. 84/08/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director 3pp 25985:001. 24X
Fiche: 50-000, 84/08/02, 8408080198

--8408080205 Amend 4 to "Fire Protection Rept."
* Commonwealth Edison Co 84/07/31 125pp. 25985 004. 24X
Fiche. 50-000, 84/08/02, 8408080198

8408130401 Responds to 840705 clarification of info re util means of satisfying annual regulatory requirement to review emergency action levels w/offsite emergency support organizations Info acceptable
PAPERIELLO, C. J Region 3, Office of Director 84/08/07. REED, C Commonwealth Edison Co 1p 26010 130 24X Fiche 50-000, 84/08/07, 8408130401

--8408130413 Responds to 840604 ltr re means for satisfying requirements of 10CFR50, App E, Paragraph IV. B Proposal for satisfying requirements to review emergency action levels by offsite agencies clarified
FARRAR, D L. Commonwealth Edison Co 84/07/05 PAPERIELLO, C J Region 3, Office of Director. 8pp 26010 131 24X
Fiche 50-000, 84/08/07, 8408130401.

Q Adjudicatory correspondence

8408010200 Responds to request for listing of all attys not presently employed by NRC but who once worked for Commission & had responsibilites re facilities J Gallo was chief hearing counsel during CP process Related correspondence
KARMAN,M Hearing Branch 1 DSN 689 84/07/25 BOCK,C A Affiliation Not Assigned 1p 25854 352 24X Fiche 50-456, 84/07/25,8408010200

8408140028 Motion for leave to file response to Intervenor D Neiner Farms,Inc 840705 status rept re Contention 4 concerning transport of hazardous matl near facility Contention admissibility still pending before ASLB
COPELAND,V G Commonwealth Edison Co COPELAND,V G Isham, Lincoln & Beale DSB 958 84/08/09 Atomic Safety and Licensing Board Panel 1p 26044 194 24X Fiche 50-456,84/08/09,8408140028

--8408140034 Response to Neiner Farms 840705 status rept re Contention 4 concerning transport of hazardous matl near facility Intervenor offers no new substantial info Contention 4 should be dismissed
COPELAND,V G Commonwealth Edison Co COPELAND,V G Isham, Lincoln & Beale 84/08/09 Atomic Safety and Licensing Board Panel 6pp 26044 195 24X Fiche 50-456,84/08/09,8408140028

--8408140038 Affidavit of D Demos re possible future reactivation of Joliet Army Ammunitions Plant Notice of appearance & Certificate of Svc encl
DEMOS,D Commonwealth Edison Co 84/08/08 6pp 26044 201 24X Fiche 50-456,84/08/09,8408140028

K Utility Final Safety Analysis Report (FSAR) & amends

8408300053 Forwards affidavit attesting to distribution of FSAR Amends 44 & 45
TRAMM,T R Commonwealth Edison Co 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26307 236 24X Fiche 50-000,84/08/16,8408300053

O Inspection reports, IE Bulletins & correspondence

8408130415 Forwards, for review, Rev 1 to "Evaluation of Energy Absorbing Matl for Pipe Whip Restraints," in response to IE Insp Repts 50-454/83-06 & 50-455/83-05
SWARTZ,E D Commonwealth Edison Co 84/04/13 KEPPLER,J G Region 3, Office of Director 2pp 26011 038 24X Fiche 50-000,84/04/13, 8408130415

--8408130420 Rev 1 to "Evaluation of Energy Absorbing Matl for Pipe Whip Restraints "
RAO,G C Sargent & Lundy, Inc SAD-431 R01 84/04/30 47pp 26011 040 24X Fiche 50-000,84/04/13,8408130415

8406140101 Forwards IE Insp Repts 50-456/84-08 & 50-457/84-08 on 840401-30 & notice of violation
WARNICK,R F Region 3, Office of Director 84/05/22 REED,C Commonwealth Edison Co 3pp 24928 284 24X Fiche 50-456,84/05/22, 8406140101

--8406140102 Notice of violation from insp on 840401-30
WARNICK,R F Region 3, Office of Director 84/05/22 2pp 24928 287 24X Fiche 50-456,84/05/22,8406140101

--8406140104 IE Insp Repts 50-456/84-08 & 50-457/84-08 on 840401-30 Noncompliance noted failure to perform required fit-up insp & take corrective action re welding insp
FORNEY,W Region 3, Office of Director 84/05/22 15pp 24928 289 24X Fiche 50-456,84/05/22,8406140101

8408070338 Forwards IE Insp Repts 50-456/84-14 & 50-457/84-14 on 840612,15,20 & 21 No noncompliance noted
LITTLE,W S Region 3, Office of Director 84/07/18 REED,C Commonwealth Edison Co 2pp 25953.093 24X Fiche 50-456,84/07/18, 8408070338

--8408070340 IE Insp Repts 50-456/84-14 & 50-457/84-14 on 840612,15,20 & 21 No noncompliance or deviations noted Major areas inspected allegations re deficiencies in design & installation of HVAC sys
KEY,W J , DANIELSON,D H Region 3, Office of Director 84/07/17 14pp 25953 095 24X Fiche 50-456,84/07/18,8408070338

8408080188 Forwards IE Insp Repts 50-454/84-25, 50-455/84-18, 50-456/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted
SPESSARD,R L Region 3, Office of Director 84/07/18 REED,C Commonwealth Edison Co 2pp 25974 327 24X Fiche 50-000,84/07/18, 8408080188

--8408080195 IE Insp Repts 50-454/84-25,50-455/84-18,50 456/84-11 & 50-457/84-11 on 840425 & 0522-23 No noncompliance noted Major areas inspected design calculations re primary shield wall & reactor pressure shield wall
MUFFETT,J W , DANIELSON,D H Region 3, Office of Director 84/07/18 4pp 25974 329 24X Fiche 50-000,84/07/18,8408080188

8408060302 Forwards IE Insp Repts 50-456/84-07 & 50-457/84-07 on 840326-0531 & notice of violation
WALKER,R D Region 3, Office of Director 84/07/20 REED,C Commonwealth Edison Co 2pp 25936 056 24X Fiche 50-456,84/07/20, 8408060302

--8408060303 Notice of violation from insp on 840326-0531
WALKER,R D Region 3, Office of Director 84/07/20 2pp 25936 058 24X Fiche 50-456,84/07/20,8408060302

--8408060309 IE Insp Repts 50-456/84-07 & 50-457/84-07 on 840326-0531 Noncompliances noted failure to establish & implement personnel training,failure to provide adequate training & failure to identify & correct nonconforming conditions
SCHULZ,R , MALLOY,J , KROPP,W Region 3, Office of Director 84/07/20 9pp 25936 060 24X Fiche 50-456,84/07/20,8408060302

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408090049 Informs that 840730 const appraisal team insp postponed NRC will notify licensee of new insp date
NORELIUS,C Region 3, Office of Director 84/07/27 REED,C Commonwealth Edison Co 1p 25992 332 24X Fiche 50-456,84/07/27, 8408090049

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408100112 Ack receipt of 840723 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-456/83-09 & 50-457/83-09
WARNICK,R F Region 3, Office of Director 84/08/03 REED,C Commonwealth Edison Co 1p 25991 030 24X Fiche 50-456,84/08/03, 8408100112

--8408100119 Responds to NRC 840507 ltr re nonconformance noted in IE Insp Repts 50-456/83-09 & 50-457/83-09 Corrective actions nonconformance rept will be written,requesting engineering disposition of lack of fit-up insp of duct hanger welds
SWARTZ,E D Commonwealth Edison Co 84/07/23 KEPPLER,J G Region 3, Office of Director 2pp 25991 031 24X Fiche 50-456,84/08/03,8408100112

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche.50-000,84/08/06,8408010337

8408290549 Forwards Insp Repts 50-456/84-13 & 50-457/84-13 on 840605-0706 & notice of violation
WARNICK,R F Region 3, Office of Director 84/08/07 REED,C Commonwealth Edison Co 2pp 26296 156 24X Fiche 50-456,84/08/07, 8408290549

--8408290553 Notice of violation from insp on 840605-0706
WARNICK,R F Region 3, Office of Director 84/08/07 2pp 26296 158 24X Fiche 50-456,84/08/07,8408290549

--8408290561 Insp Repts 50-456/84-13 & 50-457/84-13 on 840605-0706 Noncompliance noted procurement documents did not specify that provisions of Part 21 apply for heat shrink tubing & failure to control weld rod for cable pan welding
FORNEY,W L Region 3, Office of Director 84/08/06 28pp 26296 160 24X Fiche 50-456,84/08/07,8408290549

DOCKETED ITEMS

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 12Opp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408140344 Confirms 840803 plans to meet w/util on 840907 in Glen Ellyn, IL to discuss regulatory improvement program
NORELIUS, C E Region 3, Office of Director 84/08/08 REED, C
Commonwealth Edison Co 2pp 26041 050 24X Fiche 50-000, 84/08/08, 8408140344

8408150098 Supplx 840711 response to IE Bulletin 84-02 re visual insp during monthly functional tests to verify proper contact on reactor trip sys & primary containment isolation sys relays
Exemptions requested for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26067 053 24X
Fiche 50-000, 84/08/08, 8408150098

8408200331 Supplx response to IE Bulletin 84-02 re failure of GE Type HFA relays Exemption requested from commitment for visual insp verifying proper relay contact during monthly functional check for listed relays
ALEXANDER, G L Commonwealth Edison Co 84/08/08 KEPPLER, J G
Region 3, Office of Director 3pp 26132 318 24X
Fiche 50-000, 84/08/08, 8408200331

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 12Spp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408220079 Documents schedule for submitting inservice insp (ISI) programs Commitment will be incorporated into FSAR in next amend ISI program will be submitted within 6 months after issuance of OLs
TRAMM, T R Commonwealth Edison Co 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26193 251 24X
Fiche 50-000, 84/08/13, 8408220079

8408300118 Forwards Insp Repts 50-456/84-19 & 50-457/84-18 on 840711-12 No noncompliance noted
SPESSARD, R L Region 3, Office of Director 84/08/14 REED, C
Commonwealth Edison Co 2pp 26307 215 24X Fiche 50-456, 84/08/14, 8408300118

--8408300121 Insp Repts 50-456/84-19 & 50-457/84-18 on 840711-12 No noncompliance or deviations noted Major areas inspected licensee action on previously identified items
GAUTAM, A S , TANI, K , HAWKINS, F Region 3, Office of Director
84/08/14 8pp 26307 217 24X Fiche 50-456, 84/08/14, 8408300118

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408210342 Ack receipt of 840731 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/84-09 & 50-457/84-09
WARNICK, R F Region 3, Office of Director 84/08/15 REED, C
Commonwealth Edison Co 2pp 26180 189 24X Fiche 50-456, 84/08/15, 8408210342

--8408210358 Responds to NRC 840702 ltr re violations noted in IE Insp Repts 50-456/84-09 & 50-457/84-09 Corrective actions util & Sargent & Lundy developing qualitative & quantitative clearance info to be included in contractor spec
FARRAR, D L Commonwealth Edison Co 84/07/31 KEPPLER, J G
Region 3, Office of Director 6pp 26180 191 24X
Fiche 50-456, 84/08/15, 8408210342

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 12Opp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8407100002 Final Deficiency Rept 84-07 re concrete expansion anchor installation Initially reported on 840511 Deficiencies will be reworked per Sargent & Lundy requirements & contractors will contact company for installation instructions
SWARTZ, E D Commonwealth Edison Co 84/06/11 KEPPLER, J G Region 3, Office of Director 2pp 25512 146 24X Fiche 50-456, 84/06/11, 8407100002

8407310030 Board Notification 84-134 forwards JF Streeter 840711 memo to DG Eisenhut re steam generator snubber testing failures Insp repts documenting results of testing & applicant reevaluation efforts will be forwarded to Board
NOVAK, T M Assistant Director for Licensing 84/07/27 SMITH, I W Atomic Safety and Licensing Board Panel 2pp 25936 033 24X
Fiche 50-000, 84/07/27, 8407310030

--8408060344 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE Insp repts
STREETER, J F Region 3, Office of Director 84/07/11
EISENHUT, D G Division of Licensing 1p 25936 035 24X
Fiche 50-000, 84/07/27, 8407310030

8408130231 Interim Deficiency Repts 84-05 & 84-11 re unsatisfactory operation during qualification testing of steam generator snubbers supplied by Boeing Co Initially reported on 840628 Next rept expected by 840901
SWARTZ, E D Commonwealth Edison Co 84/07/31 KEPPLER, J G Region 3, Office of Director 4pp 26008 194 24X Fiche 50-000, 84/07/31, 8408130231

8408300044 Interim Deficiency Rept 84-04 re out of tolerance radiographic film densities Initially reported on 840306 Pipe welds w/radiographic film records exceeding density requirements are being reradiographed & repaired
SWARTZ, E D Commonwealth Edison Co 84/08/16 KEPPLER, J G Region 3, Office of Director 3pp 26307 069 24X Fiche 50-456, 84/08/16, 8408300044

8408300214 Final rept of Deficiency 84-06, NCR 604 re leak in recycle holdup tanks OABD1TA & OABD1TB Initially reported on 840413 Rev of tank design procedures to utilize butt weld const for tank bottom underway
SWARTZ, E D Commonwealth Edison Co 84/08/16 KEPPLER, J G Region 3, Office of Director 2pp 26307 052 24X Fiche 50-456, 84/08/16, 8408300214

V Operator Examinations

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 84/08/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26051 240
24X Fiche 50-000, 84/08/07, 8408140372

--8408140389 "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)."
* Commonwealth Edison Co. 84/07/19 10pp 26051 242 24X
Fiche 50-000, 84/08/07, 8408140372

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp. 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A Application/construction stage documents & correspondence

8408030043 Ack receipt of 840621 ltr transmitting current description of QA program
JOHNSON, E H Region 4, Office of Director 84/07/30 CAHILL, W J
Gulf States Utilities Co 1p 25907 030 24X Fiche 50-458, 84/07/30, 8408030043

8408060028 Notifies that final submittal re containment issues raised by Humphreys will be provided by 841015
BOOKER, J E Gulf States Utilities Co 84/07/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25933 182 24X Fiche 50-458, 84/07/31, 8408060028

8408160386 Forwards master lists for categories of NSSS & balance-of-plant equipment, including NSSS electrical equipment requiring qualification per 10CFR50 49 & Seismic Category I safety-related NSSS equipment
BOOKER, J E Gulf States Utilities Co 84/07/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 88pp 26089 036
24X Fiche 50-458, 84/07/31, 8408160386

--8408160390 "QE Plant Piping Analysis II, Design Memo 150-96 "
NGUYEN, H , YEH, N , SINHA, U N General Electric Co 84/01/13
223pp 26089 124 24X Fiche 50-458, 84/07/31, 8408160386

8408140421 Forwards final response to Sections 1 1.2 1.2 2 & 4 5 of Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events " Response to Sections 3 1 & 3 2 will be provided prior to fuel load
BOOKER, J E Gulf States Utilities Co 84/08/03 EISENHUT, D G
Division of Licensing 21pp 26051 081 24X Fiche 50-458, 84/08/03, 8408140421

--8408140423 "Vendor Equipment Technical Info Program," on Generic Ltr 83-28, Section 2 2 2
* Nuclear Utility Task Action Committee 84/03/31 47pp
26051 102 24X Fiche 50-458, 84/08/03, 8408140421

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408210490 Forwards operating shift experience tables, per DG Eisenhut 840531 request Info updates 840306 ltr Shift advisors will not be used to augment operating staff
BOOKER, J E Gulf States Utilities Co 84/08/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 26148 020
24X Fiche 50-458, 84/08/13, 8408210490

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp. 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

8408290338 Forwards request for addl info re 840416 application for license to store unirradiated fuel onsite Attempt will be made to process application by 841201 if info reviewed by 840924
BIDINGER, G H Uranium Fuel Licensing Branch 84/08/22 BOOKER, J E
Gulf States Utilities Co 2pp 26311 300 24X
Fiche 50-458, 84/08/22, 8408290338

8408310132 Ack receipt of ltr re design & const problems at facility Addl info needed to investigate problems completely Telcon requested.
JOHNSON, E H, Region 1, Office of Director 84/08/24 TAYLOR, H P
Affiliation Not Assigned 1p 26322 108 24X Fiche 50-458, 84/08/24, 8408310132

C Utility Environmental Report (ER), amends & correspondence

8408240426 Interim Deficiency Rept DR-220 re license indications on valve seats of cyclinder leads in standby diesel generators supplied by TDI Interim or final status rept will be submitted by 841101
BOOKER, J E Gulf States Utilities Co 84/08/13 COLLINS, J T
Region 4, Office of Director 1p 26237 120 24X
Fiche 50-458, 84/08/13, 8408240426

D NRC Draft/Final Environmental Statements, suppls & correspondence

8408220325 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF RIVER BEND STATION Docket No 50-458 (Gulf States Utilities Company & Cajun Electric Power Cooperative)
* Division of Licensing NUREG-1073 84/07/31 249pp 26199 001
24X Fiche 50-458, 84/07/31, 8408220325

8408200540 Forwards DES (NUREG-1073) & FR notice of availability W/o DES
SCHWENCER, A Licensing Branch 2 84/08/09 CAHILL, W J Gulf States Utilities Co 2pp 26143 285 24X Fiche 50-458, 84/08/09, 8408200540

--8408200546 Notice of availability of DES (NUREG-1073) Related correspondence
SCHWENCER, A Licensing Branch 2 84/08/09 2pp 26143 287 24X
Fiche 50-458, 84/08/09, 8408200540

8408200552 Forwards DES (NUREG-1073) & FR notice of issuance & availability W/o DES
SCHWENCER, A Licensing Branch 2 84/08/09 HIRSCH, A
Environmental Protection Agency 2pp 26143 277 24X
Fiche 50-458, 84/08/09, 8408200552

8408220164 Forwards DES & FR notice re facility operation for review & comment W/o DES
SCHWENCER, A Licensing Branch 2 84/08/09 WOOD, J M Commerce, Dept of, Natl Oceanographic & Atmospheric Administration 5pp
26212 001 24X Fiche 50-458, 84/08/09, 8408220164

8408220434 Forwards DES (NUREG-1073) & FR notice of issuance Comments due 45 days after FR publication W/o DES
SCHWENCER, A Licensing Branch 2 84/08/09 Louisiana, State of
1p 26209 336 24X Fiche 50-458, 84/08/09, 8408220434

8408230412 Ack receipt of DES & submits no comment
MIRANOWSKI, J A Agriculture, Dept of 84/08/17 SCHWENCER, A
Licensing Branch 2 1p 26205 248 24X Fiche 50-458, 84/08/17, 8408230412

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408070208 Notification of 840807-09 meetings w/util in St Francisville, LA to discuss instrumentation & controls SER open & confirmatory items
WEINKAM, E J Licensing Branch 2 84/07/24 SCHWENCER, A Licensing Branch 2 4pp 25957 060 24X Fiche 50-458, 84/07/24, 8408070208

8408080249 Notification of location change for 840807-09 meetings w/util & GE in San Jose, CA to discuss instrumentation & controls SER open & confirmatory items Meeting originally scheduled to be held in St Francisville, LA
WEINKAM, E J Licensing Branch 2 84/07/24 SCHWENCER, A Licensing Branch 2 3pp 25978 316 24X Fiche 50-458, 84/07/24, 8408080249

8408060147 Forwards response to close out Item 17 of SER, Table 1 3, "Listing of Outstanding Issues " Changes will be incorporated in future FSAR amend
BOOKER, J E Gulf States Utilities Co 84/07/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 25923 304
24X Fiche 50-458, 84/07/30, 8408060147

8408140340 Forwards suppl to 840622 response to SER Confirmatory Item 3 re svc water tunnel Changes to FSAR, Section 2 5 4 11 & Table 2 5-16 to be included in future amend encl
BOOKER, J E Gulf States Utilities Co 84/08/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 26042 319
24X Fiche 50-458, 84/08/09, 8408140340

8408310172 Forwards responses to SER Outstanding Issue 18 & Confirmatory Item 59 & 840620 ltr re emergency action levels & emergency medical assistance program
BOOKER, J E Gulf States Utilities Co 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 291pp 26316 001
24X Fiche 50-458, 84/08/14, 8408310172

F Security, medical, emergency & fire protection plans

8408160511 Forwards IE Insp Rept 50-458/84-12 on 840604-08 No violations or deviations noted
JOHNSON, E H, Region 4, Office of Director 84/07/30 CAHILL, W J
Gulf States Utilities Co 2pp 26108 001 24X
Fiche 50-458, 84/07/30, 8408160511

--8408160515 IE Insp Rept 50-458/84-12 on 840604-08 No violations or deviations noted Major areas inspected radiological environ monitoring program, including organization & mgt controls, training & qualifications & equipment & supplies
BAER, R E , WISE, R , MURRAY, B Region 4, Office of Director
84/07/30 8pp 26108 003 24X Fiche 50-458, 84/07/30, 8408160511

8408310172 Forwards responses to SER Outstanding Issue 18 & Confirmatory Item 59 & 840620 ltr re emergency action levels & emergency medical assistance program
BOOKER, J E Gulf States Utilities Co 84/08/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 291pp 26316 001
24X Fiche 50-458, 84/08/14, 8408310172

8408240194 Forwards comments on Rev 2 to physical security plan submitted on 840307 Comments identify concerns re upgrading or changes to plan to satisfy regulatory requirements Encl withheld (ref 10CFR73 21)
SCHWENCER, A Licensing Branch 2 84/08/20 CAHILL, W J Gulf States Utilities Co 1p 26227 354 24X Fiche 50-458, 84/08/20, 8408240194

8408270003 Forwards Insp Rept 50-458/84-20 on 840717-20 No violations or deviations observed
JOHNSON, E H Region 4, Office of Director 84/08/20 CAHILL, W J
Gulf States Utilities Co 2pp 26247 001 24X
Fiche 50-458, 84/08/20, 8408270003

--8408270007 Insp Rept 50-458/84-20 on 840717-20 No violations or deviations identified Major areas inspected security plan & implementing procedures, mgt, personnel & access control Details withheld (ref 10CFR73 21)
EVANS, C A , HALL, R E , JAUDON, J P Region 4, Office of Director
84/08/20 1p 26247 003 24X Fiche 50-458, 84/08/20, 8408270003

A Adjudicatory correspondence

8408010241 Forwards FSAR & environ rept - OL stage, updated through 840701, per 840622 request W/o encls Related correspondence
BOOKER, J E Gulf States Utilities Co DSB 661 84/07/12
COTTER, B P Atomic Safety and Licensing Board Panel , 1p
25856 009 24X Fiche 50-458, 84/07/12, 8408010241

8408010210 Notice of appearance in proceeding Certificate of Svc encl
DAVIS, W G Louisiana, State of DSB 666 84/07/24 3pp
25856 053 24X Fiche 50-458, 84/07/24, 8408010210

8408010245 Requests that WJ Guste & ID Lindsey be removed from svc list
DAVIS, W G Louisiana, State of DSB 667 84/07/24 Docketing & Services Branch 1p 25856 005 24X Fiche 50-458, 84/07/24, 8408010245

8408010258 Answers to first set of interrogatories & response to request for production of documents Certificate of Svc encl Related correspondence
WATKINS, L B Joint Intervenors - River Bend WATKINS, L B Watkins, L B DSB 654 84/07/24 Gulf States Utilities Co 10pp
25854 168 24X Fiche 50-458, 84/07/24, 8408010258

8408070390 Responds to 840706 questions re NRC board notification procedures, specifically Board Notification 84-062 Info contained in notification will be included in BBER Related correspondence
DEWEY, L S Hearing Branch 3 DSB 815 84/08/02 MCNEILL, J D
Louisiana, State of 2pp 25945 267 24X Fiche 50-458, 84/08/02, 8408070390

8408140458 Answers to applicant first set of interrogatories re Contentions 1 & 2 Related correspondence
MCNEILL, J D Louisiana, State of DSB 814 84/08/13 Gulf States Utilities Co 7pp 26040 353 24X Fiche 50-458, 84/08/13, 8408140458

M Antitrust correspondence

8408290342 Forwards updates & supplS to 830915 ltr providing info showing significant changes since CP antitrust review which render info provided by util in 1981 outdated & deficient.
SPIEGEL, G , GUTTMAN, D Spiegel & McDiarmid 84/02/03 REGAN, W
Site Analysis Branch 88pp 26289 247 24X Fiche 50-458, 84/02/03, 8408290342

8408090519 Expresses appreciation for assistance in antitrust OL review re dealings among bulk power suppliers in State of LA
LAMBE, W Site Analysis Branch 84/08/01 WILLIS, E H St Martinville, LA 1p 25983 107 24X Fiche 50-458, 84/08/01, 8408090519

8408130488 Summary of 840802 telcon w/L Campisi re status of antitrust discussions/negotiations between city of Abbeville, LA & Gulf States Utils concerning possible transmission agreement between two sys
LAMBE, W Site Analysis Branch 84/08/07 Site Analysis Branch
1p 26040 361 24X Fiche 50-458, 84/08/07, 8408130488

8408130580 Expresses appreciation for insight into various relationships among power sys in State of LA re NRC antitrust OL review
LAMBE, W Office of Nuclear Reactor Regulation, Director 84/08/07
CAMPISI, L J Abbeville, LA 1p 26038 314 24X
Fiche 50-458, 84/08/07, 8408130580

8408130609 Ack telcon in which insight into various relationships among power supply sys in State of LA helpful to antitrust OL review
LAMBE, W Site Analysis Branch 84/08/07 CAMPISI, L J Abbeville, LA 1p 26036 357 24X Fiche 50-458, 84/08/07, 8408130609

8408150390 Discusses telcon w/Mayor E Willis of St Martinville, LA re allegations of util anti-competitive behavior City had difficulty obtaining wheeling rights over util transmission lines Power delivery agreement recently negotiated
LAMBE, W Site Analysis Branch 84/08/07 Site Analysis Branch
1p 26105 010 24X Fiche 50-458, 84/08/07, 8408150390

O Inspection reports, IE Bulletins & correspondence

8408100108 Provides status rept re IE Bulletin 83-06, "Nonconforming Matls Supplied by Tube Line Corp Facilities at Long Island City, NY, Houston, TX & Carol Stream, IL " Stub ends found on flex hoses for main steam & relief valve sys
BOOKER, J E Gulf States Utilities Co 84/04/16 COLLINS, J T.
Region 4, Office of Director 3pp 25991 011 24X
Fiche 50-458, 84/04/16, 8408100108

8408160455 Ack receipt of 840525 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/84-08 Corrective actions will be reviewed during future insp
JOHNSON, E H Region 4, Office of Director 84/06/20 CAHILL, W J
Gulf States Utilities Co 1p 26107 280 24X Fiche 50-458, 84/06/20, 8408160455

--8408160457 Responds to NRC 840514 ltr re violations noted in IE Insp Rept 50-458/84-08 Corrective actions Procedure RBPP-B 1 amended to clearly state that reviewer w/o comments need not sign & return control form to licensing group
WEIGAND, J G Gulf States Utilities Co 84/05/25 COLLINS, J T
Region 4, Office of Director 4pp 26107 281 24X
Fiche 50-458, 84/06/20, 8408160455

8408100068 Submits final response to IE Bulletin 83-06, "Nonconforming Matls Supplied by Tube-Line Corp Facilities at Long Island City, NY, Houston, TX & Carol Stream, IL " No Tube Line matl supplied through TVA
BOOKER, J E Gulf States Utilities Co 84/07/02 COLLINS, J T
Region 4, Office of Director 2pp 25990 182 24X
Fiche 50-458, 84/07/02, 8408100068

8408090090 Forward IE Insp Rept 50-458/84-10 on 840501-31 No violations or deviations identified
JOHNSON, E H Region 4, Office of Director 84/07/10 CAHILL, W J
Gulf States Utilities Co 2pp. 25992 227 24X
Fiche 50-458, 84/07/10, 8408090090

--8408090095 IE Insp Rept 50-458/84-10 on 840501-31 No violations or deviations identified Major areas inspected reactor pressure vessel sys hydro activities, punch list program, IE bulletin followup & diesel generator testing
CHAMBERLAIN, D , JAUDON, J P Region 4, Office of Director
84/07/05 10pp 25992 229 24X Fiche 50-458, 84/07/10, 8408090090

8408220152 Forwards IE Insp Rept 50-458/84-06 on 840430-0504 No violations or deviations noted
JOHNSON, E H Region 4, Office of Director 84/07/19 CAHILL, W J
Gulf States Utilities Co 2pp 26188 076 24X
Fiche 50-458, 84/07/19, 8408220152

--8408220157 IE Insp Rept 50-458/84-06 on 840430-0504, No violations noted Major areas inspected radiation protection program including organization, mgt controls, staffing, qualifications, training programs & selected NUREG-0737 action items
CHANEY, N D , MURRAY, B. , JAUDON, J P Region 4, Office of Director
84/07/18 26pp 26188 078 24X Fiche 50-458, 84/07/19, 8408220152

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/07/27. Consolidated Edison Co. of New York, Inc 119pp. 25865 047. 24X Fiche 50-000, 84/07/27, 8407250229.

8408060412 Summary of 840501 meeting w/util, Rockwell & EG&G Idaho in Bethesda, MD re recording of ultrasonic indications in piping sys susceptible to IGSCC & exams of reactor vessel feedwater inlet nozzles
WEINKAM, E J Licensing Branch 2 84/07/30 Licensing Branch 2
12pp 25951 130 24X Fiche 50-458, 84/07/30, 8408060412

8408160230 Forwards IE Insp Rept 50-458/84-11 on 840625-29 No violations or deviations noted
JOHNSON, E H Region 4, Office of Director 84/07/30 CAHILL, W J
Gulf States Utilities Co 2pp 26106 220 24X
Fiche 50-458, 84/07/30, 8408160230

--8408160237 IE Insp Rept 50-458/84-11 on 840625-29 No violations or deviations noted Major areas inspected operational staffing, personnel qualification & training
MURPHY, M E , HARBUCK, C C , IRELAND, R E Region 4, Office of Director 84/07/27 8pp 26106 222 24X Fiche 50-458, 84/07/30, 8408160230

8408160511 Forwards IE Insp Rept 50-458/84-12 on 840604-08 No violations or deviations noted
JOHNSON, E H Region 4, Office of Director 84/07/30 CAHILL, W J
Gulf States Utilities Co 2pp 26108 001 24X
Fiche 50-458, 84/07/30, 8408160511

--8408160515 IE Insp Rept 50-458/84-12 on 840604-08 No violations or deviations noted Major areas inspected radiological environ monitoring program, including organization & mgt controls, training & qualifications & equipment & supplies
BAER, R E , WISE, R , MURRAY, B Region 4, Office of Director
84/07/30 8pp 26108 003 24X Fiche 50-458, 84/07/30, 8408160511

8408290103 Forwards Insp Rept 50-458/84-17 on 840625-29 No violations or deviations noted
JOHNSON, E H Region 4, Office of Director 84/07/31 CAHILL, W J
Gulf States Utilities Co 2pp 26298 005 24X
Fiche 50-458, 84/07/31, 8408290103

--8408290108 Insp Rept 50-458/84-17 on 840625-29 No violations or deviations noted Major areas inspected const site tour, electrical terminations, QC personnel training records & QA procedures re pulling & termination of electrical cable
BESS, J E , JAUDON, J P , HUNNICUTT, D M Region 4, Office of Director 84/07/27 6pp 26298 007 24X Fiche 50-458, 84/07/31, 8408290103

8408200290 Forwards IE Insp Rept 50-458/84-13 on 840517-0616 No violations noted
JOHNSON, E H Region 4, Office of Director 84/08/02 CAHILL, W J
Gulf States Utilities Co 2pp 26140 092 24X
Fiche 50-458, 84/08/02, 8408200290

--8408200292 IE Insp Rept 50-458/84-13 on 840517-0616 No violations noted Major areas inspected licensee actions on previous findings, deficiency repts, site tours, electrical cable qualification, safety concern program & allegation review
FARRELL, R E , JAUDON, J P Region 4, Office of Director 84/08/02
7pp 26140 094 24X Fiche 50-458, 84/08/02, 8408200290

8408200316 Forwards IE Insp Rept 50-458/84-16 on 840709-15 & notice of violation
JOHNSON, E H Region 4, Office of Director 84/08/02 CAHILL, W J
Gulf States Utilities Co 2pp 26140 114 24X
Fiche 50-458, 84/08/02, 8408200316

---8408200321 Notice of violation from insp on 840709-15
* Region 4, Office of Director 84/08/02 2pp 26140 116 24X
Fiche 50-458, 84/08/02, 8408200316

--8408200326 IE Insp Rept 50-458/84-16 on 840709-13 Noncompliance noted failure to effectively control design drawings & specs
MCNEILL, W M , JAUDON, J P Region 4, Office of Director 84/08/02
4pp 26140 118 24X Fiche 50-458, 84/08/02, 8408200316

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408100033 Forwards QA Program Insp Rept 99900743/84-01 on 840821, for info & action Return receipt requested W/o encl.
JOHNSON, E H Region 4, Office of Director 84/08/06 CAHILL, W J
Gulf States Utilities Co 2pp 25990 168 24X
Fiche 50-458, 84/08/06, 8408100033

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408140091 Ack receipt of 840604 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-458/84-02
JOHNSON, E H Region 4, Office of Director 84/08/10 CAHILL, W J
Gulf States Utilities Co 1p 26044 358 24X Fiche 50-458, 84/08/10, 8408140091

--8408140095 Responds to NRC 840522 ltr re violations noted in IE Insp Rept 50-458/84-02 Corrective actions addl review of other QC radiographs performed No discrepancies identified Util in full compliance as of 840604
CAHILL, W J Gulf States Utilities Co 84/06/04 COLLINS, J T
Region 4, Office of Director 4pp 26044 359 24X
Fiche 50-458, 84/08/10, 8408140091

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408270003 Forwards Insp Rept 50-458/84-20 on 840717-20 No violations or deviations observed
JOHNSON, E H Region 4, Office of Director 84/08/20 CAHILL, W J
Gulf States Utilities Co 2pp 26247 001 24X
Fiche 50-458, 84/08/20, 8408270003

--8408270007 Insp Rept 50-458/84-20 on 840717-20 No violations or deviations identified Major areas inspected security plan & implementing procedures, mgt, personnel & access control
Details withheld (ref 10CFR73 21)
EVANS, C A , HALL, R E , JAUDON, J P Region 4, Office of Director
84/08/20 1p 26247 003 24X Fiche 50-458, 84/08/20, 8408270003

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408220317 Part 21 rept re failure of ITE-27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/13, DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000, 84/03/13, 8408220317

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY, C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000, 84/05/24, 8405290062

'Investigation of Types AF & AE Piston Skirts "
Analysis Associates FAAA-84-2-14 84/05/23 120pp
50-000,84/05/24,8405290062

wards "Evaluation of Emergency Diesel Generator
at Shoreham & Grand Gulf Nuclear Power

'I (Transamerica Delaval, Inc) Owners Group 84/05/24
Office of Nuclear Reactor Regulation, Director 2pp
24X Fiche 50-000,84/05/24,8405290179

wards repts received by BNWL & consultants directly from
wners Group at 840622 meeting Draft "Overview of
is & Recommendations re Main Propulsion Engines
" encl
M Battelle Memorial Institute, Pacific Northwest
84/06/28 MILLER,M Division of Licensing 158pp
24X Fiche 50-000,84/06/28,8408060405

wards info addressing open items identified in NRC/BNWL/
enerator Owners Group 840622 meeting
I (Transamerica Delaval, Inc) Owners Group 84/07/10
Director's Office, Office of Inspection and
43pp 25933 133 24X Fiche 50-000,84/07/10,

al Deficiency Rept DR-146 re multipole circuit breakers
Electrical Products Initially reported on
rcuit breakers supplied were determined
ndition not reportable under 10CFR50 55(e)
Gulf States Utilities Co 84/07/16 COLLINS,J T
fice of Director 1p 25866 243 24X
,84/07/16,8408010004

al Deficiency Rept DR-171 re flow adjustment subassembly
4 Robertshaw thermostatic flow control valves on
cooling sys for TDI standby diesel generators
t reportable under 10CFR50 55(e)
Gulf States Utilities Co 84/07/16 COLLINS,J T
fice of Director 1p 25866 267 24X
,84/07/16,8408010012

uards program plan for evaluating & testing TDI standby
stors Program includes all recommended actions
s Group & TDI Changes to number of start tests &
ts requested
Gulf States Utilities Co 84/07/19 DENTON,H R
clear Reactor Regulation, Director 43pp 25882 229
-458,84/07/19,8408020025

arim Deficiency Rept DR-153 re orifice plates supplied
ntrols Co & mfg by Allegheny Ludlum Steel Corp
ainless Steel Co Next rept will be provided by

Gulf States Utilities Co 84/07/24 COLLINS,J T
fice of Director. 1p 25974 333 24X
84/07/24,8408080199

al Deficiency Rept DR-165 re traceability of copper bus
by Southern Metals Corp & Gulf Coast Supply
f to Category I & acceptable in Class IE
ndition not reportable under 10CFR50 55(e)
Gulf States Utilities Co 84/07/25 COLLINS,J T
fice of Director 1p 25975 163 24X
84/07/25,8408080471

arim Deficiency Rept DR-184 re shop weld on support
lied by BF Shaw Next rept will be supplied by

Gulf States Utilities Co 84/07/26 COLLINS,J T
fice of Director. 1p. 25953 038 24X
84/07/26,8408070529

uards "Emergency Diesel Generator Auxiliary Module
ng & Termination Qualification Review " Addl
,o BNWL
I (Transamerica Delaval, Inc) Owners Group 84/07/27
Office of Nuclear Reactor Regulation, Director 2pp
24X Fiche 50-000,84/07/27,8408060102

mergency Diesel Generator Auxiliary Module Control Wiring
on Qualification Review."
Webster Engineering Corp 84/07/31 36pp 25932 139
50-000,84/07/27,8408060102

arim Deficiency Rept DR-212 re battery cell spacer matl
ould Co Next rept will be provided by 840824
Gulf States Utilities Co 84/07/27 COLLINS,J T
fice of Director 1p 25953 032 24X
84/07/27,8408070520

8408080236 Interim Deficiency Rept DR-140 re TDI standby diesel
generator fuel oil piping & header assembly Next rept will
be provided by 841011 Field QC insp of generator IEGS#EGIB
will be performed in near future
BOOKER,J E Gulf States Utilities Co 84/07/27 COLLINS,J T
Region 4, Office of Director 1p 25974 338 24X
Fiche 50-458,84/07/27,8408080236

8408140554 Interim Deficiency Rept DR-215 re uninterruptible power
supply inverters supplied by Elgar Corp Interim or final
rept will be submitted by 840913
BOOKER,J E Gulf States Utilities Co 84/07/30 COLLINS,J T
Region 4, Office of Director 1p 26064 121 24X
Fiche 50-458,84/07/30,8408140554

8408150177 Interim Deficiency Rept DR-188 re hubs on socket-weld
flanges supplied by Guyon Alloys for instrument lines on
main steam isolation sys Next rept will be provided by
840829
BOOKER,J E Gulf States Utilities Co 84/07/30 COLLINS,J T
Region 4, Office of Director 1p 26075 353 24X
Fiche 50-458,84/07/30,8408150177

8408150385 Final Deficiency Rept DR-137 re defective springs in Pacific
Scientific Models PSA-1 & PSA-3 mechanical shock arrestors
Testing indicated sufficiently sound springs Item not
reportable under 10CFR50 55(e)
BOOKER,J E Gulf States Utilities Co 84/07/30 COLLINS,J T
Region 4, Office of Director 1p 26078 001 24X
Fiche 50-458,84/07/30,8408150385

8408150704 Interim Deficiency Rept DR-213 re pressure setting on safety
relief valves for air start sys air receivers on HPCS diesel
generator supplied by GE Next rept will be provided by
841030
BOOKER,J E Gulf States Utilities Co 84/07/30 COLLINS,J T
Region 4, Office of Director 1p 26079 007 24X
Fiche 50-458,84/07/30,8408150704

8408150707 Interim Deficiency Rept DR-214 re gauges on seating surface
in stainless steel overlay of cover on feed check valve
supplied by Atwood & Morrill Next rept will be provided by
840905
BOOKER,J E Gulf States Utilities Co 84/07/30 COLLINS,J T
Region 4, Office of Director 1p 26079 101 24X
Fiche 50-458,84/07/30,8408150707

8408220504 Corrected final Deficiency Rept DR-139 re potentially
defective springs in Pacific Scientific PSA-1 & PSA-3
mechanical shock arrestors Snubbers rotated & requalified
by vendor Condition not reportable under 10CFR50 55(e)
BOOKER,J E Gulf States Utilities Co 84/07/30 COLLINS,J T
Region 4, Office of Director 1p 26196-011 24X
Fiche 50-458,84/07/30,8408220504

8408150152 Interim Deficiency Rept DR-186 re conduit plugs in
transmitters supplied by Rosemount Next rept will be
provided by 840815
BOOKER,J E Gulf States Utilities Co 84/07/31 COLLINS,J T
Region 4, Office of Director 1p 26075 338 24X
Fiche 50-458,84/07/31,8408150152

8408150162 Interim Deficiency Rept DR-187 re CRD hydraulic lines Next
rept will be provided by 840919
BOOKER,J E. Gulf States Utilities Co 84/07/31 COLLINS,J T
Region 4, Office of Director 1p 26075 354 24X
Fiche 50-458,84/07/31,8408150162

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger
Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator
Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25927 064 24X Fiche 50-000,84/08/01,8408060324

8408150308 Interim Deficiency Rept DR-154 re high voltage cable
terminations Next rept will be provided by 840920
BOOKER,J E Gulf States Utilities Co 84/08/02 COLLINS,J T
Region 4, Office of Director 1p 26075 360 24X
Fiche 50-458,84/08/02,8408150308

8408150691 Final Deficiency Rept DR-169 re groundwire defect in
switchgear supplied by Brown-Boveri Electric Single
undetected ground would not affect dc sys operation Item not
reportable per 10CFR50 55(e)
BOOKER,J E Gulf States Utilities Co 84/08/03 COLLINS,J T
Region 4, Office of Director 1p 26079.099 24X
Fiche 50-458,84/08/03,8408150691

8408160194 Interim Deficiency Rept DR-216 re electrical penetrations
supplied by Conax Corp Next rept will be provided by 841009
BOOKER,J E Gulf States Utilities Co 84/08/06 COLLINS,J T
Region 4, Office of Director 1p 26106 337 24X
Fiche 50-458,84/08/06,8408160194

DOCKETED ITEMS

60242 Interim Deficiency Rept DR-145 re design mod to reactor
g beam welded to embedment plate Next rept will be
vided by 840928
KER, J E Gulf States Utilities Co 84/08/06 COLLINS, J T
ion 4, Office of Director 1p 26106 208 24X
che 50-458, 84/08/06, 8408160242

220511 Interim Deficiency Rept DR-218 re piston rods in Brown
veri Electric Type SHK circuit breakers Next rept will be
mitted by 841024
OKER, J E Gulf States Utilities Co 84/08/08 COLLINS, J T
gion 4, Office of Director 1p 26196 008 24X
che 50-458, 84/08/08, 8408220511

230538 Interim Deficiency Rept DR-217 re bolting matls supplied by
rdinal Industrial Products Next rept will be submitted by
1017
OKER, J E Gulf States Utilities Co. 84/08/08, COLLINS, J T
gion 4, Office of Director 1p 26212 352 24X
che. 50-458, 84/08/08, 8408230538

3160394 Forwards "Design Review of Engine Base & Bearing Caps for
DI DSRV-16 Diesel Engines "
V, C, L. TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
ENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
5091 147 24X Fiche 50-000, 84/08/10, 8408160394

408160403 "Design Review of Engine Base & Bearing Caps for TDI
DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp.
26091:149. 24X Fiche 50-000, 84/08/10, 8408160394

8220505 Interim Deficiency Rept DR-168 re interpretation of W3
elding procedure, Next rept will be submitted by 841018
OOKER, J E Gulf States Utilities Co. 84/08/10 COLLINS, J T
egion 4, Office of Director. 1p 26196 010. 24X
iche. 50-458, 84/08/10, 8408220505

8240115 Forwards SER re TDI Owners Group program plan. SER addresses
esign review/quality revalidation program; testing & insp,
aint & surveillance & sets forth requirements for operation
rior to completion of program plan
ISENHUT, D G. Division of Licensing 84/08/13 GEORGE, J, B TDI
Transamerica Delaval, Inc.) Owners Group 1p. 26255 194 24X
Fiche 50-000, 84/08/13, 8408240115.

8408240157 Safety evaluation of TDI Owners Group program plan Based on
BNWL evaluation, plan incorporates essential elements needed
to resolve outstanding concerns re reliability of TDI
engines for nuclear svc.
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255. 195. 24X Fiche 50-000, 84/08/13, 8408240115.

08240310 Interim Deficiency Rept DR-221 re cylinder head fire deck
wall thickness of standby diesel generators Interim or
final status rept will be provided by 841101
BOOKER, J E Gulf States Utilities Co 84/08/13 COLLINS, J T
Region 4, Office of Director 1p 26234 321 24X
Fiche. 50-458, 84/08/13, 8408240310

08240404 Interim Deficiency Rept DR-219 re design loads of conduit
supports Interim or final status rept will be provided
by 841101
BOOKER, J E Gulf States Utilities Co. 84/08/13 COLLINS, J T.
Region 4, Office of Director 1p. 26237. 105 24X
Fiche: 50-458, 84/08/13, 8408240404.

8408240426 Interim Deficiency Rept DR-220 re license indications on
valve seats of cyclinder heads in standby diesel generators
supplied by TDI Interim or final status rept will be
submitted by 841101
BOOKER, J E. Gulf States Utilities Co. 84/08/13 COLLINS, J T.
Region 4, Office of Director 1p 26237 120 24X
Fiche. 50-458, 84/08/13, 8408240426

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger
Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator
Sets," representing final GA verified rept Addl copy
forwarded to BNWL, per NRC request.
RAY, C, L. TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp
26088 163. 24X Fiche 50-000, 84/08/14, 8408160395

8408160397 "Design Review of Elliott Model 900 Turbocharger Used on
TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp.
26088 165. 24X Fiche: 50-000, 84/08/14, 8408160395

8408280408 Interim Deficiency Rept DR-126 re standby 480-volt load ctrs
supplied by Powell Electric Next rept will be provided by
841030
BOOKER, J E Gulf States Utilities Co 84/08/15 COLLINS, J T
Region 4, Office of Director 1p 26282 108 24X
Fiche 50-458, 84/08/15, 8408280408

8408280458 Final Deficiency Rept DR-183 re contact configurations of
94AX relays supplied by Gould-Brown Boveri Condition not
reportable under 10CFR50 55(e) requirements
BOOKER, J E Gulf States Utilities Co 84/08/15 COLLINS, J T
Region 4, Office of Director 1p 26282 040 24X
Fiche 50-458, 84/08/15, 8408280458

8408280414 Interim Deficiency Rept DR-186 re Rosemount Model 1153
series transmitters Next rept will be provided by 840913
BOOKER, J E Gulf States Utilities Co 84/08/16 COLLINS, J T
Region 4, Office of Director 1p 26282 113 24X
Fiche 50-458, 84/08/16, 8408280414

8408280416 Interim Deficiency Rept DR-222 re relocation of Div III
125-volt panel Next rept will provided by 841025
BOOKER, J E Gulf States Utilities Co 84/08/16 COLLINS, J T
Region 4, Office of Director 1p 26282 114 24X
Fiche 50-458, 84/08/16, 8408280416

8408280446 Interim Deficiency Rept DR-184 re shop weld in support
trunion supplied by BF Shaw Next rept will be submitted by
840930.
BOOKER, J E Gulf States Utilities Co 84/08/16 COLLINS, J T
Region 4, Office of Director 1p 26282 140 24X
Fiche 50-458, 84/08/16, 8408280446

8408280428 Interim Deficiency Rept DR-177 re neutron monitoring sys
cable supplied by Rockbestos Cable Co. Next rept will be
provided by 840928
BOOKER, J E Gulf States Utilities Co 84/08/17 COLLINS, J T
Region 4, Office of Director 1p 26282 127 24X
Fiche 50-458, 84/08/17, 8408280428

8408300343 Final Deficiency Rept DR-138 re ITE-Gould Type 2150 overload
relays Initially reported on 840720 W/o stated encl
BOOKER, J E Gulf States Utilities Co 84/08/20 COLLINS, J T
Region 4, Office of Director 1p 26308 342 24X
Fiche 50-458, 84/08/20, 8408300343

8408310087 Interim Deficiency Rept DR-223 re installation of mechanical
snubbers supplied by Pacific Scientific Next rept will be
provided by 841026
BOOKER, J E Gulf States Utilities Co 84/08/20 COLLINS, J T
Region 4, Office of Director 1p 26334 242 24X
Fiche: 50-458, 84/08/20, 8408310087

8408300494 Interim Deficiency Rept DR-224 re main steam piping thermal
movement analysis supplied by GE Next rept will be provided
by 841115
BOOKER, J E Gulf States Utilities Co 84/08/22 COLLINS, J T
Region 4, Office of Director 1p 26314 009 24X
Fiche 50-458, 84/08/22, 8408300494

8408300507 Interim Deficiency Rept DR-225 re motor torque for motor
operated valves supplied by Velan Engineering, Ltd Next rept
will be provided by 841026.
BOOKER, J E Gulf States Utilities Co 84/08/22 COLLINS, J T
Region 4, Office of Director 1p 26314 068 24X
Fiche 50-458, 84/08/22, 8408300507.

8408290179 Forwards response to 840723 request for addl info on rpts
submitted by TDI Diesel Generator Owners Group.
RAY, C, L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23.
BERLINGER, C Office of Nuclear Reactor Regulation, Director 12pp
26289: 221 24X Fiche 50-000, 84/08/23, 8408290179

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

8408030043 Ack receipt of 840621 ltr transmitting current description
of QA program
JOHNSON, E H Region 4, Office of Director 84/07/30 CAHILL, W J
Gulf States Utilities Co 1p 25907 030. 24X Fiche: 50-458,
84/07/30, 8408030043

F Security, medical, emergency & fire protection plans

8408240194 Forwards comments on Rev 2 to physical security plan submitted on 840307 Comments identify concerns re upgrading or changes to plan to satisfy regulatory requirements Encl withheld (ref 10CFR73 21)
SCHWENCER,A Licensing Branch 2 84/08/20 CAHILL,W J Gulf States Utilities Co 1p 26227 354 24X Fiche 50-458,84/08/20, 8408240194

G Adjudicatory correspondence

8408010210 Notice of appearance in proceeding Certificate of Svc encl
DAVIS,W G Louisiana, State of DSB 666 84/07/24 3pp
25856 053 24X Fiche 50-458,84/07/24,8408010210

8408010245 Requests that WJ Guste & ID Lindsey be removed from svc list
DAVIS,W G Louisiana, State of DSB 667 84/07/24 Docketing & Services Branch 1p 25856 005 24X Fiche 50-458,84/07/24, 8408010245

8408010258 Answers to first set of interrogatories & response to request for production of documents Certificate of Svc encl Related correspondence
WATKINS,L B Joint Intervenors - River Bend WATKINS,L B Watkins, L B DSB 654 84/07/24 Gulf States Utilities Co 10pp
25854 168 24X Fiche 50-458,84/07/24,8408010258

8408070390 Responds to 840706 questions re NRC board notification procedures,specifically Board Notification 84-062 Info contained in notification will be included in SSER Related correspondence
DEWEY,L S Hearing Branch 3 DSB 815 84/08/02 MCNEILL,J D Louisiana, State of 2pp 25945 267 24X Fiche 50-458,84/08/02, 8408070390

8408140458 Answers to applicant first set of interrogatories re Contentions 1 & 2 Related correspondence
MCNEILL,J D Louisiana, State of DSB 014 84/08/13 Gulf States Utilities Co 7pp 26060 393 24X Fiche 50-458,84/08/13, 8408140458

M Antitrust correspondence

8408290342 Forwards updates & suppls to 830915 ltr providing info showing significant changes since CP antitrust review which render info provided by util in 1981 outdated & deficient
SPIEGEL,G , GUTTMAN,D Spiegel & McDiarmid 84/02/03 REGAN,W Site Analysis Branch 88pp 26289 247 24X Fiche 50-458,84/02/03, 8408290342

S Reportable occurrences, LERs & related correspondence

8405290062 Forwards "Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
24692 090 24X Fiche 50-000,84/05/24,8405290179

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp
25926 173 24X Fiche 50-000,84/06/28,8408060405

8408060050 Forwards info addressing open items identified in NRC/BNWL/ TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office, Office of Inspection and Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10, 8408060050

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 137 24X Fiche 50-000,84/07/27,8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000,84/07/27,8408060102

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25927 044 24X Fiche 50-000,84/08/01,8408060324

8408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26091 147 24X Fiche 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
* Failure Analysis Associates FAAA-84-6-53 84/08/31 44pp
26091 149 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program,testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X Fiche 50-000,84/08/13,8408240115.

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation,plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL,per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26088 163 24X Fiche 50-000,84/08/14,8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp
26289 221 24X Fiche 50-000,84/08/23,8408290179

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI,P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24X Fiche 50-000,84/07/27, 8408080288

8408080175 Forwards proposed agenda for 840906 meeting to discuss status & project completion plans,per 840711 telcon Proposed supply sys role,ongoing programs & activities & concepts for acceptance of work will be discussed
SORENSEN,G C Washington Public Power Supply System 84/07/31
EISENHUT,D G Division of Licensing 3pp 25959 001 24X
Fiche 50-460,84/07/31,8408080175

8408170031 Forwards supplemental response to Generic Ltr 83-28 re Salem ATWS events Util investigating possibility of modifying existing GE AK breakers or replacing breakers w/different device
SORENSEN,G C Washington Public Power Supply System 84/08/10
ADENSAM,E G Licensing Branch 4 4pp 26119 079 24X
Fiche 50-460,84/08/10,8408170031

DOCKETED ITEMS

Adjudicatory correspondence

8020008 Advises that time for Commission to review ALAB-771 expired ommission declined review Decision became final agency ction on 840723 Served on 840801
HILK,S J Office of the Secretary of the Commission DSB 706 4/08/01 Atomic Safety and Licensing Board Panel 1p 5883 059 24X Fiche 50-460,84/08/01,8408020008

Reportable occurrences, LERs & related correspondence

05290062 Forwards "Investigation of Types AF & AE Piston Skirts " lept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000,84/05/24,8405290062

8405290075 "Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates FAAA-84-2-14 84/05/23 120pp
24X Fiche 50-000,84/05/24,8405290062

05290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/05/24
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000,84/05/24,8405290179

08060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest Laboratories 84/06/28 MILLER,M Division of Licensing 158pp 25926 173 24X Fiche 50-000,84/06/28,8408060405

08060050 Forwards info addressing open items identified in NRC/BNWL/ TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/10
BERLINGER,C Director's Office: Office of Inspection and Enforcement. 43pp 25933 133 24X Fiche 50-000,84/07/10, 8408060050

408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/07/27
DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp 25932 137 24X Fiche 50-000,84/07/27,8408060102

-8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932:139
24X Fiche 50-000,84/07/27,8408060102

408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/01
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25927 064 24X Fiche 50-000,84/08/01,8408060324

3408200317 Interim deficiency rept re defective welds on Kaman Instrumentation radiation monitor display panels Initially reported on 840710 Caused by insufficient spot welds on some local indication & control units
ROOT,R W Washington Public Power Supply System 84/08/07
MARTIN,J B Region 5, Office of Director 2pp 26140 085. 24X Fiche 50-460,84/08/07,8408200317

3408160394 Forwards "Design Review of Engine Base & Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/10
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche. 50-000,84/08/10,8408160394

--8408160403 "Design Review of Engine Base & Bearing Caps for TDI *DSRV-16 Diesel Engines* "
* Failure Analysis Associates FAAA-84-6-53 84/08/31. 44pp
26091 149. 24X Fiche 50-000,84/08/10,8408160394

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program;testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT,D G Division of Licensing 84/08/13 GEORGE,J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255-194. 24X Fiche 50-000,84/08/13,8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation,plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000,84/08/13,8408240115

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final GA verified rept Addl copy forwarded to BNWL,per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000,84/08/14,8408160395

--8408160397 "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
* Failure Analysis Associates FAAA-84-5-7 84/07/31 61pp
26088 165 24X Fiche 50-000,84/08/14,8408160395

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group 84/08/23
BERLINGER,C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000,84/08/23,8408290179

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8408310156 FOIA request that SECY-84-29 & encl of PL William 840303 ltr re Functional description of safety parameter display sys be placed in PDR
DOVE,R Affiliation Not Assigned 84/04/12 FELTON,J M Division of Rules and Records 1p 26352 001 24X Fiche 50-461,84/04/12, 8408310156

8408130152 Summary of 840628 meeting w/util,Bechtel,Schiff Hardin, Sargent & Lundy,Newman & Holtzinger & State of IL in Bethesda,MD re proposed IDVP Forwards transcript of meeting minutes
SIEGEL,B L Licensing Branch 2 84/08/01 Licensing Branch 2
4pp 26034 154 24X Fiche 50-461,84/08/01,8408130152

--8408130156 Transcript of 840628 open meeting in Washington,DC re facility IDVP Pp 1-131 Supporting documentation encl
* Commissioners 84/06/28 175pp 26034 158 24X
Fiche 50-461,84/08/01,8408130152

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408100089 Forwards "Generic 300 Start Tests for Electro-Motive Div of General Motors (EMD) Model EMD-645E4 Diesels" & "Production Test," to substantiate HPCS diesel generator reliability,per 840613 ltr
HERBORN,D I Illinois Power Co 84/08/06 SCHWENCER,A Licensing Branch 2 2pp 25995 025 24X Fiche 50-461,84/08/06,8408100089

--8408100101 "Generic 300 Start Tests for Electro-Motive Div of General Motors (EMD) Model EMD-645E4 Diesels "
FALTER,H W Morrison-Knudsen Co , Inc 84/05/10 152pp
25995 027 24X Fiche 50-461,84/08/06,8408100089.

--8408100106 "Production Test "
* Stewart & Stevenson Services FTR-75744-1 84/08/06 175pp
25995 178 24X Fiche 50-461,84/08/06,8408100089

8408130120 Requests rev to 840606 QA program submittal to comply w/paragraph (3)(ii) of 10CFR50 55(f) requirement to identify each change,reason for change & basis for concluding that change satisfies 10CFR50,App B criteria
SPESSARD,R L Region 3, Office of Director 84/08/06
GERSTNER,W C Iowa Electric Light & Power Co 2pp 26007:333 24X
Fiche 50-461,84/08/06,8408130120

8408240303 Forwards request for addl info re safety parameter display sys Response requested within 60 days to allow adequate time to perform onsite audits before plant licensing
SCHWENCER,A Licensing Branch 2 84/08/17 HERBORN,D I Illinois Power Co 8pp 26237 352 24X Fiche 50-461,84/08/17,8408240303

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000, 84/08/20, 8408200275

8408270135 Forwards Bechtel response to NRC comments re Rev 1 to independent design review program plan Concurs w/Bechtel suggestion that response be considered as immediately effective amend to plan
HALL, D P Illinois Power Co 84/08/22 SCHWENCER, A Licensing Branch 2 8pp 26245 205 24X Fiche 50-461, 84/08/22, 8408270135

8408280094 Application to amend CPPR-137, extending latest completion date for const of facility to 861001, per 10CFR50 55(b) Series of stop work orders & recovery programs initiated to implement corrective action constitutes basis for request
HALL, D P Illinois Power Co 84/08/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26261 180 24X Fiche 50-461, 84/08/22, 8408280094

E NRC Safety Evaluation Report (SER), suppls & correspondence

8406190045 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CLINTON POWER STATION, UNIT NO 1 Docket No 50-461 (Illinois Power Company, et al)
* Division of Licensing NUREG-0853 603 84/05/31 40pp 25025 274 24X Fiche 50-461, 84/05/31, 8406190045

8408140351 Forwards response to NRC 840522 request for addl info re SER Outstanding Issue 9 & Confirmatory Issues 13 & 71 re suppression pool hydrodynamics
HERBORN, D I Illinois Power Co 84/08/08 SCHWENCER, A Licensing Branch 2 6pp 26041 044 24X Fiche 50-461, 84/08/08, 8408140351

F Security, medical, emergency & fire protection plans

8408210470 Forwards Preoperational Physical Protection Insp Rept 50-461/84-22 on 840724-27 No noncompliance identified
AXELSON, W L Region 3, Office of Director 84/08/17 GERSTNER, W C Illinois Power Co 2pp 26177 196 24X Fiche 50-461, 84/08/17, 8408210470

--8408210471 Preoperational Physical Protection Insp Rept 50-461/84-22 on 840726-27 No noncompliance identified Major areas inspected planning & implementation of security program Details withheld (ref 10CFR73 21)
PIRTLE, G L , CREED, J R Region 3, Office of Director 84/08/16 1p 26177 198 24X Fiche 50-461, 84/08/17, 8408210470

G Adjudicatory correspondence

8408130294 Forwards NRC response to util Rev 1 to independent design review program Related correspondence
GODDARD, R J Hearing Branch 3 DSB 899 84/08/09 SAMELSON, A Illinois, State of 11pp 26010 268 24X Fiche 50-461, 84/08/09, 8408130294

8408170314 Notice of appearance in proceeding Certificate of Svc encl
SIEDOR, G R Illinois, State of DSB 089 84/08/13 CLARK, H K , FERGUSON, G A , PARIS, G H Atomic Safety and Licensing Board Panel 5pp 26114 232 24X Fiche 50-461, 84/08/13, 8408170314

8408170323 Forwards notice of appearance W/o encl Related correspondence
SIEDOR, G R Illinois, State of DSB 089 84/08/13 Docketing & Services Branch 1p 26113 334 24X Fiche 50-461, 84/08/13, 8408170323

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408150502 Forwards IE Insp Rept 50-461/84-17 on 840611-15 & notice of violation
WALKER, R D Region 3, Office of Director 84/07/27 GERSTNER, W C Illinois Power Co 2pp 26079 109 24X Fiche 50-461, 84/07/27, 8408150502

--8408150507 Notice of violation from insp on 840611-15
WALKER, R D Region 3, Office of Director 84/07/27 1p 26079 111 24X Fiche 50-461, 84/07/27, 8408150502

--8408150511 IE Insp Rept 50-461/84-17 on 840611-15 Violation noted const contractor failed to follow up outstanding document control transmittals as required by Baldwin Assoc procedures
VANDEL, T E , SMEENGE, R J , HAWKINS, F C Region 3, Office of Director 84/07/26 13pp 26079 112 24X Fiche 50-461, 84/07/27, 8408150502

8408070452 Ack receipt of 840726 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/84-15 Corrective actions will be examined during subsequent insp
WALKER, R D Region 3, Office of Director 84/08/02 GERSTNER, W C Illinois Power Co 1p 25940 292 24X Fiche 50-461, 84/08/02, 8408070452

--8408070460 Responds to NRC 840612 ltr re violations noted in IE Insp Rept 50-461/84-15 Corrective actions nonconforming piping spools will be resolved by Nonconformance Repts 18443, 18462, 18643 & 18609
HALL, D P Illinois Power Co 84/07/26 KEPPLER, J G Region 3, Office of Director 2pp 25940 293 24X Fiche 50-461, 84/08/02, 8408070452

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408240314 Forwards Insp Rept 50-461/84-14 on 840529-31, 0601, 28-29 & 0711-13 No noncompliance noted
WARNICK, R F Region 3, Office of Director 84/08/03 GERSTNER, W C Illinois Power Co 2pp 26236 330 24X Fiche 50-461, 84/08/03, 8408240314

--8408240321 Insp Rept 50-461/84-14 on 840529-31, 0601, 28-29 & 0711-13 No noncompliance noted Major areas inspected allegations re equipment installation, including intimidation, qualification & training of personnel & quality of hanger matls
JABLONSKI, F J , KNOP, R C Region 3, Office of Director 84/08/03 13pp 26236 332 24X Fiche 50-461, 84/08/03, 8408240314

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26127 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 84081

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8

8408100055 IE Info Notice 84-66, "Undetected Unavailability Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engin
Response (Post 830103) 84/08/17 Consolidated Edis
York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/

DOCKETED ITEMS

8140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ igh Failure Rates " Svc list encl
ORDAN,E L Division of Emergency Preparedness & Engineering esponse (Post 830103) 84/08/17 Consolidated Edison Co of New ork, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8210470 Forwards Preoperational Physical Protection Insp Rept 0-461/84-22 on 840726-27 No noncompliance identified
XCLSON,W L Region 3, Office of Director 84/08/17 GERSTNER W C Illinois Power Co 2pp 26177 196 24X Fiche 50-461,84/08/17, 8408210470

8408210471 Preoperational Physical Protection Insp Rept 50-461/84-22 on 840726-27 No noncompliance identified Major areas inspected planning & implementation of security program Details withheld (ref 10CFR73 21)
PIRTLE,O L , CREED,J R Region 3, Office of Director 84/08/16 1p 26177 198 24X Fiche 50-461,84/08/17,8408210470

08210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

Periodic operating reports & related correspondence

408070219 Provides quarterly update re const schedule, in response to HR Denton 840529 ltr Critical path schedule analysis shows that limiting sys schedule for reactor water cleanup approx 53 days behind schedule
HALL,D P Illinois Power Co 84/07/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 25949 261 24X Fiche 50-461,84/07/30,8408070219

Reportable occurrences, LERs & related correspondence

408060366 Interim Potential Deficiency Rept 55-84-14 re Baldwin Assoc QA vendor surveillance program Initially reported on 840621 Investigation incomplete Update on investigation will be submitted in approx 90 days
HALL,D P Illinois Power Co 84/07/20 KEPPLER,J G Region 3, Office of Director 3pp 25936 097 24X Fiche 50-461,84/07/20, 8408060366

8408080540 Interim Deficiency Rept 55-84-15 re installation of skewed auxiliary steel connections w/o required approved design details Initially reported on 840629 Investigation plan will be implemented to determine extent of problem
HALL,D P Illinois Power Co 84/07/26 KEPPLER,J G Region 3, Office of Director 2pp. 25975 321 24X Fiche 50-461,84/07/26, 8408080540

8408130238 Part 21 Rept 21-84-10 re potential functional problem w/transmitter amplifier board supplied by Rosemount,Inc as spare part or part within complete Model 1153,Series B transmitter Rosemount 840718 ltr informing of defect encl
HALL,D P Illinois Power Co 84/07/30 KEPPLER,J G Region 3, Office of Director 3pp 26008 198 24X Fiche 50-461,84/07/30, 8408130238

8408200332 Part 21 rept re tension wires on Titus Grills,Model 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested provide acceptable fix for retention
SCHNEIDER,S L Phillips Industries, Inc 84/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26133 315 24X Fiche 50-000,84/08/07,8408200332

8408200338 Part 21 rept re tension wires used for adjustment of blades on Orille Model 272 not remaining in place when blades closed, Review & testing conducted to identify total number of grilles & rework methods,
SCHNEIDER,S L Phillips Industries, Inc 84/08/07 USINGER,R Zack Co 1p 26132 356 24X Fiche 50-461,84/08/07,8408200338

8408300022 Final deficiency rept re damage to Conax cable penetrations through containment wall Initially reported on 840328 Measures taken to preclude recurrence of similar damage/ deficiencies during replacement operations
HALL,D P Illinois Power Co 84/08/15 KEPPLER,J G Region 3, Office of Director 4pp 26307 083 24X Fiche 50-461,84/08/15, 8408300022

8408300224 Interim rept of Deficiency 55-84-09 re improperly certified pipe penetration head fitting matls supplied by Rockwell Engineering & Carbon Steel Products Initially reported on 840328, Class 1 shear lugs replaced
HALL,D.P. Illinois Power Co 84/08/15, KEPPLER,J G Region 3, Office of Director 3pp 26307 004, 24X Fiche 50-461,84/08/15, 8408300224

8408270318 Interim Deficiency Rept 55-84-16 re internal wiring workmanship in Electrical Panels HPCS-DG Initially reported on 840720 Investigation plan implemented Final rept will be submitted within 90 days
HALL,D P Illinois Power Co 84/08/17 KEPPLER,J G Region 3, Office of Director 3pp 26244 184 24X Fiche 50-461,84/08/17, 8408270318

8408300076 Final rept of Deficiency 55-84-10 re loose metallic debris found in power supplies of NSPS panels Initially reported on 840403 Emphasis given to training courses in housekeeping for future work involving electronic panels
HALL,D P Illinois Power Co 84/08/17 KEPPLER,J G Region 3, Office of Director 4pp 26307 183 24X Fiche 50-461,84/08/17, 8408300076

8408300210 Interim rept of Deficiency 55-84-07 re possible use of GE generic vs plant-specific design specs in developing preoperational test procedures Initially reported on 840328 Training conducted on proper use of GE documentation
HALL,D P Illinois Power Co 84/08/17 KEPPLER,J G Region 3, Office of Director 4pp 26307 048 24X Fiche 50-461,84/08/17, 8408300210

T, Hearing transcripts on non-antitrust matters

8408130152 Summary of 840628 meeting w/util,Bechtel,Schiff Hardin, Sargent & Lundy,Newman & Holtzinger & State of IL in Bethesda,MD re proposed IDVP Forwards transcript of meeting minutes
SIEGEL,B L Licensing Branch 2 84/08/01 Licensing Branch 2 4pp 26034 154 24X Fiche 50-461,84/08/01,8408130152

--8408130156 Transcript of 840628 open meeting in Washington,DC re Facility IDVP Pp 1-131 Supporting documentation encl
* Commissioners 84/06/28 175pp 26034 158 24X
Fiche 50-461,84/08/01,8408130152

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8408310156 FOIA request that SECY-84-29 & encl of PL William 840303 ltr re functional description of safety parameter display sys be placed in PDR
DOVE,K Affiliation Not Assigned 84/04/12, FELTON,J M Division of Rules and Records 1p 26352 001 24X Fiche 50-461,84/04/12, 8408310156

8408130120 Requests rev to 840606 QA program submittal to comply w/paragraph (3)(ii) of 10CFR50 55(f) requirement to identify each change,reason for change & basis for concluding that change satisfies 10CFR50,App B criteria
SPESSARD,R L Region 3, Office of Director 84/08/06
GERSTNER,W C Iowa Electric Light & Power Co 2pp 26007 333 24X Fiche 50-461,84/08/06,8408130120

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc,except info for examiners
WALKER,R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10,8408140426

DOCKET STN-50-470 CESSAR SYSTEM 80

A Application/construction stage documents & correspondence

8408140390 Responds to 840327 request for info re potential single failure in auxiliary pressurizer spray sys C-E completed preliminary review of info requested Info expected to be provided by Sept 1984
SCHERER,A E Combustion Engineering, Inc 84/08/03 EISENHUT,D G Division of Licensing 1p 26052:361 24X Fiche 50-470,84/08/03, 8408140390

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408140230 Forwards items for updating when SER generated to close out remaining issues Items include steam generator tube rupture, radiological consequences of DBA & shutdown cooling (RHR) sys
SCHERER, A E Combustion Engineering, Inc 84/08/03 EISENHUT, D G Division of Licensing 2pp 26055 313 24X Fiche 50-470, 84/08/03, 8408140230

G Inspection Reports, IE Bulletins & Correspondence

8408310044 Forwards Exam Rept 50-470/OL-84-06 of exam administered during wk of 840618
STAROSTECKI, R Division of Project & Resident Programs 84/08/01
SCHERER, A E Combustion Engineering, Inc 2pp 26334 184 24X Fiche 50-470, 84/08/01, 8408310044

--8408310048 Exam Rept 50-470/OL-84-06 administered on 840617-18 Exam results not listed
DUDLEY, N F Region 4, Office of Director 84/07/26 41pp 26334 186 24X Fiche 50-470, 84/08/01, 8408310044

V Operator Examinations

8408310044 Forwards Exam Rept 50-470/OL-84-06 of exam administered during wk of 840618
STAROSTECKI, R Division of Project & Resident Programs 84/08/01
SCHERER, A E Combustion Engineering, Inc 2pp 26334 184 24X Fiche 50-470, 84/08/01, 8408310044

--8408310048 Exam Rept 50-470/OL-84-06 administered on 840617-18 Exam results not listed
DUDLEY, N F Region 4, Office of Director 84/07/26 41pp 26334 186 24X Fiche 50-470, 84/08/01, 8408310044

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8408010187 Notification of 840730 meeting w/util in Bethesda, MD to discuss util proposed dual function shift technical advisor
O'CONNOR, P W Licensing Branch 1 84/07/20 YOUNGBLOOD, B J Licensing Branch 1 4pp 25873 288 24X Fiche 50-482, 84/07/20, 8408010187

8408070394 Notification of rescheduled 840801 meeting w/util in Bethesda, MD to discuss util proposed dual function shift technical advisor Date & time of meeting changed
O'CONNOR, P W Licensing Branch 1 84/07/20 YOUNGBLOOD, B J Licensing Branch 1 3pp 25956 256 24X Fiche 50-482, 84/07/20, 8408070394

8407310144 Forwards proprietary WCAP-10621, "Westinghouse Thermocouple/Core Cooling Monitor Sys Isolation Tests " Rept withheld (ref 10CFR2 790)
PETRICK, N A Standardized Nuclear Unit Power Plant System
84/07/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 25835 258 24X Fiche 50-000, 84/07/26, 8407310144

8408060399 Forwards request for addl info re seismic & dynamic qualification Response should be received by 840731 to support schedule for full power operation at Callaway
YOUNGBLOOD, B J Licensing Branch 1 84/07/26 SCHNELL, D F Union Electric Co KOESTER, G L Kansas Gas & Electric Co 9pp 25951 169 24X Fiche 50-000, 84/07/26, 8408060399

8408070028 Summarizes Caseload Forecast Panel 840524 tour & confirms util commitment to provide updated milestone schedule every 2 wks Nov-Dec const completion date achievable Tour attendance list & milestone sheet encl
YOUNGBLOOD, B J Licensing Branch 1 84/07/26 KOESTER, G L Kansas Gas & Electric Co 7pp 25956 180 24X Fiche 50-482, 84/07/26, 8408070028

8408060234 Responds to 840726 request for addl info re seismic qualification of thermocouple/core cooling monitor sys acceptance criteria Termination of justification for interim operation maintained
PETRICK, N A Standardized Nuclear Unit Power Plant System
84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 25934 112 24X Fiche 50-000, 84/07/27, 8408060234

--8408060240 Requests addl info re seismic & dynamic qualification of thermocouple/core cooling monitoring sys, per review of info concerning 100% power amend
YOUNGBLOOD, B J Licensing Branch 1 84/07/26 SCHNELL, D F Union Electric Co KOESTER, G L Kansas Gas & Electric Co 2pp, 25934 115 24X Fiche 50-000, 84/07/27, 8408060234

8408030159 Forwards revised Figure 5 1-4 to Tech Specs re boundary for liquid effluents Info incorporated into OL application
KOESTER, G L Kansas Gas & Electric Co 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 25912 019 24X Fiche 50-482, 84/07/30, 8408030159

8408030012 Forwards update of B10905 & 18 inservice testing programs for pumps & valves Original inservice testing program developed in compliance w/Section XI of ASME Boiler & Pressure Vessel Code
KOESTER, G L Kansas Gas & Electric Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25907 124 24X Fiche 50-482, 84/07/31, 8408030012

--8408030016 "Inservice Testing Program for Pumps & Valves "
* Kansas Gas & Electric Co 84/07/31 117pp 25907 126 24X Fiche 50-482, 84/07/31, 8408030012

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000, 84/08/06, 8408070110

8408140350 Forwards one oversize milestone schedule as of 840801 Aperture card available in PDR
KOESTER, G L Kansas Gas & Electric Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24X Fiche 50-482, 84/08/08, 8408140350

8408200119 Forwards updated "Wolf Creek Unit 1 Environ Protection Plan (Nonradiological)," reflecting current regulatory conditions & revising refs
KOESTER, G L Kansas Gas & Electric Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26133 237 24X Fiche 50-482, 84/08/15, 8408200119

--8408200123 "Wolf Creek Unit 1 Environ Protection Plan (Nonradiological) "
* Kansas Gas & Electric Co 84/07/31 15pp 26133 239 24X Fiche 50-482, 84/08/15, 8408200119

8408220389 Forwards addl info re Sargent & Lundy design verification activities concerning three UHS-related items Info documents that UHS design calculations reflect as-built conditions & design info controlled & coordinated among organizations
KOESTER, G L Kansas Gas & Electric Co 84/08/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 38pp 26191 308 24X Fiche 50-482, 84/08/15, 8408220389

8408210313 Forwards revised FSAR App 7A pages addressing NRC 840625-26 requests for addl info re Reg Guide 1 97 As-built plant design info, not included in original submittal, incorporated Design provides info required to satisfy Rev 2 to reg guide
PETRICK, N A Standardized Nuclear Unit Power Plant System
84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 65pp 26179 060 24X Fiche 50-000, 84/08/16, 8408210313

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244, 24X Fiche 50-000, 84/08/20, 8408200275

8408270377 Forwards one oversize milestone schedule as of 840815 Aperture card available in PDR
KOESTER, G L Kansas Gas & Electric Co 84/08/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp, 26240 195 24X Fiche 50-482, 84/08/22, 8408270377

8408310101 Confirms transmittal of preservice insp program plan to PW O'Connor Document updated to incorporate approved field changes & to reflect as-built plant condition Relief request will be submitted
BEIKEN, S J Standardized Nuclear Unit Power Plant System 84/08/28
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26322 233 24X Fiche 50-482, 84/08/28, 8408310101

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408100066 Submits commitments to close out SER, Open Item I A 1 1 re shift technical advisor program Academic training for senior reactor operators will be provided Commitment incorporated into OL application
KOESTER, G L Kansas Gas & Electric Co 84/08/07 DENTON, H Office of Nuclear Reactor Regulation, Director 7pp 25990 175 24X Fiche 50-482, 84/08/07, 8408100066

8408160063 Clarifies SNUPPS design & procedural controls for mitigation of postulated control room fires, per SSER 3 (NUREG-0830) Requests meeting w/NRC, per procedures for disposition of backfitting requirements implemented by IE & NRR
PETRICK, N A Standardized Nuclear Unit Power Plant System
84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26085 313 24X Fiche 50-000, 84/08/10, 8408160063

8408270389 Requests that new regulatory position re control room fires be reviewed per 10CFR50 109 Meeting w/appropriate NRC mgt re procedures for disposition of backfitting requirements implemented by IE & NRR also requested
PETRICK, N A Standardized Nuclear Unit Power Plant System
84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26238 124 24X Fiche 50-482, 84/08/10, 8408270389

F Security, medical, emergency & fire protection plans

8408060175 Forwards IE Insp Rept 50-482/84-13 on 840501-04 No violations or deviations noted
JOHNSON, E H Region 4, Office of Director 84/05/25 KOESTER, G L
Kansas Gas & Electric Co 2pp 25935 172 24X
Fiche 50-482, 84/05/25, 8408060175

--8408060180 IE Insp Rept 50-482/84-13 on 840501-04 No violations or deviations noted Major areas inspected interim security plan for protection of SNM of low strategic significance Details withheld (ref 10CFR73 21)
KELLY, J A Region 4, Office of Director HALL, R E , JOHNSON, W D
Region 2, Office of Director 84/05/25 4pp 25935 174 24X
Fiche 50-482, 84/05/25, 8408060175

8408160520 Forwards IE Insp Rept 50-482/84-17 on 840626-29 No violations or deviations noted
HUNTER, D R Region 4, Office of Director 84/07/27 KOESTER, G L
Kansas Gas & Electric Co 2pp 26108 015 24X
Fiche 50-482, 84/07/27, 8408160520

--8408160523 IE Insp Rept 50-482/84-17 on 840626-29 No violations or deviations noted Major areas inspected physical security plan & implementing procedures & mgt effectiveness-security program Details withheld (ref 10CFR73 21)
KELLY, J A , HALL, R E , MARTIN, L E Region 4, Office of Director
84/07/27 1p 26108 017 24X Fiche 50-482, 84/07/27, 8408160520

8408020105 Forwards "State of KS Annex A, Nuclear Facilities Incidents Response Plan to Assistance R, Nuclear Emergencies of State Disaster Emergency Plan" & "Coffey County Contingency Plans for Incidents Involving Commercial Nuclear Power "
KOESTER, G L Kansas Gas & Electric Co 84/07/31 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 25892 306 24X
Fiche 50-482, 84/07/31, 8408020105

--8408020114 "State of KS Annex A, Nuclear Facilities Incidents Response Plan to Assistance R, Nuclear Emergencies of State Disaster Emergency Plan "
MANNELL, L Kansas, State of 84/06/30 356pp 25892 307 24X
Fiche 50-482, 84/07/31, 8408020105

-8408020117 Rev 3 to "Coffey County Contingency Plan for Incidents Involving Commercial Nuclear Power "
* Coffey County, KS 84/06/30 300pp 25893 303 24X
Fiche 50-482, 84/07/31, 8408020105

8408140337 Submits addl info to 840404 response to NRC questions re procedures generation package Technical content of procedures in accordance w/Rev 1 (840901) to Westinghouse high pressure emergency response guidelines
KOESTER, G L Kansas Gas & Electric Co 84/08/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26042 317
24X Fiche 50-482, 84/08/10, 8408140337

8408160063 Clarifies SNUPPS design & procedural controls for mitigation of postulated control room fires, per SSER 3 (NUREG-0830) Requests meeting w/NRC, per procedures for disposition of backfitting requirements implemented by IE & NRR
PETRICK, N A Standardized Nuclear Unit Power Plant System,
84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26085 313 24X Fiche 50-000, 84/08/10, 8408160063

8408270389 Requests that new regulatory position re control room fires be reviewed per 10CFR50 109 Meeting w/appropriate NRC mgt re procedures for disposition of backfitting requirements implemented by IE & NRR also requested
PETRICK, N A Standardized Nuclear Unit Power Plant System
84/08/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26238 124 24X Fiche 50-482, 84/08/10, 8408270389

8409210558 Notification of 840815 meeting w/utils & SNUPPS in Bethesda, MD to discuss fire protection review
HOLONICH, J J , O'CONNOR, P W Licensing Branch 1 84/08/15
YOUNGBLOOD, B J Licensing Branch 1 2pp 26195 257 24X
Fiche 50-000, 84/08/15, 8408210558

8408220207 Forwards Rev 4 to physical security plan Plan withheld (ref 10CFR73 21)
KOESTER, G L Kansas Gas & Electric Co 84/08/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 26194 049
24X Fiche 50-482, 84/08/15, 8408220207

8408280037 Notification of 840822 meeting w/utils & SNUPPS in Bethesda, MD to discuss SNUPPS fire protection review
HOLONICH, J J , O'CONNOR, P W Licensing Branch 1 84/08/20
YOUNGBLOOD, B J Licensing Branch 1 5pp 26294 152 24X
Fiche 50-000, 84/08/20, 8408280037

8408290033 Forwards Rev 4 to safeguards contingency plan Rev withheld (ref 10CFR73 21)
KOESTER, G L Kansas Gas & Electric Co 84/08/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 13pp 26291 254
24X Fiche 50-482, 84/08/22, 8408290033

8408300075 Summary of 840815 meeting w/utils, SNUPPS & Bechtel re SNUPPS fire protection program & safe shutdown analysis
Attendees list encl
O'CONNOR, P W , HOLONICH, J J Licensing Branch 1 84/08/22
Licensing Branch 1 6pp 26329 354 24X Fiche 50-000, 84/08/22, 8408300075

8408300090 Forwards results of evaluation re control room fire & summary of response plan necessary to ensure achievement & maint of hot standby w/postulated fire damage
PETRICK, N A Standardized Nuclear Unit Power Plant System
84/08/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 15pp 26306 120 24X Fiche 50-000, 84/08/23, 8408300090

8408280229 Board Notification 84-145 provides info re fire protection concern discovered during insp Based on preliminary insp, NRC determined safety evaluation for alternate shutdown capability incorrect
EISENHUT, D G Division of Licensing 84/08/24 PALLADINO
Consolidated Edison Co of New York, Inc ROBERTS, ASSELSTINE
Commissioners 3pp 26322 128 24X Fiche 50-000, 84/08/24, 408280229

8408280229 Board Notification 84-145 provides info re fire protection concern discovered during insp Based on preliminary insp, NRC determined safety evaluation for alternate shutdown capability incorrect
EISENHUT, D G Division of Licensing 84/08/24 PALLADINO
Consolidated Edison Co of New York, Inc 3pp 26322 128 24X
Fiche 50-000, 84/08/24, 8408280229

Q Adjudicatory correspondence

8408060221 Order determining that ASLB 840702 initial decision not final until completion of ASLAB sua sponte review Served on 840803
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel DSB 741
84/08/03 Office of the Executive Legal Director 1p 25923 361
24X Fiche 50-482, 84/08/03, 8408060221

Q Inspection reports, IE Bulletins & correspondence

8408060175 Forwards IE Insp Rept 50-482/84-13 on 840501-04 No violations or deviations noted
JOHNSON, E H Region 4, Office of Director 84/05/25 KOESTER, G L
Kansas Gas & Electric Co 2pp 25935 172 24X
Fiche 50-482, 84/05/25, 8408060175

--8408060180 IE Insp Rept 50-482/84-13 on 840501-04 No violations or deviations noted Major areas inspected interim security plan for protection of SNM of low strategic significance Details withheld (ref 10CFR73 21)
KELLY, J A Region 4, Office of Director HALL, R E , JOHNSON, W D
Region 2, Office of Director 84/05/25 4pp 25935 174 24X
Fiche 50-482, 84/05/25, 8408060175

8408060092 Forwards exam rept of initial operator exams administered in May 1984
JOHNSON, E H Region 4, Office of Director 84/07/03 KOESTER, G L
Kansas Gas & Electric Co 2pp 25935 309 24X
Fiche 50-482, 84/07/03, 8408060092

--8408060099 Exam rept of initial exams administered in May 1984 Exam results 18 of 23 senior operator candidates & all four operator candidates passed written, oral & simulator exams
PELLET, J L , COOLEY, R A Region 4, Office of Director 84/07/02
75pp 25935 311 24X Fiche 50-482, 84/07/03, 8408060092

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

Forwards IE Insp Rept 50-482/84-17 on 840626-29 No
's or deviations noted
R Region 4, Office of Director 84/07/27 KOESTER, G L
's & Electric Co 2pp 26108 015 24X
482, 84/07/27, 8408160520

'3 IE Insp Rept 50-482/84-17 on 840626-29 No violations or
ons noted Major areas inspected physical security
mplementing procedures & mgt effectiveness-security
Details withheld (ref 10CFR73 21)
A , HALL, R E , MARTIN, L E Region 4, Office of Director
'7 1p 26108 017 24X Fiche 50-482, 84/07/27, 8408160520

Ack receipt of 840601 ltr informing NRC of steps taken to
iolations noted in IE Insp Rept 50-482/84-08
R Region 4, Office of Director 84/07/31 KOESTER, G L
's & Electric Co 1p 25987 027 24X Fiche 50-482,
8408100069

5 Responds to NRC 840504 ltr re violations noted in IE Insp
-482/84-08 Corrective actions Daniel Intl Corp has
Nonconformance Rept 1SN17097P, requiring corrected
ta rept for Spool EJ-044-5016 obtained from vendor
, G L Kansas Gas & Electric Co 84/06/01 JOHNSON, E H
4, Office of Director 5pp 25987 028 24X
0-482, 84/07/31, 8408100069

Forwards QA Program Insp Repts 99900519/84-01, 99900387/84-01
4/84-02 for action Requests signature on
nt to ack receipt of repts W/o encls
R Region 4, Office of Director 84/08/03 KOESTER, G L
's & Electric Co 2pp 25988 265 24X
482, 84/08/03, 8408100139

IE Info Notice 84-59, "Deliberate Circumventing of Station
ysics Procedures " Svc list encl
L Division of Emergency Preparedness & Engineering
(Post 830103) 84/08/06 Consolidated Edison Co of New
. 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

IE Info Notice 84-60, "Failure of Air Purifying Respirator
o Meet Efficiency Requirement " Svc list encl
L Division of Emergency Preparedness & Engineering
(Post 830103) 84/08/06 Consolidated Edison Co of New
. 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

IE Info Notice 84-61, "Overexposure of Diver in PWR
Cavity " Svc list encl
L Division of Emergency Preparedness & Engineering
(Post 830103) 84/08/08 Consolidated Edison Co of New
. 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

IE Info Notice 84-62, "Therapy Misadministrations to
Undergoing Co-60 Teletherapy Treatments " Svc
.
l. Division of QA, Safeguards & Inspection Programs (Post
84/08/10 Consolidated Edison Co of New York, Inc
26130 001 24X Fiche 50-000, 84/08/10, 8408070376

IE Info Notice 84-63, "Defective RHR Replacement Piping "
encl
L Division of Emergency Preparedness & Engineering
(Post 830103) 84/08/13 Consolidated Edison Co of New
119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

IE Info Notice 84-64, "BWR HPCI Initiation Seal-In &
n. " Svc list encl
L Division of Emergency Preparedness & Engineering
(Post 830103) 84/08/15 Consolidated Edison Co of New
.. 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

IE Info Notice 84-65, "Underrated Fuses Which May Adversely
eration of Essential Electrical Equipment " Svc
.
L Division of Emergency Preparedness & Engineering
(Post 830103) 84/08/16 Consolidated Edison Co of New
. 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

IE Info Notice 84-66, "Undetected Unavailability of
riven Auxiliary Feedwater Train " Svc list encl
L Division of Emergency Preparedness & Engineering
(Post 830103) 84/08/17 Consolidated Edison Co of New
. 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

IE Info Notice 84-67, "Recent Snubber Inservice Testing W/
ure Rates " Svc list encl
L Division of Emergency Preparedness & Engineering
(Post 830103) 84/08/17 Consolidated Edison Co of New
.. 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly
Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New
York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408280229 Board Notification 84-145 provides info re fire protection
concern discovered during insp Based on preliminary insp, NRC
determined safety evaluation for alternate shutdown
capability incorrect
EISENHUT, D G Division of Licensing 84/08/24 PALLADINO
Consolidated Edison Co of New York, Inc ROBERTS, ASSELSTINE
Commissioners 3pp 26322 128 24X Fiche 50-000, 84/08/24, 408280229

S Reportable occurrences, LERs & related correspondence

8408010386 Supplemental final deficiency rept re generic defects in
Gould/Rundel 4-position & 2-position selector switches
failure Initially reported on 840209 Failed units to be
replaced from alternate supplier
SEIKEN, S J Standardized Nuclear Unit Power Plant System 84/07/20
COLLINS, J T Region 4, Office of Director 2pp 25866 284 24X
Fiche 50-000, 84/07/20, 8408010386

8408030255 Interim Significant Deficiency Rept SDR 84-04 re Limitorque
operator motor pinion/worm shaft clutch gear failure
Limitorque will conduct cycle testing & Westinghouse will
conduct metallurgical tests Next rept expected by 840930
SEIKEN, S J Standardized Nuclear Unit Power Plant System 84/07/20
KEPPLER, J G Region 3, Office of Director COLLINS, J T Region 4,
Office of Director 3pp 25917 234 24X Fiche 50-000, 84/07/20,
8408030255

8408140001 Deficiency rept re Anchor Darling 10-inch gate valve in
essential svc water sys Initially reported on 840223 Valve
failed in open position & does not represent safety concern
Condition not reportable per 10CFR50 55(e)
KOESTER, G L Kansas Gas & Electric Co 84/08/06 HUNTER, D R
Region 4, Office of Director 1p 26044 357 24X
Fiche 50-482, 84/08/06, 8408140001

8408140020 Final deficiency rept re compromised Level II welding
inspector exams Initially reported on 820712 Inspectors
retested & welds reinspected
KOESTER, G L Kansas Gas & Electric Co 84/08/06 HUNTER, D R
Region 4, Office of Director 2pp 26044 189 24X
Fiche 50-482, 84/08/06, 8408140020

8408140237 Final deficiency rept re improper fittings on low pressure
switch of nitrogen accumulator for MSIV Initially reported
on 831025 Transition piece installed in low pressure switch
assembly of each affected valve
KOESTER, G L Kansas Gas & Electric Co 84/08/06 HUNTER, D R
Region 4, Office of Director 1p 26055 315 24X
Fiche 50-482, 84/08/06, 8408140237

8408140308 Final deficiency rept re butterfly valves Supplied by
Fischer Control Initially reported on 840110 Valves w/loose
or missing pins repaired per manufacturer instructions,
including cleaning of tapered holes
KOESTER, G L Kansas Gas & Electric Co 84/08/06 HUNTER, D R
Region 4, Office of Director 7pp 26042 326 24X
Fiche 50-482, 84/08/06, 8408140308

8408160305 Final deficiency rept re insufficient torque on structural
steel bolted connections Connections reworked & reverified
to assure quality & procedures revised to complete
corrective actions
KOESTER, G L Kansas Gas & Electric Co 84/08/06 JOHNSON, E H
Region 4, Office of Director 5pp 26107 321 24X
Fiche 50-482, 84/08/06, 8408160305

8408160514 Final deficiency rept re component failures in
safety-related battery chargers Initially reported on 830309
Chargers inspected, upgraded & tested Corrective action
completed
KOESTER, G L Kansas Gas & Electric Co 84/08/06 JOHNSON, E H
Region 4, Office of Director 1p 26108 011 24X
Fiche 50-482, 84/08/06, 8408160514

8408220158 Supplemental final deficiency rept re auxiliary feedwater
turbine control circuit Field rework plan altered vendor
supplied circuitry to be compatible w/facility circuitry
KOESTER, G L Kansas Gas & Electric Co 84/08/08 HUNTER, D P.
Region 4, Office of Director 1p 26188 110 24X
Fiche 50-482, 84/08/08, 8408220158

8408220217 Final deficiency rept re ducting installation in torsion restraint area Initially reported on 831110 Damaged bolts replaced & single modified duct piece inspected & found to be welded satisfactorily to flange
KOESTER,G L Kansas Gas & Electric Co 84/08/08 HUNTER,D R
Region 4, Office of Director 2pp 26188 264 24X
Fiche 50-482,84/08/08,8408220217

8408220248 Final deficiency rept re Beta Products,Inc isolation relay cards Initially reported on 840426 Affected cards modified so that card failure would not cause loss of control power
KOESTER,G L Kansas Gas & Electric Co 84/08/08 HUNTER,D R
Region 4, Office of Director 1p 26189 216 24X
Fiche 50-482,84/08/08,8408220248

8408220479 Final deficiency rept re incorrect differential pressure correction in reactor vessel level instrumentation sys Initially reported on 840427 Input circuitry into Process Cabinet 7300 reworked
KOESTER,G L Kansas Gas & Electric Co 84/08/08 HUNTER,D R
Region 4, Office of Director 1p 26196 032 24X
Fiche 50-482,84/08/08,8408220479

8408280435 Interim deficiency rept re lubricating oil piping sys for safety injection & centrifugal charging pumps Initially reported on 840717 As-built drawings of sys developed to assess work performed w/o QA program approval
KOESTER,G L Kansas Gas & Electric Co 84/08/17 HUNTER,D R
Region 4, Office of Director 2pp 26282 128 24X
Fiche 50-482,84/08/17,8408280435

V Operator Examinations

8408060092 Forwards exam rept of initial operator exams administered in May 1984
JOHNSON,E H Region 4, Office of Director 84/07/03 KOESTER,G L
Kansas Gas & Electric Co 2pp 25935 309 24X
Fiche 50-482,84/07/03,8408060092

--8408060099 Exam rept of initial exams administered in May 1984 Exam results 18 of 23 senior operator candidates & all four operator candidates passed written,oral & simulator exams
PELLET,J L , COOLEY,R A Region 4, Office of Director 84/07/02
75pp 25935 311 24X Fiche 50-482,84/07/03,8408060092

8408280193 Advises that requested matls made available for use in developing license exams for reactor/senior operators per NRC 840629 request Training will be provided for cold licensed operators on plant procedure changes
KOESTER,G L Kansas Gas & Electric Co 84/07/23 HUNTER,D R
Region 4, Office of Director 1p 26269 358 24X
Fiche 50-482,84/07/23,8408280193

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

8406140221 Forwards marked-up Tech Specs changed since 840531 ltr Tech Specs accurately reflect design & operating program described in FSAR
SCHNELL,D F Union Electric Co 84/06/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 21pp 24924 280 24X
Fiche 50-483,84/06/11,8406140221

NRC Safety Evaluation Report (SER), supplS & correspondence

8408160063 Clarifies SNUPPS design & procedural controls for mitigation of postulated control room fires,per SSER 3 (NUREG-0830) Requests meeting w/NRC,per procedures for disposition of backfitting requirements implemented by IE & NRR
PETRICK,N A Standardized Nuclear Unit Power Plant System
84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 26085 313 24X Fiche 50-000,84/08/10,8408160063

8408270389 Requests that new regulatory position re control room fires be reviewed per 10CFR50 109 Meeting w/appropriate NRC mgt re procedures for disposition of backfitting requirements implemented by IE & NRR also requested
PETRICK,N A Standardized Nuclear Unit Power Plant System
84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26238 124 24X Fiche 50-482,84/08/10,8408270389

F Security, medical, emergency & fire protection plans

8408130397 Discusses six items from Attachment 1 to License NPF-25, covering emergency lighting in safe shutdown areas & communications outside control room,per App R requirements
SCHNELL,D F Union Electric Co 84/07/27 KEPPLER,J G Region 3, Office of Director 4pp 26011 113 24X Fiche 50-483,84/07/27, 8408130397

8408060148 Requests LERs 81-002-00 & 81-005-00 re malfunction of plant security hardware be removed from PDR,per 10CFR73 21 Util now considers LERs as safeguards info
MILTENBERGER,S Union Electric Co 84/07/30 Record Services Branch (Document Control Desk) 2pp 25923 308 24X
Fiche 50-483,84/07/30,8408060148

8408100026 Ack receipt of 840706 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-483/84-10
PAPERIELLO,C J Region 3, Office of Director 84/08/06
SCHNELL,D F Union Electric Co 1p 25990 159 24X
Fiche 50-483,84/08/06,8408100026

--8408100034 Responds to NRC 840525 ltr re improvement items noted in IE Emergency Preparedness Appraisal Rept 50-483/84-10 Corrective actions role of shift advisors,as county emergency operation ctr technical representative,evaluated
SCHNELL,D F Union Electric Co 84/07/06 PAPERIELLO,C J
Region 3, Office of Director 8pp 25990 160 24X
Fiche 50-483,84/08/06,8408100026

8408140129 Forwards Rev 4 to physical security plan Rev withheld (ref 10CFR73 21)
SCHNELL,D F Union Electric Co 84/08/09 KEPPLER,J G Region 3, Office of Director 3pp 26047 008 24X Fiche 50-483,84/08/09, 8408140129

8408210402 Rev 3 to Emergency Plan Implementing Procedure EIP-ZZ-00102, "Emergency Implementing Actions" & revised index W/840814 transmittal memo
MUTTENBERGE,S Union Electric Co 84/08/09 25pp 26179 215 24X
Fiche 50-483,84/08/09,8408210402

8408270393 Revised emergency plan implementing procedures,including EIP-22-00201 re notifications,EIP-22-00203 re addl assistance & EPIP-22-00211 re field monitoring direction & assessment W/840815 transmittal ltr
* Union Electric Co 84/08/09 200pp 26238 287 24X
Fiche 50-483,84/08/09,8408270393

8408160063 Clarifies SNUPPS design & procedural controls for mitigation of postulated control room fires,per SSER 3 (NUREG-0830) Requests meeting w/NRC,per procedures for disposition of backfitting requirements implemented by IE & NRR
PETRICK,N A Standardized Nuclear Unit Power Plant System
84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 26085 313 24X Fiche 50-000,84/08/10,8408160063

8408270389 Requests that new regulatory position re control room fires be reviewed per 10CFR50 109 Meeting w/appropriate NRC mgt re procedures for disposition of backfitting requirements implemented by IE & NRR also requested
PETRICK,N A Standardized Nuclear Unit Power Plant System
84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26238 124 24X Fiche 50-482,84/08/10,8408270389

8408210558 Notification of 840815 meeting w/utils & SNUPPS in Bethesda, MD to discuss fire protection review
HOLONICH,J J , O'CONNOR,P W Licensing Branch 1 84/08/15
YOUNGBLOOD,B J Licensing Branch 1 2pp 26195 257 24X
Fiche 50-000,84/08/15,8408210558

8408280037 Notification of 840822 meeting w/utils & SNUPPS in Bethesda,MD to discuss SNUPPS fire protection review
HOLONICH,J J , O'CONNOR,P W Licensing Branch 1 84/08/20
YOUNGBLOOD,B J Licensing Branch 1 5pp 26294 152 24X
Fiche 50-000,84/08/20,8408280037

8408300075 Summary of 840815 meeting w/utils,SNUPPS & Bechtel re SNUPPS fire protection program & safe shutdown analysis
Attendees list encl
O'CONNOR,P W , HOLONICH,J J Licensing Branch 1 84/08/22
Licensing Branch 1 6pp 26329 354 24X Fiche 50-000,84/08/22, 8408300075

8408300090 Forwards results of evaluation re control room fire & summary of response plan necessary to ensure achievement & maint of hot standby w/postulated fire damage
PETRICK,N A Standardized Nuclear Unit Power Plant System
84/08/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 15pp 26306 120 24X Fiche 50-000,84/08/23,8408300090

8408280229 Board Notification 84-145 provides info re fire protection concern discovered during insp Based on preliminary insp,NRC determined safety evaluation for alternate shutdown capability incorrect
EISENHUT,D G Division of Licensing 84/08/24 PALLADINO
Consolidated Edison Co of New York, Inc ROBERTS, ASSELSTINE
Commissioners 3pp 26322 128 24X Fiche 50-000,84/08/24,8408280229

G Adjudicatory correspondence

8408150431 Informs that Commissioner Zech will tour emergency offsite facility on 840823 & corporate ofc on 840824 Served on 840815
BECKHAM, D Commissioners DSB 059 84/08/14 Atomic Safety and Licensing Board Panel 1p 26068 261 24X Fiche 50-483, 84/08/14, 8408150431

8408200567 Informs of Chairman Palladino 840827 site visit No more than one representative of each party invited to attend Requests notification to util re attendance plans
GARNER, D J Commissioners DSB 153 84/08/17 Office of the Executive Legal Director 1p 26137 050 24X Fiche 50-483, 84/08/17, 8408200567

P Operating license stage documents & correspondence

8408010082 Forwards SER re response to Generic Ltr 83-28, Item 4 3, "Reactor Trip Sys Reliability (Automatic Actuation of Shunt Trip Attachment for Westinghouse Plants) " Shunt trip mod acceptable Util should submit proposed Tech Specs
YOUNGBLOOD, B J Licensing Branch 1 84/07/18 SCHNELL, D F Union Electric Co 3pp 25897 071 24X Fiche 50-483, 84/07/18, 8408010082

--8408010085 SER supporting licensee response to Generic Ltr 83-28, Item 4 3 re reactor trip breaker automatic shunt trip
* NRC - No Detailed Affiliation Given 84/07/18 11pp 25897 074 24X Fiche 50-483, 84/07/18, 8408010082

8407310144 Forwards proprietary WCAP-10621, "Westinghouse Thermocouple/Core Cooling Monitor Sys Isolation Tests " Rept withheld (ref 10CFR2 790)
PETRICK, N A Standardized Nuclear Unit Power Plant System 84/07/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 25835 258 24X Fiche 50-000, 84/07/26, 8407310144

8408060399 Forwards request for addl info re seismic & dynamic qualification Response should be received by 840731 to support schedule for full power operation at Callaway
YOUNGBLOOD, B J Licensing Branch 1 84/07/26 SCHNELL, D F Union Electric Co KOESTER, G L Kansas Gas & Electric Co 5pp 25951 169 24X Fiche 50-000, 84/07/26, 8408060399

8408060234 Responds to 840726 request for addl info re seismic qualification of thermocouple/core cooling monitor sys acceptance criteria Termination of justification for interim operation maintained
PETRICK, N A Standardized Nuclear Unit Power Plant System 84/07/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 25934 112 24X Fiche 50-000, 84/07/27, 8408060234

--8408060240 Requests addl info re seismic & dynamic qualification of thermocouple/core cooling monitoring sys, per review of info concerning 100% power amend
YOUNGBLOOD, B J Licensing Branch 1 84/07/26 SCHNELL, D F Union Electric Co KOESTER, G L Kansas Gas & Electric Co 2pp 25934 115 24X Fiche 50-000, 84/07/27, 8408060234

8408030098 Requests partial exemption from 10CFR50, App J, to allow reduced pressure leakage testing of containment air locks following periods when air locks open & containment integrity not required by Tech Specs
SCHNELL, D F Union Electric Co 84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 12pp 25916 043 24X Fiche 50-483, 84/07/31, 8408030098

8408060286 Application for amend to License NPF-25, revising Tech Spec Table 3 3-1 re source range neutron flux monitors during shutdown conditions Fee encl
SCHNELL, D F Union Electric Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 25933 306 24X Fiche 50-483, 84/08/01, 8408060286

--8408060287 Proposed Tech Spec changes re source range neutron flux monitors during shutdown conditions
* Union Electric Co 84/08/01 6pp 25933 310 24X Fiche 50-483, 84/08/01, 8408060286

8408070480 Confirms 840808 meeting at Region III ofc to discuss util plans to have operating staff work 12 h shifts, in four shift-crew rotation, for remainder of post-fuel load target schedule, per 840725 telcon
KEPPLER, J G Region 3, Office of Director 84/08/03 SCHNELL, D F Union Electric Co 1p 25941 210 24X Fiche 50-483, 84/08/03, 8408070480

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000, 84/08/06, 8408070110

8408160067 Forwards SER re util 840726 request for permission to exclude cold rod drop testing outlined in Reg Guide 1 68, App A, 2 & Request acceptable
YOUNGBLOOD, B J Licensing Branch 1 84/08/07 SCHNELL, D F Union Electric Co 3pp 26126 350 24X Fiche 50-483, 84/08/07, 8408160067

--8408160072 SER re deletion of cold control rod drop test Request acceptable
* Division of Licensing 84/08/07 1p 26126 353 24X Fiche 50-483, 84/08/07, 8408160067

8408140385 Discusses 840509 briefing for NRR & Region III mgt personnel re operation w/four 12 h shift rotations, distributing personnel from six crews among rotations Chart portraying interim schedule on wk-to-wk basis encl
SCHNELL, D F Union Electric Co 84/08/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 15pp 26052 346 24X Fiche 50-483, 84/08/08, 8408140385

8408220278 Requests extension to 841031 for submittal of response to Generic Ltr 84-15, "Proposed Staff Actions to Improve & Maintain Diesel Generator Reliability "
SCHNELL, D F Union Electric Co 84/08/14 EISENHUT, D G Division of Licensing 2pp 26194 078 24X Fiche 50-483, 84/08/14, 8408220278

8408210313 Forwards revised FSAR App 7A pages addressing NRC 840625-26 requests for addl info re Reg Guide 1 97 As-built plant design info, not included in original submittal, incorporated Design provides info required to satisfy Rev 2 to reg guide
PETRICK, N A Standardized Nuclear Unit Power Plant System 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 65pp 26179 060 24X Fiche 50-000, 84/08/16, 8408210313

8408230170 Confirms 840820 meeting to discuss proposed escalated enforcement action of Tech Specs violation re facility being in operational Mode 4 w/both containment spray sys trains inoperable
KEPPLER, J G Region 3, Office of Director 84/08/17 SCHNELL, D F Union Electric Co 1p 26209 276 24X Fiche 50-483, 84/08/17, 8408230170

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000, 84/08/20, 8408200275

8408280279 Informs of 840815 conference call between Containment Sys Branch & util to discuss Tech Spec 3/4 6 3 re surveillance requirement for MSIVs Passive sys (steam generators & associated piping) considered blind flange
HOLONICH, J J Licensing Branch 1 84/08/23 LITTLE, B NRC - No Detailed Affiliation Given 1p 26294 089 24X Fiche, 50-483, 84/08/23, 8408280279

Q Inspection reports, IE Bulletins & correspondence

8408230220 Forwards IE Insp Rept 50-483/84-21 on 840516-0630 No noncompliance noted
WARNICK, R F Region 3, Office of Director 84/07/26 SCHNELL, D F Union Electric Co. 2pp 26213 339 24X Fiche 50-483, 84/07/26, 8408230220

--8408230233 IE Insp Rept 50-483/84-21 on 840516-0630 No noncompliance or deviations noted Major areas inspected SER items, licensee events, QA for startup test program, initial fuel load witnessing & plant tours
FORNEY, W L Region 3, Office of Director 84/07/25 10pp 26213 341 24X Fiche 50-483, 84/07/26, 8408230220

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 11pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408160184 Forwards IE Insp Rept 50-483/84-31 on 840611-0713 & notice of violation
SPESSARD, R L Region 3, Office of Director 84/07/30 SCHNELL, D F Union Electric Co 2pp 26106 319 24X Fiche 50-483, 84/07/30, 8408160184

--8408160190 Notice of violation from insp on 840611-0713
SPESSARD,R L Region 3, Office of Director 84/07/30 1p
26106 321 24X Fiche 50-483,84/07/30,8408160184

--8408160193 IE Insp Rept 50-483/84-31 on 840611-0713 Noncompliance noted failure to adhere to approved preoperational test procedure & failure to adequately review preoperational test results
FARBER,M J , MCCORMICK-BARGE, WOHLD,P R Region 3, Office of Director 84/07/30 6pp 26106 322 24X Fiche 50-483,84/07/30, 8408160184

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted,effective 840820 Preprinted form will be used rather than ltr
KEPPLER,J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000,84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408100026 Ack receipt of 840706 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-483/84-10
PAPERIELLO,C J Region 3, Office of Director 84/08/06
SCHNELL,D F Union Electric Co 1p 25990 159 24X
Fiche 50-483,84/08/06,8408100026

--8408100034 Responds to NRC 840525 ltr re improvement items noted in IE Emergency Preparedness Appraisal Rept 50-483/84-10 Corrective actions role of shift advisors,as county emergency operation ctr technical representative,evaluated
SCHNELL,D F Union Electric Co 84/07/06 PAPERIELLO,C J Region 3, Office of Director, 8pp 25990 160 24X
Fiche 50-483,84/08/06,8408100026

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408140402 Ack receipt of 840724 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/84-23 Emergency boration flow adequacy of scaling Meters BG-FI-183A & B will be examined during future insp
SPESSARD,R L Region 3, Office of Director 84/08/10 SCHNELL,D F Union Electric Co 1p 26052 337 24X Fiche 50-483,84/08/10, 8408140402

--8408140404 Responds to NRC 840625 ltr re violations noted in IE Insp Rept 50-483/84-23 Corrective actions util & Westinghouse performing review of startup field repts w/use-as-is dispositions Full compliance should be achieved by 840803
SCHNELL,D F Union Electric Co 84/07/24 SPESSARD,R L Region 3, Office of Director 5pp 26052 338 24X Fiche 50-483, 84/08/10,8408140402

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408280229 Board Notification 84-145 provides info re fire protection concern discovered during insp Based on preliminary insp,NRC determined safety evaluation for alternate shutdown capability incorrect
EISENHUT,D G Division of Licensing 84/08/24 PALLADINO
Consolidated Edison Co of New York, Inc 3pp 26322 128 24X
Fiche 50-000,84/08/24,8408280229

S Reportable occurrences, LERs & related correspondence

8408010386 Supplemental final deficiency rept re generic defects in Gould/Rundel 4-position & 2-position selector switches failure Initially reported on 840209 Failed units to be replaced from alternate supplier
SEIKEN,S J Standardized Nuclear Unit Power Plant System 84/07/20
COLLINS,J T Region 4, Office of Director 2pp 25866 284 24X
Fiche 50-000,84/07/20,8408010386

8408030255 Interim Significant Deficiency Rept SDR 84-04 re Limitorque operator motor pinion/worm shaft clutch gear failure Limitorque will conduct cycle testing & Westinghouse will conduct metallurgical tests Next rept expected by 840930
SEIKEN,S J Standardized Nuclear Unit Power Plant System 84/07/20
KEPPLER,J G Region 3, Office of Director COLLINS,J T Region 4, Office of Director 3pp 25917 234 24X Fiche 50-000,84/07/20, 8408030255

8408070123 LER 84-006-01 on 840618,sample pump for vent wide range gas monitor turned off,causing alarm Caused by operator error Alarm response procedure issued for RM-11 & RM-23 radiation monitor control & display modules W/840725 ltr
DAVIS,J E , MILTENBERGER,S Union Electric Co 84/07/25 4pp
25993 109 24X Fiche 50-483,84/07/25,8408070123

8408060148 Requests LERs 84-002-00 & 84-005-00 re malfunction of plant security hardware be removed from PDR,per 10CFR73 21 Util now considers LERs as safeguards info
MILTENBERGER,S Union Electric Co 84/07/30 Record Services Branch (Document Control Desk) 2pp 25923 308 24X
Fiche 50-483,84/07/30,8408060148

8408090271 LER 84-019-00 on 840719,fuel bldg ventilation isolation signal actuated by fuel bldg radiation monitor alarm Caused by monitor not powered & feeder breaker accidentally opened Radiation monitor restored W/840730 ltr
DAVIS,J E , MILTENBERGER,S Union Electric Co 84/07/30 4pp
25994 144 24X Fiche 50-483,84/07/30,8408090271

8408160174 LER 84-015-00 on 840716,pressure transient occurred in RCS as result of loss of instrument air To reduce pressure,PORV cycled manually Instrument air lost again & PORV actuated automatically W/840810 ltr
TAYLOR,M E , MILTENBERGER,S Union Electric Co 84/08/10 4pp
26108 047 24X Fiche 50-483,84/08/10,8408160174

8408160256 LER 84-014-00 on 840714,high flux at shutdown alarm received from source range monitor SE-NI-31B Caused by dirt & moisture on source range monitor cable connectors Connectors cleaned & dried Unit functioned satisfactorily W/840810 ltr
TAYLOR,M E , MILTENBERGER,S Union Electric Co 84/08/10 4pp
26106 184 24X Fiche 50-483,84/08/10,8408160256

8408200324 PNO-III-84-064 on 840813,1,200 gallons of water from refueling water storage tank injected into primary sys via boron injection tank No release of radioactivity occurred Caused by faulty electrical channels
FORNEY,W , WARNICK,R Region 3, Office of Director 84/08/13 1p
26133-001 24X Fiche 50-483,84/08/13,8408200324

8408240193 LER 84-016-00 on 840717, RCS depressurized to 0 psig & primary seal on reactor coolant pump C damaged Caused by improper sequence of valve operation on RHR pump A procedure restoration Seal replaced W/840816 ltr
TAYLOR, M E , MILTENBERGER, S Union Electric Co 84/08/16 4pp 26236 234 24X Fiche 50-483, 84/08/16, 8408240193

8408230427 LER 84-021-00 on 840719, Train A of SSPS found in inhibit mode w/Train B in test Train B returned to normal Surveillance procedure changed W/840817 ltr
NASLUND, C D , MILTENBERGER, S Union Electric Co 84/08/17 5pp 26213 044 24X Fiche 50-483, 84/08/17, 8408230427

8408230546 LER 84-018-00 on 840718, fuel bldg isolation & control room ventilation isolation signals initiated from radiation monitoring elements Caused by brief voltage abnormality during bus realignment Design change requested W/840817 ltr
NASLUND, C D , MILTENBERGER, S Union Electric Co 84/08/17 4pp 26213 001 24X Fiche 50-483, 84/08/17, 8408230546

8408240315 Special Rept 84-01 on 840718, PORVs BB-PCV-455 & BB-PCV-456 lifted while starting reactor coolant pump B w/RCS in solid plant condition Administrative limit established for Delta T before starting reactor coolant pump
MILTENBERGER, S Union Electric Co 84/08/17 KEPPLER, J G Region 3, Office of Director 3pp 26236 327 24X Fiche 50-483, 84/08/17, 8408240315

V Operator Examinations

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER, R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

8408170089 Forwards list of ref matl required for operator/senior operator licensing exam & administration of operator licensing written exam, in preparation for 841106-08 exam Matl requested by 840924
WALKER, R D Region 3, Office of Director 84/08/14 SCHNELL, D F Union Electric Co 5pp 26119 067 24X Fiche 50-483, 84/08/14, 8408170089

DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

I Financial information

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26237 137 24X Fiche 50-000, 84/08/16, 8408240224

--8408240242 "1983 Annual Rept "
LEE, W S Duke Power Co 83/12/31 47pp 26237 167 24X Fiche 50-000, 84/08/16, 8408240224

DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

I Financial information

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26237 137 24X Fiche 50-000, 84/08/16, 8408240224

--8408240242 "1983 Annual Rept "
LEE, W S Duke Power Co 83/12/31 47pp 26237 167 24X Fiche 50-000, 84/08/16, 8408240224

DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

I Financial information

8408240224 Forwards Duke Power Co & North Carolina Municipal Power Agency 1 1983 annual repts
TUCKER, H B Duke Power Co 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26237 137 24X Fiche 50-000, 84/08/16, 8408240224

--8408240242 "1983 Annual Rept "
LEE, W S Duke Power Co 83/12/31 47pp 26237 167 24X Fiche 50-000, 84/08/16, 8408240224

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 138 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
ORACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co. of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865.047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc 122pp. 26068 001. 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 12Spp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

Application/construction stage documents & correspondence

8408210311 Forwards Rev 5 to QA program description for design & const phases Includes revs to Bechtel & Ebasco programs
OPREA,G W Houston Lighting & Power Co 83/11/01 COLLINS,J T
Region 4, Office of Director 5pp 26179.001 24X
Fiche 50-498,83/11/01,8408210311

-8408210317 Rev 5 to QA program for design & const of South Texas Project
* Houston Lighting & Power Co 83/11/01. 54pp 26179 006 24X
Fiche 50-498,83/11/01,8408210311

8408210500 Forwards Rev 6 to QA program description for design & const phase of facilities Changes clarify definition of Bechtel div quality policies & defines responsibilities for trend analysis
OPREA,G W Houston Lighting & Power Co 84/04/02 COLLINS,J T
Region 4, Office of Director 3pp 26148 175 24X
Fiche 50-498,84/04/02,8408210500

--8408210503 Rev 6 to QA program description for design & const of facilities
* Houston Lighting & Power Co. 84/04/02 190pp 26148 178 24X
Fiche 50-498,84/04/02,8408210500

8408070446 Requests exemption from 10CFR50,App A,GDC 4 re elimination of postulated circumferential & longitudinal breaks in RCS main loop piping & WCAP-10559 & WCAP-10560 Repts withheld (ref 10CFR2 790)
GOLDBERG,J H Houston Lighting & Power Co 84/07/17 DENTON,H R
Office of Nuclear Reactor Regulation, Director 4pp 25940 349 24X Fiche 50-498,84/07/17,8408070446

--8408070456 Safety Balance for Elimination of RCS Main Loop Pipe Break Protective Devices,South Texas Project,Units 1 & 2 "
Response to NRC request for addl info re leak before break analysis encl
* Bechtel Corp 84/04/05 14pp 25940 353 24X
Fiche 50-498,84/07/17,8408070446

--8408070465 Requests withholding of WCAP-10559 & WCAP-10560, "Technical Bases for Eliminating Large Primary Loop Pipe Rupture as Structural Design Basis for South Texas Project,Units 1 & 2" (ref 10CFR2 790)
WIESEMANN,R A Westinghouse Electric Corp 84/06/01 DENTON,H R
Office of Nuclear Reactor Regulation, Director 6pp 25941 005 24X Fiche 50-498,84/07/17,8408070446

8408090497 Summary of 840717 meeting w/Westinghouse Owners Steam Generator Tube Rupture Subgroup in Bethesda,MD re proposed steam generator tube rupture generic program List of attendees & viewgraphs encl
SINGH,B K Licensing Branch 3 84/07/31 Licensing Branch 3
18pp 25983 130 24X Fiche 50-000,84/07/31,8408090497

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408170282 Responds to 840727 submittal of Rev 7 to QA program for design & const phase Submittal satisfies requirements of 10CFR50,App B Rev 7 acceptable
JOHNSON,E H Region 4, Office of Director 84/08/14 OPREA,G W
Houston Lighting & Power Co 2pp 26114 230 24X
Fiche 50-498,84/08/14,8408170282

8408220161 Forwards draft "in furtherance" certificate re issuance of pollution control revenue bonds, for review Necessary mods & signed certificate requested by 840915
GOLDBERG,J H Houston Lighting & Power Co 84/08/14 DENTON,H R
Office of Nuclear Reactor Regulation, Director 6pp 26194 042 24X Fiche 50-498,84/08/14,8408220161

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408270355 Opposes requirement re designing for arbitrary intermediate breaks Approval for listed alternative pipe break criteria requested, excluding RCS primary loop Addl info supporting request encl
GOLDBERG,J H Houston Lighting & Power Co 84/08/20 DENTON,H R
Office of Nuclear Reactor Regulation, Director 19pp 26245 021 24X Fiche 50-498,84/08/20,8408270355

0 Adjudicatory correspondence

8408080186 Motion for enlargement of page limitation for appellate brief in response to Citizens Concerned About Nuclear Power,Inc 840708 brief on appeal of partial initial decision Certificate of Svc encl Related correspondence
GUTTERMAN,A H Houston Lighting & Power Co GUTTERMAN,A H Newman & Holtzinger DSB 024 84/08/06 Atomic Safety and Licensing Appeal Panel 4pp 25960 243 24X Fiche 50-498,84/08/06, 8408080186

8408150077 Response to applicant 840808 motion for enlargement of page limitation of appellate brief to 90 pages No objection offered Certificate of Svc encl
PIRFO,O R Hearing Branch 3 DSB 043, 84/08/10 Atomic Safety and Licensing Appeal Panel 3pp 26067 018 24X
Fiche 50-498,84/08/10,8408150077

8408150138 Motion for enlargement of page limitation of appellate brief to 90 pages Certificate of Svc encl Related correspondence
PIRFO,O R Hearing Branch 3 DSB 039 84/08/11 Atomic Safety and Licensing Appeal Panel 3pp 26067 013 24X
Fiche 50-498,84/08/11,8408150138

8408150176 Motion for enlargement of page limitation of appellate brief to 90 pages Granted for ASLAB on 840813
PIRFO,O R Hearing Branch 3 DSB 054 84/08/11 Atomic Safety and Licensing Appeal Panel 1p 26066 313 24X
Fiche 50-498,84/08/11,8408150176

DOCKETED ITEMS

8408160196 Response opposing Citizens Concerned About Nuclear Power, Inc 840708 brief on appeal from ASLB 840314 partial initial decision Request for de novo review & ab initio opinion w/o merit Certificate of Svc encl
NEWMAN, J R Houston Lighting & Power Co NEWMAN, J R Newman & Holtzinger DSB 075 84/08/13 Atomic Safety and Licensing Appeal Panel 94pp 26091 004 24X Fiche 50-498, 84/08/13, 8408160196

8408280396 Brief in response to Citizens Concerned About Nuclear Power brief on appeal from ASLB 840314 partial initial decision Certificate of Svc encl
REIS, E J , PIRFO, O R Hearing Branch 3 DSB 340 84/08/23 Atomic Safety and Licensing Appeal Panel 85pp 26280 046 24X Fiche 50-498, 84/08/23, 8408280396

8408280452 Response to ASLB 830622 memorandum & order re reportability of Quadrex rept Quadrex rept should be examined under 10CFR50 59(e) Applicants should have provided rept to ASLB in May 1981 Certificate of Svc encl
PERLIS, R G Hearing Branch 3 DSB 338 84/08/24 43pp 26281 266 24X Fiche 50-498, 84/08/24, 8408280452

K Utility Final Safety Analysis Report (FSAR) & amends

8408010222 Forwards Amend 39 to South Texas Project, Units 1 & 2 FSAR, incorporating revised response to NRC questions & miscellaneous FSAR text revs & editorial changes
GOLDBERG, J H Houston Lighting & Power Co 84/07/27 DENTON, H Office of Nuclear Reactor Regulation, Director 8pp 25901 017 24X Fiche 50-498, 84/07/27, 8408010222

--8408010225 Amend 39 to South Texas Project, Units 1 & 2 FSAR
* Houston Lighting & Power Co 84/07/27 1, 350pp 25901 025 24X Fiche 50-498, 84/07/27, 8408010222

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408270212 Forwards refinements & changes to 840221 response to notice of violation in Insp Rept 83-22 re improvements to matl control program Current program provides adequate control of safety-related matls
OPREA, G W Houston Lighting & Power Co 84/07/30 COLLINS, J T
Region 4, Office of Director 4pp 26240 244 24X
Fiche 50-498, 84/07/30, 8408270212

8408200299 Forwards IE Insp Rpts 50-498/84-10 & 50-499/84-10 on 840625-29 No violations noted
JOHNSON, E H Region 4, Office of Director 84/08/02 OPREA, G W
Houston Lighting & Power Co 2pp 26140 106 24X
Fiche 50-498, 84/08/02, 8408200299

--8408200304 IE Insp Rpts 50-498/84-10 & 50-499/84-10 on 840625-29 No violations noted Major areas inspected safety-related structural steel
JOHNSON, C E , JAUDON, J P Region 4, Office of Director 84/08/02
6pp 26140 108 24X Fiche 50-498, 84/08/02, 8408200299

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408100132 Forwards GA vendor insp repts for info & evaluation Util should evaluate significance of findings, Ack of receipt requested W/o encl
JOHNSON, E H Region 4, Office of Director 84/08/06 OPREA, G W
Houston Lighting & Power Co 2pp 25988 283 24X
Fiche 50-498, 84/08/06, 8408100132

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408210090 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/84-04 & 50-499/84-04 Corrective actions will be reviewed during future insp
JOHNSON, E H Region 4, Office of Director 84/08/16 OPREA, G W
Houston Lighting & Power Co 2pp 26147 071 24X
Fiche 50-498, 84/08/16, 8408210090

--8408210096 Responds to NRC 840614 ltr re violations noted in IE Insp Repts 50-498/84-04 & 50-499/84-04 Corrective actions site std for nonconformance reporting revised
OPREA, G W Houston Lighting & Power Co 84/07/16 COLLINS, J T
Region 4, Office of Director 4pp 26147 073 24X
Fiche 50-498, 84/08/16, 8408210090

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co. of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408220130 Third interim deficiency rept re corrosion in safety injection sys weld Initially reported on 831020 Weld removed for analysis to determine defects & insp of stainless steel tanks initiated Next rept will be submitted by 841116
OPREA, G W Houston Lighting & Power Co 84/07/31 COLLINS, J T
Region 4, Office of Director 5pp 26189 058. 24X
Fiche 50-498, 84/07/31, 8408220130

8408150389 Final deficiency rept re rear brackets for snubbers supplie by Nuclear Power Svcs Initially reported on 840706 8 rear brackets will be replaced within 6 months
OPREA, G W Houston Lighting & Power Co 84/08/03 COLLINS, J T
Region 4, Office of Director 5pp. 26077 352 24X
Fiche 50-498, 84/08/03, 8408150389

8408240312 Third interim deficiency rept re corrosion in safety injection sys pipe weld Initially reported on 831020 Next rept will be submitted by 841116
OPREA, G W Houston Lighting & Power Co. 84/08/10 COLLINS, J T
Region 4, Office of Director 5pp. 26236 322 24X
Fiche 50-498, 84/08/10, 8408240312

8408300370 Final Deficiency Rept DER 84-016 re ASTM A-194 Grade 2H & ASTM A563 Grade A nuts Initially reported on 840713 ASTM A563 Grade A std hex nuts will be purged from site. Item considered not reportable per 10CFR50 55(e)
OPREA, G W Houston Lighting & Power Co 84/08/20 COLLINS, J T
Region 4, Office of Director. 9pp 26308 231 24X
Fiche 50-498, 84/08/20, 8408300370

DOCKETED ITEMS

TN-50-499 SOUTH TEXAS PROJECT, UNIT 2

lcation/construction stage documents & correspondence

:11 Forwards Rev 5 to QA program description for design & const
Includes revs to Bechtel & Ebasco programs
Q W Houston Lighting & Power Co 83/11/01 COLLINS, J T
, 4, Office of Director 5pp 26179 001 24X
50-498, 83/11/01, 8408210311

:0317 Rev 5 to QA program for design & const of South Texas
ject
Houston Lighting & Power Co 83/11/01 54pp 26179 006 24X
:e 50-498, 83/11/01, 8408210311

500 Forwards Rev 6 to QA program description for design & const
of facilities Changes clarify definition of Bechtel
uality policies & defines responsibilities for trend
sis
,Q W Houston Lighting & Power Co 84/04/02 COLLINS, J T
:: 4, Office of Director 3pp 26148 175 24X
50-498, 84/04/02, 8408210500

10503 Rev 6 to QA program description for design & const of
ilities
Houston Lighting & Power Co 84/04/02 190pp 26148 178 24X
he 50-498, 84/04/02, 8408210500

446 Requests exemption from 10CFR50, App A, GDC 4 re elimination
stulated circumferential & longitudinal breaks in RCS
loop piping & WCAP-10559 & WCAP-10560 Repts withheld
10CFR2 790)
ERG, J H Houston Lighting & Power Co 84/07/17 DENTON, H R
: of Nuclear Reactor Regulation, Director 4pp 25940 349
iche 50-498, 84/07/17, 8408070446

70456 "Safety Balance for Elimination of RCS Main Loop Pipe Break
tective Devices, South Texas Project, Units 1 & 2 "
ponse to NRC request for addl info re leak before break
lysis encl
Bechtel Corp 84/04/05 14pp 25940 353 24X
he 50-498, 84/07/17, 8408070446

70465 Requests withholding of WCAP-10559 & WCAP-10560, "Technical
es for Eliminating Large Primary Loop Pipe Rupture as
uctural Design Basis for South Texas Project, Units 1 &
(ref 10CFR2 790)
SEMANN, R A Westinghouse Electric Corp 84/06/01 DENTON, H R
fice of Nuclear Reactor Regulation, Director 6pp 25941 005
Fiche 50-498, 84/07/17, 8408070446

497 Summary of 840717 meeting w/Westinghouse Owners Steam
ator Tube Rupture Subgroup in Bethesda, MD re proposed
: generator tube rupture generic program List of
dees & viewgraphs encl
', B K Licensing Branch 3 84/07/31 Licensing Branch 3
25983 130 24X Fiche 50-000, 84/07/31, 8408090497

:110 Generic Ltr 84-19 to all licensees of operating reactors,
cants for OLs & holders of CPs re availability of
1 to NUREG-0933, "Prioritization of Generic Safety
s." Svc list encl
HUT, D Q Division of Licensing 84/08/06 Consolidated
:: Co of New York, Inc 18pp 26129 238 24X
50-000, 84/08/06, 8408070110

:282 Responds to 840727 submittal of Rev 7 to QA program for
n & const phase Submittal satisfies requirements of
50, App B Rev 7 acceptable
ON, E H Region 4, Office of Director 84/08/14 OPREA, G W
on Lighting & Power Co 2pp 26114 230 24X
50-498, 84/08/14, 8408170282

161 Forwards draft "in furtherance" certificate re issuance of
tion control revenue bonds, for review Necessary mods
ned certificate requested by 840915
ERG, J H Houston Lighting & Power Co 84/08/14 DENTON, H R
e of Nuclear Reactor Regulation, Director 6pp 26194 042
iche 50-498, 84/08/14, 8408220161

:275 Generic Ltr 84-20 to all licensees of operating reactors &
cants for OLs re scheduling guidance for licensee
ttals of reloads that involve unreviewed safety
ions Svc list encl
HUT, D Q Division of Licensing 84/08/20 Consolidated
:: Co of New York, Inc 17pp 26276 244 24X
50-000, 84/08/20, 8408200275

8408270355 Opposes requirement re designing for arbitrary intermediate
breaks Approval for listed alternative pipe break criteria
requested, excluding RCS primary loop Addl info supporting
request encl
GOLDBERG, J H Houston Lighting & Power Co 84/08/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 19pp 26245 021
24X Fiche 50-498, 84/08/20, 8408270355

G Adjudicatory correspondence

8408080186 Motion for enlargement of page limitation for appellate
brief in response to Citizens Concerned About Nuclear
Power, Inc 840708 brief on appeal of partial initial
decision Certificate of Svc encl Related correspondence
GUTTERMAN, A H Houston Lighting & Power Co GUTTERMAN, A H Newman
& Holtzinger DSB 824 84/08/06 Atomic Safety and Licensing
Appeal Panel 4pp 25960 243 24X Fiche 50-498, 84/08/06,
8408080186

8408150077 Response to applicant 840808 motion for enlargement of page
limitation of appellate brief to 90 pages No objection
offered Certificate of Svc encl
PIRFO, O R Hearing Branch 3 DSB 043 84/08/10 Atomic Safety
and Licensing Appeal Panel 3pp 26067 018 24X
Fiche 50-498, 84/08/10, 8408150077

8408150138 Motion for enlargement of page limitation of appellate brief
to 90 pages Certificate of Svc encl Related correspondence
PIRFO, O R Hearing Branch 3 DSB 039 84/08/11 Atomic Safety
and Licensing Appeal Panel 3pp 26067 013 24X
Fiche 50-498, 84/08/11, 8408150138

8408150176 Motion for enlargement of page limitation of appellate brief
to 90 pages Granted for ASLAB on 840813
PIRFO, O R Hearing Branch 3 DSB 054 84/08/11 Atomic Safety
and Licensing Appeal Panel ip 26066 313 24X
Fiche 50-498, 84/08/11, 8408150176

8408160196 Response opposing Citizens Concerned About Nuclear Power, Inc
840708 brief on appeal from ASLB 840314 partial initial
decision Request for de novo review & ab initio opinion w/o
merit Certificate of Svc encl
NEWMAN, J R Houston Lighting & Power Co NEWMAN, J R Newman &
Holtzinger DSB 075 84/08/13 Atomic Safety and Licensing
Appeal Panel 94pp 26091 004 24X Fiche 50-498, 84/08/13,
8408160196

8408280396 Brief in response to Citizens Concerned About Nuclear Power
brief on appeal from ASLB 840314 partial initial decision
Certificate of Svc encl
REIS, E J , PIRFO, O R Hearing Branch 3 DSB 340 84/08/23
Atomic Safety and Licensing Appeal Panel 85pp 26280 046 24X
Fiche 50-498, 84/08/23, 8408280396

8408280452 Response to ASLB 830622 memorandum & order re reportability
of Quadrex rept Quadrex rept should be examined under
10CFR50 55(e) Applicants should have provided rept to ASLB
in May 1981 Certificate of Svc encl
PERLIS, R G Hearing Branch 3 DSB 338 84/08/24 43pp
26281 266 24X Fiche 50-498, 84/08/24, 8408280452

K Utility Final Safety Analysis Report (FSAR) & amends

8408010222 Forwards Amend 39 to South Texas Project, Units 1 & 2 FSAR,
incorporating revised response to NRC questions &
miscellaneous FSAR text revs & editorial changes
GOLDBERG, J H Houston Lighting & Power Co 84/07/27 DENTON, H
Office of Nuclear Reactor Regulation, Director 8pp 25901 017
24X Fiche 50-498, 84/07/27, 8408010222

--8408010225 Amend 39 to South Texas Project, Units 1 & 2 FSAR
Houston Lighting & Power Co 84/07/27 1,350pp 25901 025
24X Fiche 50-498, 84/07/27, 8408010222

G Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture
Intrusion in Safety-Related Electrical Equipment at
Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New
York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408270212 Forwards refinements & changes to 840221 response to notice
of violation in Insp Rept 83-22 re improvements to matl
control program Current program provides adequate control of
safety-related matls
OPREA, G W Houston Lighting & Power Co 84/07/30 COLLINS, J T
Region 4, Office of Director 4pp 26240 244 24X
Fiche 50-498, 84/07/30, 8408270212

8408200299 Forwards IE Insp Repts 50-498/84-10 & 50-499/84-10 on 840625-29 No violations noted
JOHNSON, E H Region 4, Office of Director 84/08/02 OPREA, G W
Houston Lighting & Power Co 2pp 26140 106 24X
Fiche 50-498, 84/08/02, 8408200299

--8408200304 IE Insp Repts 50-498/84-10 & 50-499/84-10 on 840625-29 No violations noted Major areas inspected safety-related structural steel
JOHNSON, C E , JAUDON, J P Region 4, Office of Director 84/08/02
6pp 26140 108 24X Fiche 50-498, 84/08/02, 8408200299

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408100132 Forwards QA vendor insp repts for info & evaluation Util should evaluate significance of findings Ack of receipt requested W/o encl
JOHNSON, E H Region 4, Office of Director 84/08/06 OPREA, G W
Houston Lighting & Power Co 2pp 25988 283 24X
Fiche 50-498, 84/08/06, 8408100132

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408210090 Ack receipt of 840716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/84-04 & 50-499/84-04 Corrective actions will be reviewed during future insp
JOHNSON, E H Region 4, Office of Director 84/08/16 OPREA, G W
Houston Lighting & Power Co 2pp 26147 071 24X
Fiche 50-498, 84/08/16, 8408210090

--8408210096 Responds to NRC 840614 ltr re violations noted in IE Insp Repts 50-498/84-04 & 50-499/84-04 Corrective actions site std for nonconformance reporting revised
OPREA, G W Houston Lighting & Power Co 84/07/16 COLLINS, J T
Region 4, Office of Director 4pp 26147 073 24X
Fiche 50-498, 84/08/16, 8408210090

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408220130 Third interim deficiency rept re corrosion in safety injection sys weld Initially reported on 831020 Weld removed for analysis to determine defects & insp of stainless steel tanks initiated Next rept will be submitted by 841116
OPREA, G W Houston Lighting & Power Co 84/07/31 COLLINS, J T
Region 4, Office of Director 5pp 26189 058 24X
Fiche 50-498, 84/07/31, 8408220130

8408150389 Final deficiency rept re rear brackets for snubbers supplied by Nuclear Power Svcs Initially reported on 840706 8 rear brackets will be replaced within 6 months
OPREA, G W Houston Lighting & Power Co 84/08/03 COLLINS, J T
Region 4, Office of Director 5pp 26077 352 24X
Fiche 50-498, 84/08/03, 8408150389

8408240312 Third interim deficiency rept re corrosion in safety injection sys pipe weld Initially reported on 831020 Next rept will be submitted by 841116
OPREA, G W Houston Lighting & Power Co 84/08/10 COLLINS, J T
Region 4, Office of Director 5pp 26236 322 24X
Fiche 50-498, 84/08/10, 8408240312

8408300370 Final Deficiency Rept DER 84-016 re ASTM A-194 Grade 2H & ASTM A563 Grade A nuts Initially reported on 840713 ASTM A563 Grade A std hex nuts will be purged from site Item considered not reportable per 10CFR50 55(e)
OPREA, G W Houston Lighting & Power Co 84/08/20 COLLINS, J T
Region 4, Office of Director 9pp 26308 231 24X
Fiche 50-498, 84/08/20, 8408300370

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8408080175 Forwards proposed agenda for 840906 meeting to discuss status & project completion plans, per 840711 telcon Proposed supply sys role, ongoing programs & activities & concepts for acceptance of work will be discussed
SORENSEN, G C Washington Public Power Supply System 84/07/31
EISENHUT, D G Division of Licensing 3pp 25959 001 24X
Fiche 50-460, 84/07/31, 8408080175

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408160404 Forwards "Juan De Fuca/North American Plate Convergence Seismic or Aseismic Subduction" & "Study of Western Washington Margin & Adjacent " W/eight oversize drawings Aperture cards in PDR
SORENSEN, G C Washington Public Power Supply System 84/08/08
KNIGHTON, G W Licensing Branch 3 2pp 26084 157 24X
Fiche 50-508, 84/08/08, 8408160404

--8408160405 "Juan De Fuca/North American Plate Convergence Seismic or Aseismic Subduction "
DAVIS, G A Southern California, Univ of, Los Angeles, CA
COOMBS, H A , CROSSON, R S Washington, Univ of, Seattle, WA
84/08/31 60pp 26084 160 24X Fiche 50-508, 84/08/08, 8408160404

--8408160407 "Study of Western Washington/Oregon Margin & Adjacent Juan De Fuca Plate," final rept
KULM, V. Kulm, V 83/07/22 81pp 26084 221 24X
Fiche 50-508, 84/08/08, 8408160404

--8408160411 "Finite Element Investigation of Uplift & Strain in Puget Sound Region," final rept
MELOSH, H J Melosh, H J 83/06/01 34pp 26084 304 24X
Fiche 50-508, 84/08/08, 8408160404

--8408160413 "Juan De Fuca Plate Comparison Task JFP-2 " W/five oversize tables Aperture cards in PDR.
* Woodward-Clyde Consultants, Inc. 84/02/29 52pp 26084 337.
24X Fiche 50-508, 84/08/08, 8408160404.

--8408160414 "JFP-3A - Analysis of Geodetic Data " W/two oversize graphs Aperture cards in PDR
PELTON, J R Pelton, J R 83/05/25 150pp 26085 029 24X
Fiche 50-508, 84/08/08, 8408160404

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408170255 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " Future use of GE Type HFA relays in safety-related sys not planned
KOHLER, A D Washington Public Power Supply System 84/08/06
MARTIN, J Region 5, Office of Director 3pp 26115 271 24X
Fiche 50-508, 84/08/06, 8408170255

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070374 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408200332 Part 21 rept re tension wires on Titus Grille, Model 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested provide acceptable fix for retention
SCHNEIDER, S L Phillips Industries, Inc 84/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26133 315 24X
Fiche 50-000, 84/08/07, 8408200332

DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

Q Inspection reports, IE Bulletins & correspondence

8408170255 Responds to IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class 1E Safety Sys " Future use of GE Type HFA relays in safety-related sys not planned
KOHLER, A D Washington Public Power Supply System 84/08/06
MARTIN, J Region 5, Office of Director 3pp 26115 271 24X
Fiche 50-508, 84/08/06, 8408170255

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8408230318 Requests remittance of fee for 830121 application for extension of const completion dates
DIGGS, R M License Fee Management Branch 84/08/16 PARRIS, H G
Tennessee Valley Authority 2pp 26236 098 24X
Fiche 50-000, 84/08/16, 8408230318

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

A Application/construction stage documents & correspondence

8408230318 Requests remittance of fee for 830121 application for extension of const completion dates
DIGGS, R M License Fee Management Branch 84/08/16 PARRIS, H G
Tennessee Valley Authority 2pp 26236 098 24X
Fiche 50-000, 84/08/16, 8408230318

DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865.047 24X Fiche 50-000, 84/07/27, 8407250229

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co. of New York, Inc 122pp. 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06. Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp. 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8408090483 Forwards request for addl info re isolation devices used in reactor protective sys Response requested within 2 wks of ltr receipt
KNIGHTON, G W Licensing Branch 3 84/07/25 VAN BRUNT, E E
Arizona Public Service Co 7pp 25983 153 24X
Fiche 50-528, 84/07/25, 8408090483

8408090523 Summary of 840705 & 06 mgt meetings w/util, Bechtel & C-E at site & in Phoenix, AZ, respectively, re actions that need to be taken prior to fuel load Attendance list & viewgraphs encl
LICITRA, E A Licensing Branch 3 84/07/27 Licensing Branch 3
80pp 25983 340 24X Fiche 50-528, 84/07/27, 8408090523

8408060319 Notifies that response to 840702 request for info re surveillance requirements for ESF actuation sys will be provided by 840901
VAN BRUNT, E E Arizona Public Service Co 84/07/31 KNIGHTON, G
Licensing Branch 3 2pp 25936 036 24X Fiche 50-528, 84/07/31, 8408060319

8408030144 Forwards table of Type A variables & revs & updates of compliance to Reg Guide 1 97, Rev 2, Types B, C & D variable requirements, in response to 831203 request.
VAN BRUNT, E E Arizona Public Service Co 84/08/01 KNIGHTON, G
Licensing Branch 3 28pp 25911.161 24X Fiche 50-528, 84/08/01, 8408030144

8408080048 Informs that response to NRC 840627 info request re control element assembly shroud will be be submitted by 840815
VAN BRUNT, E E, Arizona Public Service Co 84/08/02 KNIGHTON, G W
Licensing Branch 3, 1p 25961 036 24X Fiche 50-528, 84/08/02, 8408080048

8408100127 Forwards "Calculation of Trip Setpoint Values, Plant Protection Sys," in response to 830620 ltr
VAN BRUNT, E E Arizona Public Service Co 84/08/02 KNIGHTON, G
Licensing Branch 3 1p 25991.042 24X Fiche 50-528, 84/08/02, 8408100127

--8408100137 Rev 0 to "Calculation of Trip Setpoint Values, Plant Protection Sys,"
* Combustion Engineering, Inc CEN-286(V) R00 84/07/31 123pp
25991 043 24X Fiche 50-528, 84/08/02, 8408100127

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408200255 Informs of launching of new program to seek out concerns re const & safe operation Ltr to all const workers inviting rept of concerns for investigation encl
TURLEY,K Arizona Public Service Co 84/08/06 MARTIN,J Region 5, Office of Director 3pp 26133 208 24X Fiche 50-528,84/08/06, 8408200255

8408130274 Forwards solid radwaste process control program, in response to OH Knighton 840403 ltr to EE Van Brunt Solid radwaste process control program incorporates 830630 response to 830415 request for addl info
VAN BRUNT,E E Arizona Public Service Co 84/08/07 KNIGHTON,G Licensing Branch 3 2pp 26010 008 24X Fiche 50-528,84/08/07, 8408130274

--8408130277 Solid radwaste process control program
* Arizona Public Service Co 84/08/07 9pp 26010 010 24X
Fiche 50-528,84/08/07,8408130274

8408140227 Advises that GE Willer medical problem, disclosed on NRC Form 396, will not impair ability to perform assigned job tasks Evaluation based on examining physician statement & mgt observation of past performance
VAN BRUNT,E E Arizona Public Service Co 84/08/07 MARTIN,J B Region 5, Office of Director 1p 26055 309 24X
Fiche 50-528,84/08/07,8408140227

8408150207 Forwards suppls to util 840702 ltr re organizational structure, based on 840716 discussion Suppls include removal of Note b ref from FSAR Page 13 1-28, Note b from Page 13 1-29 & update to response to Question 13A 18
VAN BRUNT,E E Arizona Public Service Co 84/08/13 KNIGHTON,G Licensing Branch 3 4pp 26067 125 24X Fiche 50-528,84/08/13, 8408150207

8408230367 Notification of 840822 & 23 meetings w/util, Bechtel & DOE at site to discuss evaluation of effects of water leaks on foundation stability
LICITRA,E A Licensing Branch 3 84/08/14 KNIGHTON,G W
Licensing Branch 3 4pp 26230 350 24X Fiche 50-528,84/08/14, 8408230367

8408230369 Forwards proof & review Tech Specs for review & comments Final draft will be submitted 30 days prior to OL issuance W/o encl
KNIGHTON,G W Licensing Branch 3 84/08/14 VAN BRUNT,E E
Arizona Public Service Co 2pp 26230 348 24X
Fiche 50-528,84/08/14,8408230369

8408170348 Forwards addl fabrication info on Unit 1 control element assembly shroud assembly, per 840627 request Seventeen proprietary oversize drawings encl Drawings withheld (ref 10CFR2 790) Aperture card available in Central Files
VAN BRUNT,E E Arizona Public Service Co 84/08/15 KNIGHTON,G Licensing Branch 3 4pp 26145 001 24X Fiche 50-528,84/08/15, 8408170348

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408240261 Forwards Rev 2 to "Pump & Valve Inservice Testing Program" & proposed changes to Rev 2 W/46 oversize drawings Aperture cards available in PDR
VAN BRUNT,E E Arizona Public Service Co 84/08/21 KNIGHTON,G Licensing Branch 3 3pp 26227 018 24X Fiche 50-528,84/08/21, 8408240261

--8408240263 Rev 2 to "Pump & Valve Inservice Testing Program "
* Arizona Public Service Co 84/07/16 204pp 26227 021 24X
Fiche 50-528,84/08/21,8408240261

8408240289 Forwards mod to deviation request in FSAR Amend 13, Sections 9B 2 1,9B 2 2 & Figures 9B-8,9,10 & 11 Updated response to FSAR Question 9A-98 Part (2) also encl Changes will be incorporated in next FSAR amend
VAN BRUNT,E E Arizona Public Service Co 84/08/21 KNIGHTON,G
Licensing Branch 3 15pp 26223 199 24X Fiche 50-528,84/08/21, 8408240289

D NRC Draft/Final Environmental Statements, suppls & correspondence

8407120136 Appeals denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similiar environ documents & FOIA fee waiver decision
RYAN,J A Streich, Lang, Weeks & Cardon 84/03/27 Office of the Executive Director for Operations 4pp 25557 018 24X
Fiche 50-528,84/03/27,8407120136

8407120142 Responds to appeal re denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similar environ documents Appeal granted
DIRCKS,W J Office of the Executive Director for Operations
84/05/21 RYAN,J A Streich, Lang, Weeks & Cardon 1p 25557 022
24X Fiche 50-528,84/05/21,8407120142

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408130391 Forwards update to 830127 description of natural circulation test program & "Evaluation of Natural Circulation Cooldown Test Performed at San Onofre Nuclear Generating Station " Confirmatory Item 7 in NUREG-0857, SSER 5 closed
VAN BRUNT,E E Arizona Public Service Co 84/08/07 KNIGHTON,G
Licensing Branch 3 23pp 26006 170 24X Fiche 50-528,84/08/07, 8408130391

8408270133 Forwards "Containment Ultimate Capacity Analysis," per NUREG-0857, "SER re Operation of Palo Verde Nuclear Generating Station, Units 1,2 & 3 " Analysis should close license condition discussed in Section 3 8 1
VAN BRUNT,E E Arizona Public Service Co 84/08/20 KNIGHTON,G
Licensing Branch 3 3pp 26245 061 24X Fiche 50-528,84/08/20, 8408270133

--8408270140 "Containment Ultimate Capacity Analysis "
* Arizona Public Service Co 84/08/31 38pp 26245 064 24X
Fiche 50-528,84/08/20,8408270133

F Security, medical, emergency & fire protection plans

8408090448 Notification of 840730-31 & 0801 meetings w/util & Comex in Phoenix,AZ & site, respectively, to discuss open issues in onsite emergency planning
LICITRA,E A Licensing Branch 3 84/07/25 KNIGHTON,G W
Licensing Branch 3 2pp 25983 213 24X Fiche 50-528,84/07/25, 8408090448

8408090523 Summary of 840705 & 06 mgt meetings w/util, Bechtel & C-E at site & in Phoenix,AZ, respectively, re actions that need to be taken prior to fuel load Attendance list & viewgraphs encl
LICITRA,E A Licensing Branch 3 84/07/27 Licensing Branch 3
80pp 25983 340 24X Fiche 50-528,84/07/27,8408090523

8408130182 Forwards request for addl info re evacuation time estimate analysis for emergency plan Response requested within 2 wks of ltr receipt
KNIGHTON,G W Licensing Branch 3 84/07/27 VAN BRUNT,E E
Arizona Public Service Co 3pp 26011 351 24X
Fiche 50-528,84/07/27,8408130182

8408130160 Confirms 840625 telcon re outcome of 840531 appeal meeting re alternate shutdown capability Appeal granted, based on listed design features for plant & commitment to perform confirmatory PRA analysis
NOVAK,T M Assistant Director for Licensing 84/07/30 VAN
BRUNT,E E Arizona Public Service Co 2pp 26034 351 24X
Fiche 50-528,84/07/30,8408130160

8408030097 Forwards response to NRC 840605 comments re emergency procedure generation package Steps to verify adequate instruments & controls available for operator to perform assigned task incorporated into validation procedure
VAN BRUNT,E E Arizona Public Service Co 84/08/01 KNIGHTON,G
Licensing Branch 3 7pp 25904 342 24X Fiche 50-528,84/08/01, 8408030097

8408230310 Confirms 840822-24 audit of emergency operating procedures (EOPs) Five sets of current EOPs, along w/procedure generation package rev, should be provided to NRC by 840813
KNIGHTON,G W Licensing Branch 3 84/08/02 VAN BRUNT,E E
Arizona Public Service Co 2pp 26236 100 24X
Fiche 50-528,84/08/02,8408230310

8408300125 Forwards Insp Rept 50-528/84-26 on 840716-20 No violations or deficiencies noted
SCHUSTER,M D Region 5, Office of Director 84/08/03 VAN BRUNT,E E Arizona Public Service Co 2pp 26307 225 24X Fiche 50-528,84/08/03,8408300125

--8408300127 Insp Rept 50-528/84-26 on 840716-20 No violations or deficiencies noted Major areas inspected open & improvement items identified during emergency preparedness preoperational 830411-22 insp
TEMPLE,G M , FISH,R F , PRENDERGAST,K Region 5, Office of Director 84/08/03 9pp 26307 227 24X Fiche 50-528,84/08/03, 8408300125

8408300383 Forwards Insp Repts 50-528/84-25, 50-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation
BISHOP,T W Region 5, Office of Director 84/08/08 VAN BRUNT,E E Arizona Public Service Co 2pp 26308 122 24X Fiche 50-528,84/08/08,8408300383

--8408300390 Notice of violation from insp on 840709-13
MILLER,L Region 5, Office of Director 84/08/08 2pp 26308 124 24X Fiche 50-528,84/08/08,8408300383

--8408300397 Notice of deviation from insp on 840709-13
MILLER,L Region 5, Office of Director 84/08/08 1p 26308 126 24X Fiche 50-528,84/08/08,8408300383

--8408300407 Insp Repts 50-528/84-25, 50-529/84-19 & 50-530/84-12 on 840709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event
CLARK,C , NARBUT,P P , MILLER,L. Region 5, Office of Director 84/08/03 24pp 26308 127 24X Fiche 50-528,84/08/08,8408300383

8408200599 Submits Rev 4 to emergency plan Rev addresses NRC comments, is aligned more concisely w/current operating procedures & clarifies barrier approach to emergency action levels
VAN BRUNT,E E Arizona Public Service Co 84/08/15 KNIGHTON,G Licensing Branch 3 3pp 26137 052 24X Fiche 50-528,84/08/15, 8408200599

--8408200600 Rev 4 to emergency plan
* Arizona Public Service Co 84/05/31 83pp 26137 055 24X Fiche 50-528,84/08/15,8408200599

8408200112 Forwards "Evaluation Time Analysis,10-Mile Emergency Planning Zone,Arizona Div of Emergency Svcs" & response to 840727 request for addl info
VAN BRUNT,E E Arizona Public Service Co 84/08/16 KNIGHTON,G Licensing Branch 3 4pp 26132 321 24X Fiche 50-528,84/08/16, 8408200112

--8408200334 "Evacuation Time Analysis,10-Mile Emergency Planning Zone, Arizona Div of Emergency Svcs "
* Arizona, State of BLUHM,R B Maricopa County, AZ 84/01/31 22pp 26132 325 24X Fiche 50-528,84/08/16,8408200112

8408200217 Forwards Rev 5 to emergency action levels Rev addresses comments raised at 840731 meeting re security,external events & challenge/failure of fission product barriers
VAN BRUNT,E E Arizona Public Service Co 84/08/16 KNIGHTON,G Licensing Branch 3 3pp 26133 099 24X Fiche 50-528,84/08/16, 8408200217

--8408200224 Rev 5 to emergency action levels
* Arizona Public Service Co 84/08/31 86pp 26133 102 24X Fiche 50-528,84/08/16,8408200217

8408270260 Requests approval of two temporary deviations in emergency preparedness plan from goals for augmentation of emergency response organization in Suppl 1 to NUREG-0737 Nature & duration of deviations encl
VAN BRUNT,E E Arizona Public Service Co 84/08/20 KNIGHTON,G Licensing Branch 3 27pp 26243 131 24X Fiche 50-528,84/08/20, 8408270260

K Utility Final Safety Analysis Report (FSAR) & amends

8408030102 Forwards page change list for Amend 13 to FSAR Replacement of original pages requested
* Bechtel Corp 84/07/31 Office of Nuclear Reactor Regulation, Director 3pp 25904 336 24X Fiche 50-528,84/07/31,8408030102

8408030142 Forwards corrected Pages 3 & 4 to list of effective pages for Palo Verde FSAR,Amend 13
* Bechtel Corp 84/07/31 Office of Nuclear Reactor Regulation, Director 3pp 25915 325 24X Fiche 50-528,84/07/31,8408030142

8408030093 Forwards page change list for Palo Verde Nuclear Generating Station FSAR,Amend 13,Pages A through J
GILMORE,T Bechtel Corp 84/08/01 Office of Nuclear Reactor Regulation, Director 6pp 25916 031 24X Fiche 50-528,84/08/01, 8408030093

8408060075 Forwards info revising Insert 1 to FSAR,Page 14 2-3 re initial test program
VAN BRUNT,E E Arizona Public Service Co 84/08/01 KNIGHTON,G W Licensing Branch 3 7pp 25933 215 24X Fiche 50-528,84/08/01, 8408060075

8408010215 Amend 13 to FSAR for Palo Verde Nuclear Generating Station, Units 1,2 & 3 W/34 oversize figures Aperture cards available in PDR W/840801 ltr
VAN BRUNT,E E Arizona Public Service Co 84/08/31 1408pp 25999 122 24X Fiche 50-528,84/08/31,8408010215

Q Inspection reports, IE Bulletins & correspondence

8406230210 "Region V Outstanding Items Rept Open & Closed "
* Region 5, Office of Director 84/06/12 57pp 25129 101 24X Fiche 50-528,84/06/12,8406230210

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000,84/07/27,8407250229

8408300187 Forwards Insp Repts 50-528/84-23 & 50-529/84-17 on 840602-0701 No noncompliance noted
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 84/08/02 VAN BRUNT,E E Arizona Public Service Co 2pp 26308 014 24X Fiche 50-528,84/08/02,8408300187

--8408300195 Insp Repts 50-528/84-23 & 50-529/84-17 on 840602-0701 No violations noted Major areas inspected preoperational testing activities,maint,review of maint & followup on TMI Lessons Learned implementation
ZIMMERMAN,R , FIORELLI,G , BOSTED,C Region 5, Office of Director 84/08/01 12pp 26308 016 24X Fiche 50-528,84/08/02, 8408300187

8408300125 Forwards Insp Rept 50-528/84-26 on 840716-20 No violations or deficiencies noted
SCHUSTER,M D Region 5, Office of Director 84/08/03 VAN BRUNT,E E Arizona Public Service Co 2pp 26307 225 24X Fiche 50-528,84/08/03,8408300125

--8408300127 Insp Rept 50-528/84-26 on 840716-20 No violations or deficiencies noted Major areas inspected open & improvement items identified during emergency preparedness preoperational 830411-22 insp
TEMPLE,G M , FISH,R F , PRENDERGAST,K Region 5, Office of Director 84/08/03 9pp 26307 227 24X Fiche 50-528,84/08/03, 8408300125

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 198 24X Fiche 50-000,84/08/06,8408010337

8408300094 Forwards Insp Repts 50-528/84-21, 50-529/84-16 & 50-530/84-10 on 840402-0531 & notice of violation
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 84/08/07 VAN BRUNT,E E Arizona Public Service Co 2pp 26306 141 24X Fiche 50-528,84/08/07,8408300094

--8408300100 Notice of violation from insp on 840402-0531, YOUNG,T Region 5, Office of Director 84/08/07 1p 26306 143 24X Fiche 50-528,84/08/07,8408300094

--8408300103 Insp Repts 50-528/84-21, 50-529/84-16 & 50-530/84-10 on 840402-0531 Violation noted failure to control mods on Units 1 & 2 diesel generator bldg wall mounted instruments
VORDERBRUEGGEN, YOUNG,T Region 5, Office of Director 84/08/07 7pp 26306 144 24X Fiche 50-528,84/08/07,8408300094

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408300383 Forwards Insp Repts 50-528/84-25,50-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation
BISHOP,T W Region 5, Office of Director 84/08/08 VAN BRUNT,E E Arizona Public Service Co 2pp 26308 122 24X
Fiche 50-528,84/08/08,8408300383

--8408300390 Notice of violation from insp on 840709-13
MILLER,L Region 5, Office of Director 84/08/08 2pp
26308 124 24X Fiche 50-528,84/08/08,8408300383

--8408300397 Notice of deviation from insp on 840709-13
MILLER,L Region 5, Office of Director 84/08/08 1p
26308 126 24X Fiche 50-528,84/08/08,8408300383

--8408300407 Insp Repts 50-528/84-25,50-529/84-19 & 50-530/84-12 on 840709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event
CLARK,C , SORENSEN,R C , HOLLENBACH,D Region 5, Office of Director 84/08/03 24pp 26308 127 24X Fiche 50-528,84/08/08, 8408300383

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408220051 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE insp repts conducted between 840501-0601
BISHOP,T W Region 5, Office of Director 84/08/16 VAN BRUNT,E E Arizona Public Service Co 1p 26193 237 24X
iche 50-528,84/08/16,8408220051

8408220071 Responds to NRC 840722 ltr re violations noted in IE insp repts conducted between 840501-0601 Corrective actions Pump A disassembled & defective seal replaced w/new seal Walkdown team established
VAN BRUNT,E E Arizona Public Service Co 84/07/20 BISHOP,T W
Region 5, Office of Director 10pp 26193 238 24X
Fiche 50-528,84/08/16,8408220051

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

S Reportable occurrences, LERs & related correspondence

8408030048 Final Deficiency Rept DER 83-56,Rev 1 re discrepancies w/ Anchor-Darling MSIVs Initially reported on 830808 Larger hydraulic reservoir w/baffles installed in each MSIV & feedwater isolation valve
VAN BRUNT,E E Arizona Public Service Co 84/04/13 BISHOP,T W
Region 5, Office of Director 7pp 25917 330 24X
Fiche 50-528,84/04/13,8408030048

8408020232 Corrected Rev 1 to Final Deficiency Rept DER 83-56 re discrepancies w/MSIV mfg by Anchor-Darling Initially reported on 830808 Vendor Instruction Manual E9023-9 revised Also reported per Part 21
VAN BRUNT,E E Arizona Public Service Co 84/07/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 7pp
25898 046 24X Fiche 50-528,84/07/13,8408020232

8408030302 Final Deficiency Rept DER 84-02 re rust,scale & pitting in clevis & arm of several safety injection & CH valves Rust insignificant Deficiency determined not reportable under 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/07/13 BISHOP,T W
Region 5, Office of Director 2pp 25917 115 24X
Fiche 50-528,84/07/13,8408030302

8408010377 Interim Deficiency Rept DER 84-18 re wiring error on LPSI pump B switch CS-3 Initially reported on 840326 Final rept will be submitted by 840822
VAN BRUNT,E E Arizona Public Service Co 84/07/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
25866 288 24X Fiche 50-528,84/07/16,8408010377

8408010381 Interim Deficiency Rept DER 84-09 re ITT/Barton Model 763 transmitters not meeting specs Initially reported on 840229 Final rept will be submitted by 840824
VAN BRUNT,E E Arizona Public Service Co 84/07/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
25866 290 24X Fiche 50-528,84/07/16,8408010381

8408010384 Interim Deficiency Rept DER 83-80 re main feedwater isolation valves closing in 20 s instead of Tech Spec required 5 s Initially reported on 831122 Final rept will be submitted by 840823
VAN BRUNT,E E Arizona Public Service Co 84/07/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
25866 286 24X Fiche 50-528,84/07/16,8408010384

8408030240 Interim Deficiency Rept DER 83-63 re HPSI isolation valves mfg by Borg-Warner failing to open against pump A & B flows Initially reported on 830923 Time extension requested due to extensive investigation Next rept by 840831
VAN BRUNT,E E Arizona Public Service Co 84/07/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
25917 221 24X Fiche 50-528,84/07/16,8408030240

8408010346 Final Deficiency Rept DER 82-37,Rev 1,re Class 1E wiring termination crimped w/less pressure than specified Work Plant Procedure/QC Instruction 255 0 revised to require maint program
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 12pp
25866 310 24X Fiche 50-528,84/07/18,8408010346

8408010388 Interim Deficiency Evaluation Rept 84-43 re HPSI 3-inch gate valve failing to open Initially reported on 840622 Conditions not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
25866 281 24X Fiche 50-528,84/07/18,8408010388

8408030053 Interim Potential Deficiency Rept DER 84-42 re replacement of environmentally qualified torque switches w/unqualified switches Initially reported on 840618 Final rept expected by 840820
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Region 5, Office of Director 3pp 25917 327 24X
Fiche 50-528,84/07/18,8408030053

8408080499 Final Deficiency Rept DER 83-75 re improper torquing of bolts on two DD12ASA panel filler assemblies Bolts retorqued Deficiency not reportable under 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/07/24 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 5pp
25975 232 24X Fiche 50-528,84/07/24,8408080499

8408080529 Rev 1 to final Deficiency Rept DER 81-49 re erroneous readings on NSSS water level transmitters due to variations of water leg Condensate pots for steam generator & pressurizer level measurements installed on root valves
VAN BRUNT,E E Arizona Public Service Co, 84/07/24 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
25975 298 24X Fiche 50-528,84/07/24,8408080529,

8408090012 Final Deficiency Rept DER 84-08 re failure of ITT/Barton Model 763 transmitters to meet specs PPS setpoints revised on existing transmitters & Barton working on physical mod to meet specs Also reportable under Part 21
VAN BRUNT,E E Arizona Public Service Co 84/07/24 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
25995 011 24X Fiche 50-528,84/07/24,8408090012

8408130172 Interim Deficiency Rept DER 83-81 re manufacturing defect in Gulfally Schedule 160 SS pipe Initially reported on 831128 Due to extensive investigation & evaluation required,final rept will be delayed until 840830
VAN BRUNT,E E Arizona Public Service Co 84/07/27 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26010 036 24X Fiche 50-528,84/07/27,8408130172

8408130332 Interim Deficiency Rept DER 84-09 re CAD welding for cathodic protection ground connection Initially reported on 840229 Final rept will be submitted by 840830
VAN BRUNT,E E Arizona Public Service Co 84/07/27 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26010 303 24X Fiche 50-528,84/07/27,8408130332

8408130303 Final Deficiency Rept DER 84-19 re improperly tagged or marked blind flanges removed from piping sys Initially reported on 840430 Deficiency not reportable per 10CFR50 55(e) or Part 21
VAN BRUNT,E E Arizona Public Service Co 84/07/30 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
26010 251 24X Fiche 50-528,84/07/30,8408130303

8408130344 Interim Deficiency Rept DER 82-80 re low insulation resistance values or terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept by 840817
VAN BRUNT,E E Arizona Public Service Co 84/07/30 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26010 222 24X Fiche 50-528,84/07/30,8408130344

8408160192 Final Deficiency Rept DER 84-10 re resistance temp detectors Caused by torsional twisting of element & sheath during honing operation,resulting in broken internal wire Item not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/08/01 BISHOP,T W
Region 4, Office of Director 3pp 26106 334 24X
Fiche 50-528,84/08/01,8408160192

8408170384 Final Deficiency Rept DER 84-22 re control element assembly shroud support contaminated w/oil Initially reported on 840420 Shroud cleaned & inspected & drip pan installed to contain possible leakage Also reported per Part 21
VAN BRUNT,E E Arizona Public Service Co 84/08/01 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
26129 099 24X Fiche 50-528,84/08/01,8408170384

8408160480 Final Deficiency Rept DER 84-16 re ESF actuation sys relay cabinet baseplates Initially reported on 840321 Cabinet backs will be reinforced w/3/8-inch thick vertical stiffener plate Also reportable under Part 21
VAN BRUNT,E E Arizona Public Service Co 84/08/02 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
26107 292 24X Fiche 50-528,84/08/02,8408160480

8408160506 Final Deficiency Rept DER 83-78 re lack of users test documentation & controlling procedure for rock bolt expansion anchors Initially reported on 831109 Item not reportable under 10CFR50 55(e) & Part 21
VAN BRUNT,E E Arizona Public Service Co 84/08/02 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 9pp
26107 326 24X Fiche 50-528,84/08/02,8408160506

8408220128 Interim Deficiency Rept DER 84-33 re incorrectly installed hanger support assembly Initially reported on 840504 Due to extensive investigation,final rept will be available 840831 instead of 840810
VAN BRUNT,E E Arizona Public Service Co 84/08/06 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26188 348 24X Fiche 50-528,84/08/06,8408220128

8408220143 Interim Deficiency Rept DER 84-44 re fatigue failures of Gaulin charging pumps Initially reported on 840706 Bechtel investigating Final rept to be completed by 840927 Reported under Part 21 by Northeast Utils
VAN BRUNT,E E Arizona Public Service Co 84/08/06 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 3pp
26188 065 24X Fiche 50-528,84/08/06,8408220143

8408200332 Part 21 rept re tension wires on Titus Grille,Model 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested provide acceptable fix for retention
SCHNEIDER,S L Phillips Industries, Inc 84/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26133 315 24X
Fiche 50-000,84/08/07,8408200332

8408200333 Part 21 rept re tension wires used for adjustment of blades on Grille Model 272 not remaining in place when blades closed Review & testing conducted to identify number of grilles & rework methods to be utilized
SCHNEIDER,S L Phillips Industries, Inc 84/08/07 STRAIT,R
Arizona Public Service Co 1p 26132 360 24X
Fiche 50-528,84/08/07,8408200333

8408200297 Interim Deficiency Rept DER 84-34 re critical friction-type high strength connectors Due to extensive evaluation,next rept delayed until 840904
VAN BRUNT,E E Arizona Public Service Co 84/08/09 BISHOP,T W
Region 5, Office of Director 2pp 26140 090 24X
Fiche 50-528,84/08/09,8408200297

8408200322 Final Deficiency Rept DER 83-61 re C-E low pressure safety injection pump failure to start & produce required head Case wear rings replaced & clearance between impeller & casing increased Proprietary CEN-285 (V)-P encl
VAN BRUNT,E E Arizona Public Service Co 84/08/09 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 40pp
26133 318 24X Fiche 50-528,84/08/09,8408200322

8408200285 Final Deficiency Rept DER 83-82 re improper bend radius in diesel generator control cabinets Initially reported on 840103 Forwards "Technical Rept for Palo Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63619 "
VAN BRUNT,E E Arizona Public Service Co 84/08/10 BISHOP,T W
Region 5, Office of Director 13pp 26139 307 24X
Fiche 50-528,84/08/10,8408200285

---8408200288 "Technical Rept for Palo Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63619 "
MONTGOMERY,R , BEASLEY,D Anaconda Co (subs of Atlantic Richfield Co) 84/01/24 11pp 26139 320 24X
Fiche 50-528,84/08/10,8408200285

8408280302 Interim Deficiency Rept DER 83-57 re cracks in control element assembly shroud Initially reported on 830729 Requests extension until 840915 for submittal of final rept to allow for post-demonstration test insp evaluation
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 161 24X Fiche 50-528,84/08/13,8408280302

8408280317 Interim Deficiency Rept DER 83-49 re broken impeller blades & diffuser bolts broken/loose in reactor coolant pumps Initially reported on 830715 Time extension until 840915 for final rept requested for post-demonstration test insp
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 257 24X Fiche 50-528,84/08/13,8408280317

8408280325 Interim Deficiency Rept DER 83-51 re auxiliary feedwater pump failure to meet requirements of hot functional test Initially reported on 840802 Extension until 840915 requested for submittal of post-demonstration test rept
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Region 5, Office of Director 2pp 26282 273 24X
Fiche 50-528,84/08/13,8408280325

8408280335 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on 830629 Extension for submittal of final rept from 840815 to 840915 requested due to need for evaluation of post-demonstration test insp
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 239 24X Fiche 50-528,84/08/13,8408280335

8408280357 Interim Deficiency Rept DER 84-26 re improperly tested or adjusted plunger interlock Initially reported on 840510 Final rept will be submitted by 840915
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 230 24X Fiche 50-528,84/08/13,8408280357

8408280204 Interim Deficiency Rept DER 84-25 re containment supply register failure to cycle Initially reported on 840501 Galvanized wire will be replaced w/stainless steel wire to gain higher tensile strength Next rept expected by 840921
VAN BRUNT,E E Arizona Public Service Co 84/08/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 3pp
26282 166 24X Fiche 50-528,84/08/16,8408280204

8408280263 Interim Deficiency Rept DER 84-45 re spot welding on skid mounted indication & control Initially reported on 840717 Kaman Instrumentation will perform torque test for site testing of stud welds Next rept expected by 840928
VAN BRUNT,E E Arizona Public Service Co 84/08/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs. 3pp
26282 169 24X Fiche 50-528,84/08/16,8408280263

8408280275 Rev 1 to interim Deficiency Rept DER 82-24 re Limitorque valve operators found loose on valve bodies Valves will be stroked to full open, hex bolts loosened & retorqued per vendor requirements Next rept by 840918
VAN BRUNT, E E Arizona Public Service Co 84/08/16 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 26282 172 24X Fiche 50-528, 84/08/16, 8408280275

8408280297 Interim Deficiency Rept DER 84-44 re refueling water tank penetration sleeves Initially reported on 840717 Bechtel evaluation of reportability & corrective action in progress
VAN BRUNT, E E Arizona Public Service Co 84/08/16 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 26282 150 24X Fiche 50-528, 84/08/16, 8408280297

8408280283 Interim Deficiency Rept DER 82-80 re low insulation resistance values for terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept expected by 840903
VAN BRUNT, E E Arizona Public Service Co 84/08/17 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 26282 178 24X Fiche 50-528, 84/08/17, 8408280283

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8408090483 Forwards request for addl info re isolation devices used in reactor protective sys Response requested within 2 wks of ltr receipt
KNIGHTON, G W Licensing Branch 3 84/07/25 VAN BRUNT, E E Arizona Public Service Co 7pp 25983 153 24X Fiche 50-528, 84/07/25, 8408090483

8408060319 Notifies that response to 840702 request for info re surveillance requirements for ESF actuation sys will be provided by 840901
VAN BRUNT, E E Arizona Public Service Co 84/07/31 KNIGHTON, G Licensing Branch 3 2pp 25936 036 24X Fiche 50-528, 84/07/31, 8408060319

8408030144 Forwards table of Type A variables & revs & updates of compliance to Reg Guide 1 97, Rev 2, Types B, C & D variable requirements, in response to 831203 request
VAN BRUNT, E E Arizona Public Service Co 84/08/01 KNIGHTON, G Licensing Branch 3 28pp 25911 161 24X Fiche 50-528, 84/08/01, 8408030144

8408080048 Informs that response to NRC 840627 info request re control element assembly shroud will be be submitted by 840815
VAN BRUNT, E E Arizona Public Service Co 84/08/02 KNIGHTON, G W Licensing Branch 3 1p 25961 036 24X Fiche 50-528, 84/08/02, 8408080048

8408100127 Forwards "Calculation of Trip Setpoint Values, Plant Protection Sys," in response to 830620 ltr
VAN BRUNT, E E Arizona Public Service Co 84/08/02 KNIGHTON, G Licensing Branch 3 1p 25991 042 24X Fiche 50-528, 84/08/02, 8408100127

--8408100137 Rev 0 to "Calculation of Trip Setpoint Values, Plant Protection Sys "
* Combustion Engineering, Inc CEN-286(V) R00 84/07/31 123pp 25991 043 24X Fiche 50-528, 84/08/02, 8408100127

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000, 84/08/06, 8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY, P P Operating Reactors Assessment Branch 84/08/06 HOLAHAN, G M Operating Reactors Assessment Branch 13pp 25991 350 24X Fiche 50-000, 84/08/06, 8408090317

8408200255 Informs of launching of new program to seek out concerns re const & safe operation Ltr to all const workers inviting rept of concerns for investigation encl
TURLEY, K. Arizona Public Service Co 84/08/06 MARTIN, J Region 5, Office of Director 3pp 26133 208 24X Fiche 50-528, 84/08/06, 8408200255

8408130274 Forwards solid radwaste process control program, in response to GW Knighton 840403 ltr to EE Van Brunt Solid radwaste process control program incorporates 830630 response to 830415 request for addl info
VAN BRUNT, E E Arizona Public Service Co 84/08/07 KNIGHTON, G Licensing Branch 3 2pp 26010 008 24X Fiche 50-528, 84/08/07, 8408130274

--8408130277 Solid radwaste process control program
* Arizona Public Service Co 84/08/07 9pp 26010 010 24X Fiche 50-528, 84/08/07, 8408130274

8408140227 Advises that OE Willer medical problem, disclosed on NRC Form 396, will not impair ability to perform assigned job tasks Evaluation based on examining physician statement & mgt observation of past performance
VAN BRUNT, E E Arizona Public Service Co 84/08/07 MARTIN, J B Region 5, Office of Director 1p 26055 309 24X Fiche 50-528, 84/08/07, 8408140227

8408150207 Forwards supplS to util 840702 ltr re organizational structure, based on 840716 discussion SupplS include removal of Note b ref from FSAR Page 13 1-28, Note b from Page 13 1-29 & update to response to Question 13A 18
VAN BRUNT, E E Arizona Public Service Co 84/08/13 KNIGHTON, G Licensing Branch 3 6pp 26067 125 24X Fiche 50-528, 84/08/13, 8408150207

8408230367 Notification of 840822 & 23 meetings w/util, Bechtel & DOE at site to discuss evaluation of effects of water leaks on foundation stability
LICITRA, E A Licensing Branch 3 84/08/14 KNIGHTON, G W Licensing Branch 3 4pp 26230 350 24X Fiche 50-528, 84/08/14, 8408230367

8408170348 Forwards addl fabrication info on Unit 1 control element assembly shroud assembly, per 840627 request Seventeen proprietary oversize drawings encl Drawings withheld (ref 10CFR2 790) Aperture card available in Central Files
VAN BRUNT, E E Arizona Public Service Co 84/08/15 KNIGHTON, G Licensing Branch 3 4pp 26145 001 24X Fiche 50-528, 84/08/15, 8408170348

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50-000, 84/08/20, 8408200275

8408240261 Forwards Rev 2 to "Pump & Valve Inservice Testing Program" & proposed changes to Rev 2 W/46 oversize drawings Aperture cards available in PDR
VAN BRUNT, E E Arizona Public Service Co 84/08/21 KNIGHTON, G Licensing Branch 3 3pp 26227 018 24X Fiche 50-528, 84/08/21, 8408240261

--8408240263 Rev 2 to "Pump & Valve Inservice Testing Program "
* Arizona Public Service Co 84/07/16 206pp 26227 021 24X Fiche 50-528, 84/08/21, 8408240261

8408240289 Forwards mod to deviation request in FSAR Amend 13, Sections 9B 2 1, 9B 2 2 & Figures 9B-8, 9, 10 & 11 Updated response to FSAR Question 9A-98 Part (2) also encl Changes will be incorporated in next FSAR amend
VAN BRUNT, E E Arizona Public Service Co 84/08/21 KNIGHTON, G Licensing Branch 3 15pp 26223 199 24X Fiche 50-528, 84/08/21, 8408240289

D NRC Draft/Final Environmental Statements, supplS & correspondence

8407120136 Appeals denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similiar environ documents & FOIA fee waiver decision
RYAN, J A Streich, Lang, Weeks & Cardon 84/03/27 Office of the Executive Director for Operations 4pp 25557 018 24X Fiche 50-528, 84/03/27, 8407120136

8407120142 Responds to appeal re denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similar environ documents Appeal granted
DIRCKS, W J Office of the Executive Director for Operations 84/05/21 RYAN, J A Streich, Lang, Weeks & Cardon 1p 25557 022 24X Fiche 50-528, 84/05/21, 8407120142

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), supplS & correspondence

8408130351 Forwards update to 830127 description of natural circulation test program & "Evaluation of Natural Circulation Cooldown Test Performed at San Onofre Nuclear Generating Station " Confirmatory Item 7 in NUREG-0857, SSER 5 closed
VAN BRUNT, E E Arizona Public Service Co 84/08/07 KNIGHTON, G
Licensing Branch 3 23pp 26006 170 24X Fiche 50-528, 84/08/07, 8408130351

8408270133 Forwards "Containment Ultimate Capacity Analysis," per NUREG-0857, "SER re Operation of Palo Verde Nuclear Generating Station, Units 1, 2 & 3 " Analysis should close license condition discussed in Section 3 8 1
VAN BRUNT, E E Arizona Public Service Co 84/08/20 KNIGHTON, G
Licensing Branch 3 3pp 26245 061 24X Fiche 50-528, 84/08/20, 8408270133

--8408270140 "Containment Ultimate Capacity Analysis "
* Arizona Public Service Co 84/08/31 38pp 26245 064 24X Fiche 50-528, 84/08/20, 8408270133

F Security, medical, emergency & fire protection plans

8408090448 Notification of 840730-31 & 0801 meetings w/util & Comex in Phoenix, AZ & site, respectively, to discuss open issues in onsite emergency planning
LICITRA, E A Licensing Branch 3 84/07/25 KNIGHTON, G W
Licensing Branch 3 2pp 25983 213 24X Fiche 50-528, 84/07/25, 8408090448

8408130182 Forwards request for addl info re evacuation time estimate analysis for emergency plan Response requested within 2 wks of ltr receipt
KNIGHTON, G W Licensing Branch 3 84/07/27 VAN BRUNT, E E
Arizona Public Service Co 3pp 26011 351 24X
Fiche 50-528, 84/07/27, 8408130182

8408130160 Confirms 840625 telcon re outcome of 840531 appeal meeting re alternate shutdown capability Appeal granted, based on listed design features for plant & commitment to perform confirmatory PRA analysis
NOVAK, T M Assistant Director for Licensing 84/07/30 VAN BRUNT, E E Arizona Public Service Co 2pp 26034 351 24X
Fiche 50-528, 84/07/30, 8408130160

8408030097 Forwards response to NRC 840605 comments re emergency procedure generation package Steps to verify adequate instruments & controls available for operator to perform assigned task incorporated into validation procedure
VAN BRUNT, E E Arizona Public Service Co 84/08/01 KNIGHTON, G
Licensing Branch 3 7pp 25904 342 24X Fiche 50-528, 84/08/01, 8408030097

8408230310 Confirms 840822-24 audit of emergency operating procedures (EOPs) Five sets of current EOPs, along w/procedure generation package rev, should be provided to NRC by 840813
KNIGHTON, G W Licensing Branch 3 84/08/02 VAN BRUNT, E E
Arizona Public Service Co 2pp 26236 100 24X
Fiche 50-528, 84/08/02, 8408230310

8408300383 Forwards Insp Repts 50-528/84-25, 50-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation
BISHOP, T W Region 5, Office of Director 84/08/08 VAN BRUNT, E E
Arizona Public Service Co 2pp 26308 122 24X
Fiche 50-528, 84/08/09, 8408300383

--8408300390 Notice of violation from insp on 840709-13
MILLER, L Region 5, Office of Director 84/08/08 2pp
26308 124 24X Fiche 50-528, 84/08/08, 8408300383

--8408300397 Notice of deviation from insp on 840709-13
MILLER, L Region 5, Office of Director 84/08/08 1p
26308 126 24X Fiche 50-528, 84/08/08, 8408300383

--8408300407 Insp Repts 50-528/84-25, 50-529/84-19 & 50-530/84-12 on 840709-13 Violations noted Fire protection sys not designed to retain structural integrity during seismic event.
CLARK, C , NARBUT, P P , MILLER, L Region 5, Office of Director
84/08/03 24pp 26308 127 24X Fiche 50-528, 84/08/08, 8408300383

8408200599 Submits Rev 4 to emergency plan Rev addresses NRC comments, is aligned more concisely w/current operating procedures & clarifies barrier approach to emergency action levels
VAN BRUNT, E E Arizona Public Service Co 84/08/15 KNIGHTON, G
Licensing Branch 3 3pp 26137 052 24X Fiche 50-528, 84/08/15, 8408200599

--8408200600 Rev 4 to emergency plan
* Arizona Public Service Co 84/05/31 83pp 26137 055 24X Fiche 50-528, 84/08/15, 8408200599

8408200112 Forwards "Evaluation Time Analysis, 10-Mile Emergency Planning Zone, Arizona Div of Emergency Svcs" & response to 840727 request for addl info
VAN BRUNT, E E Arizona Public Service Co 84/08/16 KNIGHTON, G
Licensing Branch 3 4pp 26132 321 24X Fiche 50-528, 84/08/16, 8408200112

--8408200334 "Evacuation Time Analysis, 10-Mile Emergency Planning Zone, Arizona Div of Emergency Svcs "
* Arizona, State of BLUHM, R B Maricopa County, AZ 84/01/31 22pp 26132 325 24X Fiche 50-528, 84/08/16, 8408200112

8408200217 Forwards Rev 5 to emergency action levels Rev addresses comments raised at 840731 meeting re security, external events & challenge/failure of fission product barriers
VAN BRUNT, E E Arizona Public Service Co 84/08/16 KNIGHTON, G
Licensing Branch 3 3pp 26133 099 24X Fiche 50-528, 84/08/16, 8408200217

--8408200224 Rev 5 to emergency action levels
* Arizona Public Service Co 84/08/31 86pp 26133 102 24X Fiche 50-528, 84/08/16, 8408200217

8408270260 Requests approval of two temporary deviations in emergency preparedness plan from goals for augmentation of emergency response organization in Suppl 1 to NUREG-0737 Nature & duration of deviations encl
VAN BRUNT, E E Arizona Public Service Co 84/08/20 KNIGHTON, G
Licensing Branch 3 27pp 26243 131 24X Fiche 50-528, 84/08/20, 8408270260

K Utility Final Safety Analysis Report (FSAR) & amends

8408030102 Forwards page change list for Amend 13 to FSAR Replacement of original pages requested
* Bechtel Corp 84/07/31 Office of Nuclear Reactor Regulation, Director 3pp 25904 336 24X Fiche 50-528, 84/07/31, 8408030102

8408030142 Forwards corrected Pages 3 & 4 to list of effective pages for Palo Verde FSAR, Amend 13
* Bechtel Corp 84/07/31 Office of Nuclear Reactor Regulation, Director 3pp 25915 325 24X Fiche 50-528, 84/07/31, 8408030142

8408030093 Forwards page change list for Palo Verde Nuclear Generating Station FSAR, Amend 13, Pages A through J
GILMORE, T Bechtel Corp 84/08/01 Office of Nuclear Reactor Regulation, Director 6pp 25916 031 24X Fiche 50-528, 84/08/01, 8408030093

8408060075 Forwards info revising Insert 1 to FSAR, Page 14 2-3 re initial test program
VAN BRUNT, E E Arizona Public Service Co 84/08/01 KNIGHTON, G W
Licensing Branch 3 7pp 25933 215 24X Fiche 50-528, 84/08/01, 8408060075

8408010215 Amend 13 to FSAR for Palo Verde Nuclear Generating Station, Units 1, 2 & 3 W/34 oversize figures Aperture cards available in PDR W/840801 ltr
VAN BRUNT, E E Arizona Public Service Co 84/08/31 1408pp
25999 122 24X Fiche 50-528, 84/08/31, 8408010215

Q Inspection reports, IE Bulletins & correspondence

8406230213 "Region V Outstanding Items Rept Open & Closed "
* Region 5, Office of Director 84/06/12 25pp 25127 076 24X Fiche 50-529, 84/06/12, 8406230213

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408300187 Forwards Insp Repts 50-528/84-23 & 50-529/84-17 on 840602-0701 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/08/02 VAN BRUNT, E E Arizona Public Service Co
2pp 26308 014 24X Fiche 50-528, 84/08/02, 8408300187

--8408300195 Insp Repts 50-528/84-23 & 50-529/84-17 on 840602-0701 No violations noted Major areas inspected preoperational testing activities,maint,review of maint & followup on TMI Lessons Learned implementation
ZIMMERMAN,R , FIORELLI,G , BOSTED,C Region 5, Office of Director 84/08/01 12pp 26308 016 24X Fiche 50-528,84/08/02, 8408300187

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26069 001 24X Fiche 50-000,84/08/06,8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000,84/08/06,8408010337

8408300094 Forwards Insp Repts 50-528/84-21,50-529/84-16 & 50-530/84-10 on 840402-0531 & notice of violation
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 84/08/07 VAN BRUNT,E E Arizona Public Service Co 2pp 26306 141 24X Fiche 50-528,84/08/07,8408300094

--8408300100 Notice of violation from insp on 840402-0531
YOUNG,T Region 5, Office of Director 84/08/07 1p 26306 143 24X Fiche 50-528,84/08/07,8408300094

--8408300105 Insp Repts 50-528/84-21,50-529/84-16 & 50-530/84-10 on 840402-0531 Violation noted failure to control mods on Units 1 & 2 diesel generator bldg wall mounted instruments
VORDERBRUEGGEN, YOUNG,T Region 5, Office of Director 84/08/07 7pp 26306 144 24X Fiche 50-528,84/08/07,8408300094

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000,84/08/08,8408070120

8408300383 Forwards Insp Repts 50-528/84-25,50-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation
BISHOP,T W Region 5, Office of Director 84/08/08 VAN BRUNT,E E Arizona Public Service Co 2pp 26308 122 24X
Fiche 50-528,84/08/08,8408300383

--8408300390 Notice of violation from insp on 840709-13
MILLER,L Region 5, Office of Director 84/08/08 2pp 26308 124 24X Fiche 50-528,84/08/08,8408300383

--8408300397 Notice of deviation from insp on 840709-13
MILLER,L Region 5, Office of Director 84/08/08 1p 26308 126 24X Fiche 50-528,84/08/08,8408300383

--8408300407 Insp Repts 50-528/84-25,50-529/84-19 & 50-530/84-12 on 840709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event
CLARK,C , SORENSEN,R C , HOLLENBACH,D Region 5, Office of Director 84/08/03 24pp 26308 127 24X Fiche 50-528,84/08/08, 8408300383

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000,84/08/10,8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000,84/08/16,8408100021

8408220051 Ack receipt of 840720 ltr informing NRC of steps taken to correct violations noted in IE insp repts conducted between 840501-0601
BISHOP,T W Region 5, Office of Director 84/08/16 VAN BRUNT,E E Arizona Public Service Co 1p 26193 237 24X
Fiche 50-528,84/08/16,8408220051

--8408220071 Responds to NRC 840722 ltr re violations noted in IE insp repts conducted between 840501-0601 Corrective actions Pump A disassembled & defective seal replaced w/new seal Walkdown team established
VAN BRUNT,E E Arizona Public Service Co 84/07/20 BISHOP,T W Region 5, Office of Director 10pp 26193 238 24X
Fiche 50-528,84/08/16,8408220051

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

B Reportable occurrences, LERs & related correspondence

8408030048 Final Deficiency Rept DER 83-56,Rev 1 re discrepancies w/ Anchor-Darling MSIVs Initially reported on 830808 Larger hydraulic reservoir w/baffles installed in each MSIV & feedwater isolation valve
VAN BRUNT,E E Arizona Public Service Co 84/04/13 BISHOP,T W Region 5, Office of Director 7pp 25917 330 24X
Fiche 50-528,84/04/13,8408030048

8408020232 Corrected Rev 1 to Final Deficiency Rept DER 83-56 re discrepancies w/MSIV mfg by Anchor-Darling Initially reported on 830808 Vendor Instruction Manual E9023-9 revised Also reported per Part 21
VAN BRUNT,E E Arizona Public Service Co 84/07/13 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 7pp 25898 046 24X Fiche 50-528,84/07/13,8408020232

8408030061 Final Deficiency Rept DER 83-77 re concrete pour containing honeycombed concrete Initially reported on 831109 Honeycombed concrete removed & repaired Item not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/07/13 BISHOP,T W Region 5, Office of Director 4pp 25917 323 24X
Fiche 50-529,84/07/13,8408030061

8408030302 Final Deficiency Rept DER 84-02 re rust, scale & pitting in clevis & arm of several safety injection & CH valves Rust insignificant Deficiency determined not reportable under 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/07/13 BISHOP,T W Region 5, Office of Director 2pp 25917 115 24X
Fiche 50-528,84/07/13,8408030302

8408010377 Interim Deficiency Rept DER 84-18 re wiring error on LPSI pump B switch CS-3 Initially reported on 840326 Final rept will be submitted by 840822
VAN BRUNT,E E Arizona Public Service Co 84/07/16 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 2pp 25866 288 24X Fiche 50-528,84/07/16,8408010377

8408010381 Interim Deficiency Rept DER 84-08 re ITT/Barton Model 763 transmitters not meeting specs Initially reported on 840229 Final rept will be submitted by 840824
VAN BRUNT,E E Arizona Public Service Co 84/07/16 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 2pp 25866 290 24X Fiche 50-528,84/07/16,8408010381

8408010384 Interim Deficiency Rept DER 83-80 re main feedwater isolation valves closing in 20 s instead of Tech Spec required 5 s Initially reported on 831122 Final rept will be submitted by 840823,
VAN BRUNT,E E Arizona Public Service Co 84/07/16 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 2pp 25866 286 24X Fiche 50-528,84/07/16,8408010384

8408030240 Interim Deficiency Rept DER 83-63 re HPSI isolation valves mfg by Borg-Warner failing to open against pump A & B flows Initially reported on 830923 Time extension requested due to extensive investigation Next rept by 840831
VAN BRUNT,E E Arizona Public Service Co 84/07/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
25917 221 24X Fiche 50-528,84/07/16,8408030240

8408010346 Final Deficiency Rept DER 82-37,Rev 1,re Class 1E wiring termination crimped w/less pressure than specified Work Plant Procedure/QC Instruction 255 0 revised to require maint program
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 12pp
25866 310 24X Fiche 50-528,84/07/18,8408010346

8408010388 Interim Deficiency Evaluation Rept 84-43 re HPSI 3-inch gate valve failing to open Initially reported on 840622 Conditions not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
25866 281 24X Fiche 50-528,84/07/18,8408010388

8408020229 Final Deficiency Rept DER 83-59,Rev 1,re IEEE-384 separation criteria violated by wiring in post-accident control room & safety radiation monitoring cabinets Sheet metal barriers added between terminal blocks Not reportable per 10CFR50 55
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 5pp
25898 041 24X Fiche 50-529,84/07/18,8408020229

8408030053 Interim Potential Deficiency Rept DER 84-42 re replacement of environmentally qualified torque switches w/unqualified switches Initially reported on 840618 Final rept expected by 840820
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Region 5, Office of Director 3pp 25917 327 24X
Fiche 50-528,84/07/18,8408030053

8408080499 Final Deficiency Rept DER 83-75 re improper torquing of bolts on two D01268A panel filler assemblies Bolts retorqued Deficiency not reportable under 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/07/24 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 5pp
25975 232 24X Fiche 50-528,84/07/24,8408080499

8408080529 Rev 1 to Final Deficiency Rept DER 81-49 re erroneous readings on NSSS water level transmitters due to variations of water leg Condensate pots for steam generator & pressurizer level measurements installed on root valves
VAN BRUNT,E E Arizona Public Service Co 84/07/24 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
25975 298 24X Fiche 50-528,84/07/24,8408080529

8408090012 Final Deficiency Rept DER 84-08 re failure of ITT/Barton Model 763 transmitters to meet specs PPS setpoints revised on existing transmitters & Barton working on physical mod to meet specs Also reportable under Part 21
VAN BRUNT,E E Arizona Public Service Co 84/07/24 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
25995 011 24X Fiche 50-528,84/07/24,8408090012

8408130172 Interim Deficiency Rept DER 83-81 re manufacturing defect in Gulfally Schedule 160 SS pipe Initially reported on 831128 Due to extensive investigation & evaluation required,final rept will be delayed until 840830
VAN BRUNT,E E Arizona Public Service Co 84/07/27 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26010 036 24X Fiche 50-528,84/07/27,8408130172

8408130332 Interim Deficiency Rept DER 84-09 re CAD welding for cathodic protection ground connection Initially reported on 840229 Final rept will be submitted by 840830
VAN BRUNT,E E Arizona Public Service Co 84/07/27 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26010 303 24X Fiche 50-528,84/07/27,8408130332

8408130344 Interim Deficiency Rept DER 82-80 re low insulation resistance values or terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept by 840817
VAN BRUNT,E E Arizona Public Service Co 84/07/30 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26010 222 24X Fiche 50-528,84/07/30,8408130344

8408130429 Interim Deficiency Rept DER 84-15 re welds attaching pipe restraint supports less than design calculated dimensions Initially reported on 840321 Final rept will be submitted by 840914
VAN BRUNT,E E Arizona Public Service Co 84/07/30 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26004 354 24X Fiche 50-529,84/07/30,8408130429

8408160192 Final Deficiency Rept DER 84-10 re resistance temp detectors Caused by torsional twisting of element & sheath during honing operation,resulting in broken internal wire Item not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/08/01 BISHOP,T W
Region 4, Office of Director 3pp 26106 334 24X
Fiche 50-528,84/08/01,8408160192

8408160480 Final Deficiency Rept DER 84-16 re ESF actuation sys relay cabinet baseplates Initially reported on 840321 Cabinet backs will be reinforced w/3/8-inch thick vertical stiffener plate Also reportable under Part 21
VAN BRUNT,E E Arizona Public Service Co 84/08/02 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
26107 292 24X Fiche 50-528,84/08/02,8408160480

8408160506 Final Deficiency Rept DER 83-78 re lack of users test documentation & controlling procedure for rock bolt expansion anchors Initially reported on 831109 Item not reportable under 10CFR50 55(e) & Part 21
VAN BRUNT,E E Arizona Public Service Co 84/08/02 BISHOP,T W
Divisinn of Resident,Reactor Project & Engineering Programs 9pp
26107 326 24X Fiche 50-528,84/08/02,8408160506

8408220128 Interim Deficiency Rept DER 84-33 re incorrectly installed hanger support assembly Initially reported on 840504 Due to extensive investigation,final rept will be available 840831 instead of 840810
VAN BRUNT,E E Arizona Public Service Co 84/08/06 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26188 348 24X Fiche 50-528,84/08/06,8408220128

8408220143 Interim Deficiency Rept DER 84-44 re fatigue failures of Gaulin charging pumps Initially reported on 840706 Bechtel investigating Final rept to be completed by 840927 Reported under Part 21 by Northeast Utils
VAN BRUNT,E E Arizona Public Service Co 84/08/06 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 3pp
26188 065 24X Fiche 50-528,84/08/06,8408220143

8408200332 Part 21 rept re tension wires on Titus Grille,Model 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested to provide acceptable fix for retention
SCHNEIDER,S L Phillips Industries, Inc 84/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26133 315 24X
Fiche 50-000,84/08/07,8408200332

8408200333 Part 21 rept re tension wires used for adjustment of blades on Grille Model 272 not remaining in place when blades closed Review & testing conducted to identify number of grilles & rework methods to be utilized
SCHNEIDER,S L Phillips Industries, Inc 84/08/07 STRAIT,R
Arizona Public Service Co 1p 26132 360 24X
Fiche 50-528,84/08/07,8408200333

8408200297 Interim Deficiency Rept DER 84-34 re critical friction-type high strength connectors Due to extensive evaluation,next rept delayed until 840904
VAN BRUNT,E E Arizona Public Service Co 84/08/09 BISHOP,T W
Region 5, Office of Director 2pp 26140 090 24X
Fiche 50-528,84/08/09,8408200297

8408200322 Final Deficiency Rept DER 83-61 re C-E low pressure safety injection pump failure to start & produce required head Case wear rings replaced & clearance between impeller & casing increased Proprietary CEN-285 (V)-P encl
VAN BRUNT,E E Arizona Public Service Co 84/08/09 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 40pp
26133 318 24X Fiche 50-528,84/08/09,8408200322

8408200285 Final Deficiency Rept DER 83-82 re improper bend radius in diesel generator control cabinets Initially reported on 840103 Forwards "Technical Rept for Palo Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63619 "
VAN BRUNT,E E Arizona Public Service Co 84/08/10 BISHOP,T W
Region 5, Office of Director 13pp 26139 307 24X
Fiche 50-528,84/08/10,8408200285

--8408200288 "Technical Rept for Palo Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63619 "
MONTGOMERY,R , BEASLEY,B Anaconda Co (subs of Atlantic Richfield Co) 84/01/24 11pp 26139 320 24X
Fiche 50-528,84/08/10,8408200285

8408280302 Interim Deficiency Rept DER 83-57 re cracks in control element assembly shroud Initially reported on 830729 Requests extension until 840915 for submittal of final rept to allow for post-demonstration test insp evaluation
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 161 24X Fiche 50-528,84/08/13,8408280302

DOCKETED ITEMS

8408200317 Interim Deficiency Rept DER 83-49 re broken impeller blades & diffuser bolts broken/loose in reactor coolant pumps Initially reported on 830715 Time extension until 840915 for final rept requested for post-demonstration test insp
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 257 24X Fiche 50-528,84/08/13,8408280317

8408200335 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on 830629 Extension for submittal of final rept from 840815 to 840915 requested due to need for evaluation of post-demonstration test insp
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 259 24X Fiche 50-528,84/08/13,8408280335

8408280357 Interim Deficiency Rept DER 84-26 re improperly tested or adjusted plunger interlock Initially reported on 840510 Final rept will be submitted by 840915
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 250 24X Fiche 50-528,84/08/13,8408280357

8408280204 Interim Deficiency Rept DER 84-25 re containment supply register failure to cycle Initially reported on 840501 Galvanized wire will be replaced w/stainless steel wire to gain higher tensile strength Next rept expected by 840921
VAN BRUNT,E E Arizona Public Service Co 84/08/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 3pp
26282 166 24X Fiche 50-528,84/08/16,8408280204

8408280263 Interim Deficiency Rept DER 84-45 re spot welding on skid mounted indication & control Initially reported on 840717 Kaman Instrumentation will perform torque test for site testing of stud welds Next rept expected by 840928
VAN BRUNT,E E Arizona Public Service Co 84/08/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 3pp
26282,169 24X Fiche 50-528,84/08/16,8408280263

8408280297 Interim Deficiency Rept DER 84-46 re refueling water tank penetration sleeves Initially reported on 840717 Bechtel evaluation of reportability & corrective action in progress
VAN BRUNT,E E Arizona Public Service Co 84/08/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 3pp
26282 150 24X Fiche 50-528,84/08/16,8408280297

8408280283 Interim Deficiency Rept DER 82-80 re low insulation resistance values for terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept expected by 840903
VAN BRUNT,E E Arizona Public Service Co 84/08/17 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 178 24X Fiche 50-528,84/08/17,8408280283

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8408090483 Forwards request for addl info re isolation devices used in reactor protective sys Response requested within 2 wks of ltr receipt
KNIGHTON,G W Licensing Branch 3 84/07/25 VAN BRUNT,E E
Arizona Public Service Co 7pp 25983 153 24X
Fiche 50-528,84/07/25,8408090483

B060319 Notifies that response to 840702 request for info re urveillance requirements for ESF actuation sys will be rovided by 840901
AN BRUNT,E E Arizona Public Service Co 84/07/31 KNIGHTON,G
icensing Branch 3 2pp 25936 036 24X Fiche 50-528,84/07/31,
8408060319

08030144 Forwards table of Type A variables & revs & updates of compliance to Reg Guide 1 97,Rev 2,Types D,C & B variable requirements,in response to 831203 request.
VAN BRUNT,E E Arizona Public Service Co 84/08/01 KNIGHTON,G
Licensing Branch 3 28pp 25911 161 24X Fiche 50-528,84/08/01,
8408030144

08080048 Informs that response to NRC 840627 info request re control element assembly shroud will be be submitted by 840815
VAN BRUNT,E E Arizona Public Service Co 84/08/02 KNIGHTON,G W
Licensing Branch 3 1p 25961 036 24X Fiche 50-528,84/08/02,
8408080048.

8408100127 Forwards "Calculation of Trip Setpoint Values,Plant Protection Sys," in response to 830620 ltr
VAN BRUNT,E E Arizona Public Service Co 84/08/02 KNIGHTON,G
Licensing Branch 3 1p 25991 042 24X Fiche 50-528,84/08/02,
8408100127

--8408100137 Rev 0 to "Calculation of Trip Setpoint Values,Plant Protection Sys "
* Combustion Engineering, Inc CEN-286(V) R00 84/07/31 123pp
25991 043 24X Fiche 50-528,84/08/02,8408100127

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT,D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000,84/08/06,8408070110

8408090317 Forwards monthly status rept re plant-specific backfitting activities for operating reactors & license applicants for Jul 1984
TREMBLAY,P P Operating Reactors Assessment Branch 84/08/06
HOLAHAN,G M Operating Reactors Assessment Branch 13pp
25991 350 24X Fiche 50-000,84/08/06,8408090317

8408200255 Informs of launching of new program to seek out concerns re const & safe operation Ltr to all const workers inviting rept of concerns for investigation encl
TURLEY,K Arizona Public Service Co 84/08/06 MARTIN,J Region
5, Office of Director 3pp 26133 208 24X Fiche 50-528,84/08/06,
8408200255

8408130274 Forwards solid radwaste process control program,in response to GW Knighton 840403 ltr to EE Van Brunt Solid radwaste process control program incorporates 830630 response to 830415 request for addl info
VAN BRUNT,E E Arizona Public Service Co 84/08/07 KNIGHTON,G
Licensing Branch 3 2pp 26010 008 24X Fiche 50-528,84/08/07,
8408130274

--8408130277 Solid radwaste process control program
* Arizona Public Service Co 84/08/07 9pp 26010 010 24X
Fiche 50-528,84/08/07,8408130274

8408140227 Advises that GE Miller medical problem,disclosed on NRC Form 396,will not impair ability to perform assigned job tasks Evaluation based on examining physician statement & mgt observation of past performance
VAN BRUNT,E E Arizona Public Service Co 84/08/07 MARTIN,J B
Region 5, Office of Director 1p 26055 309 24X
Fiche 50-528,84/08/07,8408140227

8408150207 Forwards supplts to util 840702 ltr re organizational structure,based on 840716 discussion Supplts include removal of Note b ref from FSAR Page 13 1-28,Note b from Page 13 1-29 & update to response to Question 13A 18
VAN BRUNT,E E Arizona Public Service Co 84/08/13 KNIGHTON,G
Licensing Branch 3 6pp 26067 125 24X Fiche 50-528,84/08/13,
8408150207

8408230367 Notification of 840822 & 23 meetings w/util,Bechtel & DOE at site to discuss evaluation of effects of water leaks on foundation stability
LICITRA,E A Licensing Branch 3 84/08/14 KNIGHTON,G W
Licensing Branch 3 4pp 26230 350 24X Fiche 50-528,84/08/14,
8408230367

8408170348 Forwards addl fabrication info on Unit 1 control element assembly shroud assembly,per 840627 request Seventeen proprietary oversize drawings encl Drawings withheld (ref 10CFR2 790) Aperture card available in Central Files
VAN BRUNT,E E Arizona Public Service Co 84/08/15 KNIGHTON,G
Licensing Branch 3 6pp 26145 001 24X Fiche 50-528,84/08/15,
8408170348

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT,D G Division of Licensing 84/08/20 Consolidated
Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000,84/08/20,8408200275

8408240261 Forwards Rev 2 to "Pump & Valve Inservice Testing Program" & proposed changes to Rev 2 W/46 oversize drawings Aperture cards available in PDR
VAN BRUNT,E E Arizona Public Service Co 84/08/21 KNIGHTON,G
Licensing Branch 3 3pp 26227 018 24X Fiche 50-528,84/08/21,
8408240261

--8408240263 Rev 2 to "Pump & Valve Inservice Testing Program "
* Arizona Public Service Co 84/07/16 206pp 26227 021 24X
Fiche 50-528,84/08/21,8408240261

8408240289 Forwards mod to deviation request in FSAR Amend 13, Sections 9B 2 1, 9B 2 2 & Figures 9B-8, 9.10 & 11 Updated response to FSAR Question 9A-98 Part (2) also encl Changes will be incorporated in next FSAR amend
VAN BRUNT, E E Arizona Public Service Co 84/08/21 KNIGHTON, G
Licensing Branch 3 15pp 26223 199 24X Fiche 50-528, 84/08/21, 8408240289

D NRC Draft/Final Environmental Statements, suppls & correspondence

8407120136 Appeals denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similiar environ documents & FOIA fee waiver decision
RYAN, J A Streich, Lang, Weeks & Cardon 84/03/27 Office of the Executive Director for Operations 4pp 25557 018 24X
Fiche 50-528, 84/03/27, 8407120136

8407120142 Responds to appeal re denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similar environ documents Appeal granted
DIRCKS, W J Office of the Executive Director for Operations
84/05/21 RYAN, J A Streich, Lang, Weeks & Cardon 1p 25557 022
24X Fiche 50-528, 84/05/21, 8407120142

E NRC Safety Evaluation Report (SER), suppls & correspondence

8408130351 Forwards update to 830127 description of natural circulation test program & "Evaluation of Natural Circulation Cooldown Test Performed at San Onofre Nuclear Generating Station " Confirmatory Item 7 in NUREG-0857, SSER 5 closed
VAN BRUNT, E E Arizona Public Service Co 84/08/07 KNIGHTON, G
Licensing Branch 3 23pp 26006 170 24X Fiche 50-528, 84/08/07, 8408130351

8408270133 Forwards "Containment Ultimate Capacity Analysis, " per NUREG-0857, "SER re Operation of Palo Verde Nuclear Generating Station, Units 1, 2 & 3 " Analysis should close license condition discussed in Section 3 8 1
VAN BRUNT, E E Arizona Public Service Co 84/08/20 KNIGHTON, G
Licensing Branch 3 3pp 26245 061 24X Fiche 50-528, 84/08/20, 8408270133

--8408270140 "Containment Ultimate Capacity Analysis "
* Arizona Public Service Co 84/08/31 38pp 26245 064 24X
Fiche 50-528, 84/08/20, 8408270133

F Security, medical, emergency & fire protection plans

8408090448 Notification of 840730-31 & 0801 meetings w/util & Comex in Phoenix, AZ & site, respectively, to discuss open issues in onsite emergency planning
LICITRA, E A Licensing Branch 3 84/07/25 KNIGHTON, G W
Licensing Branch 3 2pp 25983 213 24X Fiche 50-528, 84/07/25, 8408090448

8408130182 Forwards request for addl info re evacuation time estimate analysis for emergency plan Response requested within 2 wks of ltr receipt
KNIGHTON, G W Licensing Branch 3 84/07/27 VAN BRUNT, E E
Arizona Public Service Co 3pp 26011 351 24X
Fiche 50-528, 84/07/27, 8408130182

8408130160 Confirms 840625 telcon re outcome of 840531 appeal meeting re alternate shutdown capability Appeal granted, based on listed design features for plant & commitment to perform confirmatory PRA analysis
NOVAK, T M Assistant Director for Licensing 84/07/30 VAN BRUNT, E E Arizona Public Service Co 2pp 26034 351 24X
Fiche, 50-528, 84/07/30, 8408130160

8408030097 Forwards response to NRC 840605 comments re emergency procedure generation package Steps to verify adequate instruments & controls available for operator to perform assigned task incorporated into validation procedure
VAN BRUNT, E E Arizona Public Service Co 84/08/01 KNIGHTON, G
Licensing Branch 3 7pp 25904 342 24X Fiche 50-528, 84/08/01, 8408030097

8408230310 Confirms 840822-24 audit of emergency operating procedures (EOPs) Five sets of current EOPs, along w/procedure generation package rev, should be provided to NRC by 840913
KNIGHTON, G W Licensing Branch 3 84/08/02 VAN BRUNT, E E
Arizona Public Service Co. 2pp 26236 100 24X
Fiche 50-528, 84/08/02, 8408230310

8408300383 Forwards Insp Repts 50-528/84-25, 50-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation
BISHOP, T W Region 5, Office of Director 84/08/08 VAN BRUNT, E E
Arizona Public Service Co 2pp 26308 122 24X
Fiche: 50-528, 84/08/08, 8408300383

--8408300390 Notice of violation from insp on 840709-13
MILLER, L Region 5, Office of Director 84/08/08 2pp
26308 124 24X Fiche 50-528, 84/08/08, 8408300383

--8408300397 Notice of deviation from insp on 840709-13
MILLER, L Region 5, Office of Director 84/08/08 1p
26308 126 24X Fiche 50-528, 84/08/08, 8408300383

--8408300407 Insp Repts 50-528/84-25, 50-529/84-19 & 50-530/84-12 on 840709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event
CLARK, C Region 5, Office of Director 84/08/03 24pp
26308 127 24X Fiche 50-528, 84/08/08, 8408300383

8408200599 Submits Rev 4 to emergency plan Rev addresses NRC comments, is aligned more concisely w/current operating procedures & clarifies barrier approach to emergency action levels
VAN BRUNT, E E Arizona Public Service Co 84/08/15 KNIGHTON, G
Licensing Branch 3 3pp 26137 052 24X Fiche 50-528, 84/08/15, 8408200599

--8408200600 Rev 4 to emergency plan
* Arizona Public Service Co 84/05/31 83pp 26137 055 24X
Fiche 50-528, 84/08/15, 8408200599

8408200112 Forwards "Evaluation Time Analysis, 10-Mile Emergency Planning Zone, Arizona Div of Emergency Svcs" & response to 840727 request for addl info
VAN BRUNT, E E Arizona Public Service Co 84/08/16 KNIGHTON, G
Licensing Branch 3 4pp 26132 321 24X Fiche 50-528, 84/08/16, 8408200112

--8408200334 "Evacuation Time Analysis, 10-Mile Emergency Planning Zone, Arizona Div of Emergency Svcs "
* Arizona, State of DLUHM, R B Maricopa County, AZ 84/01/31
22pp 26132 325 24X Fiche 50-528, 84/08/16, 8408200112

8408200217 Forwards Rev 5 to emergency action levels Rev addresses comments raised at 840731 meeting re security, external events & challenge/failure of fission product barriers
VAN BRUNT, E E Arizona Public Service Co 84/08/16 KNIGHTON, G
Licensing Branch 3 3pp 26133 099 24X Fiche 50-528, 84/08/16, 8408200217

--8408200224 Rev 5 to emergency action levels
* Arizona Public Service Co 84/08/31 86pp 26133 102 24X
Fiche 50-528, 84/08/16, 8408200217

8408270260 Requests approval of two temporary deviations in emergency preparedness plan from goals for augmentation of emergency response organization in Suppl 1 to NUREG-0737 Nature & duration of deviations encl
VAN BRUNT, E E Arizona Public Service Co 84/08/20 KNIGHTON, G
Licensing Branch 3 27pp 26243 131 24X Fiche 50-528, 84/08/20, 8408270260

K Utility Final Safety Analysis Report (FSAR) & amends

8408030102 Forwards page change list for Amend 13 to FSAR Replacement of original pages requested
* Bechtel Corp 84/07/31 Office of Nuclear Reactor Regulation, Director 3pp 25904 336 24X Fiche 50-528, 84/07/31, 8408030102

8408030142 Forwards corrected Pages 3 & 4 to list of effective pages for Palo Verde FSAR, Amend 13
* Bechtel Corp 84/07/31 Office of Nuclear Reactor Regulation, Director 3pp 25915 325 24X Fiche 50-528, 84/07/31, 8408030142

8408030093 Forwards page change list for Palo Verde Nuclear Generating Station FSAR, Amend 13, Pages A through J
GILMORE, T Bechtel Corp 84/08/01 Office of Nuclear Reactor Regulation, Director 6pp 25916 031 24X Fiche 50-528, 84/08/01, 8408030093

8408060075 Forwards info revising Insert 1 to FSAR, Page 14 2-3 re initial test program
VAN BRUNT, E E Arizona Public Service Co 84/08/01 KNIGHTON, G W
Licensing Branch 3 7pp 25933 215 24X Fiche 50-528, 84/08/01, 8408060075

8408010215 Amend 13 to FSAR for Palo Verde Nuclear Generating Station, Units 1, 2 & 3 W/34 oversize figures Aperture cards available in PDR W/840801 ltr
VAN BRUNT, E E Arizona Public Service Co 84/08/31 1408pp,
25999 122 24X Fiche 50-528, 84/08/31, 8408010215

DOCKETED ITEMS

pection reports, IE Bulletins & correspondence

30218 "Region V Outstanding Items Rept Open & Closed "
Region 5, Office of Director 84/06/12 22pp 25129 159 24X
ie 50-530, 84/06/12, 8406230218

50229 IE Info Notice 84-57, "Operating Experience re Moisture
rusion in Safety-Related Electrical Equipment at
nercial Power Plants " Svc list encl
DAN, E L Division of Emergency Preparedness & Engineering
ponse (Post 830103) 84/07/27 Consolidated Edison Co of New
k, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

10333 IE Info Notice 84-59, "Deliberate Circumventing of Station
lth Physics Procedures " Svc list encl
DAN, E L Division of Emergency Preparedness & Engineering
ponse (Post 830103) 84/08/06 Consolidated Edison Co of New
k, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

10337 IE Info Notice 84-60, "Failure of Air Purifying Respirator
ters to Meet Efficiency Requirement " Svc list encl
DAN, E L Division of Emergency Preparedness & Engineering
ponse (Post 830103) 84/08/06 Consolidated Edison Co of New
k, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

00094 Forwards Insp Repts 50-528/84-21, 50-529/84-16 & 50-530/84-10
840402-0531 & notice of violation
HDP, T W Division of Resident, Reactor Project & Engineering
grams 84/08/07 VAN BRUNT, E E Arizona Public Service Co
26306 141 24X Fiche 50-528, 84/08/07, 8408300094

8300105 Insp Repts 50-528/84-21, 50-529/84-16 & 50-530/84-10 on
840402-0531 Violation noted failure to control mods on
nits 1 & 2 diesel generator bldg wall mounted instruments
ORDERBRUEGGEN, YOUNG, T Region 5, Office of Director 84/08/07
pp 26306 144 24X Fiche 50-528, 84/08/07, 8408300094

70120 IE Info Notice 84-61, "Overexposure of Diver in PWR
ueling Cavity " Svc list encl
DAN, E L Division of Emergency Preparedness & Engineering
ponse (Post 830103) 84/08/08 Consolidated Edison Co of New
k, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

300383 Forwards Insp Repts 50-528/84-25, 50-529/84-19 &
-530/84-12 on 840709-13 & notices of violation &
iolation
HDP, T W Region 5, Office of Director 84/08/08 VAN BRUNT, E E
rizona Public Service Co 2pp 26308 122 24X
he 50-528, 84/08/08, 8408300383

8300390 Notice of violation from insp on 840709-13
ILLER, L Region 5, Office of Director 84/08/08 2pp
26308 124 24X Fiche 50-528, 84/08/08, 8408300383

8300397 Notice of deviation from insp on 840709-13
ILLER, L Region 5, Office of Director 84/08/08 1p
26308 126 24X Fiche 50-528, 84/08/08, 8408300383

8300407 Insp Repts 50-528/84-25, 50-529/84-19 & 50-530/84-12 on
840709-13 Violations noted fire protection sys not designed
to retain structural integrity during seismic event
CLARK, C , SORENSEN, R C , HOLLENBACH, D Region 5, Office of
Director 84/08/03 24pp 26308 127 24X Fiche 50-528, 84/08/08,
8408300383

70376 IE Info Notice 84-62, "Therapy Misadministrations to
tients Undergoing Co-60 Teletherapy Treatments " Svc
st encl
ACE, J N Division of QA, Safeguards & Inspection Programs (Post
0103) 84/08/10 Consolidated Edison Co of New York, Inc
5pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

00009 IE Info Notice 84-63, "Defective RHR Replacement Piping "
c list encl
RDAN, E L Division of Emergency Preparedness & Engineering
sponse (Post 830103) 84/08/13 Consolidated Edison Co of New
rk, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

00038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In &
dication " Svc list encl
RDAN, E L Division of Emergency Preparedness & Engineering
sponse (Post 830103) 84/08/15 Consolidated Edison Co of New
rk, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

00021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely
fect Operation of Essential Electrical Equipment " Svc
st encl
RDAN, E L Division of Emergency Preparedness & Engineering
sponse (Post 830103) 84/08/16 Consolidated Edison Co of New
rk, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408220051 Acf receipt of 840720 ltr informing NRC of steps taken to
correct violations noted in IE insp repts conducted between
840501-0601
BISHOP, T W Region 5, Office of Director 84/08/16 VAN BRUNT, E E
Arizona Public Service Co 1p 26193 237 24X
Fiche 50-528, 84/08/16, 8408220051

-8408220071 Responds to NRC 840722 ltr re violations noted in IE insp
repts conducted between 840501-0601 Corrective actions Pump
A disassembled & defective seal replaced w/new seal Walkdown
team established
VAN BRUNT, E E Arizona Public Service Co 84/07/20 BISHOP, T W
Region 5, Office of Director 10pp 26193 238 24X
Fiche 50-528, 84/08/16, 8408220051

8408100055 IE Info Notice 84-66, "Undetected Unavailability of
Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/
High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New
York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly
Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New
York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8408030048 Final Deficiency Rept DER 83-56, Rev 1 re discrepancies w/
Anchor-Darling MSIVs Initially reported on 830808 Larger
hydraulic reservoir w/baffles installed in each MSIV &
feedwater isolation valve
VAN BRUNT, E E Arizona Public Service Co 84/04/13 BISHOP, T W
Region 5, Office of Director 7pp 25917 330 24X
Fiche 50-528, 84/04/13, 8408030048

8408020232 Corrected Rev 1 to Final Deficiency Rept DER 83-56 re
discrepancies w/MSIV mfg by Anchor-Darling Initially
reported on 830808 Vendor Instruction Manual E9023-9
revised Also reported per Part 21
VAN BRUNT, E E Arizona Public Service Co 84/07/13 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 7pp
25898 046 24X Fiche 50-528, 84/07/13, 8408020232

8408030061 Final Deficiency Rept DER 83-77 re concrete pour containing
honeycombed concrete Initially reported on 831109
Honeycombed concrete removed & repaired Item not
reportable per 10CFR50 55(e)
VAN BRUNT, E E Arizona Public Service Co 84/07/13 BISHOP, T W
Region 5, Office of Director 4pp 25917 323 24X
Fiche 50-529, 84/07/13, 8408030061

8408030302 Final Deficiency Rept DER 84-02 re rust, scale & pitting in
clevis & arm of several safety injection & CH valves Rust
insignificant Deficiency determined not reportable under
10CFR50 55(e)
VAN BRUNT, E E Arizona Public Service Co 84/07/13 BISHOP, T W
Region 5, Office of Director 2pp 25917 115 24X
Fiche 50-528, 84/07/13, 8408030302

8408010377 Interim Deficiency Rept DER 84-18 re wiring error on LPSI
pump B switch CS-3 Initially reported on 840326 Final rept
will be submitted by 840822
VAN BRUNT, E E Arizona Public Service Co 84/07/16 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp
25866 288 24X Fiche 50-528, 84/07/16, 8408010377

8408010381 Interim Deficiency Rept DER 84-08 re ITT/Barton Model 763
transmitters not meeting specs Initially reported on 840229
Final rept will be submitted by 840824
VAN BRUNT, E E Arizona Public Service Co 84/07/16 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp
25866 290 24X Fiche 50-528, 84/07/16, 8408010381

8408010384 Interim Deficiency Rept DER 83-80 re main feedwater
isolation valves closing in 20 s instead of Tech Spec
required 5 s Initially reported on 831122 Final rept will
be submitted by 840823
VAN BRUNT, E E Arizona Public Service Co 84/07/16 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp
25866 286 24X Fiche, 50-528, 84/07/16, 8408010384

8408030240 Interim Deficiency Rept DER 83-63 re HPSI isolation valves mfg by Borg-Warner failing to open against pump A & B flows Initially reported on 830923 Time extension requested due to extensive investigation Next rept by 840831
VAN BRUNT,E E Arizona Public Service Co 84/07/16 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
25917 221 24X Fiche 50-528,84/07/16,8408030240

8408010346 Final Deficiency Rept DER 82-37,Rev 1,re Class 1E wiring termination crimped w/less pressure than specified Work Plant Procedure/QC Instruction 295 0 revised to require maint program
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 12pp
25866 310 24X Fiche 50-528,84/07/18,8408010346

8408010388 Interim Deficiency Evaluation Rept 84-43 re HPSI 3-inch gate valve failing to open Initially reported on 840622 Conditions not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
25866 281 24X Fiche 50-528,84/07/18,8408010388

8408030053 Interim Potential Deficiency Rept DER 84-42 re replacement of environmentally qualified torque switches w/unqualified switches Initially reported on 840618 Final rept expected by 840820
VAN BRUNT,E E Arizona Public Service Co 84/07/18 BISHOP,T W
Region 5, Office of Director 3pp 25917 327 24X
Fiche 50-528,84/07/18,8408030053

8408080499 Final Deficiency Rept DER 83-75 re improper torquing of bolts on two DD126SA panel filler assemblies Bolts retorqued Deficiency not reportable under 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/07/24 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 3pp
25975 232 24X Fiche 50-528,84/07/24,8408080499

8408080529 Rev 1 to final Deficiency Rept DER 81-49 re erroneous readings on NSSS water level transmitters due to variations of water leg Condensate pots for steam generator & pressurizer level measurements installed on root valves
VAN BRUNT,E E Arizona Public Service Co 84/07/24 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
25975 298 24X Fiche 50-528,84/07/24,8408080529

8408090012 Final Deficiency Rept DER 84-08 re failure of ITT/Barton Model 763 transmitters to meet specs PPS setpoints revised on existing transmitters & Barton working on physical mod to meet specs Also reportable under Part 21
VAN BRUNT,E E Arizona Public Service Co 84/07/24 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
25995 011 24X Fiche 50-528,84/07/24,8408090012

8408130172 Interim Deficiency Rept DER 83-81 re manufacturing defect in Gulfally Schedule 160 SS pipe Initially reported on 831128 Due to extensive investigation & evaluation required,final rept will be delayed until 840830
VAN BRUNT,E E Arizona Public Service Co 84/07/27 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26010 036 24X Fiche 50-528,84/07/27,8408130172

8408130332 Interim Deficiency Rept DER 84-09 re CAD welding for cathodic protection ground connection Initially reported on 840229 Final rept will be submitted by 840830
VAN BRUNT,E E Arizona Public Service Co 84/07/27 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26010 303 24X Fiche 50-528,84/07/27,8408130332

8408130344 Interim Deficiency Rept DER 82-80 re low insulation resistance values or terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept by 840817
VAN BRUNT,E E Arizona Public Service Co 84/07/30 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26010 222 24X Fiche 50-528,84/07/30,8408130344

8408160192 Final Deficiency Rept DER 84-10 re resistance temp detectors Caused by torsional twisting of element & sheath during honing operation,resulting in broken internal wire Item not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 84/08/01 BISHOP,T W
Region 4, Office of Director 3pp 26106 334 24X
Fiche 50-528,84/08/01,8408160192

8408160480 Final Deficiency Rept DER 84-16 re ESF actuation sys relay cabinet baseplates Initially reported on 840321 Cabinet backs will be reinforced w/3/8-inch thick vertical stiffener plate Also reportable under Part 21
VAN BRUNT,E E Arizona Public Service Co 84/08/02 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 4pp
26107 292 24X Fiche 50-528,84/08/02,8408160480

8408160506 Final Deficiency Rept DER 83-78 re lack of users test documentation & controlling procedure for rock bolt expansion anchors Initially reported on 831109 Item not reportable under 10CFR50 55(e) & Part 21
VAN BRUNT E E Arizona Public Service Co 84/08/02 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 9pp
26107 326 24X Fiche 50-528,84/08/02,8408160506

8408220128 Interim Deficiency Rept DER 84-33 re incorrectly installed hanger support assembly Initially reported on 840504 Due to extensive investigation,final rept will be available 840831 instead of 840810
VAN BRUNT,E E Arizona Public Service Co 84/08/06 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26188 348 24X Fiche 50-528,84/08/06,8408220128

8408220143 Interim Deficiency Rept DER 84-44 re fatigue failures of Gaulin charging pumps Initially reported on 840706 Bechtel investigating Final rept to be completed by 840927 Reported under Part 21 by Northeast Utils
VAN BRUNT,E E Arizona Public Service Co 84/08/06 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 3pp
26188 065 24X Fiche 50-528,84/08/06,8408220143

8408200332 Part 21 rept re tension wires on Titus Grille,Model 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested to provide acceptable fix for retention
SCHNEIDER,S L Phillips Industries, Inc 84/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26133 315 24X
Fiche 50-000,84/08/07,8408200332

8408200333 Part 21 rept re tension wires used for adjustment of blades on Grille Model 272 not remaining in place when blades closed Review & testing conducted to identify number of grilles & rework methods to be utilized
SCHNEIDER,S L Phillips Industries, Inc 84/08/07 STRAIT,R
Arizona Public Service Co 1p 26132 360 24X
Fiche 50-528,84/08/07,8408200333

8408200297 Interim Deficiency Rept DER 84-34 re critical friction-type high strength connectors Due to extensive evaluation,next rept delayed until 840904
VAN BRUNT,E E Arizona Public Service Co 84/08/09 BISHOP,T W
Region 5, Office of Director 2pp 26140 090 24X
Fiche 50-528,84/08/09,8408200297

8408200322 Final Deficiency Rept DER 83-61 re C-E low pressure safety injection pump failure to start & produce required head Case wear rings replaced & clearance between impeller & casing increased Proprietary CEN-285 (V)-P encl
VAN BRUNT,E E Arizona Public Service Co 84/08/09 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 40pp
26133 318 24X Fiche 50-528,84/08/09,8408200322

8408200285 Final Deficiency Rept DER 83-82 re improper bend radius in diesel generator control cabinets Initially reported on 840103 Forwards "Technical Rept for Palo Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63619 "
VAN BRUNT,E E Arizona Public Service Co 84/08/10 BISHOP,T W
Region 5, Office of Director 13pp 26139 307 24X
Fiche 50-528,84/08/10,8408200285

--8408200288 "Technical Rept for Palo Verde Nuclear Station-Bechtel Power Corp on Returned Cable NCR E63619 "
MONTGOMERY,R , BEASLEY,B Anaconda Co (subs of Atlantic Richfield Co) 84/01/24 11pp 26139 320 24X
Fiche 50-528,84/08/10,8408200285

8408280302 Interim Deficiency Rept DER 83-57 re cracks in control element assembly shroud Initially reported on 830729 Requests extension until 840915 for submittal of final rept to allow for post-demonstration test insp evaluation
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 161 24X Fiche 50-528,84/08/13,8408280302

8408280317 Interim Deficiency Rept DER 83-49 re broken impeller blades & diffuser bolts broken/loose in reactor coolant pumps Initially reported on 830715 Time extension until 840915 for final rept requested for post-demonstration test insp
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 257 24X Fiche 50-528,84/08/13,8408280317

8408280335 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on 830629 Extension for submittal of final rept from 840815 to 840915 requested due to need for evaluation of post-demonstration test insp
VAN BRUNT,E E Arizona Public Service Co 84/08/13 BISHOP,T W
Division of Resident,Reactor Project & Engineering Programs 2pp
26282 259 24X Fiche 50-528,84/08/13,8408280335

8408280357 Interim Deficiency Rept DER 84-26 re improperly tested or adjusted plunger interlock Initially reported on 840510 Final rept will be submitted by 840715
VAN BRUNT, E E Arizona Public Service Co 84/08/13 BISHOP, T W Division of Resident/Reactor Project & Engineering Programs 2pp 26282 250 24X Fiche 50-528, 84/08/13, 8408280357

8408280204 Interim Deficiency Rept DER 84-25 re containment supply register failure to cycle Initially reported on 840501 Galvanized wire will be replaced w/stainless steel wire to gain higher tensile strength Next rept expected by 840921
VAN BRUNT, E E Arizona Public Service Co 84/08/16 BISHOP, T W Division of Resident/Reactor Project & Engineering Programs 3pp 26282 166 24X Fiche 50-528, 84/08/16, 8408280204

8408280297 Interim Deficiency Rept DER 84-46 re refueling water tank penetration sleeves Initially reported on 840717 Bechtel evaluation of reportability & corrective action in progress
VAN BRUNT, E E Arizona Public Service Co 84/08/16 BISHOP, T W Division of Resident/Reactor Project & Engineering Programs 3pp 26282 150 24X Fiche 50-528, 84/08/16, 8408280297

8408280283 Interim Deficiency Rept DER 82-80 re low insulation resistance values for terminal blocks supplied by Conax Corp Initially reported on 821217 Final rept expected by 840903
VAN BRUNT, E E Arizona Public Service Co 84/08/17 BISHOP, T W Division of Resident/Reactor Project & Engineering Programs 2pp 26282 178 24X Fiche 50-528, 84/08/17, 8408280283

DOCKET 50-538 MEMPHIS STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8408170286 Revised "Emergency Plan, Memphis State Univ, AGN-201 Reactor Facility " W/840809 ltr
JONES, D W Memphis State Univ , Memphis, TN 84/08/01 THOMAS, C O Standardization & Special Projects Branch 35pp 26114 282 24X Fiche 50-538, 84/08/01, 8408170286

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X Fiche 50-000, 84/08/06, 8408070110

8408200279 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X Fiche 50 000, 84/08/20, 8408200279

H General correspondence

8405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron Facility
DIRCKS, W J Office of the Executive Director for Operations 84/05/04 LUGAR, R G Senate 7pp 24524 329 24X Fiche 50-000, 84/05/04, 8405180145

--8405180152 Requests response to encl W & V Smelser 840210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron Facility
LUGAR, R G Senate 84/03/14 PALLADINO, N Commissioners 3pp 24524 331 24X Fiche 50-000, 84/05/04, 8405180145

O Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03 Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26069 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ *High Failure Rates* " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8407310030 Board Notification 84-134 forwards JF Streeter 840711 memo to DG Eisenhut re steam generator snubber testing failures Insp repts documenting results of testing & applicant reevaluation efforts will be forwarded to Board
NOVAK, T M Assistant Director for Licensing 84/07/27 SMITH, I W Atomic Safety and Licensing Board Panel 2pp 25936 033 24X Fiche 50-000, 84/07/27, 8407310030

--8408060344 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE insp repts
STREETER, J F Region 3, Office of Director 84/07/11 EISENHUT, D G Division of Licensing 1p 25936 035 24X Fiche 50-000, 84/07/27, 8407310030

DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408200275 Generic Ltr 84-20 to all licensees of operating reactors & applicants for OLs re scheduling guidance for licensee submittals of reloads that involve unreviewed safety questions Svc list encl
EISENHUT, D G Division of Licensing 84/08/20 Consolidated Edison Co of New York, Inc 17pp 26276 244 24X
Fiche 50-000, 84/08/20, 8408200275

H General correspondence

8405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
DIRCKS, W J Office of the Executive Director for Operations 84/05/04 LUGAR, R G Senate 7pp 24524 325 24X
Fiche 50-000, 84/05/04, 8405180145

--8405180152 Requests response to encl W & V Smelser 840210 inquiry into NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
LUGAR, R G Senate 84/03/14 PALLADINO, N Commissioners 3pp 24524 331 24X Fiche 50-000, 84/05/04, 8405180145

Q Inspection reports, IE Bulletins & correspondence

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re nonconpliance found during insp instituted, effective 840820 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc 125pp 26130 001 24X Fiche 50-000, 84/08/10, 8408070376

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100055

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

S Reportable occurrences, LERs & related correspondence

8407310030 Board Notification 84-134 forwards JF Streeter 840711 memo to DG Eisenhut re steam generator snubber testing failures Insp repts documenting results of testing & applicant reevaluation efforts will be forwarded to Board
NOVAK, T M Assistant Director for Licensing 84/07/27 SMITH, I W
Atomic Safety and Licensing Board Panel 2pp 25936 033 24X
Fiche 50-000, 84/07/27, 8407310030

--8408060344 Discusses steam generator snubber testing failures Snubbers made by Boeing Co Vendor Program Branch will be notified Results of testing & applicant reevaluation efforts will be documented in IE insp repts
STREETER, J F Region 3, Office of Director 84/07/11
EISENHUT, D G Division of Licensing 1p 25936 035 24X
Fiche 50-000, 84/07/27, 8407310030

DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8408230318 Requests remittance of fee for 830121 application for extension of const completion dates
DIGGS, R M License Fee Management Branch 84/08/16 PARRIS, H G
Tennessee Valley Authority 2pp 26236 098 24X
Fiche 50-000, 84/08/16, 8408230318

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8408230318 Requests remittance of fee for 830121 application for extension of const completion dates
DIGGS, R M License Fee Management Branch 84/08/16 PARRIS, H G
Tennessee Valley Authority 2pp 26236 098 24X
Fiche 50-000, 84/08/16, 8408230318

DOCKET 50-601 RESAR SP/90

A Application/construction stage documents & correspondence

8408090321 Informs that RESAR-SP/90 Preliminary Design Approval Module 4, "RCS," will be withheld from public disclosure, per review of application to withhold matl (ref 10CFR2 790) Westinghouse reasons for exemption listed
THOMAS, C O Standardization & Special Projects Branch 84/08/01
WIEBEMAN, R A Westinghouse Electric Corp 3pp 25984 347 24X
Fiche 50-601, 84/08/01, 8408090321

8408140278 Forwards table of contents illustrating integrated Modules 6 & 8 re secondary side safeguards sys & steam & power conversion sys
RAHE, E P Westinghouse Electric Corp 84/08/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1lpp 26055 344, 24X Fiche 50-601, 84/08/02, 8408140278

8408230467 Notifies that 840731 request to withhold RESAR-SP/90 preliminary design approval application from public disclosure under 10CFR2 790 granted Matl will be treated as proprietary info
THOMAS, C O Standardization & Special Projects Branch 84/08/16
WIEBEMAN, R A Westinghouse Electric Corp 3pp 26230 251 24X
Fiche 50-601, 84/08/16, 8408230467

F Security, medical, emergency & fire protection plans

8408140278 Forwards table of contents illustrating integrated Modules 6 & 8 re secondary side safeguards sys & steam & power conversion sys
RAHE,E P Westinghouse Electric Corp 84/08/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 11pp 26055 344
24X Fiche 50-601,84/08/02,8408140278

K Utility Final Safety Analysis Report (FSAR) & amends

8408080278 Forwards proprietary & nonproprietary Vols 1 & 2 of RESAR-SP/90 Westinghouse Advanced PWR,Module 5, "Reactor Sys " Proprietary rept withheld (ref 10CFR2 790)
RAHE,E P Westinghouse Electric Corp 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director ECCLESTON,K T
Standardization & Special Projects Branch 2pp 25985 129 24X
Fiche 50-601,84/07/31,8408080278

--8408080286 Requests withholding proprietary Vols 1 & 2 of RESAR-SP/90 Westinghouse Advanced PWR,Module 5, "Reactor Sys" (ref 10CFR2 790) Affidavit AW-82-57 encl
WIEGEMANN,R A Westinghouse Electric Corp 84/07/31 DENTON,H R
Office of Nuclear Reactor Regulation, Director 9pp 25985 131
24X Fiche 50-601,84/07/31,8408080278

--8408080289 Nonproprietary Vols 1 & 2 of RESAR-SP/90 Westinghouse Advanced PWR,Module 5, "Reactor Sys "
* Westinghouse Electric Corp 84/07/31 562pp 25985 140 24X
Fiche 50-601,84/07/31,8408080278

--8408080292 Nonproprietary Chapter 1 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Introduction & General Description of Plant "
* Westinghouse Electric Corp 84/07/31 34pp 25985 175 24X
Fiche 50-601,84/07/31,8408080278

--8408080295 Nonproprietary Chapter 2 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Site Characteristics "
* Westinghouse Electric Corp 84/07/31 1p 25985 209 24X
Fiche 50-601,84/07/31,8408080278

--8408080298 Nonproprietary Chapter 3 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Design of Structures, Components, Equipment & Sys "
* Westinghouse Electric Corp 84/07/31 51pp 25985 210 24X
Fiche 50-601,84/07/31,8408080278

--8408080301 Nonproprietary Chapter 4 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Reactor "
* Westinghouse Electric Corp 84/07/31 296pp 25985 261 24X
Fiche 50-601,84/07/31,8408080278

--8408080304 Nonproprietary Chapter 5 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "RCS & Connected Sys "
* Westinghouse Electric Corp 84/07/31 1p 25986 197 24X
Fiche 50-601,84/07/31,8408080278

8408080307 Nonproprietary Chapter 6 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "ESF "
* Westinghouse Electric Corp 84/07/31 1p 25986 198 24X
Fiche 50-601,84/07/31,8408080278

8408080309 Nonproprietary Chapter 7 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Instrumentation & Controls "
* Westinghouse Electric Corp 84/07/31 1p 25986 199 24X
Fiche 50-601,84/07/31,8408080278

8408080312 Nonproprietary Chapter 8 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Electric Power "
* Westinghouse Electric Corp 84/07/31 1p 25986 200 24X
Fiche 50-601,84/07/31,8408080278

-8408080315 Nonproprietary Chapter 9 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Auxiliary Sys "
* Westinghouse Electric Corp 84/07/31 1p 25986 201 24X
Fiche 50-601,84/07/31,8408080278

--8408080318 Nonproprietary Chapter 10 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Steam & Power Conversion "
* Westinghouse Electric Corp 84/07/31 1p 25986 202 24X
Fiche 50-601,84/07/31,8408080278

--8408080320 Nonproprietary Chapter 11 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Radwaste Mgt "
* Westinghouse Electric Corp 84/07/31 1p 25986 203 24X
Fiche 50-601,84/07/31,8408080278

--8408080323 Nonproprietary Chapter 12 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Radiation Protection "
* Westinghouse Electric Corp 84/07/31 1p 25986 204 24X
Fiche 50-601,84/07/31,8408080278

--8408080330 Nonproprietary Chapter 13 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Conduct of Operations "
* Westinghouse Electric Corp 84/07/31 1p 25986 205 24X
Fiche 50-601,84/07/31,8408080278

--8408080342 Nonproprietary Chapter 14 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Initial Test Program "
* Westinghouse Electric Corp 84/07/31 1p 25986 206 24X
Fiche 50-601,84/07/31,8408080278

--8408080343 Nonproprietary Chapter 15 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Accident Analyses "
* Westinghouse Electric Corp 84/07/31 133pp 25986 207 24X
Fiche 50-601,84/07/31,8408080278

--8408080345 Nonproprietary Chapter 16 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "Tech Specs "
* Westinghouse Electric Corp 84/07/31 1p 25986 340 24X
Fiche 50-601,84/07/31,8408080278

--8408080347 Nonproprietary Chapter 17 of RESAR-SP/90 Westinghouse Advanced PWR Module 5, "Reactor Sys," "QA "
* Westinghouse Electric Corp 84/07/31 1p 25986 341 24X
Fiche 50-601,84/07/31,8408080278

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH

8408020220 Forwards IE Insp Rept 70-0008/84-02 on 840611-14 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 84/07/06 UNGAR,E W
Battelle Memorial Institute, Columbus Laboratories 2pp
25898 012

--8408020223 IE Insp Rept 70-0008/84-02 on 840611-14 No noncompliance noted Major areas inspected licensing status,operations review,radiation protection,safety committees & nuclear criticality safety
FRANCE,D M , MILLER,D E , GREGER,L R Region 3, Office of Director 84/07/06 10pp 25898 014

--8408020225 Forwards ANL rept re technical review of Region III Insp Repts 70-0008/83-03 & 70-0008/84-01 ANL work confirms NRC conclusions re metabolic data & body radioactivity
BERGER,J D Oak Ridge Associated Univs 84/05/03 GREGER,R
Region 3, Office of Director 7pp 25898 024

8408170016 Application for amend to License SNM-7,authorizing incineration of low level radwaste at West Jefferson Nuclear Sciences area Response to list of questions following initial NRC review will be furnished by 840930
TOY,H L Battelle Memorial Institute, Columbus Laboratories
84/07/30 ROUSE,L Advanced Fuel & Spent Fuel Licensing Branch
2pp 26135 345

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP , CANOGA PARK, CA

8408150564 Forwards revised Pages 12,16 & 17 of ESG-80-17, "Physical Security Plan for Protection of Moderate Strategic Quantities of SNM at Hot Labs of Energy Sys Group of Rockwell Intl " Rev withheld (ref 10CFR2 790 & 9 5)
REMLEY,M E Rockwell International Corp 84/07/24 MARTIN,J B
Region 5, Office of Director 2pp 26080 306

DOCKET 70-0027 BABCOCK & WILCOX CO , LYNCHBURG, VA

8408300367 Forwards summary of NRC 840531 meeting w/B&W in Region II ofc re activities authorized by License SNM-42 List of meeting attendees also encl
STOHR,J P Region 2, Office of Director 84/06/07 ECKERT,J P
Babcock & Wilcox Co 3pp 26308 189

8408130454 Application for amend to License SNM-42,forwarding changes to fundamental nuclear matls control plan,per 10CFR70 32
Encls withheld (ref 10CFR2 790)
REGAN,N A Babcock & Wilcox Co 84/06/22 O'REILLY,J P Region 2,
Office of Director 1p 26040 362

8408300391 Forwards Insp Rept 70-0027/84-12 on 840611-15 No violations or deviations identified
STOHR,J P Region 2, Office of Director 84/06/28 ECKERT,J P
Babcock & Wilcox Co 2pp 26314 357

--8408300394 Insp Rept 70-0027/84-12 on 840611-15 No violations or deviations identified Major areas inspected limit of error associated w/inventory difference Details withheld (ref 10CFR2 790 & 73 21)
JONES,D W , MCALPINE,E J Region 2, Office of Director 84/06/27
1p 26314 359

8408310031 Ack receipt of 840619 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0027/84-09
STOHR,J P Region 2, Office of Director 84/07/12 ECKERT,J P
Babcock & Wilcox Co 1p 26335 165

--8408310039 Responds to NRC 840524 ltr re violation noted in Insp Rept 70-0027/84-09 Corrective actions measurement control coordinator shall investigate exceeded control data limits within established time interval
ECKERT,J P Babcock & Wilcox Co 84/06/19 O'REILLY,J P Region 2, Office of Director 3pp 26335 166

8408300398 Forwards Insp Rept 70-0027/84-14 on 840627-0702 No violations or deviations identified
STOHR,J P Region 2, Office of Director 84/07/18 ECKERT,J P
Babcock & Wilcox Co 2pp 26314 360

--8408300401 Insp Rept 70-0027/84-14 on 840627-0702 No violations or deviations identified Major areas inspected storage & internal control,physical inventory,records & repts Details withheld (ref 10CFR2 790 & 73 21)
TODD,G A , BATES,J W , JONES,D W Region 2, Office of Director
84/07/18 1p 26314 362

8408210483 Application to amend License SNM-42,adding Cs-137 to possession limits & allowing nuclear safety evaluations & consultations to be made by nuclear criticality safety engineer Fee encl
REGAN,N A Babcock & Wilcox Co 84/07/27 PAGE,R G Uranium Fuel Licensing Branch 23pp 26195 264

8408270524 Forwards Insp Rept 70-0027/84-16 on 840626-29 No violations or deviations identified
STOHR,J P Region 2, Office of Director 84/07/27 ECKERT,J P
Babcock & Wilcox Co 2pp 26256 136

--8408270531 Insp Rept 70-0027/84-16 on 840626-29 No violations or deviations identified Major areas inspected radiation protection,radwaste mgt,periodic maint of packaging & transportation
PEERY,W W , JENKINS,G R Region 2, Office of Director 84/07/25
5pp 26256 138

8408270254 Ack receipt of 840621 & 0726 ltrs informing NRC of steps taken to correct violations noted in Insp Rept 70-0027/84-10
STOHR,J P Region 2, Office of Director 84/08/01 ECKERT,J P
Babcock & Wilcox Co 1p 26258 129

--8408270258 Submits addl response to NRC 840523 ltr re violations noted in Insp Repts 70-0027/84-10 Corrective actions proposed changes of organizational structure will be reviewed for licensing impact
ECKERT,J P Babcock & Wilcox Co 84/07/26 O'REILLY,J P Region 2, Office of Director 2pp 26258 130

--8408270274 Responds to NRC 840523 ltr re violations noted in Insp Rept 70-0027/84-10 Corrective actions amend will be submitted to renewed license indicating present organization reporting scheme for health & safety function
ECKERT,J P Babcock & Wilcox Co 84/06/21 O'REILLY,J P Region 2, Office of Director 2pp 26258 132

--8408270280 Forwards Insp Rept 70-0027/84-10 on 840424-27 & notice of violation
STOHR,J P Region 2, Office of Director 84/05/23 ECKERT,J P
Babcock & Wilcox Co 2pp 26258 134

--8408270282 Notice of violation from insp on 840424-27
* Region 2, Office of Director 84/05/23 1p 26258 136

--8408270286 Insp Rept 70-0027/84-10 on 840424-27 Violation noted:failure to conform to required health & safety organizational structure
KAHLE,J B , MCALPINE,E J Region 2, Office of Director 84/05/21
6pp 26258 137

8408270116 Ack receipt of 840716 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0027/84-11
STOHR,J P Region 2, Office of Director 84/08/09 ECKERT,J P
Babcock & Wilcox Co 1p 26258 235

--8408270121 Responds to NRC 840622 ltr re violation noted in IE Insp Rept 70-0027/84-11 Corrective actions period data for control chart limits tested & data shown to be statistically different not used in computing new limits
ECKERT,J P Babcock & Wilcox Co 84/07/16 O'REILLY,J P Region 2, Office of Director 5pp 26258 236

--8408270125 Forwards IE Insp Rept 70-0027/84-11 on 840604-07 & notice of violation Encls withheld (ref 10CFR2 790 & 73 21)
STOHR,J P Region 2, Office of Director 84/06/22 ECKERT,J P
Babcock & Wilcox Co 2pp 26258 241

DOCKET 70-0036 COMBUSTION ENGINEERING, INC , WINDSOR, CT

8408210183 Forwards application to renew License SNM-33 Fee encl
ESKRIDGE,H E Combustion Engineering, Inc 82/02/26 PAGE,R G
Uranium Fuel Licensing Branch 2pp 26194 081

--8408210190 Informs of withdrawal of proprietary designation from Chapters II 9 0 & II 10 0 of license renewal application
ESKRIDGE,H E Combustion Engineering, Inc 82/07/21 CROW,W T
Uranium Fuel Licensing Branch 5pp 26194 082

--8408210197 Application for renewal of License SNM-33 Five oversize drawings encl Aperture cards are available in PDR
* Combustion Engineering, Inc 82/01/29 232pp 26194 087

8408020205 Application for amend to License SNM-33,providing proposed decommissioning plan required by License Condition 10 Proposed plan & fee encl
ESKRIDGE,H E Combustion Engineering, Inc 84/05/31 PAGE,R G
Uranium Fuel Licensing Branch 1p 25898 170

--8408020207 "Proposed Decommissioning Plan for Evaporation Ponds. "
* Combustion Engineering, Inc 84/05/31 6pp 25898 171

--8408020209 Ack receipt of 840531 request for approval of decommissioning plan Request classified as requiring minor amend to License SNM-33 Amend fee required,per 10CFR170 31
WEISS,D License Fee Management Branch 84/06/28 ESKRIDGE,H E
Combustion Engineering, Inc 2pp 25898 177

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC , ERWIN, TN

8408150156 Forwards "Environ Rept " per 840524 ltr
IDEKER,R L Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/07/27 Materials Licensing Branch 2pp 26105 068

--8408150161 "Environ Rept "
* Nuclear Fuel Services, Inc (subs of Getty Oil Co) 84/07/31
175pp 26105 070

8408170012 Forwards Rev 14 to physical safeguards plan,including updated drawings Rev withheld (ref 10CFR2 790)
HENSLEY,K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/03/29 BROWN,W B Fuel Facility Safeguards Licensing Branch
1p 26135 350

8408170392 Application for amend to License SNM-124,to include specific nuclear criticality safety controls on scrubber sys at 200 & 300 complexes,per NRC request
IDEKER,R L Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/03/30 PAGE,R G Uranium Fuel Licensing Branch 6pp
26134 185

--8408170393 Notifies of fee due for review of 840330 application for Amend 25 to License SNM-124
WEISS,D License Fee Management Branch 84/07/ 9 IDEKER,R
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p
26134 191

--8408170394 Notifies of fee due for review of 840330 application to amend License SNM-124 NRC will recompute fee after review complete & make refund,if necessary
WEISS,D License Fee Management Branch 84/04/27 IDEKER,R L
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p
26134 192

8408280174 Responds to NRC 840503 ltr re violations noted in Insp Rept 70-0143/84-13 No proprietary info found
QUINN,F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/05/29 STOHR,J P Division of Emergency Preparedness & Materials Safety 1p 26274 300

8408020154 Requests extension until 840704 for shutdown of process ventilation sys identified in 840611 ltr
IDEKER,R L Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/07/02 PAGE,R G Uranium Fuel Licensing Branch 3pp
25898 079

8408080393 Forwards findings & recommendations from 840618-21 site visit re review of upgraded physical protection program Measures suggested essential to provide required level of performance Comments requested within 30 days
BROWN,W B Fuel Facility Safeguards Licensing Branch 84/07/17
HENSLEY,K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
1p 25978 082

8408300284 Confirms arrangements made during 840716 telcon w/KP Barr re 840719 mgt meeting to discuss safeguards issues
STOHR,J P Region 2, Office of Director 84/07/17 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
26306 360

8408150545 Forwards Rev 65 to fundamental nuclear matl control plan, Section 3 Rev withheld (ref 10CFR2 790 & 9 5)
HENSLEY,K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/07/25 O'REILLY,J P Region 2, Office of Director 2pp
26080 304

8408280051 Ack receipt of 840710 ltr informing NRC of steps taken to correct violation noted in Insp Rept 70-0143/84-18
STOHR,J P Region 2, Office of Director 84/07/26 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p
26281 309

--8408280053 Responds to NRC 840613 ltr re violation noted in Insp Rept 70-0143/84-18 Corrective actions withheld (ref 10CFR2 790)
QUINN,F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/07/10 STOHR,P Division of Emergency Preparedness & Materials Safety 1p 26281 310

8408280298 Ack receipt of 840711 ltr informing NRC of steps taken to correct violation noted in Insp Rept 70-0143/84-19 Implementation of corrective actions will be examined during future insp
STOHR,J P Region 2, Office of Director 84/07/26 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p
26281 311

--8408280299 Responds to NRC 840619 ltr re violation noted in Insp Rept 70-0143/84-19 Corrective actions seal inventory prepared for central seal storage area & defective seals storage area & defective seals discarded
QUINN,F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/07/11 STOHR,P Division of Emergency Preparedness & Materials Safety 2pp 26281 312

--8408280300 Forwards Insp Rept 70-0143/84-19 on 840529-0601 & notice of violation Notice of violation & insp rept withheld (ref 10CFR2 790 & 10CFR73 21)
STOHR,J P Region 2, Office of Director 84/06/19 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
26281 314

8408030029 Forwards IE Safeguards Insp Rept 70-0143/84-22 on 840611-0706 No violations or deviations observed
STOHR,J P Region 2, Office of Director 84/07/27 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
25907 070

--8408030033 IE Safeguards Insp Rept 70-0143/84-22 on 840611-0706 No violations or deviations noted Major areas inspected plant operations, nuclear criticality safety & radiation & environ protection Portion of details withheld (ref 10CFR2 790)
LEE,T D , MCALPINE,E J Region 2, Office of Director 84/07/26
5pp 25907 072

8408300280 Confirms arrangements made during 840726 telcon re 840808 mgt meeting to discuss safeguards issues
STOHR,J P Region 2, Office of Director 84/07/30 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p
26306, 362

8408270411 Ack receipt of 840718 ltr informing NRC of steps taken to correct violations noted in Insp Rept 70-0143/84-20
STOHR,J P Region 2, Office of Director 84/08/02 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p
26286 334

--8408270413 Responds to NRC 840619 ltr re violations noted in Insp Rept 70-0143/84-20 Corrective actions nail pattern modified to permit use of addl nails w/o splitting crate stud frame & cement nails implemented
QUINN,F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/07/18 Region 2, Office of Director 3pp 26256 335

--8408270415 Forwards Insp Rept 70-0143/84-20 on 840529-0601 & notice of violation
STOHR,J P Region 2, Office of Director 84/06/19 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
26256 338

--8408270421 Notice of violation from insp on 840529-0601
Region 2, Office of Director 84/06/19 1p 26256 340

--8408270423 Insp Rept 70-0143/84-20 on 840529-0601 Violation noted failure to transport package of radioactive matl to burial site in strong, tight container
WRAY,J R , JENKINS,G A Region 2, Office of Director 84/06/15
4pp 26256 341

8408160310 Forwards IE Safeguards Mgt Meeting Rept 70-0143/84-28 on 840719
STOHR,J P Region 2, Office of Director 84/08/03 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
26106 145

--8408160317 IE Safeguards Mgt Meeting Rept 70-0143/84-28 on 840719 Major areas discussed improved safeguards control of maint & mod activities re matl access area barrier penetrations Details withheld (ref 10CFR95)
TOBIN,W J , MCGUIRE,D R Region 2, Office of Director 84/08/02
1p 26106 147

8408140136 PNO-II-84-047 on 840806, licensee reported inventory difference from 840703 physical inventory Difference was accounting loss & within associated limit of error & other regulatory requirements State of TN informed
MCALPINE,E J Region 2, Office of Director 84/08/07 1p
26048 321

8408130257 Ack receipt of check in amount of $18,750 for payment of civil penalties proposed on 840909 Corrective actions will be examined during subsequent insps
AXELRAD,J A Director's Office, Office of Inspection and Enforcement 84/08/08 TAYLOR,C W Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 26040 353

8408130380 Ack receipt of 840723 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0143/84-17
STOHR,J P Region 2, Office of Director 84/08/09 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p
26010 168

--8408130381 Responds to NRC 840622 ltr re violations noted in IE Insp Rept 70-0143/84-17 Corrective actions posting instructions reviewed w/administrative & secretarial personnel
QUINN,F K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
84/07/23 STOHR,J P Region 2, Office of Director 2pp
26010 169

--8408130382 Forwards IE Insp Rept 70-0143/84-17 on 840504-0608 & notice of violation Notice of violation & rept details withheld (ref 10CFR2 790 & 73 21)
STOHR,J P Region 2, Office of Director 84/06/22 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
26010 172

--8408130383 IE Insp Rept 70-0143/84-17 on 840504-0608 Violation noted failure to post notice of violation re radiological working conditions & proposed imposition of civil penalty & response to NRC Details withheld (ref 10CFR2 790 & 73 21)
LEE,T D , MCALPINE,E J Region 2, Office of Director 84/06/22
1p 26010 174

8408270420 Forwards Safeguards Insp Rept 70-0143/84-27 on 840723-27 No noncompliance noted
STOHR,J P Region 2, Office of Director 84/08/09 QUINN,F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
26258 243

--8408270427 Safeguards Insp Rept 70-0143/84-27 on 840723-27 No violations or deviations noted Major areas inspected measurements, measurement verification, internal controls & physical inventory Details withheld (ref 10CFR2 790)
BATES,J W , TODD,G A , MCALPINE,E J Region 2, Office of Director
84/08/09 1p 26258 245

8408230055 Submits items of interest re Whittaker Corp, Greenville, PA, EIAs & Kerr-McGee - Oklahoma
PAGE, R G Uranium Fuel Licensing Branch 84/08/16 DAVIS, J G
Office of Nuclear Material Safety & Safeguards, Director 2pp
26233 288

8408280034 Submits review schedule for application to renew License SNM-124 Comments & recommendations re scheduled insp dates requested
CROW, W T Uranium Fuel Licensing Branch 84/08/17 BARR, K P
Region 2, Office of Director 1p 26294 157

8408230281 Ack receipt of 840529 ltr transmitting Rev 61 to fundamental nuclear matl control plan & forwards proprietary changes to plan Changes withheld (ref 10CFR2 790)
STOHR, J P Region 2, Office of Director 84/08/20 QUINN, F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
26207 288

8408290351 Forwards environ assessment schedules for Westinghouse & NFS license renewals Site visits tentatively scheduled on 840919 for Westinghouse & 841024 for NFS W/o encl
WYNGARDEN, S D Uranium Fuel Licensing Branch 84/08/22 MCLEAN, R
Oak Ridge National Laboratory 1p 26310 362

8408280189 Forwards Mgt Meeting Rept 70-0143/84-32 on 840808-09 Meeting provided better understanding of NRC policy as found in Safeguards License Guidance Group Bulletin 38
STOHR, J P Region 2, Office of Director 84/08/23 QUINN, F K
Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp
26279 203

--8408280192 Mgt Meeting 70-143/84-32 on 840808-09 Items discussed NRC policy as found in Safeguards License Bulletin 38 & procedures re matl access area barrier penetrations Details withheld (ref 10CFR95)
TOBIN, W , MCQUIRE, D R Region 2, Office of Director 84/08/22
1p 26279 205

DOCKET 70-0221 GENERAL DYNAMICS CORP , GROTON, CT

8408310320 Ack receipt of 840207 ltr informing NRC of steps taken to correct violations noted in Insp Repts 30-03772/83-01 & 70-0221/83-01 Notice of violation justified Corrective actions due in 20 days
MARTIN, T T Division of Engineering & Technical Programs 84/08/13
TOVAR, F G General Dynamics Corp 2pp 26333 300

DOCKET 70-0303 CARNEGIE-MELLON UNIV , PITTSBURGH, PA

8408210189 Discusses IE insp of Licenses 37-00602-03 & SNM-281 on 840523-25 & forwards notice of violation Civil penalty not issued since corrective action prompt & extensive
MURLEY, T E Region 1, Office of Director 84/07/25 ROGERS, F
Carnegie-Mellon Univ , Pittsburgh, PA 3pp 26184 221

--8408210196 Notice of violation from insp on 840523-25 Violations noted failure to adequately control access to rooms containing radioactive matl & failure of radiation safety committee to meet quarterly during 1983
MURLEY, T E Region 1, Office of Director 84/07/25 4pp
26184 224

DOCKET 70-0364 BABCOCK & WILCOX CO , APOLLO, PA

8408010020 Forwards administrative amend fee for 840608 revs to Chapter XIII, "Environ Monitoring Program" of License SNM-414
AUSTIN, M A Babcock & Wilcox Co 84/06/25 ELASSER, T C Region 1,
Office of Director 1p 25866 361

8408060439 Summary of 840712 meeting w/B&W re plan for mod of existing Parks Township site facility for refurbishment of PWR control rod guide tubes Vendor will submit application to amend License SNM-414
LOYSEN, P Advanced Fuel & Spent Fuel Licensing Branch 84/07/30
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 1p
25937 315

8408080443 Ack receipt of 840608 ltr re changes to environ monitoring program No license amend required Submittal meets requirements of License Condition 25 Amend fee will be returned Revised pages to environ monitoring program encl
GREENMAN, E G Division of Project & Resident Programs 84/07/31
AUSTIN, M A Babcock & Wilcox Co 10pp 25977 164

8408150667 Application for amend to License SNM-414, increasing possession limit to 1,000 Ci isotopes in Condition 8 H 2 & 3,000 Ci in Condition 8 H 4
AUSTIN, M A Babcock & Wilcox Co 84/08/03 MCCABE, E C Region 1,
Office of Director 50pp 26103 309

8408220429 Discusses B&W request to amend License SNM-414 to increase matl possession limits Application meets criteria of 10CFR51 22(c)(11) for categorical exclusion & no environ assessment required
CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 84/08/17
STAROSTECKI, R Division of Project & Resident Programs 3pp
26209 350

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC , UNCASVILLE, CT

8408300134 "Effluent Monitoring Rept, Jan-June 1984 " W/840817 ltr
KIRK, W F United Nuclear Corp 84/06/30 MURLEY, T E Region 1,
Office of Director 2pp 26307 317

8408080324 Responds to 840601 comments on NRC 840503 regulatory effectiveness review rept Response on each item withheld (ref 10CFR2 790) Comments by 840828 requested
BROWN, W B Fuel Facility Safeguards Licensing Branch 84/07/13
AMY, G G United Nuclear Corp 1p 25978 204

8408150398 Forwards IE Safeguards Insp Rept 70-0371/84-07 on 840618-22 No violations observed
MARTIN, T T Division of Engineering & Technical Programs 84/07/27
AMY, G G United Nuclear Corp 2pp 26077 331

--8408150407 IE Safeguards Insp Rept 70-0371/84-07 on 840618-22 No noncompliance noted Major areas inspected measurement controls, inventory difference & associated limit of error verification & records & repts
SMITH, G C , DELLA RATTA, A , KEIMIG, R R Region 1, Office of Director 84/07/26 3pp 26077 333

8408030146 Responds to 840717 ltr requesting copy of closeout rept on United Nuclear Corp bldg in New Haven, CT Survey results indicate max identified fixed contamination level less than 25% of allowable limit
STAROSTECKI, R Division of Project & Resident Programs 84/07/31
HOUSMAN, J J HRP Associates 3pp 25915 328

--8408030147 Forwards IE Insp Rept 70-0371/76-06 on 760308-10 No noncompliance noted
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 76/04/02 GAISE, G D United Nuclear Corp 3pp
25915 330

--8408030148 IE Insp Rept 70-0371/76-06 on 760308-10 No noncompliance noted Major areas inspected licensee final survey rept after decontamination of H-tract facility
PLUMLEE, K E , KNAPP, P J Region 1, Philadelphia, Office of the Director 76/04/02 6pp 25915 333

8408230055 Submits items of interest re Whittaker Corp, Greenville, PA, EIAs & Kerr-McGee - Oklahoma
PAGE, R G Uranium Fuel Licensing Branch 84/08/16 DAVIS, J G
Office of Nuclear Material Safety & Safeguards, Director 2pp
26233 288

DOCKET 70-0398 COMMERCE, DEPT OF, WASHINGTON, DC

8408230055 Submits items of interest re Whittaker Corp, Greenville, PA, EIAs & Kerr-McGee - Oklahoma
PAGE, R G Uranium Fuel Licensing Branch 84/08/16 DAVIS, J G
Office of Nuclear Material Safety & Safeguards, Director 2pp
26233 288

DOCKET 70-0466 MAINE MARITIME ACADEMY, CASTINE, ME

8408010397 Discusses IE insp of Licenses SNM-493 & SUD-283 on 840614 & forwards notice of violation
MARTIN, T T Region 1, Office of Director 84/07/19 CUKIERSKI, M W
Maine Maritime Academy, Castine, ME 2pp 25866,053

--8408010400 Notice of violation from insp on 840614, Violation noted yearly calibr of survey meters undocumented, monthly exchange of film badges not performed & sealed sources not tested for leakage
* Region 1, Office of Director 84/07/19 1p 25866 055,

DOCKET 70-0687 UNION CARBIDE CORP TUXEDO, NY

8408090556 Forwards SNM-639 license submittal & updated pages, per 840713 telcon Updates address license conditions, safety demonstration & leak testing guidelines Annual rept also encl
MCGOVERN, J J Union Carbide Corp 84/07/16 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 243pp 25984 052

8408150247 Forwards info re License SNM-639 submittal, per 840713 telcon
MCGOVERN, J J Union Carbide Corp 84/07/16 ROUSE, L C Division of Fuel Cycle & Material Safety 245pp 26103 001

8408270510 Forwards Insp Repts 50-054/84-02 & 70-0687/84-02 on 840709-11 No violations observed
STAROSTECKI, R Division of Project & Resident Programs 84/08/07
MCGOVERN, J J Union Carbide Corp 2pp 26256 162 24X
Fiche 50-054, 84/08/01, 8408270510

--8408270518 Insp Repts 50-054/84-02 & 70-0687/84-02 on 840709-11 No deviations of violations identified Major areas inspected organization, facility changes & mods, safety committees, nuclear criticality safety & radiation protection
ROTH, J Region 1, Office of Director ELBASSER, T C Division of Project & Resident Programs 84/08/02 6pp 26256 164 24X
Fiche 50-054, 84/08/07, 8408270510

DOCKET 70-0734 GA TECHNOLOGIES, INC , SAN DIEGO, CA

8408020253 Forwards Rev 4 to "Part II Specs Vol, SNM-696 Matl License Renewal," in response to NRC questions
MOWRY, W R GA Technologies, Inc /General Atomic Co 84/06/28
CROW, W T Office of Nuclear Material Safety & Safeguards, Director
1p 25898 112

--8408020256 Rev 4 to "Part II Specs Vol, SNM-696 Matl License Renewal "
* GA Technologies, Inc /General Atomic Co 84/06/30 5pp
25898 113

8408080425 Requests comments on encl review of commitments of upgraded Category I physical protection plan Response requested in 30 days Encl withheld
BROWN, W B Fuel Facility Safeguards Licensing Branch 84/07/16,
MOWRY, R GA Technologies, Inc /General Atomic Co 1p 25977 190

8408080147 Forwards IE Insp Rept 70-0734/84-07 on 840604-08 No violations noted
WENSLAWSKI, F A Region 5, Office of Director 84/07/18
COLANDREA, T R GA Technologies, Inc /General Atomic Co 2pp
25974 314

--8408080151 IE Insp Rept 70-0734/84-07 on 840604-08 No violations noted Major areas inspected organization, facility changes & mods, internal review & audit, radiation protection, training & emergency planning
BROCK, B L , ZURAKOWSKI, P R , THOMAS, R D Region 5, Office of Director 84/07/13 11pp 25974 316

8408080371 Notifies that License Condition 9 1 C to License SNM-696 re safeguards contingency plan, corrected to read License Condition 9 1 B
BROWN, W B Fuel Facility Safeguards Licensing Branch 84/07/23
MOWRY, W R GA Technologies, Inc /General Atomic Co 1p 25978 083

8408230216 Forwards IE Safeguards Insp Rept 70-0734/84-09 on 840716-20 & 31 & notice of violation Encls withheld (ref 10CFR73 21)
SCHUSTER, M D Region 5, Office of Director 84/08/17
COLANDREA, T R GA Technologies, Inc /General Atomic Co 2pp
26207 181

8408270337 Forwards Safeguards Insp Rept 70-0734/84-08 on 840709-13 & 19-27 No violations noted
SCHUSTER, M D Region 5, Office of Director 84/08/21
COLANDREA, T R GA Technologies, Inc /General Atomic Co 2pp
26238 148

--8408270346 Safeguards Insp Rept 70-0734/84-08 on 840709-27 No violations noted Major areas inspected physical inventory, inventory verification & records & repts Details withheld (ref 10CFR2 790)
NELSON, G B , WIEDER, A V , HAMADA, G H Region 5, Office of Director 84/08/17 1p 26238 150

8408270311 Forwards ltrs documenting cooperation w/local law enforcement agencies & medical facilities re radiological contingency plan
MOWRY, W R GA Technologies, Inc /General Atomic Co 84/08/22
CUNNINGHAM, R Division of Fuel Cycle & Material Safety THOMAS, C O Standardization & Special Projects Branch 4pp 26241 004 24X
Fiche 50-089, 84/08/22, 8408270311

DOCKET 70-0820 UNITED NUCLEAR CORP , WOOD RIVER JUNCTION, RI

8408010024 Forwards final survey data sheets for third floor columns room ceiling, for insertion in final survey rept
HELGESON, K A United Nuclear Corp 84/06/27 CROW, W T Division of Fuel Cycle & Material Safety 7pp 25897 098

8408020096 Forwards revised discussion page to replace existing page in final survey rept, covering ceiling of third floor columns room Page located in Vol II, Section I, Subsection 3 4 1 1
HELGESON, K A United Nuclear Corp 84/07/05 CROW, W T Office of Nuclear Material Safety & Safeguards, Director 3pp 25898 107

DOCKET 70-0824 BABCOCK & WILCOX CO , LYNCHBURG, VA

8408300190 Ack receipt of 840606 ltr informing NRC of steps taken to correct violations noted in Insp Rept 70-0824/84-01
STOHR, J P Region 2, Office of Director 84/06/19 ENGELDER, T C
Babcock & Wilcox Co 1p 26308 001

--8408300194 Responds to NRC 840509 ltr re violations noted in Insp Rept 70-0824/84-01 Corrective actions support brackets on drum gripper modified to remove sharp corners & all fork truck operators in waste shipment loading will be trained
ENGELDER, T C Babcock & Wilcox Co 84/06/06 STOHR, J P Region 2, Office of Director 4pp 26308 002

--8408300200 Forwards Insp Rept 70-0824/84-01 on 840418-19 & notice of violation
STOHR, J P Region 2, Office of Director 84/05/08 ENGELDER, T C
Babcock & Wilcox Co 2pp 26308 006

--8408300202 Notice of Violation from insp on 840418-19
* Region 2, Office of Director 84/05/08 2pp 26308 008

--8408300206 Insp Rept 70-0824/84-01 on 840418-19 Violations noted unauthorized transfer of radioactive matl, failure to label radwaste package & failure to meet DOT requirements for shipment of radioactive matl
ALBRIGHT, R H , JENKINS, G R Region 2, Office of Director
84/05/07 4pp 26308 010

8408020203 Application for Amend 7 to License SNM-778, revising Section A 9 4 1 to permit postings other than caution radiation area signs, where appropriate Fee encl
OLSEN, A F Babcock & Wilcox Co 84/06/20 PAGE, R G Uranium Fuel Licensing Branch 6pp 25898 179

DOCKET 70-0925 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8408300322 "Radioactivity in Gaseous Effluents & Particulates Elevated & Total Release, No Batch Mode, Jan-June 1984 " W/840821 ltr
SINKE, G J Kerr-McGee Corp 84/06/30 3pp 26308 329

DOCKET 70-0938 MASSACHUSETTS INSTITUTE OF TECHNOLOGY, CAMBRIDGE, MA

8408130205 Forwards Rev 1 to 820728 application for renewal of License SNM-986, Rev includes responses to NRC comments received on 830301 re renewal application
CLARK, L Massachusetts Institute of Technology, Cambridge, MA
84/07/13 PAGE, R G Uranium Fuel Licensing Branch 2pp
26060 053

--8408130212 Rev 1 to 820728 application for renewal of License SNM-986, authorizing possession of listed licensed matl
CLARK, L , POWELL, P C Massachusetts Institute of Technology, Cambridge, MA 84/07/13. 110pp 26060 056

8408280351 Requests review & comments on 840713 application for renewal of License SNM-986 Review schedule listed
CROW, W T Uranium Fuel Licensing Branch 84/08/17 WENZINGER, E
Region 1, Office of Director 1p 26292 361

DOCKET 70-0984 BATTELLE MEMORIAL INSTITUTE RICHLAND, WA

8408090120 Forwards IE Insp Rept 70-0984/84-03 on 840620 No noncompliance noted
WENSLAWSKI,F A Region 5, Office of Director 84/07/23
SIMPSON,C L Battelle Memorial Institute, Pacific Northwest Laboratories 2pp 25992 245

--8408090122 IE Insp Rept 70-0984/84-03 on 840620 No violations noted
Major areas inspected emergency planning (fire prevention & protection,test & drills,facilities,equipment & procedures) & radiation protection
BROCK,B L , THOMAS,R D Region 5, Office of Director 84/07/23
4pp 25992 247

DOCKET 70-1068 FLORIDA, UNIV OF, GAINESVILLE, FL

8408130261 Application to renew License SNM-1050,extending expiration date to 850930
DIAZ,N J Florida, Univ of, Gainesville, FL 84/07/19 PAGE,R G Uranium Fuel Licensing Branch 3pp 26040 351

DOCKET 70-1113 GENERAL ELECTRIC CO , WILMINGTON, NC

8405300761 Responds to 840406 telcon Internal & external radiation exposure data encl
VAUGHAN,C M General Electric Co 84/04/11 BOONG,A L NRC - No Detailed Affiliation Given 2pp 24732 317

--8405300762 Personnel monitoring of total wholebody exposure for 1982
VAUGHAN,C M General Electric Co 82/12/31 Office of Management and Program Analysis 2pp 24732 319

--8405300763 Personnel monitoring of total wholebody exposure for 1981
VAUGHAN,C M General Electric Co 81/12/31 Office of Management and Program Analysis 1ipp 24732 321

8408280111 Ack receipt of NRC 840712 ltr re results of Insp Rept 70-1113/84-07 on 840618-21 Rept contains no proprietary info
VAUGHAN,C M General Electric Co 84/07/17 STOHR,J P Region 2, Office of Director 1p 26261 112

--8408280118 Forwards Insp Rept 70-1113/84-07 on 840618-21 No violations or deviations identified
STOHR,J P Region 2, Office of Director 84/07/12 LONG,J A General Electric Co 2pp 26261 113

--8408280123 Insp Rept 70-1113/84-07 on 840618-21 No violations or deviations identified Major areas inspected radwaste mgt & environ monitoring
STODDART,P G , MONTGOMERY,D M Region 2, Office of Director 84/07/09 10pp 26261 115

8408270534 Forwards Insp Rept 70-1113/84-10 on 840709-13 No violations or deviations identified
STOHR,J P Region 4, Office of Director 84/07/27 LONG,J A General Electric Co 2pp 26256 129

--8408270540 Insp Rept 70-1113/84-10 on 840709-13 No violations or deviations noted Major areas inspected maint,training, nuclear criticality safety,Part 21 operations review, procedures control & independent effort
KAHLE,J B , MCALPINE,E J Region 2, Office of Director 84/07/25
5pp 26256 131

8408280362 Forwards Insp Rept 70-1113/84-09 on 840716-20 No noncompliance noted
STOHR,J P Region 2, Office of Director 84/08/09 LONG,J A General Electric Co 2pp 26281 316

--8408280367 Insp Rept 70-1113/84-09 on 840716-20 No noncompliance noted Major areas inspected measurement & statistical controls, organization & physical inventory preparations Details withheld (ref 10CFR2 790)
CLAY,E L , MCALPINE,E J Region 2, Office of Director 84/08/08
1p 26281 318

8408140199 Ack receipt of 840214 & 0321 revs to fundamental nuclear matl control plan Portions of plan described in encl not consistent w/10CFR70 32(c) Encl list of inconsistent changes withheld (ref 10CFR2 790)
STOHR,J P Region 2, Office of Director 84/08/10 LONG,J A General Electric Co 2pp 26042 361

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

8406260175 Forwards IE Insp Rept 70-1143/84-02 on 840507-12 No violations noted
STAROSTECKI,R Division of Project & Resident Programs 84/06/06
SLEMBER,R Westinghouse Electric Corp 2pp 25164 343

--8406260179 IE Insp Rept 70-1143/84-02 on 840507-12 No violations noted
Major areas inspected confirmatory survey of licensee decommissioned site located at Cheswick,PA
ROTH,J , ELSASSER,T C Region 1, Office of Director 84/06/05
7pp 25164 345

--8406260184 "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use of Termination of Licenses for Byproduct,Source or SNM "
* Division of Fuel Cycle & Material Safety 76/11/30 7pp 25164 352

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

8408310254 Forwards Insp Rept 70-1151/84-07 on 840514-18 No noncompliance noted
STOHR,J P Region 2, Office of Director 84/05/31 BRITTON,W H Westinghouse Electric Corp 2pp 26335 169

--8408310255 Insp Rept 70-1151/84-07 on 840514-18 No noncompliance noted Major areas inspected physical inventory observation Details withheld (ref 10CFR2 790 & 73 21)
TODD,C A , JONES,D W , BATES,J W Region 2, Office of Director 84/05/30 1p 26335 171

8408280148 Ack receipt of 840531 ltr re Safeguards Insp Rept 70-1151/84-07 on 840514-18
SANDERS,C F Westinghouse Electric Corp 84/06/13 O'REILLY,J P Region 2, Office of Director 1p 26269 357

8408010040 Requests limited exemption to regulations & fundamental nuclear matl control plan Request described in App A to ltr Fee encl App A withheld
NARDI,A J Westinghouse Electric Corp 84/06/28 BROWN,W D Fuel Facility Safeguards Licensing Branch 1p 25866 349

8408160352 Application for amend to License SNM-1107,changing license condition to nuclear matl control plan,per encl App A Fee encl App A withheld (ref 10CFR2 790)
NARDI,A J Westinghouse Electric Corp 84/07/12 BROWN,W D Fuel Facility Safeguards Licensing Branch 1p 26126 247

8408160064 Responds to 840628 ltr requesting limited exception to requirements of 10CFR70 58(e) Unnumbered license condition to Amend SG-1 issued
BROWN,W D Fuel Facility Safeguards Licensing Branch 84/07/16
SANDERS,C F Westinghouse Electric Corp 2pp 26126 354

8408080386 Approves 840712 request for mod to unnumbered license condition issued on 840529 for License SNM-1107
BROWN,W D Fuel Facility Safeguards Licensing Branch 84/07/23
SANDERS,C F Westinghouse Electric Corp 1p 25978 084

8408150383 Forwards Rev 4 to Columbia site emergency plan Rev effective 840430
FISCHER,R E Westinghouse Electric Corp 84/07/24 Division of Fuel Cycle & Material Safety 2pp 26106 001

--8408150389 Rev 4 to Columbia site emergency plan
* Westinghouse Electric Corp 84/04/30 22pp 26106 003

8408270222 Forwards Insp Rept 70-1151/84-09 on 840723-27 No violations or deviations identified
STOHR,J P Region 2, Office of Director 84/08/09 D'AMORE,M Westinghouse Electric Corp 2pp 26258 232

--8408270225 Insp Rept 70-1151/84-09 on 840723-27 No violations or deviations identified Major areas inspected statistical controls associated w/nuclear matl control & accounting measurements Details withheld (ref 10CFR2 790)
JONES,D W , MCALPINE,E J Region 2, Office of Director 84/08/08
1p 26258 234

8408230055 Submits items of interest re Whittaker Corp,Greenville,PA, EIAs & Kerr-McGee - Oklahoma
PAGE,R G Uranium Fuel Licensing Branch 84/08/16 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director. 2pp 26233 288

8408290560 Effluent monitoring rept for Jan-June 1984
GOODWIN,W L Westinghouse Electric Corp 84/08/17 Director's Office, Office of Inspection and Enforcement 1p 26295 353

8408290351 Forwards environ assessment schedules for Westinghouse & NFS license renewals Site visits tentatively scheduled on 840919 for Westinghouse & 841024 for NFS W/o encl
WYNGARDEN,S D Uranium Fuel Licensing Branch 84/08/22 MCLEAN,R Oak Ridge National Laboratory 1p 26310 362

DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8408300322 "Radioactivity in Gaseous Effluents & Particulates Elevated & Total Release,No Batch Mode,Jan-June 1984 " W/840821 ltr
SINKE,G J Kerr-McGee Corp 84/06/30 3pp 26308 329

DOCKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA

8408300296 Forwards Insp Rept 70-1201/84-04 on 840521-22 No violations or deviations noted
STOHR,J P Region 2, Office of Director 84/06/06 ALTO,R A
Babcock & Wilcox Co 2pp 26306 347

--8408300307 Insp Rept 70-1201/84-04 on 840521-22 No violations or deviations noted Major areas inspected nuclear criticality safety, operations review, 10CFR21, safety committees, facility changes & mods, training & internal audits
KAHLE,J B , MCALPINE,E J Region 2, Office of Director 84/06/06 4pp 26306 349

8408280090 Ack receipt of 840618 & 0725 ltrs informing NRC of steps taken to correct violation noted in Insp Rept 70-1201/84-02
STOHR,J P Region 2, Office of Director 84/08/03 ALTO,R A
Babcock & Wilcox Co 1p 26282 225

--8408280270 Responds to NRC 840529 ltr re violation noted in Insp Rept 70-1201/84-02 Corrective actions revised pages of License SNM-1168 reflecting organizational changes submitted on 840504 for approval
ZEFF,D W Babcock & Wilcox Co 84/06/18 STOHR,J P Region 2, Office of Director 3pp 26282 226

--8408280277 Supplemental response to violations noted in Insp Rept 70-1201/84-02 Corrective actions health & safety reporting chain restructured to report to regulatory control mgt
ZEFF,D W Babcock & Wilcox Co 84/07/25 STOHR,J P Region 2, Office of Director 2pp 26282 229

--8408280282 Forwards Insp Rept 70-1201/84-02 on 840417-20 & notice of violation
STOHR,J P Region 2, Office of Director 84/05/23 ALTO,R A
Babcock & Wilcox Co 2pp 26282 231

--8408280285 Notice of violation from insp on 840417-20
* Region 2, Office of Director 84/05/23 1p 26282 233

--8408280269 Insp Rept 70-1201/84-02 on 840417-20 Violation noted reorganization implemented w/o license condition change
ALBRIGHT,R H , JENKINS,G R Region 2, Office of Director 84/05/23 5pp 26282 234

KET 70-1257 EXXON NUCLEAR CO , INC , RICHLAND, WA

8080435 Approves 840712 request to download 10 encapsulated fuel ods containing up to 600 g U-235
BROWN,W B Fuel Facility Safeguards Licensing Branch 84/07/16
SCHNEIDER,R A Exxon Nuclear Co , Inc (subs of Exxon Corp) 1p 25977 183

10B130502 Forwards IE Insp Rept 70-1257/84-05 on 840618-22 & notice of violation
SCARANO,R A Division of Radiological Safety & Safeguards Program
84/07/27 NILSON,R Exxon Nuclear Co , Inc (subs of Exxon Corp) 2pp 26032 340

-8408130507 Notice of violation from insp on 840618-22
THOMAS,R D Region 5, Office of Director 84/07/27 2pp 26032 342

--8408130511 IE Insp Rept 70-1257/84-05 on 840618-22 Violations identified containers not labeled w/mass & enrichment of content & continuous fissile inventory sheet not maintained
BROCK,B L , ZURAKOWSKI,P R , THOMAS,R D Region 5, Office of Director 84/07/20 9pp 26032 344

8408080273 Forwards IE Reactive Safeguards Insp Rept 70-1257/84-06 on 840627-29 No violations noted Rept withheld (ref 10CFR2 790)
SCHUSTER,M D Region 5, Office of Director 84/08/02 NILSON,R
Exxon Nuclear Co , Inc (subs of Exxon Corp) 1p 25966 079

8408220340 Forwards proprietary IE Safeguards Insp Rept 70-1257/84-07 on 840801-03 No violations noted Rept withheld (ref 10CFR2 790)
SCHUSTER,M D Region 5, Office of Director 84/08/16 NILSON,R
Exxon Nuclear Co , Inc (subs of Exxon Corp) 2pp 26191 355

8408300007 Ack receipt of 840514 ltr transmitting Rev 6 to physical protection plan for matl of low strategic significance Changes acceptable Rev withheld (ref 10CFR2 790)
SCHUSTER,M D Safeguards & Materials Program Branch 84/08/22
SCHNEIDER,R A Exxon Nuclear Co , Inc (subs of Exxon Corp) 1p 26331 340

DOCKET 70-1308 GENERAL ELECTRIC CO , SAN JOSE, CA

8408130033 Responds to 840711 request for clarification of items identified during review of new rev to consolidated SAR, NEDO-21326 D Revised pages encl
HERRINGTON,C C General Electric Co 84/07/24 CUNNINGHAM,R E
Division of Fuel Cycle & Material Safety 15pp 26058 330

8408130590 Summary of 840726 meeting w/GE in Silver Spring,MD re GE response to comments on update of consolidated SAR for Morris Operation
ROBERTS,J P Advanced Fuel & Spent Fuel Licensing Branch 84/08/07
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 1p 26038 313

8408160461 Dockets Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan," w/WC Wheadon & DM Dawson 830329 & 0210 ltrs,respectively,to assure docket file complete due to rev & resubmittal of rept as Rev 8
ROBERTS,J P Advanced Fuel & Spent Fuel Licensing Branch 84/08/10
Advanced Fuel & Spent Fuel Licensing Branch 1p 26126 078

--8408160466 Forwards Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan " Rev due to organizational change within spent fuel svcs operation & GE U Mgt Corp
WHEADON,W C General Electric Co 83/03/29 ROBERTS,J P NRC - No Detailed Affiliation Given 1p 26126 079

--8408160472 Forwards Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan," referenced in License SNM-2500 for GE Morris Operation & incorporated in NEDO-21326,App B-8
DAWSON,D M General Electric Co 83/02/10 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 1p 26126 080

8408310268 PNO-III-84-067 first of several spent reactor fuel shipments from Cooper Station arrived safely Rail shipment consisted of three NRC-certified shipping casks,each containing 18 spent fuel assemblies
LOVENDALE,P , PAPERIELLO,C J Region 3, Office of Director
84/08/24 1p 26333 329

DOCKET 70-1342 CORATOMIC, INC , INDIANA, PA

8408310061 Insp Findings & Licensee Ack on 840817 of License SNM-1319 Insp findings no violations observed Steps taken to correct violations identified during last insp verified
LUDUN,R H Region 1, Office of Director 84/08/17 1p 26334 230

DOCKET 70-1362 HAHNEMANN MEDICAL COLLEGE & HOSP , PHILADELPHIA, PA

8408060373 Ack receipt of 840207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1362/83-01 & 30-02959/83-01 Addl info requested within 30 days
MARTIN,T T Division of Engineering & Technical Programs 84/07/16
MILLS,L C Hahnemann Univ Hosp , Philadelphia, PA (formerly Hahnemann Medical Coll & Hosp) 3pp 25936 100

--8408060378 Forwards response to NRC 831223 ltr re violations noted in IE Insp Repts 70-1362/83-01 & 30-02959/83-01
MILLS,L C Hahnemann Univ Hosp , Philadelphia, PA (formerly Hahnemann Medical Coll & Hosp) 84/02/07 MARTIN,T T Division of Engineering & Technical Programs 1p 25936 103

--8408060382 Responds to NRC 831223 ltr re violations noted in IE Insp Repts 70-1362/83-01 & 30-02959/83-01 Corrective actions security guards posted at all street entrances to bldg & members of housekeeping staff attended training sessions
DAY, J Hahnemann Univ Hosp , Philadelphia, PA (formerly Hahnemann Medical Coll & Hosp) 84/01/30 MARTIN, T T Division of Engineering & Technical Programs 27pp 25936 104

DOCKET 70-1450 BERKSHIRE MEDICAL CENTER, PITTSFIELD, MA

8408230183 Ack receipt of 840417 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 20-12009-01, 20-02009-03 & SNM-1439 on 840213
MARTIN, T T Division of Engineering & Technical Programs 84/08/15
PRYER, K Berkshire Medical Center, Pittsfield, MA 1p 26209 273

--8408230196 Responds to NRC 840221 ltr re violations noted in IE insp of Licenses 20-12009-01, 20-12009-03 & SNM-1439 on 840213 Corrective actions thyroid monitoring required 3 days after administration of radioiodine
WU, R R Berkshire Medical Center, Pittsfield, MA 84/04/17
MARTIN, T T Division of Engineering & Technical Programs 2pp 26209 274

DOCKET 70-1941 PASSAIC GENERAL HOSP , PASSAIC, NJ

8408100041 Discusses IE insp of Licenses SNM-1525 & 29-01040-01 & forwards notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/08/07
KORNETT, M Passaic General Hosp , Passaic, NJ 2pp 25990 057

--8408100051 Notice of violation from insp on 840718 Violation noted no security personnel received training in radiation safety procedures & surveys of hands, feet & clothing not monitored by personnel before leaving area
* Region 1, Office of Director 84/08/07 1p 25990 059

DOCKET 70-2377 DENTSPLY INTERNATIONAL, INC , YORK, PA

8408060084 IE Insp Findings & Licensee Ack dtd 840718 of License SNM-1669 Insp findings records of sealed source leak tests not properly maintained & NRC-3 form not posted
MCFADDEN, J Region 1, Office of Director 84/07/18 1p 25935 286

DOCKET 70-2571 YALE-NEW HAVEN HOSP , NEW HAVEN, CT

8408310140 Discusses insp of Licenses SNM-1734 & 06-00819-03 on 840605 & 21 & forwards notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/08/23
MCINTYRE, D Yale-New Haven Hosp , New Haven, CT 2pp 26322 203

--8408310144 Notice of violation from insp on 840605 & 21 Violation noted individual working in restricted areas received whole body radiation dose of 1 39 rems during fourth calendar quarter of 1983
* Region 1, Office of Director 84/08/22 3pp 26322 205

DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO , CINCINNATI, OH

8408210491 Forwards proprietary IE Safeguards Mail Control & Accountability Insp Rept 70-2838/84-06 on 840731 No noncompliance noted Rept withheld (ref 10CFR2 790 & 73 21)
AXELSON, W L Region 3, Office of Director 84/08/16 SCHOTT, J R Cincinnati Gas & Electric Co 2pp 26177 231

DOCKET 70-2872 RS HOLDING, INC , CLEVELAND, OH

8408130180 Ack receipt of encl 840727 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 70-2872/84-01 & 70-2872/84-02 Encl withheld (ref 10CFR2 790)
AXELSON, W L Region 3, Office of Director 84/08/08 PALKO, G Reuter-Stokes, Inc 1p 26006 334

DOCKET 70-2884 LONG ISLAND LIGHTING CO , HICKSVILLE, NY

8408070259 Advises of issuance of Amend 2 to License SNM-1857, extending expiration date to 851231 or upon conversion of CPPR-95 to OL, per 840417 application All other conditions of license remain unchanged SER encl
PAGE, R G Uranium Fuel Licensing Branch 84/07/31 Long Island Lighting Co 1p 25957 034

8408070266 SER supporting issuance of amend to License SNM-1857, extending expiration date to 851231 or upon conversion of CPPR-95 to OL
KETZLACH, N Uranium Fuel Licensing Branch 84/07/31 1p 25957 035

DOCKET 70-2988 PHILADELPHIA ELECTRIC CO , PHILADELPHIA, PA

8408060368 Issues Amend 1 to License SNM-1926 Amend authorizes using Pu-239, depleted U & Th-230, revises License Conditions 17 re physical security & adds License Conditions 17 & 18 Safety evaluation encl
PAGE, R G Uranium Fuel Licensing Branch 84/07/27 BAUER, E G Philadelphia Electric Co 3pp 25951 007

--8408060371 SER supporting Amend 1 to License SNM-1926
SERINI, B L Uranium Fuel Licensing Branch 84/07/27 9pp 25951 010

--8408060375 Grants categorical exclusion from EIA/EIS re 840607 request to receive & use Pu-239, depleted U & Th-230 as plated calibr sources
PAGE, R G Uranium Fuel Licensing Branch 84/07/27 Uranium Fuel Licensing Branch 1p 25951 019

8408090238 Forwards NRC 840727 Amend 1 to License SNM-1926 & SER in support of amend Related correspondence
VOGLER, B H Hearing Branch 4 DSB 872 84/08/07 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 14pp 25972 152 24X Fiche 50-352, 84/08/07, 8408090232

DOCKET 70-2998 GULF STATES UTILITIES CO , BEAUMONT, TX

8408290338 Forwards request for addl info re 840416 application for license to store unirradiated fuel onsite Attempt will be made to process application by 841201 if info reviewed by 840924
BIDINGER, G H Uranium Fuel Licensing Branch 84/08/22 BOOKER, J E Gulf States Utilities Co 2pp 26311 300 24X Fiche 50-458, 84/08/22, 8408290338

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0008 COMMONWEALTH EDISON CO

8408060429 Informs of expiration of QA program approval for radioactive package on 840630 Application fee & renewal request required for continuation of program
MACDONALD, C E Transportation Certification Branch 84/07/30 Commonwealth Edison Co 1p 25937 334

DOCKET 71-0011 ARROW TANK & ENGINEERING CO

8408080268 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified
MACDONALD, C E Transportation Certification Branch 84/08/01
SOLTIS, L R Arrow Tank & Engineering Co 1p 25978 310

DOCKET 71-0014 ADIRONDACK STEEL CASTING CO

8408080139 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired, NRC should be so notified
MACDONALD, C E Transportation Certification Branch 84/08/01
HOLLANDER, W D Adirondack Steel Casting Co , Inc 1p 25979 105

DOCKETED ITEMS

DOCKET 71-0015 CHICAGO BRIDGE & IRON CO

8408080176 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
KRUZIC,R W Chicago Bridge & Iron Co lp 25978 351

DOCKET 71-0016 NORTHWEST AIRLINES, INC

8408080264 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
HUSKINS,W F Northwest Airlines,Inc lp 25978 312

8408310436 Forwards QA program approval for radioactive matl package 0016,Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
LIGHTFOOT,B H Northwest Airlines,Inc lp 26350 140

--8408310438 QA program approval for radioactive matl package 0016,Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
lp 26350 141

DOCKET 71-0020 INTERNATIONAL TESTING LABS

8408080126 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
MARANS,M P International Testing Laboratories, Inc lp
25979 116

DOCKET 71-0022 NEWPORT NEWS INDUSTRIAL CORP

8408080270 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
MORIN,E U Newport News Industrial Corp (subs of Newport News Shipbuilding) lp 25978 309

DOCKET 71-0028 BORG-WARNER CORP

8408080136 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
BOOTH,J H Borg-Warner Corp lp 25979 107

DOCKET 71-0032 PANHANDLE EASTERN PIPE LINE CO

8408080220 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
DOHRMAN,K F Panhandle Eastern Pipe Line Co lp 25978 324

DOCKET 71-0033 IND TEST LAB SERVICES CORP

8408080137 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
HAMDRAHAN,E Industrial Testing Laboratory Services Corp lp
25979 106

DOCKET 71-0031 BABCOCK & WILCOX CO

8408080401 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
LONE,J R Babcock & Wilcox Co lp 25978 078

DOCKET 71-0034 ITT GRINNELL CORP

8408080283 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
KOWALSKI,J G ITT Grinnell (subs of ITT) lp 25978 305

DOCKET 71-0037 NAVY, DEPT OF

8408080444 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
Navy, Dept of lp 25977 182

DOCKET 71-0038 CRANE CO

8408060421 Informs that QA program approval for radioactive packages expired on 840531 Request for renewal & fee required for continuation of QA program
MACDONALD,C E Transportation Certification Branch 84/07/30
Crane Co lp 25937 340

DOCKET 71-0039 WALWORTH CO

8408080279 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SHIELDS,R R Walworth Co (subs of IU International Corp) lp
25978 307

8408210093 Informs that QA program approval for radioactive package no longer needed Facility in Greensburg,PA not operational
AWTREY,P H Walworth Co (subs of IU International Corp)
84/08/01 MACDONALD,C E Transportation Certification Branch lp
26195 351

DOCKET 71-0044 UNITED AIRLINES, INC

8408080071 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
KASTENS,J W United Airlines, Inc lp 25981 101

DOCKET 71-0047 CAPITOL INTERNATIONAL AWYS , INC

8408080076 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SPARKS,E Capitol International Airways, Inc lp 25981 097

DOCKET 71-0051 HARRISON STEEL CASTINGS CO

8408080447 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
WILLIAMSON,G Harrison Steel Cast lp 25977 150

DOCKET 71-0055 H R INSPECTION SERVICE

8408080225 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
H R Inspection Service 1p 25978 323

DOCKET 71-0056 PHILADELPHIA ELECTRIC CO

8408060433 Informs that QA program approval for radioactive packages expired on 840630 Request for renewal & fee required for continuation of QA program
MACDONALD,C E Transportation Certification Branch 84/07/30
COONEY,J J Philadelphia Electric Co 1p 25937 324

DOCKET 71-0057 EXXON CO , USA

8408090081 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SWARTZ,J H Exxon Corp 1p 25979 143

DOCKET 71-0059 GENERAL ELECTRIC CO

8408080418 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
LABRANCHE,F R General Electric Co 1p 25977 337

DOCKET 71-0061 NAVY, DEPT OF

8408080411 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
Navy,Dept of, Naval Weapons Station Concord,CA, 1p 25978 074

DOCKET 71-0063 OZARK AIRLINES, INC

8408080135 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
YOUNG,R E Ozark Airlines 1p 25979 109

DOCKET 71-0066 CERTIFIED TESTING LABS , INC

8408080143 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
PULMSTEAD,P F Certified Testing Laboratories, Inc 1p 25979 082

8408310354 Forwards QA program approval for radioactive matl package 0066,Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
PLUMSTEAD,R F Certified Testing Laboratories, Inc 1p 26350 323

--8408310358 QA program approval for radioactive matl package 0066,Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
1p 26350 324

DOCKET 71-0068 YANKEE ATOMIC ELECTRIC CO

8408070056 Informs that QA program approval for radioactive packages expires on 840731 Request for renewal & fee should be submitted to provide for continuation of QA program
MACDONALD,C E Transportation Certification Branch 84/07/30
HEIDER,L H Yankee Atomic Electric Co 1p 25955 332

DOCKET 71-0070 GAMMA FIELD RADIOGRAPHIC FACILITY

8408080132 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
ABRAMS,C J Gamma Field Radiographic Facility 1p 25979 110

8408310443 Forwards QA program approval for radioactive matl package 0070,Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
ABRAMS,C J Gamma Field Radiographic Facility 1p 26350 133

--8408310457 QA program approval for radioactive matl package 0070, Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
1p 26350 134

DOCKET 71-0074 NUCLEAR WELDING, INC

8408080065 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
HANES,T S NWI International (Nuclear Welding,Inc) 1p 25981 085

DOCKET 71-0075 NORFOLK SHIPBUILDING & DRY DOCK CO

8408080079 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
EURE,C H Norfolk Shipbuilding & Drydock Corp 1p 25981 098

DOCKET 71-0077 MIDSTATE TESTING LABORATORY

8408080078 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
KEILMAN,T J Midstate Testing Laboratory, Inc 1p 25981 096

DOCKET 71-0080 TRANSWORLD AIRLINES, INC

8408080056 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
BOENEN,E A Trans World Airlines, Inc 1p 25981 072

DOCKET 71-0081 ITT GRINNELL INDUSTRIAL PIPING, INC

8408080210 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
HARRIS,D C ITT Grinnell (subs of ITT) 1p 25978 328

DOCKET 71-0083 NORTHERN STATES POWER CO

8408130020 Requests addl 5-yr extension of QA program approval for radioactive matl packages QA requirements of 10CFR71 will be satisfied through NRC approved program Forwards Rev 9 to "Operational QA Plan " Fee encl
MUSOLF,D Northern States Power Co 84/06/28 MACDONALD,C E
Transportation Certification Branch 2pp 26011 128

--8408130021 Rev 9 to "Operational QA Plan "
Northern States Power Co 84/04/12 93pp 26011 130

--8408130024 Forwards fee for 840628 request for renewal of radioactive matl transport package QA program,per 840718 request
MUSOLF,D Northern States Power Co 84/07/24 CABELL,A S
License Fee Management Branch 1p 26011 223

--8408130027 Requests remittance for 840628 request for renewal of radioactive matl transport package QA program,per 10CFR170 W/o stated encl
CABELL,A S License Fee Management Branch 84/07/18 MUSOLF,D Northern States Power Co 1p 26011 224

DOCKET 71-0087 NAVY, DEPT OF

8408080281 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
Navy, Dept of 1p 25978 306

DOCKET 71-0089 NAVY, DEPT OF

8408080185 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
Navy, Dept of 1p 25978 340

DOCKET 71-0093 HUNTINGTON TESTING

8408080063 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
YEOMAN,W Huntington Testing 1p 25981 084

DOCKET 71-0095 UNITED STATES TESTING CO , INC

8408080079 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
YODER,C B United States Testing Co , Inc 1p 25979 145

DOCKET 71-0099 FOSTER WHEELER ENERGY CORP

8408080469 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
KOVACS,B Foster Wheeler Corp 1p 25976 065

DOCKET 71-0100 VENEGAS IND TEST LABS , INC

8408080325 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
VENEGUS,M Venegas Industrial Testing Laboratories,Inc 1p 25978 199

DOCKET 71-0103 TWIN CITY TESTING & ENGR LAB

8408080328 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SCHULZE,H T Twin City Testing & Engineering Laboratory, Inc 1p 25978 200

DOCKET 71-0104 CHICAGO BRIDGE & IRON CO

8408080145 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
WEHRLE,R R Chicago Bridge & Iron Co 1p 25979 055

DOCKET 71-0105 UNIVERSAL TESTING LABORATORIES

8408080163 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
JOHNSON,W R Universal Technical Testing Laboratories,Inc 1p 25978 362

DOCKET 71-0110 BUCKEYE STEEL CASTINGS

8408080313 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
KRANER,J F Buckeye Steel Castings (subs of Buckeye International) 1p 25978 226

DOCKET 71-0111 MATERIAL TESTING LAB OF VIRGINIA, INC

8408310421 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
STEELE,W F Material Testing Laboratory of Virginia, Inc 1p 26350 214

DOCKET 71-0113 NOOTER CORP

8408080156 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
FRAZIER,D L Nooter Corp 1p 25979 009

DOCKET 71-0119 INGERSOLL-RAND CO

8408080107 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
MORGANELL,M M Ingersoll-Rand Co 1p 25979 130

DOCKET 71-0120 DANIEL INTERNATIONAL CORP

8408080122 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
PREWITT,R N Daniel International (subs of Fluor Corp) 1p 25979 118

DOCKET 71-0123 HERRON TESTING LABS , INC

8408080287 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
THIERET,H T Herron Testing Laboratories,Inc 1p 25978 304

DOCKET 71-0124 HOUSTON INSPECTION LABS , INC

8408310418 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
BALLARD,B R Houston Inspection Laboratories,Inc 1p 26350 217

DOCKETED ITEMS

DOCKET 71-0125 TESTCO, INC

8408080125 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
FOUSHEE,J R Testco,Inc 1p 25979 117

DOCKET 71-0127 NATIONAL ANNEALING BOX CO

8408080045 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
FRANTZ,J R National Annealing Box Co 1p 25981 066

DOCKET 71-0128 AMOCO OIL CO

8408080017 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
KLIEBER,E P American Oil Co (subs of Standard Oil Co of Indiana) 1p 25981 036

DOCKET 71-0130 CHICAGO BRIDGE & IRON CO

8408080015 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
STULL,D J Chicago Bridge & Iron Co 1p 25981 035

DOCKET 71-0132 ADVANCED RADIATION SERVICE

8408080112 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
KURTZ,A S Advanced Radiation Service, Inc 1p 25979 121

DOCKET 71-0133 NAVY, DEPT OF

8408080111 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
Navy, Dept of, Pearl Harbor Naval Shipyard 1p 25979 122

DOCKET 71-0134 LABARGE, INC

8408080117 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
DIGGERS,S LaBarge, Inc 1p 25979 120

DOCKET 71-0137 METALS TESTING CO , INC

8408080128 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
LEINS,J H Metals Testing Co , Inc 1p 25979 114

DOCKET 71-0140 WALWORTH CO

8408080092 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
NICHOLS,G Walworth Co (subs of IU International Corp) 1p 25979 139

DOCKET 71-0145 THAYER INSPECTION SERVICE, INC

8408080088 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
MOSS,J C Thayer Inspection Service, Inc 1p 25979 140

DOCKET 71-0148 UNITED ENGINEERS & CONSTRUCTORS, INC

8408080095 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
RABEHOLD,C F United Engineers & Constructors, Inc (subs of Raytheon Co) 1p 25979 136

DOCKET 71-0151 HESS OIL VIRGIN ISLANDS CORP

8408080069 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
COMBS,L D Hess Oil Virgin Islands Corp 1p 25981 087

DOCKET 71-0152 VIRGINIA, COMMONWEALTH OF

8408080293 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
VIA,W F Virginia, Commonwealth of, 1p 25978 302

DOCKET 71-0154 GENERAL DYNAMICS CORP

8408080291 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
ALGAR,L B General Dynamics Corp 1p 25978 303

DOCKET 71-0156 INDUSTRIAL FABRICATING CO

8408080058 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
BOZARTH,W Industrial Fabricating 1p 25981.079

DOCKET 71-0157 FROEHLING & ROBERTSON, INC

8408080101 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
BRODY,W R Froehling & Robertson, Inc 1p 25979 133

DOCKET 71-0158 X-RAY INDUSTRIES, INC

8408310289 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
SHIPLET,M J X-Ray Industries, Inc 1p 26350 285

DOCKET 71-0161 CURTISS-WRIGHT CORP

8408080154 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
JACKSON,C Curtiss - Wright Corp 1p 25979 010

DOCKET 71-0162 EBASCO SERVICES, INC

8408080406 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
BULLEN,H C Ebasco Services, Inc (subs of Enserch Corp) 1p 25978 075

DOCKET 71-0166 NEW YORK TESTING LABS, INC

8408080451 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
HARVEY,G J New York Testing Laboratories, Inc 1p 25977 148

DOCKET 71-0167 FINLAY TESTING LABORATORIES

8408310287 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
FINLAY,G W Finlay Testing Laboratories 1p 26350 294

DOCKET 71-0168 QUALITY ASSURANCE LABS

8408080462 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
TRAUTVETTER,C Quality Assurance Laboratories, Inc (formerly Jannetti Corp) 1p 25976 067

ICKET 71-0169 FLORIDA POWER & LIGHT CO

108070010 Informs of expiration of QA program approval for radioactive packages on 840831 Application fee & renewal request required 30 days prior to expiration
MACDONALD,C E Transportation Certification Branch 84/07/30
WETHY,C W Florida Power & Light Co 1p 25956 207

1408310455 Forwards QA program approval for radioactive matl package 0169,Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
WILLIAMS,J W Florida Power & Light Co 1p 26350 124

-8408310456 QA program approval for radioactive matl package 0169,Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
1p 26350 125

DOCKET 71-0171 INDUSTRIAL INSPECTION INDUSTRIES

8408080247 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
HOPKINS,S M Industrial Inspection Industries, Inc 1p 25978 311

DOCKET 71-0172 EMPIRE STEEL CASTINGS, INC

8408310293 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
GAUMER,G R Empire Steel Castings, Inc 1p 26350 293

DOCKET 71-0174 SOUTHERN CALIFORNIA EDISON CO

8408070064 Advises that request for renewal of QA program should be submitted 30 days prior to 840831 expiration date
MACDONALD,C E Transportation Certification Branch 84/07/30
BRIDENBECKER,R Southern California Edison Co 1p 25955 322

DOCKET 71-0175 QC SERVICES, INC

8408080465 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
FILL,K S QC Services, Inc 1p 25976 066

DOCKET 71-0181 CONSOLIDATED X-RAY SERVICE CORP

8408080274 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
CULLINGTON,R F Consolidated X-Ray Service Corp 1p 25978 308

DOCKET 71-0183 GAMMA SONICS EX LABS

8408080231 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SANDERS,H A Gamma Sonics Examination Laboratories,Inc 1p 25978 321

DOCKET 71-0184 PULLMAN POWER PRODUCTS

8408130278 Requests that previously Commission approved QA program, which satisfies applicable criteria of 10CFR50,App B,be accepted for continuous use
BAIR,A Pullman, Inc 84/07/10 Office of Nuclear Material Safety & Safeguards,Director 2pp 26040 338

--8408130283 Remits renewal fee for Rev 0 to QA program,per 840720 ltr
BAIR,A Pullman, Inc 84/07/26 JACKSON,G License Fee Management Branch 1p 26040 339

--8408130292 Requests remittance of fee for 840710 application for renewal of QA program Revised 10CFR170 encl W/o encl
JACKSON,G License Fee Management Branch 84/07/20 BAIR,A Pullman, Inc 1p 26040 340

DOCKET 71-0186 HIGH STEEL STRUCTURES, INC

8408310444 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
KRESS,C R High Steel Structures, Inc 1p 26350 132

DOCKET 71-0188 MAYNARD STEEL CASTING CO

8408080247 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
FAIST,C A Maynard Electric Steel 1p 25978 319

DOCKET 71-0195 TOLEDO EDISON CO

8408070151 Informs of expiration of QA program approval for radioactive packages on 840831 Application fee & renewal request required 30 days prior to expiration
MACDONALD,C E Transportation Certification Branch 84/07/30
MURRAY,T Toledo Edison Co lp 25957 119

DOCKET 71-0202 PACIFIC GAS & ELECTRIC CO

8408010036 Notifies of util intent to apply previously approved corporate QA program to transportation activities at Diablo Canyon,Unit 1
SCHUYLER,J O Pacific Gas & Electric Co 84/07/05 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 2pp 25873 341

DOCKET 71-0205 QUALITY TESTING, INC

8408080258 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
BECKER,C A Quality Testing, Inc lp 25978 314

DOCKET 71-0207 CONNECTICUT YANKEE ATOMIC POWER CO

8408060376 Informs that QA insp program for radioactive packages expires on 840831 To continue QA program to be applied to packaging & transportation activities,renewal request should be made at least 30 days prior to expiration date
MACDONALD,C E Transportation Certification Branch 84/07/30
GRAVES,R H Connecticut Yankee Atomic Power Co lp 25951 235

DOCKET 71-0208 NORTHEAST NUCLEAR ENERGY CO

8408080098 Informs of expiration of QA program approval for radioactive packages on 840831 Application fee & renewal request required within 30 days prior to expiration
MACDONALD,C E Transportation Certification Branch 84/07/30
CHEATHAM,A G Northeast Nuclear Energy Co (subs of Northeast Utilities) lp 25979 134

DOCKET 71-0211 BOSTON EDISON CO

8408070159 Informs that QA program approval for radioactive packages expired 840531 Renewal of QA program recommended in order to provide for continuation of program to be applied to packaging & transportation activities Fee required
MACDONALD,C E Transportation Certification Branch 84/07/30
MACHON,R Boston Edison Co lp 25957 117

DOCKET 71-0212 GENERAL ELECTRIC CO

8408080233 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
ENGEL,J D General Electric Co lp 25978 315

DOCKET 71-0213 INTERMOUNTAIN TESTING CO

8408080263 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
CHANDLER,J W Intermountain Technologies, Inc lp 25978 313

DOCKET 71-0214 GAS RENTALS, INC

8408080460 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
LUDWIG,T Gas Rentals lp 25976 068

DOCKET 71-0215 SPACE SCIENCE SERVICES, INC

8408080103 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
GEIGER,D A Space Science Services, Inc lp 25979 132

DOCKET 71-0216 NUCLEAR ENERGY SERVICES, INC

8408080452 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
GAMBLE,D C Nuclear Energy Services, Inc lp 25977 147

8408310449 Forwards QA program approval for radioactive matl package 0216,Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
SLACK,R J Nuclear Energy Services, Inc lp 26350 129

--8408310453 QA program approval for radioactive matl package 0216,Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/28
lp 26350 130

DOCKET 71-0217 PULLMAN, INC

8408080086 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
TURNER,J E Pullman, Inc lp 25979 141

DOCKET 71-0218 CUMBERLAND BRIDGE CO

8408080459 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
HARRIS,W I Cumberland Bridge Co lp 25976 069

DOCKET 71-0219 TEREX CORP

8408080470 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
HEINTZELMAN,K TEREX Corp lp 25976 063

DOCKET 71-0220 GENERAL DYNAMICS CORP

8408080468 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SURPRENANT,R H General Dynamics Corp lp 25976 064

DOCKET 71-0221 ALLIS-CHALMERS CORP

8408070500 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
NAYLOR,C A Allis-Chalmers Corp lp 25956 235

DOCKET 71-0222 ST LOUIS TESTING LABORATORIES, INC

8408070504 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
TROWBRIDGE,C D St Louis Testing Laboratories, Inc, lp 25956 237

DOCKET 71-0223 BENJAMIN F SHAW CO

8408080074 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SMEAL,L P Benjamin F Shaw Co (subs of Blount, Inc) 1p 25981 099

DOCKET 71-0224 GUYON POWER & PROCESS PIPING

8408070507 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
DURDHOFFER,J M Guyon Alloys, Inc 1p 25956 235

DOCKET 71-0225 NAVY, DEPT OF

8408070503 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
Navy, Dept of, Naval Research Laboratory 1p 25956 238

DOCKET 71-0229 WORD INDUSTRIES PIPE FABRICATING, INC

8408080446 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
ROBBINS,R W Word Industries Pipe Fabricating, Inc 1p 25977 151

DOCKET 71-0232 LAKEHEAD TESTING LAB , INC

8408080072 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
WIRTZ,G L Lakehead Testing Laboratory, Inc 1p 25981 100

DOCKET 71-0233 O'NEILL TANK CO , INC

8408080104 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
ADAMS,K O'Neill Tank Co , Inc 1p 25979 131

DOCKET 71-0234 X-RAY, INC

8408080089 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
CONNEL,L G X-Ray, Inc 1p 25979 142

DOCKET 71-0237 COLUMBIA GAS TRANSMISSION CORP

8408080378 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
WHITE,D C Columbia Gas Transmission Corp (subs of Columbia Gas Sys, Inc) 1p 25978 089

DOCKET 71-0240 POWER AUTHORITY OF STATE OF NEW YORK

8408150147 Forwards payment for renewal of QA program approval for radioactive matl packages
BAYNE,J P Power Authority of the State of New York 84/07/24
MACDONALD,C E Transportation Certification Branch 3pp
26104 195

8408200086 Forwards QA program approval for radioactive matl package 0240, Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/13
BAYNE J P Power Authority of the State of New York 1p
26142 335

--8409200090 QA program approval for radioactive matl package 0240, Rev 2
MACDONALD,C E Transportation Certification Branch 84/08/13
1p 26142 336

DOCKET 71-0242 LAW ENGINEERING TESTING CO

8408080381 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
ERWIN,R G Law Engineering Testing Co 1p 25978 087

DOCKET 71-0245 NAVY, DEPT OF

8408310415 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
Navy, Dept of 1p 26350 221

DOCKET 71-0247 IRT CORP

8408080424 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
CROSBIE,K L IRT Corp 1p 25977 191

DOCKET 71-0253 TWIN PORTS TESTING, INC

8408080379 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
MCKEEVER,R D Twin Ports Testing, Inc 1p 25978 088

DOCKET 71-0254 GENERAL ELECTRIC CO

8408310407 Advises that QA proram approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
VAUGHAN,C M General Electric Co 1p 26352 044

DOCKET 71-0256 OMAHA PUBLIC POWER DISTRICT

8408150136 Requests renewal for QA program approval for radioactive matl packages Fee encl
ANDREWS,R L Omaha Public Power District 84/07/13 MACDONALD,C E
Transportation Certification Branch 2pp 26104 247

DOCKET 71-0257 INDUSTRIAL LABS, INC

8408080475 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
WELLS,B R Industrial Laboratories, Inc 1p 25976 061

DOCKETED ITEMS

DOCKET 71-0261 NAVY, DEPT OF

8408310403 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
Navy, Dept of 1p 26350 277

DOCKET 71-0268 NAVY, DEPT OF

8408310393 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
Navy, Dept of 1p 26350 291

DOCKET 71-0269 LEHIGH TESTING LABORATORIES, INC

8408310399 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
RECCHIA,R Lehigh Testing Laboratories,Inc 1p 26350 278

DOCKET 71-0270 FACTORY MUTUAL ENGINEERING CORP

8408080310 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
RICHARDS,C A Factory Mutual Engineering Corp 1p 25978 227

DOCKET 71-0272 CRANE CO

8408080127 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
ESTERT,G W Crane Co 1p 25979 115

DOCKET 71-0274 NAVY, DEPT OF

8408310387 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
Navy, Dept of 1p 26350 274

DOCKET 71-0275 DUQUESNE LIGHT CO

8408060326 Informs that QA insp program for radioactive packages expires on 840831 To continue QA program to be applied to packaging & transportation activities,renewal request should be made at least 30 days prior to expiration date
MACDONALD,C E Transportation Certification Branch 84/07/30
KOSMAL,J A Duquesne Light Co 1p 25937 360

DOCKET 71-0276 NAVY, DEPT OF

8408310382 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
Navy, Dept of 1p 26350 273

DOCKET 71-0279 UNIVERSAL TESTING, INC

8408090038 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
MULLIKIN,M S United Timber Corp 1p 25991 292

DOCKET 71-0280 ABCO PERFORATORS, INC

8408310377 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
COOK,C L Abco Perforators, Inc 1p 26350 271

DOCKET 71-0281 DELTA AIRLINES, INC

8408090474 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
EDWARDS,A D Delta Air Lines, Inc 1p 25976 062

DOCKET 71-0282 WKM WELLHEAD SYSTEMS, INC

8408310369 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
CANNON,E WKM Wellhead Systems, Inc 1p 26350 353

DOCKET 71-0283 MCMANUS INSPECTION SERVICE

8408080060 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
MCMANUS,G McManus Inspection Service 1p 25981 062

DOCKET 71-0284 ULTRASONIC SPECIALISTS, INC

8408080234 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SOUTHERS,L Ultrasonic Specialists, Inc 1p 25978 320

DOCKET 71-0285 BELL GEOPHYSICS

8408310348 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
BELL,J A Bell Geophysics 1p 26350 348

DOCKET 71-0286 BPB INSTRUMENTS, INC

8408310364 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
GRACE,J G BPB Instruments, Inc. 1p 26350 359

DOCKET 71-0287 CARSON NON-DESTRUCTIVE TESTING

8408310357 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
MCVAUGH,R W Carson Non Destructive Testing 1p 26350 354

DOCKET 71-0288 NORTH DAKOTA, STATE OF

8408310352 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
BURKE,P A North Dakota, State of 1p 26350 349

DOCKET 71-0289 TERRADATA GEOPHYSICAL, INC

8408310356 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
MCBRIDE,G E Terradata Geophysical, Inc 1p 26350 279

DOCKET 71-0290 UNITED TESTING SERVICES, INC

8408310350 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
JUNEAU,V United Testing Services, Inc 1p 26350 307

DOCKET 71-0291 DJ INSPECTION SERVICES, INC

8408310346 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
JOHNSON,M DJ Inspection Services, Inc 1p 26350 308

DOCKET 71-0292 INDUSTRIAL GAMMA INSPECTION

8408080215 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SMITH,R Industrial Gamma Inspection 1p 25978 327

DOCKET 71-0293 BRAND X PERFORATORS, INC

8408310278 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
MEADOWS,W Brand X Perforators 1p 26350 272

DOCKET 71-0294 APPLIED ENGINEERING CO

8408080094 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
GOODWIN,J Applied Engineering Co 1p 25979 137

DOCKET 71-0295 ACUREX CORP

8408310283 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
FENTON,N J Acurex Corp 1p 26350 286

DOCKET 71-0296 IOWA ELECTRIC LIGHT & POWER CO

8408060374 Informs that QA insp program for radioactive packages expired on 840630 To continue QA program to be applied to packaging & transportation activities,renewal request should be made & fee paid 30 days prior to expiration
MACDONALD,C E Transportation Certification Branch 84/07/30
YOUNG,K Iowa Electric Light & Power Co 1p 25951 236

DOCKET 71-0297 E LEWIS COOK & ASSOCIATES

8408310300 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
[illegible]BEE,K W E Lewis Cook & Associates 1p 26350 299

DOCKET 71-0298 STEEL TANK CONSTRUCTION CO

8408080044 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
PADGETT,G Steel Tank Construction Co 1p 25981 065

DOCKET 71-0299 QUALITY CONTROL SERVICES

8408310371 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
SACHSE J QC Services, Inc 1p 26350 262

DOCKET 71-0300 INDEPENDENT TESTING LABORATORIES

8408080040 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SHAIN,W E Independent Testing Laboratories 1p 25981 064

DOCKET 71-0301 CTL ENGINEERING, INC

8408310366 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
CROWLEY,J L CTL Engineers, Inc 1p 26350 263

DOCKET 71-0302 ASSOCIATED PIPING & ENGINEERING CORP

8408080457 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
JONES,K C Associated Piping & Engineering Corp (subs of Johnson Controls, Inc) 1p 25976 070

DOCKET 71-0303 MEMPHIS TESTING SERVICES, INC

8408310391 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
REID,R E Memphis Testing Services, Inc 1p 26350 356

DOCKET 71-0304 TELEDYNE BROWN ENGINEERING CO

8408080080 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
MEYER,W A Teledyne Brown Engineering 1p 25979 144

DOCKET 71-0305 AMERICAN X-RAY & INSPECTION, INC

8408080057 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
GRASHAW,T D American X-Ray & Inspection 1p 25981 078

DOCKET 71-0306 SNYDER DRILLING & WELL SERV

8408080066 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
SNYDER,H L Snyder Drilling-Well Servicing 1p 25981 086

DOCKET 71-0307 TEXAS PIPE BENDING CO OF PUERTO RICO

8408080062 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD Transportation Certification Branch 84/08/01
WARREN,M C Texas Pipe Bending Co 1p 25981 083

DOCKET 71-0310 BUCYRUS-ERIE CO

8408080229 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
MERTZ,J M Bucyrus-Erie Co 1p 25978 322

DOCKET 71-0311 LOGWELL, INC

8408310388 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
BAILEY,F G Logwell 1p 26352 042

DOCKET 71-0312 METALFORMS, INC

8408310384 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
BENNETT,C Metalforms, Inc 1p 26352 045

DOCKET 71-0313 PRECISION INSPECTION, LTD

8408310380 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
SINK,J E Precision Inspection,Ltd 1p 26352 046

DOCKET 71-0314 SMITH-EMERY CO

8408080182 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
DUNHAM,M S Smith-Emery Co 1p 25978 341

DOCKET 71-0317 HUDSON PRODUCTS CORP

8408310375 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
BENEFIELD,W E Hudson Products Corp 1p 26352 047

DOCKET 71-0318 MARATHON OIL CO

8408310372 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
BARRE,C H Marathon Oil Co 1p 26352 043

DOCKET 71-0319 GENERAL TESTING & INSPECTION CO

8408080169 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
KRUEGEL,R E General Test & Inspection 1p 25978 352

DOCKET 71-0320 PITTSBURGH-DES MOINES STEEL CO

8408080450 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
STIGER,M H Pittsburgh-Des Moines Corp 1p 25977 149

DOCKET 71-0322 BABCOCK & WILCOX CO

8408080097 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
LAWRENCE,M Babcock & Wilcox Co 1p 25979 135

DOCKET 71-0325 CONSUMERS POWER CO

8408060327 Informs that QA insp program for radioactive packages expires on 840831 To continue QA program to be applied to packaging & transportation activities,renewal request should be made at least 30 days prior to expiration date
MACDONALD,C E Transportation Certification Branch 84/07/30
NEAL,T P Consumers Power Co 1p 25937 359

DOCKET 71-0326 INDUSTRIAL NDT SER DIVISION

8408080093 Advises that QA program approval for radioactive packages expires on 840930 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/01
THOMPSON,J M Industrial NDT Co 1p 25979 138

DOCKET 71-0327 PORTLAND GENERAL ELECTRIC CO

8408060328 Informs that QA insp program for radioactive packages expires on 840831 To continue QA program to be applied to packaging & transportation activities,renewal request should be made at least 30 days prior to expiration date
MACDONALD,C E Transportation Certification Branch 84/07/30
NEAL,T P Portland General Electric Co 1p 25937 358

DOCKET 71-0328 PUBLIC SERVICE ELECTRIC & GAS CO

8408060370 Informs that QA insp program for radioactive packages expires on 840831 To continue QA program to be applied to packaging & transportation activities,renewal request should be made at least 30 days prior to expiration date
MACDONALD,C E Transportation Certification Branch 84/07/30
MIDURA,H J Public Service Electric & Gas Co of New Jersey 1p 25951 237

DOCKET 71-0329 HOWMET TURBINE COMPONENTS CORP

8408310297 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
BRANDBETTER,C Howmet Turbine Components Corp (subs Pechiney Ugine Kuhlmann Corp) 1p 26350 292

DOCKET 71-0330 ALLIED INSPECTION SERVICES, INC

8408310360 Advises that QA program approval for radioactive packages expires on 841030 Renewal must be requested within 30 days of expiration If renewal not desired,NRC should be so notified
MACDONALD,C E Transportation Certification Branch 84/08/28
GRASHAW,T D Allied Inspection Services, Inc 1p 26350 280

DOCKET 71-0522 CALIFORNIA, UNIV OF, LOS ANGELES, CA

8408150141 Forwards hardcopy of "QA Program for Shipment of Irradiated Fuel," confirming facsimile transmission on 840702
WEGST,W F California, Univ of, Los Angeles, CA 84/07/10
MACDONALD,C E Transportation Certification Branch 1p 26104 198

--8408150143 "QA Program for Shipment of Unirradiated Fuel "
* California, Univ of, Los Angeles, CA 84/07/10 3pp
26104 199

DOCKET 71-5805 MODEL CNS 3-55, CHEM-NUCLEAR SYSTEMS, INC

8408280324 Notification of registration as user of Model CNS 3-55,in response to 840731 request
MACDONALD,C E Transportation Certification Branch 84/08/21
VOGEL,A M Baltimore Gas & Electric Co 1p 26294 052

DOCKET 71-5926 MODEL GE-100, GENERAL ELECTRIC CO

8408160290 Requests registration as user of Model GE-1000
MILLER,R I Sacramento Municipal Utility District 84/08/02
MACDONALD,C E Transportation Certification Branch 1p 26124 346

8408240202 Notification of registration as user of Model GE-100,in response to 840802 request
MACDONALD,C E Transportation Certification Branch 84/08/20
MILLER,R I Sacramento Municipal Utility District 1p 26255 251

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

8408170021 Forwards response to request for addl info & updated safety analysis in support of renewal of Certificate of Compliance 6244,Model 4-85
POPPE,L K Chem-Nuclear Systems, Inc 84/08/03 MACDONALD,C E
Transportation Certification Branch 10pp 26134 198

--8408170023 Revised "SAR for Chem-Nuclear Sys,Inc Model 6244 (Model CNS 4-85) "
* Chem-Nuclear Systems, Inc 84/07/31 11pp 26134 208

DOCKET 71-6346 MODEL FSV-1, GA TECHNOLOGIES, INC

8408150109 Forwards response to NRC 840619 request for addl info re structural analysis of lead shielded canister within cask Failure at top flange region in skirt joining flange to canister body would not adversely affect canister shielding
MOWRY,W R GA Technologies, Inc /General Atomic Co 84/07/27
MACDONALD,C E Transportation Certification Branch 15pp 26104,282

--8408150114 Speech entitled, "Selection of Analytic Solutions & Experimental Results for Verification of Large Deformation Inelastic Dynamic Computer Programs," presented at Sept 1983 meeting in Peoples Republic of China
KEY,S W Re/Spec, Inc 83/09/31 21pp 26104 297

8408150542 Requests registration as user of Model FSV-1
GARRISON,R F Energy, Dept of 84/07/30 MACDONALD,C E
Transportation Certification Branch 1p 26080 302

8408310073 Notification of registration as user of Model FSV-1 in response to 840730 request
MACDONALD,C E Transportation Certification Branch 84/08/22
GARRISON,R F Energy, Dept of 1p 26350 185

DOCKET 71-6591 MODEL 51032-1 & 1A, EXXON NUCLEAR CO , INC

8408310170 Advises that Model 51032-1 & 1a packages meet requirements of 1973 IAEA for AF package,per 831130 request,Exxon Nuclear Co,Inc 830930 application & NRC 840529 approval
MACDONALD,C E Transportation Certification Branch 84/08/24
RAWL,R R Transportation, Dept of 1p 26351 350

DOCKET 71-6717 MODEL 6717-B, GAMMA INDUSTRIES

8408150122 Requests registration as user of Models 6717-B & 20,20A,50 & 50A
SAMMONS,R J Dayton X-Ray Co 84/07/20 Division of Fuel Cycle & Material Safety 1p 26104 256

8408150607 Requests registration as user of Models 6717-B,20,20A,50 & 50A
SAMMONS,R J Dayton X-Ray Co 84/07/20 Office of Nuclear Material Safety & Safeguards,Director 2pp 26098 362

8408310376 Notification of registration as user of Models 6717-B,20, 20A,50 & 50A,in response to 840720 request
MACDONALD,C E Transportation Certification Branch 84/08/22
SAMMONS,R J Dayton X-Ray Co 1p 26350 264

DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO

8408060420 Summary of 840726 meeting w/GE in Silver Spring,MD re renewal of Certificate of Compliance 9001 for Model IF-300 Agenda encl
ODEGAARDEN,R H Transportation Certification Branch 84/07/27
Transportation Certification Branch 3pp 25937 341

DOCKET 71-9016 MODEL TN-9, NO USERS

8408140469 Forwards Rev 0 to "TN-8 & TN-9 SAR,First Addendum for TN-9 Packaging "
GOLDMANN,K Transnuclear, Inc 84/06/26 MACDONALD,C E
Transportation Certification Branch 2pp 26061 297

--8408140476 Forwards fee for 840626 request for amend to Certificate of Compliance 9016
GOLDMANN,K Transnuclear, Inc 84/07/27 JACKSON,G License Fee Management Branch 1p 26061 300

--8408140480 Requests amend fee for review of 840626 application to amend Certificate of Compliance 9016
JACKSON,G License Fee Management Branch 84/07/16 GOLDMANN,K
Transnuclear, Inc 1p 26061 301

--8408140485 Rev 0 to "TN-8 & TN-9,First Addendum for TN-9 Packaging "
* Transnuclear, Inc 84/06/26 12pp 26061 302

8408150647 Forwards second addendum to TN-8 & TN-9 SAR Requests issuance of revised certificate of compliance for Model TN-9 packaging
GOLDMANN,K Transnuclear, Inc 84/07/30 MACDONALD,C E
Transportation Certification Branch 2pp 26098 344

--8408150654 Rev 0 to "TN-8 & TN-9 SAR,Second Addendum for TN-9 Packaging "
* Transnuclear, Inc 84/07/30 12pp 26098 347

8408150594 Forwards "TN-8 & TN-9 SAR,Third Addendum for TN-9 Packaging "
GOLDMANN,K Transnuclear, Inc 84/07/31 MACDONALD,C E
Transportation Certification Branch 2pp 26105 330

--8408150600 "TN-8 & TN-9 SAR,Third Addendum for TN-9 Packaging "
* Transnuclear, Inc 84/07/31 16pp 26105 333

8408310169 Advises that Certificate of Compliance 9016 amended to authorize shipment of 18 Comm Ed Dresden Unit 1 thoria spent fuel rods in modified D-1 canister placed inside Model TN-9 Approval record encl
MACDONALD,C E Transportation Certification Branch 84/08/27
GOLDMANN,K Transnuclear, Inc 2pp 26351 351

DOCKET 71-9021 MODEL 750, TECHNICAL OPERATIONS, INC

8408020201 Application for renewal of Certificate of Compliance 9021 for Model 750 Type B package Fee encl
MUNRO,J J Tech/Ops 84/07/09 MACDONALD,C E Transportation Certification Branch 2pp 25898 185

DOCKET 71-9073 MODEL OH-142 SERIES & NUS 10-135, NUCLEAR PACKAGING,

8408150598 Requests registration as user of Model OH-142
SMEDIRA,C Neutron Products, Inc 84/07/31 MACDONALD,C E
Transportation Certification Branch 2pp 26080 359

8408150733 Application for amend to Certificate of Compliance 9073, adding design for Type B radwaste shipping cask Revs to Procedures WM-013,WM-022,WM-021,WM-023 & two oversize drawings encl Aperture cards available in PDR Fee encl
VOIT,R E NUS Corp 84/07/31 MACDONALD,C E Transportation Certification Branch 3pp 26103 244

--8408150736 Rev E to Procedure WM-013, "Gamma Scanning of Lead Shielding for NUS Type Casks "
MCCAY,S D NUS Corp 84/04/19 7pp 26103 247

--8408150739 Rev A to Procedure WM-022, "NUS 10-135 Type B Maint "
REAGAN,E E NUS Corp 84/07/31 13pp 26103 254

--8408150742 Rev A to Procedure WM-021, "Operational Instructions for Loading & Unloading NUS 10-135 Type B Cask "
REAGAN,E E NUS Corp 84/07/31 20pp 26103 267

--8408150744 Rev A to Procedure WM-023, "NUS PSC Halogen Leak Test Procedure for NUS 10-135 Type B Cask "
REAGAN,E E NUS Corp 84/07/31 11pp 26103 287

8408240325 Notification of registration as user of Models OH-142, OH-142 MKI,OH-142 MKIB,OH-142 MKII in response to 840731 request
MACDONALD,C E Transportation Certification Branch 84/08/20
TURKANIS,M Neutron Products, Inc 1p 26253 339

8408270580 Notification of registration as user of Models OH-142 & OH-142 MKI,MKIB & MKII, in response to 840808 request
MACDONALD,C E Transportation Certification Branch 84/08/21
WITHERS,B D Portland General Electric Co 1p 26258 360

DOCKET 71-9092 MODEL HN-300, HITTMAN NUCLEAR & DEVELOPMENT CORP

8408020258 Withdraws 830930 application for renewal of Certificates of Compliance 9092,Rev 1 & 9093,Rev 1,due to type & activity of matls to be shipped in casks
LEDUC,R J Hittman Nuclear & Development Corp (subs of Hittman Corp) 84/07/06 MACDONALD,C Transportation Certification Branch 2pp 25898 110

DOCKET 71-9093 MODEL HN-400, HITTMAN NUCLEAR & DEVELOPMENT CORP

8408020258 Withdraws 830933 application for renewal of Certificates of Compliance 9092,Rev 1 & 9093,Rev 1,due to type & activity of matls to be shipped in casks
LEDUC,R J Hittman Nuclear & Development Corp (subs of Hittman Corp) 84/07/06 MACDONALD,C Transportation Certification Branch 2pp 25898 110

DOCKET 71-9111 MODEL CNS 6-80-2 & CNS 6-80-2A, CHEM-NUCLEAR SYS, INC

8408150602 Requests registration as user of Models CNS 6-80-2 & CNS 6-80-2A
FLEISCHMANN,R Philadelphia Electric Co 84/07/27 MACDONALD,C E
Transportation Certification Branch 2pp 26080 361

8408240323 Notification of registration as user of Model CNS 6-80-2A in response to 840727 request
MACDONALD,C E Transportation Certification Branch 84/08/20
KNAPP,W J Philadelphia Electric Co 1p 26253 347

DOCKET 71-9126 MODEL 20, 20A, 50, 50A, GAMMA INDUSTRIES

8408150122 Requests registration as user of Models 6717-B & 20,20A,50 & 50A
SAMMONS,R J Dayton X-Ray Co 84/07/20 Division of Fuel Cycle & Material Safety 1p 26104 256

8408150607 Requests registration as user of Models 6717-B,20,20A,50 & 50A
SAMMONS,R J Dayton X-Ray Co 84/07/20 Office of Nuclear Material Safety & Safeguards,Director 2pp 26098 362

8408310376 Notification of registration as user of Models 6717-B,20, 20A,50 & 50A,in response to 840720 request
MACDONALD,C E Transportation Certification Branch 84/08/22
SAMMONS,R J Dayton X-Ray Co 1p 26350 264

DOCKET 71-9143 MODEL 920, TECHNICAL OPERATIONS, INC

8408310078 Notification of registration as user of Models 850 & 920 in response to 840724 request
MACDONALD,C E Transportation Certification Branch 84/08/22
BRITSII,D Atlas Foundry & Machine Co 1p 26350 184

DOCKET 71-9147 MODEL 850, TECHNICAL OPERATIONS, INC

8408150592 Requests registration as user of Model 850
MEHRER,R Atlas Foundry & Machine Co 84/07/24 MACDONALD,C E
Transportation Certification Branch 2pp 26080 355

8408310078 Notification of registration as user of Models 850 & 920 in response to 840724 request
MACDONALD,C E Transportation Certification Branch 84/08/22
BRITSII,D Atlas Foundry & Machine Co 1p 26350 184

DOCKET 71-9151 MODEL HN-100 SERIES 3, CNS 14-170 SERIES III & NUS

8408160525 Requests registration as user of Model CNS 14-170
DIXON,O W South Carolina Electric & Gas Co 84/07/31
MACDONALD,C E Transportation Certification Branch 1p 26122 353

8408270490 Notification of registration as user of Model CNS 14-170 III in response to 840731 request
MACDONALD,C E Transportation Certification Branch 84/08/20
NICHOLS,T C South Carolina Electric & Gas Co 1p 26277 062

DOCKET 71-9163 MODEL GNG-20, GULF NUCLEAR, INC

8408010025 Forwards Page 1 of Rev 2 to Type B GNG-20 container certification Requests amend so transportation of other model number sources can be made
BEVILL,M Gulf Nuclear, Inc 84/05/07 MACDONALD,C E
Transportation Certification Branch 3pp 25866 355

--8408010028 Advises that,unless fee for 840521 application for amend to Certificate of Compliance 9163 received within 30 days,NRC will consider application abandoned
JACKSON,G License Fee Management Branch 84/07/12 BEVILL,M
Gulf Nuclear, Inc 1p 25866 359

--8408010031 Advises that minor amend fee required re 840507 application for amend to Certificate of Compliance 9163
JACKSON,G License Fee Management Branch 84/05/21 BEVILL,M
Gulf Nuclear, Inc 1p 25866 360

DOCKET 71-9184 MODEL PAS-1, NUCLEAR PACKAGING, INC

8408270570 Notification of registration as user of Model PAS-1 in response to 840709 request
MACDONALD,C E Transportation Certification Branch 84/08/21
YOUNG,K Iowa Electric Light & Power Co 1p 26277 243

DOCKET 71-9186 MODEL S-6213, ENERGY, DEPT OF

8408060269 Forwards request for addl info re 840113 application,as supplemented 840305;requesting approval of Model UX-30
Revised affidavit for withholding should be submitted
Response within 30 days of date of ltr requested
MACDONALD,C E Transportation Certification Branch 84/07/26
TEMUS,C J Nuclear Packaging, Inc 3pp 25950 299

DOCKET 71-9188 MODEL AP-300, ANEFCO, INC

8408030072 Returns unreviewed 840309 application requesting approval of Model AP-300 Application incomplete & no response to NMSS 840321 ltr received
MACDONALD,C E Transportation Certification Branch 84/07/25
MURPHY,J D Anefco, Inc 1p 25917 345

DOCKET 71-9192 MODEL AP-300, ANEFCO, INC

8408170070 Forwards response to questions re Model AP-300,Type A package & revised pages to SAR Comments requested
MURPHY,J D Anefco, Inc 84/07/31 MCDONALD,C NRC - No Detailed Affiliation Given 73pp 26135 251

8408170204 Forwards revised pages to SAR for Model AP-300,Type A package,inadvertently omitted from 840731 response
MURPHY,S Anefco, Inc 84/08/03 MCDONALD,C NRC - No Detailed Affiliation Given 7pp 26134 319

DOCKET 71-9193 MODEL NES-5, NUCLEAR ENERGY SERVICES, INC

8408070020 Forwards request for addl info re 840618 application for approval of Model NES-5 Submittal date requested within 30 days
MACDONALD,C E Transportation Certification Branch 84/07/27
MAY,J R Nuclear Energy Services, Inc 4pp 25956 197

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO

8408130033 Responds to 840711 request for clarification of items identified during review of new rev to consolidated SAR, NEDO-21326 D Revised pages encl
HERRINGTON,C C General Electric Co 84/07/24 CUNNINGHAM,R E Division of Fuel Cycle & Material Safety 15pp 26058 330

8408130590 Summary of 840726 meeting w/GE in Silver Spring,MD re GE response to r[illegible]nts on update of consolidated SAR for Morris Opera[illegible]n
ROBERTS,J P Advanced Fuel & Spent Fuel Licensing Branch 84/08/07
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 1p
26038 313

8408160461 Dockets Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan," u/WC Wheadon & DM Dawson 830329 & 0210 ltrs,respectively,to assure docket file complete due to rev & resubmittal of rept as Rev 8
ROBERTS,J P Advanced Fuel & Spent Fuel Licensing Branch 84/08/10
Advanced Fuel & Spent Fuel Licensing Branch 1p 26126 078

--8408160466 Forwards Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan " Rev due to organizational change within spent fuel svcs operation & GE U Mgt Corp
WHEADON,W C General Electric Co 83/03/29 ROBERTS,J P NRC - No Detailed Affiliation Given 1p 26126 079

--8408160472 Forwards Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan," referenced in License SNM-2900 for GE Morris Operation & incorporated in NEDO-21326,App B-8
DAWSON,D M General Electric Co 83/02/10 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 1p 26126 080

8408310268 PNO-III-84-067 first of several spent reactor fuel shipments from Cooper Station arrived safely Rail shipment consisted of three NRC-certified shipping casks,each containing 18 spent fuel assemblies
LOVENDALE,P , PAPERIELLO,C J Region 3, Office of Director
84/08/24 1p 26333 329

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO

8408240009 Summary of 840810 meeting w/util,Bechtel & SAI in Silver Spring,MD re dry cask spent fuel storage application Meeting agenda & attendees list encl
ROBERTS,J P Advanced Fuel & Spent Fuel Licensing Branch 84/08/20
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 4pp
26252 355 24X Fiche 50-280,84/08/20,8408240009

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

8408010133 Staff requirements memo re 840516 Commission vote determining that 10CFR50 57(c) should not be read to make GDC 17 inapplicable to low power operation
CHILK,S J Office of the Secretary of the Commission MB40516B
84/05/18 Office of the Secretary of the Commission 1p
25873 312 24X Fiche 50-322,84/05/18,8408010133

8408060417 Staff requirements memo re 840726 affirmation session in Washington,DC on review of ALAB-729
CHILK,S J Office of the Secretary of the Commission MB40726C
84/07/27 PLAINE,H H Office of the General Counsel 1p
25950 360

8408060430 Transcript of Commission 840725 meeting in Washington,DC re discussion of Commission practice on granting exemptions in light of Decision CL-84-8 Pp 1-100
* Commissioners CL-84-08 84/07/25 103pp 25951 020

8408060434 Staff requirements memo re 840725 meeting on interpretation of Decision CLI-84-8 & reexam of exemption process
CHILK,S J Office of the Secretary of the Commission MB40723A
84/07/26 DIRCKS,W J Office of the Executive Director for Operations 2pp 25937 322 24X Fiche 50-322,84/07/26,8408060434

8408060437 Revised staff requirements memo re 840725 discussion on interpretation of Decision CLI-84-8 & reexam of exemption process
CHILK,S J Office of the Secretary of the Commission MB40725A
84/07/27 DIRCKS,W J Office of the Executive Director for Operations PLAINE,H H Office of the Executive Legal Director
1p 25937 316 24X Fiche 50-322,84/07/27,8408060437

8408060446 Staff requirements memo re 840726 discussion in Washington,DC requesting rept on role of NRC in contested licensing proceedings & status of effort to resolve ex parte & separation of function regulations
CHILK,S J Office of the Secretary of the Commission MB40726A
84/07/26 DIRCKS,W J Office of the Executive Director for Operations PLAINE,H H Office of the Executive Legal Director
TOURTELLOTTE,J Regulatory Reform Task Force 1p 25937 314

8408080024 Staff requirements memo re 840731 meeting in Washington,DC on industry views on terms important to safety & safety-related
CHILK,S J Office of the Secretary of the Commission MB40731C
84/08/01 Office of the Secretary of the Commission 1p
25981 037

8408080216 Staff requirements memo re 840731 discussion/possible vote on full power OL in Washington,DC Commission voted 4-0 to authorize staff to issue full power OL amend
CHILK,S J Office of the Secretary of the Commission MB40731D
84/08/01 DIRCKS,W J Office of the Executive Director for Operations 1p 25978 326 24X Fiche 50-416,84/08/01,8408080216

8408100150 Transcript of 840726 Commission public meeting in Washington,DC re discussion of role of staff/ex parte
Supporting documentation encl
* Commissioners 84/07/26 100pp 25996 348

8408130004 Transcript of Commission 840726 affirmation/discussion & vote in Washington,DC re SECY-84-232 & ALAB-729 on TMI hardware Pp 1-4
* Commissioners ALAB-729 84/07/26 7pp 26011 354

8408130013 Transcript of 840731 open meeting in Washington,DC re discussion & vote on full power OL Pp 1-114 Supporting documentation encl
* Commissioners 84/07/31 129pp 26059 102 24X
Fiche 50-416,84/07/31,8408130013

8408200407 Transcript of 840803 Commission meeting in Washington,DC re discussion/possible vote on order concerning earthquakes & emergency planning Pp 1-8
* Commissioners 84/08/03 12pp 26141 178 24X
Fiche 50-275,84/08/03,8408200407

8408200502 Transcript of 840731 Commission meeting in Washington,DC re industry views on "important to safety" & "safety-related" Pp 1-74 Industry presentations & viewgraphs encl
* Commissioners 84/07/31 106pp 26144 210

8408220338 Transcript of 840802 open meeting in Washington,DC re discussion/possible vote on full power OL Pp 1-195
Supporting documentation encl
* Commissioners 84/08/02 222pp 26211 083 24X
Fiche 50-275,84/08/02,8408220338

8408240113 Transcript of 840816 Commission meeting in Washington,DC re discussion/possible vote on final rulemaking on financial qualifications Pp 1-45
* Commissioners 84/08/16 47pp 26255 276

8408240424 Staff requirements memo re affirmation/discussion & vote denying 2 206 relief (SECY-84-203),approving order responding to petitions for review of ALAB-763 (SECY-84-254) & approving order denying LILCO 840719 motion (SECY-84-296)
CHILK,S J Office of the Secretary of the Commission MB40817C
84/08/20 Office of the Secretary of the Commission 3pp
26248 269 24X Fiche 50-000,84/08/20,8408240424

8408280020 Transcript of 840816 Commission meeting in Washington,DC re affirmation/discussion & vote Pp 1-7
* Commissioners 84/08/16 10pp 26294 013 24X
Fiche 50-000,84/08/16,8408280020

8408280025 Transcript of 840816 Commission meeting in Washington,DC re continuation of 840723 discussion of adjudicatory proceeding Pp 1-76
* Commissioners 84/08/16 78pp 26293 169 24X
Fiche 50-003,84/08/16,8408280025

8408280333 Staff requirements memo re 840816 continuation of 840723 discussion of issues requiring resolution prior to issuance of order in proceeding Commission requested briefing on PRA including discussion of uncertainties & basis of comparison
CHILK,S J Office of the Secretary of the Commission 84/08/21
DIRCKS,W J Office of the Executive Director for Operations
ZERBE,J E Office of Policy Evaluations 2pp 26294 050 24X
Fiche 50-003,84/08/21,8408280333

8408300043 Staff requirements memo re 840816 discussion/possible vote on financial qualification rule Ofc of General Counsel should circulate final version prior to signature by secretary Expedition of decommissioning rule requested
CHILK,S J Office of the Secretary of the Commission MB40816A
84/08/22 PLAINE,H H Office of the General Counsel DIRCKS,W J
Office of the Executive Director for Operations 1p 26331 345

8408310423 Staff requirements memo summarizing 840815 oral presentations by parties re restart Commission requested Aamodt provide names of individuals appropriate to carry out epidemiological study
CHILK,S J Office of the Secretary of the Commission MB40815
84/08/27 DIRCKS,W J Office of the Executive Director for Operations 2pp 26363 047 24X Fiche 50-289,84/08/27,8408310423

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

8408010009 Summary of ACRS Maint Practices & Procedures Subcommittee 840508 meeting in Washington,,DC re NRC maint plan & R Borkowski presentation on in-plant reliability data program
* ACRS - Advisory Committee on Reactor Safeguards 84/07/11
ACRS - Advisory Committee on Reactor Safeguards 12pp 25897 122

8408010011 Summary of ACRS Reactor Operations Subcommittee 840503 meeting in Washington, DC re review of AEOD trends & patterns program plan
* ACRS - Advisory Committee on Reactor Safeguards 84/06/18
ACRS - Advisory Committee on Reactor Safeguards 11pp 25871 350

8408010015 Summary of ACRS Class-9 Accidents Subcommittee 840427 meeting in Washington, DC re draft NUREG-1070, "NRC Policy on Future Reactor Design Decisions on Severe Accident Issues in Nuclear Power Plant Design "
* ACRS - Advisory Committee on Reactor Safeguards 84/07/02
ACRS - Advisory Committee on Reactor Safeguards 17pp 25897 104

8408010017 Summary of ACRS Advanced Reactors Subcommittee 840612 meeting in Washington, DC re review of NRC/RES activities concerning LMFBR & advanced reactors research
* ACRS - Advisory Committee on Reactor Safeguards 84/06/18
ACRS - Advisory Committee on Reactor Safeguards 13pp 25897 085

8408010033 Summary of ACRS Electrical Sys Subcommittee 840601 meeting in Washington, DC re NRC programs in areas of electrical instrumentation & control for ACRS rept to Commission on FY86-87 budget
* ACRS - Advisory Committee on Reactor Safeguards 84/06/01
ACRS - Advisory Committee on Reactor Safeguards 5pp 25866 350

8408010111 Summary of ACRS Subcommittee on Air Sys 840426 meeting in Washington, DC re review of general design of essential chilled water sys & analysis & prioritization of new Generic Safety Issue 43, "Contamination of Instrument "
* ACRS - Advisory Committee on Reactor Safeguards 84/06/15
ACRS - Advisory Committee on Reactor Safeguards 11pp 25873 341

8408020170 Comments on ACRS 840604-05 consultant rept re modular test facility proposed by RES Analytical model improvements needed in several areas
SULLIVAN, M Affiliation Not Assigned SULLIVAN, M ACRS - Advisory Committee on Reactor Safeguards 84/06/11, BOEHNERT, P A ACRS - Advisory Committee on Reactor Safeguards 4pp 25898 072

8408020211 Comments on ACRS ECCS Subcommittee 840604 meeting re review of proposal of new modular test facility New facility, if constructed, must have capability of allowing both integral & separate effects tests
TIEN, C California, Univ of, Berkeley, CA TIEN, C ACRS - Advisory Committee on Reactor Safeguards 84/06/29 BOEHNERT, P A ACRS - Advisory Committee on Reactor Safeguards 2pp 25898 168

8408020213 Comments on Metal Components Subcommittee 840517 & 18 meetings re pressurized thermal shock
BENDER, M Affiliation Not Assigned BENDER, M ACRS - Advisory Committee on Reactor Safeguards 84/06/13 AXTMANN, R ACRS - Advisory Committee on Reactor Safeguards 4pp 25898 164

8408020235 Forwards written comments on NUREG-1070, per Class-9 Accident Subcommittee meeting NUREG should state precisely whether new generation std plants will be safer than current plants
CORRADINI, M L Michigan, Univ of, Ann Arbor, MI CORRADINI, M L ACRS - Advisory Committee on Reactor Safeguards 84/06/11 KERR, W ACRS - Advisory Committee on Reactor Safeguards KERR, W Michigan, Univ of, Ann Arbor, MI 4pp 25898 189

8408020237 Comments on 840628 & 0702 matl re disposal of nuclear waste in unsaturated zone in comparison w/disposal in saturated zone In demonstrably impervious rock Matl does not change validity of 840320 comments on NUREG-1046
PHILBRICK, S S Philbrick, S S PHILBRICK, S S ACRS - Advisory Committee on Reactor Safeguards 84/07/06 MOELLER, D W ACRS - Advisory Committee on Reactor Safeguards 1p 25898 188

08020242 Forwards comments on ACRS 840523 tour of plant site, in response to 840915 ltr
MYSINGER, E D Tennessee Valley Authority 84/08/01 MCKINLEY, J C ACRS - Advisory Committee on Reactor Safeguards 4pp 25898 157
24X Fiche 50-275, 84/08/01, 8408020242

8408020244 Forwards addl comments on 840418 draft severe accident policy statement, based on 840531 Class 9 accident
BENDER, M Affiliation Not Assigned, BENDER, M ACRS - Advisory Committee on Reactor Safeguards 84/06/07 KERR, W ACRS - Advisory Committee on Reactor Safeguards 10pp 25898 147

8408020248 Summarizes DHR Subcommittee 840605 meeting re Unresolved Safety Issue A-45, "Shutdown DHR Requirement " Various studies do not contain all elements along heat flow path From heat source to heat sink
CATTON, I ACRS - Advisory Committee on Reactor Safeguards 84/06/11 BOEHNERT, P ACRS - Advisory Committee on Reactor Safeguards 2pp 25898 145

8408020250 Proposed minutes of ACRS Extreme External Phenomena 840404 meeting in Washington, DC re review of generic methodology for developing design basis severe winds for SEP plants & specific applications for Ginna Nuclear Power Plant
* ACRS - Advisory Committee on Reactor Safeguards 84/05/17
ACRS - Advisory Committee on Reactor Safeguards 25pp 25898 120
24X Fiche 50-244, 84/05/17, 8408020250

8408020252 Summarizes ACRS ECCS Subcommittee 840604 meeting re experimental resolution of issues & multi-party agreements w/vendors & others Facility dedicated to NRC needs & operated by NRC as necessary
CATTON, I ACRS - Advisory Committee on Reactor Safeguards 84/06/11 BOEHNERT, P ACRS - Advisory Committee on Reactor Safeguards 2pp 25898 118

8408030091 Transcript of ACRS Subcommittee on ECCS 840731 meeting in Washington, DC Pp 1-272 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/07/31
400pp 25909 030

8408030101 Attachments for transcript of ACRS Subcommittee on Qualification Program for Safety-Related Equipment 840730 meeting in Washington, DC Pp 1-326
* ACRS - Advisory Committee on Reactor Safeguards 84/07/30
344pp 25906 024

8408030204 Transcript of ACRS Subcommittee on Qualification Program for Safety-Related Equipment 840730 meeting in Washington, DC Pp 1-326
* ACRS - Advisory Committee on Reactor Safeguards 84/07/30
328pp 25916 146

8408140133 Transcript of ACRS 292nd meeting on 840810 in Washington, DC Pp 210-576
* ACRS - Advisory Committee on Reactor Safeguards 84/08/10
358pp 26047 019

8408140203 Transcript of ACRS Subcommittee on Reactor Radiological Effects & Waste Mgt 840808 meeting in Washington, DC Pp 249-329 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/08/08
104pp 26045 207

8408140206 Transcript of ACRS 292nd meeting on 840809 in Washington, DC Pp 187-217 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/08/09 43pp
26045 311

8408140210 Transcript of ACRS Subcommittee on Reactor Radiological Effects & Waste Mgt 840807 meeting in Washington, DC Pp 1-248 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/08/07
276pp 26056 329

8408140212 Transcript of ACRS 292nd meeting on 840809 in Washington, DC Pp 1-188 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 84/08/09
275pp 26054 001

8408140306 Attachments to transcript of ACRS 292nd meeting on 840810 in Washington, DC
* ACRS - Advisory Committee on Reactor Safeguards 84/08/10
137pp 26043 179

8408170287 Forwards summary of comments from ACRS 292nd meeting on 840809-11 in Washington, DC re draft DOE mission plan for civilian radwaste mgt program
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 84/08/13 DIRCKS, W J Office of the Executive Director for Operations 5pp 26115 112

8408170316 Summarizes ACRS 292nd meeting on 840809-11 re Task Action Plan A-45, "Shutdown DHR Requirements " Effort to apportion quantitative reliability goals among plant subsys endorsed
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 84/08/14 DIRCKS, W J Office of the Executive Director for Operations 2pp 26114 280

8408170373 Summarizes ACRS 292nd meeting on 840809-11 re proposed amends to 10CFR60 concerning disposal of high level radwastes in geological repositories Disposal in unsaturated zone recognized as possible alternative
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 84/08/14 PALLADINO, N J Commissioners 2pp 26112 359

NONDOCKETED ITEMS

8408170378 Summarizes ACRS 292nd meeting on 840809-11 re NRC proposal to designate Generic Issue 23, Reactor Coolant Pump Seal Leakage, as unresolved safety issue Higher priority rating should expedite satisfactory resolution
EBERSOLE J C ACRS - Advisory Committee on Reactor Safeguards
84/08/14 DIRCKS,W J Office of the Executive Director for Operations 2pp 26113 353

8408200074 Transcript of ACRS Subcommittee on ECCS 840604 meeting in Washington,DC Pp 1-263
* ACRS - Advisory Committee on Reactor Safeguards 84/06/04
265pp 26143 001

8408200240 Corrected transcript of ACRS Subcommittee on DHR Sys 840605 meeting in Washington,DC Pp 1-234
* ACRS - Advisory Committee on Reactor Safeguards 84/06/05
235pp 26142 015

8408290323 Summary of ACRS Subcommittee on ECCS 840502 meeting in Washington,DC re joint NRC/B&W Owners Group/B&W/EPRI integral test program
* ACRS - Advisory Committee on Reactor Safeguards 84/07/12
ACRS - Advisory Committee on Reactor Safeguards 37pp 26312 260

8408290333 Summary of ACRS Subcommittee on Safety Research Program 840509 meeting in Washington,DC re proposed NRC safety research program & budget for FY86 & 87 Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 84/07/12
ACRS - Advisory Committee on Reactor Safeguards 36pp 26311 324

8408290335 Summary of ACRS Subcommittee on Metal Components 840517-18 meetings in Washington,DC re status of LWR water chemistry & effect on metal degradation & progress in pressurized thermal shock research program
* ACRS - Advisory Committee on Reactor Safeguards 84/07/13
ACRS - Advisory Committee on Reactor Safeguards 22pp 26311 302

8408290368 Summary of ACRS Subcommittees on Reactor Radiological Effects, Air Sys & Waste Mgt 840531-0601 meetings in Washington,DC re NRC proposed research programs & budget for FY86 & 87 & INPO rept on ALARA program implementation
* ACRS - Advisory Committee on Reactor Safeguards 84/07/13
ACRS - Advisory Committee on Reactor Safeguards 18pp 26310 293

8408290369 Summary of ACRS Subcommittee on ECCS 840424 meeting in Washington,DC re GE SAFER/GESTR ECCS EM Code
* ACRS - Advisory Committee on Reactor Safeguards 84/06/21
ACRS - Advisory Committee on Reactor Safeguards 34pp 26310 259

8408290370 Summary of ACRS Subcommittee on Waste Mgt 840711 meeting in Washington,DC re DOE draft mission plan for civilian radwaste mgt program,NRC High Level Waste Oversight Committee rept & proposed amends to 10CFR60
* ACRS - Advisory Committee on Reactor Safeguards 84/07/23
ACRS - Advisory Committee on Reactor Safeguards 13pp 26309 348

8408290371 Summary of ACRS 289th meeting on 840510-12 in Washington,DC Apps encl
* ACRS - Advisory Committee on Reactor Safeguards 84/05/12
ACRS - Advisory Committee on Reactor Safeguards 210pp 26310 014

8408290534 Summary of ACRS 287th meeting on 840315-17 in Washington,DC Apps encl
* ACRS - Advisory Committee on Reactor Safeguards 84/03/17
ACRS - Advisory Committee on Reactor Safeguards 40pp 26312 344

8408290562 Summary of ACRS Subcommittee on DHR Sys 840605 meeting in Washington,DC re resolution effort for Unresolved Safety Issue A-45, "Shutdown DHR Sys "
* ACRS - Advisory Committee on Reactor Safeguards 84/06/21
ACRS - Advisory Committee on Reactor Safeguards 27pp 26310 232

8408290567 Summary of ACRS Subcommittee on Regulatory Activities 840612 meeting in Washington,DC
* ACRS - Advisory Committee on Reactor Safeguards 84/07/11
ACRS - Advisory Committee on Reactor Safeguards 18pp 26309 330

8408300051 Summary of ACRS 288th meeting on 840405-07 in Washington,DC Apps encl
* ACRS - Advisory Committee on Reactor Safeguards 84/04/05
ACRS - Advisory Committee on Reactor Safeguards 200pp 26332 145

8408300265 Summary of 286th ACRS meeting on 840209-11 in Washington,DC Apps encl
* ACRS - Advisory Committee on Reactor Safeguards 84/08/30
ACRS - Advisory Committee on Reactor Safeguards 200pp 26330 001

8408300286 Summary of ACRS Subcommittee on ECCS 840604 meeting in Washington,DC re review of NRC/RES thermal-hydraulic research program for rept to Commission on FY86-87 budget
* ACRS - Advisory Committee on Reactor Safeguards 84/06/21
ACRS - Advisory Committee on Reactor Safeguards 30pp 26330 303

8408310227 Transcript of ACRS Subcommittee on Reliability & Probabilistic Assessment 840827 meeting in Windsor Locks,CT Pp 1-230 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/08/28
321pp 26319 281 24X Fiche 50-423,84/08/28,8408310227

ADVCM NRC ADVISORY COMMITTEE

8408020046 Transcript of 840712 meeting in Harrisburg,PA Pp 1-113 Supporting documentation encl
* Advisory Council for Decontamination of TMI Unit 2 84/07/12
183pp 25883 316 24X Fiche 50-320,84/07/12,8408020046

8408220444 Accepts resignation from Advisory Panel on Decontamination of TMI-2 Expresses appreciation for & recognition of contributions made to activities of panel while serving as member since 1980
PALLADINO,N J Commissioners 84/08/16 WAGNER,H N Johns Hopkins Medical Institutions, Baltimore, MD 3pp 26201 351 24X Fiche 50-320,84/08/16,8408220444

--8408220448 Submits ltr of resignation from Citizen Advisory Panel on Decontamination of TMI-2
WAGNER,H N Johns Hopkins Medical Institutions, Baltimore, MD
WAGNER,H N Advisory Council for Decontamination of TMI Unit 2
84/07/09 PALLADINO,N J Commissioners 1p 26201 354 24X Fiche 50-320,84/08/16,8408220444

8408270096 Transcript of TMI Advisory Panel on TMI Unit 2 Decontamination on 840809 public meeting in Harrisburg,PA Pp 1-33 Supporting documentation encl
* Advisory Council for Decontamination of TMI Unit 2 84/08/09
138pp 26257 048 24X Fiche 50-320,84/08/09,8408270096

8408290154 Accepts resignation as member of Advisory Panel for Decontamination for TMI-2 Certificate of appreciation encl
PALLADINO,N J Commissioners 84/08/16 WAGNER,H N Affiliation Not Assigned 2pp 26311 360 24X Fiche 50-320,84/08/16, 8408290154

COMMISSION NRC COMMISSIONERS

8405180145 Responds to 840314 ltr to Chairman Palladino which encl W & V Smelser concern re Marble Hill & Bailly cancellation, withdrawal of util application for Zimmer & denial of license for Byron facility
DIRCKS,W J Office of the Executive Director for Operations
84/05/04 LUGAR,R G Senate 7pp 24524 325 24X
Fiche 50-000,84/05/04,8405180145

--8405180152 Requests response to encl W & V Smelser 840210 inquiry int NRC attitude toward utils Concerns include Marble Hill & Bailly cancellation,withdrawal of util application for Zimmer & denial of license for Byron facility
LUGAR,R G Senate 84/03/14 PALLADINO,N Commissioners 3pp 24524 331 24X Fiche 50-000,84/05/04,8405180145

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18
RICE,C M Kirkland & Ellis 2pp 26500 001

--8206060008 Summarizes 266th ACRS meeting on 820603-05 Subj to satisfactorily completion of const & staffing & if due regard given to ACRS comments,plant can operate at 5% power w/o undue risk to public Full power recommendation deferred
SHEHMON,P ACRS - Advisory Committee on Reactor Safeguards BX14 004 82/06/08 PALLADINO,N Commissioners 6pp 26500 028

8408010275 Responds to 840208 ltr re concerns over perceived tendency by staff to assume that margins of safety established by criteria need not be adhered to for sys not pivotal to safety
DIRCKS,W J Office of the Executive Director for Operations
84/07/20 PANETTA,L House of Rep 9pp 25872 342 24X
Fiche 50-275,84/07/20,8408010275

--8408010277 Requests preparation of response to Panetta 840208 ltr on concerns re QA hearing
PALLADINO,N J Commissioners 84/06/19 DIRCKS,W J Office of the Executive Director for Operations 1p 25872 351, 24X
Fiche 50-275,84/07/20,8408010275

NONDOCKETED ITEMS

108070201 Responds to 840522 ltr re plant problems & estimate of when plant fully operational Commission meeting for briefing & possible vote on full-power OL scheduled on 840731
DIRCKS,W J Office of the Executive Director for Operations
84/07/27 BETHUNE,E House of Rep 3pp 25957 066 24X
Fiche 50-416,84/07/27,8408070201

-8408070207 Requests encl Insert A re minor plant problems not delaying full power licensing be placed in Dircks 840727 ltr draft
SCINTO,J NRC - No Detailed Affiliation Given 84/07/02
ADENSAM,E NRC - No Detailed Affiliation Given 3pp 25957 071
24X Fiche 50-416,84/07/27,8408070201

-8408070215 Requests info re spec & surveillance problems at plant & estimate of when plant will be fully operational
BETHUNE,E House of Rep 84/03/22 PALLADINO,N Commissioners
1p 25957 075 24X Fiche 50-416,84/07/27,8408070201

408070211 Ack receipt of 840622 ltr to Palladino requesting info re safety questions raised by JW Huber Concerns highlighted in Huber 830309 list,encompassing design,const & testing, involve no violations of NRC regulations
DIRCKS,W J Office of the Executive Director for Operations
84/07/25 CARNEY,W House of Rep 4pp 25957 054 24X
Fiche 50-322,84/07/25,8408070211

-8408070217 Forwards JW Huber 840612 ltr re safety questions noted during employment by util Info addressing Huber contentions requested W/840611 telcon record
CARNEY,W House of Rep 84/06/22 PALLADINO,N J Commissioners
3pp 25957 057 24X Fiche 50-322,84/07/25,8408070211

408080034 Ack receipt of 840612 ltr re NRC assistance to State of TX on programs for developing low level radwaste disposal capacity NRC will provide State of TX & other Agreement States w/technical assistance appropriate to needs
PALLADINO,N J Commissioners 84/07/20 WHITE,M Texas, State of
2pp 25981 061

-8408080038 Encourages NRC to ensure adequate resources for assistance to states in complying w/10CFR61 re low level radwaste disposal
WHITE,M Texas, State of 84/06/12 PALLADINO,N Commissioners
1p 25981 063

8408080082 Responds to 840614 ltr to Palladino commenting on 10CFR50 54 permitting deviations from Tech Specs in emergency & requesting regulation be canceled Lists circumstances which must exist before rule can be used
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/07/26 YOUNG,C Affiliation Not Assigned 14pp 25978 264
24X Fiche 50-320,84/07/26,8408080082

-8408080087 Reaffirms recommendations stated in 840503 ltr re canceling regulations permitting licensee to deviate from Tech Specs in emergency & ensuring that president of facility implement policy to operate in accordance w/OL & Tech Specs
YOUNG,C Affiliation Not Assigned 84/06/14 PALLADINO,N J
Commissioners 8pp 25978 276 24X Fiche 50-320,84/07/26,
8408080082

8408080384 Discusses jurisdictional issue re EPA proposed environ stds for mgt & disposal of spent nuclear fuel & NRC regulation 10CFR60 Mod to 10CFR60 appropriate to incorporate EPA proposed assurance requirements
ROBERTS,T M Commissioners 84/07/19 RUCKELSHAUS,W
Environmental Protection Agency 2pp 25978 085

8408080427 Regrets to learn of death of Z Bartolome
PALLADINO,N J Commissioners 84/07/23 VER ALBANO,A
Philippines, Govt of 1p 25977 189

8408080430 Responds to 840531 ltr raising concerns re NRC 840522 order & continued low power operation in spite of outstanding issues of compliance w/OGC 17 Asselstine opinion encl
PALLADINO,N J Commissioners 84/07/23 MARKEY,E J House of
Rep , Interior & Insular Affairs 3pp 25977 184 24X
Fiche 50-416,84/07/23,8408080430

-8408080432 Expresses concern re NRC apparent abandonment of agency regulations w/licensing of plant Overwhelming weight of evidence creates impression that operation of plant constitutes violation of NRC regulations
MARKEY,E J House of Rep , Interior & Insular Affairs 84/05/31
PALLADINO,N J Commissioners 2pp 25977.187 24X
Fiche 50-416,84/07/23,8408080430

8408080484 Weekly info rept for wk ending 840727.
REHM,T A Office of the Executive Director for Operations
84/08/02 41pp 25976 013

8408090102 Responds to 840614 request for Commission generic resolution of safety equipment classification issue Issue addressed in Commission 840606 Order CLI-84-9 Rulemaking proceeding initiated
PLAINE,H H Office of the General Counsel CLI-84-9 84/07/25
HARSHE,B L Utility Safety Classification Group 2pp 25991 237

--8408090106 Comments on NRC 840511 briefing re safety classification issue & requests opportunity to discuss issue w/Commission
HARSHE,B L Utility Safety Classification Group 84/06/14
PALLADINO,N Commissioners 3pp 25991 249

8408090109 Forwards "Annual Rept for 1983 on Administration of Govt in Sunshine Act of 1976 "
PALLADINO,N J Commissioners 84/07/25 O'NEILL,T P House of
Rep Speaker of the House 1p 25991 214

--8408090111 Forwards "Annual Rept for 1983 on Administration of Govt in Sunshine Act of 1976 "
PALLADINO,N J Commissioners 84/07/25 BUSH,G Senate,
President of the Senate 1p 25991 215

--8408090113 "Annual Rept for 1983 on Administration of Govt in Sunshine Act of 1976 "
* Commissioners 84/07/25 21pp 25991 216

8408090216 Forwards NRC comments re DOE draft "Mission Plan for Civilian Radwaste Mgt Program " NRC objections based on regulatory info needs,establishment of performance goals & need for addl consultation w/NRC Asselstine comments encl
PALLADINO,N J Commissioners 84/07/31 RUSCHE,B C Energy, Dept
of 59pp 25992 013

8408130202 Responds to 840330 ltr re deficiencies at facility NRC unaware of serious defects at plant Enforcement action still pending re matl false statements in operator records
DIRCKS,W J Office of the Executive Director for Operations
84/07/31 ANTHONY,B House of Rep 46pp 26060 166 24X
Fiche 50-416,84/07/31,8408130202

--8408130210 Requests info re deficiencies in design & const of plant & in qualification & training of staff Raises concerns on possibility of higher costs being passed on to constituents
ANTHONY,B House of Rep 84/03/30 PALLADINO,N J
Commissioners 4pp 26060 213 24X Fiche 50-416,84/07/31,
8408130202

8408160030 Weekly info rept for wk ending 840803
REHM,T A Office of the Executive Director for Operations
84/08/10 35pp 26128 175

8408200225 Discusses Tech Spec errors discovered subsequent to NRC approval Susquehanna Tech Spec amends had no safety significance McGuire Tech Specs still under review w/no identified safety significance thus far
ASSELSTINE,J K Commissioners 84/08/10 MARKEY,E J House of
Rep , Interior & Insular Affairs 4pp 26141 244 24X
Fiche 50-000,84/08/10,8408200225

--8408200235 Forwards technical evaluation rept re Tech Spec audit Only discrepancy involved lack of quantitative criteria for limit switch setting & calibr for suppression chamber vacuum breakers Util should resolve rept recommendations
STAROSTECKI,R Division of Project & Resident Programs 84/04/10
EISENHUT,D G Division of Licensing 3pp 26141 262 24X
Fiche 50-000,84/08/10,8408200225

--8408040095 Forwards "Audit of Susquehanna Unit 2 Tech Specs," technical evaluation rept
PANDEY,S Franklin Institute/Franklin Research Center
NRC-03-81-130 84/03/30 CARRINGTON,M NRC - No Detailed
Affiliation Given 1p 26141 265 24X Fiche 50-000,84/08/10,
8408200225

--8404040098 TER-C5506-524
"Audit of Susquehanna Unit 2 Tech Specs," technical evaluation rept
DACANSKAS,V P , MURPHY,J A Franklin Institute/Franklin Research Center NRC-03-81-130 84/03/30 BETTENHAUSEN,L , MCCABE,E NRC - No Detailed Affiliation Given 26pp 26141 266 24X
Fiche 50-000,84/08/10,8408200225

--8408200263 Forwards IE Insp Rept 50-416/84-11 on 840328-30 & notice of deviation
LEWIS,R C Division of Project & Resident Programs 84/04/24
RICHARD,J B Mississippi Power & Light Co 2pp 26141 330 24X
Fiche 50-000,84/08/10,8408200225

--8408200267 Notice of deviation from insp on 840328-30
* Region 2, Office of Director 84/04/24 1p 26141 332 24X
Fiche 50-000,84/08/10,8408200225

-8408300271 IE Insp Rept 50-416/84-11 on 840328-30 Deviation noted no surveillance procedure established to periodically test remote shutdown control components & components not tested since preoperational testing
CALDWELL J L , HEHL,C W , JULIAN,C A Region 2, Office of Director 84/04/24 7pp 26141 333 24X Fiche 50-000,84/08/10, 8408200225

--8408200279 Requests further info re Tech Spec errors for specs approved since TMI-2 episode Info re near-term OL activities also requested
MARKEY,E J House of Rep Interior & Insular Affairs 84/07/12
PALLADINO,N J Commissioners 1p 26112 002 24X
Fiche 50-000,84/08/10 8408200225

8408220444 Accepts resignation from Advisory Panel on Decontamination of TMI-2 Expresses appreciation for & recognition of contributions made to activities of panel while serving as member since 1980
PALLADINO,N J Commissioners 84/08/16 WAGNER,H N Johns Hopkins Medical Institutions, Baltimore, MD 3pp 26201 351 24X
Fiche 50-320,84/08/16,8408220444

--8408220448 Submits ltr of resignation from Citizen Advisory Panel on Decontamination of TMI-2
WAGNER,H N Johns Hopkins Medical Institutions, Baltimore, MD
WAGNER,H N Advisory Council for Decontamination of TMI Unit 2
81/07/09 PALLADINO,N J Commissioners 1p 26201 354 24X
Fiche 50-320,84/08/16,8408220444

8408280467 Ack receipt of 840702 ltr & invitation to observe 840819 emergency exercise Tentative arrangements made for NRC representatives to attend exercise at Kori II in Sept in lieu of personal attendance by Chairman
PALLADINO,N J Commissioners 84/08/13 JUNG-KI,P Korea Electric Co 1p 26294 113

--8408280471 Expresses thanks for meeting during recent visit & extends invitation to observe 840819 emergency response exercise against radioactive matl leakage in Korea
JUNG-KI,P Korea Electric Co 84/07/02 PALLADINO,N J
Commissioners 2pp 26294 114

8408290154 Accepts resignation as member of Advisory Panel for Decontamination for TMI-2 Certificate of appreciation encl
PALLADINO,N J Commissioners 84/08/16 WAGNER,H N Affiliation Not Assigned 2pp 26311 360 24X Fiche 50-320,84/08/16, 8408290154

8408290348 Responds to 840703 request for suggestions re preparation of fifth Natl Energy Policy Plan Addressing of future natl electricity supply & projected mix of coal & nuclear power in supply recommended
PALLADINO,N J Commissioners 84/08/15 HODEL,D P Energy, Dept of 1p 26311 267

--8408290390 Requests proposals for strategies,programs & initiatives for consideration during preparation of Fifth Natl Energy Policy Plan (NEPP) Input requested by 840901 Fourth NEPP encl
HODEL,D P Energy, Dept of 84/07/03 PALLADINO,N J
Commissioners 1p 26311 268

--8408290352 DOE/S-0014/L
"Natl Energy Policy Plan "
* Energy, Dept of 83/10/31 27pp 26311 269

8408290356 Forwards 20th joint quarterly status rept re emergency preparedness covering period through 840630 No delay in current licensing proceedings due to emergency preparedness issues
BERNTHAL,F M Commissioners GIUFFRIDA,L O Federal Emergency Management Agency 84/08/09 SIMPSON,A K Senate, Environment & Public Works 1p 26310 311

--8408290359 "NRC/FEMA Joint Quarterly Rept to Congress on Emergency Preparedness,Through 840630 "
* NRC - No Detailed Affiliation Given * Federal Emergency Management Agency 84/06/30 46pp 26310 312

8408300290 Weekly info rept for wk ending 840817
REHM,T A Office of the Executive Director for Operations
84/08/23 40pp 26329 313

CONTRACT NRC CONTRACTS AND MODIFICATIONS

8408010041 Notification of contract execution,Mod 3, to "Support Svcs for Research & Evaluation of Severe Accident Phenomenon & Mitigation " Contractor Battelle Columbus Labs
WOLLETT,S Technical Assistance Contracts Branch FIN B-7499
NRC-04-84-127 84/07/24 BATSON,W Office of Nuclear Regulatory Research, Director LARKINS,J NRC - No Detailed Affiliation Given 1p 25866 347

--8408010048 Mod 3, providing incremental funding, to "Support Svcs for Evaluation of Severe Accident Phenomenon & Mitigation "
* Battelle Memorial Institute, Columbus Laboratories SMITH,P A Division of Contracts FIN B-7499 NRC-04-84-127 84/07/24 1p 25866 348

8408010175 Notification of contract execution,Mod 7, to "Geotechnical Assistance " Contractor US Army Corps of Engineers
FLEENOR,C Technical Assistance Contracts Branch NRC-02-81-036
84/05/14 DAVIS,J Office of Nuclear Material Safety & Safeguards, Director WESTBROOK,K NRC - No Detailed Affiliation Given 1p 25873 302

--8408010182 Mod 7, designating NRC project officer to replace project officer identified under agreement, to "Geotechnical Assistance "
* Army, Dept of, Corps of Engineers SMITH,P A Division of Contracts NRC-02-81-036 84/05/14 1p 25873 303

8408060014 Notification of contract execution,Mod 2, to "Maint & Operation of LPDRs " Contractor Clermont County,OH Public Library
HOPPER,A Administrative Contracts Branch NRC-10-83-740
84/07/20 FELTON,J M Division of Rules and Records SOUDER,J
NRC - No Detailed Affiliation Given 1p 25936 352

--8408060017 Mod 2, extending period of performance until 850921 & increasing funds, to "Maint & Operation of LPDRs "
* Clermont County, OH HAGAN,T F Division of Contracts
NRC-10-83-740 84/07/20 2pp 25936 353

8408060018 Notification of contract execution,Mod 2, to "Maint & Operation of LPDRs " Contractor Rochester,NY Public Library
HOPPER,A Administrative Contracts Branch NRC-10-83-729
84/07/24 FELTON,J M Division of Rules and Records SOUDER,J
NRC - No Detailed Affiliation Given 1p 25936 355

--8408060025 Mod 2, extending period of performance until 850916 & increasing funding, to "Maint & Operation of LPDRs "
* Rochester, NY HAGAN,T F Division of Contracts
NRC-10-83-729 84/07/24 2pp 25936 356

8408060031 Notification of contract execution,Mod 2, to "Maint & Operation of LPDRs " Contractor WH Abel Memorial Library, Montesano,WA
HOPPER,A Administrative Contracts Branch NRC-10-83-753
84/07/24 FELTON,J M Division of Rules and Records SOUDER,J L
NRC - No Detailed Affiliation Given 1p 25937 071

--8408060037 Mod 2, extending period of performance until 850929 & increasing funding, to "Maint & Operation of LPDRs "
* Montesano, WA HAGAN,T F Division of Contracts
NRC-10-83-753 84/07/24 2pp 25937 072

8408060038 Notification of contract execution,Mod 2, to "Maint & Operation of LPDRs " Contractor Morris,IL Public Library
HOYLE,A Administrative Contracts Branch NRC-10-83-735 84/06/19
FELTON,J M Division of Rules and Records SOUDER,J NRC - No Detailed Affiliation Given 1p 25937 074

--8408060040 Mod 2, extending period of performance until 850505 & increasing funds, to "Maint & Operation of LPDRs "
* Morris, IL HAGAN,T F Division of Contracts NRC-10-83-735
84/06/19 1p 25937 075

8408060041 Notification of contract execution,Mod 2, to "Maint & Operation of LPDRs " Contractor Indian River Community College
HOPPER,A Administrative Contracts Branch NRC-10-83-750
84/07/24 FELTON,J M Division of Rules and Records SOUDER,J L
NRC - No Detailed Affiliation Given 1p 25937 092

--8408060048 Mod 2, extending period of performance until 850916 & increasing funding, to "Maint & Operation of LPDRs "
* Indian River Community College, Ft Pierce, FL HAGAN,T F
Division of Contracts NRC-10-83-750 84/07/24 2pp 25937 093

8408060211 Notification of contract execution Mod 2, to 'Maint & Operation of LPDRs ' Contractor Madison-Jefferson County Public Library
HOPPER, A Administrative Contracts Branch NRC-10-83-741
84/07/24 FELTON, J M Division of Rules and Records SOUDER, J L
NRC - No Detailed Affiliation Given 1p 25936 180

--8408060214 Mod 2, extending period of performance to 850916 & increasing funds, to "Maint & Operation of LPDRs "
BABBITT, D L Madison, IN HAGAN, T F Division of Contracts
NRC-10-83-741 84/07/24 2pp 25936 181

8408060424 Notification of grant execution, Mod 1, to 'Preliminary Analysis of Procedures for Calibr of Short Circuit Currents in Electrical Penetration Assemblies ' Grantee Tuskegee Inst
UMBEL, D Technical Assistance Contracts Branch FIN G-1059
NRC-G-04-84-003 84/07/24 BATSON, W Office of Nuclear Regulatory Research, Director SULLIVAN, D NRC - No Detailed Affiliation Given 1p 25937 336

--8408060426 Mod 1, extending period of performance to 841114, to "Preliminary Analysis of Procedures for Calibr of Short Circuit Currents in Electrical Penetration Assemblies "
WILLIAMS, L A Tuskegee Institute, Tuskegee, AL MORTON, K V
Technical Assistance Contracts Branch FIN G-1059
NRC-G-04-84-003 84/07/24 1p 25937 337

8408070047 Notification of contract execution, Mod 1, to "Technical Assistance to Support IE Personnel in Integrated Design Insps " Contractor Westec Svcs, Inc
WOLLETT, S Technical Assistance Contracts Branch FIN B-8719
NRC-05-84-151 84/07/25 MUIR, A Director's Office, Office of Inspection and Enforcement MILHOAN, J NRC - No Detailed Affiliation Given 1p 25955 338

--8408070053 Mod 1, providing incremental funding & specifying period of performance, to "Technical Assistance to Support IE Personnel in Integrated Design Insps "
* WESTEC Services, Inc SMITH, P A Division of Contracts FIN B-8719 NRC-05-84-151 84/07/25 1p 25955 339

8408070080 Notification of contract execution, Mod 1, to "Hydrogeologic Evaluations of U Recovery Facilities " Contractor Williams & Assoc, Inc
BAISDEN, L Technical Assistance Contracts Branch FIN B-8505
NRC-31-84-501 84/07/26 ROSE, H Uranium Recovery Field Office
HILDENBRAND, P NRC - No Detailed Affiliation Given 1p 25957 093

--8408070087 Mod 1, changing contract number & obligation amount, to "Hydrogeologic Evaluations of U Recovery Facilities "
* Williams & Associates MORTON, K V Division of Contracts FIN B-8505 NRC-31-84-501 84/07/26 2pp 25957 094

8408070101 Notification of contract execution, Mod 3, to "Low Level Nuclear Waste Processing & Shallow Land Burial Trench Isolation " Contractor Univ of Arizona
UMBEL, D Technical Assistance Contracts Branch FIN B-7072
NRC-04-81-220 84/07/25 BATSON, W Office of Nuclear Reactor Regulation, Director O'DONNEL, E NRC - No Detailed Affiliation Given 1p 25955 224

--8408070104 Mod 3, changing co-principal investigator, to "Low Level Nuclear Waste Processing & Shallow Land Burial Trench Isolation "
WHEELER, J T Arizona, State of SMITH, P A Technical Assistance Contracts Branch FIN B-7072 NRC-04-81-220 84/07/25 2pp 25955 225

8408080005 Notification of grant execution "American Statistical Assoc Conference on Radiation & Health," awarded to American Statistical Assoc
UMBEL, D Technical Assistance Contracts Branch FIN G-1072
NRC-G-04-84-008 84/07/31 BATSON, W Office of Nuclear Regulatory Research, Director GINEVAN, M E NRC - No Detailed Affiliation Given. 2pp 25982 170

--8408080008 Grant "American Statistical Assoc Conference on Radiation & Health," awarded to American Statistical Assoc
DENENBERG, E American Statistical Association MORTON, K V
Research Contracts Branch FIN G-1072 NRC-G-04-84-008
84/07/31 1p 25982 172

8408080020 Notification of contract execution "Region IV Data Entry Svcs," awarded to AIC Analysts Corp
HAGEY, H Administrative Contracts Branch NRC-33-84-383 84/07/06
BASSET, H S Division of Data Automation & Management Information
KAY, B NRC - No Detailed Affiliation Given 1p 25981 038

--8408080025 Ltr Contract NRC-33-84-383 "Region IV Data Entry Svc," awarded to AIC Analysts Corp
MATTIA, M J Division of Contracts NRC-33-84-383 84/07/05
DOHERTY, M J AIC Analysts Corp 15pp 25981 039

8408080052 Notification of contract execution, Mod 2, to Nuclear Power Plant Operations Courses " Contractor Chattanooga State Technical Community College
UMBEL D Technical Assistance Contracts Branch FIN B-1279
NRC-05-81-251 84/07/31 BLAHA, J Program Support * Analysis Staff ROESSLER, S D NRC - No Detailed Affiliation Given 1p 25981 067

--8408080064 Mod 2, extending period of performance & obligating funds to "Nuclear Power Plant Operations Course "
BRANCH, C W Chattanooga State Technical Community College, Chattanooga, TN SMITH, P A Technical Assistance Contracts Branch FIN B-1279 NRC-05-81-251 84/07/31 2pp 25981 068

8408080059 Notification of contract execution, Mod 2, to "Maint & Operation of LPDRs " Contractor Wheeler Basin Regional Library
HOPPER, A Administrative Contracts Branch NRC-10-83-751
84/07/26 FELTON, J M Division of Rules and Records SOUDER, J L
NRC - No Detailed Affiliation Given 1p 25981 080

--8408080067 Mod 2, extending period of performance to 850916 & increasing funding, to "Maint & Operation of LPDRs "
* Wheeler Basin Regional Library, Decatur, AL HAGAN, T F
Division of Contracts NRC-10-83-751 84/07/26 1p 25981 081

8408080317 Notification of contract execution, Mod 1, to "Hydrogeologic Evaluations " Contractor INTERA Technologies, Inc
UMBEL, D Technical Assistance Contracts Branch FIN B-7384
NRC-02-83-041 84/08/01 BROWN, R S Program Support Branch
WIDMAYER, D NRC - No Detailed Affiliation Given 1p 25978 205

--8408080321 Mod 1, adding FY84 funds & changing company name & principal investigator to, "Hydrogeologic Evaluations "
PAHWA, S B INTERA Technologies, Inc SMITH, P A Division of Contracts FIN B-7384 NRC-02-83-041 84/08/01 2pp 25978 206

8408080476 Notification of contract execution, Mod 6, to "Shuttle Bus Svc " Contractor Beltway Limousine Svc
BROMBERG, B J Administrative Contracts Branch NRC-10-82-378
84/08/01 CORLEY, J Division of Facility Operations GRANT, L NRC - No Detailed Affiliation Given 1p 25976 059

--8408080480 Mod 6, deobligating funds to enable contract closeout, to "Shuttle Bus Svc " Contractor Beltway Limousine Svc
ROBERTSON, J Beltway Limousine Service, Inc HAGAN, T F Division of Contracts NRC-10-82-378 84/08/01 1p 25976 060

8408080502 Notification of contract execution, Mod 24, Task 62, to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents " Contractor Parameter, Inc
WOLLETT, S Technical Assistance Contracts Branch FIN B-1302
NRC-05-82-249 84/07/18 BLAHA, J Director's Office, Office of Inspection and Enforcement LAUDAN, W NRC - No Detailed Affiliation Given 1p 25976 008

--8408080507 Mod 24, Task 62, adding RCS leak rate for PWRs, to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents "
LOFY, R A Parameter, Inc SMITH, P A Division of Contracts FIN B-1302 NRC-05-82-249 84/07/18 4pp 25976 009

8408090041 Notification of grant execution, Mod 7, to "Experimental Phase of Development of Noninvasive Liquid Level & Density Gauge for Nuclear Power Reactor Vessels " Grantee Pennsylvania State Univ
UMBEL, D Technical Assistance Contracts Branch FIN G-1029
NRC-G-04-81-024 84/07/31 BATSON, W Office of Nuclear Regulatory Research, Director CHEN, Y NRC - No Detailed Affiliation Given 1p 25991 290

--8408090046 Mod 7, providing addl funds & extending period of performance to 850531, to "Experimental Phase of Development of Noninvasive Liquid Level & Density Gauge for Nuclear Power Reactor Vessels "
BAKER, R H Pennsylvania State Univ , University Park, PA
MORTON, K V Research Contracts Branch FIN G-1029
NRC-G-04-81-024 84/07/31 1p 25991 291

8408090072 Notification of contract execution "Technical Assistance for Support of Const Appraisal Team (CAT) Insps " Contractor Parameter, Inc
WIGGINS, E Technical Assistance Contracts Branch FIN B-8718
NRC-05-84-152 84/07/31 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement LOFY, R NRC - No Detailed Affiliation Given 1p 25991 257

--8408090074 Contract "Technical Assistance for Support of Const Appraisal Team (CAT) Insps," awarded to Parameter, Inc
LOFY, R Parameter, Inc MORTON, K V Division of Contracts FIN B-8718 NRC-05-84-152 84/07/31 32pp 25991 258

8408090115 Corrected notification of contract execution,Mod 2,to "Nuclear Power Plant Operation Courses " Contractor Chattanooga State Technical Community College
UMBEL,D Technical Assistance Contracts Branch FIN B-1279
NRC-05-81-251 84/07/31 BLAHA,J Director's Office, Office of Inspection and Enforcement ROESSLER,S D NRC - No Detailed Affiliation Given 1p 25991 210

8408090135 Notification of contract execution,Mod 3,to "Integral Sys Test Program - Once-Through Integral Sys & Multiloop Integral Sys Test Components ' Contractor B&W
WOLLETT,S Technical Assistance Contracts Branch FIN B-8909
NRC-04-83-168 84/07/24 BATSON,W Office of Nuclear Regulatory Research, Director YOUNG,M NRC - No Detailed Affiliation Given 1p 25991 211

--8408090142 Ltr Contract NRC-04-83-168,Mod 3,providing incremental funding,to ' Integral Sys Test Program - Once-Through Integral Sys & Multiloop Integral Sys Test Components "
SMITH,P A Technical Assistance Contracts Branch FIN B-8909
NRC-04-83-168 84/06/27 LUKASIK,M Babcock & Wilcox Co 1p 25991 212

8408090504 Notification of contract execution,Mod 5,to "Safety Aspects of Industrial Radiography Courses " Contractor GAMMA Industries
GILDENHORN,A J Administrative Contracts Branch NRC-05-82-251
84/08/01 MUIR,A P Program Support & Analysis Staff
HASSELBERG,R NRC - No Detailed Affiliation Given 1p 25983 128

--8408090510 Mod 5,deleting dates for third course in entirety,to "Safety Aspects of Industrial Radiography Courses "
RIDDLE,R R Nuclear System HAGAN,T F Division of Contracts
NRC-05-82-251 84/08/01 1p 25983 127

8408090548 Notification of contract execution,Mod 5,to "Radionuclide Migration Around U Ore Bodies - Analogue of Radwaste Repositories " Contractor Australian Atomic Energy Commission
WOLLETT,S Technical Assistance Contracts Branch FIN B-6661
NRC-04-81-172 84/07/31 BATSON,W Office of Nuclear Regulatory Research, Director BIRCHARD,G NRC - No Detailed Affiliation Given 1p 25983 229

--8408090551 Mod 5,extending period of performance to 840930 at no addl cost,to "Radionuclide Migration Around U Ore Bodies - Analogue of Raduaste Repositories "
RATCLIFF,W H Australia, Govt of SMITH,P A Division of Contracts FIN B-6661 NRC-04-81-172 84/07/31 1p 25983 230

8408130308 Notification of contract execution,Mod 3,to "New Madrid/ Midwest Continent Geological & Seismological Research Program " Contractor Univ of Michigan
MACE,M Technical Assistance Contracts Branch FIN B-8080
NRC-04-81-195 84/08/01 BATSON,W Office of Nuclear Regulatory Research, Director MURPHY,A NRC - No Detailed Affiliation Given 1p 26040 331

--8408130314 Mod 3,adding requirements to statement of work & obligating addl funds,to "New Madrid/Midwest Continent Geological & Seismological Research Program "
MATTHEWS,C W Michigan, Univ of, Ann Arbor, MI SMITH,P A Division of Contracts FIN B-8080 NRC-04-81-195 84/08/01 2pp 26040 332

8408130435 Notification of contract execution,Mod 3,to "Licensing Technical Assistance " Contractor Science Applications,Inc
SILVIS,R M Technical Assistance Contracts Branch FIN B-6947-0
NRC-02-80-035 84/08/02 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director LOYSEN,P NRC - No Detailed Affiliation Given 1p 26058 356

--8408130437 Mod 3,incorporating final overhead rates for FY81 & 82 & deobligating balance of funds,to "Licensing Technical Assistance "
FINDLEY,D E Science Applications, Inc SMITH,P A Division of Contracts FIN B-6947-0 NRC-02-80-035 84/08/02 1p 26058 357

8408130440 Notification of contract execution,Mod 2,to "Licensing Technical Assistance " Contractor Science Applications,Inc
SILVIS,R M Technical Assistance Contracts Branch FIN B-6955-0
NRC-02-80-035 84/08/02 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director LOYSEN,P NRC - No Detailed Affiliation Given 1p 26058 354

--8408130442 Mod 2,incorporating final overhead rates for FY81 & 82,to "Licensing Technical Assistance "
FINDLEY,D E Science Applications, Inc SMITH,P A Division of Contracts FIN B-6955-0 NRC-02-80-035 84/08/02 1p 26058 355

8408130444 Notification of contract execution,Mod 4,to "Licensing Technical Assistance " Contractor Science Applications,Inc
SILVIS,R M Technical Assistance Contracts Branch FIN B-6953-0
NRC-02-80-035 84/08/02 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director LOYSEN,P NRC - No Detailed Affiliation Given 1p 26058 352

--8408130445 Mod 4,incorporting final overhead rates for FY81 & 82,to "Licensing Technical Assistance "
FINDLEY,D E Science Applications, Inc SMITH,P A Division of Contracts FIN B-6953-0 NRC-02-80-035 84/08/02 1p 26058 353

8408130592 Notification of contract execution,Mod 4,to "Technical Assistance in Hydrogeology ' Contractor Law Engineering Testing Co
FLEENOR,C Technical Assistance Contracts Branch NRC-02-82-028-01
84/08/06 DAVIS,J Office of Nuclear Material Safety & Safeguards,Director JOHNSON,R NRC - No Detailed Affiliation Given 1p 26036 361

--8408130597 Mod 4,extending period of performance until 850107,to "Technical Assistance in Hydrogeology "
STEINBRENNER,F Law Engineering Testing Co SMITH,P A Division of Contracts NRC-02-82-028-01 84/08/06 1p 26036 362

8408140510 Notification of contract execution,Mod 1,to "QA Congressional Study " Contractor NC Kist & Assoc,Inc
WIGGINS,E Technical Assistance Contracts Branch WOLLETT,S
Division of Contracts NRC-05-84-155 84/07/26 BLAHA,J Program Support & Analysis Staff BRACH,W NRC - No Detailed Affiliation Given 1p 26061 294

--8408140517 Mod 1,adding procedures for replacement of task orders & identifying names of individuals to receive monthly repts, to "QA Congressional Study "
HEIDENREICH,J N C Kist & Associates, Inc MORTON,K V Division of Contracts NRC-05-84-155 84/07/26 1p 26061 295

8408200590 Notification of contract execution,Mod 2,to "Maint & Operation of LPDRs " Contractor Plymouth,MA Public Library
TOWNSEND,B Administrative Contracts Branch NRC-10-83-748
84/08/14 FELTON,J M Division of Rules and Records SOUDER,J
NRC - No Detailed Affiliation Given 1p 26143 273

--8408200597 Mod 2,extending period of performance to 850916 & increasing funds,to 'Maint & Operation of LPDRs "
* Plymouth, MA HAGAN,T F Division of Contracts
NRC-10-83-748 84/08/14 1p 26143 274

8408200602 Notification of contract execution,Mod 2,to "Maint & Operation of LPDRs " Contractor Crystal River,FL Public Library
TOWNSEND,B Administrative Contracts Branch NRC-10-83-747
84/08/14 FELTON,J M Division of Rules and Records SOUDER,J
NRC - No Detailed Affiliation Given 1p 26143 281

--8408200606 Mod 2,extending period of performance to 850916 & increasing funding,to "Maint & Operation of LPDRs "
* Crystal River, FL HAGAN,T F Division of Contracts
NRC-10-83-747 84/08/14 1p 26143 282

8408210024 Notification of contract execution,Mod 1,to "Maint & Operation of LPDRs " Contractor Russell Library, Middletown,CT
TOWNSEND,B Administrative Contracts Branch NRC-10-83-731
84/08/14 FELTON,J M Division of Rules and Records SOUDER,J
NRC - No Detailed Affiliation Given 1p 26195 182

--8408210032 Mod 1,exercising option to extend period of performance for 1 yr to 850921 & increasing funding,to "Maint & Operation of LPDRs "
* Middletown, CT HAGAN,T F Division of Contracts
NRC-10-83-731 84/08/14 1p 26195 183

8408210040 Notification of contract execution,Mod 2,to "Maint & Operation of LPDRs " Contractor Perry,OH Public Library
TOWNSEND,B Administrative Contracts Branch NRC-10-83-736
84/08/14 FELTON,J M Division of Rules and Records SOUDER,J
NRC - No Detailed Affiliation Given 1p 26195 179

--8408210047 Mod 2,exercising option to extend period of performance for 1 yr to 850916 & increasing funding,to "Maint & Operation of LPDRs "
* Perry, OH HAGAN,T F Division of Contracts NRC-10-83-736
84/08/14 1p 26195 180

8408210042 Notification of contract execution, Mod 4, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " Contractor MIT
HOPPER, A Administrative Contracts Branch FIN B-6898
NRC-03-80-144 84/06/12 VOLLMER, R Division of Engineering
JACKSON, R NRC - No Detailed Affiliation Given 1p 26195 176
24X Fiche 50-206, 84/06/12, 8408210042

--8408210046 Mod 4, deobligating unliquidated fee remaining in contract, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station "
AKI, K Massachusetts Institute of Technology, Cambridge, MA
HAGAN, T F Division of Contracts FIN B-6898 NRC-03-80-144
84/06/12 1p 26195 177 24X Fiche 50-206, 84/06/12, 8408210042

8408220075 Notification of contract execution, Mod 2, to "IMS/IDAS Sys Support " Contractor SBA Subcontractor Wilson Hill Assoc, Inc
GILDENHORN, A J Administrative Contracts Branch FIN D-1211
NRC-33-84-378 84/08/02 BASSETT, H S Division of Data Automation & Management Information BADINI, J B NRC - No Detailed Affiliation Given 1p 26210 353

--8408220080 Mod 2, increasing funding & extending period of performance to 840830, to "IMS/IDAS Sys Support "
THOMAS, M E Small Business Administration HILL, P W Wilson Hill Associates, Inc HAGAN, T F Division of Contracts FIN D-1211
NRC-33-84-378 84/08/02 4pp 26210 354

8408220150 Notification of contract execution, Mod 10, to "Central Virginia Regional Seismic Network " Contractor " Virginia Polytechnic Inst & State Univ
PAGE, M Technical Assistance Contracts Branch FIN B-6249
NRC-04-177-134 84/08/10 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given 1p 26212 179

--8408220156 Mod 10, increasing funding & extending period of performance to 850731, to "Central Virginia Regional Seismic Network "
STEISS, A W Virginia Polytechnic Institute & State Univ , Blacksburg, VA SMITH, P A Division of Contracts FIN B-6249
NRC-04-77-134 84/08/10 4pp 26212 180

8408220384 Notification of contract execution, Mod 6, to "Residual Stress at Girth Butt Welds in Pipes or Pressure Vessels " Contractor BMI
SILVIS, R M Research Contracts Branch FIN B-5608 NRC-04-76-293
84/08/02 BATSON, W Office of Nuclear Regulatory Research, Director LYNN, E K NRC - No Detailed Affiliation Given 1p 26209 360

--8408220387 Mod 6, incorporating final overhead rate for FY76-78, to "Residual Stress at Girth Butt Welds in Pipes or Pressure Vessels "
LUKZ, F J Battelle Memorial Institute, Columbus Laboratories
SMITH, P A Division of Contracts FIN B-5608 NRC-04-76-293
84/08/02 1p 26209 361

8408220397 Notification of contract execution "Photographic Reproduction Svcs," awarded to SBA Subcontractor Domus Design Studios, Inc
HAWKINS, D A Administrative Contracts Branch NRC-10-84-270
84/07/18 BEBAW, W J Division of Technical Information & Document Control DEHN, D NRC - No Detailed Affiliation Given 1p 26210 277

--8408220400 Contract "Photographic Reproduction Svcs," awarded to Domus Design Studios, Inc
WADDLE, J W Domus Design Studios, Inc THOMAS, M E Small Business Administration NRC-10-84-270. 84/07/18 2pp 26210 278

--8408220404 Contract "Photographic Reproduction Svcs," awarded to SBA Subcontractor Domus Design Studios, Inc
THOMAS, M E Small Business Administration * Domus Design Studios, Inc HAGAN, T F Division of Contracts NRC-10-84-270
84/07/18 56pp 26210 280

8408230330 Notification of contract execution, Mod 4, to "Reviewing Hydrogeologic Investigations of Bedded & Dome Salt Basins - Project B " Contractor Golder Assoc, Inc
FLEENOR, C Administrative Contracts Branch NRC-02-83-034
84/08/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director COOKE, B NRC - No Detailed Affiliation Given 1p 26236 076

--8408230336 Mod 4, terminating contract, to "Reviewing Hydrogeologic Investigations of Bedded & Dome Salt Basins - Project B "
PENTZ, D L Golder Associates SMITH, P A Division of Contracts
NRC-02-83-034, 84/08/03 2pp 26236 077

8408230484 Notification of contract execution, Mod 3, to "Mod of Existing Air Pathway Model for Low Level Waste Assessment & Training Course " Contractor NOAA
PAGE, M Technical Assistance Contracts Branch FIN B-7359-3
NRC-02-83-031 84/08/16 BROWN, R S Program Support Branch
NEUDER, S NRC - No Detailed Affiliation Given 1p 26230 258

--8408230506 Mod 3, extending period of performance to 841030, to "Mod of Existing Air Pathway Model for Low Level Waste Assessment Training Course "
MAHLER, R J Commerce, Dept of, Natl Oceanographic & Atmospheric Administration SMITH, P A Division of Contracts FIN B-7359-3
NRC-02-83-031 84/08/16 1p 26230 259

8408240089 Notification of contract execution, Mod 11, to "Computer Time-Sharing & Related Svcs " Contractor NIH
BROMBERG, B Administrative Contracts Branch FIN B-1666
NRC-25-82-312 84/08/17 BASSETT, H S , SHIELDS, J Office of Resource Management, Director 1p 26255 325

--8408240094 Mod 11, adding funding to "Computer Time-Sharing & Related Svcs "
* HHS, Dept of, U S Public Health Service HAGAN, T F Division of Contracts FIN B-1666 NRC-25-82-312 84/08/17 1p 26255 326

8408270497 Notification of contract execution "Stenographic Reporting Svcs Throughout Contiguous US Excluding Washington, DC Metropolitan Area," awarded to Ace-Federal Reporters, Inc
DAVIS, K Administrative Contracts Branch FIN B-8183
NRC-21-84-352 84/08/06 COTTER, B P Atomic Safety and Licensing Board Panel LEINS, E , MORAN, D NRC - No Detailed Affiliation Given 1p 26277 066

--8408270503 Contract "Stenographic Reporting Svcs Throughout Contiguous US Excluding Washington, DC Metropolitan Area," awarded to Ace-Federal Reporters, Inc
* ACE Federal Reporters, Inc MATTIA, M J Division of Contracts FIN B-8183 NRC-21-84-352 84/08/06 1p 26277 067

--8408270508 Solicitation, offer & award of "Stenographic Reporting Svcs Throughout Contiguous US Excluding Washington, DC Metropolitan Area," to Ace-Federal Reporters, Inc
MONICK, R J ACE Federal Reporters, Inc * Division of Contracts FIN B-8183 NRC-21-84-352 84/06/29 130pp 26277 068

8408270547 Notification of contract execution, Mod 12, to "Memphis Area Regional Seismic Network - New Madrid " Contractor Memphis State Univ
PAGE, M Technical Assistance Contracts Branch FIN B-6276
NRC-04-78-200 84/08/20 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given 1p 26277 033

--8408270552 Mod 12, revising statement of work to add cooperative effort w/Univ of Kentucky, to "Memphis Area Regional Seismic Network - New Madrid "
CARPENTER, T G Memphis State Univ , Memphis, TN SMITH, P A Division of Contracts FIN B-6276 NRC-04-78-200 84/08/20 4pp 26277 034

8408270557 Notification of contract execution, Mod 13, to "In-Process Control of SNM " Contractor Science Applications, Inc
WOLLEFT, S Technical Assistance Contracts Branch FIN B-7315-4
NRC-02-81-040 84/08/13 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director MILLER, M NRC - No Detailed Affiliation Given 1p 26277 266

--8408270558 Mod 13, revising period of performance to end 840815 in lieu of 841031 & providing for decrease to scope of work to reflect shortened performance period, to "In-Process Control of SNM "
MCDONALD, R Science Applications, Inc SMITH, P A Division of Contracts FIN B-7315-4 NRC-02-81-040 84/08/13 2pp 26277 267

8408270574 Notification of contract execution, Mod 8, to "Maint of Data General Computers & Peripheral " Contractor Data Consultants, Inc
HAWKINS, D A Administrative Contracts Branch FIN B-1663
NRC-25-82-311 84/07/30 BASSETT, H Division of Data Automation & Management Information JOHNSON, C NRC - No Detailed Affiliation Given 1p 26258 361

--8408270576 Mod 8, extending period of performance from 840526 to 840613 at no cost, to "Maint of Data General Computers & Peripheral "
BONNIES, G Data Consultants, Inc HOGAN, T F Administrative Contracts Branch FIN B-1663 NRC-25-82-311 84/07/30 1p 26258 362

8408270581 Notification of contract execution, Mod 3, to 'Consulting Svcs of E Rodabaugh to Investigate Nozzle Load Design Limits, Overall Design Margins & Loading Rate Effects " Contractor EC Rodabaugh Assoc, Inc
PAGE, M Technical Assistance Contracts Branch FIN B-8690 NRC-03-84-071 84/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director SULLIVAN, E NRC - No Detailed Affiliation Given 1p 26258 357

--8408270582 Mod 3, revising statement of work for contractor participation on pipelock review panel, to "Consulting Svcs of Rodabaugh to Investigate Nozzle Load Design Limits, Overall Design Margins & Loading Rate Effects "
RODABAUGH, E C E C Rodabaugh Associates, Inc SMITH, P A Division of Contracts FIN B-8690 NRC-03-84-071 84/08/20 7pp 26258 358

8408290347 Notification of contract execution, Mod 2, to "Processing & Packaging Documents for Transmittal to LPDRs " Contractor Maxima Corp
HANKINS, D A Administrative Contracts Branch NRC-10-84-247 84/08/14 FELTON, J M Division of Rules and Records SOUDER, J NRC - No Detailed Affiliation Given 1p 26311 296

--8408290349 Mod 2, revising contract to incorporate administrative corrections & computer costs, to "Processing & Packaging Documents for Transmittal to LPDRs "
ZUTOVSKY, L E Maxima Corp HILL, D Small Business Administration HAGAN, T F Division of Contracts NRC-10-84-247 84/08/14 3pp 26311 297

8408300233 Notification of contract execution, Mod 2, to "Clinical Response to Chronic Stress in TMI " Contractor Uniformed Svcs Univ of Health Sciences
HOYLE, A Administrative Contracts Branch FIN B-8008 NRC-03-81-135 84/08/14 VOLLMER, R H Division of Engineering CLEARY, D P NRC - No Detailed Affiliation Given 1p 26315 361 24X Fiche 50-289, 84/08/14, 8408300233

--8408300237 Mod 2, extending period of performance to 840915, to "Clinical Response to Chronic Stress in TMI "
BAUM, A Uniformed Services Univ of Health Sciences HAGAN, T F Division of Contracts FIN B-8008 NRC-03-81-135 84/08/14 1p 26315 362 24X Fiche 50-289, 84/08/14, 8408300233

8408310082 Notification of contract execution, Mod 1 to "Career Counseling for NRC Participants in Region IV " Contractor RB Clark
MURPHY, L G Administrative Contracts Branch NRC-10-83-721 84/08/23 GOLDMAN, P J Management Development & Training Staff VAN SANTEN, L NRC - No Detailed Affiliation Given 1p 26352 038

--8408310088 Mod 1, extending period of performance to 850630 & increasing monetary amount, to "Career Counseling for NRC Participants in Region IV "
CLARK, R Clark, R B HAGAN, T F Division of Contracts NRC-10-83-721 84/08/23 2pp 26352 039

8408310232 Requests that completion date for Contract NRC-05-83-215, "Insp Model for Environ Qualification of Electrical Equipment," be extended from Aug 1984 to Feb 1985
POTAPOVS, U Vendor Program Branch 84/08/29 LAUDAN, W Engineering & Generic Communications Branch 2pp 26320 326

8408310260 Notification of contract execution, Mod 5, to "Assay of Long-Lived Radionuclides in Low Level Wastes From Power Reactors " Contractor Science Applications, Inc
PAGE, M Technical Assistance Contracts Branch FIN B-7356-4 NRC-02-82-043 84/08/16 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director JOHNSON, T NRC - No Detailed Affiliation Given 1p 26350 282

--8408310262 Mod 5, extending period of performance until 841031 & providing addl funds, to "Assay of Long-Lived Radionuclides in Low Level Wastes From Power Reactors "
ARCHER, C D Science Applications, Inc SMITH, P A Division of Contracts FIN B-7356-4 NRC-02-82-043 84/08/16 2pp 26350 283

8408310363 Notification of contract execution, Mod 1, to "Regional Economic Impacts of Accidents " Contractor Dept of Commerce
PAGE, M Technical Assistance Contracts Branch FIN B-8678 NRC-03-84-065 84/08/23 VOLLMER, R H Division of Engineering RICHTER, B NRC - No Detailed Affiliation Given 1p 26350 330

--8408310368 Mod 1, revising completion date for Task 6 at no addl cost, to "Regional Economic Impacts of Accidents "
TROTT, E A Commerce, Dept of, SMITH, P A Division of Contracts FIN B-8678 NRC-03-84-065 84/08/23 2pp 26350 331

8408310385 Notification of contract execution, Mod 4, to "Panel Member & Documentation Review for Selected Meetings of Peer Review Group " Contractor AB Reynolds
TOWNSEND, B L Administrative Contracts Branch FIN B-8985 NRC-04-83-010 84/08/27 BASSETT, D E Division of Accident Evaluation JANKOWSKI, M W , MEYERS, R NRC - No Detailed Affiliation Given 1p 26350 275

--8408310390 Mod 4, extending period of performance until 840501, to "Panel Member & Documentation Review for Selected Meetings of Peer Review Group "
& Virginia, Univ of, Charlottesville, VA HALMAN, E L Division of Contracts FIN B-8985 NRC-04-83-010 84/08/27 1p 26350 276

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

8407120136 Appeals denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similar environ documents & FOIA fee waiver decision
RYAN, J A Streich, Lang, Weeks & Cardon 84/03/27 Office of the Executive Director for Operations 4pp 25557 018 24X Fiche 50-528, 84/03/27, 8407120136

8407120142 Responds to appeal re denial of FOIA request for 27 documents referenced in 1975 EIS re facility & all EIS, supplemental EIS or similar environ documents Appeal granted
DIRCKS, W J Office of the Executive Director for Operations 84/05/21 RYAN, J A Streich, Lang, Weeks & Cardon 1p 25557 022 24X Fiche 50-528, 84/05/21, 8407120142

8407130037 Further response to FOIA request for numerous categories of records re issues discussed in IE Info Notices 81-29, 83-52, 83-57 & 83-72 & Board Notifications 83-128 & 83-128A Forwards Apps C & D documents Search continuing
FELTON, J M Division of Rules and Records 84/04/13 JORDAN, W S Harmon & Weiss 7pp 25584 078 24X Fiche 50-000, 84/04/13, 8407130037

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records DX14 000 84/07/18 RICE, C M Kirkland & Ellis 2pp 26500 001 24X Fiche 50-329, 84/07/18, 8408010061

--8408020188 Responds to Mooney concept theory re SRP 2 5 4 & FSAR review Suggestion to OELD re Mooney testimony encl
HOOD, D NRC - No Detailed Affiliation Given DX17 027 83/11/22 HASSEL, D M NRC - No Detailed Affiliation Given 4pp 26519 193 24X Fiche 50-329, 84/07/18, 8408010061

--7812070142 Discusses IE Insp Repts 50-329/78-12 & 50-330/78-12 Contributing factors to settlements of diesel generator bldg foundation & generator pedestals include variable properties of random fill matl supporting structure & cooling pond
KEPPLER, J G Region 3, Chicago, Office of the Director DX16 001 78/11/01 THORNBURG, H D Division of Reactor Construction Inspection 2pp 26506 211 24X Fiche 50-329, 84/07/18, 8408010061

--7909290119 Forwards outline history of geotechnical engineering problems re plant fill Lists pertinent FSAR & FSAR criteria & summarizes foundation conditions & remedial measures for all Category I structures founded on plant fill
GILLEN, D M Geosciences Branch DX16 015 79/08/28 JACKSON, R E Geosciences Branch 10pp 26510 309 24X Fiche 50-329, 84/07/18, 8408010061

--8004040738 Summary of 800227 & 28 meeting & site visit w/util in Midland, MI re soil settlement problems & related investigation program
GONZALES, R O Hydrology Meteorology Branch DX16 032 80/03/10 BIVINS, W S Hydrology Meteorology Branch 9pp 26511 119 24X Fiche 50-329, 84/07/18, 8408010061

--8008130764 Summarizes status of seismological input parameters re geosciences & geotechnical review of facilities as discussed at 800702 & 22 meetings
KIMBALL, J Geosciences Branch DX16 029 80/08/07 JACKSON, R E Geosciences Branch 6pp 26511 095 24X Fiche 50-329, 84/07/18, 8408010061

--8010160005 Submits questions in response to request for interrogatory input re hearing
LEAR, G E Hydrologic & Geotechnical Engineering Branch DX17 013 80/10/06 MIRAGLIA, F Licensing Branch 3 2pp 26518 144 24X Fiche 50-329, 84/07/18, 8408010061

--8011240409 Forwards Hydrologic Engineering Section interrogatories re permanent dewatering sys at facilities
LEAR, G E Hydrologic & Geotechnical Engineering Branch BX17 008
80/11/10 TEDESCO, R L Assistant Director for Licensing 3pp
26517 244 24X Fiche 50-329, 84/07/18, 8408010061

--8104230479 Submits comments on applicant response to NRC Interrogatories 1-3 No results available for review of Interrogatories 1 & 2 since no consolidation tests on samples were obtained from surcharged area of plant fill
MCCALLISTER, P Army, Dept of, Corps of Engineers BX17 014
81/03/27 LEAR, G Hydrologic & Geotechnical Engineering Branch
2pp 26518 150 24X Fiche 50-329, 84/07/18, 8408010061

--8105070480 Responds to request re Geosciences Branch estimate of time required to complete site review Approx 30 days are needed to review addl info requested for Part 1 & 3 months are needed for review of Part 2 submittal
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) BX16 057B 81/04/24 PATON, W D Office of the Executive Legal Director 1p 26513 189 24X
Fiche 50-329, 84/07/18, 8408010061

--8110190801 Forwards topic discussions for inclusion in 1981 annual rept, per 810902 commitment Discussions of technical assistance program for licensing, GETR review & Midland remedial repair info encl
HELLER, L W Hydrologic & Geotechnical Engineering Branch BX16 033 81/09/16 LEAR, G Hydrologic & Geotechnical Engineering Branch 6pp 26512 253 24X Fiche 50-329, 84/07/18, 8408010061

--8110260082 Informs that licensee taking position that IEEE 279 jurisdiction starts w/transmitter Jurisdiction should start at sensing line connection to process piping
HENDERSON, J B Reactor Projects Sections (Regions 1 & 3) BX19 024 81/10/01 WILLIAMS, C C Plant Systems Section 1p
26533 050 24X Fiche 50-329, 84/07/18, 8408010061

--8111240064 Informs of 811016 conference call w/util to discuss revised schedule for soils hearing requests revision to better accommodate const schedule Agreed schedule for hearings will be 811201-04 & 1214-18
HOOD, D Licensing Branch 4 BX19 036B 81/10/30 TEDESCO, R L Assistant Director for Licensing 3pp 26535 252 24X
Fiche 50-329, 84/07/18, 8408010061

--8201050063 Summarizes 811207 telcon re 820105 soils hearing
HOOD, D Licensing Branch 4 BX18 032 81/12/14 ADENSAM, E G Licensing Branch 4 2pp 26526 099 24X Fiche 50-329, 84/07/18, 8408010061

--8201220049 Advises of 1-month delay in meeting R Tedesco 811214 schedule in support of facility hearing & review Viable schedule must recognize need for iteration w/applicant following each significant submittal
VOLLMER, R H Division of Engineering BX16 074 81/12/28
EISENHUT, D G Division of Licensing 3pp 26514 188 24X
Fiche 50-329, 84/07/18, 8408010061

--8202040352 Informs that certain SER sections, especially soil remedial actions, will not be complete by 820406 deadline
ADENSAM, E G Licensing Branch 4 BX16 055 82/01/19
EISENHUT, D G Division of Licensing 3pp 26512 266 24X
Fiche 50-329, 84/07/18, 8408010061

--8203020050 Summary of 811006-07 meeting w/util, Bechtel & consultants in Bethesda, MD re underground piping in inadequately compact plant fill
HOOD, D S Licensing Branch 4 BX21 002 OM 82/02/05
DENTON, H R NRC - No Detailed Affiliation Given 37pp
26549 084 24X Fiche 50-329, 84/07/18, 8408010061

--8205050209 Forwards listing of issues to be resolved prior to start of Phase 2 underpinning operations for auxiliary bldg
LEAR, G Hydrologic & Geotechnical Engineering Branch BX16 035
82/04/28 ADENSAM, E Licensing Branch 4 2pp 26511 200 24X
Fiche 50-329, 84/07/18, 8408010061

--8205120033 Summarizes technical comments from ACRS subcommittee 820429 meeting re remedial activities for deficient soils
ADENSAM, E G Licensing Branch 4 BX18 035 82/05/04 BOSNAK, R
NRC - No Detailed Affiliation Given 4pp 26527 183 24X
Fiche 50-329, 84/07/18, 8408010061

--8205210467 Notifies that util submittal re Phase 2 of underpinning repair work at facility acceptable, provided that encl mods & requirements are incorporated into Phase 2 program
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) BX16 039 82/05/10 TEDESCO, R L Assistant Director for Licensing 34pp 26511 203 24X
Fiche 50-329, 84/07/18, 8408010061

--8205240603 Advises that ad hoc ACRS subcommittee recommendations re foundation problems & related remedial actions at facilities acceptable, per 820429 & 0506-08 meetings Discussion of seismic-related issues tentatively scheduled for 820520-21
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards BX14 003 11879 82/05/14 DIRCKS, W J Office of the Executive Director for Operations 1p 26500 027 24X
Fiche 50-329, 84/07/18, 8408010061

--8206020051 Comments on draft of acceptance provisions for Phase 2 Final transmittal to applicant should move through DE for concurrence
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) BX16 036 82/05/13 KANE, J Assistant Director for Comp & Structures Engineering (Pre 830201) 1p 26511 202
24X Fiche 50-329, 84/07/18, 8408010061

--8206060008 Summarizes 266th ACRS meeting on 820603-05 Subj to satisfactorily completion of const & staffing & if due regard given to ACRS comments, plant can operate at 5% power w/o undue risk to public Full power recommendation deferred
SHEWMON, P ACRS - Advisory Committee on Reactor Safeguards BX14 004 82/06/08 PALLADINO, N Commissioners 6pp 26500 028
24X Fiche 50-329, 84/07/18, 8408010061

--8206240401 Forwards comments on 820422 response to NRC request for addl info re borated water storage tank & underpinning of svc water pump structure Contact w/applicant to resolve differences recommended
LEAR, G Hydrologic & Geotechnical Engineering Branch 82/06/16
ADENSAM, E Licensing Branch 4 105pp 66129 031 24X
Fiche 50-329, 84/07/18, 8408010061

--8206290161 Submits proposed schedule for facility soils review
ADENSAM, E G Licensing Branch 4 BX18 036 82/06/25
EISENHUT, D G Division of Licensing 2pp 26527 187 24X
Fiche 50-329, 84/07/18, 8408010061

--8207140330 Forwards request for addl info from Structural Engineering Branch re applicant proposed remedial actions
SCHAUER, F P Structural Engineering Branch BX19 029 82/06/15
ADENSAM, E Licensing Branch 4 5pp 26533 206 24X
Fiche 50-329, 84/07/18, 8408010061

--8209230536 Forwards discussion of deficiencies noted in Supplemental SER 2 Requests mod to attached draft be provided addressing concerns
NOVAK, T M Assistant Director for Licensing BX18 040 82/08/27
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 3pp 26527 243 24X Fiche 50-329, 84/07/18, 8408010061

--8210130322 Forwards info re location of data on underpinning dimensions & load transfer procedures
POULOS, S J Geotechnical Engineers, Inc BX16 060 81907-17
82/10/07 KANE, J Division of Engineering 6pp 26513 234 24X
Fiche 50-329, 84/07/18, 8408010061

--8210150698 Clarifies NRC/util interaction re OL review Maint of proper control by licensing property managers necessary to manage licensing activities properly Reviewers requested to follow guidelines
ADENSAM, E G Licensing Branch 4 BX16 070 82/09/29
TOMLINSON, E NRC - No Detailed Affiliation Given 2pp
26514 109 24X Fiche 50-329, 84/07/18, 8408010061

--8210270126 Forwards input for testimony for 821027-1104 ASLB hearings Stamiris Contention 4 C b re dewatering & svc water pump structure should be addressed by Structural Engineering Branch
LEAR, G Hydrologic & Geotechnical Engineering Branch BX17 018
82/10/15 ADENSAM, E Licensing Branch 4 4pp 26519 005 24X
Fiche 50-329, 84/07/18, 8408010061

--8211030222 Forwards Hydrological & Geotechnical Engineering Branch input for testimony at ASLB 821027-1104 hearings re bearing capacity beneath diesel generator bldg, piping svc water pump structure & permanent dewatering
LEAR, G Hydrologic & Geotechnical Engineering Branch BX17 017
82/10/14 ADENSAM, E G Licensing Branch 4 9pp 26518 358 24X
Fiche 50-329, 84/07/18, 8408010061

--8301190487 Assigns NRC sponsors for each of M Sinclair rewritten contentions for OL hearing Schedule for filing of testimony forthcoming
HOOD, D S Licensing Branch 4 BX17 024 83/01/14 NOVAK, T M
Assistant Director for Licensing 1p 26519 072 24X
Fiche 50-329, 84/07/18, 8408010061

--8305270222 Forwards trip rept of 830510-13 site visit re underpinning contract Other topics discussed include cracks in svc water pump structure heave over freeze wall need to stop laying back soil along underpinning drifts & settlements
POULOS, S J Geotechnical Engineers, Inc BX18 022 81907-23 83/05/23 KANE, J Division of Engineering 19pp 26524 317 24X Fiche 50-329, 84/07/18, 8408010061

--8306060387 Trip rept of 830511 & 12 site visits to view pier load test installation & results
KANE, J D Structural & Geotechnical Engineering Branch BX18 021 TAC 9134 83/05/27 LEAR, G Structural & Geotechnical Engineering Branch 2pp 26524 315 24X Fiche 50-329, 84/07/18, 8408010061

--8307130423 Forwards paper entitled "Use of Site Dependent Spectra" to be presented at workshop on "Site-Specific Effects of Soil & Rock on Ground Motion & Implications for Earthquauake-Resistant Design" on 830726-28
KIMBALL, J Geosciences Branch BX17 039 83/06/27 JACKSON, R E Geosciences Branch 1p 26520 069 24X Fiche 50-329, 84/07/18, 8408010061

--8307130425 Speech entitled "Use of Site Dependent Spectra," to be presented at 830726-28 workshop on "Site-Specific Effects of Soil & Rock on Ground Motion & Implications for Earthquake-Resistant Design" in Santa Fe, NM
KIMBALL, J Geosciences Branch BX17 040 83/06/27 25pp 26520 070 24X Fiche 50-329, 84/07/18, 8408010061

--8309130017 Discusses IE insp on 821012-1125 & 830119-21 & forwards order imposing civil monetary penalties in amount of $120,000 for violation re breakdown in implementation of QA program per 10CFR50, App B
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement BX21 018 EA-83-003 83/08/29 SELBY, J D Consumers Power Co 3pp 26554 045 24X Fiche 50-329, 84/07/18, 8408010061

--8309270366 Responds to 830523 & 0810 requests for assistance in reviewing util proposed findings of fact & conclusions of law on remedial soils issues Agrees w/Findings Recommends paragraph re occurence of liquefaction be revised
BALLARD, R L Environmental & Hydrologic Engineering Branch BX17 037 83/09/14 PATON, W D Office of the Executive Legal Director 2pp 26520 062 24X Fiche 50-329, 84/07/18, 8408010061

--8310050136 Discusses structural engineering review of "Applicants Proposed Findings of Facts & Conclusions of Law on Remedial Soil Issues" along w/related info on seismic models & borated water storage tanks resulting from ASLB hearings
LEAR, G Structural & Geotechnical Engineering Branch BX17 035 83/09/22 PATON, W Office of the Executive Legal Director 5pp 26520 051 24X Fiche 50-329, 84/07/18, 8408010061

--8310070101 Forwards comments on applicant proposed findings of fact & conclusions of law on remedial soil issues
LEAR, G Structural & Geotechnical Engineering Branch BX17 035A 83/09/29 PATON, W Office of the Executive Legal Director 4pp 26520 052 24X Fiche 50-329, 84/07/18, 8408010061

--8310070262 Forwards second phase of Geotechnical Engineering input on findings of fact & conclusions of law in response to OELD request Several areas of significant differences exist re diesel generator bldg
LEAR, G Structural & Geotechnical Engineering Branch BX17 032 83/09/30 PATON, W D Office of the Executive Legal Director 6pp 26519 246 24X Fiche 50-329, 84/07/18, 8408010061

--8310240291 Informs that structural review of document "Applicant Proposed Findings of Facts & Conclusions of Law on Remedial Soil Issues," completed Structures adequate Comments encl
LEAR, G Structural & Geotechnical Engineering Branch BX17 036 83/10/14 PATON, W Office of the Executive Legal Director. 5pp 26520 056 24X Fiche 50-329, 84/07/18, 8408010061

--8312080185 Forwards technical evaluation of HVAC structural design adequacy, based on findings of Mechanical Engineering Branch design review & audit
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) BX18 051 TAC 52311 83/11/25 NOVAK, T M Assistant Director for Licensing 27pp 26528 206 24X Fiche 50-329, 84/07/18, 8408010061

--8312120393 Requests requisite info re followup action to be taken by Region III to 831108 recommendation for board notification
EISENHUT, D G Division of Licensing BX21 014 DM 83/11/30 WARNICK, R F Region 3, Office of Director 1p 26553 204 24X Fiche 50-329, 84/07/18, 8408010061

--8406020280 Trip rept on 840504 site visit to participate in public meeting on mgt appraisal program to be performed on util Comments on independent mgt appraisal encl
MCLAUGHLIN, P Licensee Qualifications Branch BX20 010 84/05/22 BOOHER, H R Licensee Qualifications Branch 5pp 26539 045 24X Fiche 50-329, 84/07/18, 8408010061

--8408010132 Forwards TERA Corp 830815 ltr describing four conceptual options for independent quality verification program methodologies Option 1 integral part of IDCVP at Midland
FISCHER, D ACRS - Advisory Committee on Reactor Safeguards BX14 001 83/11/15 ACRS - Advisory Committee on Reactor Safeguards 2pp 26500 012 24X Fiche 50-329, 84/07/18, 8408010061

--8408010135 Forwards QA/QC project status rept presented at ACRS 274th meeting on 830210
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards BX14 002 83/03/03 ACRS - Advisory Committee on Reactor Safeguards 6pp 26500 021 24X Fiche 50-329, 84/07/18, 8408010061

--8408010143 Forwards summary & conclusion of overall effectiveness portion of Region III rept on design & const problems Lack of aggressive QA attitude & overreliance on AE contribute to QA problems
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards BX14 005 82/12/09 ACRS - Advisory Committee on Reactor Safeguards 4pp 26500 034 24X Fiche 50-329, 84/07/18, 8408010061

--8408010147 Forwards JW Cook 810430 ltr & executive summary re QA program update, per 830215 request
SOMMERS, D A Consumers Power Co BX14 006 DAS 9-83 83/02/16 FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards 1p 26500 038 24X Fiche 50-329, 84/07/18, 8408010061

--8408010149 Forwards executive summary re QA program update, per 810331 meeting commitment & NRC 810402 ltr Apps will be transmitted by 810522
COOK, J W Consumers Power Co BX14 007 11980 81/04/30 KEPPLER, J G Region 3, Chicago, Office of the Director (81/03/01) 19pp 26500 039 24X Fiche 50-329, 84/07/18, 8408010061

--8408010152 Forwards status rept re QA/QC activities at facility to be presented at ACRS 274th meeting on 830210
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards BX14 008 83/02/07 ACRS - Advisory Committee on Reactor Safeguards 7pp 26500 058 24X Fiche 50-329, 84/07/18, 8408010061

--8408010153 Discusses major reduction in safety-related work at Midland ACRS comments to NJ Palladino encl
FISCHER, D ACRS - Advisory Committee on Reactor Safeguards BX14 009 82/12/09 ACRS - Advisory Committee on Reactor Safeguards 3pp 26500 065 24X Fiche 50-329, 84/07/18, 8408010061

--8408010160 Forwards interim 10CFR50 55(e) rept re QA program & mfg deficiencies affecting radiation monitoring equipment supplied by Victoreen, Inc
FISCHER, D ACRS - Advisory Committee on Reactor Safeguards BX14 011 82/11/15 OKRENT, D ACRS - Advisory Committee on Reactor Safeguards 1p 26500 072 24X Fiche 50-329, 84/07/18, 8408010061

--8408010163 Forwards cost estimate for once through steam generator overfill protection mod, per request
DREHOBL, K E Consumers Power Co BX14 012 18457 82/08/17 FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards 2pp 26500 073 24X Fiche 50-329, 84/07/18, 8408010061

--8408010168 Forwards SSER 1, addressing ACRS recommendations contained in 820608 interim rept Operating license review project status repts for 820520-21 & 0602 encl W/o SSER
FISCHER, D ACRS - Advisory Committee on Reactor Safeguards BX14 013 82/07/19 OKRENT, D ACRS - Advisory Committee on Reactor Safeguards 12pp 26500 075 24X Fiche 50-329, 84/07/18, 8408010061

--8408010173 Discusses util approach for satisfying safety review requirements at Big Rock Point, Palisades & Midland Summary of 820504 meeting & viewgraphs encl
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards BX14 014 82/05/17 ACRS - Advisory Committee on Reactor Safeguards 45pp 26500 087 24X Fiche 50-329, 84/07/18, 8408010061

--8408010178 Forwards summary of ad hoc Subcommittee on Midland Units 1 & 2 820429 meeting Related info encl
FISCHER, D ACRS - Advisory Committee on Reactor Safeguards BX14 016 82/05/06 SIESS, C ACRS - Advisory Committee on Reactor Safeguards 32pp 26500 133 24X Fiche 50-329, 84/07/18, 8408010061

--8408010183 Discusses acceptability of Midland reactor pressure vessel anchor bolts, per util Bll123 ltr ? attached rept Expresses concern re rept sufficiency
SHEWMON, P G ACRS - Advisory Committee on Reactor Safeguards BX14 017 82/02/03 VOLLMER, R H Division of Engineering 1p 26500 173 24X Fiche 50-329, 84/07/18, 8408010061

--8408010188 Forwards util 800522 ltr identifying one of many QA problems at facility Incident re fill matl under vital structures noted in P Tam 800516 ltr Incidents should be considered in evaluation of need for subcommittee meeting
YOUNG, G G ACRS - Advisory Committee on Reactor Safeguards BX14 018 80/06/03 SHEWMON, P ACRS - Advisory Committee on Reactor Safeguards 1p 26500 174 24X Fiche 50-329, 84/07/18, 8408010061

--8408010191 Summary of 800523 meeting w/util in Bethesda, MD re reactor vessel holddown stud failures at facility
YOUNG, G G ACRS - Advisory Committee on Reactor Safeguards BX14 019 80/05/28 SHEWMON, P ACRS - Advisory Committee on Reactor Safeguards 3pp 26500 184 24X Fiche 50-329, 84/07/18, 8408010061

--8408010195 Recommends review of foundation problems at facility Poor quality fill matl used under containment & other vital structures
TAM, P ACRS - Advisory Committee on Reactor Safeguards BX14 020 80/05/16 SHEWMON, P ACRS - Advisory Committee on Reactor Safeguards 1p 26500 187 24X Fiche 50-329, 84/07/18, 8408010061

--8408010198 Advises that unresolved safety issue exists in poor quality of fill matl under containment & other vital structures as evidenced by diesel generator bldg settlement
MCKINLEY, J C ACRS - Advisory Committee on Reactor Safeguards BX14 021 80/05/09 TAM, P ACRS - Advisory Committee on Reactor Safeguards 1p 26500 201 24X Fiche 50-329, 84/07/18, 8408010061

--8408010202 Forwards portions of FSAR for review of soil/foundation problems Site visit & subcommittee meeting will be arranged
MCKINLEY, J C ACRS - Advisory Committee on Reactor Safeguards BX14 022 80/03/21 OSTERBERG, J O Northwestern Univ, Evanston, IL 1p 26500 202 24X Fiche 50-329, 84/07/18, 8408010061

--8408010204 Discusses facility safe shutdown boration capability B&W Water Reactors Subcommittee review to explore proposed fixes suggested
MULLER, R ACRS - Advisory Committee on Reactor Safeguards BX14 023 79/11/14 ETHERINGTON, H ACRS - Advisory Committee on Reactor Safeguards 1p 26500 207 24X Fiche 50-329, 84/07/18, 8408010061

--8408010206 Summary of 790718 meeting w/util onsite re abnormal settlement of fill & structures Agenda & viewgraphs encl
ZUMWR, D J ACRS - Advisory Committee on Reactor Safeguards BX14 024 79/07/31 ACRS - Advisory Committee on Reactor Safeguards 78pp 26500 210 24X Fiche 50-329, 84/07/18, 8408010061

--8408020038 Lists questions asked of util during FSAR & 10CFR50 54(f) review, including questions re geological & seismological matters & intake & discharge structures for svc water sys
KANE, J NRC - No Detailed Affiliation Given BX17 001 84/07/18 19pp 26514 273 24X Fiche 50-329, 84/07/18, 8408010061

--8408020043 Lists questions & responses re condition of soils onsite, correction to foundation problems & risk in allowing const to continue.
* NRC - No Detailed Affiliation Given BX17 002 79/03/05 15pp 26514 322 24X Fiche 50-329, 84/07/18, 8408010061

--8408020071 Forwards draft answers to util interrogatories re definition of acceptance criteria of 791206 order on mod Opinion as to whether items in brackets should be deleted requested
KANE, J NRC - No Detailed Affiliation Given BX17 006 81/02/24 HOOD, D NRC - No Detailed Affiliation Given 1p 26515 058 24X Fiche 50-329, 84/07/18, 8408010061

--8408020074 Draft answers to util interrogatories re definition of acceptance criteria on Page 3 of 791206 order on mod
* NRC - No Detailed Affiliation Given BX17 006A DM 84/07/18 Consumers Power Co 87pp 26515 059 24X Fiche 50-329, 84/07/18, 8408010061

--8408020086 Marked-up copy of Rev 1, Vol 4 to FSAR re stability of subsurface matls & foundations, questions re response to Interrogatories 13-16 & interpretations of intent of Interogatory 13
KANE, J NRC - No Detailed Affiliation Given BX17 009 77/11/30 12pp 26517.309 24X Fiche 50-329, 84/07/18, 8408010061

--8408020099 Answers to util interrogatories re staff requests directed on determination ' justification of acceptance criteria applied to various remedial measures taken on page 3 of Order
KANE, J NRC - No Detailed Affiliation Given BX17 010 DM 84/07/18 Consumers Power Co 31pp 26517 331 24X Fiche 50-329, 84/07/18, 8408010061

--8408020107 Forwards motions, 1980 audit repts & input re upcoming util QA decision Applicant acceptance of poor quality performance by Bechtel criticized
STAMIRIS, B Stamiris, B BX17 011 81/05/26 KEPPLER, J G Region 3, Office of Director 2pp 26518 132 24X Fiche 50-329, 84/07/18, 8408010061

--8408020112 Question re discrepancy in magnitude of loading stress on Fig 2 of 800914 rept & info on Tables 4-1A & 2 5-14
* NRC - No Detailed Affiliation Given BX17 012 84/07/18 1p 26518 143 24X Fiche 50-329, 84/07/18, 8408010061

--8408020122 Provides trip rept for /81107 meeting in Urbana, IL re settlement of far east bay of diesel generator bldg List of correction action options provided
COOKE, T C Consumers Power Co BX17 015 CSC-3674 78/12/12 Consumers Power Co 4pp 26518 264 24X Fiche 50-329, 84/07/18, 8408010061

--8408020127 Summary of NRC recommendations of ASLB position re Stamiris Contention 2 including draft ASLB proposed findings & input into NRC testimony re Peck 790810 statement on electrical penetration area structures
KANE, J NRC - No Detailed Affiliation Given BX17 016 81/10/19 91pp 26518 268 24X Fiche 50-329, 84/07/18, 8408010061

--8408020171 Summarizes issues to be covered at ASLB 830214-18 hearing, including Stamiris contentions, Warren contention & seismic shakedown for all structures other than diesel generator bldg
* NRC - No Detailed Affiliation Given BX17 019 83/01/05 9pp 26519 009 24X Fiche 50-329, 84/07/18, 8408010061

--8408020177 Suggests schedule for testimony to answer Warren Contentions 1-3, Stamiris Contention 4, Sinclair Contention 24 & Marhsall Contention 2 in Feb & Mar hearings Text of contentions encl Suggests inclusion of rebuttals to contentions
BLUME, M NRC - No Detailed Affiliation Given BX17 020 82/01/27 HOOD, D , KANE, J , RINALDI, F NRC - No Detailed Affiliation Given 7pp 26519 020 24X Fiche 50-329, 84/07/18, 8408010061

--8408020178 Testimony of DS Hood & J Kane re matl false statement identified in NRC 791206 mod order
HOOD, D S , KANE, J NRC - No Detailed Affiliation Given BX17 021 83/01/31 3pp 26519 027 24X Fiche 50-329, 84/07/18, 8408010061

--8408020180 Forwards input to staff testimony in preparation for ASLB 821115-23 hearings, in response to W Paton verbal request & M Wilcove request Structural Engineering Branch input applicable only to svc water pump structure
SCHAUER, F P Structural Engineering Branch BX17 022 82/10/22 ADENSAM, E G Licensing Branch 4 5pp 26519 050 24X Fiche 50-329, 84/07/18, 8408010061

--8408020181 Comments on applicant 840805 proposed findings of fact conclusions of law on remedial soils issues, including items re auxiliary bldg & svc water pump structure
POULOS, S J Geotechnical Engineers, Inc BX17 031 81907-29 83/09/23 KANE, J Division of Engineering 4pp 26519 242 24X Fiche 50-329, 84/07/18, 8408010061

--8408020182 Responds to M Wilcove verbal request Structural Engineering Branch area of concern identified by Judge Harbour applies only to consideration of structure-to-structure interaction Outstanding contentions encl
SCHAUER, F P Structural Engineering Branch BX17 023 OL 82/10/28 ADENSAM, E G Licensing Branch 4 7pp 26519 055 24X Fiche 50-329, 84/07/18, 8408010061

--8408020183 Forwards response to applicant proposed findings of fact & conclusions of law on remedial soil issues Pagination needed Findings will be filed 831115
PATON, W D Hearing Branch 2 BX17 033 83/11/11 KANE, J NRC - No Detailed Affiliation Given 1p 26519 315 24X Fiche 50-329, 84/07/18, 8408010061

--8408020184 Forwards marked-up input to staff testimony in preparation for ASLB 821027-1104 hearings re bearing capacity & underground piping, in response to verbal request of W Paton & M Wilcove Response to Stamiris contention encl
LEAR, G E Hydrologic & Geotechnical Engineering Branch BX17 023A 82/10/14 ADENSAM, E G Licensing Branch 4 10pp 26519 062 24X Fiche 50-329, 84/07/18, 8408010061

--8408020185 Responsive findings to applicant proposed findings of fact & conclusions of law on remedial soil issues
PATON,W D ; WILCOVE,M N Hearing Branch 2 BX17 034 OM
83/11/15 100pp 26519 316 24X Fiche 50-329,84/07/18,
8408010061

--8408020186 Response to R Landsman B30106 questions re B Stamiris Request 4(b) re excavation of deep "Q" duct bans in Freezewall Pit 4 & Tech Spec for static cone penetrometer
KANE,J NRC - No Detailed Affiliation Given BX17 026 83/01/06
2pp 26519 146 24X Fiche 50-329,84/07/18,8408010061

--8408020187 Forwards updated version of Stamiris contentions,including addl Stamiris examples for Contentions 1,2 & 3 & changed wording of Contention 4C NRC testimony must address encl additions & changes
BROWN,E M NRC - No Detailed Affiliation Given BX17 025
81/05/19 Consumers Power Co 19pp 26519 124 24X
Fiche 50-329,84/07/18,8408010061

--8408020189 Forwards applicant testimony re alleged violation of ASLB B20430 order for determination of cross-examination List of questions re excavations & fireline piping provided
WILCOVE,M N Hearing Branch 2 BX17 042 83/05/13 LANDSMAN,R ;
COOK,R ; HOOD,D NRC - No Detailed Affiliation Given 2pp
26520 116 24X Fiche 50-329,84/07/18,8408010061

--8408020190 IE Investigation Rept 3-82-061 on 830103-0330 No noncompliance noted Major areas investigated allegations that util violated ASLB B20430 order re NRC approval for excavating in remedial soils program Investigation closed
WEIL,C H ; PAWLICK,E T Region 3, Office of Director BX17 028
83/06/02 17pp 26519 178 24X Fiche 50-329,84/07/18,8408010061

--8408020192 Forwards applicant advance copy of meeting notes for B20727-30 design audit of soils remedial activities in Ann Arbor, MI Questions should be referred to J Kane
LEAR,G Hydrologic & Geotechnical Engineering Branch BX17 043
OL 82/09/17 ADENSAM,E Licensing Branch 4 22pp 26520 224
24X Fiche 50-329,84/07/18,8408010061

--8408020193 Informs that Structural Mechanics Assoc seismic margin review studies indicate soil layering profiles & soil properties differ from properties previously addressed
KANE,J Structural & Geotechnical Engineering Branch BX17 044
82/05/11 LEAR,G Structural & Geotechnical Engineering Branch
2pp 26520 247 24X Fiche 50-329,84/07/18,8408010061

--8408020194 IE Investigation Rept 3-82-061 on 830711-0808,No noncompliance noted Major areas investigated allegations that util violated ASLB B20430 order re NRC approval for excavating in remedial soils program Investigation reopened
WEIL,C H ; PAWLICK,E T Region 3, Office of Director WARD,W J
Office of Investigation BX17 029 83/09/12 20pp 26519 199
24X Fiche 50-329,84/07/18,8408010061

--8408020195 Summary of 840417 meeting w/TERA,Structural Mechanics Assoc (SMA) & util in Chicago,IL to discuss SMA seismic margins evaluation & potential applicability to disposition of outstanding civil/structural issues
RINALDI,F Structural & Geotechnical Engineering Branch BX17
045 84/07/18 LEAR,G Structural & Geotechnical Engineering
Branch 2pp 26520 249 24X Fiche 50-329,84/07/18,8408010061

--8408020196 Provides Supplemental Ofc of Investigation Rept 3-82-061 re util alleged violation of ASLB order
HAYES,B D Office of Investigation BX17 030 83/09/12
KEPPLER,J G Region 3, Office of Director 3pp 26519 221 24X
Fiche 50-329,84/07/18,8408010061

--8408020199 Forwards request for addl structural engineering info needed to continue OL review of NPP application as applicable to seismic margins review,svc water pump structure & diesel generator bldg
LEAR,G Structural & Geotechnical Engineering Branch BX17 046
84/05/03 ADENSAM Licensing Branch 4 5pp. 26521 042 24X
Fiche 50-329,84/07/18,8408010061

--8408020202 Discusses status of efforts re NRC Midland findings dve 831115 Requests meeting at earliest date
HOOD,D NRC - No Detailed Affiliation Given BX17 041. 83/09/23
PATON,W D ; WILCOVE,M N Hearing Branch 2 7pp 26520 095 24X
Fiche 50-329,84/07/18,8408010061

--8408030001 Handwritten notes & outline of conference call w/Bechtel & util re review of buried piping,monitoring program & future settlement
MEISENHEIMER,J NRC - No Detailed Affiliation Given BX17 047
81/12/15 6pp 26515.146 24X Fiche 50-329,84/07/18,8408010061

--8408030004 Summary of 811006-07 meeting w/util in Bethesda,MD re underground piping in inadequately compacted plant fill Meeting agenda,attendance list & const hydro test viewgraphs encl
HOOD,D S Licensing Branch 4 BX17 048 OM 82/02/05
Licensing Branch 4 36pp 26515 241 24X Fiche 50-329,84/07/18,
8408010061

--8408030009 Summary of 810721 meeting w/applicant in Bethesda,MD re summary of San Onofre meeting on confirmatory analysis of piping sys design Confirmatory analysis encl
HOOD,H Licensing Branch 3 BX17 049 81/08/19 Licensing
Branch 3 29pp 26515 277 24X Fiche 50-329,84/07/18,8408010061

--8408030013 Notification of 820416 meeting w/util in Bethesda,MD to discuss buried piping & related applicant 820316 submittal W/handwritten notes of 820407 conference call & outline of outstanding issues in geotechnical engineering area
HOOD,D S Licensing Branch 4 BX17 050 OM 82/04/13
ADENSAM,E G Licensing Branch 4 22pp 26515 306 24X
Fiche 50-329,84/07/18,8408010061

--8408030020 Handwritten notes on 810120 meeting re stress analysis for underground piping Outline of discussion topics for pipe stress analysis encl
KANE,J NRC - No Detailed Affiliation Given BX17 052 81/01/20
NRC - No Detailed Affiliation Given 18pp 26515 355 24X
Fiche 50-329,84/07/18,8408010061

--8408030028 Agenda for 820121-22 meeting to discuss underground piping concerns W/handwritten summary of 820107 conference call re underground piping & 820120 evaluation of sand settlement due to earthquake
KANE,J NRC - No Detailed Affiliation Given BX17 055 82/01/22
NRC - No Detailed Affiliation Given 23pp 26516 017 24X
Fiche 50-329,84/07/18,8408010061

--8408030042 Agenda for 811006 meeting w/Bechtel,util & Army Corps of Engineers to discuss underground piping reprofiling,proposed demonstration solution & 1981 measurement results
* NRC - No Detailed Affiliation Given BX17 058 81/10/06
Office of Nuclear Reactor Regulation, Director 11pp 26516 045
24X Fiche 50-329,84/07/18,8408010061

--8408030051 Handwritten notes re addl boring logs at buried diesel generator fuel oil storage tank location Calculation sheets & boring logs encl
MEISENHEIMER,J NRC - No Detailed Affiliation Given BX17 060
82/03/29 KANE,J NRC - No Detailed Affiliation Given 13pp
26516 057 24X Fiche 50-329,84/07/18,8408010061

--8408030056 Handwritten notes re 810120 meeting w/applicant on settlement of Category I underground piping
KANE,J NRC - No Detailed Affiliation Given BX17 061 81/02/09
CAPPUCCI,T NRC - No Detailed Affiliation Given 4pp
26516 070 24X Fiche 50-329,84/07/18,8408010061

--8408030058 Forwards evaluation of general acceptability of effects of settlement in several buried svc piping sys Rept partial response to FSAR Questions 16 through 20 & 34
KLEIN,B R Bechtel Corp BX17 062 80/08/01 CURTIS,L H
Bechtel Corp 7pp 26516 074 24X Fiche 50-329,84/07/18,
8408010061

--8408030064 Forwards analysis of buried piping background info,in support of proposed demonstration solution & in response to NRC concern re underground piping Addl engineering info encl
KEELEY,G S. Consumers Power Co BX17 063 15093 81/12/15
DENTON,H R Office of Nuclear Reactor Regulation, Director 76pp
26516 081 24X Fiche 50-329,84/07/18,8408010061

--8408030068 Forwards stress analysis of several underground pipe lines as profiled in Rev 6 of "Responses to NRC 10CFR50 54(f) Requests re Plant Fill" dtd 800401
BATES,J O Rockwell International Corp BX17 064
80ETEC-DRF-4220 80/10/01 BOSNAK,R J Mechanical Engineering
Branch 52pp 26516 162 24X Fiche 50-329,84/07/18,8408010061.

--8408130227 Contract for consulting svcs between util & Mgt Analysis Co, agreeing to perform technical svcs,including consulting & QA svcs Purchase requisition,internal memos & supporting documentation encl
COOK,J W Consumers Power Co BX15 001 82/01/15 350pp
26500 316 24X Fiche 50-329,84/07/18,8408010061

--8408130230 Discusses 830118 & 26 meetings in Glen Ellyn,IL re Region III insp of diesel generator bldg & independent design review program,respectively Midland project manager will attend 830126 public meeting
ADENSAM,E G Licensing Branch 4 BX15 002 83/01/05 NOVAK,T M,
Assistant Director for Licensing 19pp 26502 089 24X
Fiche 50-329,84/07/18,8408010061

--8408130234 Draft memo re issues of potential impact on Hearing Board considerations concerning QA program
KEPPLER,J G Region 3, Office of Director BX15 003 82/04/02
EISENHUT,D G Division of Licensing 7pp 26502 121 24X
Fiche 50-329,84/07/18,8408010061

--8408130241 Notification of 821207 mgt meeting w/Region III to discuss implementation of QA & IDVPs
HERNAN,R W Licensing Branch 4 BX15 004 82/11/01 NOVAK,T M
Assistant Director for Licensing 2pp 26502 131 24X
Fiche 50-329,84/07/18,8408010061

--8408130244 Forwards SALP 3 schedule Internal memos,handwritten in-process insp notices,program notes & supporting documentation encl
TAMBLING,T N Region 3, Office of Director BX15 005 82/11/01
Region 3, Office of Director 53pp 26502 133 24X
Fiche 50-329,84/07/18,8408010061

--8408130255 Forwards response to draft SALP rept Requests meeting w/ Keppler to review detailed contents of response Internal memos & handwritten notes encl
COOK,J W Consumers Power Co BX15 006 17485 82/05/17
KEPPLER,J G Region 3, Office of Director 91pp 26502 188 24X
Fiche 50-329,84/07/18,8408010061

--8408130269 "Const Project Evaluation of Consumers Power Co,Midland Energy Ctr Project,Units 1 & 2 (Observations) "
* Management Analysis Co BX15 007 83/01/31 160pp
26502 311 24X Fiche 50-329,84/07/18,8408010061

--8408130290 Forwards Mgt Analysis Co assessment of Midland QA program Rept endorses program W/o encl
COOK,J W Consumers Power Co BX15 008A 12715 81/06/01
KEPPLER,J G Region 3, Chicago, Office of the Director (81/03/01)
40pp 26503 178 24X Fiche 50-329,84/07/18,8408010061

--8408130301 Submits changes to be implemented prior to util resuming remedial soils work Draft list of noncompliances & deviations,handwritten notes & list of events since Jul 1981 hearings encl
WARNICK,R F Region 3, Office of Director BX15 010 82/09/20
KEPPLER,J G Region 3, Office of Director 70pp 26504 031 24X
Fiche 50-329,84/07/18,8408010061

--8408130306 "Biennial QA Audit of Midland Plant,Units 1 & 2 " Opening remarks of NRC 830208 meeting w/util & independent review encl
* Management Analysis Co BX15 011 83/03/01 75pp 26504 131
24X Fiche 50-329,84/07/18,8408010061

--8408130311 Notification of significant licensee 830315 meeting in Glen Ellyn,IL to present INPO findings
* Region 3, Office of Director BX15 012 83/03/09 Region 3, Office of Director 1p 26504 261 24X Fiche 50-329,84/07/18, 8408010061

--8408130315 Testimony of JG Keppler re QA problems at facility & corrective actions taken
KEPPLER,J G Region 3, Office of Director BX15 012A 84/07/18
25pp 26504 262 24X Fiche 50-329,84/07/18,8408010061

--8408130320 Forwards status rept for Midland Project for Jan 1983 W/o encl
WARNICK,R F Region 3, Office of Director BX15 013 83/02/14
KEPPLER,J G Region 3, Office of Director 1p 26504 293 24X
Fiche 50-329,84/07/18,8408010061

--8408130323 Forwards status rept for Jan 1983 Rept contains input from each member of insp site team of Ofc of Special Cases
COOK,R J Region 3, Office of Director BX15 014 83/02/10
SHAFER,W D Region 3, Office of Director 3pp 26504 294 24X
Fiche 50-329,84/07/18,8408010061

--8408130327 Forwards monthly status repts for Aug-Oct 1982
WARNICK,R F Region 3, Office of Director BX15 015 82/12/20
KEPPLER,J G Region 3, Office of Director 10pp 26504 303 24X
Fiche 50-329,84/07/18,8408010061

--8408130336 Requests approval not to perform SALP 3 assessments,due to widespread recognition of mgt,QA & const problems Draft notice of violation,insp rept & handwritten notes re diesel generator bldg monorail encl
KEPPLER,J G Region 3, Office of Director BX15 017 83/04/01
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 98pp 26505 043 24X Fiche 50-329,84/07/18, 8408010061

--8408130348 Submits issues to be addressed at forthcoming evidentiary session on QA & QC matters
PATON,W D Consumers Power Co BX15 019 82/08/10 ADENSAM,E G
NRC - No Detailed Affiliation Given 6pp 26505 276 24X
Fiche 50-329,84/07/18,8408010061

--8408130356 Forwards monthly status rept for Midland Project for Jan 1983
COOK,R J Region 3, Office of Director BX15 022 83/02/10
SHAFER,W D Region 3, Office of Director 3pp 26505 302 24X
Fiche 50-329,84/07/18,8408010061

--8408140039 Draft IE Insp Repts 50-329/78-20 & 50-330/78-20 from insp on 781211-20 & 790104-25 Violations noted inadequate control & supervision of plant fill matl placement & const specs not followed
PHILLIP,G A , GALLAGHER,E J , MAXWELL,G F Region 3, Office of Director BX16 002 50-330/78-20 84/07/18 60pp 26507 112
24X Fiche 50-329,84/07/18,8408010061

--8408140050 Summary of NRC 790607 site tour & meeting on differential settlement of plant bldgs TC Cooke 790706 ltr to Bechtel re stainless steel pipe deficiency encl
COOKE,T C Consumers Power Co BX16 003 CSC-4138 79/06/13
Consumers Power Co 4pp 26507 311 24X Fiche 50-329,84/07/18, 8408010061

--8408140055 Preliminary "Discussion of NRC Insp Facts Resulting From NRC Investigation of Diesel Generator Bldg Settlement "
* Consumers Power Co BX16 004 79/03/05 35pp 26507 315
24X Fiche 50-329,84/07/18,8408010061

--8408140060 Forwards synopsis of 800228 presentation, "Remedial Measures for Electrical Penetration Wings of Control Bldg & Isolation Valve Pits" conducted before NRC representatives in Midland, MI
GOULD,C H Affiliation Not Assigned BX16 005 80/03/17
AFIFI,S S Bechtel Corp 22pp 26507 350 24X
Fiche 50-329,84/07/18,8408010061

--8408140065 Forwards general procedures & details employed by contractor to underpin fine arts bldg Sketches encl
MARR,G Bechtel Corp BX16 006 79/04/25 AFIFI,S Bechtel Corp 6pp 26508 010 24X Fiche 50-329,84/07/18,8408010061

--8408140069 Lists areas to be clarified &/or amplified,in responses to 10CFR50 54(f) questions Summary of soils chronology & 790807 internal memo re pre-meeting w/consultants encl
COOKE,T C Consumers Power Co BX16 007 CSC-4763 80/01/25
ROTHWELL,M D Bechtel Corp 14pp 26508 016 24X
Fiche 50-329,84/07/18,8408010061

--8408140071 Submits const QC response to 790329 questions re diesel generator bldg No variance exists from QA program requirements
JOHNSON,D R Bechtel Corp BX16 008 2-CQC-402679 79/04/09
RICHARDSON,O L Bechtel Corp 9pp 26508 030 24X
Fiche 50-329,84/07/18,8408010061

--8408140076 Comments on recommendations given in soils repts prepared by Dames & Moore as compared to Bechtel earthwork specs Plant area fill supporting surrounding structures,Category I slopes & berm fill discussed
AFIFI,S S Bechtel Corp BX16 009 74/09/13 CASTLEBERRY,R
Bechtel Corp 5pp 26508 039 24X Fiche 50-329,84/07/18, 8408010061

--8408140079 Recommends issuance of revised TPO std specs re large settlement due to incorrectly placed backfill Addl correspondence on problem alert & summary of soils chronology encl
RUMBAUGH,E Bechtel Corp BX16 010 79/12/27 JOHNSON,T E
Bechtel Corp 33pp 26508 044 24X Fiche 50-329,84/07/18, 8408010061

--8408140102 Forwards complete set of all abstracts of transcripts of hearings conducted on 811231-830630 W/listing of entire set of abstracts
HAMPTON,L Isham, Lincoln & Beale BX16 012 83/07/18
PATON,W D Hearing Branch 2 425pp 26508 097 24X
Fiche 50-329,84/07/18,8408010061

--8408140134 Handwritten notes re borings in area of svc water piping that have indicated potential for liquefaction W/Dept of Army memo re Feb 1980 visit to util & review of FSAR
KANE,J NRC - No Detailed Affiliation Given BX16 014 82/10/14
19pp 26510 227 24X Fiche 50-329,84/07/18,8408010061

--8408140144 Testimony of HN Singh re unresolved geotechnical engineering safety issues, including reactor bldg foundation, diesel generator bldg settlement & svc water bldg foundation & borated water tanks
SINGH, H N Army, Dept of, Corps of Engineers BX16 016
84/07/18 13pp 26510 319 24X Fiche 50-329, 84/07/18, 8408010061

--8408140152 Handwritten notes on admission of facts re plant fill problem & cracking of certain safety-related structures resulting from inadequately compacted fill matls W/ handwritten notes re discussion w/B Paton on hearings
* NRC - No Detailed Affiliation Given BX16 017 81/03/06 2pp
26510 331 24X Fiche 50-329, 84/07/18, 8408010061

--8408140158 Notifies of plan to take depositions of Bechtel employees in Ann Arbor beginning on 801209 Depositions will address errors made in soil placement
PATON, W D Office of the Executive Legal Director BX16 018
80/11/19 OLMSTEAD, W J Regulations Division 2pp 26510 333
24X Fiche 50-329, 84/07/18, 8408010061

--8408140163 Presents reasons why Phase II const will not be detrimental to foundation support of auxiliary bldg Phase II primary consists of 3x6 ft hand dug piers & 7x6 ft wide access drifts for access to pier
KANE, J , BARTLETT, D NRC - No Detailed Affiliation Given BX16 019 82/01/19 11pp 26510 335 24X Fiche 50-329, 84/07/18, 8408010061

--8408140170 Handwritten notes re general description of extent of plant fill problem Proposed remedial measures, list of viewgraphs & viewgraphs for ACRS presentation encl
KANE, J NRC - No Detailed Affiliation Given BX16 020 82/04/26
37pp 26510 346 24X Fiche 50-329, 84/07/18, 8408010061

--8408140185 Confirms comments previously provided re Item E on Page 5 of 830715 ltr concerning slope layback during underpinning Item E expresses concern by S&W inspectors that slope layback is greater than in design
POULOS, S J Geotechnical Engineers, Inc BX16 022 810907-28
83/09/22 KANE, J Office of Nuclear Reactor Regulation, Director
2pp 26511 029 24X Fiche 50-329, 84/07/18, 8408010061

--8408140196 Summarizes comments re 830914-15 audit of facility underpinning Purpose of audit was to gather info from applicant re effect on design & const of reducing modulus of hard clay foundation from 3000 Ksf to 5000 Ksf
POULOS, S J Geotechnical Engineers, Inc BX16 023 81907-27
83/09/22 KANE, J Office of Nuclear Reactor Regulation, Director
3pp 26511 031 24X Fiche 50-329, 84/07/18, 8408010061

--8408140209 Handwritten notes re design details for borated water storage tanks & util position on cause of cracking
KANE, J NRC - No Detailed Affiliation Given BX16 024 81/07/28
2pp 26511 030 24X Fiche 50-329, 84/07/18, 8408010061

--8408140213 Handwritten summary of 810805 meeting in Ramada Central Inn re borated water storage tank W/810728 handwritten memo re status of review on borated water storage tank
KANE, J NRC - No Detailed Affiliation Given BX16 025 81/08/05
NRC - No Detailed Affiliation Given 2pp 26511 052 24X
Fiche 50-329, 84/07/18, 8408010061

--8408140218 Handwritten notes re discussion w/G Gallagher about surcharging of valve pits near borated water tanks Record of telcon w/util, Bechtel & Geotechnical Engineering on 810715 re surcharging valve pits encl
* NRC - No Detailed Affiliation Given BX16 026 81/07/01 4pp
26511 054 24X Fiche 50-329, 84/07/18, 8408010061

--8408140223 Handwritten notes reviewing comments on borated water storage tanks & valve pit settlements
KANE, J NRC - No Detailed Affiliation Given BX16 027 81/07/28
1p 26511 074 24X Fiche 50-329, 84/07/18, 8408010061

--8408140232 Forwards draft comments on info received from applicant through Amend 85 to OL request & Rev 10 to 10CFR50 54(f) requests re borated water tanks Info received addresses all questions raised in 800707 ltr
MCCALLISTER, P Army, Dept of, Corps of Engineers BX16 028
81/03/26 JACKSON, R E NRC - No Detailed Affiliation Given
14pp 26511 075 24X Fiche 50-329, 84/07/18, 8408010061

--8408140242 Forwards branch position re seismological input parameters Position necessary to resolve differences between applicant & NRC on seismological issues & to provide guidance for inputing vibratory motion in evaluations
JACKSON, R E Geosciences Branch BX16 030 80/07/08
SCHWENCER, A Licensing Branch 3 6pp 26511 101 24X
Fiche 50-329, 84/07/18, 8408010061

--8408140218 Urges studies evaluating soil liquefaction & stability under dynamic loading & using values of acceleration in range of 0 12g to 0 19g at ground surface Also forwards list of strong motion records
ROTHMAN, R L Geosciences Branch BX16 031 80/02/11
JACKSON, R E Geosciences Branch 9pp 26511 107 24X
Fiche 50-329, 84/07/18, 8408010061

--8408140258 Handwritten notes re ASLB actions on 800527 motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues concerning soil conditions for safety-related structures & sys
KANE, J NRC - No Detailed Affiliation Given BX16 033 80/06/09
1p 26511 158 24X Fiche 50-329, 84/07/18, 8408010061

--8408140263 Motion to consolidate for discovery, evidentiary presentation & fact finding purposes issues relating to soil conditions for safety-related structures & sys founded in & on plant fill matl in hearing considering 791206 order
FARNELL, A S Consumers Power Co FARNELL, A S Isham, Lincoln & Beale BX16 034 OM 80/05/27 Atomic Safety and Licensing Board Panel 15pp 26511 159 24X Fiche 50-329, 84/07/18, 8408010061

--8408140286 Testimony of H Singh re origin remedial measures proposed by applicant for auxiliary bldg & Corps of Engineers evaluation of remedial measures
SINGH, H NRC - No Detailed Affiliation Given BX16 038B
81/11/12 9pp 26511 242 24X Fiche 50-329, 84/07/18, 8408010061

--8408140296 Draft testimony of SJ Poulos re remedial underpinning of svc water pump structure
POULOS, S J Geotechnical Engineers, Inc BX16 040 82/03/30
11pp 26511 271 24X Fiche 50-329, 84/07/18, 8408010061

--8408140300 Testimony of HN Singh re svc water pump structure
SINGH, H N Geotechnical Engineers, Inc BX16 041 OM 82/04/08
7pp 26511 282 24X Fiche 50-329, 84/07/18, 8408010061

--8408140319 Summary of 810917 meeting w/CPC, US Army Corps of Engineers, NRC, Bechtel & Mueser, Rutledge, Wentworth & Johnson in Bethesda, MD re preliminary design of proposed remedial measures for svc water pumping structure
SINGH, H N Army, Dept of, Corps of Engineers BX16 044
81/09/18 Army, Dept of, Corps of Engineers 3pp 26511 341
24X Fiche 50-329, 84/07/18, 8408010061

--8408140347 Summary of 820422 meeting w/CPC, consisting of answers to GES questions re permanent dewatering sys, soil stabilization, jacking procedure & draft SER
KANE, J NRC - No Detailed Affiliation Given BX16 046 82/06/25
NRC - No Detailed Affiliation Given 4pp 26511 348 24X
Fiche 50-329, 84/07/18, 8408010061

--8408140352 "Dynamic Core Penetrometer " Sketchs & design calculations of underpinning & settlement analysis study encl
ANDERSON, J NRC - No Detailed Affiliation Given BX16 047
82/03/17 42pp 26512 036 24X Fiche 50-329, 84/07/18, 8408010061

--8408140359 Handwritten notes re settlement monitoring programs, classification of fines, instrumentation & agenda for 781204 meeting re diesel generator bldg
* NRC - No Detailed Affiliation Given BX16 049 84/07/18
10pp 26512 210 24X Fiche 50-329, 84/07/18, 8408010061

--8408140367 Draft ltr re Interagency Agreement NRC-03-76-167, Task 1, Subtask 3 concerning comment on Amend 85 List of specific discrepancies re settlement evaluations encl
SINGH, H Army, Dept of, Corps of Engineers BX16 051 81/02/26
KANE, J , JACKSON, R E NRC - No Detailed Affiliation Given 13pp
26512 221 24X Fiche 50-329, 84/07/18, 8408010061

--8408140513 Summary of R Landsman 810325-27 & 0407-09 insps conducted to verify QA program for util soil borings conducted in response to Corps of Engineers request for addl soil info
* NRC - No Detailed Affiliation Given BX16 054 84/07/18 4pp
26512 259 24X Fiche 50-329, 84/07/18, 8408010061

--8408140522 Informs that, in preparation for issuance of draft SER in mid-late Jan, section by section review of which sections of draft received by Div of Licensing to date complete
HERNAN, R W Licensing Branch 4 BX16 055A 82/01/12
ADENSAM, E G Licensing Branch 4 3pg 26512 269 24X
Fiche 50-329, 84/07/18, 8408010061

--8408140526 Summarizes 810608 stipulation filed by util & NRC re QA aspects of hearing on soils settlement scheduled to begin 810707
HOOD, D Licensing Branch 4 BX16 056 OM, 81/06/08 DENTON, H ,
CARTER, J Office of Nuclear Reactor Regulation, Director
EISENHUT, D G Division of Licensing 1p 26512 272 24X
Fiche 50-329, 84/07/18, 8408010061

NONDOCKETED ITEMS

8408140530 Draft memo providing estimate for completing review & preparing testimony on proposed remedial actions, in response to OELD request for schedule for review
LEAR, J NRC - No Detailed Affiliation Given BX16 057 81/06/19
KNIGHT, J NRC - No Detailed Affiliation Given 3pp 26513 185
24X Fiche 50-329, 84/07/18, 8408010061

-8408140539 Requests estimate of time required to complete review & prepare testimony re proposed remedial actions Testimony by F Rinaldi, T Cappucci & J Kane needs to be filed by 810915
PATON, W D Office of the Executive Legal Director BX16 057A
81/07/18 KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 1p 26513 188 24X
Fiche 50-329, 84/07/18, 8408010061

-8408140553 Util news ltr re lifting of part of series of stop work orders that halted const of plant
* Consumers Power Co BX16 061 84/01/20 1p 26513 249 24X
Fiche 50-329, 84/07/18, 8408010061

-8408140556 Documents contacts by Kirkland & Ellis attys representing Dow Chemical in suit against CPC Summary of meeting by Geotechnical Engineering, Inc encl
KANE, J D Structural & Geotechnical Engineering Branch BX16 062
84/01/23 Structural & Geotechnical Engineering Branch 14pp
26513 263 24X Fiche 50-329, 84/07/18, 8408010061

--8408140557 Forwards comments re applicant submissions concerning cracks in diesel generator, fixation of cracks in borated water storage tanks, underpinnings & effects or cracks on serviceability of structures
MCCALLISTER, P Army, Dept of, Corps of Engineers BX16 063
82/06/15 LEAR, G Division of Engineering 14pp 26513 277
24X Fiche 50-329, 84/07/18, 8408010061

--8408140562 Handwritten document summarizing util response to NRC Questions 24, 45 & 47 on permanent dewatering re geotechnical engineering issues Meeting summaries encl
* Consumers Power Co BX16 064 81/10/12 32pp 26513 291
24X Fiche 50-329, 84/07/18, 8408010061

--8408140565 Handwritten document re liquefaction analysis
KANE, J C NRC - No Detailed Affiliation Given BX16 065
82/08/16 5pp 26513 323 24X Fiche 50-329, 84/07/18, 8408010061

--8408140566 Requests analysis of possible enforcement action re applicant failure to inform NRC of settlement of diesel generator bldg
PALLADINO, N. NRC - No Detailed Affiliation Given BX16 066
84/05/24 DIRCKS, W Office of the Executive Director for Operations 1p 26514 031 24X Fiche 50-329, 84/07/18, 8408010061

--8408140570 "Administrative Bldg Foundation Settlements Along Column Line O 4 "
* Bechtel Corp BX16 068 77/12/31 21pp 26514 033 24X
Fiche 50-329, 84/07/18, 8408010061

--8408140573 Forwards Bechtel rept, "Administrative Bldg Foundation Settlements Along Column Line O 4 "
BRUNNER, J E Consumers Power Co BX16 067 81/09/14 PATON, W
NRC - No Detailed Affiliation Given 1p 26514 032 24X
Fiche 50-329, 84/07/18, 8408010061

--8408140575 Handwritten summary of 781204 site meeting re excessive settlement of diesel generator bldg & foundations & other Category I structures
GALLAGHER, G Region 3, Office of Director BX16 069 78/12/07
HOOD, D NRC - No Detailed Affiliation Given 8pp 26514 068
24X Fiche 50-329, 84/07/18, 8408010061

--8408150015 Requests addl borings & existing soil data Revised Encl 1 to 800327 ltr encl
MCCALLISTER, P Army, Dept of, Corps of Engineers BX16 071
84/07/18 JACKSON, R E NRC - No Detailed Affiliation Given 6pp
26514 140 24X Fiche 50-329, 84/07/18, 8408010061

--8408150019 Handwritten notes re status of ASLB hearings First session, completed 810707-17, covered items re Stamiris Contention 1, QA breakdown, NRC-util stipulation on QA managerial attitude & FSAR false statement
KANE, J NRC - No Detailed Affiliation Given BX16 072 81/08/18
11pp 26514 146 24X Fiche 50-329, 84/07/18, 8408010061

--8408150022 Handwritten notes re location of sources of important util submittals prior to 791204 Topics outlined include auxiliary bldg, diesel generator bldg, borated water storage tank & permanent dewatering
KANE, J NRC - No Detailed Affiliation Given BX16 073 81/05/18
31pp 26514 157 24X Fiche 50-329, 84/07/18, 8408010061

--8408150027 Summary of 840304 meeting w/util re schedules & topics for instant hearing on soils matters Hearing schedule resulting in inefficient reviews due to changing const priorities by applicant
HOOD, D Licensing Branch 4 BX16 075 82/03/11 TEDESCO, R L
Assistant Director for Licensing 43pp 26514 191 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150029 Task interface agreement re plant remedial soils issue
IPPOLITO, T Region 3, Office of Director NORELIUS, C Director's Office, Office of Inspection and Enforcement VOLLMER, R Office of Nuclear Reactor Regulation, Director BX16 076 TAC 51341
83/04/18 5pp 26514 234 24X Fiche 50-329, 84/07/18, 8408010061

--8408150033 Discusses 830929 conference call during which D Hood gave verbal approval to allow licensee to proceed w/underpinning through UATs
LANDSMAN, R B Region 3, Office of Director BX16 077 83/09/30
Region 3, Office of Director 1p 26514 241 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150042 Handwritten notes commenting on Peck 810807 transcript re compaction criteria
KANE, J NRC - No Detailed Affiliation Given BX16 079 81/08/10
2pp 26514 264 24X Fiche 50-329, 84/07/18, 8408010061

--8408150046 Handwritten notes re electrical penetration area w/comments of H Singh on unresolved issues prior to 791206 & underground utils
SINGH, H NRC - No Detailed Affiliation Given BX16 080
81/05/20 2pp 26514 266 24X Fiche 50-329, 84/07/18, 8408010061

--8408150560 Comments on licensee draft commitments to improve implementation of quality program in remedial soils area & remaining const activities, per 820907 request Noted changes should be made in program
WARNICK, R F Region 3, Office of Director BX21 001 82/09/24
KEPPLER, J G Region 3, Office of Director 4pp 26549 080 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150566 "Pier Load Test Data - Load by Carlson vs Load by Jacks " Related info encl
HUNT, S W Bechtel Corp BX21 003 83/04/29 200pp 26549 215
24X Fiche 50-329, 84/07/18, 8408010061

--8408150571 "Well OBS-4 Subsidence Rept "
HUNT, S W Bechtel Corp BX21 004 82/06/11 50pp 26550 120
24X Fiche 50-329, 84/07/18, 8408010061

--8408150577 Forwards recent audit repts by Midland QA dept, per request
BRUNNER, J E. Consumers Power Co BX21 005 OM 82/01/15
BECHHOEFER, C , HARBOUR, J Atomic Safety and Licensing Board Panel
COWAN, F P Affiliation Not Assigned 26pp 26550 222 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150586 Forwards recent audit repts by Midland QA dept, per request Related info encl, including notes of CPC/NRC 830308 public meeting re const completion program
BRUNNER, J E Consumers Power Co BX21 006 OM 82/02/05
BECHHOEFER, C , HARBOUR, J Atomic Safety and Licensing Board Panel
COWAN, F P Affiliation Not Assigned 106pp 26550 248 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150595 Opposes issuance of fuel license (10CFR70) for applicant, based upon extensiveness of remedial soils work & potential for work to impact auxiliary bldg Related info encl
COOK, R J Region 3, Office of Director BX21 007 83/01/25
SHAFER, W D Region 3, Office of Director 19pp 26551 001 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150603 Forwards Midland monthly status repts for Aug-Sept & Nov 1982 Related info encl
WARNICK, R F Region 3, Office of Director BX21 008 82/12/20
KEPPLER, J G Region 3, Office of Director. 23pp 26551 236 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150608 Rev 4 to "Quality Plan for Underpinning Activities, " Related info encl
BIRD, W , BOOS, A J , MOONEY, J Consumers Power Co BX21 009
82/10/12 59pp 26551 316 24X Fiche 50-329, 84/07/18, 8408010061

--8408150612 Draft final SSER re geotechnical engineering Related info encl
KANE, J D Hydrologic & Geotechnical Engineering Branch BX21 010
82/08/12 78pp 26553 002 24X Fiche 50-329, 84/07/18,
8408010061

--8408150616 Enumerates QA issues to be addressed at evidentiary session in Midland proceeding, per encl 820707 memorandum & order W/o encl
PATON, W D Office of the Executive Legal Director BX21 011
82/08/10 ADENSAM, E G NRC - No Detailed Affiliation Given 2pp
26553 087 24X Fiche 50-329, 84/07/18, 8408010061

--8408150617 Forwards further response to FOIA-84-96, consisting of records selected from files of Harrison & Norelius during 840628 visit
ROY, G W Office of Resource Management, Director BX20 001
84/07/06 RICE, C M Kirkland & Ellis 3pp 26537 339 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150622 Discusses basis for recommendation to extend SALP III evaluation period from 820630 to 821231, per 820719-20 discussions Related info encl
COOK, R J Region 3, Office of Director BX21 012 82/08/06
SPESSARD, R L Division of Project & Resident Programs 13pp
26553 145 24X Fiche 50-329, 84/07/18, 8408010061

--8408150624 Draft summary of NRC 840229 meeting w/util at Region III ofc re results of NRC HVAC insps & investigation of allegations & expansion of QA training, qualification & certification activities Viewgraphs encl
* Region 3, Office of Director BX20 002 84/02/29 Region 3, Office of Director 21pp 26537 342 24X Fiche 50-329, 84/07/18, 8408010061

--8408150626 Forwards HR Denton 831219 ltr distinguishing between terms "important to safety" & "safety-related " Related info encl
KEPPLER, J G Region 3, Office of Director BX21 013 83/12/29
Region 3, Office of Director 5pp 26553 163 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150630 Forwards addl info re Region III inquiries into Ofc of Special Cases concerning Midland & Zimmer Nuclear Power Plant problems in implementing QA programs Nonconformance rept also encl
WARNICK, R F Region 3, Office of Director BX20 003 83/09/16
BOULDEN, H Office of Inspector & Auditor 18pp 26538 001 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150633 Forwards Rev 4 to "Region III SALP Schedule " Schedule changes to listed facilities explained in remarks sections of schedule Addl handwritten notes also encl
NORELIUS, C E Region 3, Office of Director BX20 004 84/06/04
KEPPLER, J G , DAVIS, A B , SPESSARD, R L Region 3, Office of Director 22pp 26538 025 24X Fiche 50-329, 84/07/18, 8408010061

--8408150635 Notifies that commercial operation date of Unit 2 may be delayed until mid-1986 Const schedule for Unit 1 will be revised based on cash flow requirements, need for power, final cost estimates & schedule for Unit 2
KOSCHIK, M G Consumers Power Co BX21 015 83/11/09 STRASMA, J
Region 3, Office of Director 2pp 26553 216 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150639 Discusses Ofc of Special Cases special insp on 821012-1125 & forwards draft notice of violation re significant breakdown in implementation of QA program Handwritten NRR comments also encl
KEPPLER, J G Region 3, Office of Director BX20 005 EA-83-003
83/01/05 COOK, J W Consumers Power Co 84pp 26538 049 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150640 Ack receipt of 830926 ltr & payment in amount of $116,500 for civil penalty imposed by 830829 order
AXELRAD, J A Enforcement Staff BX21 016 EA-83-003 83/10/04
SELBY, J D Consumers Power Co 2pp 26553 305 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150643 Forwards listed documentation in response to FOIA 83-397 for reproduction
WARNICK, R F Region 3, Office of Director BX20 006 83/07/20.
SMIDTH, P T Region 3, Office of Director ip 26538 156 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150644 Forwards payment in amount of $116,500 in response to 830829 ltr imposing civil penalty for violations found during Insp 83-23 (EA 83-03). Related info encl, including matl on 830811 public meeting
COOK, J W Consumers Power Co BX21 017 25914 83/09/26
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 29pp 26554.005 24X Fiche 50-329, 84/07/18, 8408010061

--8408150648 Draft summary of NRC Caseload Forecast Panel 830419-21 meeting w/util at plant site re basis for util revised estimates of Oct 1984 & Feb 1985 for Unit 2 & 1, respectively Rept on Rev 12 schedule encl
NOVAK, T M Assistant Director for Licensing BX20 007. 83/05/25
COOK, J W Consumers Power Co. 32pp 26538 157 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150651 Requests NRC approval to postpone yellowbook update due to inadequate work experience enabling development of definitive project schedule, per B31014 ltr
QUAMME, D L Consumers Power Co BX20 008 CSC-7161 84/01/12
HARTFIELD, R A Management Information Branch ip 26539 002
24X Fiche 50-329, 84/07/18, 8408010061

--8408150652 Notifies of intent to continue const of plant following recent notification from Dow Chemical Co of decision to terminate agreement to purchase energy Related info encl
FITZPATRICK, R Consumers Power Co BX21 019 83/07/15
STRASMA, J Region 3, Office of Director 72pp 26554 061 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150656 Responds to 840409 comments re util proposed plan to conduct independent mgt appraisal of Midland Nuclear Project Affidavits of independence of individuals working on audit encl
REHM, T A Office of the Executive Director for Operations. BX20 009 84/06/08 GARDE, B P Government Accountability Project 31pp 26539 014 24X Fiche 50-329, 84/07/18, 8408010061

--8408150658 Recommends issuance of board notification for encl potential Part 21 rept from Zack Co (HVAC subcontractor) re accuracy of welder records
WARNICK, R F Region 3, Office of Director BX21 020 OM
82/09/01 EISENHUT, D G Division of Licensing 2pp 26554 179
24X Fiche 50-329, 84/07/18, 8408010061

--8408150662 Enumerates agreements/understandings reached at 820823 meeting w/NRC re approval for portions of Phase II underpinning work Related info encl
MILLER, D B Consumers Power Co BX21 021 CSC-6266 82/08/25
SHAFER, W D Region 3, Office of Director 14pp 26554 241. 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150665 Comments on util 840307 proposed independent mgt plan Plan does not indicate how Gresap, McCormick & Paget & TERA will function & interface Roles, authorities & responsibilities should be identified Handwritten comments encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement BX20 011 84/03/27 KEPPLER, J G Region 3, Office of Director 4pp. 26539 052 24X Fiche 50-329, 84/07/18, 8408010061

--8408150666 Summary of NRC 840314 meeting w/D Bridenbaugh of MAB Technical Assocs in Region III re info on Midland & Zimmer plants Util 840124 ltr to Atty General of State of MI encl
WARNICK, R F Region 3, Office of Director. BX20 012 84/03/20
Region 3, Office of Director 7pp 26539 136 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150669 Corrects Page 3-1 of Attachment 3 to util 820517 response to draft SALP rept for Jul 1980 - June 1981, clarifying stop work order on drilling
COOK, J W Consumers Power Co BX21 024 17249 82/05/21
KEPPLER, J G Region 3, Office of Director 31pp 26554 313. 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150672 Forwards response to draft SALP rept for Jul 1980 - June 1981, discussed at 820426 meeting w/NRC
COOK, J W Consumers Power Co BX21 025 17485 82/05/17.
KEPPLER, J G Region 3, Office of Director 38pp 26554 344. 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150676 Forwards util testimony on cable pulling incident Requests comments Lists questions to be addressed
WILCOVE, M N Office of the Executive Legal Director BX20 014. 83/05/13 LANDSMAN, R , COOK, R. , GARDNER, R NRC - No Detailed Affiliation Given 7pp 26539 306 24X Fiche 50-329, 84/07/18, 8408010061

--8408150677 Discusses SALP appraisals for Zimmer & Midland Suggests limited SALP-3 appraisal for Midland to cover remedial soils work, B&W work & HVAC activities
KEPPLER, J G Region 3, Office of Director BX21 026 83/04/18
HIND, J A Division of Radiological & Materials Safety Programs ip 26555 066 24X Fiche 50-329, 84/07/18, 8408010061.

--8408150681 Discusses policy & procedure changes re communications w/ licensee Related info encl
WARNICK, R F Region 3, Office of Director BX21 027. 82/09/17
SPESSARD, R L Division of Project & Resident Programs
NORELIUS, C E Division of Engineering HIND, J. A. Division of Radiological & Materials Safety Programs. 8pp 26555.067 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150682 Advises that FOIA Request 82-616 received Matl requested must be submitted to director by 840103 Nonconformance repts & Interim Rept 3 re cable tray support const welding discrepancy encl
SMIDTH, P T Region 3, Office of Director BX20 013 82/12/22
Region 3, Office of Director 2pp. 26539.359 24X
Fiche 50-329, 84/07/18, 8408010061.

--8408150685 Discusses QA program re underpinning instrumentation installation Lists steps to follow to implement reclassification of underpinning activities
COOK, J W Consumers Power Co BX21 028 16779 82/03/31
NORELIUS, C E Division of Engineering 2pp 26555 110 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150686 Advises that allegations received from Dow Chemical & util are treated equally Forwards E Driker 840504 ltr re Dow Chemical vs CPC lawsuit
BERKOVITZ, D M Office of the General Counsel BX20 016
84/05/11 LEWIS, S H Region 3, Office of Director 1p
26540 094 24X Fiche 50-329, 84/07/18, 8408010061

--8408150689 Submits summary of views re regulatory status of plant Illegible handwritten notes encl
KEPPLER, J G Region 3, Office of Director BX20 016A 84/06/06
FISCHER, R Michigan, State of 12pp 26540 095 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150690 Lists reasons why SALP III evaluation period should be extended to 821231, per 820719-20 discussion Related info encl
COOK, R J Region 3, Office of Director BX21 029 82/08/06
SPESSARD, R L Division of Project & Resident Programs 21pp
26555 112 24X Fiche 50-329, 84/07/18, 8408010061

--8408150692 Forwards newspaper stories indicating representives of Dow Chemical met w/NRC to discuss matters in litigation pending in County Circuit Court w/util JD Selby 840608 ltr to PJ Kelley encl
DRIKER, E Barris, Sott, Denn & Driker BX20 017 84/05/04
BERKOVITZ, D Office of the General Counsel 18pp 26540 160
24X Fiche 50-329, 84/07/18, 8408010061

--8408150694 PNO-77-035 on 770226, bulge discovered in containment liner plate Caused by water coming through tears in liner plate Addl holes cut in plate to facilitate draining Related info encl
WARNICK, R F , ROY, G W , THOMPSON, D Office of Inspection & Enforcement, Office of the Director BX21 030 77/03/01 7pp
26555 134 24X Fiche 50-329, 84/07/18, 8408010061

--8408150695 "Site Visit to Evaluate Crack Reported 830218 in Roof of Feedwater Isolation Valve Pit Unit 1, Midland Nuclear Power Plant " Draft confirmatory orders, handwritten notes & RF Warnick memo re FOIA Request 84-24 encl
CORLEY, W G Construction Technology Laboratories BX20 019
83/02/28 111pp 26540 178 24X Fiche 50-329, 84/07/18, 8408010061

--8408150698 Forwards monthly status rept for Dec 1983, containing input from insp site team of Ofc of Special Cases
COOK, R J Region 3, Office of Director BX21 031 83/01/12
WARNICK, R F Region 3, Office of Director 2pp 26555 161 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150700 Forwards draft confirmatory order prepared by IE re plan for independant appraisal of site & corporate mgt organizations Requests review prior to meeting
LIEBERMAN, S NRC - No Detailed Affiliation Given BX20 020
83/12/30 KEPPLER, WARNICK, HARRISON NRC - No Detailed
Affiliation Given 10pp 26540 335 24X Fiche 50-329, 84/07/18, 8408010061

--8408150702 Advises that Region III has no document re discovery request for info concerning alleged violation of ASLB order concerning remedial soils Handwritten notes, internal memos & list of repts, 1977 - 1983, encl
HARRISON, J J Region 3, Office of Director BX20 021 83/10/25
WRIGHT, N Office of the Executive Legal Director 199pp
26540 345 24X Fiche 50-329, 84/07/18, 8408010061

--8408150706 Advises that S Lewis leaving Region III to assume position of Deputy Assistant Chief Hearing Counsel in OELD B Berson replacement Chronological list of reactor holddown bolt encl
KEPPLER, J G Region 3, Office of Director BX20 022 84/05/14
Region 3, Office of Director 12pp 26541 263 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150709 Summary of 800523 meeting w/util, B&W, Bechtel & Teledyne in Bethesda, MD re preservice failure of three reactor vessel holddown studs List of attendees, agenda & viewgraph slides encl Sketches for underpinning auxiliary bldg encl
HOOD, D S Licensing Branch 3 BX20 023 80/07/07 Licensing
Branch 3 82pp 26541 328 24X Fiche: 50-329, 84/07/18, 8408010061

--8408150710 Assessment rept QA program, performed during Mar & Apr 1981
* Management Analysis Co BX21 033 81/06/01 400pp
26555 182 24X Fiche 50-329, 84/07/18, 8408010061

--8408150712 "Quality Program for Underpinning Activities "
* Consumers Power Co BX20 024A 82/04/05 22pp 26542 132
24X Fiche 50-329, 84/07/18, 8408010061

--8408150714 'Independent Assessment of Underpinning 90-Day Rept "
KILBER, W E Stone & Webster, Inc BX21 034 83/04/30 250pp
26556 194 24X Fiche 50-329, 84/07/18, 8408010061

--8408150716 "Test Program Status & Rev 12 - Test Schedule "
* Consumers Power Co BX21 035 83/04/12 100pp 26557 091
24X Fiche 50-329, 84/07/18, 8408010061

--8408150718 Documents conclusions & commitments made at 820330 meeting & 820402 telcons re QA applied to remedial foundation work Expansion of QA program recognized in overall success of project "Quality Program for Underpinning Activities" encl
COOK, J W Consumers Power Co BX20 024B 16161 82/04/05
KEPPLER, J G Region 3, Office of Director 4pp 26542 154 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150720 "Electrical Raceway Support Tests Rept, Part 1 "
NOWAK, A S Bechtel Corp BX21 036 81/11/25 100pp 26557 192
24X Fiche 50-329, 84/07/18, 8408010061

--8408150723 Forwards CPC testimony on alleged violation of Board order Investigation of violation coming in future Requests analysis of testimony & comments Handwritten notes encl
WILCOVE, M N Office of the Executive Legal Director BX20 026
OM 83/05/13 LANDSMAN, R , COOK, R , HOOD, D NRC - No Detailed
Affiliation Given 99pp 26542 165 24X Fiche 50-329, 84/07/18, 8408010061

--8408150725 Requests review of attached draft SALP rept in preparation for 830706 SALP Board meeting
WARNICK, R F Region 3, Office of Director BX20 027 83/07/01
HIND, J A , NORELIUS, C E , SPESSARD, R L NRC - No Detailed
Affiliation Given 149pp 26542 288 24X Fiche 50-329, 84/07/18, 8408010061

--8408150727 Summarizes 800227-28 meeting at site re soils settlement issue & effects Handwritten note encl
GALLAGHER, E Region 3, Chicago, Office of the Director BX20 034
80/03/03 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 46pp 26544 306 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150728 Forwards advance copy of proposed rev to Manual Chapter 0516, SALP, for review
NORELIUS, C E Division of Project & Resident Programs BX20 035
84/04/13 Region 3, Office of Director 2pp 26545 069 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150729 Advises of problems concurring w/proposed response to M Cherry 770427 ltr as noted by detailed comments provided Requests redraft be considered
REINMUTH, G W Division of Reactor Construction Inspection BX20
029 77/06/10 HOEFLING, R K Office of the Executive Legal
Director 7pp 26543 234 24X Fiche 50-329, 84/07/18, 8408010061

--8408150731 Advises of possible ex parte contact in facility proceeding Requests memo & attached summary of discussion be served to all parties in proceeding & PDR
GIBSON, T R NRC - No Detailed Affiliation Given BX20 030 OM
80/12/24 CHILK, S J Office of the Secretary of the Commission
2pp 26543 250 24X Fiche 50-329, 84/07/18, 8408010061

--8408150732 Notifies that incorrect target dates entered in 830219 SALP schedule Correct target dates provided
NORELIUS, C E Division of Project & Resident Programs BX20 035A
84/03/08 HIND, J A Division of Radiological & Materials Safety Programs SPESSARD, R L Division of Engineering DOUGHERTY, D J Office of Resource Management, Director 2pp 26545 117 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150734 Revises previously issued SALP 4 schedule dtd 831004, by extending assessment to 18 months Rev incorporates addl milestone dates
NORELIUS, C E Division of Project & Resident Programs BX20 035B
83/12/19 Region 3, Office of Director, 2pp 26545 119 24X
Fiche 50-329, 84/07/18, 8408010061

--8408150735 Requests concurrence on proposed auxiliary bldg guideline, "Guidelines for Bldg Movements During Temporary Underpinning " Handwritten notes & communications record w/Warnick re withdrawal of potential 10CFR50 55(e) encl
MOONEY, J A Consumers Power Co BX20 031, CSC-7809 84/05/25
HARRISON, J J Region 3, Office of Director 25pp 26543 252
24X Fiche 50-329, 84/07/18, 8408010061

--8408150737 Forwards NRC Manual Chapter 0516, SALP Evaluation criteria published in FR on 820322 for public comments Comments due by 820701
TAMBLING, T N Region 3, Office of Director BX20 039C 82/05/04
AXELSON, W L , BARRETT, P A , BOYD, D C NRC - No Detailed Affiliation Given 3pp 26545 123 24X Fiche 50-329, 84/07/18, 8408010061

--8408150738 Forwards summary of 840229 meeting in Region III ofc re results of HVAC insps & investigation of allegations & expansion of training, qualification & certification activities Handuritten notes encl
WELLS, R A Consumers Power Co BX20 032 28921 84/03/29
HARRISON, J J Region 3, Office of Director 169pp 26544 014 24X Fiche 50-329, 84/07/18, 8408010061

--8408150740 "Chapter 0516 SALP," describing basis structure & overall procedures for implementation of NRC program to assess licensee performance HA Miller marked-up memo re evaluation of SALP encl
* Director's Office, Office of Inspection and Enforcement BX20 0350 82/03/23 47pp 26545 126 24X Fiche 50-329, 84/07/18, 8408010061

--8408150741 Forwards "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking "
LEVIN, H A TERA Corp BX20 033 OM 83/01/04 KEPPLER, J G , EISENHUT, D G Region 3, Office of Director COOK, J W Consumers Power Co 4pp 26544 212 24X Fiche 50-329, 84/07/18, 8408010061

--8408150743 Submits reasons for extending SALP III evaluation period to 821231 Rept contains issues being resolved between NRC & licensee Extension can be used as performance motivator Handuritten note & supporting documentation encl
COOK, R J Region 3, Office of Director BX20 036 82/08/06
SPESSARD, R L Division of Project & Resident Programs 350pp 26545 173 24X Fiche 50-329, 84/07/18, 8408010061

--8408150745 "Structural Evaluation of Diesel Generator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking " Handuritten notes encl
* TERA Corp BX20 033A 83/01/04 89pp 26544 216 24X Fiche 50-329, 84/07/18, 8408010061

--8408150747 Submits supplemental SALP input for facility Changes required to provide overall Div of Engineering & Technical Insp rating for QA functional area & consolidate comments for recommended increased insp frequency
PIRTLE, G Region 3, Office of Director BX20 037 83/10/01
BOYD, D Region 3, Office of Director 1p 26547 011 24X Fiche 50-329, 84/07/18, 8408010061

--8408150749 Forwards list of items reviewed by util & determined ready for review & closure by NRC Handuritten notes & supporting documentation encl
WELLS, R A Consumers Power Co BX20 038A 25261 83/10/04
KEPPLER, J G Region 3, Office of Director 147pp 26547 165 24X Fiche 50-329, 84/07/18, 8408010061

--8408150750 Forwards SALP input except for Matls & Processes Section
PIRTLE, G Division of Engineering & Technical Inspection BX20 038 81/09/22 BOYD, D Division of Engineering & Technical Inspection 137pp 26547 012 24X Fiche 50-329, 84/07/18, 8408010061

--8408150751 Forwards const status rept as of 791001 Handuritten notes re diesel generator bldg & soil settlement & errata to NUREG-0834 encl
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch BX20 041A 79/10/05 KNOP, R C , HAYES, D W , DANIELSON, D H NRC - No Detailed Affiliation Given 107pp 26548 359 24X Fiche 50-329, 84/07/18, 8408010061

--8408150752 Submits QA issues to be addressed at evidentiary session in facility proceeding Summary rept & oral communications record re reinsp requirements based on results of certification testing encl
PATON, W D NRC - No Detailed Affiliation Given BX20 041 82/08/10 ADENSAM, E G, NRC - No Detailed Affiliation Given 18pp 26548 075 24X Fiche 50-329, 84/07/18, 8408010061

--8408170081 "Response to NRC Staff Review Concerns for Underpinning of Auxiliary Bldg "
* Consumers Power Co BX19 001 82/06/03 40pp 26529 122 24X Fiche 50-329, 84/07/18, 8408010061

--8408170090 Discusses util 820428 telcon notifyng that, while drilling well in G area, electric duct bank struck Drawings indicated duct bank elsewhere Investigation continuing
SHAFER, W D Region 3, Office of Director BX19 001A 82/04/28
WILLIAMS, G C , LANDSMAN, R B NRC - No Detailed Affiliation Given 1p 26529 285 24X Fiche 50-329, 84/07/18, 8408010061

--8408170098 Testimony of RB Landsman in Glen Ellyn, IL re QA criteria & proredures to remedial foundation work underway at site
LANDSMAN, R B NRC - No Detailed Affiliation Given BX19 002 82/04/19 2pp 26529 332 24X Fiche 50-329, 84/07/18, 8408010061

--8408170102 Forwards addl documents re facility soils issue, in response to request for info
DREHOBL, K E Consumers Power Co BX19 003 16625 82/04/12
FISCHER, D C ACRS - Advisory Committee on Reactor Safeguards 7pp 26530 009 24X Fiche 50-329, 84/07/18, 8408010061

--8408170119 Confirms that underpinning instrumentation installation will be suspended until procedures & drawings developed & plans & schedules established to inspect & audit activities, per 820319 telcon
KEPPLER, J G Region 3, Office of Director BX19 007 CAL 82/03/19 COOK, J W Consumers Power Co 2pp 26530 037 24X Fiche 50-329, 84/07/18, 8408010061

--8408170141 Requests review of files to determine documents withholdable under FOIA, per FOIA-84-96
LEWIS, S H NRC - No Detailed Affiliation Given BX19 009 84/05/08 HARRISON, J J , GARDNER, R , LANDSMAN, R NRC - No Detailed Affiliation Given 1p 26530 066 24X Fiche 50-329, 84/07/18, 8408010061

--8408170145 Forwards draft ltr to util re review of licensee 830310, 0624 & 0712 responses to 830208 & 0523 notice of violation & proposed imposition of civil penalty Recommends imposition of $120,000 civil penalty
SCHULTZ, W H Region 3, Office of Director BX19 010 83/07/28
AXELRAD, J A Director's Office, Office of Inspection and Enforcement 165pp 26530 067 24X Fiche 50-329, 84/07/18, 8408010061

--8408170152 Forwards redrafted insp rept Rept has been reviewed w/NRC for format & content Rept covers insp made 821129-1210
CHARAK, I Argonne National Laboratory BX19 011 NAP-83-55
82/01/07 WARNICK, R Region 3, Office of Director 7pp 26530 233 24X Fiche 50-329, 84/07/18, 8408010061

--8408170157 Forwards draft insp rept re findings of personnel who participated in routine insps on 821129-1203 & 1208-10
CHARAK, I Argonne National Laboratory BX19 012 82/12/22
WARNICK, R Region 3, Office of Director 14pp 26530 240 24X Fiche 50-329, 84/07/18, 8408010061

--8408170166 Testimony of RN Gardner re allegations concerning qualification of personnel employed by Camstock
GARDNER, R N Region 3, Office of Director BX19 012A 84/07/18 100pp 26530 321 24X Fiche 50-329, 84/07/18, 8408010061

--8408170174 Forwards IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820514
NORELIUS, C E Region 3, Office of Director BX19 013 82/06/28
COOK, J W Consumers Power Co 2pp 26531 033 24X Fiche 50-329, 84/07/18, 8408010061

--8408170181 IE Mgt Meeting Repts 50-329/82-09 & 50-330/82-09 on 820514 Major areas discussed licensee disposition of results of electrical overview insps
GARDNER, R N , WILLIAMS, G C Region 3, Office of Director BX19 013A 50-330/82-09 82/06/24 3pp 26531 035 24X Fiche 50-329, 84/07/18, 8408010061

--8408170187 Forwards rept results re special electrical overinsp requested by NRC to support testimony concerning adequacy of certification/qualification process of Bechtel electrical QC inspectors
SHAEFFER, M J Consumers Power Co BX19 015 82/02/25 COOKE, R NRC - No Detailed Affiliation Given BIRD, W R , COOK, J W Consumers Power Co 14pp 26531 048 24X Fiche 50-329, 84/07/18, 8408010061

--8408170195 Draft "Rept on Cable Installation "
* Consumers Power Co BX19 014 82/05/14 111pp 26531 038 24X Fiche 50-329, 84/07/18, 8408010061

--8408170205 Forwards IE Insp Repts 50-329/82-07 & 50-330/82-07 on 820421-23 No noncompliance noted Schedule for reinsp program of piping suspension sys requested within 25 days from receipt of ltr
* Region 3, Office of Director BX19 017 82/07/15 Consumers Power Co 2pp 26531 071 24X Fiche 50-329, 84/07/18, 8408010061

--8408170223 Requests Commission review Director's Decisions DD-83-16 & DD-84-02 to require all ongoing activity be included under order of mod of CP & remove util from managerial responsibility of QA/QC function
GARDE,B P Government Accountability Project BX19 022 2 206
84/02/10 PALLADINO,N , GILINSKY,V , ASSELSTINE,J Commissioners
72pp 26532 090 24X Fiche 50-329,84/07/18,8408010061

--8408170232 Forwards SALP Repts 50-329/82-14 & 50-330/82-14 for period Jul 1980 - June 1981
KEPPLER,J G Region 3, Office of Director BX19 026 84/07/18
COOK,J W Consumers Power Co 2pp 26533 158 24X
Fiche 50-329,84/07/18,8408010061

--8408170236 Ack receipt of 820114 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/81-12 & 50-330/81-12
NORELIUS,C E Division of Engineering BX19 028 82/02/03
COOK,J W Consumers Power Co 4pp 26533 188 24X
Fiche 50-329,84/07/18,8408010061

--8408170253 Discusses W Marshal telcon re permanent dewatering well being drilled at northeast corner of diesel generator bldg on 820519 Drilling mud flushed into line when drilling line broke No further comment necessary
LANDSMAN,R B Region 3, Office of Director BX19 031 82/06/14
PATON,W Office of the Executive Legal Director 2pp 26533 325
24X Fiche 50-329,84/07/18,8408010061

--8408170257 Summary of ACRS Subcommittee on Midland Units 1 & 2 820520 & 21 meetings w/util in Midland,MI re review of OL application
FISCHER,D ACRS - Advisory Committee on Reactor Safeguards. BX19 032 82/08/09 OKRENT,D ACRS - Advisory Committee on Reactor Safeguards 13pp 26533 359 24X Fiche 50-329,84/07/18, 8408010061

--8408170260 Informs of review of encl allegations re Comstock QC at site Ofc of Investigations responsible for continuing investigation
WARNICK,R F Region 3, Office of Director BX19 033 82/11/16
FOSTER,J E Office of Investigation 125pp 26534 010 24X
Fiche 50-329,84/07/18,8408010061

--8408170268 Discusses 830922 off-the-record meeting w/Bechtel employee re allegations concerning inadequacy of plant fire detection sys Concerns raised re copyright laws concerning App R to 10CFR50
BURGESS,B L Region 3, Office of Director BX19 034 83/09/26
ROY,G W Region 3, Office of Director 39pp 26534 246 24X
Fiche 50-329,84/07/18,8408010061

--8408170271 Requests Ofc of Investigations provide investigator to assist Ofc of Special Cases in closeout of unresolved item in Insp Rept 329/82-22-27 re use of unofficial documents for recording nonconformances & deficiencies
WARNICK,R F NRC - No Detailed Affiliation Given BX19 035
83/01/27 PAWLIK,E T Region 3, Office of Director 1p
26534 295 24X Fiche 50-329,84/07/18,8408010061

--8408170274 Discusses 831021 interview w/A Gautam & unnamed individual re allegations concerning Comstock,Bechtel & Zack const activities at plant Details of issues referred to Ofc of Investigation & Ofc of Inspector & Auditor
HAWKINS,F C Region 3, Office of Director BX19 036 83/10/26
Region 3, Office of Director 1p 26534 296 24X
Fiche 50-329,84/07/18,8408010061

--8408170276 Forwards util repts re auxiliary bldg seismic analysis & cracks in borated water storage tank foundation;per util B10121-22 notifications Const deficiency info may aid in resolution of matter
NORELIUS,C E Division of Engineering BX19 036A0 81/11/24
EISENHUT,D G Division of Licensing 1p 26535 165 24X
Fiche 50-329,84/07/18,8408010061

--8408170279 "Structural Stresses Induced by Differential Settlement of Diesel Generator Bldg "
* Consumers Power Co BX19 037 84/07/18 51pp 26535 285
24X Fiche 50-329,84/07/18,8408010061

--8408170284 Summary of 810502-04 meeting w/util & Bechtel in Bethesda,MD re remedial actions & update of soils deficiencies & to review Amend 85 to application
LANDSMAN,R B Region 3, Office of Director BX19 039 81/05/12
WILLIAMS,C C Region 3, Office of Director 65pp 26536 043
24X Fiche 50-329,84/07/18,8408010061

--8408170292 Transcript of B Stamiris 840425 statement re soil settlement problems at plant
STAMIRIS,D G Stamiris, B BX19 041 84/04/25 3pp 26536 134
24X Fiche 50-329,84/07/18,8408010061

--8408170297 Transcript of M Sinclair 840425 statement re problems w/util announced Dec 1986 const completion date Documentation encl
SINCLAIR,M Sinclair, M BX19 042 84/04/25 10pp 26536 137
24X Fiche 50-329,84/07/18,8408010061

--8408170304 Transcript of T Hearron 840425 statement opposing completion,licensing & operation of plant
HEARRON,T Lone Tree Council BX19 043 84/04/25 4pp
26536 147 24X Fiche 50-329,84/07/18,8408010061

--8408170312 Transcript of DP Garde 840425 statement re Govt Accountability Project 840210 supplemental 10CFR2 206 petition,mgt breakdown,NRC action problems & adequate Commission review of complex project
GARDE,D P Government Accountability Project BX19 044
84/04/25 19pp 26536 151 24X Fiche 50-329,84/07/18,8408010061

--8408170320 Summary of 840202-05 meeting w/util,Bechtel & consultants in Ann Arbor,MI re discussion & audit of preparations for underpinning southern part of auxiliary bldg Viewgraphs encl
HOOD,D Licensing Branch 4 BX19 045 84/02/22 Licensing
Branch 4 81pp 26536 189 24X Fiche 50-329,84/07/18,8408010061

--8408170338 S&W 840209 public meeting re cracking criteria & cracking mapping program
* Consumers Power Co BX19 046 84/02/09 Consumers Power Co
2pp 26536 349 24X Fiche 50-329,84/07/18,8408010061

--8408170360 Submits list of documents supplied or withheld by JJ Harrison & RB Landsman,in response to FOIA Request 84-24
WARNICK,R F Region 3, Office of Director BX19 047 84/01/18
SMITH,P T Region 3, Office of Director 2pp 26536 351 24X
Fiche 50-329,84/07/18,8408010061

--8408170365 Handwritten summary of 840104 public meeting w/util,S&W Bechtel re monthly activities,crack rept,crack mapping & open items Supporting documentation & attendance list encl
* Consumers Power Co BX19 048 84/01/13 Consumers Power Co
74pp 26536 356 24X Fiche 50-329,84/07/18,8408010061

--8408170367 Crack mapping monitoring status rept for 831031-1130, including handwritten status rept of 831208 S&W meeting & info re grillage acceptance criteria
* Consumers Power Co BX19 049 84/08/01 10pp 26537 107
24X Fiche 50-329,84/07/18,8408010061

--8408170372 Handwritten summary of 831110 public meeting Re tracking open items of new crack monitoring procedures 831009-1105
* Consumers Power Co BX19 050 83/11/10 Consumers Power Co
3pp 26537 129 24(Fiche 50-329,84/07/18,8408010061

--8408170374 Rev 44 & 47 to FSAR Response to Audit Point 1 & handwritten summaries of S&W 831013 public meeting encl
* Consumers Power Co BX19 051 84/08/01 34pp 26537 170
24X Fiche 50-329,84/07/18,8408010061

--8408170377 Handwritten notes re auxiliary bldg & underpinning design including settlement stress,results of areas of max stress & rigid body rotation
* Consumers Power Co BX19 053 84/08/01 76pp 26537 253
24X Fiche 50-329,84/07/18,8408010061

--8408210367 Agenda for 780502 site visit w/util Bechtel & NUS Agenda for 781204 meeting w/util & Bechtel on site encl
* NRC - No Detailed Affiliation Given BX18 001 78/05/02
NRC - No Detailed Affiliation Given 6pp 26521 049 24X
Fiche 50-329,84/07/18,8408010061

--8408210377 Notification of 780907 meeting w/Midland Technical Reviewers in Washington,DC to discuss project status of facility safety review Reviewers will be asked to summarize review status on problem areas affecting review schedule
HOOD,D Light Water Reactors Branch 4 BX18 003 78/09/06
NRC - No Detailed Affiliation Given 7pp 26521 091 24X
Fiche 50-329,84/07/18,8408010061

--8408210379 Provides info in response to B Garde FOIAs 83-451,-452,-454 & -449
HOOD,D Licensing Branch 4 BX18 023 83/08/19 WILSON,V NRC
- No Detailed Affiliation Given 2pp 26524 336 24X
Fiche 50-329,84/07/18,8408010061

--8408210384 Notification of rescheduled 790718 meeting w/util & Bechtel in Bethesda,MD to discuss abnormal settlement of fill & structures at site Agenda & attendance list encl
HOOD,D Light Water Reactors Branch 4 BX18 004 79/06/13
VARGA,S A Light Water Reactors Branch 4 7pp 26521 100 24X
Fiche 50-329,84/07/18,8408010061

--8408210386 Forwards B Garde FOIA request for documents re meetings between NRC, TERA & util on 830518, 0608 & 23 concerning independent design verification W/draft ltr to util re implementation of Ford Amend
WILSON, V H Management Analysis Branch BX18 024 83/08/09
Management Analysis Branch 2pp 26524 338 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210391 Notice of W Ferris, S Afifi & J Wanzeck 801028-29 deposition in Ann Arbor, MI re 791206 order modifying const permits
Related info encl
PATON, W D Office of the General Counsel BX18 005 OM
80/10/06 68pp 26521 126 24X Fiche 50-329, 84/07/18, 8408010061

--8408210392 Forwards B Garde FOIA 83-452 request for documents re 830615 Commission briefing
WILSON, V H Management Analysis Branch BX18 025 83/08/09
Management Analysis Branch 2pp 26524 354 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210397 Forwards B Garde FOIA 83-454 request for documents re re-review of structural adequacy of diesel generator bldg
WILSON, V H Management Analysis Branch BX18 026 83/08/10
LEAR, G Hydrologic & Geotechnical Engineering Branch BOSNAK, R
Mechanical Engineering Branch 2pp 26524 358 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210398 Notice of B Dahr 801217 deposition in Ann Arbor, MI re issues set forth in Licensing Board 791206 order modifying const permits & contentions of intervenors Stamiris & Warren.
Resume of TR Thiruvengadam encl
* Atomic Safety and Licensing Board Panel BX18 006 OM
80/12/11 5pp 26521 199 24X Fiche 50-329, 84/07/18, 8408010061

--8408210401 Forwards B Garde FOIA Request 83-449 for documents submitted by util re consideration of candidate companies or methodologies to perform const implementation overview of const completion plan
WILSON, V H Management Analysis Branch BX18 027 84/08/09
Management Analysis Branch 2pp 26525 001 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210404 Determines that info transmitted by 830721 memo should be issued as Board Notification 83-106
EISENHUT, D G Division of Licensing BX18 028 84/07/18
NOVAK, T Assistant Director for Licensing 1p 26525 152 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210410 Board Notification 83-016 forwards notice of violation & proposed imposition of civil penalties, based on util failure to implement adequate QA program for installation of electrical, mechanical & civil components
NOVAK, T M Division of Licensing BX18 029 OM 84/02/15
Atomic Safety and Licensing Board Panel 1p 26525 160 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210411 Handwritten questions for RB Peck re consultant responsibilities & settlement monitoring Handwritten deposition of RB Beck encl
* NRC - No Detailed Affiliation Given BX18 008 81/01/31
NRC - No Detailed Affiliation Given 36pp 26521 228 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210414 Forwards Board Notification 83-16 which supersedes 830215 notification
NOVAK, T M NRC - No Detailed Affiliation Given BX18 030
84/02/10 Atomic Safety and Licensing Board Panel 1p
26525 184 24X Fiche 50-329, 84/07/18, 8408010061

--8408210418 Submits package received from B Jones from H Singh, consisting of questions of Dr Peck by H Singh, J Dunnicliff 800208 ltr to S Afifi & summary of J Kane deposition
SINGH, H NRC - No Detailed Affiliation Given BX18 009
84/07/18 JONES, B NRC - No Detailed Affiliation Given 36pp
26521 269 24X Fiche 50-329, 84/07/18, 8408010061

--8408210421 "Questions for Davisson 810114-15 Deposition " Questions of Dr Peck on testimony, dtd 810725 encl
* NRC - No Detailed Affiliation Given BX18 010 81/01/11
34pp 26521 305 24X Fiche 50-329, 84/07/18, 8408010061

--8408210425 "Questions for Davisson 810114-15 Deposition "
* NRC - No Detailed Affiliation Given BX18 011 81/01/11
43pp 26522 070 24X Fiche 50-329, 84/07/18, 8408010061.

--8408210430 Draft memo informing of status of NRC-03-79-16T, Task 1, Subtask 3 Index of Davisson deposition encl.
SINGH, H NRC - No Detailed Affiliation Given BX18 012
80/10/16 LEAR, G Hydrologic & Geotechnical Engineering Branch
17pp 26522 116 24X Fiche 50-329, 84/07/18, 8408010061

--8408210433 Recommends issuance of encl matl as Board Notification 84-083 re update on stop work status & NRC staffing changes
Related info encl
EISENHUT, D G Division of Licensing BX18 016 84/04/18
NOVAK, T Division of Licensing 2pp 26522 350 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210446 Summary of 820202-05 meeting w/util & Bechtel in Ann Arbor, MI re audit preparations for underpinning southern portion of auxiliary bldg Bechtel meeting notes & viewgraphs encl
HOOD, D Licensing Branch 4 BX18 019 84/02/22 Licensing
Branch 4 79pp 26523 232 24X Fiche 50-329, 84/07/18, 8408010061

--8408210450 Determines that encl rept on review of diesel generator bldg should be issued as Board Notification 83-165
EISENHUT, D G Division of Licensing BX18 020 83/10/28
NOVAK, T Assistant Director for Licensing 4pp 26524 302 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210453 "Observed Settlements (Inches) of Structures, 790930 to Present " Summary of soil properties & summary of soils info encl
WANZEC, T NRC - No Detailed Affiliation Given BX18 037
80/08/27 10pp 26527 199 24X Fiche 50-329, 84/07/18, 8408010061

--8408210454 Submits marked-up ltr re program for plant soils remedial work, in response to draft SER open items
COOK, J W Consumers Power Co BX18 047 82/09/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 47pp 26528 039
24X Fiche 50-329, 84/07/18, 8408010061

--8408210455 Agenda for 800930 meeting w/util on site for appeal of NRC position
* NRC - No Detailed Affiliation Given BX18 038 84/07/18
NRC - No Detailed Affiliation Given 1p 26527 209 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210461 Trip rept of 831005-07 site visit re design review & audit of HVAC sys
TERAO, D Mechanical Engineering Branch BX18 052 83/10/28
BOSNAK, R J Mechanical Engineering Branch 17pp 26528 234 24X
Fiche 50-329, 84/07/18, 8408010061

--8408210463 Draft notes recommending that listed actions be considered by Region III in effort to improve licensee regulatory attitude & performance & increase assurance that completed & ongoing const work acceptable
* NRC - No Detailed Affiliation Given BX18 046 82/08/06 4pp
26528 034 24X Fiche 50-329, 84/07/18, 8408010061.

--8408210464 Notifies of 830708 meeting to discuss NRR SALP III assessment based on recent hearing testimony by Region III & several third-party reviewers
NOVAK, T M Assistant Director for Licensing BX18 055 83/07/07
JOHNSTON, W , KNIGHT, J P , RUBENSTEIN, L NRC - No Detailed
Affiliation Given 11pp 26528 262 24X Fiche 50-329, 84/07/18, 8408010061

--8408220059 Responds to 830829 ltr re imposition of civil penalty for violations noted during Insp 83-23 Penalty reduced because of prompt corrective actions Check encl
COOK, J W Consumers Power Co BX19 052 25914 83/09/26
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 2pp 26537 208 24X Fiche 50-329, 84/07/18, 8408010061

--8408220064 Testimony of RN Gardner re qualification of Bechtel QC personnel Certificate of Svc & related info encl
GARDNER, R N Region 3, Office of Director BX19 023, OL
82/01/22 120pp 26532 292 24X Fiche 50-329, 84/07/18, 8408010061

--8408220070 Delineates Control Sys Branch position on identification of protection sys instrument sensing lines & requests position be transmitted to near-term OL applicants
SPEIS, T P Assistant Director for Reactor Safety BX19 025
84/07/18 TEDESCO, R L Assistant Director for Licensing. 3pp
26533 051 24X Fiche 50-329, 84/07/18, 8408010061

--8408220078 SALP Rpts 50-329/82-14 & 50-330/82-14 for Jul 1980 - June 1981.
* Region 3, Office of Director BX19 027, 50-330/82-14
82/03/31 28pp 26533 160 24X Fiche 50-329, 84/07/18, 8408010061

--8408220085 Attendance list of 820223 meeting w/util, chronological list events before & after issuance of NRC order modifying CPs, plant underpinning questions re svc water pump structure & review of 1981 technical rept on underpinning
* NRC - No Detailed Affiliation Given BX19 036A 82/02/23.
38pp 26534 327 24X Fiche 50-329, 84/07/18, 8408010061.

--8408220090 "Observed Cracks in Walls of Midland Plant Structures "
CORLEY,W G ; FIORATO,A E Portland Cement Association BX19 031A
82/06/14 32pp 26533 327 24X Fiche 50-329,84/07/18,
8408010061

--8408270315 Draft ltr informing of decision re addl soil borings & testing NRC request for sampling & testing coaling pond enbankments reconsidered & relocation of certain borings determined
VOLLMER,R H Division of Engineering BX18 010A 80/11/03
COOK,J W Consumers Power Co 1p 26522 022 24X
Fiche 50-329,84/07/18,8408010061

--8408270323 Submits listed items that inspectors consider to be indicative of questionable licensee performance
COOK,R J Region 3, Office of Director BX19 019 82/07/23
WARNICK,R F Region 3, Office of Director 11pp 26531 291 24X
Fiche 50-329,84/07/18,8408010061

--8408270330 Forwards summary of 840229 meeting w/Region III & util in Region III re results of insps & investigation into allegations re HVAC work
WELLS,R A Consumers Power Co BX19 020 28921 84/03/24
HARRISON,J J Region 3, Office of Director 17pp 26532 023
24X Fiche 50-329,84/07/18,8408010061

--8408270336 Testimony of BP Garde re Midland Nuclear Power Plant
GARDE,B P Government Accountability Project BX19 021
84/02/13 22pp 26532 040 24X Fiche 50-329,84/07/18,8408010061

--8309270518 Forwards comments on util proposed findings of fact & conclusions of law on remedial soils issues
JACKSON,R E Geosciences Branch BX17 038 83/09/21 PATON,W D
Hearing Branch 2 5pp 26520 064 24X Fiche 50-329,84/07/18,
8408010061

8408140311 Summary of 810717 meeting w/CPC re preliminary design of mods to svc water pump structure to resolve concerns resulting from inadequate compaction of site fill
KANE,J NRC - No Detailed Affiliation Given BX16 043 81/10/30
NRC - No Detailed Affiliation Given 2pp 26511 339 24X
Fiche 50-329,84/07/18,8408040061

8408310135 Responds to FOIA request for all documents made publicly available per R Belair FOIA Request 84-250 Documents available in PDR
FELTON,J M Division of Rules and Records 84/05/30 SAYLOR,N S
Hunton & Williams 1p 26352 016

8408310137 FOIA request for all documents made publicly available per R Belair FOIA Request 84-250
SAYLOR,N S Hunton & Williams 84/05/15 FELTON,J M Division of Rules and Records 2pp 26352 017

8408310138 FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by PG&E re earthquake on Nacimiento fault & one equal to 1906 San Francisco earthquake
CALSOYAS,C D Affiliation Not Assigned 84/04/07 NRC - No
Detailed Affiliation Given 4pp 26352 011 24X
Fiche 50-275,84/04/07,8408310138

8408310142 Responds to FOIA request for positive identification of Mothers for Peace of San Luis Obispo & calculations performed by PG&E re earthquake Forwards printout of documents re Mothers for Peace Other documents in PDR
FELTON,J M Division of Rules and Records 84/06/01 CALSOYAS,C D
Affiliation Not Assigned 1p 26352 015 24X
Fiche 50-275,84/06/01,8408310142

8408310147 Partial response to FOIA request for detailed instruction re use of risk assessment techniques & analysis & calculations on which ground accelerations for design & max hypothetical earthquake based Documents available in PDR
FELTON,J M Division of Rules and Records 84/06/01 CALSOYAS,L D
Affiliation Not Assigned 1p 26351 358 24X
Fiche 50-344,84/06/01,8408310147

8408310149 FOIA request for detailed instructions re use of risk assessment techniques & analysis & calculations on which ground accelerations for design & max hypothetical earthquake based
CALSOYAS,C D Affiliation Not Assigned 84/05/12 NRC - No
Detailed Affiliation Given 4pp 26351 359 24X
Fiche 50-344,84/05/12,8408310149

8408310151 Responds to FOIA request for documents between UCLA & NRC re current reactor shutdown & records re proposed work to be performed during shutdown Forwards WF Wegst 840213 ltr to NRC
FELTON,J M Division of Rules and Records 84/06/04 HIRSCH,D
Committee to Bridge the Gap 1p 26351 355 24X
Fiche 50-142,84/06/04,8408310151

8408310152 FOIA request for all correspondence or other documents between UCLA & NRC re incident occurring in early Feb 1984, which led to current shutdown of UCLA research reactor
HIRSCH,D Committee to Bridge the Gap 84/04/24 Office of Administration 1p 26351 356 24X Fiche 50-142,84/04/24,
8408310152

8408310155 Final response to FOIA request for documents re suppression pool scrubbing experiments conducted by GE & Battelle No further documents located subj to request
FELTON,J M Division of Rules and Records 84/05/30 BHOLLY,S
Union of Concerned Scientists 1p 26351 353

8408310156 FOIA request that SECY-84-29 & encl of PL William 840303 ltr re functional description of safety parameter display sys be placed in PDR
DOVE,K Affiliation Not Assigned 84/04/12 FELTON,J M Division
of Rules and Records 1p 26352 001 24X Fiche 50-461,84/04/12,
8408310156

GEN TEC IS GENERIC TECHNICAL ISSUES

8406230301 NUREG/CR-3704
THREE-DIMENSIONAL CALCULATIONS OF TRANSIENT FLUID-THERMAL MIXING IN THE DOWNCOMER OF THE CLAVERT CLIFFS-1 PLANT USING SOLA-PTS
DALY,B J Los Alamos Scientific Laboratory FIN A-7306
LA-10039-MS 84/04/30 Division of Accident Evaluation 86pp
25131 319 24X Fiche 50-317,84/04/30,8406230301

8407170313 Requests review of draft NUREG-1032,App A re loss of offsite power frequency & duration relationship & of ORNL draft rept on loss of offsite power operating experience Comments requested by 840801 W/o encl
BARANOWSKY,P W Reactor Risk Branch 84/07/11 KNIEL,K Generic Issues Branch 2pp 26068 061

--8407170316 Forwards draft loss of offsite power frequency & duration analyses Results indicate significant reduction in estimated frequency & duration of loss of power transient & contradict previous EPRI findings Review requested for 840731 meeting
BARANOWSKY,P W Reactor Risk Branch 84/07/11 BERGER,W E
Sargent & Lundy, Inc 96pp 26068 063

8408010042 Summary of CROR Meeting 66 on 840711 re status of long-range plans to address BWR pipe cracking due to IGSCC & review of proposed resolution of Unresolved Safety Issue A-43 re containment emergency sump
STELLO,V Committee to Review Generic Requirements 84/07/24
DIRCKS,W J Office of the Executive Director for Operations 2pp
25854 038

8408010159 Forwards summary of CROR activities for Jul 1984 Summary will be included in EDO weekly rept to Commission for wk ending 840803
SNIEZEK,J Regional Operations & Generic Requirements 84/07/30
Committee to Review Generic Requirements 4pp 25854 040

8408010161 Notification of 840727 meeting w/util at site to discuss questions re control of heavy loads (Multi-Plant Action C-15)
NEIGHBORS,D Operating Reactors Branch 1 84/07/20 VARGA,S A
Operating Reactors Branch 1 2pp 25873 304 24X
Fiche 50-280,84/07/20,8408010161

8408020213 Comments on Metal Components Subcommittee 840517 & 18 meetings re pressurized thermal shock
BENDER,M Affiliation Not Assigned BENDER,M ACRS - Advisory
Committee on Reactor Safeguards 84/06/13 AXTMANN,R ACRS -
Advisory Committee on Reactor Safeguards 4pp 25898 164

8408020248 Summarizes DHR Subcommittee 840605 meeting re Unresolved Safety Issue A-45, "Shutdown DHR Requirement " Various studies do not contain all elements along heat flow path from heat source to heat sink
CATTON,I ACRS - Advisory Committee on Reactor Safeguards
84/06/11 BOEHNERT,P ACRS - Advisory Committee on Reactor
Safeguards 2pp 25898 145

8408030019 Forwards responses to J Singh 840522 verbal questions re control of heavy loads
MILLS,L M Tennessee Valley Authority 84/07/27 ADENSAM,E
Licensing Branch 4 2pp 25907 092 24X Fiche 50-327,84/07/27,
8408030019

--8408030025 Rev 3 to Procedure MI-6 22, "Control of Heavy Loads in Critical Lifting Zones - NUREG-0612 "
DOTY,J W Tennessee Valley Authority 84/05/21 23pp
25907 094 24X Fiche 50-327,84/07/27,8408030019

8408070075 Forwards request for addl info re pressurized thermal shock flux reduction program Response requested within 3 wks of ltr receipt W/o encl
VARGA,S A Operating Reactors Branch 1 84/07/26 WILLIAMS,J W
Florida Power & Light Co 2pp 25955 317 24X
Fiche 50-250,84/07/26,8408070075

8408070076 Advises of completion of review of AEOD/C403, "Case Study Rept for EI Hatch,Unit 2 Plant Sys Interaction Event on 820825 " Case study recommends event be considered in developing final positions relative to NUREG-0803
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/07/30 HELTEMES,C J Director's Office 2pp 25955 272 24X
Fiche 50-366,84/07/30,8408070076

8408070446 Requests exemption from 10CFR50,App A,GDC 4 re elimination of postulated circumferential & longitudinal breaks in RCS main loop piping & WCAP-10559 & WCAP-10560 Repts withheld (ref 10CFR2 790)
GOLDBERG,J H Houston Lighting & Power Co GL-84-04 84/07/17
DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp
25940 349 24X Fiche 50-498,84/07/17,8408070446

8408070515 Forwards "NUREG-0612,Control of Heavy Loads," final rept Submittal contains evaluation results & resolutions of open items since 840326 submittal
KOBER,R W Rochester Gas & Electric Corp 84/07/31 PAULSON,W A
Operating Reactors Branch 5 1p 25941 172 24X
Fiche 50-244,84/07/31,8408070515

--8408070516 "NUREG-0612,Control of Heavy Loads," final rept
* Rochester Gas & Electric Corp 84/08/31 12pp 25941 173
24X Fiche 50-244,84/07/31,8408070515

8408080472 NUREG/CR-3840
COST ANALYSIS FOR POTENTIAL MODIFICATIONS TO ENHANCE THE ABILITY OF A NUCLEAR PLANT TO ENDURE STATION BLACKOUT
CLARK,R A , THOMAS,W R Science & Engineering Associates, Inc
RIGRDON,B J MATHTECH, Inc FIN B-8838 84/07/31 Division of Budget & Analysis 167pp Available at NRC $5 50 25980 160

8408090530 Forwards request for addl info for review of 840214 submittal re control of heavy loads Tech Spec change Response requested within 45 days of ltr receipt
VARGA,S A Operating Reactors Branch 1 84/08/01 O'TOOLE,J
Consolidated Edison Co of New York, Inc 4pp 25983 332 24X
Fiche 50-247,84/08/01,8408090530

8408130233 Forwards safety evaluation & technical evaluation rept re control of heavy loads,Phase 1
VARGA,S A Operating Reactors Branch 1 84/07/25 MCDONALD,R P
Alabama Power Co 2pp 26060 027 24X Fiche 50-348,84/07/25,
8408130233

--8408130258 SER re control of heavy loads,Phase 1 Phase 1 acceptable
* NRC - No Detailed Affiliation Given 84/07/25 2pp
26060 029 24X Fiche 50-348,84/07/25,8408130233

8408130449 Forwards "Control of Heavy Loads (Phase II-NUREG-0612) for Commanche Peak,Units 1 & 2," draft technical evaluation rept
YOUNGBLOOD,B J Licensing Branch 1 84/07/26 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
3pp 26059 271 24X Fiche 50-445,84/07/26,8408130449

--8408130455 "Control of Heavy Loads (Phase II-NUREG-0612),Commanche Peak,Units 1 & 2," draft technical evaluation rept
YEN,T C EG&G, Inc FIN A-6457 84/04/30 NRC - No Detailed Affiliation Given 40pp 26059 274 24X Fiche 50-445,84/07/26,
8408130449

8408160035 Informs that util plans to prepare general safety evaluation to expand safe load path boundaries in reactor bldg Evaluation will be submitted for review by 841101
KANGA,B K General Public Utilities - GPU Service Corp
4410-84-L-0131 84/08/10 SNYDER,D J TMI Program Office 2pp
26092 050 24X Fiche 50-320,84/08/10,8408160035

8408160248 NUREG/CR-3761
RELAP5 THERMAL-HYDRAULIC ANALYSES OF PRESSURIZED THERMAL SHOCK SEQUENCES FOR THE OCONEE-1 PRESSURIZED WATER REACTOR
FLETCHER,C D , BOLANDER,M A , STITT,B D EG&G, Inc FIN A-6047
EGG-2310 84/07/31 Division of Accident Evaluation 165pp.
26125 001 24X Fiche 50-269,84/07/31,8408160248

8408170316 Summarizes ACRS 292nd meeting on 840809-11 re Task Action Plan A-45, "Shutdown DHR Requirements " Effort to apportion quantitative reliability goals among plant subsys endorsed
EBERSOLE,J C ACRS - Advisory Committee on Reactor Safeguards
84/08/14 DIRCKS,W J Office of the Executive Director for Operations 2pp 26114 280

8408210396 Forwards info documenting results of review & implementation of required changes & mods,per Generic Ltr 81-07, "Control of Heavy Loads" & NUREG-0612 Minor error noted in 801222 ltr corrected
TUCKER,H B Duke Power Co GL-81-07 84/08/17 DENTON,H R
Office of Nuclear Reactor Regulation, Director 36pp 26180 271
24X Fiche 50-369,84/08/17,8408210396

8408220326 Forwards safety evaluation & technical evaluation rept re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants - Phase I " Sections 5 1 1 & 5 3 satisfied Phase I acceptalbe
PAULSON,W A Operating Reactors Branch 5 LSO5-84-08-026
84/08/20 COUNSIL,W G Connecticut Yankee Atomic Power Co 2pp,
26193 111 24X Fiche 50-213,84/08/20,8408220326

--8408220330 Safety evaluation re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants - Phase I "
* Operating Reactors Branch 5 84/08/20 2pp 26193 113 24X
Fiche 50-213,84/08/20,8408220326

--8407300136 TER-C5506-358
"Control of Heavy Loads,Connecticut Yankee Atomic Power Co, Haddam Neck Plant," technical evaluation rept
DOMBERGER,C Franklin Institute/Franklin Research Center
NRC-03-81-130 TAC 07993 84/07/25 SINGH,A NRC - No Detailed Affiliation Given 24pp 26193 115 24X Fiche 50-213,84/08/20,
8408220326

8408220363 Forwards response to request for addl info re control of heavy loads mods,per NUREG-0612,resulting from discussions w/Franklin Research Ctr & Rev 0 to Procedure 1408-6, "Procedure for Insp of Wire Rope or Synthetic Slings "
HUKILL,H D General Public Utilities - GPU Service Corp
5211-84-2200 84/08/16 EISENHUT,D G Division of Licensing 6pp
26189 324 24X Fiche 50-289,84/08/16,8408220363

8408230172 Forwards ORNL draft "Chapter 9 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Sequences," of pressurized thermal shock rept Comments requested by 840822
JOHNSON,C NRC - No Detailed Affiliation Given 84/07/30 WOODS,R
NRC - No Detailed Affiliation Given 1p 26230 028 24X
Fiche 50-317,84/07/30,8408230172

--8408230184 Forwards ORNL draft "Chapter 9 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Sequences," of pressurized thermal shock rept Comments requested by 840822
SELBY,D L Oak Ridge National Laboratory 84/07/30 JOHNSON,C E
NRC - No Detailed Affiliation Given KOENIG,J E Los Alamos Scientific Laboratory MIRSKY,S M Baltimore Gas & Electric Co
1p 26230 029 24X Fiche 50-317,84/07/30,8408230172

8408230292 Forwards Rev 3 to "Overhead Handling Sys Review " Rept revised,per NUREG-0612,to address concerns identified in draft technical evaluation rept on control of heavy loads & support resolution of SER License Condition 7
KEMPER,J S Philadelphia Electric Co 84/08/13 SCHWENCER,A
Licensing Branch 2 3pp 26207 001 24X Fiche 50-352,84/08/13,
8408230292

--8408230297 Rev 3 to final rept "Overhead Handling Sys Review "
* Philadelphia Electric Co 84/08/30 175pp 26207.004 24X
Fiche 50-352,84/08/13,8408230292

8408280199 Documents closeout of several issues raised by NRC during review of responses to requirements of Generic Ltr 81-14, "Seismic Qualification of Auxiliary Feedwater Sys " Any mods will be made per Generic Issue A-46
ZIMMERMAN,S R Carolina Power & Light Co NLS-84-258 84/08/23.
VARGA,S A Operating Reactors Branch 1 1p 26275 362 24X
Fiche.50-261,84/08/23,8408280199

8408280238 Forwards addl neutron source data for NRC review of pressurized thermal shock flux reduction program,per 840726 request
WILLIAMS,J W Florida Power & Light Co L-84-216 84/08/22
VARGA,S A Operating Reactors Branch 1 36pp 26262 243. 24X
Fiche 50-250,84/08/22,8408280238

8408280290 Forwards draft technical evaluation rept re control of heavy loads;for review & comment Project manager should be contacted within 30 days to discuss outstanding items W/o encl
VARGA,S A Operating Reactors Branch 1 84/08/20 O'TOOLE,J D
Consolidated Edison Co. of New York, Inc 1p 26274 086 24X
Fiche:50-247,84/08/20,8408280290

8408280319 Forwards draft technical evaluation rept, "Control of Heavy Loads - Phase II,Davis-Besse Nuclear Power Station Unit 1," for review
STOLZ,J F Operating Reactors Branch 4 TAC 52271 84/08/17
CROUSE,R P Toledo Edison Co 2pp 26294 053 24X
Fiche 50-346,84/08/17,8408280319

--8408280321 TER-C5506-489 DRFT
Draft "Control of Heavy Loads - Phase II, Davis-Besse Nuclear Power Station Unit 1," technical evaluation rept
BOMBERGER, C R , WALTER, R J , SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 52271
84/07/10 SINGH, A NRC - No Detailed Affiliation Given 26pp
26294 035 24X Fiche 50-346, 84/08/17, 8408280319

8408290562 Summary of ACRS Subcommittee on DHR Sys 840605 meeting in Washington, DC re resolution effort for Unresolved Safety Issue A-45, "Shutdown DHR Sys "
* ACRS - Advisory Committee on Reactor Safeguards 84/06/21
ACRS - Advisory Committee on Reactor Safeguards 27pp 26310 232

8408310007 Responds to 840206 ltr on SER License Condition 7 re compliance w/NUREG-0612, control of heavy loads, Phase II "Limerick Overhead Handling Sys Final Rept (Rev 3)" revised per 840206 request Related correspondence
KEMPER, J S Philadelphia Electric Co DSB 293 GL 84/08/18
SCHWENCER, A Licensing Branch 2 3pp 26350 197 24X
Fiche 50-352, 84/08/18, 8408310007

8408230191 Draft "Pressurized Thermal Shock Evaluation of Calvert Cliffs Unit 1 Nuclear Power Plant, Chapter 5 Probabilistic Fracture-Mechanics Analysis of Calvert Cliffs Unit 1 Sequences "
* Oak Ridge National Laboratory 84/07/27 NRC - No Detailed Affiliation Given 169pp 26230 030 24X Fiche 50-317, 84/07/30, 8408230172

I&E INSPECTION AND ENFORCEMENT

8407110250 EN-84-039 on 840710, notice of violation & proposed imposition of civil penalties in amount of $500 will be issued to licensee Action based on failure to comply w/ requirements re mgt oversight & control of radiation safety
FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/07/03 1p 25526 310

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Gould & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON, J M Division of Rules and Records DX14 000 84/07/18
RICE, C M Kirkland & Ellis 2pp 26500 001

--8408150694 PNO-77-035 on 770226, bulge discovered in containment liner plate Caused by water coming through tears in liner plate Addl holes cut in plate to facilitate draining Related info encl
WARNICK, R F Office of Inspection & Enforcement, Office of the Director DX21 030 77/03/01 7pp 26555 154

8408010162 EN-84-050 on 840727, confirmatory order issued to util confirming commitment for immediate cold shut down Action taken because of loss of ac power due to diesel generators not recieving start signal
FARRON, F , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/07/30 1p 25855 304, 24X Fiche 50-388, 84/07/30, 8408010162

8408010164 EN-84-049; on 840730, notice of violation & proposed imposition of civil penalties in amount of $40,000 will be issued to licensee Action involves failure to adequately implement svc life monitoring program for snubbers
KLINGLER, G , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/07/25 1p 25855 305 24X Fiche 50-280, 84/07/25, 8408010164

8408010170 PNO-TMI-84-008B on 840724, reactor vessel closure head set down on storage stand Placement accomplished by use of pry bar & winch attached to containment wall NRC will be supplied w/24 h/day coverage until fixture in place
FASANO, A , GRANT, P. TMI Program Office 84/07/25 1p 25855 320
24X Fiche 50-320, 84/07/25, 8408010170

8408010174 PNO-TMI-84-008A on 840724, reactor vessel closure head lifted clear of reactor vessel flange Licensee devising means of aligning vessel head w/storage stand guide pins in preparation for lowering head to stand
COOK, R , FASANO, A , GRANT, P TMI Program Office 84/07/25 1p
25855 321 24X Fiche 50-320, 84/07/25, 8408010174

8408010220 PNO-TMI-84-008D on 840726, lead shield platform put in place over top of internals indexing fixture While lowering shielding, crane failed Licensee manually unscrewed lifting turnbuckles until platform made contact
COOK, R , FASANO, A , GRANT, P TMI Program Office 84/07/26 1p
25856 026 24X Fiche 50-320, 84/07/26, 8408010220

8408010230 PNO-TMI-84-008C on 840726, licensee lifted internals indexing fixture w/polar crane & lowered fixture into place on reactor vessel flange Containment purging initiated
COOK, R , FASANO, A , GRANT, P TMI Program Office 84/07/26 1p
25856 018 24X Fiche 50-320, 84/07/26, 8408010230

8408010251 EN-84-048 on 840730, notice of violation & proposed imposition of civil penalty issued in amount of $4,000, based on licensee failure to implement effective mgt control over radiation safety program & falsification of records
FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/07/25 1p 25854 341

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 85pp 26067 278 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408020052 PNO-III-84-041 on 840726, insp of shipments found Tc-99m apparently contaminated w/Mo-99 Caused by mfg defect Confirmatory action ltr sent to licensee for commitment to notify all customers of potentially contaminated Tc-99m
WIEDEMAN, D , AXELSON, W L Region 3, Office of Director 84/07/27
2pp 25892 258

8408030002 PNO-I-84-064 on 840731, determined licensee radiographer received quarterly whole body radiation exposure of 4 37 rem for Second Quarter 1984 Investigation to evaluate exposure will be conducted
NICOLOSI, J , JOYNER, J Region 1, Office of Director 84/07/31 1p
25906 023

8408030023 PNO-II-84-045 on 840729, senior resident inspector W Swan fatally injured in traffic accident Funeral svcs held 840801 in Athens, TN
JULIAN, C A , VERRELLI, D M Region 2, Office of Director 84/07/30
1p 25907 086 24X Fiche 50-390, 84/07/30, 8408030023

8408030157 PNO-I-84-062A on 840726, during planned loss of offsite ac power startup test at 30% reactor power, backup emergency diesel generators did not automatically start Caused by incorrectly positioned dc power switches
EGELGROTH, P , GREENMAN, E Region 1, Office of Director 84/07/27
1p 25912 018 24X Fiche 50-388, 84/07/27, 8408030157

8408060013 PNO-V-84-046 on 840728, w/unit in hot standby, inadvertent safety injection actuation occurred Caused by high steam flow signal resulting from surveillance testing in progress
JOHNSON, P , MENDONCA, M M Region 5, Office of Director 84/07/30
1p 25933 183 24X Fiche 50-275, 84/07/30, 8408060013

8408060123 PNO-V-84-045 on 840710, licensee began evaporating highly purified liquid radwaste to dryness, resulting in airborne release of radioactive tritium Approx 5,500 gallons water processed resulting in release of 1 39 Ci to atmosphere
YUHAS, G , WENSLAWSKI, F Region 5, Office of Director 84/07/27
1p 25933 193 24X Fiche 50-312, 84/07/27, 8408060123

8408060156 PNO-V-84-044 on 840723, licensee learned that highly radioactive 2 x 0 6 x 0 1-inch metal object removed from steam generator B primary side inlet Source of metal or extent of personnel exposures not identified
YUHAS, G , WENSLAWSKI, F Region 5, Office of Director 84/07/27
1p 25932 198 24X Fiche, 50-312, 84/07/27, 8408060156

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070135 PNS-V-84-012 on 840727, routine safety patrol discovered suspicious-looking device near control room Device determined not explosive, Technician identified device as electrical test equipment
SCHWAN, C A , SCHUSTER, M D Region 5, Office of Director 84/07/30
1p 25949 342 24X Fiche, 50-397, 84/07/30, 8408070135

8408070205 PNO-I-84-065 on 840802 personnel noted smoke coming from cubicle in switchgear room Caused by tripped breaker due to electrical fault during surveillance testing Damaged bus deenergized Licensee decreasing power for plant shutdown
ELSASSER T GREENMAN,E Region 1 Office of Director 84/08/02
2pp 25949 268 24X Fiche 50-029 84/08/02,8408070205

8408070329 PNO-III-84-062 on 840801, fire broke out in lab fume hood, eventually destroying four Mo-99/Tc-99m generators Low level contamination found in hallway near fire & removed Caused by electrical malfunction Fire extinguished
WIEDEMAN,D G , AXELSON,W L Region 3, Office of Director 84/08/03
1p 25945 143

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
GRACE,J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc
125pp 26129 256 24X Fiche 50-000,84/08/10,8408070376

8408070416 PNO-V-84-047 on 840731, temporary work stoppage occurred following misunderstanding re alleged contamination of const workers on 840730 No contamination found on workers or vehicles Issue resolved by contractor
NORTH,H , WENSLAWSKI F Region 5, Office of Director 84/07/31
1p 25942 052 24X Fiche 50-312,84/07/31,8408070416

8408090176 PNO-IV-84-015 on 840720, liquid release from reactor bldg exceeded Tech Spec gross beta limits by factor of 2 24 Violation not recognized until 840726 Investigation ongoing Special insp of event scheduled for wk of 840730
MURRAY,B , HALL,R Region 4, Office of Director 84/07/27 1p
25994 362 24X Fiche 50-267,84/07/27,8408090176

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000,84/08/13,8408100009

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26197 337 24X Fiche 50-000,84/08/16,8408100021

8408100035 PNO-I-84-065A on 840802, plant shut down following switchgear fire Cause unidentified Extensive bus & switchgear damage found Corrective actions will be monitored
ASARO,A , FERLIC,K Region 1, Office of Director 84/08/03 1p
25990 060 24X Fiche 50-029,84/08/03,8408100035

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000,84/08/15,8408100038

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 120pp 26276 001 24X Fiche 50-000,84/08/17,8408100055

8408100072 PNO-I-84-067 on 840806, indication detected in reactor vessel wall during ultrasonic test Evaluation & review of const records & photographs continuing Startup from 10-yr inservice insp outage scheduled for late Sept 1984
DURR,J P , NORRHOLM,L Region 1, Office of Director 84/08/08 1p
25990 043 24X Fiche 50-247,84/08/08,8408100072

8408100109 PNO-III-84-058B on 840718, licensee successfully completed integrated leak rate test following 840718 shutdown for failure to demonstrate integrity of containment Unit expected to start up by 840816
BUERMANN,J , WRIGHT,G , REYES,L Region 3, Office of Director
84/08/02 1p 25990 362 24X Fiche 50-295,84/08/02,8408100109

8408100129 PNO-I-84-066 on 840807, NRC notified that 5 mCi Kr-85 source stolen during Jan 1984 break-in at Fort Richardson, FL facility Personnel responsible for failure to rept theft immediately reprimanded
JOHANSEN,J , GLENN,J , JOYNER,J Region 1, Office of Director
84/08/08 1p 25988 278

8408140136 PNO-II-84-047 on 840806, licensee reported inventory difference from 840703 physical inventory Difference was accounting loss & within associated limit of error & other regulatory requirements State of TN informed
MCALPINE,E J Region 2, Office of Director 84/08/07 1p
26048 321

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W/ High Failure Rates " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/17 Consolidated Edison Co of New York, Inc 122pp 26276 122 24X Fiche 50-000,84/08/17,8408140208

8408140324 PNO-II-84-046 on 830806, w/unit in cold shutdown, packing ring blew out from chemical & vol control sys letdown line valve connected to RHR sys Line break occurred in auxiliary bldg room socket weld, discharging 3,500 gallons water
IGNATONIS,A , BROWNLEE,V L Region 2, Office of Director 84/08/06
2pp 26042 351 24X Fiche 50-370,84/08/06,8408140324

8408140346 PNO-V-84-048 during present outage for steam generator tube plugging repairs, two swagelok fitting leaks identified in process piping installed during 1983 outage All swagelok fittings undergoing insp Outage extended
MYERS,C , ECKHARDT,J Region 5, Office of Director 84/08/08 1p
26042 325 24X Fiche 50-312,84/08/08,8408140346

8408150466 Forwards draft IE info notice, "Defective Replacement GE Tubes for Eberline Instrument Model 6112B Teletectors " Verification of facts requested by 840815 for consideration in final version
BAER,R L Engineering & Generic Communications Branch 84/08/06
LND, Inc 3pp 26105 232

8408160003 PNO-I-84-068 on 840808, received notification that during routine bioassay on 840803, worker had thyroid burden of approx 500 uCi I-125 Worker performed iodination using 7 mCi I-125 on 840729 Investigation ongoing
DARDEN,T , KINNEMAN,J , JOYNER,J Region 1, Office of Director
84/08/09 1p 26128 214

8408160130 PNS-I-84-016 on 840809, employee discovered box marked "Bomb" adjacent to front door of bldg Local police & fire personnel responded Bomb squad supplied small explosive charge which detonated Bldg searched for addl packages
JOYNER,J , MARTIN,T Region 1, Office of Director 84/08/09 1p
26126 166

8408170369 PNO-V-84-049 on 840812, unusual event declared when prairie brush fire led to potential for loss of offsite 230-kV startup powerlines & 115-kV backup power lines Plant diesel generators started as contingency
TOTH,A D , DODDS,R T Region 5, Office of Director 84/08/13 1p
26112 358 24X Fiche 50-397,84/08/13,8408170369

8408200308 PNO-III-84-063 on 840810, unusual event declared due to leakage from primary coolant sys pressure sensing line isolation valve MV-1019A Weld cracked Piping & weld to be cut out & replaced Startup scheduled by 840816
WRIGHT,G , SHAFER,W Region 3, Office of Director 84/08/13 1p
26133 018 24X Fiche 50-255,84/08/13,8408200308

8408200324 PNO-III-84-064 on 840813, 1,200 gallons of water from refueling water storage tank injected into primary sys via boron injection tank No release of radioactivity occurred Caused by faulty electrical channels
FORNEY,W , WARNICK,R Region 3, Office of Director 84/08/13 1p
26133 001 24X Fiche 50-483,84/08/13,8408200324

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000,84/08/21,8408210142

8408210269 PNO-III-84-065 on 840814, Unit 1 tripped from 100% due to failure of control room instrument distribution panel Failure caused reactor protection sys to lose flow in one coolant loop Panel replaced Tests performed for operability
WRIGHT,G , SHAFER,W Region 3, Office of Director 84/08/15 1p
26180 344 24X Fiche 50-315,84/08/15,8408210269

8408210280 PNO-I-84-068A on 840808, individual working at facility had thyroid burden of 500 mCi I-125 Licensee believes iodine accidently swallowed Contamination levels ranging from 1,000 to 20,000 counts per minute found in apartment
DARDEN,T , KINNEMAN,J , JOYNER,J Region 1, Office of Director
84/08/13 2pp. 26180-345

8408210383 PNO-I-84-069 on 840718, licensee reported five missing lower head steam generator plugs Licensee working w/ Westinghouse to develop method of testing plugs Evaluation continuing
CONNER,E Region 1, Office of Director 84/08/15 1p 26180:251
24X Fiche 50-289,84/08/15,8408210383

8408210407 EN-84-051 on B40817, notice of violation & proposed imposition of civil penalties in amount of $500 will be issued Action based on unauthorized individuals storing source holder in unrestricted area
FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/08/14 1p 26180 338

8408210485 PNO-II-84-050 lung cancer patient received dose of 3,060 rads to portion of lung instead of prescribed dose of 1,500-1,800 rads Caused by failure to insert new filter block in teletherapy device Rept will be submitted within 15 days
CHAMBLESS, P M , POTTER, J P Region 2, Office of Director 84/08/15 2pp 26181 121

8408220139 PNO-V-84-050 on 840815, influx of seaweed caused reduction in circulating water flow Power reduced as condenser vacuum degraded High differential pressure observed on train B component cooling water HX while train A inoperable
KIRSCH, D , HAIST, D Region 5, Office of Director 84/08/15 1p 26194 048 24X Fiche 50-361, 84/08/15, 8408220139

8408230001 PNO-II-84-052 on 840820, leak developed inside containment while upper head injection sys filled & checked for air entrapment Caused by glass on upper head injection sys blown out during pressurization No environ release occurred
IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director 84/08/20 2pp 26209 158 24X Fiche 50-370, 84/08/20, 8408230001

8408230040 PNO-II-84-049 on 840814, possible overpressurization of one core spray sys loop occurred Caused by backflow of primary coolant into loop because outboard isolation valve & inboard isolation check valve leaked
BUTCHER, R C , CANTRELL, F S Region 2, Office of Director 84/08/15 2pp 26204 018 24X Fiche 50-259, 84/08/15, 8408230040

8408230392 PNO-II-84-051 on 840817, earth tremor measuring 3 8 on Richter scale occurred Tremor did not trip plant seismic monitoring equipment
ELROD, S A , DANCE, H C Region 2, Office of Director 84/08/17 1p 26205 303 24X Fiche 50-338, 84/08/17, 8408230392

8408240114 PNO-III-84-066 on 840818, RHR B loop full flow test valve failed to completely close manually, rendering low pressure injection, shutdown cooling & suppression pool cooling inoperable Unit in cold shutdown pending repairs & maint
CHRISSOTIMOS, N , SHAFER, W Region 3, Office of Director 84/08/20 1p 26228 216 24X Fiche 50-374, 84/08/20, 8408240114

8408240283 PNO-I-84-071 on 840821, reactor automatically scrammed due to low water level caused by feedwater control sys failure Scram resulted in primary containment isolation sys Group 1 isolation & tripped recirculation pumps
GALLO, R Region 1, Office of Director 50-278840821 84/08/21 1p 26223 196 24X Fiche 50-278, 84/08/21, 8408240283

8408240286 PNO-II-84-053 on 840820, unit shut down after pressure surge caused opening of ice condenser doors, causing relief tank pressure drop & containment pressure rise Caused by relief tank disc rupture or broken safety valve tailpipe
FREDERICKSON, P , CONTRELL, F B Region 2, Office of Director 84/08/21 2pp 26223 194 24X Fiche 50-328, 84/08/21, 8408240286

8408240287 PNO-V-84-051 on 840818, control rod L-3 bank D, stuck at almost fully withdrawn position during cold rod drop tests Seal weld for control rod guide mechanism will be cut to determine if latching mechanism at fault
DODDS, R T , RICHARDS, S A Region 5, Office of Director 84/08/20 1p 26223 186 24X Fiche 50-344, 84/08/20, 8408240287

8408240290 PNO-II-84-052A on 840820, 4,800 gallons reactor coolant inventory spilled into reactor bldg sump area Caused by sight glass being blown out of upper head injection sys Alarm printer reviewed & sight glass replaced
IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director 84/08/21 2pp 26223 191 24X Fiche 50-370, 84/08/21, 8408240290

8408240329 PNO-II-84-054 on 840821, after Unit 1 reactor tripped, operators manually isolated MSIVs to prevent overcooling, resulting in water hammer in secondary sys Damage being assessed
IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director 84/08/22 2pp 26225 306 24X Fiche 50-369, 84/08/22, 8408240329

8408240357 EN-84-052 on 840822, notice of violation & proposed imposition of civil penalty in amount of $1,600 will be issued Action based on use of unauthorized matl & failure to calibr survey meters at required intervals
FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/08/17 1p 26225 312

8408280068 EN-84-016A on B10330, notice of violation & proposed imposition of civil penalties in amount of $2,500 issued Action based on unauthorized transfer of licensed matl & failure to perform required leak tests
FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/08/20 1p 26261 216

8408280073 EN-84-053 on 840823, notice of violation & proposed imposition of civil penalties in amount of $8,500 will be issued Action based on distribution of radiopharms by Blue Ash facility contaminated w/Mo-99
FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/08/20 1p 26261 215

8408280078 PNO-V-84-052 on 840821, licensee determined that HPSI potentially degraded due to component cooling water HX mini flow bypass open for subgroup relay testing Formal investigation being conducted
MORRILL, P , HAIST, D Region 5, Office of Director 84/08/22 1p 26261 206 24X Fiche 50-362, 84/08/22, 8408280078

8408280107 PNO-I-84-070 on 840821, reactor vessel cavity seal failed when initially filled Caused by trip in containment sump pump under reactor vessel Licensee evaluating situation Notification of state & local authorities undertaken
SWETLAND, P , MCCABE, E Region 1, Office of Director 84/08/21 1p 26261 301 24X Fiche 50-213, 84/08/21, 8408280107

8408280152 PNO-II-84-055 on 840823, util announced that seven employees dismissed due to alleged unauthorized bid disclosures in procurement of small tools & expendable const supplies Dealings w/one vendor terminated
PANCIERA, V , DANCE, H C Region 2, Office of Director 84/08/24 1p 26274 309 24X Fiche 50-424, 84/08/24, 8408280152

8408280158 PNO-II-84-054A on 840821, reactor trip occurred due to partial loss of offsite power Caused by inadvertent opening of switchyard computer operated breakers Reactors restarted
IGNATONIS, A J , BROWNLEE, V L Region 2, Office of Director 84/08/23 1p 26259 212 24X Fiche 50-369, 84/08/23, 8408280158

8408280267 PNO-II-84-056 Nuclear Safety Review Staff rept assessing TVA actions re 840419 in-core probe seal table break received Inspectors will investigate event further on 840827 Util & NRC responding to media inquiries
FREDERICKSON, P , WEISE, S Region 2, Office of Director IEIN-84-55 84/08/24 1p 26261 341 24X Fiche 50-327, 84/08/24, 8408280267

8408290036 PNO-V-84-053 on 840822, thermal transient occurred in reactor feedwater sys downstream of high pressure feedwater heaters 6A & 6B Transient caused pipe hanger & support damage resulting in leakage of approx 20 gallons water
DODDS, R T , TOTH, A D Region 5, Office of Director 84/08/23 1p 26291 213 24X Fiche 50-397, 84/08/23, 8408290036

8408290120 EN-84-054 notice of violation & proposed imposition of civil penalties in amount of $500 to be issued for license Action based on storage of 450 nCi Cs-137 contained in density gauge in unrestricted area & failure to monitor lab areas
ROBINSON, P , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/08/23 1p 26289 233

8408300146 EN-84-009A notice of violation & proposed imposition of civil penalty in amount of $30,000 issued re failure to follow procedures for entry into locked high radiation area
FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/08/28 1p 26304 357 24X Fiche 50-261, 84/08/28, 8408300146

8408310041 PNO-I-84-072 on 840823, Southwest Nuclear found to be in violation of license by storing biomedical & low level waste in warehouse in Beltsville, MD No leakage or contamination found Waste to be shipped within 30 days
BRENNEMAN, F Region 1, Office of Director 84/08/24 1p 26322 131

8408310065 PNS-I-84-017 on 840827, unidentified male telephoned security post at Elevation 100 ft of Unit 1 on internal line & told security guard that bomb planted in containment Bomb search teams deployed No bomb found No explosion occurred
DUNLAP, J , KEIMIG, R , JOYNER, J Region 1, Office of Director 84/08/27 1p 26323 203 24X Fiche 50-272, 84/08/27, 8408310065

8408310074 PNO-I-84-073 on 840824, offsite power lost Emergency diesel A started but did not close to bus & RHR flow for shutdown reactor lost until RHR pump supplied by emergency diesel placed on-line Tripped transformer placed on-line
SWETLAND, P , MCCABE, E Region 1, Office of Director 84/08/24 1p 26322 201 24X Fiche 50-213, 84/08/24, 8408310074

8408310080 PND-I-84-074 on 840824, Accuray Model O-2 gauging device containing 55 mCi Sr-90 lost Gauge removed from storage on 840425 to perform routine leak test Gauge apparently disposed of w/other equipment in refuse bin or compactor
TAYLOR, M KINNEMAN, J , JOYNER, J Region 1, Office of Director
84/08/27 1p 26323 202

8408310111 PND-I-84-070A on 840823, refueling cavity to reactor vessel seal failure identified during fuel transfer Cavity-to-vessel inflatable boot seal unique in US Failure w/fuel transfer tube open would result in high radiation
SWETLAND, P , MCCABE, E Region 1, Office of Director 84/08/24 1p
26322 113 24X Fiche 50-213 84/08/24, 8408310111

8408310268 PND-III-84-067 First of several spent reactor fuel shipments from Cooper Station arrived safely Rail shipment consisted of three NRC-certified shipping casks, each containing 18 spent fuel assemblies
LOVENDALE, P , PAPERIELLO, C J Region 3, Office of Director
84/08/24 1p 26333 329

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

8408010157 Requests attendance at 840727 & 30 training sessions on Inspector Rept Form 766
TROTTIER, E Vendor Program Branch 84/07/26 Vendor Program Branch 1p 25955 303

8408030277 Responds to 840703 ltr re seismic safety of nuclear reactors in Mississippi Valley states Forwards responses to specific questions Info re seismic design contained in SER for each plant available in PDR
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/07/24 TOTTEN, M Critical Mass Energy Project 7pp 25935 125

--8408030282 Requests clarification of 840531 ltr re seismic safety of nuclear reactor in Mississippi Valley states
TOTTEN, M Critical Mass Energy Project 84/07/03 DIRCKS, W J Office of the Executive Director for Operations 2pp 25935 133

8408060069 Forwards case study rept, "Steam Binding of Auxiliary Feedwater Pumps " Backleakage represents potential common cause failure for auxiliary feedwater sys
HELTEMES, C J Director's Office 84/07/23 ROSSIN, D Nuclear Safety Analysis Center 1p 25937 005

--8408060073 Forwards case study rept, "Steam Binding of Auxiliary Feedwater Pumps " Backleakage represents potential common cause failure for auxiliary feedwater sys
HELTEMES, C J Director's Office 84/07/23 PATE, Z Institute of Nuclear Power Operations 1p 25937 006

--8408060077 Forwards case study rept, "Steam Binding of Auxiliary Feedwater Pumps " NRR considering interim measures to reduce potential for steam binding of auxiliary feedwater pumps at operating PWRs until generic issue resolved
HELTEMES, C J Director's Office 84/07/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 25937 007

--8408060081 Forwards case study rept, "Steam Binding of Auxiliary Feedwater Pumps " Backleakage represents potential common cause failure for auxiliary feedwater sys
HELTEMES, C J Director's Office 84/07/23 RAHE, E P Westinghouse Electric Corp SHEPPARD, J Westinghouse Owners Group SHEPPARD, J Carolina Power & Light Co 2pp
25937 009

--8408060083 "Steam Binding of Auxiliary Feedwater Pumps "
LANNING, W Reactor Operations Analysis Branch AEOD/C404
84/07/31 60pp 25937 011

8408060389 Forwards AEOD "Steam Binding of Auxiliary Feedwater Pumps," final rept Rept reflects peer review process AEOD recommendations re study previously forwarded to NRR for appropriate action
DIRCKS, W J Office of the Executive Director for Operations
84/07/26 PALLADINO, ROBERTS, ASSELSTINE Commissioners, 1p
25951 174

8408070008 Summary of 840719 operating reactor events meeting w/div directors re events occurring since 840628 meeting List of attendees & viewgraphs encl
CRUTCHFIELD, D Assistant Director for Safety Assessment 84/07/27
EISENHUT, D G Division of Licensing 12pp 25956 208

8408070057 Notification of 840815 meeting w/SM Stoller Corp in Bethesda, MD to hear presentation on OPEC-2 computer sys
MORRIS, C Reliability & Risk Assessment Branch 84/07/30
THADANI, A Reliability & Risk Assessment Branch 2pp 25955 330

8408160439 Forwards evaluation of Generic Issue 49 re interlocks & limiting conditions for operation for Class 1E tie breakers Schedule for resolving generic issue should be in accordance w/NRR Ltr 40
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/07/31 MULLER, D R Division of Systems Integration (post 811005) 11pp 26108 353

8408170280 Requests removal of J Hard from distribution list for listed repts or documents
LEINS, E Atomic Safety and Licensing Board Panel 84/08/09
SCHAEFFER, C Document Management Branch 1p 26115 255

8408220441 Forwards errata sheet for AEOD Special Study Rept AEOD/S402 re pressure locking of flexible disk wedge-type gate valves, previously transmitted as attachment to 840706 memo
HELTEMES, C J Director's Office 84/08/03 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp
26201 355

8408240369 Forwards FR notice re issuance of amend to OL Amend involves NSHC, not withstanding pendency before Commission of hearing request W/o encl
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/08/01 SIMPSON, A Senate, Environment & Public Works 2pp
26254 345

8408240401 Forwards monthly status rept on plant-specific backfits through Jul 1984 Table depicting status of appeal items for operating reactors & OL applicants provided Supplemental tables also encl
EISENHUT, D G Division of Licensing 84/08/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 26248 324

8408240425 Forwards comments & updates on AEOD second semiannual rept of unresolved recommendations
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/08/16 HELTEMES, C J Director's Office 7pp 26248 227,

8408300143 Outlines qualification requirements for OL personnel assigned to Div of Reactor Safety Training & qualification manual encl
SPESSARD, R L Region 3, Office of Director 84/08/22 Region 3, Office of Director 30pp 26331 268

8408310410 Responds to 840731 memo re analysis of nonpower reactor sabotage Criteria of 10CFR100 inapplicable for assessment of radiological consequences of sabotage at nonpower reactors Study should evaluate sabotage consequences
EISENHUT, D G Division of Licensing 84/08/20 BURNETT, R F Office of Nuclear Material Safety & Safeguards, Director 3pp
26350 345

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

8405210578 NUREG/CR-3633 V02
TRAC-BD1/MOD1 AN ADVANCED BEST ESTIMATE COMPUTER PROGRAM FOR BOILING WATER REACTOR TRANBIENT ANALYSIS Volume 2 Users Guide
SCHUMWAY, R W , MOHR, C M EG&G, Inc FIN A-6052 EGG-2294
84/04/30 Division of Accident Evaluation 117pp 24528 232

8405210579 NUREG/CR-3633 V03
TRAC-BD1/MOD1 AN ADVANCED BEST ESTIMATE COMPUTER PROGRAM FOR BOILING WATER REACTOR TRANBIENT ANALYSIS Volume 3 Code Structure and Programming Information
SINGER, C L , MOHR, C M EG&G, Inc FIN A-6052 EGG-2294 84/04/30
Division of Accident Evaluation 110pp 24528 357

8406190045 NUREG-0853 S03
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CLINTON POWER STATION, UNIT NO 1 Docket No 50-461 (Illinois Power Company, et al)
* Division of Licensing 84/05/31 40pp 25025 274 24X
Fiche 50-461, 84/05/31, 8406190045

8406190069 NUREG-0776 S07
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SUSQUEHANNA STEAM ELECTRIC STATION, UNITS 1 AND 2 Docket Nos 50-387 And 50-388 (Pennsylvania Power And Light Company, Allegheny Electric Cooperative, Incorporated)
* Division of Licensing 84/05/31 19pp Available at NRC, $3 00 25025 253 24X Fiche 50-387, 84/05/31, 8406190069

8406220100 Requests notification of analyses utilizing methodology not previously approved in NUREG-0661, "Mark I Containment Long-Term Program" in determining need for logic changes
RIVENBARK, G W Operating Reactors Branch 2 84/06/11 BAUER, E G Philadelphia Electric Co 3pp 25100 343 24X
Fiche 50-277, 84/06/11, 8406220100

8406230301 NUREG/CR-3704
THREE-DIMENSIONAL CALCULATIONS OF TRANSIENT FLUID-THERMAL MIXING IN THE DOWNCOMER OF THE CLAVERT CLIFFS-1 PLANT USING SOLA-PTS
DALY,B J Los Alamos Scientific Laboratory FIN A-7306
LA-10039-MS 84/04/30 Division of Accident Evaluation 86pp
25131 319 24X Fiche 50-317,84/04/30,8406230301

8407130502 NUREG-1020LD V01
GPU V B&W LAWSUIT REVIEW AND ITS EFFECT ON TMI-1 General Public Utilities Corporation,et al v The Babcock & Wilcox Company,et al Three Mile Island Nuclear Station,Unit 1, Docket 50-289
* Office of Nuclear Reactor Regulation, Director 84/06/30 152pp
25579 089 24X Fiche 50-289,84/06/30,8407130502

8407170313 Requests review of draft NUREG-1032,App A re loss of offsite power frequency & duration relationship & of ORNL draft rept on loss of offsite power operating experience Comments requested by 840801 W/o encl
BARANOWSKY,P W Reactor Risk Branch 84/07/11 KNIEL,K Generic Issues Branch 2pp 26068 061

--8407170316 Forwards draft loss of offsite power frequency & duration analyses Results indicate significant reduction in estimated frequency & duration of loss of power transient & contradict previous EPRI findings Review requested for 840731 meeting
BARANOWSKY,P W Reactor Risk Branch 84/07/11 BERGER,W E Sargent & Lundy, Inc 96pp 26068 063

8407230153 Comments on NUREG-1055, "Improving Quality & Assurance of Quality in Design & Const of Nuclear Power Plants " Comprehensive third-party audits should be used to periodically confirm effectiveness of mgt QA/QC programs
HARRISON,S F National Board of Boiler & Pressure Vessel Inspectors, 84/07/18 GRACE,N Office of the Secretary of the Commission
9pp 26061 236

8408010005 Request correction to date of ltr,forwarded on 840602, requesting info on NUREG-0737,Item II D 1 re performance testing of relief & safety valves Correct date is 840702
VARGA,S A Operating Reactors Branch 1 84/07/23 MCDONALD,R P Alabama Power Co 2pp 25867 361 24X Fiche 50-250,84/07/23, 8408010005

8408010015 Summary of ACRS Class-9 Accidents Subcommittee 840427 meeting in Washington,DC re draft NUREG-1070, "NRC Policy on Future Reactor Design Decisions on Severe Accident Issues in Nuclear Power Plant Design "
* ACRS - Advisory Committee on Reactor Safeguards 84/07/02
ACRS - Advisory Committee on Reactor Safeguards 17pp 25897 104

8408010018 Forwards SER & EG&G technical evaluation rept re response to Generic Ltr 81-04 (Rev 1 to NUREG-0313) concerning BWR coolant pressure boundary piping
VASSALLO,D B Operating Reactors Branch 2 GL-81-04 84/07/23
PILANT,J M Nebraska Public Power District 3pp 25867 305 24X Fiche 50-298,84/07/23,8408010018

--8408010022 Safety evalution re IGSCC in RCPB piping sys,per Generic Ltr 81-04 Licensee response does not meet NUREG-0313 guidelines Further action will depend upon responses to Generic Ltrs 84-07 & 84-11
* Office of Nuclear Reactor Regulation, Director GL-81-04
84/07/23 4pp 25867 308 24X Fiche 50-298,84/07/23,8408010018

--8408010027 EGG-FM-6521
"Technical Evaluation of Integrity of Cooper Nuclear Station Reactor Coolant Boundary Piping Sys "
NAGATA,P K EG&G, Inc FIN A-6429 TAC 46657 83/07/31
KOO,W H Division of Engineering 40pp 25867 312 24X
Fiche 50-298,84/07/23,8408010018

8408010030 Forwards SER re containment hydrogen monitor (NUREG-0737, Item II F 1 6) Monitor meets all criteria of NUREG-0737 except requirement for redundancy Response requested within 30 days
PAULSON,W A Operating Reactors Branch 5 84/07/30 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 7pp
25855 326 24X Fiche 50-245,84/07/30,8408010030

8408010061 Further response to FOIA request for 16 categories of records re facility Documents identified by J Goold & M Siebert on 840514 & 15 (App B) forwarded App A documents already forwarded Index forthcoming Search continuing
FELTON,J M Division of Rules and Records BX14 000 84/07/18,
RICE,C M Kirkland & Ellis 2pp 26500 001

--8408150751 Forwards const status rept as of 791001 Handwritten notes re diesel generator bldg & soil settlement & errata to NUREG-0634 encl
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch BX20 041A 79/10/05 KNOP,R C NRC - No
Detailed Affiliation Given 107pp 26548 359

8408010078 Informs that licensee responses to NUREG-0737, Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling," acceptable SSER input & milestones encl
YOUNGBLOOD,B J Licensing Branch 1 84/07/19 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
12pp 25897 225 24X Fiche 50-445,84/07/19,8408010078

8408010099 Forwards request for addl info re applicability of generic test results for safety/relief valves submitted in NEDE-24988-P by BWR Owners Group Info needed for review of response to NUREG-0737, Item II D 1
YOUNGBLOOD,B J Licensing Branch 1 84/07/20 CURTIS,N W
Pennsylvania Power & Light Co 3pp 25897 057 24X
Fiche 50-387,84/07/20,8408010099

8408010107 Forwards request for addl info re NUREG-0737, Item II D 1, including basis for application of findings of NEDE-24988-P, "Analysis of Generic BWR Safety 1 Relief Valve Operability Test Results," submitted by BWR Owners Group
SCHWENCER,A Licensing Branch 2 84/07/24 FARRAR,D L
Commonwealth Edison Co 4pp 25873 355 24X Fiche 50-373,84/07/24, 8408010107

8408010129 Forwards DES (NUREG-1064) & notice of availability for Millstone 3 Comments due within 45 days after publication of FR notice of issuance W/o NUREG
YOUNGBLOOD,B J Licensing Branch 1 84/07/24 Connecticut, State of 2pp 25873 313 24X Fiche 50-423,84/07/24,8408010129

--8408010131 Notice of availability of DES (NUREG-1064) for Millstone 3
YOUNGBLOOD,B J Licensing Branch 1 84/07/24 2pp 25873 315
24X Fiche 50-423,84/07/24,8408010129

8408010148 NUREG-1064
DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF MILLSTONE NUCLEAR POWER STATION,UNIT 3 DOCKET NO 50-423 (NORTHEAST NUCLEAR ENERGY COMPANY,et al)
* Division of Licensing 84/07/31 335pp Available at NRC
$8 00 25871 012 24X Fiche 50-423,84/07/31,8408010148

8408010151 NUREG/CR-3844
CHARACTERIZATION OF THE RADIOACTIVE WASTE PACKAGES OF THE MINNESOTA MINING AND MANUFACTURING COMPANY
KEMPF,C R , SISKIND,B , BARLETTA,R E Brookhaven National Laboratory FIN A-3172 BNL-NUREG-51787 84/07/31 Division of Waste Management 93pp Available at NRC $4 50 25872 001

8408010154 Forwards "Procedures Generation Package For Beaver Valley Power Station,Unit 2," in response to Generic Ltr 82-33, describing methods for developing function oriented emergency operating procedures,per NUREG-0737, Item II C 1
WOOLEVER,E J Duquesne Light Co GL-82-33 84/07/26
EISENHUT,D G Division of Licensing 3pp 25855 184 24X
Fiche.50-412,84/07/26,8408010154

--8408010156 "Procedures Generation Package For Beaver Valley Power Station,Unit 2 "
CLEMENTS,R H , JONES,D T Duquesne Light Co 84/08/01 116pp
25855 187 24X Fiche 50-412,84/07/26,8408010154

8408010155 NUREG/CR-3826
RECOMMENDATIONS FOR PROTECTING AGAINST FAILURE BY BRITTLE FRACTURE IN FERRITIC STEEL SHIPPING CONTAINERS GREATER THAN FOUR INCHES THICK
SCHWARTZ,M W Lawrence Livermore National Laboratory FIN A-0374
UCRL-53338 84/07/31 Division of Engineering Technology 131pp
Available at NRC $5 50 25872 087

8408010158 NUREG/CR-3897
EVALUATION OF ECOSYSTEM SIMULATION MODELS AS TOOLS FOR ASSESSMENT OF POWER PLANT IMPACTS ON FISH POPULATIONS
Final Rept
SWARTZMAN,G L Washington, Univ of, Seattle, WA FIN B-7018
84/07/31 Division of Health, Siting & Waste Management 10pp
Available at NRC $3 00 25867 292

8408010161 Notification of 840727 meeting w/util at site to discuss questions re control of heavy loads (Multi-Plant Action C-15)
NEIGHBORS,D Operating Reactors Branch 1 84/07/20 VARGA,S A
Operating Reactors Branch 1 2pp 25873 304 24X
Fiche 50-280,84/07/20,8408010161

8408010166 NUREG/CR-3518 V01
SLIM-MAUD AN APPROACH TO ASSESSING HUMAN ERROR PROBABILITIES USING STRUCTURED EXPERT JUDGEMENT Volume I Overview of SLIM-MAUD,
EMBREY,D E , HUMPHREYS,P , ROSA,E A Brookhaven National Laboratory FIN A-3219 BNL-NUREG-51716 84/07/31 Division of Facility Operations 36pp 25867 253

8010179 NUREG/CR-2331 V03 N3
AFETY RESEARCH PROGRAMS SPONSORED BY OFFICE OF NUCLEAR
EGULATORY RESEARCH Quarterly Progress Report, July-September
83
EISS, A J Brookhaven National Laboratory FIN A-3011
L-NUREG-51454 84/07/31 Division of Accident Evaluation
4pp 25870 181

8010197 Forwards DES (NUREG-1064) & FR notice of issuance W/o
JREG
OUNGBLOOD, B J Licensing Branch 1 84/07/24 COUNSIL, W G
rtheast Nuclear Energy Co (subs of Northeast Utilities) 3pp
873 272 24X Fiche 50-423, 84/07/24, 8408010197

8010216 Discusses control room design review open items status, per
R (NUREG-0798) Encls identify human engineering
ficiencies, status & where possible, ref document to
pport closure of item
NS, W H Detroit Edison Co EF2-69 137 84/07/25
OUNGBLOOD, B J Licensing Branch 1 9pp 25856 027 24X
che 50-341, 84/07/25, 8408010216

8010252 Forwards DES (NUREG-1064) & FR notice of availability, for
view & comment Comments due within 45 days after
blication in FR W/o NUREG
OUNGBLOOD, B J Licensing Branch 1 84/07/24 WOOD, J M Commerce,
pt of, Natl Oceanographic & Atmospheric Administration 4pp
872 331 24X Fiche 50-423, 84/07/24, 8408010252

8010253 Response to ASLB 840712 inquiry whether NUREG/CR-3756
nstitutes substantial new info to lead to redetermination
adequacy of seismic design Inquiry fully warranted
rtificate of Svc encl
HNSON, T Campaign for Prosperous Georgia DSB 664 OL
/07/26 17pp 25854 324 24X Fiche 50-424, 84/07/26, 8408010253

8010319 Forwards application to amend License DPR-59, changing Tech
ecs re NUREG-0737, Item II K 3 18, "Mod of Automatic
pressurization Sys Logic - Feasibility for Increased
versity for Some Event Sequences "
YNE, J P Power Authority of the State of New York JPN-84-50
/07/25 VASSALLO, D B Operating Reactors Branch 2 2pp
866 129 24X Fiche 50-333, 84/07/25, 8408010319

8010321 Application to amend License DPR-59, changing Tech Specs re
NUREG-0737, Item II K 3 18, "Mod of Automatic
Depressurization Sys Logic - Feasibility for Increased
Diversity for Some Event Sequences "
AYNE, J P Power Authority of the State of New York 84/07/24
3pp 25866 131 24X Fiche 50-333, 84/07/25, 8408010319

8010322 Proposed Tech Spec changes re NUREG-0737, Item II K 3 18
covering implementation of automatic depressurization sys
logic mods
* Power Authority of the State of New York 84/07/25 10pp
25866 134 24X Fiche 50-333, 84/07/25, 8408010319

8020014 Advises that util Board of Directors ordered shutdown of
sign const & testing activities for facilities on
0716 CP & OL applications for both units will be
intained Issuance of SSER 4 (NUREG-0793) requested
OK, J W Consumers Power Co 31636 84/07/27 DENTON, H R
fice of Nuclear Reactor Regulation, Director 4pp 25883 116
X Fiche 50-329, 84/07/27, 8408020014

8020030 Forwards requested info on NUREG-0737, Item II F 1 re interim
ocedures for quantifying high level accidental radioactive
leases Info re Item III D 1 1 will be furnished in Sept
84
MPER, J S Philadelphia Electric Co 84/07/27 SCHWENCER, A
censing Branch 2 14pp 25883 218 24X Fiche 50-352, 84/07/27,
8020030

8020072 Comments on NUREG-1055, "Improving Quality & QA in Design
Const of Commercial Nuclear Power Plants " Proposed audits
reviews unnecessary, if sys ensures adequate mgt team
sembled prior to CP issuance
ANGLER, R G Texas Utilities Electric Co (formerly Texas Utilities
nerating Co) TXX-4234 84/07/19 Office of the Secretary of
e Commission 3pp 25891 031

8020079 Comments on NUREG-1055 re improving quality & QA in design &
nst of nuclear power plants (Ford Amend Study) Programs
ould be developed which maximize mgt ability by optimizing
gulatory environ.
STEN, D G Niagara Mohawk Power Corp 84/07/23 CHILK, S J
fice of the Secretary of the Commission 3pp 25891.285

8020091 Comments on NUREG-1055, "Improving Quality & QA in Design &
nst of Commercial Nuclear Power Plants " Further analysis
discussion of issues necessary prior to implementation of
posed NRC actions
TE, Z T Institute of Nuclear Power Operations 84/07/25
keting & Services Branch 3pp 25892 260

8408020106 Package of two comments on NUREG-1055, "Improving Quality &
QA in Design & Const of Nuclear Power Plants "
CROWE, D M Southern Co Services, Inc COOK, J W Consumers Power
Co 49FR14698 84/07/30 Docketing & Services Branch 5pp
25892 295

8408020130 Clarifies util positions re NUREG-0737, Item I C 6 concerning
tagging authorization, independent verification, post-maint
configuration verification & ALARA concerns, in response to
NRC 840614 ltr Revised procedures encl
HARRINGTON, W D Boston Edison Co 84-114 84/07/27 VASSALLO, D B
Operating Reactors Branch 2 4pp 25885 268 24X
Fiche 50-293, 84/07/27, 8408020130

8408020138 Advises that Tech Spec change requests per Generic Ltr
83-37, "NUREG-0737 Tech Specs," will be submitted by 841231,
per 840615 telcon request
O'TOOLE, J D Consolidated Edison Co of New York, Inc OL-83-37
84/07/26 EISENHUT, D G Division of Licensing 1p 25892 305
24X Fiche 50-247, 84/07/26, 8408020138

8408020140 Forwards FR notice of issuance & DES (NUREG-1064)W/o DES
YOUNGBLOOD, B J Licensing Branch 1 84/07/24 HIRSCH, A
Environmental Protection Agency 2pp 25898 091 24X
Fiche 50-423, 84/07/24, 8408020140

8408020237 Comments on 840628 & 0702 matl re disposal of nuclear waste
in unsaturated zone in comparison w/disposal in saturated
zone in demonstrably impervious rock Natl does not change
validity of 840320 comments on NUREG-1046
PHILBRICK, S S Philbrick, S S PHILBRICK, S S ACRS - Advisory
Committee on Reactor Safeguards 84/07/06 MOELLER, D W ACRS -
Advisory Committee on Reactor Safeguards 1p 25898 188

8408030019 Forwards responses to J Singh 840522 verbal questions re
control of heavy loads
MILLS, L M Tennessee Valley Authority 84/07/27 ADENSAM, E
Licensing Branch 4 2pp 25907 092, 24X Fiche 50-327, 84/07/27,
8408030019

--8408030025 Rev 3 to Procedure MI-6 22, "Control of Heavy Loads in
Critical Lifting Zones - NUREG-0612 "
DOTY, J W , WHEELER, L J Tennessee Valley Authority 84/05/21
23pp 25907 094 24X Fiche 50-327, 84/07/27, 8408030019

8408030032 Confirms that Westinghouse has completed review of listed
power ascension & emergency procedures, per 810914 ltr Util
reviewed Westinghouse comments & appropriate revs will be
made before Unit 1 startup
MILLS, L M Tennessee Valley Authority 84/07/27 ADENSAM, E
Licensing Branch 4 2pp 25907 068 24X Fiche 50-390, 84/07/27,
8408030032

8408030096 Application for amend to License DPR-23, revising Tech Specs
re reactor vessel level instrumentation sys Revs will
include instrumentation sys, per NUREG-0737 requirements
CUTTER, A B Carolina Power & Light Co NLS-84-318 84/07/20
VARGA, S A Operating Reactors Branch 1 2pp 25904:349 24X
Fiche 50-261, 84/07/20, 8408030096

--8408030100 Proposed Tech Specs re reactor vessel level instrumentation
* Carolina Power & Light Co OL-83-37 84/07/20. 4pp
25904 351 24X Fiche 50-261, 84/07/20, 8408030096

8408030104 Ack receipt of 840703 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-289/84-03
Corrective actions will be examined during future insp
MARTIN, T T Division of Engineering & Technical Programs 84/07/30
HUKILL, H D General Public Utilities - GPU Service Corp 4pp.
25904 303 24X Fiche 50-289, 84/07/30, 8408030104

--8408030108 TDR 563
Rev 0 to "TMI-1, Post-Accident RMA-5 Grab Sampling & MAP-5
Filter Removal Radiological Analyses "
* General Public Utilities - GPU Service Corp 84/07/02 26pp
25904.310 24X Fiche 50-289, 84/07/30, 8408030104

8408030144 Forwards table of Type A variables & revs & updates of
compliance to Reg Guide 1 97, Rev 2, Types B, C & D variable
requirements, in response to 831203 request
VAN BRUNT, E E Arizona Public Service Co ANPP-30092-EEVB
84/08/01 KNIGHTON, G Licensing Branch 3 28pp 25911:161 24X
Fiche 50-528, 84/08/01, 8408030144

8408030167 Forwards Rev 0 to "Control Room Design Review Program Plan,"
in partial fulfillment of Generic Ltr 82-33, "Suppl 1 to
NUREG-0737 - Requirements for Emergency Response
Capability "
FAY, C W Wisconsin Electric Power Co GL-82-33. 84/07/31,
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
25911 193 24X Fiche 50-266, 84/07/31, 8408030167

8408060145 Application for amend to Licenses NPF-11 & NPF-18, changing Tech Specs re accident monitoring instrumentation (NUREG-0737, Items II F 1 1, II F 1 3 & II F 1 6) Fee encl
MARSHALL, J G Commonwealth Edison Co 9010N 84/07/25
DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp
25925 285 24X Fiche 50-373, 84/07/25, 8408060145

8408060165 Responds to Generic Ltr 83-10C re resolution of NUREG-0737, Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Facilities bound by results of Westinghouse Owners Group manual pump trip justification rept
SCHMIDT, H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) GL-83-10C 84/07/27 YOUNGBLOOD, B J Licensing Branch 1 1p 25932 197 24X Fiche 50-445, 84/07/27, 8408060165

8408060190 Forwards IE Insp Rept 50-213/84-06 on 840509-11 No violations noted Items of concern noted in App A
MARTIN, T T Division of Engineering & Technical Programs 84/07/09
COUNSIL, W G Connecticut Yankee Atomic Power Co 3pp 25935 191
24X Fiche 50-213, 84/07/09, 8408060190

--8408060208 IE Insp Rept 50-213/84-06 on 840509-11 No violations noted Major areas inspected status of previously identified insp items & IE Insp Procedures 82206, 82207 & 82208
SMITH, R H , CROCKER, H W Region 1, Office of Director 84/06/26
5pp 25935 194 24X Fiche 50-213, 84/07/09, 8408060190

8408060257 Forwards marked-up Tech Specs, based on Rev 4 to NUREG-0452, "STS for Westinghouse Pressurized Reactors " Offsite dose calculation manual will be submitted by 840831 Future submittals will address listed subjs
CUTTER, A B Carolina Power & Light Co NLS-84-338 84/07/30
DENTON, H R Office of Nuclear Reactor Regulation, Director 636pp
25924 001 24X Fiche 50-400, 84/07/30, 8408060257

8408060295 Forwards J Buckley 840705 memo re typographical error in App V, Vol 2 of NUREG-0960
WRIGHT, R J Repository Projects Branch (Post 831001) 00916
84/07/23 OLSON, D L Energy, Dept of 1p 25950 349

8408060386 NUREG/CR-3896
SIMULATION EXPERIMENTS COMPARING ALTERNATIVE PROCESS FORMULATIONS USING A FACTORIAL DESIGN
KALUZNY, S P , SWARTZMAN, G L Washington, Univ of, Seattle, WA FIN B-7018 84/07/31 Division of Health, Siting & Waste Management
29pp Available at NRC $3 50 25937 282

8408060413 NUREG-0680 S05
TMI-1 RESTART An Evaluation Of The Licensee's Management Integrity As It Affects Restart Of Three Mile Island Unit 1 Docket 50-289
* Division of Licensing 84/07/31 179pp Available at NRC
$6 00 25937 102 24X Fiche 50-289, 84/07/31, 8408060413

8408070007 NUREG/CR-2000 V03 N6
LICENSEE EVENT REPORT (LER) COMPILATION For Month of June 1984
* Oak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200
84/07/31 Director's Office 87pp 25955 112

8408070009 NUREG-0954 S03
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAWBA NUCLEAR STATION, UNITS 1 AND 2 DOCKET Nos 50-413 And 50-414 (Duke Power Company, et al)
* Division of Licensing 84/07/31 140pp Available at NRC
$5 50 25954 334 24X Fiche 50-413, 84/07/31, 8408070009

8408070014 NUREG/CR-3834
ON THE THRESHOLD SULFUR AND LITHIUM TO SULFUR RATIO IN STRESS CORROSION CRACKING OF SENSITIZED ALLOY 600 IN BORATED THIOSULFATE SOLUTION
BANDY, R , KELLY, K Brookhaven National Laboratory FIN A-3380
BNL/NUREG-51785 84/07/31 Division of Engineering 35pp
Available at NRC $3 75 25954 296

8408070015 Advises that 800930 description of proposed mods to ensure containment isolation single failure proof during purging satisfies requirements of Item II E 4 1 of NUREG-0737, based on completion of mods by 850701
VASSALLO, D B Operating Reactors Branch 2 84/07/26 BAYNE, J P
Power Authority of the State of New York 3pp 25956 204 24X
Fiche 50-333, 84/07/26, 8408070015

8408070037 Forwards response to Procedures & Sys Review Branch queries re emergency procedures & selection of containment vent pressure
KEMPER, J S Philadelphia Electric Co 84/08/02 SCHWENCER, A
Licensing Branch 2 6pp 25949 329 24X Fiche 50-352, 84/08/02, 8408070037

8408070065 Forwards corrected page to 840612 confirmatory order, confirming Dec 1986 schedule for implementation of Suppl 1 to NUREG-0737 & Generic Ltr 82-33 re completion of structural mods to technical support ctr W/o encl
VARGA, S A Operating Reactors Branch 1 GL-82-33 84/07/26
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp
25955 319 24X Fiche 50-272, 84/07/26, 8408070065

8408070076 Advises of completion of review of AEOD/C403, "Case Study Rept for EI Hatch, Unit 2 Plant Sys Interaction Event on 820825 " Case study recommends event be considered in developing final positions relative to NUREG-0803
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/07/30 HELTEMES, C J Director's Office 2pp 25955 272 24X
Fiche 50-366, 84/07/30, 8408070076

--8406010162 Forwards case study rept of 820825 plant sys interaction event Comments requested W/o encl
HELTEMES, C J Director's Office 84/05/18 DENTON, H R Office of Nuclear Reactor Regulation, Director DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 25955 273
24X Fiche 50-366, 84/07/30, 8408070076

8408070110 Generic Ltr 84-19 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of Suppl 1 to NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/08/06 Consolidated
Edison Co of New York, Inc 18pp 26129 238 24X
Fiche 50-000, 84/08/06, 8408070110

8408070114 Provides schedule info re NUREG-0737, Suppl 1 on emergency response commitment & clarifies schedular error in 840612 confirmatory order Amend to order prior to Sept 1985 suggested
O'TOOLE, J D Consolidated Edison Co of New York, Inc GL-82-33
84/07/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 25950 034 24X Fiche 50-247, 84/07/31, 8408070114

8408070142 Forwards request for addl info to continue review of 831028 submittal re safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737 Response requested within 60 days
MILLER, J R Operating Reactors Branch 3 84/07/24 JONES, W C
Omaha Public Power District 4pp 25957 134 24X
Fiche 50-285, 84/07/24, 8408070142

8408070230 Forwards revised procedures generation package, per 840507 & 30 requests Submittal completes requirements of NUREG-0737, Suppl 1 re upgrade of emergency operating procedures
COOK, K W Louisiana Power & Light Co NSP84-2062 84/07/31
KNIGHTON, G W Licensing Branch 3 2pp 25948 228 24X
Fiche 50-382, 84/07/31, 8408070230

8408070271 Responds to 840604 request for NRC concurrence in plans to train & qualify six senior control room operators as shift technical advisors Personnel entering program must be degreed or equivalent, per NUREG-0737, Item I A 1 1
MILLER, J R Operating Reactors Branch 3 84/07/26 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 25956 261 24X
Fiche 50-317, 84/07/26, 8408070271

8408070298 Informs that requested info re detailed control room design review provided in licensee 840409, 0525 & 0216 submittals, per Suppl 1 to NUREG-0737 Task analyses for inadequate core cooling & ATWS event conducted during control room review
TUCKER, H B Duke Power Co GL-83-23 84/07/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director ADENSAM, E G
Licensing Branch 4 2pp 25947 295 24X Fiche 50-369, 84/07/27, 8408070298

8408070343 Forwards plant-specific technical guidelines, required by Suppl 1 to NUREG-0737, to aid NRC in completing review of emergency procedures generation package, in response to 840614 request
LUNDVALL, A E Baltimore Gas & Electric Co 84/08/03 MILLER, J R
Operating Reactors Branch 3 6pp 25944 154 24X
Fiche 50-317, 84/08/03, 8408070343

8408070362 Responds to NRC review of util conformance to NUREG-0737, Suppl 1, SER Outstanding Issue 19 NRC concerns re sys function, task analysis & control room inventory addressed Emergency response procedure program encl
DEVINCENTIS, J Yankee Atomic Electric Co SBW-701 84/07/30
KNIGHTON, G W Licensing Branch 3 202pp 25944 284 24X
Fiche 50-443, 84/07/30, 8408070362

8408070393 Submits info on schedule for implementing upgraded emergency operating procedures, per Suppl 1 to NUREG-0737 Schedule outline prepared to perform listed actions Upgraded procedures will be implemented prior to Cycle 19 operation
KAY, J A Yankee Atomic Electric Co FYR 84-82 84/07/27
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 25945 246 24X
Fiche 50-029, 84/07/27, 8408070393

NONDOCKETED ITEMS

8408070376 Forwards comments on NUREG-1055, 'Improving Quality & QA in Design & Const of Nuclear Power Plants " All future CP applicants should not be required to contract for third party insps
MILLS, L M Tennessee Valley Authority 84/07/30 Docketing & Services Branch 5pp 25942 246

8408070404 Forwards supplemental info re qualification of safety relief valves (SRV), Seitz solenoid valves Interim operation justified until SRV solenoid valves fully qualified, per NUREG-0588 & 10CFR50 49
DALE, L F Mississippi Power & Light Co AECM-84/0394 84/08/05
DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 25942 177 24X Fiche 50-416, 84/08/05, 8408070404

8408070421 Responds to manual reactor coolant pump trip issue Upgraded emergency operating procedures & integrated operator training being implemented, per Suppl 1 to NUREG-0737 & Generic Ltr 83-10D
O'TOOLE, J D Consolidated Edison Co of New York, Inc OL-83-10D 84/08/01 EISENHUT, D G Division of Licensing 2pp 25942 026 24X Fiche 50-247, 84/08/01, 8408070421

8408070431 Application for amend to License DPR-20, adding Section 3 0 limiting conditions for operation applicability, in response to B31031 radiological effluent Tech Specs transmitting Draft 7 of Rev 3 to NUREG-0472
VANDEWALLE, D J Consumers Power Co 84/07/31 CRUTCHFIELD, D Operating Reactors Branch 5 10pp 25939 221 24X Fiche 50-255, 84/07/31, 8408070431

8408070435 Forwards Rev 3 to milestone commitments on Suppl 1 to NUREG-0737 & "PSAR, Safety Parameter Display Sys," per B30913 & 16 submittals
JOHNSON, B D Consumers Power Co 84/07/31 CRUTCHFIELD, D Operating Reactors Branch 5 6pp 25942 361 24X Fiche 50-255, 84/07/31, 8408070435

8408070440 Advises of plans to implement Option 4 of NUREG-0737, Item II K 3 IB, "Mod of Automatic Depressurization Sys Logic," per NRC approval Plans include installation of sys manual inhibit switch
JENS, W H Detroit Edison Co EF2-66712 84/07/31 YOUNGBLOOD, B J Licensing Branch 1 2pp 25942 357 24X Fiche 50-341, 84/07/31, 8408070440

8408070489 Forwards hot license simulator reactor startup certification program, per NUREG-0094 Program limits student to instructor ratio to four-to-one, conforming to INPO Guide 82-005 W/o encl
STEWART, W L Virginia Electric & Power Co 345 84/08/06
PERSENSKY, J J NRC - No Detailed Affiliation Given 2pp 25940 347 24X Fiche 50-000, 84/08/06, 8408070489

8408070515 Forwards "NUREG-0612, Control of Heavy Loads," final rept Submittal contains evaluation results & resolutions of open items since 840326 submittal
KOBER, R W Rochester Gas & Electric Corp 84/07/31, PAULSON, W A Operating Reactors Branch 5 1p 25941 172 24X Fiche 50-244, 84/07/31, 8408070515

--8408070516 "NUREG-0612, Control of Heavy Loads," final rept
* Rochester Gas & Electric Corp 84/08/31 12pp 25941 173 24X Fiche 50-244, 84/07/31, 8408070515

8408080178 Informs of review of responses to Generic Ltr 83-02 re Tech Specs for NUREG-0737 items which were to be implemented by B11231 Tech Specs for Item II E 4 2 7 have not been provided Response requested within 30 days
STOLZ, J F Operating Reactors Branch 4 OL-83-02 84/08/01
BECKHAM, J T Georgia Power Co 2pp 25978 342 24X Fiche 50-321, 84/08/01, 8408080178

8408080252 Responds to 840613 request for info re analyses used in determining if setpoint logic changes needed to reduce water clearing thrust loads associated w/second safety relief valve actuations Analyses conducted per NUREG-0661
CUTTER, A B Carolina Power & Light Co NLS-84-309 84/08/01, VASSALLO, D B Operating Reactors Branch 2 2pp 25966.300 24X Fiche 50-324, 84/08/01, 8408080252

8408080255 Forwards comments on NUREG-1055 re improving quality & QA in const of commercial nuclear power plants Supports Ford amend as objective & useful
CERZOSIMO, R R American Society of Quality Control 84/08/01 Docketing & Services Branch 7pp 25965 307

8408080297 Forwards comments on NUREG-1055 re improving quality & QA in design & const of nuclear power plants AEs & NRC should clearly define stable acceptance criteria before const started
* American Society of Mechanical Engineers 84/07/30 Docketing & Services Branch 6pp 25964 311

-8408080303 Speech entitled "Disciplined Approach for Introducing Certainty & Improving Quality in Nuclear Power Plant Const," presented at 840320 meeting of AIF & ANEC boards
SIERN, T Atomic Industrial Forum 84/03/20 4pp 25964 317

8408080355 NUREG/CR-3744 V01
HEAVY-SECTION STEEL TECHNOLOGY PROGRAM SEMIANNUAL PROGRESS REPORT FOR OCTOBER 1983 - MARCH 1984
PUGH, C E Oak Ridge National Laboratory FIN B-0119 ORNL/TM-9154/V1 84/07/31 Division of Engineering Technology 200pp 25979 146

8408080357 NUREG/CR-3679
CALIBRATION AND QUALIFICATION OF THE LOS ALAMOS FAILURE MODEL (LAFM)
BAARS, R E Los Alamos Scientific Laboratory FIN A-7015 LA-10041-MS 84/07/31 Division of Accident Evaluation 64pp 25980 329

8408080359 NUREG/CR-3643
HETEROGENEOUS OXIDATIVE DEGRADATION IN IRRADIATED POLYMERS
CLOUGH, R L , GILLER, K T , QUINTANA, C A Sandia Laboratories FIN A-1051 SAND83-2493 84/07/31 Division of Engineering Technology 43pp 25978 153

8408080363 NUREG-0748 V04 N06
OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of June 30, 1984
* Office of Resource Management, Director 84/07/31 400pp 25981 129

8408080367 NUREG/CR-3777
CAPABILITIES AND DIAGNOSTICS OF THE SANDIA PELLETRON-RABTER SYSTEM
BUCKALEW, W H , LOCKWOOD, G J , LUKER, S M Sandia Laboratories FIN A-1051 SAND84-0912 84/07/31 Division of Engineering Technology 61pp 25978 090

8408080370 NUREG-1075
DECENTRALIZATION OF OPERATING REACTOR LICENSING REVIEWS NRR Pilot Program
HANNON, J L Division of Licensing 84/07/31 26pp 25981 102

8408080371 NUREG/BR-0018 R02
THE HONOR LAW GRADUATE PROGRAM
* NRC - No Detailed Affiliation Given 84/09/01 12pp 25979 34

8408080374 NUREG/CR-3804 V01
PHYSICS OF REACTOR SAFETY Quarterly Report January - March 1984
* Argonne National Laboratory FIN A-2015 ANL-84-35 84/07/31 Division of Accident Evaluation 1p 25979 356

8408080407 NUREG/CR-3678
ESTIMATION METHODS FOR PROCESS HOLDUP OF SPECIAL NUCLEAR MATERIALS
PILLAY, K S , PICARD, R R , MARSHALL, R S Los Alamos Scientific Laboratory FIN A-7226 LA-10038 84/07/31 Division of Facility Operations 121pp 25980 028

8408080415 NUREG/CR-3618
OCA-P, A DETERMINISTIC AND PROBABILISTIC FRACTURE-MECHANICS CODE FOR APPLICATION TO PRESSURE VESSELS
CHEVERTON, R D , BALL, D G Oak Ridge National Laboratory FIN B-0119 ORNL-5991 84/07/31 Division of Engineering Technology 105pp 25977 338

8408080419 NUREG/CR-3671
ASSESSMENT OF RADIATION EFFECTS RELATING TO REACTOR PRESSURE VESSEL CLADDING
CORWIN, W R Oak Ridge National Laboratory FIN B-0119 ORNL-6047 84/07/31 Division of Engineering Technology 70pp 25977 271

8408080422 NUREG/CR-3714
ON THE DEVELOPMENT OF ENVIRONMENTAL RADIATION STANDARDS FOR GEOLOGIC DISPOSAL OF HIGH-LEVEL RADIOACTIVE WASTES
KOCHER, D C Oak Ridge National Laboratory FIN A-9041 ORNL-6006 84/07/31 Division of Health, Siting & Waste Management 80pp 25977 192

8408080445 Forwards request for addl info re safety parameter display sys (SPDS) Continued implementation of SPDS acceptable Response requested within 60 days of ltr receipt
RIVENBARK, G Operating Reactors Branch 4 84/07/27 RODRIGUEZ, R Sacramento Municipal Utility District 4pp 25977 152 24X Fiche 50-312, 84/07/27, 8408080445

--8408080449 Safety evaluation supporting continued implementation of safety parameter display sys, per Suppl 1 to NUREG-0737
* NRC - No Detailed Affiliation Given 84/07/27 8pp 25977 156 24X Fiche 50-312, 84/07/27, 8408080445

NONDOCKETED ITEMS

8808804?2 NUREG/CR-3840
COST ANALYSIS FOR POTENTIAL MODIFICATIONS TO ENHANCE THE ABILITY OF A NUCLEAR PLANT TO ENDURE STATION BLACKOUT
CLARK, R A , THOMAS, W R Science & Engineering Associates, Inc RICORDON, B J MATHTECH, Inc FIN B-8838 84/07/31 Division of Budget & Analysis 167pp Available at NRC $5 50 25980 160

108090099 Summarizes appraisal procedure re emergency response facilities, per NUREG-0737, Suppl 1
PAULSON, W A Operating Reactors Branch 5 84/07/31 Operating Reactors Branch 5 3pp 25991 252

408090149 Provides upgraded in-core thermocouple implementation schedule, per 840221 commitment Util proposes to complete Reg Guide 1 97 (ref NUREG-0737, Item II F 2) mods prior to or during 1986 refueling outages
STEWART, W L Virginia Electric & Power Co 447 84/08/03
DENTON, H R Office of Nuclear Reactor Regulation, Director
EISENHUT, D G Division of Licensing 2pp 25973 122 24X
Fiche 50-338, 84/08/03, 8408090149

1408090272 NUREG/CR-3795
CLOSEOUT OF IE BULLETIN 82-04 DEFICIENCIES IN PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
FOLEY, W J , HENNICK, A Parameter, Inc FIN B-8714 IEB-82-04
84/07/31 Division of Emergency Preparedness & Engineering Response (Post 830103) 53pp Available at NRC $4, 50 25983 001

1408090282 Summary of 840620 meeting w/util & Bechtel in Bethesda, MD re implementation of Reg Guide 1 97 requirements by licensee Util will provide supplemental rept to 840715 submission to address separation problems Viewgraphs encl
MINER, G Operating Reactors Branch 4 84/08/01 Operating Reactors Branch 4 12pp 25992 001 24X Fiche 50-312, 84/08/01, 8408090282

8408090311 Forwards application for amend to License DPR-34, revising Tech Specs to comply w/NUREG-0737, Items II B 3, II F 1 3 & III D 3 4
LEE, O R Public Service Co of Colorado F-84242 84/07/31
JOHNSON, E H Region 4, Office of Director 3pp 25994 114 24X
Fiche 50-267, 84/07/31, 8408090311

--8408090316 Application for amend to License DPR-34, revising Tech Specs to comply w/NUREG-0737, Items II B 3, II F 1 3 & II D 3 4 Fee encl
LEE, O R Public Service Co of Colorado 84/07/31 6pp
25994 117 24X Fiche 50-267, 84/07/31, 8408090311

--8408090322 Proposed revs to Tech Spec limiting conditions re control room temp, area radiation monitors, seismic instrumentation, primary coolant moisture instrumentation, switchgear room temp, emergency ventilation sys & fire suppression sys.
* Public Service Co of Colorado 84/07/31 21pp 25994 123
24X Fiche 50-267, 84/07/31, 8408090311

8408090530 Forwards request for addl info for review of 840214 submittal re control of heavy loads Tech Spec change
Response requested within 45 days of ltr receipt
VARGA, S A Operating Reactors Branch 1 84/08/01 O'TOOLE, J Consolidated Edison Co of New York, Inc 4pp 25983 332 24X
Fiche 50-247, 84/08/01, 8408090530

1408100002 Forwards emergency operating procedure generation package in response to requirements of Generic Ltr 82-33, "Suppl 1 to NUREG-0737 - Requirements for Emergency Response Capability," Section 7
DIXON, O W South Carolina Electric & Gas Co GL-82-33 84/07/30
DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp, 25989, 310 24X Fiche 50-395, 84/07/30, 8408100002

--8408100012 Rev 0 to Station Administrative Procedure SAP-207, "Development of Emergency Operating Procedure "
* South Carolina Electric & Gas Co GL-82-33 84/04/02 77pp
25989 321 24X Fiche 50-395, 84/07/30, 8408100002

8408100094 Forwards responses to NRC 840508 request for addl info re detailed control room design review (DCRDR) Encls include functions of DCRDR teams, control room instrumentation & emergency response capability integration plan
ALEXICH, M P Indiana & Michigan Electric Co AEP NRC 0773H
84/08/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 26pp 25988 204 24X Fiche 50-315, 84/08/06, 8408100094

--8408010079 Summarizes 840329 meeting w/Westinghouse Owners Group re task analysis requirements of Suppl 1 to NUREG-0737 (Generic Ltr 82-33)
CLAYTON, H B Procedures & Systems Review Branch GL-82-33
84/04/05 ZIEMANN, D L. Procedures & Systems Review Branch 17pp
25988, 230 24X Fiche: 50-315, 84/08/06, 8408100094.

8408100103 Forwards application for amend to License DPR-63, per Generic Ltr 83-19 Fee encl
MANGAN, C V Niagara Mohawk Power Corp GL-83-19 84/08/07
VASSALLO, D B Operating Reactors Branch 2 1p 25990 355 24X
Fiche 50-220, 84/08/07, 8408100103

--8408100111 Application for amend to License DPR-63, changing Tech Specs by deleting "all" from review & audit section, to be consistent w/Rev 2 to BWR Tech Specs (NUREG-0123)
MANGAN, C V Niagara Mohawk Power Corp 84/08/07 5pp
25990 356 24X Fiche 50-220, 84/08/07, 8408100103

8408100147 NUREG/CR-3820 V01
THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM Quarterly Report, January-March 1984
THOMPSON, S L Sandia Laboratories FIN A-1205 SAND84-1025/1
84/07/31 Division of Accident Evaluation 62pp 25996 280

8408100149 NUREG-0936 V03 N02
NRC REGULATORY AGENDA Quarterly Report, April-June 1984
* Division of Rules and Records 84/07/31 201pp 25998 112

8408100151 NUREG/CR-3689 V01
MATERIAL SCIENCE AND TECHNOLOGY DIVISION LIGHT-WATER-REACTOR SAFETY RESEARCH PROGRAM Quarterly Progress Report, January-March 1983
SHACK, W J Argonne National Laboratory FIN A-2016 ANL-83-85
84/07/31 Office of Nuclear Regulatory Research, Director 169pp
25998 313

8408100152 NUREG/CR-3734
LIGHT WATER REACTOR SAFETY RESEARCH PROGRAM Semiannual Report, October 1982 - March 1983
BERMAN, M Sandia Laboratories FIN A-1019 SAND84-0688 84/07/31
Division of Accident Evaluation 276pp 25996 001

8408100153 NUREG/CR-3742
BUCKLING OF STEEL CONTAINMENT SHELLS UNDER TIME-DEPENDENT LOADING
BABCOCK, C D , BAKER, W E , FLY, J Los Alamos Scientific Laboratory
FIN A-7221 LA-10087-MS 84/07/31 Division of Engineering Technology 38pp 25997 268

8408100155 NUREG/CR-3273
COMBUSTION OF HYDROGEN AIR MIXTURES IN THE VGES CYLINDRICAL TANK
BENEDICK, W B , CUMMINGS, J C , PRASSINOS, P G Sandia Laboratories
FIN A-1246 SAND83-1022 84/07/31 Division of Accident Evaluation 165pp 25997 308

8408130001 NUREG/CR-3492 V04
HIGH-TEMPERATURE GAS-COOLED REACTOR SAFETY STUDIES FOR THE DIVISION OF ACCIDENT EVALUATION QUARTERLY PROGRESS REPORT, October-December 1983
BALL, S J , CLEVELAND, J C , HARRINGTON, R M Oak Ridge National Laboratory FIN B-0122 ORNL/TM-8921/V4 84/07/31 Division of Accident Evaluation 27pp 26011 225

8408130002 NUREG-0675 S24
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 & 2 Docket Nos 50-275 & 50-323 (Pacific Gas & Electric Company)
* Division of Licensing 84/07/31 16pp 26038 295 24X
Fiche 50-275, 84/07/31, 8408130002

8408130006 NUREG/CR-3369
AN UNCERTAINTY STUDY OF PWR STEAM EXPLOSIONS
BERMAN, M , SWENSON, D V , WICKETT, A J Sandia Laboratories FIN A-1030 SAND83-1438 84/07/31 Division of Accident Evaluation 91pp 26040 238

8408130007 NUREG/CR-3139
SCENARIOS AND ANALYTICAL METHODS FOR UF6 RELEASES AT NRC-LICENSED FUEL CYCLE FACILITIES
SIMAN-TOV, M , DYKSTRA, J , HOLT, D D Oak Ridge National Laboratory
FIN B-0495 ORNL/ENG/TM-25 84/07/31 Division of Risk Analysis & Operations (post 840429) 97pp 26038 203

8408130009 NUREG/CR-3346
BIOASSAY DATA AND A RETENTION-EXCRETION MODEL FOR SYSTEMIC PLUTONIUM
LEGGETT, R W Oak Ridge National Laboratory FIN B-0480-2
ORNL/TM-8795 84/07/31, Division of Facility Operations 96pp, 26038, 108

8408130011 NUREG-1072
TECHNICAL SPECIFICATIONS FOR CATAWBA NUCLEAR STATION, Unit 1 Docket No 50-413
ANDERSON, F D Division of Licensing 84/07/31 525pp Available at NRC $10 00 26039 001 24X Fiche 50-413, 84/07/31, 8408130011

8408130041 NUREG/CR-3599
SOURCES OF UNCERTAINTY IN THE CALCULATIONS OF LOADS ON SUPPORTS OF PIPING SYSTEMS
* Oak Ridge National Laboratory RODABAUGH,E C E C Rodabaugh Associates, Inc FIN B 0474 84/07/31 Division of Engineering Technology 73pp 26040 166

8408130043 NUREG/CR-3751
EFFECTS OF ROCK RIPRAP DESIGN PARAMETERS ON FLOOD PROTECTION COSTS FOR URANIUM TAILINGS IMPOUNDMENTS
ECKER,R M Battelle Memorial Institute, Pacific Northwest Laboratories FIN B-2370 PNL-5068 84/07/31 Division of Radiation Programs & Earth Sciences (post 840429) 98pp Available at NRC $4 75 26011 254

8408130049 NUREG-0540 V06 N05
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE May 1-31, 1984
* Division of Technical Information & Document Control 84/07/31 649pp 26035 001

8408130129 Responds to 840602 SER re safety parameter display sys,per Suppl 1 to NUREG-0737 Secondary displays may be called up temporarily,but display always returns to primary display automatically
CURTIS,N W Pennsylvania Power & Light Co PLA-2258 84/08/08
SCHWENCER,A Licensing Branch 2 9pp 26007 335 24X
Fiche 50-387,84/08/08,8408130129

8408130169 Forwards description & justification for proposed piping seismic analysis changes,adopting damping values & spectra shifting methods for piping sys,per WRC recommendations, for review/approval
TUCKER,H B Duke Power Co 84/08/01 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 3pp 26010 027 24X Fiche 50-369,84/08/01,8408130169

8408130186 NUREG-0040 V08 N02
LICENSEE CONTRACTOR AND VENDOR INSPECTION STATUS REPORT
Quarterly Report,April-June 1984 (White Book)
* Division of QA, Safeguards & Inspection Programs (Post 830103) 84/07/31 433pp 26037 001

8408130191 Informs of error in 840627 correspondence re NUREG-0737,Item I C 1,Table 2 Phase 1 emergency operating procedures (EOPs) not in place in Nov 1983 EOPs will be implemented prior to restart from Cycle 10 refueling outage
FIEDLER,P B General Public Utilities - GPU Service Corp 84/08/06
CRUTCHFIELD,D Operating Reactors Branch 5 1p 26006 362 24X
Fiche 50-219,84/08/06,8408130191

8408130218 Forwards "PRA of Offsite Releases Initiated by Toxic Chemical Release," per NUREG-0737,Item III D 3 4 Transportation of offsite chemicals in vicinity of facility will not pose undue risk to control room operator
HUKILL,H D General Public Utilities - GPU Service Corp
5211-84-2199 84/08/08 STOLZ,J F Operating Reactors Branch 4
2pp 26008 065 24X Fiche 50-289,84/08/08,8408130218

--8408130225 PLG-0370
"PRA of Offsite Releases Initiated by Toxic Chemical Release," final rept
FENSTERMACHER, HUBBARD,F R , CALABRESE,R V Pickard, Lowe & Garrick, Inc PLG-0370 84/07/30 118pp 26008 067 24X
Fiche 50-289,84/08/08,8408130218

8408130233 Forwards safety evaluation & technical evaluation rept re control of heavy loads,Phase 1
VARGA,S A Operating Reactors Branch 1. 84/07/25 MCDONALD,R P, Alabama Power Co 2pp 26060 027 24X Fiche 50-348,84/07/25, 8408130233

--8408130258 SER re control of heavy loads,Phase 1 Phase 1 acceptable.
* NRC - No Detailed Affiliation Given 84/07/25 2pp
26060 029 24X Fiche 50-348,84/07/25,8408130233

8408130265 NUREG/CR-3053
CLOSEOUT OF IE BULLETIN 80-08 EXAMINATION OF CONTAINMENT LINER PENETRATION WELDS
DEAN,R S , FOLEY,W J , HENNICK,A Parameter, Inc FIN B-1013
IEB-80-08 84/07/31 Division of Emergency Preparedness & Engineering Response (Post 830103) 31pp Available at NRC $3 75
26038 074

8408130267 Forwards request for addl info re Suppl 1 to NUREG-0737 concerning safety parameter display sys.Project manager should be prepared to address info request within 5 days of ltr receipt
YOUNGBLOOD,B J Licensing Branch 1 GL-82-33 84/08/07
SPENCE,M D Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 5pp 26040 345 24X Fiche 50-445,84/08/07, 8408130267

8408130325 Submits schedule info on detailed control room design review summary rept,per Suppl 1 to NUREG-0737 Clarifies schedular error in 840612 confirmatory order Amend to order requested prior to Sept 1985
O'TOOLE,J D Consolidated Edison Co of New York, Inc GL-82-33
84/08/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26010 057 24X Fiche 50-247,84/08/06,8408130325

8408130349 Responds to 840702 request for addl info on CEN-268 re resolution of NUREG-0737,Item II K 3 5, "Study Need for Automatic Trip of Reactor Coolant Pumps " Response will be discussed at 840920 meeting
WELLS,R W C-E Operating Plants Owners Group WELLS,R W Northeast Utilities Service Co (subs of Northeast Utilities) RWW-84-60
84/08/07 MILLER,J R Operating Reactors Branch 3 2pp
26010 224

8408130351 Forwards update to 830127 description of natural circulation test program & "Evaluation of Natural Circulation Cooldown Test Performed at San Onofre Nuclear Generating Station " Confirmatory Item 7 in NUREG-0857,SSER 5 closed
VAN BRUNT,E E Arizona Public Service Co ANPP-30141-EEVB
84/08/07 KNIGHTON,G Licensing Branch 3 23pp 26006 170 24X
Fiche 50-528,84/08/07,8408130351

8408130357 Forwards response to 840604 request for addl info re NUREG-0737,Item II F 2 concerning inadequate core cooling instrumentation.
KOBER,R W Rochester Gas & Electric Corp 84/08/07 PAULSON,W A
Operating Reactors Branch 5 7pp 26010 060 24X
Fiche 50-244,84/08/07,8408130357

8408130449 Forwards "Control of Heavy Loads (Phase II-NUREG-0612) for Commanche Peak,Units 1 & 2," draft technical evaluation rept
YOUNGBLOOD,B J Licensing Branch 1 84/07/26 SPENCE,M D Texas Utilities Electric Co (Formerly Texas Utilities Generating Co) 3pp 26059 271 24X Fiche 50-445,84/07/26,8408130449

--8408130455 "Control of Heavy Loads (Phase II-NUREG-0612),Commanche Peak,Units 1 & 2," draft technical evaluation rept
YEN,T C EQ&G, Inc FIN A-6457 84/04/30 NRC - No Detailed Affiliation Given 40pp 26059 274 24X Fiche 50-445,84/07/26, 8408130449

8408130530 Forwards Amend 73 to License NPF-3 & safety evaluation Amend revises Tech Specs to add new Sections 3 3 2 3 & 4 3 2 3 & Tables 3 3-15 & 4 3-15 to reflect final anticipatory reactor trip sys
RIVENBARK,G W Operating Reactors Branch 4 GL-82-16 84/07/25
CROUSE,R P Toledo Edison Co 3pp 26038 341 24X
Fiche 50-346,84/07/25,8408130530

--8408130545 Safety evaluation supporting Amend 73 to License NPF-3
Evaluation of licensee B21115 response to Generic Ltr 82-16 also included
* Office of Nuclear Reactor Regulation, Director GL-82-16
84/07/25 8pp 26038 355 24X Fiche 50-346,84/07/25,8408130530

8408130585 Notifies that any permanent changes to new fuel container lifting rig will be made per ANSI N14.6-1978 requirements & NUREG-0612
STEWART,W L Virginia Electric & Power Co 364 84/08/03
DENTON,H R Office of Nuclear Reactor Regulation, Director
EISENHUT,D G Division of Licensing 1p 26031 359 24X
Fiche 50-280,84/08/03,8408130585

8408140029 Forwards corrected Page 2 to attachment to 840614 order confirming licensee commitments to implement post-TMI related items in Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability" (Generic Ltr 82-33)
MILLER,J R Operating Reactors Branch 3 GL-82-33 84/07/24
STEWART,W L Virginia Electric & Power Co 3pp 26061 259 24X
Fiche 50-338,84/07/24,8408140029

--8408140033 Correction to 840614 order confirming licensee commitments to Suppl 1 to NUREG-0737 Completion date for technical support ctr to be fully functional changed to 850731
MILLER,J R Operating Reactors Branch 3 84/07/24 Virginia Electric & Power Co 1p 26061 263 24X Fiche 50-338,84/07/24, 8408140029

8408140088 Forwards addl info on draft SER,Outstanding Issue 56 on TMI Item II K 3 12,Issue 58 re undetected failure of on-line ESF relays & Issue 77 on control sys failures caused by malfunction of instrument line
WOOLEVER,E J Duquesne Light Co 2NRC-4-119 84/08/09
KNIGHTON,G W Licensing Branch 3 5pp. 26045 354 24X
Fiche 50-412,84/08/09,8408140088

8408140239 Application for amend to License DPR-35, changing Tech Specs to provide redundant temp monitoring sys for suppression pool & responding to portions of TMI action plan requirements of NUREG-0737
HARRINGTON, W D Boston Edison Co BECO 84-128 84/08/09
VASSALLO, D B Operating Reactors Branch 2 1p 26055 316 24X
Fiche 50-293, 84/08/09, 8408140239

--8408140245 Proposed Tech Spec changes, providing redundant temp monitoring sys for suppression pool & responding to portions of TMI action plan requirements of NUREG-0737
* Boston Edison Co 84/08/09 13pp 26055 317 24X
Fiche 50-293, 84/08/09, 8408140239

8408140250 Responds to NRC 840613 request for info re analysis & methodology for Mark I long-term program for safety relief valve actuation not in conformance w/NUREG-0661 Review of procedures reveals complete conformance
HARRINGTON, W D Boston Edison Co BECO 84-127 84/08/09
VASSALLO, D B Operating Reactors Branch 2 1p 26053 358 24X
Fiche 50-293, 84/08/09, 8408140250

8408140295 Provides editorial changes to 840731 cover ltr & Attachment 1 re Suppl 1 to NUREG-0737, safety parameter display sys PSAR & implementation schedule, per Reg Guide 1 97 variables
JOHNSON, B D Consumers Power Co 84/08/09 CRUTCHFIELD, D
Operating Reactors Branch 5 6pp 26043 144 24X
Fiche 50-255, 84/08/09, 8408140295

8408140372 Forwards proposed rev to "Requalification Program for Licensed Operators, Senior Operators & Senior Operators (Limited)," in response to NUREG-0737, Item I A 3 1
MARSHALL, J G Commonwealth Edison Co 9034N 84/08/07
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
26051 240 24X Fiche 50-000, 84/08/07, 8408140372

8408140408 Forwards request for addl info to complete evaluation of util 830311 response to Generic Ltr 82-28 re inadequate core cooling instrument sys, NUREG-0737, Item II F 2
CRUTCHFIELD, D Assistant Director for Safety Assessment
LS05-84-08-008 84/08/06 COUNSIL, W G Connecticut Yankee Atomic
Power Co 6pp 26050 349 24X Fiche 50-213, 84/08/06, 8408140408

8408140411 Forwards corrected Tech Spec Section 6 16, "Post-Accident Sampling Programs" & Table 4 1-1 re instrument surveillance requirements, in response to NRC request for changes to 840604 Tech Spec Change Request 115
HUKILL, H D General Public Utilities - GPU Service Corp
5211-84-2198 84/08/08 STOLZ, J F Operating Reactors Branch 4
1p 26048 359 24X Fiche 50-289, 84/08/08, 8408140411

---8408140415 Corrected Tech Spec Change Request 115, adding phrases to clarify Tech Spec Section 6 16, "Post-Accident Sampling Programs," (NUREG-0737, II B 3 & II F 1 2) & Table 4 1-1 re instrument surveillance requirements
* General Public Utilities - GPU Service Corp 84/08/08 2pp
26048 360 24X Fiche 50-289, 84/08/08, 8408140411

8408140417 Comments on NUREG-1055 re Ford Amend Study on improving quality & QA in design & const of nuclear power plants Rept should be sent to intervenors who participated as full parties to CP & OL proceedings
BELL, N Nuclear Information & Resource Service 84/06/27
ANKRUM, O T QA Branch 1p 26050 333

8408140431 Responds to NRC 840604 review of detailed control room design review program plan, per Suppl 1 to NUREG-0737 Summary rept will be submitted by Dec 1984
PILANT, J M Nebraska Public Power District NLS8400226 84/08/09
VASSALLO, D B Operating Reactors Branch 2 3pp 26050 359 24X
Fiche 50-298, 84/08/09, 8408140431

8408140558 Forwards Amend 7 to License R-70, SER, EIA & notice of issuance & availability Amend renews license until June 29, 2000
EISENHUT, D G Division of Licensing 84/08/07 KERR, F Maryland, Univ of, College Park, MD 3pp 26065 236 24X
Fiche 50-166, 84/08/07, 8408140558

8408150087 Responds to NRC 820809 ltr re guidelines developed to facilitate review following implementation of NUREG-0737, Item II B 3 re post-accident sampling sys Info submitted to assist in SER preparation
HARRINGTON, W D Boston Edison Co BECO 84-122 84/08/09
VASSALLO, D B Operating Reactors Branch 2 9pp 26066 256 24X
Fiche 50-293, 84/08/09, 8408150087

8408150137 Forwards NRC comments on design evaluation rept program plan elements for detailed control room design review, including info re control room inventory & selection of design improvements Response by 850101 requested
KNIGHTON, G W Licensing Branch 3 84/08/01 UTLEY, E E Carolina
Power & Light Co 11pp 26104 203 24X Fiche 50-400, 84/08/01, 8408150137

8408150212 Requests exemption from NUREG-0737, Table II F 1-2, design basis shielding envelope criteria of 100 uCi/cc of gaseous radioiodine / particulates deposited on sampling media
LINDER, F Dairyland Power Cooperative LAC-10104 84/08/01
CRUTCHFIELD, D Operating Reactors Branch 5 4pp 26066 241 24X
Fiche 50-409 84/08/01, 8408150212

8408150223 Forwards responses to 840504 ltr re INEL rept on util conformance to Reg Guide 1 97 requirements for emergency response capability & Suppl 1 to NUREG-0737 Changes to 830921 implementation plan listed
LIDEN, E A Public Service Electric & Gas Co of New Jersey
84/08/09 VARGA, S A Operating Reactors Branch 1 9pp 26066 081
24X Fiche 50-272, 84/08/09, 8408150223

8408150269 Forwards "Evaluation of Detailed Control Room Design Review Summary Rept for Oyster Creek Nuclear Generating Station," technical evaluation rept, per Suppl 1 to NUREG-0737 SALP input also encl
PAULSON, W A Operating Reactors Branch 5 LS05-84-08-016
84/08/14 FIEDLER, P B General Public Utilities - GPU Service Corp
14pp 26067 066 24X Fiche 50-219, 84/08/14, 8408150269

8408150310 Forwards SER re TMI Items II F 1 1, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor " Design acceptable
VASSALLO, D B Operating Reactors Branch 2 84/07/30 UTLEY, E E
Carolina Power & Light Co 12pp 26099 341 24X
Fiche 50-324, 84/07/30, 8408150310

8408150320 Forwards, for review & concurrence, NUREG/BR-0051, "Power Reactor Events, Jan-Feb 1984 " Concurrence requested by 840713
HELTEMES, C J Director's Office 84/07/11 DENTON, H R Office of
Nuclear Reactor Regulation, Director 1p 26099 284

8408150380 Forwards IE Insp Rept 50-440/84-13 on 840709-12 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/07/27
EDELMAN, M R Cleveland Electric Illuminating Co 2pp 26078 002
24X Fiche 50-440, 84/07/27, 8408150380

--8408150381 IE Insp Rept 50-440/84-13 on 840709-12 No violations or deviations noted Major areas inspected radiation protection program, including organization & staffing, training & procedures & radiography incident on 840616
MILLER, D E , GREGER, L R Region 3, Office of Director 84/07/27
6pp 26078 004 24X Fiche 50-440, 84/07/27, 8408150380

8408150526 Forwards NUREG-1031, "SER re Operation of Millstone Nuclear Power Station, Unit 3 "
YOUNGBLOOD, B J Licensing Branch 1 84/08/02 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 454pp
26094 167 24X Fiche 50-423, 84/08/02, 8408150526

8408150544 Forwards IE Insp Rept 50-263/84-14 on 840625-29 & notice of violation
PAPERIELLO, C J Region 3, Office of Director 84/07/26
LARSON, C E Northern States Power Co 2pp 26079 222 24X
Fiche 50-263, 84/07/26, 8408150544

--8408150547 IE Insp Rept 50-263/84-14 on 840625-29 Violation noted solid radwaste contained free standing liquid
GRANT, W B , NICHOLSON, N A , GREGER, L R Region 3, Office of
Director 84/07/26 9pp 26079 225 24X Fiche 50-263, 84/07/26, 8408150544

8408160021 Requests justification of emergency operating guidelines by ref to Oconee guideline approved by NRC Response by 840914 requested
STOLZ, J F Operating Reactors Branch 4 84/08/08 CROUSE, R P
Toledo Edison Co 2pp 26128 210 24X Fiche 50-346, 84/08/08, 8408160021

8408160035 Informs that util plans to prepare general safety evaluation to expand safe load path boundaries in reactor bldg Evaluation will be submitted for review by 841101
KANGA, B K General Public Utilities - GPU Service Corp
4410-84-L-0131 84/08/10 SNYDER, B J TMI Program Office 2pp
26092 050 24X Fiche 50-320, 84/08/10, 8408160035

8408160039 Advises that upgraded in-core thermocouple sys schedule will be completed by 1986 refueling outage, per 840221 commitment & will meet requirements of NUREG-0737, Item II F 2
STEWART, W L Virginia Electric & Power Co 448 84/08/01
DENTON, H R Office of Nuclear Reactor Regulation, Director
EISENHUT, D G Division of Licensing 1p 26092 052 24X
Fiche 50-280, 84/08/01, 8408160039

8408160046 Forwards request for addl info re procedures generation package (PGP) Review or PGP conducted per Generic Ltr 82-33 (Suppl 1 to NUREG-0737)
VASSALLO,D B Operating Reactors Branch 2 GL-82-33 84/07/27
UTLEY,E E Carolina Power & Light Co 9pp 26128 162 24X
Fiche 50-324,84/07/27,8408160046

8408160063 Clarifies SNUPPS design & procedural controls for mitigation of postulated control room fires,per SSER 3 (NUREG-0830)
Requests meeting w/NRC,per procedures for disposition of backfitting requirements implemented by IE & NRR
PETRICK,N A Standardized Nuclear Unit Power Plant System BLNRC 84-0106 84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 26085 313 24X Fiche 50-000,84/08/10, 8408160063

8408160080 NUREG-0675 S25
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT,UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Pacific Gas And Electric Company)
* Division of Licensing 84/07/31 122pp Available at NRC
$5 50 26124 033 24X Fiche 50-275,84/07/31,8408160080

8408160092 Forwards safety parameter display sys (SPDS) preimplementation audit results Schedule for submittal of addl SPDS info due within 60 days of ltr receipt NUREG-0737, Suppl 1 guidelines require resolution
VASSALLO,D B Operating Reactors Branch 2 84/08/03 PILANT,J M
Nebraska Public Power District 12pp 26126 329 24X
Fiche 50-298,84/08/03,8408160092

8408160102 Forwards IE Insp Repts 50-317/84-16 & 50-318/84-16 on 840604-08 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 84/07/24
LUNDVALL,A E Baltimore Gas & Electric Co 2pp 26108 135 24X
Fiche 50-317,84/07/24,8408160102

--8408160115 IE Insp Repts 50-317/84-16 & 50-318/84-16 on 840604-08
Violation noted failure to establish procedures for incomplete work followup on safety-related mod to auxiliary feedwater sys
BLUMBERG,N , BETTENHAUSEN,L Region 1, Office of Director
50-318/84-16 84/07/12 12pp 26108 138 24X
Fiche 50-317,84/07/24,8408160102

8408160125 NUREG/CR-3870
RADIATION DOSE ESTIMATES AND HAZARD EVALUATIONS FOR INHALED AIRBORNE RADIONUCLIDES Annual Progress Rept July 1982 - June 1983
MEWHINNEY,J A Inhalation Toxicology Research Institute FIN A-1031 LMF-109 84/07/31 38pp Available at NRC $3 75
26122 313

8408160146 NUREG/CR-3735
ACCIDENT-INDUCED FLOW AND MATERIAL TRANSPORT IN NUCLEAR FACILITIES--A LITERATURE REVIEW
BOLSTAD,J W , GREGORY,W S , MARTIN,R A Los Alamos Scientific Laboratory FIN A-7029 LA-10007?-MS 84/07/31 45pp 26122 266

8408160155 Forwards SER on NUREG-0737,Item II K 3 22 re automatic switchover of RCIC sys suction Manual switchover of RCIC suction on low water level in condensate storage tank acceptable
VASSALLO,D B Operating Reactors Branch 2 84/07/27 PARRIS,H G
Tennessee Valley Authority 9pp 26126 154 24X
Fiche 50-259,84/07/27,8408160155

8408160163 Forwards DES (NUREG-1085) & FR notice of availability W/o DES
SCHWENCER,A Licensing Branch 2 84/08/09 HIRSCH,A
Environmental Protection Agency 2pp 26124 355 24X
Fiche 50-410,84/08/09,8408160163

--8408160166 Notice of availability of DES (NUREG-1085)
SCHWENCER,A Licensing Branch 2 84/08/09 2pp 26124 357 24X
Fiche 50-410,84/08/09,8408160163

8408160167 Informs of review of 840615 ltr re auxiliary feedwater sys (AFW) (TMI Item II E 1 1) Requests Tech Spec for monthly surveillance testing of AFW sys pumps
MILLER,J R Operating Reactors Branch 3 84/08/01 RANDAZZA,J B
Maine Yankee Atomic Power Co 2pp 26124 350 24X
Fiche 50-309,84/08/01,8408160167

8408160188 Forwards results of review of NUREG-0737,Item II B 3 open items re post-accident sampling sys Mods will be completed & sys operational by Sept 1984
ALEXICH,M P Indiana & Michigan Electric Co AEP NRC 0678H
84/08/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 26092 036 24X Fiche 50-315,84/08/02,8408160188

8408160191 NUREG-0020 VOB N06
LICENSED OPERATING REACTORS STATUS SUMMARY REPT Data As Of May 31,1984 (Gray Book)
* Division of Budget & Analysis 84/07/31 394pp 26123 001

8408160215 Forwards addl info re current alternate post-accident sampling sys methods,completion schedules for procurement of components,const & operator training & justification for deferral to Cycle IX refueling outage
MEDFORD,M O Southern California Edison Co 84/08/14 PAULSON,W A
Operating Reactors Branch 5 17pp 26090 334 24X
Fiche 50-206,84/08/14,8408160215

8408160220 Forwards IE Insp Rept 50-382/84-21 on 840514-18 No violations or deviations noted
GAGLIARDO,J E Region 4, Office of Director 84/06/28
LEDDICK,R S Louisiana Power & Light Co 2pp 26106 237 24X
Fiche 50-382,84/06/28,8408160220

--8408160226 IE Insp Rept 50-382/84-21 on 840514-18 No violations or deviations noted Major areas inspected previously identified insp findings & selected TMI action plan requirements
CHANEY,H D , MURRAY,B , CROSSMAN,W A Region 4, Office of Director 84/06/28 9pp 26106 239 24X Fiche 50-382,84/06/28, 8408160220

8408160248 NUREG/CR-3761
RELAP5 THERMAL-HYDRAULIC ANALYSES OF PRESSURIZED THERMAL SHOCK SEQUENCES FOR THE OCONEE-1 PRESSURIZED WATER REACTOR
FLETCHER,C D , BOLANDER,M A , STITT,B D EG&G, Inc FIN A-6047
EGG-2310 84/07/31 Division of Accident Evaluation 165pp
26129 001 24X Fiche 50-269,84/07/31,8408160248

8408160249 Notification of 840829 meeting w/C-E Owners Group Operations Subcommittee in Bethesda,MD to discuss task analysis requirement of Suppl 1 to NUREG-0737 & Generic Ltr 82-33 & portions of CEN-152,Rev 2 re inadequate core cooling
CLAYTON,H B Procedures & Systems Review Branch GL-82-33
84/08/09 ZIEMANN,D L Procedures & Systems Review Branch 5pp
26126 248

8408160250 NUREG-0675 S27
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT,UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Pacific Gas And Electric Company)
* Division of Licensing 84/07/31 31pp Available at NRC
$3 50 26122 235 24X Fiche 50-275,84/07/31,8408160250

8408160262 NUREG-1031
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF MILLSTONE NUCLEAR POWER STATION,UNIT NO 3 Docket No 50-423 (Northeast Nuclear Energy Company)
* Division of Licensing 84/07/31 591pp Available at NRC
$11 00 26121 001 24X Fiche 50-423,84/07/31,8408160262

8408160333 Forwards responses to Parts 2 & 3 of Accident Evaluation Branch draft SER Open Item 53 re control room habitability
WOOLEVER,E J Duquesne Light Co 2NRC-4-124 84/08/13
KNIGHTON,G W Licensing Branch 3 3pp 26085 338 24X
Fiche 50-412,84/08/13,8408160333

8408160368 Forwards Rev 1 to "Detailed Control Room Design Review Program Plan," per NUREG-0737,Item I D 1 & Suppl 1 to NUREG-0737
HARRINGTON,W D Boston Edison Co BECO 84-134 84/08/14
VASSALLO,D B Operating Reactors Branch 2 1p 26090 159 24X
Fiche 50-293,84/08/14,8408160368

--8408160369 Rev 1 to "Detailed Control Room Design Review Program Plan "
* Boston Edison Co 84/06/30 120pp 26090 160 24X
Fiche 50-293,84/08/14,8408160368

8408160374 Forwards proprietary "Conceptual Design Description for Pilgrim Nuclear Power Station Emergency & Plant Info Computer (EPIC) Safety Parameter Display Sys (SPDS)," per 831026 commitment & TMI Action Item I D 2 Rept withheld.
HARRINGTON,W D Boston Edison Co BECO 84-133 84/08/10
VASSALLO,D B Operating Reactors Branch 2 1p 26091:192 24X
Fiche 50-293,84/08/10,8408160374

8408160431 Forwards DES (NUREG-1085) & FR notice of availability W/o DES
SCHWENCER,A Licensing Branch 2 84/08/09 HOOTEN,B J, Niagara Mohawk Power Corp 2pp 26122 355 24X Fiche 50-410,84/08/09, 8408160431

8408160511 Forwards IE Insp Rept 50-458/84-12 on 840604-08 No violations or deviations noted
JOHNSON,E H Region 4, Office of Director 84/07/30 CAHILL,W J
Gulf States Utilities Co 2pp 26108 001 24X
Fiche 50-458,84/07/30,8408160511

--8408160915 IE Insp Rept 50-458/84-12 on 840604-08 No violations or deviations noted Major areas inspected radiological environ monitoring program, including organization & mgt controls, training & qualifications & equipment & supplies
BAER, R E , WISE, R , MURRAY, D Region 4, Office of Director
84/07/30 8pp 26108 003 24X Fiche 50-458, 84/07/30, 8408160511

8408170052 Forwards "Control Room Design Review Summary Rept - Hope Creek Generating Station," in response to Generic Ltr 82-33, Item 5 (NUREG-0737, Suppl 1) Meeting requested
MITTL, R L Public Service Electric & Gas Co of New Jersey
GL-82-33 84/08/14 SCHWENCER, A Licensing Branch 2 2pp
26118 133 24X Fiche 50-354, 84/08/14, 8408170052

8408170094 Responds to 840712 ltr re 840502 Pottstown Mercury article & related petition Low level normal operation releases expected to be well within recognized safety limits Excerpts from DES encl
DIRCKS, W J Office of the Executive Director for Operations
84/08/08 WALKER, R S House of Rep 1p 26135 322 24X
Fiche 50-352, 84/08/08, 8408170094

8408170104 Forwards FR notice of availability of DES (NUREG-1085). Svc list encl
SCHWENCER, A Licensing Branch 2 84/08/09 Library of Congress
3pp 26134 355 24X Fiche 50-410, 84/08/09, 8408170104

8408170107 Forwards DES (NUREG-1085) Comments due 45 days after publication of FR notice of availability W/o encl
SCHWENCER, A Licensing Branch 2 84/08/09 New York, State of
1p 26134 352 24X Fiche 50-410, 84/08/09, 8408170107

8408170110 Forwards DES (NUREG-1085) Comments due 45 days after publication of FR notice of availability W/o encl
SCHWENCER, A Licensing Branch 2 84/08/09 WOOD, J M Commerce, Dept of, Natl Oceanographic & Atmospheric Administration 5pp
26134 345 24X Fiche 50-410, 84/08/09, 8408170110

8408170138 Forwards evaluation re resolution of SER Confirmatory Issue 5, TMI action plan items & status of review of steam generator tube rupture event
YOUNGBLOOD, B J Licensing Branch 1 84/08/09 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co)
10pp. 26134 335 24X Fiche 50-445, 84/08/09, 8408170138

8408170277 Forwards info on NUREG-0737, Item II B 3 re post-accident sampling sys, supplementing 831026, 1202 & 840323 submittals Results of engineering evaluation of post-accident airborne particulates will be sent by June 1985
BAYNE, J P Power Authority of the State of New York IPN-84-31,
84/08/13 VARGA, S A Operating Reactors Branch 1 3pp 26115 256
24X Fiche 50-286, 84/08/13, 8408170277

8408170386 Requests meeting to discuss detailed control room design review w/respect to Nuclear Util Task Action Committee documents
VARGA, S A Operating Reactors Branch 1 84/05/24 MCDONALD, R P
Alabama Power Co 3pp 26134 193 24X Fiche 50-348, 84/05/24,
8408170386.

8408200018 Board Notification 84-143 forwards Ofc of Investigation Rept 1-83-010 on alleged falsification of TMI-2 leak rate surveillance test data. Rept consistent w/Suppl 5 to NUREG-0680 re TMI-1 restart
EISENHUT, D G Division of Licensing 84/08/15 PALLADINO, ROBERTS, ASSELSTINE Commissioners 5pp 26300 145 24X
Fiche 50-289, 84/08/15, 8408200018

8408200135 Forwards addl info concerning NUREG-0737, Item II B 3 re post-accident sampling, per 840719 request Rexnord Model 340 portable oxygen monitor used to determine dissolved oxygen in reactor coolant sample.
CROUSE, R P Toledo Edison Co 1066 84/08/14 STOLZ, J F
Operating Reactors Branch 4. 19pp 26133 260 24X
Fiche 50-346, 84/08/14, 8408200135

8408200172 Forwards response to 840709 request for addl info re inadequate core cooling instrumentation, per Generic Ltr 82-28 Comments re subcooled margin monitor, core exit thermocouples & heated junction thermocouples encl
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities A04089 84/08/14
MILLER, J R Operating Reactors Branch 3 34pp 26133 025 24X
Fiche 50-336, 84/08/14, 8408200172

8408200190 Forwards SER on proposed resolution for integrated plant SAR (NUREG-0824), Section 4 28.3 re gas turbine preventive maint program. Program acceptable
SHEA, J Operating Reactors Branch 5 LS05-84-019 84/08/16
COUNSIL, W G Northeast Nuclear Energy Co, (subs of Northeast Utilities) 4pp 26133 064. 24X Fiche 50-245, 84/08/16, 8408200190

8408200219 Denies 830927 request to revise Tech Specs re containment hydrogen analyzers Present calibr requirement preferred because of more accurate hydrogen concentration measurement
MILLER, J R Operating Reactors Branch 3 84/08/01 GRIFFIN, J M
Arkansas Power & Light Co 2pp 26142 286 24X
Fiche 50-368, 84/08/01, 8408200219

8408200303 Informs that response to Recommendation GL-2 re inadvertent closure to condensate storage tank isolation valve (NUREG-0737, Item II E 1 1) will be delayed until 840824 due to outage preparation work
MARSHALL, J R Arkansas Power & Light Co OCAN088409 84/08/10
STOLZ, J F Operating Reactors Branch 4 1p 26133 358 24X
Fiche 50-313, 84/08/10, 8408200303

8408200311 Advises that Emergency Operating Procedure OP-404, "DHR Sys," addresses concern raised at 840215 meeting re boron precipitation decay heat sys flow into reactor hot leg
WESTAFER, G R Florida Power Corp 3F0884-03 84/08/08
RIVENBARK, G W Operating Reactors Branch 4 1p 26133 019 24X
Fiche 50-302, 84/08/08, 8408200311

8408200330 Provides excerpts from Missile Impact Analysis Rept E/L 20622 re turbine-driven emergency feedwater pump missile potential, in response to NUREG-0737, Item II E 1 1 Response satisfies Item 2b of 840501 SER
WESTAFER, G R Florida Power Corp 3F0884-02 84/08/08
RIVENBARK, G W Operating Reactors Branch 4 2pp 26133 002 24X
Fiche 50-302, 84/08/08, 8408200330

8408200359 Forwards Amend 82 to License DPR-40 & safety evaluation Amend adds operability & surveillance requirements for containment hydrogen, water & pressure monitors
TOURIGNY, E G Operating Reactors Branch 3 84/08/02 JONES, W C
Omaha Public Power District 1p 26141 220 24X
Fiche 50-285, 84/08/02, 8408200359

--8408200361 Safety evaluation supporting Amend 82 to License DPR-40
* Office of Nuclear Reactor Regulation, Director GL-83-37
84/08/02 4pp 26141 226 24X Fiche 50-285, 84/08/02, 8408200359

8408200386 Forwards DES (NUREG-1074), per 840810 telcon w/D Wagner W/o encl
SCHWENCER, A Licensing Branch 2 84/08/10 ALS, E Environmental Protection Agency 3pp 26141 217 24X Fiche 50-354, 84/08/10,
8408200386

8408200387 Advises that program plan for conducting detailed control room design review meets intent of Suppl 1 to NUREG-0737 Listed areas should be described in summary rept expected 850830
VARGA, S A Licensing Branch 1 84/08/10 STEWART, W L Virginia Electric & Power Co 2pp 26141 215 24X Fiche 50-000, 84/08/10,
8408200387

8408200414 Forwards draft safety evaluation of procedures generation package for emergency operating procedures Response to open items re writers guide & validation/verification programs requested within 30 days of ltr receipt.
RIVENBARK, G W Operating Reactors Branch 4 84/08/09 TUCKER, H B
Duke Power Co 2pp 26182 001 24X Fiche 50-269, 84/08/09,
8408200414

8408200449 Responds to 840712 request for consideration of constituent H Mayerson 840607 ltr w/840502 Pottstown Mercury article & encl petition Low level normal operation releases expected to be well within recognized safety limits
DIRCKS, W J Office of the Executive Director for Operations
84/08/08 WALKER, R S House of Rep 5pp 26182 313 24X
Fiche 50-352, 84/08/08, 8408200449

--8408200454 Forwards constituent H Mayerson 840607 ltr w/840502 Pottstown Mercury article, "Limerick to Release Very Small Amounts of Radioactivity" & petition & requests investigation of statements
WALKER, R S House of Rep 84/07/12 KAMMERER, C Office of Congressional Affairs 6pp 26182 332 24X Fiche 50-352,
84/08/08, 8408200449

8408200469 Forwards SER (NUREG-1031) re operation & FR notice of availability W/o SER
YOUNGBLOOD, B J Licensing Branch 1 84/08/13 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities). 3pp
26143 356 24X Fiche 50-423, 84/08/13, 8408200469

--8408200471 Notice of availability of SER (NUREG-1031)
YOUNGBLOOD, B J Licensing Branch 1 84/08/13 2pp 26143 359
24X Fiche 50-423, 84/08/13, 8408200469

8408200521 Protests ref to author in Suppl 5 to NUREG-0680 as one of five util mgt personnel involved or implicated in indictment Staff accusation improper & damaging to author reputation Requests withdrawal of findings
KUNDER, G A Affiliation Not Assigned DSB 162 SP 84/08/13
PALLADINO, N J Commissioners 2pp 26136 361 24X
Fiche 50-289, 84/08/13, 8408200521

8408200531 Protests treatment of author in Suppl 5 to NUREG-0680 re leak rate tests at TMI-2 US Atty conclusions in statement of fact misleading, out of context or erroneous Requests refusal of staff conclusions
FLOYD, J R Affiliation Not Assigned DSB 161 SP 84/08/13
PALLADINO, N J Commissioners 2pp 26137 026 24X
Fiche 50-289, 84/08/13, 8408200531

8408200540 Forwards DES (NUREG-1073) & FR notice of availability W/o DES
SCHWENCER, A Licensing Branch 2 84/08/09 CAHILL, W J Gulf States Utilities Co 2pp 26143 285 24X Fiche 50-458, 84/08/09, 8408200540

--8408200546 Notice of availability of DES (NUREG-1073) Related correspondence
SCHWENCER, A Licensing Branch 2 84/08/09 2pp 26143 287 24X
Fiche 50-458, 84/08/09, 8408200540

8408200552 Forwards DES (NUREG-1073) & FR notice of issuance & availability W/o DES
SCHWENCER, A Licensing Branch 2 84/08/09 HIRSCH, A Environmental Protection Agency 2pp 26143 277 24X
Fiche 50-458, 84/08/09, 8408200552

8408200580 Expresses dissatisfaction w/staff conclusions re author in Suppl 5 to NUREG-0680 concerning RCS leak rate tests Conclusion that author involved or implicated in indictment misleading & unfair NRC conclusions should not be adopted
SEELINGER, J L Affiliation Not Assigned DSB 163 SP 84/08/09
PALLADINO, N J Commissioners 2pp 26137 138 24X
Fiche 50-289, 84/08/09, 8408200580

8408210002 Forwards SAR for safety assessment sys/safety parameter display sys, per NUREG-0737, Suppl 1 & 830415 & 840312 ltrs.
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/08/15
EISENHUT, D G Division of Licensing 13pp 26183 054 24X
Fiche 50-247, 84/08/15, 8408210002

8408210029 Advises that mods to containment pressure monitoring sys to increase sys range & sys mod to measure vacuum up to 5 psig satisfy NUREG-0737 requirements & are acceptable
PAULSON, W A Operating Reactors Branch 5 LSDS-84-08-021
84/08/17 LINDER, F Dairyland Power Cooperative 2pp 26181 335
24X Fiche 50-409, 84/08/17, 8408210029

8408210031 Forwards addl info requested in NRC 840430 ltr re exceptions to conformance to Rev 2 to Reg Guide 1 97 Encls should close Open Item 12 of SER (NUREG-0991)
KEMPER, J S Philadelphia Electric Co 84/08/16 SCHWENCER, A Licensing Branch 2 11pp 26181 337 24X Fiche 50-352, 84/08/16, 8408210031

8408210054 Forwards Amend 71 to License DPR-72 & safety evaluation Amend revises format of physical security plan to be compatible w/NUREG-0908 & changes number of operational & administrative requirements
SILVER, H Operating Reactors Branch 4 84/08/13 WILGUS, W S Florida Power Corp 3pp 26195 163 24X Fiche 50-302, 84/08/13, 8408210054

--8408210061 Amend 71 to License DPR-72, revising format of physical security plan to be compatible w/NUREG-0908 & changing number of operational & administrative requirements
STOLZ, J F Operating Reactors Branch 4 84/08/13 2pp
26195 166 24X Fiche 50-302, 84/08/13, 8408210054

8408210128 Forwards 840629 QA review plan, per 840725 request Package includes transmittal ltr, QA review plan & NUREG-1055 W/o encl
LINEHAN, J J Repository Projects Branch (Post 831001) 626
84/07/30 NEFF, J O Energy, Dept of 1p 26195, 319

8408210158 Forwards status rept re control room design review, per Suppl 1 to NUREG-0737 If plan not fully resolved by fuel load, licensing will be accomplished on PDA basis
YOUNGBLOOD, B J Licensing Branch 1 84/08/13 SPENCE, M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 20pp 26195 287 24X Fiche 50-445, 84/08/13, 8408210158

8408210313 Forwards revised FSAR App 7A pages addressing NRC 840625-26 requests for addl info re Reg Guide 1 97 As-built plant design info not included in original submittal, incorporated Design provides info required to satisfy Rev 2 to reg guide
PETRICK, N A Standardized Nuclear Unit Power Plant System SLNRC 84-107 84/08/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 65pp 26179 060 24X Fiche 50-000, 84/08/16, 8408210313

8408210333 Submits safety analysis of safety parameter display sys & operational support ctr as required by Generic Ltr 82-33 re emergency response capability (Suppl 1 to NUREG-0737)
LINDER, F Dairyland Power Cooperative LAC-10124 84/08/13
CRUTCHFIELD, D Operating Reactors Branch 5 8pp 26179 332 24X
Fiche 50-409, 84/08/13, 8408210333

8408210338 Informs that no addl post-accident sampling sys required to meet guidance of NUREG-0737, Item II B 3 Item complete High-range containment radiation monitors acceptable method of providing indication of core damage
PAULSON, W A Operating Reactors Branch 5 LSDS-84-08-021
84/08/17 VANDEWALLE, D J Consumers Power Co 3pp 26179 358
24X Fiche 50-155, 84/08/17, 8408210338

8408210346 Forwards "Crystal River Nuclear Power Plant Exercise " Rev specific NUREG-0654/FEMA-REP-1, Rev 1, deficiencies observed during 840425 emergency exercise State of FL & Citrus & Levy counties participated
KRIMM, R W Federal Emergency Management Agency 84/08/13
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26179 136 24X Fiche 50-302, 84/08/13, 8408210346

--8408210354 "Crystal River Nuclear Power Plant Exercise "
* Federal Emergency Management Agency 84/05/11 42pp
26179 138 24X Fiche 50-302, 84/08/13, 8408210346.

8408210357 Responds to 840801 ltr re NUREG-0737, Item II E 4 2(7), "Purge & Vent Valve Isolation " Revs to Unit 2 Tech Specs expected to be submitted by 840905 Unit 1 mods will be completed during scheduled Fall 1984 refueling outage
GUCWA, L T Georgia Power Co NED-84-425 84/08/16 STOLZ, J F Operating Reactors Branch 4 2pp 26160, 241 24X
Fiche 50-321, 84/08/16, 8408210357

8408210368 Forwards IE Insp Repts 50-352/84-26 & 50-353/84-09 on 840601-30 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/08/02
KEMPER, J S Philadelphia Electric Co 2pp 26183 109 24X
Fiche 50-352, 84/08/02, 8408210368

--8408210381 IE Insp Repts 50-352/84-26 & 50-353/84-09 on 840601-30 Violations identified inadequate diesel generator test program implementation & inadequate calibr procedure for valve position indicating sys
CHAUDHARY, S K , WIGGINS, J T , BAUNACK, W Region 1, Office of Director 50-353/84-09 84/07/24 13pp 26183 115. 24X
Fiche 50-352, 84/08/02, 8408210368

8408210396 Forwards info documenting results of review & implementation of required changes & mods, per Generic Ltr 81-07, "Control of Heavy Loads" & NUREG-0612 Minor error noted in 801222 ltr corrected
TUCKER, H B Duke Power Co GL-81-07. 84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 36pp 26180 271 24X Fiche 50-369, 84/08/17, 8408210396

8408210415 Requests extension for implementation of upgraded emergency operating procedures from Third Quarter 1985 until Fourth Quarter 1985 Extension will allow all licensed operators to receive training in use of new procedures at simulator
WITHERS, B D Portland General Electric Co GL-82-33 84/08/15
EISENHUT, D G Division of Licensing 5pp 26180:339 24X
Fiche 50-344, 84/08/15, 8408210415

8408210419 Forwards Rev 0 to CYGNA rept, "Main Steam/Feedwater Piping Analysis Rept " Rept addresses SEP Topic III-6 re safe shutdown sys piping outside vapor container
KAY, J A Yankee Atomic Electric Co FYR 84-87 84/08/16
CRUTCHFIELD, D. Operating Reactors Branch 5 1p 26178 196 24X
Fiche 50-029, 84/08/16, 8408210419

8408210484 Submits revised commitments & proposed changes to Tech Specs & emergency procedures re meteorological sys, per NUREG-0654, App 2 Quarterly meteorological sensor calibr should be performed semiannually.
DALE, L F Mississippi Power & Light Co AECM-8410354. 84/08/14
DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp.
26177, 358 24X Fiche 50-416, 84/08/14, 8408210484

8408210564 Forwards draft safety evaluation of NUREG-0737, Item II F 2 re inadequate core cooling instrumentation sys Evaluation identifies open items Addl info requested within 2 wks W/o encl
VARGA, S A Operating Reactors Branch 1 84/08/14 WILLIAMS, J W Florida Power & Light Co 1p 26195 255 24X Fiche 50-250, 84/08/14, 8408210564

8408220107 NUREG-0420 S06
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SHOREHAM NUCLEAR POWER STATION, UNIT NO 1 Docket No 50-322 (Long Island Lighting Company)
* Division of Licensing 84/07/31 33pp Available at NRC $3 75 26199 304 24X Fiche 50-322, 84/07/31, 8408220107

8408220152 Forwards IE Insp Rept 50-458/84-06 on 840430-0504 No violations or deviations noted
JOHNSON, E H Region 1, Office of Director 84/07/19 CAHILL, W J Gulf States Utilities Co 2pp 26188 076 24X Fiche 50-458, 84/07/19, 8408220152

--8408220157 IE Insp Rept 50-458/84-06 on 840430-0504 No violations noted Major areas inspected radiation protection program including organization, mgt controls, staffing, qualifications, training programs & selected NUREG-0737 action items
CHANEY, H D , MURRAY, B , JAUDON, J P Region 1, Office of Director 84/07/18 26pp 26188 078 24X Fiche 50-458, 84/07/19, 8408220152

8408220239 Discusses post-accident sampling sys being installed to address NRC requirements in NUREG-0737, Item II B 3 High radiation sampling sys described in FSAR will be operational on each unit prior to initial criticality
TRAMM, T R Commonwealth Edison Co 9072N 84/08/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 26193 139 24X Fiche 50-000, 84/08/13, 8408220239

8408220265 NUREG-0933 S01
A PRIORITIZATION OF GENERIC SAFETY ISSUES
EMRIT, R , MINNERS, W , VANDER MOLEN, H Division of Safety Technology 84/07/31 120pp 26212 062

8408220308 NUREG-0940 V03 N02
ENFORCEMENT ACTIONS SIGNIFICANT ACTIONS RESOLVED Quarterly Progress Report, April-June 1984
* Enforcement Staff 84/07/31 363pp 26202 001

8408220318 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF NINE MILE POINT NUCLEAR STATION, UNIT NO 2 Docket No 50-410 (Niagara Mohawk Power Corporation, Rochester Gas & Electric Corporation And Central Hudson Gas & Electric Corporation)
* Division of Licensing 84/07/31 313pp 26201 037 24X Fiche 50-410, 84/07/31, 8408220318

8408220325 NUREG-1073
DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF RIVER BEND STATION Docket No 50-458 (Gulf States Utilities Company & Cajun Electric Power Cooperative)
* Division of Licensing 84/07/31 249pp 26199 001 24X Fiche 50-458, 84/07/31, 8408220325

8408220326 Forwards safety evaluation & technical evaluation rept re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants - Phase I " Sections 5 1 1 & 5 3 satisfied Phase I acceptable
PAULSON, W A Operating Reactors Branch 3 L805-84-08-026 84/08/20 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 26193 111 24X Fiche 50-213, 84/08/20, 8408220326

--8408220330 Safety evaluation re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants - Phase I "
* Operating Reactors Branch 3 84/08/20 2pp 26193 113 24X Fiche 50-213, 84/08/20, 8408220326

--8407300136 TCR-C5506-358
"Control of Heavy Loads, Connecticut Yankee Atomic Power Co, Haddam Neck Plant," technical evaluation rept
BOMBERGER, C Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 07993 84/07/25 SINGH, A NRC - No Detailed Affiliation Given 24pp 26193 115 24X Fiche 50-213, 84/08/20, 8408220326

8408220327 NUREG/CR-3874
NEAR-GROUND TORNADO WIND FIELDS
MCDONALD, J R Texas Tech Univ , Lubbock, TX FIN B-8099 84/07/31 Division of Radiation Programs & Earth Sciences (post 840429) 164pp Available at NRC $5 50 26198 197

8408220332 Comments on NUREG-1055 re Ford Amend rept Study of human behavioral factors as applied to QA should be recognized, evaluated & developed as constructive mgt effort of nuclear industry
MANNING, H A Gilbert/Commonwealth, Inc (formerly Gilbert Associates, Inc) 84/08/16 CHILK, S J Office of the Secretary of the Commission 1p 26194 062

8408220333 NUREG/CR-3493
A REVIEW OF THE LIMERICK GENERATING STATION SEVERE ACCIDENT RISK ASSESSMENT Review of Core Melt Frequency
AZARM, M A , BARI, R A , BOCCIO, J L Brookhaven National Laboratory FIN A-3393 BNL-NUREG-51711 84/07/31 Division of Safety Technology 192pp Available at NRC $6 00 26200 205 24X Fiche 50-352, 84/07/31, 8408220333

8408220346 NUREG-0675 S26
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2
* Division of Licensing 84/07/31 204pp Available at NRC $6 50 26200 001 24X Fiche 50-275, 84/07/31, 8408220346

8408220363 Forwards response to request for addl info re control of heavy loads mods, per NUREG-0612, resulting from discussions w/Franklin Research Ctr & Rev 0 to Procedure 1408-6, "Procedure for Insp of Wire Rope or Synthetic Slings "
HUKILL, H D General Public Utilities - GPU Service Corp 5211-84-2200 84/08/16 EISENHUT, D G Division of Licensing 6pp 26189 324 24X Fiche 50-289, 84/08/16, 8408220363

8408220370 NUREG/CR-3869
ANALYSIS OF THE IMPACT OF INSERVICE INSPECTION USING A PIPING RELIABILITY MODEL
SIMONEN, F A , WOO, H W Battelle Memorial Institute, Pacific Northwest Laboratories FIN B-2289 PNL-5149 84/08/31 Division of Engineering Technology 55pp Available at NRC $4 25 26199 249

8408220375 Responds to request for addl info re analysis to determine gas & water clearing thrust loads concerning second safety relief valve actuations in discharge lines, per NUREG-0661 Containment adequate for five & addl five valve actuation
FIEDLER, P B General Public Utilities - GPU Service Corp 84/08/15 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 26191 347 24X Fiche 50-219, 84/08/15, 8408220375

8408220378 NUREG/BR-0081
A DIRECTORY OF HIGH-TECHNOLOGY B(a) FIRMS
* Miranda Associates, Inc 84/07/31 Ofc of Small & Disadvantaged Bus Utilization & Civil Rights 400pp 26231 001

8408220434 Forwards DES (NUREG-1073) & FR notice of issuance Comments due 45 days after FR publication W/o DES
SCHWENCER, A Licensing Branch 2 84/08/09 Louisiana, State of 1p 26209 336 24X Fiche 50-458, 84/08/09, 8408220434

8408230033 Advises that Nuclear Packaging, Inc topical rept on FL-50 container acceptable Rept info should include list of solid waste species & source which might be incompatible w/ container matl Info should meet NUREG-0800 guidance
OAKHILL, W P Meteorology & Effluent Treatment Branch 84/07/15 BARRETT, L H Engineering Branch (Post 831001) 1p 26233 353

8408230046 Forwards selected major comments re draft Umbrella Site technical position for salt, geology, groundwater geochemistry, design & waste package Comments developed considering need to minimize efforts to make revs
MILLER, H J Repository Projects Branch (Post 831001) 84/08/07 KNAPP, M R Geotechnical Branch (Post 831001) BARRETT, L Engineering Branch (Post 831001) 15pp 26233 316

8408230056 Responds to 840727 ltr transmitting SL Benavidez 840627 concerns re failure of reactor trip sys of nuclear plants NRC established 10CFR50 62, which requires addl features be installed at each reactor to assure shutdown if sys fails
DIRCKS, W J Office of the Executive Director for Operations 84/08/15 DOMENICI, P V Senate 6pp 26233 275 24X Fiche 50-000, 84/08/15, 8408230056

8408230078 Forwards IE Insp Rept 50-312/84-08 on 840521-25 No violations noted Matters re post-accident sampling program & offsite dose projection errors unresolved
SCARANO, R A Division of Radiological Safety & Safeguards Program 84/07/30 RODRIGUEZ, R J Sacramento Municipal Utility District 3pp 26213 159 24X Fiche 50-312, 84/07/30, 8408230078

--8408230087 IE Insp Rept 50-312/84-08 on 840521-25 No violations or deviations noted Major areas inspected unresolved items (NUREG-0737, II B 3 re post-accident sampling sys) & offsite dose calculation code errors
NORTH, H S , YUHAS, G P Region 5, Office of Director 84/07/06 16pp 26213 161 24X Fiche 50-312, 84/07/30, 8408230078

8408230084 Forwards responses to questions re BAW-10155 "FOAM2," submitted on behalf of B&W Owners Group as part of small break LOCA methods program response to NUREG-0565 & NUREG-0737, Item II K 3 30
TAYLOR, J H Babcock & Wilcox Co ESC-535 84/08/15 THOMAS, C O Standardization & Special Projects Branch 14pp 26209 041

8408230125 NUREG-0386 D03
UNITED STATES NUCLEAR REGULATORY COMMISSION STAFF PRACTICE AND PROCEDURE DIGEST
* Office of the Executive Legal Director * Aspen Systems, Inc 84/07/31 569pp 26232 033

8408230132 Informs of review of 840705 ltr which clarified interpretation of on-shift training requirements Util will be required to provide documentation that senior reactor operator upgrade candidates comply w/listed requirements
WALVER, R D Region 3, Office of Director 84/08/20 LARSON, C E Northern States Power Co 2pp 26209 061 24X
Fiche 50-000, 84/08/20, 8408230132

8408230292 Forwards Rev 3 to 'Overhead Handling Sys Review " Rept revised, per NUREG-0612, to address concerns identified in draft technical evaluation rept on control of heavy loads & support resolution of SER License Condition 7
KEMPER, J S Philadelphia Electric Co 84/08/13 SCHWENCER, A Licensing Branch 2 3pp 26207 001 24X Fiche 50-352, 84/08/13, 8408230292

--8408230297 Rev 3 to final rept "Overhead Handling Sys Review "
* Philadelphia Electric Co 84/06/30 175pp 26207 004 24X
Fiche 50-352, 84/08/13, 8408230292

8408230295 Forwards request for addl info re proposed safety parameter display sys Response requested 30 days prior to exceeding 5% rated power
KNIGHTON, G W Licensing Branch 3 84/08/06 LEDDICK, R S Louisiana Power & Light Co 7pp 26236 119 24X
Fiche 50-382, 84/08/06, 8408230295

8408230296 Forwards Rev 1 to Radiation Chemistry Procedure 78 000 15, "Determination of Extent of Core Damage," to resolve SSER 3 (NUREG-0798) open items Procedure supports deletion of license condition proposed in SER
JENS, W H Detroit Edison Co EF2-72758 84/08/16 YOUNGBLOOD, B J Licensing Branch 1 4pp 26208 005 24X Fiche 50-341, 84/08/16, 8408230296

8408230306 Advises that 840131 submittal on detailed control room design review does not meet all requirements of Suppl 1 to NUREG-0737 Review did not include task analysis Addl significant concerns listed
KNIGHTON, G W Licensing Branch 3 84/08/09 BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp 26236 102 24X Fiche 50-361, 84/08/09, 8408230306

8408230340 Forwards proprietary draft answers to questions in NRC Request 2 for addl info on WCAP-10054(P) & WCAP-10054, Addendum 1 to "Westinghouse Small Break ECCS Evaluation Model Using NOTRUMP Code For C-E NSSS "
RAHE, E P Westinghouse Electric Corp NS-EPR-2940 84/08/10
THOMAS, C O NRC - No Detailed Affiliation Given 3pp 26205 350

8408230379 Forwards SSERs 24-27 (NUREG-0675) Distribution of svc list includes SSERs 25-27 since Board Notification 84-137 issued SSER 24 W/o encl
KNIGHTON, G W Licensing Branch 3 84/08/10 SCHUYLER, J O Pacific Gas & Electric Co 4pp 26230 334 24X Fiche 50-275, 84/08/10, 8408230379

8408230384 Forwards SER re util resolution of integrated plant SAR Section 4 14 re thermal overload protection of motor operated valves Program described in 840730 ltr acceptable
PAULSON, W A Operating Reactors Branch 5 LSO5-84-08-024
84/08/20 FIEDLER, P B Jersey Central Power & Light Co 2pp 26205 315 24X Fiche 50-219, 84/08/20, 8408230384

--8408230385 Safety evaluation re integrated plant SAR Section 4 14 re thermal overload protection of motor operated valves Program proposed in 840730 ltr acceptable
* Operating Reactors Branch 5 84/08/20 2pp 26205 317 24X
Fiche 50-219, 84/08/20, 8408230384

8408230389 Forwards, for review, "Control Room Design Review Program Plan for Fermi 2," per Suppl 1 to NUREG-0737 & Generic Ltr 82-33
JENS, W H Detroit Edison Co EF2-72747 84/08/16 YOUNGBLOOD, B J Licensing Branch 1 2pp 26205 249 24X Fiche 50-341, 84/08/16, 8408230389

--8408230391 "Control Room Design Review Program Plan fo Fermi 2 "
* Detroit Edison Co EF2-72747 84/08/04 48pp 26205 251
24X Fiche 50-341, 84/08/16, 8408230389

8408230418 Informs that original approval of program re NUREG-0737, Item I A 1 1, "Shift Technical Advisor," remains unchanged All new hires must meet training requirements specified in 790913 & 1030 ltrs
PAULSON, W A Operating Reactors Branch 5 LSO5-84-08-029
84/08/22 LINDER, F Dairyland Power Cooperative 2pp 26204 009
24X Fiche 50-409, 84/08/22, 8408230418

8408230420 Comments on groundwater STP for Palo Duro & Paradox bedded salt basins Program inconsistent in treating prewaste emplacement phenomenon w/post-emplacement phenomenon, per 10CFR60 113
JOHNSON, T C Engineering Branch (Post 831001) 6pp 84/08/07
POHLE, J Geotechnical Branch (Post 831001) 2pp 26230 241

8408230502 Forwards IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance noted
WARNICK, R F Region 3, Office of Director 84/08/03 COOK, J W Consumers Power Co 2pp 26212 264 24X Fiche 50-329, 84/08/03, 8408230502

--8408230512 IE Insp Repts 50-329/84-24 & 50-330/84-25 on 840611-15 & 25-29 No noncompliance or deviations noted Major areas inspected licensee action on 10CFR50 55(e) items
HARRISON, J J Region 3, Office of Director 50-330/84-25
84/08/03 8pp 26212 266 24X Fiche 50-329, 84/08/03, 8408230502

8408240155 Forwards description of how Rev 3 to Reg Guide 1 97, "Instrumentation for LWR Nuclear Power Plants to Assess Plant & Environs Condition During & Following Accident," per Suppl 1 to NUREG-0737 Mods will be implemented by 871231
BAYNARD, P V Florida Power Corp 3F0884-07 84/08/21
RIVENBARK, G W Operating Reactors Branch 4 85pp 26228 001 24X
Fiche 50-302, 84/08/21, 8408240155

8408240187 NUREG-0750 V19 N03
NUCLEAR REGULATORY COMMISSION ISSUANCES March 1984 Pages 555-936
* Division of Technical Information & Document Control 84/08/31
386pp 26250 001

8408240188 Forwards status rept on inadequate core cooling instrumentation sys, per 831219 request Rept addresses reactor vessel instrumentation sys, core exit thermocouples, subcooling margin monitor & NUREG-0737, Item II F 2
ALEXICH, M P Indiana & Michigan Electric Co AEP NRC 0761C
84/08/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 26227 355 24X Fiche 50-315, 84/08/20, 8408240188

8408240229 Summary of 840725 meeting w/util re detailed control room design review, per NUREG-0737, Suppl 1
REEVES, E A Operating Reactors Branch 1 84/08/16 Operating Reactors Branch 1 6pp 26251 227 24X Fiche 50-348, 84/08/16, 8408240229

8408240249 NUREG/CP-0053
PROCEEDINGS OF THE NINTH ANNUAL STATISTICS SYMPOSIUM ON NATIONAL ENERGY ISSUES, October 19-21, 1983
BRYSON, M C Los Alamos Scientific Laboratory FIN A-7225
LA-10127-C 84/08/31 Division of Risk Analysis & Operations (post 840429) 200pp 26251 027

8408240266 Forwards order correcting administrative error in 840612 order re licensee commitments on emergency response capability Order requires implementation to meet criteria of Table 1 of Suppl 1 to NUREG-0737 by 850701
PAULSON, W A Operating Reactors Branch 5 LSO5-84-08-030
84/08/23 KAY, J A Yankee Atomic Electric Co 3pp 26223 112
24X Fiche 50-029, 84/08/23, 8408240266

--8408240281 Order confirming further licensee commitment on emergency response capability Licensee required to complete implementation of upgraded emergency operations facility to meet criteria of Table 1 of Suppl 1 to NUREG-0737 by 850901
MIRAGLIA, F J Division of Licensing 84/08/23 Yankee Atomic Electric Co 4pp 26223 115 24X Fiche 50-029, 84/08/23, 8408240266

8408240293 Comments on DES (NUREG-1074) Water treatment intake sys, cooling water sys, power transmission sys, groundwater, water use, terrestrial resources, aquatic resources & historical & archaeological sites discussed
MITTL, R L Public Service Electric & Gas Co. of New Jersey
84/08/17 SCHWENCER, A Licensing Branch 2. 8pp 26236 271 24X
Fiche 50-354, 84/08/17, 8408240293

8408240320 NUREG/CR-3818
REPORT OF RESULTS OF NUCLEAR POWER PLANT AGING WORKSHOPS
CLARK,N H , BERRY,D L Sandia Laboratories FIN A-1357
SAND-84-0374 84/08/31 Division of Engineering Technology
64pp 26237 284

8408240322 NUREG/CR-3894
ULTRASONIC AND METALLURGICAL EXAMINATION OF A CRACKED TYPE
304 STAINLESS STEEL BWR PIPE WELDMENT
PARK,J Y , KUPPERMAN,D Argonne National Laboratory FIN A-2212
ANL-84-6 84/07/31 Division of Engineering Technology 22pp
26255 169

8408240328 Confirms 840829 meeting in Bethesda,MD to discuss task analysis requirements of NUREG-0737,Suppl 1 & SER open items on CEN-152 re inadequate core cooling & reactor vessel level monitoring sys
THOMPSON,H L Division of Human Factors Safety 84/08/13
BARRON,J Florida Power & Light Co 1p 26253 336 24X
Fiche 50-250,84/08/13,8408240328

--8408240330 Notification of 840829 meeting w/util in Bethesda,MD to discuss task analysis requirements of NUREG-0737,Suppl 1 & SER open items on CEN-152 re inadequate core cooling & reactor vessel level monitoring sys
CLAYTON,H B Procedures & Systems Review Branch 84/08/09
ZIEMAN,D L Procedures & Systems Review Branch 2pp 26253 337
24X Fiche 50-250,84/08/13,8408240328

8408240364 Forwards Insp Repts 50-321/84-23 & 50-366/84-23 on 840618-22 No violations or deviations noted Unresolved items identified will be pursued during future insps
DANCE,H C Region 2, Office of Director 84/07/11 KELLY,R J
Georgia Power Co 2pp 26237 080 24X Fiche 50-321,84/07/11,
8408240364

--8408240366 Insp Repts 50-321/84-23 & 50-366/84-23 on 840618-22 No violations or deviations noted Major areas inspected evaluation of ultrasonic test indications in feedwater weld 2021-1FW-12AA-12 (Unit 2)
CROWLEY,D R , COLEY,J L , BLAKE,J J Region 2, Office of Director
50-366/84-23 84/07/10 12pp 26237 082 24X
Fiche 50-321,84/07/11,8408240364

8408240379 NUREG/CR-3708
LWR SPENT FUEL DRY STORAGE BEHAVIOR AT 229 C
EINZIGER,R E Westinghouse Electric Corp COOK,J A EG&G, Inc
FIN B-2435 84/07/31 Division of Engineering Technology 134pp
26255 001

8408240382 NUREG/CR-1740 R01
DATA SUMMARIES OF LICENSEE EVENT REPORTS OF SELECTED INSTRUMENTATION AND CONTROL COMPONENTS AT U S COMMERCIAL NUCLEAR POWER PLANTS JANUARY 1,1976 TO DECEMBER 31,1981
TROJOUSKY,M , BROWN,S R, EG&G, Inc FIN A-6393 EGG-2307
84/07/31 Division of Risk Analysis & Operations (post 840429),
344pp 26249,001

8408240428 Forwards Insp Rept 50-305/84-07 on 840709-13 & notice of violation Licensee should address emergency preparedness weaknesses identified in App B Shift staffing also questioned W/o notice of violation & App B
HIND,J A Region 3, Office of Director 84/08/06 GIESLER,C W
Wisconsin Public Service Corp 3pp 26237 121 24X
Fiche 50-305,84/08/06,8408240428

8408270019 Forwards remittance for 840615 request for amends in response to Generic Ltr 83-37 re NUREG-0737 Tech Specs,per 10CFR170 22
WILLIAMS,J W Florida Power & Light Co. L-84-215 84/08/21
EISENHUT,D G Division of Licensing 1p 26247 194 24X
Fiche 50-250,84/08/21,8408270019

8408270030 Advises of adoption of Westinghouse generic core damage assessment methodology,in response to NUREG-0737,Item II B.3, "Post-Accident Sampling Capability "
SCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) TXX-4273 84/08/20 YOUNGBLOOD,B J Licensing
Branch 1 1p 26245 058 24X Fiche, 50-445,84/08/20,8408270030

8408270084 Forwards Insp Rept 50-341/84-27 on 840709-13 & 25 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 84/08/10 JENS,W H
Detroit Edison Co 2pp 26258 210 24X Fiche 50-341,84/08/10,
8408270084

--8408270090 Insp Rept 50-341/84-27 on 840709-13 & 25 No noncompliance noted Major areas inspected:preoperational radiation protection program,facilities,equipment,NUREG-0737 items, status of preoperational sys & drain sys
HUETER,L J , GILL,C F , GREGER,L R Region 3, Office of Director
84/08/10 20pp 26258 212 24X Fiche 50-341,84/08/10,8408270084

8408270113 Informs of schedule for resolving concerns re provisions for sampling gaseous radioiodine OL should be conditioned to require resolution of NUREG-0737 requirements for sampling gaseous effluent steam prior to refueling outage
TRAMM,T R Commonwealth Edison Co 9097N 84/08/17 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 26247 329 24X
Fiche 50-454,84/08/17,8408270113

8408270114 Provides supplemental response to Generic Ltr 83-36, "NUREG-0737 Tech Specs " Mods to Quad Cities radiological ETS will not be complete until Fall 1984 Complete response w/Tech Spec amend requests expected by 841115
ALEXANDER,G L Commonwealth Edison Co GL-83-36 84/08/15
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
26247 330 24X Fiche 50-000,84/08/15,8408270114

8408270133 Forwards "Containment Ultimate Capacity Analysis," per NUREG-0897, "SER re Operation of Palo Verde Nuclear Generating Station,Units 1,2 & 3 " Analysis should close license condition discussed in Section 3 8 1
VAN BRUNT,E E Arizona Public Service Co ANPP-30284-EEVB
84/08/20 KNIGHTON,G Licensing Branch 3 3pp 26245 061 24X
Fiche 50-528,84/08/20,8408270133

8408270204 Forwards addl info re monitoring of leakage from sys outside containment used to transport highly radioactive fluid & gases in post-accident condition Info should close SER Confirmatory Issue 28(a)
TRAMM,T R Commonwealth Edison Co 9065N 84/08/11 DENTON,H R
Office of Nuclear Reactor Regulation, Director 7pp 26245 103
24X Fiche 50-000,84/08/11,8408270204

8408270260 Requests approval of two temporary deviations in emergency preparedness plan from goals for augmentation of emergency response organization in Suppl 1 to NUREG-0737 Nature & duration of deviations encl
VAN BRUNT,E E Arizona Public Service Co ANPP-30234-EEVB
84/08/20 KNIGHTON,G Licensing Branch 3 27pp 26243 131 24X
Fiche 50-528,84/08/20,8408270260

8408270285 Forwards Technical Data Rept 580 re repair & failure analysis data for isolation condenser sys piping cracked welds,per 840628 request concerning SER of Rev 1 to NUREG-0313 implementation
FIEDLER,P B General Public Utilities - GPU Service Corp 84/08/22
PAULSON,W A Operating Reactors Branch 5 1p 26243 158 24X
Fiche 50-219,84/08/22,8408270285

8408270289 Forwards Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted
DANCE,H C Region 2, Office of Director 84/07/09 WILLIAMS,J W
Florida Power & Light Co 2pp 26258 167 24X
Fiche 50-250,84/07/09,8408270289

--8408270295 Insp Repts 50-250/84-19 & 50-251/84-19 on 840604-08 No violations or deviations noted Major areas inspected emergency preparedness
MARSTON,R R Region 2, Office of Director 50-251/84-19
84/07/06 9pp 26258 169 24X Fiche 50-250,84/07/09,8408270289

8408270291 Ack receipt of 840709 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/84-18 & 50-389/84-19
DANCE,H C Region 2, Office of Director 84/08/02 WILLIAMS,J W
Florida Power & Light Co 1p 26258 178 24X Fiche 50-335,
84/08/02,8408270291

--8408270298 Responds to NRC 840608 ltr re violations noted in Insp Repts 50-335/84-18 & 50-389/84-19 Corrective actions installed detectors will be replaced & two spare detectors properly calibr
WILLIAMS,J W Florida Power & Light Co L-84-173 84/07/09
O'REILLY,J P Region 2, Office of Director 2pp 26258 179 24X
Fiche 50-335,84/08/02,8408270291

--8408270310 Notice of violation from insp on 840514-18
* Region 2, Office of Director 50-389/84-19 84/06/08 1p
26258 183 24X Fiche 50-335,84/08/02,8408270291

--8408270317 Insp Repts 50-335/84-18 & 50-389/84-19 on 840514-18 Noncompliance noted failure to certify proper vendor calibr of containment high-range radiation monitors prior to initial use
WRAY,J R , JENKINS,O R Region 2, Office of Director
50-389/84-19 84/06/08 6pp 26258 184 24X
Fiche 50-335,84/08/02,8408270291

8408270293 Forwards Rev 1 to 840403 application for amend to License DPR-22 Rev modifies surveillance requirements for emergency filtration train charcoal absorber & filters & toxic gas monitoring requirements for control room
MUSOLF,D Northern States Power Co 84/08/17 Office of Nuclear
Reactor Regulation, Director 1p 26242 313 24X
Fiche 50-263,84/08/17,8408270293

8408280238 Forwards plant-specific procedures for estimating core damage as required by NUREG-0737, Item II B 3, Criterion 2, per SER confirmatory item
COUNSIL, W G , FEE, W F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities F0540A
84/08/16 YOUNGBLOOD, B J Licensing Branch 1 2pp 26262 070
24X Fiche 50-423, 84/08/16, 8408280238

8408280290 Forwards draft technical evaluation rept re control of heavy loads, for review & comment Project manager should be contacted within 30 days to discuss outstanding items W/o encl
VARGA, S A Operating Reactors Branch 1 84/08/20 O'TOOLE, J D
Consolidated Edison Co of New York, Inc 1p 26294 086 24X
Fiche 50-247, 84/08/20, 8408280290

8408280319 Forwards draft technical evaluation rept, "Control of Heavy Loads - Phase II, Davis-Besse Nuclear Power Station Unit 1," for review
STOLZ, J F Operating Reactors Branch 4 TAC 52271 84/08/17
CROUSE, R P Toledo Edison Co 2pp 26294 053 24X
Fiche 50-346, 84/08/17, 8408280319

--8408280321 TER-C5506-489 DRFT
Draft "Control of Heavy Loads - Phase II, Davis-Besse Nuclear Power Station Unit 1,' technical evaluation rept
BOMBERGER, C R , WALTER, R J , SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 52271
84/07/10 SINGH, A NRC - No Detailed Affiliation Given 26pp
26294 059 24X Fiche 50-346, 84/08/17, 8408280319

8408280488 Confirms util 840808 commitment to submit by 841001, revised Tech Specs re instrumentation for containment sump level & containment pressure & equipment for RCS high point vents, per Generic Ltr 83-37 & NUREG-0737
STOLZ, J F Operating Reactors Branch 4 GL-83-37 84/08/17
CROUSE, R P Toledo Edison Co 2pp 26292 355 24X
Fiche 50-346, 84/08/17, 8408280488

8408290001 Advises that Multi-Plant Action B-59 re masonry wall design complete Plant structures will be seismically evaluated for weak links, per NUREG-0828
PAULSON, W A Operating Reactors Branch 5 LSD5-84-08-035
84/08/27 VANDEWALLE, D J Consumers Power Co 5pp 26291 269
24X Fiche 50-155, 84/08/27, 8408290001

8408290158 NUREG-1048
REVIEW INSIGHTS ON THE PROBABILISTIC RISK ASSESSMENTS FOR THE LIMERICK GENERATING STATION, UNIT 1 AND 2
CHELLIAH, E Division of Safety Technology 84/08/31 126pp
Available at NRC $5 00 26309 151 24X Fiche 50-352, 84/08/31, 8408290158

8408290171 NUREG/CR-3569
SPECIAL AND DOSIMETRIC MEASUREMENTS OF PHOTON FIELDS AT COMMERCIAL NUCLEAR SITES
ROBERSON, P L , FOX, R A , HOLBROOK, K L Battelle Memorial Institute, Pacific Northwest Laboratories FIN B-2419 PNL-4915 84/08/31
Division of Facility Operations 182pp Available at NRC $6 00
26299 119

8408290185 NUREG/CR-3884
EVALUATION OF NUCLEAR FACILITY DECOMMISSIONING PROJECTS PROGRAM - THREE MILE ISLAND UNIT 2 POLAR CRANE RECOVERY
DOERGE, D H , MILLER, R L United Nuclear Corp FIN B-7568
84/08/31 Division of Engineering Technology 63pp Available at NRC $4 50 26309 267

8408290190 NUREG/CR-3591 V01
PRECURSORS TO POTENTIAL SEVERE CORE DAMAGE ACCIDENTS 1980-1981 A Status Report
COTTRELL, W B , MINARICK, J W , AUSTIN, P N Oak Ridge National Laboratory FIN B-0435 84/07/31 Division of Risk Analysis & Operations (post 840429) 262pp 26312 001

8408290198 NUREG/CR-3591 V02
PRECURSORS TO POTENTIAL SEVERE CORE DAMAGE ACCIDENTS 1980-1981 A Status Report
COTTRELL, W B , MINARICK, J W , AUSTIN, P N Oak Ridge National Laboratory FIN B-0435 84/07/31 Division of Risk Analysis & Operations (post 840429) 266pp 26311 001

8408290353 NUREG-0090 V07 NO1
REPORT TO CONGRESS ON ABNORMAL OCCURRENCES January-March 1984
Director's Office 84/07/31 52pp 26299 305

8408290478 Forwards Insp Rept 50-322/84-23 on 840528-0701 No violations noted.
STAROSTECKI, R Division of Project & Resident Programs 84/08/08
LEONARD, J L Long Island Lighting Co 4pp. 26294 189 24X
Fiche 50-322, 84/08/08, 8408290478

NONDOCKETED ITEMS

--8408290483 Insp Rept 50-322/84-23 on 840528-0701 No violations noted Major areas inspected discharge of security guard weapon, status of Colt diesel generator project, storage of emergency equipment lockers & IE Bulletin 80-06
PETRONE, C , ESELGROTH, P , SHEDLOSKY, J Region 1, Office of Director IEB-80 06 84/07/19 12pp 26294 193 24X
Fiche 50-322, 84/08/08, 8408290478

8408300156 Forwards Insp Rept 50-255/84-06 on 840322-23 & 0427 W/o notice of violation
KEPPLER, J G Region 3, Office of Director 84/07/11 DEWITT, R B Consumers Power Co 2pp 26307 333 24X Fiche 50-255, 84/07/11, 8408300156

--8408300164 Insp Rept 50-255/84-06 on 840322-23 & 0427 Noncompliance noted dose to worker exceeded 10CFR20 101 limits, failure to provide proper monitoring for high radiation area access & failure to follow radiation protection procedures
LOVENDALE, P C , GREGER, L R Region 3, Office of Director
84/07/10 13pp 26307 335 24X Fiche 50-255, 84/07/11, 8408300156

8408300187 Forwards Insp Repts 50-528/84-23 & 50-529/84-17 on 840602-0701 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/08/02 VAN BRUNT, E E Arizona Public Service Co
2pp 26308 014 24X Fiche 50-528, 84/08/02, 8408300187

--8408300193 Insp Repts 50-528/84-23 & 50-529/84-17 on 840602-0701 No violations noted Major areas inspected preoperational testing activities, maint, review of maint & followup on TMI Lessons Learned implementation
ZIMMERMAN, R , FIORELLI, G , BOSTED, C Region 5, Office of Director
50-529/84-17 84/08/01 12pp 26308 016 24X
Fiche 50-528, 84/08/02, 8408300187

8408300208 Forwards FEMA findings on State of FL & associated local emergency plans re plant
DANCE, H C Region 2, Office of Director 84/06/05 WILGUS, W S Florida Power Corp 1p 26307 044 24X Fiche 50-302, 84/06/05, 8408300208

--8408300211 Approves State of FL & local plans & preparedness for alerting & protecting public in event of radiological emergency Approval conditional on verification of alert & notification per App 3 of NUREG-0654/FEMA-REP-1, Rev 1
SPECK, S W Federal Emergency Management Agency 84/02/15
DIRCKS, W J Office of the Executive Director for Operations 1p
26307 045 24X Fiche 50-302, 84/06/05, 8408300208

8408300272 NUREG/CR-3590
EVALUATION OF ISOTOPE DILUTION MASS SPECTROMETRY FOR BIOASSAY MEASUREMENT OF URANIUM, PLUTONIUM, AND THORIUM IN URINE
DYER, F F , MAY, M P , WALKER, R L Oak Ridge National Laboratory FIN B-0494 ORNL/TM-9006 84/08/31 Division of Facility Operations
79pp 26330 224

8408300279 NUREG-0304 V09 N02
REGULATORY AND TECHNICAL REPORTS Compilation For Second Quarter 1984
* Division of Technical Information & Document Control 84/08/31
180pp 26331 346

8408300282 NUREG/CR-3851 V01
PROGRESS IN EVALUATION OF RADIONUCLIDE GEOCHEMICAL INFORMATION DEVELOPED BY DOE HIGH-LEVEL NUCLEAR WASTE REPOSITORY SITE PROJECTS Report for October-December 1983
KELMERS, A D , KESSLER, J H , ARNOLD, W D Oak Ridge National Laboratory ORNL/TM-9191/V1 84/08/31 Division of Waste Management 48pp Available at NRC $4 00 26331 224

8408300287 NUREG/CR-2000 V03 N7
LICENSEE EVENT REPORT (LER) Compilation For Month of July 1984
* Oak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200
84/08/31 Director's Office 101pp 26331 123

8408300289 NUREG/BR-0025 V10 N6
INFORMATION REPORT ON STATE LEGISLATION
KERR, O W , MCGUADE, J Office of State Programs, Director 84/07/27
9pp 26330 333

8408300292 NUREG-1054
SIMPLIFIED ANALYSIS FOR LIQUID PATHWAY STUDIES
CODELL, R B Division of Engineering 84/08/31 104pp Available at NRC $5 00 26331 001

8408300304 Ack receipt of DES (NUREG-1074) Future submissions should be sent to Commissioner, State of NJ, Dept of Environ Protection
SILVER, N S New Jersey, State of 84/08/24 SCHWENCER, A
Licensing Branch 2 1p 26306 359 24X Fiche 50-354, 84/08/24, 8408300304

8408300381 Forwards Insp Repts 50-528/84-25 50-529/84-19 & 50-530/84-12 on 840709-13 & notices of violation & deviation
BISHOP, T W Region 5, Office of Director 84/08/08 VAN BRUNT, E E Arizona Public Service Co 2pp 26308 122 24X
Fiche 50-528, 84/08/08, 8408300383

--8408300407 Insp Repts 50-528/84-25 50-529/84-19 & 50-530/84-12 on 840709-13 Violations noted fire protection sys not designed to retain structural integrity during seismic event
CLARK, C Region 5, Office of Director 50-530/84-12 84/08/03
24pp 26308 127 24X Fiche 50-528, 84/08/08, 8408300383

8408310003 Forwards request for addl info re safety parameter display sys implementation plan & parameter selection rept submitted in 840501 response to Generic Ltr 82-33
(NUREG-0737, Suppl 1) Response requested within 45 days
VARGA, S A Operating Reactors Branch 1 GL-82-33 84/08/15
WILLIAMS, J W Florida Power & Light Co 4pp 26350 202 24X
Fiche 50-250, 84/08/15, 8408310003

8408310007 Responds to 840206 ltr on SER License Condition 7 re compliance w/NUREG-0612, control of heavy loads, Phase II "Limerick Overhead Handling Sys Final Rept (Rev 3)" revised per 840206 request Related correspondence
KEMPER, J S Philadelphia Electric Co DSB 293 OL 84/08/16
SCHWENCER, A Licensing Branch 2 3pp 26350 197 24X
Fiche 50-352, 84/08/16, 8408310007

8408310030 Forwards comments on equivalent cold license training program Requests addl info re hot license program Hot license program equivalent to cold license training for determining eligibility
DANCE, H C Region 2, Office of Director 84/06/07 WILLIAMS, J W
Florida Power & Light Co 3pp 26335 017 24X
Fiche 50-250, 84/06/07, 8408310030

8408310075 NUREG/CR-3798
CHARACTERIZATION OF CEMENT AND BITUMEN WASTE FORMS CONTAINING SIMULATED LOW-LEVEL WASTE INCINERATOR ASH
WESTSIK, J H , BUSCHBOM, R L , DIVINE, J R Battelle Memorial Institute, Pacific Northwest Laboratories FIN B-2401 PNL-5153
84/08/31 Division of Radiation Programs & Earth Sciences (post 840429) 100pp Available at NRC $4 75 26347 319

8408310077 NUREG/CR-3689 V03
MATERIALS SCIENCE AND TECHNOLOGY DIVISION LIGHT-WATER REACTOR SAFETY RESEARCH PROGRAM Quarterly Progress Report, July-September 1983
REST, J Argonne National Laboratory FIN A-2016 ANL-83-85
84/07/31 Division of Engineering Technology 40pp 26347 277

8408310083 NUREG/CR-3689 V02
MATERIALS SCIENCE AND TECHNOLOGY DIVISION LIGHT-WATER REACTOR SAFETY RESEARCH PROGRAM Quarterly Progress Report, April-June 1983
SHACK, W J Argonne National Laboratory FIN A-2016 ANL-83-85
84/07/31 Division of Engineering Technology 141pp 26348 215

8408310084 NUREG/CR-3792
CLOSEOUT OF IE BULLETIN 79-11 FAULTY OVERCURRENT TRIP DEVICE IN CIRCUIT BREAKERS FOR ENGINEERED SAFETY SYSTEMS
FOLEY, W J , DEAN, R S , HENNICK, A Parameter, Inc FIN B-8714
IEB-79-11 84/08/31 Division of Emergency Preparedness & Engineering Response (Post 830103) 34pp Available at NRC $4 00
26348 057

8408310089 NUREG/CR-3690
RELAP5 ASSESSMENT SEMISCALE NATURAL CIRCULATION TESTS S-NC-3, S-NC-4, AND S-NC-8
WONG, C C , KMETY, K L Sandia Laboratories FIN A-1205 SAND-0402
84/07/31 Division of Accident Evaluation 115pp 26348 099

8408310093 Requests extension of schedule for implementation of upgraded emergency operating procedures until 850601, due to need to complete operator training on procedures, per Suppl 1 to NUREG-0737
MURPHY, W P Vermont Yankee Nuclear Power Corp FVY 84-105
84/08/22 VASSALLO, D B Operating Reactors Branch 2 2pp
26323 200 24X Fiche 50-271, 84/08/22, 8408310093

8408310121 Requests extension of time to respond to 840720 ltr re util plans for establishing emergency operations facility design consistent w/requirements of Suppl 1 to NUREG-0737 Extension requested due to judicial review of util appeal
TUCKER, H B Duke Power Co 84/08/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 26322 243 24X
Fiche 50-269, 84/08/24, 8408310121

8408310146 Forwards response to 840509 request for addl info re NUREG-0737, Item III D 1 1. "Primary Coolant Outside Containment " Info will be incorporated in Sept 1984 FSAR rev
KEMPER, J S Philadelphia Electric Co 84/08/24 SCHWENCER, A Licensing Branch 2 9pp 26322 208 24X Fiche 50-352, 84/08/24, 8408310146

8408310200 Discusses PRA of proposed mod to auxiliary feedwater sys, per NUREG-0737, Item II E 1 1 Efforts on mod stopped as result of PRA conclusion that installation of addl check valves will not significantly improve availability of sys
CASCARANO, R N Commonwealth Edison Co 9113N 84/08/23
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 26318 308 24X Fiche 50-295, 84/08/23, 8408310200

8408310225 Forwards detailed response to Question 420 01 re verification of adequate safety parameter display sys isolation from safety-related sys No Tech Spec changes needed NUREG-0737, Suppl 1 requirements met
COOK, K W Louisiana Power & Light Co W3P84-2366 84/08/27
KNIGHTON, G W Licensing Branch 3 5pp 26319 276 24X Fiche 50-382, 84/08/27, 8408310225

8408310231 Forwards revs to proposed Tech Spec changes for NUREG-0737 items re containment radiation monitors & post-accident sampling, per Generic Ltr 83-37
GRIFFIN, J M Arkansas Power & Light Co GL-83-37 84/08/22
STOLZ, J F Operating Reactors Branch 4 12pp 26320 314 24X Fiche 50-313, 84/08/22, 8408310231

8408310315 Advises that Amend 4 to radiological emergency response plan acceptable, per 10CFR50 47 & Rev 1 to NUREG-0654
SCHUSTER, M D Region 5, Office of Director 84/08/17 WITHERS, B D Portland General Electric Co 2pp 26333 298 24X Fiche 50-344, 84/08/17, 8408310315

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

8405240290 Responds to 840424 memo for FEMA review of util request for delay in scheduling next full-scale emergency preparedness exercise at site until 841130 Delay acceptable
KRIMM, R Federal Emergency Management Agency 84/05/18
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 24614 336 24X Fiche 50-003, 84/05/18, 8405240290

8407250229 IE Info Notice 84-57, "Operating Experience re Moisture Intrusion in Safety-Related Electrical Equipment at Commercial Power Plants " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/07/27 Consolidated Edison Co of New York, Inc 119pp 25865 047 24X Fiche 50-000, 84/07/27, 8407250229

8408010046 Forwards "FES Remedial Actions at Former Vitro Chemical Co Site, South Salt Lake City, Salt Lake County, UT "
MORLEY, J A Energy, Dept of 84/07/13 Affiliation Not Assigned 1p 25868 001

--8408010053 DOE/EIS-0099-F
"FES Remedial Actions at Former Vitro Chemical Co Site, South Salt Lake, Salt Lake County, UT Vol I - Text "
* Energy, Dept of 84/07/31 501pp 25868 002

--8408010063 DOE/EIS-0099-F
"FES Remedial Actions at Former Vitro Chemical Co, South Salt Lake, Salt Lake County, UT Vol II - Apps "
* Energy, Dept of 84/07/31 398pp 25869 143

8408010064 Forwards revised "UMTRA Project Environ, Health & Safety Plan, " incorporating NRC comments
MORLEY, J A Energy, Dept of 84/07/17 HIGGINBOTHAM Low-Level Waste & Uranium Recovery Projects Branch 2pp 25897 238

--8408010072 "UMTRA Project Environ, Health & Safety Plan "
* Energy, Dept of 84/06/30 2pp 25897 240

8408010333 IE Info Notice 84-59, "Deliberate Circumventing of Station Health Physics Procedures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co of New York, Inc 122pp 26068 001. 24X Fiche 50-000, 84/08/06, 8408010333

8408010337 IE Info Notice 84-60, "Failure of Air Purifying Respirator Filters to Meet Efficiency Requirement " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/06 Consolidated Edison Co, of New York, Inc 123pp 26067 158 24X Fiche 50-000, 84/08/06, 8408010337

8408060019 Responds to approval request for info collection re limiting use of highly enriched U in research reactors
MACRAE, J B Office of Management & Budget OMB 3150-0011
84/07/24 SCOTT, S Document Management Branch 2pp 25936 358

8408060059 App 7 to MOU between NRC & DOE re repository projects in site suitability & planning phase
* NRC - No Detailed Affiliation Given * Energy, Dept of 00324
84/07/27 3pp 25937 083

8408060106 Forwards draft processing site & disposal site characterization repts for Salt Lake City, UT Repts contain current data re conceptual design analysis Comments requested by 840824
MATTHEWS, M L Energy, Dept of 84/07/20 MARTIN, D Uranium Recovery Licensing Branch 1p 25952 001

--8408060111 UMTRA-DOE/AL-050102
Draft "Disposal Site Characterization Rept for U Mill Tailings Site at Salt Lake City, UT " Two oversize maps encl Aperture cards available in PDR
* Energy, Dept of 84/06/30 155pp 25952 003

--8408060122 UMTRA-DOE/AL-050102
Review draft of "Processing Site Characterization Rept for U Mill Tailings Site at Salt Lake City, UT " Six oversize maps encl Aperture cards available in PDR
* Energy, Dept of 84/06/30 236pp 25952 156

8408060114 Responds to approval request for info collection re 10CFR51, "Licensing & Regulatory Policy & Procedures for Environ Protection" & Reg Guide 4 2, "Preparation of Environ Repts for Nuclear Power Plants "
MACRAE, J B Office of Management & Budget. OMB 3150-0021
84/07/24 SCOTT, S Document Management Branch 2pp. 25936 350

8408060219 Responds to approval request for info collection re survey of users of gauges under general license
MACRAE, J B Office of Management & Budget OMB 3150-0124
84/07/24 SCOTT, S Document Management Branch 2pp 25950 251

8408070026 Forwards draft "Fifth Semiannual Staff Evaluation of Status of NPRDS " Final rept & associated Commission paper will be submitted to EDO on 840725, for forwarding to Commission
HEBDON, F J Program Technology Branch 84/07/19 ROSEN, S Institute of Nuclear Power Operations 1p 25957 076

--8407250575 Draft "Fifth Semiannual Staff Evaluation of Status of NPRDS "
* Director's Office 84/07/31 15pp 25957 077

8408070031 Responds to approval request for info collection re personnel security questionnaire
MACRAE, J B Office of Management & Budget OMB 3150-0048
84/07/24 SCOTT, S. Document Management Branch 2pp 25956 178

8408070103 Forwards request for OMB review & supporting statement re proposed revs to 10CFR50 & 10CFR73, "Insider Safeguards Rules "
NORRY, P G Office of Administration 84/07/30 MCRAE, J. B Office of Management & Budget 1p 25955 199

8408070120 IE Info Notice 84-61, "Overexposure of Diver in PWR Refueling Cavity " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/08 Consolidated Edison Co of New York, Inc 120pp 26129 118 24X Fiche 50-000, 84/08/08, 8408070120

8408070368 Advises of FEMA 840706 completion of analysis of alert notification sys Sys adequate eliminating caveat in FEMA 830516 finding FEMA rept encl Related correspondence
GODDARD, R J Hearing Branch 3 OSD 817 OLA 84/08/02
BLOCH, P B , PARIS, D H , SHON, F J Atomic Safety and Licensing Board Panel 72pp 25944 210. 24X Fiche 50-155, 84/08/02, 8408070368

8408070376 IE Info Notice 84-62, "Therapy Misadministrations to Patients Undergoing Co-60 Teletherapy Treatments " Svc list encl
ORACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/10 Consolidated Edison Co of New York, Inc. 125pp 26130 001. 24X Fiche 50-000, 84/08/10, 8408070376

8408080024 Staff requirements memo re 840731 meeting in Washington, DC on industry views on terms important to safety & safety-related
CHILK, S J Office of the Secretary of the Commission MB40731C
84/08/01 Office of the Secretary of the Commission. 1p
25981 037

8408080138 Forwards "Grand Gulf Nuclear Power Station Exercise," of offsite radiological emergency conducted on 840411 Meeting held on 840531 w/util & State of MS to discuss deficiency re coordination of issuance of public info
KRIMM, R W Federal Emergency Management Agency 84/07/30
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 3pp 25960 266 24X Fiche 50-416, 84/07/30, 8408080138

--8408080141 "Grand Gulf Nuclear Power Station Exercise," conducted on 840411
* Federal Emergency Management Agency 84/04/24 69pp
25960 269 24X Fiche 50-416, 84/07/30, 8408080138

8408080177 Forwards request for OMB review & supporting statement re revised 10CFR110, "Export & Import of Nuclear Equipment & Matls "
NORRY, P G Office of Administration 84/08/03 MACRAE, J B Office of Management & Budget 1p 25978 345

8408080297 Forwards comments on NUREG-1055 re improving quality & QA in design & const of nuclear power plants AEs & NRC should clearly define stable acceptance criteria before const started
* American Society of Mechanical Engineers 84/07/30 Docketing & Services Branch 6pp 25964 311

--8408080303 Speech entitled "Disciplined Approach for Introducing Certainty & Improving Quality in Nuclear Power Plant Const," presented at 840320 meeting of AIF & ANEC boards
STERN, T Atomic Industrial Forum 84/03/20 4pp 25964 317

8408080384 Discusses jurisdictional issue re EPA proposed environ stds for mgt & disposal of spent nuclear fuel & NRC regulation 10CFR60 Mod to 10CFR60 appropriate to incorporate EPA proposed assurance requirements
ROBERTS, T M Commissioners 84/07/19 RUCKELSHAUS, W Environmental Protection Agency 2pp 25978 085

8408090042 Forwards States of NC & SC responses to regional assistance committee findings on offsite radiological emergency response preparedness & exercise on 840215-16 State & local emergency plans adequate
KRIMM, R W Federal Emergency Management Agency 84/07/27
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 8pp 25992 324 24X Fiche 50-413, 84/07/27, 8408090042

8408090056 Clarifies addl issues raised by NRC in 840626 telcon re New York PIRG petition to suspend OLs due to emergency planning inadequacies FEMA rept & State of NY response to FEMA 840611 ltr encl
KRIMM, R W Federal Emergency Management Agency 84/07/31
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 1p 25992 335 24X Fiche 50-247, 84/07/31, 8408090056

8408090059 "Evaluation of Addl Issues Raised by NRC re New York PIRG Petition to Suspend Operation of Indian Point, Units 2 & 3 "
* Federal Emergency Management Agency 84/07/26 10pp
25992 336 24X Fiche 50-247, 84/07/31, 8408090056

--8408090061 "Addl Info Obtained From NY State on New York PIRG Petition Which SupplS FEMA Rept to NRC dtd 840608 "
* Federal Emergency Management Agency 84/07/26 8pp
25992 346 24X Fiche 50-247, 84/07/31, 8408090056

8408090216 Forwards NRC comments re DOE draft "Mission Plan for Civilian Radwaste Mgt Program " NRC objections based on regulatory info needs, establishment of performance goals & need for addl consultation w/NRC Asselstine comments encl
PALLADINO, N J Commissioners 84/07/31 RUSCHE, B C Energy, Dept of 59pp 25992 013

8408100009 IE Info Notice 84-63, "Defective RHR Replacement Piping " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/13 Consolidated Edison Co of New York, Inc 119pp 26197 218 24X Fiche 50-000, 84/08/13, 8408100009

8408100021 IE Info Notice 84-65, "Underrated Fuses Which May Adversely Affect Operation of Essential Electrical Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/16 Consolidated Edison Co of New York, Inc 118pp 26198 001 24X Fiche 50-000, 84/08/16, 8408100021

8408100038 IE Info Notice 84-64, "BWR HPCI Initiation Seal-In & Indication " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/15 Consolidated Edison Co of New York, Inc 104pp 26198 093 24X Fiche 50-000, 84/08/15, 8408100038

8408100055 IE Info Notice 84-66, "Undetected Unavailability of Turbine-Driven Auxiliary Feedwater Train " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of N York, Inc 120pp 26276 001 24X Fiche 50-000, 84/08/17, 8408100

8408100060 Determines that, based on evaluation, State of WI & local plans for radiological emergencies adequate
SPECK, S W Federal Emergency Management Agency 84/08/02
DIRCKS, W J Office of the Executive Director for Operations 1p
25989 092 24X Fiche 50-295, 84/08/02, 8408100060

8408130373 Testimony on training Contentions 39, 40, 41, 44, 98, 99 & 100 Pp 101-111 Certificate of Svc encl Related correspondence
* Federal Emergency Management Agency DSO 903 OL-3 84/08/06
14pp 26011 001 24X Fiche 50-322, 84/08/06, 8408130373

8408140208 IE Info Notice 84-67, "Recent Snubber Inservice Testing W High Failure Rates " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/08/17 Consolidated Edison Co of N York, Inc 122pp 26276 122 24X Fiche 50-000, 84/08/17, 8408140208

8408150443 Response to Suffolk County motion for directed certificati of ASLB 840710 order which denied Suffolk County request for production of documents dealt w/in ASLAB 840613 Order
ALAB-773 Certificate of Svc encl Related correspondence
GLASS, B M Federal Emergency Management Agency DSO 063 OL-3
84/08/10 Atomic Safety and Licensing Appeal Panel 14pp
26068 235 24X Fiche 50-322, 84/08/10, 8408150443

8408150535 Forwards request for OMB review & supporting statement re 10CFR50 concerning domestic licensing of production & utilization facilities
NORRY, P G Office of Administration 84/08/09 MACRAE, J B Offi of Management & Budget 1p 26080 294

8408160048 Forwards draft interagency programmatic agreement re U mil tailings disposal sites Redraft contains new provisions re problems concerning low level radwaste mgt & language which commits NRC & EPA to seek legislative relief
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director
84/07/25 CANNON, J , THOMAS, L Environmental Protection Agency
16pp 26128 146

8408160257 Forwards 840328, 0419, 0604 & 08 ltrs between EPA & NRC re EPA proposal to develop federal guidance &/or stds for decontamination & decommissioning of radioactively contaminated sites & facilities
HARMON, D F Health Effects Branch (post 840429) 84/06/29
HARWARD, D Atomic Industrial Forum 1p 26125 174

--8408160264 Requests participation in interagency working group 8406 meeting re guidance &/or stds for decontamination & decommissioning of radioactively contaminated sites & facilities Minutes of 840625 meeting encl
SJOBLOM, O L Environmental Protection Agency 84/06/08
HARMON, D F Office of Nuclear Regulatory Research, Director
15pp 26125 175

--8408160271 Expresses appreciation for opportunity to participate in 840430 meeting re decommissioning Confirms NRC view that decommissioning guidelines urgently needed WA Mills designated NRC representative to EPA interagency work group
MINOGUE, R B Office of Nuclear Regulatory Research, Director
84/06/04 CANNON, J A Environmental Protection Agency 2pp
26125 190

--8408160275 Ack receipt of 840328 ltr inviting NRC to 840430 meeting development of criteria & guidance for decontamination & decommissioning of facilities NRC engaged in establishing residual radioactive contamination limits
MINOGUE, R B Office of Nuclear Regulatory Research, Director
84/04/19 CANNON, J A Environmental Protection Agency 2pp
26125 192

--8408160280 Forwards proposed rule, changing Commission regulations i 10CFR20 to specify residual radioactive contamination limits for decommissioning, for comment
MINOGUE, R B Office of Nuclear Regulatory Research, Director
84/02/23 FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 41pp 26125 194

--8408160288 Defers concurrence on proposed EPA guidance, "Federal Radiation Guidance on Dose Limits for Persons Exposed to Transuranium Elements in General Environ " Broader need exists for uniform & consistent guidance
DIRCKS, W J Office of the Executive Director for Operations
83/09/09 ELKINS, C L Environmental Protection Agency 2pp
26125 235

8408160292 Discusses need for stds, criteria & guidelines to protect public & to direct decontamination & decommissioning programs Rulemaking investigation on problem initiated Requests 840430 meeting w/designee to discuss matters CANNON J A Environmental Protection Agency 84/03/28 DIRCKS, W J Office of the Executive Director for Operations 2pp 26125 237

8408160278 Forwards "Project Licensing Plan For UMTRAP Sites" for review & concurrence MORLEY, J H Energy Dept of 84/08/07 HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 1p 26126 043

--8408160283 "Project Licensing Plan for UMTRAP Sites * Energy, Dept of 84/07/31 37pp 26126 044

8408160289 Discusses status of Falls City, TX inactive U mill site & plan of action Since current contractor due to lose license, DOE prepared to begin remedial action BAUDLITZ, J E Energy, Dept of 84/08/06 HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 2pp 26124 348

8408200490 Forwards FEMA responses to 840629 interrogatories Certificate of Svc encl Related correspondence MOORE, J E Hearing Branch 1 DSB 174 OL 84/08/14 EDDLEMAN, W Eddleman, W 3pp 26136 321 24X Fiche 50-400, 84/08/14, 8408200490

--8408200497 Response to interrogatories propounded by intervenor W Eddleman Related correspondence HAWKINS, T I , ROCHLIS, S M Federal Emergency Management Agency OL 84/08/07 EDDLEMAN, W Eddleman, W 31pp 26136 324 24X Fiche 50-400, 84/08/14, 8408200490

8408210142 IE Info Notice 84-68, "Potential Deficiency in Improperly Rated Field Wiring to Solenoid Valves " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/21 Consolidated Edison Co of New York, Inc 115pp 26329 008 24X Fiche 50-000, 84/08/21, 8408210142

8408210341 Forwards order establishing schedule for offsite emergency planning issues W/o encl Related correspondence VOGLER, B H Hearing Branch 2 DSB 186 OL 84/08/16 PERRY, S Federal Emergency Management Agency 2pp 26179 361 24X Fiche 50-352, 84/08/16, 8408210341

8408210346 Forwards "Crystal River Nuclear Power Plant Exercise " Few specific NUREG-0654/FEMA-REP-1, Rev 1, deficiencies observed during 840425 emergency exercise State of FL & Citrus & Levy counties participated KRIMM, R W Federal Emergency Management Agency 84/08/13 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26179 136 24X Fiche 50-302, 84/08/13, 8408210346

--8408210354 "Crystal River Nuclear Power Plant Exercise, " * Federal Emergency Management Agency 84/05/11 42pp 261/9 138 24X Fiche 50-302, 84/08/13, 8408210346

8408210408 Informs that FEMA does not intend to conduct full-scale evaluation of Hope Creek 1985 exercise Since Salem Unit 1 OL issued prior to 820713, full participation in 1985 not required by NRC or FEMA rules KRIMM, R W Federal Emergency Management Agency 84/08/13 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26177 256 24X Fiche 50-000, 84/08/13, 8408210408

8408220274 Responds to 840716 ltr re NRC data on reactor scrams during 1983 that may conflict w/INPO data NRC figures viewed as entirely consistent w/INPO findings DIRCKS, W J Office of the Executive Director for Operations 84/08/15 PATE, Z T Institute of Nuclear Power Operations 2pp 26212 008

--8408220302 Forwards 1983 reactor trip statistics compiled by Operating Reactors Assessment Branch Automatic trip frequency of 4 3 trips/plant/yr consistent w/industry study EISENHUT, D G Division of Licensing 84/08/09 THOMPSON, H L Division of Human Factors Safety SPEIS, T Division of Safety Technology BERNERO, R M Division of Systems Integration (post 811005) 18pp 26212 010

--8408220310 Expresses concern re NRC statistics showing increase in scrams for 1983, whereas INPO study showed decrease Clarification requested as discrepancy may have adverse effect on INPO credibility PATE, Z T Institute of Nuclear Power Operations 84/07/16 DIRCKS, W J Office of the Executive Director for Operations 10pp 26212 028

--8408220315 INPO 84-013 "Reactor Trips in US Nuclear Power Plants " * Institute of Nuclear Power Operations 84/03/31 19pp 26212 038

8408230300 Forwards RH Kramm 840711 ltr transmitting FEMA interim finding in State of CA emergency response plan Plan adequate Areas for improvement identified, including protective action guideline doses KNIGHTON, G W Licensing Branch 3 84/08/16 SCHUYLER, J D Pacific Gas & Electric Co 3pp 26235 105 24X Fiche 50-275, 84/08/16, 8408230300

8408240354 Forwards "Nevada Nuclear Waste Storage Investigations Project, Monthly Rept, May 1984 " VIETH, D L Energy, Dept of 84/07/10 BENNETT, J W Energy, Dept of 1p 26253 205

--8408240355 "Nevada Nuclear Waste Storage Investigations Project, Monthly Rept, May 1984 " * Energy, Dept of 84/05/31 75pp 26253 207

8408270050 Discusses concerns re "Determination of Radionuclide Solubility in Groundwater for Assessment of High Level Radwaste Isolation " Marked-up draft repts encl KELMERS, A D Oak Ridge National Laboratory FIN B-0287 1409 84/08/15 BROOKS, D J Geotechnical Branch (Post 831001) 65pp 2625B 246

8408270309 Informs of FEMA approval of State of WI emergency response & local plan Adequacy of public alerting & notification sys must be verified per FEMA/NRC joint criteria in App 3 of NUREG-0654/FEMA-REP-1 PAPERIELLO, C J Region 3, Office of Director 84/08/22 REED, C Commonwealth Edison Co 2pp 26239 157 24X Fiche 50-295, 84/08/22, 8408270309

8408290197 Informs that NRC representative will not be available to attend FEMA preexercise briefing W Snell will contact FEMA after NRC 840910 entrance & attend 840913 public critique Region III representation at FY85 public critiques unlikely PAPERIELLO, C J Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/24 WEAVER, W J Federal Emergency Management Agency 1p 26291 176 24X Fiche 50-266, 84/08/24, 8408290197

--8408290206 Forwards schedule for 1984 emergency exercise NRC representation at pre & post-exercise briefings requested WEAVER, W J Federal Emergency Management Agency 84/08/16 KEPPLER, J G Region 3, Office of Director 33p 26291 177 2 Fiche 50-266, 84/08/24, 8408290197

8408290348 Responds to 840703 request for suggestions re preparation fifth Natl Energy Policy Plan Addressing of future natl electricity supply & projected mix of coal & nuclear power in supply recommended PALLADINO, N J Commissioners 84/08/15 HODEL, D P Energy, Dept of 1p 26311 267

--8408290350 Requests proposals for strategies, programs & initiatives fo consideration during preparation of fifth Natl Energy Policy Plan (NEPP) Input requested by 840901 Fourth NEPP encl HODEL, D P Energy, Dept of 84/07/03 PALLADINO, N J Commissioners 1p 26311 268

--8408290352 DOE/S-0014/L "Natl Energy Policy Plan " * Energy, Dept of 83/10/31 27pp 26311 269

8408290356 Forwards 20th joint quarterly status rept re emergency preparedness covering period through 840630 No delay in current licensing proceedings due to emergency preparedness issues BERNTHAL, F M Commissioners GIUFFRIDA, L D Federal Emerge Management Agency 84/08/09 SIMPSON, A K Senate, Environm Public Works 1p 26310 311

--8408290359 "NRC/FEMA Joint Quarterly Rept to Congress on Emergen Preparedness, Through 840630 " * NRC - No Detailed Affiliation Given * Federal Emergency Management Agency 84/06/30 46pp 26310 312

8408300208 Forwards FEMA findings on State of FL & associated local emergency plans re plant DANCE, H C Region 2, Office of Director 84/06/05 WILGUS, W B Florida Power Corp 1p 26307 044 24X Fiche 50-302, 84/06/05, 8408300208

8408300211 Approves State of FL & local plans & preparedness for alerting & protecting public in event of radiological emergency Approval conditional on verification of alert & notification per App 3 of NUREG-0654/FEMA-REP-1, Rev 1
SPECK, S W Federal Emergency Management Agency 84/02/15
DIRCKS, W J Office of the Executive Director for Operations 1p
26307 045 24X Fiche 50-302, 84/06/05, 8408300208

8408300222 Forwards request for OMB review & supporting statement re NRC Form 482, "Registration Certificate, Medical Use of Byproduct Matl Under General License "
MORRY, P G Office of Administration 84/08/21 MACRAE, J B Office of Management & Budget 1p 26331 298

8408300303 Forwards FEMA "Exercise Rept on St Lucie Nuclear Power Plant Exercise on 840306 "
DANCE, H C Region 2, Office of Director 84/08/14 WILLIAMS, J W Florida Power Corp 3pp 26306 151 24X Fiche 50-335, 84/08/14, 8408300303

8408300315 Forwards correspondence from FEMA forwarding evaluation of offsite emergency preparedness for 830517 exercise
LEWIS, R C Region 2, Office of Director 84/07/19 UTLEY, E E Carolina Power & Light Co 2pp 26313 213 24X
Fiche 50-324, 84/07/19, 8408300315

--8408300319 Forwards "Brunswick Nuclear Power Plant Exercise on 830517, " final rept
KRIMM, R W Federal Emergency Management Agency 84/06/19
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8pp 26313 215 24X
Fiche 50-324, 84/07/19, 8408300315

--8408300323 "Brunswick Nuclear Power Plant Exercise on 830517, " final rept
* Federal Emergency Management Agency 84/06/03 40pp
26313 223 24X Fiche 50-324, 84/07/19, 8408300315

8408300398 Forwards FEMA "Exercise Rept, Catawba Nuclear Station, 840215-16 "
DANCE, H C Region 2, Office of Director 84/06/25 TUCKER, H B Duke Power Co 1p 26308 264 24X Fiche 50-413, 84/06/25, 8408300398

8408300427 Forwards FEMA "Oconee Nuclear Power Plant Full-Scale Local Exercise Conducted on 830406, " final rept
DANCE, H C Region 2, Office of Director 84/07/11 TUCKER, H B Duke Power Co 1p 26315 205 24X Fiche 50-269, 84/07/11, 8408300427

PR PROPOSED RULE

8405310267 Comments on proposed rule 10CFR70 re changes to SNM matl control & accounting requirements for certain licensed facilities Requests extension of comment period by at least 3 months
MONRY, W R GA Technologies, Inc /General Atomic Co 49FR4091 84/05/25 Docketing & Services Branch 3pp 24716 358

8408020081 Comments on proposed rule 10CFR50 re limiting use of highly enriched U in domestic research & test reactors Requests 60-day extension of 840904 closing date for comments
WANG, C H Oregon State Univ , Corvallis, OR 49FR27769 84/07/26 Docketing & Servic Branch 2pp 25891 283

8408020085 Comments on proposed rule 10CFR50 re high enriched U/low enriched U Opposes rule due to lack of regard to formal comments received from listed companies Requests 60-day extension of comment period
WILSON, W E Washington State Univ , Pullman, WA 49FR27769 001 84/07/25 Docketing & Services Branch 1p 25891 288

8408020088 Comments on proposed rules 10CFR2 & 50 re elimination of review of financial qualifications of electric utils in OL reviews & hearing for nuclear power plants
RASMUSSEN, L C Kansas City Power & Light 49FR13044 039 84/07/26 Docketing & Services Branch 5pp 25891 325

8408020110 Comments on proposed rules 10CFR30, 40, 70, 71 & 73 re statement of policy concerning response to accidents involving transportation of radioactive matl Type of on-scene assistance NRC will provide, not clear
LACKER, D K Texas, State of 49FR12335 006 84/07/24 Office of the Secretary of the Commission 1p 25891 030

8408020111 Comments on proposed rules 10CFR30, 40, 70, 71 & 73 re statement of policy on NRC response to accidents occurring during transportation of radioactive matl Opposes statement
LEWIS, M I Lewis, M 49FR12335 008 84/07/30 Office of the Secretary of the Commission 2pp 25892 269

8408020120 Comments on proposed rules 10CFR30, 40, 70, 71 & 73 re statement of policy on NRC response to accidents occurring during transportation of radioactive matl Statement ensures NRC coordination w/affected state agencies, DOE & FEMA
TROSTEN, L R LeBoeuf, Lamb, Leiby & MacRae 49FR12335 007
84/07/27 CHILK, S J Docketing & Services Branch 5pp 25892 300

8408070268 Forwards chart reflecting NRR input to public comments received in response to 49FR16900, "Rev of Backfitting Process for Power Reactors "
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/07/27 STELLO, V Regional Operations & Generic Requirements 15pp 25957 019

--8406200226 Requests consideration & repts re changes designed to backfit procedures by 840706 SJ Chilks 840208 memo, public comments received in response to 49FR16900 & list of public comments encl
STELLO, V Regional Operations & Generic Requirements 84/06/13
DENTON, H R Office of Nuclear Reactor Regulation, Director
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 25956 268

--8404250191 Advises of Commission approval of NRC plan for mgt of plant-specific backfitting of operating power reactors (SECY-83-321)
CHILK, S J Office of the Secretary of the Commission 84/02/08
DIRCKS, W J Office of the Executive Director for Operations
MESSENGER, G Office of Investigation 1p 25956 269

--8406280010 Forwards addl public comments on proposed rule 10CFR50 re consideration of revs to backfit procedures & revised list of comments
STELLO, V Regional Operations & Generic Requirements 84/06/20
DENTON, H R Office of Nuclear Reactor Regulation, Director
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 25956 354

8408070286 Forwards UCS comments on proposed rules 10CFR2 & 50 re regulatory reform proposal concerning rules of practice, licensing of production & utilization facilities NRC should sponsor round of depositions of all witnesses for hearings
JORDAN, W S Harmon & Weiss 49FR14698 031 84/07/30 CHILK, S Office of the Secretary of the Commission 26pp 25948 192

8408070344 Comments on proposed rule 10CFR50 re environ qualification Requests UCS comments be given full consideration due to deadline discrepancy
CURRAN, D , JORDAN, W S Harmon & Weiss 49FR8445 84/07/31
PALLADINO, N J , ASSELSTINE, J K , BERNTHAL, F M Commissioners 4pp 25944 130

8408070345 Comments on proposed rule 10CFR50 re limiting use of highly enriched U in domestic research & test reactors Opposes rule due to cost to taxpayers & lack of commitment for funding proposed fuel changes
WILBUR, L C Worcester Polytechnic Institute, Worcester, MA
49FR27769 003 84/07/31 Office of the Secretary of the Commission 2pp 25945 192

8408070346 Comments on proposed rule 10CFR50 re limiting use of highly enriched U in domestic research & test reactors Requests 30-day extension of comment period to allow discussion at training research & test reactor meeting
RICHARDS, W J American Nuclear Society 49FR27769 84/07/27
Docketing & Services Branch 1p 25945 194

8408070349 Comments on proposed rule 10CFR50 re use of low enriched U in research reactors Use of highly enriched U unnecessary & dangerous Switching to low enriched U will reduce danger
LEWIS, M I Lewis, M 49FR27769 002 84/07/29 Docketing & Services Branch 1p 25945 199

8408070383 Advises that comment period extended to 840813 for proposed rule 10CFR50 re environ qualification of electrical equipment FR notice encl
CHILK, S J Office of the Secretary of the Commission 84/08/02
BELL, N Nuclear Information & Resource Service RUNKLE, J Conservation Council of North Carolina O'NEIL, J O'Neill, J 3pp 25947 068

--8408070398 Proposed rule 10CFR50, "Environ Qualification of Electrical Equipment, Removal of 820630 Deadline " Rule extends comment period to 840813
CHILK, S J Office of the Secretary of the Commission 84/08/02
3pp 25947 071

8408070407 Comments on proposed rules 10CFR30,40 70 '1 * 73 re NRC general statement of policy on response to accidents occurring during transportation of radioactive matl Supports rules
ZIMMERMAN S R Carolina Power ? Light Co 49FR12335 009 84/07/27
CHILK,S J Docketing ? Services Branch 1p 25942 173

8408070413 Comments on proposed rule 10CFR9 re production or disclosure in response to subpoenas or demands of court or other authorities Rule would prohibit NRC employees or former employees from producing info in files to General Counsel
HANAUER S H Interstate Amiesite Corp 49FR28073 001 84/07/30
Office of the Secretary of the Commission 2pp 25942 150

8408080333 Comments on proposed rule 10CFR60 re disposal of high level radwaste in geologic repositories Disagrees w/NRC re contents of site characterization plan MN Humphrey 840525 comments encl
KALITOWSKI T Minnesota, State of 49FR5934 015 84/08/01
BROWNING,R Division of Waste Management 6pp 25964 091

--8408080334 Comments on suggestions for procedural changes in nuclear power plant licensing process Supports creation of ASLB screening boards
HUMPHREY,H H , OLSON,J F , SENECHAL,M E Minnesota, State of 49FR11698 84/05/25 Office of the Secretary of the Commission 8pp 25964 097

8408080335 Comments on proposed rule 10CFR50 re limiting use of highly enriched U in domestic research ? test reactors Rule should be redrafted after input from all affected parties obtained
SPINRAD,B I Iowa Wesleyan College, Mt Pleasant, IA 49FR27769 004 84/07/31 Docketing & Services Branch 9pp 25964 082

8408080340 Comments on proposed rule 10CFR73 re mod of protection requirements for spent fuel shipments Concurs w/conclusion that relaxation of rigorous safeguards on shipments warranted
LEONARD,J D Long Island Lighting Co 49FR23867 004 84/08/01
CHILK,S J Office of the Secretary of the Commission 10pp 25963 301

8408090332 Requests comment period be extended until 841104 for proposed rule 10CFR50 re limiting use of highly enriched U in domestic research & test reactors
DIMEGLIO,A F Rhode Island, State of 49FR27769 005 84/08/06
Office of the Secretary of the Commission 2pp 25971 041

8408130346 Comments on proposed rule 10CFR50 re conversion of research reactors from highly enriched U fuel to low enriched U fuel Supports rule Conversion should be implemented as soon as possible
RUBIN,J Venice Alliance for Survival 49FR27769 006 84/08/06
Docketing & Services Branch 1p 26010 317

8408130398 Package of two comments opposing proposed rule 10CFR9 re production or disclosure in response to subpoenaes or demands of courts or other authorities
CONNER,T B Conner ? Wetterhahn * LeBoeuf, Lamb, Leiby & MacRae 49FR28073 84/08/09 CHILK,S J Office of the Secretary of the Commission 7pp 26011 120

8408130402 Comments on proposed rule 10CFR9 re production or disclosure in response to subpoenas or demands of courts or other authorities Supports proposed rule,w/exception of minor change to delete "or former employee" in Section 9 201
BENNETT,J P Baltimore Gas & Electric Co 49FR28073 002 84/08/07
Docketing & Services Branch 1p 26010 188

8408140377 Comments on proposed rule 10CFR50 re conversion of research reactors from highly enriched U fuel to low enriched U fuel Supports rule & requests implementation as soon as possible
COHEN,D A Cohen, D A MD 49FR27769 007 84/08/05 Office of the Secretary of the Commission 1p 26041 164

8408140419 Submits second comment on proposed rule 10CFR50, "Environ Qualification of Electric Equipment Removal of 820630 Deadline " Comment based exclusively on info re Pilgrim-1 Deadline should not be removed
DOHERTY,J F Doherty, J F 49FR8445 022 84/08/10 Office of the Secretary of the Commission 15pp 26050 334

8408140420 Comments on proposed rules 10CFR2 & 50 re elimination of review of financial qualifications of electric utils in operating reviews & hearings for power plants Analysis of financial qualifications & operational safety encl
SILBERG,J E Shaw, Pittman, Potts & Trowbridge 49FR13044 040 84/08/10 Docketing & Services Branch 1p 26051 001

--8408140422 "Statistical Analysis of Financial Qualifications & Operational Safety for Electric Utils Operating Nuclear Power Reactors "
* CYGNA Energy Services 84/08/09 79pp 26051 002

8408160382 Comments on proposed rules 10CFR2 & 50 re elimination of review of financial qualifications Opposes rule
O'NEILL J Affiliation Not Assigned 49FR13044 041 84/08/13
Docketing ? Services Branch 1p 26092 172

8408210314 Comments on proposed rule 10CFR73 re mod of protection requirements for spent fuel Supports any rule which would reduce transport & manpower costs,but unclear that proposed rule will accomplish that goal
MANGUSI,J Transnuclear, Inc 49FR23867 004 84/08/13
Docketing & Services Branch 2pp 26179 125

8408210349 Comments on proposed rule 10CFR50 re sufficiency of justification for continued operation for Wisconsin Electric Power Co,Point Beach Nuclear Plant I & II Streamlining NRC licensing & regulatory roles inadequate in solving problems
PROUDMAN,S Wisconsin's Environmental Decade 49FR8445 023
84/08/10 Docketing & Services Branch 12pp 26179 183

8408210359 Comments on proposed rule 10CFR50 re limiting use of highly enriched U in domestic research ? test reactors Urges NRC reconsideration due to absence of any indication of realistic threat of diversion
WEGST,W F California, Univ of, Los Angeles, CA 49FR27769 008
84/08/09 Docketing & Services Branch 2pp 26180 243

8408210432 Comments on proposed rules 10CFR2 & 50 re elimination of review of financial qualifications Discusses several instances of safety improvements not made because cost judged to be excessive
O'NEILL,J O'Neill, J 49FR13044 042 84/08/12 NRC - No Detailed Affiliation Given 1p 26181 297

8408220322 Comments on proposed rule 10CFR50 re use of highly enriched U in domestic research & test reactors Requests 60-day extension on comment period,to conduct careful analysis
COLLINS,P F NMC, Inc 49FR27769 84/08/15 Docketing & Services Branch 1p 26194 054

8408220337 Comments on proposed rule 10CFR50 re limiting use of highly enriched U in domestic research & test reactors Recommends rule state exemptions from conversion to low enriched U may not be reason or excuse to add addl security requirements
BRUGGER,R M Los Alamos Scientific Laboratory 49FR27769 009
84/08/07 Office of the Secretary of the Commission 3pp 26194 064

8408220343 Package of two comments on proposed rule 10CFR50 re conversion of nuclear research reactors from highly enriched U to low enriched U Supports rule
MAHAFFEY,M Detroit, MI CAMPBELL,B End Nuclear Dumping in the Pacific 49FR27769 84/08/20 Docketing & Services Branch 2pp 26189 347

8408220348 Comments on proposed rule 10CFR50 re limiting use of U enriched to greater than 20% U-235 in domestic nonpower reactors Rule discourages all new nonpower reactor development in US
NELSON,G W Affiliation Not Assigned 49FR27769 011 84/08/08
Docketing & Services Branch 2pp 26189 349

8408220350 Comments on proposed rule 10CFR50 re conversion of research reactors from high enriched U to low enriched U fuel Supports rule
CUSHNIR,M CEIP Fund, Inc 49FR27769 010 84/08/14 Docketing & Services Branch 1p 26189 317

8408230387 Comments on proposed rule 10CFR73 re vital islands policy NRC should stop wasting taxpayer & ratepayer dollars for politically motivated projects & concentrate on streamlining regulations
CAPANO-DOLAN,L Affiliation Not Assigned 49FR30735 001 84/08/17
Office of the Secretary of the Commission 2pp 26205 310

8408270319 Comments on proposed rule 10CFR50 re rev of backfitting process for power reactors Supports rule Statutory basis would add dimension of policy stability & predictability to NRC administrative proposals
GRIFFITH,J D Energy, Dept of 49FR16900 023 84/06/07
CHILK,S J Office of the Secretary of the Commission 4pp 26242 307

8408270328 Comments on proposed rule 10CFR50 re highly enriched U conversion rule Supports conversion Conversion should be taken before fuel stolen & used to build atomic weapon
DEGOLT,R Affiliation Not Assigned 49FR27769 014 84/08/23
Docketing & Services Branch 1p 26239 227

8408270350 Comments on proposed rules 10CFR2 & 50 re Natl Association of Util Regulators financial qualifications study Proposed rule raises genuine problems & should be weighed carefully & deliberately
SCOTT,N Coalition for Responsible Energy Education 49FR13044 043
84/08/10 Docketing & Services Branch 12pp 26245 008

8408280093 Package of two comments supporting proposed rule 10CFR50 re high enriched U conversion
BLUMENTHAL,A Affiliation Not Assigned MISCHEL,A National Lawyers Guild, Los Angeles Chapter 49FR27769 84/08/24
Docketing & Services Branch 2pp 26261 126

8408290290 Decision in matter of rulemaking on storage & disposal of nuclear waste (waste confidence rulemaking) Served on 840827
CHILK,S J Office of the Secretary of the Commission DSB 376
44FR61372 84/08/22 160pp 26291 001

--8408290297 "Requirements for Licensee Actions re Disposition of Spent Fuel Upon Expiration of Reactor OLs," 10CFR50 & 51 final rule Discussion of environ impact of spent fuel storage not required
CHILK,S J Office of the Secretary of the Commission 44FR61372
84/08/22 37pp 26291 124

8408310139 Comments on proposed rule 10CFR73 re mod of protection requirements for spent fuel shipments Recommends that in absence of research on shipment,no easing of requirement should be contemplated
KUCERA,R Missouri, State of 49FR23867 005 84/08/22
Docketing & Services Branch 1p 26322 262

8408310141 Forwards comments on proposed rule 10CFR50 re limited use of highly enriched U in domestic research & test reactors
WEGST,W F California, Univ of, Los Angeles, CA 49FR27769 008
84/08/21 PALLADINO,N J Commissioners 1p 26322 266

8408310154 Package of three comments supporting proposed rule 10CFR50 re conversion of domestic research reactors from highly enriched to low enriched U fuels
BOURASSA,L California, Univ of, San Francisco, CA RICE,R A California, Univ of, Berkeley, CA RUZ,R R California, Univ of, Riverside, CA 49FR27769 84/08/27 Docketing & Services Branch
3pp 26322 217

8408310212 Comments on proposed rule 10CFR50 re conversion of domestic research reactors from highly enriched to low enriched U fuels Supports rule Testimony presented to ACRS on 840612 encl
HAFEMEISTER,D Affiliation Not Assigned 49FR27769 020 84/08/16
Office of the Secretary of the Commission 1p 26318 109

--8408310215 Testimony of DW Hafemeister re need to convert domestic research reactors from highly enriched to low enriched U fuels
* ACRS - Advisory Committee on Reactor Safeguards HAFEMEISTER,D
Affiliation Not Assigned 84/06/12 6pp 26318 110

8408310219 Comments on proposed rule 10CFR50 re conversion of research reactors using highly enriched U to non-weapons-grade fuels Supports rule Testimony presented to ACRS on 840127 encl
TAYLOR,T B Affiliation Not Assigned 49FR27769 018 84/08/24
Docketing & Services Branch 1p 26318 158

--8408310221 Testimony of TB Taylor re need to convert domestic research reactors from highly enriched to low enriched U fuels
TAYLOR,T B Affiliation Not Assigned 84/01/27 11pp
26318 139

PRM PETITION FOR RULEMAKING

8408070312 Advises that on 840621,NRC approved petition for rulemaking PRM-50-33 governing emergency exercise frequency Expresses appreciation for participation & assistance provided during rulemaking
CHILK,S J Office of the Secretary of the Commission 47FR29252
84/07/31 OTT,C A National Emergency Management Association 1p
25947 362

8408070319 Advises that on 840621,NRC approved petition for rulemaking PRM-50-34 governing emergency exercise frequency Expresses appreciation for participation & assistance provided during rulemaking
CHILK,S J Office of the Secretary of the Commission 47FR50918
84/07/31 MILLER,R South Carolina, State of 1p 25944 160

8408070451 Petition for rulemaking PRM-7-2 requesting NRC institute rulemaking to amend 10CFR7 9 to establish formal procedure for petitioning Commission to reconsider decisions
NAUTZ,J L Nantz, J L 84/07/25 Office of the Secretary of the Commission 8pp 25942 251

8408070153 Forwards petition for rulemaking PRM-20-15 re disposal of radwaste oil from nuclear power plants below regulatory concern
BAUSER,M A Neuman & Holtzinger 84/07/31 Docketing & Services Branch 2pp 25940 097

--8408070457 Petition for rulemaking PRM-20-15 re disposal of low level radwaste oil from nuclear power plants requesting radionuclide concentrations in waste oil be disposed of w/o regard to radioactive matl content
* Edison Electric Institute * Utility Nuclear Waste Management Group 84/07/31 Commissioners 20pp 25940 099

--8408070462 "Development of Recommended Regulatory Cutoff Levels for Low Level Radioactively Contaminated Oils From Nuclear Power Plants"
BLAND,J S , LIEBERMAN,J A , MORTON,H W OTHA Inc 83/10/31
63pp 25940 119

8408130555 Forwards comments re staff review & proposed resolution of Nuclear Util Backfitting * Reform Group petition for rulemaking PRM 50-36
DENTON,H R Office of Nuclear Reactor Regulation, Director
84/08/03 NORRY,P G Office of Administration 7pp 26059 231

--8408130560 Forwards Nuclear Util Backfitting & Reform Group petition for rulemaking PRM 50-36, summaries of staff comments, status of rulemakings & proposed resolutions
NORRY,P G Office of Administration GL-83-43 84/06/26
HELTEMES,C J Director's Office DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 26059 238

PROJ PROJECTS - PREDOCKET LICENSING

8408070036 Summary of 840718-19 meetings w/LLL,Swanson,Chem-Nuclear, Fracture Control,TVA,VEPCO,Gesellschaft Nuclear Svc & BNWL in Livermore,CA re rev to CASTOR Ic dry spent fuel storage cask ISFSI topical rept
ROBERTS,J P Advanced Fuel & Spent Fuel Licensing Branch 84/07/30
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 4pp
25955 352

8408090562 Forwards Rev 1 to "QA Handbook for Dry Spent Fuel Storage Cask," per 831221 request re 830929 submittal of Rev 2 to "Topical SAR for Castor IC Cask ISFSI (Dry Storage) "
BAATZ,H , RITTSCHER,D Gesellschaft fuer Nuklear Service, mbH
23891 84/07/23 ROUSE,L C Advanced Fuel & Spent Fuel Licensing
Branch 1p 25983 054

--8408090564 Rev 1 to "QA Handbook for Dry Spent Fuel Storage Cask "
BITTNER,R Gesellschaft fuer Nuklear Service, mbH 23891
84/06/22 52pp 25983 055

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

8408020230 Corrected Rev 1 to Final Deficiency Rept DER 83-56 re discrepancies w/MSIV mfg by Anchor-Darling Initially reported on 830808 Vendor Instruction Manual E9023-9 revised Also reported per Part 21
VAN BRUNT,E E Arizona Public Service Co DER 83-56 84/07/13
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 7pp 25898 046 24X Fiche 50-528,84/07/13,8408020232

8408070233 Potential Part 21 rept re defective threaded rod matl supplied by Texas Bolt Co on 840618 Rods returned to vendor for replacement Nonconformance Repts 84-187 & 84-205 encl
LEE,O R Public Service Co of Colorado P-84244 84/07/30
Director's Office, Office of Inspection and Enforcement 19pp
25948 304 24X Fiche 50-267,81/07/30,8408070233

8408090012 Final Deficiency Rept DER 84-08 re failure of ITT/Barton Model 763 transmitters to meet specs PPS setpoints revised on existing transmitters & Barton working on physical mod to meet specs Also reportable under Part 21
VAN BRUNT,E E Arizona Public Service Co DER 84-08 84/07/24
BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 4pp 25995 011 24X Fiche 50-528,84/07/24,8408090012

8408090055 Interim deficiency rept, Item 131 re weldolets lacking complete chemical analysis documentation Initially reported on 840627 Corrective action to be determined upon completion of investigation Reported under Part 21 by Guyon Alloys
JENS, N H Detroit Edison Co 131 84/07/24 KEPPLER, J G Region 3, Office of Director 2pp 25992 333 24X Fiche 50-341, 84/07/24, 8408090055

8408090066 Deficiency & Part 21 repts, Item 179 re Westinghouse not considering interaction scenario when postulating in-core flux mapping sys Initially reported on 840622 Reportability to be determined by 840930
PARSONS, R M Carolina Power & Light Co NRC-241 84/07/19
O'REILLY J P Region 2, Office of Director 1p 25992 146 24X
Fiche 50-400, 84/07/19, 8408090066

8408090114 Part 21 rept re twisted shielded pair cable in Nutherm Intl, Inc Analog Trip Cabinets C2228A1, C2228A2, C2229B1 & C2229B2 Initially reported on 840713 Caused by poor workmanship Cables exhibiting defects replaced
HARRINGTON, W D Boston Edison Co BECO 84-105 84/07/13
MURLEY, T E Region 1, Office of Director 3pp 25992 242 24X
Fiche 50-293, 84/07/13, 8408090114

8408090131 Interim deficiency & Part 21 repts, Item 178 re stainless steel sockolettes & weldolettes supplied by Guyon Alloys, Inc not in accordance w/NCA 3800 Initially reported on 840619 Next rept by 840915
PARSONS, R M Carolina Power & Light Co NRC-239 84/07/16
O'REILLY, J P Region 2, Office of Director 4pp 25994 320 24X
Fiche 50-400, 84/07/16, 8408090131

8408090148 Final Deficiency Rept (RDC 92(84)) re potential problem w/standby diesel generator loose flexible coupling drive hubs supplied by TDI Initially reported on 840120
Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co (RDC 92(84))
84/07/27 KEPPLER, J G Region 3, Office of Director 2pp
25993 176 24X Fiche 50-440, 84/07/27, 8408090148

8408090279 Fourth interim deficiency rept re makeup HPI pump vibration Initially reported on 830622 Cause not stated Pumps balanced & vibration level measured Next rept expected by 841119 Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 84/07/20 O'REILLY, J P
Region 2, Office of Director 2pp 25994 161 24X
Fiche 50 438, 84/07/20, 8408090279

8408100085 Interim deficiency rept re cracked bosses on Colt Industries diesel generator lube oil pump discharge nozzles Initially reported on 840425 Design for tapered thread adapter changed Next rept expected by 840807 Reportable per Part 21
MARTIN, T J Public Service Electric & Gas Co of New Jersey
84/07/18 MURLEY, T E Region 1, Office of Director 2pp
25990 198 24X Fiche 50-354, 84/07/18, 8408100085

8408100118 Final deficiency rept re excessive wear on Pacific Air Products linear converters Initially reported on 840213 Design of converters satisfactory for dampers Also reportable per Part 21 Not reportable per 10CFR50 55(e)
MANGAN, C V Niagara Mohawk Power Corp NMP2L 0115 84/07/30
STAROSTECKI, R Division of Project & Resident Programs 2pp
25988 253 24X Fiche 50-410, 84/07/30, 8408100118

8408130157 Updated Part 21 rept re calculational errors in original design Initially reported on 840705 More detailed & less conservative analysis being performed to verify compliance w/specified allowables Next rept expected by 840901
GODFREY, D A W J Woolley Co 84/08/01 KEPPLER, J G Region 3, Office of Director 1p 26010 026

8408130238 Part 21 Rept 21-84-10 re potential functional problem w/transmitter amplifier board supplied by Rosemount, Inc as spare part or part within complete Model 1153, Series B transmitter Rosemount 840718 ltr informing of defect encl
HALL, D P Illinois Power Co U-10184 84/07/30 KEPPLER, J G
Region 3, Office of Director 5pp 26008 198 24X
Fiche 50-461, 84/07/30, 8408130238

8408140461 Ack receipt of Part 21 rept re potentially defective personnel neutron dosimeters Requests resolution of problem, plans to disseminate info to potentially affected customers & steps planned or taken to prevent recurrence
BAER, R L Engineering & Generic Communications Branch 84/08/03
TODD, W E Siemens Gammasonics, Inc 3pp 26061 286 24X
Fiche 50-027, 84/08/03, 8408140461

8408160061 Final Deficiency Rept PRD-84/10 re possible swelling of GH Bettis valve actuator ethylene propylene rubber elastomer seals in contact w/hydrocarbon lubricant Initially reported on 840730 Reportable under Part 21 for Unit 1
RICHARD, J B Mississippi Power & Light Co PRD-84/10 84/08/03
O'REILLY, J P Region 2, Office of Director 5pp 26108 219 24X
Fiche 50-416, 84/08/03, 8408160061

8408160066 Final deficiency rept re loose drive hubs on overspeed governor drive shaft on TDI diesel engines Initially reported on 840203 Hubs acceptable Also reportable under Part 21
MILLS, L M Tennessee Valley Authority 84/08/03 O'REILLY, J P
Region 2 Office of Director 2pp 26108 224 24X
Fiche 50-438, 84/08/03, 8408160066

8408160421 Final Deficiency Rept PRD-81/17 re flow rate in standby svc water sys loops A & B & loss of standby svc water basin transfer capability Initially reported on 810303 Also reportable per Part 21
RICHARD, J B Mississippi Power & Light Co AECM-84/0341 84/07/31
O'REILLY, J P Region 2, Office of Director 5pp 26106 076 24X
Fiche 50-416, 84/07/31, 8408160421

8408160438 Interim deficiency rept, Item 175 re exceeding max bolt hardness values Initially reported on 840517 Corrective action & submission of final rept will be accomplished by 840926 Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co NRC-243 84/07/24
O'REILLY, J P Region 2, Office of Director 4pp 26106 343 24X
Fiche 50-400, 84/07/24, 8408160438

8408160443 Interim deficiency rept, Item 168 re 6 9-kV switchgear circuit breakers Initially reported on 840420 Corrective action & submission of final report will be accomplished by 841001 Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co NRC-246 84/07/30
O'REILLY, J P Region 2, Office of Director 5pp 26107 268 24X
Fiche 50-400, 84/07/30, 8408160443

8408160480 Final Deficiency Rept DER 84-16 re ESF actuation sys relay cabinet baseplates Initially reported on 840321 Cabinet backs will be reinforced w/3/8-inch thick vertical stiffener plate Also reportable under Part 21
VAN BRUNT, E E Arizona Public Service Co ANPP-30105-TDB/
84/08/02 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 26107 292 24X Fiche 50-528, 84/08/02, 8408160480

8408170384 Final Deficiency Rept DER 84-22 re control element assembly shroud support contaminated w/oil Initially reported on 840420 Shroud cleaned & inspected & drip pan installed to contain possible leakage Also reported per Part 21
VAN BRUNT, E E Arizona Public Service Co DER 84-22 84/08/01
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 26129 079 24X Fiche 50-528, 84/08/01, 8408170384

8408200307 Suppl 7 to Part 21 rept re possible thermostatic valve malfunction fail safe to full cooling position Lower overrun assemblies in Robertshaw valves installed on diesel generator sets replaced w/cotter pins to lock nut to stem
MORIARTY, J M Colt Industries, Inc 84/08/08 KEPPLER, J G Region 3, Office of Director 1p 26133 017 24X Fiche 50-352, 84/08/08, 8408200307

8408200332 Part 21 rept re tension wires on Titus Grille, Model 272, not remaining in place when deflection blades closed Affected job sites identified in encl Products being tested to provide acceptable fix For retention
SCHNEIDER, S L Phillips Industries, Inc 84/08/07 Director's Office, Office of Inspection and Enforcement 3pp 26133 315 24X
Fiche 50-000, 84/08/07, 8408200332

8408200333 Part 21 rept re tension wires used for adjustment of blades on Grille Model 272 not remaining in place when blades closed Review & testing conducted to identify number of grilles & rework methods to be utilized
SCHNEIDER, S L Phillips Industries, Inc 84/08/07 STRAIT, R
Arizona Public Service Co 1p 26132 360 24X
Fiche 50-528, 84/08/07, 8408200333

8408200338 Part 21 rept re tension wires used for adjustment of blades on Grille Model 272 not remaining in place when blades closed Review & testing conducted to identify total number of grilles & rework methods
SCHNEIDER, S L Phillips Industries, Inc 84/08/07 USINGER, R
Zack Co 1p 26132 356 24X Fiche 50-461, 84/08/07, 8408200338

8408210298 Part 21 rept re separation of rod eye connected to piston rod from threaded portion of piston rod at approx 750,000 lb stress load Caused by insufficient matl thickness to withstand faulted load Matl certification encl
MILLS, C R Chicago Fluid Power Co 84/08/16 Director's Office, Office of Inspection and Enforcement 4pp 26180 349 24X
Fiche 50-282, 84/08/16, 8408210298

NONDOCKETED ITEMS

8408220143 Interim Deficiency Rept DLR 84-44 re fatigue failures of Gaulin charging pumps Initially reported on 840706 Bechtel investigating Final rept to be completed by 840927 Reported under Part 21 by Northeast Utils
VAN BRUNT E E Arizona Public Service Co ANPP-30128-TDS/ 84/08/06 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 3pp 26188 065 24X Fiche 50-528,84/08/06, 8408220143

8408220317 Part 21 rept re failure of ITE 27N undervoltage relay to drop out on listed undervoltage conditions Problem due to excessive feedback around operational amplifier U2 Clamping diode must be added Affected units listed
DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) PT21 84-170-000 84/03/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26191 357 24X Fiche 50-000,84/03/13,8408220317

8408240313 Part 21 rept re fitting leaks at incore probe seal tables at PWRs,per IE Info Notice 84-55 Subj fittings not used as instructed
WILSON,B Crauford Fitting Co IEIN-84-55 84/08/13 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 26235 313 24X Fiche 50-327,84/08/13,8408240313

8408240332 Submits annotated requests for followup on potentially generic problem in encl Part 21 rept from Basler Electric re SCRs on nuclear exciters mounted w/too much pressure
NORELIUS,C E Division of Project & Resident Programs 84/04/25 JORDAN,E L Director's Office, Office of Inspection and Enforcement 1p 26225 303 24X Fiche 50-000,84/04/25,8408240332

8408240348 Part 21 rept re presence of Loctite-242 in CRD hydraulic control unit scram pilot solenoid valve plunger Initially reported on 840413 New thread locking devices investigated
SHERWOOD,G G General Electric Co MFN# 041 84/04/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 26222 256 24X Fiche 50-000,84/04/13,8408240348

8408280127 Part 21 rept re defects in 18-inch SA-333 RHR pipe Samples of defective pipe matl being shipped to Technintat Corp,per request Defects located in one length of SA-333 Grade 6 pipe
CROSBY,G E Northern States Power Co SPLM-754 84/08/22 COLLINS,J NRC - No Detailed Affiliation Given 1p 26275 144 24X Fiche 50-263,84/08/22,8408280127

8408300521 Final rept,Significant Const Deficiency 115 re unacceptably high fluoride levels in Micro-Lok insulation supplied by Johns-Manville Condition not reportable under 10CFR50 55(e) Apparently reported under Part 21 by Johns-Manville
GERRETS,T F Louisiana Power & Light Co 115 84/08/20 COLLINS,J T Region 4, Office of Director 3pp 26313 359 24X Fiche 50-382,84/08/20,8408300521

8408310110 Significant Deficiency Rept 148 re design calculations made by WJ Woolley Co for doors specified to meet tornado-generated missile criteria Door reanalysis underway Previously reported under Part 21 by WJ Woolley Co
KEMPER,J S Philadelphia Electric Co (SDR #148) 84/08/23 MURLEY,T E Region 1, Office of Director 1p 26322 239 24X Fiche 50-352,84/08/23,8408310110

8408310160 Part 21 rept re ground fault failures of actuation solenoids for Crosby safety relief valves PRC 84-24 Problem still considered germane condition Memo of 840808 telcon updating 840615 interim rept encl
DIAMBALVO,E W General Electric Co MFN# 125-84 84/08/21 ROSSI,C E Director's Office, Office of Inspection and Enforcement 4pp 26322 220 24X Fiche 50-373,84/08/21,8408310160

8408310186 Part 21 rept re torus-to-reactor bldg vacuum breakers Memo of 840820 telcon reporting equipment quality & separation of controls to butterfly valves encl GE lacks technical info to adequately evaluate condition
VILLA,R General Electric Co MFN# 117-84 84/08/21 ROSSI,C E Director's Office, Office of Inspection and Enforcement 3pp 26318 327 24X Fiche 50-000,84/08/21,8408310186

QA999 QUALITY ASSURANCE INSPECTIONS

8405300191 Ack receipt of 840503 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900833/84-01 Corrective actions will be reviewed during future insp
POTAPOVS,U Region 4, Office of Director 84/05/22 MEISSNER,F N Electro Switch Corp 1p 24699 257

8408010364 Forwards QA Program Insp Rept 99900823/83-01 on 830613-17 & notices of violation & nonconformance
POTAPOVS,U Vendor Program Branch 83/11/18 THOMAS,A Diversified Threaded Products Co 3pp 25866 292

--8408010368 Notice of violation from insp on 830613-17
* Vendor Program Branch 83/11/18 1p 25866 295

--8408010369 Notice of nonconformance from insp on 830613-17 Safeguards info deleted (ref 10CFR2 790)
* Vendor Program Branch 83/11/18 4pp 25866 296

--8408010372 QA Program Insp Rept 99900823/83-01 on 830613-17 Noncompliance noted posted Part 21 guidance outdated (821230) & procedures to evaluate deviations did not exist Safeguards info deleted (ref 10CFR2 790)
CONWAY,J T BARNES,I Vendor Program Branch 83/08/20 5pp 25866 300

8408030021 Forwards Updating Status Memo 20 for Nuclear QA Program Manual ETR 1001,summarizing changes made
TENZER,B E Ebasco Services, Inc (subs of Enserch Corp) 84/07/24 POTAPOVS,U Vendor Program Branch 4pp 25907 088

8408030037 Responds to NRC 840613 ltr re nonconformance noted in QA Program Insp Rept 99900831/84-01 Corrective actions random review of patrol insps to be conducted,patrol insp items listed & parts assembled at work station inspected
CHRISTOPHER,T Westinghouse Electric Corp 84/07/09 POTAPOVS,U Vendor Program Branch 5pp 25907 063

8408030041 Responds to NRC 840618 ltr re nonconformance noted in QA program insp rept Corrective actions annual review & rev of Natl Technical Sys QC manual will be completed by 840801
HARTMAN,W C National Technical Systems 84/07/17 POTAPOVS,U Vendor Program Branch 3pp 25907 031

8408030089 Responds to violation & nonconformance noted in QA program insp on 840417-19 Corrective actions drawing forms revised to conform to practice of one signoff on rev block & testers instructed on proper operation of ITE 27 relays
DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/07/16 POTAPOVS,U Vendor Program Branch 2pp 25910 074

8408030115 Responds to 840529 ltr re problems identified at Bahnson Co Winston-Salem facility No HVAC equipment received from subj facility Bahnson Co solicited to assess or to take any needed actions to improve QA program
CLEMENTS,B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) TXX-4238 84/07/23 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 2pp 25916 104 24X Fiche 50-445,84/07/23,8408030115

8408030137 Responds to NRC 840618 ltr re nonconformances noted in QA Program Insp Rept 99900500/84-01 Corrective actions new Procedure TS-2 9 issued to consolidate & enhance requirements for tracking,closing & mgt actions
REINSCH,H O Bechtel Corp 84/07/10 POTAPOVS,U Vendor Program Branch 2pp 25916 141

8408030136 Responds to 840627 ltr re 840604 response to nonconformances noted in QA Program Insp Rept 99900809/04 01 on 840206-10 Nonconformances do not indicate failure of program to comply w/Reg Guide 1 144 & ANSI N45 2 12-1977
KELLY,R B Stone & Webster Engineering Corp 84/07/20 POTAPOVS,U Vendor Program Branch 4pp 25916 137

8408030143 Responds to NRC 840628 ltr re nonconformance noted in QA Program Insp Rept 99900507/84-02 Corrective actions Mechanical Std MAS-27 revised on 840625 to specifically address use & documentation re engineering judgment
TAYLOR,N S Sargent & Lundy, Inc 00?7 00 84/07/27 POTAPOVS,U Vendor Program Branch 8pp 25915 307

8408030165 Responds to NRC notice of nonconformance noted in QA program insp at Bland Operation on 840507 10 Corrective actions QAP 2 3 revised to indicate 2-wk training session by QA supervisor & experienced QC personnel
DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/07/16 POTAPOVS,U Vendor Program Branch 4pp 25915 345

8408030175 Responds to NRC 840530 ltr re deviations noted in QA Program Insp Rept 99900804/83-01 Corrective actions Texas Flange Div customers requested to invoke Code Case N 242-1 for deficiencies identified in NRC 840330 ltr
BLANKLEY,W F Amelek, Inc 84/07/31 POTAPOVS,U Vendor Program Branch 26pp 25916 005

8408050041 Ack receipt of 840426 & 0706 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900911/84-01 Another insp necessary to resolve outstanding findings from NRC 840330 ltr
ZECH,G G Vendor Program Branch 84/08/02 BRUGGEMAN,W H General Electric Co 1p 25933 102

...15 ...nfirms GA program insp at San Jose,CA plant on 840813-17
...0731 telcon
...G ...endor Program Branch 84/08/03 SHIRLEY,N C General
...tric Co 1p 25925 318

...31 Ack receipt of 840214,0329,0615 & 0713 ltrs informing NRC
...ps taken to correct de...iation noted in GA Program Insp
99900277/83-01,99900277/83-02 & 99900277/83-04
...G Vendor Program Branch 84/08/03 PEED,E S Rockbestos
...p 25933 190

...91 Responds to NRC 840709 ltr re nonconformance noted in GA
...am Insp Rept 99900053/84-01 Corrective actions all
...es in-house modified to install new gaskets &
...mers notified of problem
...P,G W Anchor/Darling Valve Co (subs of Anchor/Darling
...ries, Inc) 84/07/20 POTAPOVS,U Vendor Program Branch
25949 339

...117 Responds to Item G of GA Program Insp Rept 99900617/84-01
...ctive actions program implemented to require weekly
...ulation of data from data rpts to provide electronic
...fer of info on two diskettes
...SON,S F National Board of Boiler & Pressure Vessel Inspectors
...7/17 POTAPOVS,U Region 4, Office of Director 1p
...341

...170 Forwards announcement of organizational changes,per 831019
...changes will be incorporated in next amend to
...R-17A
...S,N N Gibbs & Hill, Inc (subs of Dravo Corp) 84/07/25
...OVS,U Region 4, Office of Director 3pp 25949 270

...317 Amends response to 840716 ltr re nonconformance noted in GA
...am Insp Rept 99900743/84-01 Relay identified as ITE-27
...d be ITE-32D
...L,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd)
...7/23 POTAPOVS,U Region 4, Office of Director 1p
...307

...334 Responds to NRC 831205 ltr re nonconformance noted in GA
...ram Insp Repts 99900277/83-02 & 83-04 Extension of
...onse date to 840215 requested Cable classifications will
...equalified
...EHALES,G Rockbestos Co 83/12/27 POTAPOVS,U Region 4,
...e of Director 2pp 25945 233

...337 Confirms GA program insp at Phoenixville,PA plant on
...20-24,per 840802 telcon
...G G Vendor Program Branch 84/08/03 HEIDER,P Phoenix
...1 Corp 1p 25947 067

...466 Supplis 840214 response to NRC ltr re nonconformance noted in
...rogram Insp Rept 99900277/83-02 Corrective actions
...orting data qualification rept organized by file to be
...ily retrievable
...EHALES,G Rockbestos Co 84/03/29 POTAPOVS,V Region 4,
...e of Director 2pp 25940 334

...046 Ack receipt of 840716 request for extension of time to
...17 for Power Breakers,Inc to respond to NRC 840611 ltr
...A Program Rept 99900832/84-01 Extension acceptable
...,G G Vendor Program Branch 84/08/03 FLOOD,R W General
...tric Co 1p 25961 338

...050 Forwards GA Program Insp Rept 99900387/84-01 on 840423-27 re
...rmittent lock-up problems in RM23 radiation monitoring
...display channel Item AITS F02700336 closed W/o encl
...,G G Vendor Program Branch VITS 83-075 84/08/06
...S,R C Division of Project & Resident Programs 1p 25964 360

...114 Ack receipt of 840706 ltr informing NRC of steps taken to
...rect nonconformance & violations noted in GA Program Insp
...99900841/84-01 Addl info requested re failure to use
...test for deviation form
...,G G Vendor Program Branch 84/08/03 RICHARDS,A C GNB
...teries, Inc 2pp 25962 001

...130 Ack receipt of 840612 & 0712 ltrs informing NRC of steps
...en to correct nonconformance noted in GA Program Insp
...99900404/84-02 Responses to violations require addl
...ew & will be covered in future insp
...,G G Vendor Program Branch 84/08/03 GALLAGHER,J L
...inghouse Electric Corp 1p 67473 144

...218 Forwards GA Program Insp Rept 99900387/84-01 on 840423-27 &
...ce of nonconformance Description of steps taken to
...rect & prevent recurrence of deficiencies in GA program
...ested W/o encl
...POVS,U Region 4, Office of Director 84/06/11 BIJARCHI,I
Technologies, Inc /General Atomic Co 2pp 25975 014

8408080282 Confirms GA program insp at Streamwood,IL plant on 840827-31 per 840803 telcon
ZECH,G G, Vendor Program Branch 84/08/06 FRANZEN,J Chicago Fluid Power Co 1p 25965 269

8408080306 Ack receipt of 840713 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900387/84-01 Implementation of corrective actions will be reviewed during future insp
ZECH,G G Vendor Program Branch 84/08/03 BIJARCHI,I GA Technologies, Inc /General Atomic Co 1p 25964 114

8408080308 Ack receipt of 840113 & 0402 ltrs informing NRC of steps taken to correct inconsistency noted in GA Program Insp Rept 99900283/83-02 List of customer audits & list of customers supplied w/safety-related cable requested
ZECH,G G Vendor Program Branch 84/08/06 MANCHESTER,E BIW Cable Systems, Inc 2pp 25964 112

8408080311 Ack receipt of 840606 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900521/83-02 Addl info re seismic qualification & documentation of dedication process required
ZECH,G G Vendor Program Branch 84/08/03 HINKLEMAN,L G Bechtel Corp 1p 25964 111

8408080336 Confirms GA program insp at San Jose,CA on 840827-31,per 840806 telcon
ZECH,G G Vendor Program Branch 84/08/06 SHIRLEY,N C General Electric Co 1p 25964 081

8408080341 Ack receipt of 840525 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900403/84-01 GA Program Insp Rept 99900291/84-01 of Johnson Controls, Inc should be referenced
ZECH,G G Vendor Program Branch 84/08/06 BRUGGENMAN,W H General Electric Co 1p 25963 289

8408090002 Informs that corrective steps taken re nonconformance noted in GA Program Insp Rept 99900399/84-01 Test program completed w/satisfactory results
MADDIAN,A American Insulated Wire Corp 84/07/30 POTAPOVS,U Region 4, Office of Director 1p 25973 112

8408090006 Confirms GA program insp at Wilmington,NC plant on 840813-17,per 840723 telcon
ZECH,G G Vendor Program Branch 84/08/07 LONG,J A General Electric Co 1p 25973 007

8408090063 Ack receipt of 840627 ltr informing NRC of steps taken to correct nonconformance & violations noted in GA Program Insp Rept 99900786/84-01
ZECH,G G Vendor Program Branch 84/08/07 DEVAULT,E N General Electric Co 1p 25972 299

8408090174 Confirms GA program insp at Wrentham,MA plant on 840910-14, per 840803 telcon
ZECH,G G Vendor Program Branch 84/08/07 GREEN,J J Crosby Valve & Gage Co 1p 25972 285

8408090181 Ack receipt of 840621 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900259/83-02 Corrective actions will be examined during future insp
ZECH,G G Vendor Program Branch 84/08/07 POTEET,W R Combustion Engineering, Inc 1p 25973 183

8408090190 Ack receipt of 840622 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900300/84-01 Listed info requested within 25 days of ltr date
ZECH,G G Vendor Program Branch 84/08/08 MORIARTY,J M Colt Industries, Inc 1p 25973 184

8408100033 Forwards GA Program Insp Rept 99900743/84-01 on 840821,for info & action Return receipt requested W/o encl
JOHNSON,E H Region 4, Office of Director 84/08/06 CAHILL,W J Gulf States Utilities Co 2pp 25990 168 24X
Fiche 50-458,84/08/06,8408100033

8408100097 Forwards GA Program Insp Repts 99900387/84-01 & 99900404/84-02 Requests evaluation of significance of reported findings re quality & acceptability of product or svc provided by vendor W/o encl
HUNTER,D R Region 4, Office of Director 84/08/03 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 25991 014 24Y Fiche 50-445,84/08/03,8408100097

8408100107 Forwards QA Program Insp Repts 99900911/84-01, 99900715/84-01 & 99900325/84-01 Requests evaluation of significance of reported findings re quality & acceptability of vendor product or svc W/o encls
JOHNSON, E H Region 4, Office of Director 84/08/03 PILANT, J M Nebraska Public Power District 2pp 25990 200 24X
Fiche 50-298 84/08/03, 8408100107

8408100124 Responds to NRC 840723 ltr re nonconformance noted in QA program insp rept Corrective actions subcontractor validation/surveillance program underway & effort to verify certification of products accelerated
FIEDLER, D C Cardinal Industrial Products Corp 84/08/08
ZECH, G G Vendor Program Branch 13pp 25986 343

8408100128 Ack receipt of 840717 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900911/84-01 Implementation of corrective actions will be reviewed during future insp
ZECH, G G Vendor Program Branch 84/08/09 ISON, W J National Technical Systems 1p 25988 277

8408100131 Forwards vendor insp repts for evaluating significance of reported findings re quality & acceptability of product or svc provided by vendor Ack or receipt requested W/o encl
JOHNSON, E H Region 4, Office of Director 84/08/06 LEDDICK, R S Louisiana Power & Light Co 2pp 25988 281 24X
Fiche 50-382, 84/08/06, 8408100131

8408100132 Forwards QA vendor insp repts for info & evaluation Util should evaluate significance of findings Ack of receipt requested W/o encl
JOHNSON, E H Region 4, Office of Director 84/08/06 GPREA, G W Houston Lighting & Power Co 2pp 25988 283 24X
Fiche 50-498, 84/08/06, 8408100132

8408100139 Forwards QA Program Insp Repts 99900519/84-01, 99900387/84-01 & 99900404/84-02 for action Requests signature on endorsement to ack receipt of repts W/o encls
HUNTER, D R Region 4, Office of Director 84/08/03 KOESTER, G L Kansas Gas & Electric Co 2pp 25988 265 24X
Fiche 50-482, 84/08/03, 8408100139

8408140290 Ack receipt of 840720 ltr informing NRC of steps taken to correct violation/nonconformance noted in QA Program Insp Rept 99900053/84-01 Corrective actions will be reviewed during future insp
ZECH, G G Vendor Program Branch 84/08/13 CARON, A E Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc) 1p 26054 346

8408140298 Ack receipt of 840423 ltr informing NRC of steps taken to correct violation/nonconformance noted in QA Program Insp Rept 99900399/84-01 Cable qualification data will be reviewed on case-by-case basis by customers
ZECH, G G Vendor Program Branch 84/08/08 GALKIN, I S American Insulated Wire Corp 1p 26042 359

8408150001 Responds to NRC ltr re nonconformance noted in QA Program insp Rept 99900837/84-01 Requests extension to 840910 for plementation of corrective action
RNENGO, B Weed Instrument Co , Inc 84/08/08 POTAPOVS, U gion 4, Office of Director 1p 26067 052

8408150057 Ack receipt of 840412, 0613, 0808 & 0809 ltrs informing NRC of ceps taken to correct nonconformance noted in QA Program nsp Rept 99900840/83-01 Implementation of corrective action ill be reviewed during future insp
DEYOUNG, R C Director's Office, Office of Inspection and nforcement 84/08/10 DONOVAN, M J Cardinal Industrial Products orp 2pp 26066 349

8408160071 Advises that completion date for five new procedures is 40721, in response to Nonconformances B, Item B of NRC & nsp on 840116-20
JANDL, J C Lone Star Screw Co 84/08/07 POTAPOVS, U Region 4, Office of Director POTAPOVS, U Vendor Program Branch 2pp 26085 316

8408160077 Responds to 840629 ltr re whether NRC requires preaward evaluations & post-award audits for calibr svcs procured from NBS-certified state agencies Evaluation & audits not required
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/09 ANTONICH, P , KESEL, G P Dravo Corp 2pp 26126 347

8408160156 Notifies that name change to Gilbert/Commonwealth, Inc & organizational changes acceptable, per NRC QA requirements Changes should be incorporated in next topical rept rev & issued to all topical rept holders
GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/08/09 SAILER, W F Gilbert/Commonwealth, Inc (formerly Gilbert Associates, Inc) 2pp 26124 362

8408170021 Confirms QA program insp at East Grandby CT plant on 840820 wk per 840809 telcon
ZECH, G G Vendor Program Branch 84/08/13 JONES, G Rockbestos Co 1p 26118 350

8408170095 Confirms QA program insp at Wickliffe OH plant on 840820-24 per 840810 telcon
ZECH, G G Vendor Program Branch 84/08/16 KEYES, M A Bailey Controls Co (subs of Babcock & Wilcox Co) 2pp 26119 016

8408170105 Ack receipt of 840504 & 0720 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900509/84-01 Corrective actions & preventive measures will be reviewed during future insp
ZECH, G G Vendor Program Branch 84/08/13 KELLEY, R B Stone & Webster Engineering Corp 1p 26119 076

8408200315 Ack receipt of 840727 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900507/84-02
ZECH, G G Vendor Program Branch 84/08/16 ACKMANN, L E Sargent & Lundy, Inc 1p 26133 020

8408200351 Informs that GA Bettis Co notified all affected customers re swelling of ethylene propylene seals in contact w/ actuator lubricant Mobilegrease-28 & possible degradation of actuator stroke time Lubricant changed to Molykote-44
ZECH, G G Vendor Program Branch 84/08/16 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103)
NORELIUS, C E Region 3, Office of Director 5pp 26132 347

8408210390 Ack receipt of 840808 ltr requesting 1-month extension for implementing corrective action for App B nonconformance of QA Program Insp Rept 99900837/84-01
ZECH, G G Vendor Program Branch 84/08/16 MILLER, W O Weed Instrument Co , Inc 1p 26179 240

8408220320 Forwards QA Insp Repts 99900224/83-02, 99900224/84-01 & 99900851/84-01 re insps on 830912-16, 840416-18 & 0214-17 Safety significance of cracks in connectors low due to seismic qualification conducted w/connectors w/cracks
ZECH, G G Vendor Program Branch 84/08/20 LEWIS, R C Region 2, Office of Director 1p 26193 095

8408220360 Ack receipt of 840612 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900049/84-01 Addl info response to Nonconformances A & D requested
ZECH, G G Vendor Program Branch 84/08/20 COVEY, J Atwood & Morrill Co , Inc (subs of Foster Wheeler Corp) 2pp 26189 322

8408220383 Ack receipt of 831223 & 840627 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900347/83-01 Implementation of corrective actions will be reviewed during future insp
ZECH, G G Vendor Program Branch 84/08/20 MURPHY, T A Gulf & Western Industries, Inc 1p 26189 338

8408230215 Responds to NRC 840806 request for addl info re QA Program Insp Rept 99900283/83-02 Rept B915A will be modified & audit repts available in Boston, MA ofc
JEANMONOD, J BIW Cable Systems, Inc 84/08/16 ZECH, G G Vendor Program Branch 9pp 26209 160

8408230229 Responds to NRC 840711 ltr re nonconformance noted in QA Program Insp Repts 99900334/83-02 & 99900334/83-03 Corrective actions QA manual revised & assembly drawings reviewed
BOYER, R E Transamerica Delaval, Inc 84/08/08 POTAPOVS, U Region 4, Office of Director 2pp 26207 298

8408240125 Forwards QA Program Insp Rept 99900861/84-01 on 840521-25 & notices of nonconformance & violation
ZECH, G G Vendor Program Branch 84/07/27 BENNETT, W DuBose Steel, Inc 2pp 26236 165

--8408240128 Notice of violation from insp on 840521-25
* Vendor Program Branch 84/07/27 1p 26236 167

--8408240131 Notice of nonconformance from insp on 840521-25
* Vendor Program Branch 84/07/27 10pp 26236 168

--8408240140 QA Program Insp Rept 99900861/84-01 on 840521-25 Violation noted failure to report defective matl within 2 days of receipt of notification that matl defective
BAKER, E , MERSCHOFF, E W Vendor Program Branch 84/07/19 15pp 26236 170

8408240257 Forwards ltr re items A & B noted in QA Insp Rept 99900730/84-01 & corrective actions, QA Procedure II 1 revised on 8404?? & "High & low voltage QC switchgear checklists will be revised to ref QA Procedure 10 7 for sample size"
DUVALL,D E Brown Boveri Corp (subs of Brown Boveri & Co , Ltd)
84/08/13 ZECH,G G Vendor Program Branch 2pp 26222 359

8408240276 Responds to nonconformance noted in QA Program Insp Rept 99900803/84-01 Corrective actions procedures & instructions applicable to quality program prepared & maintained & training sessions for administering elements conducted
JERSE,J L Power Breakers, Inc 84/08/09 ZECH,G G Vendor Program Branch 14pp 24222 334

8408240276 Submits requested addl info to 840601 ltr re training of personnel on control crimping tool calibr,engineering review of stds & misunderstanding or insp of crimped wire terminals
DUVALL,D E Brown Boveri Corp (subs of Brown Boveri & Co , Ltd)
84/08/13 ZECH,G G Vendor Program Branch 2pp 26223 197

8408270354 Confirms QA program insp at Philadelphia,PA plant on 840827-31,per 840820 telcon
ZECH,G G Vendor Program Branch 84/08/22 VICKERY,D Tioga Pipe Supply Co , Inc 1p 26245 020

8408280067 Forwards response to NRC 840727 ltr re nonconformance noted in QA Program Insp Rept 99900522/84-02 Corrective actions now control form dtd 840820 issued as cover sheet to current user/theoretical manual for BSAP CE800
STATION,C D Bechtel Corp 84/08/20 ZECH,G G Vendor Program Branch 4pp 26261 220

8408280120 Forwards ASME responses re code inquiry concerning 840530 notice of nonconformance in QA Program Insp Rept 99900791/84-01 Addl info requested within 25 days
ZECH,G G Vendor Program Branch 84/08/22 DOWICKI,W J MCC Pacific Valves 1p 26259 061

--8408280126 Responds to 840419 inquiry re requirements for completion of data rept forms for parts when alternative marking method employed & when certificate holder is mfg replacement parts for components originally mrg & stamped
ENNIS,P American Society of Mechanical Engineers 84/07/26
BAKER,T T Vendor Program Branch 1p 26259 062

--8408280139 Responds to 840419 inquiry re requirements for completion of data forms for parts when alternative marking method employed & alternative identification markings traceable to required data rept form
ENNIS,P American Society of Mechanical Engineers 84/07/26
BAKER,T T Vendor Program Branch 1p 26259 063

8408280215 Forwards QA Insp Rept 99900295/83-01 re defective capstan spring lugs in PSA-1 & PSA J mechanical snubbers mfg by Pacific Scientific Co Process requiring vendor to form spring hinge age hardening specified
ZECH,G G Vendor Program Branch 84/08/22 LEWIS,R C Division of Project & Resident Programs 6pp 26274 301 24X
Fiche 50 000,84/08/22 8408280215

8408290701 Ack receipt of 840730 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900401/84 02
ZECH,G G Vendor Program Branch 84/08/27 ETHERIDGE,M R Combustion Engineering, Inc 1p 26290 338

8408290319 Ack receipt of 840709 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900831/84-01 Requests addl info re listed items in notice of nonconformance & status of previous insp findings
ZECH,G G Vendor Program Branch 84/08/27 CHRISTOPHER,T Westinghouse Electric Corp 2pp 26290 358

RECGD REGULATORY GUIDES

8408020107 Comments on proposed Reg Guide 1 8,Task RS 807-5,re selection & training of nuclear plant personnel Shift operating experience requirements should reflect position outlined in Chairman Palladino 840614 ltr
MILLER,J M Institute of Nuclear Power Operations 84/07/25
DIRCKS,W J Office of the Executive Director for Operations 1p 25892 263

8408030271 Reg Guide 1 147,Rev 3, "Inservice Insp Code Case Acceptability ASME Section XI,Div 1 "
* Office of Nuclear Regulatory Research, Director 84/07/31 4pp 25920 034

8408060114 Responds to approval request for info collection re 10CFR51, Licensing & Regulatory Policy & Procedures for Environ Protection & Reg Guide 4 2 "Preparation of Environ Repts for Nuclear Power Plants "
MACRAE,J B Office of Management & Budget OMB 3150-0021
84/07/24 SCOTT S Document Management Branch 2pp 25936 350

8408070114 Provides schedule info re NUREG-0737,Suppl 1 on emergency response commitment & clarifies schedular error in 840612 confirmatory order Amend to order prior to Sept 1985 suggested
O'TOOLE,J D Consolidated Edison Co of New York, Inc OL-82-33
84/07/31 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 25950 034 24X Fiche 50-247,84/07/31,8408070114

8408080344 Forwards nonproprietary "Use of Code Case N-192 " & proprietary repts,including "Documentation of Compliance of MBC P/N 73989 " & "Hose Assembly " qualification test procedures,per Reg Guide 1 84 Proprietary repts withheld
MITTL,R L Public Service Electric & Gas Co of New Jersey
84/07/30 SCHWENCER,A Licensing Branch 2 10pp 25963 276 24X
Fiche 50-354,84/07/30,8408080344

--8408080346 Nonproprietary "Use of Code Case N-192 (Compliance W/Addl Requirements of Reg Guide 1 84) "
* Public Service Electric & Gas Co of New Jersey 84/06/30
3pp 25963 284 24X Fiche 50-354,84/07/30,8408080344

8408090282 Summary of 840520 meeting w/util & Bechtel in Bethesda,MD re implementation of Reg Guide 1 97 requirements by licensee Util will provide supplemental rept to 840715 submission to address separation problems Viewgraphs encl
MINER,S Operating Reactors Branch 4 84/08/01 Operating Reactors Branch 4 12pp 25992 001 24X Fiche 50-312,84/08/01, 8408090282

8408130217 Accepts conditionally util 840622 request to use ASME Code Case N-369 for application in pressure testing of piping associated w/discharge side of Code Classes 2 & 3 centrifugal pumps Case should be documented in FSAR
KNIGHTON,G W Licensing Branch 3, 84/07/30 HARRISON,R J Public Service Co of New Hampshire 5pp 26058 325 24X
Fiche 50-443,84/07/30,8408130217

8408140295 Provides editorial changes to 840731 cover ltr & Attachment 1 re Suppl 1 to NUREG-0737,safety parameter display sys FSAR & implementation schedule,per Reg Guide 1 97 variables
JOHNSON,D D Consumers Power Co 84/08/09 CRUTCHFIELD,D Operating Reactors Branch 5 6pp 26043 144 24X
Fiche 50-255,84/08/09,8408140295

8408160485 Forwards IE Insp Rept 50-445/84-15 on 840301-0430 & notice of deviation
HANGART,R L Region 4, Office of Director 84/07/30, SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26107 296 24X Fiche 50-445,84/07/30,8408160485

--8408160495 Notice of deviation from insp on 840301-0430
* Region 4, Office of Director 84/07/30 1p 26107 299 24X
Fiche 50-445,84/07/30,8408160485

--8408160500 IE Insp Rept 50-445/84-15 on 840301-0430 Deviation noted failure to provide review & approval for safety-related maint instructions,per Rev 2 to Reg Guide 1 33
KELLEY,D L , SMITH,W F , RUNNICUTT,D M Region 4, Office of Director 84/07/27 11pp 26107 300 24X Fiche 50-445,84/07/30, 8408160485

8408210031 Forwards addl info requested in NRC 840430 ltr re exceptions to conformance to Rev 2 to Reg Guide 1 97 Encls should close Open Item 12 of SER (NUREG-0991)
KEMPER,J S Philadelphia Electric Co 84/08/16 SCHWENCER,A Licensing Branch 2 11pp 26181 337 24X Fiche 50-352,84/08/16, 8408210031

8408210159 Notification of 840830 meeting w/util in Bethesda,MD to discuss implementation of Reg Guide 1 97 requirements
MINER,S Operating Reactors Branch 4 84/08/15 STOLZ,J F Operating Reactors Branch 4 2pp 26195 223 24X
Fiche 50-312,84/08/15,8408210159

8408210313 Forwards revised FSAR App 7A pages addressing NRC 840625-26 requests for addl info re Reg Guide 1 97 As-built plant design info,not included in original submittal,incorporated Design provides info required to satisfy Rev 2 to reg guide
PETRICK,N A Standardized Nuclear Unit Power Plant System SLNRC 84-107 84/08/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 65pp 26179 060 24X Fiche 50-000,84/08/16, 8408210313

8408210412 Forwards list of accident monitoring equipment to be replaced within extended schedule of 10CFR50 49,per Reg Guide 1 97
MCDONALD,R P Alabama Power Co 84/08/17 VARGA,S A Office of Nuclear Reactor Regulation, Director 4pp 26179 211 24X
Fiche 50-364,84/08/17,8408210412

8408210416 Comments on Rev 1 to Reg Guide 1 58, "Qualification of Nuclear Power Plant Insp Exam & Testing Personnel "
SWAIN,H W Georgia Power Co 84/08/10 Docketing & Services Branch 2pp 26460 128

8408280113 Responds to 840717 ltr requesting extension of completion dates for submitting final rept re Reg Guide 1 97 requirements of Suppl 1 to NUREG-0737 Extension granted Adequate justification provided
EISENHUT,D G Division of Licensing LS05-84-08-032 84/08/23
VANDEWALLE,D J Consumers Power Co 4pp 26261 296 24X
Fiche 50-255,84/08/23,8408280113

8408280436 Third interim Significant Const Deficiency Rept 105 re electrical separation defects (Reg Guide 1 75) Initially reported on 840719 Rework generated by evaluations of walkdown results incomplete Next rept expected by 840831
GERRETS,T F Louisiana Power & Light Co 105 84/08/17
COLLINS,J T Region 4, Office of Director 2pp 26282 130 24X
Fiche 50-382,84/08/17,8408280436

8408300106 Forwards Insp Rept 50-247/84-18 on 840717-20 No violations noted
MARTIN,T T Division of Engineering & Technical Programs 84/08/14
O'TOOLE,J D Consolidated Edison Co of New York, Inc 2pp 26308 100 24X Fiche 50-247,84/08/14,8408300106

--8408300113 Insp Rept 50-247/84-18 on 840717-20 No violations noted Major areas inspected inservice activities,including program review,observations of work in progress,NDE procedure & licensee actions re Reg Guide 1 150
MCBREARTY,R A Region 1, Office of Director DURR,J P Division of Engineering & Technical Programs 84/08/06 3pp 26308 102 24X Fiche 50-247,84/08/14,8408300106

8408300139 Forwards original & Rev 2 to Reg Guide 1 75,per G Berry commitment Rev 1 to Reg Guide 1 75 bound in Disposition Exhibit Disclosure F-9a W/o encl Related correspondence
MIZUNO,G S Hearing Branch 1 OBR 382 OL-2 84/08/27
SPEKTER,M L Affiliation Not Assigned 1p 26304 362 24X
Fiche 50-445,84/08/27,8408300139

VIEW GRP NRC RESEARCH REVIEW GROUPS

8407020541 Suggests CRGR meeting be scheduled during wk of 840701 for rereview of proposed IE bulletin re undervoltage trip attachments of reactor trip breakers Burden of addl testing imposed by bulletin miniscule
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 84/06/27 STELLO,V Committee to Review Generic Requirements 8pp 26136 001

--8405180433 Informs that listed analysis performed in order to be responsive to V Stello concern that addl monitoring of parameters could be detrimental to safety re proposed IE bulletin on UV trip
HOLAHAN,G M Operating Reactors Assessment Branch 84/05/04
ROSSI,C E Events Analysis Branch 2pp 26136 009

--8407020544 Forwards safety impact analysis of proposed IE bulletin re undervoltage trip attachments of reactor trip breakers No clear not quantifiable safety benefit from proposed bulletin for Westinghouse plants considered in analysis
SPEIS,T P Division of Safety Technology 84/06/19 JORDAN,E C Division of Emergency Preparedness & Engineering Response (Post 830103) 14pp 26136 011

--8407030011 SECY-84-215
Informs Commission of status of licensee responses to Generic Ltr 83-28 re Salem ATWS events
DIRCKS,W J Office of the Executive Director for Operations
GL-83-28 84/05/24 9pp 26136 085

8407200109 Forwards for review & comment,draft generic ltr on required QA actions associated w/ATWS rule Comments due by 840720,as guidance to be issued by 840801
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 84/07/13 DENTON,H R Office of Nuclear Reactor Regulation, Director MINOGUE,R B Office of Nuclear Regulatory Research, Director MURLEY,T Region 1, Office of Director 24pp 26136 093

8408010246 Summary of CRGR Meeting 66 on 840711 re status of long-range plans to address BWR pipe cracking due to IGSCC & review of proposed resolution of Unresolved Safety Issue A-43 re containment emergency sump
STELLO, Committee to Review Generic Requirements 84/07/24
DIRCKS,W J Office of the Executive Director for Operations 2pp 25854 038

8408010159 Forwards summary of CRGR activities for Jul 1984 Summary will be included in EHO weekly rept to Commission for wk ending 840803
SNIEZEK,J Regional Operations & Generic Requirements 84/07/30
Committee to Review Generic Requirements 4pp 25854 040

8408020116 Notification of date & location change for 840802 meeting w/Regulatory Response Group in Bethesda,MD to discuss licensee efforts to quantify superheat steam releases resulting from main steam line break
WIGGINTON D L Operating Reactors Branch 1 84/07/23 VARGA,S A
Operating Reactors Branch 1 1p 25898 102

8408070081 Notification of CRGR Meeting 68 on 840808 in Bethesda,MD to review revised version of proposed rule amends re decommissioning criteria for facilities
STELLO,V Committee to Review Generic Requirements 84/07/26
EISENHUT,D Division of Licensing JORDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards,Director 2pp 25955 257

8408070149 Forwards revised "Document Accessions List,Jul 1984," for Rockwell Hanford Operations
* Basalt Waste Isolation Project 920 84/07/26 WRIGHT,R J
Division of Waste Management 1p 25957 210

--8408070153 Q06-30-84
Revised "Document Accessions List,Jul 1984," for Rockwell Hanford Operations
* Basalt Waste Isolation Project 84/07/31 512pp 25957 211

8408230396 Summary of CRGR 840808 Meeting 68 re revised version of RES proposed amends to 10CFR,Parts 30,40,50,51,70, & 72 to incorporate "Decomissioning Criteria for Nuclear Facilities " Proposal revised per CRGR 840425 Meeting 62
STELLO,V Committee to Review Generic Requirements 84/08/14
DIRCKS,W J Office of the Executive Director for Operations 2pp 26204 026

8408270102 Forwards summaries of proposed Apr 1984 bulletin entitled, "Undervoltage Trip Attachments of Reactor Trip Breakers" & of briefing re generic ltr specifying QA requirements for nonsafety-related ATWS equipment Encls withheld
STELLO,V Committee to Review Generic Requirements STELLO,V
Regional Operations & Generic Requirements 84/08/03 DIRCKS,W J
Office of the Executive Director for Operations 2pp 26258 208

8408270343 Notifies of CRGR Meeting 69 on 840905 to discuss proposed IE bulletin re cracking in BWR Mark I & II containments caused by inerting sys failure W/o stated encl
STELLO,V Committee to Review Generic Requirements 84/08/24
BERNERO,R Office of Nuclear Reactor Regulation, Director
JORDAN,E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards,Director 2pp 26238 142

8408270446 Advises that exemption of proposed final rule 10CFR53 from CRGR review will be granted providing CRGR offers no objection Rule not significantly changed from proposed rule reviewed at CRGR Meeting 33 on 830309 W/o stated encl
STELLO,V Regional Operations & Generic Requirements 84/08/24
BERNERO,R Office of Nuclear Reactor Regulation, Director
JORDAN,E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards,Director 1p 26238 127

8408300020 Submits list of current CRGR members
DIRCKS,W J Office of the Executive Director for Operations
84/08/28 PALLADINO, ROBERTS, ASSELSTINE Commissioners 1p
26300 138

SECY POSITION PAPERS BEFORE THE COMMISSION

8407300105 SECY-84-290A
Relates recent exemption decision to Section 185 of Atomic Energy Act,requiring NRC to find plant in conformity w/ provisions & rules & regulations of Commission before issuing OL
PLAINE,H H Office of the General Counsel 84/07/24 29pp
25920 001 24X Fiche 50-322,84/07/24,8407300105

8408070138 Draft Commission paper on NRC actions re QA in design implementation
DIRCKS,W J Office of the Executive Director for Operations
84/06/14 1pp 25991 207

8408090406 SECY-84-301
Informs Commission of long-range plan for dealing w/stress corrosion cracking in BWR piping & discussed progress made re execution of plan
DIRCKS,W J Office of the Executive Director for Operations
84/07/30 45pp 25991 304

8408240110 SECY-84-329
Recommends adoption of encl draft final financial qualification rule Rule eliminates financial qualification reviews from OL proceedings but reinstates such reviews for CP applications
MALSCH,H G Office of the General Counsel 84/08/14 33pp
26256 001

8408310156 FOIA request that SECY-84-29 & encl of PL William 840303 ltr re functional description of safety parameter display sys be placed in PMR
DOVE,K Affiliation Not Assigned 84/04/12 FELTON,J M Division of Rules and Records 1p 26352 001

STATE PROG STATE PROGRAMS

8406210504 Agenda for Nuclear Waste Board 840509 meeting in Olympia, WA Map encl
* Washington, State of 800 84/05/09 Washington, State of
4pp 25093 005

8408010334 Responds to NRC 840919 ltr offering technical comments & recommendations on State of ND radiation control program Program established procedures for handling escalated enforcement cases,per state statutes & rules
MOUNT,D P North Dakota, State of 84/07/19 COLLINS,J T Region 4, Office of Director 2pp 25866 075

8408020109 Forwards "State of KS Annex A,Nuclear Facilities Incidents Response Plan to Assistance R,Nuclear Emergencies of State Disaster Emergency Plan" & "Coffey County Contingency Plans for Incidents Involving Commercial Nuclear Power "
KOESTER,G L Kansas Gas & Electric Co KMLNRC 84-126 84/07/31
DENTON,H R Office of Nuclear Reactor Regulation, Director 1p
25892 306 24X Fiche 50-482,84/07/31,8408020105

--8408020114 "State of KS Annex A,Nuclear Facilities Incidents Response Plan to Assistance R,Nuclear Emergencies of State Disaster Emergency Plan "
MANNELL,L Kansas, State of 84/06/30 356pp 25892 307 24X
Fiche 50-482,84/07/31,8408020105

8408030087 Forwards Mod A003 to Cooperative Agreement DE-FC04-81AL16309 w/State of UT Agreement supports UMTRAP in State of UT, per Public Law 95-604
HILL,T V Energy, Dept of 84/06/13 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 84pp 25920 242

8408030084 Forwards "Cooperative Agreement Between DOE & State of OR "
HILL,T V Energy, Dept of 84/07/03 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 58pp 25934 136

8408030092 Forwards,for review & comment,minutes of 840531 meeting w/Salt state representatives re land acquisition, transportation & environ assessments Minutes of 840329-30 meetings w/Salt representatives in Columbus,OH also encl
TAYLOR,T J Energy, Dept of IN 412-84 84/07/17 LINEHAN,J J
Repository Projects Branch (Post 831001) 284pp 25921 001

8408030177 Confirms 840615 discussion w/P Lahaus following review & evaluation of Dept of Health radiation control program Application of guidelines for NRC review of Agreement State radiation control programs,comments & recommendations encl
MURLEY,T E Region 1, Office of Director 84/07/12 SENGER,D J
New York, NY 5pp 25917 310

8408060338 Forwards listed documents re decision on DOE guidelines, including transcript of 840622 Commission meeting & three written testimonies from Commission 840622 meeting W/o encl
RUSSELL,C F Division of Waste Management 84/07/03 STEVENS,D
Washington, State of 1p 25937 353

8408060341 Forwards listed documents re decision on DOE guidelines, including transcript of Commission 840622 meeting & three written testimonies from Commission 840622 meeting W/o encl
MATTSON,D R Policy & Program Control Branch (Post 831001) 612
84/07/03 BOHLINGER,H Louisiana, State of 1p 25937 352

8408070315 Ack receipt of 840719 response to technical comments & recommendations re review of State of ND radiation control program Commends efforts to improve quality of agreement matls functions & improve license & insp programs
COLLINS,J T Region 4, Office of Director 84/08/01 MOUNT,D
North Dakota, State of 1p 25947 306

8408070319 Advises that on 840621,NRC approved petition for rulemaking PRM-50-34 governing emergency exercise frequency Expresses appreciation for participation & assistance provided during rulemaking
CHILK,S J Office of the Secretary of the Commission 47FR30918
84/07/31 MILLER,R South Carolina, State of 1p 25944 160

8408070339 Confirms recent orientation meeting RS Heyer & RJ Dodd held w/A Alkema to discuss agreement matls program for new Agreement States Development of insp schedule & short-term action plan encouraged
COLLINS,J T Region 4, Office of Director 84/08/02 ANDERSON,L
Utah, State of 1p 25945 229

8408070434 Forwards rev to "NY State Radiological Emergency Preparedness Plan "
MANGAN,C V Niagara Mohawk Power Corp 84/08/03 Record Services
Branch (Document Control Desk) 2pp 25938 016 24X
Fiche 50-220,84/08/03,8408070434

--8408070439 Rev to "NY State Radiological Emergency Preparedness Plan "
* New York, State of 84/07/12 559pp 25938 018 24X
Fiche 50-220,84/08/03,8408070434

8408080034 Ack receipt of 840612 ltr re NRC assistance to State of TX on programs for developing low level radwaste disposal capacity NRC will provide State of TX & other Agreement States w/technical assistance appropriate to needs
PALLADINO,N J Commissioners 84/07/20 WHITE,M Texas, State of
2pp 25981 061

--8408080038 Encourages NRC to ensure adequate resources for assistance to states in complying w/10CFR61 re low level radwaste disposal
WHITE,M Texas, State of 84/06/12 PALLADINO,N Commissioners
1p 25981 063

8408080227 Forwards response to 840705 ltr re review & evaluation of State of NV radiation control program Response contains specific actions to be taken w/respect to each NRC recommendation
JACKA,B Nevada, State of 84/07/23 MARTIN,J B Region 5, Office of Director 2pp 25975 012

8408080333 Comments on proposed rule 10CFR60 re disposal of high level radwaste in geologic repositories Disagrees w/NRC re contents of site characterization plan HH Humphrey 840525 comments encl
KALITOWSKI,T Minnesota, State of 49FR5934 015 84/08/01
BROWNING,R Division of Waste Management 6pp 25964 091

--8408080334 Comments on suggestions for procedural changes in nuclear power plant licensing process Supports creation of ASLB screening boards
HUMPHREY,H H , OLSON,J F , SENECHAL,M E Minnesota, State of
49FR14698 84/05/25 Office of the Secretary of the Commission
8pp 25964 097

8408090042 Forwards States of NC & SC responses to regional assistance committee findings on offsite radiological emergency response preparedness & exercise on 840215-16 State & local emergency plans adequate
KRIMM,R W Federal Emergency Management Agency 84/07/27
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 8pp 25992 324 24X Fiche 50-413,84/07/27,
8408090042

8408090328 Summary of 840717 meeting w/State of CO,EPA,DOE & DOE contractors in Denver,CO re Durango EIS Attendee list encl
PENNIFILL,R A Low-Level Waste & Uranium Recovery Projects Branch
84/07/24 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery
Projects Branch 3pp 25984 341

8408090331 Comments on study of soil samples from Beatty,NV disposal site Questions raised re plans for further testing for Tc-99,I-129 & H-3 & use of results by State of NV
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch
84/03/27 NUSSBAUMER,D A Assistant Director for State Agreements
Programs 1p 25984 340

8408130077 Forwards marked-up draft Beatty site closure plan submitted by US Ecology, for review & comments Comments requested by 840808
NUSSBAUMER,D Assistant Director for State Agreements Programs
84/07/13 HIGGINBOTHAM,L Low Level Waste Licensing Branch 35pp
26059 001

8408130130 Forwards 'Geology & Mineral Deposits of Southern Nye County,' 'Nevada Statistical Abstract,' 'Annual Rept 1981-82,' 'Nevada Map Atlas-Fourth Edition' & 'Financial Statement,' per C Johnson 840613 request W/o encl
LOUX,R R Nevada, State of 32B 84/07/25 RUSSELL,C F Policy & Program Control Branch (Post 831001) 1p 26034 330

8408130140 Concurs w/remedial action plan for State of CO tailings repository
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 84/07/27 CREW,M E Energy, Dept of 2pp 26034 326

8408160479 Submits comments on draft 'Mission Plan for Civilian Raduaste Mgt Program,' per Nuclear Waste Policy Act,Section 301(b)
FRISHMAN,S Texas, State of 84/07/09 RUSCHE,B C Energy, Dept of 20pp 26108 331

8408210477 Forwards Rev 1 to Commonwealth of MA "Comprehensive Emergency Response Plan " Marked-up changes indicated
BOULAY,R J Massachusetts, Commonwealth of 84/06/15 NRC - No Detailed Affiliation Given 2pp 26181 143

--8408210478 Rev 1 to "Comprehensive Emergency Response Plan "
* Massachusetts, Commonwealth of 84/06/15 50pp 26181 145

8408220061 Forwards State of NV comments on draft mission plan
LOUX,R R Nevada, State of 84/08/10 BROWNING,R E Division of Waste Management 36pp 26211 305

8408230027 Summary of 840730 meeting w/DOE & Colorado Dept of Health preliminary findings for Gunnison,CO site
HAIGFIELD,M J PENNIFILL,R A Low-Level Waste & Uranium Recovery Projects Branch 84/08/06 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 2pp 26233 361

8408230031 Forwards comments on draft Beatty site closure plan Plan inadequate for effecting proper closure of facility Major deficiencies include lack of documentation re geology & hydrology & support for cost & financial data
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 84/08/15 NUSSBAUMER,D A Assistant Director for State Agreements Programs 5pp 26233 354

8408230253 Submits response to Category II indicators noted during NRC review of State of CO radiation control program
HOZLE,A J Colorado, State of 84/08/01 COLLINS,J Region 4, Office of Director 2pp 26213 271

8408230259 Submits list of actions taken in response to 840711 ltr re NRC review of State of CO radiation control program
VERNON,T M Colorado, State of 84/07/31 COLLINS,J T Region 4, Office of Director 1p 26213 270

)8230362 Forwards request for addl info to continue review of Nuclear Packaging,Inc topical rept on FL 50 Ferralium 225 high integrity container Response requested within 45 days of ltr receipt W/o encl
NUSSBAUMER,D A Assistant Director for State Agreements Programs 34/08/15 KIRNER,N P Washington, State of, Dept of Social & Health Services 1p 26230 358

408290225 Ack receipt of 840723 response to 1984 review of Agreement State radiation control program Changes satisfactory
MARTIN,J B Region 5, Office of Director 84/08/24 JACKA,S B Nevada, State of 1p 26290 308

408290229 Ack receipt of 840724 response to 1984 review of Agreement State radiation control program Changes acceptable, pending rev of state regulations
MARTIN,J B Region 5, Office of Director 84/08/24 TEDFORD,C F Arizona, State of 1p 26290 346

8408300289 NUREG/BR-0025 V10 N6
INFORMATION REPORT ON STATE LEGISLATION
KERR,G W , MCQUADE,J Office of State Programs, Director 84/07/27 9pp 26330 333

8408300320 Confirms 840622 discussion between RL Woodruff & SK Moore, J Brown & E Fuente concerning 840622 review & evaluation of State of MS radiation control program Program for regulation of agreement matls adequate
O'REILLY,J P Region 2, Office of Director 84/08/09 COBB,A B Mississippi, State of 5pp 26313 354

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8405290062 Forwards 'Investigation of Types AF & AE Piston Skirts " Rept supercedes 840227 submittal
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group OGTP-41
84/05/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24690 045 24X Fiche 50-000,84/05/24,8405290062

--8405290075 FAAA-84-2-14
"Investigation of Types AF & AE Piston Skirts "
* Failure Analysis Associates 84/05/23 120pp 24X
Fiche 50-000,84/05/24,8405290062

8405290179 Forwards "Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group OGTP-39
84/05/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 24692 090 24X Fiche 50-000,84/05/24,8405290179

--8405290271 FAAA-84-3-16
"Evaluation of Emergency Diesel Generator Crankshafts at Shoreham & Grand Gulf Nuclear Power Stations "
* Failure Analysis Associates 84/05/22 89pp 24692 092 24X
Fiche 50-000,84/05/24,8405290179

8407130037 Further response to FOIA request for numerous categories of records re issues discussed in IE Info Notices 81-29,83-52, 83-57 & 83-72 & Board Notifications 83-128 & 83-128A Forwards Apps C & D documents Search continuing
FELTON,J M Division of Rules and Records 84/04/13 JORDAN,W S Harmon & Weiss 7pp 25984 078 24X Fiche 50-000,84/04/13, 8407130037

8407230200 Forwards request for withholding proprietary viewgraphs entitled, 'Consistency Between Safety-Analysis & Tech Specs 10CFR50 36 Number of Operating Loops Mode 3 "
RAHE,E P Westinghouse Electric Corp NS-TA-84-003 84/07/09
EISENHUT,D Division of Licensing 5pp 25704 174

--8407230203 Requests withholding proprietary viewgraphs entitled, "Consistency Between Safety Analysis & Tech Specs 10CFR50 36 Number of Operating Loops Mode 3 "
WIESEMANN,R A Westinghouse Electric Corp AW-84-63 84/07/09
EISENHUT,D Division of Licensing 10pp 25704 179

8407300143 Forwards proprietary XN-NF-84-67(P), "Stability Evaluation Methodology for BWR Cores " Rept withheld (ref 10CFR2 790) Affidavit for withholding encl
CHANDLER,J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
84/07/02 THOMAS,C O Standardization & Special Projects Branch 4pp 25806 149

8407310144 Forwards proprietary WCAP-10621, "Westinghouse Thermocouple/Core Cooling Monitor Sys Isolation Tests " Rept withheld (ref 10CFR2 790)
PETRICK,N A Standardized Nuclear Unit Power Plant System SLNRC 84-0104 84/07/26 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 25835 258 24X Fiche 50-000,84/07/26, 8407310144

8408010012 Final Deficiency Rept DR-171 re flow adjustment subassembly on Model 1284 Robertshaw thermostatic flow control valves on jacket water cooling sys for TDI standby diesel generators Condition not reportable under 10CFR50 55(e)
BOOKER,J E Gulf States Utilities Co RBG-18228 84/07/16
COLLINS,J T Region 4, Office of Director 1p 25866 267 24X Fiche 50-458,84/07/16,8408010012

8408010038 Informs of review of 840629 ltr on operating experience, insp & analysis results re reliability of TDI V-20 diesels Lead engine testing,disassembly & insp not required before restart
CRUTCHFIELD,D Assistant Director for Safety Assessment
LS05-84-07-027 84/07/26 BASKIN,K P Southern California Edison Co 7pp 25855 333 24X Fiche 50-206,84/07/26,8408010038

8408010141 Submits schedule to provide addl info requested in NRC 840725 ltr re NUREG-1300P, "RELAP5YA - Computer Program for LWR Sys Thermal-Hydraulic Analysis," submitted in response to TMI Action Item II K 3 30
KAY,J A Yankee Atomic Electric Co FYR 84-80 84/07/25
CRUTCHFIELD D Operating Reactors Branch 5 2pp 25855 182 24X Fiche 50-029,84/07/25,8408010141

8408010240 Forwards C-E nonproprietary & proprietary "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station Units 2 & 3" & "CPC/CEAC Software Mods Proprietary repts withheld (ref 10CFR2 790)
MEDFORD,M O Southern California Edison Co 84/07/20,
KNIGHTON,G W Licensing Branch 3 13pp 25855 001 24X
Fiche 50-361,84/07/20,8408010240

--8408010217 CEN-284(S)-NP
Nonproprietary "Safety Analysis & CPC Methodology Changes for San Onofre Nuclear Generating Station,Units 2 & 3 " Info deleted
* Combustion Engineering Inc 84/06/30 35pp 25855 014 24X Fiche 50-361,84/07/20,8408010240

--8408010256 CEN-281(S)-NP
Nonproprietary "CPC/CEAC Software Mods for San Onofre Nuclear Generating Station Units 2 & 3 " Info deleted
* Combustion Engineering, Inc 84/07/31 24pp 25855 050 24X Fiche 50-361,84/07/20,8408010240

8408020025 Forwards program plan for evaluating & testing TDI standby diesel generators Program includes all recommended actions of TDI Owners Group & TDI Changes to number of start tests & overload tests requested
BOOKER,J E Gulf States Utilities Co RBG-18,244 84/07/19
DENTON,H R Office of Nuclear Reactor Regulation, Director 43pp
25882 229 24X Fiche 50-458,84/07/19,8408020025

8408020031 Informs of planned mod to C-E control element assembly guide tube wear sleeve Mod includes relocation of sleeve flare,sleeve expansion over full length of sleeve & relocation or crimp,providing resistance to axial motion
SCHERER,A E Combustion Engineering, Inc LD-84-039 84/07/27
RUBENSTEIN,L S Assistant Director for Core & Plant Systems 2pp
25880 238 24X Fiche 50-000,84/07/27,8408020031

8408020054 Provides requested info re schedule for testing & insps of two TDI diesel generators for standby emergency power Operational testing scheduled for Last Quarter 1984 & early 1985 Svc list encl Related correspondence
O'NEILL,J H Shaw, Pittman, Potts & Trowbridge O'NEILL,J H
Carolina Power & Light Co DSB 700 DL 84/07/31 KELLY,J L ,
BRIGHT,G O , CARPENTER,J H Atomic Safety and Licensing Board Panel
3pp 25891 330 24X Fiche 50-400,84/07/31,8408020054

8408020129 Joint direct testimony of RN Anderson,BQ Christensen, QD Eley,A Oakshi,DO Bridenbaugh & RB Hubbard re Suffolk County emergency diesel generator contentions Certificate of Svc encl Related correspondence
ANDERSON,R N San Jose State Univ , San Jose, CA CHRISTENSEN,S
U S Merchant Marine Academy, Kings Point, NY ELEY,G D Ocean
Fleets Consultancy Service DSB 709 DL 84/07/31 1324pp
25886 223 24X Fiche 50-322,84/07/31,8408020129

8408030120 Supplemental RO on 840726,while performing routine maint on Div 1 TDI diesel engine,water observed coming from open cylinder cock on left bank cylinder head 7 Caused by 2-inch crack in right exhaust port casting Head replaced
DALE,L F Mississippi Power & Light Co AECM-84/0401 84/07/30
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25916 110 24X Fiche 50-416,84/07/30,8408030120

8408060045 Forwards corrected Page 46 from App A to "ENVIROSTONE Gypsum Cement 10CFR61 Compliance Testing Topical Rept" (USG-684-1P & USG 684-1NP) re mix ratios for ion exchange bead resins solidified w/ENVIROSTONE Gypsum cement
LANGE R G U S Gypsum Co 84/07/19 HIGGINBOTHAM,L Low Level
Waste Licensing Branch 2pp 25937 089

--8408060047 USG-684-1NP CRR
Corrected Page 46 from App A to "ENVIROSTONE Gypsum Cement 10CFR61 Compliance Testing Topical Rept "
* U S Gypsum Co 84/07/19 1p 25937 091

8408060050 Forwards info addressing open items identified in NRC/BNWL/ TDI Diesel Generator Owners Group 840622 meeting
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group OGTP-108-N
84/07/10 BERLINGER,C Director's Office, Office of Inspection and
Enforcement 43pp 25933 133 24X Fiche 50-000,84/07/10,
8408060050

8408060102 Forwards "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review " Addl copies sent to BNWL
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group
OGTP-140-N-28 84/07/27 DENTON,H R Office of Nuclear Reactor
Regulation, Director 2pp 25932 137 24X Fiche 50-000,84/07/27,
8408060102

--8408060138 "Emergency Diesel Generator Auxiliary Module Control Wiring & Termination Qualification Review "
* Stone & Webster Engineering Corp 84/07/31 36pp 25932 139
24X Fiche 50-000,84/07/27,8408060102

8408060116 Forwards proprietary responses to NRC second round questions on CONDOR Topical Rept WCAP-10107 & application for withholding Responses withheld (ref 10CFR2 790(a))
RAHE,E P Westinghouse Electric Corp NS-EPR-2939 84/07/23
THOMAS,C O Standardization & Special Projects Branch 2pp
25936 038

--8408060125 Requests withholding of proprietary responses to NRC second round questions on CONDOR Topical Rept WCAP-10107,per 10CFR2 790
WIESEMANN,R A Westinghouse Electric Corp AW-84-68 84/07/23
THOMAS,C O Standardization & Special Projects Branch 1p
25936 040

8408060189 Confirms completion of listed 840720 & 26 commitments re TDI diesel generators Correction of deficiencies noted during confirmatory walkdown of engine fuel oil lines completed
DALE,L F Mississippi Power & Light Co ACEM-84/0392 84/08/03
DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp
25932 286 24X Fiche 50-416,84/08/03,8408060189

8408060220 Forwards final summary Rept WCAP-10509, "Analysis of Capsule T From TVA Sequoyah,Unit 2 Reactor Vessel Radiation Surveillance Program " Change in capsule withdrawal schedule in Tech Spec Table 4 4-5 not required
MILLS,L M Tennessee Valley Authority 84/07/31 ADENSAM,E
Licensing Branch 4 2pp 25929 109 24X Fiche 50-328,84/07/31,
8408060220

--8408060231 WCAP-10509
"Analysis of Capsule T From TVA Sequoyah,Unit 2 Reactor Vessel Radiation Surveillance Program "
BOOSE,R S , VANICHKO,S E , CHENEY,C A Westinghouse Electric Corp
84/04/30 85pp 25929 111 24X Fiche 50-328,84/07/31,
8408060220

8408060324 Forwards "Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group
OGTP-147-N-29 84/08/01 DENTON,H R Office of Nuclear Reactor
Regulation, Director 2pp 25927 064 24X Fiche 50-000,84/08/01,
8408060324

--8408060387 FAAA-84-6-56
"Design Review of Elliott Model 650 Turbocharger Used on TDI DSRV-12-4 & DSRV-20-4 Emergency Diesel Generator Sets "
* Failure Analysis Associates 84/07/31 62pp 25927 066 24X
Fiche 50-000,84/08/01,8408060324

8408060405 Forwards repts received by BNWL & consultants directly from FaAA & TDI Owners Group at 840622 meeting Draft "Overview of Repts,Analysis & Recommendations re Main Propulsion Engines M/V Columbia" encl
ALZHEIMER,J M Battelle Memorial Institute, Pacific Northwest
Laboratories 84/06/28 MILLER,M Division of Licensing 158pp
25926 173 24X Fiche 50-000,84/06/28,8408060405

8408070193 Forwards request for addl info re AECC-4 (P/NP), "Mobile Vol Reduction Sys " Response by 840817 requested
THOMAS,C O Standardization & Special Projects Branch 84/07/24
GARCIA R Aerojet Energy Conversion Co (subs of General Tire &
Rubber Co) 12pp 25937 100

8408070222 Informs that based on GE 840525 details,GE fuel surveillance program complies w/SRP Section 4 2 II D 3 & acceptable Increased on-line surveillance per SRP Section 4 2 II D 2 still required
RUBENSTEIN,L S Assistant Director for Core & Plant Systems
84/06/27 GRIDLEY,R L General Electric Co 2pp 25957 051

8408070236 Forwards "Failure of Access Door Between Drywell & Wetwell," technical review rept Review concludes that no similar access design exists between foreign & domestic Mark II containments
WOLF,T R Reactor Operations Analysis Branch AEOD/T412 84/06/18
SEYFRIT,K V Reactor Operations Analysis Branch 1p 25957 044

--8408070242 "Failure of Access Door Between Drywell & Wetwell," technical review rept
WOLF,T Director's Office AEOD/T412 84/06/18 3pp
25957 045

8408070275 Forwards addl info on safety parameter display sys in response to 840326 request & suppl to SAR Sys scheduled for implementation by end of Spring 1985 refueling outage Rev 1-A to WCAP-7819 & WCAP-7685A encl
HINTZ,D C Washington Public Power Supply System NRC-84-123
84/08/01 EISENHUT,D G Division of Licensing 25pp 25948 123
24X Fiche 50-305,84/08/01,8408070275

--8408070282 WCAP-7819 R01A
Rev 1-A to "Nuclear Instrumentation Sys Isolation Amplifier "
LIPCHAK,J B , BARTHOLOMEW,R Westinghouse Electric Corp
75/04/30 33pp 25948 149 24X Fiche 50-305,84/08/01,8408070275

--8408070288 WCAP-7685-A
"Test Rept on Isolation Amplifiers "
GARBER, I Westinghouse Electric Corp 75/05/31 10pp
25949 183 24X Fiche 50-305 84/08/01, 8408070275

8408070401 Informs that new sys of acknowledging receipt of licensee correspondence re noncompliance found during insp instituted, effective 840320 Preprinted form will be used rather than ltr
KEPPLER, J G Region 3, Office of Director 84/08/03
Commonwealth Edison Co 3pp 25942 188 24X Fiche 50-000, 84/08/03, 8408070401

8408070414 Forwards nonproprietary Rev 0 to WCAP-10170, "Key Safety Parameter Selection " & proprietary Rev 1 to WCAP-10170, "Key Safety Parameter Selection " (Generic Ltr 82-33) Proprietary rept withheld (ref 10CFR2 790)
WOOLEVER, E J Duquesne Light Co GL-82-33 84/08/01
EISENHUT, D G Division of Licensing 4pp 25938 001 24X
Fiche 50-412, 84/08/01 8408070414

--8408070419 WCAP-10170 APC S1 R0
Nonproprietary Rev 0 to App C to Suppl 1 to "Key Safety Parameter Selection for Beaver Valley Unit 2 Safety Parameter Display Sys (SPDS) "
MORLEY, R C Westinghouse Electric Corp 84/07/30 11pp
25938 005 24X Fiche 50-412, 84/08/01, 8408070414

8408070445 Forwards response to several TDI emergency diesel engine issues raised during NRC & Battelle 840726 visit Jacket water sys parameters show no evidence of flow resistance increase
TUCKER, H B Duke Power Co 84/08/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 5pp 25942 263 24X Fiche 50-413, 84/08/01, 8408070445

8408070446 Requests exemption from 10CFR50, App A, GDC 4 re elimination of postulated circumferential & longitudinal breaks in RCS main loop piping & WCAP-10559 & WCAP-10560 Repts withheld (ref 10CFR2 790)
GOLDBERG, J H Houston Lighting & Power Co ST-HL-AE-1096
84/07/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 25940 349 24X Fiche 50-498, 84/07/17, 8408070446

8408080016 Informs that B&W plans to use BWC correlation for licensing analyses to be performed w/CHATA & TEMP core thermal hydraulic analysis codes For reload repts supporting upcoming cycles of Oconee, Unit 1 & Rancho Seco
TAYLOR, J H Babcock & Wilcox Co 84/08/02 THOMAS, C O
Standardization & Special Projects Branch 2pp 25970 306

8408080236 Interim Deficiency Rept DR-140 re TDI standby diesel generator fuel oil piping & header assembly Next rept will be provided by 841011 Field QC insp of generator IEGS*EGIB will be performed in near future
BOOKER, J E Gulf States Utilities Co RBG-18318 84/07/27
COLLINS, J T Region 4, Office of Director 1p 25974 358 24X
Fiche 50-458, 84/07/27, 8408080236

8408080275 Forwards proprietary & nonproprietary "Westinghouse Setpoint Methodology for Protection Sys, Catawba Station," in response to Section 7 3 24 of SER Application for withholding proprietary rept encl
TUCKER, H B Duke Power Co 84/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 25964 228 24X Fiche 50-413, 84/07/30, 8408080275

--8408080280 Requests withholding of proprietary "Westinghouse Setpoint Methodology for Protection Sys, Catawba Station" (ref 10CFR2 790)
WIESEMANN, R A Westinghouse Electric Corp CAW-84-69 84/07/20
DENTON, H Office of Nuclear Reactor Regulation, Director 8pp
25964 230 24X Fiche 50-413, 84/07/30, 8408080275

--8408080284 Nonproprietary "Westinghouse Setpoint Methodology for Protection Sys, Catawba Station " Two oversize tables encl Aperture cards available in PDR
JANSEN, R L , TULEY, C R Westinghouse Electric Corp 84/06/30
71pp 25964 239 24X Fiche 50-413, 84/07/30, 8408080275

8408080288 Summary of 840712 meeting w/B&W Owners Group re non-nuclear instrumentation sys status Attendance list & viewgraphs encl
KADAMBI, P Operating Reactors Branch 4 84/07/27 Operating Reactors Branch 4 36pp 25978 228 24X Fiche 50-000, 84/07/27, 8408080288

8408090148 Final Deficiency Rept [RDC 92(84)] re potential problem w/standby diesel generator loose flexible coupling drive hubs supplied by TDI Initially reported on 840120
Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co [RDC 92(84)]
84/07/27 KEPPLER, J G Region 3, Office of Director 2pp
25993 176 24X Fiche 50-440, 84/07/27, 8408090148

8408090193 Forwards nonproprietary version of Rev 2 to XN-NF-84-21, "DC Cook Unit 2 Cycle 5 5% Steam Generator Tube Plugging Limiting Break LOCA/ECCS Analysis," per American Electric Power Svc Co request
CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
JCC 110 84 84/08/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 25972 038 24X Fiche 50-316, 84/08/07, 8408090178

--8408090209 XN-NF-84-21 (NP) R02
Nonproprietary Version of Rev 2 to "DC Cook Unit 2 Cycle 5 5% Steam Generator Tube Plugging Limiting Break LOCA/ECCS Analysis
KAYSER, W V , CHANDLER, J C , STOUT, R B Exxon Nuclear Co , Inc (subs of Exxon Corp) 84/08/07 75pp 25972 039 24X
Fiche 50-316, 84/08/07, 8408090193

8408090230 Forwards proprietary Rev 1, Suppl 4 to XN-NF-82-20(P), "Exxon Nuclear Co Evaluation Model EXEM/PWR ECCS Model Updates Adjustments to FLECHT Based Heat Transfer Correlations " Rept withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
JCC 105 84 84/07/27 THOMAS, C O Standardization & Special Projects Branch 1p 25971 113

8408090347 Discusses alternatives for responding to NRC 840424 request for addl info re XN-NF-82-49(P), "Exxon Nuclear Co Evaluation Model EXEM/PWR Small Break Models " Exxon should respond by 841001 to maintain current schedule
THOMAS, C O Standardization & Special Projects Branch 84/07/30
CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp) 3pp
25984 337

8408090353 Forwards requests for addl info re CENPD 199, Rev 1 (P/NP), "C-E Set Point Methodology " Response to questions requested by 840624
THOMAS, C O Standardization & Special Projects Branch 84/07/30
SCHERER, A E Combustion Engineering, Inc 5pp 25984 331

8408090433 Notification of 840808 meeting w/B&W Owners Group in Bethesda, MD to discuss potential application of leak-before-break concept to B&W reactors
KADAMBI, P Operating Reactors Branch 4 84/08/06 STOLZ, J F
Operating Reactors Branch 4 2pp 25983 360

8408100063 Forwards Vols I & II of "NUSCo Thermal Hydraulic Model Qualification," for RETRAN & VIPRE
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities B11278 84/07/30 MILLER, J R
Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors
Branch 3 2pp 25987 072 24X Fiche 50-213, 84/07/30, 8408100063

--8408100070 NUSCO 140-1
Vol I of "NUSCo Thermal Hydraulic Model Qualification (RETRAN) "
* Northeast Utilities 84/07/30 262pp 25987 074 24X
Fiche 50-213, 84/07/30, 8408100063

--8408100077 NUSCO 140-2
Vol II of "NUSCo Thermal Hydraulic Model Qualification (VIPRE) "
* Northeast Utilities 84/07/30 229pp 25987 336 24X
Fiche 50-213, 84/07/30, 8408100063

8408100121 Responds to 840723 request for addl info on AECC-2-P(NP) & Amend 1 Draft response discussed w/NRC, util & Saigent & Lundy on 840731 Info will be provided as Amend 2 on 840810
GARCIA, R Aerojet Energy Conversion Co (subs of General Tire & Rubber Co) 0500 4210 RG AB 84/08/08 THOMAS, C O
Standardization & Special Projects Branch 2pp 25988 255

8408100127 Forwards "Calculation of Trip Setpoint Values, Plant Protection Sys," in response to 830620 ltr
VAN BRUNT, E E Arizona Public Service Co ANPP-30109-EEVB
84/08/02 KNIGHTON, G Licensing Branch 3 1p 25991 042 24X
Fiche 50-528, 84/08/02, 8408100127

--8408100137 CEN-286(V) R00
Rev 0 to "Calculation of Trip Setpoint Values, Plant Protection Sys "
* Combustion Engineering, Inc 84/07/31 118pp 25991 043 24X
Fiche 50-528, 84/08/02, 8408100127

8408130170 Forwards GE rept, "Reduced RHR Svc Water Flow & Suppression Pool Temp Response Licensing Ltr Rept " Encl replaces proprietary rept
MCGAUGHY, R W Iowa Electric Light & Power Co NG-84-3270
84/08/08 DENTON, H Office of Nuclear Reactor Regulation, Director
1p 26010 030 24X Fiche 50-331, 84/08/08, 8408130170

-8408130172 Reduced RHR S/c Water Flow & Suppression Pool Temp Response Licensing Ltr Rept '
GRIDLEY, P L General Electric Co 84/07/18 5pp 26010 031
24X Fiche 50-331, 84/08/08, 8408130170

8408130181 Forwards details of items to be included in future util submittals re TDI diesel generator reliability verification
YOUNGBLOOD, T J Licensing Branch 1 84/08/02 SPENCE, M D Texas Utilities Electric Co (formerl, Texas Utilities Generating Co)
7pp 26036 286 24X Fiche 50-445, 84/08/02, 8408130181

8408130349 Responds to 840702 request for addl info on CEN-268 re resolution of NUREG-0737, Item II K 3 5, 'Study Need for Automatic Trip of Reactor Coolant Pumps " Response will be discussed at 840920 meeting
WELLS, R W C-E Operating Plants Owners Group WELLS, R W Northeast Utilities Service Co (subs of Northeast Utilities) RWW-84-60
84/08/07 MILLER, J R Operating Reactors Branch 3 2pp
26010 224

8408140191 Forwards XN-NF-691(P)(A), 'Stability Evaluation of BWR Core Sensitivity Analyses ' Rept withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
JCC 109 84 84/08/07 THOMAS, C O Standardization & Special Projects Branch 1p 26042 360

8408140200 Forwards proprietary Amend 2 to AECC-2-P & nonproprietary Amend 2 to AECC-2-NP, 'Radwaste Vol Reduction Sys," per NRC 840723 request Proprietary version withheld
(ref 10CFR2 790) Affidavit encl
GARCIA, R Aerojet Energy Conversion Co (subs of General Tire & Rubber Co) 84/08/10 THOMAS, C O Standardization & Special Projects Branch 5pp 26043 001

--8408140204 AECC-2-NP A02
Nonproprietary Amend 2 to 'Radwaste Vol Reduction Sys "
* Aerojet Energy Conversion Co (subs of General Tire & Rubber Co) 84/08/10 66pp 26043 006

8408140356 Forwards Suppl 1 to Rev 2 to XN-NF-83-72, "HB Robinson, Unit 2, Cycle 10 SAR - Disposition of Chapter 15 Events " Rept provides confirmatory analyses results for SAR Remainder of analyses will be submitted by 840817
ZIMMERMAN, S R Carolina Power & Light Co NLS-84-352 84/08/08
VARGA, S A Operating Reactors Branch 1 2pp 26041 001 24X
Fiche 50-261 84/08/08, 8408140356

--8408140363 XN-NF-83-72 S01 R02
Suppl 1 to Rev 2 to 'HB Robinson, Unit 2, Cycle 10 SAR - Disposition of Chapter 15 Events "
LEACH, C E , KAYSER, W V , CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp) 84/07/20 33pp 26041 003 24X
Fiche 50-261, 84/08/08, 8408140356

8408140396 Forwards Rev 2 to XN NF-81-21(p), 'Generic Mechanical Design for Exxon Nuclear Jet Pump BWR Reload Fuel " Rept withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
JCC 107 84 84/08/07 THOMAS, C O Standardization & Special Projects Branch 7pp 26049 078

8408140410 Forwards "Analyses of Capsule TE1-B, Toledo Edison Co, Davis-Besse Nuclear Power Station, Unit 1 Reactor Vessel Matl Surveillance Program "
CROUSE, R P Toledo Edison Co 1069 84/08/10 EISENHUT, D G
Division of Licensing 1p 26049 001 24X Fiche 50-346, 84/08/10, 8408140410

--8408140413 BAW-1834
"Analyses of Capsule TE1-B, Toledo Edison Co, Davis-Besse Nuclear Power Station, Unit 1 Reactor Vessel Matl Surveillance Program '
LOWE, A , COLLINS, L L , EWING, J W Babcock & Wilcox Co 84/05/31
75pp 26049 002 24X Fiche 50-346, 84/08/10, 8408140410

8408140426 Provides address for transmitting all operator licensing correspondence to Region III ofc, except info for examiners
WALKER R D Region 3, Office of Director 84/08/10 Michigan, Univ of, Ann Arbor, MI 2pp 26051 198 24X Fiche 50-000, 84/08/10, 8408140426

8408140429 Forwards "Analyses of Capsule ANI-A, Arkansas Power & Light Co, Arkansas Nuclear One, Unit 1, Reactor Vessel Matl Surveillance Program '
MARSHALL, J R Arkansas Power & Light Co 1CAN088407 84/08/06
STOLZ, J F Operating Reactors Branch 4 1p 26049 301 24X
Fiche 50-313, 84/08/06, 8408140429

--8408140433 BAW-1836
'Analyses of Capsule ANI-A, Arkansas Power & Light Co, Arkansas Nuclear One, Unit 1, Reactor Vessel Matl Surveillance Program
LOWE, A L , ANDLAND, J D , COLLINS, L L Babcock & Wilcox Co
84/07/31 93pp 26049 302 24X Fiche 50-313, 84/08/06, 8408140429

8408150084 Forwards proprietary response to NRC 840713 request for addl info on Special Rept MFN-068-84, "Generic Licensing of 1984 Lead Test Assemblies ' Encl Withheld (ref 10CFR2 790)
CHARNLEY, J S General Electric Co MFN-102-84 84/07/24
THOMAS, C O Standardization & Special Projects Branch 1pp
26067 131

8408150180 Application to amend License DPR-51, modifying designation of areas in steam generator imperfections found & allowing sleeving of tubes Proprietary affidavit & BAW-1823P, "Once-Through Steam " encl Fee encl
GRIFFIN, J M Arkansas Power & Light Co 1CAN088404 84/08/13
STOLZ, J F Operating Reactors Branch 4 6pp 26067 132 24X
Fiche 50-313, 84/08/13, 8408150180

8408150414 Forwards IE Insp Rept 50-445/84-18 on 840501-31 & notice of violation Areas inspected include preoperational test witnessing, followup of TDI diesel generator insp & plant tours
BANGART, R L Region 4, Office of Director 84/07/26 SPENCE, M D
Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26077 252 24X Fiche 50-445, 84/07/26, 8408150414

--8408150417 Notice of Violation from insp on 840501-31
* Region 4, Office of Director 84/07/26 2pp 26077 254 24X
Fiche 50-445, 84/07/26, 8408150414

--8408150440 IE Insp Rept 50-445/84-18 on 840501-31 Violations noted failure to follow procedure during Train A emergency diesel generator auxiliary sys retest & hold tags improperly removed from Train A diesel engine
KELLEY, D L , SMITH, W F , HUNNICUTT, D M Region 4, Office of Director 84/07/06 10pp 26077 256 24X Fiche 50-445, 84/07/26, 8408150414

8408150438 Motion for leave to make restricted svc of certain documents, for protective order & for in camera cross-examination re documents Certificate of Svc encl Related correspondence
FARLEY, E M Long Island Lighting Co FARLEY, E M Hunton & Williams DSB 057 OL 84/08/14 Atomic Safety and Licensing Board Panel 9pp 26068 262 24X Fiche 50-322, 84/08/14, 8408150438

8408150473 Forwards direct testimony & supporting exhibits on adequacy & reliability of TDI emergency diesel generators W/o motion for protective order Certificate of Svc encl Related correspondence
TARLETZ, D B Hunton & Williams TARLETZ, D B Long Island Lighting Co DSB 065 OL 84/08/14 BRENNER, L , FERGUSON, G A , MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 26068 295 24X
Fiche 50-322, 84/08/14, 8408150473

--8408150476 Testimony of CH Wells, DP Johnson, HF Wachob, C Seaman, D Cimino & NK Burrell re shotpeening of replacement crankshafts Related correspondence
WELLS, C H , JOHNSON, D P , WACHOB, H F Long Island Lighting Co
OL 84/08/14 36pp 26068 299 24X Fiche 50-322, 84/08/14, 8408150473

--8408150485 Testimony of RL McCarthy, PR Johnson, EF Montgomery & SK Chen on Suffolk County contention re replacement crankshafts on diesel generators Related correspondence
MCCARTHY, R L , JOHNSON, P R , MONTGOMERY, E F Long Island Lighting Co OL 84/08/14 62pp 26068 337 24X Fiche 50-322, 84/08/14, 8408150473

--8408150498 Testimony of EJ Youngling & FF Pischinger on Suffolk County contention re replacement crankshafts on diesel generators Exhibits encl Related correspondence
YOUNGLING, E J , PISCHINGER, F F Long Island Lighting Co OL
84/08/14 400pp 26069 036 24X Fiche 50-322, 84/08/14, 8408150473

--8408150505 Vols 1, 2 & 3 of testimony of RL McCarthy, CA Rau, CH Wells, HF Wachob, D Johnson, RK Taylor, CK Seaman, EJ Youngling, CS Mathews, MH Lowrey, JF Wallace & MH Schuster on Suffolk County contention re cylinder blocks Related correspondence
MCCARTHY, R L , RAU, C A , WELLS, C H Long Island Lighting Co OL
84/08/14 300pp 26070 313 24X Fiche 50-322, 84/08/14, 8408150473

--8408150514 Vols 1 & 2 of testimony of DO Harris DP Johnson,RL McCarthy, FF Pischinger,CK Seaman LA Swanger & EJ Youngling on Suffolk County contention re AE piston skirts Related correspondence
HARRIS,D O , JOHNSON,D P , MCCARTHY,R L Long Island Lighting Co OL 84/08/14 450pp 26071 200 24X Fiche 50-322,84/08/14, 8408150473

--8408150530 Vols 1 & 2 of testimony of CK Seaman,EJ Youngling, JC Kammeyer,CH Wells,LA Swanger,JF Wallace,CB Mathews & FC Pischinger on Suffolk County contention re cylinder heads Exhibits 1-26 encl Related correspondence
SEAMAN,C K , YOUNGLING,E J , KAMMEYER,J C Long Island Lighting Co OL 84/08/14 300pp 26072 327 24X Fiche 50-322,84/08/14, 8408150473

8408160018 Discusses revised draft maint & surveillance program plan Revs include five-phase approach to program mgt & identification of relevant industry programs & approx schedules Meeting scheduled for 840822 to address plan
RUSSELL,W T Division of Human Factors Safety 84/08/07
TAYLOR,J H Babcock & Wilcox Co 1p 26128,213

8408160026 Forwards IE Insp Rept 50-445/84-20 on 840503-0619 No violations or deviations identified
BANGART,R L Region 4, Office of Director 84/07/26 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 26108 150 24X Fiche 50-445,84/07/26,8408160026

--8408160037 IE Insp Rept 50-445/84-20 on 840503-0619 No violations or deviations noted Major areas inspected work & documentation associated w/site portion of recertification program implemented on Train B TDI emergency diesel generator
SMITH,W F , HUNNICUTT,D M Region 4, Office of Director 84/07/05 9pp 26109 152 24X Fiche 50-445,84/07/26,8408160026

8408160066 Final deficiency rept re loose drive hubs on overspeed governor drive shaft on TDI diesel engines Initially reported on 840203 Hubs acceptable Also reportable under Part 21
MILLS,L M Tennessee Valley Authority 84/08/03 O'REILLY,J P Region 2, Office of Director 2pp 26108 224 24X Fiche 50-438,84/08/03,8408160066

8408160249 Notification of 840829 meeting w/C-E Owners Group Operations Subcommittee in Bethesda,MD to discuss task analysis requirement of Suppl 1 to NUREG-0737 & Generic Ltr 82-33 & portions of CEN-152,Rev 2 re inadequate core cooling
CLAYTON,H B Procedures & Systems Review Branch GL-82-33 84/08/09 ZIEMANN,D L Procedures & Systems Review Branch 5pp 26126 248

8408160371 Forwards nonproprietary WCAP-10566 & proprietary WCAP-10567, "Technical Bases for Eliminating Large Primary Loop Pipe Rupture ," per Generic Ltr 84-04 & application for withholding info Proprietary rept withheld (ref 10CFR2 790)
DE VINCENTIS,J Yankee Atomic Electric Co DE VINCENTIS,J Public Service Co of New Hampshire GL-84-04 84/08/09 KNIGHTON,G W Licensing Branch 3 2pp 26091 099 24X Fiche 50-443,84/08/09, 8408160371

8408160373 Requests withholding of stated proprietary rept from public disclosure (ref 10CFR2 790) Affidavit CAW-83-80 encl
WIESEMANN,R A Westinghouse Electric Corp CAW-84-94 84/06/07
DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 26091 101 24X Fiche 50-443,84/08/09,8408160371

-8408160378 WCAP-10566
Nonproprietary "Technical Bases For Eliminating Large Primary Loop Pipe Rupture as Structural Design Basis for Seabrook Units 1 & 2 " Info deleted (ref 10CFR2 790)
SWAMY,S A , CLARK,H F , LEE,Y S Westinghouse Electric Corp 84/06/30 40pp 26091 107 24X Fiche 50-443,84/08/09,8408160371

8408160374 Forwards proprietary "Conceptual Design Description for Pilgrim Nuclear Power Station Emergency & Plant Info Computer (EPIC) Safety Parameter Display Sys (SPDS)," per 831026 commitment & TMI Action Item I D 2 Rept withheld
HARRINGTON,W D Boston Edison Co BECO 84-133 84/08/10
VASSALLO,D B Operating Reactors Branch 2 1p 26091 192 24X Fiche 50-293,84/08/10,8408160374

8408160377 Forwards proprietary NEDE-24284-PA & nonproprietary NEDO-24284-A, "Assessment of Fuel Rod Bowing in GE BWRs " Affidavit for withholding proprietary version encl
CAW 790)
General Electric Co MFN-106-84 84/07/27 THOMAS,C O tion & Special Projects Branch 5pp 26088 225

GE BWRs "
83pp 26088 230

8408160391 Forwards "Design Re iew of Engine Base " Bearing Caps for TDI DSRV-16 Diesel Engines "
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group OGTP-181-N 31 84/08/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26091 147 24X Fiche 50-000,84/08/10, 8408160394

--8408160403 FAAA-84-6-53
"Design Review of Engine Base " Bearing Caps for TDI DSRV-16 Diesel Engines "
" Failure Analysis Associates PA07596 84/08/31 44pp 26091 149 24X Fiche 50-000,84/08/10,8408160394

8408160395 Forwards "Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets," representing final QA verified rept Addl copy forwarded to BNWL,per NRC request
RAY,C L TDI (Transamerica Delaval, Inc) Owners Group OGTP-190-N-33 84/08/14 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26088 163 24X Fiche 50-000,84/08/14, 8408160395

--8408160397 FAAA-84-5-7
"Design Review of Elliott Model 900 Turbocharger Used on TDI DSR-48 & DSRV-16 Emergency Diesel Generator Sets "
" Failure Analysis Associates 84/07/31 61pp 26088 165 24X Fiche 50-000,84/08/14,8408160395

8408160409 Ack receipt of 840703 ltr denying C-E Owners Group 840508 request for relief from NRC review fee on CEN-152 Addl info re further actions on review fee will be forwarded following C-E Owners Group 840920 meeting
WELLS,R W C-E Operating Plants Owners Group WELLS,R W Northeast Utilities RHW-84-61 84/08/09 MILLER,W O License Fee Management Branch 1p 26085 360

8408160461 Dockets Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan," w/WC Wheadon & DM Dawson 830329 & 0210 ltrs,respectively,to assure docket file complete due to rev & resubmittal of rept as Rev 8
ROBERTS,J P Advanced Fuel " Spent Fuel Licensing Branch 84/08/10
Advanced Fuel & Spent Fuel Licensing Branch 1p 26126 078

--8408160466 Forwards Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan " Rev due to organizational change within spent fuel svcs operation & GE U Mgt Corp
WHEADON,W C General Electric Co 83/03/29 ROBERTS,J P NRC - No Detailed Affiliation Given 1p 26126 079

--8408160472 Forwards Rev 7 to NEDO-20776, "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan," referenced in License SNM-2500 for GE Morris Operation & incorporated in NEDO-21326,App B-8
DAWSON,D M General Electric Co DMD-709 83/02/10 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 1p 26126 080

8408160485 Forwards IE Insp Rept 50-445/84-15 on 840301-0430 & notice of deviation
BANGART,R L Region 4, Office of Director 84/07/30 SPENCE,M D Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 26107 296 24X Fiche 50-445,84/07/30,8408160485

--8408160500 IE Insp Rept 50-445/84-15 on 840301-0430 Deviation noted failure to provide review & approval for safety-related maint instructions,per Rev 2 to Reg Guide 1 33
KELLEY,D L , SMITH,W F , HUNNICUTT,D M Region 4, Office of Director 84/07/27 11pp 26107 300 24X Fiche 50-445,84/07/30, 8408160485

8408160517 Significant Deficiency Rept SD 413-414/84-18 re residual stress in Type AN piston skirts of TDI diesels Initially reported on 840628 Skirt cracks being evaluated Next rept by 850115
TUCKER,H B Duke Power Co 84/07/27 O'REILLY,J P Region 2, Office of Director 3pp 26108 012 24X Fiche 50-413,84/07/27, 8408160517

8408170252 Forwards Rev 1 to NEDO-30477, "Safety Analysis of RHR Intertie Line,Monticello Nuclear Generating Plant " Rev suppls 840529 application to amend License DPR-22
MUSOLF,D Northern States Power Co 84/08/16 Office of Nuclear Reactor Regulation, Director 1p 26118 103 24X Fiche 50-263,84/08/16,8408170252

--8408170262 NEDO-30477 R01
Rev 1 to, "Safety Analysis of RHR Intertie Line,Monticello Nuclear Generating Plant "
BRANDON,R J , ORIDLEY,R L General Electric Co 84/06/30 27pp 26118 104 24X Fiche 50-263,84/08/16,8408170252

8408170336 Forwards QE Design Memos 170-107 & 170-109 & Bechtel Stress Rept Calculation SR10R55-S527 re stiff pipe clamps described in IE Info Notice 83-80 Submittal addresses draft SER Open Item 96
MITTL R L Public Service Electric & Gas Co of New Jersey
IEIN-83-80 84/08/14 SCHWENCER,A Licensing Branch 2 2pp
26114 062 24X Fiche 50-354,84/08/14,8408170336

--8408170339 170-107
"Clamp Induced Stress on Hope Creek Recirculation Piping "
FARRELL,C A , ZALIZNIAK,M , THOMPSON,J L General Electric Co
84/07/27 18pp 26114 064 24X Fiche 50-354,84/08/14,8408170336

--8408170342 170-109
Clamp Induced Stress on Hope Creek Main Steam Piping Lines C & D
ZALIZNYAK,M A , FARRELL,C A , THOMPSON,J L General Electric Co
84/07/27 22pp 26114 082 24X Fiche 50-354,84/08/14,8408170336

8408200322 Final Deficiency Rept DER 83-61 re C-E low pressure safety injection pump failure to start & produce required head Case wear rings replaced & clearance between impeller & casing increased Proprietary CEN-289 (V)-P encl
VAN BRUNT,E E Arizona Public Service Co ANPP-30134-TDS/
84/08/09 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs 40pp 26133 318 24X Fiche 50-528,84/08/09,8408200322

8408200481 Forwards SER re reliability of diesel generators Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 175 OL 84/08/14 GUILD,R
Palmetto Alliance RILEY,J L Carolina Environmental Study Group
11pp 26136 307 24X Fiche 50-413,84/08/14,8408200481

8408200499 Forwards addl info re NRC witnesses on intervenor diesel generator contention & two addl comments Related correspondence
JOHNSON,G E Hearing Branch 4 DSB 172 OL 84/08/15 GUILD,R
Palmetto Alliance RILEY,J L Carolina Environmental Study Group
1p 26137 001 24X Fiche 50-413,84/08/15,8408200499

--8408200511 Supplemental responses to Palmetto Alliance & Carolina Environ Study Group 840318 general interrogatories Certificate of Svc encl Related correspondence
JOHNSON,G E Hearing Branch 4 OL 84/08/15 Palmetto
Alliance 15pp 26137 002 24X Fiche 50-413,84/08/15,8408200499

8408210311 Forwards Rev 5 to QA program description for design & const phases Includes revs to Bechtel & Ebasco programs
OPREA,O W Houston Lighting & Power Co ST-HL-AE-1019 83/11/01
COLLINS,J T Region 4, Office of Director 9pp 26179 001 24X
Fiche 50-498,83/11/01,8408210311

--8408210317 Rev 5 to QA program for design & const of South Texas Project
* Houston Lighting & Power Co 83/11/01 54pp 26179 006 24X
Fiche 50-498,83/11/01,8408210311

8408210365 Forwards "Torsiograph Test of Emergency Diesel Generator 1A at Catawba Nuclear Power Station," in response to 840809 telcon request Start 61 should show run duration of 35 h rather than 43
TUCKER,H B Duke Power Co 84/08/14 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 3pp 26178 175 24X Fiche 50-413,84/08/14,8408210365

--8408210370 FAAA-84-5-23
"Torsiograph Test of Emergency Diesel Generator 1A at Catawba Nuclear Power Station "
* Failure Analysis Associates PA07702 84/05/29 19pp
26178 178 24X Fiche 50-413,84/08/14,8408210365

8408210375 Forwards B&W summary technical repts of first capsule from reactor vessel surveillance program,per App H of 10CFR50 Repts delayed due to administrative oversight
STEWART,W L Virginia Electric & Power Co 479 84/08/16
DENTON,H R Office of Nuclear Reactor Regulation, Director 1p
26178 001 24X Fiche 50-338,84/08/16,8408210375

--8408210387 BAW-1794
"Analysis of Capsule V,VEPCO,North Anna Unit 2,Reactor Vessel Matls Surveillance Program "
LOWE,A L , COLLINS,L L , PAVINICH,W A Babcock & Wilcox Co
83/10/31 173pp 26178 002 24X Fiche 50-338,84/08/16,
8408210375

--8408210393 BAW-1638
"Analysis of Capsule V,VEPCO,North Anna Unit 1,Reactor Vessel Matls Surveillance Program "
LOWE,A L , PAVINICH,W A , SCHMOTZER,J K Babcock & Wilcox Co
81/05/31 76pp 26178 099 24X Fiche 50-338,84/08/16,8408210375

8408210376 Forwards final Containment Issue Review Panel rept "Assessment of Humphrey Concerns," technical memo
ENGLAND,L A Containment Issues Owners Group ENGLAND,L A Gulf States Utilities Co LAE-OG-121 84/07/27 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 26180 001

--8408210382 TM-928
"Assessment of Humphrey Concerns," technical memo
PATEL,B R Containment Issues Owners Group PATEL,B R Creare, Inc HENNESSY,W P Stone & Webster Engineering Corp 84/07/31
186pp 26180 003

8408210486 Forwards 'Emergency Response Guidelines Comparison of Rev 1 w/Basic," per NRC 840620 request for addl info
SHEPPARD,J J Westinghouse Operating Plants Owners Group
SHEPPARD,J J Carolina Power & Light Co OG-132 84/08/15
EISENHUT,D G Division of Licensing 4pp 26177 206

--8408210489 "Emergency Response Guidelines Comparison of Rev 1 W/Basic "
* Westinghouse Electric Corp 84/08/15 21pp 26177 210

8408210500 Forwards Rev 6 to QA program description for design & const phase of facilities Changes clarify definition of Bechtel div quality policies & defines responsibilities for trend analysis
OPREA,O W Houston Lighting & Power Co ST-HL-AE-1077 84/04/02
COLLINS,J T Region 4, Office of Director 3pp 26148 175 24X
Fiche 50-498,84/04/02,8408210500

--8408210503 Rev 6 to QA program description for design & const of facilities
* Houston Lighting & Power Co 84/04/02 190pp 26148 178 24X
Fiche 50-498,84/04/02,8408210500

8408220544 Summary of 840801 meeting w/BWR Owners Group Subcommittee on Emergency Procedures & GE re open items in SER concerning emergency procedure guidelines List of attendees encl
MCCOY,M A Procedures & Systems Review Branch 84/08/16
ZIEMANN,D L Procedures & Systems Review Branch 12pp 26199 342

8408230041 Ack receipt of nonproprietary & proprietary STD-R-03-008, "Hittman RADLOK High Integrity Containers," transmitted on 840628 Tentative schedule for review of rept encl
TIKTINSKY,D H Engineering Branch (Post 831001) 84/08/14
LEDUC,R J Westinghouse Hittman Nuclear, Inc 2pp 26233 331

8408230051 Forwards response to TDI emergency diesel generator issues raised by NRC & Battelle personnel during 840726 visit Identification of cylinder heads addressed
TUCKER,H B Duke Power Co 84/08/08 DENTON,H R Office of
Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 4pp 26204 014 24X Fiche 50-413,84/08/08,8408230051

8408230069 Requests review & comments on encl Westinghouse Hittman STD-R-03-008, "Hittman RADLOK High Integrity Containers," by 841102 Encl withheld
BARRETT,L H Engineering Branch (Post 831001) 84/08/15
COSTANZI,F A Division of Waste Management 1p 26233 272

8408230084 Forwards responses to questions re BAW-10155 "FOAM2," submitted on behalf of B&W Owners Group as part of small break LOCA methods program response to NUREG-0565 & NUREG-0737, Item II K 3 30
TAYLOR,J H Babcock & Wilcox Co ESC-535 84/08/15 THOMAS,C O
Standardization & Special Projects Branch 14pp 26209 041

8408230093 Forwards XN NF-84-72,Suppl 1, "Large Break LOCA-ECCS Analysis W/Increased Enthalpy Rise Factor Break Spectrum " Info submitted to suppl request for license amend for Cycle 10 operation
CUTLER,A B Carolina Power & Light Co NLS-84-378 84/08/20
VARGA,S A Operating Reactors Branch 1 2pp 26208 082 24X
Fiche 50-261,84/08/20,8408230093

--8408230103 XN-NF-84-72 S01
"Large Break LOCA-ECCS Analysis W/Increased Enthalpy Rise Factor Break Spectrum "
TAHVILI,T , KAYSER,W V , CHANDLER,J C Exxon Nuclear Co , Inc
(subs of Exxon Corp) 84/08/31 102pp 26208 084 24X
Fiche 50-261,84/08/20,8408230093

8408230109 Forwards discussion of containment thermal insulation safety issues considered for Owens-Corning NUKON insulation (Topical Rept OCF-1) Issues should be included in NRC review process
PINSKY,G P Owens-Corning Fiberglas Corp 84/08/17 DENTON,H R
Office of Nuclear Reactor Regulation, Director THOMAS,C O NRC -
No Detailed Affiliation Given 6pp 26209 055

8408230117 Forwards XN-NF-84-74, "Plant Transient Analysis for HB Robinson Unit 2 at 2,300 MWt W/Increased FN(Delta)H "
CUTTER, A B Carolina Power & Light Co NLS-84-381 84/08/20
VARGA, S A Operating Reactors Branch 1 2pp 26208 187 24X
Fiche 50-261, 84/08/20, 8408230117

--8408230122 XN-NF-84-74
"Plant Transient Analysis for HB Robinson Unit 2 at 2,300 MWt W/Increased FN(Delta)H "
LEACH, C E , ADAMS, F T , KILLGORE, M R Exxon Nuclear Co , Inc (subs of Exxon Corp) 84/08/16 200pp 26208 189 24X
Fiche 50-261, 84/08/20, 8408230117

8408230263 Forwards XN-NF-83-61, "DC Cook Unit 1 LOCA-ECCS Analysis for Extended Exposure" & proprietary XN-NF-84-25(P), "Mechanical Design Rept Suppl for DC Cook Unit 1 Extended Burnup Fuel Assemblies " Proprietary rept withheld
CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp) 84/08/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 26204 028 24X Fiche 50-315, 84/08/21, 8408230263

--8408230266 XN-NF-83-61
"DC Cook Unit 1 LOCA-ECCS Analysis for Extended Exposure "
TAHVILI, T , KAYSER, W V , STOUT, R B Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/08/03 33pp 26204 033 24X
Fiche 50-315, 84/08/21, 8408230263

8408230340 Forwards proprietary draft answers to questions in NRC Request 2 for addl info on WCAP-10054(P) & WCAP-10054, Addendum 1 to "Westinghouse Small Break ECCS Evaluation Model Using NOTRUMP Code" For C-E NSSS "
RAHE, E P Westinghouse Electric Corp NS-EPR-2940 84/08/10
THOMAS, C O NRC - No Detailed Affiliation Given 3pp 26205 350

--8408230346 Requests proprietary draft answers to questions in NRC Request 2 for addl info on WCAP-10054(P) & WCAP-10054, Addendum 1 "Westinghouse Small Break ECCS Evaluation Model Using NOTRUMP Code," be withheld (ref 10CFR2 790)
WIESEMANN, R A Westinghouse Electric Corp AW-84-74 84/08/10
THOMAS, C O NRC - No Detailed Affiliation Given 1p 26205 353

8408240115 Forwards SER re TDI Owners Group program plan SER addresses design review/quality revalidation program, testing & insp, maint & surveillance & sets forth requirements for operation prior to completion of program plan
EISENHUT, D G Division of Licensing 84/08/13 GEORGE, J B TDI (Transamerica Delaval, Inc) Owners Group 1p 26255 194 24X
Fiche 50-000, 84/08/13, 8408240115

--8408240157 Safety evaluation of TDI Owners Group program plan Based on BNWL evaluation, plan incorporates essential elements needed to resolve outstanding concerns re reliability of TDI engines for nuclear svc
* NRC - No Detailed Affiliation Given 84/08/13 21pp
26255 195 24X Fiche 50-000, 84/08/13, 8408240115

8408240122 Forwards proprietary responses to 840326 request for addl info re NEDE-22148 concerning extended burnup application Responses withheld (ref 10CFR2 790)
CHARNLEY, J S General Electric Co MFN-120-84 84/08/16
THOMAS, C O Standardization & Special Projects Branch 1p
26227 313

8408240268 Forwards proprietary responses to four technical questions re XN-NF-75-21(P), "XCOBRA-IIIC Computer Code to Determine Distribution of Coolant During Steady State & Transient Core Operation " Response withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp) 84/08/17 THOMAS, C O Standardization & Special Projects Branch 1p 26223 185

8408240426 Interim Deficiency Rept DR-220 re license indications on valve seats of cylinder leads in standby diesel generators supplied by TDI Interim or final status rept will be submitted by 841101
BOOKER, J E Gulf States Utilities Co DR-220 84/08/13
COLLINS, J T Region 4, Office of Director 1p 26237 120 24X
Fiche 50-458, 84/08/13, 8408240426

8408270065 Forwards Insp Repts 50-445/84-17 re disassembly, insp & reassembly of TDI emergency diesel generator, 50-445/84-05 re allegations on fabrication of pipe supports & restraints & 50-445/84-10 re walkdown Related correspondence
MIZUNO, G S Hearing Branch 1 DSB 304 OL 84/08/16 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 26247 069 24X
Fiche 50-445, 84/08/16, 8408270065

8408270098 Forwards response to NRC 831229 ltr re TDI emergency diesel generators Includes procurement & performance specs & insp results
SHELL, R H Tennessee Valley Authority 84/08/17 ADENSAM, E G Licensing Branch 4 167pp 26248 032 24X Fiche 50-438, 84/08/17, 8408270098

8408270109 Forwards SER re TDI Diesel Generator Owners Group program plan W/o encl Related correspondence
JOHNSON, G E Hearing Branch 4 DSB 310 OL 84/08/20
KELLEY, J L , PURDOM, P W , FOSTER, R F Atomic Safety and Licensing Board Panel 1p 26247 325 24X Fiche 50-413, 84/08/20, 8408270109

8408270122 Forwards SER re TDI Diesel Generator Owners Group program plan Rept discussed during 840810 conference call Related correspondence
MOORE, J F Hearing Branch 1 DSB 308 OL 84/08/21 KELLEY, J L , CARPENTER, J H , BRIGHT, G O Atomic Safety and Licensing Board Panel 50pp 26248 002 24X Fiche 50-400, 84/08/21, 8408270122

8408270137 Motion for extension of time until 840831 to file direct testimony, as opposed to presently scheduled date of 840821 Related correspondence
GODDARD, R J Hearing Branch 3 DSB 314 OL 84/08/17 Atomic Safety and Licensing Board Panel 2pp 26245 213 24X
Fiche 50-322, 84/08/17, 8408270137

--8408270143 Affidavit of R Caruso supporting NRC motion for extension of time to file testimony re TDI emergency diesel generators Certificate of Svc encl Related correspondence
CARUSO, R Division of Licensing OL 84/08/17 7pp 26245 215
24X Fiche 50-322, 84/08/17, 8408270137

8408270155 Requests exemption to revise 10CFR170 license fee schedule re GESSAR II review Exemption to schedule appropriate since review of GESSAR II design committed under regulations & policies in existence in early 1982
SHERWOOD, G G General Electric Co MFN#115-84 84/08/10
DIRCKS, W J Office of the Executive Director for Operations 2pp
26245 222 24X Fiche 50-447, 84/08/10, 8408270155

8408270159 Informs that fee sent to Licensing Fee Mgt Branch for review & acceptance of 840724 request to extend use of burnable poison rod assembly retainers for four 18-month fuel cycles
TAYLOR, J H Babcock & Wilcox Co ESC-537 84/08/20 THOMAS, C O Standardization & Special Projects Branch 1p 26245 258

8408270167 Application to amend License DPR-49, revising Tech Specs to allow power uprate to 1,658 MWt Approval requested prior to startup for Cycle 8 Forwards NEDO-30603 & NEDC-30603-P
NEDC-30603-P withheld (ref 10CFR2 790) Fee paid
MCGAUGHY, R W Iowa Electric Light & Power Co NG-84F-2518
84/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 20pp 26244 081 24X Fiche 50-331, 84/08/17, 8408270167

--8408270175 NEDO-30603
"D Arnold Power Uprate "
BRANDON, R J , GRIDLEY, R L General Electric Co 84/07/31 33pp
26244 153 24X Fiche 50-331, 84/08/17, 8408270167

8408270312 Documents changes to computer codes compromising 1981 ECCS evaluation model described in Rev 1 to WCAP-9220-P-A Impacted computer codes are SATAN, COCO & LOCTA Westinghouse plants need reanalysis, per 10CFR50 46
RAHE, E P Westinghouse Electric Corp NS-EPR-2952 84/08/14
THOMAS, C O Standardization & Special Projects Branch 8pp
26242 349

8408270409 Forwards proprietary & nonproprietary Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept," Rev 0 to "CPC/CEAC Sys Phase II ," & Rev 0 to "SONGS-2 Cycle 1 " Proprietary repts withheld (ref 10CFR2 790)
MEDFORD, M O Southern California Edison Co 84/08/01
KNIGHTON, G W Licensing Branch 1 2pp 26238 001 24X
Fiche 50-361, 84/08/01, 8408270409

--8408270412 CEN-269(S)-NP R00
Nonproprietary version of Rev 0 to "CPC/CEAC Sys Phase II Software Verification Test Rept "
* Combustion Engineering, Inc 84/03/31 25pp 26238 003 24X
Fiche 50-361, 84/08/01, 8408270409

--8408270416 CEN-266(S)-NP R00
Nonproprietary version of Rev 0 to "SONGS-2 Cycle 1, CPC & CEAC Data Base "
* Combustion Engineering, Inc 84/03/31 66pp 26238 029 24X
Fiche 50-361, 84/08/01, 8408270409

--8408270418 CEN-176(S)-NP R02
Nonproprietary version of Rev 2 to "CPC/CEAC Sys Phase I Software Verification Test Rept "
* Combustion Engineering, Inc 84/03/31 27pp 26238 096 24X
Fiche 50-361, 84/08/01, 8408270409

08270449 Requests review & comments on plan to analyze addl gravity reload tests as part of BASH code verification & assessment of App K conservatism Comparison methodology listed
RAHE E P Westinghouse Electric Corp NS-EPR-84-2953 84/08/17
LANGFORD D Reactor Systems Branch BUXTON L Sandia Laboratories
5pp 26238 128

08270559 Notification of 840824 meeting w/Westinghouse Owners Group in Bethesda, MD to discuss SER inputs
BRINKMAN D S Standardization & Special Projects Branch 84/08/17
THOMAS C O Standardization & Special Projects Branch 3pp
26277 263

08280109 Forwards outline of actions required to insure reliability of TDI V-20 diesel engines prior to restart, in response to 840629 summary of operating experience, insp results & analysis results
BERLINGER C H Division of Licensing 84/08/20 GRIMES C I
Systematic Evaluation Program Branch 11pp 26294 141 24X
Fiche 50-206, 84/08/20, 8408280109

08280122 Forwards application fee for XN-NF-84-67(P), "Stability Evaluation Methodology for BWR Cores," per 10CFR170
CHANDLER J C Exxon Nuclear Co, Inc (subs of Exxon Corp)
JCC 112 84 84/08/15 MILLER W O License Fee Management Branch
1p 26261 125

08280202 Application for amend to License DPR-49, revising Tech Specs re operating limits of new bundle types, LOCA design basis, MAPLHGR & min critical power ratio for Cycle 8 reload
MCGAUGHY R W Iowa Electric Light & Power Co NG-84-3525
84/08/17 DENTON H R Office of Nuclear Reactor Regulation, Director 5pp 26264 057 24X Fiche 50-331, 84/08/17, 8408280202

8408280209 NEDO-21082-03 APP A
App A to "LOCA Analysis Rept for Duane Arnold Energy Ctr (Lead Plant)"
* General Electric Co 84/06/30 46pp 26264 091 24X
Fiche 50-331, 84/08/17, 8408280202

8408280211 23A1739 R00
Rev 0 to "Supplemental Reload Licensing Submittal for Duane Arnold Atomic Energy Ctr, Unit 1, Reload 7"
LAMBERT P A General Electric Co 84/06/30 22pp 26264 138
24X Fiche 50-331, 84/08/17, 8408280202

08280205 Testimony of ON Hallman, RP Muschick, SR Ward, JA Gorman, CA Wells, LA Svanger, SK Chen, JD Barbour, JM Curtis & RC Oamberg re problems encountered in diesel generator qualification program Related correspondence
HALLMAN G W, MUSCHICK R P, WARD S R Duke Power Co DSB 322 OL
84/08/18 444pp 26271 316 24X Fiche 50-413, 84/08/18, 8408280205

08280212 Forwards proprietary responses to Round Two questions on Rev 2 to XN-74-5, "Description of Exxon Nuclear Plant Transient Simulation Model for PWRs, (PTSPWR)" Responses withheld (ref 10CFR2 790)
CHANDLER J C Exxon Nuclear Co, Inc (subs of Exxon Corp)
JCC 111 84 84/08/14 THOMAS C O Standardization & Special Projects Branch 1p 26264 066

08280220 Application for amend to License DPR-52, changing Tech Specs to accommodate Unit 2 Cycle 6 operation & reflecting plant mods to be performed during refueling outage
MILLS L M Tennessee Valley Authority 84/08/23 DENTON H R
Office of Nuclear Reactor Regulation, Director 3pp 26269 201
24X Fiche 50-260, 84/08/23, 8408280220

8408280226 TVA RLR-002
"Reload Licensing Rept for Browns Ferry Unit 2 Cycle 6"
Determination of no significant hazards encl
* Tennessee Valley Authority 84/07/31 38pp 26269 282 24X
Fiche 50-260, 84/08/23, 8408280220

08280259 Forwards "Westinghouse Position on Damping Values for Nuclear Power Plant Piping" Provides justification for use of higher damping values, defines intended applications for values & requests NRC approval of position
RAHE E P Westinghouse Electric Corp NS-EPR-84-2955 84/08/16
KNIGHT J P Assistant Director for Comp & Structures Engineering
(Post 830201) 2pp 26262 047

-8408280260 "Westinghouse Position on Damping Values for Nuclear Power Plant Piping"
* Westinghouse Electric Corp 84/08/16 21pp 26262 049

08280265 Response to ASLB 840615 request for addl info re TDI diesel generators ASLB should conclude that TDI QA program adequate at all times Related correspondence
REYNOLDS N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) REYNOLDS N S Bishop, Liberman, Cook, Purcell & Reynolds DSB 334 OL 84/08/25 29pp 26262 008 24X
Fiche 50-445, 84/08/25, 8408280265

--8408280268 Affidavit of EJ Kreh re evaluation of TDI QA program TDI QA program acceptable prior to Jul 1980 discovery of auxiliary skid deficiency Prof qualifications & Certificate of Svc encl Related correspondence
KREH E J O'Donnell & Associates, Inc OL 84/08/24 10pp
26262 037 24X Fiche 50-445, 84/08/25, 8408280265

8408280424 Informs that staff proposed witnesses include C Berlinger, SJ Bush, AJ Henriksen, WW Laity & A Sarsten, per ASLB 840821 memorandum & order Prof qualifications of witnesses & Certificate of Svc encl Related correspondence
GODDARD R J Hearing Branch 3 DSB 339 OL 84/08/24
BRENNER L, MORRIS P A, FERGUSON G A Atomic Safety and Licensing Board Panel 72pp 26280 218 24X Fiche 50-322, 84/08/24, 8408280424

8408280461 Notifies that CAW-84-9 re setpoint methodology for reactor protection sys is proprietary & will be withheld from public disclosure per 10CFR2 790
YOUNGBLOOD B J Licensing Branch 1 84/08/22 WIESEMANN R A
Westinghouse Electric Corp 3pp 26292 337 24X
Fiche 50-445, 84/08/22, 8408280461

8408290179 Forwards response to 840723 request for addl info on repts submitted by TDI Diesel Generator Owners Group
RAY C L TDI (Transamerica Delaval, Inc) Owners Group
OGTP-218-N-34 84/08/23 BERLINGER C Office of Nuclear Reactor Regulation, Director 12pp 26289 221 24X Fiche 50-000, 84/08/23, 8408290179

8408290288 Forwards responses to 840131 questions re TDI diesel generators Remaining responses will be delayed until completion of TDI Owners Group site-specific DR/GR repts, Phase 1 disassembly & insp, Phase 2 testing & Phase 3 insp
RODRIGUEZ R J Sacramento Municipal Utility District RJR 84-336
84/08/24 STOLZ J F Operating Reactors Branch 4 15pp
26291 161 24X Fiche 50-312, 84/08/24, 8408290288

8408300141 Requests formal withdrawal of Rev 3 to BAW-10084, "Program to Determine In-Reactor Performance of B&W Fuels Cladding Creep Collapse" Rept will be revised to include info on small gap collapse & new modeling techniques
TAYLOR J H Babcock & Wilcox Co ESC-555 84/08/27 THOMAS C O
Standardization & Special Projects Branch 1p 26300 137

8408300232 Forwards description of program to implement TDI diesel insp requirements for restart & methods used to determine ESF loads, per 840726 request Program covers insps, tests & maint & surveillance activities
MEDFORD M O Southern California Edison Co 84/08/28 PAULSON W A
Operating Reactors Branch 5 12pp 26300 111 24X
Fiche 50-206, 84/08/28, 8408300232

8408310108 Concurs in implementation of criteria for evaluating personnel capability in sizing IGSCC, per 840807 ltr Meeting to review application of criteria & addl results appropriate
DEYOUNG R C Director's Office, Office of Inspection and Enforcement 84/08/24 NEILS G H Northern States Power Co 2pp
26352 032

--8408310112 Forwards proposed grading criteria for IGSCC depth sizing course developed & offered by EPRI NDE Ctr Concurrence requested
NEILS G H Northern States Power Co 84/08/07 DEYOUNG R C
Director's Office, Office of Inspection and Enforcement 4pp.
26352 034

8408310195 Forwards proprietary Rev 2, Suppl 4 to XN-74-5(P), "Description of Exxon Nuclear Plant Transient Simulation Model for PWRs" Rept withheld (ref 10CFR2 790)
CHANDLER J C Exxon Nuclear Co, Inc (subs of Exxon Corp)
JCC-119-84 84/08/29 THOMAS C O Standardization & Special Projects Branch 1p 26316 292

8408310205 Expresses disagreement w/conclusions expressed in util, BNWL & NRC staff repts re reliability of TDI emergency diesel generators Pattern of deficiencies exists which precludes findings Related correspondence
GUILD R Guild, R GUILD R Palmetto Alliance GUILD R Carolina Environmental Study Group DSB 430 OL 84/08/16 KELLEY J L, PURDOM P W, FOSTER R F Atomic Safety and Licensing Board Panel 193pp 26317 228 24X Fiche 50-413, 84/08/16, 8408310205

8408310345 Advises of completion of review & forwards evaluation re BAW-10129, "Lynx 1 - Reactor Fuel Assembly Thermal Hydraulic Analysis Code" Rept acceptable for referencing in license applications to extent specified
THOMAS C O Standardization & Special Projects Branch 84/08/23
TAYLOR J H Babcock & Wilcox Co 4pp [illegible] 048

--8408090124 Topical rept evaluation of BAW-10129, "LYNX 1 - Reactor Fuel Assembly Thermal Hydraulic Analysis Code" & BAW-10130, "LYNX 2 - Subchannel Thermal Hydraulic Analysis Program Repts acceptable
* Core Performance Branch TAC 4338 84/07/31 6pp 26352 052

WASTE MGT NUCLEAR WASTE MANAGEMENT

8406190514 Trip rept of 840418-19 site visit re DOE UMTRAP mid-yr review Viewgraphs encl
GNUGNOLI,G N Low-Level Waste & Uranium Recovery Projects Branch 84/04/27 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 85pp 25037 001

8406210504 Agenda for Nuclear Waste Board 840509 meeting in Olympia, WA Map encl
* Washington, State of 800 84/05/09 Washington, State of 4pp 25093 005

8408010043 Submits comments on Science Advisory Board review of proposed EPA stds for mgt & disposal of spent nuclear fuel, high level & transuranic radwastes NRC does not consider increased proposed release limits necessary
BROWNING,R E Division of Waste Management 84/07/06 Environmental Protection Agency 6pp 25866 341

8408010046 Forwards "FES Remedial Actions at Former Vitro Chemical Co Site,South Salt Lake City,Salt Lake County,UT "
MORLEY,J A Energy, Dept of 84/07/13 Affiliation Not Assigned 1p 25868 001

--8408010053 DOE/EIS-0099-F
"FES Remedial Actions at Former Vitro Chemical Co Site,South Salt Lake,Salt Lake County,UT Vol I - Text "
* Energy, Dept of 84/07/31 501pp 25868 002

--8408010063 DOE/EIS-0099-F
"FES Remedial Actions at Former Vitro Chemical Co,South Salt Lake,Salt Lake County,UT Vol II - Apps "
* Energy, Dept of 84/07/31 398pp 25869 143

8408010064 Forwards revised "UMTRA Project Environ,Health & Safety Plan," incorporating NRC comments
MORLEY,J A Energy, Dept of 84/07/17 HIGGINBOTHAM Low-Level Waste & Uranium Recovery Projects Branch 2pp 25897 238

--8408010072 "UMTRA Project Environ,Health & Safety Plan "
* Energy, Dept of 84/06/30 2pp 25897 240

8010070 Provides Salt Repository Project site rept for wk of 840709
CAHA,T R NRC - No Detailed Affiliation Given 610 84/07/16
BOWNING,R E Division of Waste Management 1p 25897 237

8010079 Forwards, for review, draft Paradox STP-1 O, "Site Technical osition Groundwater Issues for Paradox Bedded Salt Basin" & draft Palo Duro STP-1 O, "Site Technical Position Groundwater Issues for Palo Duro Bedded Salt Basin "
KNAPP,M R Geotechnical Branch (Post 831001) 611 84/07/19
BROWNING,R E Division of Waste Management 1p 25897 196

-8408010083 PARADOX STP-1 O DRFT
Draft "Site Technical Position Groundwater Issues for Paradox Bedded Salt Basin "
* Division of Waste Management 84/07/31 14pp 25897 197

--8408010088 PALO DURO STP-1 O DR
Draft "Site Technical Position Groundwater Issues for Palo Duro Bedded Salt Basin "
* Division of Waste Management 84/07/31 14pp 25897 211

8408010114 Submits comments comprising Confederated Tribes of Umatilla Indian Reservation input on draft mission plan
PATAWA,E H Confederated Tribes of Umatilla Indian Reservation 906 84/07/16 HEAD,C R Energy, Dept of 2pp 25873 334

8408010123 Forwards viewgraphs from Attachment 4 to summary meeting notes of 840109-12 workshop on geochemistry DOE sources & refs requested for each viewgraph
WRIGHT,R J Repository Projects Branch (Post 831001) 909 84/07/13 OLSON,O L Energy, Dept of 266pp 25873 001

8408010193 Summary of 840716 meeting w/DOE re establishment of contact w/& briefing by DOE on plans for project decision schedule Copies of advanced draft provided DOE plans to issue draft project decision schedule in late Jul
NUMARK,N J Policy & Program Control Branch (Post 831001) 84/07/16 Policy & Program Control Branch (Post 831001) 2pp 25873 286

8408010377 Trip rept of 840618-20 visits to Edgemont SD for meetings w/town council & homeowners on DOE remedial action program
FLORY,C A Low-Level Waste & Uranium Recovery Projects Branch 84/06/28 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 2pp 25872 312

8408010361 Forwards Title I review documentation for Salt Lake City, Shiprock & Canonsburg remedial action plans W/o encls
MARTIN,D E Low-Level Waste & Uranium Recovery Projects Branch 84/07/10 SMITH,D Uranium Recovery Field Office 1p 25872 359

8408020217 Notifies of time change re Mitsubishi 840712 high integrity container meeting in Bethesda,MD Time changed to 3 pm rather than 2 pm as stated in 840702 memo
JOHNSON,T C Engineering Branch (Post 831001) 84/07/06 BROWNING,R E Division of Waste Management BARRETT,L Engineering Branch (Post 831001) HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 2pp 25898 199

8408020236 DOE/NE-SH01 ERR
Errata to "UMTRAP Radiological Survey of Shiprock Vicinity Property SH01,Shiprock,NM "
* Argonne National Laboratory 84/07/05 2pp 25898 161

--8408020239 DOE/NE-SH02 ERR
Errata to "UMTRAP Radiological Survey of Shiprock Vicinity Property SH02,Shiprock,NM "
* Argonne National Laboratory 84/07/05 1p 25898 163

8408030045 Forwards modeling strategy document for high level waste performance assessment
LINEHAN,J J Repository Projects Branch (Post 831001) 84/07/16
MILLER,H J Repository Projects Branch (Post 831001) 71pp 25920 171

8408030082 Forwards Mod A003 to Cooperative Agreement DE-FC04-81AL16309 w/State of UT Agreement supports UMTRAP in State of UT, per Public Law 95-604
HILL,T V Energy, Dept of 84/06/13 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 84pp 25920 242

8408030084 Forwards "Cooperative Agreement Between DOE & State of OR "
HILL,T V Energy, Dept of 84/07/03 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 38pp 25934 136

8408030092 Forwards, for review & comment, minutes of 840531 meeting w/Salt state representatives re land acquisition, transportation & environ assessments Minutes of 840329-30 meetings w/Salt representatives in Columbus,OH also encl
TAYLOR,T J Energy, Dept of IN 412-84 84/07/17 LINEHAN,J J Repository Projects Branch (Post 831001) 284pp 25921 001

8408030187 Forwards draft "Radiological & Engineering Assessment for Property ED-00270-RS," for review, comment, rev &/or concurrence
ROBERTS,W A Energy, Dept of 84/07/23 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 1p 25934 193

--8408030197 REA00270 REA-E-D-7DR
Draft "Radiological & Engineering Assessment for Property ED-00270-RS "
* Bendix Corp 84/07/31 21pp 25934 194

8408030263 Forwards drafts "Radiological & Engineering Assessment for Property OJ-08742-MR," "Radiological & Engineering Assessment for Property OJ-13716-MR" & "Radiological & Engineering Assessment OJ-00119-MR," for concurrence
TUCKER,M K Energy, Dept of 84/07/16 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 1p 25920 068

--8408030264 REA08742 REA-104/LS
Draft "Radiological & Engineering Assessment for Property OJ-08742-MR " W/Four oversize figures Aperture cards available in PDR
* Bendix Corp 84/06/30 39pp 25920 069

--8408030268 REA13716 REA-7 DRFT
Draft "Radiological & Engineering Assessment for Property OJ-13716-MR " W/five oversize figures Aperture cards available in PDR
* Bendix Corp 84/07/31 34pp 25920 104

--8408030270 REA00119 REA-7 DRFT
Draft "Radiological & Engineering Assessment for Property OJ-00119 MR "
* Bendix Corp 84/06/30 33pp 25920 138

8408030279 Summary of DOE/NRC 840612 & 13 meetings in Gaithersburg,MD re BWIP hydrologic characterization Attendee comments encl
WRIGHT,R J NRC - No Detailed Affiliation Given MECCA,J E Energy, Dept of 00918 84/06/14 NRC - No Detailed Affiliation Given 13pp 25920 050

8408030283 Forwards West Valley Nuclear Svcs,Inc security & safeguards plan Plan should be returned to DOE within 1 yr & should not be duplicated OE will allow Fluor to view plan at Sunnyvale facility
WUNDERLICH R C Energy, Dept of 00615 84/07/18 MALLONEE,T O Fluor Corp 3pp 25919 360

8408060045 Forwards corrected Page 46 from App A to 'ENVIROSTONE Gypsum Cement 10CFR61 Compliance Testing Topical Rept" (USG-684-1P & USG-684-1NP) re mix ratios for ion exchange bead resins solidified w/ENVIROSTONE Gypsum cement
LANDE,R G U S Gypsum Co 84/07/19 HIGGINBOTHAM,L Low Level Waste Licensing Branch 2pp 25937 089

--8408060047 USG-684-1NP ERR
Corrected Page 46 from App A to "ENVIROSTONE Gypsum Cement 10CFR61 Compliance Testing Topical Rept "
* U S Gypsum Co 84/07/19 1p 25937 091

8408060051 Forwards proposed agenda & list of topics beneficial to address in Salt Repository Project Ofc info mgt sys 840803 briefing NRC becoming familiar w/sys in use
LINEHAN,J J Repository Projects Branch (Post 831001) 00618 84/07/24 NEFF,J D Energy, Dept of 3pp 25937 086

8408060059 App 7 to MOU between NRC & DOE re repository projects in site suitability & planning phase
* NRC - No Detailed Affiliation Given * Energy, Dept of 00324 84/07/27 3pp 25937 083

8408060067 Informs of upcoming meetings w/NRC for Jul-Nov 1984 Meeting announcement will be updated weekly
TAYLOR,T J Energy Dept or 00617 84/07/20 LINEHAN,J NRC - No Detailed Affiliation Given FRISHMAN,S Texas, State of FORSYTHE,R Mississippi, State of 2pp 25937 076

8408060106 Forwards draft processing site & disposal site characterization repts for Salt Lake City,UT Repts contain current data re conceptual design analysis Comments requested by 840824
MATTHEWS,M L Energy, Dept of 84/07/20 MARTIN,D Uranium Recovery Licensing Branch 1p 25952 001

--8408060111 UMTRA-DOE/AL-050102
Draft "Disposal Site Characterization Rept for U Mill Tailings Site at Salt Lake City,UT " Two oversize maps encl Aperture cards available in PDR
* Energy, Dept of 84/06/30 155pp 25952 003

--8408060122 UMTRA-DOE/AL 050102
Review draft of "Processing Site Characterization Rept for U Mill Tailings Site at Salt Lake City,UT " Six oversize maps encl Aperture cards available in PDR
* Energy, Dept of 84/06/30 236pp 25952 156

8408060149 Forwards final summary of hydrology data review on 840514-18 in Columbus,OH Summary will be sent to representatives from Salt states & USGS Agenda,attendance list & related info encl
LINEHAN,J J Repository Projects Branch (Post 831001) 614 84/07/09 NEFF,J D Energy, Dept of 20pp 25936 324

8408060163 Forwards revised modeling strategy document for high level waste performance assessment
BROWNING,R E Division of Waste Management 84/07/23 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 70pp 25936 204

8408060173 Suggests that Nevada Nuclear Waste Storage Investigation geology data review be held during wks of 840820 & 27 Requested data listed including calibr of current seismic velocity crustal model
COPLAN,S Repository Projects Branch (Post 831001) 323 84/07/05 VIETH,D Energy, Dept of 2pp 25936 202

8408060178 Comments on Page 82 of House Rept 98-755,agreeing that DOE should have capability to destructively evaluate glass melted at PNNL to determine quality
WICK,E A Engineering Branch (Post 831001) 84/07/16 JOHNSON,T C Engineering Branch (Post 831001) 1p 25936 201

8408060186 Trip rept of Nevada Nuclear Waste Storage Investigation 840710-12 geochemistry workshop,840713 geochemistry/ mineralogy-petrology workshop visit & 840709 program review of Project A-7150
STARMER,R J , VOVACH,L A Geotechnical Branch (Post 831001) FIN A-7150 00325 84/07/26 KNAPP,M R Geotechnical Branch (Post 831001) 38pp 25950 256

8408060225 Forwards listed documents, including NUREG-0170, NUREG/CR-0743, NUREG-0194 & proposed rule for mod of protection requirements for spent fuel shipment, per request W/o encl
RUSSELL,C F Policy & Program Control Branch (Post 831001) 00327 84/07/19 LOUX,R R Nevada, State of 1p 25950 249

8408060242 Forwards K Westbrook 840511 & 0605 memos re 840313-15 BWIP/NRC workshops on geology W/o encls
WRIGHT,R J Repository Projects Branch (Post 831001) 911 84/07/03 OLSON,O L Energy, Dept of 1p 25937 362

8408060252 "Geotechnical Investigation for Bodo Canyon U Mill Tailings Remedial Action Program,Durango Site,Durango,CO "
* Dames & Moore 83/10/20 43pp 25951 298

8408060256 Clarifies response to question re results of drop tests Under conditions consistent w/10CFR61,no evidence of water leakage after drop tests existed
EPSTEIN,G Mitsubishi International Corp (subs of Mitsubishi Corp) WSH-219 84/07/19 JOHNSON,T Division of Waste Management 2pp 25950 345

8408060264 Forwards revised final agenda for seventh bimonthly 840801-02 meetings w/Salt states & NRC in Columbus,OH
TAYLOR,T J Energy, Dept of 84/07/26 LINEHAN,J J Repository Projects Branch (Post 831001) 4pp 25950 341

8408060266 Forwards engineering fact sheet for Alternative 5, reprocessing,per 840717 meeting re forthcoming Durango EIS
PARKER,G E Jacobs Engineering Group, Inc 84/07/19 PENNIFILL,R Low Level Waste Licensing Branch 32pp 25950 309

8408060274 Discusses proposed alternative sites for disposal of Durango mill tailings Based on field observations,major engineering design measures will be needed at Long Hollow & Bodo Canyon sites to satisfy groundwater protection requirements
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 84/07/23 MORLEY,J A Energy, Dept of 2pp 25950 296

8408060295 Forwards J Buckley 840705 memo re typographical error in App V,Vol 2 of NUREG-0960
WRIGHT,R J Repository Projects Branch (Post 831001) 00916 84/07/23 OLSON,O L Energy, Dept of 1p 25950 349

8408060338 Forwards listed documents re decision on DOE guidelines, including transcript of 840622 Commission meeting & three written testimonies from Commission 840622 meeting W/o encl
RUSSELL,C F Division of Waste Management 84/07/03 STEVENS,D Washington, State of 1p 25937 353

8408060341 Forwards listed documents re decision on DOE guidelines, including transcript of Commission 840622 meeting & three written testimonies from Commission 840622 meeting W/o encl
MATTSON,D R Policy & Program Control Branch (Post 831001) 612 84/07/03 BOHLINGER,H Louisiana, State of 1p 25937 352

8408060431 "Bodo Canyon (Area E) Site Geomorphic Evaluation "
SCHUMM,S A , HARVEY,M D Water Engineering & Technology, Inc 83/11/10 9pp 25937 325

8408070063 Responds to S Coplan 840607 memo re Nevada Nuclear Waste Site Investigations proposed data reviews w/NRC for two of three upcoming meetings Public will not be invited
FREI,M W Energy, Dept of 84/07/03 BENNETT,W J Energy, Dept of 2pp 25955 323

8408070136 Forwards "Overview of Low Temp Sensitization," prepared by LLL as part of waste package evaluation for Nevada Nuclear Waste Storage Investigations
BARRETT,L H Engineering Branch (Post 831001) 00326 84/04/24 CONTE,E F Division of Waste Management 1p 25957 156

--8408070140 UCRL-15619
"Overview of Low Temp Sensitization "
FOX,M J , MCCRIGHT,D R Lawrence Livermore National Laboratory 83/12/31 41pp 25957 157

8408070149 Forwards revised "Document Accessions List,Jul 1984," for Rockwell Hanford Operations
* Basalt Waste Isolation Project 920 84/07/26 WRIGHT,R J Division of Waste Management 1p 25957 210

--8408070153 Q06-30 84
Revised Document Accessions List Jul 1984,' for Rockwell Hanford Operations
* Basalt Waste Isolation Project 84/07/31 512pp 25957 211

8408070161 'Radiological * Engineering Assessment for Salt Lake City Property SL-049 '
* Morrison-Knudsen Co , Inc 84/07/03 78pp 26058 229

8408070276 Advises that NRC cannot concur w/interagency agreement between DOE & TVA re disposal of residual radioactive matls from vicinity properties in Edgemont,SD,as presently worded Agreement should be revised
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 84/07/25 HILL,T V Energy, Dept of 2pp 25956 259

8408070523 Trip rept of 840720 meeting at EPA,Athens,GA re metal speciation & transport modeling List of attendees & 840531 telcon record encl
KELLEY,W R Geotechnical Branch (Post 831001) 84/07/24
STARMER,R J Geotechnical Branch (Post 831001) 4pp 25956 220

8408080322 Confirms 840816 meeting in Silver Spring,MD to discuss 61TRAK & WASTETRAN,w/primary emphasis on scaling factor modeling contained in 61TRAK,per 840727 telcon
VANCE,J N Impell Corp 84/07/27 ROLES,G Low-Level Waste & Uranium Recovery Projects Branch 1p 25976 007

8408070299 Forwards DOE comments re proposed amend to 10CFR60 for disposal of high level waste in unsaturated zone & alternatives
JOHNSON,C Policy & Program Control Branch (Post 831001) 331
84/07/27 JOHNSON,C Nevada, State of 1p 25984 352

--8408070303 Forwards suggested alternate performance objective re amend to 10CFR60 for disposal of high level waste in unsaturated zones Proposal related to geologic setting of sites within zone
RUSCHE,B C Energy, Dept of 84/07/11 CHILK,S J Docketing & Services Branch 7pp 25984 353

8408070328 Summary of 840717 meeting w/State of CO,EPA,DOE & DOE contractors in Denver,CO re Durango EIS Attendee list encl
PENNIFILL,R A Low-Level Waste & Uranium Recovery Projects Branch
84/07/24 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 3pp 25984 341

8408070331 Comments on study or soil samples from Beatty,NV disposal site Questions raised re plans for further testing for Tc-99, I-129 & H-3 & use of results by State of NV
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch
84/03/27 NUSSBAUMER,D A Assistant Director for State Agreements Programs 1p 25984 340

8408130077 Forwards marked-up draft Beatty site closure plan submitted by US Ecology,for review & comments Comments requested by 840808
NUSSBAUMER,D Assistant Director for State Agreements Programs
4/07/13 HIGGINBOTHAM,L Low Level Waste Licensing Branch 35pp
6059 001

408130079 "Geohydrological Studies Beatty,NV Disposal Facility "
* Law Engineering Testing Co 81/08/13 94pp 26059 038

3408130081 "Gravel Cap Design Analysis Beatty Low Level Radwaste Disposal Site,Beatty,NV "
HOOPER,R L U S Ecology, Inc (Formerly Nuclear Engineering, Inc) 84/06/04 11pp 26059 091

08130085 Summary of NRC hydrology data orientation & data review 840514-18 meetings in Columbus,OH Agenda,notes & attendee list encl
PEARRING,J R Engineering Branch (Post 831001) 621 84/06/06
GREEVES,J T Engineering Branch (Post 831001) 20pp 26036 310

408130099 Forwards draft umbrella site technical position on BWIP geology, to fulfill Operating Plan Milestone 3314215 12 Comments requested
KNAPP,M R Geotechnical Branch (Post 831001) 923 84/07/30
BROWNING,R E Office of Nuclear Material Safety & Safeguards,Director 1p 26036 293

--8408130101 "Site Technical Position - Geologic Issues for BWIP "
* Geotechnical Branch (Post 831001) 84/07/31 16pp 26036 294

8408130105 Discusses impact of neat cement zone on baseline head distribution in boreholes w/nested piezometers used to collect downhole pressure data Problems w/piezometer design identified * modeling methods discussed Addl work needed
GORDON,M Geotechnical Branch (Post 831001) 921 84/07/10
KNAPP,M Geotechnical Branch (Post 831001) WRIGHT,R Repository Projects Branch (Post 831001) 16pp 26034 335

8408130116 Returns DOE-TVA interagency agreement transmitted by L Higginbotham 840725 ltr,per 840730 telcon W/o encl
MARQUEZ,R A Energy, Dept of 84/07/30 GNUGNOLI,G NRC - No Detailed Affiliation Given 1p 26034 331

8408130122 Acks receipt of 840709 data inventory & forwards list of data that would be useful during 840724-27 hydrology data review
COPLAN,S M Repository Projects Branch (Post 831001) 330
84/07/20 VIETH,D L Energy, Dept of 3pp 26034 331

8408130130 Forwards 'Geology & Mineral Deposits of Southern Nye County," 'Nevada Statistical Abstract," "Annual Rept 1981-82,' "Nevada Map Atlas-Fourth Edition" & 'Financial Statement," per C Johnson 840613 request W/o encl
LOUX,R R Nevada, State of 328 84/07/25 RUSSELL,C F Policy & Program Control Branch (Post 831001) 1p 26034 330

8408130137 Notifies of upcoming meetings during 840801-1129 Updates will be submitted weekly
TAYLOR,T J Energy, Dept of 620 84/07/27 LINEHAN,J NRC - No Detailed Affiliation Given HINCHMAN,J Utah, State of
FORSYTHE,R Texas, State of 2pp 26034 328

8408130140 Concurs w/remedial action plan for State of CO tailings repository
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch
84/07/27 CREW,M E Energy, Dept of 2pp 26034 326

8408130144 Forwards cutaway diagram of Hanford basalt units, showing interbeds & basalts being considered for repository host rock
WRIGHT,R J Repository Projects Branch (Post 831001) 908
84/07/19 FARROW,M J Confederated Tribes of Umatilla Indian Reservation 2pp 26034 324

8408130577 "Codes That May Be Used in Nevada Nuclear Waste Site Investigations Performance Assessment "
* Sandia Laboratories 329 84/08/08 2pp 26038 315

8408140358 Approves DOE remedial action plan for removal of matl from former White Truck site in Salt Lake City Requests future submissions allow 1 month rather than 10 days for review & concurrence NRC concurrence should not be assumed
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch
84/07/25 MORLEY,J A Energy, Dept of 1p 26061 285

8408150144 Forwards "DES Remedial Actions at Former Vanadium Corp of America Site,Durango,La Plata County,CO," per 840717 meeting Evaluation should be concentrated in four listed areas Comments requested by 840817
MORLEY,J A Energy, Dept of 84/08/01 PENNIFILL,R Low-Level Waste & Uranium Recovery Projects Branch 1p 26100 001

--8408150149 "DES - Remedial Actions at Former Vanadium Corp of America Site,Durango,La Plata County,CO "
* Dames & Moore 84/07/31 1,000pp 26100 003

8408150252 Forwards comments on geotechnical engineering issues in "Processing Site Characterization Rept for U Mill Tailings Site at Riverton,WY," per 840719 request
SMYKOWSKI,S Engineering Branch (Post 831001) 84/08/01
PENNIFILL,R Low-Level Waste & Uranium Recovery Projects Branch
3pp 26099 355

8408150337 Forwards "SRP for Draft Environ Assessment Developed by DOE, per Section 112(b) of Nuclear Waste Policy Act," for NRC use NRC will not comment on DOE methodology to compare sites,per 10CFR60
BROWNING,R E Division of Waste Management 84/07/05 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 2pp 26098 298

--8408150341 Advises of major inconsistency between position taken in environ assessment review plan & DOE siting guidelines re methodology used by DOE to compare or select sites & relative merits of one site against another
SURMEIER,J NRC - No Detailed Affiliation Given 84/07/03
JOHNSON,B NRC - No Detailed Affiliation Given 2pp 26098 300

--8408150344 "SRP for Draft Environ Assessment Developed by DOE,per Section 112(b) of Nuclear Waste Policy Act "
* Division of Waste Management 84/06/22 41pp 26098 302

8408150352 Draft "Remedial Action Plan & Site Conceptual Design for Stabilization of the Inactive U Mill Tailings Site at Gunnison, CO "
* Energy, Dept of 84/06/30 250pp 26098 038

8408150365 Draft "Processing Site Characterization Rept for U Mill Tailings Site at Gunnison CO "
* Energy, Dept of 84/06/30 300pp 26097 069

8408150400 "Disposal Site Characterization Rept for Alternate U Mill Tailings Disposal Site in East Gold Basin near Gunnison,CO "
MORLEY,J A Energy, Dept of 84/05/31 34pp 26104 338

8408150403 "Disposal Site Characterization Rept for Alternate U Mill Tailings Disposal Site in Chance Gulch Near Gunnison,CO "
MORLEY,J A Energy, Dept of 84/05/31 34pp 26105 235

8408150419 "Environ Assessment of Remedial Action at Gunnison U Mill Tailing Site,Gunnison,CO
* Energy, Dept of 84/06/30 400pp 26096 038

8408150531 Forwards "Radiological & Engineering Assessment for Property ED-00005-RS "
ROBERTS,W A Energy, Dept of 84/08/01 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 1p 26080 272

--8408150533 "Radiological & Engineering Assessment for Property ED-00005-RS "
* Bendix Corp 84/07/31 21pp 26080 273

8408150568 Forwards "NRC Review Plan QA Program for Site Characterization of High Level Nuclear Waste Repositories " Discusses steps taken to establish early agreement on QA program Site visits for Jul & Aug proposed
BROWNING,R E Division of Waste Management 84/06/29 BENNETT,W J Energy, Dept of 4pp 26080 316

--8408150572 "NRC Review Plan QA Program for Site Characterization of High Level Nuclear Waste Repositories "
* Repository Projects Branch (Post 831001) 84/06/30 33pp 26080 320

8408150664 Forwards NRC comments re DOE draft "Mission Plan for Civilian Radwaste Mgt Program," per MJ Lawrence 840508 request NRC/DOE interaction to ensure timely preparation of final mission plan continuing
PALLADINO N Commissioners 84/07/31 RUSCHE,B C Energy, Dept of 57pp 26104 009

8408160048 Forwards draft interagency programmatic agreement re U mill tailings disposal sites Redraft contains new provisions re problems concerning low level radwaste mgt & language which commits NRC & EPA to seek legislative relief
DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 84/07/25 CANNON,J , THOMAS,L Environmental Protection Agency 16pp 26128 146

8408160051 Informs of review of radiological & engineering assessment for vicinity property listed in encl & concurrence w/planned remedial action Concurrence based on listed items
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 84/07/27 CREW,E Energy, Dept of 2pp 26126 361

8408160055 Forwards documents re NRC efforts in defining high level radwaste under Nuclear Waste Policy Act of 1982 & NRC comments to EPA on high level waste std
BELL,M J Division of Waste Management 84/08/03 BENNETT,J W Energy, Dept of 5pp 26126 356

8408160278 Forwards "Project Licensing Plan for UMTRAP Sites" for review & concurrence
MORLEY,J A Energy, Dept of 84/08/07 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 1p 26126 043

--8408160283 "Project Licensing Plan for UMTRAP Sites "
* Energy, Dept of 84/07/31 37pp 26126 044

8408160289 Discusses status of Falls City,TX inactive U mill site & plan of action Since current contractor due to lose license, DOE prepared to begin remedial action
BAUBLITZ,J E Energy, Dept of 84/08/06 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 2pp 26124 348

8408160297 Discusses Barrier-55 high integrity container for low level radwaste Barrier fully complies w/10CFR61 & approved for use at Barnwell site
HIPSHER,W M NUS Corp 84/08/07 JOHNSON,T Low-Level Waste & Uranium Recovery Projects Branch 3pp 26124 342

8408160464 Advises that briefing by Impell Corp re waste classification computer programs (61 TRAK & WASTETRAK) shifted from 840809 to 840921
ROLES,G W Low-Level Waste & Uranium Recovery Projects Branch 84/08/02 GAMILL,W Meteorology & Effluent Treatment Branch MACDONALD,C E Transportation Certification Branch GRELLA,A W Safeguards & Materials Program Branch 1p 26124 341

8408160467 Comments on topical rept re ENVIROSTONE gypsum cement Approval of rept should be limited to formulae which give acceptable product Long-term performance of gypsum cement needs further study
COSTANZI,F A Waste Management Branch (post 840429) 84/08/09
BARRETT L Engineering Branch (Post 831001) 1p 26120 348

8408160470 Forwards "Draft Generic Technical Position on Licensing Assessment Methodology for High Level Waste Geologic Repositories" for guidance to DOE
MILLER,H J Repository Projects Branch (Post 831001) 84/07/31
BROWNING,R E Division of Waste Management 1p 26124 298

--8408160475 "Draft Generic Technical Position on Licensing Assessment Methodology for High Level Waste Geologic Repositories "
* Division of Waste Management 84/07/31 39pp 26124 299

8408160479 Submits comments on draft "Mission Plan for Civilian Radwaste Mgt Program," per Nuclear Waste Policy Act,Section 301(b)
FRISHMAN,S Texas, State of 84/07/09 RUSCHE,B C Energy, Dept of 20pp 26108 331

8408170413 Forwards draft "Radiological & Engineering Assessment & Final Design for Salt Lake City Property,SL-044 "
* Morrison-Knudsen Co , Inc 84/07/27 FLORY,C NRC - No Detailed Affiliation Given 1p 26135 186

--8408170415 Draft "Radiological & Engineering Assessment & Final Design for Salt Lake City Property,SL-044 "
* Morrison-Knudsen Co , Inc 84/07/25 62pp 26135 187

8408170427 Forwards draft umbrella site technical position on geology for Nevada Nuclear Waste Site Investigations Document distributed to Engineering Branch for technical comments & Repository Projects Branch for general review
KNAPP,M R Geotechnical Branch (Post 831001) 84/07/27
BROWNING,R E Division of Waste Management 14pp 26134 278

8408200134 Forwards draft "Radiological & Engineering Assessment for Salt Lake City Property SLC-019 " Comments requested by 840806
PEPIN J G Morrison-Knudsen Co , Inc 84/07/26 FLORY,C NRC - No Detailed Affiliation Given 1p 26141 088

--8408200157 Draft "Radiological & Engineering Assessment for Salt Lake City Property SLC-019 "
* Morrison-Knudsen Co , Inc 84/07/24 45pp 26141 089

8408200187 Advises that testing of cement solidified activated carbon as stable mix meeting stability requirements of 10CFR61, in process Appropriate data & formulation for review will be submitted at conclusion of testing
LEDUC,R J Westinghouse Hittman Nuclear, Inc WHNI-E-792
84/08/09 PERSON,L S Low-Level Waste & Uranium Recovery Projects Branch 2pp 26142 293

8408200197 Forwards list of inadequacies based on brief review of draft US Ecology,Inc closure plan proposal for Beatty low level waste disposal facility Addl info re hydrology, geology & geochemistry warranted
KNAPP,M R Geotechnical Branch (Post 831001) 84/08/08
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 2pp 26142 290

8408200208 Advises of completion of review of radiological & engineering assessments for TVA millsite at Edgemont,SD & concurrence w/planned remedial actions
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 84/08/08 CREW,M E Energy, Dept of 2pp 26142 288

8408200329 "Lakeview Activity Status Rept,840619 "
* Oregon, State of 84/06/19 5pp 26142 281

8408200232 Notification of 840710 meeting w/Engineers Intl & US Bureau of Mines in Silver Spring,MD to prepare for Nevada Nuclear Waste Site Investigations repository design data review scheduled for 840716-20 Proposed agenda encl
* Engineering Branch (Post 831001) 84/07/10 Engineering Branch (Post 831001) 19pp 26142 262

8408200234 Lakeview U Mill Site Remedial Action Project Status Rept, May-June 1984 "
* Oregon, State of 84/06/30 11pp 26142 251

8408200242 'Lakeview Activity Status Rept,840515 '
* Oregon, State of 84/05/15 10pp 26142 005

8408200245 "Lakeview U Mill Site Remedial Action Project Status Rept, Feb 1984 '
* Oregon, State of 84/02/29 2pp 26142 003

8408200252 "Lakeview U Mill Site Remedial Action Project Status Rept, Mar-Apr 1984 "
* Oregon, State of 84/04/30 6pp 26143 323

8408200342 "Draft Radiological & Engineering Assessment,Vicinity Property SLC-050 "
* Morrison-Knudsen Co , Inc 84/07/25 60pp 26141 020

8408200404 Forwards proposed agenda for 840827 meeting to discuss issue & mgt info tracking sys used by repository program ofcs
WRIGHT,R J Repository Projects Branch (Post 831001) 84/08/01
OLSON,O L Energy, Dept of 4pp 26141 190

8408200409 Forwards comments on Riverton processing site characterization rept (PSCR) PSCR fails to achieve purpose of containing inventory of data relevant to remedial actions
WEBER,M F Geotechnical Branch (Post 831001) 84/08/07 FLORY,C
Low-Level Waste & Uranium Recovery Projects Branch 16pp
26141 162

8408200425 Trip rept of 840723-27 visit to USGS in Denver,CO re Nevada Nuclear Waste Site Investigations hydrology data review
RICE,B J Geotechnical Branch (Post 831001) 332 84/08/09
JUSTUS,P S Geotechnical Branch (Post 831001) 3pp 26144 358

8408200426 Forwards draft 'Site Technical Position - Geochemistry Issues for BWIP," in response to OPS Plan Milestone 3314215 52 Comments requested by 840813
STARMER,R J Geotechnical Branch (Post 831001) 930 84/07/30
WRIGHT,R J Repository Projects Branch (Post 831001) GREEVES,J T ,
JOHNSON,T C Engineering Branch (Post 831001) 1p 26183 007

--8408200432 Draft 'Site Technical Position - Geochemistry Issues for BWIP "
* NRC - No Detailed Affiliation Given 84/07/30 31pp
26183 008

8408200430 Confirms that geology data review scheduled for 2-wk period commencing on 840917 at Yucca Mountain site
VIETH,D L Energy, Dept of 334 84/08/07 COPLAN,S M
Repository Projects Branch (Post 831001) 2pp 26144 352

8408200435 Forwards,for signature,summary of 840710-12 geochemistry workshop Summary should be returned so encls can be added & distribution completed
VIETH,D L Energy, Dept of 337 84/08/14 COPLAN,S M
Repository Projects Branch (Post 831001) 10pp 26144 338

8408200439 Forwards,for review,aquifer analysis paper re Gunnison,CO site Paper concludes that aquifer restoration not economically feasible & no addl field data required
MORLEY,J A Energy, Dept of 84/08/13 HAISFIELD,M NRC - No
Detailed Affiliation Given 32pp 26182 337

8408200444 Points out error in NRC 840705 comment ltr on "Repository Horizon Identification Rept," RHO-BW-ST-28P Comment 3 should read " performance function is paramount "
WRIGHT,R J Repository Projects Branch (Post 831001) 932
84/08/02 OLSON,O L Energy, Dept of 1p 26144 328

8408200452 Responds to DOE 840703 request for concurrence in Cooperative Agreement DE-FC04-84AL20334 between DOE & State of OR Concurrence granted w/concern re failure to mention NRC as cooperating agency W/o encl
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch
84/07/24 HILL,T V Energy, Dept of 1p 26143 362

8408200459 Trip rept of 840712-19 site visit to U recovery operation in Wyoming re review of environ assessment & remedial action plan & preparation for U recovery rulemaking
DAM,W Geotechnical Branch (Post 831001) 84/08/07 STARMER,R J
Geotechnical Branch (Post 831001) 5pp 26144 322

8408200470 Forwards draft "Review of Geochemical Condition Info at BWIP Site (1979-82), " in response to OPS Plan Milestone 3314215 631
BROOKS,D J Geotechnical Branch (Post 831001) 929 84/07/31
KNAPP,M R Geotechnical Branch (Post 831001) 1p 26182 227

--8408200475 Draft 'Review of Geochemical Condition Info at BWIP Site (1979-82), "
* NRC - No Detailed Affiliation Given 82/12/31 66pp
26182 228

8408200474 Submits Nevada Nuclear Waste Storage Investigations site rept for wk of 840730 Agenda for 840801-02 project manager-technical project officers meeting encl
PRESTHOLT,P T Division of Waste Management 339 84/08/06
BROWNING,R E Division of Waste Management 19pp 26182 294

8408200480 Forwards draft "Groundwater Issues for BWIP," site technical position
KNAPP,M R Geotechnical Branch (Post 831001) 84/07/31 MILLER,H
Repository Projects Branch (Post 831001) 1p 26143 340

--8408200491 BWIP STP 1 0 DRFT
Draft "Groundwater Issues for BWIP," site technical position
* Division of Waste Management 84/07/31 15pp 26143 341

8408200536 Forwards draft data locations list & topical bibliography re thermal/thermomechanical properties of rock,for 840820 meeting w/NRC Lists will be updated as necessary
CASEY,L Energy, Dept of 629 84/08/08 JOHNSON,R NRC - No
Detailed Affiliation Given 79pp 26144 132

8408200514 Notifies of upcoming meetings w/NRC re info sys,underground testing & rock mechanics data review
TAYLOR,T J Energy, Dept of 624 84/08/03 HINCHMAN,J ,
FRISHMAN,F , FORSYTHE,R Energy, Dept of 2pp 26143 321

8408200517 Requests transmittal of well summary repts & characterization status repts to R Johnson of NMSS,Div of Waste Mgt
SHERWIN,J A Energy, Dept of 623 84/08/06 WERMUND,E G
Texas, Univ of, Austin, TX 1p 26143 320

8408210038 Agrees to 840827 scheduled meeting in Richland,WA to discuss DOE/BWIP info sys,per 840801 ltr Proposed agenda accepted w/o comments
OLSON,O L Energy, Dept of 925 84/08/10 WRIGHT,R J
Repository Projects Branch (Post 831001) 1p 26195 181

8408210044 Agenda of State of WA Nuclear Waste Board 840818 meeting in Lacey,WA to discuss status of federal actions & defense waste project proposal
* Washington, State of 927 84/06/18 Washington, State of
1p 26195 151

8408210071 Corrected agenda of State of WA Nuclear Waste Board 840817 meeting in Lacey,WA to discuss status of federal actions & defense waste project proposal
* Washington, State of 928 84/08/17 Washington, State of
2pp 26195 149

8408210087 Forwards state comments on draft mission plan for civilian raduaste mgt program (except MRS),per C Russell request State of MN comments will be sent directly by state
GERVERS,J R Latir Energy Consultants 84/08/10 BROWNING,R E
Division of Waste Management 88pp 26194 319

8408210115 Forwards "Draft Umbrella Site Technical Position on Geochemical Issues for High Level Waste Disposal Facility in Tuff " Comments requested by 840813
STARMER,R J Geotechnical Branch (Post 831001) 338 84/07/30
COPLAN,S M Repository Projects Branch (Post 831001) GREEVES,J T ,
JOHNSON,T C Engineering Branch (Post 831001) 1p 26195 320

--8408210124 "Draft Umbrella Site Technical Position on Geochemical Issues for High Level Waste Disposal Facility in Tuff "
* Division of Waste Management 84/07/30 24pp 26195 321

8408210125 Forwards 840629 QA review plan,per 840725 request Package includes transmittal ltr,QA review plan & NUREG-1055 W/o encl
LINEHAN,J J Repository Projects Branch (Post 831001) 626
84/07/30 NEFF,J D Energy, Dept of 1p 26195 319

8408210130 Ack receipt of topical rept of CYTRAK computer program Computer code listing requested
ROLFS,G W Low-Level Waste & Uranium Recovery Projects Branch
84/08/07 SHULMAN,M N CYGNA Energy Services 1p 26195 318

8408210131 Requests meeting w/DOE & Science Applications, Inc on 840830 & 31 to discuss info mgt sys currently in use & planned by Nevada Nuclear Waste Storage Investigation Proposed agenda & list of topics encl
COPLAN, S M Repository Projects Branch (Post 831001) 335
84/08/09 VIETH, D L Energy, Dept of 4pp 26195 314

8408210171 Requests color prints of Yucca Mountain core boxes for DOE Waste Mgt Project Ofc
VIETH, D L Energy, Dept of 336 84/08/08 REED, R C Pan American World Airways, Inc 1p 26195 220

8408210180 "Group Visit Info Sheet " for upcoming Nevada Test Site visit
GLORA, M Science Applications, Inc 333 84/08/06 5pp 26187 351

8408220061 Forwards State of NV comments on draft mission plan
LOUX, R R Nevada, State of 84/08/10 BROWNING, R E Division of Waste Management 36pp 26211 305

8408220065 Requests copy of official version of CHEMRN transport model
KERRISK, J F Los Alamos Scientific Laboratory WX-4-6492
84/08/08 STARMER, R J NRC - No Detailed Affiliation Given 1p 26209 359

8408220076 Forwards comments on DOE draft Apr 1984 "Mission Plan for Civilian Radwaste Mgt Program " Comments based on discussion at ACRS Subcommittee on Waste Mgt 840807 meeting
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards
84/08/13 DIRCKS, W J Office of the Executive Director for Operations 2pp 26210 358

--8408220081 Comments on DOE draft Apr 1984 "Mission Plan for Civilian Radwaste Mgt Program "
* ACRS - Advisory Committee on Reactor Safeguards 84/08/08
3pp 26210 360

8408220122 Forwards revised site-specific procedural agreement, incorporating changes agreed to at 840731 meeting, for NRC signature
BENNETT, J W Energy, Dept of 84/08/09 BROWNING, R E Division of Waste Management 17pp 26211 341

8408220167 Discusses DOE 810625 responses to NRC 840416 comments re "Slope Stability & Seismic Risk Evaluation" of Dec 1983 draft Shiprock remedial action plan Seismological aspects adequate & Chapter 3 statements accurate
BLACKFORD, M NRC - No Detailed Affiliation Given 84/08/07
PENNIFILL R NRC - No Detailed Affiliation Given 1p 26203 362

8408220215 Forwards fully executed Interagency Agreement DE-AI04-84AL27241 between DOE & TVA NRC concurrence conditioned upon satisfactory resolution of NRC concerns by appropriate mod to agreement by 841002
HILL, T V Energy, Dept of 84/08/10 DONOVAN, T K Tennessee Valley Authority 12pp 26210 336

--8408220219 Concurs in interagency agreement between DOE & TVA re disposal of radioactive matls from vicinity properties in Edgemont, SD Concurrence conditioned upon satisfactory resolution of NRC concerns
HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 84/08/03 MARQUEZ, R Energy, Dept of 3pp 26210 350

8408220223 Submits notice of upcoming meetings, per 830719-20 meeting Notice will be updated weekly
TAYLOR, T J Energy, Dept of 637 84/08/10 LINEHAN, J NRC - No Detailed Affiliation Given HINCHMAN, J Utah, State of
FRISHMAN, S Texas, State of 2pp 26203 360

8408220227 Confirms 840921 meeting in Denver, CO re comments on revised preliminary DES Proposed approach on groundwater analysis will be transmitted by 840813 for inclusion in DES
MORLEY, J A Energy, Dept of 84/08/10 PENNIFILL, R NRC - No Detailed Affiliation Given 9pp 26203 351

8408220232 Informs of publication of FES for UMTRA project in Salt Lake City, UT, per 840612 ltr FES modified to incorporate statements re unconfined aquifer into Sections D 3 6 5 & D 89
BAUBLITZ, J E Energy, Dept of 84/08/08 HIGGINBOTHAM, L Low Level Waste Licensing Branch 15pp 26203 336

8408220234 Submits June 1984 highlights re remedial action plan Highlights include signing of MOU w/TVA re tailings disposal for Edgemont vicinity property & completion of Shiprock final EIA
MORLEY, J A Energy, Dept of 84/08/13 HIGGINBOTHAM, L Low Level Waste Licensing Branch 7pp 26203 329

8408220238 Annotated "Memo on Water Supply Investigation at Shiprock School Navajo Indian Reservation, San Juan County, NM "
CALLAHAN, J P , HARSHBARGER, J Interior, Dept of, Geological Survey
55/03/31 16pp 26203 313

8408220240 Agenda for 840817 meeting in Lacey, WA to discuss description of grant proposal, status of CSC agreement & DOE presentation of mission plan
* Washington, State of 926 84/08/17 Washington, State of
1p 26203 312

8408220324 Trip rept of 840717 visit to State of NV rockmechanics waste test site & 840718-20 visit to Sandia Natl Labs in Albuquerque, NM re design test review Viewgraphs encl
GREEVES, J T , DUTTA, P , TANIOUS, N Engineering Branch (Post 831001) 343 84/08/07 COPLAN, S Repository Projects Branch (Post 831001) 310pp 26203 001

8408220496 Agenda for 840726 meeting w/listed attendees in Silver Spring, MD to discuss site characterization plan format & content
MILLER, R J , COOLEY, C NRC - No Detailed Affiliation Given
84/07/26 NRC - No Detailed Affiliation Given 31pp 26210 245

8408230027 Summary of 840730 meeting w/DOE & Colorado Dept of Health preliminary findings for Gunnison, CO site
HAISFIELD, M , PENNIFILL, R A Low-Level Waste & Uranium Recovery Projects Branch 84/08/06 HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 2pp 26233 361

8408230031 Forwards comments on draft Beatty site closure plan Plan inadequate for effecting proper closure of facility Major deficiencies include lack of documentation re geology & hydrology & support for cost & financial data
HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch
84/08/15 NUSSBAUMER, D A Assistant Director for State Agreements Programs 5pp 26233 354

8408230033 Advises that Nuclear Packaging, Inc topical rept on FL-50 container acceptable Rept info should include list of solid waste species & source which might be incompatible w/ container matl Info should meet NUREG-0800 guidance
GAMMILL, W P Meteorology & Effluent Treatment Branch 84/07/15
BARRETT, L H Engineering Branch (Post 831001) 1p 26233 353

8408230034 Trip rept of 840729-0802 visit to Hanford Reservation, WA re review of geologic maps & field work performed since 1979 publication of ST-4
CUTLER, J M Geotechnical Branch (Post 831001) 937 84/08/14
JUSTUS, P S Geotechnical Branch (Post 831001) 2pp 26233 351

8408230036 Forwards Geotechnical Engineering review comments & questions re Shiprock remedial action plan
BARRETT, L H Engineering Branch (Post 831001) 84/08/10
HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 6pp 26233 345

8408230038 Submits BWIP site rept for wks of 840708-0810 re transportation safety & review of issue tracking sys & data/records mgt sys
COOK, F R Division of Waste Management 84/08/11 BROWNING, R E Division of Waste Management 4pp 26233 333

--8408230043 Advises that request for limited access to BNWL documents re MCC-D2 data package, in support of Matls Review Board review of data package, honored
WHITE, J D Energy, Dept of 84/08/03 COOK, F R NRC - No Detailed Affiliation Given 8pp 26233 337

8408230041 Ack receipt of nonproprietary & proprietary STD-R-03-008, "Hittman RADLOK High Integrity Containers," transmitted on 840628 Tentative schedule for review of rept encl
TIKTINSKY, D H Engineering Branch (Post 831001) 84/08/14
LEDUC, R J Westinghouse Hittman Nuclear, Inc 2pp 26233 331

8408230046 Forwards selected major comments re draft Umbrella Site technical position for salt, geology, groundwater geochemistry, design & waste package Comments developed considering need to minimize efforts to make revs
MILLER, H J Repository Projects Branch (Post 831001) 84/08/07
KNAPP, M R Geotechnical Branch (Post 831001) BARRETT, L. Engineering Branch (Post 831001) 15pp 26233 316

8408230053 Trip rept of attendance at American Geophysical Union Spring conference on 840514 in Cincinnati, OH re presentation of paper on flow parameters of partly saturated soils & spatial variability Viewgraphs encl
COOKE, B A Geotechnical Branch (Post 831001) 84/08/02. KNAPP, M R Geotechnical Branch (Post 831001) 26pp 26233 290

8408230062 Comments on revised modeling strategy document for high level waste performance assessment Discrepancies exist between document & DOE siting guidelines
FEHRINGER,D J Repository Projects Branch (Post 831001) 84/08/06
PFLUM,C G Repository Projects Branch (Post 831001) 2pp
26233 273

8408230069 Requests review & comments on encl Westinghouse Hittman STD-R-03-008, "Hittman RADLOK High Integrity Containers," by 841102 Encl withheld
BARRETT,L H Engineering Branch (Post 831001) 84/08/15
COSTANZI,F A Division of Waste Management 1p 26233 272

8408230079 Forwards comments on BMI/ONWI-513, "Salton Sea Geothermal Field,California as Near-Field Natural Analog of Radwaste Repository in Salt " NRC supports use of natural analogs for DOE assessment of high level waste site
LINEHAN,J J Repository Projects Branch (Post 831001) 633
84/08/10 NEFF,J O Energy, Dept of 5pp 26233 244

8408230085 Concurs w/planned remedial actions for vicinity property identified in encl,based on review of radiological & engineering assessments
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch
84/08/01 MORLEY,J A Energy, Dept of 2pp 26233 242

8408230100 Provides clarification of NRC position re revised procedure for extending & documenting NRC concurrence in vicinity property remedial actions,per recipient 840711 comments
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch
84/08/06 MORLEY,J A Energy, Dept of 2pp 26236 129

8408230362 Forwards request for addl info to continue review of Nuclear Packaging,Inc topical rept on FL 30 Ferralium 225 high integrity container Response requested within 45 days of ltr receipt W/o encl
NUSSBAUMER,D A Assistant Director for State Agreements Programs
84/08/15 KIRNER,N P Washington, State of, Dept of Social & Health Services 1p 26230 358

8408230394 Forwards list of documents needed to allow comment on 840601 preliminary draft environ assessment for Nevada Nuclear Waste Storage Investigations Project W/o encl
COPLAN,S M Repository Projects Branch (Post 831001) 345
84/08/10 VIETH,D L Energy, Dept of 1p 26230 257

8408230395 Forwards draft generic technical position of licensing assessment methodology for high level waste geologic repositories W/o encl
MILLER,H J Repository Projects Branch (Post 831001) 84/08/10
BENNETT,J W Energy Dept of 2pp 26230 255

8408230420 Comments on groundwater SIP for Palo Duro & Paradox bedded salt basins Program inconsistent in treating prewaste emplacement phenomenon w/post-emplacement phenomenon, per 10CFR60 113
JOHNSON,T C Engineering Branch (Post 831001) 636 84/08/07
POHLE,J Geotechnical Branch (Post 831001) 2pp 26230 241

8408230423 Comments on draft site technical position on groundwater issues for Palo Duro & Paradox bedded salt basins Emphasis on groundwater & exclusion of waste package interactions urged
PETERSON,C H Division of Waste Management 632 84/08/03
TOKAR,M Division of Waste Management 2pp 26230 227

8408240005 Agenda of 840710-12 geochemistry workshop w/Nevada Nuclear Waste Site Investigations at Los Alamos Natl Lab to discuss geochemical issues Viewgraphs encl
* NRC - No Detailed Affiliation Given 340 84/07/12 NRC - No Detailed Affiliation Given 354pp 26252 001

8408240103 Ack receipt of ltr re high level repository sites in UT Paradox Basin NRC preparing to review site environ assessments from DOE US Park Svc views will be considered in review
LINEHAN,D J Repository Projects Branch (Post 831001) 639
84/08/06 MINTZMYER,L Interior, Dept of, National Park Service 1p 26255 352

8408240119 Comments on Jun 1984 progress rept for Contract NRC-02-84-002 Task Orders 001 & 002 complete Remaining work under Task Orders 003-006 noted
BUCKLEY,J T Engineering Branch (Post 831001) NRC-02-84-002
1420 84/08/07 CUMMINGS,R Engineers International, Inc 2pp
26255 274

8408240214 "Geochemical Sensitivity Analysis," monthly rept for Jul 1984
SIEGEL,M D Sandia Laboratories FIN A-1756 1424 84/08/15
KELLY,W NRC - No Detailed Affiliation Given 5pp 26254 351

8408240221 Forwards comments on NRC review of DOE 840111 response to NRC 830615 concerns on exploratory shaft const & sealing methods
CUMMINGS R A Engineers International, Inc FIN D-1004
1148-003-04C 84/08/13 BUCKLEY,J High Level Waste Technical Development Branch 20pp 26255 137

8408240260 "Monitor/Review Aspects of DOE & Other Natl & Intl Waste Mgt Programs" & "Short-Term Technical Assistance," summary of activities for Jul 1984
CRANWELL,R M Sandia Laboratories FIN A-1165 1423 84/08/15
PEETERS,L A Repository Projects Branch (Post 831001) 3pp
26237 360

8408240265 "Technical Assistance in Seismo-Tectonic Impacts in Repositories," Monthly Mgt Ltr Progress Rept 16 for Jul 1984
CHUNG,D H Laurence Livermore National Laboratory FIN A-0294
EG-84-065/03264 84/08/09 BLACKFORD,M E Geotechnical Branch (Post 831001) 6pp 26251 266

8408240284 "Coupled Thermal-Hydrological-Mechanical Assessments & Site Characterization Activities for Geologic Repositories," monthly rept for Jul 1984
CHU,M S Sandia Laboratories FIN A-1755 1425 84/08/15
NATARAJA,M S Engineering Branch (Post 831001) 2pp 26252 359

8408240291 "Benchmarking of Computer Codes & Licensing Assistance," monthly ltr progress rept for Jul 1984
VOGT,D K CorSTAR Research, Inc FIN B-6985 1410 84/08/10
BROOKS,P Division of Waste Management 44pp 26251 319

8408240295 "Geological Stability Issues for BWIP," site technical rept
CHUNG,D H Laurence Livermore National Laboratory FIN A-0294
1430 84/08/10 Division of Waste Management 34pp 26251 285

8408240335 Requests technical assistance in reviewing encl list re salt environ assessments & corrosion & failure of 1025 wrought steel overpack Comments requested by 840810
WICK,C A Engineering Branch (Post 831001) FIN A-3167 1413
84/08/03 SOO,P Brookhaven National Laboratory 7pp 26253 325

8408240354 Forwards "Nevada Nuclear Waste Storage Investigations Project,Monthly Rept,May 1984 "
VIETH,D L Energy, Dept of 84/07/10 BENNETT,J W Energy, Dept of 1p 26253 205

---8408240355 "Nevada Nuclear Waste Storage Investigations Project,Monthly Rept,May 1984 "
* Energy, Dept of 84/05/31 75pp 26253 207

8408240372 Informs that memo on thermodynamic relations in magnetite-hematite water sys reviewed, in response to 840720 memo Inconsistent use of sign conventions by DOE in draft SCR created confusion
KNAPP,M R Geotechnical Branch (Post 831001) 84/08/10
BARRETT,L H Engineering Branch (Post 831001) 1p 26254 344

8408240374 Reviews rept of investigation for AML Project 7,Part III outlining proposed reclamation plan for several abandoned mines near Baggs,WY Points requiring discussion at 840705 meeting listed
BEACH,C Wyoming, State of 01254 84/06/19 ANSELMI,K ,
VOELLER,J Wyoming, State of 4pp 26254 336

8408240376 Recommends that work backfill be changed to engineered barrier sys in performance Issues 3 & 8 from App C of BWIP SCA,per 840724 meeting w/J Greeves
TIKTINSKY,D Engineering Branch (Post 831001) 84/08/06
JOHNSON,R Repository Projects Branch (Post 831001) 1p
26254 334

8408240378 Forwards details of concerns about DOE treatment of waste package environ re thermodynamic relations in magnetite water sys as set forth in BWIP SCR of Nov 1982 W/o encl
BARRETT,L H Engineering Branch (Post 831001) 84/07/20
KNAPP,M R Geotechnical Branch (Post 831001) 1p 26254 332

8408240388 Discusses evaluation of seismogenic hazard concepts at Palo Duro Basin salt sites developed from recent work along Meers Fault near Lawton,OK Possible connection of neotectonic activity needs assessment Lists tests
CHUNG,D H Laurence Livermore National Laboratory FIN A-0294
EG-84-066 84/08/09 JUSTUS,P S Geotechnical Branch (Post 831001) 2pp 26249 360

8408240390 "BWIP Hydrogeology," Ltr Rept 88 for Jul 1984
ROWE,J Golder Associates FIN B-7373 823-1033 84/08/08
GORDON,M Division of Waste Management 2pp 26248 360

8408240392 Summary of 840714 meeting w/BNL in Silver Spring MD re BNL final rept on data review in support of environ assessment rept analysis (FIN A-3164 re review of DI of Engineering waste package program)
WICK E A Engineering Branch (Post 831001) FIN A-3164 1412
84/08/07 CARRETT,L H Engineering Branch (Post 831001) 4pp
26249 151

8408270350 Discusses concerns re "Determination of Radionuclide Solubility in Groundwater for Assessment of High Level Radwaste Isolation Marked-up draft repts encl
KELMERS,A D Oak Ridge National Laboratory FIN B-0287 1409
84/08/15 BROOKS,D J Geotechnical Branch (Post 831001) 65pp
26258 246

8408270070 Comments on review of thermal analysis of environ assessment for Swisher repository in salt Two components of uncertainty in prediction of temps exist NRC should request code listings w/sample problems & documentation
SASTRE,C Brookhaven National Laboratory 1426 84/08/10
Brookhaven National Laboratory 19pp 26278 325

8408270074 Forwards review comments for repository site design & rock mechanics sections of draft Nevada Nuclear Waste Storage Investigation Project rept
HOLLOW,E E Interior, Dept of, Bureau of Mines 1422 84/08/10
AMEY,E B Interior, Dept of, Bureau of Mines 1p 26278 318

--8408270078 Forwards review comments for draft Nevada Nuclear Waste Storage Investigation Project environ assessment
HOLLOP,E E Interior, Dept of, Bureau of Mines 84/08/10
TIKTINSKY,D Engineering Branch (Post 831001) 6pp 26278 319

8408270250 Forwards draft radiological & engineering assessment rpts for Properties GJ-12261 MR,GJ-34247-RS,GJ-06318-VL, GJ-00153-CS,GJ-03142-CS,GJ-05785-CS & GJ-09566-VL
TUCKER,M K Energy, Dept of 84/08/01 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 1p 26278 001

--8408270253 Draft "Radiological & Engineering Assessment for Property GJ-12261-MR "
* Bendix Corp 84/07/31 36pp 26278 002

--8408270256 REA-GJ-34247-RS REA-
Draft "Radiological & Engineering Assessment for Property GJ-34247-RS "
* Bendix Corp 84/07/31 28pp 26278 036

--8408270262 REA06318-GJ REA-108/
Draft "Radiological & Engineering Assessment for Property GJ-06318-VL "
* Bendix Corp 84/07/31 30pp 26278 064

--8408270264 REA00153-03142 REA-5
Draft "Radiological & Engineering Assessment for Property GJ-00153-CS & GJ-03142-CS " W/one oversize map Aperture card available in PDR
* Bendix Corp 84/07/31 24pp 26278 094

--8408270267 REA05785-GJ REA-112A
Draft "Radiological & Engineering Assessment for Property GJ-05785-CS & Property GJ-09566-VL "
* Bendix Corp 84/07/31 27pp 26278 119

8408280005 Forwards marked-up "Progress in Evaluation of Radionuclide Geochemical Info Developed by DOE ," BWIP rept & M Siegel rept, "Calculations of Radioelement Solubilities in Basalt Ground Waters "
BRADBURY,J W Geotechnical Branch (Post 831001) FIN B-0290
84/08/13 WHATLEY,S K Oak Ridge National Laboratory 77pp
26293 248

--8408280007 SD-BWI-DP-001 RA-0
Rev A-0 to "BWIP Data Package for Ref Solubility & Kd Values "
SALTER,P F , JACOBS,G K Rockwell International Corp 83/01/06
9pp 26293 327

--8408280009 "Calculations of Radioelement Solubilities in Basalt Ground Waters," ltr rept
SIEGEL,M Sandia Laboratories 83/10/31 15pp 26293 336

8408280031 Summarizes comments & recommendations,per review of revised rept, "Benchmark Problems for Repository Siting Models," (NUREG/CR-3097) Addl paragraphs on ground rules using benchmark problems needed
BROOKS,P P Repository Projects Branch (Post 831001) FIN B-6985
84/08/06 VOOT,D K CorSTAR Research, Inc 13pp 26293 156

8408280112 'Shiprock Well Completions "
PRICE,J Jacobs Engineering Group, Inc 84/08/13 WEBER,M F NRC
- No Detailed Affiliation Given 15pp 26294 124

8408280121 'Comments on Double-Porosity Models for Fissured Groundwater Reservoir w/Fracture Skin '
WILLIAMS,R E Idaho, Univ of, Moscow, ID FIN B-7377 1431
84/08/27 Division of Waste Management 8pp 26294 116

8408280338 Informs of review of process control program section of Chem-Nuclear CNSI-WF C-01-NP, "Waste Form Certification " Chem-Nuclear requested to provide written description of causes & corrective actions taken
GAMMILL,W P Meteorology & Effluent Treatment Branch 84/08/15
HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch
2pp 26294 048

8408280340 Forwards comments on "Design Criteria for Stabilization of Inactive U Mill Tailings Sites," per 840717 request
SMYKOWSKI,S , GILLEN,D M Engineering Branch (Post 831001)
84/08/01 PENNIFILL,R Low-Level Waste & Uranium Recovery Projects Branch 2pp 26294 041

8408290295 Activities of Contract NRC-02-84-001,Monthly Progress Ltr Rept 4,advising that no task order commitments assigned for or in state of assignment
MURPHY,V J Weston Geophysical Corp FIN D-1003 WQC-R531
84/08/14 RICE,B J Geotechnical Branch (Post 831001) 1p
26309 009

8408290337 "Maint & Validation of Computer Programs," monthly rept for Jul 1984
CRANWELL,R M Sandia Laboratories FIN A-1166 84/07/31
CODELL,R Geotechnical Branch (Post 831001) 3pp 26329 005

8408300178 "Maint & Violation of Computer Programs," revised monthly rept for Feb 1984
ORTIZ,N R Sandia Laboratories FIN A-1166 1073 84/02/29
CODELL,R Geotechnical Branch (Post 831001) 18pp 26330 342

8408310269 Forwards C Jacobs trip rept of 840822 visit to ONWI
WHATLEY,S K Oak Ridge National Laboratory FIN B-0287 1445
84/08/23 BROOKS,D J Geotechnical Branch (Post 831001) 75pp
26351 259

8408310270 Forwards response to 840612 comments on UMTRA Salt Lake City FES & on 840606 meeting groundwater issues FR notice of FES availability published on 840803 Comment period closes on 840903
MORLEY,J A Energy, Dept of 84/08/24 HIGGINBOTHAM,L Low-Level Waste & Uranium Recovery Projects Branch 5pp 26350 318

8408310273 Confirms 840831 info mgt sys meeting in Las Vegas,NV,per 840809 request
VIETH,D L Energy, Dept of 84/08/20 COPLAN,S M Repository Projects Branch (Post 831001) 1p 26350 317

8408310331 Forwards results of radium & radon emanation coefficient tests on four U tailings samples received 840213 from Riverton,WY site Encl completes Task 3b deliverables Lab test procedure described in 830603 memo
NIELSON,K K Rogers & Associates Engineering Corp 84/03/27
DZAACK,D D Jacobs Engineering Group, Inc 8pp 26351 001

--8408310335 UMTRA-DOE/AL-0230
"Data for Geochemical Investigation of UMTRAP Designated Site at Riverton,WY "
MARKOS,G , BUSH,K J , MORLEY,J A Energy, Dept of 83/09/30
70pp 26351 009

--8408310339 UMTRA-DOE/AL-0229
"Geochemical Investigation of UMTRAP Designated Site at Riverton,WY "
MARKOS,G , BUSH,K J , MORLEY,J A Energy, Dept of 83/09/30
83pp 26351 079

--8408310344 "Hydrogeochemical Studies of U Mill Tailings at Riverton,WY & Maybell,CO," quarterly progress rept,Jul-Sept 1982 Undated Riverton Mill radiological contamination survey encl
NARASIMHAN,T N Lawrence Berkeley Laboratory 82/09/30 112pp
26351 162

WASTE RES WASTE MANAGEMENT RESEARCH REPORTS

8408240119 Comments on Jun 1984 progress rept for Contract NRC-02-84-002 Task Orders 001 & 002 complete Remaining work under Task Orders 003-006 noted
BUCKLEY,J T Engineering Branch (Post 831001) FIN D-1004 1420
84/08/07 CUMMINGS,R Engineers International, Inc 2pp
26255 274

8408240214 "Geochemical Sensitivity Analysis," monthly rept for Jul 1984
BIEGEL,M D Sandia Laboratories FIN A-1756 1424 84/08/15
KELLY,W NRC - No Detailed Affiliation Given 5pp 26254 351

8408240221 Forwards comments on NRC review of DOE 840111 response to NRC 830615 concerns on exploratory shaft const & sealing methods
CUMMINGS,R A Engineers International, Inc FIN D-1004 1421
84/08/13 BUCKLEY,J High Level Waste Technical Development Branch 20pp 26255 137

8408240260 "Monitor/Review Aspects of DOE & Other Natl & Intl Waste Mgt Programs" & "Short-Term Technical Assistance," summary of activities for Jul 1984
CRANWELL,R M Sandia Laboratories FIN A-1165 1423 84/08/15
PEETERS,L A Repository Projects Branch (Post 831001) 3pp 26237 360

8408240265 "Technical Assistance in Seismo-Tectonic Impacts in Repositories," Monthly Mgt Ltr Progress Rept 16 for Jul 1984
CHUNG,D H Laurence Livermore National Laboratory FIN A-0294 1429 84/08/09 BLACKFORD,M E Geotechnical Branch (Post 831001) 6pp 26254 266

8408240284 "Coupled Thermal-Hydrological-Mechanical Assessments & Site Characterization Activities for Geologic Repositories," monthly rept for Jul 1984
CHU,M S Sandia Laboratories FIN A-1755 1425 84/08/15
NATARAJA,M S Engineering Branch (Post 831001) 2pp 26252 359

8408240291 "Benchmarking of Computer Codes & Licensing Assistance," monthly ltr progress rept for Jul 1984
VOGT,D K CorSTAR Research, Inc FIN B-6985 NRC-02-81-026
84/08/10 BROOKS,P Division of Waste Management 44pp 26251 319

8408240295 "Geological Stability Issues for BWIP," site technical rept
CHUNG,D H Laurence Livermore National Laboratory FIN A-0294
L-95 84/08/10 Division of Waste Management 34pp 26251 285

8408240390 "BWIP Hydrogeology," Ltr Rept 88 for Jul 1984
ROWE,J Golder Associates FIN B-7373 NRC-02-82-045 84/08/08
GORDON,M Division of Waste Management 2pp 26248 360

8408270050 Discusses concerns re "Determination of Radionuclide Solubility in Groundwater for Assessment of High Level Radwaste Isolation " Marked-up draft repts encl
KELMERS,A D Oak Ridge National Laboratory FIN B-0287 1409
84/08/15 BROOKS,D J Geotechnical Branch (Post 831001) 65pp 26258 246

8408280031 Summarizes comments & recommendations, per review of revised rept, "Benchmark Problems for Repository Siting Models," (NUREG/CR-3097) Addl paragraphs on ground rules using benchmark problems needed
BROOKS,P P Repository Projects Branch (Post 831001) FIN B-6985
84/08/06 VOGT,D K CorSTAR Research, Inc 13pp 26293 156

8408280121 "Comments on Double-Porosity Models for Fissured Groundwater Reservoir w/Fracture Skin "
WILLIAMS,R E Idaho, Univ of, Moscow, ID FIN B-7377 1431
84/08/27 Division of Waste Management 8pp 26294 116

8408290295 Activities of Contract NRC-02-84-001, Monthly Progress Ltr Rept 4, advising that no task order commitments assigned for or in state of assignment
MURPHY,V J Weston Geophysical Corp FIN D-1003 WGC-R531
84/08/14 RICE,D J Geotechnical Branch (Post 831001) 1p 26309 009

8408290337 "Maint & Validation of Computer Programs," monthly rept for Jul 1984
CRANWELL,R M Sandia Laboratories FIN A-1166 84/07/31
CODELL,R Geotechnical Branch (Post 831001), 3pp 26329 005

8408300178 "Maint & Violation of Computer Programs," revised monthly rept for Feb 1984
ORTIZ,N R Sandia Laboratories FIN A-1166 1073 84/02/29
CODELL,R Geotechnical Branch (Post 831001) 18pp 26330 342

8408310245 Forwards 0 Jacobs trip rept of 840822 visit to ONWI
WHATLEY,S K Oak Ridge National Laboratory FIN D-0287, 1445
84/08/23 BROOKS,D J Geotechnical Branch (Post 831001) 75pp 26331,259

XPORTLIC EXPORT AND IMPORT LICENSES

8405160213 Ltr re assurance re export of 302 kg U-235, contained in 10,066 kg U, to Japan
SHIRAKAWA,T Japan, Gov't of 84/04/20 RAYMOND,J F Energy, Dept of 1p 24487 247

8405160242 License for Natl Nuclear Corp to export 2 58 mg Cf-252, contained in one neutron source, to United Kingdom
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards BNFL-C-720 84/04/30 1p 24491 004

8408010136 Amend 2 to Westinghouse export license, extending expiration date from 850101 to 901231 for export of licensed matls to Spain
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards MMH-496 84/05/22 1p 25873 311

8408010138 Executive Branch position re DOE application to export 2 kg Pu & 12 kg depleted U to Japan License should be granted Assurance ltr encl
DEVINE,J B State, Dept of 84/05/18 SHEA,J R Office of International Programs, Director 2pp 25873 309

8408010142 Application for license to export Zircaloy-4 double thimble tubes to Japan
ASTLEY,E R Sandvik Special Metals Corp SSM-41135 84/05/17 1p 25873 306

8408060064 Forwards application to amend export license, adding Blayais 3 as addl ultimate consignee Ltr of assurance required
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 84/07/30 THORNE,C E Energy, Dept of 1p 25937 078

8408060350 License for GE to export 3 085 kg U-235, contained in 85 kg U, to Spain
MOORE,R N Assistant Director for Export/Import & International Safeguards BDW-83-006 84/07/27 2pp 25937 350

8408060351 License for Westinghouse to export 10 g U-235, contained in 220 g U, to Spain
MOORE,R N Assistant Director for Export/Import & International Safeguards MMH-361 84/07/27 2pp 25937 348

8408060353 License for GE to export U densitometer to Spain
MOORE,R N Assistant Director for Export/Import & International Safeguards BDW-84-114 84/07/27 1p 25937 345

8408060359 License for Elgar Intl Corp to export one lot inverters, converters, frequency changers & generators, having multiphase electrical power output within range of 600 to 2,000 Hz, to France
MOORE,R N Assistant Director for Export/Import & International Safeguards Z-206A 84/07/27 1p 25937 344

8408060402 Application for license to export 15,327 kg U, as UF6, to Japan
OKADA,S Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd)
MBK-F5-R7(A) 84/07/24 1p 25950 362

8408060406 Application for license to export 11,139 kg U, as UF6, to Japan
OKADA,S Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd)
MBK-F5-R7 (B) 84/07/19 1p 25950 361

8408060432 Application for license to export 789 mg U-238, enriched to 93% U-235, to Italy
HEIMAN,D Reactor Experiments, Inc ITAL-42695 84/07/18 1p 25937 333

8408060435 Requests Executive Branch position re Mitsui & Co (USA), Inc application for license to export 351 kg U-235, as UF6, to Japan
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 84/07/27 THORNE,C E Energy, Dept, of 1p 25937 320

--8408060438 Application for license to export 351 kg U-235, as UF6, to Japan
OKADA,S Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd.)
MBK-F5-R7 (B) 84/07/19 1p 25937 321

8408070049 License for GE to export 1,000 kg natural U, as UO2 powder, to Spain
MOORE,R N Assistant Director for Export/Import & International Safeguards 84/07/27 2pp 25955 336

8408070171 Application for license to export Model 848TCM-3-4-1-2 oscillator / inverters, converters & frequency changers, to France
LANE, M E California Instruments 28326 84/06/19 3pp
25957 114

8408070175 Requests Executive Branch postion re 810210 & 0506 applications for license to export reloads of low enriched U
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/07/31 THORNE, C E Energy, Dept of 1p
25957 113

8408070181 Amend 1 to Westinghouse export license, adding Westinghouse Nuclear Japan as addl intermediate consignee
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/07/30 1p 25957 112

8408070202 Amend 1 to Mitsui Air Intl, Inc export license, increasing value of equipment
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/07/31 1p 25957 099

8408070206 Amend 2 to Mitsui Air Intl, Inc export license, increasing value of equipment, adding Hamaoka 3 power reactor as addl facility & adding Electrolizing, Inc as new supplier
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/07/31 1p 25957 098

8408070209 Amend 3 to Mitsui Air Intl, Inc export license, adding Fukushima 4 & 2 facilities
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/07/31 1p 25957 097

8408070214 Amend 3 to Mitsui Air Intl, Inc export license, adding Fukushima 4 & 2 facilities
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/07/31 1p 25957 096

8408070506 License for Carpenter Technology Corp to export 210 Zircaloy-BUR fuel channels to Italy
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards SPD 5732 84/07/31 1p 25956 236

8408070510 License for Elgar Intl Corp to export inverters, converters, frequency changers / generators, to Sweden
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 18366 SWEDEN 84/07/31 1p 25956 225

8408070512 License for Elgar Intl Corp to export inverters, converters, frequency changers / generators, to The Netherlands
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/07/31 1p 25956 224

8408080013 Informs that Australian govt not prepared to give prior consent to export of all Australian origin nuclear matl specified in License XSNI-0740 & XSNM-1472 Govt exercising prior consent over retransfer on case-by-case basis
CEJA, S N Energy, Dept of 84/07/26 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 2pp
25981 033

8408080108 License for Sigma Chemical Corp to export 5 0 kg deuterium oxide to Spain
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards D-115 84/08/01 1p 25979 108

8408080118 License for Westinghouse to export 660 zirconium tubes, 2,800 zirconium plugs, 1,400 stainless steel springs, 100 thimble screws & 14 Inconel grids to Spain
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MMH-523 84/08/01 1p 25979 119

8408080219 Application for license to export spare parts, consisting of P/N NV23-1 & P/N NV23-2 check valves, to Canada
SMITH, N Brunswick Co N42150 84/07/26 1p 25978 325

8408080532 Application to amend import license, adding addl isotope of Pu Renewal of license also requested
BAGBY, L A Amersham Corp 84/07/26 MOORE, N Office of International Programs, Director 2pp 25975 358

8408080534 License for General Motors, Saginaw Steering Gear Div, to export spare parts for loading & unloading fuel elements to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84146 84/08/02 1p 25975 357

8408150112 License for Transnuclear, Inc to export 12,380 kg U-235 to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards NUK-451 84/08/08 2pp 26104 280

8408150128 Ltr of assurance re export of 208 kg U-235, contained in 7,206 kg U, to Japan
SHIRAKAWA, T Japan, Govt of 84/07/27 THORNE, C E Energy, Dept of 1p 26104 255

8408150131 Advises that govt of Australia will require fabricator (UKAEA) to dilute high enriched U to at least 80%
SAVAGE, E N Australia, Govt of 208/14/8 84/07/31 WRIGHT, B Office of International Programs, Director 1p 26104 254

8408150135 Application to amend export license, extending expiration date to 871001
BRYAN, D C Texas Nuclear Div (subs of Ramsay Engineering Co) 84/07/27 WRIGHT, B Assistant Director for Export/Import & International Safeguards 1p 26104 250

8408150163 License for Westinghouse to export 70 pieces of Inconel-600 steam generator tubing to United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MMH-529 84/08/06 1p 26104 001

8408150166 Amend 3 to import license for Edlow Intl Co for British Nuclear Fuels, Ltd, extending expiration date until 870101 & increasing quantity to 230 kg U
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/08 2pp 26103 361

8408150169 License for Exxon Nuclear Co, Inc to export 1,035 kg U-235, contained in 30,451 kg U, to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/08 2pp 26103 359

8408150179 Ltr of assurance re export of 749 kg U-235, contained in 24,229 kg U, to Japan
SHIRAKAWA, T Japan, Govt of 84/07/27 THORNE, C E Energy, Dept of 1p 26102 362

8408150182 Informs that License XSNM-2150 may be issued No matl changed circumstances since issuance of License XSNM-1975
MOORE, R N Assistant Director for Export/Import & International Safeguards 84/08/08 Assistant Director for Export/Import & International Safeguards 1p 26102 361

8408150237 Application for license to import max of 27,830 kg U as UF6, from France
HERSCH, M M Westinghouse Electric Corp MMH-536 84/08/07
MOORE, R N Assistant Director for Export/Import & International Safeguards 2pp 26102 359

8408150246 Requests Executive Branch position re Harnischfeger Corp application for license to export two electric overhead traveling cranes to China for use in Qinshan Nuclear Power Reactor
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/08 STOIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 26099 358

--8408150250 Application for license to export two electric overhead traveling cranes to China for use in Qinshan Nuclear Power Reactor
CHERONES, W J Harnischfeger Corp CNEC-84 84/07/25 1p
26099 359

8408150270 License for Exxon Nuclear Co, Inc to export 1,380 kg U-235, contained in 44,530 kg U, to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/08 2pp 26099 353

8408150359 Application for license to export 10 Ci spherical microshell glass or plastic pellets, containing elementary deuterium & tritium, to France
WIDMAN, J C KMS Fusion, Inc (Subs of KMS Industries, Inc)
EMSF-0684-EP 84/08/06 3pp 26099 360

--8408150361 Forwards application for license to export 10 Ci spherical microshell glass or plastic pellets, containing elementary deuterium & tritium, to France
WIDMAN, J C KMS Fusion, Inc (Subs of KMS Industries, Inc)
RSO-396-JCW 84/08/06 Assistant Director for Export/Import & International Safeguards 1p 26099 363

8408150402 Informs that License XSNM-2153 may be issued No matl changed circumstances since issuance of License XSNM-1975
MOORE, R N Assistant Director for Export/Import & International Safeguards 84/08/08 Assistant Director for Export/Import & International Safeguards 1p 26105 269

8408150642 Application for license to export two electric overhead traveling cranes to China
CHERDNES,W J Harnischfeger Corp CMEC-84 84/08/03 1p
26102 338

8408150703 Informs that License XSNM-2154 may be issued No matl changed circumstances since issuance of License XSNM-1973
MOORE,R N Assistant Director for Export/Import & International Safeguards 84/08/08 Assistant Director for Export/Import & International Safeguards 1p 26102 355

8408150705 Informs that Amend 1 to License XSNM-2124 may be issued No matl changed circumstances since issuance of License XSNM-2126
MOORE,R N Assistant Director for Export/Import & International Safeguards 84/08/08 Assistant Director for Export/Import & International Safeguards 1p 26102 354

8408150708 Amend 1 to Braunkohle Transport USA export license, authorizing increase from 15 kg U-235, contained in 307 kg U, to 77 kg U-235, contained in 1,533 kg U
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards HEX-EX-4 84/08/08 1p 26102 353

8408150713 Amend 2 to Delegation of Commission of European Communities export license, adding listed countries to license
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards AO/1576 84/08/08 1p 26102 352

8408150717 License for Exxon Nuclear Co, Inc to export 1,130 kg U-235, contained in 32,273 kg U, to Belgium
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 84/08/08 2pp 26102 350

8408150719 Application for license to export 47,108 kg U, containing 1,743 kg U-235, to France
HERSCH,M M Westinghouse Electric Corp MMH-532 84/08/02 1p
26102 349

8408150722 Application for license to export packing to South Korea
BUTLER,D L Borg-Warner Corp P60431N 84/08/07 1p 26102 348

8408150724 Application for license to export mechanical, hollow core, helix wrapped cable & slip ring assembly to Taiwan
HINKLE,K A Teleflex, Inc 019110 84/07/02 1p 26102 347

8408150726 Application for license to export 500 liters deuterium to Japan
* Matheson Gas Products NSK 73184 84/07/31 1p 26102 346

8408150730 Application for license to export two fission chambers to France
HERSCH,M M Westinghouse Electric Corp MMH 533 84/08/03 1p
26102 345

8408170220 Application to amend export license, extending period of performance for 2 addl yrs
MORGENSTERN,A Sigma Chemical Co 84/08/06 HEMBY,E Assistant Director for Export/Import & International Safeguards 1p
26134 318

8408170405 License for Mitsui & Co to export 749 kg U-235, contained in 24,229 kg U, to Japan
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards MBW-01-R2 84/08/13 2pp 26134 300

8408170406 Forwards application to export enriched UF6 to Japan
SHIBATA,Y Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5484-02 84/08/03 Assistant Director for Export/Import & International Safeguards 2pp 26134 297

--8408170408 Application for license to export 585 kg U-235, contained in 16,467 kg U, to Japan
SHIBATA,Y Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5484-02 84/08/03 1p 26134 299

8408170411 License for Mitsui & Co, Inc to export 208 kg U-235, contained in 7,206 kg U, to Japan
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards MBK-T2-R7 84/08/13 2pp 26134 295

8408170423 License for Edis Corp to export digital analog programmer having multi-phase electrical power output within range of 600 to 2,000 Hertz, to Italy
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards S D 51667 84/08/09 1p 26134 294

8408170424 Informs that License XSNM-2127 may be issued No matl changed circumstances since issuance of License XSNM-2131
MOORE,R N Assistant Director for Export/Import & International Safeguards 84/08/13 Assistant Director for Export/Import & International Safeguards 1p 26134 293

8408170425 Informs that License XSNM-2137 may be issued No matl changed circumstances since issuance of License XSNM-2131
MOORE,R N Assistant Director for Export/Import & International Safeguards 84/08/13 Assistant Director for Export/Import & International Safeguards 1p 26134 292

8408200150 License for Nuclear Valve Div of Borg-Warner Corp to export miscellaneous spare parts for use in valves, to South Korea
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards P60431 N 84/08/09 1p 26142 329

8408200160 License for Reactor Experiments, Inc to export 789 mg U-235, contained in 848 mg U, to Italy
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards ITAL-42695 84/08/09 2pp 26142 361

8408200189 Discusses 840807 application for license to export spare valve parts to South Korea License issued w/o normal 15-day waiting period
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 84/08/09 Assistant Director for Export/Import & International Safeguards 1p 26142 292

8408200314 Forwards end use statement re export of remote control measuring device to Taiwan
HINKLE,K Teleflex, Inc 84/08/06 HEMBY,E NRC - No Detailed Affiliation Given 2pp 26141 240

8408200450 License for California Instruments to export one Model 848TCM-3-4-1-2 oscillator & instruction manual to France
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 28326 84/08/14 1p 26144 327

8408200457 Application for license to export 503T ac power source & 850T-3 plug-in oscillator to France
LANE,M California Instruments 28439 84/08/09 1p 26143 361

8408200485 Requests Executive Branch position re Westinghouse application for license to export 47,108 kg enriched U to France
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 84/08/14 STOIBER,C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 26143 329

--8408200493 Application for license to export 1,743 kg U-235, contained in 47,108 kg U, to France
HERSCH,M M Westinghouse Electric Corp MMH-532 84/08/02 1p
26143 330

8408200537 Application for license to export power source, oscillator & frequency changers to United Kingdom
LANE,M California Instruments 28515 84/08/08 2pp 26143 289

8408200541 Application for license to export Model 850T-3-2467 plug-in oscillator & CCL4569B frequency changer to Austria
LANE,M California Instruments 28380 84/08/08 2pp 26143 283

8408200563 Forwards application to export zirconium tubing to Canada
BAUMGARD,R W Cabot Corp 1127V 84/08/09 HEMBY,E Assistant Director for Export/Import & International Safeguards 1p
26143 275

--8408200566 Application for license to export zirconium tubing to Canada
BAUMGARD,R W Cabot Corp 84494-00 84/08/09 1p 26143 276

8408200596 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 84/08/14 THORNE,C E Energy, Dept of 1p
26143 269

8408210084 Informs that polishing compound matls will be shipped to Iran, per recent telcon
PICIOCCHI,J M Gerard Kluyskens Co , Inc 84/08/08 MOORE,N NRC - No Detailed Affiliation Given 1p 26195 148

8408210164 Application for license to export 12 Type WX 33080 CO-SPN detectors to West Germany
HEEFNER,W Westinghouse Electric Corp ZE 10629 84/08/10 1p
26195 229

8408210169 Application for license to export six Type WX 33080 CO-SPN detectors to West Germany
HELFMER, W Westinghouse Electric Corp ZE 10628 84/08/10 1p 26195 221

8408220420 Amend 1 to Sigma Chemical Co export license, extending expiration date from 840901 to 860901
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards D-96 84/08/16 1p 26211 080

8408220421 License for Westinghouse to export two WL-8073 fission chambers to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MNH 533 84/08/20 1p 26211 082

8408220422 License for California Instruments to export power source, oscillator & instruction manuals to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 28046 84/08/17 1p 26211 081

8408220430 Requests Executive Branch views on KMS Fusion, Inc application to export deuterium & tritium to France
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/17 STOIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 26209 346

8408230464 Application for amend to export license, adding Blayais 3 reactor to end use of SNM in original application
DUBOIS, D European Communities, Commission of 84/08/13
THORNE, C E Energy, Dept of 1p 26230 254

8408230468 Application for amend to export license, requesting increase in max enrichment from 3 8% to 4 0% & providing intermediate consignee
WILSON, B D General Electric Co BDW-123-84 84/08/14
WRIGHT, B L Office of International Programs, Director 1p 26230 250

8408230469 Application for license to export 121 8 kg U to France & 81 2 kg U to West Germany
MCDONOUGH, M D Energy, Dept of 84-63 84/08/06 7pp 26230 243

8408230473 Application for license to export power sys, oscillator & other electrical equipment to Brazil
LANE, M California Instruments 27733 84/03/01 2pp 26230 217

8408230485 Application for license to export inverters, converters, generator, power source & oscillators to Brazil
LANE, M California Instruments 28131 84/03/29 2pp 26230 214

8408230488 Application for license to export zirconium fuel tubes & end plugs & stainless steel springs to Belgium
HERSCH, M M Westinghouse Electric Corp MMH-539 84/08/13 1p 26230 213

8408230493 Application for license to export inverters, converters, frequency changers, generators & oscillator to Switzerland
LANE, M California Instruments 27967 84/01/19 1p 26230 212

8408230498 Application for license to import 38,377 kg U as UF6, containing 1,344 kg U-235, from Belgium
HERSCH, M M Westinghouse Electric Corp MMH-540 84/08/13
MOORE, R N Assistant Director for Export/Import & International Safeguards 2pp 26230 210

8408230500 Application for license to export inverters, converters, frequency changers, generators, power source & oscillator to France
LANE, M California Instruments 28046 84/03/01 1p 26230 209

8408230505 Application for license to export 830T-4-2-4-1973 oscillator to United Kingdom
LANE, M California Instruments 28542 84/08/13 2pp 26230 207

8408230510 Application for license to export 38,377 kg U, containing 1,344 kg U-235, to Belgium
HERSCH, M M Westinghouse Electric Corp MMH-543 84/08/15 1p 26230 206

8408230513 Application for amend to export license, requesting increase in max enrichment from 3 95% to 4 0% & amending 840503 request
WILSON, B D General Electric Co BDW-122-84 84/08/14
WRIGHT, B L Office of International Programs, Director 1p 26230 205

8408230516 Amend 1 to Amersham Corp import license, adding 2 micrograms Pu-238 authorized for import from United Kingdom & extending expiration date from 840901 to 870901
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/17 1p 26230 204

8408230519 License for Brunswick Corp to export one NV 23-1 & one NV 23-2 check valve to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards NA2150 84/08/16 1p 26230 203

8408230525 License for Transnuclear, Inc to export 4 879 kg U-235, contained in 10 747 kg U, to Switzerland
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards NUK-441 84/08/15 2pp 26230 201

8408230530 License for Matheson Gas Products, Inc to export 90 g deuterium, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards NSK-73184 84/08/17 1p 26230 200

8408230535 Amend 2 to Ramsey Engineering Co export license, extending expiration date from 841001 to 871001
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/17 1p 26230 199

8408230560 Issues license to export frequency changers to France w/o customary 15-day waiting period
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/17 Assistant Director for Export/Import & International Safeguards 1p 26230 265

8408230562 Forwards application for export license to ship 623,939 kg U, containing 22,141 kg U-235, to Sweden
HANNETT, B A Transnuclear, Inc TNH-453 84/08/16 MOORE, N
Office of International Programs, Director 1p 26230 262

--8408230563 Application for license to export 623,939 kg U, containing 22,141 kg U-235, to Sweden
HANNETT, B A Transnuclear, Inc TNH-453 84/08/16 2pp 26230 263

8408310001 Requests ltr of assurance be obtained re DOE application for license to export low enriched U fuel to Federal Republic of Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/21 THORNE, C E Energy, Dept of 1p 26350 206

--8408310005 Application for license to export 203 kg U metal to Federal Republic of Germany
MCDONOUGH, M D Energy, Dept of 84-63 84/08/06 7pp 26350 207

8408310006 Requests ltr of assurance be obtained re Westinghouse application for license to export 1,344 kg U-235, contained in 38,377 kg UF-6, to Belgium
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/20 THORNE, C E Energy, Dept of 2pp 26350 200

8408310019 Forwards Dupont NEN Products application for export license for minor nuclear export Ltr of assurance required
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/24 STOIBER, C R Energy, Dept of 1p 26350 190

--8408310025 Application for license to export tritium gas net 092 in breakseal tubes to Chile
DUMAS, D E I du Pont de Nemours & Co , Inc 84/08/08 1p 26350 191

8408310178 License for Thorn EMI Gencom, Inc to import 30 mg Pu-238 from United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/24 1p 26351 339

8408310180 Application for license to export inverters, converters, frequency changers & generators to Switzerland
HALUB, P Elgar Corp 17176 84/08/21 1p 26352 041

8408310303 Application for license to export H-3 gas in breakseal tube to Australia
DUMAS, D E I du Pont de Nemours & Co , Inc 84/08/08 1p 26350 300

8408310307 Application to amend export license, extending expiration date until 890831 & increasing amount to 100 kg
BROWN, L R Edlow International Co 84/08/21 WRIGHT, B Assistant Director for Export/Import & International Safeguards 1p
26350 301

8408310310 Application for license to export 40 tubes, made from Zirconia, to Canada
AERNI, B L Teledyne Geotech 1107 (RFH) 84/08/15 1p
26350 306

8408310317 Requests Executive Branch position re Transnuclear, Inc application for license to export 22,141 170 kg U-235, in form of UF6 to Sweden
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/08/21 THORNE, C E Energy, Dept of 1p
26350 302

--8408310321 Application for license to export 22,141 170 kg U-235, in form of UF6, to Sweden
HANNETT, B A Transnuclear, Inc TNH-453 84/08/16 2pp
26350 303

--8408310325 Forwards application to export 22,141 170 kg U-235 to Sweden
HANNETT, B A Transnuclear, Inc TNH-453 84/08/16 MOORE, N
Assistant Director for Export/Import & International Safeguards
1p 26350 305

8408310330 License for Teleflex, Inc to export 1 cable, mechanical, hollow core helix wrapped P/N 22695-164-9 & 3 slip ring assemblies
P/N 80095-1 to Taiwan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 019110 84/08/21 1p 26350 312

8408310337 Application for license to export Pu-239 in Model CS-1 alpha check source Pu-239 & Model S94-4 alpha calibr std set, to Republic of Korea
ESPINOSA, G Eberline Instrument Corp SO ND 809804 84/08/14 1p
26350 311

8408310341 License for DOE to export 2 kg Pu & 12 kg depleted U to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83-74 84/08/21 2pp 26350 309

8408310448 Application for license to export 24 Ci tritium gas, in glass break seal ampoule, to Japan
DUMAS, D E I du Pont de Nemours & Co, Inc 84/08/08 1p
26350 131

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AADLAND, J D	8408140433*	50-313 P
ABELSON, H I	8408010140	50-333 P
ABELSON, H I	8408150609	50-333 P
ABRAMOVICI, J D	8408270290*	50-219 P
ADAMS, F T	8408230122*	50-261 P
ADENSAM, E G	8202040352*	50-329 A
ADENSAM, E G	8205120033*	50-329 A
ADENSAM, E G	8206290161*	50-329 A
ADENSAM, E G	8210150698*	50-329 A
ADENSAM, E G	8408130177*	50-413 P
ADENSAM, E G	8408130230*	50-329 A
ADENSAM, E G	8408300385	50-328 P
ADENSAM, E G	8408300387*	50-328 P
ADENSAM, E G	8408310448	50-424 E
AERNI, B L	8408310310	XPORTLIC
AFIFI, S S	8408140076*	50-329 A
AKI, K	8408210046*	50-206 P
ALARCON, E	8408080168*	50-445 Q
ALBRIGHT, R H	8408280289*	70-1201
ALBRIGHT, R H	8408300206*	70-824
ALDRICH, L R	8408060227	50-374 S
ALDRICH, L R	8408090324	50-373 S
ALESIO, W G	8408080144	40-8681
ALEXANDER, G	8408160415	50-454 A
ALEXANDER, G L	8408150098	50-237 Q
ALEXANDER, G L	8408200331	50-237 Q
ALEXANDER, G L	8408270087	50-295 Q
ALEXANDER, G L	8408270114	50-237 P
ALEXANDER, G L	8408280119	50-295 P
ALEXICH, M P	8408060076	50-315 P
ALEXICH, M P	8408060118	50-315 F
ALEXICH, M P	8408060348	50-315 F
ALEXICH, M P	8408080084	50-315 Q
ALEXICH, M P	8408100094	50-315 F
ALEXICH, M P	8408140164	50-315 P
ALEXICH, M P	8408160188	50-315 P
ALEXICH, M P	8408170322	50-315 F
ALEXICH, M P	8408240121	50-316 P
ALEXICH, M P	8408240188	50-315 P
ALLEN, J A	8408210361*	50-382 A
ALLEN, M H	8408080498	50-219 S
ALZHEIMER, J M	8408060405	50-206 S
ANAND, R	8408060323*	50-382 Q
ANDERSON, C D	8408300108*	50-10 Q
ANDERSON, C J	8408080256*	50-289 Q
ANDERSON, C J	8408090330*	50-322 Q
ANDERSON, C J	8408150110*	50-336 Q
ANDERSON, C J	8408160246*	50-245 Q
ANDERSON, C J	8408200504*	50-354 Q
ANDERSON, C J	8408210501*	50-245 Q
ANDERSON, D L	8408080100	50-445 T
ANDERSON, F D	8408130011	50-413 P
ANDERSON, J	8408140352*	50-329 A
ANDERSON, J J	8408010317	50-286 S
ANDERSON, J J	8408240048	50-286 S
ANDERSON, R N	8408020129	50-322 T
ANDERSON, R N	8408140017*	50-322 T
ANDREWS, R L	8408060289	50-285 S
ANDREWS, R L	8408070128	50-285 P
ANDREWS, R L	8408090401	50-285 S
ANDREWS, R L	8408090405	50-285 S
ANDREWS, R L	8408100104	50-285 P
ANDREWS, R L	8408150136	71-256
ANDREWS, R L	8408200589	50-285 R
ANDREWS, R L	8408240230	50-285 S
ANDREWS, R L	8408270244	50-285 P
ANDREWS, R L	8408280288	50-285 S
ANDREWS, R L	8408280343	50-285 S
ANDRUS, N J	8408270361	40-4492
ANDRUS, N J	8408310338	40-4492
ANTHONY, B	8408130210*	50-416 U
ANTHONY, R L	8408080191	50-352 Q
ANTHONY, R L	8408080191	50-352 G
ANTHONY, R L	8408090263*	50-352 Q
ANTHONY, R L	8408280491	50-352 Q
ANTHONY, R L	8408280491	50-352 Q
ANTHONY, R L	8408310096	50-352 Q
ANTHONY, R L	8408310096	50-352 G
ARAND, J	8408060255	50-373 S
ARCHER, C D	8408310262*	CONTRACT
ARMBRUST, A J	8408060026	27-39
ARNOLD, K D	8408060197*	50-70 Q
ARNOLD, W D	8408300282	NUREG
ASARS, A	8408100035	50-29 S
ASHE, F	8408310365	50-317 S
ASHE, F	8408310370*	50-317 S
ASSELSTINE, J K	8408130333*	50-382 Q
ASSELSTINE, J K	8408200225	50-369 U
ASTLEY, E R	8408010142	XPORTLIC
AU, T Y	8408140131	50-289 Q
AUGUST, B K	8408060179	50-352 Q
AUSMUS, B B	8408020070*	50-133 P
AUSTIN, G	8408160122	50-295 R
AUSTIN, M A	8408010020	70-364
AUSTIN, M A	8408150657	70-364
AUSTIN, P N	8408290190	NUREG
AUSTIN, P N	8408290198	NUREG
AWTREY, P H	8408210093	71-39
AXELRAD, J	8407110250	I&E
AXELRAD, J	8408010162	50-388 Q
AXELRAD, J	8408010164	50-280 Q
AXELRAD, J	8408010251	I&E
AXELRAD, J	8408210407	I&E
AXELRAD, J	8408240357	I&E
AXELRAD, J	8408280068	I&E
AXELRAD, J	8408280073	I&E
AXELRAD, J	8408290120	I&E
AXELRAD, J	8408300146	50-261 Q
AXELRAD, J A	8408130257	70-143
AXELRAD, J A	8408130431	50-275 Q
AXELRAD, J A	8408150640*	50-329
AXELRAD, J A	8408230070	50-277
AXELRAD, J A	8408240104	50-289
AXELRAD, J A	8408240108	50-387
AXELRAD, J A	8408240343	50-331
AXELRAD, M	8408310247	50-275
AXELSON, W L	8408020020	50-315
AXELSON, W L	8408020052	I&E
AXELSON, W L	8408060024	50-341
AXELSON, W L	8408070050	50-315
AXELSON, W L	8408070329	I&E
AXELSON, W L	8408070464	50-331
AXELSON, W L	8408100029	50-282
AXELSON, W L	8408130153	50-341
AXELSON, W L	8408130180	70-2872
AXELSON, W L	8408130370	50-155
AXELSON, W L	8408170198	50-266
AXELSON, W L	8408200230	50-373
AXELSON, W L	8408200248	50-254
AXELSON, W L	8408200281	50-10
AXELSON, W L	8408200319	50-255
AXELSON, W L	8408200345	50-295
AXELSON, W L	8408210470	50-461
AXELSON, W L	8408210491	70-2838
AZARM, M A	8408220333	50-352
BAARS, R E	8408080357	NUREG
BAATZ, H	8408090562	PROJ
BABBITT, D L	8408060214*	CONTRACT
BABCOCK, C D	8408100153	NUREG
BACANSKAS, V P	8404040078*	50-368
BACHMANN, R G	8408270186*	50-445
BAER, R L	8408140461	50-27
BAER, R L	8408150466	I&E
BAER, R L	8408160515*	50-458
BAGBY, L A	8408080532	XPORTLIC
BAILEY, M W	8408130456	50-304
BAILEY, R J	8408030192*	50-410
BAILEY, R J	8408060352	50-277
BAILEY, R J	8408150424*	50-277
BAILEY, R J	8408150721*	50-317
BAILEYS, T P	8408090439	50-387
BAIR, A	8408130278	71-184
BAIR, A	8408130283*	71-184
BAIR, G G	8408280147	50-344
BAISDEN, L	8408070080	CONTRACT
BAKER, E	8408240140*	QA999
BAKER, K R	8408060151	50-316
BAKER, K R	8408160127	50-316
BAKER, K R	8408220486	50-315
BAKER, R H	8408090046*	CONTRACT
BAKER, W E	8408100153	NUREG
BAKSHI, A	8408020129	50-322
BALL, D G	8408080415	NUREG
BALL, S J	8408130001	NUREG
BALLARD, R L	8309270366*	50-329

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BALLINGER, P L	8408240072	50-298 S
BANDHAUER, W K	8408060306	50-302 S
BANDHAUER, W K	8408140247	50-302 S
BANDHAUER, W K	8408200346	50-302 S
BANDHAUER, W K	8408230424	50-302 S
BANDHAUER, W K	8408230430	50-302 S
BANDY, R	8408070014	NUREG
BANGART, R L	8408100042	50-445 Q
BANGART, R L	8408100050	50-445 A
BANGART, R L	8408140383	50-445 A
BANGART, R L	8408150091	50-445 Q
BANGART, R L	8408150414	50-445 Q
BANGART, R L	8408150649	50-445 Q
BANGART, R L	8408160026	50-445 Q
BANGART, R L	8408160201	50-445 Q
BANGART, R L	8408160485	50-445 Q
BANGART, R L	8408210148	50-445 F
BANGART, R L	8408230147	50-445 Q
BANKS, H R.	8408140151*	50-400 T
BARANOWSKY, P W	8407170313	NUREG
BARANOWSKY, P W	8407170316*	NUREG
BARBOUR, J O	8408280205	50-413 T
BARHAM, C D.	8408210027	50-400 J
BARI, R A	8408220333	50-352 A
BARKHURST, R P	8408210361*	50-382 A
BARLETTA, R E	8408010151	NUREG
BARLOW, G	8408060183	50-70 Q
BARLOW, G	8408060191*	50-70 Q
BARLOW, G	8408060197*	50-70 Q
BARLOW, G	8408060206*	50-70 Q
BARNES, I	8408010372*	GA999
BARNES, I	8408090130*	50-313 Q
BARNES, I	8408230013*	50-298 Q
BARNES, L	8408080027	50-445 T
BARR, S	8408230527	50-269 P
BARRETT, L H	8408070136	WASTE MGT
BARRETT, L H	8408230036	WASTE MGT
BARRETT, L H	8408230069	WASTE MGT
BARRETT, L H	8408240378	WASTE MGT
BARTH, C A	8408090170	50-400 Q
BARTH, C A	8408090224	50-400 Q
BARTH, C A	8408140064	50-400 T
BARTH, C A	8408280439	50-400 Q
BARTHOLOMEW, R	8408070282*	50-305 F
BARTLETT, D	8408140163*	50-329 A
BARZANO, W J	8408070311	40-2061
BARZANO, W J	8408130329	40-2061
BARZANO, W J	8408130337*	40-2061
BASKIN, K P	8408090187	50-361 P
BASKIN, K P.	8408090194*	50-361 P
BASKIN, K P	8408130203	50-206 Q
BATEMAN, W H	8408200366*	50-354 Q
BATES, J G	8408030068*	50-329 A
BATES, J W	8408270427*	70-143
BATES, J W	8408300401*	70-27
BATES, J W	8408310255*	70-1151
BATSEL, J	8408060197*	50-70 Q
BAUBLITZ, J E	8408140289	WASTE MGT
BAUBLITZ, J E	8408220232	WASTE MGT
BAUM, A	8408300237*	50-289 P
BAUMGARD, R W	8408200563	XPORTLIC
BAUMGARD, R W	8408200566*	XPORTLIC
BAUNACK, W	8408150271*	50-289 Q
BAUNACK, W	8408210381*	50-352 Q
BAUSER, D B	8408080217	50-400 Q
BAUSER, D B	8408080217	50-400 Q
BAUSER, D B.	8408130300	50-289 Q
BAUSER, D B	8408130300	50-289 Q
BAUSER, D B	8408200468	50-289 Q
BAUSER, D B	8408200468	50-289 Q
BAUSER, D B	8408200515	50-289 Q
BAUSER, D B	8408200515	50-289 Q
BAUSER, D B	8408270115	50-289 Q
BAUSER, D B	8408270115	50-289 Q
BAUSER, D B	8408310207	50-289 Q
BAUSER, D B	8408310207	50-289 Q
BAUSER, M A	8408070453	PRM
BAUSER, M A	8408140214	50-250 Q
BAUSER, M A	8408140214	50-250 Q
BAUSER, M A	8408140220*	50-250 Q
BAUSER, M A	8408140220*	50-250 Q
BAUSER, M A	8408140236*	50-250 Q
BAUSER, M A	8408140236*	50-250 Q
BAUSER, M A	8408140236*	50-250 Q
BAUSER, M A	8408140253*	50-250 Q
BAUSER, M A	8408140253*	50-250 Q
BAUSER, M A	8408140253*	50-250 Q
BAUSER, M A	8408140271*	50-250 Q
BAUSER, M A	8408140271*	50-250 Q
BAUSER, M A	8408140277*	50-250 Q
BAUSER, M A	8408140277*	50-250 Q
BAUSER, M A	8408140277*	50-250 Q
BAXTER, T A	8408140014	50-400 T
BAXTER, T A	8408140014	50-400 T
BAYLESS, R S	8407100420	50-263 S
BAYNARD, P Y	8408240155	50-302 F
BAYNARD, P Y	8408270211*	50-302 Q
BAYNE, J P	8408010319	50-333 P
BAYNE, J P	8408010321*	50-333 P
BAYNE, J P	8408070364	50-333 P
BAYNE, J P	8408070417	50-333 P
BAYNE, J P	8408070423*	50-333 P
BAYNE, J P	8408100087	50-333 F
BAYNE, J P	8408130309	50-286 F
BAYNE, J P	8408150147	71-240
BAYNE, J P	8408150230	50-286 F
BAYNE, J P	8408170277	50-286 P
BAYNE, J P	8408210436*	50-333 Q
BAYNE, J P	8408210443	50-286 P
BAYNE, J P	8408210449*	50-286 P
BAYNE, J P	8408220224	50-333 P
BAYNE, J P	8408230164	50-286 F
BAYNE, J P	8408240145	50-333 P
BAYNE, J P	8408310095	50-333 P
BEACH, A B	8408170117*	50-443 Q
BEACH, A B	8408170117*	50-443 Q
BEACH, A B	8408170117*	50-443 Q
BEACH, D L	8408310165*	50-255 Q
BEACH, G	8408240374	WASTE MGT
BEASLEY, D	8408200288*	50-528 S
BEATTY, G P	8408030234	50-261 P
BEATTY, G P	8408140151*	50-400 T
BEAVER, J	8408300031	50-320 P
BEAVER, J R	8408140197	50-320 F
BECK, G P	8408030276	50-151 F
BECK, G P	8408300184	50-151 S
BECKER, B D	8405250241	50-454 Q
BECKER, B D	8405250241	50-454 Q
BECKHAM, D	8408150431	50-483 Q
BECKHAM, J T	8408100045	50-366 P
BECKHAM, J T	8408130561	50-321 P
BECKHAM, J T	8408140106	50-321 P
BEHRENS, P A	8408300308*	50-254 R
BELANGER, J L	8408100037*	50-282 Q
BELCHER, R L	8408220172	50-166 R
BELISLE, G A	8408270221*	50-335 Q
BELISLE, G A	8408270492*	50-413 Q
BELKE, W	8408150515*	50-382 Q
BELL, J	8408200023*	50-289 Q
BELL, M J	8408160055	WASTE MGT
BELL, N	8408140417	NUREG
BELLAMY, R	8408030209	50-333 Q
BELLAMY, R R	8408030236	50-272 Q
BELTER, L W	8408220331	50-445 Q
BELTER, L W	8408220331	50-445 Q
BELTER, L W	8408220336	50-445 Q
BELTER, L W	8408270154	50-445 Q
BELTER, L W	8408270154	50-445 Q
BEMIS, P	8408270572*	50-395 Q
BEMIS, P R	8408140070*	50-400 T
BEMIS, P R	8408140081*	50-400 T
BEMIS, P R.	8408140086*	50-400 T
BEMIS, P R.	8408270536*	50-261 Q
BENDER, M	8408020213	ACRS
BENDER, M	8408020213	ACRS
BENDER, M	8408020244	ACRS
BENDER, M	8408020244	ACRS
BENEDICK, W. B	8408100155	NUREG
BENNETT, J Q	8408100153	NUREG
BENNETT, J P	8408130402	PR
BENNETT, J W	8408220122	WASTE MGT
BERG, R E	8408270028	40-8585
BERGAN, Q W	8408060100	50-237 S
BERGAN, Q W	8408200519	50-249 S
BERGER, D	8408310238	50-289 P
BERGER, J D	8408020225*	70-8
BERKOVITZ, D M	8408150686*	50-329 A
BERLINGER, C H	8408280109	50-206 Q
BERMAN, M	8408100152	NUREG
BERMAN, M	8408130006	NUREG
BERNABEI, L	8408060224*	50-289 Q
BERNABEI, L	8408060201	50-289 Q
BERNABEI, L	8408060201	50-289 Q
BERNABEI, L	8408060224*	50-289 Q
BERNABEI, L	8408070408	50-289 Q
BERNABEI, L	8408070408	50-289 Q
BERNABEI, L	8408140479	50-289 Q
BERNABEI, L	8408140479	50-289 Q
BERNABEI, L	8408220258	50-289 Q
BERNABEI, L	8408220258	50-289 Q
BERNABEI, L	8408220263*	50-289 Q
BERNABEI, L	8408220263*	50-289 Q
BERNABEI, L	8408220366	50-289 Q
BERNABEI, L	8408220366	50-289 Q
BERNABEI, L	8408240251	50-289 Q
BERNABEI, L	8408240251	50-289 Q
BERNABEI, L	8408310106	50-382 Q
BERNABEI, L	8408310106	50-382 Q
BERNABEI, L	8408310106	50-382 Q
BERNABEI, L	8408070382	50-289 Q
BERNABEI, L	8408070382	50-289 Q
BERNHOFT, S	8408060244	50-305 Q
BERNHOFT, S	8408080510	50-305 Q
BERNTHAL, F	8408200486	50-348 M
BERNTHAL, F M	8408290356	COMMISSION
BERRY, D L	8408240320	NUREG
BERRY, J A	8408080466*	50-245 Q
BERRY, R B	8408220307	50-269 Q
BESS, J	8408150515*	50-382 Q
BESS, J E	8408290108*	50-458 Q
BETHUNE, E	8408070215*	50-416 Q
BETTENHAUSEN, L	8408080461*	50-220 Q
BETTENHAUSEN, L	8408080478*	50-322 Q
BETTENHAUSEN, L	8408080490*	50-289 Q
BETTENHAUSEN, L	8408080530*	50-352 Q
BETTENHAUSEN, L	8408130410*	50-289 Q
BETTENHAUSEN, L	8408160119*	50-317 Q
BETTENHAUSEN, L	8408160432*	50-245 Q
BEVAN, R B	8408060425	50-237 P
BEVAN, R B	8408150588	50-254 P
BEVILL, M	8408010025	71-9163
BEYEA, J	8408310157*	50-289 P
BEYEA, J	8408310239*	50-289 P
BIBB, H E	8408270363*	50-335 Q
BICEHOUSE, H J	8408230136*	50-277 Q
BIDINGER, G H	8408290338	50-458 A
BIGGS, C	8408080297	50-445 1
BIRCH, M L	8408270169*	50-269 P
BIRD, N	8408150608*	50-329 A
BISHOP, E	8408210268*	50-331 I
BISHOP, T W	8408010278	50-344 Q
BISHOP, T W	8408030262	50-344 Q
BISHOP, T W	8408070324	50-275 Q
BISHOP, T W	8408070531	50-275 P
BISHOP, T W	8408070532*	50-275 P
BISHOP, T W	8408080491	50-275 Q
BISHOP, T W	8408080494	50-344 Q
BISHOP, T W	8408090016	50-397 Q
BISHOP, T W	8408090043	50-361 Q
BISHOP, T W	8408200313	50-275 Q
BISHOP, T W	8408220051	50-528 Q
BISHOP, T W	8408270325	50-206 P
BISHOP, T W	8408270349	50-206 Q
BISHOP, T W	8408290168	50-397 Q
BISHOP, T W	8408300094	50-528 Q
BISHOP, T W	8408300110	50-312 Q
BISHOP, T W	8408300140	50-275 Q
BISHOP, T W	8408300187	50-528 Q
BISHOP, T W	8408300248	50-312 Q
BISHOP, T W	8408300373	50-344 Q
BISHOP, T W	8408300383	50-528 Q
BISHOP, T W	8408300446	50-397 Q
BISSETT, P	8408080166*	50-387 Q
BISSETT, P	8408090330*	50-322 Q
BITTNER, R	8408070564*	PROJ
BLACK, K M	8408060200*	50-416 S
BLACKFORD, M	8408220167	WASTE MGT
BLAKE, E L	8408020042	50-269 Q
BLAKE, E L	8408020042	50-269 Q
BLAKE, E L	8408150458	50-269 Q
BLAKE, E L	8408200557	50-289 Q
BLAKE, E L	8408200557	50-289 Q
BLAKE, J J	8408140081*	50-400 Q
BLAKE, J J	8408240342*	50-259 Q
BLAKE, J J	8408240366*	50-321 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BLAKE, J J	8408270240*	50-438 Q
BLAKE, J J	8408270275*	50-417 Q
BLAKE, J J	8408270388*	50-338 Q
BLAKE, J J	8408270469*	50-390 Q
BLAKE, J J	8408280046*	50-261 Q
BLAKE, J J	8408280091*	50-400 Q
BLAKE, J J	8408280393*	50-413 Q
BLAKE, J J	8408290039*	50-261 Q
BLAKE, R	8408280203*	50-412 E
BLANCHARD, B	8408210213	50-354 D
BLAND, J S	8408070462*	PRM
BLANKLEY, W E	8408030175	GA999
BLATT, M	8408200539	50-247 S
BLATT, M	8408220214	50-247 S
BLEVEL, W H	8408170321*	50-454 T
BLIND, A A	8408130307	50-316 S
BLOCH, P B	8408280255	50-445 Q
BLOCH, P B	8408280391	50-155 Q
BLOUGH, A R	8408150244*	50-277 Q
BLUBAUGH, R E	8408240056	40-3453
BLUHM, R B	8408200334*	50-528 F
BLUMBERG, N	8408080478*	50-322 Q
BLUMBERG, N	8408160115*	50-317 Q
BLUME, M	8408020177*	50-329 Q
BLUMENTHAL, A	8408280093	PR
BOARDMAN, J R	8408150375*	50-313 Q
BOARDMAN, J R	8408220256*	50-382 Q
BOARDMAN, J R	8408270500*	50-298 Q*
BOCCIO, J L	8408220333	50-352 A
BOGDEN, Q	8408270038	40-8684
BOGDEN, Q	8408270131	40-1162
BOGGS, R S	8408060231*	50-328 P
BOLANDER, M A	8408160248	50-269 P
BOLSTAD, J W	8408160146	NUREG
BOMBERGER, C	8407300136*	50-213 P
BOMBERGER, C R	8408280321*	50-346 P
BONNIES, Q	8408270576*	CONTRACT
BOOKER, J E	8408010004	50-458 S
BOOKER, J E	8408010012	50-458 S
BOOKER, J E	8408010241	50-458 Q
BOOKER, J E	8408020025	50-458 S
BOOKER, J E	8408060028	50-458 A
BOOKER, J E	8408060147	50-458 E
BOOKER, J E	8408070520	50-458 S
BOOKER, J E	8408070529	50-458 S
BOOKER, J E	8408080199	50-458 S
BOOKER, J E	8408080236	50-458 S
BOOKER, J E	8408080471	50-458 S
BOOKER, J E	8408100068	50-458 Q
BOOKER, J E	8408100108	50-458 Q
BOOKER, J E	8408140340	50-458 E
BOOKER, J E	8408140421	50-458 A
BOOKER, J E	8408140554	50-458 S
BOOKER, J E	8408150152	50-458 S
BOOKER, J E	8408150162	50-458 S
BOOKER, J E,	8408150177	50-458 S
BOOKER, J E,	8408150308	50-458 S
BOOKER, J E	8408150385	50-458 S
BOOKER, J E	8408150691	50-458 S
BOOKER, J E	8408150704	50-458 S
BOOKER, J E	8408150707	50-458 S
BOOKER, J E	8408160194	50-458 S
BOOKER, J E	8408160242	50-458 S
BOOKER, J E	8408160386	50-458 A
BOOKER, J E	8408210490	50-458 A
BOOKER, J E	8408220504	50-458 S
BOOKER, J E	8408220505	50-458 S
BOOKER, J E	8408220511	50-458 S
BOOKER, J E	8408230538	50-458 S
BOOKER, J E	8408240310	50-458 S
BOOKER, J E	8408240404	50-458 S
BOOKER, J E	8408240426	50-458 C
BOOKER, J E	8408280408	50-458 S
BOOKER, J E	8408280414	50-458 S
BOOKER, J E	8408280416	50-458 S
BOOKER, J E	8408280428	50-458 S
BOOKER, J E	8408280446	50-458 S
BOOKER, J E	8408280458	50-458 S
BOOKER, J E	8408300343	50-458 S
BOOKER, J E	8408300494	50-458 S
BOOKER, J E	8408300507	50-458 S
BOOKER, J E	8408310087	50-458 S
BOOKER, J E.	8408310172	50-458 E
BOOS, A J.	8408150608*	50-329 A
BOOTH, D W	8408240242*	50-413 I
BORDENICK, B M	8408010254	50-322 Q
BORDENICK, B M	8408070395	50-322 Q
BORDENICK, B M	8408090161	50-322 Q
BORDENICK, B M	8408090210	50-322 Q
BORDENICK, B M	8408150090	50-322 Q
BORDINE, T C	8408270127	50-255 S
BORDINE, T C	8408270130	50-255 S
BORDINE, T C	8408280003*	50-255 Q
BOREN, A	8408080245	50-445 T
BOSKEY, B	8408080197	50-348 M
BOSKEY, B	8408080197	50-348 M
BOSKEY, B	8408080202	50-348 M
BOSKEY, B	8408080202	50-348 M
BOSKEY, B	8408080241	50-348 M
BOSKEY, B	8408080241	50-348 M
BOSTED, C	8408300195*	50-528 Q
BOULAY, R J	8408210477	State Prog
BOURASSA, L	8408310154	PR
BOWERS, H	8408310035*	50-275 P
BOYD, D C	8408010402*	50-263 Q
BOYD, D C	8408030179*	50-155 Q
BOYD, D C	8408230238*	50-409 Q
BOYD, D C	8408230497*	50-263 Q
BOYER, R E	8408230229	GA999
BOYER, V S	8408020075*	50-352 A
BOYER, V S	8408070433*	50-352 Q
BOYER, V S	8408070450*	50-352 Q
BOYER, V S	8408210389	50-277 P
BOYLE, L A	8408310071	50-249 S
BOYLE, M L	8408210573	50-29 P
BRADBURY, J W	8408280005	WASTE MGT
BRADFORD, L	8408140010	50-289 Q
BRADLEY, E J	8408020058	50-352 A
BRADLEY, E J	8408070033	50-352 A
BRADLEY, E J	8408210074	50-352 K
BRADLEY, E J	8408280272	50-278 P
BRADLEY, E J	8408280273*	50-278 P
BRANCH, C W	8408080064*	CONTRACT
BRANCH, E B	8408310194*	50-454 T
BRANCO, J C	8408160486	50-354 D
BRANDENBURG, B	8408140493	50-247 Q
BRANDENBURG, B	8408170270	50-247 Q
BRANDON, R J	8408170262*	50-263 P
BRANDON, R J	8408270175*	50-331 P
BREDES, N	8408020002	50-322 Q
BREEN, W	8408130405	50-304 S
BRENNEMAN, F	8408310041	I&E
BRENNER, L	8408030085	50-322 Q
BRENNER, L	8408090490	50-322 Q
BRENNER, L	8408150142	50-322 Q
BRENNER, L	8408150155	50-322 Q
BRENNER, L	8408150183	50-352 Q
BRENNER, L	8408170305	50-352 Q
BRENNER, L	8408170332	50-322 Q
BRENNER, L	8408220342	50-322 Q
BRENNER, L	8408230200	50-352 Q
BRENNER, L	8408270364	50-322 Q
BRENNER, L	8408280162	50-352 Q
BRENNER, L	8408300168	50-352 Q
BRICH, R F	8408240391	40-1341
BRICH, R F	8408270056	40-1341
BRIDENBAUGH, D	8408020129	50-322 T
BRIGATI, J J	8408130341	50-322 Q
BRIGATI, J J	8408210388	50-322 Q
BRIGATI, J J	8408210388	50-322 Q
BRIGGS, L E	8408080530*	50-352 Q
BRIGHT, Q Q	8408070293	50-400 Q
BRINKMAN, D S	8408270559	TOPREP
BRITT, R W	8408020155*	50-266 F
BRITT, R W	8408060127	50-266 P
BRITT, R W	8408070030	50-266 P
BRITT, R W	8408070245	50-266 P
BRITT, R W	8408070328	50-266 P
BROCK, B L	8408080151*	70-734
BROCK, B L	8408090122*	70-984
BROCK, B L	8408130511*	70-1297
BROMBERG, B	8408240089	CONTRACT
BROMBERG, B J	8408080476	CONTRACT
BRONS, J C	8408010317	50-286 S
BRONS, J C	8408230428	50-286 R
BRONS, J C	8408240048	50-286 S
BRONS, J C	8408310177	50-286 Q
BROOKS, D J	8408200470	WASTE MGT
BROOKS, P P	8408280031	WASTE MANA
BROWN, C H	8408230149*	50-409 Q
BROWN, E M	8408020187*	50-329 Q
BROWN, J E	8408220393*	50-445 T
BROWN, J E	8408220393*	50-445 T
BROWN, L R	8408310307	XPORTLIC
BROWN, N D	8408280179	50-289 F
BROWN, S R	8408240382	NUREG
BROWN, W B	8408080324	70-371
BROWN, W B	8408080386	70-1151
BROWN, W B	8408080391	70-734
BROWN, W B	8408080393	70-143
BROWN, W B	8408080425	70-734
BROWN, W B	8408080435	70-1257
BROWN, W B	8408160064	70-1151
BROWN, W L	8408240395	40-8829
BROWNING, R E	8408010043	WASTE MGT
BROWNING, R E	8408060163	WASTE MGT
BROWNING, R E	8408150337	WASTE MGT
BROWNING, R E	8408150568	WASTE MGT
BROWNLEE, V L	8408140324	50-370 S
BROWNLEE, V L	8408230001	50-370 S
BROWNLEE, V L	8408240290	50-370 S
BROWNLEE, V L	8408240329	50-369 S
BROWNLEE, V L	8408240421*	50-269 Q
BROWNLEE, V L	8408270279*	50-369 Q
BROWNLEE, V L	8408280158	50-369 S
BRUCIAK, J D	8408060042	50-374 S
BRUCIAK, J D	8408230533	50-374 S
BRUGGER, R M	8408220337	PR
BRUNNER, J E	8408140573*	50-329 A
BRUNNER, J E	8408150577*	50-329 A
BRUNNER, J E	8408150586*	50-329 A
BRUND, G E	8408140273	50-275 D
BRYAN, D C	8408150135	XPORTLIC
BRYANT, J	8408240421*	50-269 Q
BRYSON, M C	8408240249	NUREG
BUCHANAN, J K	8408310194*	50-454 T
BUCKALEW, W H	8408080367	NUREG
BUCKLEY, B	8408090473	50-400 F
BUCKLEY, B.	8408230364	50-400 A
BUCKLEY, J T	8408240119	WASTE MANA
BURDOIN, J F.	8408080513*	50-275 Q
BURDOIN, J F	8408300133*	50-312 Q
BURGER, F J	8408270152	50-271 R
BURGESS, B L	8408170268*	50-329 F
BURKE, D J	8408270456*	50-280 Q
BURNETT, P T	8408280049*	50-390 Q
BURNS, J J	8309220362*	50-295 P
BURNS, J J	8408280400*	50-295 P
BURNS, S	8408070273	50-445 T
BURNS, S G	8408150062	40-2061
BURRELL, N K	8408150476*	50-322 T
BURWELL, S B	8408060153	50-445 A
BURWELL, S B	8408090435	50-445 Q
BURWELL, S B	8408090451	50-445 F
BURWELL, S B	8408160501	50-445 T
BURWELL, S B	8408200156	50-445 A
BURWELL, S B	8408210561	50-445 Q
BURWELL, S B	8408270565	50-445 A
BUSCHBOM, R L	8408310075	NUREG
BUSH, K J	8408310335*	WASTE MGT
BUSH, K J	8408310339*	WASTE MGT
BUSH, M W	8408220379	50-352 Q
BUTCHER, E	8408300219*	50-366 P
BUTCHER, R C	8408230040	50-259 S
BUTCHER, R C	8408310114*	50-259 Q
BUTLER, D	8408230252*	50-454 Q
BUTLER, D	8408270277*	50-454 Q
BUTLER, D L	8408150722	XPORTLIC
BUTLER, S D	8408270382*	50-327 Q
BYRD, R W	8408060030	50-416 S
BYRD, R W	8408060193*	50-416 S
BYRD, R W	8408080538	50-416 S
BYRD, R W.	8408160175	50-416 S
BYRD, R W	8408240210	50-416 S
BYRD, R W	8408300490	50-416 S
CABELL, A B	8408130027*	71-83
CAHILL, W J.	8408140095*	50-458 Q
CAIN, J M	8408020033	50-382 A
CAIN, J M	8408140284	50-382 A
CALABRESE, R V.	8408130225*	50-289 P
CALDWELL, J L	8408200271*	50-416 Q
CALDWELL, J L	8408270347*	50-416 Q
CALDWELL, R A	8408230152*	50-445 Q
CALDWELL, R A	8408230466*	50-285 Q
CALLAHAN, J P.	8408220238	WASTE MGT

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CALSOYAS, C D	8408310138	50-275 P
CALSOYAS, C D	8408310149	50-344 P
CAMPBELL, B	8408220343	PR
CAMPBELL, P L	8408080512	50-368 S
CAMPBELL, P L	8408240077	50-368 S
CAMPBELL, R M	8408270242*	50-410 Q
CANNON, J A	8408160292*	ORG
CANTRELL, F	8408270187*	50-395 Q
CANTRELL, F S	8408230040	50-259 S
CANTRELL, F S	8408230240*	50-259 Q
CANTRELL, F S	8408270572*	50-395 Q
CANTRELL, F S	8408310114*	50-259 Q
CAPAND-DOLAN, L	8408230387	PR
CAPSTICK, R W	8408310279	50-271 H
CAREY, J J	8408130436	50-334 P
CAREY, J J	8408130439*	50-334 P
CAREY, J J	8408150499	50-334 P
CAREY, J J	8408230299	50-334 Q
CAREY, J J	8408270341*	50-334 Q
CARNEY, W	8408070217*	50-322 H
CARPENTER, D	8408090019*	50-397 Q
CARPENTER, D C	8408150371	50-59 R
CARPENTER, F D	8408060419	50-352 R
CARPENTER, F D	8408310023	50-352 R
CARPENTER, J H	8408070293	50-400 Q
CARPENTER, T Q	8408270552*	CONTRACT
CARR, A V	8408060035	50-413 Q
CARR, A V	8408060339	50-413 Q
CARR, A V	8408140103	50-413 Q
CARR, A V	8408140110*	50-413 Q
CARR, A V	8408140115*	50-413 Q
CARR, A V	8408160121	50-413 Q
CARROLL, R	8408270347*	50-416 Q
CARSON, B H	8408230157*	50-352 Q
CARTER, S	8408090020	50-259 S
CARUSO, R	8408270143*	50-322 Q
CASCARANO, R N	8408010165	50-295 F
CASCARANO, R N	8408100015	50-295 P
CASCARANO, R N	8408220086	50-295 Q
CASCARANO, R N	8408270372	50-295 P
CASCARANO, R N	8408310115	50-304 P
CASCARANO, R N	8408310200	50-295 P
CASCARANO, R N	8408310202	50-295 P
CASEY, L	8408200506	WASTE MGT
CASHWELL, R J	8408140521	50-156 F
CASSEL, D W	*8408170319*	*50-454* T
CASSIDY, T J	8408170203*	50-266 Q
CASTELLI, F P	8408010231*	50-354 E
CASTIGLIONE, L	8408290067	50-155 S
CASTIGLIONE, L	8408290251	50-155 S
CATCHPOLE, G J	8408240050	40-8745
CATCHPOLE, G J	8408240079	40-8745
CATON, G M	8408300272	NUREG
CATTON, I	8408020248	ACRS
CATTON, I	8408020252	ACRS
CEJA, S N	8408080013	XPORTLIC
CERNE, A C	8408150262*	50-443 Q
CERZOSIMO, R R	8408080255	NUREG
CESARE, J G	8408210105	50-416 R
CHAMBERLAIN, D	8408090095*	50-458 Q
CHAMBERLAIN, D	8408280203*	50-412 E
CHAMBLESS, P M	8408210485	I&E
CHAN, T L	8408170117*	50-443 Q
CHANDLER, J C	8407300143	TOPREP
CHANDLER, J C	8408090198	50-316 P
CHANDLER, J C	8408090209*	50-316 P
CHANDLER, J C	8408090230	TOPREP
CHANDLER, J C	8408140191	TOPREP
CHANDLER, J C	8408140363*	50-261 P
CHANDLER, J C	8408140396	TOPREP
CHANDLER, J C	8408230103*	50-261 P
CHANDLER, J C	8408230263	50-315 P
CHANDLER, J C	8408240268	TOPREP
CHANDLER, J C	8408280122	TOPREP
CHANDLER, J C	8408280212	TOPREP
CHANDLER, J C	8408310195	TOPREP
CHANDLER, L J	8408010209	50-320 Q
CHANDLER, L J	8408020222	50-275 Q
CHANDLER, L J	8408020227*	50-275 Q
CHANDLER, L J	8408020231*	50-275 Q
CHANDLER, L J	8408020233*	50-275 Q
CHANDLER, L J	8408020233*	50-275 Q
CHANEY, H D	8408160226*	50-382 Q
CHANEY, H D	8408270157*	50-458 Q
CHAPLIN, S D	8408200115	50-320 S
CHAPMAN, D N	8408080146	50-445 T
CHARAK, I	8408170152*	50-329 Q
CHARAK, I	8408170157*	50-329 Q
CHARNLEY, J S	8312020299*	50-354 E
CHARNLEY, J S	8408150084	TOPREP
CHARNLEY, J S	8408240122	TOPREP
CHAUDHARY, S K	8408210381*	50-352 Q
CHAUDHARY, S K	8408240253*	50-410 Q
CHEH, U	8408200504*	50-354 Q
CHELLIAH, E	8408290158	50-352 A
CHEN, S K	8408150485*	50-322 T
CHEN, S K	8408280205	50-413 T
CHENEY, C A	8408060231*	50-328 P
CHERONES, W J	8408150250*	XPORTLIC
CHERONES, W J	8408150442	XPORTLIC
CHEUNG, L	8408090330*	50-322 Q
CHEUNG, L	8408200504*	50-354 Q
CHEVERTON, R D	8408080415	NUREG
CHILES, L	8408010340*	50-335 H
CHILK, S J	8404250191*	PR
CHILK, S J	8407230112	40-8027
CHILK, S J	8408010133	50-322 Q
CHILK, S J	8408020008	50-460 Q
CHILK, S J	8408020013	50-413 Q
CHILK, S J	8408020044	50-322 Q
CHILK, S J	8408020197	50-275 Q
CHILK, S J	8408020206	50-275 Q
CHILK, S J	8408060417	10CFR
CHILK, S J	8408060434	50-322 Q
CHILK, S J	8408060437	50-322 Q
CHILK, S J	8408060446	10CFR
CHILK, S J	8408070265	50-275 Q
CHILK, S J	8408070312	PRM
CHILK, S J	8408070319	PRM
CHILK, S J	8408070361	50-275 Q
CHILK, S J	8408070383	PR
CHILK, S J	*8408070398**	*PR*
CHILK, S J	8408070463	50-454 Q
CHILK, S J	8408070467	50-275 Q
CHILK, S J	8408070491	50-293 Q
CHILK, S J	8408080024	10CFR
CHILK, S J	8408080216	50-416 P
CHILK, S J	*8408140006*	*50-275* Q
CHILK, S J	8408140009	50-275 Q
CHILK, S J	8408140454	50-454 Q
CHILK, S J	8408140460	50-275 Q
CHILK, S J	8408140486	50-275 Q
CHILK, S J	8408200573	50-329 Q
CHILK, S J	8408200608	50-293 Q
CHILK, S J	8408210352	50-322 Q
CHILK, S J	8408220251	50-275 Q
CHILK, S J	8408220323	50-275 Q
CHILK, S J	8408220358	50-289 Q
CHILK, S J	*8408240424*	*50-275* Q
CHILK, S J	8408270046	50-289 Q
CHILK, S J	8408280168	50-289 Q
CHILK, S J	8408280175	50-289 Q
CHILK, S J	8408280217	50-275 Q
CHILK, S J	8408280237	50-352 Q
CHILK, S J	*8408280333*	*50-3* P
CHILK, S J	8408280398	50-445 Q
CHILK, S J	8408290290	PR
CHILK, S J	*8408290297**	PR
CHILK, S J	8408300043	10CFR
CHILK, S J	8408300161	50-322 Q
CHILK, S J	8408310099	50-289 Q
CHILK, S J	8408310423	50-289 Q
CHIN, R Y	8408090404	50-295 S
CHOI, K	*8408170343**	*50-354* Q
CHOKSHI, N C	8408270170*	50-155 Q
CHOULES, N C	8408230298*	50-373 Q
CHOULES, N C	8408300199*	50-305 Q
CHRISSOTIMOS, N	8408010294*	50-373 Q
CHRISSOTIMOS, N	8408010316*	50-374 Q
CHRISSOTIMOS, N	8408230355*	50-254 Q
CHRISSOTIMOS, N	8408240114	50-374 S
CHRISSOTIMOS, N	8408300108*	50-10 Q
CHRISTENSEN, S	8408020129	50-322 T
CHRISTMAN, J N	*8408010261*	*50-322* Q
CHRISTMAN, J N	8408010261	50-322 Q
CHRISTMAN, J N	8408080408	50-322 Q
CHRISTMAN, J N	8408080408	50-322 Q
CHRISTMAN, J N	8408300124	50-322 Q
CHRISTMAN, J N	8408300124	50-322 Q
CHRISTMAN, W T	*8408080417*	*50-322* Q
CHRISTMAN, W T	8408080417	50-322 Q
CHRISTNOT, E	8408200227*	50-454 Q
CHRISTNOT, E	8408270277*	50-454 Q
CHRISTNOT, E	8408300196*	50-440 Q
CHRISTNOT, E F	8408090217*	50-454 Q
CHRISTOFFER, G	8408150394*	50-454 Q
CHRISTOFFER, G	8408150446*	50-341 Q
CHRISTOPHER, T	8408030037	GA999
CHU, M S.	8408240284	WASTE MANA
CHUNG, D H	8408240265	WASTE MANA
CHUNG, D H	8408240295	WASTE MANA
CHUNG, D H	8408240388	WASTE MGT
CHUNG, J W	8408130410*	50-289 Q
CHUNG, J W	8408130417*	50-289 Q
CHURCHILL, B W	8408070437	50-289 Q
CHURCHILL, B W	8408070437	50-289 Q
CHURCHILL, B W	8408230272	50-289 Q
CHURCHILL, B W	8408230272	50-289 Q
CHURCHILL, B W	8408280219	50-382 Q
CHURCHILL, B W	8408280219	50-382 Q
CILIMBERG, R L	8408160341*	50-341 Q
CILLIS, M	8408090021*	50-344 Q
CILLIS, M	8408090080*	50-344 Q
CIMINO, D	8408150476*	50-322 T
CINQUEMANI, D K	8408140449	50-219 Q
CIOFFI, J	8408200023*	50-289 Q
CIPOLLA, A J	8408130240	40-3392
CIPOLLA, A J	8408130273	40-3392
CIPOLLA, A J	8408170395	40-3392
CLARK, B L	8408080533	50-277 S
CLARK, B L	8408080535	50-277 S
CLARK, B L	8408130601	50-277 S
CLARK, B L	8408290107	50-277 S
CLARK, B W	8408300183*	50-263 F
CLARK, C	*8408300407**	*50-328* Q
CLARK, H F	8408160378*	50-443 A
CLARK, J R	8408090341	50-259 S
CLARK, L	8408130205	70-938
CLARK, L	8408130212*	70-938
CLARK, N E	8408200340	50-395 S
CLARK, N. E.	8408200344	50-395 S
CLARK, N. H	8408240320	NUREG
CLARK, P. R	8408270145	50-289 Q
CLARK, P R	8408310153	50-289 P
CLARK, R.	8408310088*	CONTRACT
CLARK, R. A	8408080472	NUREG
CLARK, R J.	8408080110	50-296 P
CLARK, R. J	8408130026	50-259 P
CLARK, R. J	8408160424	50-259 P
CLARK, R J	8408200264	50-259 P
CLARK, R J	8408210003	50-259 P
CLARK, R J.	8408280257	50-259 P
CLARK, R J	8408290282	50-259 P
CLARK, R J	8408310414	50-259 P
CLARK, R J	8408310420	50-259 P
CLARK, R. J.	8408310424	50-260 P
CLAWSON, C A	8408020048	50-322 T
CLAY, E L	8408280367*	70-1113
CLAY, G W	8408240239*	50-413 I
CLAYTON, H. B	8405010079*	50-315 F
CLAYTON, H B	8408160249	TOPREP
CLAYTON, H. B	8408240330*	50-250 F
CLEMENTS, B R	8408030115	50-445 S
CLEMENTS, B R	8408090044	50-445 S
CLEMENTS, B R	8408090105*	50-445 A
CLEMENTS, B R	8408140185	50-445 S
CLEMENTS, B. R	8408160204*	50-445 Q
CLEMENTS, B R	8408160510	50-445 S
CLEMENTS, B R	8408270068	50-445 F
CLEMENTS, B R	8408280375	50-445 S
CLEMENTS, B R	8408280384	50-445 S
CLEMENTS, B. R	8408280468	50-445 S
CLEMENTS, B. R	8408290125	50-445 S
CLEMENTS, B R	8408290208	50-445 K
CLEMENTS, R. H	8408010156*	50-412 F
CLEMENTS, W L	8408070388	50-322 Q
CLEMENTS, W. L	8408140548	50-275 Q
CLEMENTS, W L	*8408230305*	*50-445* Q
CLEMENTS, W L.	8408230311	50-445 Q
CLEMENTS, W L	8408270058	50-445 Q
CLEMONS, P	8408200023*	50-289 Q
CLEMONS, P	8408240231*	50-213 Q
CLEMONS, P E.	8408010286*	50-247 Q
CLEVELAND, J. C.	8408130001	NUREG
CLEWETT, J	8408140478	50-400 T

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CLINE, W	8408270227*	50-302 G
CLINE, W E	8408270295*	50-250 G
CLINE, W E	8408270432*	50-302 G
CLINE, W E	8408280370*	50-269 G
CLOUGH, R L	8408080359	NUREG
COATS, M L	8408080026	50-445 T
CODELL, R B	8408300292	NUREG
COHEN, D A	8408140377	PR
COHEN, I	8408030221*	50-333 G
COHEN, I	8408230235*	50-220 G
COLARULLI, P F	8408140488	50-247 G
COLARULLI, P F	8408140488	50-247 G
COLBURN, T G	8408090514	50-266 H
COLE, A W	8408020126*	50-440 I
COLE, R F	8408300168	50-352 G
COLEY, J L	8408240366*	50-321 G
COLEY, J L	8408290039*	50-261 G
COLL, N A	8408090397	50-250 G
COLL, N A	8408090397	50-250 G
COLL, N A	8408090437	50-250 G
COLL, N A	8408090437	50-250 G
COLLINS, J T	8408070315	State Prog
COLLINS, J T	8408070339	State Prog
COLLINS, J T	8408090022	50-313 G
COLLINS, J T	8408100141	50-382 G
COLLINS, L L	8408140413*	50-346 P
COLLINS, L L	8408140433*	50-313 P
COLLINS, L L	8408210387*	50-338 P
COLLINS, P F	8408220322	PR
COLLINS, S	8408310271	50-333 G
COLLINS, S J	8408150632	50-410 A
COLLINS, S J	8408240253*	50-410 G
COLLINS, S J	8408270541*	50-333 G
COLLINS, T R	8408280082*	50-302 G
COLMAR, R	8408220265	NUREG
COLOMBO, R W	8408280240	50-312 P
COLOMBO, R W	8408310196	50-312 S
CONLON, T E	8408240359*	50-321 G
CONLON, T E	8408240362*	50-390 G
CONLON, T E	8408270191*	50-413 G
CONLON, T E	8408270371*	50-413 G
CONLON, T E	8408270414*	50-424 G
CONLON, T E	8408270440*	50-424 G
CONLON, T E	8408280028*	50-400 G
CONLON, T E	8408280140*	50-259 G
CONNAUGHTON, K	8408070221*	50-454 G
CONNELL, K	8408310191*	50-341 F
CONNER, E	8408150271*	50-289 G
CONNER, E	8408210383	50-289 S
CONNER, E L	8408280293*	50-219 G
CONNER, E L	8408300096*	50-219 G
CONNER, T B	8408010246	50-354 G
CONNER, T B	8408010246	50-354 G
CONNER, T B	8408010255	50-352 G
CONNER, T B	8408010255	50-352 G
CONNER, T B	8408070287	50-352 G
CONNER, T B	8408070287	50-352 G
CONNER, T B	8408070291*	50-352 G
CONNER, T B	8408070291*	50-352 G
CONNER, T B	8408070350	50-352 G
CONNER, T B	8408070350	50-352 G
CONNER, T B	8408070495	50-352 G
CONNER, T B	8408070495	50-352 G
CONNER, T B	8408080019	50-354 D
CONNER, T B	8408080399	50-352 G
CONNER, T B	8408080399	50-352 G
CONNER, T B	8408130398	PR
CONNER, T B.	8408240236	50-352 G
CONNER, T B	8408240236	50-352 G
CONNER, T B.	8408240241	50-352 G
CONNER, T B	8408240241	50-352 G
CONNER, T B	8408240256	50-352 G
CONNER, T B	8408240256	50-352 G
CONNER, T B.	8408280448	50-354 G
CONNER, T B	8408280448	50-354 G
CONRAD, H F	8408140075*	50-400 T
CONTE, R.	8408150271*	50-289 G
CONTRELL, F S	8408240286	50-328 S
CONWAY, J T	8408010372*	GA999
COOK, D B	8408230496	50-254 S
COOK, F R.	8408230038	WASTE MGT
COOK, J.	8408160311	50-333 R
COOK, J A.	8408240379	NUREG
COOK, J W	8408010149*	50-329 A
COOK, J W	8408020014	50-329 A
COOK, J W	8408020315	50-329 A
COOK, J W	8408020106	NUREG
COOK, J W	8408070183	50-329 G
COOK, J W	8408070227	50-329 G
COOK, J W	8408090284	50-329 S
COOK, J W	8408130227*	50-329 A
COOK, J W	8408130255*	50-329 A
COOK, J W	8408130290*	50-329 A
COOK, J W	8408150644*	50-329 G
COOK, J W	8408150669*	50-329 G
COOK, J W	8408150672*	50-329 G
COOK, J W	8408150685*	50-329 A
COOK, J W	8408150718*	50-329 A
COOK, J W	8408210454*	50-329 E
COOK, J W	8408220059*	50-329 G
COOK, J W	8408310054	50-329 S
COOK, J W	8408310259	50-329 S
COOK, K W	8408070109	50-382 F
COOK, K W	8408070230	50-382 F
COOK, K W	8408100006	50-382 G
COOK, K W	8408100007	50-382 G
COOK, K W	8408100117	50-382 F
COOK, K W	8408130342	50-382 F
COOK, K W	8408210305	50-382 A
COOK, K W	8408230179	50-382 A
COOK, K W	8408230284*	50-382 G
COOK, K W	8408310225	50-382 F
COOK, K W	8408310236	50-382 A
COOK, R	8408010174	50-320 S
COOK, R	8408010220	50-320 S
COOK, R	8408010230	50-320 S
COOK, R	8408300381*	50-320 G
COOK, R J	8408130323*	50-329 A
COOK, R J	8408130356*	50-329 A
COOK, R J	8408150395*	50-329 A
COOK, R J	8408150622*	50-329 G
COOK, R J	8408150690*	50-329 G
COOK, R J	8408150698*	50-329 R
COOK, R J	8408150743*	50-329 A
COOK, R J	8408270323*	50-329 A
COOKE, B A	8408230053	WASTE MGT
COOKE, T C	8408020122*	50-329 A
COOKE, T C	8408140050*	50-329 A
COOKE, T C	8408140069*	50-329 A
COOLEY, C	8408220496	WASTE MGT
COOLEY, R A	8408060099*	50-482 G
COOLEY, R A	8408090037*	50-298 G
COOLEY, R A	8408090073*	50-382 G
COOLEY, R A	8408290115*	50-368 G
COOLEY, R A	8408290142*	50-285 G
COOLEY, R A	8408290176*	50-368 G
COOMBS, H A	8408160405*	50-508 A
COONEY, M J	8408160355	50-352 F
COONEY, M J	8408230185	50-277 P
COONEY, M J	8408310004	50-277 G
COONEY, M J	8408310417	50-352 G
COOPER, M R	8408090156	50-327 S
COOPER, M R	8408160493	50-327 S
COOPER, M R	8408160522	50-327 S
COPELAND, V G	8408010260	50-155 G
COPELAND, V G	8408010260	50-155 G
COPELAND, V G	8408080224	50-155 G
COPELAND, V G	8408080224	50-155 G
COPELAND, V G	8408140028	50-456 G
COPELAND, V G	8408140028	50-456 G
COPELAND, V G	8408140034*	50-456 G
COPELAND, V G	8408140034*	50-456 G
COPLAN, S	8408060173	WASTE MGT
COPLAN, S M	8408130122	WASTE MGT
COPLAN, S M	8408210135	WASTE MGT
COPLAN, S M	8408230394	WASTE MGT
CORDARO, M C	8408020048	50-322 T
CORDARO, M C	8408130352*	50-322 G
CORLEY, W G	8408150695*	50-329 A
CORLEY, W G	8408220090*	50-329 A
CORRADINI, M L	8408020235	ACRS
CORRADINI, M. L	8408020235	ACRS
CORWIN, W R	8408080419	NUREG
COSTANZI, F A	8408160467	WASTE MGT
COSTELLO, F	8408200023*	50-289 G
COTTER, B P	8408070475	50-322 G
COTTRELL, W B	8408290190	NUREG
COTTRELL, W B	8408290198	NUREG
COUNSIL, W G	8408070220	50-423 A
COUNSIL, W G	8408070220	50-423 A
COUNSIL, W G	8408070321	50-213
COUNSIL, W G	8408070321	50-213
COUNSIL, W G	8408070321	50-213
COUNSIL, W G	8408070341	50-336
COUNSIL, W G	8408070341	50-336
COUNSIL, W G	8408080414*	50-245
COUNSIL, W G	8408080414*	50-245
COUNSIL, W G	8408090092	50-423
COUNSIL, W G	8408090092	50-423
COUNSIL, W G	8408090180	50-213
COUNSIL, W G	8408100063	50-213
COUNSIL, W G	8408100063	50-213
COUNSIL, W G	8408100063	50-213
COUNSIL, W G	8408100064	50-423
COUNSIL, W G	8408100064	50-423
COUNSIL, W G	8408100102	50-245
COUNSIL, W G	8408100102	50-245
COUNSIL, W G	8408100116	50-213
COUNSIL, W G	8408100116	50-213
COUNSIL, W G	8408100116	50-213
COUNSIL, W G	8408130316	50-336
COUNSIL, W G	8408130316	50-336
COUNSIL, W G	8408150232	50-336
COUNSIL, W G	8408150232	50-336
COUNSIL, W G	8408160328	50-213
COUNSIL, W G	8408160350	50-213
COUNSIL, W G	8408200172	50-336
COUNSIL, W G	8408200172	50-336
COUNSIL, W G	8408210306	50-245
COUNSIL, W G	8408210306	50-245
COUNSIL, W G	8408210339	50-423
COUNSIL, W G	8408210339	50-423
COUNSIL, W G	8408210469*	50-336
COUNSIL, W G	8408210469*	50-336
COUNSIL, W G	8408210480	50-213
COUNSIL, W G	8408210480	50-213
COUNSIL, W G	8408210480	50-213
COUNSIL, W G	8408270222	50-213
COUNSIL, W G	8408280159	50-423
COUNSIL, W G	8408280159	50-423
COUNSIL, W G	8408280258	50-423
COUNSIL, W. G	8408280258	50-423
COUNSIL, W G	8408290298	50-213
COUNSIL, W. G	8408290298	50-213
COUNSIL, W. G	8408290298	50-213
COUNSIL, W. G	8408300135	50-213
COUNSIL, W. G	8408310107	50-213
COUNSIL, W. G	8408310187	50-213
COUNSIL, W. G	8408310187	50-213
COUNSIL, W G	8408310187	50-213
COVILL, D W	8408270290*	50-219
COWAN, K D.	8406070192	50-397
COWGILL, C. J	8408280293*	50-219
COWGILL, C. J	8408300096*	50-219
COYLE, L	8408060203	50-237
COYLE, L	8408200501	50-10
COYLE, L	8408240218	50-237
COYLE, L	8408270455	50-249
CRACKER, H W	8408230235*	50-220
CRANE, P A	8408300482	50-275
CRANWELL, R. M	8408240260	WASTE
CRANWELL, R M	8408290337	WASTE
CREED, J R	8408060036*	50-341
CREED, J R	8408100037*	50-282
CREED, J R	8408210471*	50-461
CRLENJAK, R. V	8408270269*	50-321
CROCKER, H W	8408030221*	50-333
CROCKER, H. W	8408060208*	50-213
CROCKER, H W	8408150380*	50-29
CROCKER, H W	8408160272*	50-334
CROCKER, H W	8408270465*	50-271
CROBBY, G E	8408280127	50-263
CROSSMAN, W	8408150515*	50-382
CROSSMAN, W A	8408030275*	50-382
CROSSMAN, W A	8408060057*	50-382
CROSSMAN, W A	8408060325*	50-382
CROSSMAN, W A	8408160226*	50-382
CROSSMAN, W A	8408220500*	50-382
CROSSON, R B	8408160405*	50-508
CROUCH, D. B.	8408280365	40-843
CROUSE, R P	8408070301	50-346
CROUSE, R P.	8408070335	50-346
CROUSE, R. P	8408130390*	50-346
CROUSE, R. P	8408130395*	50-346
CROUSE, R. P	8408130411*	50-346

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CROUSE, R P	8408130421	50-346 P
CROUSE, R P	8408130428*	50-346 P
CROUSE, R P	8408140410	50-346 P
CROUSE, R P	8408170214	50-346 G
CROUSE, R P	8408200135	50-346 P
CROUSE, R P	8408210345	50-346 G
CROUSE, R P	8408210456	50-346 P
CROUSE, R P	8408280197	50-346 K
CROW, W T	8408090319	40-6940
CROW, W T	8408280034	70-143
CROW, W T	8408280351	70-938
CROWE, D M	8408020106	NUREG
CROWLEY, B R	8408240366*	50-321 G
CROWLEY, B R	8408270275*	50-417 G
CRUTCHFIELD, D	8408010038	50-206 P
CRUTCHFIELD, D	8408060388	50-341 A
CRUTCHFIELD, D	8408070008	MISC
CRUTCHFIELD, D	8408070099	50-29 P
CRUTCHFIELD, D	8408130251*	50-382 G
CRUTCHFIELD, D	8408140188	50-206 P
CRUTCHFIELD, D	8408140408	50-213 P
CRUTCHFIELD, D	8408160172	50-155 P
CRUTCHFIELD, D	8408200114	50-206 P
CRUTCHFIELD, D	8408230077	50-29 S
CULLEN, E J	8408150404	50-352 G
CULLEN, E J	8408200286	50-352 G
CULLEN, E J	8408240262	50-352 G
CUMMINGS, G E	8408080515*	50-275 G
CUMMINGS, G E	8408080517*	50-275 G
CUMMINGS, G E	8408080521*	50-275 G
CUMMINGS, J C	8408100155	NUREG
CUMMINGS, R A	8408240221	WASTE MANA
CUMMINS, J E	8408150102*	50-445 G
CUMMINS, J E	8408150655*	50-445 G
CUNNINGHAM, G E	8408090335	50-73 P
CUNNINGHAM, G H	8408070029*	50-447 H
CUNNINGHAM, G H	8408150120	50-348 M
CUNNINGHAM, R E	8408010244	40-2061
CUNNINGHAM, R E	8408030183	40-2061
CUNNINGHAM, R E	8408060023	40-2061
CUNNINGHAM, R E	8408220429	70-364
CUNNINGHAM, R G	8408230267	50-5 P
OCO, L M	8408150062	40-2061
RAN, D	8408070344	PR
RAN, D	8408240234	50-443 G
TIS, J M	8408280205	50-413 T
TIS, N W	8408060143	50-387 I
TIS, N W	8408070342	50-387 P
TIS, N W	8408130129	50-387 F
JHNIR, H	8408220350	PR
/TLER, J M	8408230034	WASTE MGT
JTSHALL, N H	8408300282	NUREG
UTTER, A B	8408030094	50-261 F
UTTER, A B	8408030096	50-261 P
CUTTER, A B	8408030162	50-261 P
CUTTER, A B	8408060257	50-400 A
CUTTER, A B	8408070374	50-261 P
CUTTER, A B	8408080252	50-324 P
CUTTER, A B	8408160129	50-324 G
CUTTER, A B	8408220126	50-261 F
CUTTER, A B	8408270229	50-261 P
CUTTER, A B	8408230093	50-261 P
CUTTER, A B	8408230117	50-261 P
CUTTER, A B	8408280166	50-324 G
DAHLEN, D	8408240042	50-295 B
DALE, L F	8408030075	50-416 P
DALE, L F	8408030095	50-416 P
DALE, L F	8408030103	50-416 P
DALE, L F	8408030106	50-417 A
DALE, L F	8408030120	50-416 S
DALE, L F	8408060030	50-416 S
DALE, L F	8408060174	50-416 P
DALE, L F	8408060185	50-416 S
DALE, L F	8408060189	50-416 S
DALE, L F	8408060249	50-416 P
DALE, L F	8408070404	50-416 P
DALE, L F	8408070430	50-416 P
DALE, L F	8408070436	50-416 P
DALE, L F	8408080538	50-416 S
DALE, L F	8408090137	50-416 S
DALE, L F	8408090163	50-416 S
DALE, L F	8408130365	50-416 S
DALE, L F	8408130371	50-416 S
DALE, L F	8408140116	50-416 P
DALE, L F	8408150131	50-416 P
DALE, L F	8408150201	50-416 P
DALE, L F	8408160175	50-416 S
DALE, L F	8408210105	50-416 R
DALE, L F	8408210151	50-416 F
DALE, L F	8408210484	50-416 F
DALE, L F	8408240210	50-416 S
DALE, L F	8408270263*	50-417 G
DALE, L F	8408270321*	50-416 G
DALE, L F	8408300490	50-416 S
DALE, L F	8408310222	50-416 P
DALTROFF, S L	8407160090	50-277 F
DALTROFF, S L	8408060321	50-277 P
DALTROFF, S L	8408070303	50-278 P
DALTROFF, S L	8408220497	50-352 F
DALTROFF, S L	8408230258	50-352 V
DALTROFF, S L	8408310008	50-352 F
DALY, B J	8406230301	50-317 P
DAM, W	8408200459	WASTE MGT
DANCE, H C	8408030126	50-335 G
DANCE, H C	8408130149	50-249 G
DANCE, H C	8408230392	50-338 S
DANCE, H C	8408240356	50-321 G
DANCE, H C	8408240364	50-321 G
DANCE, H C	8408240416	50-249 G
DANCE, H C	8408270184	50-413 G
DANCE, H C	8408270219*	50-302 G
DANCE, H C	8408270289	50-250 G
DANCE, H C	8408270291	50-335 G
DANCE, H C	8408270306*	50-335 G
DANCE, H C	8408270334	50-321 G
DANCE, H C	8408270342	50-424 G
DANCE, H. C	8408270360	50-335 G
DANCE, H C	8408270367	50-413 G
DANCE, H C	8408270383	50-369 G
DANCE, H C	8408270387	50-338 G
DANCE, H C	8408270408	50-424 G
DANCE, H C	8408270428	50-302 G
DANCE, H C	8408270429	50-424 G
DANCE, H C	8408270433*	50-424 G
DANCE, H C	8408270443	50-280 G
DANCE, H C	8408270444	50-369 G
DANCE, H C.	8408270452*	50-280 G
DANCE, H C	8408270474	50-413 G
DANCE, H C	8408270484	50-413 G
DANCE, H C	8408280061	50-302 G
DANCE, H C	8408280072*	50-302 G
DANCE, H C	8408280152	50-424 S
DANCE, H C	8408280327	50-413 G
DANCE, H C	8408280361	50-269 G
DANCE, H C	8408280386	50-413 G
DANCE, H C	8408290330	50-338 G
DANCE, H C	8408300208	50-302 F
DANCE, H C	8408300238	50-366 P
DANCE, H C	8408300244	50-269 F
DANCE, H C	8408300303	50-335 F
DANCE, H C	8408300344	50-424 G
DANCE, H C	8408300358	50-413 F
DANCE, H. C	8408300395	50-335 G
DANCE, H C	8408300419	50-250 P
DANCE, H C	8408300427	50-269 F
DANCE, H C	8408300429	50-280 F
DANCE, H C	8408300433	50-280 F
DANCE, H C	8408300436	50-321 F
DANCE, H C	8408310030	50-250 V
DANCE, H C.	8408310057	50-321 F
DANCE, H C	8408310060	50-280 F
DANCE, H C	8408310425	50-250 V
DANIELSEN, D C	8408290275	50-454 G
DANIELSON, D H	8408070340*	50-456 G
DANIELSON, D H	8408080195*	50-454 G
DANIELSON, D H	8408090189*	50-266 G
DANIELSON, D H	8408090195*	50-255 G
DANIELSON, D H	8408150487*	50-454 G
DANIELSON, D H	8408160327*	50-346 G
DANIELSON, D H	8408160341*	50-341 G
DANIELSON, D H	8408310394*	50-341 G
DARDEN, T	8408160003	I&E
DARDEN, T	8408210280	I&E
DARLING, S B	8408150395	50-318 S
DAVIS, G A	8408160405*	50-508 A
DAVIS, J E	8408070123	50-483 S
DAVIS, J E.	8408090271	50-483 S
DAVIS, J G	8408160048	WASTE MGT
DAVIS, J. M	8408140151*	50-400 T
DAVIS, K.	8408270497	CONTRACT
DAVIS, M J	8408270456*	50-280 G
DAVIS, P	8408130319	50-382 G
DAVIS, P R	8408130324*	50-382 G
DAVIS, W G	8408010210	50-458 G
DAVIS, W G	8408010245	50-458 G
DAWSON, D M	8408160472*	70-1308
DAY, J	8408060382*	70-1362
DE VINCENTIS, J	8408160371	50-443 A
DE VINCENTIS, J	8408160371	50-443 A
DEAGAZIO, A	8408170002	50-346 P
DEAGAZIO, A	8408270471	50-346 F
DEAGAZIO, A	8408280345	50-346 F
DEAGAZIO, A W	8408070499	50-346 P
DEAN, R S	8408130265	NUREG
DEAN, R S	8408310084	NUREG
DEBOLT, B	8408060197*	50-70 G
DEBOLT, R	8408270328	PR
DECKER, T R	8408270227*	50-302 G
DECKER, T R	8408280370*	50-269 G
DEFAYETTE, R W	8408030179*	50-155 G
DELGAIZA, T J	8204150347*	50-293 P
DELGEORGE, L G	8408280274	50-454 G
DELLA RATTA, A	8408150407*	70-371
DEMOOR, D E	8408230239	50-155 S
DEMOS, D	8408140038*	50-456 G
DEMOSS, D M	8408310194*	50-454 T
DENENBERG, E	8408080008*	CONTRACT
DENTON, H R	8408030215*	50-320 P
DENTON, H R	8408030218*	50-320 P
DENTON, H R	8408030223*	50-320 P
DENTON, H R	8408030277	MISC
DENTON, H R	8408070025	50-447 H
DENTON, H R	8408070076	50-366 S
DENTON, H R	8408070268	PR
DENTON, H R	8408080082	50-320 H
DENTON, H R	8408130022	50-295 P
DENTON, H R	8408130075	50-348 M
DENTON, H R	8408130168*	50-413 P
DENTON, H R	8408130242	50-366 P
DENTON, H R	8408130555	PRM
DENTON, H R	8408150611	50-254 P
DENTON, H R	8408160161	50-271 P
DENTON, H R	8408160439	MISC
DENTON, H R	8408170007	50-344 P
DENTON, H R	8408200274	50-209 H
DENTON, H R	8408230355	50-302 H
DENTON, H R	8408230436	50-209 H
DENTON, H R	8408240369	MISC
DENTON, H R	8408240425	MISC
DENTON, H R	8408300175*	50-219 F
DENTON, R E	8408070074	50-317 G
DESLANDES, K D	8408080531	50-336 S
DEVINCENTIS, J	8408070332	50-443 A
DEVINCENTIS, J	8408070332	50-443 A
DEVINCENTIS, J	8408070362	50-443 F
DEVINCENTIS, J	8408070362	50-443 F
DEVINCENTIS, J	8408100013	50-443 S
DEVINCENTIS, J	8408100013	50-443 S
DEVINCENTIS, J	8408100083	50-443 S
DEVINCENTIS, J	8408100136	50-443 S
DEVINCENTIS, J	8408100136	50-443 S
DEVINE, J B	8408010138	XPORTLIC
DEVINE, T	8408010235	50-275 G
DEVINE, T	8408020152	50-275 G
DEWEY, L B	8408070390	50-458 G
DEWEY, L B	8408130102	50-354 G
DEYOUNG, R	8311020513	50-445 A
DEYOUNG, R C	8303300734	50-445 A
DEYOUNG, R C	8303300736*	50-445 A
DEYOUNG, R C	8309130017*	50-329 G
DEYOUNG, R C	8309130110	50-445 A
DEYOUNG, R C	8309130112*	50-445 A
DEYOUNG, R C	8309130117*	50-445 A
DEYOUNG, R C	8407020541	REVIEW GRP
DEYOUNG, R C	8407200109	REVIEW GRP
DEYOUNG, R C	8407300142	50-329 G
DEYOUNG, R C	8407300151*	50-329 G
DEYOUNG, R C	8407300156*	50-329 G
DEYOUNG, R C	8408150057	QA999
DEYOUNG, R C	8408150665*	50-329 A
DEYOUNG, R C	8408170109	50-443 G
DEYOUNG, R C	8408220431	50-309 F
DEYOUNG, R C	8408310108	TOPREP
DEYOUNG, R D	8408240021	50-382 G
DIAZ, N J	8408130261	70-1068

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DICK, G F	8408080029	50-244 F
DICK, G F	8408300027	50-244 F
DIEDERICH, G J	8408060042	50-374 S
DIEDERICH, G J	8408060055	50-373 S
DIEDERICH, G J	8408060053	50-373 S
DIEDERICH, G J	8408060107	50-374 S
DIEDERICH, G J	8408060207	50-373 S
DIEDERICH, G J	8408060227	50-374 S
DIEDERICH, G J	8408060255	50-373 S
DIEDERICH, G J	8408060283	50-374 S
DIEDERICH, G J	8408070391	50-374 S
DIEDERICH, G J	8408070490	50-374 S
DIEDERICH, G J	8408090324	50-373 S
DIEDERICH, G J	8408160140	50-373 R
DIEDERICH, G J	8408200323	50-373 S
DIEDERICH, G J	8408200526	50-373 S
DIEDERICH, G J	8408230524	50-374 S
DIEDERICH, G J	8408230533	50-374 S
DIEDERICH, G J	8408240044	50-374 S
DIEDERICH, G J	8408240179	90-374 S
DIEDERICH, G J	8408300388	50-373 R
DIEDERICH, G J	8408300508	50-373 R
DIEDERICH, G J	8408310047	50-373 S
DIEDERICH, G J	8408310353	50-374 S
DIENES, A F	8408160255	50-255 R
DIETZ, C R	8408060128	50-325 S
DIETZ, C R	8408090032	50-325 S
DIETZ, C R	8408090390	50-324 S
DIETZ, C R	8408090432	50-325 S
DIETZ, C R	8408100039	50-324 S
DIETZ, C R	8408130338	50-324 S
DIETZ, C R	8408140151*	50-400 T
DIETZ, C R	8408160075	50-325 S
DIETZ, C R	8408160133	50-325 S
DIETZ, C R	8408240227	50-324 S
DIETZ, C R	8408270431*	50-324 Q
DIGGS, R M	8408010122	50-366 P
DIGGS, R M	8408070040	50-155 P
DIGGS, R M	8408070154	50-213 P
DIGGS, R M	8408090491	50-250 P
DIGGS, R M	8408140073	50-344 P
DIGGS, R M	8408160295	50-255 P
DIGGS, R M	8408160494	50-315 P
DIGGS, R M	8408170017	50-237 P
DIGGS, R M	8408210547	50-409 P
DIGGS, R M	8408210550	50-266 Q
DIGGS, R M	8408210552	50-304 P
DIGGS, R M	8408210525	50-206 P
DIGGS, R M	8408230291	50-309 P
DIGGS, R M	8408230318	50-518 A
DIIANNI, D C	8408160482	50-244 P
DIMEGLIO, A F	8408090332	PR
DIMEGLIO, A F	8408210328	50-193 S
DIMMOCK, L	8408300060*	50-263 Q
DIRCKS, W J	8405180145	50-358 H
DIRCKS, W J	840703001I*	REVIEW GRP
DIRCKS, W J	8407120142	50-528 D
DIRCKS, W J	8408010275	50-275 U
DIRCKS, W J	8408010338	50-335 H
DIRCKS, W J	8408060389	MISC
DIRCKS, W J	8408070041	50-416 H
DIRCKS, W J	8408070201	50-416 U
DIRCKS, W J	8408070211	50-322 H
DIRCKS, W J	8408090138	SECY
DIRCKS, W J	8408090406	SECY
DIRCKS, W J	8408090508	50-413 U
DIRCKS, W J	8408130202	50-416 U
DIRCKS, W J	8408130547	50-322 A
DIRCKS, W J	8408160288*	ORG
DIRCKS, W J	8408170094	50-352 U
DIRCKS, W J	8408200449	50-352 U
DIRCKS, W J	8408220274	ORG
DIRCKS, W J	8408230086	50-272 H
DIRCKS, W J	8408280054	50-322 H
DIRCKS, W J	8408300020	REVIEW GRP
DIVINE, J R	8408310075	NUREG
DIXON, D W	8408060103	50-395 P
DIXON, D W	8408060134	50-395 P
DIXON, D W	8408060140	50-395 P
DIXON, D W	8408070373	50-395 P
DIXON, D W	8408070402	50-395 Q
DIXON, D W	8408080124	50-395 P
DIXON, D W	8408080187	50-395 K
DIXON, D W	8408090143	50-395 S
DIXON, D W	8408090241	50-395 S
DIXON, D W	8408100002	50-395 F
DIXON, D W	8408130340	50-395 S
DIXON, D W	8408130364	50-395 F
DIXON, D W	8408140265	50-395 P
DIXON, D W	8408160525	71-9151
DIXON, D W	8408170308	50-395 V
DIXON, D W	8408200340	50-395 S
DIXON, D W	8408200344	50-395 S
DIXON, D W	8408230507	50-395 S
DIXON, D W	8408240002	50-395 P
DIXON, D W	8408270174*	50-395 Q
DIXON, D W	8408280104	50-395 P
DIXON, D W	8408280287	50-395 Q
DIXON, D W	8408300514	50-395 S
DJEMAL, A	8408220148	50-369 J
DJEMAL, A	8408290006	50-269 J
DODDS, R T	840808O497*	50-344 Q
DODDS, R T	8408090019*	50-397 Q
DODDS, R T	8408170369	50-397 S
DODDS, R T	8408240287	50-344 S
DODDS, R T	8408290036	50-397 S
DODDS, R T	8408300250*	50-312 Q
DODDS, R T	8408300377*	50-344 Q
DODDS, R T	8408300380*	50-344 Q
DODDS, R T	8408300451*	50-397 Q
DODDS, R T	8408300464*	50-397 Q
DOERFLEIN, L T	8408270541*	50-333 Q
DOERGE, D H	8408290185	NUREG
DOHERTY, J F	8408140419	PR
DOMENICI, P V	8408230063*	50-272 H
DOMER, J A	8408140331	50-259 S
DOMER, J A	8408140375	50-259 P
DOMER, J A	8408150213	50-296 Q
DOMER, J A	8408200131	50-259 P
DOMER, J A	8408240109	50-259 Q
DOOLITTLE, E L	8408090438	50-423 A
DOROSHOW, J	8408060201	50-289 Q
DOROSHOW, J	8408060201	50-289 Q
DOROSHOW, J	8408060224*	50-289 Q
DOROSHOW, J	8408060224*	50-289 Q
DOROSHOW, J	8408070382	50-289 Q
DOROSHOW, J	8408070382	50-289 Q
DOROSHOW, J	8408070408	50-289 Q
DOROSHOW, J	8408070408	50-289 Q
DOROSHOW, J	8408140449	50-219 Q
DOROSHOW, J	8408140479	50-289 Q
DOROSHOW, J	8408140479	50-289 Q
DOROSHOW, J	8408240250	50-219 Q
DOTY, J W	8408030025*	50-327 P
DOUGHERTY, D	8408010151	NUREG
DOUGHERTY, J B	8408010250	50-338 Q
DOUGHERTY, J B	8408010250	50-338 Q
DOVE, K	8408310156	50-461 A
DOWNEY, B L	8408280156	50-445 Q
DOWNEY, B L	8408280156	50-445 Q
DOWNEY, B L	8408280251	50-445 Q
DOWNEY, B L	8408280251	50-445 Q
DOYLE, J	8408090503*	50-445 Q
DRAGOUN, T	8408030267*	50-272 Q
DRAGOUN, T	8408240076*	50-334 Q
DRAGOUN, T F	8408230136*	50-277 Q
DREHOBL, K E	8408010163*	50-329 O
DREHOBL, K E	8408170102*	50-329 A
DREIFUS, D	8408090218	50-322 Q
DREIFUS, D	8408090218	50-322 Q
DREIFUS, D	8408090223*	50-322 Q
DREIFUS, D	8408090223*	50-322 Q
DRIKER, E	8408150692*	50-329 A
DRUGA, R J	8408100092	50-334 S
DRUGA, R J	8408100113	50-334 S
DRUGA, R J	8408210016	50-334 S
DRUGA, R J	8408210023	50-334 S
DUBOIS, D	8408230464	XPORTLIC
DUBOIS, D L	8408270500*	50-298 Q
DUDLEY, N F	8408310048*	50-470 Q
DUGGIN, G	8408170053	50-328 S
DUGGIN, G	8408230509	50-327 S
DUGGIN, G E	8408310050	50-327 S
DUMAS, D	8408310025*	XPORTLIC
DUMAS, D	8408310303	XPORTLIC
DUMAS, D	8408310446	XPORTLIC
DUNCAN, R M	8408220374*	50-445 T
DUNCAN, R M	8408220374*	50-445 T
DUNLAP, J	8408310065	50-272 S
DUNLAP, J M	8408030192*	50-410 Q
DUNLAP, J M	8408150424*	50-277 Q
DUNLOP, A	8408230252*	50-454 Q
DUPONT, S G	8408150475*	50-341 Q
DURR, J P	8408100072	50-247 S
DURR, J P	8408150619	50-352 Q
DURR, J P	8408150634*	50-272 Q
DURR, J P	8408150653*	50-354 Q
DURR, J P	8408160260*	50-322 Q
DURR, J P	8408210317*	50-336 Q
DURR, J P	8408230145*	50-271 Q
DURR, J P	8408230285*	50-293 Q
DURR, J P	8408270242*	50-410 Q
DURR, J P	8408300113*	50-247 Q
DURR, J P	8408300116*	50-29 Q
DUS, R S	8408160140	50-373 R
DUTTA, P	8408220324	WASTE MGT
DUVALL, D D	8408030089	GA999
DUVALL, D D	8408030165	GA999
DUVALL, D D	8408070317	GA999
DUVALL, D D	8408220317	50-245 S
DUVALL, D D	8408240259	GA999
DUVALL, D D	8408240276	GA999
DYER, F F	8408300272	NUREG
DYKSTRA, J	8408130007	NUREG
DYNNER, A R	8408140013	50-322 T
DYNNER, A R	8408140013	50-322 T
DYNNER, A R	8408140466	50-322 Q
DYNNER, A R	8408140466	50-322 Q
DYNNER, A R	8408230264	50-322 Q
DYNNER, A R	8408230264	50-322 Q
DZENIS, E A	8408140262*	50-250 Q
DZENIS, E A	8408140262*	50-250 Q
EAGLE, J B	8408060251	50-265 S
EAPEN, P K	8408090051*	50-277 Q
EARLE, D K	8408020029	50-341 K
EARLE, D K	8408160474	50-341 A
EBERLY, R	8408140093*	50-400 T
EBERSOLE, J C	8408170287	ACRS
EBERSOLE, J C	8408170316	ACRS
EBERSOLE, J C	8408170373	ACRS
EBERSOLE, J C	8408170378	ACRS
EBERSOLE, J C	8408220076	WASTE MGT
ECKER, R M	8408130043	NUREG
ECKERT, J P	8408270121*	70-27
ECKERT, J P	8408270256*	70-27
ECKERT, J P	8408270274*	70-27
ECKERT, J P	8408310039*	70-27
ECKHARDT, J	8408140346	50-312 S
ECKHARDT, J H	8408300254*	50-312 Q
ECONOMOS, N	8408280393*	50-413 Q
EDDLEMAN, W	8408030070	50-400 Q
EDDLEMAN, W	8408030070	50-400 Q
EDDLEMAN, W	8408070459	50-400 Q
EDDLEMAN, W	8408140002	50-400 Q
EDDLEMAN, W	8408140119	50-400 Q
EDDLEMAN, W	8408140122*	50-400 Q
EDDLEMAN, W	8408140125*	50-400 Q
EDDLEMAN, W	8408160105	50-400 Q
EDDLEMAN, W	8408200498	50-400 Q
EDELMAN, M R	8408020118	50-440 I
EDELMAN, M R	8408030145	50-440 A
EDELMAN, M R	8408070184	50-440 A
EDELMAN, M R	8408090148	50-440 S
EDELMAN, M R	8408090261	50-440 S
EDELMAN, M R	8408130393	50-440 S
EDELMAN, M R	8408220498	50-440 S
EDELMAN, M R	8408220502	50-440 S
EDELMAN, M R	8408270320	50-440 F
EDELMAN, M R	8408280131*	50-440 Q
EDELMAN, M R	8408300054	50-440 S
EDWARDS, E W	8408010196	50-416 Q
EGBERT, D K	8408220399*	50-445 T
EICHENHOLZ, H	8408160082*	50-29 Q
EICHENHOLZ, H	8408270579*	50-29 Q
EINZIGER, R E	8408240379	NUREG
EISELE, W F	8408230524	50-374 S
EISENHUT, D G	8312120393*	50-329 A
EISENHUT, D G	8405160470	50-89 P
EISENHUT, D G	8405160473*	50-89 P
EISENHUT, D G	8406290259	50-322 T
EISENHUT, D G	8407310035	50-275 Q
EISENHUT, D G	8407310038	50-275 E
EISENHUT, D G	8408060161*	50-293 P
EISENHUT, D G	8408060408	50-206 P
EISENHUT, D G	8408070038*	50-170 P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
EISENHUT, D G	8408070059	50-311	P
EISENHUT, D G	8408070110	50-3	P
EISENHUT, D G	8408070127*	50-166	P
EISENHUT, D G	8408070309*	50-219	P
EISENHUT, D G	8408070455	50-445	A
EISENHUT, D G	8408080037*	50-346	F
EISENHUT, D G	8408080454	50-445	A
EISENHUT, D G	8408090409*	50-397	P
EISENHUT, D G	8408090414*	50-397	P
EISENHUT, D G	8408090517*	50-334	P
EISENHUT, D G	8408090524*	50-334	P
EISENHUT, D G	8408090533	50-170	P
EISENHUT, D G	8408090534*	50-170	P
EISENHUT, D G	8408130164	50-413	P
EISENHUT, D G	8408130298*	50-10	F
EISENHUT, D G	8408130559*	50-334	P
EISENHUT, D G	8408140558	50-166	P
EISENHUT, D G	8408140561*	50-166	P
EISENHUT, D G	8408150228*	50-219	P
EISENHUT, D G	8408150585*	50-271	P
EISENHUT, D G	8408160313	50-445	G
EISENHUT, D G	8408160477	50-352	A
EISENHUT, D G	8408170346*	50-334	F
EISENHUT, D G	8408200018	50-289	G
EISENHUT, D G	8408200275	50-3	P
EISENHUT, D G	8408200306	50-423	A
EISENHUT, D G	8408200441*	50-260	P
EISENHUT, D G	8408200489*	50-282	F
EISENHUT, D G	8408210005*	50-10	F
EISENHUT, D G	8408210011*	50-219	P
EISENHUT, D G	8408210359*	50-255	P
EISENHUT, D G	8408210404*	50-329	A
EISENHUT, D G	8408210433*	50-329	A
EISENHUT, D G	8408210450*	50-329	A
EISENHUT, D G	8408220099*	50-409	P
EISENHUT, D G	8408220173	50-445	T
EISENHUT, D G	8408220302*	ORG	
EISENHUT, D G	8408220469	50-289	P
EISENHUT, D G	8408230374	50-382	A
EISENHUT, D G	8408240115	50-206	S
EISENHUT, D G	8408240401	MISC	
EISENHUT, D G	8408270478*	50-346	F
EISENHUT, D G	8408280113	50-255	F
EISENHUT, D G	8408280171	50-213	F
EISENHUT, D G	8408280229	50-482	F
EISENHUT, D G	8408280348*	50-346	F
EISENHUT, D G	8408300515*	50-261	F
EISENHUT, D G	8408310284	50-266	P
EISENHUT, D G	8408310374	50-305	P
EISENHUT, D G	8408310410	MISC	
ELAM, B D	8408270290*	50-219	P
ELAYAT, H	8404230171*	50-400	F
ELEY, G D	8408020129	50-322	T
ELIN, J O	8408310244*	50-206	G
ELLEMAN, T S	8408140151*	50-400	T
ELLERSHAW, L E	8408090130*	50-313	G
ELLIOTT, C W	8408010190	50-352	G
ELLIOTT, C W	8408060170	50-352	G
ELLIS, D W	8408090104	50-29	S
ELLIS, D W	8408230340	50-29	S
ELLIS, J	8408090408	50-445	G
ELLIS, J	8408090420*	50-445	G
ELLIS, J	8408090434*	50-445	G
ELLIS, J	8408090463*	50-445	G
ELLIS, J	8408090480*	50-445	G
ELLIS, J	8408090488*	50-445	G
ELLIS, J	8408090512*	50-445	G
ELLIS, J	8408160106	50-445	G
ELLIS, J	8408160113*	50-445	G
ELLIS, J	8408160114	50-445	G
ELLIS, J	8408160141	50-445	G
ELLIS, J	8408160153*	50-445	G
ELLIS, J	8408160171	50-445	G
ELLIS, J	8408160178*	50-445	G
ELLIS, J	8408200605	50-445	G
ELLIS, J	8408240244	50-445	G
ELLIS, J	8408280136	50-445	G
ELLIS, J	8408280141*	50-445	G
ELLIS, J	8408310102	50-445	G
ELLIS, J	8408310105*	50-445	G
	8408270456*	50-280	G
	8408230392	50-338	S
	84082703294	50-250	G
	8408270363*	50-335	G
	8408070205	50-29	S
ELSASSER, T	8408290007*	50-423	G
ELSASSER, T C	8406260179*	70-1143	
ELSASSER, T C	8408080403*	50-245	G
ELSASSER, T C	8408090141*	50-213	G
ELSASSER, T C	8408150255*	50-213	G
ELSASSER, T C	8408270486*	50-184	G
ELSASSER, T C	8408270518*	50-54	G
ELTON, T L	8408200438	50-366	S
ELTON, T L	8408220491	50-366	S
ELTON, T L	8408270229	50-321	S
ELTON, T L	8408300333	50-321	S
EMBREY, D E	8408010166	NUREG	
EMCH, R L	8408160343	50-155	P
EMCH, R L	8408160346	50-155	P
EMMETT, J	8408290328	50-454	G
EMRIT, R	8408220265	NUREG	
ENDRES, G W	8408290171	NUREG	
ENG, P	8408230252*	50-454	G
ENGEL, R F	8408280353	50-354	H
ENGELDER, T C	84083001944	70-824	
ENGELKEN, R H	8408130220	50-361	A
ENGELKEN, R H	8408130293	50-361	G
ENGELMANN, R	8408240406	40-8584	
ENGELMANN, R	8408270104	40-4492	
ENGLAND, L A	8408210376	TOPREP	
ENGLAND, L A	8408210376	TOPREP	
ENGLE, L B	8408090441	50-338	P
ENGLE, L B	8408210575	50-338	P
ENNIS, J D	8408130204*	50-395	G
ENNIS, J D	8408130418*	50-338	G
ENNIS, K	8408280126*	QA999	
ENNIS, K	8408280139*	QA999	
EPSTEIN, G	8408060256	WASTE MGT	
ERDMAN, C A	8408150371	50-59	R
ERICKSEN, E P	8408170326*	50-454	T
ERICKSEN, E P	8408170326*	50-454	T
ERLER, B	8408310192	50-454	T
ESCH, H E	8408310165*	50-255	G
ESELGROTH, P	8408030157	50-388	S
ESELGROTH, P	8408290483*	50-322	G
ESKRIDGE, H E	8408020205	70-36	
ESKRIDGE, H E	8408210183	70-36	
ESKRIDGE, H E	8408210190*	70-36	
ESPINOSA, G	8408310037	XPORTLIC	
ETHRIDGE, D	8408080089	50-445	T
ETHRIDGE, D	8408220403*	50-445	T
ETHRIDGE, D	8408220403*	50-445	T
EVANS, C A	8408030275*	50-382	G
EVANS, C A	8408160504*	50-313	G
EVANS, C A	8408230522*	50-267	G
EVANS, C A	8408270007*	50-458	G
EVERETT, R J	8408200052*	50-272	G
EWING, J W	8408140413*	50-346	P
EYSTER, R	8408150324	50-413	G
FALCONER, D P	8408230166*	50-251	G
FALEVITS, Z	8408150293*	50-255	G
FALEVITS, Z	8408300196*	50-440	G
FALEVITS, Z	8408300220*	50-341	G
FALLIN, J F	8408160234	50-275	G
FALTER, H W	8408100101*	50-461	A
FANNING, G	8408080257	50-445	T
FARBER, M J	8408160193*	50-483	G
FARLEY, E M	8408010169	50-322	G
FARLEY, E M	8408010169	50-322	G
FARLEY, E M	8408090411	50-322	G
FARLEY, E M	8408090411	50-322	G
FARLEY, E M	8408090431	50-322	G
FARLEY, E M	8408090431	50-322	G
FARLEY, E M	8408150438	50-322	G
FARLEY, E M	8408150438	50-322	G
FARLEY, E M	8408230231	50-322	G
FARLEY, E M	8408230231	50-322	G
FARLEY, E M	8408280492	50-322	G
FARLEY, E M	8408280492	50-322	G
FARLEY, E M	8408290317	50-322	G
FARLEY, E M	8408290317	50-322	G
FARLEY, E M	8408310218	50-322	G
FARLEY, E M	8408310218	50-322	G
FARLEY, E M	8408310224	50-322	G
FARLEY, E M	8408310224	50-322	G
FARNELL, A S	8408140263*	50-329	A
FARNELL, A S	8408140263*	50-329	A
FARRAR, D L	8408030252*	50-10	G
FARRAR, D L	8408070212*	50-454	G
FARRAR, D L	8408130413*	50-10	F
FARRAR, D L	8408140139	50-237	F
FARRAR, D L	8408140169*	50-374	G
FARRAR, D L	8408140180*	50-374	G
FARRAR, D L	8408140190*	50-374	G
FARRAR, D L	8408140241*	50-454	G
FARRAR, D L	8408140397	50-237	F
FARRAR, D L	8408160145*	50-10	G
FARRAR, D L	8408160345	50-237	P
FARRAR, D L	8408170359	50-454	A
FARRAR, D L	8408210203*	50-374	G
FARRAR, D L	8408210358*	50-454	G
FARRELL, C A	8408170339*	50-354	G
FARRELL, C A	8408170342*	50-354	G
FARRELL, E V	8408150188	50-317	S
FARRELL, R E	84082002924	50-458	G
FARRON, P	8408010162	50-388	G
FASANO, A	8408010170	50-320	S
FASANO, A	8408010174	50-320	S
FASANO, A	8408010220	50-320	S
FASANO, A	8408010230	50-320	S
FASANO, A	84083003814	50-320	G
FAUBER, J	8408270031	40-8502	
FAUBER, J	8408270069	40-8502	
FAUBER, J	8408270138	40-8502	
FAW, R E	8408310117	50-188	F
FAY, C W	8407310166	50-266	K
FAY, C W	8408030147	50-266	F
FAY, C W	84081000324	50-266	G
FAY, C W	8408210232	50-266	R
FAY, C W	8408270233	50-266	P
FAY, C W	8408280128	50-266	P
FAY, C W	8408280216	50-266	P
FAY, C W	8408300311	50-266	S
FAY, C W	8408300518	50-266	S
FEE, W F	8408280258	50-423	E
FEE, W F	8408280258	50-423	E
FEHRINGER, D J	8408230062	WASTE MGT	
FEIERABEND, C D	84082703634	50-335	G
FELTON, J M	8407130037	FOIA	
FELTON, J M	8408010061	50-329	A
FELTON, J M	8408310135	FOIA	
FELTON, J M	8408310142	50-275	P
FELTON, J M	8408310147	50-344	P
FELTON, J M	8408310151	50-142	P
FELTON, J M	8408310158	FOIA	
FENSTERMACHER	8408130225*	50-289	P
FERGUSON, R L	8408140093*	50-400	T
FERKIN, Z G	8408020047	50-352	G
FERLIC, K	8408100035	50-29	S
FERLIC, K	84082704104	50-309	G
FERNANDEZ, C	83070100394	50-277	P
FEY, F L	8408300174	50-263	F
FEY, F L	84083001804	50-263	F
FEY, F L	84083001834	50-263	F
FIEDLER, D C	8408100124	QA999	
FIEDLER, P B	8408010293	50-219	G
FIEDLER, P B	84080601424	50-219	G
FIEDLER, P B	8408070152	50-219	P
FIEDLER, P B	8408070300	50-219	P
FIEDLER, P B	8408070349	50-219	P
FIEDLER, P B	8408070454	50-219	P
FIEDLER, P B	8408080498	50-219	G
FIEDLER, P B	8408090250	50-219	P
FIEDLER, P B	8408130191	50-219	F
FIEDLER, P B	8408220356	50-219	P
FIEDLER, P B	8408220375	50-219	P
FIEDLER, P B	84082300984	50-219	G
FIEDLER, P B	8408270285	50-219	P
FIEDLER, P B	8408270381	50-219	P
FIEDLER, P B	8408310128	50-219	G
FIELDS, J S	8408300340	50-387	S
FIKAR, L F	8408200295	50-445	G
FIKAR, L F	84082204124	50-445	G
FINDLEY, D E	84081304374	CONTRACT	
FINDLEY, D E	84081304424	CONTRACT	
FINDLEY, D E	84081304454	CONTRACT	
FINKEL, A	84080804904	50-289	G
FINKEL, A	84080703304	50-322	G
FINKEL, A	84082005044	50-354	G
FIORATO, A E	84082200904	50-329	A
FIORELLI, G	84081507514	50-329	A
FIORELLI, G	84083001954	50-528	G
FIORENTA, A J	84082802034	50-412	E
FISCHER, B S	8408200455	50-289	G
FISCHER, D	84080101324	50-329	G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FISCHER, D	8408010153*	50-329 O
FISCHER, D	8408010160*	50-329 S
FISCHER, D	8408010168*	50-329 O
FISCHER, D	8408010178*	50-329 O
FISCHER, D	8408170257*	50-329 A
FISCHER, D C	8408010135*	50-329 O
FISCHER, D C	8408010143*	50-329 O
FISCHER, D C	8408010152*	50-329 O
FISCHER, D C	8408010173*	50-329 O
FISCHER, D C	8408220428	50-272 F
FISCHER, R E	8408150983	70-1151
FISH, R F	8408300127*	50-528 Q
FISH, R F	8408300504*	50-312 Q
FISICARO, J J	8408060289	50-285 S
FITZPATRICK, R	8408150652*	50-329 A
FLACK, E	8407110250	I&E
FLACK, E	8408010251	I&E
FLACK, E	8408210407	I&E
FLACK, E	8408240357	I&E
FLACK, E	8408280068	I&E
FLACK, E	8408280073	I&E
FLACK, E	8408300146	50-261 Q
FLEENOR, C	8408010175	CONTRACT
FLEENOR, C	8408130592	CONTRACT
FLEENOR, C.	8408230330	CONTRACT
FLEISCHMANN, R	8408150602	71-9111
FLETCHER, C D	8408160248	50-269 P
FLORY, C A	8408010327	WASTE MGT
FLOYD, J R	8408200531	50-289 Q
FLOYD, J R	8408220390	50-289 H
FLUEHR, J	8408280343	50-285 S
FLUEHR, J J	8408240230	50-285 S
FLY, J	8408100153	NUREG
FLYNN, S F	8408140146	50-400 T
FOGARTY, D J	8408210479	50-362 Q
FOLEY, T	8408010300*	50-247 Q
FOLEY, T	8408240363*	50-317 Q
FOLEY, W J	8408090272	NUREG
FOLEY, W J	8408130265	NUREG
FOLEY, W J	8408310084	NUREG
FONTANA, M H	8408230097	50-327 P
FORD, E J	8408270382*	50-327 Q
FORNEY, W	8406140104*	50-456 Q
FORNEY, W	8408200324	50-483 S
FORNEY, W L	8408230233*	50-483 Q
FORNEY, W L	84082304B0*	50-358 Q
FORNEY, W L	8408290561*	50-456 Q
FORTUNA, R	8408020194*	FOIA
FOSTER, D O.	8408010336	50-424 H
FOSTER, D O	8408060003	50-424 F
FOSTER, D O	8408090023	50-424 S
FOSTER, D O	8408130412	50-424 A
FOSTER, D O.	8408150494	50-424 A
FOSTER, D O	8408170301	50-424 A
FOSTER, D O	8408240367*	50-424 Q
FOSTER, D O	8408270430*	50-424 Q
FOSTER, D O	8408280208	50-424 A
FOSTER, D O	8408300346*	50-424 Q
FOSTER, L C	8408270221*	50-335 Q
FOSTER, L E	8408270492*	50-413 Q
FOWLER, L	8408010267	50-424 Q
FOWLER, L	8408010267	50-424 Q
FOX, M J	8408070140*	WASTE MGT
FOX, R A	8408290171	NUREG
FRALEY, R F	8205240603*	50-327 O
FRANCE, G M	8408020223*	70-8
FRANCE, G M	8408200241*	50-155 Q
FRANKEL, M R	8408310194*	50-454 T
FRANKEL, M R	8408310194*	50-454 T
FRANZ, W D	8408220151	50-456 D
FREDERICKSON, P	8408240286	50-328 S
FREDERICKSON, P	8408280267	50-327 S
FREEMAN, M D	8408240339	40-8768
FREEMAN, M D	8408240377	40-8768
FREI, M W	8408070063	WASTE MGT
FRISCH, R R	8408090398	50-255 S
FRISHMAN, S	8408160479	WASTE MGT
FRYE, J H	8408080201	50-358 Q
FRYE, J H	8408080239	50-142 Q
FRYE, J H	8408220288	50-70 Q
FRYE, J H	8408310104	50-358 Q
FUHRMAN, G R.	8408270535	50-317 R
FULLER, A Q	8408140023*	50-400 T
FULLER, C	8408230457*	50-267 R
FULLER, C.	8408230459*	50-267 R
FUNCHES, J L	8408200182	50-255 O
FURR, B J	8408280186	50-400 Q
GAGLIARDO, J E	8408030266	50-382 Q
GAGLIARDO, J E	8408060054	50-382 Q
GAGLIARDO, J E	8408060317	50-382 Q
GAGLIARDO, J E	8408150510	50-382 Q
GAGLIARDO, J E	8408160220	50-382 Q
GAGLIARDO, J E	8408220247	50-382 Q
GAGLIARDO, J E	8408220494	50-382 Q
GAGLIARDO, J E	8408230275	50-382 Q
GAHM, J W	8408210462	50-267 P
GAHM, J W	8408230456	50-267 R
GAHM, J W	8408280480	50-267 F
GALLAGHER, E	8408150727*	50-329 A
GALLAGHER, E J	8408140039*	50-329 A
GALLAGHER, G	8408140575*	50-329 A
GALLAGHER, J W	8408070228	50-352 A
GALLAGHER, J W	8408210394*	50-352 Q
GALLO, J	8408270163	50-454 Q
GALLO, J	8408270163	50-454 Q
GALLO, R	8408230091*	50-293 Q
GALLO, R	8408240283	50-278 S
GALLO, R M	8408030229*	50-271 Q
GALLO, R M	8408130262*	50-443 Q
GALLO, R M	8408210381*	50-352 Q
GAMBERG, R C	8408280205	50-413 T
GAMMILL, W P	8408230033	WASTE MGT
GAMMILL, W P	8408280338	WASTE MGT
GARBER, I	8408070288*	50-305 F
GARCIA, P J	8408210120*	40-2259
GARCIA, P J	8408210143*	40-4492
GARCIA, P J	8408240116	40-299
GARCIA, P J	8408240163	40-299
GARCIA, P J	8408240185	40-299
GARCIA, P J	8408240380	40-299
GARCIA, P J	8408270037	40-299
GARCIA, P J	8408270068	40-299
GARCIA, P J	8408270228	40-8084
GARCIA, R	8408100121	TOPREP
GARCIA, R	8408140200	TOPREP
GARDE, B P	8408170223*	50-329 Q
GARDE, B P	8408170312*	50-329 T
GARDE, B P	8408270336*	50-329 T
GARDNER, R N	8408170166*	50-329 A
GARDNER, R N	8408170181*	50-329 Q
GARDNER, R N	8408220064*	50-329 T
GARLAND, W	8408240040	40-8727
GARNER, D J	8408200567	50-483 Q
GARNER, L	8408270269*	50-321 Q
GARNER, L	8408270536*	50-261 Q
GARNER, L F	8408140027*	50-400 T
GARRISON, R F	8408150542	71-6346
GAUTAM, A	8408300196*	50-440 Q
GAUTAM, A	8408300220*	50-341 Q
GAUTAM, A S	8408300121*	50-456 Q
GAYLEY, J	8408010249	50-454 T
GEARS, G	8408210237	50-278 P
GEARS, G E	8408220527	50-277 P
GEKAS, G W	8408020208	50-289 Q
GEORGE, J B	8408030153	50-445 A
GEORGE, J B	8408060184	50-445 R
GEORGE, J B	8408170065	50-445 R
GEORGIEV, G B	8408170117*	50-443 Q
GERDEMAN, F W	8408130272	40-8674
GERDEMAN, F W	8408240047	40-8674
GERDEMAN, F W	8408240351	40-7869
GERDEMAN, F W	8408240410	40-8678
GERRETS, T F	8408010399	50-382 S
GERRETS, T F	8408030296	50-382 S
GERRETS, T F	8408060032	50-382 S
GERRETS, T F	8408060061	50-382 S
GERRETS, T. F	8408090029	50-382 S
GERRETS, T F	8408160180	50-382 S
GERRETS, T F	8408160221	50-382 S
GERRETS, T F.	8408160228	50-382 S
GERRETS, T F	8408240407	50-382 S
GERRETS, T F	8408280436	50-382 S
GERRETS, T F	8408280440	50-382 S
GERRETS, T F.	8408290131	50-382 S
GERRETS, T F	8408290139	50-382 S
GERRETS, T F	8408290145	50-382 S
GERRETS, T F	8408300521	50-382 S
GERVERS, J H	8408210097	WASTE MGT
GEWEHR, S	8408090274	50-370 S
GEWEHR, S	8408150221	50-369 S
GEWEHR, S	8408280389	50-369 S
GEWEHR, S	8408290094	50-370 S
GIAMBALVO, E W	8408310160	50-373 S
GIBBON, T R	8408150731*	50-329 A
GIBBONS, T D	8408270414*	50-424 Q
GIBSON, J	8408200594	50-336 R
GIESLER, C W	8407260161	50-305 K
GIESLER, C W	8408020073	50-305 P
GIESLER, C W	8408310122	50-305 P
GILDENHORN, A J	8408090504	CONTRACT
GILDENHORN, A J	8408220075	CONTRACT
GILL, C F	8408010341*	50-454 Q
GILL, C F	8408270090*	50-341 Q
GILLEN, D M	7909290119*	50-329 A
GILLEN, D M	8408280340	WASTE MGT
GILLER, K T	8408080359	NUREG
GILMORE, T	8408030093	50-528 K
GIRARD, E H	8408240342*	50-259 Q
GIRARD, E H	8408270240*	50-438 Q
GIUFFRIDA, L O	8408290356	COMMISSION
GLASS, S M	8408070427	50-322 Q
GLASS, S M	8408150443	50-322 Q
GLENN, J	8408100129	I&E
GLOERSEN, W B	8408010299*	50-409 Q
GLOERSEN, W B	8408240429*	50-305 Q
GLORA, M	8408210180	WASTE MGT
GNUGNOLI, G N	8406190514	WASTE MGT
GODDARD, R J	8408070368	50-155 Q
GODDARD, R J	8408130294	50-461 Q
GODDARD, R J	8408200250	50-322 Q
GODDARD, R J	8408270082	50-322 Q
GODDARD, R J	8408270088*	50-322 Q
GODDARD, R J	8408270137	50-322 Q
GODDARD, R J	8408270164	50-155 Q
GODDARD, R J	8408280424	50-322 Q
GODFREY, D A	8408130157	PT21
GODY, A	8408080166*	50-387 Q
GODY, A T	8408080242*	50-244 Q
GODY, A T	8408090051*	50-277 Q
GODY, A T	8408150455*	50-333 Q
GOGOL, E	8408100110	50-295 P
GOLDBERG, J H	8408010222	50-498 K
GOLDBERG, J H	8408070446	50-498 A
GOLDBERG, J H	8408220161	50-498 A
GOLDBERG, J H	8408270355	50-498 A
GOLDBERG, J R	8408010194	50-289 Q
GOLDBERG, J R	8408090415	50-289 Q
GOLDBERG, J R	8408270072	50-289 Q
GOLDBERG, J R	8408280409	50-289 Q
GOLDBERG, J R	8408290012	50-289 Q
GOLDEN, M P	8408150129	50-244 J
GOLDMANN, K	8408140469	71-9016
GOLDMANN, K	8408140476*	71-9016
GOLDMANN, K.	8408150594	71-9016
GOLDMANN, K	8408150647	71-9016
GOLDSTEIN, I L	8408240248*	50-445 T
GOLDSTEIN, I L	8408240248*	50-445 T
GONZALES, R O	8004040738*	50-329 A
GOODMAN, L S	8408160186	50-409 S
GOODMAN, L S	8408160309	50-409 S
GOODWIN, W L	8408290560	70-1151
GORDON, M	8408130105	WASTE MGT
GORMAN, J A	8408280205	50-413 T
GOULD, C H	8408140060*	50-329 A
GRACE, J N	8408070376	50-3 Q
GRACE, J N	8408160077	QA999
GRACE, J N	8408160156	QA999
GRADY, W D	8408020132	50-280 F
GRAESSER, K L	8408060290	50-304 S
GRAESSER, K L	8408090047	50-304 S
GRAESSER, K L	8408090326	50-304 S
GRAESSER, K L	8408090404	50-295 S
GRAESSER, K L	8408130405	50-304 S
GRAESSER, K L	8408130456	50-304 S
GRAESSER, K L	8408130604	50-295 S
GRAESSER, K L	8408160122	50-295 R
GRAESSER, K L	8408160150	50-295 S
GRAESSER, K L	8408200547	50-304 S
GRAESSER, K L	8408230514	50-295 S
GRAESSER, K L	8408240042	50-295 S
GRAESSER, K L	8408300093	50-295 S
GRAESSER, K L	8408300136	50-295 R
GRAESSER, K L	8408310168	50-295 F
GRAHAM, D	8408160326	50-302 R
GRAMM, R A	8408240253*	50-410 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
GRANELEY, G W	8408080144	40-8681	
GRANT, P	8408010170	50-320	S
GRANT, P	8408010174	50-320	S
GRANT, P	8408010220	50-320	S
GRANT, P	8408010230	50-320	S
GRANT, P J	8408010055	50-320	R
GRANT, P J	8408010090	50-320	P
GRANT, P J	8408010100	50-320	P
GRANT, P J	8408010105	50-320	P
GRANT, P J	8408010242	50-320	P
GRANT, P J	8408070252	50-320	R
GRANT, P J	8408090555	50-320	R
GRANT, P J	8408230425	50-289	R
GRANT, W B	8408150547*	50-263	Q
GRANT, W B	8408230480*	50-338	Q
GRAVES, R H	8408230482	50-213	S
GRAY, E H	8408150370*	50-272	Q
GRAY, E H	8408170117*	50-443	Q
GRAY, E H	8408210517*	50-336	Q
GRAY, E H	8408270410*	50-309	Q
GREENE, T R	8408060101*	50-373	F
GREENMAN, E	8408030157	50-388	S
GREENMAN, E	8408070205	50-29	S
GREENMAN, E C	8408080443	70-364	
GREEVES, J T	8408220324	WASTE MGT	
GREGER, L R	8408010341*	50-454	Q
GREGER, L R	8408020223*	70-8	
GREGER, L R	8408080496*	50-295	Q
GREGER, L R	8408150381*	50-440	Q
GREGER, L R	8408150406*	50-266	Q
GREGER, L R	8408150547*	50-263	Q
GREGER, L R	8408200241*	50-155	Q
GREGER, L R	8408270090*	50-341	Q
GREGER, L R.	8408300164*	50-255	Q
GREGG, H	8408080530*	50-352	Q
GREGORY, M	8408070105	50-445	T
GREGORY, M	8408070105	50-445	T
GREGORY, W B	8408160146	NUREG	
GRIDLEY, R L	8408130173*	50-331	P
GRIDLEY, R L	8408170262*	50-263	P
GRIDLEY, R L	8408270175*	50-331	P
GRIFFIN, J M	8408150180	50-313	P
GRIFFIN, J M	8408220313	50-313	P
GRIFFIN, J M	8408310231	50-313	P
GRIFFITH, J D	8408270319	PR	
GROTENHUIS, M	8408070218	50-324	P
GROTENHUIS, M	8408210009	50-325	P
GROVES, D N.	8408300060*	50-263	Q
GRUMLEY, J E	8408290307	50-454	Q
GUCWA, L T	8408070141	50-366	Q
GUCWA, L T	8408070148	50-321	P
GUCWA, L T	8408130379	50-321	P
UCWA, L T	8408150242	50-366	P
CWA, L T	8408210175	50-366	P
CWA, L T	8408210357	50-321	P
CWA, L T	8408210474	50-321	P
CWA, L T	8408230251	50-321	P
CWA, L T	8408270247*	50-321	Q
CWA, L. T.	8408280183	50-366	Q
CWA, L T	8408280239	50-321	Q
JCWA, L T	8408300024	50-321	P
UCWA, L T	8408300072	50-321	I
GUCWA, L T	8408300115	50-366	P
GUEY, C N	8408010287*	50-206	P
GUILD, R	8408070443	50-413	Q
GUILD, R	8408070443	50-413	Q
GUILD, R	8408070443	50-413	Q
GUILD, R	8408200548	50-413	Q
GUILD, R	8408200548	50-413	Q
GUILD, R	8408200548	50-413	Q
GUILD, R	8408310205	50-413	Q
GUILD, R	8408310205	50-413	Q
GUILD, R	8408310205	50-413	Q
GUINN, F K.	8408130381*	70-143	
GUINN, F K	8408270413*	70-143	
GUINN, F K.	8408280053*	70-143	
GUINN, F K	8408280174	70-143	
GUINN, F K	8408280299*	70-143	
GULDEMOND, W G	8408080181*	50-263	Q
GULDEMOND, W G.	8408160331*	50-266	Q
GULDEMOND, W G	8408280085*	50-254	Q
GUNN, H F	8408080032	50-445	T
GUNN, H F	8408080032	50-445	T
GUNN, H. F	8408220405*	50-445	T
GUNN, H F	8408220405*	50-445	T
GUO, J S	8408150569*	50-346	P
GUSTE, W J	8408090154*	50-416	Q
GUTHRIE, S	8408030179*	50-155	Q
GUTTERMAN, A H	8408080186	50-498	Q
GUTTERMAN, A H	8408080186	50-498	Q
GUTTMAN, D	8408290342	50-458	M
HAFEMEISTER, D	8408310212	PR	
HAFEMEISTER, D	8408310215*	PR	
HAGAN, T F	8408060017*	CONTRACT	
HAGAN, T F	8408060025*	CONTRACT	
HAGAN, T F.	8408060037*	CONTRACT	
HAGAN, T F	8408060040*	CONTRACT	
HAGAN, T F.	8408060048*	CONTRACT	
HAGAN, T F	8408060214*	CONTRACT	
HAGAN, T F	8408080057*	CONTRACT	
HAGAN, T F	8408080480*	CONTRACT	
HAGAN, T F	8408090510*	CONTRACT	
HAGAN, T F	8408200597*	CONTRACT	
HAGAN, T F	8408200606*	CONTRACT	
HAGAN, T F	8408210032*	CONTRACT	
HAGAN, T F.	8408210046*	50-206	P
HAGAN, T F.	8408210047*	CONTRACT	
HAGAN, T F	8408220080*	CONTRACT	
HAGAN, T F.	8408220404*	CONTRACT	
HAGAN, T F.	8408240094*	CONTRACT	
HAGAN, T F.	8408290349*	CONTRACT	
HAGAN, T F	8408300237*	50-289	P
HAGAN, T F	84083100BB*	CONTRACT	
HAGEN, E W.	8408290190	NUREG	
HAGEN, E W.	8408290198	NUREG	
HAGEY, H	8408080020	CONTRACT	
HAGGARD, D. L	8408290171	NUREG	
HAISFIELD, M	8408230027	WASTE MGT	
HAIST, D	8408220139	50-361	S
HAIST, D	8408280078	50-362	S
HAIST, D P	8408080497*	50-344	Q
HALL, B L	8408070409*	50-390	Q
HALL, B L	8408130446*	50-338	Q
HALL, D P	8408060366	50-461	S
HALL, D P	8408070219	50-461	R
HALL, D P	8408070460*	50-461	Q
HALL, D P	8408080540	50-461	S
HALL, D P	8408130238	50-461	S
HALL, D P	8408270135	50-461	A
HALL, D P	8408270318	50-461	S
HALL, D P	8408280094	50-461	A
HALL, D P	8408300022	50-461	S
HALL, D P	8408300076	50-461	S
HALL, D P.	8408300210	50-461	S
HALL, D P.	8408300224	50-461	S
HALL, R	8408090174	50-267	S
HALL, R E.	8408060057*	50-382	Q
HALL, R E.	8408060180*	50-482	Q
HALL, R E	8408160523*	50-482	Q
HALL, R. E	8408200052*	50-272	Q
HALL, R E.	8408230152*	50-445	Q
HALL, R E	8408230466*	50-285	Q
HALL, R E.	8408230522*	50-267	Q
HALL, R E	8408270007*	50-458	Q
HALL, R E	8408290104*	50-298	Q
HALL, W. J	8408140194*	50-206	P
HALLMAN, G W	8408280205	50-413	T
HALLSTROM, G A	8408140081*	50-400	T
HALMAN, E L	8408310390*	CONTRACT	
HALUB, P	8408310180	XPORTLIC	
HAMADA, G	8408090004*	50-361	Q
HAMADA, G.	8408090091*	50-312	Q
HAMADA, G. H	8408270346*	70-734	
HAMILTON, P	8408160094	50-293	R
HAMILTON, P. J	8408100046	50-293	S
HAMILTON, P J.	8408100099	50-293	S
HAMILTON, P. J	8408300348	50-293	S
HAMMERICH, T	8408060107	50-374	S
HAMPTON, J. W	8408270169*	50-269	P
HAMPTON, L	8408140102*	50-329	A
HANAN, N	8408220333	50-352	A
HANAUER, S H	8408070413	PR	
HANNETT, B. A	8408230562	XPORTLIC	
HANNETT, B. A	8408230563*	XPORTLIC	
HANNETT, B A	8408310321*	XPORTLIC	
HANNETT, B. A	8408310325*	XPORTLIC	
HANNON, J. L	8408080370	NUREG	
HARBUCK, C C	8408160237*	50-458	Q
HARBUCK, C. C	8408220500*	50-382	Q
HARDGROVE, T W	8408240413	40-2259	
HARDGROVE, T W	8408270093	40-2259	
HARE, S M	8408280085*	50-254	Q
HARMON, D F	8408160257	ORG	
HARPSTER, T L	8408150459*	50-333	Q
HARRAN, G	8408230431	50-245	R
HARRELL, P H	8408090160*	50-313	Q
HARRINGTON, R M	8408130001	NUREG	
HARRINGTON, T E	8408100008	50-293	Q
HARRINGTON, W D	8408020130	50-293	P
HARRINGTON, W D	8408030022	50-293	S
HARRINGTON, W D	8408060005	50-293	P
HARRINGTON, W D	8408080503	50-293	R
HARRINGTON, W D	8408090114	50-293	S
HARRINGTON, W D	8408090248	50-293	P
HARRINGTON, W D	8408100046	50-293	S
HARRINGTON, W D	8408100099	50-293	S
HARRINGTON, W D	8408140239	50-293	P
HARRINGTON, W D	8408140250	50-293	P
HARRINGTON, W D	8408140251	50-293	P
HARRINGTON, W D	8408150055	50-293	Q
HARRINGTON, W D	8408150087	50-293	P
HARRINGTON, W D	8408160033	50-293	P
HARRINGTON, W D	8408160041	50-293	P
HARRINGTON, W D	8408160094	50-293	R
HARRINGTON, W D	8408160368	50-293	F
HARRINGTON, W D	8408160374	50-293	F
HARRINGTON, W D	8408220133	50-293	P
HARRINGTON, W D	8408300198	50-293	P
HARRINGTON, W D	8408300348	50-293	S
HARRIS, D O	8408150514*	50-322	T
HARRIS, J D	8408290190	NUREG	
HARRIS, J D	8408290198	NUREG	
HARRIS, J R	8408140086*	50-400	T
HARRIS, M S.	8408240172	50-331	S
HARRIS, R H	8408270242*	50-410	Q
HARRISON, J J	8408030076*	50-329	Q
HARRISON, J J	8408070173	50-329	A
HARRISON, J J	8408130399	50-329	A
HARRISON, J J	8408150702*	50-329	Q
HARRISON, J J	8408230512*	50-329	Q
HARRISON, J J	8408240144*	50-329	Q
HARRISON, S F	8407230153	NUREG	
HARRISON, S F	8408070117	GA999	
HARROLD, K	8408060197*	50-70	Q
HARSHBARGER, J	8408220238	WASTE MGT	
HARSHE, B L	8408090106*	COMMISSION	
HART, R D.	8408010311	50-251	S
HART, R D	8408030239	50-250	S
HART, R D	8408080230	50-250	S
HART, R. D	8408270203	50-250	S
HARTMAN, S L	8408220367	50-445	T
HARTMAN, S. L	8408220367	50-445	T
HARTMAN, W C	8408030041	GA999	
HARVEY, C O	8408310075	NUREG	
HARVEY, M D	8408060431	WASTE MGT	
HASSE, R.	8408010285*	50-341	Q
HASSELL, D. F	8408270151	50-322	Q
HASSELL, D F.	8408300129	50-338	Q
HATE, K. V	8408140023*	50-400	T
HAUGHEY, M F	8408060409	50-410	F
HAUGHEY, M F	8408080164	50-410	E
HAUGHEY, M. F	8408200148	50-410	E
HAUGHEY, M F	8408310267	50-410	A
HAUGHEY, M F	8408310351	50-410	E
HAWKINS, D A	8408220397	CONTRACT	
HAWKINS, D. A	8408270574	CONTRACT	
HAWKINS, D. A.	8408290347	CONTRACT	
HAWKINS, E F	8408240177	40-8722	
HAWKINS, E F	8408240180*	40-8768	
HAWKINS, E F	8408240183*	40-8768	
HAWKINS, E. F	8408240207	40-8698	
HAWKINS, E F	8408270040	40-8681	
HAWKINS, E F	8408270048	40-8768	
HAWKINS, E F	8408270099	40-8829	
HAWKINS, E F	8408270100	40-8698	
HAWKINS, E F.	8408270117	40-8681	
HAWKINS, E F	8408270197	40-8064	
HAWKINS, E F.	8408270205	40-8728	
HAWKINS, E F.	8408280334	40-8768	
HAWKINS, F	8408010285*	50-341	Q
HAWKINS, F.	8408060309*	50-456	Q
HAWKINS, F.	8408160217*	50-454	Q
HAWKINS, F	8408300121*	50-456	Q
HAWKINS, F. C	8408150511*	50-461	Q
HAWKINS, F C.	8408170274*	50-329	Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
HAWKINS, F C	8408230278*	50-373	Q
HAWKINS, F C	8408300199*	50-305	Q
HAWKINS, T I	8408200497*	50-400	Q
HAWXHURST, J	8408230235*	50-220	Q
HAWXHURST, J J	8408030221*	50-333	Q
HAYES, B B	8408020194*	FOIA	
HAYES, B B	8408020196*	50-329	Q
HAYES, B B	8408170311	50-289	Q
HAYES, D W	8408070221*	50-454	Q
HAYNES, J Q	8408010304	50-361	S
HAYNES, J Q	8408030123	50-206	F
HAYNES, J Q	8408060034	50-361	S
HAYNES, J Q	8408060039*	50-361	S
HAYNES, J Q	8408060223	50-361	S
HAYNES, J Q	8408070379	50-206	S
HAYNES, J Q	8408080489	50-361	S
HAYNES, J. Q	8408090418	50-362	S
HAYNES, J Q	8408140216	50-206	S
HAYNES, J Q	8408170059	50-361	S
HAYNES, J Q	8408240084	50-361	S
HAYNES, J Q	8408240200	50-362	S
HAYNES, J. Q	8408280225	50-361	S
HAYNES, J Q	8408280296	50-361	S
HAYNES, J Q	8408300492	50-361	S
HAZELTINE, J	8408210518*	50-352	A
HEARRON, T	8408170304*	50-329	T
HEBDON, F J	8408070026	DRQ	
HECKER, G E	8408270147*	50-412	E
HEETHER, W	8408210164	XPORTLIC	
HEETHER, W	8408210169	XPORTLIC	
HEHL, C W	8408200271*	50-416	Q
HEHL, C W	8408270187*	50-395	Q
HEHL, C W	8408270572*	50-395	Q
HEIDENREICH, J	8408140517*	CONTRACT	
HEIDER, L H.	8408100053	50-29	Q
HEIMAN, D	8408060432	XPORTLIC	
HEINS, J	8408230301*	50-341	E
HEINZ, J	8408220296	50-289	Q
HEISHMAN, R F	8408170117*	50-443	Q
HELGESON, K A	8408010024	70-820	
HELGESON, K. A.	8408020096	70-820	
HELLER, J K	8408300188*	50-315	Q
HELLER, L W.	8110190801*	50-329	A
HELTEMES, C. J	8406010162*	50-366	S
HELTEMES, C J.	8408060069	MISC	
HELTEMES, C. J.	8408060073*	MISC	
HELTEMES, C. J.	8408060077*	MISC	
HELTEMES, C. J	8408060081*	MISC	
HELTEMES, C. J	8408150320	NUREG	
HELTEMES, C J	8408220441	MISC	
HENDERSON, J D	8110260082*	50-329	S
HENNESSY, W P	8408210382*	TOPREP	
HENNICK, A	8408090272	NUREG	
HENNICK, A	8408130265	NUREG	
HENNICK, A	8408310084	NUREG	
HENRIES, W E	8408090182*	50-309	P
HENRY, L. Q	8408060162	50-57	F
HENSHAW, E.	8406130219	40-8027	
HENSHAW, E	8408080455	40-8027	
HENSLEY, K D	8408150545	70-143	
HENSLEY, K D.	8408170012	70-143	
HERBERT, R J	8408090340	50-245	S
HERBERT, R. J.	8408090340	50-245	S
HERBORN, D. I.	8408100089	50-461	A
HERBORN, D. I	8408140351	50-461	E
HERING, R F.	8405160248	50-315	Q
HERING, R. F.	8406080109	50-316	P
HERMANN, R. A.	8408060278	50-220	P
HERMANN, R. A.	8408060332	50-220	P
HERMANN, R. A.	8408150623*	50-293	P
HERNAN, R. W	8408130241*	50-329	A
HERNAN, R. W.	8408140522*	50-329	A
HERRICK, R. C	8407090037*	50-219	P
HERRINGTON, C C.	8408130033	70-1308	
HERSCH, M. M.	8408150237	XPORTLIC	
HERSCH, M M	8408150719	XPORTLIC	
HERSCH, M M.	8408150730	XPORTLIC	
HERSCH, M. M.	8408200493*	XPORTLIC	
HERSCH, M. M.	8408230488	XPORTLIC	
HERSCH, M M.	8408230498	XPORTLIC	
HERSCH, M. M	8408230510	XPORTLIC	
HERSHEY, S P	8408140540	50-352	Q
HIATT, S L.	8408090196	50-440	Q
HIATT, S. L.	8408090202*	50-440	Q
HIATT, S. L	8408090231	50-440	Q
HIATT, S L.	8408090245	50-440	Q
HIGGINBOTHAM, L	8408060274	WASTE MGT	
HIGGINBOTHAM, L	8408070276	WASTE MGT	
HIGGINBOTHAM, L	8408090331	WASTE MGT	
HIGGINBOTHAM, L	8408130140	WASTE MGT	
HIGGINBOTHAM, L	8408140358	WASTE MGT	
HIGGINBOTHAM, L	8408160051	WASTE MGT	
HIGGINBOTHAM, L	8408200208	WASTE MGT	
HIGGINBOTHAM, L	8408200452	WASTE MGT	
HIGGINBOTHAM, L	8408220219*	WASTE MGT	
HIGGINBOTHAM, L	8408230031	WASTE MGT	
HIGGINBOTHAM, L	8408230085	WASTE MGT	
HIGGINBOTHAM, L	8408230100	WASTE MGT	
HIGGINS, B E	8408160454	50-354	D
HIGGINS, J C	8408220424*	50-445	Q
HIGGINS, R L	8408310302*	50-255	Q
HILDEBRAND, J E	8408070203	50-320	Q
HILDENBRAND, P	8408240180*	40-8768	
HILDENBRAND, P	8408240183*	40-8768	
HILDENBRAND, P	8408240333*	40-8586	
HILDENBRAND, P	8408240385	40-8674	
HILDENBRAND, P	8408270040	40-8681	
HILDENBRAND, P	8408270048	40-8769	
HILDENBRAND, P	8408270117	40-8681	
HILDENBRAND, P	8408280334	40-8768	
HILL, C Z	8408240417	40-8584	
HILL, C Z.	8408270238	40-8584	
HILL, D	8408090019*	50-397	Q
HILL, D.	8408290349*	CONTRACT	
HILL, P. W	8408220080*	CONTRACT	
HILL, T V	8408030082	WASTE MGT	
HILL, T. V.	8408030084	WASTE MGT	
HILL, T. V	8408150193	40-6500	
HILL, T. V	8408270215	WASTE MGT	
HILL, T. V	8408240211	40-1341	
HILLS, D E	8408150475*	50-341	Q
HIND, J. A.	8408240428	50-305	Q
HINKLE, K	8408200314	XPORTLIC	
HINKLE, K A	8408150724	XPORTLIC	
HINTZ, D C	8408060244	50-305	S
HINTZ, D C.	8408070275	50-305	F
HINTZ, D C	8408070292	50-305	F
HINTZ, D C	8408080033	50-305	S
HINTZ, D C	8408080510	50-305	S
HINTZ, D C	8408100019	50-305	F
HINTZ, D C	8408100078	50-305	P
HINTZ, D C	8408160211	50-305	R
HINTZ, D C	8408220284	50-305	P
HINTZ, D C.	8408240199	50-305	P
HINTZ, D C.	8408280144	50-305	F
HINTZ, D C.	8408280475	50-305	P
HIPSHER, W. M	8408160297	WASTE MGT	
HIRSCH, D.	8408070386	50-142	Q
HIRSCH, D	8408070474	50-142	Q
HIRSCH, D	8408310152	50-142	P
HIRSCH, D	8408310209	50-142	Q
HITCHLER, M. J	8408140018*	50-400	T
HITCHLER, M J	8408140018*	50-400	T
HOCHBRUECKNER	8406040336	50-322	Q
HOCHENDONER, L	8408140449	50-219	Q
HODEL, D P.	8408290350*	COMMISSION	
HODGDON, A P	8408090197	50-352	Q
HODGDON, A P	8408090236*	50-352	T
HODSON, J	8408090330*	50-322	Q
HODSON, J.	8408200504*	50-354	Q
HOFFMAN, J.	8408160344	50-413	J
HOFMAN, L. A	8408020070*	50-133	P
HOGAN, R	8408150541*	50-333	Q
HOGAN, R T.	8408150305*	50-317	Q
HOGAN, R. T.	8408200544*	50-247	Q
HOGAN, T. F.	8408270576*	CONTRACT	
HOGGARD, S. T	8408080023	50-445	T
HOGGARD, S. T	8408220396*	50-445	T
HOLAHAN, G. M	8405180433*	REVIEW GRP	
HOLBROOK, K. L	8408290171	NUREG	
HOLCOMBE, J C	8408090194*	50-361	P
HOLDEN, C.	8408270410*	50-309	Q
HOLLAR, D E	8408130288	50-400	Q
HOLLENBACH, D.	8408300407*	50-528	Q
HOLLOP, E. E	8408270074	WASTE MGT	
HOLLOP, E E	8408270078*	WASTE MGT	
HOLMBERG, J	8408290309	50-454	Q
HOLMES, H. H	8408270284*	50-454	E
HOLMES, H. H	8408270292*	50-454	E
HOLMES, H H	8408270296*	50-454	E
HOLONICH, J J	8408210558	50-482	
HOLONICH, J J	8408280037	50-482	
HOLONICH, J J	8408280279	50-483	
HOLONICH, J J	8408300075	50-482	
HOLT, D D	8408130007	NUREG	
HON, A	8408080497*	50-344	
HOOD, D	8111240064*	50-329	
HOOD, D	8201050063*	50-329	
HOOD, D	8408020188*	50-329	
HOOD, D	8408020202*	50-329	
HOOD, D	8408140526*	50-329	
HOOD, D	8408150027*	50-329	
HOOD, D	8408170320*	50-329	
HOOD, D	8408210377*	50-329	
HOOD, D	8408210379*	50-329	
HOOD, D	8408210384*	50-329	
HOOD, D	8408210446*	50-329	
HOOD, D S	8203020050*	50-329	
HOOD, D S	8301190487*	50-329	
HOOD, D S	8408020178*	50-329	
HOOD, D S	8408030004*	50-329	
HOOD, D S	8408030013*	50-329	
HOOD, D S	8408150709*	50-329	
HOOKS, R. W	8408310199*	50-454	
HOOPER, R L	8408130081*	WASTE MGT	
HOOTEN, B Q	8408020079	NUREG	
HOPKE, P K	8408030276	50-151	
HOPKINS, J	8408220427	50-395	
HOPPER, A	8408060014	CONTRACT	
HOPPER, A	8408060018	CONTRACT	
HOPPER, A	8408060031	CONTRACT	
HOPPER, A	8408060041	CONTRACT	
HOPPER, A	8408060211	CONTRACT	
HOPPER, A	8408080059	CONTRACT	
HOPPER, A	8408210042	50-206	
HORIN, W A	8408080413	50-445	
HORIN, W A	8408080413	50-445	
HORIN, W A	8408130305	50-445	
HORIN, W A	8408130305	50-445	
HORIN, W A	8408230319	50-445	
HORIN, W. A	8408230319	50-445	
HORIN, W A	8408280083	50-445	
HORIN, W A	8408280083	50-445	
HORIN, W A	8408310216	50-445	
HORIN, W A	8408310216	50-445	
HORVATH, E	8408200073	50-346	
HOWARD, J E	8408030121	50-293	
HOWARD, K E	8408080083	50-331	
HOWATH, E A	8408280087	50-346	
HOWE, P W	8408140151*	50-400	
HOWE, P W	8408280235	50-324	
HOYLE, A.	8408060038	CONTRACT	
HOYLE, A	8408300233	50-289	
HOYT, G W	8408090194*	50-361	
HOZLE, A J	8408230253	State Pr	
HSU, C.	8408310355	50-298	
HSU, C	8408310359*	50-298	
HU, C K.	8408170343*	50-354	
HUBBARD, F R	8408130225*	50-289	
HUBBARD, R B	8408020129	50-322	
HUDSON, G	8408300180*	50-263	
HUDSPETH, J. B.	8408210417	50-364	
HUETER, L J	8408010341*	50-454	
HUETER, L J.	8408270090*	50-341	
HUGHES, E A	8408010276*	50-206	
HUGHES, E A	8408010287*	50-206	
HUKILL, H D	8408020137	50-289	
HUKILL, H D	8408030006	50-289	
HUKILL, H D.	8408030088	50-289	
HUKILL, H D	8408030107*	50-289	
HUKILL, H. D.	8408070238	50-289	
HUKILL, H D	8408070280	50-289	
HUKILL, H D.	8408080300	50-289	
HUKILL, H D	8408090144	50-289	
HUKILL, H D	8408130218	50-289	
HUKILL, H D	8408130343	50-289	
HUKILL, H D	8408140404	50-289	
HUKILL, H D.	8408140411	50-289	
HUKILL, H. D	8408160182	50-289	
HUKILL, H. D	8408220218	50-289	
HUKILL, H D	8408220363	50-289	
HUKILL, H. D	8408240066	50-289	
HUKILL, H D	8408240167	50-289	
HUKILL, H D	8408270195	50-289	
HUKILL, H D	8408300503	50-289	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HULL, R E	8408160504*	50-313 Q
HUMPHREY, H H	8408080334*	PR
HUMPHREYS, P	8408010166	NUREG
HUNNICUTT, D	8408230152*	50-445 Q
HUNNICUTT, D M	8408150102*	50-445 Q
HUNNICUTT, D M	8408150440*	50-445 Q
HUNNICUTT, D M	8408150655*	50-445 Q
HUNNICUTT, D M	8408160037*	50-445 Q
HUNNICUTT, D M	8408160500*	50-445 Q
HUNNICUTT, D M	8408290108*	50-458 Q
HUNSTAD, A A	8408240238	50-282 S
HUNT, S W	8408150566*	50-329 A
HUNT, S W	8408150571*	50-329 A
HUNTER, D R	8408090121	50-313 Q
HUNTER, D R	8408100057	50-285 Q
HUNTER, D R	8408100069	50-482 Q
HUNTER, D R	8408100097	50-445 Q
HUNTER, D R	8408100139	50-482 Q
HUNTER, D R	8408140266	50-445 V
HUNTER, D R	8408160498	50-313 Q
HUNTER, D R	8408160520	50-482 Q
HUNTER, D R	8408230461	50-285 Q
HUNTER, D R	8408280075	50-285 V
HUNTER, D R	8408290113	50-368 Q
HUNTER, D R	8408290140	50-285 Q
HUNTER, D R	8408290172	50-368 Q
HURLEY, J	8408280143	50-416 F
HUSAIN, A	8408070478*	50-29 P
HUXTABLE, W P	8408130007	NUREG
HYDER, J E	8408010308*	50-151 Q
IDEKER, R. L	8408020154	70-143
IDEKER, R L	8408150136	70-143
IDEKER, R L	8408170392	70-143
IGNATONIS, A	8408140324	50-370 S
IGNATONIS, A J	8408230001	50-370 S
IGNATONIS, A J	8408240290	50-370 S
IGNATONIS, A J	8408240329	50-369 S
IGNATONIS, A J	8408280158	50-369 S
IMBRO, E	8408010345*	50-318 S
IMBRO, E V	8408010343	50-318 S
IPPOLITO, T	8408150029*	50-329 A
IPPOLITO, T A	8408090505	50-445 A
IPPOLITO, T A	8408140066	50-445 E
IRELAND, R E	8408060325*	50-382 Q
IRELAND, R E	8408160237*	50-458 Q
IRELAND, R E	8408160316*	50-267 Q
IRELAND, R E	8408220500*	50-382 Q
IRWIN, D P	8408070274	50-322 Q
RWIN, D P	8408070274	50-322 Q
RWIN, D P	8408070442	50-322 Q
RWIN, D P	8408070442	50-322 Q
RWIN, D P	8408070448*	50-322 Q
RWIN, D P	8408070448*	50-322 Q
RWIN, D P	8408080428	50-322 Q
RWIN, D P.	8408080428	50-322 Q
IRWIN, D P	8408140003	50-322 Q
IRWIN, D P	8408140003	50-322 Q
ISLEY, T.	8408160497	50-346 S
JABLONSKI, F J	8408240321*	50-461 Q
JACKA, B	8408080227	State Prog
JACKIW, I N	8408290570*	50-266 Q
JACKSON, G.	8408010028*	71-9163
JACKSON, G.	8408010031*	71-9163
JACKSON, G.	8408130292*	71-184
JACKSON, G	8408140480*	71-9016
JACKSON, R. E	8309270518*	50-329 Q
JACKSON, R E	8408140242*	50-329 A
JACOBS, G K	8408280007*	WASTE MGT
JACOBS, G K	8408300282	NUREG
JACOBS, R	8408090053*	50-387 Q
JACOBS, R. H	8408200041*	50-387 Q
JAFFE, D H	8403290354	50-317 S
JAFFE, D H	8408200320	50-317 P
JAFFE, D H	8408240015	50-317 P
JANDL, J C	8408160071	GA999
JANG, J	8408240076*	50-334 Q
JANG, J C	8408010398*	50-387 Q
JANG, J C	8408080467*	50-219 Q
JANG, J C	8408150305*	50-317 Q
JANSEN, R L	8408080284*	50-413 E
JAPE, F	8408270338*	50-321 Q
JAPE, F	8408270419*	50-390 Q
JAPE, F	8408270480*	50-413 Q
JAPE, F.	8408280049*	50-390 Q
JAUDON, J. P	8408060313*	50-285 Q
JAUDON, J P	8408090095*	50-458 Q
JAUDON, J P	8408150375*	50-313 Q
JAUDON, J P	8408160237*	50-458 Q
JAUDON, J P	8408160515*	50-458 Q
JAUDON, J P	8408200292*	50-458 Q
JAUDON, J P	8408200304*	50-458 Q
JAUDON, J P	8408200326*	50-458 Q
JAUDON, J P	8408220157*	50-458 Q
JAUDON, J P	8408220256*	50-382 Q
JAUDON, J P	8408220500*	50-382 Q
JAUDON, J P	8408230013*	50-298 Q
JAUDON, J P	8408270007*	50-458 Q
JAUDON, J P	8408270500*	50-298 Q
JAUDON, J P	8408290104*	50-298 Q
JAUDON, J P	8408290108*	50-458 Q
JEANMONOD, J	8408230215	GA999
JENKINS, G R	8408270317*	50-335 Q
JENKINS, G R	8408270423*	70-143
JENKINS, G R	8408270447*	50-389 Q
JENKINS, G R	8408270531*	70-27
JENKINS, G R	8408280082*	50-302 Q
JENKINS, G R	8408280289*	70-1201
JENKINS, G R	8408280485*	50-269 Q
JENKINS, G R	8408300204*	70-824
JENS, W H	8406010037	50-341 A
JENS, W H	8408010216	50-341 E
JENS, W H	8408060082	50-341 Q
JENS, W H	8408070356*	50-341 Q
JENS, W H	8408070440	50-341 A
JENS, W H	8408080299	50-341 F
JENS, W H	8408080305	50-341 F
JENS, W H	8408080511	50-341 S
JENS, W H	8408080516	50-341 S
JENS, W H	8408090055	50-341 S
JENS, W H	8408090062	50-341 S
JENS, W H	8408090071	50-341 S
JENS, W H	8408130163*	50-341 Q
JENS, W H	8408140016	50-341 S
JENS, W H	8408160444	50-341 S
JENS, W H	8408210079	50-341 A
JENS, W H	8408220135	50-341 S
JENS, W H	8408220175	50-341 S
JENS, W H	8408220193	50-341 S
JENS, W H	8408220209	50-341 S
JENS, W H	8408230274	50-341 F
JENS, W H	8408230276	50-341 E
JENS, W H	8408230389	50-341 F
JENS, W H	8408270352*	50-341 Q
JENS, W H	8408300045	50-341 S
JENS, W H	8408300061	50-341 S
JENS, W H	8408300069	50-341 S
JENS, W H	8408300209	50-341 S
JENS, W H	8408300216	50-341 S
JENS, W H	8408300223	50-341 S
JENS, W H	8408300251	50-341 S
JENS, W H	8408300257	50-341 S
JENS, W H	8408310188	50-341 F
JENSEN, C M	8408030066	50-112 F
JERSE, J L	8408240270	GA999
JIERREE, C C	8408210120*	40-2259
JIERREE, C C	8408210143*	40-4492
JIERREE, C C	8408230481*	40-8102
JIERREE, C C	8408240192	40-299
JIERREE, C C	8408240197*	40-299
JIERREE, C C	8408240209	40-8084
JIERREE, C C	8408270049	40-8452
JOHANSEN, J	8408100129	I&E
JOHNSON, A D	8408090019*	50-397 Q
JOHNSON, B D	8408060263	50-255 S
JOHNSON, B D	8408070435	50-255 F
JOHNSON, B D,	8408080331	50-255 P
JOHNSON, B, D	8408140295	50-255 F
JOHNSON, B D	8408140388	50-255 P
JOHNSON, B D	8408160279	50-255 S
JOHNSON, B, D	8408170364	50-255 F
JOHNSON, B D	8408230201	50-255 P
JOHNSON, B D	8408310056	50-255 S
JOHNSON, B D	8408310059	50-255 S
JOHNSON, B D	8408310161	50-255 Q
JOHNSON, C	8408090299	WASTE MGT
JOHNSON, C,	8408230172	50-317 P
JOHNSON, C E	8408200304*	50-498 Q
JOHNSON, D	8408150505*	50-322 T
JOHNSON, D, M	8408080448*	50-334 Q
JOHNSON, D P	8408150476*	50-322 T
JOHNSON, D P	8408150514*	50-322 T
JOHNSON, D R	8408140071*	50-329 A
JOHNSON, E H	8408030043	50-458 A
JOHNSON, E H	8408030044	50-298 Q
JOHNSON, E H	8408060092	50-482 Q
JOHNSON, E H	8408060175	50-482 Q
JOHNSON, E H	8408060202	50-298 Q
JOHNSON, E H	8408060307	50-285 Q
JOHNSON, E H	8408070225	50-267 P
JOHNSON, E H	8408090034	50-298 Q
JOHNSON, E H	8408090070	50-382 Q
JOHNSON, E H	8408090090	50-458 Q
JOHNSON, E H	8408090150	50-313 Q
JOHNSON, E H	8408100033	50-458 Q
JOHNSON, E H	8408100107	50-298 Q
JOHNSON, E H	8408100131	50-382 Q
JOHNSON, E H	8408100132	50-498 Q
JOHNSON, E H	8408140091	50-458 Q
JOHNSON, E H	8408150312	50-313 Q
JOHNSON, E H	8408150372	50-313 Q
JOHNSON, E H	8408160230	50-458 Q
JOHNSON, E H	8408160455	50-458 Q
JOHNSON, E H	8408160507	50-267 Q
JOHNSON, E H	8408160511	50-458 Q
JOHNSON, E H	8408170282	50-498 A
JOHNSON, E H	8408200290	50-458 Q
JOHNSON, E H	8408200299	50-498 Q
JOHNSON, E H	8408200316	50-458 Q
JOHNSON, E H	8408200581	50-267 P
JOHNSON, E H	8408210090	50-498 Q
JOHNSON, E H	8408220152	50-458 Q
JOHNSON, E H	8408230010	50-298 Q
JOHNSON, E H	8408230471	50-267 Q
JOHNSON, E H	8408270003	50-458 Q
JOHNSON, E H	8408270489	50-298 Q
JOHNSON, E H	8408270500*	50-298 Q
JOHNSON, E H	8408290101	50-298 Q
JOHNSON, E H	8408290103	50-458 Q
JOHNSON, E H	8408310040	50-267 P
JOHNSON, E H	8408310132	50-458 A
JOHNSON, F R	8408210518*	50-352 A
JOHNSON, G E	8408010211	50-413 Q
JOHNSON, G E	8408070422	50-413 Q
JOHNSON, G E	8408090191	50-413 Q
JOHNSON, G, E	8408130270	50-413 Q
JOHNSON, G E	8408200481	50-413 Q
JOHNSON, G E	8408200499	50-413 Q
JOHNSON, G E	8408200508	50-413 Q
JOHNSON, G E	8408200511*	50-413 Q
JOHNSON, G E	8408270092	50-413 Q
JOHNSON, G E	8408270109	50-413 Q
JOHNSON, G E	8408270119	50-413 Q
JOHNSON, G E	8408280455	50-413 Q
JOHNSON, H D	8408100094*	50-250 F
JOHNSON, J	8408230091*	50-293 Q
JOHNSON, P	8408060013	50-275 B
JOHNSON, P R	8408150485*	50-322 T
JOHNSON, T	8408010253	50-424 Q
JOHNSON, T C	8408020217	WASTE MGT
JOHNSON, T C	8408230420	WASTE MGT
JOHNSON, W D	8408060180*	50-482 Q
JOHNSON, W D	8408090130*	50-313 Q
JOHNSON, W D	8408090160*	50-313 Q
JOHNSON, W D	8408150375*	50-313 Q
JOHNSON, W. R	8408090178	50-382 Q
JOHNSTON, G W	8408300390*	50-344 Q
JOHNSTON, J B	8408070048*	50-414 H
JONES, D E	8408090189*	50-266 Q
JONES, D E	8408090195*	50-255 Q
JONES, D E	8408160327*	50-346 Q
JONES, D T,	8408010156*	50-412 F
JONES, D W	8408170286	50-538 F
JONES, D W	8408270225*	70-1151
JONES, D. W	8408300394*	70-27
JONES, D W	8408300401*	70-27
JONES, D. W	8408310255*	70-1151
JONES, G T	8408030257	50-259 S
JONES, G T	8408060113	50-259 S
JONES, G. T	8408080518	50-259 S
JONES, G. T	8408090020	50-259 S
JONES, G T	8408090341	50-259 S
JONES, G T	8408160508	50-259 S
JONES, G T	8408160518	50-259 S
JONES, G T	8408160519	50-259 S
JONES, G. T	8408200300	50-259 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JONES, G T	8408200412	50-296 S
JONES, G T	8408270150	50-296 S
JONES, G T	8408270366	50-259 R
JONES, G T	8408280349	50-259 S
JONES, V H	8408220171	50-280 R
JONES, W C	8408100062*	50-285 G
JORDAN, E L	8404040322*	50-321 F
JORDAN, E L	8406140090*	50-413 F
JORDAN, E L	8407250229	50-3 G
JORDAN, E L	8408010333	50-3 G
JORDAN, E L	8408010337	50-3 G
JORDAN, E L	8408070120	50-3 G
JORDAN, E L	8408100009	50-3 G
JORDAN, E L	8408100021	50-3 G
JORDAN, E L	8408100038	50-3 G
JORDAN, E L	8408100055	50-3 G
JORDAN, E L	8408140208	50-3 G
JORDAN, E L	8408210142	50-3 G
JORDAN, W S	8408070286	PR
JORDAN, W S	8408070344	PR
JORDAN, W S	8408130396	50-289 G
JORDAN, W S	8408130396	50-289 Q
JORDAN, W S	8408140035	50-289 Q
JORDAN, W S	8408140035	50-289 G
JORDAN, W S	8408240234	50-443 G
JORDAN, W S	8408240234	50-443 G
JOYNER, J	8408030002	I&E
JOYNER, J	8408100129	I&E
JOYNER, J	8408160003	I&E
JOYNER, J	8408160130	I&E
JOYNER, J	8408210280	I&E
JOYNER, J	8408310065	50-272 S
JOYNER, J	8408310080	I&E
JOYNER, J H	8408030188	50-410 G
JUDD, P V	8408140401	50-382 A
JUDD, P V	8408210403	50-382 A
JUDSON, V A	8408010181	50-454 G
JUDSON, V A	8408010181	50-454 G
JUDSON, V A	8408010181	50-454 G
JUDSON, V A	8408080390	50-454 Q
JUDSON, V A	8408080390	50-454 G
JUDSON, V A	8408080390	50-454 G
JUDSON, V A	8408080395	50-454 G
JUDSON, V A	8408170298	50-454 T
JULIAN, C A	8408030023	50-390 S
JULIAN, C A	8408200271*	50-416 G
JULIAN, C A	8408270347*	50-416 G
JULIAN, C A	8408270382*	50-327 G
JUNG-KI, P	8408280471*	COMMISSION
JUST, R A	8409130007	NUREG
JUSTICE, A D	8408220371*	50-445 T
JUSTICE, A D	8408220371*	50-445 T
KADAK, A C	8408280055	50-271 P
KADAMBI, P	8408080288	50-269 P
KADAMBI, P	8408090433	TOPREP
KAFKA, A	8408220333	50-352 A
KAHLE, J B	8408270286*	70-27
KAHLE, J B	8408270540*	70-1113
KAHLE, J B	8408300307*	70-1201
KALITOWSKI, T	8408080333	PR
KALIVIANAKIS, N	8408060251	50-265 S
KALIVIANAKIS, N	8408210068	50-254 R
KALIVIANAKIS, N	8408230435	50-254 R
KALIVIANAKIS, N	8408230496	50-254 S
KALIVIANAKIS, N	8408300299	50-254 R
KALMON, K J	8408310053	50-374 S
KALUZNY, S P	8408040386	NUREG
KAMMER, D S	8408300469*	50-327 G
KAMMEYER, J C	8408150530*	50-322 T
KANAKARIS, G A	8408140027*	50-400 T
KANAKARIS, G A	8408140027*	50-400 T
KANE, J	8408020038*	50-329 A
KANE, J	8408020071*	50-329 G
KANE, J	8408020086*	50-329 G
KANE, J	8408020099*	50-329 A
KANE, J	8408020127*	50-329 G
KANE, J	8408020178*	50-329 T
KANE, J	8408020186*	50-329 G
KANE, J	8408020193*	50-329 A
KANE, J	8408030020*	50-329 A
KANE, J	8408030028*	50-329 A
KANE, J	8408030056*	50-329 A
KANE, J	8408140134*	50-329 A
KANE, J	8408140163*	50-329 A
KANE, J	8408140170*	50-329 A
KANE, J	8408140209*	50-329 A
KANE, J	8408140213*	50-329 A
KANE, J	8408140223*	50-329 A
KANE, J	8408140258*	50-329 G
KANE, J	8408140311*	50-329 A
KANE, J	8408140347*	50-329 A
KANE, J	8408150019*	50-329 A
KANE, J	8408150022*	50-329 A
KANE, J	8408150042*	50-329 A
KANE, J C	8408140565*	50-329 A
KANE, J D	8306060387*	50-329 A
KANE, J D	8408140556*	50-329 A
KANE, J D	8408150612*	50-329 E
KANE, R S	8408170407	50-199 I
KANGA, B K	8408030141	50-320 P
KANGA, B K	8408060166	50-320 F
KANGA, B K	8408060310	50-320 S
KANGA, B K	8408100130	50-320 Q
KANGA, B K	8408140279	50-320 P
KANGA, B K	8408160035	50-320 P
KANGA, B K	8408200115	50-320 S
KANGA, B K	8408240225	50-320 H
KANGA, B K	8408280076	50-320 Q
KANGA, B K	8408310129	50-320 P
KANTOR, F	8408150646*	50-341 Q
KAO, G C	8408130420*	50-454 Q
KARAM, R A	8408280195	50-160 F
KARMAN, M	8408010200	50-456 G
KARR, J E	8406010038	50-329 S
KARR, J E	8408240148*	50-329 R
KARR, J E	8408240152*	50-329 R
KARR, J E	8408240159*	50-329 R
KASSNER, G	8408130604	50-295 S
KASSNER, G	8408140428	50-295 F
KATTAN, J	8408230569*	50-293 Q
KAUFMAN, P D	8408080195*	50-454 Q
KAUFMAN, P D	8408150497*	50-454 Q
KAUFMAN, P D	8408160341*	50-341 Q
KAUFMAN, P D	8408310394*	50-341 Q
KAY, J A	8408010141	50-29 P
KAY, J A	8408020039	50-29 P
KAY, J A	8408070393	50-29 F
KAY, J A	8408140312	50-29 P
KAY, J A	8408210419	50-29 P
KAY, J A	8408230162	50-29 P
KAYSER, W V	8408090209*	50-316 P
KAYSER, W V	8408140363*	50-261 P
KAYSER, W V	8408230103*	50-261 P
KAYSER, W V	8408230266*	50-315 P
KEATING, D E	8408160341*	50-341 Q
KEDDIB, N N	8408070170	GA999
KEELEY, G S	8408030064*	50-329 A
KEIMIG, R	8408160082*	50-29 Q
KEIMIG, R	8408310065	50-272 S
KEIMIG, R R	8408030192*	50-410 Q
KEIMIG, R R	8408150407*	70-371
KEIMIG, R R	8408150424*	50-277 Q
KEIMIG, R R	8408150693*	50-245 Q
KEIMIG, R R	8408150721*	50-317 Q
KEIMIG, R R.	8408200487*	50-29 Q
KEISER, H W	8408080142	50-388 S
KEISER, H W	8408090393	50-388 S
KEISER, H W	8408090395	50-387 S
KEISER, H W	8408090396	50-387 S
KEISER, H W	8408090421	50-387 S
KEISER, H W	8408090439	50-387 S
KEISER, H W	8408160164	50-388 S
KEISER, H W	8408200283	50-387 S
KEISER, H W	8408210290	50-387 S
KEISER, H W	8408240065	50-387 S
KEISER, H W	8408240246	50-387 S
KEISER, H W	8408300189	50-388 S
KEISER, H W	8408300399	50-388 S
KEISER, H W	8408300484	50-388 S
KEISER, H W	8408300489	50-387 S
KEITH, H N	8408240243	50-333 S
KEITH, W R	8408160261	50-331 S
KELLER, J C	8408080294	50-445 T
KELLER, J C	8408080294	50-445 T
KELLEY, D L	8408150440*	50-445 Q
KELLEY, D L	8408160500*	50-445 Q
KELLEY, J L	8408020062	50-413 Q
KELLEY, J L	8408070293	50-400 Q
KELLEY, J L	8408230160	50-400 Q
KELLEY, J L	8408230280	50-413 G
KELLEY, W R	8408070523	WASTE MGT
KELLY, E	8408310276	50-354 A
KELLY, G	8408090053*	50-387 Q
KELLY, J	8408060057*	50-382 Q
KELLY, J A	8408030275*	50-382 Q
KELLY, J A	8408060180*	50-482 Q
KELLY, J A	8408160523*	50-482 G
KELLY, J A	8408290104*	50-298 Q
KELLY, K	8408070014	NUREG
KELLY, L	8408230428	50-286 R
KELLY, R B	8408030136	GA999
KELLY, W J	8408070369	50-275 S
KELLY, W J	8408310038	50-275 S
KELMERS, A D	8408270050	WASTE MANA
KELMERS, A D	8408300282	NUREG
KEMPER, J	8408210429*	50-352 Q
KEMPER, J S	8408020030	50-352 A
KEMPER, J S	8408060232	50-352 E
KEMPER, J S	8408070037	50-352 A
KEMPER, J S	8408070289	50-352 E
KEMPER, J S	8408070513	50-352 E
KEMPER, J S	8408130296	50-352 Q
KEMPER, J S	8408130317	50-352 A
KEMPER, J S	8408140303	50-352 E
KEMPER, J S	8408160379	50-352 E
KEMPER, J S	8408200147	50-352 F
KEMPER, J S	8408200206	50-352 F
KEMPER, J S	8408200262	50-352 E
KEMPER, J S	8408210031	50-352 E
KEMPER, J S	8408210303	50-352 A
KEMPER, J S	8408210452	50-352 F
KEMPER, J S	8408210513	50-352 A
KEMPER, J S	8408220119	50-352 A
KEMPER, J S	8408220145	50-352 A
KEMPER, J S	8408230292	50-352 E
KEMPER, J S	8408270161	50-352 A
KEMPER, J S	8408270376	50-352 E
KEMPER, J S	8408280130	50-352 A
KEMPER, J S	8408280177	50-352 F
KEMPER, J S	8408310007	50-352 A
KEMPER, J S	8408310012	50-352 A
KEMPER, J S	8408310018	50-352 A
KEMPER, J S	8408310058	50-352 Q
KEMPER, J S	8408310110	50-352 S
KEMPER, J S	8408310124	50-352 Q
KEMPER, J S	8408310146	50-352 A
KEMPER, J S	8408310413	50-352 A
KEMPF, C R	8408010151	NUREG
KENYON, B D	8408030178*	50-387 Q
KENYON, B D	8408080269	50-387 Q
KENYON, B D	8408100125	50-387 F
KENYON, B D	8408310118	50-387 Q
KENYON, B D	8408310214	50-387 F
KENYON, T J	8408090428	50-390 A
KEPPLER, J G	7812070142*	50-329 A
KEPPLER, J G	8408070401	50-10 Q
KEPPLER, J G	8408070480	50-483 P
KEPPLER, J G	8408080539	50-456 A
KEPPLER, J G	8408130234*	50-329 A
KEPPLER, J G	8408130315*	50-329 T
KEPPLER, J G	8408130336*	50-329 A
KEPPLER, J G	8408150299*	50-255 Q
KEPPLER, J G	8408150626*	50-329 A
KEPPLER, J G	8408150639*	50-329 Q
KEPPLER, J G	8408150677*	50-329 Q
KEPPLER, J G	8408150689*	50-329 A
KEPPLER, J G	8408150706*	50-329 A
KEPPLER, J G	8408170119*	50-329 Q
KEPPLER, J G	8408170232*	50-329 Q
KEPPLER, J G	8408170263	50-295 Q
KEPPLER, J G	8408230170	50-483 P
KEPPLER, J G	8408240296	50-315 V
KEPPLER, J G	8408280147	50-315 Q
KEPPLER, J G	8408300156	50-255 Q
KERCH, H W	8408270242*	50-410 Q
KERR, G W	8408300289	NUREG
KERRIGK, J F	8408270065	WASTE MGT
KESSEL, R	8408010077	50-322 T
KESSLER, J H	8408300282	NUREG
KESSLER, J J.	8408240165	50-354 D
KETZLACH, N	8408070266	70-2884
KEUMIN, J L	8408230239	50-155 S
KEY, B W	8408150114*	71-6346
KEY, W J	8408070340*	50-456 Q
KHLAFALLAH, M Z	8408170343*	50-354 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KILBER, W E	8408150714*	50-329 A
KILLGORE, M R	8408230122*	50-241 P
KILLGORE, M R	8408240309	50-241 P
KIMBALL, J	8008130764*	50-329 A
KIMBALL, J	8307130423*	50-329 A
KIMBALL, J	8307130425*	50-329 A
KIMERY, A L	8408020103	40-8027
KIMLER, D	8408230435	50-234 R
KIMMELMAN, I I	8408280353	50-354 H
KINNEMAN, J	8408160093	I&E
KINNEMAN, J	8408210280	I&E
KINNEMAN, J	8408270297*	40-672
KINNEMAN, J	8408310080	I&E
KINTNER, L L	8408310264	50-341 A
KIRK, G B	8408060241	50-327 S
KIRK, G B	8408160269	50-328 S
KIRK, W F	8408300134	70-371
KIRSCH, D	8408220139	50-361 S
KIRSCH, D F	8408300149*	50-275 G
KIRWAN, B	8408010166	NUREG
KLEIN, B R	8408030058*	50-329 A
KLEIN, T J	8408240408	40-8584
KLEIN, T J	8408270157	40-8584
KLEINSMITH, M E	8408160132*	50-324 G
KLEINSORGE, W P	8408280046*	50-261 G
KLEINSORGE, W P	8408280091*	50-400 G
KLIKA, J C	8408240044	50-374 S
KLINGLER, G	8408010164	50-280 G
KLOPP, G T	8408210344*	50-454 G
KMETY, K L	8408310089	NUREG
KNAPP, M R	8408010079	WASTE MGT
KNAPP, M R	8408130099	WASTE MGT
KNAPP, M R	8408170427	WASTE MGT
KNAPP, M R	8408200197	WASTE MGT
KNAPP, M R	8408200480	WASTE MGT
KNAPP, M R	8408240372	WASTE MGT
KNAPP, P J	8408030148*	70-371
KNICELEY, J R	8408100037*	50-282 G
KNIESER, G W	8408070094	GA999
KNIGHT, J P	81050704B0*	50-329 A
KNIGHT, J P	8205210457*	50-329 A
KNIGHT, J P	8206020051*	50-329 A
KNIGHT, J P	*8312080183**	*50-329 A*
KNIGHT, J P	8408130260*	50-382 G
KNIGHT, M R	8408270195	50-289 S
KNIGHTON, G W	8408090424	50-361 P
KNIGHTON, G W	*8408090483*	*50-328 A*
KNIGHTON, G W	8408130182	50-528 F
KNIGHTON, G W	*8408130217*	*50-443 A*
KNIGHTON, G W	8408140036	50-361 G
NIGHTON, G W	8408150137	50-400 F
NIGHTON, G W	8408230295	50-382 F
NIGHTON, G W	8408230300	50-275 F
NIGHTON, G W	*8408230306*	*50-361 F*
NIGHTON, G W	8408230310	50-528 F
NIGHTON, G W	8408230369	50-528 A
NIGHTON, G W	8408230377	50-412 A
KNIGHTON, G W	8408230379	50-275 E
KNOP, R C	8408030207*	50-341 G
KNOP, R C	8408090304*	50-440 G
KNOP, R C	8408240321*	50-461 G
KNOTTS, J B	*8408020027*	*50-416 G*
KOBER, R W	8408030014*	50-244 G
KOBER, R W	8408070178*	50-244 G
KOBER, R W	8408070198	50-244 G
KOBER, R W	8408070248	50-244 P
KOBER, R W	8408070515	50-244 P
KOBER, R W	8408070524	50-244 P
KOBER, R W	*8408080091*	*50-244 P*
KOBER, R W	8408100032*	50-244 G
KOBER, R W	8408100056*	50-244 G
KOBER, R W	8408130357	50-244 P
KOBER, R W	8408140161	50-244 F
KOBER, R W	8408170047	50-244 P
KOBER, R W	8408170056	50-244 P
KOBER, R W	8408290112	50-244 S
KOCHER, D C	8408080422	NUREG
KOCHHAR, D S	8408170307	50-454 T
KOENIGS, R L	8408090443	50-397 S
KOENIGS, R. L	8408090450	50-397 S
KOENIGS, R. L	8408090458	50-397 S
KOENIGS, R L	8408200132	50-397 S
KOENIGS, R L	8408200341	50-397 S
KOENIGS, R L	8408290017	50-397 S
KOENIGS, R L	8408290024	50-397 S
KOENIGS, R L	8408290030	50-397 S
KOENIGS, R L	8408290116	50-397 S
KOESTER, G L	8408020105	50-482 F
KOESTER, G L	8408030012	50-482 A
KOESTER, G L	8408030159	50-482 A
KOESTER, G L	8408100066	50-482 E
KOESTER, G L	8408100075*	50-482 G
KOESTER, G L	8408140001	50-482 S
KOESTER, G L	8408140020	50-482 S
KOESTER, G L	8408140237	50-482 S
KOESTER, G L	8408140308	50-482 S
KOESTER, G L	8408140337	50-482 F
KOESTER, G L	8408140350	50-482 A
KOESTER, G L	8408160505	50-482 S
KOESTER, G L	8408160514	50-482 S
KOESTER, G L	8408200119	50-482 A
KOESTER, G L	8408220158	50-482 S
KOESTER, G L	8408220207	50-482 F
KOESTER, G L	8408220217	50-482 S
KOESTER, G L	8408220248	50-482 S
KOESTER, G L	8408220389	50-482 A
KOESTER, G L	8408220479	50-482 S
KOESTER, G L	8408270377	50-482 A
KOESTER, G L	8408280193	50-482 V
KOESTER, G L	8408280435	50-482 S
KOESTER, G L	8408290033	50-482 F
KOHL, C N	8408090178	50-382 G
KOHLER, A D	8408170255	50-508 G
KOLTAY, P	8408010300*	50-247 G
KONWINSKI, G R	8408240324	40-1162
KONWINSKI, G R	8408240373	40-8698
KONWINSKI, G R	8408270033	40-1162
KONWINSKI, G R	8408270041	40-2259
KONWINSKI, G R	8408270047	40-1162
KONWINSKI, G R	8408270053	40-8584
KONWINSKI, G R	8408270063	40-1162
KONWINSKI, G R	8408270064	40-279
KONWINSKI, G R	8408270235	40-3453
KONWINSKI, G R	8408270248	40-8584
KOON, A R	8408230507	50-395 S
KOON, A R	8408300514	50-395 S
KOSCHIK, M G	8408150635*	50-329 A
KOSTAL, K T	8408270172*	50-454 G
KOSTAL, K T	8408270172*	50-454 G
KOTTAN, J	8408200023*	50-289 G
KOTTAN, J J	8408010398*	50-387 G
KOTTAN, J J	8408230157*	50-352 G
KOUSEL, D J	8408310166	50-289 F
KOVACH, L A	8408060186	WASTE MGT
KOWINSKI, G R	8408270220	40-1162
KRASOPOULOS, A	8408210501*	50-245 G
KRAUSE, C W	8408210232	50-266 R
KRAUSE, D	8408070272	50-315 F
KREH, E J	8408280268*	50-445 G
KREH, J L	8408270432*	50-302 G
KRICH, R M	8408060115*	50-155 G
KRICH, R M	8408210287	50-155 P
KRICH, R M	*8408210498*	*50-155 F*
KRIESEL, T A	8408300505	50-315 S
KRIMM, R	8405240290	50-3 F
KRIMM, R W	8404040169	50-10 F
KRIMM, R W	*8408080138*	*50-416 F*
KRIMM, R W	8408090042	50-413 F
KRIMM, R W	8408090056	50-247 F
KRIMM, R W	*8408210346*	*50-302 F*
KRIMM, R W	8408210408	50-272 F
KRIMM, R W	*8408300319**	*50-324 F*
KROES, R J	8408130094*	50-433 G
KROPP, W	*8408060309**	*50-456 G*
KROPP, W	8408160217*	50-454 G
KRUG, H E	8408230166*	50-251 G
KUCERA, R	8408310139	PR
KUCHARSKI, S	840808047B*	50-322 G
KUCZYNSKI, L A	*8408090393*	*50-388 S*
KUCZYNSKI, L A	8408090395	50-387 S
KUCZYNSKI, L A	8408090396	50-387 S
KUCZYNSKI, L A	*8408300489*	*50-387 S*
KUECHLE, C	8408160150	50-295 S
KUEMIN, J L	8408160181	50-155 P
KUEMIN, J L	8408290067	50-155 S
KUEMIN, J L	8408290251	50-155 S
KUEMIN, J L	*8408300086*	*50-155 S*
KULM, V	8408160407*	50-508 A
KUNDER, G A	8408200521	50-289 G
KUPPERMAN, D	8408240322	NUREG
KUSEK, L T	8408090401	50-285 S
KUSEK, L T	8408090405	50-285 S
KUSHNER, W L	8408150628	50-317 F
KUSHNER, W L	8408170179	50-293 F
KUZCYNSKI, L A	8408200283	50-387 S
KUZO, G B	8408270386*	50-369 G
KUZO, G B	8408270439*	50-324 G
KUZO, G B	8408280329*	50-413 G
LACEY, W S	8408100092	50-334 S
LACEY, W S	8408100113	50-334 S
LACEY, W S	8408210016	50-334 S
LACEY, W S	8408210023	50-334 S
LACKER, D K	8408020110	PR
LAFLEUR, J D	8408300204*	50-369 F
LAMBE, W	8408090519	50-458 M
LAMBE, W	8408130488	50-458 M
LAMBE, W	8408130590	50-458 M
LAMBE, W	8408130609	50-458 M
LAMBE, W	8408150390	50-458 M
LAMBERT, H E	8408010287*	50-206 P
LAMBERT, P A	8408280211*	50-331 P
LANDSMAN, R B	8408150033*	50-329 A
LANDSMAN, R B	8408170098*	50-329 T
LANDSMAN, R B	8408170253*	50-329 A
LANDSMAN, R B	8408170284*	50-329 A
LANDSMAN, R B	8408240144*	50-329 G
LANE, M	8408200457	XPORTLIC
LANE, M	8408200537	XPORTLIC
LANE, M	8408200541	XPORTLIC
LANE, M	8408230473	XPORTLIC
LANE, M	8408230485	XPORTLIC
LANE, M	8408230493	XPORTLIC
LANE, M	8408230500	XPORTLIC
LANE, M	8408230505	XPORTLIC
LANE, M E	8408070171	XPORTLIC
LANE, R C	8408230514	50-295 S
LANGE, R G	8408060045	WASTE MGT
LANKSBURY, R D	8408230149*	50-409 G
LANNING, W	8408060083*	MISC
LARIVIERE, P	8408240165	50-354 D
LARIZZA, G F	8408290112	50-244 S
LAROCHE, G E	8408210374*	50-358 G
LARSON, C E	8408070197*	50-282 G
LARSON, C E	8408300180*	50-263 F
LARSON, D E	8408080099	50-263 S
LATHWELL, M J	8408130376*	50-155 F
LAURENSON, J A	8408090215	50-322 G
LAURENSON, J A	8408090242	50-322 G
LAURENSON, J A	8408150073	50-322 G
LAZARUS, W	840807025B*	50-244 P
LEACH, C E	8408140363*	50-261 P
LEACH, C E	8408230122*	50-261 P
LEAHY, M	8408210104	50-249 S
LEAHY, M	8408310067	50-237 S
LEAR, G	8205050209*	50-329 A
LEAR, G	8206240401*	50-329 A
LEAR, G	8210270126*	50-329 G
LEAR, G	8211030222*	50-329 G
LEAR, G	8310050136*	50-329 G
LEAR, G	8310070101*	50-329 G
LEAR, G	8310070262*	50-329 A
LEAR, G	8310240291*	50-329 G
LEAR, G	8408020192*	50-329 A
LEAR, G	8408020199*	50-329 A
LEAR, G E	8010160005*	50-329 G
LEAR, G E	8011240409*	50-329 A
LEAR, G E	8408020184*	50-329 G
LEAR, J	8408140530*	50-329 A
LEARNER, H A	8408010177	50-454 G
LEARNER, H A	8408010177	50-454 G
LEARNER, H A	8408010177	50-454 G
LEDDICK, R S	8408210378	50-382 A
LEDDICK, R S	8408270303	50-382 A
LEDUC, R J	8408020258	71-9092
LEDUC, R J	8408200187	WASTE MGT
LEE, D R	8408030168	50-267 F
LEE, D R	8408070233	50-267 S
LEE, D R	8408080520	50-267 G
LEE, D R	8408080525	50-267 P
LEE, D R	8408090311	50-267 P
LEE, D R	8408090316*	50-267 P
LEE, D R	8408290256	50-267 P
LEE, R. S	8408280033	50-368 P
LEE, S Y	8408300282	NUREG
LEE, T. D	8408030033*	70-143

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LEE, T D	8408130383*	70-143
LEE, W S	8408240242*	50-413 I
LEE, Y S	8408160378*	50-443 A
LEECH, P H	8408150520	50-293 P
LEECH, P H	8408310396	50-293 P
LEGGETT, R W	8408130009	NUREG
LEINS, E	8408170280	MISC
LEMPGES, T E	8408020115	50-220 R
LEMPGES, T E	8408030201	50-220 S
LEMPGES, T E	8408080259	50-220 S
LEMPGES, T E	8408080483	50-220 S
LEMPGES, T E	8408280248*	50-220 Q
LENAHAN, J J	8408140396*	50-400 T
LENTSCH, J W	8408020350	50-344 K
LENTSCH, J W	8408020059*	50-344 P
LEONARD, J D	8408060323	50-322 V
LEONARD, J D	8408070385	50-322 V
LEONARD, J D	8408080340	PR
LEONARD, J D	8408200328	50-322 A
LEONARD, J D	8408270226	50-322 A
LEONARD, J D	8408280187*	50-322 Q
LEONARD, J D	8408300123	50-322 V
LERS, L L	8408010299*	50-409 Q
LETSCHE, K J	8408010239	50-322 G
LETSCHE, K J	8408010239	50-322 Q
LETSCHE, K J	8408140470	50-322 Q
LETSCHE, K J	8408140470	50-322 G
LETSCHE, K J	8408140477*	50-322 Q
LETSCHE, K J	8408140477*	50-322 G
LETSCHE, K J	8408160210	50-322 Q
LETSCHE, K J	8408160210	50-322 G
LETSCHE, K J	8408230194	50-322 G
LETSCHE, K J	8408230194	50-322 G
LETSCHE, K J	8408280249	50-322 G
LETSCHE, K J	8408280249	50-322 G
LETSCHE, K J	8408280405	50-322 G
LETSCHE, K J	8408280405	50-322 G
LETTIERI, V	8408220419*	50-445 Q
LETTIERI, V	8408220424*	50-445 Q
LEVIN, H A	8408150741*	50-329 A
LEWIS, D R	8408200561	50-289 G
LEWIS, D R	8408200561	50-289 G
LEWIS, D R	8408230207	50-289 G
LEWIS, D R	8408230207	50-289 G
LEWIS, M I	8408020111	PR
LEWIS, M I	8408070349	PR
LEWIS, M I	8408140465	50-289 G
LEWIS, M I	8408280412	50-289 G
LEWIS, R C	8408130335	50-416 F
LEWIS, R C	8408130394	50-338 Q
LEWIS, R C	8408130408*	50-338 Q
LEWIS, R C	8408130433	50-338 G
LEWIS, R C	8408130443*	50-338 Q
LEWIS, R C	8408200263*	50-416 Q
LEWIS, R C	8408230148	50-250 Q
LEWIS, R C	8408230151	50-251 Q
LEWIS, R C	8408230158*	50-251 Q
LEWIS, R C	8408230167	50-259 G
LEWIS, R C	8408230180*	50-259 Q
LEWIS, R C	8408230219*	50-259 Q
LEWIS, R C	8408240316	50-261 Q
LEWIS, R C	8408240365	50-424 Q
LEWIS, R C	8408240368*	50-424 Q
LEWIS, R C	8408270192	50-335 Q
LEWIS, R C	8408270206	50-302 Q
LEWIS, R C	8408270209*	50-335 Q
LEWIS, R C	8408270241	50-321 Q
LEWIS, R C	8408270249	50-369 Q
LEWIS, R C	8408270255*	50-321 Q
LEWIS, R C	8408270257	50-417 Q
LEWIS, R C	8408270266*	50-369 Q
LEWIS, R C	8408270268*	50-417 Q
LEWIS, R C	8408270313	50-416 Q
LEWIS, R C	8408270314	50-250 Q
LEWIS, R C	8408270322*	50-250 Q
LEWIS, R C	8408270326*	50-416 Q
LEWIS, R C	8408270365	50-327 Q
LEWIS, R C	8408270375*	50-327 Q
LEWIS, R C	8408270513	50-261 Q
LEWIS, R C	8408270528*	50-261 Q
LEWIS, R C	8408280456	50-400 Q
LEWIS, R C	8408280472	50-269 Q
LEWIS, R C	8408280479*	50-269 Q
LEWIS, R C	8408270031*	50-261 Q
LEWIS, R C	8408300193	50-369 F
LEWIS, R C	8408300297	50-400 F
LEWIS, R C	8408300319	50-324 F
LEWIS, R C	8408300320	50-321 P
LEWIS, R C	8408300347	50-400 Q
LEWIS, R C	8408300353	50-390 Q
LEWIS, R C	8408300354	50-390 V
LEWIS, R C	8408300357	50-269 F
LEWIS, R C	8408300360	50-290 V
LEWIS, R C	8408300363	50-327 F
LEWIS, R C	8408300366	50-424 A
LEWIS, R C	8408300369	50-280 P
LEWIS, R C	8408300378	50-390 V
LEWIS, R C	8408300408	50-413 Q
LEWIS, R C	8408300413	50-416 P
LEWIS, R C	8408300421	50-321 P
LEWIS, R C	8408300424	50-390 A
LEWIS, R C	8408300428	50-416 P
LEWIS, R C	8408300435	50-416 P
LEWIS, R C	8408300440	50-413 A
LEWIS, R C	8408310016	50-413 P
LEWIS, R C	8408310021	50-321 P
LEWIS, R C	8408310028	50-413 P
LEWIS, R C	8408310052	50-321 P
LEWIS, R C	8408310062	50-302 P
LEWIS, R C	8408310069	50-280 F
LEWIS, R C	8408310241	50-413 P
LEWIS, R C	8408310242	50-413 P
LEWIS, R C	8408310398	50-366 P
LEWIS, R C	8408310401	50-280 F
LEWIS, R C	8408310405	50-424 Q
LEWIS, R C	8408310411	50-261 F
LEWIS, R C	8408310419	50-424 Q
LEWIS, R C	8408310428	50-413 A
LEWIS, S H	8408130299	50-454 Q
LEWIS, S H	8408170141*	50-329 A
LEWIS, S H	8408200587	50-338 Q
LEWIS, S H	8408200593*	50-338 Q
LEWIS, S H	8408280443	50-454 Q
LEY, M	8408230373	50-412 A
LICITRA, E A	8408090448	50-328 F
LICITRA, E A	8408090523	50-328 A
LICITRA, E A	8408230367	50-328 A
LIDEN, C A	8408020100	50-272 K
LIDEN, E A	8408030247*	50-272 Q
LIDEN, E A	8408130362	50-311 P
LIDEN, E A	8408150223	50-272 F
LIDEN, E A	8408150245	50-272 P
LIDEN, E A	8408160142	50-272 R
LIDEN, E A	8408200343	50-272 P
LIDEN, E A	8408210335	50-272 P
LIDEN, E A	8408240117	50-272 P
LIEBERMAN, J A	8408070462*	PRM
LIEBERMAN, S	8408150700*	50-329 A
LIGHTCAP, J B	8408290305	50-454 Q
LINDER, F	8408060004	50-409 Q
LINDER, F	8408140287	50-409 P
LINDER, F	8408150212	50-409 P
LINDER, F	8408160186	50-409 S
LINDER, F	8408160309	50-409 S
LINDER, F	8408210333	50-409 F
LINDER, F	8408220105	50-409 F
LINDER, F	8408220190	50-409 R
LINDER, F	8408270080	50-409 F
LINDER, F	8408270294*	50-409 Q
LINDER, F	8408310176	50-409 P
LINDSEY, D J	8408030256	50-333 S
LINDSEY, D J	8408270144	50-333 S
LINEHAN, D J	8408240103	WASTE MGT
LINEHAN, J J	8408030045	WASTE MGT
LINEHAN, J J	8408060051	WASTE MGT
LINEHAN, J J	8408060149	WASTE MGT
LINEHAN, J J	8408210125	WASTE MGT
LINEHAN, J J	8408230079	WASTE MGT
LINENBERGER, G	8408220288	50-70 Q
LINENBERGER, G	8408310104	50-358 G
LINVILLE, J C	8408030031*	50-272 Q
LINVILLE, J C	8408070237*	50-272 Q
LINVILLE, J C	8408150370*	50-272 Q
LIPCHAK, J B	8408070282*	50-305 F
LIPINSKI, D	8408230091*	50-293 Q
LIPINSKI, D R	8408080403*	50-245 Q
LIPINSKI, D R	8408160432*	50-245 Q
LISEND, R T	8408030254	50-333 S
LISEND, R T	8408230356	50-333 S
LITTLE, W S	8408060325*	50-382 Q
LITTLE, W S	8408070338	50-456 Q
LITTLE, W S	8408090184	50-266 Q
LITTLE, W S	8408090192	50-255 Q
LITTLE, W S	8408140130	50-155 Q
LITTLE, W S	8408140156	50-374 Q
LITTLE, W S	8408150290	50-255 Q
LITTLE, W S	8408160324	50-346 Q
LITTLE, W S	8408160329	50-266 Q
LITTLE, W S	8408280090	50-254 Q
LITTLE, W S	8408300179	50-440 Q
LITTLE, W S	8408300186*	50-440 Q
LITTLE, W S	8408300203	50-341 Q
LITTLE, W S	8408300207*	50-341 Q
LITTLEHALES, G	8408070334	GA999
LITTLEHALES, G	8408070466	GA999
LIU, L	8408210263*	50-331 I
LIU, W C	8408270469*	50-390 Q
LLOYD, R L	8408170117*	50-443 Q
LOCKE, R T	8408140484	50-352 Q
LOCKE, R T	8408140484	50-352 Q
LOCKWOOD, G J	8408080367	NUREG
LODGE, T J	8408280437	50-440 Q
LOFY, R	8408090074*	CONTRACT
LOFY, R A	8408080507*	CONTRACT
LOGUE, R H	8408080533	50-277 B
LOGUE, R H	8408080535	50-277 B
LOGUE, R H	8408130601	50-277 B
LOHR, J	8408290258	50-317 B
LOKKEN, R D	8408310075	NUREG
LOMAX, D B	8408080500	50-368 B
LOMAX, D B	8408300475	50-368 B
LOMBARDO, J J	8408150229	50-219 P
LOOMIS, J N	8408070478*	50-29 P
LOUX, R R	8408130130	WASTE MGT
LOUX, R R	8408220061	WASTE MGT
LOVELL, J	8408160521	50-250 B
LOVELL, J	8408200273	50-250 B
LOVENDALE, P	8408310268	70-1308
LOVENDALE, P C	8408080496*	50-295 Q
LOVENDALE, P C	8408200241*	50-155 Q
LOVENDALE, P C	8408300164*	50-255 Q
LOWE, A	8408140413*	50-346 P
LOWE, A L	8408140433*	50-313 P
LOWE, A L	8408210387*	50-338 P
LOWE, A L	8408210393*	50-338 P
LOWREY, M H	8408150505*	50-322 T
LOYSEN, P	8408060439	70-364
LUBLINSKI, M	8408220351	40-2061
LUBLINSKI, M	8408220351	40-2061
LUCKS, A S	8408240132	50-329 R
LUCKS, A S	8408240134*	50-329 R
LUCKS, A S	8408240138*	50-329 R
LUCKS, A S	8408240143*	50-329 R
LUDUN, R H	8408310061	70-1342
LUGAR, R G	8405180152*	50-367 H
LUKER, S M	8408080367	NUREG
LUKZ, P J	8408220387*	CONTRACT
LUNDVALL, A E	8408070343	50-317 F
LYDELL, B O	8408010276*	50-206 P
LYNCH, J L	8408010394	40-8842
LYNCH, M D	8408070468	50-341 F
LYONS, J E	8408230386	50-213 P
LYONS, P J	8407230131	40-299
LYONS, P J	8408060383	40-299
LYONS, P J	8408240318	40-299
LYONS, P J	8408240344	40-299
LYONS, P J	8408240384	40-299
LYONS, P J	8408240396	40-299
LYONS, P J	8408240412	40-299
LYONS, P J	8408270077	40-299
LYONS, P J	8408270120	40-299
LYONS, P J	8408270188	40-299
LYONS, P J	8408280399	40-299
MACDONALD	8408080062	71-307
MACDONALD, C E	8408030072	71-9188
MACDONALD, C E	8408060269	71-9186
MACDONALD, C E	8408060326	71-275
MACDONALD, C E	8408060327	71-325
MACDONALD, C E	8408060328	71-327
MACDONALD, C E	8408060370	71-328
MACDONALD, C E	8408060374	71-296
MACDONALD, C E	8408060376	71-207
MACDONALD, C E	8408060421	71-38
MACDONALD, C E	8408060429	71-8
MACDONALD, C E	8408060433	71-56

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MACDONALD, C E	8408070010	71-169
MACDONALD, C E	8408070020	71-9193
MACDONALD, C E	8408070056	71-68
MACDONALD, C E	8408070064	71-174
MACDONALD, C E	8408070151	71-195
MACDONALD, C E	8408070159	71-211
MACDONALD, C E	8408070500	71-221
MACDONALD, C E	8408070503	71-225
MACDONALD, C E	8408070504	71-222
MACDONALD, C E	8408070507	71-224
MACDONALD, C E	8408080015	71-130
MACDONALD, C E	8408080017	71-128
MACDONALD, C E	8408080040	71-300
MACDONALD, C E	8408080044	71-298
MACDONALD, C E	8408080045	71-127
MACDONALD, C E	8408080056	71-80
MACDONALD, C E	8408080057	71-303
MACDONALD, C E	8408080058	71-156
MACDONALD, C E	8408080060	71-283
MACDONALD, C E	8408080063	71-93
MACDONALD, C E	8408080065	71-74
MACDONALD, C E	8408080066	71-306
MACDONALD, C E	8408080069	71-151
MACDONALD, C E	8408080071	71-44
MACDONALD, C E	8408080072	71-232
MACDONALD, C E	8408080074	71-223
MACDONALD, C E	8408080075	71-75
MACDONALD, C E	8408080076	71-47
MACDONALD, C E	8408080078	71-77
MACDONALD, C E	8408080079	71-95
MACDONALD, C E	8408080080	71-304
MACDONALD, C E	8408080081	71-87
MACDONALD, C E	8408080085	71-234
MACDONALD, C E	8408080086	71-217
MACDONALD, C E	8408080088	71-145
MACDONALD, C E	8408080092	71-140
MACDONALD, C E	8408080093	71-326
MACDONALD, C E	8408080094	71-294
MACDONALD, C E	8408080095	71-148
MACDONALD, C E	8408080097	71-322
MACDONALD, C E	8408080098	71-208
MACDONALD, C E	8408080101	71-197
MACDONALD, C E	8408080103	71-215
MACDONALD, C E	8408080106	71-233
MACDONALD, C E	8408080107	71-119
MACDONALD, C E	8408080111	71-133
MACDONALD, C E	8408080112	71-132
MACDONALD, C E	8408080117	71-134
ACDONALD, C E	8408080122	71-120
ACDONALD, C E	8408080125	71-125
ACDONALD, C E	8408080126	71-20
ACDONALD, C E	8408080127	71-272
ACDONALD, C E	8408080128	71-137
ACDONALD, C E	8408080132	71-70
ACDONALD, C E	8408080135	71-63
MACDONALD, C E	8408080136	71-28
MACDONALD, C E	8408080137	71-33
MACDONALD, C E	8408080139	71-14
MACDONALD, C E	8408080143	71-46
MACDONALD, C E	8408080145	71-104
MACDONALD, C E	8408080154	71-161
MACDONALD, C E	8408080156	71-113
MACDONALD, C E	8408080163	71-105
MACDONALD, C E	8408080169	71-319
MACDONALD, C E.	8408080174	71-15
MACDONALD, C E	8408080182	71-314
MACDONALD, C E	8408080185	71-89
MACDONALD, C E	8408080210	71-81
MACDONALD, C E	8408080215	71-292
MACDONALD, C E	8408080220	71-32
MACDONALD, C E	8408080225	71-55
MACDONALD, C E	8408080229	71-310
MACDONALD, C E	8408080231	71-183
MACDONALD, C E	8408080234	71-284
MACDONALD, C E	8408080247	71-188
MACDONALD, C E	8408080253	71-212
MACDONALD, C E	8408080258	71-205
MACDONALD, C E	8408080263	71-213
MACDONALD, C E	8408080264	71-16
MACDONALD, C E	8408080267	71-171
MACDONALD, C E	8408080268	71-11
MACDONALD, C E	8408080270	71-22
CDONALD, C E	8408080274	71-181
CDONALD, C E	8408080279	71-39
CDONALD, C E	8408080281	71-87
MACDONALD, C E	8408080283	71-36
MACDONALD, C E	8408080287	71-123
MACDONALD, C E	8408080291	71-154
MACDONALD, C E	8408080293	71-152
MACDONALD, C E	8408080310	71-270
MACDONALD, C E	8408080313	71-110
MACDONALD, C E	8408080325	71-100
MACDONALD, C E	8408080328	71-103
MACDONALD, C E	8408080378	71-237
MACDONALD, C E	8408080379	71-253
MACDONALD, C E	8408080381	71-242
MACDONALD, C E	8408080401	71-34
MACDONALD, C E	8408080406	71-162
MACDONALD, C E	8408080411	71-61
MACDONALD, C E	8408080418	71-59
MACDONALD, C E	8408080424	71-247
MACDONALD, C E	8408080444	71-37
MACDONALD, C E	8408080446	71-229
MACDONALD, C E	8408080447	71-51
MACDONALD, C E	8408080450	71-320
MACDONALD, C E	8408080451	71-166
MACDONALD, C E	8408080452	71-216
MACDONALD, C E	8408080457	71-302
MACDONALD, C E	8408080459	71-218
MACDONALD, C E	8408080460	71-214
MACDONALD, C E	8408080462	71-168
MACDONALD, C E	8408080465	71-175
MACDONALD, C E	8408080468	71-220
MACDONALD, C E	8408080469	71-99
MACDONALD, C E	8408080470	71-219
MACDONALD, C E	8408080474	71-281
MACDONALD, C E	8408080475	71-257
MACDONALD, C E	8408090038	71-279
MACDONALD, C E	8408200086	71-240
MACDONALD, C E	8408200090*	71-240
MACDONALD, C E	8408240202	71-5926
MACDONALD, C E	8408240323	71-9111
MACDONALD, C E	8408240325	71-9073
MACDONALD, C E	8408270490	71-9151
MACDONALD, C E	8408270570	71-9184
MACDONALD, C E	8408270580	71-9073
MACDONALD, C E	8408280324	71-5805
MACDONALD, C E	8408310073	71-6346
MACDONALD, C E	8408310078	71-9143
MACDONALD, C E	8408310169	71-9016
MACDONALD, C E	8408310170	71-6381
MACDONALD, C E	8408310278	71-293
MACDONALD, C E	8408310283	71-295
MACDONALD, C E	8408310287	71-167
MACDONALD, C E	8408310289	71-158
MACDONALD, C E	8408310293	71-172
MACDONALD, C E	8408310297	71-329
MACDONALD, C E	8408310300	71-297
MACDONALD, C E	8408310346	71-291
MACDONALD, C E	8408310348	71-285
MACDONALD, C E	8408310350	71-290
MACDONALD, C E	8408310352	71-288
MACDONALD, C E	8408310354	71-66
MACDONALD, C E	8408310356	71-289
MACDONALD, C E	8408310357	71-287
MACDONALD, C E	8408310358*	71-66
MACDONALD, C E	8408310360	71-330
MACDONALD, C E	8408310364	71-286
MACDONALD, C E	8408310366	71-301
MACDONALD, C E	8408310369	71-282
MACDONALD, C E	8408310371	71-299
MACDONALD, C E	8408310372	71-318
MACDONALD, C E	8408310375	71-317
MACDONALD, C. E	8408310376	71-6717
MACDONALD, C. E	8408310377	71-280
MACDONALD, C E	8408310380	71-313
MACDONALD, C E	8408310382	71-276
MACDONALD, C. E	8408310384	71-312
MACDONALD, C. E	8408310387	71-274
MACDONALD, C E	8408310388	71-311
MACDONALD, C E	8408310391	71-303
MACDONALD, C E	8408310393	71-268
MACDONALD, C E	8408310399	71-269
MACDONALD, C E	8408310403	71-261
MACDONALD, C. E.	8408310407	71-254
MACDONALD, C E	8408310415	71-245
MACDONALD, C E	8408310418	71-124
MACDONALD, C E	8408310421	71-111
MACDONALD, C E	8408310436	71-16
MACDONALD, C E	8408310438*	71-16
MACDONALD, C E	8408310443	71-70
MACDONALD, C E	8408310444	71-186
MACDONALD, C E	8408310449	71-216
MACDONALD, C E	8408310453*	71-216
MACDONALD, C E	8408310455	71-169
MACDONALD, C E	8408310456*	71-169
MACDONALD, C E	8408310457*	71-70
MACE, M	8408130308	CONTRACT
MACGUINEAS, D B	8408080197	50-348 M
MACGUINEAS, D B	8408080197	50-348 M
MACGUINEAS, D B	8408080202	50-348 M
MACGUINEAS, D B	8408080202	50-348 M
MACGUINEAS, D B	8408080241	50-348 M
MACGUINEAS, D B	8408080241	50-348 M
MACRAE, J B	8408060019	ORG
MACRAE, J B	8408060114	ORG
MACRAE, J B	8408060219	ORG
MACRAE, J B	8408070031	ORG
MADDEN, P M	8408240362*	50-390 G
MADDEN, P M	8408280140*	50-259 G
MADDEN, W	8408150693*	50-245 G
MADDEN, W J	8408200487*	50-29 G
MADEDA, T J	8408060036*	50-341 G
MADOIAN, A	8408090002	QA999
MAHAFFEY, M	8408220343	PR
MAHLER, R J	8408230506*	CONTRACT
MALLOY, J	8408010285*	50-341 G
MALLOY, J	8408060309*	50-456 G
MALSCH, M G	8408090145	50-416 G
MALSCH, M G	8408100001	50-382 G
MALSCH, M G	8408100011	50-382 G
MALSCH, M G	8408100133	50-289 G
MALSCH, M G	8408130328*	50-382 G
MALSCH, M G	8408240110	SECY
MANGAN, C V	8407090212	50-410 K
MANGAN, C V	8408060154	50-220 P
MANGAN, C V	8408060171	50-220 F
MANGAN, C V	8408060248	50-220 P
MANGAN, C V	8408060260	50-410 A
MANGAN, C V	8408060284	50-410 A
MANGAN, C V	8408070434	50-220 F
MANGAN, C V	8408090077	50-220 P
MANGAN, C V	8408100071	50-410 S
MANGAN, C V	8408100074	50-220 P
MANGAN, C V	8408100076	50-220 P
MANGAN, C V	8408100081*	50-220 P
MANGAN, C V	8408100103	50-220 P
MANGAN, C. V	8408100111*	50-220 P
MANGAN, C V	8408100118	50-410 S
MANGAN, C V	8408160367	50-220 P
MANGAN, C V	8408200535	50-220 S
MANGAN, C V	8408210439	50-410 S
MANGAN, C V	8408210447	50-410 F
MANGAN, C V	8408230237	50-220 X
MANGAN, C V	8408280001	50-410 E
MANGAN, C V	8408280163	50-410 E
MANGAN, C V	8408300035	50-220 P
MANGAN, C. V	8408300037*	50-220 P
MANGAN, C V	8408300300	50-410 A
MANGAN, C V	8408300345	50-410 S
MANGAN, C V	8408300362	50-410 S
MANGAN, C V	8408300365	50-410 S
MANGAN, C. V	8408310235	50-410 G
MANGUSI, J	8408210314	PR
MANNELL, L	8408020114*	50-482 F
MANNING, H A	8408220332	NUREG
MANOLY, K	8408090053*	50-387 G
MARCHI, M	8408080033	50-305 S
MARKEY, E J	8408080432*	50-416 U
MARKEY, E J	8408200279*	50-369 U
MARKOS, G	8408310335*	WASTE MGT
MARKOS, G	8408310339*	WASTE MGT
MARLOW, J	8408140449	50-219 G
MARQUEZ, R. A.	8408130116	WASTE MGT
MARR, G	8408140645*	50-329 A
MARSH, L B	8408140075*	50-400 T
MARSHALL, J	8408070483	50-313 P
MARSHALL, J G	8408060085	50-373 G
MARSHALL, J. G	8408060145	50-373 P
MARSHALL, J G	8408140323	50-373 P
MARSHALL, J G	8408140372	50-237 V
MARSHALL, J G	8408160364	50-373 P
MARSHALL, J G.	8408160387	50-373 P
MARSHALL, J R	8408060187	50-368 S
MARSHALL, J R.	8408080493	50-368 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MARSHALL, J R	8408080500	50-368 S
MARSHALL, J R	8408080512	50-368 S
MARSHALL, J R	8408080528	50-368 S
MARSHALL, J R	8408130170	50-313 S
MARSHALL, J R	8408130326	50-313 S
MARSHALL, J R	8408130357	50-368 P
MARSHALL, J R	8408140328	50-368 P
MARSHALL, J R	8408140355	50-313 P
MARSHALL, J R	8408140403	50-313 P
MARSHALL, J R	8408140429	50-313 P
MARSHALL, J R	8408150317*	50-313 Q
MARSHALL, J R	8408170061	50-313 P
MARSHALL, J R	8408200303	50-313 P
MARSHALL, J R	8408240053	50-313 S
MARSHALL, J R	8408240077	50-368 S
MARSHALL, J R	8408240080	50-368 S
MARSHALL, J R	8408280184	50-313 F
MARSHALL, J R	8408300154	50-313 Q
MARSHALL, J R	8408300475	50-368 S
MARSHALL, J R	8408300496	50-368 S
MARSHALL, J S	8408160157	50-445 A
MARSHALL, R S	8408080409	NUREG
MARSTON, R R	8408270295*	50-250 Q
MARTIN, D E	8408010361	WASTE MGT
MARTIN, J B	8408130304	50-344 Q
MARTIN, J B	8408290225	State Prog
MARTIN, J B	8408290229	State Prog
MARTIN, J D	8406070192	50-397 R
MARTIN, J D	8408030280	50-397 S
MARTIN, J D	8408060233	50-397 S
MARTIN, J D	8408060235	50-397 S
MARTIN, J D	8408060301	50-397 S
MARTIN, J D	8408090443	50-397 S
MARTIN, J D	8408090450	50-397 S
MARTIN, J D	8408090458	50-397 S
MARTIN, J D	8408200132	50-397 S
MARTIN, J D	8408200341	50-397 S
MARTIN, J D	8408280320	50-397 R
MARTIN, J. D	8408290017	50-397 S
MARTIN, J D	8408290024	50-397 S
MARTIN, J D	8408290030	50-397 S
MARTIN, J D	8408290116	50-397 S
MARTIN, J D	8408290143	50-397 S
MARTIN, J G	8407100397*	50-413 U
MARTIN, L E	8408090160*	50-313 Q
MARTIN, L E	8408150102*	50-445 Q
MARTIN, L E	8408160304*	50-313 Q
MARTIN, L E	8408160523*	50-482 Q
MARTIN, L E	8408230466*	50-285 Q
MARTIN, R A	8408160146	NUREG
MARTIN, R E	8408010199	50-352 A
MARTIN, R E	8408060268	50-352 A
MARTIN, R E	8408080206	50-352 A
MARTIN, R E	8408140334	50-352 A
MARTIN, R E	8408150637	50-352 F
MARTIN, R E	8408210051	50-352 A
MARTIN, R E	8408270568	50-352 A
MARTIN, T	8408160130	I&E
MARTIN, T J	8408070326*	50-354 Q
MARTIN, T J	8408100095	50-354 S
MARTIN, T J	8408100096	50-354 S
MARTIN, T J	8408100140	50-354 S
MARTIN, T J	8408280066	50-354 Q
MARTIN, T J	8408300342	50-354 S
MARTIN, T T	8408010282	50-247 Q
MARTIN, T T	8408010288	50-245 Q
MARTIN, T T	8408010395	50-387 Q
MARTIN, T T	8408010397	40-6499
MARTIN, T T	8408030005	50-244 Q
MARTIN, T T	8408030104	50-289 Q
MARTIN, T T	8408030122	50-289 Q
MARTIN, T T	8408030173	50-387 Q
MARTIN, T T	8408030259	50-272 Q
MARTIN, T T	8408060139	50-219 Q
MARTIN, T T	8408060190	50-213 Q
MARTIN, T T	8408060373	70-1362
MARTIN, T T	8408070174	50-244 Q
MARTIN, T T	8408070320	50-213 P
MARTIN, T T	8408070323	50-354 Q
MARTIN, T T	8408070353	50-412 Q
MARTIN, T T	8408080157	50-387 Q
MARTIN, T T	8408080204	50-220 Q
MARTIN, T T	8408080233	50-244 Q
MARTIN, T T	8408080243	50-289 Q
MARTIN, T T	8408080246	50-289 Q
MARTIN, T T	8408080456	50-220 Q
MARTIN, T T	8408080463	50-219 Q
MARTIN, T T	8408080473	50-322 Q
MARTIN, T T	8408080481	50-289 Q
MARTIN, T T	8408080523	50-352 Q
MARTIN, T T	8408090036	50-277 Q
MARTIN, T T	8408090088*	50-271 Q
MARTIN, T T	8408090315	50-322 Q
MARTIN, T T	8408100022	50-244 Q
MARTIN, T T	8408100028	50-352 Q
MARTIN, T T	8408100041	70-1941
MARTIN, T T	8408100043	50-244 Q
MARTIN, T T	8408100093	50-272 F
MARTIN, T T	8408130385	50-247 Q
MARTIN, T T	8408130406	50-289 Q
MARTIN, T T	8408150107	50-336 Q
MARTIN, T T	8408150238	50-219 F
MARTIN, T T	8408150298	50-317 Q
MARTIN, T T	8408150398	70-371
MARTIN, T T	8408150409	50-277 Q
MARTIN, T T	8408150453	50-333 Q
MARTIN, T T	8408150537	50-333 Q
MARTIN, T T	8408150573	50-29 Q
MARTIN, T T	8408150631	50-272 Q
MARTIN, T T	8408150650	50-354 Q
MARTIN, T T	8408150698	50-245 Q
MARTIN, T T	8408150697	50-286 Q
MARTIN, T T	8408150711	50-317 Q
MARTIN, T T	8408150715*	50-317 Q
MARTIN, T T	8408160102	50-317 Q
MARTIN, T T	8408160235	50-245 Q
MARTIN, T T	8408160251	50-322 Q
MARTIN, T T	8408160266	50-334 Q
MARTIN, T T	8408160428	50-245 Q
MARTIN, T T	8408170079	50-220 P
MARTIN, T T	8408170168	50-244 P
MARTIN, T T	8408200014	50-289 Q
MARTIN, T T	8408200043	50-272 Q
MARTIN, T T	8408200476	50-29 Q
MARTIN, T T	8408200495	50-354 Q
MARTIN, T T	8408200510	50-247 Q
MARTIN, T T	8408210238	50-247 Q
MARTIN, T T	8408210277	50-333 Q
MARTIN, T T	8408210420	50-352 Q
MARTIN, T T	8408210424	50-333 Q
MARTIN, T T	8408210468	50-336 Q
MARTIN, T T	8408210494	50-245 Q
MARTIN, T T	8408210515	50-336 Q
MARTIN, T T	8408230094	50-219 Q
MARTIN, T T	8408230130	50-277 Q
MARTIN, T T	8408230139	50-271 Q
MARTIN, T T	8408230153	50-352 Q
MARTIN, T T	8408230183	70-1450
MARTIN, T T	8408230193	40-791
MARTIN, T T	8408230226	50-220 Q
MARTIN, T T	8408230242	50-322 Q
MARTIN, T T	8408230276	50-293 Q
MARTIN, T T	8408230487	50-309 Q
MARTIN, T T	8408230566	50-293 Q
MARTIN, T T	8408240071	50-334 Q
MARTIN, T T	8408240220	50-213 Q
MARTIN, T T	8408240272	50-317 F
MARTIN, T T	8408240292	50-271 Q
MARTIN, T. T	8408270230	50-293 F
MARTIN, T T	8408270234	50-410 Q
MARTIN, T T	8408270283	40-672
MARTIN, T T	8408270327	50-5 P
MARTIN, T T	8408270461	50-271 Q
MARTIN, T T	8408270470	50-333 Q
MARTIN, T T	8408280099	50-354 Q
MARTIN, T T	8408280245	50-220 Q
MARTIN, T T	8408300106	50-247 Q
MARTIN, T T	8408300107	50-29 Q
MARTIN, T T	8408310131	50-272 Q
MARTIN, T. T	8408310140	70-2571
MARTIN, T T	8408310320	70-221
MASTERSON, V	8408060207	50-373 S
MATHEWS, C S	8408150305*	50-322 T
MATHEWS, C S	8408150530*	50-322 T
MATHIASE, C D	8408160169	50-263 F
MATHIS, C. J	8408080503	50-293 R
MATTHEWS, C W	8408130314*	CONTRACT
MATTHEWS, M L	8408060106	WASTE MGT
MATTHEWS, P	8408220265	NUREG
MATTHEWS, T P	8408200599	50-285 R
MATTIA, M J	8408080025*	CONTRACT
MATTIA, M J	8408270503*	CONTRACT
MATTSON, D R	8408060341	WASTE MGT
MAUPIN, M W	8408150464	50-338 Q
MAUPIN, M W	8408150464	50-338 Q
MAUPIN, M W	8408200477	50-338 Q
MAUPIN, M W	8408200477	50-338 Q
MAUPIN, M W	8408300177	50-338 Q
MAUPIN, M W	8408300177	50-338 Q
MAUPIN, M W	8408310150	50-338 Q
MAUPIN, M W	8408310150	50-338 Q
MAURA, F	8408060325*	50-382 Q
MAURER, S F	8408310194*	50-454 T
MAXWELL, G F	8408140039*	50-329 A
MAY, E L	8408160529	50-29 S
MAY, M P	8408300272	NUREG
MAYS, W M	8408280018	40-8857
MAYS, W M	8408280022*	40-8857
MCALPINE, E J	8408030033*	70-143
MCALPINE, E J	8408130383*	70-143
MCALPINE, E J	8408140136	70-143
MCALPINE, E J	8408270225*	70-1151
MCALPINE, E J	8408270286*	70-27
MCALPINE, E J	8408270427*	70-143
MCALPINE, E J	8408270540*	70-1113
MCALPINE, E J	8408280367*	70-1113
MCALPINE, E J	8408300307*	70-1201
MCALPINE, E J	8408300394*	70-27
MCALPINE, E J	8408300401*	70-27
MCALPINE, E J	8408310255*	70-1151
MCBEE, R D	8408270380*	50-445 T
MCBEE, R D	8408280380*	50-445 T
MCBREARTY, R A	8408150634*	50-272 Q
MCBREARTY, R A	8408230145*	50-271 Q
MCBREARTY, R A	8408300113*	50-247 Q
MCBRIDE, M	8408230091*	50-293 Q
MCCABE, E	8408280107	50-213 S
MCCABE, E	8408290483*	50-322 Q
MCCABE, E	8408310074	50-213 S
MCCABE, E	8408310111	50-213 S
MCCABE, E C	8408090053*	50-387 Q
MCCABE, E C	8408200041*	50-387 Q
MCCABE, E C	8408200366*	50-354 Q
MCCALLISTER, P	8104230479*	50-329 Q
MCCALLISTER, P	8408140232*	50-329 A
MCCALLISTER, P	8408140557*	50-329 A
MCCALLISTER, P	8408150015*	50-329 A
MCCANN, M	8408220033	50-352 A
MCCARTHY, R L	8408150485*	50-322 T
MCCARTHY, R L	8408150505*	50-322 T
MCCARTHY, R L	8408150514*	50-322 T
MCCARTY, C	8408240375	40-8748
MCCAY, S B	8408150736*	71-9073
MCCLESKEY, K	8408230409	50-322 C
MCCLESKEY, K	8408230409	50-322 C
MCCLESKEY, K E	8408020024	50-322 Q
MCCLESKEY, K E	8408020024	50-322 Q
MCCLESKEY, K E	8408070256	50-322 Q
MCCLESKEY, K E	8408070256	50-322 Q
MCCORMICK-BARGE	8408160193*	50-483 Q
MCCORMICK-BARGE	8408300188*	50-315 Q
MCCOY, M A	8408220544	TOPREP
MCCRIGHT, D R	8408070140*	WASTE MGT
MCCRORY, S L	8408290115*	50-368 Q
MCCRORY, S L	8408290142*	50-285 Q
MCCRORY, S L	8408290176*	50-368 Q
MCDERMOTT, J L	8408010237*	50-275 Q
MCDIARMID, R C	8408030154	50-275 Q
MCDONALD, C E	8408070469	50-348 F
MCDONALD, D G	8408060436	50-250 P
MCDONALD, D G	8408070032	50-250 P
MCDONALD, D G	8408220546	50-250 P
MCDONALD, D G	8408230477	50-250 P
MCDONALD, D G	8408230554	50-250 P
MCDONALD, J R	8408220327	NUREG
MCDONALD, R	8408270558*	CONTRACT
MCDONALD, R P	8408070314	50-348 V
MCDONALD, R P	8408100036	50-348 P
MCDONALD, R P	8408130345	50-364 Q
MCDONALD, R P	8408130374	50-348 F
MCDONALD, R P	8408200611	50-348 R
MCDONALD, R P	8408210412	50-364 P
MCDONALD, R P	8408230398	50-348 P
MCDONALD, R P	8408230515	50-348 S
MCDONALD, R P	8408280048	50-348 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MCDONALD,R P	8408280176	50-348 G
MCDONALD,R P	8408300169	50-348 G
MCDONOUGH,M D	8408230469	XPORTLIC
MCDONOUGH,M D	8408310005*	XPORTLIC
MCDUFFIE,M A	8408070381	50-400 K
MCDUFFIE,M A	8408140151*	50-400 T
MCFADDEN,J	8408060084	70-2377
MCGARRY,J M	8408020060	50-413 G
MCGARRY,J M	8408020060	50-413 G
MCGARRY,J M	8408270347	50-413 G
MCGARRY,J M	8408220347	50-413 G
MCGAUGHY,J P	8408280137	50-416 G
MCGAUGHY,R W	8408020006	50-331 P
MCGAUGHY,R W	8408030038	50-331 P
MCGAUGHY,R W	8408060001	50-331 F
MCGAUGHY,R W	8408080083	50-331 P
MCGAUGHY,R W	8408130170	50-331 P
MCGAUGHY,R W	8408140247	50-331 P
MCGAUGHY,R W	8408140435	50-331 P
MCGAUGHY,R W	8408150004	50-331 G
MCGAUGHY,R W	8408210256	50-331 I
MCGAUGHY,R W	8408210499	50-331 P
MCGAUGHY,R W	8408240105	50-331 P
MCGAUGHY,R W	8408240118	50-331 P
MCGAUGHY,R W	8408270167	50-331 P
MCGAUGHY,R W	8408280202	50-331 P
MCGAUGHY,R W	8408310228	50-331 E
MCGOVERN,J J	8408090556	70-687
MCGOVERN,J J	8408150247	70-687
MCGUIRE,D R	8408030127*	50-335 G
MCGUIRE,D R	8408070409*	50-390 G
MCGUIRE,D R	8408130166*	50-269 G
MCGUIRE,D R	8408130204*	50-395 G
MCGUIRE,D R	8408130418*	50-338 G
MCGUIRE,D R	8408130446*	50-338 G
MCGUIRE,D R	8408160317*	70-143
MCGUIRE,D R	8408230255*	50-324 G
MCGUIRE,D R	8408240010*	50-261 G
MCGUIRE,D R	8408280192*	70-143
MCGURREN,H J	8408130270	50-413 G
MCGURREN,H J	8408200593*	50-338 G
MCKENNA,E	8408160359	50-206 P
MCKENNA,E	8408160375	50-206 P
MCKENNA,E M	8408280173	50-206 P
MCKINLEY,J C	8408010198*	50-329 O
MCKINLEY,J C	8408010202*	50-329 O
MCLAUGHLIN,P	8406020280*	50-329 A
MCMANUS,A	8408100144*	50-289 G
MCMILLEN,J I	8408300060*	50-263 G
MCMILLEN,J I	8408310302*	50-255 G
MCMURRAY,C M	8408020021	50-322 T
MURRAY,C M	8408030074	50-322 G
MURRAY,C M	8408030074	50-322 G
MURRAY,C M	8408070308	50-322 G
MURRAY,C M	8408070308	50-322 G
MURRAY,C M	8408080338	50-322 G
MURRAY,C M	8408080338	50-322 G
MURRAY,C M	8408080410	50-322 G
MCMURRAY,C M	8408080410	50-322 G
MCMURRAY,C M	8408230199	50-322 G
MCMURRAY,C M	8408230199	50-322 G
MCNEILL,C A	8408030254	50-333 S
MCNEILL,C A	8408030256	50-333 S
MCNEILL,C A	8408030287	50-333 R
MCNEILL,C A	8408160311	50-333 R
MCNEILL,C A	8408210281*	50-333 G
MCNEILL,C A	8408230356	50-333 S
MCNEILL,C A	8408240243	50-333 S
MCNEILL,C A	8408270144	50-333 S
MCNEILL,J D	8408140458	50-459 G
MCNEILL,W M	8408150655*	50-445 G
MCNEILL,W M	8408200326*	50-458 G
MCQUADE,J	8408300289	NUREG
MCQUEEN,A D	8408130450	50-206 F
MCVEY,E A	8408060055	50-373 S
MECCA,J E	8408030279	WASTE MGT
MEDFORD,M O	8408010226	50-206 P
MEDFORD,M O	8408010240	50-361 P
MEDFORD,M O	8408010272	50-206 P
MEDFORD,M O	8408030166	50-206 P
MEDFORD,M O	8408060080	50-361 P
MEDFORD,M O	8408060112	50-361 G
MEDFORD,M O	8408070411	50-206 G
MEDFORD,M O	8408100091	50-361 P
MEDFORD,M O	8408100115	50-361 P
MEDFORD,M O	8408160215	50-206 P
MEDFORD,M O	8408210165	50-206 P
MEDFORD,M O	8408220398	50-361 R
MEDFORD,M O	8408230178	50-206 P
MEDFORD,M O	8408240168	50-206 P
MEDFORD,M O	8408240267	50-361 P
MEDFORD,M O	8408240294	50-361 P
MEDFORD,M O	8408270409	50-361 P
MEDFORD,M O	8408300163	50-361 P
MEDFORD,M O	8408300232	50-206 S
MEDLOCK,R L	8408080429	40-8452
MEEK,S	8408060197*	50-70 G
MEHRER,R	8408150392	71-9147
MEISENHEIMER,J	8408030001*	50-329 A
MEISENHEIMER,J	8408030051*	50-329 A
MELOSH,H J.	8408160411*	50-508 A
MENDEZ,R	8408090217*	50-454 G
MENDEZ,R	8408200227*	50-454 G
MENDEZ,R	8408270277*	50-454 G
MENDONCA,M M	8408060013	50-275 S
MERRITT,S	8408060293	50-237 S
MERRITT,S	8408310063	50-237 S
MERRIWEATHER,N	8408240359*	50-321 G
MERRIWEATHER,N	8408270440*	50-424 G
MERRYMAN,R G	8408160146	NUREG
MERSCHOFF,E W	8408240140*	GA999
MESERVE,R A	8408070294	40-2061
MESERVE,R A	8408070482	40-2061
MESERVE,R A	8408070482	40-2061
MESERVE,R A	8408080235	40-2061
MESERVE,R A	8408080235	40-2061
MESSENGER,G H	8408310032	50-275 P
MESSENGER,G H	8408310035*	50-275 P
MEWHINNEY,J A	8408160125	NUREG
MEYER,G W	8408150244*	50-277 G
MEYER,R E	8408300282	NUREG
MILBROT,W E	8408160193*	50-483 G
MILBROT,W E	8408160331*	50-266 G
MILEY,G H	8408030276	50-151 F
MILLER,D B	8408150662*	50-329 A
MILLER,D E	8408020223*	70-8
MILLER,D E	8408150381*	50-440 G
MILLER,G E	8408270091	50-326 F
MILLER,H J	8408160470	WASTE MGT
MILLER,H J	8408220496	WASTE MGT
MILLER,H J	8408230046	WASTE MGT
MILLER,H J	8408230395	WASTE MGT
MILLER,H L	8408020132	50-280 F
MILLER,J.H	8408020102	REGGD
MILLER,J.R	8408010091	50-335 F
MILLER,J R	8408010120	50-266 P
MILLER,J R	8408010303	50-335 F
MILLER,J.R.	8408070082	50-344 P
MILLER,J R	8408070142	50-285 F
MILLER,J R	8408070271	50-317 P
MILLER,J R	8408070492	50-266 P
MILLER,J R.	8408070508	50-344 P
MILLER,J R	8408070511*	50-344 P
MILLER,J R	8408080055	50-368 G
MILLER,J R	8408130223	50-338 P
MILLER,J R	8408140029	50-338 F
MILLER,J R	8408140033*	50-338 F
MILLER,J R	8408140063	50-338 P
MILLER,J R	8408160167	50-309 P
MILLER,J R	8408170036	50-309 P
MILLER,J R	8408170147*	50-344 P
MILLER,J R	8408200002	50-266 P
MILLER,J R	8408200164*	50-336 P
MILLER,J R	8408200219	50-368 P
MILLER,J R	8408200325*	50-317 P
MILLER,J R	8408200360*	50-285 P
MILLER,J R	8408200484	50-282 F
MILLER,J R	8408240017*	50-317 P
MILLER,L	8408300390*	50-528 G
MILLER,L	8408300397*	50-528 G
MILLER,L	8408300407*	50-528 G
MILLER,L F	8408310244*	50-206 G
MILLER,L K	8408200276	50-311 R
MILLER,M	8408200023*	50-289 G
MILLER,M	8408210336	50-454 G
MILLER,M	8408210336	50-454 G
MILLER,M E	8408130109	50-322 G
MILLER,M E	8408140024	50-354 G
MILLER,M E	8408150192	50-322 G
MILLER,M E	8408210351	50-322 G
MILLER,M E	8408230168	50-322 G
MILLER,M M	8408010286*	50-247 G
MILLER,M S	8408030086	50-322 G
MILLER,M S	8408030086	50-322 G
MILLER,M S	8408030105	50-322 G
MILLER,M S	8408030105	50-322 G
MILLER,M S	8408070424	50-322 G
MILLER,M S	8408070424	50-322 G
MILLER,M T	8408230157*	50-352 G
MILLER,R I	8408160290	71-5926
MILLER,R L	8408290185	NUREG
MILLER,W H	8408240362*	50-390 G
MILLER,W H	8408280140*	50-259 G
MILLER,W J	8408160471	50-331 S
MILLER,W O	8408060212	50-305 P
MILLER,W O	8408080405	50-267 P
MILLER,W O	8408090139	50-275 P
MILLER,W O	8408160165	50-289 F
MILLER,W O	8408160299	50-247 F
MILLER,W O	8408160473	50-335 P
MILLER,W O	8408170011	50-293 F
MILLER,W O	8408170013	50-335 P
MILLER,W O	8408170385	50-389 P
MILLER,W.O	8408270493	50-320 P
MILLER,W O	8408280330	50-272 P
MILLS,C R	8408210298	50-282 S
MILLS,L C.	8408060378*	70-1362
MILLS,L M	8408010172	50-390 A
MILLS,L M	8408010344	50-259 P
MILLS,L M	8408020145	50-259 F
MILLS,L M	8408030015	50-259 F
MILLS,L M	8408030019	50-327 P
MILLS,L M	8408030026	50-327 P
MILLS,L M	8408030032	50-390 F
MILLS,L M	8408030128	50-390 A
MILLS,L M	8408030155	50-438 A
MILLS,L M	8408060021	50-259 P
MILLS,L M	8408060220	50-328 P
MILLS,L M	8408060254	50-327 F
MILLS,L M	8408070133	50-327 P
MILLS,L M	8408070370	50-259 P
MILLS,L M	8408070396	NUREG
MILLS,L M	8408090024	50-438 S
MILLS,L M	8408090025	50-438 S
MILLS,L M	8408090028	50-438 S
MILLS,L M	8408090033	50-438 S
MILLS,L M	8408090057	50-438 S
MILLS,L M	8408090065	50-390 S
MILLS,L M	8408090078	50-390 S
MILLS,L M	8408090268	50-438 S
MILLS,L M	8408090279	50-438 S
MILLS,L M	8408090416	50-438 S
MILLS,L M	8408100024	50-327 F
MILLS,L M	8408130275	50-390 A
MILLS,L M	8408130375	50-390 A
MILLS,L M	8408140532	50-327 P
MILLS,L M	8408160058	50-438 S
MILLS,L M	8408160066	50-438 S
MILLS,L M	8408160154	50-390 S
MILLS,L M	8408160173	50-390 S
MILLS,L M	8408160179	50-390 S
MILLS,L M	8408160200	50-438 S
MILLS,L M	8408160434	50-438 S
MILLS,L M	8408210435	50-390 A
MILLS,L M	8408220137	50-259 P
MILLS,L M	8408230192*	50-259 G
MILLS,L M	8408230208*	50-259 G
MILLS,L M	8408270199*	50-259 G
MILLS,L M	8408270370*	50-327 G
MILLS,L M	8408270468*	50-438 G
MILLS,L M	8408270475*	50-438 G
MILLS,L M	8408270483*	50-438 G
MILLS,L M	8408280086	50-328 P
MILLS,L M	8408280100	50-438 G
MILLS,L M	8408280116*	50-259 G
MILLS,L M	8408280220	50-260 P
MILLS,L M	8408290245	50-259 F
MILLS,L M	8408290250	50-390 A
MILLS,L M	8408290355	50-390 A
MILLS,L M	8408300477*	50-327 G
MILSTEAD,W	8408220265	NUREG
MILTENBERGER,S	8408060148	50-483 S
MILTENBERGER,S	8408070123	50-483 S
MILTENBERGER,S	8408090271	50-483 S
MILTENBERGER,S	8408160176	50-483 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MILTENBERGER, S	8408160256	50-483 S
MILTENBERGER, S	8408230427	50-483 S
MILTENBERGER, S	8408230546	50-483 S
MILTENBERGER, S	8408240193	50-483 S
MILTENBERGER, S	8408240315	50-483 S
MINARICK, J W	8408290190	NUREG
MINARICK, J W	8408290198	NUREG
MINECK, D L	8408060141	50-331 S
MINECK, D L	8408160261	50-331 S
MINECK, D L	8408160471	50-331 S
MINECK, D L	8408270202	50-331 S
MINECK, D L	8408230429	50-331 R
MINECK, D L	8408240172	50-331 S
MINER, S	8408090282	50-312 F
MINER, S	8408210159	50-312 P
MINICHIELLO, J	8408210426*	50-29 P
MINNERS, W	8408220265	NUREG
MINOGUE, R B	8408160271*	ORG
MINOGUE, R B	8408160275*	ORG
MINOGUE, R B	8408160280*	ORG
MINOR, G C	8408030112*	50-322 O
MINOR, G C	8408030112*	50-322 O
MIRAGLIA, F J	8408240281*	50-29 F
MIRANOWSKI, J A	8408230189	50-423 D
MIRANOWSKI, J A	8408230024	50-410 D
MIRANOWSKI, J A	8408230412	50-458 D
MISCHEL, A	8408280093	PR
MITTL, R L	8408010219	50-354 E
MITTL, R L	8408030069	50-354 E
MITTL, R L	8408060176	50-354 E
MITTL, R L	8408060279	50-354 A
MITTL, R L	8408080290	50-354 E
MITTL, R L	8408080344	50-354 A
MITTL, R L	8408100065	50-354 F
MITTL, R L	8408140336	50-354 E
MITTL, R L	8408160336	50-354 A
MITTL, R L	8408160348	50-354 E
MITTL, R L	8408170052	50-354 F
MITTL, R L	8408170103	50-354 E
MITTL, R L	8408170336	50-354 G
MITTL, R L	8408170337	50-354 A
MITTL, R L	8408210442	50-354 A
MITTL, R L	8408230352	50-354 A
MITTL, R L	8408240273	50-354 E
MITTL, R L	8408240293	50-354 D
MITTL, R L	8408280201	50-354 E
MITTL, R L	8408290002	50-354 F
MITTL, R L	8408290098	50-354 A
MITTL, R L	8408290134	50-354 E
MITTL, R L	8408300153	50-354 A
MITTL, R L	8408310198	50-354 K
MIZUNO, G S	8408270065	50-445 G
MIZUNO, G S	8408270094	50-445 G
MIZUNO, G S	8408270097	50-445 G
MIZUNO, G S	8408280232	50-445 G
MIZUNO, G S	8408300139	50-445 G
MOHR, C M	8405210578	NUREG
MOHR, C M	8405210579	NUREG
MONAGHAN, J A	8408280433	50-322 O
MONAGHAN, J A	8408280433	50-322 O
MONICK, R J	8408270508*	CONTRACT
MONTGOMERY, D M	8408270384*	50-369 O
MONTGOMERY, D M	8408270439*	50-324 O
MONTGOMERY, D M	8408280123*	70-1113
MONTGOMERY, D M	8408280329*	50-413 O
MONTGOMERY, E F	8408150485*	50-322 T
MONTGOMERY, J	8408150499	50-289 O
MONTGOMERY, R	8408200288*	50-528 S
MOONEY, G	8408270042	40-8502
MOONEY, G	8408270424	40-8502
MOONEY, J	8408150608*	50-329 A
MOONEY, J A	8408070180*	50-329 A
MOONEY, J A	8408150735*	50-329 A
MOORE, D E	8408130166*	50-269 O
MOORE, J E	8408070397	50-400 O
MOORE, J E	8408090172	50-400 O
MOORE, J E	8408150111	50-247 O
MOORE, J E	8408200490	50-400 O
MOORE, J E	8408270122	50-400 O
MOORE, R N	8408060350	XPORTLIC
MOORE, R N	8408060351	XPORTLIC
MOORE, R N	8408060353	XPORTLIC
MOORE, R N	8408060359	XPORTLIC
MOORE, R N	8408070049	XPORTLIC
MOORE, R N	8408150182	XPORTLIC
MOORE, R N	8408150402	XPORTLIC
MOORE, R N	8408150703	XPORTLIC
MOORE, R N	8408150705	XPORTLIC
MOORE, R N	8408170424	XPORTLIC
MOORE, R N	8408170425	XPORTLIC
MORGAN, R C	8408140151*	50-400 T
MORGAN, R E	8408060315	50-261 S
MORGAN, R E	8408100004	50-261 F
MORGAN, R E	8408160144	50-261 R
MORGAN, R E	8408170188	50-261 S
MORGAN, R E	8408240095*	50-261 O
MORGAN, R E	8408270521*	50-261 O
MORGAN, R E	8408280035*	50-261 O
MORGAN, R E	8408280133	50-261 O
MORGAN, R E	8408290025*	50-261 O
MORGAN, R E	8408290028*	50-261 O
MORGAN, T A	8408010276*	50-206 P
MORGENSTERN, A	8408170220	XPORTLIC
MORIARTY, J M	8408200307	50-352 S
MORLEY, J A	8408010046	WASTE MGT
MORLEY, J A	8408010064	WASTE MGT
MORLEY, J A	8408150144	WASTE MGT
MORLEY, J A	8408150400	WASTE MGT
MORLEY, J A	8408150403	WASTE MGT
MORLEY, J A	8408160278	WASTE MGT
MORLEY, J A	8408200439	WASTE MGT
MORLEY, J A	8408220227	WASTE MGT
MORLEY, J A	8408220234	WASTE MGT
MORLEY, J A	8408310270	WASTE MGT
MORLEY, J A	8408310335*	WASTE MGT
MORLEY, J A	8408310339*	WASTE MGT
MORLEY, R C	8408070419*	50-412 F
MORRILL, P	8408280078	50-362 S
MORRIS, C	8408070057	MISC
MORRIS, P A	8408300168	50-352 O
MORRIS, T W	8408220301	50-322 O
MORTON, H W	8408070462*	PRM
MORTON, K V	8408060426*	CONTRACT
MORTON, K V	8408070087*	CONTRACT
MORTON, K V	8408080008*	CONTRACT
MORTON, K V	8408090046*	CONTRACT
MORTON, K V	8408090074*	CONTRACT
MORTON, K V	8408140517*	CONTRACT
MOUNT, D K	8408010334	State Prog
MOWRY, W R	8405310267	PR
MOWRY, W R	8408020253	70-734
MOWRY, W R	8408150109	71-6346
MOWRY, W R	8408270311	50-89 F
MOXLEY, M	8408240399	40-4492
MROCZKA, E J	8408070112	50-245 S
MROCZKA, E J	8408080531	50-336 S
MROCZKA, E J	8408200594	50-336 R
MROCZKA, E J	8408200594	50-336 R
MROCZKA, E J	8408230431	50-245 R
MROCZKA, E J	8408230431	50-245 R
MROCZKA, E J	8408280262*	50-423 E
MROCZKA, E J	8408290004	50-245 S
MROCZKA, E J	8408290004	50-245 S
MUDD, C H	8408060070	50-348 F
MUDD, C H	8408230326	50-348 F
MUELLER, R J	8408280288	50-285 S
MUFFETT, J	8408160341*	50-341 O
MUFFETT, J W	8408080195*	50-454 O
MULDER, R U	8408010350	50-62 F
MULDER, R U	8408010391	50-62 F
MULLER, R	8408010204*	50-329 O
MULLIGAN, M	8408090258	50-352 O
MULLIGAN, M	8408170391	50-352 O
MULLIKIN, R	8408150515*	50-382 O
MUNRO, J J	8408020201	71-9021
MURDOCK, R J	8408010293	50-219 S
MURLEY, T E	8408030177	State Prog
MURLEY, T E	8408090265	50-388 S
MURLEY, T E	8408210189	70-303
MURLEY, T E	8408210196*	70-303
MURLEY, T E	8408230290	50-277 F
MURLEY, T E	8408230304	50-309 F
MURLEY, T E	8408270335	50-334 O
MURLEY, T E	8408280180	50-322 O
MURPHY, J A	8404040098*	50-388 U
MURPHY, J D	8408170070	71-9192
MURPHY, L G	8408310082	CONTRACT
MURPHY, M E	8408060325*	50-382 O
MURPHY, M E	8408160237*	50-458 O
MURPHY, M E	8408220500*	50-382 O
MURPHY, S	8408170204	71-9192
MURPHY, V J	8408290295	WASTE MANA
MURPHY, W P	8408080041	50-271 F
MURPHY, W P	8408090085	50-271 O
MURPHY, W P	8408240004	50-271 P
MURPHY, W P	8408270152	50-271 R
MURPHY, W P	8408310093	50-271 F
MURRAY, B	8408090176	50-267 S
MURRAY, B	8408160226*	50-382 O
MURRAY, B	8408160515*	50-458 O
MURRAY, B	8408220157*	50-458 O
MURRAY, T D	8408010313	50-346 S
MURRAY, T D	8408080506	50-346 S
MURRAY, T D	8408090026	50-346 S
MUSCHICK, R P	8408280205	50-413 T
MUSOLF, D	8407100420	50-263 S
MUSOLF, D	8408080099	50-263 S
MUSOLF, D	8408090011	50-263 F
MUSOLF, D	8408130020	71-83
MUSOLF, D	8408130024*	71-83
MUSOLF, D	8408160222	50-263 P
MUSOLF, D	8408160229*	50-263 P
MUSOLF, D	8408170252	50-263 P
MUSOLF, D	8408240238	50-282 S
MUSOLF, D	8408270293	50-263 P
MUSOLF, D	8408270299*	50-263 P
MUSOLF, D	8408280160	50-263 P
MUSOLF, D	8408280164*	50-263 P
MUTTENBERGER, S	8408210402	50-483 F
MYERS, C	8408140346	50-312 S
MYERS, C J	8408300254*	50-312 O
MYERS, D O	8408270456*	50-280 O
MYSINGER, E D	8408020242	50-275 O
NAGATA, P K	8408010027*	50-298 P
NAIDU, K	8408300220*	50-341 O
NAIDU, K R	8408300196*	50-440 O
NAPUDA, G	8408080242*	50-244 O
NAPUDA, G	8408090330*	50-322 O
NAPUDA, G	8408150455*	50-333 O
NARASIMHAN, T N	8408310344*	WASTE MGT
NARBUT, P	8408300195*	50-528 O
NARBUT, P P	8408300407*	50-528 O
NARDI, A J	8408010040	70-1151
NARDI, A J	8408160352	70-1151
NARROW, L	8408230285*	50-293 O
NARROW, L	8408300116*	50-29 O
NARUS, G E	8408010313	50-346 S
NARUS, G E	8408160199	50-346 S
NASLUND, C D	8408230427	50-483 S
NASLUND, C D	8408230546	50-483 S
NAUTZ, J L	8408070451	PRM
NEIGHBORS, D	8408010161	50-280 P
NEIGHBORS, D	8408010208	50-305 P
NEIGHBORS, D	8408060407	50-305 P
NEILS, G H	8408310112*	TOPREP
NELSON, G B	8408270346*	70-734
NELSON, G W	8408270348	PR
NELSON, M A	8408220365*	50-289 P
NELSON, P R	8408030147*	70-371
NELSON, R E	8408270276*	50-454 E
NERSES, V	8408230381	50-443 A
NEUMEYER, S A	8408080272	50-445 T
NEVILL, J F	8408140023*	50-400 T
NEWMAN, J R	8408160196	50-498 O
NEWMAN, J R	8408160196	50-498 O
NGUYEN, H	8408160390*	50-458 A
NGUYEN, T	8408210426*	50-29 P
NICHOLAS, H	8408080490*	50-289 O
NICHOLAS, H	8408090330*	50-322 O
NICHOLAS, H H	8408080256*	50-289 O
NICHOLS, N N	8408070372	50-352 O
NICHOLS, N N	8408070372	50-352 O
NICHOLS, N N	8408240254	50-352 T
NICHOLS, N N	8408240254	50-352 T
NICHOLSON, N A	8408080496*	50-295 O
NICHOLSON, N A	8408150547*	50-263 O
NICOLOSI, J	8408030002	I&E
NIELSON, K K	8408310331	WASTE MGT
NIEMCZYK, S J	8408070027*	50-447 H
NIEMCZYK, S J	8408160339	50-447 A
NIGHTINGALE, E	8408170117*	50-443 O
NIMITZ, R L	8408010286*	50-247 O
NIMITZ, R L	8408010292*	50-245 O
NIMITZ, R L	8408210244*	50-247 O

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NIMITZ,R L	8408230248*	50-322 Q
NIX,H	8408210472	50-321 F
NIX,H	8408280233	50-321 F
NIX,H C	8408090287	50-321 S
NIX,H C	8408200001	50-321 R
NIX,H C	8408200438	50-366 S
NIX,H C	8408270491	50-366 S
NIX,H C	8408270229	50-321 S
NIX,H C	8408300333	50-321 S
NIX,H C	8408300517	50-366 S
NOIDU,K R	8408150293*	50-255 Q
NORDERHAUG,L R	8408210167*	50-142 Q
NORELIUS,C	8408090049	50-456 Q
NORELIUS,C	8408150029*	50-329 A
NORELIUS,C E	8408010302	50-151 Q
NORELIUS,C E	8408010312	50-374 Q
NORELIUS,C E	8408010314*	50-374 Q
NORELIUS,C E	8408070366	50-10 Q
NORELIUS,C E	8408140344	50-10 Q
NORELIUS,C E	8408150533*	50-329 Q
NORELIUS,C E	8408150728*	50-329 A
NORELIUS,C E	8408150732*	50-329 A
NORELIUS,C E	8408150734*	50-329 A
NORELIUS,C E	8408170174*	50-329 Q
NORELIUS,C E	8408170236*	50-329 Q
NORELIUS,C E	8408170276*	50-329 S
NORELIUS,C E	8408210193	50-374 Q
NORELIUS,C E	8408230549	50-254 Q
NORELIUS,C E	8408230551*	50-254 Q
NORELIUS,C E	8408240332	50-352 S
NORELIUS,C E	8408270287	50-409 Q
NORMAN,C R	8408010269*	50-155 Q
NORMAN,C R	8408010269*	50-155 Q
NORRHOLM,L	8408010300*	50-247 Q
NORRHOLM,L	8408100072	50-247 S
NORRHOLM,L	8408310251	50-286 Q
NORRHOLM,L J	8408030031*	50-272 Q
NORRHOLM,L J	8408070237*	50-272 Q
NORRHOLM,L J	8408150370*	50-272 Q
NORRIS,J	8408280286	50-295 P
NORRIS,J A	8408060335	50-295 P
NORRIS,J A	8408130047	50-295 P
NORRIS,J A	8408170033	50-295 P
NORRY,P G	8408070103	ORG
NORRY,P G	8408080177	ORG
NORRY,P G	8408130560*	PRM
NORRY,P G	8408150535	ORG
NORRY,P G	8408300222	ORG
NORTH,H	8408070416	50-312 S
NORTH,H	8408090004*	50-361 Q
NORTH,H	8408090080*	50-344 Q
ORTH,H	8408090091*	50-312 Q
RTH,H S	8408230087*	50-312 Q
'TON,J	8408230144*	50-341 Q
TON,J F	8408080195*	50-454 Q
ACHEK,F	8408080514	50-267 S
AK,T M	8209230536*	50-329 E
AK,T M	8407310030	50-454 S
AK,T M	8407310032	50-454 Q
VAK,T M	8408090323	50-423 E
;OVAK,T M	8408130160	50-528 F
NOVAK,T M	8408150648*	50-329 A
NOVAK,T M	8408210410*	50-329 A
NOVAK,T M	8408210414*	50-329 A
NOVAK,T M	8408210464*	50-329 Q
NOVAK,T M	8408220463	50-352 A
NOVAK,T M	8408230247	50-454 Q
NOVAK,T M	8408290041	50-413 F
NOVAT,J	8408160146	NUREG
NOWAK,A S	8408150720*	50-329 A
NUGENT,E L	8408200400	40-2259
NUGENT,E L	8408240414	40-2259
NUMARK,N J	8408010193	WASTE MGT
NUSSBAUMER,D	8408130077	WASTE MGT
NUSSBAUMER,D A	8408230362	WASTE MGT
NYKIRK,J	8408070239	50-295 F
NYKIRK,J	8408070240	50-295 F
O'CONNOR,P W	8408010187	50-482 A
O'CONNOR,P W	8408070394	50-482 A
O'CONNOR,P W	8408210558	50-482 F
O'CONNOR,P W	8408280037	50-482 F
O'CONNOR,P W	8408300075	50-482 F
O'DWYER,G	8408150475*	50-341 Q
O'NEILL,J	8408160392	PR
O'NEILL,J	8408210327	50-155 Q
O'NEILL,J	8408210330*	50-155 Q
O'NEILL,J	8408210337*	50-155 Q
O'NEILL,J	8408210432	PR
O'NEILL,J H	8408020054	50-400 Q
O'NEILL,J H	8408020054	50-400 Q
O'NEILL,J P	8408280244	50-155 Q
O'REILLY,J P	8408070357	50-280 Q
O'REILLY,J P	8408070360*	50-280 Q
O'REILLY,J P	8408300352	50-321 F
O'REILLY,J P	8408300356	50-369 Q
O'REILLY,J P	8408300364	50-348 F
O'REILLY,J P	8408300371	50-416 P
O'REILLY,J P	8408300375	50-413 V
O'REILLY,J P	8408300376	50-321 F
O'REILLY,J P	8408300392	50-250 P
O'REILLY,J P	8408300392	50-335 V
O'REILLY,J P	8408300402	50-259 F
O'REILLY,J P	8408300417	50-302 F
O'REILLY,J P	8408300434	50-259 P
O'REILLY,J P	8408300519	50-327 F
O'REILLY,J P	8408300520	State Prog
O'REILLY,J P	8408310014	50-261 V
O'REILLY,J P	8408310036	50-259 V
O'REILLY,J P	8408310064	50-250 V
O'REILLY,J P	8408310109	50-259 Q
O'TOOLE,J D	8408020138	50-247 P
O'TOOLE,J D	8408060349	50-3 F
O'TOOLE,J D	8408070114	50-247 F
O'TOOLE,J D	8408070421	50-247 F
O'TOOLE,J D	8408070425	50-247 Q
O'TOOLE,J D	8408130211	50-247 P
O'TOOLE,J D	8408130325	50-247 F
O'TOOLE,J D	8408130398*	50-247 Q
O'TOOLE,J D	8408150121	50-3 F
O'TOOLE,J D	8408200309	50-247 Q
O'TOOLE,J D	8408200539	50-247 S
O'TOOLE,J D	8408210002	50-247 F
O'TOOLE,J D	8408220214	50-247 S
O'TOOLE,J D	8408240164	50-247 P
O'TOOLE,J D	8408290279	50-247 Q
OBERG,C R	8408150102*	50-445 Q
ODEGAARDEN,R H	8408060420	71-9001
OESTMANN,M J	8408150401*	50-254 Q
OESTMANN,M J	8408270288*	50-440 Q
OGLE,K M	8408240402	40-8502
OGLE,K M	8408270550	40-8502
OKADA,S	8408060402	XPORTLIC
OKADA,S	8408060406	XPORTLIC
OKADA,S	8408060438*	XPORTLIC
OKRENT,D	8408270142	50-142 P
OLIVEIRA,W	8408080242*	50-244 Q
OLIVEIRA,W	8408090330*	50-322 Q
OLIVERIA,W	8408080166*	50-387 Q
OLSEN,A F	8408020203	70-824
OLSEN,A F	8408150115	50-13 P
OLSHAN,L N	8408010185	50-454 E
OLSHAN,L N	8408090528	50-454 Q
OLSON,J F	8408080334*	PR
OLSON,D L	8408210038	WASTE MGT
OPEKA,J F	8408070220	50-423 A
OPEKA,J F	8408070220	50-423 A
OPEKA,J F	8408100063	50-213 P
OPEKA,J F	8408100063	50-213 P
OPREA,G W	8408150389	50-498 S
OPREA,G W	8408210096*	50-498 Q
OPREA,G W	8408210311	50-498 A
OPREA,G W	8408210500	50-498 A
OPREA,G W	8408220130	50-498 S
OPREA,G W	8408240312	50-498 S
OPREA,G W	8408270212	50-498 Q
OPREA,G W	8408300370	50-498 S
ORDERS,W	8408270279*	50-369 Q
ORTIZ,N R	8408300178	WASTE MANA
OSBORNE,D B	8408200161	50-336 P
OSTER,J	8408290038	50-10 J
OSTRANDER,N C	8408300109	50-142 R
OTTO,H W	8408070284	50-354 H
OTTO,S M	8408090144	50-289 S
OUELLETTE,R W	8408300501	50-413 S
PAGE,M	8408270150	CONTRACT
PAGE,M	8408280484	CONTRACT
PAGE,M	8408270547	CONTRACT
PAGE,M	8408270581	CONTRACT
PAGE,M	8408310260	CONTRACT
PAGE,M	8408310363	CONTRACT
PAGE,R G	8408060348	70-2988
PAGE,R G	8408060375*	70-2988
PAGE,R G	8408070259	70-2884
PAGE,R G	8408170310	40-2061
PAGE,R G	8408230555	40-2061
PAHWA,S B	8408080321*	CONTRACT
PALLADINO,N	8408140566*	50-329 A
PALLADINO,N	8408150654	WASTE MGT
PALLADINO,N J	8408010277*	50-275 U
PALLADINO,N J	8408080034	COMMISSION
PALLADINO,N J	8408080427	COMMISSION
PALLADINO,N J	8408080430	50-416 U
PALLADINO,N J	8408090109	COMMISSION
PALLADINO,N J	8408090111*	COMMISSION
PALLADINO,N J	8408090216	COMMISSION
PALLADINO,N J	8408220444	50-320 P
PALLADINO,N J	8408280467	COMMISSION
PALLADINO,N J	8408290154	50-320 U
PALLADINO,N J	8408290348	COMMISSION
PALOMINO,F G	8408010239	50-322 Q
PALOMINO,F G	8408140005	50-322 Q
PALOMINO,F G	8408140470	50-322 Q
PALOMINO,F G	8408140477*	50-322 Q
PANCIERA,V	8408270269*	50-321 Q
PANCIERA,V	8408270351*	50-424 Q
PANCIERA,V	8408280152	50-424 S
PANCIERA,V W	8408240371*	50-424 Q
PANDEY,S	8404040075*	50-388 U
PANGBURN,G C	8408230481*	40-8102
PANGBURN,G C	8408240212	40-8452
PANGBURN,G C	8408240216	40-8602
PANGBURN,G C	8408270035	40-8102
PANGBURN,G C	8408270055	40-8102
PANGBURN,G C	8408270106	40-8452
PAOLINO,R J	8408080256*	50-289 Q
PAPAZOGLOU,I A	8408220333	50-352 A
PAPERIELLO,C J	8408010297	50-409 Q
PAPERIELLO,C J	8408010332	50-454 Q
PAPERIELLO,C J	8408020150	50-266 F
PAPERIELLO,C J	8408020160	50-266 F
PAPERIELLO,C J	8408020220	70-8
PAPERIELLO,C J	8408030251	50-10 Q
PAPERIELLO,C J	8408060095	50-373 F
PAPERIELLO,C J	8408060110	50-155 Q
PAPERIELLO,C J	8408080485	50-295 Q
PAPERIELLO,C J	8408080488*	50-295 Q
PAPERIELLO,C J	8408100026	50-483 Q
PAPERIELLO,C J	8408130103	50-454 Q
PAPERIELLO,C J	8408130401	50-10 F
PAPERIELLO,C J	8408150380	50-440 Q
PAPERIELLO,C J	8408150386	50-454 Q
PAPERIELLO,C J	8408150392	50-254 Q
PAPERIELLO,C J	8408150399	50-266 Q
PAPERIELLO,C J	8408150544	50-263 Q
PAPERIELLO,C J	8408150546*	50-263 Q
PAPERIELLO,C J	8408150638	50-341 Q
PAPERIELLO,C J	8408200233	50-155 Q
PAPERIELLO,C J	8408270084	50-341 Q
PAPERIELLO,C J	8408270278	50-440 Q
PAPERIELLO,C J	8408270309	50-295 F
PAPERIELLO,C J	8408270348	50-341 Q
PAPERIELLO,C J	8408270390	50-155 Q
PAPERIELLO,C J	8408290197	50-266 F
PAPERIELLO,C J	8408310173	50-282 F
PAPERIELLO,C J	8408310268	70-1308
PAPERIELLO,C J	8408310288	50-305 Q
PARK,J Y	8408240322	NUREG
PARKER,G E	8408060266	WASTE MGT
PARKS,R D	8408220373*	50-289 Q
PARSONS,G E	8408230198*	40-791
PARSONS,R M	8408090018	50-400 S
PARSONS,R M	8408090031	50-400 S
PARSONS,R M	8408090066	50-400 S
PARSONS,R M	8408090131	50-400 S
PARSONS,R M	8408090291	50-400 S
PARSONS,R M	8408140327*	50-400 T
PARSONS,R M	8408160168	50-400 S
PARSONS,R M	8408160408	50-400 S
PARSONS,R M	8408160416	50-400 S
PARSONS,R M	8408160437	50-400 S
PARSONS,R M	8408160438	50-400 S
PARSONS,R M	8408160443	50-400 S
PARSONS,R M	8408280460*	50-400 Q
PARSONS,R M	8408280465*	50-400 Q
PARSONS,R M	8408280469*	50-400 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PARSONS,R M	8408300350*	50-400 G
PARVIN,M J	8408140226*	50-250 G
PARVIN,M J	8408140226*	50-250 G
PASCIAK,W	8408240231*	50-213 G
PASCIAK,W J	8408010398*	50-387 G
PASCIAK,W J	8408080209*	50-220 G
PASCIAK,W J	8408080467*	50-219 G
PASCIAK,W J	8408150305*	50-317 G
PASCIAK,W J	8408150541*	50-333 G
PASCIAK,W J	8408150701*	50-286 G
PASCIAK,W J	8408200544*	50-247 G
PASCIAK,W J	8408230157*	50-352 G
PASCIAK,W J	8408230248*	50-322 G
PASCIAK,W J	8408230495*	50-309 G
PASCIAK,W J	8408270473*	50-333 G
PASTVA,M J	8408060128	50-325 S
PASTVA,M J	8408090032	50-325 S
PASTVA,M J	8408090390	50-324 S
PASTVA,M J	8408090432	50-325 S
PASTVA,M J	8408160075	50-325 S
PASTVA,M J	8408160133	50-325 S
PASTVA,M J	8408240227	50-324 S
PATAWA,E H	8408010114	WASTE MGT
PATE,R J	8408070045	50-323 V
PATE,R J	8408070479	50-275 V
PATE,R J	8408090045*	50-361 G
PATE,R J	8408310243	50-206 G
PATE,Z T	8408020091	NUREG
PATE,Z T	8408220310*	ORG
PATEL,B R	8408210382*	TOPREP
PATEL,B R	8408210392*	TOPREP
PATON,W D	8408020183*	50-329 G
PATON,W.D	8408020185*	50-329 G
PATON,W D	8408070377	50-329 G
PATON,W D	8408130348*	50-329 A
PATON,W D	8408140158*	50-329 A
PATON,W D	8408140539*	50-329 A
PATON,W D	8408150616*	50-329 A
PATON,W D	8408150752*	50-329 A
PATON,W D	8408210391*	50-329 G
PATTERSON,C A	8408230240*	50-259 G
PATTERSON,J P	8408150646*	50-341 G
PATTON,J D	8408060297	40-8102
PAUL,R A	8408150406*	50-266 G
PAULITZ,F P	8408080256*	50-289 G
PAULK,G L	8408230240*	50-259 G
PAULSON,W A	8408010030	50-245 P
PAULSON,W A	8408070052	50-219 P
PAULSON,W A	8408070210	50-213 P
PAULSON,W A	8408070251	50-244 P
PAULSON,W A	8408070255*	50-244 P
PAULSON,W A	8408070304	50-219 P
PAULSON,W A	8408070331	50-204 P
PAULSON,W A	8408090099	NUREG
PAULSON,W A	8408090179	50-255 F
PAULSON,W A	8408090275	50-244 P
PAULSON,W A	8408090281*	50-244 P
PAULSON,W A	8408090307	50-155 P
PAULSON,W A	8408130282	50-29 P
PAULSON,W A	8408130289	50-10 F
PAULSON,W A	8408130358	50-29 P
PAULSON,W A	8408130366	50-255 D
PAULSON,W A	8408150225	50-219 P
PAULSON,W A	8408150269	50-219 F
PAULSON,W A	8408160062	50-237 P
PAULSON,W A	8408160070*	50-237 P
PAULSON,W A	8408160149	50-29 P
PAULSON,W A	8408160353	50-244 P
PAULSON,W A	8408160356*	50-244 P
PAULSON,W A	8408170130	50-206 P
PAULSON,W A	8408170143*	50-206 P
PAULSON,W A	8408210001	50-10 F
PAULSON,W A	8408210008	50-219 P
PAULSON,W A	8408210029	50-409 P
PAULSON,W A	8408210307	50-255 P
PAULSON,W A	8408210338	50-155 P
PAULSON,W A	8408210371	50-206 P
PAULSON,W A	8408220093	50-409 P
PAULSON,W A	8408220326	50-213 P
PAULSON,W A	8408230384	50-219 P
PAULSON,W A	8408230418	50-409 P
PAULSON,W A	8408240266	50-29 F
PAULSON,W A	8408290001	50-155 P
PAULSON,W A	8408290136	50-206 P
PAULSON,W A	8408300048	50-255 F
PAULSON,W A	8408300102	50-237 P
PAULSON,W A	8408300111*	50-237 P
PAULSON,W A	8408300128	50-255 G
PAULSON,W A	8408300148	50-219 P
PAULSON,W A	8408300172	50-219 F
PAULSON,W A	8408310125	50-213 S
PAULTON,B R	8408020065	50-297 P
PAVINICH,W A	8408210387*	50-338 P
PAVINICH,W A	8408210393*	50-338 P
PAWLICW,E T	8408020190*	50-329 G
PAWLICW,E T	8408020194*	50-329 G
PEARRING,J R	8408130085	WASTE MGT
PECK,S	8408020228	40-8724
PEEBLES,T A	8408210441	50-250 H
PEEBLES,T A	8408270329*	50-250 G
PEERY,W W	8408270531*	70-27
PELIZZA,M S	8408240353	40-8786
PELLET,J L	8408060099*	50-482 G
PELLET,J L	8408090037*	50-298 G
PELLET,J L	8408090073*	50-382 G
PELLETIER,J P	8408230534	50-271 S
PELLETIER,J P	8408230542	50-271 S
PELLETIER,J P	8408280307	50-271 S
PELLETIER,J P	8408300478	50-271 S
PELLETIER,J P	8408300488	50-271 S
PELROY,R A	8408310075	NUREG
PELTON,J R	8408160414*	50-508 A
PENNIFILL,R A	8408090328	WASTE MGT
PENNIFILL,R A	8408230027	WASTE MGT
PENNIND,B J	8408270147*	50-412 E
PENTZ,D L	8408230336*	CONTRACT
PEPIN,J G	8408200154	WASTE MGT
PERANICH,M	8408150515*	50-382 G
PEREIRA,D B	8408090045*	50-361 G
PEREZ,G P	8408300264*	50-312 G
PERKINS,A J	8408140449	50-219 G
PERKINS,L K	8408240393	40-8681
PERLIS,R G	8408010189	50-424 G
PERLIS,R G	8408010201	50-443 G
PERLIS,R G	8408070403	50-443 G
PERLIS,R G	8408200607	50-322 G
PERLIS,R G	8408270103*	50-445 G
PERLIS,R G	8408270111	50-322 G
PERLIS,R G	8408280452	50-498 G
PETERS,R J	8408210639	50-275 P
PETERSON,C H	8408230423	WASTE MGT
PETERSON,K A	8408280016*	40-8502
PETERSON,T	8408290308	50-454 G
PETRICK,N A	8407310144	50-482 A
PETRICK,N A	8408060234	50-482 A
PETRICK,N A	8408160063	50-482 F
PETRICK,N A	8408210313	50-482 A
PETRICK,N A	8408270389	50-482 F
PETRICK,N A	8408300090	50-482 F
PETRONE,C	8408290483*	50-322 G
PETROWSKI,S	8408200547	50-304 S
PETROWSKI,S E	8408060290	50-304 S
PETTENGILL,H J	8408210110	40-2259
PETTENGILL,H J	8408210120*	40-2259
PETTENGILL,H J	8408210129	40-4492
PETTENGILL,H J	8408210143*	40-4492
PETTENGILL,H J	8408230472	40-8102
PETTENGILL,H J	8408230481*	40-8102
PETTENGILL,H J	8408240142	40-3453
PETTENGILL,H J	8408240163	40-299
PETTENGILL,H J	8408240174	40-4492
PETTENGILL,H J	8408240182	40-4492
PETTENGILL,H J	8408240185	40-299
PETTENGILL,H J	8408240189	40-299
PETTENGILL,H J	8408240190	40-3453
PETTENGILL,H J	8408240192	40-299
PETTENGILL,H J	8408240197*	40-299
PETTENGILL,H J	8408240207	40-8698
PETTENGILL,H J	8408240209	40-8084
PETTENGILL,H J	8408240212	40-8452
PETTENGILL,H J	8408240216	40-8602
PETTENGILL,H J	8408240340	40-6622
PETTENGILL,H J	8408240345	40-1162
PETTENGILL,H J	8408240347	40-6622
PETTENGILL,H J	8408240373	40-8698
PETTENGILL,H J	8408240380	40-299
PETTENGILL,H J	8408270022	40-6659
PETTENGILL,H J	8408270033	40-1162
PETTENGILL,H J	8408270035	40-8102
PETTENGILL,H J	8408270037	40-299
PETTENGILL,H J	8408270041	40-2259
PETTENGILL,H J	8408270044	40-3453
PETTENGILL,H J	8408270047	40-1162
PETTENGILL,H J	8408270053	40-8584
PETTENGILL,H J	8408270055	40-8102
PETTENGILL,H J	8408270062	40-3453
PETTENGILL,H J	8408270064	40-299
PETTENGILL,H J	8408270068	40-299
PETTENGILL,H J	8408270106	40-8452
PETTENGILL,H J	8408270228	40-8084
PETTENGILL,H J	8408270248	40-8584
PEWBLE,J A	8408290310	50-454 G
PFAFF,S J	8408240346	40-6659
PHILBRICK,S S	8408020237	ACRS
PHILBRICK,S S	8408020237	ACRS
PHILLIP,G A	8408140039*	50-329 A
PHILLIPS,H W	8408170117*	50-443 G
PHILLIPS,J H	8408070478*	50-29 P
PHILLIPS,M P	8408010299*	50-409 G
PHILLIPS,M P	8408150394*	50-454 G
PHILLIPS,M P	8408150646*	50-341 G
PHILLIPS,M P	8408240429*	50-305 G
PICARD,R R	8408080409	NUREG
PICIOCCHI,J H	8408210084	XPORTLIC
PICKETT,D	8408300219*	50-366 P
PIERINGER,P	8408310042	50-318 S
PIERSON,R	8408270279*	50-369 G
PILANT,J M	8408030011	50-298 G
PILANT,J M	8408070267	50-298 F
PILANT,J M	8408070295	50-298 P
PILANT,J M	8408070316	50-298 F
PILANT,J M	8408100014	50-298 R
PILANT,J M	8408100145	50-298 P
PILANT,J M	8408140431	50-298 F
PILANT,J M	8408150447	50-298 I
PILLAY,K S	8408080409	NUREG
PINSKY,G P	8408230109	TOPREP
PIRFO,O R	8408150077	50-498 G
PIRFO,O R	8408150138	50-498 G
PIRFO,O R	8408150176	50-498 G
PIRFO,O R	8408280396	50-498 G
PIRTLE,G	8408150747*	50-329 A
PIRTLE,G	8408150750*	50-329 A
PIRTLE,G L	8408210471*	50-461 G
PISCHINGER,F F	8408150498*	50-322 T
PISCHINGER,F F	8408150514*	50-322 T
PISCHINGER,F F	8408150530*	50-322 T
PITTMAN,J	8408220265	NUREG
PITTS,J	8408080051	50-445 T
PITTS,J.	8408080051	50-445 T
PLAINE,H H	8407300105	50-322 A
PLAINE,H H	8408090102	COMMISSION
PLIML,G	8408140428	50-295 F
PLIML,G	8408310168	50-295 F
PLISCO,L	8408090053*	50-387 G
PLISCO,L R	8408200041*	50-387 G
PLOSKI,T J	8408150394*	50-454 G
PLUMLEE,G L	8408160516*	50-267 G
PLUMLEE,K E	8408030148*	70-371
POINDEXTER,T C	8408010328	50-320 P
POLK,P J	8408070055	50-286 P
POLK,P J	8408090545	50-286 P
POLLOCK,M S	8408290486*	50-322 G
POPPE,L K	8408170021	71-6244
POTAPOVB,U	8405300191	QA999
POTAPOVB,U	8408010364	QA999
POTAPOVB,U	8408080218	QA999
POTAPOVB,U	8408310232	CONTRACT
POTTER,J P	8408210485	I&E
POULOS,B J	8210130322*	50-329 A
POULOS,S J	8305270222*	50-329 A
POULOS,S J	8408020181*	50-329 G
POULOS,S J	8408140185*	50-329 A
POULOS,S J	8408140196*	50-329 A
POULOS,S J	8408140296*	50-329 A
POWELL,A W	8408140151*	50-400 T
POWELL,P C	8408130212*	70-938
POWERS,C M	8408030280	50-397 S
POWERS,C M	8408060233	50-397 S
POWERS,C M.	8408060235	50-397 S
POWERS,C M	8408060301	50-397 S
POWERS,C M	8408290143	50-397 S
POZDOLSKI,A	8408290281	50-454 G
PRASSINOS,P G	8408100155	NUREG
PRATT,W T	8408090208	50-206 P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PRELL, J A	8408090051*	50-277 Q
PRENDERGAST, K	8408300127*	50-328 Q
PRENDERGAST, K	8408300504*	50-312 Q
PRESTHOLT, P T	8408200474	WASTE MGT
PRICE, J	8408280112	WASTE MGT
PROBST, J R	8408220202	50-331 S
PROTO, N T	8408080173	40-2061
PROTO, N T	8408080173	40-2061
PROTO, N T	8408080180*	40-2061
PROTO, N T	8408080180*	40-2061
PROUDMAN, G	8408210349	PR
PUGH, C E	8408080355	NUREG
PULLANI, S V	8408210501*	50-245 Q
PURDY, G	8408230432	50-445 T
PURDY, G	8408280221	50-445 Q
PUTMAN, K S	8408230429	50-331 R
PUTNAM, K S	8408060141	50-331 S
PUZEY, A M	8408060058	50-344 F
PUZEY, A M	8408100058	50-344 F
PUZEY, A M	8408210292	50-344 F
QUAMME, D L	8408150651*	50-329 A
QUENNOZ, S M	8408160497	50-346 S
QUENNOZ, S M	8408230104	50-346 R
QUENNOZ, S N	8408160199	50-346 S
QUINTANA, C A	8408080359	NUREG
QUIRK, J F	8408160377	TOPREP
RADER, R M	8408060053	50-352 Q
RADER, R M	8408060053	50-352 Q
RADER, R M	8408060182	50-352 Q
RADER, R M	8408070363	50-352 Q
RADER, R M	8408070363	50-352 Q
RADER, R M	8408070412	50-352 Q
RADER, R M	8408070412	50-352 Q
RADER, R M	8408070444	50-352 Q
RADER, R M	8408070444	50-352 Q
RADER, R M	8408080389	50-354 Q
RADER, R M	8408080389	50-354 Q
RADER, R M	8408150477	50-352 Q
RADER, R M	*8408150477*	50-352 Q
RADER, R M	8408280223	50-354 Q
RADER, R M	8408280223	50-354 Q
RADER, R M	8408280388	50-352 Q
RADER, R M	8408280388	50-352 Q
RADFORD, E P	8408020021	50-322 T
RADFORD, E P	8408020021	50-322 T
RAHE, E P	8407230200	TOPREP
RAHE, E P	8408060116	TOPREP
RAHE, E P	8408080278	50-601 K
RAHE, E P	8408140278	50-601 A
RAHE, E P	8408230340	TOPREP
RAHE, E P	8408270312	TOPREP
RAHE, E P	8408270449	TOPREP
RAHE, E P	8408280259	TOPREP
RANDALL, R	8408030201	50-220 S
RANDALL, R	8408080259	50-220 S
RANDALL, R	8408080483	50-220 S
RANDALL, R	8408200535	50-220 S
RANDAZZA, J S	8408020121	50-309 K
RANDEN, L	8408240040	40-8727
RANGE, J J	8408280394	50-322 T
RANGE, J J	8408280394	50-322 T
RAPKIN, A	8408070311	40-2061
RAPKIN, A	8408130329	40-2061
RAPKIN, A	8408130337*	40-2061
RAPKIN, A	8408170383	40-2061
RAPKIN, A	8408170387*	40-2061
RAPKIN, A	8408170389*	40-2061
RAPKIN, A	8408170396	40-2061
RAPKIN, A	8408290008	40-2061
RASMUSSEN, L C	8408020088	PR
RATCLIFF, W H	8408090551*	CONTRACT
RATHBUN, L A	8408290171	NUREG
RAU, C A	8408130505*	50-322 T
RAVAL, J	8408090330*	50-322 Q
RAY, C L	8403290062	50-206 S
RAY, C L	8403290062	50-206 S
RAY, C L	8403290179	50-206 S
RAY, C L	8403290179	50-206 S
RAY, C L	8408060050	50-206 S
RAY, C L	8408060050	50-206 S
RAY, C L	8408060102	50-206 S
RAY, C L	8408060102	50-206 S
RAY, C L	8408060324	50-206 S
RAY, C L	8408060324	50-206 S
RAY, C L	8408160394	50-206 S
RAY, C L	8408160395	50-206 S
RAY, C L	8408160395	50-206 S
RAY, C L	8408290179	50-206 S
RAY, C L	8408290179	50-206 S
RAY, H B	8408140260	50-361 Q
RAY, H B	8408200335	50-361 Q
RAY-HOLMES, P	8408270269*	50-321 Q
RAYMOND, W J	8408030229*	50-271 Q
RAYNOR, J	8408200512	50-318 S
RAYNOR, J W	8408200492	50-318 S
REA, K	8408010166	NUREG
REAGAN, E E	8408150739*	71-9073
REAGAN, E E	8408150742*	71-9073
REAGAN, E E	8408150744*	71-9073
REAVIS, J A	8408220465	50-369 R
REAVIS, J A	8408220468	50-269 R
REAVIS, J A	8408300406	50-413 R
REAVIS, J A	8408300509	50-370 R
REBELOWSKI, T A	8408290007*	50-423 Q
REED, J	8408270333	50-352 A
REEVES, E A	8408240229	50-348 F
REGAN, N A	8408130454	70-27
REGAN, N A	8408210483	70-27
REGAN, W H	8408020136	50-352 M
REHM, T A	8408080486	COMMISSION
REHM, T A	8408150656*	50-329 A
REHM, T A	8408160030	COMMISSION
REHM, T A	8408300290	COMMISSION
REID, K	8408310042	50-318 S
REINMUTH, G W	8408150729*	50-329 A
REINSCH, H O	8408030133	GA999
REIS, E J	8408280396	50-498 Q
REIS, H F	8408210347	50-250 Q
REIS, H F	8408210347	50-250 Q
REIS, H F	8408210380	50-250 Q
REIS, H F	8408210380	50-250 Q
REMIS, S	8408270136	50-354 D
REMIS, S C	8408060090	50-354 D
REMIS, S C	8408090255	50-354 Q
REMIS, S C	8408140543	50-354 Q
REMIS, S C	8408230093	50-354 D
REMIS, S C	8408230090*	50-354 D
REMIS, S C	8408280447	50-354 Q
REMIS, S C	8408290014	50-354 Q
REMLEY, M E	8408150564	70-25
REQUA, G	*8408030248*	50-261 P
REQUA, G	8408090444	50-261 P
REQUA, G	8408270094	50-261 P
RESSLER, W C	8408090334	50-289 R
REST, J	8408310077	NUREG
REYES, L	8408100109	50-295 S
REYES, L A	8408150475*	50-341 Q
REYES, L A	8408160193*	50-483 Q
REYES, L A	8408230149*	50-409 Q
REYES, L A	8408230252*	50-454 Q
REYES, L A	*8408300188**	50-315 Q
REYNOLDS, J R	8408060046	50-275 Q
REYNOLDS, J R	8408060046	50-275 Q
REYNOLDS, J R	8408060217	50-275 Q
REYNOLDS, J R	8408060217	50-275 Q
REYNOLDS, J R	8408070297	50-275 Q
REYNOLDS, J R	8408130389	50-275 Q
REYNOLDS, J R	8408130389	50-275 Q
REYNOLDS, J R	8408140464	50-275 Q
REYNOLDS, J R	8408140464	50-275 Q
REYNOLDS, J R	8408310210	50-275 Q
REYNOLDS, J R	8408310210	50-275 Q
REYNOLDS, J W	8408030113*	50-155 P
REYNOLDS, J W	8408030151*	50-255 P
REYNOLDS, N S	8408030091	50-416 Q
REYNOLDS, N S	8408030091	50-416 Q
REYNOLDS, N S	8408080162	50-445 Q
REYNOLDS, N S	8408080162	50-445 Q
REYNOLDS, N S	8408130093	50-445 Q
REYNOLDS, N S	8408130093	50-445 Q
REYNOLDS, N S	8408230187	50-445 Q
REYNOLDS, N S	8408230187	50-445 Q
REYNOLDS, N S	*8408230257*	50-445 Q
REYNOLDS, N S	8408230257	50-445 Q
REYNOLDS, N S	8408280265	50-445 Q
REYNOLDS, N S	8408280265	50-445 Q
REYNOLDS, S	8408210381*	50-352 Q
REYTBLATT, Z	8408280378*	50-295 P
REYTBLATT, Z	8408280380*	50-295 P
REYTBLATT, Z	8408280381*	50-295 P
REYTBLATT, Z	8408280407*	50-295 P
REYTBLATT, Z	8408280411*	50-295 P
REYTBLATT, Z	8408280422*	50-295 P
REYTBLATT, Z	8408280430*	50-295 P
REYTBLATT, Z V	8408280360	50-295 P
REYTBLATT, Z V	8408280366*	50-295 P
REYTBLATT, Z V	8408280373*	50-295 P
REYTBLATT, Z V	8408280383*	50-295 P
REYTBLATT, Z V	8408280387*	50-295 P
RHODES, M L	8408070273	50-445 T
RIANI, L	8408220265	NUREG
RICE, B J	8408200425	WASTE MGT
RICE, G B	8408200603	40-2061
RICE, R A	8408310154	PR
RICHARD, J B	8408070496	50-416 P
RICHARD, J B	8408130150	50-416 Q
RICHARD, J B	8408150160	50-416 P
RICHARD, J B	8408160061	50-416 S
RICHARD, J B	8408160421	50-416 S
RICHARD, J B	8408200127	50-417 A
RICHARD, J B	8408280194	50-416 Q
RICHARDS, S A	8408240287	50-344 S
RICHARDS, S A	8408300380*	50-344 Q
RICHARDS, W J	8408070346	PR
RIDDLE, R R	8408090510*	CONTRACT
RIDGWAY, D A	8408070418	50-320 Q
RIDGWAY, D A	8408070418	50-320 Q
RIDGWAY, D A	8408070470	50-320 Q
RIDGWAY, D A	8408070470	50-320 Q
RIDGWAY, D A	8408140004	50-400 Q
RIDGWAY, D A	8408140004	50-400 Q
RIDGWAY, D A	8408140008	50-400 Q
RIDGWAY, D A	8408140008	50-400 Q
RIDGWAY, D A	8408140022	50-400 Q
RIDGWAY, D A	8408140022	50-400 Q
RIDGWAY, D A	8408140048	50-400 Q
RIDGWAY, D A	8408140048	50-400 Q
RIDGWAY, D A	8408140057	50-400 Q
RIDGWAY, D. A	8408140057	50-400 Q
RIEDL, T J	8408160340*	50-445 A
RIGERT, J A	8408130359*	50-322 Q
RIGGS, R	8408290265	NUREG
RILEY, A	8408100030	50-454 T
RILEY, S L	8408160076	50-322 Q
RILEY, S L	8408160079	50-352 Q
RILEY, S L	8408160099	50-352 Q
RILEY, S L	8408160103	50-352 Q
RILEY, S L	8408160109	50-413 Q
RILEY, S L	8408160112	50-352 Q
RILEY, S L	8408160118	50-322 Q
RILEY, S L	8408160123	50-322 Q
RILEY, S L	8408160128	50-400 Q
RINALDI, F	8408020195*	50-329 A
RING, M	8408230252*	50-454 Q
RIORDON, B. J	8408080472	NUREG
RITNER, T H	8408240349	40-8502
RITTSCHER, D	8408090562	PROJ
RIVENBARK, G	8408080397	50-312 F
RIVENBARK, G	8408080445	50-312 F
RIVENBARK, G	8408090207	50-321 F
RIVENBARK, G W	8408220100	50-277 P
RIVENBARK, G W	8408020172	50-346 P
RIVENBARK, G W.	8408020173*	50-346 P
RIVENBARK, G W.	8408070502*	50-346 P
RIVENBARK, G W.	8408080031	50-346 F
RIVENBARK, G W	8408080070	50-302 P
RIVENBARK, G W	8408080152	50-313 P
RIVENBARK, G W	8408080158*	50-313 P
RIVENBARK, G W	8408080441	50-313 F
RIVENBARK, G W	8408090010	50-313 P
RIVENBARK, G W	8408130530	50-346 P
RIVENBARK, G W	8408130537*	50-346 P
RIVENBARK, G W	8408200414	50-269 P
ROBER, R W	8408150108	50-244 P
ROBERSON, P. L	8408290171	NUREG
ROBERTS, H. R	8408280110	40-8675
ROBERTS, J P	8408070036	PROJ
ROBERTS, J P	8408130590	70-1308
ROBERTS, J P	8408160461	70-1308
ROBERTS, J P	8408240009	50-280 Y
ROBERTS, T M	8408080384	COMMISSION
ROBERTS, W A	8408030187	WASTE MGT
ROBERTS, W A	8408150531	WASTE MGT
ROBERTS, W A	8408160518	50-259 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ROBERTS, W A	8408200300	50-259 S
ROBERTS, W B	8408210518*	50-352 A
ROBERTSON, J	8408080480*	CONTRACT
ROBERTSON, J	8408290007*	50-423 G
ROBINSON, P	8408290120	I&E
ROBKIN, M A	8408170040	50-139 F
ROCHLIS, S M	8408200497*	50-400 G
RODABAUGH, E C	8408130041	NUREG
RODABAUGH, E C	8408270582*	CONTRACT
RODRIGUEZ, J H	8408270136	50-354 D
RODRIGUEZ, R J	8408060006	50-312 V
RODRIGUEZ, R J	8408060011	50-312 G
RODRIGUEZ, R J	8408060177	50-312 P
RODRIGUEZ, R J	8408130207	50-312 F
RODRIGUEZ, R J	8408140259	50-312 P
RODRIGUEZ, R J	8408170362	50-312 P
RODRIGUEZ, R J	8408200339	50-312 G
RODRIGUEZ, R J	8408240111	50-312 S
RODRIGUEZ, R J	8408240112	50-312 P
RODRIGUEZ, R J	8408270061	50-312 P
RODRIGUEZ, R J	8408270401	50-312 P
RODRIGUEZ, R J	8408270288	50-312 S
RODRIGUEZ, R J	8408310113	50-312 P
RODRIGUEZ, R J	8408310196	50-312 S
RODRIGUEZ, R J	8408310217	50-312 P
RODRIGUEZ, R J	8408310234	50-312 P
RODRIGUEZ, R J	8408310245	50-312 P
ROGAN, R E	8408010329*	50-320 P
ROGERS, D W	8408060263	50-255 S
ROGERS, D W	8408090398	50-255 S
ROGERS, D W	8408160279	50-255 S
ROGERS, D W	8408270127	50-255 S
ROGERS, D W	8408270130	50-255 S
ROGERS, D W	8408310056	50-255 S
ROGERS, D W	8408310059	50-255 S
ROGERS, J T	8408020126*	50-440 I
ROGERS, P	8408080493	50-368 S
ROGERS, P	8408130190	50-313 S
ROGERS, P	8408130326	50-313 S
ROGERS, P	8408240053	50-313 S
ROGERS, P	8408300496	50-368 S
ROGERS, P C	8408060187	50-368 S
ROGERS, P C	8408080528	50-368 S
ROGGE, J	8408270269*	50-321 G
ROGOZINSKI, R M	8408230482	50-213 S
ROHDE, J E	8408090047	50-304 S
ROHRBACHER, R A	8408170117*	50-443 G
ROISMAN, A Z	8408090200	50-445 G
ROISMAN, A Z	8408090200	50-445 G
ROISMAN, A Z	8408090206*	50-445 G
ROISMAN, A Z	8408090206*	50-445 G
ROISMAN, A Z	8408140495	50-445 G
ROISMAN, A Z	8408230173	50-445 G
ROISMAN, A Z	8408230173	50-445 G
ROISMAN, A Z	8408240247	50-445 T
ROISMAN, A Z	8408240247	50-445 T
ROISMAN, A Z	8408280197	50-445 G
ROISMAN, A Z	8408290319	50-445 G
ROISMAN, A Z	8408290319	50-445 G
ROLES, G W	8408160460	WASTE MGT
ROLES, G W	8408210130	WASTE MGT
ROLFE, R M	8408030090	50-322 G
ROLFE, R M	8408030090	50-322 G
ROLFE, R M	8408070399	50-322 G
ROLFE, R M	8408070399	50-322 G
ROLFE, R M	8408160100	50-322 G
ROLFE, R M	8408160100	50-322 G
ROMAN, T W	8408020119*	50-220 R
ROMANO, F R.	8408010233	50-352 G
ROMANO, F R	8408140450	50-352 G
ROMANO, F R	8408140452*	50-352 G
ROMANO, F R	8408200433	50-352 G
ROMANO, F R.	8408200442*	50-352 G
ROMANO, F R	8408200447*	50-352 G
ROMANO, F R	8408220354	50-352 G
ROMANO, F R	8408240240	50-352 G
ROOD, H	8408030009*	50-329 A
ROONEY, V L	8408060425	50-237 P
ROONEY, V L	8408150261	50-271 G
ROONEY, V L	8408290314	50-263 P
ROOT, R W.	8408200317	50-460 S
ROSA, E A	8408010166	NUREG
ROSS, D F	8408280390*	50-295 P
ROSS, W J	8408270388*	50-338 G
ROTH, J	8406260179*	70-1143
ROTH, J	8408270518*	50-54 G
ROTHMAN, R L	8408140248*	50-329 A
ROTMAN, M	8408060197*	50-70 G
ROWE, C	8408270297*	40-672
ROWE, J	8408240390	WASTE MANA
ROY, G W	8408150617*	50-329 A
ROY, G W	8408150694*	50-329 S
ROZAK, S	8408150401*	50-254 G
ROZAK, S	8408310296*	50-305 G
RUBENSTEIN, L S	8402020372*	50-354 E
RUBENSTEIN, L S	8408070222	TOPREP
RUBIN, J	8408130346	PR
RUFF, A B	8408270191*	50-413 G
RUFF, A B	8408270440*	50-424 G
RUGER, C	8408220333	50-352 A
RUGGLES, L E	8408060367	NUREG
RUITER, G H	8408160211	50-305 R
RUMBAUGH, E	8408140079*	50-329 A
RUNCKLE, J	8408210323	50-400 G
RUNKLE, J	8408010264	50-400 G
RUNKLE, J	8408090455	50-400 G
RUPP, J L	8408090076	50-311 S
RUPP, J L	8408130588	50-311 S
RUPP, J L	8408160276	50-272 S
RUPP, J L	8408230501	50-272 S
RUPP, J L	8408300349	50-311 S
RUPP, J L	8408300400	50-311 S
RUSCHE, B C	8408090303*	WASTE MGT
RUSLING, D H	8408200121	50-274 F
RUSSELL, C F	8408060225	WASTE MGT
RUSSELL, C F	8408060338	WASTE MGT
RUSSELL, J E	8408080326	40-6622
RUSSELL, J E	8408240334	40-6622
RUSSELL, L B	8408150188	50-317 S
RUSSELL, L B	8408150395	50-318 S
RUSSELL, L B	8408200492	50-318 S
RUSSELL, L B	8408200512	50-318 S
RUSSELL, L B	8408290258	50-317 S
RUSSELL, L B	8408310042	50-318 S
RUSSELL, W T	8408160018	TOPREP
RUSSELL, W T	8408160319	50-250 P
RUTLEDGE, C	8408240381	40-8502
RUTLEDGE, C	8408240397	40-8502
RUTLEDGE, C	8408240409	40-8502
RUTLEDGE, C	8408240427	40-8502
RUTLEDGE, C	8408270032	40-8502
RUTLEDGE, C	8408270177	40-8502
RUTLEDGE, C	8408270562	40-8502
RUTLEDGE, C	8408270564	40-8502
RUTLEDGE, C	8408270571	40-8502
RUZ, R R	8408310154	PR
RYAN, J A	8407120136	50-528 D
RYBAK, B	8408060065	50-254 G
RYBAK, B	8408060071	50-249 P
RYBAK, B	8408060108	50-254 G
RYBAK, B	8408060144	50-374 P
RYBAK, B	8408060168	50-374 P
RYBAK, B	8408060276	50-237 P
RYBAK, B	8408140317	50-254 P
RYBAK, B	8408140405	50-374 P
RYBAK, B	8408150113	50-237 P
RYBAK, B	8408270358	50-373 F
RYBAK, B	8408310203	50-254 P
RYBAK, B	8408310211	50-237 P
SAEGERT, S C	8408020021	50-322 T
SAEGERT, S C	8408020021	50-322 T
SALAH, S	8408310361	50-373 S
SALAH, S	8408310362*	50-373 S
SALTER, P F	8408280007*	WASTE MGT
SALTZMAN, J	8408060218	50-413 J
SAMMONS, R. J	8408150122	71-6717
SAMMONS, R J	8408150607	71-6717
SANDERS, C F	8408280148	70-1151
SANDERS, W F	8408240371*	50-424 G
SANDERS, W F	8408270351*	50-424 G
SANDERSON, S A	8408160234	50-275 G
SARGENT, I H	8408280321*	50-346 P
SASSER, K	8408240421*	50-269 G
SASTRE, C	8408270070	WASTE MGT
SAUER, D W	8408060093	50-305 P
SAUER, R E	8408010034	27-48
SAUM, M A	8408160327	50-315 S
SAUNDERS, R F	8408010056	50-280 S
SAUNDERS, R F	8408010060*	50-280 S
SAUNDERS, R F	8408010069*	50-280 S
SAUNDERS, R F	8408010076*	50-280 S
SAVAGE, E N	8408150131	XPORTLIC
SAYLOR, N S	8408310137	FOIA
SCALETTI, D C	8408010324	50-447 A
SCALETTI, D C	8408090203	50-447 A
SCALETTI, D C	8408090429	50-447 A
SCALICE, J A	8408130355*	50-322 G
SCARANO, R A	8408130502	70-1257
SCARANO, R A	8408230078	50-312 G
SCARANO, R A	8408230223	50-361 G
SCARBROUGH, J N	8408080089	50-445 T
SCARBROUGH, J N	8408220403*	50-445 T
SCARBROUGH, J N	8408220403*	50-445 T
SCHAEFER, D	8408210167*	50-142 G
SCHAUER, F P	8207140330*	50-329 A
SCHAUER, F P	8408020180*	50-329 G
SCHAUER, F P	8408020182*	50-329 G
SCHEIDT, D J	8408170315	50-322 G
SCHEIDT, D J	8408170315	50-322 G
SCHERER, A E	8408020031	50-317 P
SCHERER, A E	8408140230	50-470 E
SCHERER, A E	8408140390	50-470 A
SCHERRER, J S	8105130143*	50-293 P
SCHINK, A B	8408100144*	50-289 G
SCHMIDT, H C	8408060165	50-445 A
SCHMIDT, H C	8408160330	50-445 G
SCHMIDT, H C	8408160335	50-445 A
SCHMIDT, H C	8408160412	50-445 A
SCHMIDT, H C	8408230390	50-445 F
SCHMIDT, H C	8408270030	50-445 A
SCHMIDT, H C	8408270067	50-445 A
SCHMIDT, H C	8408270123	50-445 A
SCHMIDT, H C	8408270124	50-445 A
SCHMIDT, H C	8408270132	50-445 A
SCHMIDT, H C	8408270271	50-445 X
SCHMIDT, H C	8408280142	50-445 A
SCHMIDT, H C	8408280190	50-445 A
SCHMIDT, H C	8408280218	50-445 A
SCHMIDT, H C	8408300239	50-445 A
SCHMOTZER, J K	8408210393*	50-338 P
SCHNEIDER, S L	8408200332	50-461 S
SCHNEIDER, S L	8408200333	50-528 S
SCHNEIDER, S L	8408200338	50-461 S
SCHNELL, D F	8406140221	50-483 A
SCHNELL, D F	8408030098	50-483 P
SCHNELL, D F	8408060286	50-483 P
SCHNELL, D F	8408100034*	50-483 G
SCHNELL, D F	8408130397	50-483 F
SCHNELL, D F	8408140129	50-483 F
SCHNELL, D F	8408140385	50-483 P
SCHNELL, D F	8408140404*	50-483 G
SCHNELL, D F	8408220278	50-483 P
SCHRADER, D	8408290303	50-454 G
SCHROEDER, B A	8408130271	50-237 R
SCHULTZ, W H	8408170145*	50-329 A
SCHULZ, R	8408060309*	50-456 G
SCHULZ, R	8408150515*	50-382 G
SCHUMACHER, M C	8408150401*	50-254 G
SCHUMACHER, M C	8408270288*	50-440 G
SCHUMACHER, M C	8408310296*	50-305 G
SCHUMM, S A	8408060431	WASTE MGT
SCHUMWAY, R. W	8405210578	NUREG
SCHUSTER, M D	8408070135	50-397 S
SCHUSTER, M. D	8408080119	50-397 F
SCHUSTER, M D	8408080273	70-1257
SCHUSTER, M D	8408210161	50-142 G
SCHUSTER, M D	8408210167*	50-142 G
SCHUSTER, M D	8408220340	70-1257
SCHUSTER, M D	8408230114	50-206 F
SCHUSTER, M D	8408230216	70-734
SCHUSTER, M D	8408270337	70-734
SCHUSTER, M D	8408270346*	70-734
SCHUSTER, M D	8408300007	70-1257
SCHUSTER, M D.	8408300125	50-528 G
SCHUSTER, M D	8408300127*	50-528 G
SCHUSTER, M D	8408300483	50-312 G
SCHUSTER, M D	8408300498*	50-312 G
SCHUSTER, M D	8408300504*	50-312 G
SCHUSTER, M D	8408310285	50-206 G
SCHUSTER, M D	8408310315	50-344 F
SCHUSTER, M H	8408150505*	50-322 T
SCHUYLER, J O	8406150149	50-275 P
SCHUYLER, J. O	8408010036	71-202
SCHUYLER, J O	8408020056	50-133 P
SCHUYLER, J O	8408020063*	50-133 P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHUYLER, J D	8408060120	50-323 A
CHUYLER, J D	8408060126	50-323 A
CHUYLER, J D	8408070278	50-323 A
CHUYLER, J D	8408070327*	50-275 G
CHUYLER, J D	8408080453	50-275 F
CHUYLER, J D	8408080458*	50-275 F
CHUYLER, J D	8408130003	50-275 P
CHUYLER, J D	8408130188	50-275 P
CHUYLER, J D	8408130291	50-275 G
CHUYLER, J D	8408140011	50-275 P
CHUYLER, J D	8408140341	50-323 P
CHUYLER, J D	8408160267	50-275 F
CHUYLER, J D	8408200318*	50-275 G
CHUYLER, J D	8408210406	50-275 P
CHUYLER, J D	8408230008	50-275 P
CHUYLER, J D	8408230012*	50-275 P
CHUYLER, J D	8408230593	50-275 F
CHUYLER, J D	8408270396	50-323 A
CHUYLER, J D	8408300482	50-275 P
CHUYLER, J D	8408310230	50-275 F
CHWAN, C A	8408070135	50-397 S
CHWARTZ, M W	8408010155	NUREG
CHWARTZ, S A	8408070352	50-322 T
CHWENCER, A	8408010107	50-373 P
CHWENCER, A	8408010227	50-354 A
CHWENCER, A	8408060273*	50-352 A
CHWENCER, A	8408070147	50-354 F
CHWENCER, A	8408080054	50-410 C
CHWENCER, A	8408080148	50-373 P
CHWENCER, A	8408080155*	50-373 P
CHWENCER, A	8408080314	50-374 P
CHWENCER, A	8408080319*	50-374 P
CHWENCER, A	8408090213*	50-322 G
CHWENCER, A	8408090407	50-397 P
CHWENCER, A	8408090410*	50-397 P
CHWENCER, A	8408090452	50-354 E
CHWENCER, A	8408130201	50-354 A
CHWENCER, A	8408160163	50-410 D
CHWENCER, A	8408160166*	50-410 D
CHWENCER, A	8408160170	50-354 E
CHWENCER, A	8408160431	50-410 D
CHWENCER, A	8408170104	50-410 D
CHWENCER, A	8408170107	50-410 D
CHWENCER, A	8408170110	50-410 D
CHWENCER, A	8408170227	50-373 P
CHWENCER, A	8408170243*	50-373 P
CHWENCER, A	8408200386	50-354 D
CHWENCER, A	8408200540	50-458 D
CHWENCER, A	8408200546*	50-458 D
CHWENCER, A	8408200552	50-458 D
CHWENCER, A	8408220164	50-458 D
CHWENCER, A	8408220432	50-354 D
CHWENCER, A	8408220434	50-458 D
CHWENCER, A	8408220435	50-374 P
CHWENCER, A	8408240194	50-458 F
CHWENCER, A	8408240303	50-461 A
CHWENCER, A	8408270479	50-373 P
CHWENCER, A	8408270498	50-397 P
CHWENCER, A	8408270501*	50-397 P
CHWENCER, A	8408280339	50-397 P
CHWENCER, A	8408310292	50-410 F
CHWENCER, A	8408310426	50-387 P
HWENCER, A	8408310439	50-373 P
CHWENCER, A	8408310450	50-373 P
CINTO, J	8408070207*	50-416 U
COTT, A E	8408160144	50-261 R
COTT, D J	8408060100	50-237 S
COTT, D J	8408060293	50-237 S
COTT, D J	8408070052	50-237 S
COTT, D J	8408070151	50-237 S
COTT, D J	8408130146	50-249 S
COTT, D J	8408130271	50-237 R
COTT, D J	8408130330	50-237 S
COTT, D J	8408200501	50-10 S
COTT, D J	8408200519	50-249 S
COTT, D J	8408210104	50-249 S
COTT, D J	8408230283	50-10 F
COTT, D J	8408240218	50-237 S
COTT, D J	8408270455	50-249 S
COTT, D J	8408300368	50-10 R
OTT, D J.	8408310063	50-237 S
OTT, D J.	8408310067	50-237 S
OTT, D J	8408310071	50-249 S
OTT, L	8408060203	50-237 S
OTT, N	8408270350	PR
SCOTT, R	8408100061	50-346 F
SCOTT, T G	8408300272	NUREG
SCULLE, K A	8408140335	50-456 A
SCULLE, K A	8408140376	50-456 A
SEAMAN, C	8408150476*	50-322 T
SEAMAN, C K	8408150505*	50-322 T
SEAMAN, C K	8408150514*	50-322 T
SEAMAN, C K	8408150530*	50-322 T
SEARS, C F	8408090082	50-423 A
SEARS, C F	8408090082	50-423 A
SEARS, C F	8408100064	50-423 S
SEARS, C F	8408100064	50-423 S
SEARS, C F	8408100116	50-213 G
SEARS, C F	8408100116	50-213 G
SEARS, C F	8408100116	50-213 G
SEARS, C F	8408210480	50-213 G
SEARS, C F	8408210480	50-213 G
SEARS, C F	8408210480	50-213 G
SEELINGER, J L	8408200580	50-289 G
SEGE, G	8408290265	NUREG
SEIKEN, S J	8408010386	50-482 S
SEIKEN, S J	8408030255	50-482 S
SEIKEN, S J	8408310101	50-482 A
SELAN, J C	8408200173*	50-336 P
SELBY, D L	8408230184*	50-317 P
SENECHAL, M E	8408080334*	PR
SERBANESCU, M A	8408140031*	50-400 T
SERBANESCU, M A	8408140031*	50-400 T
SERINI, D L	8408060371*	70-2988
SEYFRIT, K V	8408290067	50-275 G
SHACK, W J	8408100151	NUREG
SHACK, W J	8408310083	NUREG
SHAEFFER, M J	8408170187*	50-329 A
SHAFER, W	8408200308	50-255 S
SHAFER, W	8408210269	50-315 S
SHAFER, W	8408240114	50-374 S
SHAFER, W D	8408010289	50-373 G
SHAFER, W D	8408010291*	50-373 G
SHAFER, W D	8408010401	50-263 G
SHAFER, W D	8408030176	50-155 G
SHAFER, W D	8408070189	50-282 G
SHAFER, W D	8408090169	50-295 G
SHAFER, W D	8408170387	50-346 G
SHAFER, W D	8408130391	50-346 G
SHAFER, W D	8408130407	50-346 G
SHAFER, W D	8408160139	50-10 G
SHAFER, W D	8408160198	50-373 G
SHAFER, W D	8408160206*	50-373 G
SHAFER, W D	8408170090*	50-329 S
SHAFER, W D	8408230204	50-315 G
SHAFER, W D	8408230227	50-409 G
SHAFER, W D	8408230234*	50-409 G
SHAFER, W D	8408230489	50-263 G
SHAFER, W D	8408240082	50-255 G
SHAFER, W D	8408240083*	50-255 G
SHAFER, W D	8408290365	50-266 G
SHAFER, W D	8408300095	50-10 G
SHAFER, W D	8408300099*	50-10 G
SHANBAKY, M.	8408010286*	50-247 G
SHANBAKY, M	8408030267*	50-272 G
SHANBAKY, M	8408200023*	50-289 G
SHANBAKY, M M	8408010292*	50-245 G
SHANBAKY, M M	8408210244*	50-247 G
SHANBAKY, M M	8408230136*	50-277 G
SHANBAKY, M M	8408230569*	50-293 G
SHANBAKY, M M	8408240076*	50-334 G
SHAPIRO, R E	8408270136	50-354 D
SHAPIRO, R E	8408280447	50-354 G
SHAPIRO, R E	8408280449	50-354 G
SHAPIRO, R E	8408290014	50-354 G
SHAUB, E	8408080166*	50-387 G
SHAUB, E	8408090330*	50-322 G
SHAW, R W	8408240239*	50-413 I
SHEA, J	8408200190	50-245 P
SHEA, K H	8408030087	50-331 J
SHEA, K H	8408030129	50-331 J
SHEDLOSKY, J	8408290483*	50-322 G
SHEDLOSKY, J T	8408080403*	50-245 G
SHELL, R H	8408270098	50-438 A
SHELL, R H	8408270156	50-327 P
SHEPPARD, J J	8408210486	TOPREP
SHEPPARD, J J	8408210486	TOPREP
SHERWIN, J A	8408200517	WASTE MGT
SHERWOOD, G G	8408230209	50-447 A
SHERWOOD, G G	8408240348	50-155 S
SHERWOOD, G G	8408270155	50-447 P
SHEWMAKER, R E	8408130256*	50-382 G
SHEWMON, P	8206060008*	50-329 D
SHEWMON, P G	8408010183*	50-329 D
SHIBATA, Y	8408170406	XPORTLTC
SHIBATA, Y	8408170408*	XPORTLTC
SHIELDS, J	8408070490	50-374 S
SHIELDS, J M	8408060063	50-373 S
SHIELDS, J M	8408200526	50-373 S
SHIFFER, J D	8408070369	50-275 S
SHIFFER, J D	8408160491	50-275 S
SHIFFER, J D	8408210226	50-275 S
SHIFFER, J D	8408230476	50-275 S
SHIFFER, J D	8408270112	50-275 S
SHIFFER, J D	8408310038	50-275 S
SHIFFER, J D	8408310143	50-275 S
SHIRAKAWA, T	8405160213	XPORTLTC
SHIRAKAWA, T	8408150128	XPORTLTC
SHIRAKAWA, T	8408150179	XPORTLTC
SHIU, K	8408220333	50-352 A
SHOEMAKER, C J	8408020219	50-275 G
SHOEMAKER, C J	8408030099	50-322 G
SHOEMAKER, C J	8408060221	50-482 G
SHOEMAKER, C J	8408070358	50-322 G
SHOEMAKER, C J	8408090183	50-275 G
SHOEMAKER, C J	8408130158	50-352 G
SHOEMAKER, C J	8408150418	50-322 G
SHOLLY, S C	8408140448	50-247 G
SHOLLY, S C	8408230325	50-289 G
SHON, F J	8408280391	50-155 G
SHOPENN, N M	8408210143*	40-4492
SHOPENN, N M	8408240189	40-299
SHOPENN, N M	8408240190	40-3453
SHOPENN, N M	8408240195	40-8698
SHOPENN, N M	8408240207	40-8698
SHOPENN, N M	8408270044	40-3453
SHOPENN, N M	8408270062	40-3453
SHOPENN, N M	8408270100	40-8698
SHOPPEN, N M	8408240142	40-3453
SHUMAKER, J	8408140449	50-219 G
SIEBER, J D	8408150124	50-334 P
SIEDOR, G R	8408170314	50-461 G
SIEDOR, G R	8408170323	50-461 G
SIEGEL, B L	8408130152	50-461 A
SIEGEL, M	8408280009*	WASTE MGT
SIEGEL, M D	8408240214	WASTE MANA
SILBERG, J E	8408010214	50-440 G
SILBERG, J E	8408010214	50-440 G
SILBERG, J E	8408010229	50-440 G
SILBERG, J E	8408010229	50-440 G
SILBERG, J E	8408140420	PR
SILVER, H	8408090097	50-289 F
SILVER, H	8408200418	50-302 P
SILVER, H	8408210054	50-302 P
SILVER, H	8408210547	50-302 P
SILVER, H	8408220203	50-302 P
SILVER, N S	8408300304	50-354 D
SILVIS, R M	8408130435	CONTRACT
SILVIS, R M	8408130440	CONTRACT
SILVIS, R M	8408130444	CONTRACT
SILVIS, R M	8408220384	CONTRACT
SIMAN-TOV, I	8408130001	NUREG
SIMAN-TOV, M	8408130007	NUREG
SIMONEN, F A	8408220370	NUREG
SIMPSON, R W	8408220381*	50-445 T
SIMPSON, R W	8408220381*	50-445 T
SIMS, W T	8408070273	50-445 T
SINCLAIR, J B	8408020082	50-271 G
SINCLAIR, J B	8408060226	50-271 G
SINCLAIR, J B	8408160052	50-271 P
SINCLAIR, M	8408170277*	50-329 T
SINGER, G L	8405210579	NUREG
SINGH, B K	8407300089	50-443 F
SINGH, B K	8408090497	50-244 P
SINGH, H	8408140286*	50-329 A
SINGH, H	8408140367*	50-329 A
SINGH, H	8408150046*	50-329 A
SINGH, H	8408210418*	50-329 A
SINGH, H	8408210430*	50-329 A
SINGH, H N	8408140144*	50-329 A
SINGH, H N	8408140300*	50-329 A
SINGH, H N	8408140319*	50-329 A
SINHA, U N	8408160390*	50-458 A
SINKE, G J	8408300322	70-925
SISK, D P	8408160491	50-275 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SISK, D P	8408210226	50-275 S
SISK, D P	8408230476	50-275 S
SISK, D P	8408270112	50-275 S
SISK, D P	8408310143	50-275 S
SISKIND, B	8408010151	NUREG
SJOBLOM, G I	8408160264*	ORG
SMEDIRA, C	8408150598	71-9073
SMEENGE, R J	8408150511*	50-461 Q
SMIDTH, P T	8408130682*	50-329 A
SMITH, D F	8408240169	40-8102
SMITH, D L	8408060113	50-259 S
SMITH, D L	8408080518	50-259 S
SMITH, D L	8408160519	50-259 S
SMITH, D L	8408200412	50-296 S
SMITH, D L	8408270150	50-296 S
SMITH, D L	8408280349	50-259 S
SMITH, G C	8408150407*	70-371
SMITH, G C	8408150424*	50-277 Q
SMITH, G L	8408090032	50-237 S
SMITH, G L	8408090151	50-237 S
SMITH, I W	8405250251	50-344 Q
SMITH, M E	8408010231*	50-354 E
SMITH, M J	8408150394*	50-454 Q
SMITH, N	8408080219	XPORTLIC
SMITH, P A	8408010048*	CONTRACT
SMITH, P A	8408010182*	CONTRACT
SMITH, P A	8408070053*	CONTRACT
SMITH, P A	8408070104*	CONTRACT
SMITH, P A	8408080064*	CONTRACT
SMITH, P A	8408080321*	CONTRACT
SMITH, P A	8408080507*	CONTRACT
SMITH, P A	8408090142*	CONTRACT
SMITH, P A	8408090531*	CONTRACT
SMITH, P A	8408130314*	CONTRACT
SMITH, P A	8408130437*	CONTRACT
SMITH, P A	8408130442*	CONTRACT
SMITH, P A	8408130445*	CONTRACT
SMITH, P A	8408130597*	CONTRACT
SMITH, P A	8408220156*	CONTRACT
SMITH, P A	8408220397*	CONTRACT
SMITH, P A	8408230336*	CONTRACT
SMITH, P A	8408230506*	CONTRACT
SMITH, P A	8408270552*	CONTRACT
SMITH, P A	8408270558*	CONTRACT
SMITH, P A	8408270592*	CONTRACT
SMITH, P A	8408310252*	CONTRACT
SMITH, P A	8408310358*	CONTRACT
SMITH, R D	8408070226	40-8786
SMITH, R D	8408240158	40-8084
SMITH, R D	8408240166*	40-299
SMITH, R D	8408240175	40-8768
SMITH, R D	8408240178*	40-8768
SMITH, R D	8408240181	40-2259
SMITH, R D	8408240186	40-1162
SMITH, R D	8408240198*	40-8698
SMITH, R D	8408240201*	40-299
SMITH, R D	8408240213	40-299
SMITH, R D	8408240331	40-8586
SMITH, R D	8408270026	40-8786
SMITH, R D	8408270331	40-8452
SMITH, R D	8408270354	40-299
SMITH, R D	8408270482	40-3453
SMITH, R D	8408270487	40-299
SMITH, R D	8408280006	40-299
SMITH, R D	8408280014	40-8502
SMITH, R D	8408280023	40-3453
SMITH, R H	8408060208*	50-213 Q
SMITH, R H	8408160272*	50-334 Q
SMITH, R M	8408310035*	50-275 P
SMITH, R W	8408270465*	50-271 Q
SMITH, S P	8408030272	50-309 S
SMITH, W F	8408150102*	50-445 Q
SMITH, W F	8408150440*	50-445 Q
SMITH, W F	8408160037*	50-445 Q
SMITH, W F	8408160500*	50-445 Q
SMITH, W G	8408060151	50-316 S
SMITH, W G	8408080536	50-315 S
SMITH, W G	8408130307	50-316 S
SMITH, W G	8408160127	50-316 S
SMITH, W G	8408160327	50-315 S
SMITH, W G	8408220486	50-315 S
SMITH, W G,	8408300505	50-315 S
SMYKOWSKI, S	8408150252	WASTE MGT
SMYKOWSKI, S	8408280340	WASTE MGT
SMYTH, C W	8408240066	50-289 R
SMYTHE, D R	8408200323	50-373 S
SMYTHE, D R	8408310047	50-373 S
SNELL, W G	8408010299*	50-409 Q
SNELL, W G	8408240429*	50-305 Q
SNIEZEK, J	8408010159	REVIEW GRP
SNYDER, B J	8408010049	50-320 P
SNYDER, B J	8408030211	50-320 P
SNYDER, B J	8408060253	50-320 P
SNYDER, B J	8408070083	50-320 P
SNYDER, B J	8408160042	50-320 P
SNYDER, B J	8408280341	50-320 P
SOMERVILLE, K G	8408240341	40-8783
SOMMERS, D A	8408010147*	50-329 Q
SOMSAG, M L	8408310194*	50-454 T
SORDILL, P	8408140449	50-219 Q
SORENSEN, G C	8408070247	50-397 Q
SORENSEN, G C	8408070325	50-397 P
SORENSEN, G C	8408070333	50-397 P
SORENSEN, G C	8408080175	50-460 A
SORENSEN, G C	8408090262	50-397 P
SORENSEN, G C	8408160404	50-508 A
SORENSEN, G C	8408170031	50-460 A
SORENSEN, G C	8408270073	50-397 P
SORENSEN, G C	8408270153	50-397 P
SORENSEN, R C	8408300407*	50-528 Q
SORRELL, E C	8408030163	50-321 F
SORRELL, E C	8408210472	50-321 F
SORRELL, E C	8408270301	50-321 F
SORRELL, E C	8408280233	50-321 F
SPANG, J R	8408290265	50-289 T
SPANG, J R	8408290269*	50-289 T
SPANGLER, R G	8408020072	NUREG
SPECK, S W	8408100060	50-295 F
SPECK, S W	8408300211*	50-302 F
SPEIS, T P	8407020544*	REVIEW GRP
SPEIS, T P	8408220070*	50-329 A
SPENCE, F D	8408280056*	50-322 H
SPENCE, M D	8408140393	50-445 K
SPENCE, M D	8408270075	50-445 A
SPENCER, S	8408080245	50-445 T
SPESSARD, R L	8408070204	50-454 Q
SPESSARD, R L	8408070354	50-341 Q
SPESSARD, R L	8408080171	50-263 Q
SPESSARD, R L	8408080174*	50-263 Q
SPESSARD, R L	8408080188	50-454 Q
SPESSARD, R L	8408090212	50-454 Q
SPESSARD, R L	8408100005	50-440 A
SPESSARD, R L	8408100044	50-266 Q
SPESSARD, R L	8408130372	50-305 P
SPESSARD, R L	8408140098	50-409 P
SPESSARD, R L	8408140229	50-454 Q
SPESSARD, R L	8408140402	50-483 Q
SPESSARD, R L	8408150471	50-341 Q
SPESSARD, R L	8408150492	50-454 Q
SPESSARD, R L	8408160184	50-483 Q
SPESSARD, R L	8408160190*	50-483 Q
SPESSARD, R L	8408160212	50-454 Q
SPESSARD, R L	8408160216*	50-454 Q
SPESSARD, R L	8408160334	50-341 Q
SPESSARD, R L	8408160338*	50-341 Q
SPESSARD, R L	8408170122	50-155 P
SPESSARD, R L	8408170039	50-454 Q
SPESSARD, R L	8408170099	50-331 P
SPESSARD, R L	8408200221	50-454 Q
SPESSARD, R L	8408230141	50-341 Q
SPESSARD, R L	8408230142*	50-341 Q
SPESSARD, R L	8408230245	50-454 Q
SPESSARD, R L	8408270245	50-454 Q
SPESSARD, R L	8408300118	50-456 Q
SPESSARD, R L	8408300143	MISC
SPESSARD, R L	8408310381	50-341 Q
SPESSARD, R L	8408130120	50-461 A
SPIEGEL, G	8408290312	50-458 M
SPIELES, P	8408240031	40-8697
SPIELES, P R	8408240102	40-8360
SPINRAD, B I	8408080335	PR
SPITZBERG, D B	8408090127	40-8822
SPITZBERG, D B	8408210120*	40-2259
SPIVEY, H L	8408230360*	50-302 H
SPRUNGER, C K	8408070391	50-374 S
ST LAURENT, N	8408160529	50-29 S
ST LAURENT, N N	8408090104	50-29 S
ST LAURENT, N N	8408210350	50-29 S
ST LAURENT, N N	8408230340	50-29 S
ST LAURENT, N N	8408240153	50-29 F
ST LAURENT, N N	8408300441	50-29 S
STAMIRIS, B	8408020107*	50-329 Q
STAMIRIS, B G	8408170292*	50-329 T
STANG, J	8408060325*	50-382 Q
STANLEY, R W	8408080142	50-388 S
STANLEY, R W	8408090421	50-387 S
STANLEY, R W	8408160164	50-388 S
STANLEY, R W	8408240246	50-387 S
STANLEY, R W	8408300399	50-388 S
STANLEY, R W	8408300494	50-388 S
STANSBERRY, W W	8408280370*	50-269 Q
STARKEY, R B	8408070060	50-325 S
STARKEY, R B	8408010295	50-325 S
STARKEY, R B	8408060088	50-325 S
STARKEY, R B	8408300312	50-325 S
STARMER, R J	8408060186	WASTE MGT
STARMER, R J	8408200426	WASTE MGT
STARMER, R J	8408210115	WASTE MGT
STAROSTECKI, R	8408260175	70-1143
STAROSTECKI, R	8408010296	50-247 Q
STAROSTECKI, R	8408030027	50-272 Q
STAROSTECKI, R	8408030146	70-371
STAROSTECKI, R	8408030222	50-271 Q
STAROSTECKI, R	8408070232	50-272 Q
STAROSTECKI, R	8408080212	50-334 Q
STAROSTECKI, R	8408080353	50-245 Q
STAROSTECKI, R	8408080464	50-245 Q
STAROSTECKI, R	8408090040	50-387 Q
STAROSTECKI, R	8408090133	50-213 Q
STAROSTECKI, R	8408100123	50-289 Q
STAROSTECKI, R	8408130350	50-29 Q
STAROSTECKI, R	8408150233	50-277 Q
STAROSTECKI, R	8408150251	50-213 Q
STAROSTECKI, R	8408150256	50-443 Q
STAROSTECKI, R	8408150264	50-289 Q
STAROSTECKI, R	8408150366	50-272 Q
STAROSTECKI, R	8408160073	50-29 Q
STAROSTECKI, R	8408160270	50-311 Q
STAROSTECKI, R	8408200032	50-387 Q
STAROSTECKI, R	8408200235*	50-388 V
STAROSTECKI, R	8408200354	50-354 Q
STAROSTECKI, R	8408210368	50-352 Q
STAROSTECKI, R	8408230082	50-293 Q
STAROSTECKI, R	8408240233	50-410 Q
STAROSTECKI, R	8408240361	50-317 Q
STAROSTECKI, R	8408270406	50-309 Q
STAROSTECKI, R	8408270477	50-184 Q
STAROSTECKI, R	8408270510	50-54 Q
STAROSTECKI, R	8408270538	50-333 Q
STAROSTECKI, R	8408270577	50-29 Q
STAROSTECKI, R	8408280101*	50-352 A
STAROSTECKI, R	8408280291	50-219 Q
STAROSTECKI, R	8408290003	50-423 Q
STAROSTECKI, R	8408290478	50-322 Q
STAROSTECKI, R	8408300097	50-219 Q
STAROSTECKI, R	8408300374	50-320 Q
STAROSTECKI, R	8408310044	50-470 Q
STASEK, S	8408300108*	50-10 Q
STATTON, C D	8408280062	QA999
STAUTER, J C	8408020153	40-8027
STAUTER, J C	8408150671	40-8027
STAUTER, J C	8408150675*	40-8027
STEFANO, J J	8408290396	50-440 E
STEINBRENNER, F	8408130597*	CONTRACT
STEISS, A W	8408220156*	CONTRACT
STELLO, V.	8406200226*	PR
STELLO, V	8406280010*	PR
STELLO, V	8408010042	REVIEW GRP
STELLO, V	8408070081	REVIEW GRP
STELLO, V	8408230396	REVIEW GRP
STELLO, V	8408270102	REVIEW GRP
STELLO, V	8408270102	REVIEW GRP
STELLO, V	8408270343	REVIEW GRP
STELLO, V	8408270446	REVIEW GRP
STERGAKOS, E P	8408130359*	50-322 Q
STERN, T	8408080303*	NUREG
STEVENS, J A	8408060210	50-456 F
STEWART, D L	8408310075	NUREG
STEWART, W L	8408020028	50-338 F
STEWART, W L	8408020041	50-280 Q
STEWART, W L	8408020132	50-280 F
STEWART, W L	8408070039	50-280 F
STEWART, W L	8408070400	50-338 F
STEWART, W L	8408070489	50-280 V
STEWART, W L	8408090149	50-338 P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STEWART, W L	8408090235	50-338 P
STEWART, W L	8408100098	50-280 F
STEWART, W L	8408130400*	50-338 G
STEWART, W L	8408130403*	50-338 G
STEWART, W L	8408130438*	50-338 G
STEWART, W L	8408130595	50-280 P
STEWART, W L	8408160039	50-280 P
STEWART, W L	8408160406	50-280 F
STEWART, W L	8408170222	50-280 F
STEWART, W L	8408170300	50-338 P
STEWART, W L	8408210132	50-280 P
STEWART, W L	8408210375	50-338 P
STEWART, W L	8408220171	50-280 R
STEWART, W L	8408240280	50-280 P
STEWART, W L	8408270448*	50-280 Q
STEWART, W L	8408280150	50-280 Q
STIETZEL, J F	8408080536	50-315 S
STIJGEREN, E V	8408210426*	50-29 P
STILES, J M	8408290313	50-454 G
STILES, N W	8408140456	50-443 G
STITT, B. D	8408160248	50-269 P
STODDART, P G	8408270227*	50-302 Q
STODDART, P G	8408280123*	70-1113
STOHR, J P	8408030029	70-143
STOHR, J P	8408130380	70-143
STOHR, J P	8408130382*	70-143
STOHR, J P	8408140199	70-1113
STOHR, J P	8408160310	70-143
STOHR, J P	8408230281	70-143
STOHR, J P	8408270116	70-27
STOHR, J P	8408270125*	70-27
STOHR, J P	8408270222	70-1151
STOHR, J P	8408270254	70-27
STOHR, J P	8408270280*	70-27
STOHR, J P	8408270411	70-143
STOHR, J P	8408270415*	70-143
STOHR, J P	8408270420	70-143
STOHR, J P	8408270524	70-27
STOHR, J P	8408270534	70-1113
STOHR, J P	8408280051	70-143
STOHR, J P	8408280090	70-1201
STOHR, J P	8408280118*	70-1113
STOHR, J P	8408280189	70-143
STOHR, J P	8408280282*	70-1201
STOHR, J P	8408280298	70-143
STOHR, J P	8408280300*	70-143
STOHR, J P	8408280362	70-1113
STOHR, J P	8408300190	70-824
STOHR, J P	8408300200*	70-824
STOHR, J P	8408300280	70-143
STOHR, J P	8408300284	70-143
STOHR, J. P	8408300296	70-1201
STOHR, J P	8408300367	70-27
STOHR, J P	8408300391	70-27
STOHR, J P.	8408300398	70-27
STOHR, J P.	8408310031	70-27
STOHR, J P	8408310068	50-13 F
STOHR, J P	8408310254	70-1151
STOKELY, J R	8408300272	NUREG
STOKES, C C	8408170296	50-454 T
STOKES, C C	8408170380	50-454 T
STOKES, C C	8408200458*	50-454 T
STOLZ, J F	8408080161	50-312 P
STOLZ, J F	8408080178	50-321 P
STOLZ, J. F.	8408080438	50-289 P
STOLZ, J F	8408080477	50-289 P
STOLZ, J F	8408080524	50-346 P
STOLZ, J F.	8408080527*	50-346 P
STOLZ, J F	8408130302	50-321 F
STOLZ, J F	8408150565	50-346 P
STOLZ, J F.	8408160021	50-346 F
STOLZ, J F	8408160060	50-289 P
STOLZ, J F	8408160285	50-289 P
STOLZ, J F	8408210061*	50-302 P
STOLZ, J F	8408210062	50-312 P
STOLZ, J F.	8408210070*	50-312 P
STOLZ, J F	8408210152	50-312 P
STOLZ, J F	8408210576*	50-302 P
STOLZ, J F	8408220530*	50-277 P
STOLZ, J F	8408230465	50-346 P
STOLZ, J F.	8408230556	50-346 P
STOLZ, J. F	8408270464	50-269 P
STOLZ, J F	8408270467	50-289 P
STOLZ, J F	8408270499	50-269 P
STOLZ, J. F	8408280319	50-346 P
STOLZ, J F	8408280488	50-346 P
STOLZ, J F	8408300197	50-366 P
STOLZ, J F	8408300217*	50-366 P
STOLZ, J F	8408310305	50-289 P
STOLZ, J F	8408310308*	50-289 P
STOLZ, J F	8408310406	50-302 P
STOUT, R B	8408090209*	50-316 P
STOUT, R B	8408230266*	50-315 P
STREETER, J F	8408060344*	50-454 S
STREETER, J F	8408070213	50-454 G
STREETER, J F	8408070216*	50-454 G
STREETER, J F	8408070221*	50-454 G
STREIER, G	8408310302*	50-255 G
STRUCKMEYER, R	8408150305*	50-317 G
STRUCKMEYER, R	8408150701*	50-286 G
STRUCKMEYER, R	8408200544*	50-247 G
STRUCKMEYER, R	8408230495*	50-309 G
STUBBING, J F	8408300184	50-151 S
SU, T Y	8408130420*	50-454 G
SUERMANN, J	8408100109	50-295 S
SUGARMAN, R J	8408010223	50-352 G
SUGARMAN, R J	8408010223	50-352 G
SUGARMAN, R J	8408010228*	50-352 G
SUGARMAN, R J	8408010228*	50-352 G
SUGARMAN, R J	8408010248	50-352 G
SUGARMAN, R J	8408010248	50-352 G
SUGARMAN, R J	8408090226	50-352 G
SUGARMAN, R J	8408090226	50-352 G
SUGARMAN, R J	8408090233*	50-352 G
SUGARMAN, R J	8408090233*	50-352 G
SUGARMAN, R J	8408130368	50-352 G
SUGARMAN, R J	8408130368	50-352 G
SULLIVAN, H	8408020170	ACRS
SULLIVAN, H	8408020170	ACRS
SUMMER, J T	8408130410*	50-289 G
SUMMERS, R J	8408150370*	50-272 G
SUND, H J	8408160132*	50-324 G
SUNDIN, R	8408240040	40-8727
SURMEIER, J	8408150341*	WASTE MGT
SWAIN, H W	8408210416	REGGD
SWAMY, S A	8408160378*	50-443 A
SWANGER, F	8408080508	50-346 S
SWANGER, F	8408090026	50-346 S
SWANGER, L A	8408150514*	50-322 T
SWANGER, L A	8408150530*	50-322 T
SWANGER, L A	8408280205	50-413 T
SWARTZ, E D	8407100002	50-456 S
SWARTZ, E D	8408060136	50-454 A
SWARTZ, E D	8408080198	50-454 F
SWARTZ, E D	8408100119*	50-456 G
SWARTZ, E D	8408130231	50-454 S
SWARTZ, E. D	8408130409	50-454 G
SWARTZ, E D	8408130415	50-454 G
SWARTZ, E D	8408140371	50-454 E
SWARTZ, E D	8408140380	50-454 A
SWARTZ, E D	8408140386	50-456 A
SWARTZ, E D	8408220368	50-454 A
SWARTZ, E D	8408240196	50-454 G
SWARTZ, E D	8408300044	50-456 S
SWARTZ, E D	8408300214	50-456 S
SWARTZMAN, G L	8408010158	NUREG
SWARTZMAN, G L	8408060386	NUREG
SWARTZWELDER, R	8408060310	50-320 S
SWENSON, A.	8408140449	50-219 G
SWENSON, D V	8408130006	NUREG
SWETLAND, P	8408280107	50-213 S
SWETLAND, P	8408310074	50-213 S
SWETLAND, P	8408310111	50-213 S
SWETLAND, P. D.	8408090141*	50-213 G
SWETLAND, P D	8408150255*	50-213 G
SWIGER, M. A	8408150467	50-440 G
SWIGER, M. A	8408150467	50-440 G
SWIHART, G L	8408240179	50-374 S
SZCZECH, R A	8408160182	50-289 S
TAHVILI, T	8408230103*	50-261 P
TAHVILI, T.	8408230266*	50-315 P
TAM, P	8408010195*	50-329 G
TAM, P.	8408210058	50-334 P
TAMBLING, T N	8408030179*	50-155 G
TAMBLING, T. N	8408130244*	50-329 A
TAMBLING, T. N	8408150737*	50-329 A
TANG, P K	8408160146	NUREG
TANI, K	8408300121*	50-456 G
TANI, K.	8408300196*	50-440 G
TANI, K.	8408300220*	50-341 G
TANIOUS, N	8408220324	WASTE MGT
TAPLEY, J	8408100061	50-346 F
TARLETZ, D B	8408150473	50-322 T
TARLETZ, D B	8408150473	50-322 T
TAUBLING, T N	8408010308*	50-151 G
TAYLOR, F Z	8408200282*	50-289 H
TAYLOR, H S	8408030143	GA999
TAYLOR, J A	8408290193	50-338 S
TAYLOR, J H	8408070389	50-269 P
TAYLOR, J H	8408080016	TOPREP
TAYLOR, J H	8408220415*	50-445 G
TAYLOR, J H	8408230084	TOPREP
TAYLOR, J H	8408270159	TOPREP
TAYLOR, J H	8408300141	TOPREP
TAYLOR, M	8408310080	I&E
TAYLOR, M E	8408160176	50-483 S
TAYLOR, M E	8408160256	50-483 S
TAYLOR, M E	8408240193	50-483 S
TAYLOR, P A	8408270480*	50-413 G
TAYLOR, R K	8408150505*	50-322 T
TAYLOR, T B	8408310219	PR
TAYLOR, T B	8408310221*	PR
TAYLOR, T J	8408030092	WASTE MGT
TAYLOR, T J	8408060067	WASTE MGT
TAYLOR, T J	8408060264	WASTE MGT
TAYLOR, T J	8408130137	WASTE MGT
TAYLOR, T J	8408200514	WASTE MGT
TAYLOR, T J	8408220223	WASTE MGT
TEMPLE, G M	8408300127*	50-528 G
TENZER, B. E.	8408030021	GA999
TERAO, D	8408210461*	50-329 A
THADANI, M C	8408060270	50-331 F
THADANI, M C	8408060425	50-237 P
THATCHER, D	8408220265	NUREG
THAYER, J K	8408070472	50-29 P
THIES, A. C.	8408060072	50-413 A
THOMAS, C C	8408010308*	50-151 G
THOMAS, C G	8405160476*	50-89 P
THOMAS, C O	8405300696	50-284 F
THOMAS, C O	8407110579	50-192 F
THOMAS, C O	8408010045	50-156 F
THOMAS, C. O	8408010259	50-160 P
THOMAS, C O	8408030205	50-5 P
THOMAS, C O	8408030301	50-199 V
THOMAS, C O	8408060146	50-134 F
THOMAS, C O.	8408060369	50-223 P
THOMAS, C O	8408060445	50-396 P
THOMAS, C O.	8408070011*	50-396 P
THOMAS, C O	8408070035	50-170 P
THOMAS, C O	8408070097	50-225 F
THOMAS, C O	8408070124	50-166 P
THOMAS, C O.	8408070193	TOPREP
THOMAS, C O	8408090321	50-601 A
THOMAS, C O	8408090347	TOPREP
THOMAS, C O	8408090353	TOPREP
THOMAS, C O	8408090525	50-252 F
THOMAS, C O	8408090536*	50-170 P
THOMAS, C O	8408140569*	50-166 P
THOMAS, C O	8408200461	50-188 F
THOMAS, C O	8408210097	50-97 F
THOMAS, C O	8408210101	50-116 F
THOMAS, C O	8408210141	50-294 V
THOMAS, C O	8408210629	50-30 P
THOMAS, C O.	8408230467	50-601 A
THOMAS, C O	8408240107	50-30 W
THOMAS, C. O.	8408270462	50-166 P
THOMAS, C O	8408270466*	50-166 P
THOMAS, C O	8408290277	50-163 P
THOMAS, C O	8408290286*	50-163 P
THOMAS, C. O	8408300215	50-352 E
THOMAS, C O.	8408310345	TOPREP
THOMAS, M	8408270419*	50-390 G
THOMAS, M E	8408220080*	CONTRACT
THOMAS, M. E	8408220400*	CONTRACT
THOMAS, M. E	8408220404*	CONTRACT
THOMAS, R. D.	8408080151*	70-734
THOMAS, R D	8408090122*	70-984
THOMAS, R D.	8408130507*	70-1257
THOMAS, R. D	8408130511*	70-1257
THOMAS, W R	8408080472	NUREG
THOMASON, P V.	8408240072	50-298 S
THOMPSON, D	8408150694*	50-329 S
THOMPSON, H L	8408240328	50-250 F
THOMPSON, J L	8408170339*	50-354 G
THOMPSON, J. L.	8408170342*	50-354 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
THOMPSON, R D	8408280395*	50-295 P
THOMPSON, R D	8408280404*	50-295 P
THOMPSON, R H	8408300341	50-302 S
THOMPSON, S L	8408100147	NUREG
THOMPSON, T	8408270297*	40-672
THONUS, L	8408300381*	50-320 Q
THORNBERRY, R C	8408230558*	50-275 F
THULL, T S	8408070112	50-245 S
THULL, T S	8408090340	50-245 S
THULL, T S	8408090340	50-245 S
THULL, T S	8408290004	50-245 S
TIEN, C	8408020211	ACRS
TIEN, C	8408020211	ACRS
TIKTINSKY, D	8408240376	WASTE MGT
TIKTINSKY, D H	8408230041	WASTE MGT
TILLMAN, A	8408090127*	50-335 Q
TILLMAN, A	8408230255*	50-324 Q
TILLMAN, A	8408240010*	50-261 Q
TIMBERLAKE, D R	8408140023*	50-400 T
TIPPS, B B	8408300517	50-366 S
TOBIN, W	8408280192*	70-143
TOBIN, W J	8408160317*	70-143
TODD, G A	8408270427*	70-143
TODD, G A	8408300401*	70-27
TODD, G A	8408310255*	70-1151
TODD, M R	8408070273	50-445 T
TOMLINSON, D	8408150515*	50-382 Q
TOMLINSON, D P	8408060313*	50-285 Q
TOMLINSON, D P.	8408150655*	50-445 Q
TONQUE, T M	8408300108*	50-10 Q
TOOLE, R	8408220365*	50-289 P
TOSTE, A P	8408310075	NUREG
TOTH, A. D	8408170369	50-397 S
TOTH, A D	8408290036	50-397 S
TOTH, A D.	8408300464*	50-397 Q
TOTTEN, M	8408030282*	MISC
TOURIGNY, E. G	8408200359	50-285 P
TOWNSEND, B	8408200590	CONTRACT
TOWNSEND, B	8408200602	CONTRACT
TOWNSEND, B	8408210024	CONTRACT
TOWNSEND, B	8408210040	CONTRACT
TOWNSEND, B L	8408310385	CONTRACT
TOY, H L	8408170016	70-8
TRAGER, J.	8408060197*	50-70 Q
TRAMM, T R	8408220079	50-454 Q
TRAMM, T R.	8408220106	50-454 F
TRAMM, T. R	8408220239	50-454 A
TRAMM, T R	8408220306	50-454 E
TRAMM, T R	8408270113	50-454 A
TRAMM, T. R	8408270118	50-454 A
TRAMM, T R	8408270204	50-454 E
TRAMM, T R	8408270218	50-454 F
TRAMM, T R.	8408270265	50-454 E
TRAMM, T R	8408270373	50-454 E
TRAMM, T. R	8408300053	50-454 K
TRAMM, T R	8408310163	50-454 A
TRAMM, T R.	8408310226	50-454 E
TRAMMELL, C M	8408170144	50-344 P
TRAVERS, W D	8408240394	50-320 R
TREAT, R L	8408310075	NUREG
TREBY, S. A.	8408210366	50-358 Q
TREBY, S A.	8408270179	50-445 Q
TREMBLAY, P P	8408090317	50-237 P
TRIMBLE, D C	8408240363*	50-317 Q
TRIMBLE, D. C	8408270486*	50-184 Q
TRINOSKEY, P A	8408020070*	50-133 P
TRIPP, L E.	8408080448*	50-334 Q
TRIPP, L E	8408150244*	50-277 Q
TROJOUSKY, M	8408240382	NUREG
TROSKOSKI, W M.	8408080448*	50-334 Q
TROSTEN, L M	8408020120	PR
TROTT, E A.	8408310368*	CONTRACT
TROTTIER, E	8408010157	MISC
TROWBRIDGE, G F.	8408090423	50-289 Q
TROWBRIDGE, G F	8408090423	50-289 Q
TROWBRIDGE, G F	8408140007	50-289 Q
TROWBRIDGE, G F	8408140007	50-289 Q
TROWBRIDGE, G F	8408170325	50-289 Q
TROWBRIDGE, G F	8408170325	50-289 Q
TROWBRIDGE, G. F	8408170330*	50-289 Q
TROWBRIDGE, G. F	8408170330*	50-289 Q
TUCKER, H. B.	8408030130	50-369 P
TUCKER, H. B.	8408060097	50-413 P
TUCKER, H. B.	8408060117	50-413 P
TUCKER, H. B.	8408070263	50-413 P
TUCKER, H B	8408070298	50-369 F
TUCKER, H B	8408070322	50-413 F
TUCKER, H B	8408070351	50-413 F
TUCKER, H B	8408070445	50-413 S
TUCKER, H B	8408070468	50-369 P
TUCKER, H B	8408070487	50-413 F
TUCKER, H B	8408080275	50-413 E
TUCKER, H B	8408090007	50-413 F
TUCKER, H B	8408090274	50-370 S
TUCKER, H B	8408090278	50-413 S
TUCKER, H B	8408130169	50-369 P
TUCKER, H B	8408140430	50-413 P
TUCKER, H B	8408150221	50-369 S
TUCKER, H B	8408150326	50-269 F
TUCKER, H B	8408160050	50-369 P
TUCKER, H B	8408160159	50-413 S
TUCKER, H B	8408160174	50-369 P
TUCKER, H B	8408160183	50-413 S
TUCKER, H B	8408160417	50-269 S
TUCKER, H B	8408160429	50-413 S
TUCKER, H B	8408160468	50-413 S
TUCKER, H B	8408160517	50-413 S
TUCKER, H B	8408170329	50-269 F
TUCKER, H B	8408200059	50-269 P
TUCKER, H B	8408200100	50-369 F
TUCKER, H B	8408200149	50-269 P
TUCKER, H B	8408210362	50-413 P
TUCKER, H B.	8408210365	50-413 P
TUCKER, H B	8408210396	50-369 P
TUCKER, H. B	8408220091	50-269 F
TUCKER, H B	8408220201	50-269 K
TUCKER, H B	8408220292	50-269 P
TUCKER, H B	8408220303	50-413 P
TUCKER, H B	8408220465	50-369 R
TUCKER, H B	8408220468	50-269 R
TUCKER, H B	8408230051	50-413 P
TUCKER, H B.	8408240224	50-413 I
TUCKER, H. B	8408270160	50-269 P
TUCKER, H B	8408270259*	50-369 Q
TUCKER, H B	8408270339	50-269 P
TUCKER, H B	8408270391	50-413 Q
TUCKER, H B	8408280230	50-369 Q
TUCKER, H B.	8408280234	50-369 Q
TUCKER, H B	8408280241	50-269 Q
TUCKER, H. B	8408280281	50-413 P
TUCKER, H B	8408280372	50-413 F
TUCKER, H B	8408280377*	50-413 F
TUCKER, H B	8408280389	50-369 S
TUCKER, H. B	8408280476*	50-269 Q
TUCKER, H B.	8408290094	50-370 S
TUCKER, H B	8408300014	50-269 F
TUCKER, H. B	8408300406	50-413 R
TUCKER, H B.	8408300497	50-287 S
TUCKER, H B	8408300501	50-413 S
TUCKER, H B	8408300509	50-370 R
TUCKER, H B	8408310121	50-269 F
TUCKER, M. K	8408030263	WASTE MGT
TUCKER, M. K	8408270250	WASTE MGT
TUCKMAN, M S	8408150335*	50-269 F
TULEY, C R	8408080284*	50-413 E
TURK, J.	8408060209	50-70 Q
TURK, S E	8408070299	50-382 Q
TURK, S E	8408130248	50-382 Q
TURK, S E	8408150081	50-382 Q
TURLEY, K.	8408200255	50-528 A
TURSKI, F. A	8408010263*	50-155 Q
UEHLEIN, J	8408080257	50-445 T
ULIE, J	8408060325*	50-382 Q
ULIE, J M	8408080181*	50-263 Q
ULLRICH, W T	8408270107	50-277 S
UMBEL, D.	8408060424	CONTRACT
UMBEL, D.	8408070101	CONTRACT
UMBEL, D.	8408080005	CONTRACT
UMBEL, D.	8408080052	CONTRACT
UMBEL, D	8408080317	CONTRACT
UMBEL, D	8408090041	CONTRACT
UMBEL, D	8408090115	CONTRACT
UPRIGHT, C. M	8408270221*	50-335 Q
UPRIGHT, C M	8408270492*	50-413 Q
UTLEY, E E.	8407260111	50-324 K
UTLEY, E E	8408140151*	50-400 T
VALIQUETTE, J C	8408060300	40-8722
VAN BRUNT, E E	8408010215	50-528 K
VAN BRUNT, E E.	8408010346	50-528 S
VAN BRUNT, E E.	8408010377	50-528 S
VAN BRUNT, E E	8408010391	50-528 S
VAN BRUNT, E E	8408010394	50-528 S
VAN BRUNT, E E	8408010398	50-528 S
VAN BRUNT, E E	8408020229	50-529 S
VAN BRUNT, E E	8408020232	50-528 S
VAN BRUNT, E E	8408030048	50-528 S
VAN BRUNT, E E	8408030053	50-528 S
VAN BRUNT, E E	8408030061	50-529 S
VAN BRUNT, E E	8408030097	50-528 F
VAN BRUNT, E E	8408030144	50-528 A
VAN BRUNT, E E	8408030240	50-528 S
VAN BRUNT, E E	8408030302	50-528 S
VAN BRUNT, E E	8408060075	50-528 K
VAN BRUNT, E E	8408060319	50-528 A
VAN BRUNT, E E	8408080348	50-528 A
VAN BRUNT, E E	8408080499	50-528 S
VAN BRUNT, E E	8408080529	50-528 S
VAN BRUNT, E E	8408090012	50-528 S
VAN BRUNT, E E	8408100127	50-528 A
VAN BRUNT, E E	8408130172	50-528 S
VAN BRUNT, E E	8408130274	50-528 A
VAN BRUNT, E E	8408130303	50-528 S
VAN BRUNT, E E	8408130332	50-528 S
VAN BRUNT, E E	8408130344	50-528 S
VAN BRUNT, E E	8408130351	50-528 E
VAN BRUNT, E E	8408130429	50-529 S
VAN BRUNT, E E	8408140227	50-528 A
VAN BRUNT, E E	8408150207	50-528 A
VAN BRUNT, E E	8408160192	50-528 S
VAN BRUNT, E E	8408160480	50-528 S
VAN BRUNT, E E	8408160506	50-528 S
VAN BRUNT, E E	8408170348	50-528 A
VAN BRUNT, E E	8408170384	50-528 S
VAN BRUNT, E E	8408200112	50-528 F
VAN BRUNT, E E	8408200217	50-528 F
VAN BRUNT, E E	8408200285	50-528 S
VAN BRUNT, E E	8408200297	50-528 S
VAN BRUNT, E E	8408200322	50-528 S
VAN BRUNT, E E	8408200599	50-528 F
VAN BRUNT, E E	8408220071*	50-528 Q
VAN BRUNT, E E	8408220128	50-528 S
VAN BRUNT, E E	8408220143	50-528 S
VAN BRUNT, E E	8408240261	50-528 A
VAN BRUNT, E E	8408240289	50-528 A
VAN BRUNT, E E	8408270133	50-528 E
VAN BRUNT, E E	8408270260	50-528 F
VAN BRUNT, E E	8408280204	50-528 S
VAN BRUNT, E E	8408280263	50-528 S
VAN BRUNT, E E	8408280275	50-528 S
VAN BRUNT, E E	8408280283	50-528 S
VAN BRUNT, E E	8408280297	50-528 S
VAN BRUNT, E E	8408280302	50-528 S
VAN BRUNT, E E	8408280317	50-528 S
VAN BRUNT, E E	8408280325	50-528 S
VAN BRUNT, E. E	8408280335	50-528 S
VAN BRUNT, E E	8408280357	50-528 S
VAN DENBERG, D	8408160255	50-255 R
VAN VLIET, J	8408080131	50-289 F
VAN VLIET, J	8408090199	50-289 F
VAN WAGNER, B V	8408310165*	50-255 Q
VANCE, J. N	8408080522	WASTE MGT
VANDEL, T E	8408150511*	50-461 Q
VANDENBURGH, D	8408130354*	50-29 Q
VANDER MOLEN, H	8408270265	NUREG
VANDEWALLE, D	8408130353	50-255 F
VANDEWALLE, D J	8408030109	50-155 P
VANDEWALLE, D J	8408030150	50-255 P
VANDEWALLE, D J	8408070431	50-255 P
VANDEWALLE, D J	8408090166	50-155 P
VANDEWALLE, D J	8408090171*	50-155 P
VANDEWALLE, D J	8408100134	50-255 P
VANDEWALLE, D J	8408240161	50-255 P
VANDEWALLE, D J	8408270281*	50-255 Q
VANDEWALLE, D J	8408270392*	50-155 Q
VANICHKO, B E	8408060231*	50-328 P
VANTERPOOL, E C	8408130410*	50-289 Q
VARELA, A A	8408150653*	50-354 G
VARELA, A A	8408160260*	50-322 Q
VARGA, S A	8407120020	50-247 P
VARGA, S A	8408010005	50-250 P
VARGA, S A	8408010109	50-250 F
VARGA, S A	8408010119	50-250 P
VARGA, S A	8408010218	50-334 P
VARGA, S A	8408060277	50-348 P
VARGA, S A	8408060422	50-305 F

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VARGA, S A	8408070065	50-272 F
VARGA, S A	8408070075	50-250 P
VARGA, S A	8408090515	50-334 P
VARGA, S A	8408090521	50-334 P
VARGA, S A	8408090530	50-247 P
VARGA, S A	8408130233	50-348 P
VARGA, S A	8408130554	50-334 P
VARGA, S A	8408160528	50-286 P
VARGA, S A	8408170041	50-334 F
VARGA, S A	8408170386	50-348 F
VARGA, S A	8408200387	50-280 F
VARGA, S A	8408210554	50-272 P
VARGA, S A	8408210564	50-250 P
VARGA, S A	8408210634	50-250 P
VARGA, S A	8408230073	50-261 F
VARGA, S A	8408250290	50-247 P
VARGA, S A	8408300512	50-261 F
VARGA, S A	8408310003	50-250 F
VARGA, S A	8408310136	50-247 P
VARGA, S A	8408310189	50-250 Q
VARGA, S A	8408310451	50-305 P
VASELIN, J	8408270545	40-8502
VASSALLO, D B	8407100322	50-259 Q
VASSALLO, D B	8408010018	50-298 P
VASSALLO, D B	8408030052	50-271 F
VASSALLO, D B	8408030080	50-333 P
VASSALLO, D B	8408030125*	50-296 P
VASSALLO, D B	8408030180	50-220 P
VASSALLO, D B	8408060157	50-293 P
VASSALLO, D B	8408070015	50-333 F
VASSALLO, D B	8408070016	50-324 P
VASSALLO, D B	8408070129	50-293 P
VASSALLO, D B	8408130032*	50-259 P
VASSALLO, D B	8408140026	50-259 P
VASSALLO, D B	8408150310	50-324 P
VASSALLO, D B	8408150513	50-263 P
VASSALLO, D B	8408150575	50-259 P
VASSALLO, D B	8408150578	50-271 P
VASSALLO, D B	8408150593*	50-254 P
VASSALLO, D B	8408150599	50-271 P
VASSALLO, D B	8408150604*	50-271 P
VASSALLO, D B	8408150613*	50-333 P
VASSALLO, D B	8408160046	50-324 F
VASSALLO, D B	8408160087	50-293 P
VASSALLO, D B	8408160090	50-271 P
VASSALLO, D B	8408160092	50-298 F
VASSALLO, D B	8408160137	50-331 P
VASSALLO, D B	8408160155	50-259 P
VASSALLO, D B	8408160426*	50-259 P
VASSALLO, D B	8408160465	50-254 P
VASSALLO, D B	84082002694	50-259 P
VASSALLO, D B	8408200390	50-260 P
VASSALLO, D B	84082003934	50-260 P
VASSALLO, D B	8408200423	50-263 P
VASSALLO, D B	8408200437	50-260 P
VASSALLO, D B	84082100044	50-259 P
VASSALLO, D B	8408210012*	50-325 P
VASSALLO, D B	84082802614	50-259 P
VASSALLO, D B.	84082902874	50-259 P
VASSALLO, D B	84082903244	50-263 P
VASSALLO, D B	8408310430*	50-293 P
VASSALLO, D B.	8408310431*	50-260 P
VASUKI, N C	8408100003	50-354 H
VAUGHAN, C M	8405300761	70-1113
VAUGHAN, C M	84053007624	70-1113
VAUGHAN, C M	84053007634	70-1113
VAUGHAN, C M	8408280111	70-1113
VERMA, T R	8408010070	WASTE MGT
VERNENGO, B	8408150001	GA999
VERNON, T M	8408230259	State Prog
VERRELLI, D M	8408030023	50-390 S
VERRELLI, D M	8408070405	50-390 Q
VERRELLI, D M.	8408130194	50-395 Q
VERRELLI, D M	84082002714	COMMISSION
VERRELLI, D M	8408230249	50-324 Q
VERRELLI, D M	8408240007	50-261 Q
VERRELLI, D M.	8408240091	50-261 Q
VERRELLI, D M	8408240338	50-259 Q
VERRELLI, D M	8408240360	50-390 Q
VERRELLI, D M	8408270168	50-395 Q
VERRELLI, D M	84082701784	50-395 Q
VERRELLI, D M	8408270196	50-259 Q
VERRELLI, D M	8408270232	50-438 Q
VERRELLI, D M	8408270417	50-390 Q
VERRELLI, D M	8408270426	50-324 Q
VERRELLI, D M	84082704354	50-324 Q
VERRELLI, D M	8408270460	50-438 Q
VERRELLI, D M	8408270463	50-390 Q
VERRELLI, D M	8408270561	50-395 Q
VERRELLI, D M	8408280026	50-400 Q
VERRELLI, D M	8408280027	50-261 Q
VERRELLI, D M	8408280030	50-390 Q
VERRELLI, D M	84082800394	50-261 Q
VERRELLI, D M	8408280038	50-400 Q
VERRELLI, D M	8408280096	50-259 Q
VERRELLI, D M	84082801244	50-259 Q
VERRELLI, D M	8408290021	50-261 Q
VERRELLI, D M	84082900344	50-261 Q
VERRELLI, D M	8408300316	50-327 F
VERRELLI, D M	8408300361	50-261 F
VERRELLI, D M	8408300459	50-327 Q
VERRELLI, D M	8408310051	50-261 F
VIETH, D L	8408200430	WASTE MGT
VIETH, D L	8408200435	WASTE MGT
VIETH, D L	8408210171	WASTE MGT
VIETH, D L	8408240354	WASTE MGT
VIETH, D L	8408310273	WASTE MGT
VIETTI, A	8408090445	50-445 A
VIETTI, A	8408090479	50-445 A
VILLA, R	8408310186	50-219 S
VINCELETTE, M D	8408280010	40-8675
VINCELETTE, M D	8408290216	40-8681
VINCELETTE, M D	8408290366	40-8681
VITO, D	84082103814	50-352 Q
VITO, D J	84080804614	50-220 Q
VITO, D J	84081604324	50-245 Q
VOGLER, B H	8408090197	50-352 Q
VOGLER, B H	8408090229	50-352 T
VOGLER, B H	84080902364	50-352 T
VOGLER, B H	8408090238	50-352 Q
VOGLER, B H	8408130310	50-275 M
VOGLER, B H	8408150425	50-352 Q
VOGLER, B H	8408210341	50-352 Q
VOGLER, B H	8408280415	50-352 Q
VOGLER, B H	8408280442	50-275 M
VOGLER, B H	8408300170	50-352 Q
VOGT, D K	8408240291	WASTE MANA
VOIGT, H H	84080704204	50-244 Q
VOIGT, H H	8408070420	50-244 Q
VOIGT, H H	8408200507	50-244 Q
VOIGT, H H	8408200507	50-244 Q
VOIT, R E	8408150733	71-9073
VOLGER, B H	8408150425	50-352 Q
VOLLMER, R.	84081500294	50-329 A
VOLLMER, R H	82012200494	50-329 A
VOLLMER, R H	84082703154	50-329 A
VORDERBRUEGGEN	84083001054	50-328 Q
WACHOB, H F	84081504764	50-322 T
WACHOB, H F	84081505054	50-322 T
WADDLE, J W	84082204004	CONTRACT
WADE, W O	84080805154	50-275 Q
WADE, W O	84080805174	50-275 Q
WADE, W O	84080805214	50-275 Q
WAGNER, A G	84082703474	50-416 Q
WAGNER, A W	84082002714	COMMISSION
WAGNER, D	8408080140	50-354 E
WAGNER, D	8408080149	50-354 E
WAGNER, D	8408130050	50-354 E
WAGNER, D.	84082004634	50-354 A
WAGNER, D H	8408010124	50-354 E
WAGNER, D. H	8408010126	50-354 E
WAGNER, D H	8408010212	50-354 A
WAGNER, D H	8408060204	50-354 E
WAGNER, D H	8408150170	50-354 A
WAGNER, D H	8408150173	50-354 E
WAGNER, D H	8408160487	50-354 E
WAGNER, D H	8408170403	50-354 E
WAGNER, D H	8408200151	50-354 F
WAGNER, D H	8408290513	50-354 A
WAGNER, D H	8408300101	50-354 A
WAGNER, H N	84082204484	50-320 P
WAGNER, H N	84082904484	50-320 P
WAGNER, M E	8408270176	50-289 Q
WAGNER, M C	84082701834	50-289 Q
WAGNER, W J	84083001494	50-275 Q
WAITE, R	84080900194	50-397 Q
WAITE, R S	84083004644	50-397 Q
WALDRUM, R L	84082400264	50-382 Q
WALKA, R M	8408210205	50-354 D
WALKA, R M	8408210326	50-354 D
WALKER, J B	8408030257	50-259 S
WALKER, J B	84081605084	50-259 S
WALKER, R D	8408010283	50-341 Q
WALKER, R D	8408060302	50-456 Q
WALKER, R D	84080603034	50-456 Q
WALKER, R D	8408070452	50-461 Q
WALKER, R D	8408140426	50-2 V
WALKER, R D	8408150502	50-461 Q
WALKER, R D	84081505074	50-461 Q
WALKER, R D	8408170090	50-255 V
WALKER, R D	8408170089	50-483 V
WALKER, R D	8408230132	50-263 V
WALKER, R D	8408230144	50-409 Q
WALKER, R D	8408230293	50-373 Q
WALKER, R D	8408230521	50-266 V
WALKER, R D	8408230526	50-282 V
WALKER, R D	8408280002	50-255 Q
WALKER, R D	84083000584	50-263 Q
WALKER, R D	8408300181	50-315 Q
WALKER, R D	8408300192	50-305 Q
WALKER, R D	8408310299	50-255 Q
WALKER, R L	8408300272	NUREG
WALKER, R S.	84082004544	50-352 U
WALLACE, J F	84081505054	50-322 T
WALLACE, J F	84081505304	50-322 T
WALLACE, P R	8408060241	50-327 S
WALLACE, P R	8408090156	50-327 S
WALLACE, P R	8408160269	50-328 S
WALLACE, P R	8408160453	50-327 S
WALLACE, P R	8408160493	50-327 S
WALLACE, P R	8408160522	50-327 S
WALLACE, P R	8408170053	50-328 S
WALLACE, P R	8408230509	50-327 S
WALLACE, P R	8408310050	50-327 S
WALSH, M	84080904264	50-445 Q
WALSH, M	84080904714	50-445 Q
WALSH, M	84080905034	50-445 Q
WALSH, M	8408160131*	50-445 Q
WALSH, M	84081601584	50-445 Q
WALSH, M	84081601874	50-445 Q
WALSH, M	84082801464	50-445 Q
WALTER, R J	84082803214	50-346 P
WAMBACH, P C	8408140449	50-219 Q
WAMBACH, T	84080603254	50-382 Q
WANG, C H	8408020081	PR
WANZEC, T	84082104534	50-329 A
WARD, K D	84081000404	50-454 T
WARD, S R	8408280205	50-413 T
WARD, W J	84080201944	50-329 Q
WAREMBOURG, D	8408010006	50-267 R
WAREMBOURG, D	8408020198	50-267 P
WAREMBOURG, D	8408070313	50-267 F
WAREMBOURG, D	8408080514	50-267 S
WAREMBOURG, D	8408150306	50-267 Q
WAREMBOURG, D	8408210428	50-267 Q
WAREMBOURG, D W	8408160207	50-267 Q
WAREMBOURG, D W	8408200559	50-267 P
WAREMBOURG, D W	8408290181	50-267 F
WAREMBOURG, D W	8408290264	50-267 F
WARNER, D L	8408020161	40-8027
WARNICK, R.	8408200324	50-483 S
WARNICK, R F	84061401014	50-456 Q
WARNICK, R F	84061401024	50-456 Q
WARNICK, R F	8408030071	50-329 Q
WARNICK, R F	8408030203	50-341 Q
WARNICK, R F	8408090293	50-440 Q
WARNICK, R F	84080902984	50-440 Q
WARNICK, R F	8408100112	50-456 Q
WARNICK, R F	84081303014	50-329 A
WARNICK, R F	84081303204	50-329 A
WARNICK, R F	84081303274	50-329 A
WARNICK, R F	84081505604	50-329 A
WARNICK, R F	84081506034	50-329 R
WARNICK, R F	84081506304	50-329 A
WARNICK, R F	84081506434	50-329 A
WARNICK, R F	84081506584	50-329 S
WARNICK, R F	84081506664	50-329 A
WARNICK, R F	84081506814	50-329 A
WARNICK, R F	84081506944	50-329 S
WARNICK, R F	84081507254	50-329 A
WARNICK, R F	84081702604	50-329 A
WARNICK, R F	84081702714	50-329 Q
WARNICK, R F	84081703604	50-329 A
WARNICK, R F	8408210342	50-456 Q
WARNICK, R F	8408230220	50-483 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WARNICK, R F	8408230474	50-358
WARNICK, R F	8408230502	50-329 G
WARNICK, R F	8408240136	50-329 G
WARNICK, R F	8408240314	50-461 G
WARNICK, R F	8408270239	50-329 A
WARNICK, R F	8408290549	50-456 G
WARNICK, R F	8408290553*	50-456 G
WASTLER, S L	8408240149	40-8380
WASTLER, S L	8408240154	40-8768
WASTLER, S L	8408270399	40-8829
WASTLER, S L	8408270197	40-8064
WASTLER, S L	8408270205	40-8728
WATERMAN, M E	8408160248	50-269 P
WATERS, D B	8408140036*	50-400 T
WATKINS, L B	8408010258	50-458 G
WATKINS, L B	8408010258	50-458 G
WATKINS, M	8408280165	50-445 G
WATKINS, M	8408280165	50-445 G
WATLINGTON, B E	8408080472	NUREG
WATSON, R A	8408020012	50-400 A
WATSON, R A	8408140151*	50-400 T
WATTS, R J	8408020048	50-322 T
WEAVER, K T	8408130108*	50-454 G
WEAVER, W J	8408270206*	50-266 F
WEBER, M F	8408200409	WASTE MGT
WECHSELBERGER	8408280293*	50-219 G
WECHSELBERGER	8408300096*	50-219 G
WEDDINGTON, R E	8408280485*	50-269 G
WEGST, W F	8408010339	50-142 P
WEGST, W F	8408150141	71-522
WEGST, W F	8408210359	PR
WEGST, W F	8408310141	PR
WEIGAND, J G	8408160457*	50-458 G
WEIKAM, E J	8408070208	50-458 E
WEIL, C H	8408020190*	50-329 G
WEIL, C H	8408020194*	50-329 G
WEINKAM, E J	8408060412	50-458 G
WEINKAM, E J	8408080249	50-458 E
WEISE, S	8408270536*	50-261 G
WEISE, S	8408280267	50-327 S
WEISS, A J	8408010179	NUREG
WEISS, D	8408020209*	70-36
WEISS, D	8408170393*	70-143
WEISS, D	8408170394*	70-143
WEISS, E R	8408020040	50-289 G
WEISS, E R	8408140474	50-289 G
WEISS, E R	8408140474	50-289 G
WEISS, E R	8408150145	50-289 G
WEISS, E R	8408170335	50-289 G
WEISS, E R	8408220362	50-289 G
WEISS, E R	8408220362	50-289 G
WEISS, E R	8408240245	50-289 G
WEISS, E R	8408240245	50-289 G
WEISS, E R	8408270359	50-289 G
WEISS, E R	8408270359	50-289 G
WEISS, E R	8408280493	50-289 G
WEISS, E R	8408280493	50-289 G
WELLS, B L	8408010342*	50-335 H
WELLS, C A	8408280205	50-413 T
WELLS, C H	8408150476*	50-322 T
WELLS, C H	8408150505*	50-322 T
WELLS, C H	8408150530*	50-322 T
WELLS, R A	8408150738*	50-329 A
WELLS, R A	8408150749*	50-329 A
WELLS, R A	8408270330*	50-329 G
WELLS, R W	8408130349	TOPREP
WELLS, R W	8408130349	TOPREP
WELLS, R W	8408160409	TOPREP
WELLS, R W	8408160409	TOPREP
WEN, P	8408080490*	50-289 G
WEN, P	8408090330*	50-322 G
WEN, P C	8408080256*	50-289 G
WEN, P C	8408130410*	50-289 G
WENGER, N N	8408230440*	50-289 H
WENSLAWSKI, F	8408060123	50-312 S
WENSLAWSKI, F	8408060156	50-312 S
WENSLAWSKI, F	8408070416	50-312 S
WENSLAWSKI, F A	8408080147	70-734
WENSLAWSKI, F A	8408090001	50-361 G
WENSLAWSKI, F A	8408090017	50-344 G
WENSLAWSKI, F A	8408090075	50-344 G
WENSLAWSKI, F A	8408090086	50-312 G
WENSLAWSKI, F A	8408090120	70-984
WENSLAWSKI, F A	8408130091	50-493 G
WENSLAWSKI, F A	8408130318	50-344 G
WENZINGER, C	8408160082*	50-29 G
WENZINGER, F	8408270410*	50-309 G
WENZINGER, E	8408270579*	50-29 G
WENZINGER, E C	8408240363*	50-317 G
WESCOTT, H M	8408150262*	50-443 G
WEST, D	8408030235	50-335 S
WESTAFER, G R	8408020010	50-302 P
WESTAFER, G R	8408060199	50-302 P
WESTAFER, G R	8408060306	50-302 S
WESTAFER, G R	8408080189	50-302 S
WESTAFER, G R	8408160238	50-302 S
WESTAFER, G R	8408160247	50-302 S
WESTAFER, G R	8408160410	50-302 S
WESTAFER, G R	8408160526	50-302 R
WESTAFER, G R	8408200278	50-302 P
WESTAFER, G R	8408200311	50-302 F
WESTAFER, G R	8408200330	50-302 P
WESTAFER, G R	8408200346	50-302 S
WESTAFER, G R	8408230424	50-302 S
WESTAFER, G R	8408230430	50-302 S
WESTAFER, G R	8408280069*	50-302 G
WESTAFER, G R	8408280154	50-302 P
WESTAFER, G R	8408280170	50-302 G
WESTAFER, G R	8408300341	50-302 S
WESTHALL, M	8408200446	50-454 T
WESTSIK, J H	8408310075	NUREG
WETHY, C M	8408020123	50-389 F
WETHY, C M	8408280097	50-335 F
WETTERHAHN, M J	8408060228	50-352 G
WETTERHAHN, M J	8408060228	50-352 G
WETTERHAHN, M J	8408070366	50-352 G
WETTERHAHN, M J	8408070372	50-352 G
WETTERHAHN, M J	8408070372	50-352 G
WETTERHAHN, M J	8408070429	50-352 G
WETTERHAHN, M J	8408070429	50-352 G
WETTERHAHN, M J	8408070461	50-358 G
WETTERHAHN, M J	8408070461	50-358 G
WETTERHAHN, M J	8408080404	50-352 G
WETTERHAHN, M J	8408080404	50-352 G
WETTERHAHN, M J	8408150387	50-352 G
WETTERHAHN, M J	8408150387	50-352 G
WETTERHAHN, M J	8408240254	50-352 T
WETTERHAHN, M J	8408240254	50-352 T
WETTERHAHN, M J	8408310223	50-352 G
WETTERHAHN, M J	8408310223	50-352 G
WHATLEY, S K	8408310265	WASTE MANA
WHEADON, W C	8408160466*	70-1308
WHEELER, J T	8408070104*	CONTRACT
WHEELER, L J	8408030025*	50-327 P
WHICHER, J M	8406260276	50-454 G
WHICHER, J M	8406260276	50-454 G
WHICHER, J M	8408280194	50-367 G
WHICHER, J M	8408280194	50-367 G
WHICHER, J M	8408310201	50-454 G
WHITE, J D	8408230043*	WASTE MGT
WHITE, J R	8408200023*	50-289 G
WHITE, J R	8408230569*	50-293 G
WHITE, M	8408080038*	COMMISSION
WHITENER, H L	8408270338*	50-321 G
WHITMAN, D	8408070267	50-298 F
WHITMAN, J H	8408240336	40-6659
WHITMAN, R	8408080257	50-445 T
WHITMORE, H L	8408160146	NUREG
WHITTEMORE, J	8408310302*	50-255 G
WHITTIER, G D	8408030008	50-309 F
WHITTIER, G D	8408030272	50-309 S
WHITTIER, G D	8408070367	50-309 P
WHITTIER, G D	8408090173	50-309 P
WHITTIER, G D	8408280210	50-309 F
WHITTIER, G D	8408280227	50-309 P
WICK, E A	8408060178	WASTE MGT
WICK, E A	8408240335	WASTE MGT
WICK, E A	8408240392	WASTE MGT
WICKETT, A J	8408130006	NUREG
WIDMAN, J C	8408150359	XPORTLIC
WIDMAN, J C	8408150361*	XPORTLIC
WIEDEMAN, D	8408020052	I&E
WIEDEMAN, D G	8408070329	I&E
WIEDER, A V	8408270346*	70-734
WIESEMANN, R A	8407230203*	TOPREP
WIESEMANN, R A	8408060125*	TOPREP
WIESEMANN, R A	8408070257*	50-244 P
WIESEMANN, R A	8408070465*	50-498 A
WIESEMANN, R A	8408080280*	50-413 E
WIESEMANN, R A	8408080286*	50-601 K
WIESEMANN, R A	8408160373*	50-443 A
WIESEMANN, R A	8408220321*	50-454 E
WIESEMANN, R A	8408230346*	TOPREP
WIESEMANN, R A	8408270246*	50-266 P
WIGGINS, E	8408090072	CONTRACT
WIGGINS, E	8408140510	CONTRACT
WIGGINS, J T	8408210381*	50-352 G
WIGGINTON, D L	8408010310	50-315 P
WIGGINTON, D L	8408020116	REVIEW GRP
WIGGINTON, D L	8408160425	50-315 P
WILBER, H A	8408090178	50-382 G
WILBORN, L	8408090157	40-8769
WILBUR, L G	8408070345	PR
WILCOVE, M N	8408020185*	50-329 G
WILCOVE, M N	8408020189*	50-329 G
WILCOVE, M N	8408090164	50-454 G
WILCOVE, M N	8408150119	50-454 T
WILCOVE, M N	8408150676*	50-329 A
WILCOVE, M N	8408150723*	50-329 A
WILHITE, M	8408300093	50-295 S
WILKINSON, R	8408090162	50-294 V
WILKS, B L	8408210290	50-387 S
WILKS, B L	8408240065	50-387 S
WILLETT, D J	8408090019*	50-397 G
WILLIAMS, C C	8408090217*	50-454 G
WILLIAMS, C C	8408150293*	50-255 G
WILLIAMS, C C	8408170181*	50-329 G
WILLIAMS, C C	8408200227*	50-454 G
WILLIAMS, C C	8408230144*	50-341 G
WILLIAMS, C C	8408270277*	50-454 G
WILLIAMS, C C	8408300121*	50-456 G
WILLIAMS, C C	8408300194*	50-440 G
WILLIAMS, C C	8408300220*	50-341 G
WILLIAMS, D	8408230252*	50-454 G
WILLIAMS, D L	8408160193*	50-483 G
WILLIAMS, G	8408160169	50-263 F
WILLIAMS, J H	8408150244*	50-277 G
WILLIAMS, J W	8407260218	50-250 K
WILLIAMS, J W	8408010311	50-251 S
WILLIAMS, J W	8408030164	50-335 P
WILLIAMS, J W	8408030235	50-335 S
WILLIAMS, J W	8408030239	50-250 S
WILLIAMS, J W	8408080230	50-250 S
WILLIAMS, J W	8408090009	50-335 F
WILLIAMS, J W	8408090096	50-389 P
WILLIAMS, J W	8408090243	50-335 P
WILLIAMS, J W	8408100016	50-250 F
WILLIAMS, J W	8408130215	50-335 F
WILLIAMS, J W	8408160521	50-250 S
WILLIAMS, J W	8408170054	50-389 P
WILLIAMS, J W	8408170084	50-250 P
WILLIAMS, J W	8408170233	50-335 G
WILLIAMS, J W	8408200143	50-389 P
WILLIAMS, J W	8408200200	50-389 P
WILLIAMS, J W	8408200273	50-250 S
WILLIAMS, J W	8408230155*	50-251 G
WILLIAMS, J W	8408270015	50-250 P
WILLIAMS, J W	8408270019	50-250 P
WILLIAMS, J W	8408270200*	50-335 G
WILLIAMS, J W	8408270203	50-250 S
WILLIAMS, J W	8408270298*	50-335 G
WILLIAMS, J W	8408270316*	50-250 G
WILLIAMS, J W	8408270344	50-250 P
WILLIAMS, J W	8408270384	50-250 G
WILLIAMS, J W	8408280058	50-335 G
WILLIAMS, J W	8408280106	50-389 G
WILLIAMS, J W	8408280182	50-335 G
WILLIAMS, J W	8408280236	50-335 G
WILLIAMS, J W	8408280238	50-250 P
WILLIAMS, J W	8408310133	50-250 F
WILLIAMS, J W	8408310145	50-389 P
WILLIAMS, L A	8408060426*	CONTRACT
WILLIAMS, R E	8408280121	WASTE MANA
WILLIAMS, R J	8408160384*	TOPREP
WILLIAMS, W R	8408130007	NUREG
WILLIAMSON, E L	8408020068*	50-413 G
WILLIS, J L	8408140151*	50-400 T
WILLSEY, W B	8408130361	50-277 P
WILLSEY, W B	8408210546	50-171 R
WILSON, B	8408240313	50-327 S
WILSON, B D	8408230468	XPORTLIC
WILSON, B D	8408230513	XPORTLIC
WILSON, J	8408230334	50-382 A
WILSON, J H	8408130091	NUREG
WILSON, K R	8408160238	50-302 S

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WILSON, R F	8408280178	50-289 P
WILSON, V H	8408210336*	50-329 A
WILSON, V H	8408210392*	50-329 A
WILSON, V H	8408210397*	50-329 A
WILSON, V H	8408210401*	50-329 A
WILSON, W E	8408020085	PR
WILTERDING, D J	8408220388*	50-445 T
WILTERDING, D T	8408220388*	50-445 T
WINDHAM, R	8408070267	50-298 F
WISE, C L	8408140482	50-440 G
WISE, R	8408160515*	50-458 G
WISEMAN, G R	8408270371*	50-413 G
WISEMAN, G R	8408280028*	50-400 G
WITHERS, B D	8408010281*	50-344 G
WITHERS, B D	8408020057	50-344 P
WITHERS, B D	8408070447	50-344 P
WITHERS, B D	8408080316	50-344 P
WITHERS, B D	8408090158	50-344 P
WITHERS, B D	8408090237	50-344 P
WITHERS, B D	8408130414	50-344 F
WITHERS, B D	8408140202	50-344 P
WITHERS, B D	8408140289	50-344 P
WITHERS, B D	8408210139	50-344 P
WITHERS, B D	8408210415	50-344 F
WITHERS, B D	8408210438	50-344 P
WITHERS, B D	8408280242	50-344 P
WITTENBURG, K C	8408060283	50-374 S
WOCKENFUSS, W A	8408300079	50-166 P
WOHLD, P R	8408160193*	50-483 G
WOJTULEWICZ, T.	8408130146	50-249 S
WOJTULEWICZ, T	8408130330	50-237 S
WOLF, J F	8408170291	50-320 G
WOLF, T	8408070242*	TOPREP
WOLF, T R	8408070236	TOPREP
WOLFE, J F	8408030078	50-320 G
WOLFE, S J	8408150139	50-289 G
WOLFE, S J	8408310148	50-338 G
WOLLETT, S	8408010041	CONTRACT
WOLLETT, S	8408070047	CONTRACT
WOLLETT, S	8408080502	CONTRACT
WOLLETT, S	8408090135	CONTRACT
WOLLETT, S	8408090548	CONTRACT
WOLLETT, S	8408140510	CONTRACT
WOLLETT, S	8408270557	CONTRACT
WOLTNER, E	8408150580*	50-29 G
WOLTNER, E	8408270465*	50-271 G
WONG, C C	8408310089	NUREG
WONG, H J	8408170117*	50-443 G
WOO, H W	8408220370	NUREG
WOOD, J M	8408290005	50-354 D
WOODARD, C	8408090330*	50-322 G
WOODARD, C H	8408150110*	50-336 G
WOODARD, J D	8408230515	50-348 S
WOODHEAD, C P	8408010207	50-142 G
WOODHEAD, C P	8408070498	50-440 G
WOODHEAD, C P	8408270057	50-440 G
WOODS, J	8408090326	50-304 S
WOODWARD, C H	8408160246*	50-245 G
WOODWARD, J D	8408200611	50-348 R
WOOLEVER, E J	8408010154	50-412 F
WOOLEVER, E J	8408020011	50-412 E
WOOLEVER, E J	8408020019	50-412 E
WOOLEVER, E J	8408060259	50-412 S
WOOLEVER, E J	8408070355*	50-412 G
WOOLEVER, E J	8408070414	50-412 F
WOOLEVER, E J	8408070432	50-412 E
WOOLEVER, E J	8408130005	50-412 E
WOOLEVER, E J	8408130312	50-412 E
WOOLEVER, E J	8408140088	50-412 E
WOOLEVER, E J	8408140127	50-412 E
VER, E J	8408150199	50-412 E
VER, E J	8408160333	50-412 E
VER, E J	8408160399	50-412 E
/ER, E J	8408210437	50-412 A
F /ER E J	8408210476	50-412 B
	8408230246	50-412 A
	8408230329	50-412 E
	8408240275	50-412 G
	8408270071	50-412 P
	8408270141	50-412 E
	8408270165	50-412 E
	8408280200	50-412 E
		E
		A
		F
WRAY, J R	8408270317*	50-335 G
WRAY, J R	8408270386*	50-369 G
WRAY, J R	8408270423*	70-143
WRAY, J R	8408270447*	50-369 G
WRIGHT, C L	8408060315	50-261 S
WRIGHT, C L	8408170188	50-261 S
WRIGHT, D R	8408220385*	50-445 T
WRIGHT, D R	8408220395*	50-445 T
WRIGHT, G	8408100109	50-295 S
WRIGHT, G	8408200308	50-255 S
WRIGHT, G	8408210269	50-315 S
WRIGHT, G C	8408090177*	50-295 G
WRIGHT, G C	8408230211*	50-315 G
WRIGHT, G C	8408240088*	50-255 G
WRIGHT, N A	8408070302	50-352 G
WRIGHT, N A	8408150425	50-352 G
WRIGHT, N A	8408280415	50-352 G
WRIGHT, N A	8408300119	50-352 G
WRIGHT, R J	8408010123	WASTE MGT
WRIGHT, R J	8408030279	WASTE MGT
WRIGHT, R J	8408060242	WASTE MGT
WRIGHT, R J	8408060295	WASTE MGT
WRIGHT, R J	8408130144	WASTE MGT
WRIGHT, R J	8408200404	WASTE MGT
WRIGHT, R J	8408200444	WASTE MGT
WRIGHT, T W	8408010181	50-454 G
WRIGHT, T W	8408010181	50-454 G
WRIGHT, T W	8408170382	50-454 G
WU, R R	8408230196*	70-1450
WUNDERLICH, R C	8408030283	WASTE MGT
WYANT, F J	8408080367	NUREG
WYNGARDEN, S D	8408290351	70-143
YANDELL, L A	8408060313*	50-285 G
YANDELL, L A	8408270500*	50-298 G
YANG, M S	8408130420*	50-454 G
YEH, N	8408160390*	50-458 A
YEN, T C	8408130455*	50-445 A
YIN, I T	8408020131*	50-275 G
YIN, I T	8408020134*	50-275 G
YIN, I T	8408160341*	50-341 G
YORK, J W	8408270469*	50-390 G
YOUNG, C	8408080087*	50-320 H
YOUNG, C	8408090220	50-320 H
YOUNG, F	8408150271*	50-289 G
YOUNG, G G	8408010188*	50-329 D
YOUNG, G G	8408010191*	50-329 D
YOUNG, M A	8408010213	50-250 G
YOUNG, M A	8408070305	50-250 G
YOUNG, M A	8408070477	50-414 G
YOUNG, M A	8408150133	50-244 G
YOUNG, T	8408080501*	50-275 G
YOUNG, T	8408080513*	50-275 G
YOUNG, T	8408300100*	50-528 G
YOUNG, T	8408300105*	50-528 G
YOUNG, T	8408300114*	50-312 G
YOUNG, T	8408300133*	50-312 G
YOUNGBLOOD, B J	8408010078	50-445 A
YOUNGBLOOD, B J	8408010082	50-483 P
YOUNGBLOOD, B J	8408010098	50-445 G
YOUNGBLOOD, B J	8408010099	50-387 P
YOUNGBLOOD, B J	8408010112	50-445 A
YOUNGBLOOD, B J	8408010116	50-454 A
YOUNGBLOOD, B J	8408010129	50-423 D
YOUNGBLOOD, B J	8408010131*	50-423 D
YOUNGBLOOD, B J	8408010197	50-423 D
YOUNGBLOOD, B J	8408010252	50-423 D
YOUNGBLOOD, B J	8408020140	50-423 D
YOUNGBLOOD, B J	8408060240*	50-482 A
YOUNGBLOOD, B J	8408060399	50-482 A
YOUNGBLOOD, B J	8408070028	50-482 A
YOUNGBLOOD, B J	8408070034	50-454 A
YOUNGBLOOD, B J	8408070137	50-440 A
YOUNGBLOOD, B J	8408130181	50-445 B
YOUNGBLOOD, B J	8408130267	50-445 F
YOUNGBLOOD, B J	8408130449	50-445 A
YOUNGBLOOD, B J	8408130492	50-440 A
YOUNGBLOOD, B J	8408150326	50-423 E
YOUNGBLOOD, B J	8408160067	50-483 P
YOUNGBLOOD, B J	8408170138	50-445 E
YOUNGBLOOD, B J	8408200469	50-423 E
YOUNGBLOOD, B J	8408200471*	50-423 E
YOUNGBLOOD, B J	8408200533	50-423 A
YOUNGBLOOD, B J	8408210158	50-445 F
YOUNGBLOOD, B J	8408240222	50-423 A
YOUNGBLOOD, B J	8408280301	50-454 E
YOUNGBLOOD, B J	8408280342	50-445 A
YOUNGBLOOD, B J	8408280461	50-445 A
YOUNGBLOOD, B J	8408290365	50-454 A
YOUNGBLOOD, B J	8408300017	50-423 A
YOUNGBLOOD, B J	8408300230	50-456 A
YOUNGBLOOD, B J	8408310171	50-440 F
YOUNGLING, E J	8408150498*	50-322 T
YOUNGLING, E J	8408150505*	50-322 T
YOUNGLING, E J	8408150514*	50-322 T
YOUNGLING, E J	8408150530*	50-322 T
YUHAS, G	8408060123	50-312 S
YUHAS, G	8408060136	50-312 S
YUHAS, G	8408090004*	50-361 G
YUHAS, G	8408090091*	50-312 G
YUHAS, G P	8408090021*	50-344 G
YUHAS, G P	8408090080*	50-344 G
YUHAS, G P	8408230087*	50-312 G
YUNDT, C P	8408090060	50-344 S
YUNDT, C P	8408280149	50-344 S
ZAHNLEUTER, R J	8408020200	50-322 G
ZAHNLEUTER, R J	8408080410	50-322 G
ZAHNLEUTER, R J	8408130162	50-322 G
ZAHNLEUTER, R J	8408130264	50-322 G
ZAHNLEUTER, R J	8408130284	50-322 G
ZAHNLEUTER, R J	8408140138	50-322 G
ZAHNLEUTER, R J	8408160210	50-322 G
ZALIZNYAK, M	8408170339*	50-354 G
ZALIZNYAK, M A	8408170342*	50-354 G
ZECH, G G	8408060043	GA999
ZECH, G G	8408060089	GA999
ZECH, G G	8408060131	GA999
ZECH, G G	8408070387	GA999
ZECH, G G	8408080046	GA999
ZECH, G G	8408080050	GA999
ZECH, G G	8408080114	GA999
ZECH, G G	8408080130	GA999
ZECH, G G	8408080282	GA999
ZECH, G G	8408080306	GA999
ZECH, G G	8408080308	GA999
ZECH, G G	8408080311	GA999
ZECH, G G	8408080336	GA999
ZECH, G G	8408080341	GA999
ZECH, G G	8408090006	GA999
ZECH, G G	8408090063	GA999
ZECH, G G	8408090174	GA999
ZECH, G G	8408090181	GA999
ZECH, G G	8408090190	GA999
ZECH, G G	8408100128	GA999
ZECH, G G	8408140290	GA999
ZECH, G G	8408140298	GA999
ZECH, G G	8408170024	GA999
ZECH, G G	8408170057	GA999
ZECH, G G	8408170105	GA999
ZECH, G G	8408200196	50-400 S
ZECH, G G	8408200315	GA999
ZECH, G G	8408200351	GA999
ZECH, G G	8408210390	GA999
ZECH, G G	8408210399	50-400 S
ZECH, G G	8408220320	GA999
ZECH, G G	8408220360	GA999
ZECH, G G	8408220383	GA999
ZECH, G G	8408240013	50-352 G
ZECH, G G	8408240125	GA999
ZECH, G.G	8408270353	GA999
ZECH, G G	8408280120	GA999
ZECH, G G	8408280215	50-390 G
ZECH, G G	8408290201	GA999
ZECH, G G	8408290315	GA999
ZECH, L W	8408230202	50-275 G
ZECH, L W	8408280427	50-289 G
ZEFF, D W	8408280270*	70-1201
ZEFF, D W	8408280277*	70-1201
ZEUGIN, L B	8408130347	50-322 G
ZEUGIN, L B	8408130347	50-322 G
ZIBULSKY, H	8408080209*	50-220 G
ZIBULSKY, H	8408200023*	50-289 G
ZIBULSKY, H	8408270473*	50-333 G
ZIMMERMAN, J V	8405160242	XPORTLIC
ZIMMERMAN, J V	8408010136	XPORTLIC
ZIMMERMAN, J V	8408060054	XPORTLIC
ZIMMERMAN, J V	8408060435	XPORTLIC
ZIMMERMAN, J V	8408070175	XPORTLIC
ZIMMERMAN, J V	8408070181	XPORTLIC
ZIMMERMAN, J V	8408070202	XPORTLIC
ZIMMERMAN, J V	8408070206	XPORTLIC

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
ZIMMERMAN, J V	8408070209	XPORTLIC	
ZIMMERMAN, J V	8408070214	XPORTLIC	
ZIMMERMAN, J V	8408070506	XPORTLIC	
ZIMMERMAN, J V	8408070510	XPORTLIC	
ZIMMERMAN, J V	8408070512	XPORTLIC	
ZIMMERMAN, J V	8408080108	XPORTLIC	
ZIMMERMAN, J V	8408080118	XPORTLIC	
ZIMMERMAN, J V	8408080534	XPORTLIC	
ZIMMERMAN, J V	8408150112	XPORTLIC	
ZIMMERMAN, J V	8408150163	XPORTLIC	
ZIMMERMAN, J V	8408150166	XPORTLIC	
ZIMMERMAN, J V	8408150169	XPORTLIC	
ZIMMERMAN, J V	8408150246	XPORTLIC	
ZIMMERMAN, J V	8408150270	XPORTLIC	
ZIMMERMAN, J V	8408150708	XPORTLIC	
ZIMMERMAN, J V	8408150713	XPORTLIC	
ZIMMERMAN, J V	8408150717	XPORTLIC	
ZIMMERMAN, J V	8408170405	XPORTLIC	
ZIMMERMAN, J V	8408170411	XPORTLIC	
ZIMMERMAN, J V	8408170423	XPORTLIC	
ZIMMERMAN, J V	8408200150	XPORTLIC	
ZIMMERMAN, J V	8408200160	XPORTLIC	
ZIMMERMAN, J V	8408200189	XPORTLIC	
ZIMMERMAN, J V	8408200450	XPORTLIC	
ZIMMERMAN, J V	8408200485	XPORTLIC	
ZIMMERMAN, J V	8408200596	XPORTLIC	
ZIMMERMAN, J V	8408220420	XPORTLIC	
ZIMMERMAN, J V	8408220421	XPORTLIC	
ZIMMERMAN, J V	8408220422	XPORTLIC	
ZIMMERMAN, J V	8408220430	XPORTLIC	
ZIMMERMAN, J V	8408230516	XPORTLIC	
ZIMMERMAN, J V	8408230519	XPORTLIC	
ZIMMERMAN, J V	8408230525	XPORTLIC	
ZIMMERMAN, J V	8408230530	XPORTLIC	
ZIMMERMAN, J V	8408230535	XPORTLIC	
ZIMMERMAN, J V	8408230560	XPORTLIC	
ZIMMERMAN, J V	8408310001	XPORTLIC	
ZIMMERMAN, J V	8408310006	XPORTLIC	
ZIMMERMAN, J V	8408310019	XPORTLIC	
ZIMMERMAN, J V	8408310178	XPORTLIC	
ZIMMERMAN, J V	8408310317	XPORTLIC	
ZIMMERMAN, J V	8408310330	XPORTLIC	
ZIMMERMAN, J V	8408310341	XPORTLIC	
ZIMMERMAN, R	8408300195*	50-528	Q
ZIMMERMAN, S R	8408060074	50-261	P
ZIMMERMAN, S R	8408060192	50-400	A
ZIMMERMAN, S R	8408070407	PR	
ZIMMERMAN, S R	8408080271	50-400	A
ZIMMERMAN, S R	8408080276	50-324	P
ZIMMERMAN, S R	8408080285	50-400	F
ZIMMERMAN, S R	8408080332	50-261	P
ZIMMERMAN, S R	8408080337	50-400	E
ZIMMERMAN, S R	8408090509	50-400	K
ZIMMERMAN, S R	8408140356	50-261	P
ZIMMERMAN, S R	8408230221	50-324	P
ZIMMERMAN, S R	8408280199	50-261	P
ZIMMERMAN, S R	8408280207	50-400	A
ZIMMERMAN, S R	8408290011	50-261	P
ZIMMERMAN, S R	8408300243	50-400	Q
ZUKOR, D J	8408010206*	50-329	O
ZUKOR, D J	8408310269	50-344	S
ZUPKO, J M	8408090076	50-311	S
ZUPKO, J M	84081305BB	50-311	S
ZUPKO, J M	8408160276	50-272	S
ZUPKO, J M	8408200276	50-311	R
ZUPKO, J M	8408300349	50-311	S
ZUPKO, J M	8408300400	50-311	S
ZUPKO, J W	8408230501	50-272	S
ZURAKOWSKI, P R	8408080151*	70-734	
ZURAKOWSKI, P R	8408130511*	70-1257	
ZUTOVSKY, L E	8408290349*	CONTRACT	
ZWAHR, J E	8408220388*	50-445	T
ZWAHR, J E	8408220388*	50-445	T

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
ACE Federal Reporters, Inc	8408270503*	CONTRACT
	8408270508*	CONTRACT
Aerojet Energy Conversion Co (subs of General Tire & Rubber Co)	8408100121	TOPREP
	8408140200	TOPREP
	8408140204*	TOPREP
Agriculture, Dept of	8408160486	50-354 D
	8408230189	50-423 D
	8408230412	50-458 D
Agriculture, Dept of, Research Center Air and Water Pollution Patrol	8408230024	50-410 D
	8408010233	50-352 Q
	8408140450	50-352 Q
	8408140450	50-352 Q
	8408140452*	50-352 Q
	8408140452*	50-352 Q
	8408200433	50-352 Q
	8408200442*	50-352 Q
	8408200447*	50-352 Q
	8408220354	50-352 Q
	8408240240	50-352 Q
Alabama Electric Cooperative, Inc	8408080197	50-348 M
	8408080197	50-348 M
	8408080202	50-348 M
	8408080202	50-348 M
	8408080241	50-348 M
	8408080241	50-348 M
Alabama Power Co	8408060070	50-348 F
	8408060070	50-348 F
	8408070314	50-348 V
	8408070469	50-348 F
	8408070469	50-348 F
	8408100036	50-348 P
	8408130345	50-364 Q
	8408130374	50-348 F
	8408130374	50-348 F
	8408200611	50-348 R
	8408210412	50-364 P
	8408210417	50-364 F
	8408230326	50-348 F
	8408230326	50-348 F
	8408230398	50-348 P
	8408230398	50-348 P
	8408230399*	50-348 P
	8408230399*	50-348 P
	8408230515	50-348 S
	8408280048	50-348 Q
	8408280176	50-348 Q
	8408300169	50-348 Q
Alaska, State of	8408240026*	50-382 Q
Alden Research Laboratory	8408270147*	50-412 E
Allied Chemical Corp	8408130240	40-3392
	8408130273	40-3392
	8408170395	40-3392
American Insulated Wire Corp	8408090002	QA999
American Nuclear Corp	8408270361	40-4492
	8408310338	40-4492
American Nuclear Society	8408070346	PR
American Society of Mechanical Engineers	8408080297	NUREG
	8408280126*	QA999
	8408280139*	QA999
American Society of Quality Control	8408080255	NUREG
American Society of Utility Investors	8408290265	50-289 T
	8408290269*	50-289 T
American Statistical Association	8408080008*	CONTRACT
Amersham Corp	8408080532	XPORTLIC
Ametek, Inc	8408030175	QA999
Anaconda Co (subs of Atlantic Richfield Co)	8408200288*	50-528 S
Anaheim, CA	8408090194*	50-361 P
Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc)	8408070094	QA999
Anefco, Inc	8408170070	71-9192
	8408170204	71-9192
Ann Riley & Associates	8408200446	50-454 T
Anthony, R L	8408080191	50-352 Q
	8408070263*	50-352 Q
	8408280491	50-352 Q
	8408310096	50-352 Q
Argonne National Laboratory	8408020236	WASTE MGT
	8408020239*	WASTE MGT
	8408080374	NUREG
	8408100151	NUREG
	8408170152*	50-329 Q
	8408170157*	50-329 Q
	8408240382	NUREG
	8408310077	NUREG
	8408310083	NUREG
Arizona Public Service Co	8408010215	50-528 K
	8408010215	50-528 K
	8408010215	50-528 K
	8408010346	50-528 S
	8408010346	50-528 S
	8408010346	50-528 S
	8408010377	50-528 S
	8408010377	50-528 S
	8408010377	50-528 S
	8408010381	50-528 S
	8408010381	50-528 S
	8408010381	50-528 S
	8408010384	50-528 S
	8408010384	50-528 S
	8408010384	50-528 S
	8408010388	50-528 S
	8408010388	50-528 S
	8408010388	50-528 S
	8408020229	50-529 S
	8408020232	50-528 S
	8408020232	50-528 S
	8408020232	50-528 S
	8408030048	50-528 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408030053	50-528 S
	8408030053	50-528 S
	8408030053	50-528 S
	8408030061	50-529 S
	8408030061	10-529 S
	8408030097	50-528 F
	8408030097	50-528 F
	8408030097	50-528 F
	8408030144	50-528 A
	8408030144	50-528 A
	8408030144	50-528 A
	8408030240	50-528 S
	8408030240	50-528 S
	8408030240	50-528 S
	8408030302	50-528 S
	8408030302	50-528 S
	8408030302	50-528 S
	8408060075	50-528 K
	8408060075	50-528 K
	8408060075	50-528 K
	8408060319	50-528 A
	8408080048	50-528 A
	8408080048	50-528 A
	8408080048	50-528 A
	8408080499	50-528 S
	8408080499	50-528 S
	8408080499	50-528 S
	8408080529	50-528 S
	8408080529	50-528 S
	8408080529	50-528 S
	8408090012	50-528 S
	8408090012	50-528 S
	8408090012	50-528 S
	8408100127	50-528 A
	8408100127	50-528 A
	8408100127	50-528 A
	8408130172	50-528 S
	8408130172	50-528 S
	8408130172	50-528 S
	8408130274	50-528 A
	8408130274	50-528 A
	8408130274	50-528 A
	8408130277*	50-528 A
	8408130277*	50-528 A
	8408130277*	50-528 A
	8408130303	50-528 S
	8408130332	50-528 S
	8408130332	50-528 S
	8408130332	50-528 S
	8408130344	50-528 S
	8408130344	50-528 S
	8408130351	50-528 E
	8408130351	50-528 E
	8408130351	50-528 E
	8408130429	50-527 S
	8408140227	50-528 A
	8408140227	50-528 A
	8408140227	50-528 A
	8408150207	50-528 A
	8408150207	50-528 A
	8408150207	50-528 A
	8408160192	50-528 S
	8408160192	50-528 S
	8408160192	50-528 S
	8408160480	50-528 S
	8408160480	50-528 S
	8408160480	50-528 S
	8408160506	50-528 S
	8408160506	50-528 S
	8408160506	50-528 S
	8408170348	50-528 A
	8408170348	50-528 A
	8408170348	50-528 A
	8408170384	50-528 S
	8408200112	50-528 F
	8408200112	50-528 F
	8408200112	50-528 F
	8408200217	50-528 F
	8408200217	50-528 F
	8408200217	50-528 F
	8408200224*	50-528 F
	8408200224*	50-528 F
	8408200224*	50-528 F
	8408200255	50-528 A
	8408200255	50-528 A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408200255	50-528 A
	8408200285	50-528 S
	8408200297	50-528 S
	8408200297	50-528 S
	8408200297	50-528 S
	8408200322	50-528 S
	8408200322	50-528 S
	8408200322	50-528 S
	8408200599	50-528 F
	8408200599	50-528 F
	8408200599	50-528 F
	8408200600*	50-528 F
	8408220071*	50-528 G
	8408220128	50-528 S
	8408220128	50-528 S
	8408220128	50-528 S
	8408220143	50-528 S
	8408220143	50-528 S
	8408220143	50-528 S
	8408240261	50-528 A
	8408240261	50-528 A
	8408240261	50-528 A
	8408240263*	50-528 A
	8408240263*	50-528 A
	8408240263*	50-528 A
	8408240289	50-528 A
	8408240289	50-528 A
	8408240289	50-528 A
	8408270133	50-528 E
	8408270133	50-528 E
	8408270133	50-528 E
	8408270140*	50-528 E
	8408270140*	50-528 E
	8408270140*	50-528 E
	8408270260	50-528 F
	8408270260	50-528 F
	8408270260	50-528 F
	8408280204	50-528 S
	8408280204	50-528 S
	8408280204	50-528 S
	8408280263	50-528 S
	8408280263	50-528 S
	8408280275	50-528 S
	8408280283	50-528 S
	8408280297	50-528 S
	8408280297	50-528 S
	8408280297	50-528 S
	8408280302	50-528 S
	8408280302	50-528 S
	8408280302	50-528 S
	8408280317	50-528 S
	8408280317	50-528 S
	8408280317	50-528 S
	8408280325	50-528 S
	8408280335	50-528 S
	8408280335	50-528 S
	8408280335	50-528 S
	8408280357	50-528 S
	8408280357	50-528 S
	8408280357	50-528 S
Arizona, State of	8408070104*	CONTRACT
	8408200334*	50-528 F
Arkansas Power & Light Co	8408060187	50-368 S
	8408070483	50-313 P
	8408070485*	50-313 P
	8408080493	50-368 S
	8408080500	50-368 S
	8408080512	50-368 S
	8408080528	50-368 S
	8408130190	50-313 S
	8408130326	50-313 S
	8408130367	50-368 P
	8408140328	50-368 P
	8408140355	50-313 P
	8408140355	50-313 P
	8408140403	50-313 P
	8408140429	50-313 P
	8408150180	50-313 P
	8408150184*	50-313 P
	8408150317*	50-313 G
	8408170061	50-313 P
	8408170061	50-313 P
	8408200303	50-313 P
	8408220313	50-313 P
	8408220316*	50-313 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408230401	50-313 F
	8408230417	50-313 F
	8408240053	50-313 S
	8408240077	50-368 S
	8408240080	50-368 S
	8408280184	50-313 F
	8408280184	50-313 F
	84082801BB*	50-313 F
	84082801BB*	50-313 F
	8408300154	50-313 Q
	8408300475	50-368 S
	8408300496	50-368 S
	8408310231	50-313 P
Armed Forces Radiobiological Research Institute	8408090537*	50-170 P
Army, Dept of, Corps of Engineers	8104230479*	50-329 Q
	8408010182*	CONTRACT
	8408140144*	50-329 A
	8408140144*	50-329 A
	8408140232*	50-329 A
	8408140319*	50-329 A
	8408140367*	50-329 A
	8408140557*	50-329 A
	8408150015*	50-329 A
	8408150015*	50-329 A
Arthur D Little, Inc	8408010224*	50-354 E
Ashtabula County, OH	8408140482	50-440 Q
Aspen Systems, Inc	8408230125	NUREG
Atlas Foundry & Machine Co	8408150392	71-9147
Atlas Minerals, Inc	8408240056	40-3453
Atomic Industrial Forum	8408080303*	NUREG
Australia, Govt of	8408090551*	CONTRACT
	8408150131	XPORTLIC
BIW Cable Systems, Inc	8408230215	QA999
Babcock & Wilcox Co	8408010020	70-364
	8408020203	70-824
	8408070389	50-269 P
	8408070392*	50-269 P
	8408080016	TOPREP
	8408130454	70-27
	8408140413*	50-346 P
	8408140433*	50-313 P
	8408150115	50-13 P
	8408150118*	50-13 P
	8408150667	70-364
	84082103B7*	50-338 P
	8408210393*	50-338 P
	8408210483	70-27
	8408230084	TOPREP
	8408270121*	70-27
	8408270159	TOPREP
	8408270258*	70-27
	8408270274*	70-27
	8408280270*	70-1201
	8408280277*	70-1201
	8408300141	TOPREP
	8408300194*	70-824
	8408310039*	70-27
Baltimore Gas & Electric Co	8408070074	50-317 Q
	8408070074	50-317 Q
	8408070343	50-317 F
	8408130402	PR
	8408150188	50-317 S
	8408150395	50-318 S
	8408170086	50-317 F
	8408170261	50-317 F
	8408200492	50-318 S
	8408200512	50-318 S
	8408270535	50-317 R
	8408290258	50-317 B
	8408310042	50-318 S
Barris, Sott, Denn & Driker	8408150692*	50-329 A
Basalt Waste Isolation Project	8408070149	WASTE MGT
	8408070153*	WASTE MGT
Battelle Memorial Institute, Columbus Laboratories	8408010048*	CONTRACT
	8408170016	70-8
	8408220387*	CONTRACT
Battelle Memorial Institute, Pacific Northwest Laboratories	8408060405	50-206 S
	8408130043	NUREG
	8408220370	NUREG
	8408290171	NUREG
	8408310075	NUREG
Bear Creek Uranium Co	8408080429	40-8452

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Bechtel Corp	8408020070*	50-133 P
	8408030058*	50-329 A
	8408030093	50-528 K
	8408030102	50-528 K
	8408030102	50-528 K
	8408030102	50-528 K
	8408030133	QA999
	8408030142	50-528 K
	8408030142	50-528 K
	8408030142	50-528 K
	8408070456*	50-498 A
	8408140065*	50-329 A
	8408140071*	50-329 A
	8408140076*	50-329 A
	8408140079*	50-329 A
	8408140314*	50-352 E
	8408140314*	50-352 E
	8408140320*	50-352 E
	8408140326*	50-352 E
	8408140326*	50-352 E
	8408140570*	50-329 A
	8408150566*	50-329 A
	8408150571*	50-329 A
	8408150720*	50-329 A
	8408170343*	50-354 Q
	8408270207*	50-263 P
	8408280062	QA999
Beltway Limousine Service, Inc	8408080480*	CONTRACT
Bendix Corp	8408030197*	WASTE MGT
	8408030264*	WASTE MGT
	8408030268*	WASTE MGT
	8408030270*	WASTE MGT
	8408150533*	WASTE MGT
	8408270253*	WASTE MGT
	8408270256*	WASTE MGT
	8408270262*	WASTE MGT
	8408270264*	WASTE MGT
	8408270267*	WASTE MGT
Berger, D	8408310238	50-289 P
Berkshire Medical Center, Pittsfield, MA	8408230196*	70-1450
Bishop, Liberman, Cook, Purcell & Reynolds	8408020060	50-413 Q
	8408030081	50-416 Q
	8408080162	50-445 Q
	8408080162	50-445 Q
	8408080413	50-445 Q
	8408080413	50-445 Q
	8408130093	50-445 Q
	8408130305	50-445 Q
	8408220331	50-445 Q
	8408220331	50-445 Q
	8408220336	50-445 Q
	8408220347	50-413 Q
	8408220367	50-445 T
	8408220367	50-445 T
	8408230187	50-445 Q
	8408230187	50-445 Q
	8408230257	50-445 Q
	8408230319	50-445 Q
	8408230319	50-445 Q
	8408270154	50-445 Q
	8408280083	50-445 Q
	8408280156	50-445 Q
	8408280156	50-445 Q
	8408280165	50-445 Q
	8408280165	50-445 Q
	8408280251	50-445 Q
	8408280251	50-445 Q
	8408280265	50-445 Q
	8408310216	50-445 Q
Borg-Warner Corp	8408150722	XPORTLIC
Boston Edison Co	8408020130	50-293 P
	8408020139*	50-293 P
	8408020142*	50-293 P
	8408020144*	50-293 P
	8408020147*	50-293 P
	8408020149*	50-293 P
	8408030022	50-293 S
	8408030121	50-293 P
	8408060005	50-293 P
	8408060008*	50-293 P
	8408080503	50-293 R
	8408090114	50-293 S
	8408090248	50-293 P
	8408100008	50-293 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408100046	50-293 S
	8408100099	50-293 S
	8408140239	50-293 P
	8408140245*	50-293 P
	8408140250	50-293 P
	8408140251	50-293 P
	8408140256*	50-293 P
	8408150055	50-293 G
	8408150087	50-293 P
	8408160033	50-293 P
	8408160036*	50-293 P
	8408160041	50-293 P
	8408160045*	50-293 P
	8408160094	50-293 R
	8408160368	50-293 F
	8408160369*	50-293 F
	8408160374	50-293 F
	8408220133	50-293 P
	8408280269	50-293 F
	8408300198	50-293 P
	8408300348	50-293 S
Brookhaven National Laboratory	8408010151	NUREG
	8408010166	NUREG
	8408010179	NUREG
	8408070014	NUREG
	8408090208	50-206 P
	8408220333	50-352 A
	8408220415*	50-445 G
	8408220419*	50-445 G
	8408270070	WASTE MGT
Brown & Root, Inc (subs of Halliburton Co)	8408070105	50-445 T
	8408070273	50-445 T
	8408070273	50-445 T
	8408080023	50-445 T
	8408080023	50-445 T
	8408080027	50-445 T
	8408080032	50-445 T
	8408080032	50-445 T
	8408080089	50-445 T
	8408080089	50-445 T
	8408080257	50-445 T
	8408080257	50-445 T
	8408220371*	50-445 T
	8408220371*	50-445 T
	8408220374*	50-445 T
	8408220374*	50-445 T
	8408220380*	50-445 T
	8408220380*	50-445 T
	8408220381*	50-445 T
	8408220381*	50-445 T
	8408220385*	50-445 T
	8408220385*	50-445 T
	8408220388*	50-445 T
	8408220388*	50-445 T
	8408220393*	50-445 T
	8408220393*	50-445 T
	8408220399*	50-445 T
	8408220399*	50-445 T
	8408220403*	50-445 T
	8408220403*	50-445 T
	8408220405*	50-445 T
	8408220405*	50-445 T
Brown Boveri Corp (subs of Brown Boveri & Co , Ltd)	8408030089	GA999
	8408030165	GA999
	8408070317	GA999
	8408220317	50-245 B
	8408240259	GA999
	8408240276	GA999
Brunswick Co	8408080219	XPORTLIC
Brush Wellman, Inc.	8408060300	40-8722
Businessmen for the Public Interest	8406260276	50-454 Q
	8408080395	50-454 G
	8408170298	50-454 T
	8408170326*	50-454 T
	8408170380	50-454 T
	8408170382	50-454 Q
	8408280194	50-367 Q
	8408310201	50-454 Q
C-E Operating Plants Owners Group	8408130349	TOPREP
	8408140409	TOPREP
CEIP Fund, Inc	8408220350	PR
CEPA	8408140540	50-352 G
CYGNA Energy Services	8408140422*	PR

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408210426*	50-29 P
Cabot Corp	8408200563	XPORTLIC
	8408200566*	XPORTLIC
California Instruments	8408070171	XPORTLIC
	8408200457	XPORTLIC
	8408200537	XPORTLIC
	8408200541	XPORTLIC
	8408230473	XPORTLIC
	8408230485	XPORTLIC
	8408230493	XPORTLIC
	8408230500	XPORTLIC
	8408230505	XPORTLIC
California, Univ of, Berkeley, CA	8408020211	ACRS
	8408310154	PR
California, Univ of, Irvine, CA	8408270091	50-326 P
California, Univ of, Los Angeles, CA	8408010339	50-142 P
	8408150141	71-522
	8408150143*	71-522
	8408210359	PR
	8408270142	50-142 P
	8408300109	50-142 R
	8408310141	PR
California, Univ of, Riverside, CA	8408310154	PR
California, Univ of, San Francisco, CA	8408310154	PR
California, Univ of, Santa Barbara, CA	8408130094*	50-433 G
Campaign for Prosperous Georgia	8408010253	50-424 Q
	8408010253	50-424 Q
	8408010267	50-424 Q
	8408010267	50-424 Q
Cardinal Industrial Products Corp	8408100124	GA999
Carolina Environmental Study Group	8408070443	50-413 Q
	8408200548	50-413 Q
	8408310205	50-413 Q
Carolina Power & Light Co	8406070060	50-325 B
	8407260111	50-324 K
	8407260111	50-324 K
	8407260112*	50-324 K
	8407260112*	50-324 K
	8408010295	50-325 B
	8408020012	50-400 A
	8408020054	50-400 Q
	8408030034	50-324 F
	8408030034	50-324 F
	8408030040	50-324 F
	8408030040	50-324 F
	8408030094	50-261 F
	8408030096	50-261 P
	8408030100*	50-261 P
	8408030162	50-261 P
	8408030234	50-261 P
	8408060074	50-261 P
	8408060088	50-325 B
	8408060128	50-325 B
	8408060192	50-400 A
	8408060196*	50-400 A
	8408060257	50-400 A
	8408060315	50-261 B
	8408070374	50-261 P
	8408070378*	50-261 P
	8408070381	50-400 K
	8408070384*	50-400 K
	8408070407	PR
	8408080217	50-400 Q
	8408080252	50-324 P
	8408080271	50-400 A
	8408080276	50-324 P
	8408080276	50-324 P
	8408080285	50-400 F
	8408080332	50-261 P
	8408080337	50-400 E
	8408090018	50-400 S
	8408090031	50-400 S
	8408090066	50-400 S
	8408090131	50-400 S
	8408090291	50-400 S
	8408090390	50-324 S
	8408090432	50-325 S
	8408090509	50-400 K
	8408100004	50-261 F
	8408100010*	50-261 F
	8408100039	50-324 S
	8408130288	50-400 Q
	8408130338	50-324 S
	8408140004	50-400 Q
	8408140008	50-400 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408140014	50-400 T
	8408140018*	50-400 T
	8408140022	50-400 Q
	8408140023*	50-400 T
	8408140027*	50-400 T
	8408140036*	50-400 T
	8408140048	50-400 Q
	8408140057	50-400 G
	8408140146	50-400 T
	8408140151*	50-400 T
	8408140356	50-261 P
	8408160075	50-325 S
	8408160129	50-324 Q
	8408160133	50-325 S
	8408160144	50-261 R
	8408160168	50-400 S
	8408160408	50-400 S
	8408160416	50-400 S
	8408160437	50-400 S
	8408160438	50-400 S
	8408160443	50-400 S
	8408170188	50-261 S
	8408210027	50-400 J
	84082104B6	TOPREP
	8408220126	50-261 F
	8408220229	50-261 P
	8408230093	50-261 P
	8408230117	50-261 P
	8408230221	50-324 P
	8408240095*	50-261 Q
	8408240227	50-324 S
	8408270431*	50-324 Q
	8408270521*	50-261 Q
	8408280035*	50-261 Q
	8408280133	50-261 Q
	8408280166	50-324 Q
	8408280166	50-324 Q
	8408280186	50-400 Q
	8408280199	50-261 P
	8408280207	50-400 A
	8408280235	50-324 F
	8408280460*	50-400 Q
	8408280465*	50-400 Q
	8408280469*	50-400 Q
	8408290011	50-261 P
	8408290025*	50-261 Q
	8408290028*	50-261 Q
	8408300243	50-400 Q
	8408300312	50-325 S
	8408300350*	50-400 Q
Center for Law in the Public Interest	8408060046	50-275 Q
	8408060046	50-275 Q
	8408060217	50-275 Q
	8408060217	50-275 Q
	8408130389	50-275 Q
	8408130389	50-275 Q
	8408140464	50-275 Q
	8408140464	50-275 Q
	8408310210	50-275 Q
Central Iowa Power Cooperative	8408210268*	50-331 I
Chattanooga State Technical Community College, Chattanooga, TN	8408080064*	CONTRACT
Chem-Nuclear Systems, Inc	8408170021	71-6244
	8408170023*	71-6244
Chemical Waste Management, Inc	8408210349*	50-171 R
Chicago Fluid Power Co	8408210298	50-282 S
Chicago, Univ of, Chicago, IL	8408310194*	50-454 T
Christic Institute	8408060201	50-289 Q
	8408060224*	50-289 Q
Christy, W	8408070382	50-289 Q
	8408070408	50-289 Q
	8408140479	50-289 Q
Cincinnati Gas & Electric Co	8408070461	50-358 Q
Citizens Against Nuclear Power	8408100110	50-295 P
Citizens Association for Sound Energy	8408090200	50-445 Q
	8408090200	50-445 Q
	8408090206*	50-445 Q
	8408090206*	50-445 Q
	8408090408	50-445 Q
	8408090408	50-445 Q
	8408090420*	50-445 Q
	8408090420*	50-445 Q
	8408090426*	50-445 Q
	8408090426*	50-445 Q
	8408090434*	50-445 Q
	8408090434*	50-445 Q
	8408090463*	50-445 Q
	8408090469*	50-445 Q
	8408090471*	50-445 Q
	8408090471*	50-445 Q
	8408090480*	50-445 Q
	8408090480*	50-445 Q
	8408090488*	50-445 Q
	8408090488*	50-445 Q
	8408090503*	50-445 Q
	8408090503*	50-445 Q
	8408090512*	50-445 Q
	8408090512*	50-445 Q
	8408160106	50-445 Q
	8408160106	50-445 Q
	8408160113*	50-445 Q
	8408160113*	50-445 Q
	8408160114	50-445 Q
	8408160114	50-445 Q
	8408160131*	50-445 Q
	8408160131*	50-445 Q
	8408160141	50-445 Q
	8408160141	50-445 Q
	8408160153*	50-445 Q
	8408160153*	50-445 Q
	8408160158*	50-445 Q
	8408160158*	50-445 Q
	8408160171	50-445 Q
	8408160171	50-445 Q
	8408160178*	50-445 Q
	8408160178*	50-445 Q
	8408160187*	50-445 Q
	8408160187*	50-445 Q
	8408200603	50-445 Q
	8408230173	50-445 Q
	8408240244	50-445 Q
	8408240247	50-445 T
	8408240247	50-445 T
	8408240248*	50-445 T
	8408240248*	50-445 T
	8408280136	50-445 Q
	8408280136	50-445 Q
	8408280141*	50-445 Q
	8408280141*	50-445 Q
	8408280146*	50-445 Q
	8408290319	50-445 Q
	8408310102	50-445 Q
	8408310102	50-445 Q
	8408310105*	50-445 Q
	8408310105*	50-445 Q
Citizens for Safe Energy	8408310106	50-382 Q
Citizens for an Orderly Energy Policy, Inc	8408220301	50-322 Q
City College of New York	8408020021	50-322 T
	8408310194*	50-454 T
Clark, R B	840831008B*	CONTRACT
Clermont County, OH	8408060017*	CONTRACT
Cleveland Electric Illuminating Co	8408010214	50-440 Q
	8408010214	50-440 Q
	8408010217*	50-440 Q
	8408010217*	50-440 Q
	8408020118	50-440 I
	8408020118	50-440 I
	8408030145	50-440 A
	8408070184	50-440 A
	8408090148	50-440 S
	8408090148	50-440 S
	8408090261	50-440 S
	8408130393	50-440 S
	8408150467	50-440 Q
	8408220498	50-440 S
	8408220502	50-440 S
	8408270320	50-440 F
	8408280131*	50-440 Q
	8408280131*	50-440 Q
	8408300054	50-440 S
Coalition for Responsible Energy Education	8408270350	PR
Coffey County, KS	8408020117*	50-482 F
Cohen, D A MD	8408140377	PR
Colorado, State of	8408230253	State Prog
	8408230259	State Prog
Colt Industries, Inc	8408200307	50-352 S
Combustion Engineering, Inc	8408010247*	50-361 P
	8408010256*	50-361 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B408020031	50-317 P
	B408020205	70-36
	B408020207*	70-36
	B408100137*	50-528 A
	B408140230	50-470 E
	B408140390	50-470 A
	B408210183	70-36
	B408210190*	70-36
	B408210197*	70-36
	B408270412*	50-361 P
	B408270412*	50-361 P
	B408270416*	50-361 P
	B408270416*	50-361 P
	B408270418*	50-361 P
	B408270418*	50-361 P
ommerce, Dept of,	B408310368*	CONTRACT
ommerce, Dept of, Natl Oceanographic & Atmospheric Administration	B408160454	50-354 D
	B408230506*	CONTRACT
	B408290005	50-354 D
ommittee to Bridge the Gap	B408070386	50-142 G
	B408070474	50-142 G
	B408310152	50-142 P
ommonwealth Edison Co	B405250241	50-454 G
	B407100002	50-456 S
	B408010165	50-295 F
	B408010165	50-295 F
	B408010171*	50-295 F
	B408010171*	50-295 F
	B408030252*	50-10 G
	B408060042	50-374 S
	B408060055	50-373 S
	B408060063	50-373 S
	B408060065	50-254 G
	B408060071	50-249 P
	B408060085	50-373 G
	B408060085	50-373 G
	B408060100	50-237 S
	B408060101*	50-373 F
	B408060101*	50-373 F
	B408060107	50-374 S
	B408060108	50-254 G
	B408060136	50-454 A
	B408060144	50-374 P
	B408060145	50-373 P
	B408060145	50-373 P
	B408060153*	50-373 P
	B408060153*	50-373 P
	B408060168	50-374 P
	B408060203	50-237 S
	B408060207	50-373 S
	B408060227	50-374 S
	B408060251	50-265 S
	B408060255	50-373 S
	B408060276	50-237 P
	B408060276	50-237 P
	B408060280*	50-237 P
	B408060280*	50-237 P
	B408060283	50-374 S
	B408060290	50-304 S
	B408060293	50-237 S
	B408070212*	50-454 G
	B408070239	50-295 F
	B408070239	50-295 F
	B408070240	50-295 F
	B408070240	50-295 F
	B408070391	50-374 S
	B408070490	50-374 S
	B408080198	50-454 F
	B408080198	50-454 F
	B408080198	50-454 F
	B408080198	50-454 F
	B408080198	50-454 F
	B408080205*	50-454 F
	B408080205*	50-454 F
	B408080205*	50-454 F
	B408080205*	50-454 F
	B408080205*	50-454 F
	B408090047	50-304 S
	B408090052	50-237 S
	B408090151	50-237 S
	B408090324	50-373 S
	B408090326	50-304 S
	B408090404	50-295 S
	B408100015	50-295 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B408100040*	50-454 T
	B408100119*	50-456 G
	B408130108*	50-454 G
	B408130108*	50-454 G
	B408130146	50-249 S
	B408130231	50-454 S
	B408130231	50-454 S
	B408130231	50-454 S
	B408130231	50-454 S
	B408130231	50-454 S
	B408130271	50-237 R
	B408130271	50-237 R
	B408130330	50-237 S
	B408130405	50-304 S
	B408130409	50-454 G
	B408130413*	50-10 F
	B408130415	50-454 G
	B408130456	50-304 S
	B408130604	50-295 S
	B408140028	50-456 G
	B408140028	50-456 G
	B408140034*	50-456 G
	B408140034*	50-456 G
	B408140038*	50-456 G
	B408140038*	50-456 G
	B408140139	50-237 F
	B408140139	50-237 F
	B408140139	50-237 F
	B408140139	50-237 F
	B408140139	50-237 F
	B408140169*	50-374 G
	B408140179	50-373 F
	B408140179	50-373 F
	B408140180*	50-374 G
	B408140190*	50-374 G
	B408140234	50-454 F
	B408140234	50-454 F
	B408140241*	50-454 G
	B408140317	50-254 P
	B408140323	50-373 P
	B408140323	50-373 P
	B408140365	50-254 F
	B408140371	50-454 E
	B408140371	50-454 E
	B408140371	50-454 E
	B408140371	50-454 E
	B408140372	50-237 V
	B408140372	50-237 V
	B408140372	50-237 V
	B408140372	50-237 V
	B408140372	50-237 V
	B408140372	50-237 V
	B408140380	50-454 A
	B408140380	50-454 A
	B408140380	50-454 A
	B408140380	50-454 A
	B408140380	50-454 A
	B408140386	50-456 A
	B408140386	50-456 A
	B408140389*	50-237 V
	B408140389*	50-237 V
	B408140389*	50-237 V
	B408140389*	50-237 V
	B408140389*	50-237 V
	B408140397	50-237 F
	B408140405	50-374 P
	B408140428	50-295 F
	B408140428	50-295 F
	B408150098	50-237 G
	B408150098	50-237 G
	B408150098	50-237 G
	B408150098	50-237 G
	B408150098	50-237 G
	B408150098	50-237 G
	B408150098	50-237 G
	B408150098	50-237 G
	B408150098	50-237 G
	B408150113	50-237 P
	B408160122	50-295 R
	B408160122	50-295 R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408160140	50-373 R
	8408160140	50-373 R
	8408160145*	50-10 Q
	8408160150	50-295 S
	8408160345	50-237 P
	8408160345	50-237 P
	8408160345	50-237 P
	8408160364	50-373 P
	8408160364	50-373 P
	8408160387	50-373 P
	8408160387	50-373 P
	8408160415	50-454 A
	8408160415	50-454 A
	8408170069	50-454 A
	8408170398	50-295 F
	8408170398	50-295 F
	8408170399*	50-295 F
	8408170399*	50-295 F
	8408200323	50-373 S
	8408200331	50-237 Q
	8408200331	50-237 Q
	8408200331	50-237 Q
	8408200331	50-237 Q
	8408200331	50-237 Q
	8408200331	50-237 Q
	8408200331	50-237 Q
	8408200331	50-237 Q
	8408200331	50-237 Q
	8408200331	50-237 Q
	8408200458*	50-454 T
	8408200458*	50-454 T
	8408200501	50-10 S
	8408200519	50-249 S
	8408200526	50-373 S
	8408200547	50-304 S
	8408210068	50-254 R
	8408210068	50-254 R
	8408210104	50-249 S
	8408210203*	50-374 Q
	8408210336	50-454 Q
	8408210336	50-454 Q
	8408210344*	50-454 Q
	8408210344*	50-454 Q
	8408210358*	50-456 Q
	8408210358*	50-456 Q
	8408220079	50-454 Q
	8408220079	50-454 Q
	8408220079	50-454 Q
	8408220079	50-454 Q
	8408220079	50-454 Q
	8408220086	50-295 Q
	8408220106	50-454 F
	8408220106	50-454 F
	8408220112*	50-454 F
	8408220239	50-454 A
	8408220239	50-454 A
	8408220239	50-454 A
	8408220239	50-454 A
	8408220239	50-454 A
	8408220306	50-454 E
	8408220306	50-454 E
	8408220306	50-454 E
	8408220306	50-454 E
	8408220306	50-454 E
	8408220368	50-454 A
	8408220368	50-454 A
	8408230270	50-254 F
	8408230283	50-10 F
	8408230435	50-254 R
	8408230435	50-254 R
	8408230496	50-254 S
	8408230514	50-295 S
	8408230524	50-374 S
	8408230533	50-374 S
	8408240042	50-295 S
	8408240044	50-374 S
	8408240139	50-454 F
	8408240139	50-454 F
	8408240173	50-454 F
	8408240173	50-454 F
	8408240179	50-374 S
	8408240196	50-454 Q
	8408240218	50-237 S
	8408270087	50-295 Q
	8408270113	50-454 A
	8408270114	50-237 P
	8408270114	50-237 P
	8408270114	50-237 P
	8408270118	50-454 A
	8408270118	50-454 A
	8408270163	50-454 Q
	8408270172*	50-454 Q
	8408270204	50-454 E
	8408270218	50-454 F
	8408270218	50-454 F
	8408270265	50-454 E
	8408270358	50-373 F
	8408270362*	50-373 F
	8408270372	50-295 P
	8408270373	50-454 E
	8408270373	50-454 E
	8408270373	50-454 E
	8408270455	50-249 S
	8408280119	50-295 P
	8408280274	50-454 Q
	8408290038	50-10 J
	8408300044	50-456 S
	8408300044	50-456 S
	8408300053	50-454 K
	8408300053	50-454 K
	8408300053	50-454 K
	8408300053	50-454 K
	8408300053	50-454 K
	8408300093	50-295 S
	8408300136	50-295 R
	8408300214	50-456 S
	8408300214	50-456 S
	8408300299	50-254 R
	8408300299	50-254 R
	8408300308*	50-254 R
	8408300329*	50-254 R
	8408300336*	50-254 R
	8408300368	50-10 R
	8408300388	50-373 R
	8408300390	50-373 R
	8408300393*	50-373 R
	8408300508	50-373 R
	8408300508	50-373 R
	8408300513*	50-373 R
	8408300516*	50-373 R
	8408310047	50-373 S
	8408310053	50-374 S
	8408310063	50-237 S
	8408310067	50-237 S
	8408310071	50-249 S
	8408310115	50-304 P
	8408310163	50-454 A
	8408310168	50-295 P
	8408310200	50-295 P
	8408310202	50-295 P
	8408310203	50-254 P
	8408310203	50-254 P
	8408310206*	50-254 P
	8408310206*	50-254 P
	8408310211	50-237 P
	8408310211	50-237 P
	8408310226	50-454 E
	8408310226	50-454 E
	8408310233	50-373 F
Concerned Citizens of Louisa County, VA	8408010250	50-338 Q
Confederated Tribes of Umatilla Indian Reservation	8408010114	WASTE MGT
Connecticut Yankee Atomic Power Co	8408070321	50-213 H
	8408090180	50-213 Q
	8408100063	50-213 P
	8408100116	50-213 Q
	8408160328	50-213 F
	8408210480	50-213 Q
	8408220222	50-213 Q
	8408230482	50-213 S
	8408290298	50-213 P
	8408300135	50-213 P
	8408310107	50-213 S
	8408310187	50-213 F
	8408310187	50-213 F
Conner & Wetterhahn	8408010246	50-354 Q
	8408010255	50-352 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408060053	50-352 G
	8408060053	50-352 G
	8408060182	50-352 G
	8408060182	50-352 G
	8408060228	50-352 G
	8408060228	50-352 G
	8408070287	50-352 G
	8408070287	50-352 G
	8408070291*	50-352 G
	8408070291*	50-352 G
	8408070350	50-352 G
	8408070350	50-352 G
	8408070363	50-352 G
	8408070363	50-352 G
	8408070372	50-352 G
	8408070372	50-352 G
	8408070412	50-352 G
	8408070412	50-352 G
	8408070429	50-352 G
	8408070429	50-352 G
	8408070444	50-352 G
	8408070444	50-352 G
	8408070461	50-338 G
	8408070495	50-352 G
	8408070495	50-352 G
	8408080019	50-354 D
	8408080389	50-354 G
	8408080399	50-352 G
	8408080399	50-352 G
	8408080404	50-352 G
	8408080404	50-352 G
	8408130398	PR
	8408150387	50-352 G
	8408150477	50-352 G
	8408240236	50-352 G
	8408240236	50-352 G
	8408240241	50-352 G
	8408240241	50-352 G
	8408240254	50-352 T
	8408240254	50-352 T
	8408240256	50-352 G
	8408240256	50-352 G
	8408280223	50-354 G
	8408280388	50-352 G
	8408280448	50-354 G
	8408310223	50-352 G
Conservation Council of North Carolina	8408090485	50-400 G
Consolidated Edison Co of New York, Inc	8408020138	50-247 P
	8408060349	50-3 F
	8408060349	50-3 F
	8408070114	50-247 F
	8408070421	50-247 F
	8408070425	50-247 G
	8408130211	50-247 P
	8408130325	50-247 F
	8408130388*	50-247 G
	8408140493	50-247 G
	8408140493	50-247 G
	8408150121	50-3 F
	8408150121	50-3 F
	8408150125*	50-3 F
	8408170270	50-247 G
	8408170270	50-247 G
	8408200309	50-247 G
	8408200539	50-247 S
	8408210002	50-247 F
	8408220214	50-247 S
	8408240164	50-247 P
	8408290279	50-247 G
Construction Technology Laboratories	8408150698*	50-329 A
Consumers Power Co	8408010147*	50-329 D
	8408010149*	50-329 A
	8408010163*	50-329 D
	8408010260	50-155 G
	8408010263*	50-155 G
	8408010269*	50-155 G
	8408020014	50-329 A
	8408020014	50-329 A
	8408020015	50-329 A
	8408020015	50-329 A
	8408020106	NUREG
	8408020122*	50-329 A
	8408030064*	50-329 A
	8408030109	50-155 P
	8408030113*	50-155 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408030116*	50-155 P
	8408030150	50-255 P
	8408030151*	50-255 P
	8408030152*	50-255 P
	8408060115*	50-155 G
	8408060263	50-255 S
	8408070180*	50-329 A
	8408070183	50-329 G
	8408070183	50-329 G
	8408070227	50-329 G
	8408070227	50-329 G
	8408070431	50-255 P
	8408070435	50-255 F
	8408070438*	50-255 P
	8408070441*	50-255 F
	8408080224	50-155 G
	8408080331	50-255 P
	8408090032	50-325 S
	8408090166	50-155 P
	8408090171*	50-155 P
	8408090284	50-329 S
	8408090284	50-329 S
	8408090327*	50-155 P
	8408090398	50-255 S
	8408100134	50-255 P
	8408100138*	50-255 P
	8408130227*	50-329 A
	8408130227*	50-329 A
	8408130255*	50-329 A
	8408130255*	50-329 A
	8408130290*	50-329 A
	8408130348*	50-329 A
	8408130353	50-255 F
	8408130376*	50-155 F
	8408140031*	50-400 T
	8408140050*	50-329 A
	8408140055*	50-329 A
	8408140069*	50-329 A
	8408140263*	50-329 A
	8408140295	50-255 F
	8408140388	50-255 P
	8408140553*	50-329 A
	8408140562*	50-329 A
	8408140573*	50-329 A
	8408150577*	50-329 A
	8408150577*	50-329 A
	8408150586*	50-329 A
	8408150608*	50-329 A
	8408150635*	50-329 A
	8408150644*	50-329 G
	8408150644*	50-329 G
	8408150651*	50-329 A
	8408150652*	50-329 A
	8408150662*	50-329 A
	8408150669*	50-329 G
	8408150672*	50-329 G
	8408150672*	50-329 G
	8408150685*	50-329 A
	8408150712*	50-329 A
	8408150712*	50-329 A
	8408150716*	50-329 A
	8408150718*	50-329 A
	8408150718*	50-329 A
	8408150735*	50-329 A
	8408150738*	50-329 A
	8408150749*	50-329 A
	8408160181	50-155 P
	8408160255	50-255 R
	8408160279	50-255 S
	8408170081*	50-329 A
	8408170102*	50-329 A
	8408170187*	50-329 A
	8408170195*	50-329 A
	8408170279*	50-329 A
	8408170358*	50-329 A
	8408170364	50-255 F
	8408170365*	50-329 A
	8408170367*	50-329 A
	8408170367*	50-329 A
	8408170372*	50-329 A
	8408170374*	50-329 K
	8408170374*	50-329 K
	8408170377*	50-329 A
	8408170377*	50-329 A
	8408210287	50-155 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408210454*	50-329 E
	8408210498	50-155 F
	8408220059*	50-329 G
	8408220059*	50-329 G
	8408230201	50-255 P
	8408230239	50-155 S
	8408240161	50-255 P
	8408270127	50-255 S
	8408270130	50-255 S
	8408270281*	50-255 G
	8408270330*	50-329 G
	8408270392*	50-155 G
	8408280003*	50-255 G
	8408290067	50-155 S
	8408290251	50-155 S
	8408300086	50-155 S
	8408310054	50-329 S
	8408310054	50-329 S
	8408310056	50-255 S
	8408310059	50-255 S
	8408310161	50-255 G
	8408310165*	50-255 G
	8408310259	50-329 S
	8408310259	50-329 S
Containment Issues Owners Group	8408210376	TOPREP
	8408210382*	TOPREP
CorSTAR Research, Inc	8408240291	WASTE MANA
Corn Belt Power Cooperative	8408210272*	50-331 I
Covington & Burling	8408070482	40-2061
	8408080235	40-2061
CrawFord Fitting Co	8408240313	50-327 S
Creare, Inc	8408210382*	TOPREP
Critical Mass Energy Project	8408030282*	MISC
Crystal River, FL	8408200606*	CONTRACT
Dairyland Power Cooperative	8408060004	50-409 G
	8408140287	50-409 P
	8408150212	50-409 P
	8408160186	50-409 S
	8408160309	50-409 S
	8408210333	50-409 F
	8408220105	50-409 F
	8408220190	50-409 R
	8408270080	50-409 P
	8408270294*	50-409 G
	8408310176	50-409 P
	8408310179*	50-409 P
Dames & Moore	8408060252	WASTE MGT
	8408090092*	50-423 A
	8408150149*	WASTE MGT
Data Consultants, Inc	8408270576*	CONTRACT
Dauphin County, PA	8408140449	50-219 G
Dayton X-Ray Co	8408150122	71-6717
	8408150122	71-6717
	8408150122	71-6717
	8408150607	71-6717
	8408150607	71-6717
	8408150607	71-6717
DeKalb Area Alliance for Responsible Energy	8408010177	50-454 G
	8408010177	50-454 G
	8408010181	50-454 G
	8408010181	50-454 G
	8408080390	50-454 G
	8408170319	50-454 T
Del-Aware Unlimited, Inc	8408010223	50-352 G
	8408010223	50-352 G
	8408010228*	50-352 G
	8408010228*	50-352 G
	8408010248	50-352 G
	8408090226	50-352 G
	8408090233*	50-352 G
	8408130368	50-352 G
	8408140484	50-352 G
Delaware Solid Waste Authority	8408100003	50-354 H
Delaware, State of	8408070284	50-354 H
Detroit Edison Co	8406010037	50-341 A
	8408010216	50-341 E
	8408020029	50-341 K
	8408060082	50-341 G
	8408070356*	50-341 G
	8408070440	50-341 A
	8408080299	50-341 F
	8408080302*	50-341 F
	8408080305	50-341 F
	8408080511	50-341 B
	8408080516	50-341 S
	8408090055	50-341 S
	8408090062	50-341 S
	8408090071	50-341 S
	8408130163*	50-341 G
	8408140016	50-341 S
	8408160444	50-341 S
	8408160474	50-341 A
	8408210079	50-341 A
	8408210085*	50-341 A
	8408220135	50-341 S
	8408220175	50-341 S
	8408220193	50-341 S
	8408220209	50-341 S
	8408230274	50-341 F
	8408230296	50-341 E
	8408230301*	50-341 E
	8408230389	50-341 F
	8408230391*	50-341 F
	8408270352*	50-341 G
	8408300045	50-341 S
	8408300061	50-341 S
	8408300069	50-341 S
	8408300209	50-341 S
	8408300216	50-341 S
	8408300223	50-341 S
	8408300251	50-341 S
	8408300257	50-341 S
	8408310188	50-341 F
	8408310191*	50-341 F
Detroit, MI	8408220343	PR
Doherty, J F	8408140419	PR
Domus Design Studios, Inc	8408220400*	CONTRACT
	8408220404*	CONTRACT
Don L Warner, Inc	8408020161	40-8027
Dougherty, J B	8408010250	50-338 G
Dr W J Hall	8408140194*	50-206 P
Duke Power Co	8405290062	50-206 S
	8405290062	50-206 S
	8405290062	50-206 S
	8405290179	50-206 S
	8405290179	50-206 S
	8405290179	50-206 S
	8408020060	50-413 G
	8408020060	50-413 G
	8408020066*	50-413 G
	8408020066*	50-413 G
	8408030130	50-369 P
	8408030130	50-369 P
	8408030135*	50-369 P
	8408030135*	50-369 P
	8408060035	50-413 G
	8408060035	50-413 G
	8408060050	50-206 S
	8408060072	50-413 A
	8408060097	50-413 P
	8408060102	50-206 S
	8408060102	50-206 S
	8408060102	50-206 S
	8408060104*	50-413 P
	8408060117	50-413 P
	8408060119*	50-413 P
	8408060324	50-206 S
	8408060324	50-206 S
	8408070263	50-413 P
	8408070263	50-413 P
	8408070298	50-369 P
	8408070322	50-413 F
	8408070351	50-413 F
	8408070351	50-413 F
	8408070445	50-413 S
	8408070445	50-413 S
	8408070468	50-369 P
	8408070487	50-413 F
	8408080275	50-413 E
	8408080275	50-413 E
	8408080339	50-413 G
	8408080339	50-413 G
	8408090007	50-413 F
	8408090007	50-413 F
	8408090274	50-370 S
	8408090278	50-413 S
	8408090278	50-413 S
	8408130169	50-369 P
	8408140103	50-413 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8408140103	50-413	G
	8408140110*	50-413	G
	8408140110*	50-413	G
	8408140115*	50-413	G
	8408140115*	50-413	G
	8408140430	50-413	P
	8408140430	50-413	P
	8408150221	50-369	S
	8408150326	50-269	F
	8408150335*	50-269	F
	8408160050	50-369	P
	8408160121	50-413	G
	8408160159	50-413	S
	8408160174	50-369	P
	8408160174	50-369	P
	8408160183	50-413	S
	8408160183	50-413	S
	8408160394	50-206	S
	8408160394	50-206	S
	8408160394	50-206	S
	8408160395	50-206	S
	8408160395	50-206	S
	8408160395	50-206	S
	8408160417	50-269	S
	8408160429	50-413	S
	8408160429	50-413	S
	8408160468	50-413	S
	8408160517	50-413	S
	8408160517	50-413	S
	8408170329	50-269	F
	8408170329	50-269	F
	8408170329	50-269	F
	8408200059	50-269	P
	8408200059	50-269	P
	8408200059	50-269	P
	8408200069*	50-269	P
	8408200069*	50-269	P
	8408200069*	50-269	P
	8408200100	50-369	F
	8408200149	50-269	P
	8408200149	50-269	P
	8408200149	50-269	P
	8408200155*	50-269	P
	8408200155*	50-269	P
	8408200155*	50-269	P
	8408210362	50-413	P
	8408210365	50-413	P
	8408210365	50-413	P
	8408210396	50-369	P
	8408220091	50-269	F
	8408220201	50-269	K
	8408220201	50-269	K
	8408220201	50-269	K
	8408220208*	50-269	K
	8408220208*	50-269	K
	8408220208*	50-269	K
	8408220292	50-269	P
	8408220292	50-269	P
	8408220292	50-269	P
	8408220303	50-413	P
	8408220303	50-413	P
	8408220347	50-413	Q
	8408220465	50-369	R
	8408220465	50-369	R
	8408220468	50-269	R
	8408230051	50-413	P
	8408230527	50-269	P
	8408230527	50-269	P
	8408230527	50-269	P
	8408230527	50-269	P
	8408230527	50-269	P
	8408230527	50-269	P
	8408240224	50-413	I
	8408240224	50-413	I
	8408240224	50-413	I
	8408240242*	50-413	I
	8408240242*	50-413	I
	8408240242*	50-413	I
	8408240242*	50-413	I
	8408270160	50-269	P
	8408270160	50-269	P
	8408270160	50-269	P
	8408270169*	50-269	P
	8408270169*	50-269	P
	8408270169*	50-269	P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8408270259*	50-369	Q
	8408270339	50-269	P
	8408270339	50-269	P
	8408270339	50-269	P
	8408270345*	50-269	P
	8408270345*	50-269	P
	8408270345*	50-269	P
	8408270391	50-413	Q
	8408270391	50-413	Q
	8408280205	50-413	T
	8408280230	50-369	Q
	8408280234	50-369	Q
	8408280234	50-369	Q
	8408280241	50-269	Q
	8408280281	50-413	P
	8408280372	50-413	F
	8408280372	50-413	F
	8408280377*	50-413	F
	8408280377*	50-413	F
	8408280389	50-369	S
	8408280476*	50-269	Q
	8408290094	50-370	S
	8408290179	50-206	S
	8408300014	50-269	F
	8408300014	50-269	F
	8408300014	50-269	F
	8408300014	50-269	F
	8408300014	50-269	F
	8408300014	50-269	F
	8408300021*	50-269	F
	8408300021*	50-269	F
	8408300021*	50-269	F
	8408300021*	50-269	F
	8408300021*	50-269	F
	8408300021*	50-269	F
	8408300021*	50-269	F
	8408300021*	50-269	F
	8408300028*	50-269	F
	8408300028*	50-269	F
	8408300028*	50-269	F
	8408300028*	50-269	F
	8408300028*	50-269	F
	8408300028*	50-269	F
	8408300406	50-413	R
	8408300497	50-287	S
	8408300501	50-413	S
	8408300509	50-370	R
	8408310121	50-269	F
Duquesne Light Co	8408010154	50-412	F
	8408010156*	50-412	F
	8408020011	50-412	E
	8408020019	50-412	E
	8408060259	50-412	S
	8408070355*	50-412	Q
	8408070414	50-412	F
	8408070432	50-412	E
	8408100092	50-334	S
	8408100113	50-334	S
	8408130005	50-412	E
	8408130312	50-412	E
	8408130436	50-334	P
	8408130439*	50-334	P
	8408130441*	50-334	P
	8408140088	50-412	E
	8408140127	50-412	E
	8408150124	50-334	P
	8408150199	50-412	E
	8408150499	50-334	P
	8408160333	50-412	E
	8408160399	50-412	E
	8408210016	50-334	S
	8408210023	50-334	S
	8408210437	50-412	A
	8408210476	50-412	S
	8408230246	50-412	A
	8408230299	50-334	Q
	8408230329	50-412	E
	8408240275	50-412	Q
	8408270071	50-412	P
	8408270141	50-412	E
	8408270165	50-412	E
	8408270341*	50-334	Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408280200	50-412 E
	8408290222	50-412 E
	8408290336	50-412 A
	8408310208	50-412 F
Durham, NH	8408140436	50-443 G
E C Rodabaugh Associates, Inc	8408130041	NUREG
	8408270582*	CONTRACT
E I du Pont de Nemours & Co , Inc	8408310025*	XPORTLIC
	8408310303	XPORTLIC
	8408310446	XPORTLIC
EA Engineering, Science & Technology, Inc	8408090334	50-289 R
EG&G, Inc	8405210578	NUREG
	8405210579	NUREG
	8408010027*	50-298 P
	8408090019*	50-397 G
	8408130455*	50-445 A
	8408160248	50-269 P
	8408240379	NUREG
	8408240382	NUREG
	8408300060*	50-263 G
EarthFax Engineering, Inc	8408070509	40-8084
Ebasco Services, Inc (subs of Enserch Corp)	8408030021	QA999
	8408070273	50-445 T
	8408070273	50-445 T
	8408080051	50-445 T
	8408080257	50-445 T
	8408140027*	50-400 T
	8408140031*	50-400 T
Eberline Instrument Corp	8408310337	XPORTLIC
Eddleman, W	8408030070	50-400 G
	8408070459	50-400 G
	8408140002	50-400 G
	8408140119	50-400 G
	8408140122*	50-400 G
	8408140125*	50-400 G
	8408160105	50-400 G
	8408200498	50-400 G
Edison Electric Institute	8408070457*	PRM
Edlow International Co	8408310307	XPORTLIC
Elgar Corp	8408310180	XPORTLIC
End Nuclear Dumping in the Pacific	8408220343	PR
Energy Fuels Nuclear, Inc	8408080144	40-8681
	8408240393	40-8681
	8408280010	40-8675
	8408280012*	40-8675
	8408280110	40-8675
	8408290216	40-8681
	8408290366	40-8681
Energy, Dept of	8408010046	WASTE MGT
	8408010053*	WASTE MGT
	8408010063*	WASTE MGT
	8408010064	WASTE MGT
	8408010072*	WASTE MGT
	8408030082	WASTE MGT
	8408030084	WASTE MGT
	8408030092	WASTE MGT
	8408030187	WASTE MGT
	8408030263	WASTE MGT
	8408030279	WASTE MGT
	8408030283	WASTE MGT
	8408060059	WASTE MGT
	8408060067	WASTE MGT
	8408060106	WASTE MGT
	8408060111*	WASTE MGT
	8408060122*	WASTE MGT
	8408060264	WASTE MGT
	8408070063	WASTE MGT
	8408080013	XPORTLIC
	8408090303*	WASTE MGT
	8408130116	WASTE MGT
	8408130137	WASTE MGT
	8408150144	WASTE MGT
	8408150193	40-6500
	8408150363	WASTE MGT
	8408150365	WASTE MGT
	8408150400	WASTE MGT
	8408150403	WASTE MGT
	8408150419	WASTE MGT
	8408150531	WASTE MGT
	8408150542	71-6346
	8408160270	WASTE MGT
	8408160283*	WASTE MGT
	8408160289	WASTE MGT

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408200430	WASTE MGT
	8408200435	WASTE MGT
	8408200439	WASTE MGT
	8408200506	WASTE MGT
	8408200514	WASTE MGT
	8408200517	WASTE MGT
	8408210038	WASTE MGT
	8408210171	WASTE MGT
	8408220122	WASTE MGT
	8408220215	WASTE MGT
	8408220223	WASTE MGT
	8408220227	WASTE MGT
	8408220232	WASTE MGT
	8408220234	WASTE MGT
	8408230043*	WASTE MGT
	8408230469	XPORTLIC
	8408240211	40-1341
	8408240354	WASTE MGT
	8408240355*	WASTE MGT
	8408270250	WASTE MGT
	8408270319	PR
	8408290350*	COMMISSION
	8408290352*	COMMISSION
	8408310005*	XPORTLIC
	8408310270	WASTE MGT
	8408310273	WASTE MGT
	8408310335*	WASTE MGT
	8408310339*	WASTE MGT
Engineering Planning & Management, Inc	8408170327*	50-315 F
Engineers International, Inc	8408240221	WASTE MANA
Environmental Protection Agency	8408160264*	ORG
	8408160292*	ORG
	8408210205	50-354 D
	8408210326	50-354 D
	8408220151	50-456 D
Esser Corp	8408170056*	50-354 F
European Communities, Commission of	8408230464	XPORTLIC
Everest Minerals Corp	8408280018	40-8857
	8408280022*	40-8857
	8408280024*	40-8857
Extran, Inc	8408280366*	50-295 P
	8408280373*	50-295 P
	8408280378*	50-295 P
	8408280380*	50-295 P
	8408280381*	50-295 P
	8408280411*	50-295 P
	8408280422*	50-295 P
	8408280430*	50-295 P
Exxon Corp	8408060297	40-8102
Exxon Nuclear Co , Inc (subs of Exxon Corp)	8407300143	TOPREP
	8408090198	50-316 P
	8408090209*	50-316 P
	8408090230	TOPREP
	8408140191	TOPREP
	8408140363*	50-261 P
	8408140396	TOPREP
	8408230103*	50-261 P
	8408230122*	50-261 P
	8408230263	50-315 P
	8408230266*	50-315 P
	8408240268	TOPREP
	8408240309	50-261 P
	8408280122	TOPREP
	8408280212	TOPREP
	8408310195	TOPREP
Failure Analysis Associates	8405290075*	50-206 S
	8405290075*	50-206 S
	8405290075*	50-206 S
	8405290075*	50-206 S
	8405290075*	50-206 S
	8405290075*	50-206 S
	8405290271*	50-206 S
	8408060387*	50-206 S
	8408060387*	50-206 S
	8408060387*	50-206 S
	8408060387*	50-206 S
	8408060387*	50-206 S
	8408160397*	50-206 S
	8408160397*	50-206 S
	8408160397*	50-206 S
	8408160397*	50-206 S
	8408160403*	50-206 S
	8408210370*	50-413 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Fauske & Associates, Inc	8408230112*	50-327 P
Federal Emergency Management Agency	8404040169	50-10 F
	8404040172*	50-10 F
	8405240290	50-3 F
	8408070427	50-322 Q
	8408080138	50-416 F
	8408080141*	50-416 F
	8408090042	50-413 F
	8408090056	50-247 F
	8408090059*	50-247 F
	8408090059*	50-247 F
	8408090061*	50-247 F
	8408090061*	50-247 F
	8408100060	50-295 F
	8408130373	50-322 T
	8408150443	50-322 Q
	8408200497*	50-400 Q
	8408210346	50-302 F
	8408210354*	50-302 F
	8408210408	50-272 F
	8408210408	50-272 F
	8408290206*	50-266 F
	8408290356	COMMISSION
	8408290359*	COMMISSION
	8408300211*	50-302 F
	8408300319*	50-324 F
	8408300323*	50-324 F
Florida Power & Light Co	8407260218	50-250 K
	8407260220*	50-250 K
	8408010311	50-251 B
	8408020123	50-389 F
	8408030164	50-335 P
	8408030235	50-335 B
	8408030239	50-250 B
	8408080230	50-250 B
	8408090009	50-335 F
	8408090009	50-335 F
	8408090096	50-389 P
	8408090243	50-335 P
	8408090397	50-250 Q
	8408090397	50-250 Q
	8408090437	50-250 Q
	8408090437	50-250 Q
	8408100016	50-250 F
	8408100016	50-250 F
	8408100016	50-250 F
	8408100016	50-250 F
	8408100016	50-250 F
	8408100054*	50-250 F
	8408100054*	50-250 F
	8408100054*	50-250 F
	8408100054*	50-250 F
	8408100054*	50-250 F
	8408130215	50-335 F
	8408130215	50-335 F
	8408140214	50-250 Q
	8408140214	50-250 Q
	8408140220*	50-250 Q
	8408140220*	50-250 Q
	8408140226*	50-250 Q
	8408140236*	50-250 Q
	8408140236*	50-250 Q
	8408140253*	50-250 Q
	8408140253*	50-250 Q
	8408140262*	50-250 Q
	8408140262*	50-250 Q
	8408140271*	50-250 Q
	8408140271*	50-250 Q
	8408140277*	50-250 Q
	8408140277*	50-250 Q
	8408160521	50-250 B
	8408170054	50-389 P
	8408170084	50-250 P
	8408170233	50-335 Q
	8408170237*	50-335 Q
	8408200143	50-389 P
	8408200200	50-389 P
	8408200273	50-250 B
	8408210347	50-250 Q
	8408210347	50-250 Q
	8408210380	50-250 Q
	8408210380	50-250 Q
	8408210441	50-250 H
	8408230155*	50-251 Q
	8408270015	50-250 P
	8408270019	50-250 P
	8408270200*	50-335 Q
	8408270203	50-250 B
	8408270298*	50-335 Q
	8408270316*	50-250 Q
	8408270344	50-250 P
	8408270344	50-250 P
	8408270384	50-250 Q
	8408280058	50-335 Q
	8408280097	50-335 F
	8408280106	50-389 Q
	8408280182	50-335 Q
	8408280236	50-335 Q
	8408280238	50-250 P
	8408280238	50-250 P
	8408310133	50-250 F
	8408310145	50-389 P
Florida Power Corp	8408020010	50-302 P
	8408020018*	50-302 P
	8408060199	50-302 P
	8408060306	50-302 B
	8408080189	50-302 B
	8408160238	50-302 B
	8408160247	50-302 B
	8408160410	50-302 B
	8408160526	50-302 R
	8408200278	50-302 P
	8408200311	50-302 F
	8408200330	50-302 P
	8408200346	50-302 B
	8408230424	50-302 B
	8408230430	50-302 B
	8408240155	50-302 F
	8408270211*	50-302 Q
	8408280069*	50-302 Q
	8408280154	50-302 P
	8408280170	50-302 Q
	8408300341	50-302 B
Florida, Univ of, Gainesville, FL	8408130261	70-1068
Franklin Institute/Franklin Research Center	8105130143*	50-293 P
	8204150347*	50-293 P
	8307010039*	50-277 P
	8404040095*	50-388 U
	8404040095*	50-388 U
	8404040098*	50-388 U
	8404040098*	50-388 U
	8407090037*	50-219 P
	8407300136*	50-213 P
	8408280321*	50-346 P
Friends of the Earth	8408080191	50-352 Q
	8408280491	50-352 Q
	8408310096	50-352 Q
GA Technologies, Inc /General Atomic Co	8405310267	PR
	8408020253	70-734
	8408020256*	70-734
	8408150109	71-6346
	8408270311	50-89 F
General Electric Co	8312020299*	50-354 E
	8405300761	70-1113
	8405300762*	70-1113
	8405300763*	70-1113
	8408090335	50-73 P
	8408090337*	50-73 P
	8408130033	70-1308
	8408130173*	50-331 P
	8408150084	TOPREP
	8408160377	TOPREP
	8408160384*	TOPREP
	8408160390*	50-458 A
	8408160466*	70-1308
	8408160472*	70-1308
	8408170262*	50-263 P
	8408170339*	50-354 Q
	8408170342*	50-354 Q
	8408230209	50-447 A
	8408230468	XPORTLIC
	8408230513	XPORTLIC
	8408240122	TOPREP
	8408240348	50-155 B
	8408270155	50-447 P
	8408270175*	50-331 P
	8408280111	70-1113
	8408280209*	50-331 P
	8408280211*	50-331 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408310160	50-373 S
	8408310186	50-219 S
General Public Utilities - GPU Service Corp	8408010293	50-219 S
	8408010329*	50-320 P
	8408010331*	50-320 P
	8408020137	50-289 K
	8408020141*	50-289 K
	8408030006	50-289 P
	8408030088	50-289 F
	8408030107*	50-289 Q
	8408030108*	50-289 Q
	8408030141	50-320 P
	8408060142*	50-219 Q
	8408060166	50-320 F
	8408060310	50-320 S
	8408070152	50-219 P
	8408070203	50-320 Q
	8408070238	50-289 P
	8408070280	50-289 P
	8408070300	50-219 P
	8408070306*	50-219 P
	8408070348	50-219 P
	8408070454	50-219 P
	8408080300	50-289 Q
	8408080498	50-219 S
	8408090100	50-320 F
	8408090144	50-289 S
	8408090250	50-219 P
	8408090257*	50-219 P
	8408090334	50-289 R
	8408100130	50-320 Q
	8408130191	50-219 F
	8408130218	50-289 P
	8408130343	50-289 P
	8408140197	50-320 F
	8408140279	50-320 P
	8408140406	50-289 P
	8408140411	50-289 P
	8408140415*	50-289 P
	8408160035	50-320 P
	8408160182	50-289 S
	8408200115	50-320 S
	8408210320	50-320 F
	8408220218	50-289 P
	8408220356	50-219 P
	8408220363	50-289 P
	8408220365*	50-289 P
	8408220375	50-219 P
	8408230098*	50-219 Q
	8408230101*	50-219 Q
	8408230382	50-289 F
	8408230382	50-289 F
	8408240066	50-289 R
	8408240167	50-289 P
	8408240225	50-320 H
	8408240257*	50-219 Q
	8408270145	50-289 Q
	8408270195	50-289 S
	8408270285	50-219 P
	8408270290*	50-219 P
	8408270381	50-219 P
	8408280076	50-320 Q
	8408280178	50-289 P
	8408280179	50-289 F
	8408300031	50-320 P
	8408300503	50-289 S
	8408310128	50-219 Q
	8408310129	50-320 P
	8408310153	50-289 P
	8408310166	50-289 F
Georgia Institute of Technology, Atlanta, GA	8408280195	50-160 F
Georgia Power Co	8408010336	50-424 H
	8408030163	50-321 F
	8408030163	50-321 F
	8408060003	50-424 F
	8408070141	50-366 Q
	8408070148	50-321 P
	8408090023	50-424 S
	8408090287	50-321 S
	8408100045	50-366 P
	8408100049*	50-366 P
	8408130379	50-321 F
	8408130379	50-321 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408130412	50-424 A
	8408130561	50-321 P
	8408130561	50-321 P
	8408130567*	50-321 P
	8408130567*	50-321 P
	8408140106	50-321 P
	8408140106	50-321 P
	8408140124*	50-321 P
	8408140124*	50-321 P
	8408150242	50-366 P
	8408150494	50-424 A
	8408170258	50-321 F
	8408170258	50-321 F
	8408170301	50-424 A
	8408200001	50-321 R
	8408200001	50-321 R
	8408200438	50-366 S
	8408210175	50-366 P
	8408210235*	50-366 P
	8408210357	50-321 P
	8408210357	50-321 P
	8408210416	REGGD
	8408210472	50-321 F
	8408210472	50-321 F
	8408210474	50-321 P
	8408210474	50-321 P
	8408220491	50-366 S
	8408230251	50-321 P
	8408230251	50-321 P
	8408240367*	50-424 Q
	8408270229	50-321 S
	8408270247*	50-321 Q
	8408270301	50-321 F
	8408270430*	50-424 Q
	8408280183	50-366 Q
	8408280208	50-424 A
	8408280208	50-424 A
	8408280213*	50-424 A
	8408280213*	50-424 A
	8408280233	50-321 F
	8408280239	50-321 Q
	8408300024	50-321 P
	8408300024	50-321 P
	8408300072	50-321 I
	8408300115	50-366 P
	8408300333	50-321 S
	8408300346*	50-424 Q
	8408300517	50-366 S
Geotechnical Engineers, Inc	8210130322*	50-329 A
	8305270222*	50-329 A
	8408020181*	50-329 Q
	8408140185*	50-329 A
	8408140185*	50-329 A
	8408140196*	50-329 A
	8408140196*	50-329 A
	8408140296*	50-329 A
	8408140300*	50-329 A
Gerard Kluyskens Co , Inc	8408210084	XPORTLIC
Gesellschaft fuer Nuklear Service, mbH	8408090562	PROJ
	8408090564*	PROJ
Getty/Petrotomics Co	8408240336	40-6659
	8408240346	40-6659
Gibbs & Hill, Inc (subs of Dravo Corp)	8408070170	GA999
Gilbert/Commonwealth, Inc (formerly Gilbert Associates, Inc.)	8408220332	NUREG
Golder Associates	8408230336*	CONTRACT
	8408240390	WASTE MANA
Government Accountability Project	8408010235	50-275 Q
	8408010235	50-275 Q
	8408010237*	50-275 Q
	8408010237*	50-275 Q
	8408020152	50-275 Q
	8408020152	50-275 Q
	8408060201	50-289 Q
	8408060224*	50-289 Q
	8408070182	50-289 Q
	8408070408	50-289 Q
	8408140479	50-289 Q
	8408170223*	50-329 Q
	8408170312*	50-329 T
	8408220258	50-289 Q
	8408220263*	50-289 Q
	8408220366	50-289 Q
	8408240251	50-289 Q
	8408270336*	50-329 T

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408310106	50-382 G
	8408310207	50-142 G
Guild, R	8408070443	50-413 G
	8408200548	50-413 G
	8408310205	50-413 G
Gulf Nuclear, Inc	8408010025	71-9163
Gulf States Utilities Co	8408010004	50-458 S
	8408010012	50-458 S
	8408010241	50-458 G
	8408020025	50-458 S
	8408060028	50-458 A
	8408060147	50-458 E
	8408070520	50-458 S
	8408070529	50-458 S
	8408080199	50-458 S
	8408080236	50-458 S
	8408080471	50-458 S
	8408100068	50-458 G
	8408100108	50-458 G
	8408140095*	50-458 G
	8408140340	50-458 E
	8408140421	50-458 A
	8408140554	50-458 S
	8408150152	50-458 S
	8408150162	50-458 S
	8408150177	50-458 S
	8408150308	50-458 S
	8408150385	50-458 S
	8408150691	50-458 S
	8408150704	50-458 S
	8408150707	50-458 S
	8408160194	50-458 S
	8408160242	50-458 S
	8408160386	50-458 A
	8408160457*	50-458 G
	8408210376	TOPREP
	8408210490	50-458 A
	8408220504	50-458 S
	8408220505	50-458 S
	8408220511	50-458 S
	8408230538	50-458 S
	8408240310	50-458 S
	8408240404	50-458 S
	8408240426	50-458 C
	8408280408	50-458 S
	8408280414	50-458 S
	8408280416	50-458 S
	8408280428	50-458 S
	8408280446	50-458 S
	8408280458	50-458 S
	8408300343	50-458 S
	8408300494	50-458 S
	8408300507	50-458 S
	8408310087	50-458 S
	8408310172	50-458 E
H H Holmes Testing Laboratories, Inc	8408270276*	50-454 E
	8408270284*	50-454 E
	8408270292*	50-454 E
	8408270296*	50-454 E
HHS, Dept of, U S Public Health Service	8408240094*	CONTRACT
Hahnemann Univ Hosp, Philadelphia, PA (formerly Hahnemann Medical Coll & Hosp)	8408060378*	70-1362
	8408060382*	70-1362
Harman & Weiss	8408070286	PR
	8408070344	PR
	8408130396	50-289 G
	8408140035	50-289 G
	8408140474	50-289 G
	8408220362	50-289 G
	8408240234	50-443 G
	8408240245	50-289 G
	8408270359	50-289 G
	8408280493	50-289 G
Harnischfeger Corp	8408150250*	XPORTLIC
	8408150642	XPORTLIC
Harrisburg, PA	8408140449	50-219 G
	8408220307	50-289 G
Hatfield Electric Co	8408310194*	50-454 T
Hittman Nuclear & Development Corp (subs of Hittman Corp)	8408020258	71-9092
Homestake Mining Co	8408280365	40-8434
House of Rep	8408020208	50-289 G
	8408070215*	50-416 U
	8408070217*	50-322 H
	8408130210*	50-416 U
	8408200454*	50-352 U
	8408280056*	50-322 H
House of Rep, Interior & Insular Affairs	8408080432*	50-416 U
	8408200279*	50-369 U
House of Rep, Ways and Means	8407100397*	50-413 U
Houston Lighting & Power Co	8408010222	50-498 K
	8408010222	50-498 K
	8408010225*	50-498 K
	8408010225*	50-498 K
	8408070446	50-498 A
	8408080186	50-498 G
	8408150389	50-498 S
	8408160196	50-498 G
	8408210096*	50-498 G
	8408210311	50-498 A
	8408210311	50-498 A
	8408210317*	50-498 A
	8408210317*	50-498 A
	8408210500	50-498 A
	8408210500	50-498 A
	8408210503*	50-498 A
	8408210503*	50-498 A
	8408220130	50-498 S
	8408220161	50-498 A
	8408240312	50-498 S
	8408270212	50-498 G
	8408270355	50-498 A
	8408270355	50-498 A
	8408300370	50-498 S
	8408300370	50-498 S
Hunter Corp	8408310194*	50-454 T
Hunton & Williams	8408010169	50-322 G
	8408010261	50-322 G
	8408020024	50-322 G
	8408030090	50-322 G
	8408070256	50-322 G
	8408070274	50-322 G
	8408070399	50-322 G
	8408070442	50-322 G
	8408070448*	50-322 G
	8408080408	50-322 G
	8408080417	50-322 G
	8408080428	50-322 G
	8408090218	50-322 G
	8408090223*	50-322 G
	8408090411	50-322 G
	8408090431	50-322 G
	8408130347	50-322 G
	8408140003	50-322 G
	8408150438	50-322 G
	8408150464	50-338 G
	8408150464	50-338 G
	8408150473	50-322 T
	8408160100	50-322 G
	8408200477	50-338 G
	8408200477	50-338 G
	8408230231	50-322 G
	8408230409	50-322 C
	8408280394	50-322 T
	8408280433	50-322 G
	8408280492	50-322 G
	8408290317	50-322 G
	8408300124	50-322 G
	8408300177	50-338 G
	8408300177	50-338 G
	8408310137	FOIA
	8408310150	50-338 G
	8408310150	50-338 G
	8408310218	50-322 G
	8408310224	50-322 G
INTERA Technologies, Inc	8408080321*	CONTRACT
Idaho, Univ of, Moscow, ID	8408280121	WASTE MANA
Illinois Power Co	8408060366	50-461 S
	8408070219	50-461 R
	8408070460*	50-461 G
	8408080540	50-461 S
	8408100089	50-461 A
	8408130238	50-461 S
	8408140351	50-461 E
	8408270135	50-461 A
	8408270318	50-461 S
	8408280094	50-461 A
	8408300022	50-461 S
	8408300076	50-461 S
	8408300210	50-461 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408300224	50-461 S
Illinois, State of	8408070311	40-2061
	8408130329	40-2061
	8408130337*	40-2061
	8408140335	50-456 A
	8408140376	50-456 A
	8408170314	50-461 G
	8408170323	50-461 G
	8408170383	40-2061
	8408170387*	40-2061
	8408170389*	40-2061
	8408170396	40-2061
	8408290008	40-2061
	8408290309	50-454 G
Illinois, Univ of, Urbana, IL	8408030276	50-151 F
	8408300184	50-151 S
Impell Corp	8408080522	WASTE MGT
Indian River Community College, Ft Pierce, FL	8408060048*	CONTRACT
Indiana & Michigan Electric Co	8405160248	50-315 G
	8406080109	50-316 P
	8406080113*	50-316 P
	8408060076	50-315 P
	8408060118	50-315 F
	8408060118	50-315 F
	8408060151	50-316 S
	8408060348	50-315 F
	8408060348	50-315 F
	8408070272	50-315 F
	8408070272	50-315 F
	8408070307	50-315 F
	8408070307	50-315 F
	8408080084	50-315 G
	8408080084	50-315 G
	8408080536	50-315 S
	8408100094	50-315 F
	8408130307	50-316 S
	8408130321	50-315 F
	8408140164	50-315 P
	8408160127	50-316 S
	8408160188	50-315 P
	8408160527	50-315 S
	8408170322	50-315 F
	8408210156	50-315 F
	8408210156	50-315 F
	8408220486	50-315 S
	8408240121	50-316 P
	8408240188	50-315 P
	8408240188	50-315 P
	8408300505	50-315 S
Industry Degraded Core Rulemaking Program	8408230105*	50-327 P
	8408230105*	50-327 P
	8408230108*	50-327 P
	8408230112*	50-327 P
	8408230112*	50-327 P
	8408230116*	50-327 P
	8408230116*	50-327 P
	8408230119*	50-327 P
	8408230119*	50-327 P
	8408230131*	50-327 P
Inhalation Toxicology Research Institute	8408160125	NUREG
Institute of Nuclear Power Operations	8408020091	NUREG
	8408020102	REGGD
	8408220310*	ORG
	8408220315*	ORG
Interior, Dept of	8408210213	50-354 D
Interior, Dept of, Bureau of Mines	8408270074	WASTE MGT
	8408270078*	WASTE MGT
Interior, Dept of, Geological Survey	8408200121	50-274 F
	8408220238	WASTE MGT
Interstate Amiosite Corp	8408070413	PR
Iowa Electric Light & Power Co	8408020006	50-331 P
	8408020009*	50-331 P
	8408030038	50-331 P
	8408060001	50-331 F
	8408060141	50-331 S
	8408080083	50-331 P
	8408130170	50-331 P
	8408140247	50-331 P
	8408140435	50-331 P
	8408150004	50-331 G
	8408160261	50-331 S
	8408160471	50-331 S
	8408210256	50-331 I
	8408210263*	50-331 I
	8408210499	50-331 P
	8408210502*	50-331 P
	8408220202	50-331 S
	8408230429	50-331 R
	8408240105	50-331 P
	8408240118	50-331 P
	8408240124*	50-331 P
	8408240172	50-331 S
	8408240239*	50-331 P
	8408270167	50-331 P
	8408270173*	50-331 P
	8408280202	50-331 P
	8408280206*	50-331 P
	8408310228	50-331 E
Iowa Wesleyan College, Mt Pleasant, IA	8408080339	PR
Isham, Lincoln & Beale	8405250241	50-454 G
	8408010249	50-454 T
	8408010260	50-155 G
	8408080224	50-155 G
	8408140028	50-456 G
	8408140028	50-456 G
	8408140034*	50-456 G
	8408140034*	50-456 G
	8408140102*	50-329 A
	8408140263*	50-329 A
	8408210336	50-454 G
	8408270163	50-454 G
Jacobs Engineering Group, Inc	8408060266	WASTE MGT
	8408280112	WASTE MGT
Japan, Govt of	8405160213	XPORTLIC
	8408150128	XPORTLIC
	8408150179	XPORTLIC
Johns Hopkins Medical Institutions, Baltimore, MD	8408220448*	50-320 P
Joint Intervenors - Diablo Canyon	8408060046	50-275 G
	8408060046	50-275 G
	8408060217	50-275 G
	8408060217	50-275 G
	8408070297	50-275 G
	8408070297	50-275 G
	8408130389	50-275 G
	8408130389	50-275 G
	8408140464	50-275 G
	8408140464	50-275 G
	8408310210	50-275 G
Joint Intervenors - River Bend	8408010250	50-458 G
Joint Intervenors - Shearon Harris	8408010264	50-400 G
	8408030070	50-400 G
	8408140478	50-400 T
	8408210323	50-400 G
KMC, Inc	8408220322	PR
KMS Fusion, Inc (Subs of KMS Industries, Inc)	8408150359	XPORTLIC
	8408150361*	XPORTLIC
Kansas City Power & Light	8408020088	PR
Kansas Gas & Electric Co	8408020105	50-482 F
	8408030012	50-482 A
	8408030016*	50-482 A
	8408030159	50-482 A
	8408100066	50-482 E
	8408100075*	50-482 G
	8408140001	50-482 S
	8408140020	50-482 S
	8408140237	50-482 S
	8408140308	50-482 S
	8408140337	50-482 F
	8408140350	50-482 A
	8408160505	50-482 S
	8408160514	50-482 S
	8408200119	50-482 A
	8408200123*	50-482 A
	8408220158	50-482 S
	8408220207	50-482 F
	8408220217	50-482 S
	8408220248	50-482 S
	8408220389	50-482 A
	8408220479	50-482 S
	8408270377	50-482 A
	8408280193	50-482 V
	8408280435	50-482 S
	8408290033	50-482 F
Kansas State Univ, Manhattan, KS	8408310117	50-188 F
Kansas, State of	8408020114*	50-482 F
Kelley Drye & Warren	8408080173	40-2061
	8408080180*	40-2061

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408220351	40-2061
Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)	8408070294	40-2061
	8408080235	40-2061
	8408200603	40-2061
Kerr-McGee Corp	8408020153	40-8027
	8408070482	40-2061
	8408150671	40-8027
	8408150675*	40-8027
	8408300322	70-925
Kirkpatrick, Lockhart, Hill, Christopher & Phillips	8408010239	50-322 Q
	8408030074	50-322 Q
	8408030086	50-322 Q
	8408030105	50-322 Q
	8408070308	50-322 Q
	8408070424	50-322 Q
	8408080338	50-322 Q
	8408080410	50-322 Q
	8408140013	50-322 T
	8408140466	50-322 Q
	8408140470	50-322 Q
	8408140477*	50-322 Q
	8408160210	50-322 Q
	8408170315	50-322 Q
	8408210388	50-322 Q
	8408230194	50-322 Q
	8408230199	50-322 Q
	8408230264	50-322 Q
	8408280249	50-322 Q
	8408280405	50-322 Q
Korea Electric Co	8408280471*	COMMISSION
Kulm, V	8408160407*	50-508 A
Lancaster County, PA	8408200455	50-289 Q
Latir Energy Consultants	8408210087	WASTE MGT
Law Engineering Testing Co	8408130079*	WASTE MGT
	8408130597*	CONTRACT
Lawrence Berkeley Laboratory	8408310344*	WASTE MGT
Lawrence Livermore National Laboratory	8404230171*	50-400 F
	8408010155	NUREG
	8408070140*	WASTE MGT
	8408080515*	50-275 Q
	8408080517*	50-275 Q
	8408080521*	50-275 Q
	8408200173*	50-336 P
	8408240265	WASTE MANA
	8408240295	WASTE MANA
	8408240388	WASTE MGT
LeBoeuf, Lamb, Leiby & MacRae	8408020120	PR
	8408070420	50-244 Q
	8408130398	PR
	8408200507	50-244 Q
League of Women Voters of Pennsylvania	8408100144*	50-289 Q
League of Women Voters of Rockford, IL	8408010177	50-454 Q
	8408010177	50-454 Q
	8408010181	50-454 Q
	8408010181	50-454 Q
	8408080390	50-454 Q
Legal Environmental Assistance Foundation	8408010267	50-424 Q
Lewis, M	8408020111	PR
	8408070349	PR
	8408140465	50-289 Q
	8408280412	50-289 Q
Limerick Ecology Action	8408010190	50-352 Q
	8408060170	50-352 Q
	8408090258	50-352 Q
	8408170381	50-352 Q
Lone Star Screw Co	8408160071	QA999
Lone Tree Council	8408170304*	50-329 T
Long Island Lighting Co	8408010169	50-322 Q
	8408010261	50-322 Q
	8408020024	50-322 Q
	8408020048	50-322 T
	8408030090	50-322 Q
	8408060323	50-322 V
	8408070256	50-322 Q
	8408070274	50-322 Q
	8408070385	50-322 V
	8408070399	50-322 Q
	8408070442	50-322 Q
	8408070448*	50-322 Q
	8408070458*	50-322 Q
	8408080340	PR
	8408080408	50-322 Q
	8408080417	50-322 Q
	8408080423*	50-322 Q
	8408080428	50-322 Q
	8408090218	50-322 Q
	8408090223*	50-322 Q
	8408090411	50-322 Q
	8408090431	50-322 Q
	8408130347	50-322 Q
	8408130352*	50-322 Q
	8408130355*	50-322 Q
	8408130359*	50-322 Q
	8408140003	50-322 Q
	8408150438	50-322 Q
	8408150473	50-322 T
	8408150476*	50-322 T
	8408150485*	50-322 T
	8408150498*	50-322 T
	8408150505*	50-322 T
	8408150514*	50-322 T
	8408150530*	50-322 T
	8408160100	50-322 Q
	8408200328	50-322 A
	8408230231	50-322 Q
	8408230409	50-322 C
	8408270226	50-322 A
	8408280187*	50-322 Q
	8408280394	50-322 T
	8408280397*	50-322 T
	8408280433	50-322 Q
	8408280492	50-322 Q
	8408290317	50-322 Q
	8408290486*	50-322 Q
	8408300123	50-322 V
	8408300124	50-322 Q
	8408310218	50-322 Q
	8408310224	50-322 Q
Los Alamos Scientific Laboratory	8406230301	50-317 P
	8408010308*	50-151 Q
	8408080357	NUREG
	8408080409	NUREG
	8408100153	NUREG
	8408160146	NUREG
	8408220065	WASTE MGT
	8408220337	PR
	8408240249	NUREG
Louisiana Power & Light Co	8408010399	50-382 B
	8408020033	50-382 A
	8408020035*	50-382 A
	8408030296	50-382 B
	8408060032	50-382 B
	8408060061	50-382 B
	8408070109	50-382 F
	8408070230	50-382 F
	8408090029	50-382 B
	8408100006	50-382 Q
	8408100007	50-382 Q
	8408100117	50-382 F
	8408130342	50-382 F
	8408140284	50-382 A
	8408160180	50-382 B
	8408160221	50-382 B
	8408160228	50-382 B
	8408210305	50-382 A
	8408210361*	50-382 A
	8408210378	50-382 A
	8408230179	50-382 A
	8408230284*	50-382 Q
	8408240407	50-382 B
	8408270303	50-382 A
	8408280219	50-382 Q
	8408280436	50-382 B
	8408280440	50-382 B
	8408290131	50-382 B
	8408290139	50-382 B
	8408290145	50-382 B
	8408300521	50-382 B
	8408310225	50-382 F
	8408310236	50-382 A
Louisiana, State of	8408010196	50-416 Q
	8408010210	50-458 Q
	8408010210	50-458 Q
	8408010245	50-458 Q
	8408010245	50-458 Q
	8408090154*	50-416 Q
	8408140458	50-458 Q
MATHTECH, Inc	8408080472	NUREG

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
MHB Technical Associates	8408020129	50-322 T
	8408030112*	50-322 Q
MPR Associates, Inc	8408100080*	50-220 P
Madison, IN	8408060214*	CONTRACT
Maine Yankee Atomic Power Co	8408020121	50-309 K
	8408020125*	50-309 K
	8408030008	50-309 F
	8408030272	50-309 S
	8408070367	50-309 P
	8408090173	50-309 P
	8408140399	50-309 F
	8408230331	50-309 F
	8408280210	50-309 F
	8408280227	50-309 P
	8408310204	50-309 F
Management Analysis Co	8408130269*	50-329 A
	8408130306*	50-329 A
	8408150710*	50-329 A
Manhattan College, Riverdale, NY	8408170407	50-199 I
Maricopa County, AZ	8408200334*	50-528 F
Marsh & McLennan, Inc	8408150129	50-244 J
	8408160344	50-413 J
	8408220148	50-369 J
	8408290006	50-269 J
Maryland, Univ of, College Park, MD	8408220172	50-166 R
	8408240248*	50-443 T
	8408300079	50-166 P
	8408300083*	50-166 P
Massachusetts Institute of Technology, Cambridge, MA	8408130205	70-938
	8408130212*	70-938
	8408210046*	50-206 P
Massachusetts, Commonwealth of	8408210477	State Prog
	8408210478*	State Prog
Matheson Gas Products	8408150726	XPORTLIC
Maxima Corp	8408290349*	CONTRACT
Melosh, H J	8408160411*	50-508 A
Memphis State Univ , Memphis, TN	8408170286	50-538 F
	8408270552*	CONTRACT
Meteorological Evaluation Services, Inc	8408010231*	50-354 E
Metropolitan Edison Co	8408020042	50-289 Q
	8408070418	50-320 Q
	8408070437	50-289 Q
	8408070470	50-320 Q
	8408090423	50-289 Q
	8408130300	50-289 Q
	8408140007	50-289 Q
	8408150458	50-289 Q
	8408170325	50-289 Q
	8408170330*	50-289 Q
	8408200468	50-289 Q
	8408200515	50-289 Q
	8408200557	50-289 Q
	8408200561	50-289 Q
	8408230207	50-289 Q
	8408230272	50-289 Q
	8408270115	50-289 Q
	8408310207	50-289 Q
Michigan State Univ , East Lansing, MI	8408090162	50-294 V
	8408090165*	50-294 V
Michigan, Univ of, Ann Arbor, MI	8408020235	ACRS
	8408130314*	CONTRACT
	8408170307	50-454 T
Middletown, CT	8408210032*	CONTRACT
Midwest Electric Cooperative	8408080536	50-315 S
Minnesota, State of	8408080333	PR
	8408080334*	PR
Miranda Associates, Inc	8408220378	NUREG
Mississippi Power & Light Co	8408020027	50-416 Q
	8408030075	50-416 P
	8408030075	50-416 P
	8408030081	50-416 Q
	8408030095	50-416 P
	8408030095	50-416 P
	8408030103	50-416 P
	8408030103	50-416 P
	8408030106	50-417 A
	8408030120	50-416 S
	8408030120	50-416 S
	8408060030	50-416 S
	8408060174	50-416 P
	8408060174	50-416 P
	8408060185	50-416 S
	8408060185	50-416 S
	8408060189	50-416 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408060189	50-416 S
	8408060193*	50-416 S
	8408060200*	50-416 S
	8408060249	50-416 P
	8408060249	50-416 P
	8408070404	50-416 P
	8408070404	50-416 P
	8408070430	50-416 P
	8408070436	50-416 P
	8408070436	50-416 P
	8408070486	50-416 P
	8408070486	50-416 P
	8408080938	50-416 S
	8408090137	50-416 S
	8408090163	50-416 S
	8408130150	50-416 Q
	8408130365	50-416 S
	8408130371	50-416 S
	8408140116	50-416 P
	8408150151	50-416 P
	8408150154*	50-416 P
	8408150160	50-416 P
	8408150201	50-416 P
	8408150201	50-416 P
	8408160061	50-416 S
	8408160061	50-416 S
	8408160175	50-416 S
	8408160421	50-416 S
	8408160421	50-416 S
	8408200127	50-417 A
	8408210105	50-416 R
	8408210151	50-416 F
	8408210151	50-416 F
	8408210484	50-416 F
	8408240210	50-416 S
	8408270263*	50-417 Q
	8408270321*	50-416 Q
	8408280137	50-416 Q
	8408280137	50-416 Q
	8408280143	50-416 F
	8408280143	50-416 F
	8408280196	50-416 Q
	8408300490	50-416 S
	8408310222	50-416 P
Missouri, State of	8408310139	PR
Mitsubishi International Corp (subs of Mitsubishi Corp)	8408060256	WASTE MGT
	8408170406	XPORTLIC
	8408170408*	XPORTLIC
Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd)	8408060402	XPORTLIC
	8408060406	XPORTLIC
	8408060438*	XPORTLIC
Montesano, WA	8408060037*	CONTRACT
Morgan Associates	8408140488	50-247 Q
Morris, IL	8408060040*	CONTRACT
Morrison-Knudsen Co , Inc	8408070161	WASTE MGT
	8408100101*	50-461 A
	8408170413	WASTE MGT
	8408170415*	WASTE MGT
	8408200154	WASTE MGT
	8408200157*	WASTE MGT
	8408200342	WASTE MGT
Mount Morris Times, Mount Morris, IL	8408290313	50-454 Q
N C Kist & Associates, Inc	8408140517*	CONTRACT
NUS Corp	8408140401	50-382 A
	8408150733	71-9073
	8408150736*	71-9073
	8408150739*	71-9073
	8408150742*	71-9073
	8408150744*	71-9073
	8408160297	WASTE MGT
	8408210403	50-382 A
	8408210409*	50-382 A
NUTECH Engineers, Inc	8408160132*	50-324 Q
Nantz, J L	8408070451	PRM
National Board of Boiler & Pressure Vessel Inspectors	8407230153	NUREG
	8408070117	QA999
National Lawyers Guild, Los Angeles Chapter	8408280093	PR
National Technical Systems	8408030041	QA999
Nebraska Public Power District	8408030011	50-298 Q
	8408070267	50-298 F
	8408070295	50-298 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408070316	50-298 F
	8408100014	50-298 R
	8408100017*	50-298 R
	8408100145	50-298 P
	8408140431	50-298 F
	8408150447	50-298 I
	8408240072	50-298 S
	8408240171	50-298 F
Neutron Products, Inc	8408150598	71-9073
Nevada, State of	8408080227	State Prog
	8408130130	WASTE MGT
	8408220061	WASTE MGT
New England Coalition on Nuclear Pollution	8408240234	50-443 G
New Jersey, State of	8408060090	50-354 D
	8408090255	50-354 G
	8408140543	50-354 G
	8408230083	50-354 D
	8408230090*	50-354 D
	8408270136	50-354 D
	8408280353	50-354 H
	8408280447	50-354 G
	8408280449	50-354 G
	8408290014	50-354 G
	8408300304	50-354 D
New York, State Univ of, Buffalo, NY	8408060162	50-57 F
	8408060167*	50-57 F
New York, State of	8406040336	50-322 G
	8408010077	50-322 T
	8408010239	50-322 G
	8408020200	50-322 G
	8408070439*	50-220 F
	8408080410	50-322 G
	8408130162	50-322 G
	8408130264	50-322 G
	8408130284	50-322 G
	8408140005	50-322 G
	8408140138	50-322 G
	8408140470	50-322 G
	8408140477*	50-322 G
	8408160210	50-322 G
	8408160224*	50-322 G
Newman & Holtzinger	8408030087	50-331 J
	8408030129	50-331 J
	8408070453	PRM
	8408080186	50-498 G
	8408140214	50-250 G
	8408140214	50-250 G
	8408140220*	50-250 G
	8408140220*	50-250 G
	8408140236*	50-250 G
	8408140236*	50-250 G
	8408140253*	50-250 G
	8408140253*	50-250 G
	8408140271*	50-250 G
	8408140271*	50-250 G
	8408140277*	50-250 G
	8408140277*	50-250 G
	8408160196	50-498 G
	8408210347	50-250 G
	8408210347	50-250 G
	8408210380	50-250 G
	8408210380	50-250 G
	8408310247	50-275 G
Niagara Mohawk Power Corp	8407090212	50-410 K
	8408020079	NUREG
	8408020115	50-220 R
	8408020119*	50-220 R
	8408030201	50-220 S
	8408060154	50-220 P
	8408060171	50-220 F
	8408060248	50-220 P
	8408060260	50-410 A
	8408060284	50-410 A
	8408070434	50-220 F
	8408080259	50-220 S
	8408080483	50-220 S
	8408090077	50-220 P
	8408090081*	50-220 P
	8408100071	50-410 S
	8408100074	50-220 P
	8408100076	50-220 P
	8408100081*	50-220 P
	8408100086*	50-220 P
	8408100103	50-220 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408100111*	50-220 P
	8408100118	50-410 S
	8408100120*	50-220 P
	8408160367	50-220 P
	8408160372*	50-220 P
	8408200535	50-220 S
	8408210439	50-410 S
	8408210447	50-410 F
	8408230237	50-220 X
	8408280001	50-410 E
	8408280163	50-410 E
	8408280248*	50-220 G
	8408300035	50-220 P
	8408300037*	50-220 P
	8408300041*	50-220 P
	8408300300	50-410 A
	8408300345	50-410 S
	8408300362	50-410 S
	8408300365	50-410 S
	8408310235	50-410 G
Nichiren Shoshu Temple	8408080173	40-2061
	8408080180*	40-2061
	8408220351	40-2061
North Carolina Municipal Power Agencies	8408240239*	50-413 I
North Carolina State Univ , Raleigh, NC	8408020065	50-297 P
	8408020069*	50-297 P
North Dakota, State of	8408010334	State Prog
Northeast Nuclear Energy Co (subs of Northeast Utilities)	8408070112	50-245 S
	8408070220	50-423 A
	8408070321	50-213 H
	8408070321	50-213 H
	8408070321	50-213 H
	8408070341	50-336 P
	8408080414*	50-245 G
	8408090082	50-423 A
	8408090340	50-245 S
	8408100063	50-213 P
	8408100063	50-213 P
	8408100064	50-423 S
	8408100102	50-245 P
	8408100116	50-213 G
	8408100116	50-213 G
	8408100116	50-213 G
	8408130316	50-336 P
	8408150232	50-336 P
	8408200172	50-336 P
	8408200594	50-336 R
	8408210306	50-245 P
	8408210339	50-423 E
	8408210469*	50-336 G
	8408210480	50-213 G
	8408230431	50-245 R
	8408280159	50-423 E
	8408280258	50-423 E
	8408280262*	50-423 E
	8408290004	50-245 S
	8408290298	50-213 P
	8408310187	50-213 F
Northeast Utilities	8408070112	50-245 S
	8408070321	50-213 H
	8408070321	50-213 H
	8408070321	50-213 H
	8408070341	50-336 P
	8408080414*	50-245 G
	8408080531	50-336 S
	8408090082	50-423 A
	8408090340	50-245 S
	8408100063	50-213 P
	8408100063	50-213 P
	8408100064	50-423 S
	8408100070*	50-213 P
	8408100070*	50-213 P
	8408100077*	50-213 P
	8408100077*	50-213 P
	8408100102	50-245 P
	8408100116	50-213 G
	8408100116	50-213 G
	8408100116	50-213 G
	8408130316	50-336 P
	8408150232	50-336 P
	8408160350	50-213 F
	8408160350	50-213 F
	8408160409	TOPREP
	8408200172	50-336 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408200594	50-336 R
	8408210306	50-245 P
	8408210339	50-423 E
	8408210469*	50-336 Q
	8408210480	50-213 Q
	8408230431	50-245 R
	8408280159	50-423 E
	8408280258	50-423 E
	8408290004	50-245 S
	8408290298	50-213 P
	8408310187	50-213 F
Northeast Utilities Service Co (subs of Northeast Utilities)	8408070220	50-423 A
	8408130349	TOPREP
Northern States Power Co	8407100420	50-263 S
	8408070197*	50-282 Q
	8408080097	50-263 S
	8408090011	50-263 F
	8408090014*	50-263 F
	8408130020	71-83
	8408130021*	71-83
	8408130024*	71-83
	8408160169	50-263 F
	8408160222	50-263 P
	8408160229*	50-263 P
	8408160233*	50-263 P
	8408170252	50-263 P
	8408240238	50-282 S
	8408270293	50-263 P
	8408270299*	50-263 P
	8408270302*	50-263 P
	8408280127	50-263 S
	8408280160	50-263 P
	8408280164*	50-263 P
	8408280169*	50-263 P
	8408300176	50-263 F
	8408300176	50-263 F
	8408300176	50-263 F
	8408300176	50-263 F
	8408300180*	50-263 F
	8408300180*	50-263 F
	8408300180*	50-263 F
	8408300183*	50-263 F
	8408310112*	TOPREP
Nuclear Fuel Services, Inc (subs of Getty Oil Co)	8408020154	70-143
	8408130381*	70-143
	8408150156	70-143
	8408150161*	70-143
	8408150545	70-143
	8408170012	70-143
	8408170392	70-143
	8408270413*	70-143
	8408280053*	70-143
	8408280174	70-143
	8408280299*	70-143
Nuclear Information & Resource Service	8408140417	NUREG
Nuclear System	8408090510*	CONTRACT
Nuclear Utility Task Action Committee	8408140423*	50-458 A
Nucpn, Inc	8408010276*	50-206 P
	8408010287*	50-206 P
O'Donnell & Associates, Inc	8408280268*	50-445 Q
O'Neill, J	8408210327	50-155 G
	8408210330*	50-155 G
	8408210337*	50-155 G
	8408210432	PR
	8408280244	50-155 G
OTHA, Inc	8408070462*	PRM
Oak Ridge Associated Univs	8408020225*	70-8
Oak Ridge National Laboratory	8408070007	NUREG
	8408080355	NUREG
	8408080415	NUREG
	8408080419	NUREG
	8408080422	NUREG
	8408130001	NUREG
	8408130007	NUREG
	8408130009	NUREG
	8408130041	NUREG
	8408230184*	50-317 P
	8408230191*	50-317 P
	8408270050	WASTE MANA
	8408290190	NUREG
	8408290198	NUREG
	8408300272	NUREG

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408300282	NUREG
	8408300287	NUREG
	8408310265	WASTE MANA
Ocean Fleets Consultancy Service	8408020129	50-322 T
Office of Management & Budget	8408060019	ORG
	8408060114	ORG
	8408060219	ORG
	8408070031	ORG
Ogle Petroleum, Inc	8408240050	40-8745
	8408240079	40-8745
Ohio Citizens for Responsible Energy	8408090196	50-440 Q
	8408090196	50-440 Q
	8408090202*	50-440 Q
	8408090202*	50-440 Q
	8408090231	50-440 Q
	8408090231	50-440 Q
	8408090245	50-440 Q
	8408090245	50-440 Q
Oklahoma, Univ of, Norman, OK	8408030066	50-112 F
Omaha Public Power District	8408060289	50-285 S
	8408070128	50-285 P
	8408090401	50-285 S
	8408090405	50-285 S
	8408100062*	50-285 Q
	8408100104	50-285 P
	8408150136	71-256
	8408200589	50-285 R
	8408240230	50-285 S
	8408270244	50-285 P
	8408280288	50-285 S
	8408280343	50-285 S
Oregon State Univ , Corvallis, OR	8408020081	PR
Oregon, State of	8408200229	WASTE MGT
	8408200234	WASTE MGT
	8408200242	WASTE MGT
	8408200245	WASTE MGT
	8408200252	WASTE MGT
Owens-Corning Fiberglas Corp	8408230109	TOPREP
Pacific Gas & Electric Co	8406150149	50-275 P
	8408010036	71-202
	8408020056	50-133 P
	8408020063*	50-133 P
	8408020067*	50-133 P
	8408060120	50-323 A
	8408060126	50-323 A
	8408070278	50-323 A
	8408070327*	50-275 Q
	8408070369	50-275 S
	8408080453	50-275 F
	8408080458*	50-275 F
	8408130003	50-275 P
	8408130188	50-275 P
	8408130188	50-275 P
	8408130291	50-275 Q
	8408140011	50-275 P
	8408140011	50-275 P
	8408140341	50-323 P
	8408160234	50-275 Q
	8408160267	50-275 F
	8408160267	50-275 F
	8408160273*	50-275 F
	8408160273*	50-275 F
	8408160491	50-275 S
	8408200318*	50-275 Q
	8408200318*	50-275 Q
	8408210226	50-275 S
	8408210406	50-275 P
	8408210639	50-275 P
	8408210639	50-275 P
	8408230008	50-275 P
	8408230012*	50-275 P
	8408230476	50-275 S
	8408230553	50-275 F
	8408230553	50-275 F
	8408230558*	50-275 F
	8408230558*	50-275 F
	8408270112	50-275 S
	8408270396	50-323 A
	8408300482	50-275 P
	8408310038	50-275 S
	8408310143	50-275 S
	8408310230	50-275 F
Palmetto Alliance	8408070443	50-413 Q
	8408200548	50-413 Q
	8408310205	50-413 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Parameter, Inc	8408080507*	CONTRACT
	8408090074*	CONTRACT
	8408090272	NUREG
	8408130265	NUREG
	8408310084	NUREG
Pathfinder Mines Corp	8408080326	40-6622
	8408200400	40-2259
	8408200401*	40-2259
	8408240334	40-6622
	8408240413	40-2259
	8408240414	40-2259
	8408240419*	40-2259
	8408270093	40-2259
Pelton, J R	8408160414*	50-508 A
Pennsylvania Power & Light Co	8408030178*	50-387 G
	8408060143	50-387 I
	8408070342	50-387 P
	8408070342	50-387 P
	8408080142	50-388 S
	8408080269	50-387 G
	8408080269	50-387 Q
	8408090393	50-388 S
	8408090395	50-387 S
	8408090396	50-387 S
	8408090421	50-387 S
	8408090439	50-387 S
	8408100125	50-387 F
	8408130129	50-387 F
	8408160164	50-388 S
	8408200283	50-387 S
	8408210290	50-387 S
	8408240065	50-387 S
	8408240246	50-387 S
	8408300189	50-388 S
	8408300340	50-387 S
	8408300399	50-388 S
	8408300484	50-388 S
	8408300489	50-387 S
	8408310118	50-387 Q
	8408310214	50-387 F
	8408310214	50-387 F
Pennsylvania Power Co	8408020126*	50-440 I
Pennsylvania State Univ., University Park, PA	8408090046*	CONTRACT
	8408230267	50-5 P
Pennsylvania, Commonwealth of,	8408020047	50-352 Q
	8408140131	50-289 Q
	8408140449	50-219 Q
	8408230440*	50-289 H
Perry, OH	8408210047*	CONTRACT
Philadelphia Electric Co	8407160090	50-277 F
	8407160091*	50-277 F
	8408010255	50-352 Q
	8408010255	50-352 Q
	8408020030	50-352 A
	8408020030	50-352 A
	8408020058	50-352 A
	8408020058	50-352 A
	8408020075*	50-352 A
	8408020075*	50-352 A
	8408020080*	50-352 C
	8408020080*	50-352 C
	8408020084*	50-352 K
	8408020084*	50-352 K
	8408020090*	50-352 A
	8408020090*	50-352 A
	8408060053	50-352 Q
	8408060053	50-352 Q
	8408060228	50-352 Q
	8408060228	50-352 Q
	8408060232	50-352 E
	8408060232	50-352 E
	8408060321	50-277 P
	8408070033	50-352 A
	8408070033	50-352 A
	8408070037	50-352 A
	8408070037	50-352 A
	8408070228	50-352 A
	8408070287	50-352 Q
	8408070287	50-352 Q
	8408070289	50-352 E
	8408070289	50-352 E
	8408070291*	50-352 Q
	8408070291*	50-352 Q
	8408070303	50-278 P
	8408070336	50-352 F
	8408070350	50-352 Q
	8408070350	50-352 Q
	8408070363	50-352 Q
	8408070363	50-352 Q
	8408070366	50-352 Q
	8408070366	50-352 Q
	8408070372	50-352 Q
	8408070372	50-352 Q
	8408070412	50-352 Q
	8408070412	50-352 Q
	8408070415*	50-352 Q
	8408070415*	50-352 Q
	8408070429	50-352 Q
	8408070429	50-352 Q
	8408070433*	50-352 Q
	8408070433*	50-352 Q
	8408070444	50-352 Q
	8408070444	50-352 Q
	8408070450*	50-352 Q
	8408070450*	50-352 Q
	8408070495	50-352 Q
	8408070495	50-352 Q
	8408070513	50-352 E
	8408070513	50-352 E
	8408080399	50-352 Q
	8408080399	50-352 Q
	8408080404	50-352 Q
	8408080404	50-352 Q
	8408080533	50-277 S
	8408080535	50-277 S
	8408100048	50-278 S
	8408130296	50-352 Q
	8408130296	50-352 Q
	8408130317	50-352 A
	8408130317	50-352 A
	8408130361	50-277 P
	8408130361	50-277 P
	8408130601	50-277 S
	8408140303	50-352 E
	8408140303	50-352 E
	8408150387	50-352 Q
	8408150387	50-352 Q
	8408150404	50-352 Q
	8408150404	50-352 Q
	8408150477	50-352 Q
	8408150477	50-352 Q
	8408150602	71-9111
	8408160355	50-352 F
	8408160355	50-352 F
	8408160360*	50-352 F
	8408160379	50-352 E
	8408160379	50-352 E
	8408200147	50-352 F
	8408200147	50-352 F
	8408200206	50-352 F
	8408200206	50-352 F
	8408200262	50-352 E
	8408200262	50-352 E
	8408200286	50-352 Q
	8408200286	50-352 Q
	8408210031	50-352 E
	8408210031	50-352 E
	8408210076	50-352 K
	8408210076	50-352 K
	8408210303	50-352 A
	8408210303	50-352 A
	8408210389	50-277 P
	8408210389	50-277 P
	8408210394*	50-352 Q
	8408210429*	50-352 Q
	8408210452	50-352 F
	8408210452	50-352 F
	8408210513	50-352 A
	8408210513	50-352 A
	8408210520*	50-352 A
	8408210546	50-171 R
	8408220119	50-352 A
	8408220119	50-352 A
	8408220165	50-352 A
	8408220165	50-352 A
	8408220168*	50-352 A
	8408220168*	50-352 A
	8408220497	50-352 F
	8408220497	50-352 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408220501*	50-352 F
	8408220501*	50-352 F
	8408230185	50-277 P
	8408230185	50-277 P
	8408230258	50-352 V
	8408230292	50-352 E
	8408230292	50-352 E
	8408230297*	50-352 E
	8408240236	50-352 G
	8408240236	50-352 G
	8408240241	50-352 G
	8408240241	50-352 G
	8408240254	50-352 T
	8408240254	50-352 T
	8408240256	50-352 G
	8408240256	50-352 G
	8408240262	50-352 G
	8408270161	50-352 A
	8408270161	50-352 A
	8408270376	50-352 E
	8408270376	50-352 E
	8408280130	50-352 A
	8408280130	50-352 A
	8408280132*	50-352 A
	8408280177	50-352 F
	8408280272	50-278 P
	8408280273*	50-278 P
	8408280278*	50-278 P
	8408280388	50-352 G
	8408280388	50-352 G
	8408290107	50-277 S
	8408310004	50-277 G
	8408310004	50-277 G
	8408310007	50-352 A
	8408310008	50-352 F
	8408310008	50-352 F
	8408310012	50-352 A
	8408310012	50-352 A
	8408310018	50-352 A
	8408310018	50-352 A
	8408310058	50-352 G
	8408310058	50-352 G
	8408310110	50-352 S
	8408310110	50-352 S
	8408310124	50-352 G
	8408310146	50-352 A
	8408310146	50-352 A
	8408310223	50-352 G
	8408310413	50-352 A
	8408310413	50-352 A
	8408310417	50-352 G
Philadelphia, PA	8408220379	50-352 G
Philbrick, S S	8408020237	ACRS
Phillips Industries, Inc	8408200332	50-461 S
	8408200332	50-461 S
	8408200332	50-461 S
	8408200332	50-461 S
	8408200333	50-528 S
	8408200333	50-528 S
	8408200333	50-528 S
	8408200338	50-461 S
Phoenixville, PA	8408060179	50-352 G
Pickard, Lowe & Garrick, Inc	8408130225*	50-289 P
Pittsburgh, Univ of, Pittsburgh, PA	8408020021	50-322 T
Plateau Resources, Ltd	8408130272	40-8674
	8408240047	40-8674
	8408240351	40-7869
	8408240410	40-8698
Plymouth, MA	8408200597*	CONTRACT
Portland Cement Association	8408220090*	50-329 A
Portland General Electric Co	8408010281*	50-344 Q
	8408020050	50-344 K
	8408020051*	50-344 K
	8408020057	50-344 P
	8408020059*	50-344 P
	8408020061*	50-344 P
	8408060058	50-344 F
	8408070447	50-344 P
	8408080316	50-344 P
	8408090060	50-344 S
	8408090158	50-344 P
	8408090237	50-344 P
	8408100058	50-344 F
	8408130414	50-344 F
	8408130416*	50-344 F
	8408140202	50-344 P
	8408140289	50-344 P
	8408210139	50-344 P
	8408210292	50-344 F
	8408210415	50-344 F
	8408210438	50-344 P
	8408280149	50-344 S
	8408280242	50-344 P
	8408280253	50-344 F
Power Authority of the State of New York	8408010317	50-286 S
	8408010319	50-333 P
	8408010321*	50-333 P
	8408010322*	50-333 P
	8408030254	50-333 S
	8408030256	50-333 S
	8408030287	50-333 R
	8408070364	50-333 P
	8408070417	50-333 P
	8408070423*	50-333 P
	8408070428*	50-333 P
	8408100087	50-333 F
	8408100105*	50-333 F
	8408130309	50-286 F
	8408130313*	50-286 F
	8408140488	50-247 G
	8408150147	71-240
	8408150230	50-286 F
	8408160311	50-333 R
	8408170277	50-286 P
	8408210281*	50-333 Q
	8408210436*	50-333 Q
	8408210443	50-286 P
	8408210449*	50-286 P
	8408210451*	50-286 P
	8408220224	50-333 P
	8408230164	50-286 F
	8408230171*	50-286 F
	8408230356	50-333 S
	8408230428	50-286 R
	8408240048	50-286 S
	8408240145	50-333 P
	8408240243	50-333 S
	8408270144	50-333 S
	8408310095	50-333 P
	8408310177	50-286 Q
Power Breakers, Inc	8408240270	GA999
Public Interest Research Group, California	8408060183	50-70 Q
	8408060191*	50-70 Q
	8408060197*	50-70 Q
	8408060206*	50-70 Q
Public Service Co of Colorado	8408010006	50-267 R
	8408010008*	50-267 R
	8408020198	50-267 P
	8408030168	50-267 F
	8408070233	50-267 S
	8408070313	50-267 F
	8408080514	50-267 S
	8408080520	50-267 Q
	8408080525	50-267 P
	8408090311	50-267 P
	8408090316*	50-267 P
	8408090322*	50-267 P
	8408150306	50-267 Q
	8408160207	50-267 Q
	8408200559	50-267 P
	8408210428	50-267 Q
	8408210462	50-267 P
	8408230456	50-267 R
	8408230457*	50-267 R
	8408230459*	50-267 R
	8408280460	50-267 F
	8408290181	50-267 F
	8408290256	50-267 P
	8408290264	50-267 F
Public Service Co of New Hampshire	8408070332	50-443 A
	8408070362	50-443 F
	8408070362	50-443 F
	8408100013	50-443 S
	8408100013	50-443 S
	8408100083	50-443 S
	8408100136	50-443 S
	8408100136	50-443 S
	8408160371	50-443 A
Public Service Electric & Gas Co of New Jersey	8408010219	50-354 E

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408010234*	50-354 E
	8408010246	50-354 G
	8408020100	50-272 K
	8408020108*	50-272 K
	8408030069	50-354 E
	8408030247*	50-272 Q
	8408060176	50-354 E
	8408060279	50-354 A
	8408070326*	50-354 Q
	8408080290	50-354 E
	8408080344	50-354 A
	8408080346*	50-354 A
	8408080389	50-354 Q
	8408090076	50-311 S
	8408100065	50-354 F
	8408100067*	50-354 F
	8408100085	50-354 S
	8408100096	50-354 S
	8408100140	50-354 S
	8408130342	50-311 P
	8408130588	50-311 S
	8408140336	50-354 E
	8408150223	50-272 F
	8408150245	50-272 P
	8408150245	50-272 P
	8408160142	50-272 R
	8408160142	50-272 R
	8408160276	50-272 S
	8408160336	50-354 A
	8408160348	50-354 E
	8408170052	50-354 F
	8408170103	50-354 E
	8408170336	50-354 Q
	8408170337	50-354 A
	8408200276	50-311 R
	8408200343	50-272 P
	8408210335	50-272 P
	8408210335	50-272 P
	8408210442	50-354 A
	8408230352	50-354 A
	8408230365*	50-354 C
	8408230371*	50-354 K
	8408230501	50-272 S
	8408240117	50-272 P
	8408240117	50-272 P
	8408240273	50-354 E
	8408240288*	50-354 E
	8408240293	50-354 D
	8408280066	50-354 Q
	8408280089	50-354 Q
	8408280201	50-354 E
	8408280223	50-354 Q
	8408280448	50-354 Q
	8408290002	50-354 F
	8408290098	50-354 A
	8408290102*	50-354 A
	8408290134	50-354 E
	8408290138*	50-354 E
	8408290144*	50-354 E
	8408290149*	50-354 E
	8408290160*	50-354 E
	8408300153	50-354 A
	8408300342	50-354 S
	8408300349	50-311 S
	8408300400	50-311 S
	8408310198	50-354 K
Pullman, Inc	8408130278	71-184
	8408130283*	71-184
Radiation Management Corp	8408020228	40-8724
	8408020230*	40-8724
Re/Spec, Inc	8408150114*	71-6346
Reactor Experiments, Inc	8408060432	XPORTLIC
Rhode Island & Providence Plantation	8408210328	50-193 B
Rhode Island, State of	8408090332	PR
Rochester Gas & Electric Corp	8408030014*	50-244 Q
	8408070178*	50-244 Q
	8408070198	50-244 Q
	8408070248	50-244 P
	8408070420	50-244 Q
	8408070515	50-244 P
	8408070516*	50-244 P
	8408070524	50-244 P
	8408070526*	50-244 P
	8408080091	50-244 P
	8408100032*	50-244 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408100056*	50-244 Q
	8408130357	50-244 P
	8408140161	50-244 F
	8408140167*	50-244 F
	8408150108	50-244 P
	8408170047	50-244 P
	8408170058	50-244 P
	8408200507	50-244 Q
	8408270252	50-244 F
	8408290112	50-244 S
Rochester, NY	8408060025*	CONTRACT
Rockbestos Co	8408070334	GA999
	8408070466	GA999
Rockwell International Corp	8408030068*	50-329 A
	8408150564	70-25
	8408280007*	WASTE MGT
Rocky Mountain Energy Co	8408240031	40-8697
	8408240102	40-8380
Rogers & Associates Engineering Corp	8408310331	WASTE MGT
Sacramento Municipal Utility District	8408060006	50-312 V
	8408060011	50-312 Q
	8408060177	50-312 P
	8408130207	50-312 F
	8408140259	50-312 P
	8408160290	71-5926
	8408170342	50-312 P
	8408200339	50-312 Q
	8408240111	50-312 S
	8408240112	50-312 P
	8408270061	50-312 P
	8408270401	50-312 P
	8408280240	50-312 P
	8408290288	50-312 S
	8408310113	50-312 P
	8408310196	50-312 S
	8408310217	50-312 P
	8408310220*	50-312 P
	8408310234	50-312 P
	8408310237*	50-312 P
	8408310245	50-312 P
	8408310246*	50-312 P
Safe Energy Alliance	8408140449	50-219 Q
San Diego Gas & Electric Co	8408090194*	50-361 P
San Jose State Univ , San Jose, CA	8408020129	50-322 T
Sandia Laboratories	8408080359	NUREG
	8408080367	NUREG
	8408100147	NUREG
	8408100152	NUREG
	8408100155	NUREG
	8408130006	NUREG
	8408130577	WASTE MGT
	8408240214	WASTE MANA
	8408240260	WASTE MANA
	8408240284	WASTE MANA
	8408240320	NUREG
	8408280009*	WASTE MGT
	8408290337	WASTE MANA
	8408300178	WASTE MANA
	8408310089	NUREG
Sandvik Special Metals Corp	8408010142	XPORTLIC
Sargent & Lundy, Inc	8408030143	GA999
	8408130420*	50-454 Q
	8408270172*	50-454 Q
	8408310192	50-454 T
	8408310192	50-454 T
	8408310194*	50-454 T
	8408310194*	50-454 T
	8408310199*	50-454 T
	8408310199*	50-454 T
Science & Engineering Associates, Inc	8408080472	NUREG
Science Applications, Inc	8408130437*	CONTRACT
	8408130442*	CONTRACT
	8408130445*	CONTRACT
	8408150275*	50-219 F
	8408210180	WASTE MGT
	8408270558*	CONTRACT
	8408310262*	CONTRACT
Senate	8405180152*	50-367 H
	8408010340*	50-335 H
	8408070048*	50-416 H
	8408220296	50-289 Q
	8408230063*	50-272 H
Sequoyah Fuels Corp	8408240339	40-8768
	8408240377	40-8768
Shaw, Pittman, Potts & Trowbridge	8408010214	50-440 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408010229	50-440 Q
	8408020042	50-289 Q
	8408020054	50-400 Q
	8408070418	50-320 Q
	8408070437	50-289 Q
	8408070470	50-320 Q
	8408080217	50-400 Q
	8408090423	50-289 Q
	8408130300	50-289 Q
	8408140004	50-400 Q
	8408140007	50-289 Q
	8408140008	50-400 Q
	8408140014	50-400 T
	8408140022	50-400 Q
	8408140048	50-400 Q
	8408140057	50-400 Q
	8408140420	PR
	8408150467	50-440 Q
	8408170325	50-289 Q
	8408170330*	50-289 Q
	8408200468	50-289 Q
	8408200515	50-289 Q
	8408200557	50-289 Q
	8408200561	50-289 Q
	8408230207	50-289 Q
	8408230272	50-289 Q
	8408270115	50-289 Q
	8408280219	50-382 Q
	8408310207	50-289 Q
Sierra Club	8408310106	50-382 Q
Sigma Chemical Co	8408170220	XPORTLIC
Sinclair, M	8408170297*	50-329 T
Sinnissippi Alliance for the Environment (SAFE)	8408010177	50-454 Q
	8408010177	50-454 Q
	8408010181	50-454 Q
	8408080390	50-454 Q
Small Business Administration	8408220080*	CONTRACT
	8408220400*	CONTRACT
	8408220404*	CONTRACT
	8408290349*	CONTRACT
Society Against Nuclear Energy	8408140449	50-219 Q
South Carolina Electric & Gas Co	8408060103	50-395 P
	8408060134	50-395 P
	8408060140	50-395 P
	8408070373	50-395 P
	8408070402	50-395 Q
	8408080124	50-395 P
	8408080187	50-395 K
	8408080192*	50-395 K
	8408080196*	50-395 K
	8408080200*	50-395 K
	8408080207*	50-395 K
	8408080214*	50-395 K
	8408080221*	50-395 K
	8408080226*	50-395 K
	8408080228*	50-395 K
	8408080232*	50-395 K
	8408080237*	50-395 K
	8408080240*	50-395 K
	8408080244*	50-395 K
	8408080248*	50-395 K
	8408080251*	50-395 K
	8408080254*	50-395 K
	8408080260*	50-395 K
	8408080262*	50-395 K
	8408080265*	50-395 K
	8408090143	50-395 S
	8408090241	50-395 S
	8408100002	50-395 F
	8408100012*	50-395 F
	8408130340	50-395 S
	8408130344	50-395 F
	8408140265	50-395 P
	8408160525	71-9151
	8408170308	50-395 V
	8408170313*	50-395 V
	8408170318*	50-395 V
	8408200340	50-395 S
	8408200344	50-395 S
	8408230507	50-395 S
	8408240002	50-395 P
	8408270174*	50-395 Q
	8408280104	50-395 P
	8408280114*	50-395 P
	8408280287	50-395 Q
	8408300514	50-395 S
Southern California Edison Co	8408010226	50-206 P
	8408010240	50-361 P
	8408010272	50-206 P
	8408010304	50-361 S
	8408030123	50-206 F
	8408030123	50-206 F
	8408030166	50-206 P
	8408030169*	50-206 P
	8408060034	50-361 S
	8408060039*	50-361 S
	8408060080	50-361 P
	8408060080	50-361 P
	8408060112	50-361 Q
	8408060112	50-361 Q
	8408060223	50-361 S
	8408070379	50-206 S
	8408070411	50-206 Q
	8408070411	50-206 Q
	8408080489	50-361 S
	8408090187	50-361 P
	8408090187	50-361 P
	8408090194*	50-361 P
	8408090194*	50-361 P
	8408090201*	50-361 P
	8408090201*	50-361 P
	8408090418	50-362 S
	8408100091	50-361 P
	8408100091	50-361 P
	8408100115	50-361 P
	8408130203	50-206 Q
	8408140216	50-206 S
	8408140260	50-361 Q
	8408140260	50-361 Q
	8408160215	50-206 P
	8408170059	50-361 S
	8408200335	50-361 Q
	8408200335	50-361 Q
	8408210165	50-206 P
	8408210179*	50-206 P
	8408210479	50-362 Q
	8408220098	50-361 R
	8408220098	50-361 R
	8408230178	50-206 P
	8408240084	50-361 S
	8408240168	50-206 P
	8408240200	50-362 S
	8408240267	50-361 P
	8408240267	50-361 P
	8408240294	50-361 P
	8408240297*	50-361 P
	8408270409	50-361 P
	8408270409	50-361 P
	8408280225	50-361 S
	8408280296	50-361 S
	8408300163	50-361 P
	8408300163	50-361 P
	8408300165*	50-361 P
	8408300165*	50-361 P
	8408300232	50-206 S
	8408300492	50-361 S
Southern California, Univ of, Los Angeles, CA	8408160405*	50-508 A
Southern Co Services, Inc	8408020106	NUREG
Spiegel & McDiarmid	8408030154	50-275 Q
	8408290342	50-458 M
Stamiris, B	8408020107*	50-329 Q
	8408170292*	50-329 T
Standardized Nuclear Unit Power Plant System	8407310144	50-482 A
	8408010386	50-482 S
	8408010386	50-482 S
	8408010386	50-482 S
	8408030255	50-482 S
	8408030255	50-482 S
	8408030255	50-482 S
	8408060234	50-482 A
	8408160063	50-482 F
	8408160063	50-482 F
	8408210313	50-482 A
	8408270389	50-482 F
	8408270389	50-482 F
	8408300090	50-482 F
	8408310101	50-482 A

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
State, Dept of	8408010138	XPORTLIC	
Steel, Hector & Davis	8408090397	50-250	Q
	8408090397	50-250	Q
	8408090437	50-250	Q
	8408090437	50-250	Q
	8408140236*	50-250	Q
	8408140236*	50-250	Q
	8408140253*	50-250	Q
	8408140253*	50-250	Q
	8408140277*	50-250	Q
	8408140277*	50-250	Q
Stewart & Stevenson Services	8408100106*	50-461	A
Stone & Webster Engineering Corp	8408030136	QA999	
	8408060138*	50-206	S
	8408210382*	TOPREP	
	8408280203*	50-412	E
	8408310213*	50-412	F
Stone & Webster, Inc	8406010038	50-329	S
	8408150714*	50-329	A
	8408240132	50-329	R
	8408240134*	50-329	R
	8408240138*	50-329	R
	8408240143*	50-329	R
	8408240148*	50-329	R
	8408240152*	50-329	R
	8408240159*	50-329	R
Streich, Lang, Weeks & Cardon	8407120136	50-528	D
Suffolk County, NY	8408010239	50-322	Q
	8408020021	50-322	T
	8408030074	50-322	Q
	8408030086	50-322	Q
	8408030105	50-322	Q
	8408030112*	50-322	Q
	8408070308	50-322	Q
	8408070424	50-322	Q
	8408080338	50-322	Q
	8408080410	50-322	Q
	8408130341	50-322	Q
	8408140013	50-322	T
	8408140017*	50-322	T
	8408140466	50-322	Q
	8408140470	50-322	Q
	8408140477*	50-322	Q
	8408160210	50-322	Q
	8408160224*	50-322	Q
	8408170315	50-322	Q
	8408210388	50-322	Q
	8408230194	50-322	Q
	8408230199	50-322	Q
	8408230264	50-322	Q
	8408280249	50-322	Q
	8408280405	50-322	Q
Sugarman & Denworth	8408010223	50-352	Q
	8408010223	50-352	Q
	8408010228*	50-352	Q
	8408010228*	50-352	Q
	8408010248	50-352	Q
	8408090226	50-352	Q
	8408090233*	50-352	Q
	8408130368	50-352	Q
	8408140484	50-352	Q
Sunflower Alliance	8408010229	50-440	Q
	8408280437	50-440	Q
TDI (Transamerica Delaval, Inc) Owners Group	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290062	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8405290179	50-206	S
	8408060050	50-206	S
	8408060102	50-206	S
	8408060324	50-206	S
	8408160394	50-206	S
	8408160395	50-206	S
	8408290179	50-206	S
TERA Corp	8408140012*	50-275	P
	8408150741*	50-329	A
	8408150741*	50-329	A
	8408150745*	50-329	A
	8408150745*	50-329	A
TMI Public Health Fund	8408270149*	50-289	Q
	8408310157*	50-289	P
	8408310239*	50-289	P
Tayloe Associates	8408100030	50-454	T
	8408150524	50-413	Q
	8408160076	50-322	Q
	8408160079	50-352	Q
	8408160099	50-352	Q
	8408160103	50-352	Q
	8408160109	50-413	Q
	8408160112	50-352	Q
	8408160118	50-322	Q
	8408160123	50-322	Q
	8408160128	50-400	Q
Tech/Ops	8408020201	71-9021	
Technology for Energy Corp	8408230097	50-327	P
Teledyne Engineering Services	8408060016*	50-293	P
Teledyne Geotech	8408310310	XPORTLIC	
Teledyne Isotopes	8408210555*	50-171	R
Teleflex, Inc	8408150724	XPORTLIC	
	8408200314	XPORTLIC	
Temple Univ , Philadelphia, PA	8408170326*	50-454	T
Tennessee Valley Authority	8408010172	50-390	A
	8408010172	50-390	A
	8408010344	50-259	P
	8408010344	50-259	P
	8408010344	50-259	P
	8408020145	50-259	F
	8408020145	50-259	F
	8408020145	50-259	F
	8408020151*	50-259	F
	8408020151*	50-259	F
	8408020151*	50-259	F
	8408020156*	50-259	F
	8408020156*	50-259	F
	8408020156*	50-259	F
	8408020242	50-275	O
	8408020242	50-275	O
	8408030015	50-259	F
	8408030019	50-327	P
	8408030025*	50-327	P
	8408030026	50-327	P
	8408030026	50-327	P
	8408030032	50-390	F
	8408030032	50-390	F
	8408030128	50-390	A
	8408030128	50-390	A
	8408030155	50-438	A
	8408030257	50-259	S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408060021	50-259 P
	8408060029*	50-259 P
	8408060098	50-259 R
	8408060113	50-259 S
	8408060220	50-328 P
	8408060241	50-327 S
	8408060254	50-327 F
	8408060254	50-327 F
	8408070133	50-327 P
	8408070133	50-327 P
	8408070370	50-259 P
	8408070370	50-259 P
	8408070370	50-259 P
	8408070375*	50-259 P
	8408070375*	50-259 P
	8408070375*	50-259 P
	8408070396	NUREG
	8408080518	50-259 S
	8408090020	50-259 S
	8408090024	50-438 S
	8408090025	50-438 S
	8408090025	50-438 S
	8408090028	50-438 S
	8408090028	50-438 S
	8408090033	50-438 S
	8408090033	50-438 S
	8408090057	50-438 S
	8408090065	50-390 S
	8408090078	50-390 S
	8408090156	50-327 S
	8408090268	50-438 S
	8408090279	50-438 S
	8408090341	50-259 S
	8408090416	50-438 S
	8408090416	50-438 S
	8408100024	50-327 F
	8408100024	50-327 F
	8408130275	50-390 A
	8408130275	50-390 A
	8408130280*	50-390 A
	8408130280*	50-390 A
	8408130375	50-390 A
	8408140331	50-259 S
	8408140375	50-259 P
	8408140532	50-327 P
	8408140532	50-327 P
	8408140535*	50-327 P
	8408140535*	50-327 P
	8408150213	50-296 Q
	8408160058	50-438 S
	8408160066	50-438 S
	8408160154	50-390 S
	8408160154	50-390 S
	8408160173	50-390 S
	8408160173	50-390 S
	8408160173	50-390 S
	8408160179	50-390 S
	8408160179	50-390 S
	8408160179	50-390 S
	8408160200	50-438 S
	8408160269	50-328 S
	8408160434	50-438 S
	8408160453	50-327 S
	8408160493	50-327 S
	8408160508	50-259 S
	8408160518	50-259 S
	8408160519	50-259 S
	8408160522	50-327 S
	8408170053	50-328 S
	8408200131	50-259 P
	8408200300	50-259 S
	8408200412	50-296 S
	8408210435	50-390 A
	8408220137	50-259 P
	8408230192*	50-259 Q
	8408230192*	50-259 Q
	8408230192*	50-259 Q
	8408230208*	50-259 Q
	8408230208*	50-259 Q
	8408230208*	50-259 Q
	8408230509	50-327 S
	8408240109	50-259 Q
	8408270098	50-438 A
	8408270150	50-296 S
	8408270156	50-327 P
	8408270156	50-327 P
	8408270162*	50-327 P
	8408270162*	50-327 P
	8408270199*	50-259 Q
	8408270366	50-259 R
	8408270369*	50-259 R
	8408270370*	50-327 Q
	8408270374*	50-259 R
	8408270468*	50-438 Q
	8408270475*	50-438 Q
	8408270483*	50-438 Q
	8408280086	50-328 P
	8408280100	50-438 Q
	8408280116*	50-259 Q
	8408280220	50-260 P
	8408280222*	50-260 P
	8408280226*	50-260 P
	8408280349	50-259 S
	8408290245	50-259 F
	8408290245	50-259 F
	8408290250	50-390 A
	8408290250	50-390 A
	8408290355	50-390 A
	8408290355	50-390 A
	8408300469*	50-327 Q
	8408300477*	50-327 Q
	8408310050	50-327 S
Texas A&M Univ , College Station, TX	8408150371	50-59 R
Texas Nuclear Div (subs of Ramsay Engineering Co)	8408150135	XPORTLIC
Texas Tech Univ , Lubbock, TX	8408220327	NUREG
Texas Utilities Electric Co (formerly Texas Utilities Generating Co)	8408020072	NUREG
	8408030115	50-445 S
	8408030153	50-445 A
	8408030153	50-445 A
	8408060165	50-445 A
	8408060184	50-445 R
	8408070105	50-445 T
	8408070105	50-445 T
	8408080026	50-445 T
	8408080026	50-445 T
	8408080032	50-445 T
	8408080032	50-445 T
	8408080051	50-445 T
	8408080051	50-445 T
	8408080100	50-445 T
	8408080100	50-445 T
	8408080146	50-445 T
	8408080162	50-445 Q
	8408080162	50-445 Q
	8408080168*	50-445 Q
	8408080168*	50-445 Q
	8408080245	50-445 T
	8408080245	50-445 T
	8408080272	50-445 T
	8408080272	50-445 T
	8408080294	50-445 T
	8408080294	50-445 T
	8408080413	50-445 Q
	8408080413	50-445 Q
	8408090044	50-445 S
	8408090044	50-445 S
	8408090105*	50-445 A
	8408130093	50-445 Q
	8408130093	50-445 Q
	8408130305	50-445 Q
	8408140393	50-445 K
	8408140393	50-445 K
	8408160157	50-445 A
	8408160157	50-445 A
	8408160185	50-445 S
	8408160185	50-445 S
	8408160204*	50-445 Q
	8408160330	50-445 Q
	8408160330	50-445 Q
	8408160335	50-445 A
	8408160335	50-445 A
	8408160340*	50-445 A
	8408160340*	50-445 A
	8408160412	50-445 A
	8408160412	50-445 A
	8408160510	50-445 S
	8408170065	50-445 R
	8408170065	50-445 R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408200295	50-445 S
	8408200295	50-445 S
	8408220331	50-445 Q
	8408220331	50-445 Q
	8408220367	50-445 T
	8408220367	50-445 T
	8408220371*	50-445 T
	8408220371*	50-445 T
	8408220374*	50-445 T
	8408220374*	50-445 T
	8408220380*	50-445 T
	8408220380*	50-445 T
	8408220381*	50-445 T
	8408220381*	50-445 T
	8408220385*	50-445 T
	8408220385*	50-445 T
	8408220388*	50-445 T
	8408220388*	50-445 T
	8408220393*	50-445 T
	8408220393*	50-445 T
	8408220396*	50-445 T
	8408220396*	50-445 T
	8408220403*	50-445 T
	8408220403*	50-445 T
	8408220405*	50-445 T
	8408220405*	50-445 T
	8408220412*	50-445 Q
	8408230187	50-445 Q
	8408230187	50-445 Q
	8408230257	50-445 Q
	8408230319	50-445 Q
	8408230319	50-445 Q
	8408230390	50-445 F
	8408230397*	50-445 F
	8408230400*	50-445 F
	8408230432	50-445 T
	8408270030	50-445 A
	8408270030	50-445 A
	8408270067	50-445 A
	8408270067	50-445 A
	8408270075	50-445 A
	8408270123	50-445 A
	8408270123	50-445 A
	8408270124	50-445 A
	8408270132	50-445 A
	8408270132	50-445 A
	8408270154	50-445 Q
	8408270154	50-445 Q
	8408270271	50-445 X
	8408270271	50-445 X
	8408270368	50-445 F
	8408270368	50-445 F
	8408280083	50-445 Q
	8408280083	50-445 Q
	8408280142	50-445 A
	8408280142	50-445 A
	8408280156	50-445 Q
	8408280156	50-445 Q
	8408280165	50-445 Q
	8408280165	50-445 Q
	8408280190	50-445 A
	8408280190	50-445 A
	8408280218	50-445 A
	8408280218	50-445 A
	8408280221	50-445 Q
	8408280221	50-445 Q
	8408280251	50-445 Q
	8408280251	50-445 Q
	8408280265	50-445 Q
	8408280375	50-445 S
	8408280375	50-445 S
	8408280384	50-445 S
	8408280384	50-445 S
	8408280468	50-445 S
	8408280468	50-445 S
	8408290125	50-445 S
	8408290125	50-445 S
	8408290208	50-445 K
	8408290208	50-445 K
	8408290211*	50-445 K
	8408290211*	50-445 K
	8408300239	50-445 A
	8408300239	50-445 A
	8408310216	50-445 Q
Texas, State of	8408020110	PR
	8408080038*	COMMISSION
	8408160479	WASTE MGT
Three Mile Island Alert	8408060201	50-289 Q
	8408060224*	50-289 Q
	8408070382	50-289 Q
	8408070408	50-289 Q
	8408140010	50-289 Q
	8408140449	50-219 Q
	8408140449	50-219 Q
	8408140479	50-289 Q
	8408220258	50-289 Q
	8408220263*	50-289 Q
	8408220366	50-289 Q
	8408240250	50-219 Q
	8408240251	50-289 Q
Toledo Edison Co	8408010313	50-346 S
	8408060322	50-346 F
	8408070301	50-346 X
	8408070335	50-346 P
	8408080306	50-346 S
	8408080508	50-346 S
	8408090026	50-346 S
	8408100061	50-346 F
	8408130390*	50-346 Q
	8408130395*	50-346 Q
	8408130411*	50-346 Q
	8408130421	50-346 P
	8408130428*	50-346 P
	8408140410	50-346 P
	8408160199	50-346 S
	8408160497	50-346 S
	8408170214	50-346 Q
	8408200073	50-346 F
	8408200126	50-346 F
	8408200135	50-346 P
	8408210345	50-346 Q
	8408210456	50-346 P
	8408230104	50-346 R
	8408280087	50-346 F
	8408280145	50-346 F
	8408280197	50-346 K
	8408280198*	50-346 K
Torrey Pines Technology	8408060419	50-352 R
	8408310023	50-352 R
Transamerica Delaval, Inc	8408230229	QA999
Transnuclear, Inc	8408140469	71-9016
	8408140476*	71-9016
	8408140485*	71-9016
	8408150394	71-9016
	8408150600*	71-9016
	8408150647	71-9016
	8408150654*	71-9016
	8408210314	PR
	8408230562	XPORTLIC
	8408230563*	XPORTLIC
	8408310321*	XPORTLIC
	8408310325*	XPORTLIC
Transportation, Dept of, Federal Highway Administration	8408240165	50-354 D
Trial Lawyers for Public Justice	8408090200	50-445 Q
	8408090200	50-445 Q
	8408090206*	50-445 Q
	8408090206*	50-445 Q
	8408140495	50-445 Q
	8408230173	50-445 Q
	8408240247	50-445 T
	8408280157	50-445 Q
	8408290319	50-445 Q
Turk, J	8408060209	50-70 Q
Tuskegee Institute, Tuskegee, AL	8408060426*	CONTRACT
U S Ecology, Inc (formerly Nuclear Engineering, Inc)	8408010034	27-48
	8408060026	27-39
	8408130081*	WASTE MGT
U.S Gypsum Co	8408060045	WASTE MGT
	8408060047*	WASTE MGT
U S. Merchant Marine Academy, Kings Point, NY	8408020129	50-322 T
UNETCO Minerals Corp (subs. of Union Carbide Corp)	8408080144	40-8681
Uniformed Services Univ. of Health Sciences	8408300237*	50-289 P
Union 76 Minerals Exploration Co	8408270157	40-8584
Union Carbide Corp	8407230131	40-299
	8408060383	40-299

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408090556	70-687
	8408150247	70-687
	8408240018	40-299
	8408240344	40-299
	8408240384	40-299
	8408240396	40-299
	8408240400*	40-299
	8408240412	40-299
	8408270077	40-299
	8408270120	40-299
	8408270188	40-299
	8408280399	40-299
Union Electric Co	8406140221	50-483 A
	8408030098	50-483 P
	8408060148	50-483 S
	8408060286	50-483 P
	8408060287*	50-483 P
	8408070123	50-483 S
	8408090271	50-483 S
	8408100034*	50-483 Q
	8408130397	50-483 F
	8408140129	50-483 F
	8408140385	50-483 P
	8408140404*	50-483 Q
	8408160176	50-483 S
	8408160256	50-483 S
	8408210402	50-483 F
	8408220278	50-483 P
	8408230427	50-483 S
	8408230546	50-483 S
	8408240193	50-483 S
	8408240315	50-483 S
	8408270393	50-483 F
Union Minerals	8408240408	40-8584
	8408240417	40-8584
	8408240423*	40-8584
	8408270238	40-8584
	8408270243*	40-8584
Union of Concerned Scientists	8408020040	50-289 Q
	8408070027*	50-447 H
	8408130396	50-289 Q
	8408140035	50-289 Q
	8408140448	50-247 Q
	8408140474	50-289 Q
	8408150145	50-289 Q
	8408160339	50-447 A
	8408170335	50-289 Q
	8408220362	50-289 Q
	8408230325	50-289 Q
	8408240245	50-289 Q
	8408270359	50-289 Q
	8408280493	50-289 Q
United Nuclear Corp	8408010024	70-820
	8408020096	70-820
	8408290185	NUREG
	8408300134	70-371
United Technologies Corp	8408230198*	40-791
Uranerz USA, Inc	8408240341	40-8783
Uranium Resources, Inc	8408240353	40-8784
Utility Nuclear Waste Management Group	8408070457*	PRM
Utility Safety Classification Group	8408090106*	COMMISSION
Venice Alliance for Survival	8408130346	PR
Vermont Yankee Nuclear Power Corp	8408020082	50-271 Q
	8408060226	50-271 Q
	8408080041	50-271 F
	8408090085	50-271 Q
	8408160052	50-271 P
	8408160056*	50-271 P
	8408230534	50-271 S
	8408230542	50-271 S
	8408240004	50-271 P
	8408270152	50-271 R
	8408280055	50-271 P
	8408280307	50-271 S
	8408300478	50-271 S
	8408300488	50-271 S
	8408310093	50-271 F
	8408310279	50-271 H
Virginia Electric & Power Co	8408010056	50-280 S
	8408010060*	50-280 S
	8408010069*	50-280 S
	8408010076*	50-280 S
	8408020028	50-338 F
	8408020028	50-338 F
	8408020041	50-280 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408020041	50-280 Q
	8408020041	50-280 Q
	8408020041	50-280 Q
	8408020041	50-280 Q
	8408020132	50-280 F
	8408070039	50-280 F
	8408070039	50-280 F
	8408070039	50-280 F
	8408070039	50-280 F
	8408070039	50-280 F
	8408070400	50-338 F
	8408070400	50-338 F
	8408070406*	50-338 F
	8408070489	50-280 V
	8408090149	50-338 P
	8408090235	50-338 P
	8408090235	50-338 P
	8408090239*	50-338 P
	8408090239*	50-338 P
	8408100098	50-280 F
	8408130400*	50-338 Q
	8408130403*	50-338 Q
	8408130403*	50-338 Q
	8408130438*	50-338 Q
	8408130438*	50-338 Q
	8408130585	50-280 P
	8408150464	50-338 Q
	8408150464	50-338 Q
	8408160039	50-280 P
	8408160406	50-280 F
	8408160406	50-280 F
	8408170222	50-280 F
	8408170222	50-280 F
	8408170300	50-338 P
	8408200477	50-338 Q
	8408200477	50-338 Q
	8408210132	50-280 P
	8408210132	50-280 P
	8408210375	50-338 P
	8408210375	50-338 P
	8408220171	50-280 R
	8408220171	50-280 R
	8408240280	50-280 P
	8408270448*	50-280 Q
	8408280150	50-280 Q
	8408280150	50-280 Q
	8408280150	50-280 Q
	8408280150	50-280 Q
	8408280150	50-280 Q
	8408290193	50-338 S
	8408300177	50-338 Q
	8408300177	50-338 Q
	8408310150	50-338 Q
	8408310150	50-338 Q
Virginia Polytechnic Institute & State Univ , Blacksburg, VA	8408220156*	CONTRACT
Virginia, Univ of, Charlottesville, VA	8408010350	50-62 F
	8408010391	50-62 F
	8408310390*	CONTRACT
Volpe, Boskey & Lyons	8408080197	50-348 M
	8408080197	50-348 M
	8408080202	50-348 M
	8408080202	50-348 M
	8408080241	50-348 M
	8408080241	50-348 M
W J Woolley Co	8408130137	PT21
WESTEC Services, Inc	8408070053*	CONTRACT
Walworth Co (subs of IU International Corp)	8408210093	71-39
Warren Wilson College, Swannanoa, NC	8408280360	50-295 P
	8408280383*	50-295 P
	8408280387*	50-295 P
Washington Public Power Supply System	8406070192	50-397 R
	8408030280	50-397 S
	8408060233	50-397 S
	8408060235	50-397 S
	8408060301	50-397 S
	8408070247	50-397 Q
	8408070275	50-305 F
	8408070325	50-397 P
	8408070333	50-397 P
	8408080175	50-460 A
	8408090262	50-397 P
	8408090443	50-397 S
	8408090450	50-397 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408090458	50-397 S
	8408160404	50-508 A
	8408170031	50-460 A
	8408170255	50-508 Q
	8408200132	50-397 S
	8408200317	50-460 S
	8408200341	50-397 S
	8408270073	50-397 P
	8408270153	50-397 P
	8408280320	50-397 R
	8408290017	50-397 S
	8408290024	50-397 S
	8408290030	50-397 S
	8408290116	50-397 S
	8408290143	50-397 S
Washington State Univ , Pullman, WA	8408020085	PR
	8408300293	50-27 R
Washington, State of	8406210504	WASTE MGT
	8408210064	WASTE MGT
	8408210071	WASTE MGT
	8408220240	WASTE MGT
Washington, Univ of, Seattle, WA	8408010158	NUREG
	8408060386	NUREG
	8408160405*	50-508 A
	8408170040	50-139 F
Water Engineering & Technology, Inc	8408060431	WASTE MGT
Watkins, L B	8408010258	50-458 Q
Weed Instrument Co , Inc	8408150001	QA999
Western Nuclear, Inc (subs of Phelps Dodge Corp)	8408270038	40-8684
	8408270131	40-1162
Westinghouse Electric Corp	8407230200	TOPREP
	8407230203*	TOPREP
	8408010040	70-1151
	8408030037	QA999
	8408060116	TOPREP
	8408060125*	TOPREP
	8408060231*	50-328 P
	8408070257*	50-244 P
	8408070282*	50-305 F
	8408070288*	50-305 F
	8408070419*	50-412 F
	8408070465*	50-498 A
	8408080278	50-601 K
	8408080280*	50-413 E
	8408080284*	50-413 E
	8408080286*	50-601 K
	8408080289*	50-601 K
	8408080292*	50-601 K
	8408080294	50-445 T
	8408080295*	50-601 K
	8408080298*	50-601 K
	8408080301*	50-601 K
	8408080304*	50-601 K
	8408080307*	50-601 K
	8408080309*	50-601 K
	8408080312*	50-601 K
	8408080315*	50-601 K
	8408080318*	50-601 K
	8408080320*	50-601 K
	8408080323*	50-601 K
	8408080330*	50-601 K
	8408080342*	50-601 K
	8408080343*	50-601 K
	8408080345*	50-601 K
	8408080347*	50-601 K
	8408140018*	50-400 T
	8408140226*	50-250 Q
	8408140262*	50-250 Q
	8408140278	50-601 A
	8408150237	XPORTLIC
	8408150583	70-1151
	8408150589*	70-1151
	8408150719	XPORTLIC
	8408150730	XPORTLIC
	8408160352	70-1151
	8408160373*	50-443 A
	8408160378*	50-443 A
	8408200493*	XPORTLIC
	8408210164	XPORTLIC
	8408210169	XPORTLIC
	8408210489*	TOPREP
	8408220321*	50-454 E
	8408230340	TOPREP
	8408230346*	TOPREP
	8408230488	XPORTLIC
	8408230498	XPORTLIC
	8408230510	XPORTLIC
	8408240349	40-8502
	8408240379	NUREG
	8408240381	40-8502
	8408240397	40-8502
	8408240409	40-8502
	8408240427	40-8502
	8408270028	40-8585
	8408270029*	40-8585
	8408270031	40-8502
	8408270032	40-8502
	8408270034*	40-8502
	8408270069	40-8502
	8408270138	40-8502
	8408270177	40-8502
	8408270246*	50-266 P
	8408270312	TOPREP
	8408270449	TOPREP
	8408270545	40-8502
	8408270562	40-8502
	8408270564	40-8502
	8408270571	40-8502
	8408280148	70-1151
	8408280259	TOPREP
	8408280260*	TOPREP
	8408290560	70-1151
	8408310194*	50-454 T
Westinghouse Hittman Nuclear, Inc	8408200187	WASTE MGT
Westinghouse Operating Plants Owners Group	8408210486	TOPREP
Weston Geophysical Corp	8408290295	WASTE MANA
Wheeler Basin Regional Library, Decatur, AL	8408080067*	CONTRACT
Whicher, J M	8406260276	50-454 Q
	8408280194	50-367 Q
Whiting Corp	8408010269*	50-155 Q
Williams & Associates	8408070087*	CONTRACT
Wilson Hill Associates, Inc	8408220080*	CONTRACT
Wisconsin Electric Power Co	8407310166	50-266 K
	8407310166	50-266 K
	8408020148*	50-266 K
	8408020148*	50-266 K
	8408020155*	50-266 F
	8408030167	50-266 F
	8408030167	50-266 F
	8408030170*	50-266 F
	8408030170*	50-266 F
	8408060127	50-266 P
	8408070030	50-266 P
	8408070030	50-266 P
	8408070245	50-266 P
	8408070245	50-266 P
	8408070328	50-266 P
	8408070328	50-266 P
	8408070330*	50-266 P
	8408070330*	50-266 P
	8408100052*	50-266 Q
	8408100052*	50-266 Q
	8408170203*	50-266 Q
	8408170203*	50-266 Q
	8408210232	50-266 R
	8408210232	50-266 R
	8408210343	50-266 F
	8408270233	50-266 P
	8408280128	50-266 P
	8408280216	50-266 P
	8408300511	50-266 S
	8408300518	50-266 S
	8408310229	50-266 R
Wisconsin Public Service Corp	8407260161	50-305 K
	8407260166*	50-305 K
	8408020073	50-305 P
	8408020078*	50-305 P
	8408060093	50-305 P
	8408060244	50-305 S
	8408070292	50-305 F
	8408070296*	50-305 F
	8408080033	50-305 S
	8408080510	50-305 S
	8408100019	50-305 F
	8408100078	50-305 P
	8408160211	50-305 R
	8408220284	50-305 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8408240199	50-305 P
	8408240205*	50-305 P
	8408280144	50-305 F
	8408280475	50-305 P
	8408310122	50-305 P
	8408310126*	50-305 P
Wisconsin's Environmental Decade	8408210349	PR
Wisconsin, Univ of, Madison, WI	8408140521	50-156 F
Women's International League for Peace & Freedom	8408140449	50-219 G
Woodward-Clyde Consultants, Inc	8408160413*	50-308 A
Worcester Polytechnic Institute, Worcester, MA	8408070345	PR
Wyle Laboratories	8408210518*	50-352 A
Wyoming Mineral Corp	8408240402	40-8502
Wyoming, State of	8408240040	40-8727
	8408240374	WASTE MGT
	8408240375	40-8768
	8408240399	40-4492
	8408240406	40-8584
	8408270042	40-8502
	8408270104	40-4492
	8408270424	40-8502
	8408270550	40-8502
Yankee Atomic Electric Co	8408010141	50-29 P
	8408020039	50-29 P
	8408020097*	50-271 G
	8408070332	50-443 A
	8408070362	50-443 F
	8408070362	50-443 F
	8408070365*	50-443 F
	8408070393	50-29 F
	8408070472	50-29 P
	8408070478*	50-29 P
	8408090104	50-29 S
	8408090182*	50-309 P
	8408100013	50-443 S
	8408100013	50-443 S
	8408100053	50-29 G
	8408100136	50-443 S
	8408100136	50-443 S
	8408130322	50-29 F
	8408130354*	50-29 G
	8408140304	50-29 F
	8408140312	50-29 P
	8408160357	50-271 F
	8408160371	50-443 A
	8408160529	50-29 S
	8408210350	50-29 S
	8408210419	50-29 P
	8408220012	50-29 F
	8408230162	50-29 P
	8408230540	50-29 S
	8408240153	50-29 F
	8408300441	50-29 S

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
1-263-07-557-48	8408150275*	50-219 F	TAC 51185
125	8408230459*	50-267 R	
126	8408230497*	50-267 R	
170-107	8408170339*	50-354 G	
170-109	8408170342*	50-354 G	
19	8408210555*	50-171 R	
20	8408270276*	50-454 E	
23A1739 R00	8408280211*	50-331 P	
2BVM-179	8408280203*	50-412 E	
37	8408270284*	50-454 E	
41	8408210549*	50-171 R	
46960-4	8408210518*	50-352 A	
580 R00	8408270290*	50-219 P	
81	8408270292*	50-454 E	
84-M-004 R02	8408060200*	50-416 G	
97	8408270296*	50-454 E	
AECC-2-NP A02	8408140204*	TOPREP	
BAW-1638	8408210393*	50-338 P	
BAW-1794	8408210387*	50-338 P	
BAW-1834	8408140413*	50-346 P	
BAW-1836	8408140433*	50-313 P	
BFN-REP R14	8408020156*	50-259 F	
BWIP STP 1 0 DRFT	8408200491*	WASTE MGT	
C-50918	8408010224*	50-354 E	
CEN-176(S)-NP R02	8408270418*	50-361 P	
CEN-266(S)-NP R00	8408270416*	50-361 P	
CEN-269(S)-NP R00	8408270412*	50-361 P	
CEN-281(S)-NP	8408010256*	50-361 P	
CEN-284(S)-NP	8408010247*	50-361 P	
CEN-286(V) R00	8408100137*	50-528 A	
CPL-19-103 R01	8408160132*	50-324 G	
DBD-SY-1 R01	8408230400*	50-445 F	
DOE/EIS-0099-F	8408010053*	WASTE MGT	
DOE/EIS-0099-F	8408010063*	WASTE MGT	
DOE/NE-8H01 ERR	840802023A	WASTE MGT	
DOE/NE-8H02 ERR	8408020239*	WASTE MGT	
DOE/S-0014/L	8408290352*	COMMISSION	
E-Y-YR-83033-4 R00	8408210426*	50-29 P	
EGG-FM-6521	8408010027*	50-298 P	TAC 46657
EG/IES(84)-164	8408160340*	50-445 A	
FAAA-84-2-14	8405290075*	50-206 S	
FAAA-84-3-16	8405290271*	50-206 S	
FAAA-84-5-23	8408210370*	50-413 P	PA07702
FAAA-84-5-7	8408160397*	50-206 S	
FAAA-84-6-53	8408160403*	50-206 S	PA07596
FAAA-84-6-56	8408060387*	50-206 S	
FAI/84-9 DRFT	8408230112*	50-327 P	
FTR-75744-1	8408100106*	50-461 A	
INPO 84-013	8408220315*	ORG	
NPR-820 R02	8408100080*	50-220 P	
NEDO-12725A	8408090337*	50-73 P	BONEDO26
NEDO-21082-03 APP A	8408280209*	50-331 P	
NEDO-24284-A	8408160384*	TOPREP	
NEDO-30477 R01	8408170262*	50-263 P	
NEDO-30603	8408270175*	50-331 P	
NUREG-0020 V08 N06	8408160191	NUREG	
NUREG-0040 V08 N02	8408130186	NUREG	
NUREG-0090 V07 N01	8408290353	NUREG	
NUREG-0304 V09 N02	8408300279	NUREG	
NUREG-0386 D03	8408230125	NUREG	
NUREG-0420 S06	8408220107	50-322 E	
NUREG-0540 V06 N05	8408130049	NUREG	
NUREG-0675 S24	8408130002	50-275 E	
NUREG-0675 S25	8408160080	50-275 E	
NUREG-0675 S26	8408220346	50-275 E	
NUREG-0675 S27	8408160250	50-275 E	
NUREG-0680 S05	8408060413	50-289 P	
NUREG-0748 V04 N06	8408080363	NUREG	
NUREG-0750 V19 N03	8408240187	NUREG	
NUREG-0776 S07	8406190069	50-387 E	
NUREG-0853 S03	8406190045	50-461 E	
NUREG-0933 S01	8408220265	NUREG	
NUREG-0936 V03 N02	8408100149	NUREG	
NUREG-0940 V03 N02	8408220308	NUREG	
NUREG-0954 S03	8408070009	50-413 E	
NUREG-1020LD V01	8407130502	50-289 G	
NUREG-1031	8408160262	50-423 E	
NUREG-1054	8408300292	NUREG	
NUREG-1064	8408010148	50-423 D	
NUREG-1068	8408290158	50-352 A	
NUREG-1072	8408130011	50-413 P	
NUREG-1073	8408220325	50-458 D	
NUREG-1075	8408090370	NUREG	
NUREG/BR-0018 R02	8408080371	NUREG	
NUREG/BR-0025 V10 N6	8408300289	NUREG	
NUREG/BR-0081	8408220378	NUREG	
NUREG/CP-0053	8408240249	NUREG	LA-10127-C
NUREG/CR-1740 R01	8408240382	NUREG	EGG-2307
NUREG/CR-2000 V03 N6	8408070007	NUREG	ORNL/NSIC-200
NUREG/CR-2000 V03 N7	8408300287	NUREG	ORNL/NSIC-200
NUREG/CR-2331 V03 N3	8408010179	NUREG	BNL-NUREG-51454
NUREG/CR-3053	8408130265	NUREG	IEB-80-08
NUREG/CR-3139	8408130007	NUREG	ORNL/ENG/TM-25
NUREG/CR-3273	8408100155	NUREG	SAND83-1022
NUREG/CR-3346	8408130009	NUREG	ORNL/TM-8795
NUREG/CR-3369	8408130006	NUREG	SAND83-1438
NUREG/CR-3492 V04	8408130001	NUREG	ORNL/TM-8921/V4
NUREG/CR-3493	8408220333	50-352 A	BNL-NUREG-51711
NUREG/CR-3518 V01	8408010164	NUREG	BNL-NUREG-51716
NUREG/CR-3569	8408290171	NUREG	PNL-4913
NUREG/CR-3590	8408300272	NUREG	ORNL/TM-9006
NUREG/CR-3591 V01	8408290190	NUREG	
NUREG/CR-3591 V02	8408290198	NUREG	
NUREG/CR-3599	8408130041	NUREG	
NUREG/CR-3618	8408080415	NUREG	ORNL-5991
NUREG/CR-3633 V02	8405210578	NUREG	EGG-2294
NUREG/CR-3633 V03	8405210579	NUREG	EGG-2294
NUREG/CR-3643	8408090359	NUREG	SAND83-2493
NUREG/CR-3671	8408080419	NUREG	ORNL-6047
NUREG/CR-3678	8408080409	NUREG	LA-10038

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY		OTHER REPORT NUMBER
NUREG/CR-3679	8408030357	NUREG		LA-10041-MS
NUREG/CR-3689 V01	8408100151	NUREG		ANL-83-85
NUREG/CR-3689 V02	8408310083	NUREG		ANL-83-85
NUREG/CR-3689 V03	8408310077	NUREG		ANL-83-85
NUREG/CR-3690	8408310089	NUREG		SAND-0402
NUREG/CR-3704	8406230301	50-317	P	LA-10039-MS
NUREG/CR-3708	8408240379	NUREG		
NUREG/CR-3714	8408080422	NUREG		ORNL-6006
NUREG/CR-3734	8408100152	NUREG		SAND84-0688
NUREG/CR-3735	8408160146	NUREG		LA-100079-MS
NUREG/CR-3742	8408100153	NUREG		LA-10087-MS
NUREG/CR-3744 V01	8408080355	NUREG		ORNL/TM-9154/V1
NUREG/CR-3751	8408130043	NUREG		PNL-5068
NUREG/CR-3761	8408160248	50-269	P	EGG-2310
NUREG/CR-3777	8408080367	NUREG		SAND84-0912
NUREG/CR-3792	8408310084	NUREG		IEB-79-11
NUREG/CR-3795	8408090272	NUREG		IEB-82-04
NUREG/CR-3798	8408310075	NUREG		PNL-5153
NUREG/CR-3804 V01	8408080374	NUREG		ANL-84-35
NUREG/CR-3818	8408240320	NUREG		SAND-84-0374
NUREG/CR-3820 V01	8408100147	NUREG		SAND84-1025/1
NUREG/CR-3826	8408010155	NUREG		UCRL-53538
NUREG/CR-3834	8408070014	NUREG		BNL/NUREG-51785
NUREG/CR-3840	8408080472	NUREG		
NUREG/CR-3844	8408010151	NUREG		BNL-NUREG-51787
NUREG/CR-3851 V01	8408300282	NUREG		ORNL/TM-9191/V1
NUREG/CR-3869	8408220370	NUREG		PNL-5149
NUREG/CR-3870	8408160125	NUREG		LMF-109
NUREG/CR-3874	8408220327	NUREG		
NUREG/CR-3884	8408290185	NUREG		
NUREG/CR-3894	8408240322	NUREG		ANL-84-1
NUREG/CR-3896	8408060386	NUREG		
NUREG/CR-3897	8408010158	NUREG		
NUSCO 140-1	8408100070*	50-213	P	
NUSCO 140-2	8408100077*	50-213	P	
PALO DURO STP-1 0 DR	8408010088*	WASTE MGT		
PARADOX STP-1 0 DRFT	8408010083*	WASTE MGT		
PLG-0370	8408130225*	50-289	P	
QO6-30-84	8408070153*	WASTE MGT		
REA-GJ-34247-RS REA-	8408270256*	WASTE MGT		
REA00119 REA-7 DRFT	8408030270*	WASTE MGT		
REA00153&03142 REA-5	8408270264*	WASTE MGT		
REA00270 REA-E-D-7DR	8408030197*	WASTE MGT		
REA05785-GJ REA-112A	8408270267*	WASTE MGT		
REA06318-GJ REA-108/	8408270262*	WASTE MGT		
REA08742 REA-104/LS	8408030264*	WASTE MGT		
REA13716 REA-7 DRFT	8408030268*	WASTE MGT		
SAD-431 R01	8408130420*	50-454	G	
SD-BWI-DP-001 RA-0	8408280007*	WASTE MGT		
SECY-84-215	8407030011*	REVIEW GRP		GL-83-28
SECY-84-290A	8407300105	50-322	A	
SECY-84-301	8408090406	SECY		
SECY-84-329	8408240110	SECY		
TDR 481 R00	8408090257*	50-219	P	
TDR 519 R00	8408070306*	50-219	P	
TDR 563	8408030108*	50-289	G	
TER-C5257-040	8105130143*	50-293	P	
TER-C5257-548	8204150347*	50-293	P	
TER-C5506-108/109	8307010039*	50-277	P	8122
TER-C5506-358	8407300136*	50-213	P	TAC 07993
TER-C5506-489 DRFT	8408280321*	50-346	P	TAC 52271
TER-C5506-524	8404040098*	50-388	U	
TER-C5506-525	8407090037*	50-219	P	TAC 48787
TM-928	8408210382*	TOPREP		
TR-4052-1 R02	8408060016*	50-293	P	
TVA-RLR-002	8408280226*	50-260	P	
UCID-19718	8408200173*	50-336	P	
UCRL-15619	8408070140*	WASTE MGT		
UMTRA-DOE/AL-0229	8408310339*	WASTE MGT		
UMTRA-DOE/AL-0230	8408310335*	WASTE MGT		
UMTRA-DOE/AL-050102	8408060111*	WASTE MGT		
UMTRA-DOE/AL-050102	8408060122*	WASTE MGT		
USG-684-1NP ERR	8408060047*	WASTE MGT		
WCAP-10170 APC S1 R0	8408070419*	50-412	F	
WCAP-10509	8408060231*	50-328	P	
WCAP-10566	8408160378*	50-443	A	
WCAP-7685-A	8408070288*	50-305	F	
WCAP-7819 R01A	8408070282*	50-305	F	
XN-NF-83-61	8408230266*	50-315	P	
XN-NF-83-72 S01 R02	8408140363*	50-261	P	
14-21 (NP) R02	8408090209*	50-316	P	
14-72 S01	8408230103*	50-261	P	
14-74	8408230122*	50-261	P	
37	8408070478*	50-29	P	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7812070142	8408010061	84/07/18	50-329	A
7909290119	8408010061	84/07/18	50-329	A
8004040738	8408010061	84/07/18	50-329	A
8008130764	8408010061	84/07/18	50-329	A
8010160005	8408010061	84/07/18	50-329	G
8011240409	8408010061	84/07/18	50-329	A
8104230479	8408010061	84/07/18	50-329	D
8105070480	8408010061	84/07/18	50-329	A
8105130143	8408060157	84/07/02	50-293	P
8110190801	8408010061	84/07/18	50-329	A
8110260082	8408010061	84/07/18	50-329	S
8111240064	8408010061	84/07/18	50-329	A
8201050063	8408010061	84/07/18	50-329	A
8201220049	8408010061	84/07/18	50-329	A
8202040352	8408010061	84/07/18	50-329	A
8203020050	8408010061	84/07/18	50-329	A
8204150347	8408060157	84/07/02	50-293	P
8205050209	8408010061	84/07/18	50-329	A
8205120033	8408010061	84/07/18	50-329	A
8205210467	8408010061	84/07/18	50-329	A
8205240603	8408010061	84/07/18	50-329	D
8206020051	8408010061	84/07/18	50-329	A
8206060008	8408010061	84/07/18	50-329	D
8206240401	8408010061	84/07/18	50-329	A
8206290161	8408010061	84/07/18	50-329	A
8207140330	8408010061	84/07/18	50-329	A
8209230536	8408010061	84/07/18	50-329	E
8210130322	8408010061	84/07/18	50-329	A
8210150698	8408010061	84/07/18	50-329	A
8210270126	8408010061	84/07/18	50-329	G
8211030222	8408010061	84/07/18	50-329	G
8301190487	8408010061	84/07/18	50-329	G
8303300736	8303300734	84/03/03	50-445	A
8305270222	8408010061	84/07/18	50-329	A
8306060387	8408010061	84/07/18	50-329	A
8307010039	8408220527	84/08/03	50-277	P
8307130423	8408010061	84/07/18	50-329	A
8307130425	8408010061	84/07/18	50-329	A
8309130017	8408010061	84/07/18	50-329	G
8309130112	8309130110	83/08/18	50-445	A
8309130117	8309130110	83/08/18	50-445	A
8309220362	8408280360	84/07/22	50-295	P
8309270366	8408010061	84/07/18	50-329	G
8309270518	8408010061	84/07/18	50-329	G
8310050136	8408010061	84/07/18	50-329	G
8310070101	8408010061	84/07/18	50-329	G
8310070262	8408010061	84/07/18	50-329	A
8310240271	8408010061	84/07/18	50-329	G
8312020299	8408010124	84/07/24	50-354	E
8312080185	8408010061	84/07/18	50-329	A

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8312120393	8408010061	84/07/18	50-329	A
8402020372	8408010124	84/07/24	50-354	E
8404040095	8408200225	84/08/10	50-388	U
8404040098	8408200225	84/08/10	50-388	U
8404040172	8404040169	84/03/26	50-10	F
8404040322	8408300436	84/05/07	50-321	F
8404230171	8408150137	84/08/01	50-400	F
8404250191	8408070268	84/07/27	PR	
8405010079	8408100094	84/08/06	50-315	F
8405160473	8405160470	84/04/27	50-89	P
8405160476	8405160470	84/04/27	50-89	P
8405180152	8405180145	84/05/04	50-367	H
8405180433	8407020541	84/06/27	REVIEW GRP	
8405290075	8405290062	84/05/24	50-206	S
8405290075	8405290062	84/05/24	50-206	S
8405290271	8405290179	84/05/24	50-206	S
8405300762	8405300761	84/04/11	70-1113	
8405300763	8405300761	84/04/11	70-1113	
8406010162	8408070076	84/07/30	50-366	S
8406020280	8408010061	84/07/18	50-329	A
8406080113	8406080109	84/06/04	50-316	P
8406140090	8408290041	84/08/29	50-413	F
8406140102	8406140101	84/05/22	50-456	G
8406140104	8406140101	84/05/22	50-456	G
8406200226	8408070268	84/07/27	PR	
8406260179	8406260175	84/06/06	70-1143	
8406260184	8406260175	84/06/06	70-1143	
8406280010	8408070268	84/07/27	PR	
8407020544	8407020541	84/06/27	REVIEW GRP	
8407030011	8407020541	84/06/27	REVIEW GRP	
8407090037	8408070052	84/07/27	50-219	P
8407100397	8408090308	84/07/31	50-413	U
8407160091	8407160090	83/08/29	50-277	F
8407170316	8407170313	84/07/11	NUREG	
8407230203	8407230200	84/07/09	TOPREP	
8407250575	8408070026	84/07/19	ORG	
8407260112	8407260111	84/07/20	50-324	K
8407260166	8407260161	84/07/20	50-305	K
8407260220	8407260218	84/07/23	50-250	K
8407300136	8408220326	84/08/20	50-213	P
8407300151	8407300142	84/07/24	50-329	G
8407300156	8407300142	84/07/24	50-329	G
8408010008	8408010006	84/07/20	50-267	R
8408010022	8408010018	84/07/23	50-298	P
8408010027	8408010018	84/07/23	50-298	P
8408010028	8408010025	84/05/07	71-9163	
8408010031	8408010025	84/05/07	71-9163	
8408010047	8408010045	84/07/25	50-136	F
8408010048	8408010041	84/07/24	CONTRACT	
8408010051	8408010049	84/07/17	50-320	P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408010053	8408010046	84/07/13	WASTE MGT
8408010060	8408010056	84/07/19	50-280 S
8408010063	8408010046	84/07/13	WASTE MGT
8408010069	8408010056	84/07/19	50-280 S
8408010072	8408010064	84/07/17	WASTE MGT
8408010076	8408010056	84/07/19	50-280 S
8408010083	8408010079	84/07/19	WASTE MGT
8408010085	8408010082	84/07/18	50-483 P
8408010088	8408010079	84/07/19	WASTE MGT
8408010131	8408010129	84/07/24	50-423 D
8408010132	8408010061	84/07/18	50-329 O
8408010135	8408010061	84/07/18	50-329 O
8408010143	8408010061	84/07/18	50-329 O
8408010147	8408010061	84/07/18	50-329 O
8408010149	8408010061	84/07/18	50-329 A
8408010152	8408010061	84/07/18	50-329 O
8408010153	8408010061	84/07/18	50-329 O
8408010156	8408010154	84/07/26	50-412 F
8408010160	8408010061	84/07/18	50-329 S
8408010163	8408010061	84/07/18	50-329 O
8408010168	8408010061	84/07/18	50-329 O
8408010171	8408010165	84/07/27	50-295 F
8408010173	8408010061	84/07/18	50-329 O
8408010178	8408010061	84/07/18	50-329 O
8408010182	8408010175	84/05/14	CONTRACT
8408010183	8408010061	84/07/18	50-329 O
8408010188	8408010061	84/07/18	50-329 O
8408010191	8408010061	84/07/18	50-329 O
8408010195	8408010061	84/07/18	50-329 O
8408010198	8408010061	84/07/18	50-329 O
8408010202	8408010061	84/07/18	50-329 O
8408010204	8408010061	84/07/18	50-329 O
8408010206	8408010061	84/07/18	50-329 O
8408010217	8408010214	84/07/30	50-440 Q
8408010221	8408010218	84/07/20	50-334 P
8408010224	8408010219	84/07/27	50-354 E
8408010225	8408010222	84/07/27	50-498 K
8408010228	8408010223	84/07/13	50-352 Q
8408010231	8408010219	84/07/27	50-354 E
8408010234	8408010219	84/07/27	50-354 E
8408010237	8408010235	84/07/30	50-275 Q
8408010247	8408010240	84/07/20	50-361 P
8408010256	8408010240	84/07/20	50-361 P
8408010263	8408010260	84/07/30	50-155 Q
8408010269	8408010260	84/07/30	50-155 Q
8408010276	8408010272	84/07/30	50-206 P
8408010277	8408010275	84/07/20	50-275 U
8408010281	8408010278	84/07/16	50-344 Q
8408010284	8408010282	84/07/13	50-247 Q
8408010285	8408010283	84/07/16	50-341 Q
8408010286	8408010282	84/07/13	50-247 Q
8408010287	8408010272	84/07/30	50-206 P
8408010290	8408010288	84/07/11	50-245 Q
8408010291	8408010289	84/07/10	50-373 Q
8408010292	8408010288	84/07/11	50-245 Q
8408010294	8408010289	84/07/10	50-373 Q
8408010298	8408010296	84/07/12	50-247 Q
8408010299	8408010297	84/07/10	50-409 Q
8408010300	8408010296	84/07/12	50-247 Q
8408010306	8408010303	84/07/17	50-335 F
8408010308	8408010302	84/07/19	50-151 Q
8408010314	8408010312	84/07/13	50-374 Q
8408010316	8408010312	84/07/13	50-374 Q
8408010321	8408010319	84/07/25	50-333 P
8408010322	8408010319	84/07/25	50-333 P
8408010329	8408010328	84/07/24	50-320 P
8408010331	8408010328	84/07/24	50-320 P
8408010340	8408010338	84/07/20	50-335 H
8408010341	8408010332	84/07/10	50-454 Q
8408010342	8408010338	84/07/20	50-335 H
8408010345	8408010343	84/06/06	50-318 S
8408010366	8408010364	83/11/18	QA999
8408010368	8408010364	83/11/18	QA999
8408010372	8408010364	83/11/18	QA999
8408010398	8408010395	84/07/09	50-387 Q
8408010400	8408010397	84/07/19	40-6499
8408010402	8408010401	84/07/12	50-263 Q
8408020009	8408020006	84/07/25	50-331 P
8408020018	8408020010	84/07/25	50-302 P
8408020035	8408020033	84/07/27	50-382 A

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408020038	8408010061	84/07/18	50-329 A
8408020043	8408010061	84/07/18	50-329 A
8408020051	8408020050	84/07/20	50-344 K
8408020059	8408020057	84/07/27	50-344 P
8408020061	8408020057	84/07/27	50-344 P
8408020063	8408020056	84/07/30	50-133 P
8408020066	8408020060	84/07/30	50-413 Q
8408020067	8408020056	84/07/30	50-133 P
8408020068	8408020062	84/07/27	50-413 Q
8408020069	8408020065	84/07/26	50-297 P
8408020070	8408020056	84/07/30	50-133 P
8408020071	8408010061	84/07/18	50-329 Q
8408020074	8408010061	84/07/18	50-329 Q
8408020075	8408020058	84/07/31	50-352 A
8408020078	8408020073	84/07/27	50-305 P
8408020080	8408020058	84/07/31	50-352 C
8408020084	8408020058	84/07/31	50-352 K
8408020086	8408010061	84/07/18	50-329 Q
8408020090	8408020058	84/07/31	50-352 A
8408020097	8408020082	84/07/30	50-271 Q
8408020099	8408010061	84/07/18	50-329 A
8408020107	8408010061	84/07/18	50-329 Q
8408020108	8408020100	84/07/23	50-272 K
8408020112	8408010061	84/07/18	50-329 A
8408020114	8408020105	84/07/31	50-482 F
8408020117	8408020105	84/07/31	50-482 F
8408020119	8408020115	84/07/26	50-220 R
8408020122	8408010061	84/07/18	50-329 A
8408020125	8408020121	84/07/23	50-309 K
8408020126	8408020118	84/07/20	50-440 I
8408020127	8408010061	84/07/18	50-329 Q
8408020131	8407310035	84/07/30	50-275 Q
8408020134	8407310035	84/07/30	50-275 Q
8408020139	8408020130	84/07/27	50-293 P
8408020141	8408020137	84/07/26	50-289 K
8408020142	8408020130	84/07/27	50-293 P
8408020144	8408020130	84/07/27	50-293 P
8408020147	8408020130	84/07/27	50-293 P
8408020148	8407310166	84/07/20	50-266 K
8408020149	8408020130	84/07/27	50-293 P
8408020151	8408020145	84/07/27	50-259 F
8408020155	8408020150	84/07/27	50-266 F
8408020156	8408020145	84/07/27	50-259 F
8408020171	8408010061	84/07/18	50-329 Q
8408020173	8408020172	84/07/09	50-346 P
8408020174	8408020172	84/07/09	50-346 P
8408020177	8408010061	84/07/18	50-329 Q
8408020178	8408010061	84/07/18	50-329 T
8408020180	8408010061	84/07/18	50-329 Q
8408020181	8408010061	84/07/18	50-329 Q
8408020182	8408010061	84/07/18	50-329 Q
8408020183	8408010061	84/07/18	50-329 Q
8408020184	8408010061	84/07/18	50-329 Q
8408020185	8408010061	84/07/18	50-329 Q
8408020186	8408010061	84/07/18	50-329 Q
8408020187	8408010061	84/07/18	50-329 Q
8408020188	8408010061	84/07/18	50-329 A
8408020189	8408010061	84/07/18	50-329 Q
8408020190	8408010061	84/07/18	50-329 Q
8408020192	8408010061	84/07/18	50-329 A
8408020193	8408010061	84/07/18	50-329 A
8408020194	8408010061	84/07/18	50-329 Q
8408020195	8408010061	84/07/18	50-329 A
8408020196	8408010061	84/07/18	50-329 Q
8408020199	8408010061	84/07/18	50-329 A
8408020202	8408010061	84/07/18	50-329 Q
8408020207	8408020205	84/05/31	70-36
8408020209	8408020205	84/05/31	70-36
8408020223	8408020220	84/07/06	70-8
8408020225	8408020220	84/07/06	70-8
8408020227	8408020222	84/08/01	50-275 Q
8408020230	8408020228	84/06/28	40-8724
8408020231	8408020222	84/08/01	50-275 Q
8408020233	8408020222	84/08/01	50-275 Q
8408020233	8408020222	84/08/01	50-275 Q
8408020239	8408020236	84/07/05	WASTE MGT
8408020256	8408020253	84/06/28	70-734
8408030001	8408010061	84/07/18	50-329 A
8408030004	8408010061	84/07/18	50-329 A
8408030007	8408010061	84/07/18	50-329 A

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408030013	8408010061	84/07/18	50-329 A
8408030014	8408030005	84/07/26	50-244 G
8408030016	8408030012	84/07/31	50-482 A
8408030020	8408010061	84/07/18	50-329 A
8408030025	8408030019	84/07/27	50-327 P
8408030028	8408010061	84/07/18	50-329 A
8408030031	8408030027	84/07/30	50-272 G
8408030033	8408030029	84/07/27	70-143
8408030042	8408010061	84/07/18	50-329 A
8408030051	8408010061	84/07/18	50-329 A
8408030056	8408010061	84/07/18	50-329 A
8408030057	8408030052	84/07/24	50-271 F
8408030058	8408010061	84/07/18	50-329 A
8408030064	8408010061	84/07/18	50-329 A
8408030068	8408010061	84/07/18	50-329 A
8408030076	8408030071	84/07/12	50-329 G
8408030100	8408030096	84/07/20	50-261 P
8408030107	8408030104	84/07/30	50-289 G
8408030108	8408030104	84/07/30	50-289 G
8408030112	8408030105	84/08/01	50-322 G
8408030113	8408030109	84/07/30	50-155 P
8408030116	8408030109	84/07/30	50-155 P
8408030125	8408030110	84/07/11	50-296 P
8408030127	8408030126	84/07/30	50-335 G
8408030135	8408030130	84/07/31	50-369 P
8408030140	8408030110	84/07/11	50-296 P
8408030147	8408030146	84/07/31	70-371
8408030148	8408030146	84/07/31	70-371
8408030151	8408030150	84/07/30	50-255 P
8408030152	8408030150	84/07/30	50-255 P
8408030169	8408030166	84/08/01	50-206 P
8408030170	8408030167	84/07/31	50-266 F
8408030178	8408030173	84/07/26	50-387 G
8408030179	8408030176	84/07/13	50-155 G
8408030192	8408030188	84/07/13	50-410 G
8408030197	8408030187	84/07/23	WASTE MGT
8408030207	8408030203	84/07/13	50-341 G
8408030215	8408030211	84/07/17	50-320 P
8408030218	8408030211	84/07/17	50-320 P
8408030220	8408030211	84/07/17	50-320 P
8408030221	8408030209	84/07/03	50-333 G
8408030223	8408030211	84/07/17	50-320 P
8408030224	8408030222	84/07/12	50-271 G
8408030226	8408030211	84/07/17	50-320 P
8408030228	8408030211	84/07/17	50-320 P
8408030229	8408030222	84/07/12	50-271 G
8408030231	8408030211	84/07/17	50-320 P
8408030247	8408030236	84/07/18	50-272 G
8408030252	8408030251	84/07/10	50-10 G
8408030264	8408030263	84/07/16	WASTE MGT
8408030267	8408030259	84/07/11	50-272 G
8408030268	8408030263	84/07/16	WASTE MGT
8408030270	8408030263	84/07/16	WASTE MGT
8408030275	8408030266	84/05/31	50-382 G
8408030282	8408030277	84/07/24	MISC
8408060008	8408060005	84/07/30	50-293 P
8408060016	8708060005	84/07/30	50-293 P
8408060017	8408060014	84/07/20	CONTRACT
8408060025	8408060018	84/07/24	CONTRACT
8408060029	8408060021	84/07/31	50-259 P
8408060036	8408060024	84/07/30	50-341 G
8408060037	8408060031	84/07/24	CONTRACT
8408060039	8408060034	84/07/25	50-361 B
8408060040	8408060038	84/06/19	CONTRACT
8408060047	8408060045	84/07/19	WASTE MGT
8408060048	8408060041	84/07/24	CONTRACT
8408060057	8408060054	84/06/12	50-382 G
8408060073	8408060069	84/07/23	MISC
8408060077	8408060069	84/07/23	MISC
8408060081	8408060069	84/07/23	MISC
8408060083	8408060069	84/07/23	MISC
8408060099	8408060092	84/07/03	50-482 G
8408060101	8408060095	84/08/01	50-373 F
8408060104	8408060097	84/07/31	50-413 P
8408060111	8408060106	84/07/20	WASTE MGT
8408060115	8408060110	84/07/31	50-155 G
8408060119	8408060117	84/07/27	50-413 P
8408060122	8408060106	84/07/20	WASTE MGT
8408060125	8408060116	84/07/23	TOPREP
8408060138	8408060102	84/07/27	50-206 B

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408060142	8408060139	84/07/18	50-219 G
8408060153	8408060145	84/07/25	50-373 P
8408060160	8408060146	84/07/26	50-134 F
8408060161	8408060157	84/07/02	50-293 P
8408060167	8408060162	84/07/31	50-57 F
8408060172	8408060157	84/07/02	50-293 P
8408060180	8408060175	84/05/25	50-482 G
8408060191	8408060183	84/07/30	50-70 G
8408060193	8408060185	84/07/27	50-416 S
8408060196	8408060192	84/07/27	50-400 A
8408060197	8408060183	84/07/30	50-70 G
8408060200	8408060185	84/07/27	50-416 S
8408060206	8408060183	84/07/30	50-70 G
8408060208	8408060190	84/07/09	50-213 G
8408060214	8408060211	84/07/24	CONTRACT
8408060224	8408060201	84/07/31	50-289 G
8408060231	8408060220	84/07/31	50-328 P
8408060240	8408060234	84/07/27	50-482 A
8408060273	8408060268	84/07/27	50-352 A
8408060280	8408060276	84/08/02	50-237 P
8408060287	8408060286	84/08/01	50-483 P
8408060303	8408060302	84/07/20	50-456 G
8408060309	8408060302	84/07/20	50-456 G
8408060313	8408060307	84/06/29	50-285 G
8408060320	8408060317	84/07/09	50-382 G
8408060325	8408060317	84/07/09	50-382 G
8408060344	8407310030	84/07/27	50-454 G
8408060371	8408060368	84/07/27	70-2988
8408060375	8408060368	84/07/27	70-2988
8408060378	8408060373	84/07/16	70-1362
8408060382	8408060373	84/07/16	70-1362
8408060387	8408060324	84/08/01	50-206 S
8408060426	8408060424	84/07/24	CONTRACT
8408060438	8408060435	84/07/27	XPORTLIC
8408070011	8408060445	84/07/24	50-396 P
8408070018	8408070016	84/07/26	50-324 P
8408070027	8408070025	84/07/25	50-447 H
8408070029	8408070025	84/07/25	50-447 H
8408070038	8408070035	84/07/30	50-170 P
8408070048	8408070041	84/07/26	50-416 H
8408070053	8408070047	84/07/25	CONTRACT
8408070084	8408070082	84/07/26	50-344 P
8408070087	8408070080	84/07/26	CONTRACT
8408070104	8408070101	84/07/25	CONTRACT
8408070127	8408070124	84/07/31	50-166 P
8408070140	8408070136	84/07/24	WASTE MGT
8408070153	8408070149	84/07/26	WASTE MGT
8408070178	8408070174	84/08/02	50-244 G
8408070180	8408070173	84/07/31	50-329 A
8408070197	8408070189	84/07/31	50-282 G
8408070207	8408070201	84/07/27	50-416 U
8408070212	8408070204	84/08/01	50-454 G
8408070215	8408070201	84/07/27	50-416 U
8408070216	8408070213	84/07/30	50-454 G
8408070217	8408070211	84/07/25	50-322 H
8408070221	8408070213	84/07/30	50-454 G
8408070231	8408070226	84/07/09	40-8786
8408070237	8408070232	84/08/02	50-272 G
8408070242	8408070236	84/06/18	TOPREP
8408070255	8408070251	84/07/31	50-244 P
8408070257	8408070248	84/07/31	50-244 P
8408070258	8408070251	84/07/31	50-244 P
8408070282	8408070275	84/08/01	50-305 F
8408070288	8408070275	84/08/01	50-305 F
8408070291	8408070287	84/08/03	50-352 G
8408070296	8408070292	84/07/31	50-305 F
8408070306	8408070300	84/07/30	50-219 P
8408070309	8408070304	84/08/02	50-219 P
8408070326	8408070323	84/08/01	50-354 G
8408070327	8408070324	84/08/01	50-275 G
8408070330	8408070328	84/08/01	50-266 P
8408070340	8408070338	84/07/18	50-456 G
8408070355	8408070353	84/08/01	50-412 G
8408070356	8408070354	84/08/02	50-341 G
8408070360	8408070357	84/07/31	50-280 G
8408070365	8408070362	84/07/30	50-443 F
8408070375	8408070370	84/08/01	50-259 P
8408070378	8408070374	84/08/01	50-261 P
8408070384	8408070381	84/07/27	50-400 K
8408070392	8408070389	84/07/24	50-269 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408070398	8408070383	84/08/02	PR	
8408070406	8408070400	84/07/27	50-338	F
8408070409	8408070405	84/08/03	50-390	G
8408070415	8408070412	84/08/02	50-352	G
8408070419	8408070414	84/08/01	50-412	F
8408070423	8408070417	84/07/27	50-333	P
8408070428	8408070417	84/07/27	50-333	P
8408070433	8408070429	84/08/03	50-352	G
8408070438	8408070431	84/07/31	50-255	P
8408070439	8408070434	84/08/03	50-220	F
8408070441	8408070435	84/07/31	50-255	F
8408070448	8408070442	84/08/03	50-322	G
8408070450	8408070444	84/08/06	50-352	G
8408070456	8408070446	84/07/17	50-498	A
8408070457	8408070453	84/07/31	PRM	
8408070458	8408070442	84/08/03	50-322	G
8408070460	8408070452	84/08/02	50-461	G
8408070462	8408070453	84/07/31	PRM	
8408070465	8408070446	84/07/17	50-498	A
8408070478	8408070472	84/08/01	50-29	P
8408070485	8408070483	84/07/31	50-313	P
8408070502	8408070499	84/07/20	50-346	P
8408070505	8408070499	84/07/20	50-346	P
8408070511	8408070508	84/07/27	50-344	P
8408070516	8408070515	84/07/31	50-244	P
8408070526	8408070524	84/07/09	50-244	P
8408070532	8408070531	84/07/20	50-275	P
8408080008	8408080005	84/07/31	CONTRACT	
8408080025	8408080020	84/07/06	CONTRACT	
8408080037	8408080031	84/07/26	50-346	F
8408080038	8408080034	84/07/20	COMMISSION	
8408080064	8408080052	84/07/31	CONTRACT	
8408080067	8408080059	84/07/26	CONTRACT	
8408080087	8408080082	84/07/26	50-320	H
8408080141	8408080138	84/07/30	50-416	F
8408080151	8408080147	84/07/18	70-734	
8408080155	8408080148	84/07/03	50-373	P
8408080158	8408080152	84/07/27	50-313	P
8408080159	8408080148	84/07/03	50-373	P
8408080165	8408080152	84/07/27	50-313	P
8408080166	8408080157	84/07/18	50-387	G
8408080168	8408080162	84/08/07	50-445	G
8408080170	8408080161	84/07/31	50-312	P
8408080174	8408080171	84/07/20	50-263	G
8408080180	8408080173	84/08/06	40-2061	
8408080181	8408080171	84/07/20	50-263	G
8408080192	8408080187	84/08/02	50-395	K
8408080195	8408080188	84/07/18	50-454	G
8408080196	8408080187	84/08/02	50-395	K
8408080200	8408080187	84/08/02	50-395	K
8408080205	8408080198	84/08/02	50-454	F
8408080207	8408080187	84/08/02	50-395	K
8408080209	8408080204	84/07/19	50-220	G
8408080213	8408080212	84/07/17	50-334	G
8408080214	8408080187	84/08/02	50-395	K
8408080221	8408080187	84/08/02	50-395	K
8408080226	8408080187	84/08/02	50-395	K
8408080228	8408080187	84/08/02	50-395	K
8408080232	8408080187	84/08/02	50-395	K
8408080237	8408080187	84/08/02	50-395	K
8408080238	8408080233	84/07/16	50-244	G
8408080240	8408080187	84/08/02	50-395	K
8408080242	8408080233	84/07/16	50-244	G
8408080244	8408080187	84/08/02	50-395	K
8408080248	8408080187	84/08/02	50-395	K
8408080250	8408080243	84/07/18	50-289	G
8408080251	8408080187	84/08/02	50-395	K
8408080254	8408080187	84/08/02	50-395	K
8408080256	8408080243	84/07/18	50-289	G
8408080260	8408080187	84/08/02	50-395	K
8408080262	8408080187	84/08/02	50-395	K
8408080265	8408080187	84/08/02	50-395	K
8408080280	8408080275	84/07/30	50-413	E
8408080284	8408080275	84/07/30	50-413	E
8408080286	8408080278	84/07/31	50-601	K
8408080287	8408080278	84/07/31	50-601	K
8408080292	8408080278	84/07/31	50-601	K
8408080295	8408080278	84/07/31	50-601	K
8408080298	8408080278	84/07/31	50-601	K
8408080301	8408080278	84/07/31	50-601	K

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408080302	8408080299	84/08/04	50-341	F
8408080303	8408080297	84/07/30	NUREG	
8408080304	8408080278	84/07/31	50-601	K
8408080307	8408080278	84/07/31	50-601	K
8408080309	8408080278	84/07/31	50-601	K
8408080312	8408080278	84/07/31	50-601	K
8408080315	8408080278	84/07/31	50-601	K
8408080318	8408080278	84/07/31	50-601	K
8408080319	8408080314	84/07/24	50-374	P
8408080320	8408080278	84/07/31	50-601	K
8408080321	8408080317	84/08/01	CONTRACT	
8408080322	8408080314	84/07/24	50-374	P
8408080323	8408080278	84/07/31	50-601	K
8408080330	8408080278	84/07/31	50-601	K
8408080334	8408080333	84/08/01	PR	
8408080342	8408080278	84/07/31	50-601	K
8408080343	8408080278	84/07/31	50-601	K
8408080345	8408080278	84/07/31	50-601	K
8408080346	8408080344	84/07/30	50-354	A
8408080347	8408080278	84/07/31	50-601	K
8408080383	8408080353	84/07/20	50-245	G
8408080394	8408080353	84/07/20	50-245	G
8408080403	8408080353	84/07/20	50-245	G
8408080414	8408080353	84/07/20	50-245	G
8408080423	8408080417	84/08/06	50-322	G
8408080432	8408080430	84/07/23	50-416	U
8408080448	8408080212	84/07/17	50-334	G
8408080449	8408080445	84/07/27	50-312	F
8408080458	8408080453	84/07/16	50-275	F
8408080461	8408080456	84/07/18	50-220	G
8408080466	8408080464	84/07/17	50-245	G
8408080467	8408080463	84/07/20	50-219	G
8408080478	8408080473	84/07/16	50-322	G
8408080480	8408080476	84/08/01	CONTRACT	
8408080488	8408080485	84/07/18	50-295	G
8408080490	8408080481	84/07/18	50-289	G
8408080496	8408080485	84/07/18	50-295	G
8408080497	8408080494	84/07/20	50-344	G
8408080501	8408080491	84/07/27	50-275	G
8408080507	8408080502	84/07/18	CONTRACT	
8408080513	8408080491	84/07/27	50-275	G
8408080515	8408080491	84/07/27	50-275	G
8408080517	8408080491	84/07/27	50-275	G
8408080521	8408080491	84/07/27	50-275	G
8408080526	8408080523	84/07/17	50-352	G
8408080527	8408080524	84/07/31	50-346	P
8408080530	8408080523	84/07/17	50-352	G
8408090004	8408090001	84/07/25	50-361	G
8408090013	8408090010	84/07/26	50-313	P
8408090014	8408090011	84/07/31	50-263	F
8408090019	8408090016	84/07/24	50-397	G
8408090021	8408090017	84/07/25	50-344	G
8408090037	8408090034	84/07/05	50-298	G
8408090039	8408090036	84/07/18	50-277	G
8408090045	8408090043	84/07/27	50-361	G
8408090046	8408090041	84/07/31	CONTRACT	
8408090048	8408090040	84/07/19	50-387	G
8408090051	8408090036	84/07/18	50-277	G
8408090053	8408090040	84/07/19	50-387	G
8408090059	8408090056	84/07/31	50-247	F
8408090061	8408090056	84/07/31	50-247	F
8408090073	8408090070	84/07/20	50-382	G
8408090074	8408090072	84/07/31	CONTRACT	
8408090080	8408090075	84/07/23	50-344	G
8408090081	8408090077	84/08/03	50-220	P
8408090088	8408090085	84/05/08	50-271	G
8408090091	8408090086	84/07/23	50-312	G
8408090092	8408090082	84/07/31	50-423	A
8408090095	8408090090	84/07/10	50-458	G
8408090105	8408070455	84/08/03	50-445	A
8408090106	8408090102	84/07/25	COMMISSION	
8408090111	8408090109	84/07/25	COMMISSION	
8408090113	8408090109	84/07/25	COMMISSION	
8408090122	8408090120	84/07/23	70-984	
8408090124	8408310345	84/08/23	TOPREP	
8408090130	8408090121	84/07/17	50-313	G
8408090141	8408090133	84/07/20	50-213	G
8408090142	8408090135	84/07/24	CONTRACT	
8408090154	8408090145	84/08/07	50-416	G
8408090160	8408090150	84/07/11	50-313	G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408090165	8408090162	84/07/24	50-294 V
8408090171	8408090166	84/08/06	50-155 P
8408090177	8408090169	84/07/20	50-295 G
8408090182	8408090173	84/08/03	50-309 P
8408090189	8408090184	84/07/23	50-266 G
8408090194	8408090187	84/08/07	50-361 P
8408090195	8408090192	84/07/24	50-255 G
8408090201	8408090187	84/08/07	50-361 P
8408090202	8408090196	84/08/03	50-440 G
8408090203	8408090197	84/08/06	50-352 G
8408090206	8408090200	84/08/01	50-445 G
8408090209	8408090198	84/08/07	50-316 P
8408090213	8408090210	84/08/07	50-322 G
8408090217	8408090212	84/07/23	50-454 G
8408090223	8408090218	84/08/06	50-322 G
8408090233	8408090226	84/08/03	50-352 G
8408090236	8408090229	84/08/07	50-352 T
8408090237	8408090235	84/08/01	50-338 P
8408090257	8408090250	84/08/03	50-219 P
8408090263	8408090258	84/08/06	50-352 G
8408090281	8408090275	84/07/24	50-244 P
8408090298	8408090293	84/07/18	50-440 G
8408090303	8408090299	84/07/27	WASTE MGT
8408090304	8408090293	84/07/18	50-440 G
8408090316	8408090311	84/07/31	50-267 P
8408090322	8408090311	84/07/31	50-267 P
8408090327	8408090166	84/08/06	50-155 P
8408090330	8408090315	84/07/16	50-322 G
8408090337	8408090335	84/08/02	50-73 P
8408090409	8408090407	84/07/27	50-397 P
8408090410	8408090407	84/07/27	50-397 P
8408090412	8408090407	84/07/27	50-397 P
8408090414	8408090407	84/07/27	50-397 P
8408090420	8408090408	84/08/06	50-445 G
8408090426	8408090408	84/08/06	50-445 G
8408090434	8408090408	84/08/06	50-445 G
8408090463	8408090408	84/08/06	50-445 G
8408090471	8408090408	84/08/06	50-445 G
8408090480	8408090408	84/08/06	50-445 G
8408090488	8408090408	84/08/06	50-445 G
8408090503	8408090408	84/08/06	50-445 G
8408090510	8408090504	84/08/01	CONTRACT
8408090512	8408090408	84/08/06	50-445 G
8408090517	8408090515	84/07/30	50-334 P
8408090524	8408090521	84/07/30	50-334 P
8408090534	8408090533	84/08/01	50-170 P
8408090536	8408090533	84/08/01	50-170 P
8408090537	8408090533	84/08/01	50-170 P
8408090551	8408090548	84/07/31	CONTRACT
8408090564	8408090562	84/07/23	PROJ
8408100010	8408100004	84/08/07	50-261 F
8408100012	8408100002	84/07/30	50-395 F
8408100017	8408100014	84/07/09	50-298 R
8408100032	8408100022	84/08/03	50-244 G
8408100034	8408100026	84/08/06	50-483 G
8408100037	8408100029	84/08/03	50-282 G
8408100040	8408100030	84/08/07	50-454 T
8408100049	8408100045	84/08/06	50-366 P
8408100051	8408100041	84/08/07	70-1941
8408100052	8408100044	84/08/03	50-266 G
8408100054	8408100016	84/08/08	50-250 F
8408100056	8408100043	84/08/03	50-244 G
8408100062	8408100057	84/08/07	50-285 G
8408100067	8408100065	84/07/20	50-354 F
8408100070	8408100063	84/07/30	50-213 P
8408100075	8408100069	84/07/31	50-482 G
8408100077	8408100063	84/07/30	50-213 P
8408100080	8408100074	84/08/06	50-220 P
8408100081	8408100076	84/08/06	50-220 P
8408100086	8408100076	84/08/06	50-220 P
8408100101	8408100089	84/08/06	50-461 A
8408100105	8408100087	84/05/07	50-333 F
8408100106	8408100089	84/08/06	50-461 A
8408100111	8408100103	84/08/07	50-220 P
8408100119	8408100112	84/08/03	50-456 G
8408100120	8408100103	84/08/07	50-220 P
8408100137	8408100127	84/08/02	50-528 A
8408100138	8408100134	84/08/06	50-255 P
8408100144	8408100133	84/08/08	50-289 G
8408130021	8408130020	84/06/28	71-83
8408130024	8408130020	84/06/28	71-83
8408130027	8408130020	84/06/28	71-83
8408130032	8408130026	84/07/27	50-259 P
8408130037	8408130026	84/07/27	50-259 P
8408130079	8408130077	84/07/13	WASTE MGT
8408130081	8408130077	84/07/13	WASTE MGT
8408130094	8408130091	84/08/07	50-433 G
8408130101	8408130099	84/07/30	WASTE MGT
8408130108	8408130103	84/08/06	50-454 G
8408130156	8408130152	84/08/01	50-461 A
8408130163	8408130153	84/08/08	50-341 G
8408130166	8408130149	84/08/07	50-269 G
8408130168	8408130164	84/07/18	50-413 P
8408130173	8408130170	84/08/08	50-331 P
8408130177	8408130164	84/07/18	50-413 P
8408130179	8408130164	84/07/18	50-413 P
8408130204	8408130194	84/08/07	50-395 G
8408130210	8408130202	84/07/31	50-416 U
8408130212	8408130205	84/07/13	70-938
8408130225	8408130218	84/08/08	50-289 P
8408130226	8408130223	84/07/24	50-338 P
8408130227	8408010061	84/07/18	50-329 A
8408130230	8408010061	84/07/18	50-329 A
8408130234	8408010061	84/07/18	50-329 A
8408130241	8408010061	84/07/18	50-329 A
8408130244	8408010061	84/07/18	50-329 A
8408130251	8408130248	84/08/07	50-382 G
8408130255	8408010061	84/07/18	50-329 A
8408130256	8408130248	84/08/07	50-382 G
8408130258	8408130253	84/07/25	50-348 P
8408130260	8408130248	84/08/07	50-382 G
8408130269	8408010061	84/07/18	50-329 A
8408130277	8408130274	84/08/07	50-528 A
8408130280	8408130275	84/08/07	50-390 A
8408130283	8408130278	84/07/10	71-184
8408130290	8408010061	84/07/18	50-329 A
8408130292	8408130278	84/07/10	71-184
8408130298	8408130289	84/08/10	50-10 F
8408130301	8408010061	84/07/18	50-329 A
8408130306	8408010061	84/07/18	50-329 A
8408130311	8408010061	84/07/18	50-329 A
8408130313	8408130309	84/08/03	50-286 F
8408130314	8408130308	84/08/01	CONTRACT
8408130315	8408010061	84/07/18	50-329 T
8408130320	8408010061	84/07/18	50-329 A
8408130323	8408010061	84/07/18	50-329 A
8408130324	8408130319	84/08/09	50-382 G
8408130327	8408010061	84/07/18	50-329 A
8408130328	8408130319	84/08/09	50-382 G
8408130333	8408130319	84/08/09	50-382 G
8408130336	8408010061	84/07/18	50-329 A
8408130337	8408130329	84/08/07	40-2061
8408130339	8408130319	84/08/09	50-382 G
8408130348	8408010061	84/07/18	50-329 A
8408130352	8408130347	84/08/08	50-322 G
8408130354	8408130350	84/08/09	50-29 G
8408130355	8408130347	84/08/08	50-322 G
8408130356	8408010061	84/07/18	50-329 A
8408130359	8408130347	84/08/08	50-322 G
8408130363	8408130358	84/08/09	50-29 P
8408130376	8408130370	84/08/09	50-155 F
8408130381	8408130380	84/08/09	70-143
8408130382	8408130380	84/08/09	70-143
8408130383	8408130380	84/08/09	70-143
8408130388	8408130385	84/08/08	50-247 G
8408130390	8408130387	84/08/07	50-346 G
8408130395	8408130391	84/08/08	50-346 G
8408130400	8408130394	84/08/09	50-338 G
8408130403	8408130394	84/08/09	50-338 G
8408130408	8408130394	84/08/09	50-338 G
8408130410	8408130406	84/08/08	50-289 G
8408130411	8408130407	84/08/07	50-346 G
8408130413	8408130401	84/08/07	50-10 F
8408130416	8408130414	84/07/31	50-344 F
8408130417	8408130406	84/08/08	50-289 G
8408130418	8408130394	84/08/09	50-338 G
8408130420	8408130415	84/04/13	50-454 G
8408130428	8408130421	84/08/04	50-346 P
8408130437	8408130435	84/08/02	CONTRACT
8408130438	8408130433	84/08/09	50-338 G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408130439	8408130436	84/07/31	50-334 P
8408130441	8408130436	84/07/31	50-334 P
8408130442	8408130440	84/08/02	CONTRACT
8408130443	8408130433	84/08/09	50-338 Q
8408130445	8408130444	84/08/02	CONTRACT
8408130446	8408130433	84/08/09	50-338 Q
8408130455	8408130449	84/07/26	50-445 A
8408130507	8408130502	84/07/27	70-1257
8408130511	8408130502	84/07/27	70-1257
8408130537	8408130530	84/07/25	50-346 P
8408130545	8408130530	84/07/25	50-346 P
8408130559	8408130554	84/08/01	50-334 P
8408130560	8408130555	84/08/03	PRM
8408130567	8408130561	84/08/01	50-321 P
8408130597	8408130592	84/08/06	CONTRACT
8408140012	8408140011	84/07/20	50-275 P
8408140017	8408140013	84/08/09	50-322 T
8408140018	8408140014	84/08/09	50-400 T
8408140023	8408140014	84/08/09	50-400 T
8408140027	8408140014	84/08/09	50-400 T
8408140031	8408140014	84/08/09	50-400 T
8408140033	8408140029	84/07/24	50-338 F
8408140034	8408140028	84/08/09	50-456 Q
8408140036	8408140014	84/08/09	50-400 T
8408140038	8408140028	84/08/09	50-456 Q
8408140039	8408010061	84/07/18	50-329 A
8408140050	8408010061	84/07/18	50-329 A
8408140055	8408010061	84/07/18	50-329 A
8408140060	8408010061	84/07/18	50-329 A
8408140065	8408010061	84/07/18	50-329 A
8408140069	8408010061	84/07/18	50-329 A
8408140070	8408140064	84/08/09	50-400 T
8408140071	8408010061	84/07/18	50-329 A
8408140075	8408140064	84/08/09	50-400 T
8408140076	8408010061	84/07/18	50-329 A
8408140079	8408010061	84/07/18	50-329 A
8408140081	8408140064	84/08/09	50-400 T
8408140086	8408140064	84/08/09	50-400 T
8408140093	8408140064	84/08/09	50-400 T
8408140095	8408140091	84/08/10	50-458 Q
8408140102	8408010061	84/07/18	50-329 A
8408140110	8408140103	84/08/10	50-413 Q
8408140115	8408140103	84/08/10	50-413 Q
8408140122	8408140119	84/08/09	50-400 Q
8408140124	8408140105	84/08/07	50-321 P
8408140125	8408140119	84/08/09	50-400 Q
8408140134	8408010061	84/07/18	50-329 A
8408140144	8408010061	84/07/18	50-329 A
8408140151	8408140146	84/08/09	50-400 T
8408140152	8408010061	84/07/18	50-329 A
8408140158	8408010061	84/07/18	50-329 A
8408140163	8408010061	84/07/18	50-329 A
8408140167	8408140161	84/08/09	50-244 F
8408140169	8408140156	84/08/09	50-374 Q
8408140170	8408010061	84/07/18	50-329 A
8408140180	8408140156	84/08/09	50-374 Q
8408140185	8408010061	84/07/18	50-329 A
8408140190	8408140156	84/08/09	50-374 Q
8408140194	8408140188	84/08/07	50-206 P
8408140196	8408010061	84/07/18	50-329 A
8408140204	8408140200	84/08/10	TOPREP
8408140209	8408010061	84/07/18	50-329 A
8408140213	8408010061	84/07/18	50-329 A
8408140218	8408010061	84/07/18	50-329 A
8408140220	8408140214	84/08/10	50-250 Q
8408140223	8408010061	84/07/18	50-329 A
8408140226	8408140214	84/08/10	50-250 Q
8408140232	8408010061	84/07/18	50-329 A
8408140236	8408140214	84/08/10	50-250 Q
8408140241	8408140229	84/08/09	50-454 Q
8408140242	8408010061	84/07/18	50-329 A
8408140245	8408140239	84/08/09	50-293 P
8408140248	8408010061	84/07/18	50-329 A
8408140253	8408140214	84/08/10	50-250 Q
8408140256	8408140251	84/08/09	50-293 P
8408140258	8408010061	84/07/18	50-329 Q
8408140262	8408140214	84/08/10	50-250 Q
8408140263	8408010061	84/07/18	50-329 A
8408140271	8408140214	84/08/10	50-250 Q
8408140277	8408140214	84/08/10	50-250 Q

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408140286	8408010061	84/07/18	50-329 A
8408140296	8408010061	84/07/18	50-329 A
8408140300	8408010061	84/07/18	50-329 A
8408140311	8408060061	84/07/18	50-329 A
8408140314	8408140303	84/08/08	50-352 E
8408140319	8408010061	84/07/18	50-329 A
8408140320	8408140303	84/08/08	50-352 E
8408140326	8408140303	84/08/08	50-352 E
8408140347	8408010061	84/07/18	50-329 A
8408140349	8408210097	84/08/15	50-97 F
8408140352	8408010061	84/07/18	50-329 A
8408140359	8408010061	84/07/18	50-329 A
8408140363	8408140356	84/08/08	50-261 P
8408140367	8408010061	84/07/18	50-329 A
8408140389	8408140372	84/08/07	50-237 V
8408140404	8408140402	84/08/10	50-483 Q
8408140413	8408140410	84/08/10	50-346 P
8408140415	8408140411	84/08/08	50-289 P
8408140422	8408140420	84/08/10	PR
8408140423	8408140421	84/08/03	50-458 A
8408140433	8408140429	84/08/06	50-313 P
8408140452	8408140450	84/08/08	50-352 G
8408140476	8408140469	84/06/26	71-9016
8408140477	8408140470	84/08/13	50-322 G
8408140480	8408140469	84/06/26	71-9016
8408140485	8408140469	84/06/26	71-9016
8408140513	8408010061	84/07/18	50-329 A
8408140517	8408140510	84/07/26	CONTRACT
8408140522	8408010061	84/07/18	50-329 A
8408140526	8408010061	84/07/18	50-329 A
8408140530	8408010061	84/07/18	50-329 A
8408140535	8408140532	84/08/06	50-327 P
8408140539	8408010061	84/07/18	50-329 A
8408140553	8408010061	84/07/18	50-329 A
8408140556	8408010061	84/07/18	50-329 A
8408140557	8408010061	84/07/18	50-329 A
8408140561	8408140558	84/08/07	50-166 P
8408140562	8408010061	84/07/18	50-329 A
8408140564	8408140558	84/08/07	50-166 P
8408140565	8408010061	84/07/18	50-329 A
8408140566	8408010061	84/07/18	50-329 A
8408140569	8408140558	84/08/07	50-166 P
8408140570	8408010061	84/07/18	50-329 A
8408140573	8408010061	84/07/18	50-329 A
8408140575	8408010061	84/07/18	50-329 A
8408150015	8408010061	84/07/18	50-329 A
8408150019	8408010061	84/07/18	50-329 A
8408150022	8408010061	84/07/18	50-329 A
8408150027	8408010061	84/07/18	50-329 A
8408150029	8408010061	84/07/18	50-329 A
8408150033	8408010061	84/07/18	50-329 A
8408150042	8408010061	84/07/18	50-329 A
8408150046	8408010061	84/07/18	50-329 A
8408150094	8408150091	84/07/26	50-445 Q
8408150097	8408150091	84/07/26	50-445 Q
8408150102	8408150091	84/07/26	50-445 Q
8408150110	8408150107	84/07/26	50-336 Q
8408150114	8408150109	84/07/27	71-6346
8408150118	8408150115	84/08/07	50-13 P
8408150125	8408150121	84/07/16	50-3 F
8408150127	8408150119	84/08/13	50-454 T
8408150132	8408150119	84/08/13	50-454 T
8408150143	8408150141	84/07/10	71-522
8408150149	8408150144	84/08/01	WASTE MGT
8408150154	8408150151	84/08/14	50-416 P
8408150161	8408150156	84/07/27	70-143
8408150184	8408150180	84/08/13	50-313 P
8408150228	8408150225	84/08/09	50-219 P
8408150236	8408150233	84/07/26	50-277 Q
8408150244	8408150233	84/07/26	50-277 Q
8408150250	8408150246	84/08/08	XPORTLIC
8408150255	8408150251	84/07/25	50-213 Q
8408150258	8408150256	84/07/24	50-443 Q
8408150262	8408150256	84/07/24	50-443 Q
8408150271	8408150264	84/07/26	50-289 Q
8408150275	8408150269	84/08/14	50-219 F
8408150293	8408150290	84/07/25	50-255 Q
8408150299	8408150293	84/07/25	50-255 Q
8408150301	8408150298	84/07/18	50-317 Q
8408150305	8408150298	84/07/18	50-317 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408150317	8408150312	84/07/23	50-313 G
8408150335	8408150326	84/07/17	50-269 F
8408150341	8408150337	84/07/05	WASTE MGT
8408150344	8408150337	84/07/05	WASTE MGT
8408150361	8408150359	84/08/06	XPORTLIC
8408150368	8408150366	84/07/25	50-272 G
8408150370	8408150366	84/07/25	50-272 G
8408150373	8408150372	84/05/16	50-313 G
8408150375	8408150372	84/05/16	50-313 G
8408150381	8408150380	84/07/27	50-440 G
8408150394	8408150386	84/07/27	50-454 G
8408150401	8408150392	84/07/26	50-254 G
8408150406	8408150399	84/07/25	50-266 G
8408150407	8408150398	84/07/27	70-371
8408150417	8408150414	84/07/26	50-445 G
8408150424	8408150409	84/07/25	50-277 G
8408150440	8408150414	84/07/26	50-445 G
8408150455	8408150453	84/07/26	50-333 G
8408150475	8408150471	84/07/27	50-341 G
8408150476	8408150473	84/08/14	50-322 T
8408150485	8408150473	84/08/14	50-322 T
8408150487	8408150482	84/07/27	50-454 G
8408150498	8408150473	84/08/14	50-322 T
8408150505	8408150473	84/08/14	50-322 T
8408150507	8408150502	84/07/27	50-461 G
8408150511	8408150502	84/07/27	50-461 G
8408150514	8408150473	84/08/14	50-322 T
8408150515	8408150510	84/07/20	50-382 G
8408150530	8408150473	84/08/14	50-322 T
8408150533	8408150531	84/08/01	WASTE MGT
8408150539	8408150537	84/07/27	50-333 G
8408150541	8408150537	84/07/27	50-333 G
8408150546	8408150544	84/07/26	50-263 G
8408150547	8408150544	84/07/26	50-263 G
8408150560	8408010061	84/07/18	50-329 A
8408150566	8408010061	84/07/18	50-329 A
8408150569	8408150565	84/08/03	50-346 P
8408150571	8408010061	84/07/18	50-329 A
8408150572	8408150568	84/06/29	WASTE MGT
8408150577	8408010061	84/07/18	50-329 A
8408150580	8408150573	84/07/26	50-29 G
8408150585	8408150578	84/07/30	50-271 P
8408150586	8408010061	84/07/18	50-329 A
8408150589	8408150583	84/07/24	70-1151
8408150593	8408150588	84/08/02	50-254 P
8408150595	8408010061	84/07/18	50-329 A
8408150597	8408150588	84/08/02	50-254 P
8408150600	8408150594	84/07/31	71-9016
8408150603	8408010061	84/07/18	50-329 R
8408150604	8408150599	84/08/01	50-271 P
8408150606	8408150599	84/08/01	50-271 P
8408150608	8408010061	84/07/18	50-329 A
8408150612	8408010061	84/07/18	50-329 E
8408150613	8408150609	84/08/03	50-333 P
8408150615	8408150609	84/08/03	50-333 P
8408150616	8408010061	84/07/18	50-329 A
8408150617	8408010061	84/07/18	50-329 A
8408150622	8408010061	84/07/18	50-329 Q
8408150623	8408150620	84/07/31	50-293 P
8408150624	8408010061	84/07/18	50-329 A
8408150626	8408010061	84/07/18	50-329 A
8408150630	8408010061	84/07/18	50-329 A
8408150633	8408010061	84/07/18	50-329 Q
8408150634	8408150631	84/07/24	50-272 Q
8408150635	8408010061	84/07/18	50-329 A
8408150639	8408010061	84/07/18	50-329 Q
8408150640	8408010061	84/07/18	50-329 Q
8408150643	8408010061	84/07/18	50-329 A
8408150644	8408010061	84/07/18	50-329 Q
8408150646	8408150638	84/07/27	50-341 Q
8408150648	8408010061	84/07/18	50-329 A
8408150651	8408010061	84/07/18	50-329 A
8408150652	8408010061	84/07/18	50-329 A
8408150653	8408150650	84/07/24	50-354 G
8408150654	8408150647	84/07/30	71-9016
8408150655	8408150649	84/07/23	50-445 Q
8408150656	8408010061	84/07/18	50-329 A
8408150658	8408010061	84/07/18	50-329 S
8408150662	8408010061	84/07/18	50-329 A
8408150665	8408010061	84/07/18	50-329 A

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408150666	8408010061	84/07/18	50-329 A
8408150669	8408010061	84/07/18	50-329 Q
8408150672	8408010061	84/07/18	50-329 Q
8408150675	8408150671	84/07/26	40-8027
8408150676	8408010061	84/07/18	50-329 A
8408150677	8408010061	84/07/18	50-329 Q
8408150681	8408010061	84/07/18	50-329 A
8408150682	8408010061	84/07/18	50-329 A
8408150685	8408010061	84/07/18	50-329 A
8408150686	8408010061	84/07/18	50-329 A
8408150689	8408010061	84/07/18	50-329 A
8408150690	8408010061	84/07/18	50-329 Q
8408150692	8408010061	84/07/18	50-329 A
8408150693	8408150688	84/07/27	50-245 Q
8408150694	8408010061	84/07/18	50-329 S
8408150695	8408010061	84/07/18	50-329 A
8408150698	8408010061	84/07/18	50-329 R
8408150700	8408010061	84/07/18	50-329 A
8408150701	8408150697	84/07/27	50-286 Q
8408150702	8408010061	84/07/18	50-329 Q
8408150706	8408010061	84/07/18	50-329 A
8408150709	8408010061	84/07/18	50-329 A
8408150710	8408010061	84/07/18	50-329 A
8408150712	8408010061	84/07/18	50-329 A
8408150714	8408010061	84/07/18	50-329 A
8408150715	8408150711	84/07/27	50-317 Q
8408150716	8408010061	84/07/18	50-329 A
8408150718	8408010061	84/07/18	50-329 A
8408150720	8408010061	84/07/18	50-329 A
8408150721	8408150711	84/07/27	50-317 Q
8408150723	8408010061	84/07/18	50-329 A
8408150725	8408010061	84/07/18	50-329 A
8408150727	8408010061	84/07/18	50-329 A
8408150728	8408010061	84/07/18	50-329 A
8408150729	8408010061	84/07/18	50-329 A
8408150731	8408010061	84/07/18	50-329 A
8408150732	8408010061	84/07/18	50-329 A
8408150734	8408010061	84/07/18	50-329 A
8408150735	8408010061	84/07/18	50-329 A
8408150736	8408150733	84/07/31	71-9073
8408150737	8408010061	84/07/18	50-329 A
8408150738	8408010061	84/07/18	50-329 A
8408150739	8408150733	84/07/31	71-9073
8408150740	8408010061	84/07/18	50-329 A
8408150741	8408010061	84/07/18	50-329 A
8408150742	8408150733	84/07/31	71-9073
8408150743	8408010061	84/07/18	50-329 A
8408150744	8408150733	84/07/31	71-9073
8408150745	8408010061	84/07/18	50-329 A
8408150747	8408010061	84/07/18	50-329 A
8408150749	8408010061	84/07/18	50-329 A
8408150750	8408010061	84/07/18	50-329 A
8408150751	8408010061	84/07/18	50-329 A
8408150752	8408010061	84/07/18	50-329 A
8408160036	8408160033	84/08/09	50-293 P
8408160037	8408160026	84/07/26	50-445 Q
8408160045	8408160041	84/08/09	50-293 P
8408160056	8408160052	84/08/10	50-271 P
8408160070	8408160062	84/08/06	50-237 P
8408160072	8408160067	84/08/07	50-483 P
8408160082	8408160073	84/07/27	50-29 Q
8408160107	8408160102	84/07/24	50-317 Q
8408160113	8408160106	84/08/13	50-445 Q
8408160115	8408160102	84/07/24	50-317 Q
8408160131	8408160106	84/08/13	50-445 Q
8408160132	8408160129	84/08/10	50-324 Q
8408160145	8408160139	84/08/10	50-10 Q
8408160153	8408160141	84/08/13	50-445 Q
8408160158	8408160141	84/08/13	50-445 Q
8408160166	8408160163	84/08/09	50-410 D
8408160178	8408160171	84/08/13	50-445 Q
8408160187	8408160171	84/08/13	50-445 Q
8408160190	8408160184	84/07/30	50-483 Q
8408160193	8408160184	84/07/30	50-483 Q
8408160204	8408160201	84/07/23	50-445 Q
8408160206	8408160198	84/08/10	50-373 Q
8408160216	8408160212	84/07/30	50-454 Q
8408160217	8408160212	84/07/30	50-454 Q
8408160224	8408160210	84/08/13	50-322 Q
8408160226	8408160220	84/06/28	50-382 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408160229	8408160222	84/07/27	50-263 P
8408160233	8408160222	84/07/27	50-263 P
8408160237	8408160230	84/07/30	50-458 G
8408160246	8408160235	84/08/01	50-245 G
8408160260	8408160251	84/08/01	50-322 G
8408160264	8408160257	84/06/29	ORG
8408160271	8408160257	84/06/29	ORG
8408160272	8408160266	84/07/30	50-334 G
8408160273	8408160267	84/07/20	50-275 F
8408160275	8408160257	84/06/29	ORG
8408160280	8408160257	84/06/29	ORG
8408160281	8408160270	84/07/20	50-311 G
8408160283	8408160278	84/08/07	WASTE MGT
8408160288	8408160257	84/06/29	ORG
8408160292	8408160257	84/06/29	ORG
8408160317	8408160310	84/08/03	70-143
8408160325	8408160319	84/08/07	50-250 P
8408160327	8408160324	84/07/30	50-346 G
8408160331	8408160329	84/07/30	50-266 G
8408160338	8408160334	84/07/30	50-341 G
8408160340	8408160335	84/08/10	50-445 A
8408160341	8408160334	84/07/30	50-341 G
8408160356	8408160353	84/08/14	50-244 P
8408160360	8408160355	84/07/09	50-352 F
8408160361	8408160353	84/08/14	50-244 P
8408160369	8408160368	84/08/14	50-293 F
8408160372	8408160367	84/08/14	50-220 P
8408160373	8408160371	84/08/09	50-443 A
8408160378	8408160371	84/08/09	50-443 A
8408160384	8408160377	84/07/27	TOPREP
8408160390	8408160386	84/07/31	50-458 A
8408160397	8408160395	84/08/14	50-206 S
8408160403	8408160394	84/08/10	50-206 S
8408160405	8408160404	84/08/08	50-508 A
8408160407	8408160404	84/08/08	50-508 A
8408160411	8408160404	84/08/08	50-508 A
8408160413	8408160404	84/08/08	50-508 A
8408160414	8408160404	84/08/08	50-508 A
8408160426	8408160424	84/07/30	50-259 P
8408160427	8408160424	84/07/30	50-259 P
8408160432	8408160428	84/08/01	50-245 G
8408160457	8408160455	84/06/20	50-458 G
8408160466	8408160461	84/08/10	70-1308
8408160469	8408160465	84/08/02	50-254 P
8408160472	8408160461	84/08/10	70-1308
8408160475	8408160470	84/07/31	WASTE MGT
8408160495	8408160485	84/07/30	50-445 G
8408160500	8408160485	84/07/30	50-445 G
8408160502	8408160501	84/08/02	50-445 T
8408160504	8408160498	84/07/23	50-313 G
8408160509	8408160507	84/07/23	50-267 G
8408160513	8408160507	84/07/23	50-267 G
8408160515	8408160511	84/07/30	50-458 G
8408160516	8408160507	84/07/23	50-267 G
8408160523	8408160520	84/07/27	50-482 G
8408170023	8408170021	84/08/03	71-6244
8408170046	8408170041	84/07/30	50-334 F
8408170056	8408170052	84/08/14	50-354 F
8408170081	8408010061	84/07/18	50-329 A
8408170090	8408010061	84/07/18	50-329 S
8408170098	8408010061	84/07/18	50-329 T
8408170102	8408010061	84/07/18	50-329 A
8408170117	8408170109	84/07/18	50-443 G
8408170117	8408170109	84/07/18	50-443 G
8408170117	8408170109	84/07/18	50-443 G
8408170119	8408010061	84/07/18	50-329 G
8408170141	8408010061	84/07/18	50-329 A
8408170143	8408170130	84/08/07	50-206 P
8408170145	8408010061	84/07/18	50-329 A
8408170147	8408170144	84/08/02	50-344 P
8408170150	8408170144	84/08/02	50-344 P
8408170152	8408010061	84/07/18	50-329 G
8408170155	8408170130	84/08/07	50-206 P
8408170157	8408010061	84/07/18	50-329 G
8408170166	8408010061	84/07/18	50-329 A
8408170174	8408010061	84/07/18	50-329 G
8408170181	8408010061	84/07/18	50-329 G
8408170187	8408010061	84/07/18	50-329 A
8408170195	8408010061	84/07/18	50-329 A
8408170203	8408170198	84/08/13	50-266 G

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8408170205	8408010061	84/07/18	50-329 G
8408170223	8408010061	84/07/18	50-329 G
8408170232	8408010061	84/07/18	50-329 G
8408170236	8408010061	84/07/18	50-329 G
8408170237	8408170233	84/08/14	50-335 G
8408170243	8408170227	84/08/08	50-373 P
8408170247	8408170227	84/08/08	50-373 P
8408170253	8408010061	84/07/18	50-329 A
8408170257	8408010061	84/07/18	50-329 A
8408170260	8408010061	84/07/18	50-329 A
8408170262	8408170252	84/08/16	50-263 P
8408170265	8408170263	84/08/09	50-295 G
8408170268	8408010061	84/07/18	50-329 F
8408170271	8408010061	84/07/18	50-329 G
8408170274	8408010061	84/07/18	50-329 G
8408170276	8408010061	84/07/18	50-329 S
8408170279	8408010061	84/07/18	50-329 A
8408170284	8408010061	84/07/18	50-329 A
8408170292	8408010061	84/07/18	50-329 T
8408170297	8408010061	84/07/18	50-329 T
8408170304	8408010061	84/07/18	50-329 T
8408170312	8408010061	84/07/18	50-329 T
8408170313	8408170308	84/08/10	50-395 V
8408170318	8408170308	84/08/10	50-395 V
8408170320	8408010061	84/07/18	50-329 A
8408170321	8408170319	84/08/13	50-454 T
8408170326	8408170319	84/08/13	50-454 T
8408170327	8408170322	84/08/13	50-315 F
8408170330	8408170325	84/08/15	50-289 G
8408170339	8408170336	84/08/14	50-354 G
8408170342	8408170336	84/08/14	50-354 G
8408170343	8408170336	84/08/14	50-354 G
8408170358	8408010061	84/07/18	50-329 A
8408170360	8408010061	84/07/18	50-329 A
8408170365	8408010061	84/07/18	50-329 A
8408170367	8408010061	84/07/18	50-329 A
8408170372	8408010061	84/07/18	50-329 A
8408170374	8408010061	84/07/18	50-329 K
8408170377	8408010061	84/07/18	50-329 A
8408170387	8408170383	84/08/15	40-2061
8408170389	8408170383	84/08/15	40-2061
8408170393	8408170392	84/03/30	70-143
8408170394	8408170392	84/03/30	70-143
8408170399	8408170398	84/07/31	50-295 F
8408170408	8408170406	84/08/03	XPORTLIC
8408170415	8408170413	84/07/27	WASTE MGT
8408200017	8408200014	84/07/31	50-289 G
8408200023	8408200014	84/07/31	50-289 G
8408200036	8408200032	84/07/31	50-387 G
8408200041	8408200032	84/07/31	50-387 G
8408200052	8408200043	84/07/30	50-272 G
8408200069	8408200059	84/08/08	50-269 P
8408200090	8408200086	84/08/13	71-240
8408200123	8408200117	84/08/15	50-482 A
8408200155	8408200149	84/08/02	50-269 P
8408200157	8408200154	84/07/26	WASTE MGT
8408200164	8408200161	84/08/02	50-336 P
8408200169	8408200161	84/08/02	50-336 P
8408200173	8408200161	84/08/02	50-336 P
8408200184	8408200182	84/08/08	50-255 D
8408200224	8408200217	84/08/16	50-528 F
8408200227	8408200221	84/08/03	50-454 G
8408200235	8408200225	84/08/10	50-388 U
8408200241	8408200233	84/08/02	50-155 G
8408200263	8408200225	84/08/10	50-416 G
8408200267	8408200225	84/08/10	50-416 G
8408200269	8408200264	84/08/02	50-259 P
8408200271	8408200225	84/08/10	50-416 G
8408200279	8408200225	84/08/10	50-369 U
8408200280	8408200264	84/08/02	50-259 P
8408200282	8408200274	84/08/13	50-289 H
8408200288	8408200285	84/08/10	50-528 S
8408200292	8408200290	84/08/02	50-458 G
8408200304	8408200299	84/08/02	50-498 G
8408200318	8408200313	84/08/13	50-275 G
8408200321	8408200316	84/08/02	50-458 G
8408200325	8408200320	84/08/01	50-317 P
8408200326	8408200316	84/08/02	50-458 G
8408200327	8408200320	84/08/01	50-317 P
8408200334	8408200112	84/08/16	50-528 F

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

SION NUMBER	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
E				
50	8408200359	84/08/02	50-285	P
51	8408200359	84/08/02	50-285	P
55	8408200364	84/07/31	50-354	G
56	8408200364	84/07/31	50-354	G
73	8408200390	84/08/09	50-260	P
31	8408200400	84/06/29	40-2259	
24	8408200414	84/08/09	50-269	F
32	8408200426	84/07/30	WASTE MGT	
41	8408200437	84/08/13	50-260	P
42	8408200433	84/08/14	50-352	G
17	8408200433	84/08/14	50-352	G
54	8408200449	84/08/08	50-352	U
48	8408200446	84/08/20	50-454	T
44	8408200461	84/08/13	50-188	F
71	8408200469	84/08/13	50-423	E
75	8408200470	84/07/31	WASTE MGT	
17	8408200476	84/07/30	50-29	G
19	8408200484	84/07/31	50-282	F
71	8408200480	84/07/31	WASTE MGT	
73	8408200485	84/08/14	XPORTLIC	
77	8408200490	84/08/14	50-400	G
74	8408200495	84/08/01	50-354	G
1	8408200499	84/08/15	50-413	G
8	8408200510	84/08/01	50-247	G
0	8408200510	84/08/01	50-247	G
4	8408200510	84/08/01	50-247	G
5	8408200540	84/08/09	50-458	D
6	8408200563	84/08/09	XPORTLIC	
3	8408200587	84/08/15	50-338	G
7	8408200590	84/08/14	CONTRACT	
0	8408200599	84/08/15	50-528	F
6	8408200602	84/08/14	CONTRACT	
4	8408210003	84/08/09	50-259	P
5	8408210001	84/08/14	50-10	F
7	8408210003	84/08/09	50-259	P
1	8408210008	84/08/20	50-219	P
2	8408210009	84/08/10	50-325	P
3	8408210009	84/08/10	50-325	P
2	8408210024	84/08/14	CONTRACT	
6	8408210042	84/06/12	50-206	P
7	8408210040	84/08/14	CONTRACT	
1	8408210054	84/08/13	50-302	P
5	8408210054	84/08/13	50-302	P
0	8408210062	84/08/10	50-312	P
4	8408210062	84/08/10	50-312	P
5	8408210079	84/07/25	50-341	A
5	8408210090	84/08/16	50-498	G
1	8408210110	84/07/31	40-2259	
1	8408210110	84/07/31	40-2259	
7	8408210101	84/08/14	50-116	F
0	8408210110	84/07/31	40-2259	
1	8408210115	84/07/30	WASTE MGT	
1	8408210129	84/08/03	40-4492	
0	8408210129	84/08/03	40-4492	
1	8408210129	84/08/03	40-4492	
1	8408210161	84/07/26	50-142	G
7	8408210165	84/08/16	50-206	P
0	8408210183	82/02/26	70-36	
0	8408210189	84/07/25	70-303	
1	8408210183	82/02/26	70-36	
1	8408210193	84/08/14	50-374	G
1	8408210175	84/08/16	50-366	P
	8408210238	84/08/02	50-247	G
1	8408210256	84/08/14	50-331	I
1	8408210256	84/08/14	50-331	I
1	8408210256	84/08/14	50-331	I
	8408210277	84/08/15	50-333	G
1	8408210307	84/08/20	50-255	P
	8408210311	83/11/01	50-498	A
	8408210327	84/08/15	50-155	G
	8408210327	84/08/15	50-155	G
	8408210336	84/08/16	50-454	G
	8408210346	84/08/13	50-302	F
	8408210342	84/08/15	50-456	G
	8408210305	84/08/16	50-382	A
	8408010061	84/07/18	50-329	A
	8408210365	84/08/14	50-413	P
	8408210368	84/08/02	50-352	G
	8408210366	84/08/17	50-358	G
	8408010061	84/07/18	50-329	A

ACCESSION NUMBER	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
ENCLOSURE				
8408210379	8408010061	84/07/18	50-329	A
8408210381	8408210368	84/08/02	50-352	G
8408210382	8408210376	84/07/27	TOPREP	
8408210384	8408010061	84/07/18	50-329	A
8408210386	8408010061	84/07/18	50-329	A
8408210387	8408210375	84/08/16	50-338	P
8408210391	8408010061	84/07/18	50-329	G
8408210392	8408010061	84/07/18	50-329	A
8408210393	8408210375	84/08/16	50-338	P
8408210394	8408210368	84/08/02	50-352	G
8408210397	8408010061	84/07/18	50-329	A
8408210398	8408010061	84/07/18	50-329	G
8408210401	8408010061	84/07/18	50-329	A
8408210404	8408010061	84/07/18	50-329	A
8408210409	8408210403	84/08/15	50-382	A
8408210410	8408010061	84/07/18	50-329	A
8408210411	8408010061	84/07/18	50-329	A
8408210414	8408010061	84/07/18	50-329	A
8408210418	8408010061	84/07/18	50-329	A
8408210421	8408010061	84/07/18	50-329	A
8408210425	8408010061	84/07/18	50-329	A
8408210426	8408210419	84/08/16	50-29	P
8408210429	8408210420	84/08/14	50-352	G
8408210430	8408010061	84/07/18	50-329	A
8408210433	8408010061	84/07/18	50-329	A
8408210436	8408210424	84/08/16	50-333	G
8408210446	8408010061	84/07/18	50-329	A
8408210449	8408210443	84/08/13	50-286	P
8408210450	8408010061	84/07/18	50-329	A
8408210451	8408210443	84/08/13	50-286	P
8408210453	8408010061	84/07/18	50-329	A
8408210454	8408010061	84/07/18	50-329	E
8408210455	8408010061	84/07/18	50-329	A
8408210461	8408010061	84/07/18	50-329	A
8408210463	8408010061	84/07/18	50-329	A
8408210464	8408010061	84/07/18	50-329	G
8408210469	8408210468	84/08/16	50-336	G
8408210471	8408210470	84/08/17	50-461	G
8408210478	8408210477	84/06/15	State Prog	
8408210489	8408210486	84/08/15	TOPREP	
8408210495	8408210494	84/08/01	50-245	G
8408210496	8408210494	84/08/01	50-245	G
8408210501	8408210494	84/08/01	50-245	G
8408210502	8408210499	84/08/16	50-331	P
8408210503	8408210500	84/04/02	50-498	A
8408210517	8408210515	84/08/01	50-336	G
8408210518	8408210513	84/08/16	50-352	A
8408210520	8408210513	84/08/16	50-352	A
8408210549	8408210546	84/08/09	50-171	R
8408210555	8408210546	84/08/09	50-171	R
8408210576	8408210567	84/08/10	50-302	P
8408210582	8408210567	84/08/10	50-302	P
8408220059	8408010061	84/07/18	50-329	G
8408220064	8408010061	84/07/18	50-329	T
8408220070	8408010061	84/07/18	50-329	A
8408220071	8408220051	84/08/16	50-528	G
8408220078	8408010061	84/07/18	50-329	G
8408220080	8408220075	84/08/02	CONTRACT	
8408220081	8408220076	84/08/13	WASTE MGT	
8408220085	8408010061	84/07/18	50-329	A
8408220090	8408010061	84/07/18	50-329	A
8408220099	8408220093	84/08/20	50-409	P
8408220112	8408220106	84/08/16	50-454	F
8408220156	8408220150	84/08/10	CONTRACT	
8408220157	8408220152	84/07/19	50-458	G
8408220168	8408220165	84/08/15	50-352	A
8408220208	8408220201	84/08/15	50-249	K
8408220219	8408220215	84/08/10	WASTE MGT	
8408220252	8408220247	84/07/31	50-382	G
8408220256	8408220247	84/07/31	50-382	G
8408220263	8408220258	84/08/20	50-289	G
8408220302	8408220274	84/08/15	ORG	
8408220310	8408220274	84/08/15	ORG	
8408220315	8408220274	84/08/15	ORG	
8408220316	8408220313	84/08/15	50-313	P
8408220321	8408220306	84/08/13	50-454	E
8408220330	8408220326	84/08/20	50-213	P
8408220365	8408220363	84/08/16	50-289	P
8408220371	8408220367	84/08/20	50-445	T
8408220373	8408220366	84/08/20	50-289	G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408220374	8408220367	84/08/20	50-445	T
8408220380	8408220367	84/08/20	50-445	T
8408220381	8408220367	84/08/20	50-445	T
8408220385	8408220367	84/08/20	50-445	T
8408220387	8408220384	84/08/02	CONTRACT	
8408220388	8408220367	84/08/20	50-445	T
8408220393	8408220367	84/08/20	50-445	T
8408220396	8408220367	84/08/20	50-445	T
8408220399	8408220367	84/08/20	50-445	T
8408220400	8408220397	84/07/18	CONTRACT	
8408220403	8408220367	84/08/20	50-445	T
8408220404	8408220397	84/07/18	CONTRACT	
8408220405	8408220367	84/08/20	50-445	T
8408220412	8408160313	84/08/07	50-445	Q
8408220415	8408160313	84/08/07	50-445	Q
8408220419	8408160313	84/08/07	50-445	Q
8408220424	8408160313	84/08/07	50-445	Q
8408220448	8408220444	84/08/16	50-320	P
8408220500	8408220494	84/07/31	50-382	Q
8408220501	8408220497	84/08/07	50-352	F
8408220530	8408220527	84/08/03	50-277	P
8408220531	8408220527	84/08/03	50-277	P
8408230012	8408230008	84/08/20	50-275	P
8408230013	8408230010	84/07/31	50-298	Q
8408230043	8408230038	84/08/11	WASTE MGT	
8408230063	8408230056	84/08/15	50-272	H
8408230087	8408230078	84/07/30	50-312	Q
8408230090	8408230083	84/08/17	50-354	D
8408230091	8408230082	84/08/03	50-293	Q
8408230098	8408230094	84/08/10	50-219	Q
8408230101	8408230094	84/08/10	50-219	Q
8408230103	8408230093	84/08/20	50-261	P
8408230105	8408230097	84/08/07	50-327	P
8408230108	8408230097	84/08/07	50-327	P
8408230112	8408230097	84/08/07	50-327	P
8408230116	8408230097	84/08/07	50-327	P
8408230119	8408230097	84/08/07	50-327	P
8408230122	8408230117	84/08/20	50-261	P
8408230131	8408230097	84/08/07	50-327	P
8408230133	8408230130	84/08/03	50-277	Q
8408230136	8408230130	84/08/03	50-277	Q
8408230142	8408230141	84/08/06	50-341	Q
8408230144	8408230141	84/08/06	50-341	Q
8408230145	8408230139	84/08/01	50-271	Q
8408230149	8408230146	84/08/06	50-409	Q
8408230152	8408230147	84/07/20	50-445	Q
8408230155	8408230151	84/08/17	50-251	Q
8408230157	8408230153	84/08/03	50-352	Q
8408230158	8408230151	84/08/17	50-251	Q
8408230161	8408230151	84/08/17	50-251	Q
8408230166	8408230151	84/08/17	50-251	Q
8408230171	8408230164	84/08/16	50-286	F
8408230180	8408230167	84/08/13	50-259	Q
8408230184	8408230172	84/07/30	50-317	P
8408230191	9408230172	84/07/30	50-317	P
8408230192	8408230167	84/08/13	50-259	Q
8408230196	8408230183	84/08/15	70-1450	
8408230198	8408230193	84/08/17	40-791	
8408230208	8408230167	84/08/13	50-259	Q
8408230211	8408230204	84/07/24	50-315	Q
8408230219	8408230167	84/08/13	50-259	Q
8408230225	8408230167	84/08/13	50-259	Q
8408230230	8408230226	84/08/01	50-220	Q
8408230233	8408230220	84/07/26	50-483	Q
8408230234	8408230227	84/07/31	50-409	Q
8408230235	8408230226	84/08/01	50-220	Q
8408230238	8408230227	84/07/31	50-409	Q
8408230240	8408230167	84/08/13	50-259	Q
8408230248	8408230242	84/08/03	50-322	Q
8408230252	8408230245	84/08/06	50-454	Q
8408230255	8408230249	84/08/20	50-324	Q
8408230266	8408230263	84/08/21	50-315	P
8408230284	8408230275	84/08/17	50-382	Q
8408230285	8408230276	84/08/01	50-293	Q
8408230297	8408230292	84/08/13	50-352	E
8408230298	8408230293	84/08/06	50-373	Q
8408230301	8408230296	84/08/16	50-341	E
8408230336	8408230330	84/08/03	CONTRACT	
8408230346	8408230340	84/08/10	TOPREP	
8408230360	8408230355	84/08/16	50-302	H

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408230365	8408230352	84/08/20	50-354	C
8408230371	8408230352	84/08/20	50-354	K
8408230385	8408230384	84/08/20	50-219	P
8408230391	8408230389	84/08/16	50-341	F
8408230397	8408230390	84/08/16	50-445	F
8408230399	8408230398	84/08/17	50-348	P
8408230400	8408230390	84/08/16	50-445	F
8408230440	8408230436	84/08/16	50-289	H
8408230457	8408230454	84/08/15	50-267	R
8408230459	8408230456	84/08/15	50-267	R
8408230463	8408230461	84/07/23	50-285	Q
8408230466	8408230461	84/07/23	50-285	Q
8408230470	8408230465	84/08/09	50-346	P
8408230475	8408230472	84/07/31	40-8102	
8408230478	8408230472	84/07/31	40-8102	
8408230480	8408230474	84/08/03	50-358	Q
8408230481	8408230472	84/07/31	40-8102	
8408230492	8408230487	84/08/02	50-309	Q
8408230495	8408230487	84/08/02	50-309	Q
8408230497	8408230489	84/07/26	50-263	Q
8408230506	8408230484	84/08/16	CONTRACT	
8408230512	8408230502	84/08/03	50-329	Q
8408230522	8408230471	84/07/05	50-267	Q
8408230551	8408230549	84/08/03	50-254	Q
8408230555	8408230549	84/08/03	50-254	Q
8408230558	8408230553	84/08/08	50-275	F
8408230563	8408230562	84/08/16	XPORTLIC	
8408230567	8408230566	84/08/02	50-293	Q
8408230569	8408230566	84/08/02	50-293	Q
8408240010	8408240007	84/07/10	50-261	Q
8408240017	8408240015	84/08/02	50-317	P
8408240020	8408240015	84/08/02	50-317	P
8408240024	8408240021	84/08/16	50-382	Q
8408240076	8408240071	84/08/03	50-334	Q
8408240085	8408240082	84/07/24	50-255	Q
8408240088	8408240082	84/07/24	50-255	Q
8408240094	8408240089	84/08/17	CONTRACT	
8408240095	8408240091	84/08/21	50-261	Q
8408240124	8408240118	84/08/17	50-331	P
8408240128	8408240125	84/07/27	QA999	
8408240131	8408240125	84/07/27	QA999	
8408240134	8408240132	84/08/07	50-329	R
8408240138	8408240132	84/08/07	50-329	R
8408240140	8408240125	84/07/27	QA999	
8408240143	8408240132	84/08/07	50-329	R
8408240144	8408240136	84/08/20	50-329	Q
8408240148	8408240132	84/08/07	50-329	R
8408240152	8408240132	84/08/07	50-329	R
8408240157	8408240115	84/08/13	50-206	S
8408240159	8408240132	84/08/07	50-329	R
8408240166	8408240163	84/08/08	40-299	
8408240178	8408240175	84/07/25	40-8768	
8408240180	8408240175	84/07/25	40-8768	
8408240183	8408240175	84/07/25	40-8768	
8408240197	8408240192	84/08/07	40-299	
8408240198	8408240195	84/08/07	40-8698	
8408240201	8408240192	84/08/07	40-299	
8408240205	8408240199	84/08/20	50-305	P
8408240223	8408240220	84/08/06	50-213	Q
8408240226	8408240220	84/08/06	50-213	Q
8408240231	8408240220	84/08/06	50-213	Q
8408240235	8408240105	84/08/20	50-331	P
8408240237	8408240233	84/08/06	50-410	Q
8408240239	8408240224	84/08/16	50-413	I
8408240242	8408240224	84/08/16	50-413	I
8408240248	8408240247	84/08/20	50-445	T
8408240253	8408240233	84/08/06	50-410	Q
8408240257	8408240250	84/08/22	50-219	Q
8408240263	8408240261	84/08/21	50-528	A
8408240281	8408240266	84/08/23	50-29	F
8408240288	8408240273	84/08/15	50-354	E
8408240297	8408240294	84/08/21	50-361	P
8408240319	8408240316	84/08/21	50-261	Q
8408240321	8408240314	84/08/03	50-461	Q
8408240330	8408240328	84/08/13	50-250	F
8408240333	8408240331	84/08/07	40-8586	
8408240342	8408240338	84/07/12	50-259	Q
8408240355	8408240354	84/07/10	WASTE MGT	
8408240359	8408240356	84/07/10	50-321	Q
8408240362	8408240360	84/07/13	50-390	Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408240363	8408240361	84/08/08	50-317	Q
8408240366	8408240364	84/07/11	50-321	Q
8408240367	8408240365	84/07/24	50-424	Q
8408240368	8408240365	84/07/24	50-424	Q
8408240370	8408240365	84/07/24	50-424	Q
8408240371	8408240365	84/07/24	50-424	Q
8408240400	8408240396	84/07/17	40-299	
8408240419	8408240414	84/08/02	40-2259	
8408240421	8408240416	84/07/19	50-269	Q
8408240423	8408240417	84/07/27	40-8584	
8408240429	8408240428	84/08/06	50-305	Q
8408270007	8408270003	84/08/20	50-458	Q
8408270029	8408270028	84/02/27	40-8585	
8408270034	8408270032	84/03/19	40-8502	
8408270078	8408270074	84/08/10	WASTE MGT	
8408270088	8408270082	84/08/17	50-322	Q
8408270090	8408270084	84/08/10	50-341	Q
8408270103	8408270094	84/08/22	50-445	Q
8408270121	8408270116	84/08/09	70-27	
8408270125	8408270116	84/08/09	70-27	
8408270140	8408270133	84/08/20	50-528	E
8408270143	8408270137	84/08/17	50-322	Q
8408270147	8408270141	84/08/22	50-412	E
8408270149	8408270145	84/08/23	50-289	Q
8408270162	8408270156	84/08/20	50-327	P
8408270169	8408270160	84/08/16	50-269	P
8408270170	8408270164	84/08/22	50-155	Q
8408270172	8408270163	84/08/19	50-454	Q
8408270173	8408270167	84/08/17	50-331	P
8408270174	8408270168	84/08/10	50-395	Q
8408270175	8408270167	84/08/17	50-331	P
8408270178	8408270168	84/08/10	50-395	Q
8408270182	8408270168	84/08/10	50-395	Q
8408270183	8408270176	84/08/20	50-289	Q
8408270186	8408270179	84/08/20	50-445	Q
8408270187	8408270168	84/08/10	50-395	Q
8408270191	8408270184	84/07/09	50-413	Q
8408270199	8408270196	84/07/31	50-259	Q
8408270200	8408270192	84/07/27	50-335	Q
8408270209	8408270192	84/07/27	50-335	Q
8408270211	8408270206	84/08/01	50-302	Q
8408270214	8408270192	84/07/27	50-335	Q
8408270219	8408270206	84/08/01	50-302	Q
8408270221	8408270192	84/07/27	50-335	Q
8408270224	8408270206	84/08/01	50-302	Q
8408270225	8408270222	84/08/09	70-1151	
8408270227	8408270206	84/08/01	50-302	Q
8408270237	8408270234	84/08/08	50-410	Q
8408270240	8408270232	84/07/26	50-438	Q
8408270242	8408270234	84/08/08	50-410	Q
8408270243	8408270238	84/04/03	40-8584	
8408270246	8408270233	84/08/17	50-266	P
8408270247	8408270241	84/07/20	50-321	Q
8408270253	8408270250	84/08/01	WASTE MGT	
8408270255	8408270241	84/07/20	50-321	Q
8408270256	8408270250	84/08/01	WASTE MGT	
8408270258	8408270254	84/08/01	70-27	
8408270259	8408270249	84/08/09	50-369	Q
8408270261	8408270241	84/07/20	50-321	Q
8408270262	8408270250	84/08/01	WASTE MGT	
8408270263	8408270257	84/08/01	50-417	Q
8408270264	8408270250	84/08/01	WASTE MGT	
8408270266	8408270249	84/08/09	50-369	Q
8408270267	8408270250	84/08/01	WASTE MGT	
8408270268	8408270257	84/08/01	50-417	Q
8408270269	8408270241	84/07/20	50-321	Q
8408270270	8408270249	84/08/09	50-369	Q
8408270272	8408270257	84/08/01	50-417	Q
8408270274	8408270254	84/08/01	70-27	
8408270275	8408270257	84/08/01	50-417	Q
8408270276	8408270265	84/08/10	50-454	E
8408270277	8408270245	84/08/10	50-454	Q
8408270279	8408270249	84/08/09	50-369	Q
8408270280	8408270254	84/08/01	70-27	
8408270281	8408270273	84/08/21	50-255	Q
8408270282	8408270254	84/08/01	70-27	
8408270284	8408270265	84/08/10	50-454	E
8408270286	8408270254	84/08/01	70-27	
8408270288	8408270278	84/08/10	50-440	Q
8408270290	8408270285	84/08/22	50-219	P

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408270292	8408270265	84/08/10	50-454	E
8408270294	8408270287	84/08/21	50-409	Q
8408270295	8408270289	84/07/09	50-250	Q
8408270296	8408270265	84/08/10	50-454	E
8408270297	8408270283	84/08/09	40-672	
8408270298	8408270291	84/08/02	50-335	Q
8408270299	8408270293	84/08/17	50-263	P
8408270302	8408270293	84/08/17	50-263	P
8408270306	8408270291	84/08/02	50-335	Q
8408270307	8408270293	84/08/17	50-263	P
8408270310	8408270291	84/08/02	50-335	Q
8408270315	8408010061	84/07/18	50-329	A
8408270316	8408270314	84/07/31	50-250	Q
8408270317	8408270291	84/08/02	50-335	Q
8408270321	8408270313	84/08/02	50-416	Q
8408270322	8408270314	84/07/31	50-250	Q
8408270323	8408010061	84/07/18	50-329	A
8408270324	8408270314	84/07/31	50-250	Q
8408270326	8408270313	84/08/02	50-416	Q
8408270329	8408270314	84/07/31	50-250	Q
8408270330	8408010061	84/07/18	50-329	Q
8408270333	8408270313	84/08/02	50-416	Q
8408270336	8408010061	84/07/18	50-329	T
8408270338	8408270334	84/07/20	50-321	Q
8408270340	8408270313	84/08/02	50-416	Q
8408270341	8408270335	84/08/21	50-334	Q
8408270345	8408270339	84/08/15	50-269	P
8408270346	8408270337	84/08/21	70-734	
8408270347	8408270313	84/08/02	50-416	Q
8408270351	8408270342	84/07/17	50-424	Q
8408270352	8408270348	84/08/22	50-341	Q
8408270362	8408270358	84/08/21	50-373	F
8408270363	8408270360	84/07/27	50-335	Q
8408270369	8408270366	84/08/21	50-259	R
8408270370	8408270365	84/07/27	50-327	Q
8408270371	8408270367	84/07/17	50-413	Q
8408270374	8408270366	84/08/21	50-259	R
8408270375	8408270365	84/07/27	50-327	Q
8408270378	8408270365	84/07/27	50-327	Q
8408270382	8408270365	84/07/27	50-327	Q
8408270386	8408270383	84/07/20	50-369	Q
8408270388	8408270387	84/07/11	50-338	Q
8408270392	8408270390	84/08/22	50-155	Q
8408270407	8408270406	84/08/06	50-309	Q
8408270410	8408270406	84/08/06	50-309	Q
8408270412	8408270409	84/08/01	50-361	P
8408270413	8408270411	84/08/02	70-143	
8408270414	8408270408	84/07/12	50-424	Q
8408270415	8408270411	84/08/02	70-143	
8408270416	8408270409	84/08/01	50-361	P
8408270418	8408270409	84/08/01	50-361	P
8408270419	8408270417	84/07/09	50-390	Q
8408270421	8408270411	84/08/02	70-143	
8408270423	8408270411	84/08/02	70-143	
8408270427	8408270420	84/08/09	70-143	
8408270430	8408270429	84/07/25	50-424	Q
8408270431	8408270426	84/07/31	50-324	Q
8408270432	8408270428	84/07/10	50-302	Q
8408270433	8408270429	84/07/25	50-424	Q
8408270435	8408270426	84/07/31	50-324	Q
8408270436	8408270429	84/07/25	50-424	Q
8408270437	8408270426	84/07/31	50-324	Q
8408270439	8408270426	84/07/31	50-324	Q
8408270440	8408270429	84/07/25	50-424	Q
8408270447	8408270444	84/07/24	50-369	Q
8408270448	8408270443	84/07/31	50-280	Q
8408270452	8408270443	84/07/31	50-280	Q
8408270454	8408270443	84/07/31	50-280	Q
8408270456	8408270443	84/07/31	50-280	Q
8408270465	8408270461	84/08/08	50-271	Q
8408270466	8408270462	84/08/21	50-166	P
8408270468	8408270460	84/07/26	50-438	Q
8408270469	8408270463	84/07/13	50-390	Q
8408270473	8408270470	84/08/08	50-333	Q
8408270475	8408270460	84/07/26	50-438	Q
8408270478	8408270471	84/08/20	50-346	F
8408270480	8408270474	84/07/17	50-413	Q
8408270483	8408270460	84/07/26	50-438	Q
8408270486	8408270477	84/08/06	50-184	Q
8408270492	8408270484	84/07/23	50-413	Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408270494	8408270489	84/08/09	50-298	Q
8408270500	8408270489	84/08/08	50-298	Q
8408270501	8408270498	84/08/14	50-397	P
8408270503	8408270497	84/08/06	CONTRACT	
8408270506	8408270498	84/08/14	50-397	P
8408270508	8408270497	84/08/06	CONTRACT	
8408270518	8408270510	84/08/07	50-54	Q
8408270521	8408270513	84/07/30	50-261	Q
8408270528	8408270513	84/07/30	50 261	Q
8408270530	8408270513	84/07/30	50-261	Q
8408270531	8408270524	84/07/27	70-27	
8408270536	8408270513	84/07/30	50-261	Q
8408270540	8408270534	84/07/27	70-1113	
8408270541	8408270538	84/08/03	50-333	Q
8408270552	8408270547	84/08/20	CONTRACT	
8408270558	8408270557	84/08/13	CONTRACT	
8408270572	8408270561	84/07/23	50-395	Q
8408270576	8408270574	84/07/30	CONTRACT	
8408270579	8408270577	84/08/10	50-29	Q
8408270582	8408270581	84/08/20	CONTRACT	
8408280003	8408280002	84/08/24	50-255	Q
8408280007	8408280005	84/08/13	WASTE MGT	
8408280009	8408280005	84/08/13	WASTE MGT	
8408280012	8408280010	84/05/25	40-8675	
8408280016	8408280014	84/07/16	40-8502	
8408280022	8408280018	84/07/24	40-8857	
8408280024	8408280018	84/07/24	40-8857	
8408280028	8408280026	84/07/27	50-400	Q
8408280035	8408280027	84/08/07	50-261	Q
8408280039	8408280027	84/08/07	50-261	Q
8408280042	8408280027	84/08/07	50-261	Q
8408280046	8408280027	84/08/07	50-261	Q
8408280049	8408280030	84/07/11	50-390	Q
8408280053	8408280051	84/07/26	70-143	
8408280056	8408280054	84/08/20	50-322	H
8408280069	8408280061	84/07/19	50-302	Q
8408280072	8408280061	84/07/19	50-302	Q
8408280077	8408280061	84/07/19	50-302	Q
8408280082	8408280061	84/07/19	50-302	Q
8408280085	8408280080	84/08/13	50-254	Q
8408280091	8408280088	84/07/24	50-400	Q
8408280101	8408220463	84/08/20	50-352	A
8408280114	8408280104	84/08/24	50-395	P
8408280116	8408280096	84/07/25	50-259	Q
8408280118	8408280111	84/07/17	70-1113	
8408280123	8408280111	84/07/17	70-1113	
8408280124	8408280096	84/07/25	50-259	Q
8408280126	8408280120	84/08/22	QA999	
8408280131	8408280129	84/08/23	50-440	Q
8408280132	8408280130	84/08/23	50-352	A
8408280134	8408280096	84/07/25	50-259	Q
8408280139	8408280120	84/08/22	QA999	
408280140	8408280096	84/07/25	50-259	Q
08280141	8408280136	84/08/20	50-445	Q
08280146	8408280136	84/08/20	50-445	Q
08280155	8408280147	84/08/23	50-315	Q
408280164	8408280160	84/08/17	50-263	P
408280169	8408280160	84/08/17	50-263	P
408280187	8408280180	84/08/21	50-322	Q
8408280188	8408280184	84/08/15	50-313	F
8408280192	8408280189	84/08/23	70-143	
8408280198	8408280197	84/08/17	50-346	K
8408280203	8408280200	84/08/21	50-412	E
8408280206	8408280202	84/08/17	50-331	P
8408280209	8408280202	84/08/17	50-331	P
8408280211	8408280202	84/08/17	50-331	P
8408280213	8408280208	84/08/24	50-424	A
8408280222	8408280220	84/08/23	50-260	P
8408280226	8408280220	84/08/23	50-260	P
8408280248	8408280245	84/08/20	50-220	Q
8408280260	8408280259	84/08/16	TOPREP	
8408280261	8408280257	84/08/15	50-259	P
8408280262	8408280258	84/08/16	50-423	E
8408280266	8408220173	84/08/17	50-445	T
8408280268	8408280265	84/08/25	50-445	Q
8408280270	8408280090	84/08/03	70-1201	
8408280273	8408280272	84/08/24	50-278	P
8408280276	8408280257	84/08/15	50-259	P
8408280277	8408280090	84/08/03	70-1201	
8408280278	8408280272	84/08/24	50-278	P

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408280282	8408280090	84/08/03	70-1201	
8408280285	8408280090	84/08/03	70-1201	
8408280289	8408280090	84/08/03	70-1201	
8408280293	8408280291	84/08/10	50-219	Q
8408280299	8408280298	84/07/26	70-143	
8408280300	8408280298	84/07/26	70-143	
8408280321	8408280319	84/08/17	50-346	P
8408280329	8408280327	84/07/19	50-413	Q
8408280346	8408280342	84/08/17	50-445	A
8408280348	8408280345	84/08/14	50-346	F
8408280366	8408280360	84/07/22	50-295	P
8408280367	8408280362	84/08/09	70-1113	
8408280370	8408280361	84/07/20	50-269	Q
8408280373	8408280360	84/07/22	50-295	P
8408280377	8408280372	84/08/06	50-413	F
8408280378	8408280360	84/07/22	50-295	P
8408280380	8408280360	84/07/22	50-295	P
8408280381	8408280360	84/07/22	50-295	P
8408280383	8408280360	84/07/22	50-295	P
8408280387	8408280360	84/07/22	50-295	P
8408280390	8408280360	84/07/22	50-295	P
8408280393	8408280384	84/07/11	50-413	Q
8408280395	8408280360	84/07/22	50-295	P
8408280397	8408280394	84/08/24	50-322	T
8408280400	8408280360	84/07/22	50-295	P
8408280404	8408280360	84/07/22	50-295	P
8408280407	8408280360	84/07/22	50-295	P
8408280411	8408280360	84/07/22	50-295	P
8408280422	8408280360	84/07/22	50-295	P
8408280430	8408280360	84/07/22	50-295	P
8408280460	8408280456	84/08/10	50-400	Q
8408280465	8408280456	84/08/10	50-400	Q
8408280469	8408280456	84/08/10	50-400	Q
8408280471	8408280467	84/08/13	COMMISSION	
8408280476	8408280472	84/08/01	50-269	Q
8408280479	8408280472	84/08/01	50-269	Q
8408280481	8408280472	84/08/01	50-269	Q
8408280485	8408280472	84/08/01	50-269	Q
8408290007	8408290003	84/08/10	50-423	Q
8408290025	8408290021	84/08/07	50-261	Q
8408290028	8408290021	84/08/07	50-261	Q
8408290031	8408290021	84/08/07	50-261	Q
8408290034	8408290021	84/08/07	50-261	Q
8408290035	8408290021	84/08/07	50-261	Q
8408290039	8408290021	84/08/07	50-261	Q
8408290102	8408290098	84/08/24	50-354	A
8408290104	8408290101	84/08/16	50-298	Q
8408290108	8408290103	84/07/31	50-458	Q
8408290115	8408290113	84/08/01	50-368	Q
8408290138	8408290134	84/08/24	50-354	E
8408290142	8408290140	84/08/08	50-285	Q
8408290144	8408290134	84/08/24	50-354	E
8408290149	8408290134	84/08/24	50-354	E
8408290160	8408290134	84/08/24	50-354	E
8408290176	8408290172	84/08/01	50-368	Q
8408290206	8408290197	84/08/24	50-266	F
8408290211	8408290208	84/08/27	50-445	K
8408290269	8408290265	84/08/24	50-269	T
8408290286	8408290277	84/08/17	50-163	P
8408290287	8408290282	84/08/15	50-259	P
8408290291	8408290277	84/08/17	50-163	P
8408290292	8408290282	84/08/15	50-259	P
8408290297	8408290290	84/08/22	PR	
8408290324	8408290314	84/08/15	50-263	P
8408290329	8408290314	84/08/15	50-263	P
8408290349	8408290347	84/08/14	CONTRACT	
8408290350	8408290348	84/08/15	COMMISSION	
8408290352	8408290348	84/08/15	COMMISSION	
8408290359	8408290356	84/08/09	COMMISSION	
8408290483	8408290478	84/08/08	50-322	Q
8408290486	8408290478	84/08/08	50-322	Q
8408290553	8408290549	84/08/07	50-456	Q
8408290561	8408290549	84/08/07	50-456	Q
8408290570	8408290565	84/08/10	50-266	Q
8408300021	8408300014	84/08/10	50-269	F
8408300028	8408300014	84/08/10	50-269	F
8408300037	8408300035	84/08/27	50-220	P
8408300041	8408300035	84/08/27	50-220	P
8408300060	8408300058	84/08/13	50-263	Q
8408300083	8408300079	84/08/17	50-166	P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408300096	8408300087	84/08/10	50-219	Q
8408300099	8408300095	84/08/08	50-10	Q
8408300100	8408300094	84/08/07	50-528	Q
8408300105	8408300094	84/08/07	50-528	Q
8408300108	8408300095	84/08/08	50-10	Q
8408300111	8408300102	84/08/27	50-237	P
8408300113	8408300106	84/08/14	50-247	Q
8408300114	8408300110	84/08/08	50-312	Q
8408300116	8408300107	84/08/13	50-29	Q
8408300121	8408300118	84/08/14	50-456	Q
8408300127	8408300125	84/08/03	50-528	Q
8408300132	8408300128	84/08/23	50-255	Q
8408300133	8408300110	84/08/08	50-312	Q
8408300149	8408300140	84/08/09	50-275	Q
8408300160	8408300154	84/08/24	50-313	Q
8408300164	8408300156	84/07/11	50-255	Q
8408300165	8408300163	84/08/27	50-361	P
8408300166	8408300154	84/08/24	50-313	Q
8408300175	8408300172	84/08/23	50-219	F
8408300180	8408300176	84/08/02	50-263	F
8408300183	8408300176	84/08/02	50-263	F
8408300186	8408300179	84/08/14	50-440	Q
8408300188	8408300181	84/08/14	50-315	Q
8408300194	8408300190	84/06/19	70-824	
8408300195	8408300187	84/08/02	50-528	Q
8408300196	8408300179	84/08/14	50-440	Q
8408300199	8408300192	84/08/14	50-305	Q
8408300200	8408300190	84/06/19	70-824	
8408300202	8408300190	84/06/19	70-824	
8408300204	8408300193	84/06/15	50-369	F
8408300206	8408300190	84/06/19	70-824	
8408300207	8408300203	84/08/14	50-341	Q
8408300211	8408300208	84/06/05	50-302	F
8408300217	8408300197	84/08/22	50-366	P
8408300219	8408300197	84/08/22	50-366	P
8408300220	8408300203	84/08/14	50-341	Q
8408300237	8408300233	84/08/14	50-289	P
8408300250	8408300248	84/08/10	50-312	Q
8408300254	8408300248	84/08/10	50-312	Q
8408300307	8408300296	84/06/06	70-1201	
8408300308	8408300299	84/08/15	50-254	R
8408300319	8408300315	84/07/19	50-324	F
8408300323	8408300315	84/07/19	50-324	F
8408300329	8408300299	84/08/15	50-254	R
8408300336	8408300299	84/08/15	50-254	R
8408300346	8408300344	84/07/19	50-424	Q
8408300350	8408300347	84/06/08	50-400	Q
8408300377	8408300373	84/08/01	50-344	Q
8408300380	8408300373	84/08/01	50-344	Q
8408300381	8408300374	84/08/10	50-320	Q
8408300387	8408300385	84/08/23	50-328	P
8408300389	8408300385	84/08/23	50-328	P
8408300390	8408300383	84/08/08	50-528	Q
8408300393	8408300388	84/07/23	50-373	R
8408300394	8408300391	84/06/28	70-27	
8408300397	8408300383	84/08/08	50-528	Q
8408300401	8408300398	84/07/18	70-27	
8408300407	8408300383	84/08/08	50-528	Q
8408300451	8408300446	84/08/07	50-397	Q
8408300464	8408300446	84/08/07	50-397	Q
8408300469	8408300459	84/07/13	50-327	Q
8408300477	8408300459	84/07/13	50-327	Q
8408300498	8408300483	84/08/02	50-312	Q
8408300504	8408300483	84/08/02	50-312	Q
8408300513	8408300508	84/07/25	50-373	R
8408300515	8408300512	84/08/17	50-261	F
8408300516	8408300508	84/07/25	50-373	R
8408310005	8408310001	84/08/21	XPORTLIC	
8408310025	8408310019	84/08/24	XPORTLIC	
8408310035	8408310032	84/08/01	50-275	P
8408310039	8408310031	84/07/12	70-27	
8408310048	8408310044	84/08/01	50-470	Q
8408310088	8408310082	84/08/23	CONTRACT	
8408310105	8408310102	84/08/14	50-445	Q
8408310112	8408310108	84/08/24	TOPREP	
8408310114	8408310109	84/07/09	50-259	Q
8408310126	8408310122	84/08/21	50-305	P
8408310144	8408310140	84/08/23	70-2571	
8408310157	8408310153	84/08/28	50-289	P
8408310165	8408310161	84/08/02	50-255	Q

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8408310179	8408310176	84/08/23	50-409	P
8408310191	8408310188	84/08/24	50-341	F
8408310194	8408310192	84/08/30	50-454	T
8408310199	8408310192	84/08/30	50-454	T
8408310204	8408310203	84/08/23	50-254	P
8408310213	8408310208	84/08/27	50-412	F
8408310215	8408310212	84/08/16	PR	
8408310220	8408310217	84/06/27	50-312	P
8408310221	8408310219	84/08/24	PR	
8408310237	8408310234	84/06/25	50-312	P
8408310239	8408310238	84/08/27	50-289	P
8408310244	8408310243	84/08/03	50-206	Q
8408310246	8408310245	84/08/21	50-312	P
8408310255	8408310254	84/05/31	70-1151	
8408310262	8408310260	84/08/16	CONTRACT	
8408310275	8408310269	84/08/01	50-344	S
8408310296	8408310288	84/08/17	50-305	Q
8408310302	8408310299	84/08/15	50-255	Q
8408310308	8408310305	84/08/07	50-289	P
8408310311	8408310305	84/08/07	50-289	P
8408310321	8408310317	84/08/21	XPORTLIC	
8408310329	8408310317	84/08/21	XPORTLIC	
8408310335	8408310331	84/03/27	WASTE MGT	
8408310339	8408310331	84/03/27	WASTE MGT	
8408310344	8408310331	84/03/27	WASTE MGT	
8408310358	8408310354	84/08/28	71-66	
8408310359	8408310355	84/08/20	50-298	S
8408310362	8408310361	84/08/02	50-373	S
8408310368	8408310363	84/08/23	CONTRACT	
8408310370	8408310365	84/08/06	50-317	S
8408310390	8408310385	84/08/27	CONTRACT	
8408310394	8408310381	84/08/17	50-341	Q
8408310430	8408310396	84/08/22	50-293	P
8408310431	8408310424	84/08/17	50-260	P
8408310432	8408310424	84/08/17	50-260	P
8408310433	8408310396	84/08/22	50-293	P
8408310438	8408310436	84/08/28	71-16	
8408310442	8408310439	84/08/27	50-373	P
8408310453	8408310449	84/08/28	71-216	
8408310456	8408310455	84/08/28	71-169	
8408310457	8408310443	84/08/28	71-70	

DEFINITIONS OF DOCKET 50 CATEGORIES

A APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license It includes all correspondence and documents with substantive technical content that do not fall into other specific categories Included are

1 Application for construction permit

2 General Information submitted with construction permit application

3 Amendments and changes to items 1 and 2

4 NRC questions, requests for additional information, and applicant responses

5. Correspondence and documents relating to unresolved design and construction issues

6 Meeting announcements and summaries of meeting discussions on issues of item 5

7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).

8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc)

9. Construction Permit, amendments, and correspondence relating to the construction permit.

10. Scheduling of license application submission or review.

11. Environmental review information

12 Application for operating license.

13 General Information submitted with operating license application.

14. Amendments and changes to items 12 and 13.

15. Correspondence regarding the Final Safety Analysis Report (FSAR).

16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin

17. Reports of site visits.

18. Backup technical documents (e g., topical reports) submitted in support of the application

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report)

2. Amendments and changes to the PSAR.

3 Transmittal and acknowledgement letters

4 Certificates of service to the PSAR

C UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below Other environmental documents and correspondence are filed in Categories A D M P or R

1 Environmental Report (ER) submitted by the utility

2 Amendments and supplements to the ER

3 Transmittal and acknowledgement letters

4 Information on scheduling of submittal or review of ER

5 NRC questions, requests for additional information and applicant responses

6. Federal register notices citing the availability of items 1 and 2

7 Correspondence relating to the review of ER

8 Meeting announcements or reports of meetings where the primary subject of discussion is the ER

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below Other environmental documents and correspondence are in categories A, C, M, P or R

1 Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC

2 Supplements to the DES and FES.

3 Correspondence relating to the DES and FES

4. Comments from other federal state and local government agencies

5. Transmittal and acknowledgement letters

6 Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements

7 Backup technical documents submitted in connection with above

8 Federal register notice citing availability of items 1 and 2

9 Site visits to obtain information for DES or FES

10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process

1 Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report)

2 Supplements to SER

3 Correspondence relating to SER

4 Federal register notices citing availability of items 1 and 2

5 Information on scheduling of SER submittals and review

6 Requests for additional information for use in preparing SER, responses to such requests

7 Meeting announcements or reports of meetings where the primary subject of discussion is the SER

8 Transmittal and acknowledgement letters

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1 Fire Hazard Protection Plan and surveys

2. Plant evacuation correspondence

3 Safeguards Contingency Plans

4 Review of Health Physics Program

5 Correspondence relating to aforementioned plans

6. Supplements, changes and revisions to plans

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T

1 Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.

2 Federal register notices regarding hearings

3 Requests to make appearances at hearings.

4 Motions, briefs, arguments, statements and related correspondence filed by participants for hearings

5 Transmittal of supporting documents (e g , SER, FES) to the boards.

6 Correspondence to and from intervenors

7. Board orders and decisions

8 Petitions for Commission action.

9 Legal filings and Commission orders and decisions resulting from item 8

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license Items that have no substantive technical content or meaning for the status of the license or application are included

1 Change of address notifications

2 Changes in structure of organization

3 Changes in service lists

4 NRC requests to applicant for additional copies of documents.

5 Correspondence from the public requesting information about the facility and NRC responses.

6 Correspondence on strictly administrative matters

7 Letters of support, concern or opposition to the facility

8 Correspondence regarding the Local Public Document Rooms (LPDRs)

9 Professional qualification statements not pertaining to the hearing process

I FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.

2 Separately submitted financial information and related correspondence

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.

2. Endorsements insurance policies

3 Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below All related correspondence falls in category A or P

1 Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).

2 Amendments and changes to the FSAR

3 Federal register notices citing availability of items 1 and 2

4 Transmittal and acknowledgement letters

5 Certificates of service to the FSAR.

L LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

1 Limited Work Authorizations (LWA) and amendments

2 Correspondence pertaining to work performed under LWA's

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1 Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"

2 Correspondence where the primary topic of discussion is antitrust matters

3 All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters Related correspondence falls in category M

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1 Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews

2. Correspondence from ACRS

3 Announcement of ACRS meetings

4 Transmittal and acknowledgement letters

5 ACRS reports

6 Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings

7 Minutes at ACRS Subcommittee Meetings

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license

1. Operating license amendments, proposed amendments changes and related correspondence

2 Technical specifications and changes.

3 Backup technical documents (e g , topical reports) submitted in support of items 1 and 2

4 Federal register notices citing availability of items 1 and 2

5 Correspondence regarding the Final Safety Analysis Report (FSAR)

6 All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license

7. Correspondence regarding codes (e g , ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license

8. Information on the Standard Review Plan (STP).

9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R)

10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).

11 Owner's group meeting announcements and reports

12 Quality assurance information.

13 Environmental matters (technical)

14. Emergency core cooling system documents.

15 Radioactive waste information

16. Correspondence regarding expansion of spent fuel storage pool

17. Start-up test reports

18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility, not covered by an IE Bulletin.

19. Reports of site visits

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1 Inspection reports

2 IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.

3. Responses by applicant to IE correspondence.

4. Applicant's determination of proprietary nature of inspection reports

5. Letters concerning areas of noncompliance.

6. Pre-service and in-service inspections and procedures

7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN s).

8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

1 Monthly, semiannual, or annual operating reports (other than financial)

2 Periodic environmental monitoring, effluent testing, or similar reports

3 Periodic personnel exposure reports

4 Operational Logbooks

Logbooks on Environmental Data
Logbooks on Radiological Data
Operations Log on Plant Systems Core
Plant Status Summary Sheets

5 Correspondence or other documents relating to the above listed items

S REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes.

1 All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER s) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)

2 Potential or possible reportable deficiency reports and related correspondence.

3 Personnel exposure reports.

4 Construction deficiency reports submitted under 10 CFR 50.55e

5. Preliminary Notification of Occurrence (PNO s) and Preliminary Notification of Safeguards Events (PN s).

6. Environmental Technical Specifications violation reports and Environmental Event reports

7 Part 21 Reports of defects and noncompliance

8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts

2. Testimony and statements submitted to ASLB and ASLAB.

3 Commission meeting transcripts.

4. NRC staff briefings to the Commission

5. Statements and written testimony submitted at Commission meeting or hearings

6. Transcripts of utility briefs to NRC staff

7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts

8. Corrections to above items

U CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters Routine responses to constituent inquiries are filed in category H

1 Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches

2 Preparatory and backup documents for item 1

3 Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators

2 NRC examination results

3 Power plant examination summary sheet

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

1. Application for authority to voluntarily surrender license

2. Application to dismantle the facility and dispose of component parts

3 Technical documents submitted in support of items 1 and 2, such as Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning

4. Documents relating to disposal of radioactive material and decontamination of the site

5. Other correspondence relating to above items.

6. All documentation relating to the ongoing operation of the plan, formerly filed in category P

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)

2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence
7. Staff requirements memoranda for open meetings, memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters
2. ACRS meeting announcements, description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM – NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

1. Charters of each advisory committee.
2. Verbatim transcripts of committee meetings.

3 Meeting announcements; description of meeting agendas.

4. Committee generated reports, memoranda, and correspondence that are publicly available.

5. Committee related correspondence.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

1 Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

2 Travel vouchers, telephone logs and official appointment calendars of individual Commissioners

3 Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).

2. Solicitations (RFP or IFB) issued by the NRC.

3. Notifications of contract execution specifying contract number, project title, contractor name, contract type, funding, and period of performance

4 Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include

1 Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.

2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.

3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1 Draft reports of action plans to accomplish generic tasks in the regulatory program

2 Correspondence with industry and internal correspondence regarding the methodologies analyses, and programmatic and technical aspects of issues

3. Meeting notifications and minutes

4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs)

1 I&I Circulars, which describe an event at a licensed facility and are informational in nature

2 I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.

3. I&I Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event

4 Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance

NOTE For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors

1. These reports are normally final work products and are characterized by the following criteria

   a They are predecisional documents which present information to be considered in Commission licensing and policy decisions.

   b They present the results of Commission licensing and policy decisions.

   c They present the results of technical research conducted for the Commission

2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.

3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG – Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue Included are

1 Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.

2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e g , EPA has authority to control all radioactive pollutants emitted into the air

3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development

4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S plants to withstand earthquakes.

NOTE For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are.

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.

2. Text of the Proposed Rule (PR).

3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.

4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.

2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.

4 Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1 "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.

2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.

3. Applicant's Quality Assurance Manual

4. Early site review information.

5. Backup technical documents submitted in support of the application.

6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.

2. Amendments and changes to the PSAR.

3. Transmittal letters.

4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.

2. Notices of deviations.

3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include.

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.

2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.

3. NRC inspection reports of defects cited

4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.

2. Notices of deviations.

3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

regulatory guides issued by the Commission and related cor-
the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are

1. Project description documents
2. Letter reports of accomplishments and data reports, for example,
   a. model documentation reports
   b. code documentation reports
   c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are

1 Agendas for quarterly review group meetings

2 Summary minutes of review group meetings representing views expressed, including dissenting views.

3 Research plans and predicted results of major experiments, presentations by research contractors.

4 Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.

5 Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include

1. Designations of the presiding officer and any special directions for the conduct of the hearing.

2 Notifications of hearing board meetings.

3. Petitions, motions, testimony and statements submitted by parties to the hearings.

4. Hearing board orders and rulings.

5. Technical reports submitted as evidence in the proceeding.

6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.

2. Consent Calendar items and Policy Session items.

NOTE For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies, and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:

   a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance

   b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.

2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.

3. State Legislative Reports.

4. Agreement State Licensing Statistics Reports.

NOTE. For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.

2. Revisions, modifications and amendments to topical reports.

3. Correspondence between NRC and vendors pertaining to the review of submittals.

4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.

2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes

4 NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.

2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.

3 Commission letters requesting Executive Branch views

4 Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security

5. Correspondence from foreign governments, international organizations, and members of the public

6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.

7. Filings pursuant to hearing requests or intervention petitions, if any.

8 Hearing records and decisions.

9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.

10. Licenses, license amendments and license renewals for types specified in item 1

NOTE For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 (11 81)

U.S. NUCLEAR REGULATORY COMMISSION

BIBLIOGRAPHIC DATA SHEET

1 REPORT NUMBER *(Assigned by DDC)*
NUREG-0540
Vol. 6, No. 8

4 TITLE AND SUBTITLE *(Add Volume No., if appropriate)*
Title List of Documents Made Publicly Available
August 1-31, 1984

2 *(Leave blank)*

3 RECIPIENT'S ACCESSION NO

7 AUTHOR(S)

5 DATE REPORT COMPLETED
MONTH | YEAR

9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS *(Include Zip Code)*
Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, DC 20555

DATE REPORT ISSUED
MONTH: October | YEAR: 1984

6 *(Leave blank)*

8 *(Leave blank)*

12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS *(Include Zip Code)*
Same as 9, above.

10 PROJECT/TASK/WORK UNIT NO

11 FIN NO

13 TYPE OF REPORT
Monthly

PERIOD COVERED *(Inclusive dates)*
August 1-31, 1984

15 SUPPLEMENTARY NOTES

14 *(Leave blank)*

16 ABSTRACT *(200 words or less)*

This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.

17 KEY WORDS AND DOCUMENT ANALYSIS

17a DESCRIPTORS

17b IDENTIFIERS/OPEN ENDED TERMS

18 AVAILABILITY STATEMENT
Unlimited

19 SECURITY CLASS *(This report)*
Unclassified

21 NO OF PAGES

20 SECURITY CLASS *(This page)*
Unclassified

22 PRICE
S